Title List of Documents Made Publicly Available

October 1-31, 1982

Office of Administration U.S. Nuclear Regulatory Commission



Available from

NRC/GPO Sales Program

Superintendent of Documents Government Printing Office Washington, D. C. 20402

A year's subscription consists of 12 issues for this publication.

Single copies of this publication are available from National Technical Information Service, Springfield, VA 22161

Microfiche of single copies are available from NRC/GPO Sales Program Washington, D. C. 20555

Title List of Documents Made Publicly Available

October 1-31, 1982

Division of Technical Information and Document Control Office of Administration U.S. Nuclear Regulatory Commission Washington, D.C. 20555



CONTENTS

Preface	v
Arrangement of Items by Docket Number	ix
Alphabetic Arrangement of Docket Items by Facility Name	xvii
Docketed Items	
Low Level Radwaste Disposal Sites — Docket 27	1
Domestic Licensing of Source Material — Docket 40	1
Domestic Licensing of Production and Utilization Facilities — Docket 50	7
Domestic Licensing of Special Nuclear Material — Docket 70	328
Packaging of Radioactive Material for Transport and Transportation of	
Radioactive Material Under Certain Conditions — Docket 71	335
Nondocketed Items	
10 CFR — Commission Meeting Records	339
ACRS — Advisory Committee on Reactor Safeguards	339
COMMISSION — NRC Commissioners	340
CONTRACT — NRC Contracts and Modifications	340
FOIA — Freedom of Information Act Requests and Releases	347
GEN TECH IS — Generic Technical Issues	364
I&E Inspection and Enforcement	365
MISC — Public Document Room Miscellaneous	366
NUREG — NUREG Reports and Related Correspondence	366
ORG — Correspondence with Other Organizations	370
PR — Proposed Rule	371
PRM — Petition for Rulemaking	374
PROJ — Projects - Predocket Licensing	374
PT 21 — Noncompliance Reports and Related Correspondence	374
QA999 — Quality Assurance Inspections	374
REGGD — Regulatory Guides	376
RES — Research and Technical Assistance Reports	377
REVIEW GROUP NRC Research Review Groups	378
SECY — Position Papers Before the Commission	379
STATE PROG — State Programs	379
TOPREP — Vendor Reports and Related Correspondence	380
WASTE MGT — Nuclear Waste Management	383
XPORTLIC — Export and Import Licenses	384
Personal Author Index	389
Corporate Source Index	419
Report Number Index	449
Cross Reference of Enclosures to Principal Documents	451
Appendix A — Definitions of Docket 50 Categories	A-1
Appendix B — Definitions of Nandocketed Categories	B-1

PREFACE

The Title List of Documents Made Publicly Available is a monthly publication. It contains descriptions of the information received and generated by the U.S. Nuclear Regulatory Commission (NRC). This information includes (1) docketed material associated with civilian nuclear power plants and other uses of radioactive materials and (2) nondocketed material received and generated by NRC pertinent to its role as a regulatory agency. As used here, docketed does not refer to Court dockets; it refers to the system by which NRC maintains its regulatory records. This series of documents is indexed by a Personal Author Index, a Corporate Source Index, and a Report Number Index.

The docketed information contained in the *Title List* includes the information formerly issued through the Department of Energy publication *Power Reactor Docket Information*, last published in January 1979. Microfiche of the docketed information listed in the *Title List* is available for sale on a subscription basis from the National Technical Information Service (NTIS). See NOTES at the end of the Preface for the complete NTIS address.

We encourage your comments, criticisms, and suggestions. In particular, if there are title descriptions that are not meaningful, please let us know so that we can correct the data base. In so far as possible, we would like this document to be a valuable part of your reference material.

DOCKETED ITEMS

The listings within Docket 50 are divided into the categories used for filing and searching in the NRC Public Document Room. Those categories are:

- A. Application/construction stage documents and correspondence
- B. Utility Preliminary Safety Analysis Report (PSAR), amendments
- C. Utility Environmental Report (ER), amendments and correspondence
- D. NRC Draft and Final Environmental (Impact) Statements (DES and FES), and correspondence
- E. NRC Safety Evaluation Report (SER), supplements and correspondence
- F. Security, medical, emergency and fire-protection plans
- G. Adjudicatory correspondence
- H. General correspondence
- I. Financial information
- J. Insurance and indemnity information
- K. Utility Final Safety Analysis Report (FSAR) and amendments
- L. Limited work authorization and related correspondence
- M. Antitrust correspondence
- N. Antitrust hearing transcripts
- O. Advisory Committee on Reactor Safeguards (ACRS) reports and correspondence
- P. Operating license stage documents and correspondence
- Q. Inspection reports, IE Bulletins and correspondence
- R. Periodic operating reports and related correspondence
- S. Reportable occurrences. LERs and related correspondence
- T. Hearing transcripts on non-antitrust matters
- U. Congressional/executive correspondence
- V. Licensing operators and related correspondence

- W. Decommissioning stage documents and correspondence
- X Onsite low-level wastes storage

Appendix A sets forth those categories and describes the materials available in each. Omission of a category in the listing for a docket indicates that no documents in that category were filed in the time period of the report.

The principal elements of the entries in the list are:

Operating license stage documents & correspondence

2
3
8203090028 Responds to 820201 ltr requesting documents re environ qualification of electrical equipment. All nonproprietary repts will be provided to Franklin Research. Ctr. by 820408. Proprietary repts will be provided to NRC by 820510.

4 MILLS, L.M. 5 Tennessee Valley Authority. 6 82/03/04 7 VASSALLO, D.B. Operating Reactors Branch 2. 8 1p. 1216:254. 24XFiche: 50-259, 82/03/04, 8203090028.

- 1. NRC/PDR Document category (see Appendix A)
- 2. NRC Accession Number (year, month, day, and sequence number of item).
- 3. Description of information contained in the document.
- 4. Personal author(s). An asterisk in this position indicates that there is no personal author.
- 5. Corporate, agency or nonindividual source.
- 6. Date of document described.
- 7. Recipient of document and NRC or corporate affiliation.
- 8. Pages in this document.
- 9. The NRC 48X microfiche designation for this document. This five-digit portion of this entry is the number of the microfiche copy of this document that is available to NRC staff who have access to 48X microfiche files
- This three-digit portion of this entry is the number of the frame on which this document starts.
- 11. The 24X Fiche designation consists of the docket number followed by the date of the document and the accession number for the document. This designation provides the information needed by subscribers to the National Technical Information Service docket microfiche to locate the document fiche.
- 12. If this space is blank, the document is available to the public only in the NRC Public Document Room, 1717 H St., N.W., Washington, D.C. 20555. If this space is filled, it gives other sources for copies of the document. The entry may be "Available at NRC" for sale; "Available at NTIS"; or "Available at GPO."

The Docketed Items list is arranged sequentially by Docket Number, category, and then by date of principal items. Entries indented and preceded by a dash are items that were submitted as enclosures to principal items. In general, indented items are not in accession number sequence. If the docketed document has a contract (FIN) number or a formal report number, it will appear in the last line of the item following entry 5.

NONDOCKETED ITEMS

The nondocketed items are divided into the categories used for filing and searching in the NRC Public Document Room. These categories and their symbols are:

10CFR — Commission Meeting Records
ACRS — Advisory Committee on Reactor Safeguards
COMMISSION — NRC Commissioners
CONTRACT — NRC Contracts and Modifications
DISCLOSURE — Financial Disclosure Information
FOIA — Freedom of Information Act Requests and Releases
GEN TECH IS — Generic Technical Issues

1&E - Inspection and Enforcement

MISC - Public Document Room Miscellaneous

NUREG - NUREG Reports and Related Correspondence

ORG - Correspondence with Other Organizations

PR — Proposed Rule

PRM — Petition for Rulemaking

PROJ — Projects—Predocket Licensing

PT21 — Noncomphance Reports and Related Correspondence

QA999 — Quality Assurance Inspections

REGGD - Regulatory Guides

RES — Research and Technical Assistance Reports

REVIEW GRP - NRC Research Review Groups

RM - Rulemakings

SECY — Position Papers Before the Commission

STATE PROG — State Programs

TOPREP — Vendor Reports and Related Correspondence


WASH — Regulatory Publications—Pre-NUREG Series

WASTE MGT - Nuclear Waste Management

XPORTLIC - Export and Import Licenses

Appendix B sets forth these categories and describes the material available in each. Omission of a category in the listing for a docket indicates that no documents in that category were filed in the time period of the report.

The principal elements of the nondocketed items are:



- 1. Nondocketed category
- 2. NRC Accession Number (year, month, day, and sequence number of item)
- 3. NRC Report Number
- 4. Title and description of information contained in the document
- 5. Personal author(s). An asterisk in this position indicates that there is no personal author.
- 6. Corporate, agency or other nonindividual source.
- 7. Contract or financial (FIN) number (if any). If the document has a sceondary report number, it will appear following this entry.
- 8. Secondary report number assigned by originator.
- 9 Date of document described.
- 10. NRC organizational recipient.
- 11. Pages in document.
- 12. All NUREG-series documents are available for purchase at NRC. Information on ordering documents is given below. All NUREG-series documents are also available at NTIS. Information on ordering from NTIS is also given below.
- 13. Price for which NRC sells the document.

- 14. The NRC 48X microfiche designation for this document. This five-digit portion of this entry is the number of the microfiche copy of this document that is available to NRC staff who have access to 48X microfiche files
- 15. This three-digit portion of this entry is the number of the frame on which this document starts.

The Nondocketed Items list is arranged sequentially by Accession Number within category. Indented items preceded by a dash are enclosures to unindented items.

NOTES.

1 The address for NRC is.

Director
Division of Technical Information and Document Control
U.S. Nuclear Regulatory Commission
Washington, D.C 20555

To place orders, send check or money order, payable to the Superintendent of Documents. GPO Deposit Account holders may charge their orders by calling (301) 492-9530.

2 The address for NTIS is:

National Technical Information Service Springfield, Virginia 22161

To place orders for or to obtain price information about NRC publications at NTIS, either write to NTIS or call the Sales Desk at (703) 557-4650. Specify the NRC report number and title when you place your order. Publications can be charged to American Express credit cards; supply the chargecard number when placing your order

3. The address for the PDR is:

1717 H Street, N W. Washington, D.C. 20555

To place orders, either write to the NRC PDR or call (202) 634-3274. When ordering documents listed in this publication, please identify the Document Accession Number for each citation.

Paper copy and microfiche of the documents listed in this title list may be purchased. Reproduction charges for duplication are as follows: (1) paper to paper is \$0.05 per page except for oversized documents and engineering drawings, which vary from \$0.50 to \$1.00 per square foot; (2) microform to paper is \$0.05 a page for pages on microfiche and is \$0.20 a square foot for a full-size print or \$0.25 for a reduced-size print (18" x 24") of a drawing on an aperture card; and (3) microform to microform is \$0.10 per microfiche and \$0.20 per aperture card. Orders completed for mailing or for a special delivery service will have an additional fee for the actual mailing, shipping, or delivery service rate. Unless a user requests special packing materials, there is no additional charge by the contractor for handling and wrapping materials.

Please acknowledge a willingness to assume charges for all orders but do not send payments. Orders will be processed and mailed with a bill from Literature Research Company. An account may be established with the Literature Research Company by calling (703)-941-8018

ARRANGEMENT OF ITEMS BY DOCKET NUMBER

Docket	Name	Page	Docket	Name	Page
Low Level Rad	lwaste Disposal Sites — Docket 27		40-8452	Bear Creek Uranium Co., Casper, WY	4
27-010	Beatty, NV, U.S. Ecology, Inc.	1	40-8502	Wyoming Mineral Corp., Lakewood, CO	5
27-039	Sheffield, IL, U.S. Ecology, Inc.	1	40-8577	Air Force, Dept. of, Vandenberg AFB, CA	5
27-047	Barnwell, SC, Chem-Nuclear Systems, Inc.	1	40-8602	Silver King Mines, Inc., Casper, WY	5
27-048	Richland, WA, U.S. Ecology, Inc.	1	40-8610	Stepan Chemical Co., Maywood, NJ	5
Domestic Licer	nsing of Source Material — Docket 40		40-8632	Army, Dept. of, Chambersburg, PA	5
40-0017	Dow Chemical Co., Midland, MI	1	40-8681	Energy Fuels Nuclear, Inc., Denver, CO	5
40-0299	Union Carbide Corp., Grand Junction, CO	1	40-8697	Rocky Mountain Energy Co., Denver, CO	6
40-1162	Western Nuclear Corp., Jeffrey City, WY	2	40-8698	Plateau Resources, Ltd.,	
40-1202	NL Industries, Inc., Niagara Falls, NY	2		Grand Junction, CO	6
40-1341	Tennessee Valley Authority,		40-8714	Cleveland-Cliffs Iron Co., Cleveland, OH	6
	Chattanooga, TN	2	40-8728	Teton Exploration Drilling Co., Inc., Casper, WY	6
40-2061	Kerr-McGee Chemical Corp., Oklahoma City, OK	2	40-8743	Conoco, Inc., Denver, CO	6
40-2259	Pathfinder Mines Corp., Riverton, WY	2	40-8745	Ogle Petroleum, Inc., Casper, WY	6
40-3392	Allied Chemical Corp., Morristown, NJ	2	40-8768	Kerr-McGee Nuclear Corp.,	
40-3453	Atlas Mineral, Inc., Denver, CO	2		Oklahoma City, OK	6
40-6622	Pathfinder Mines Corp.,		40-8771	Melapai Resources Co., Phoenix, AZ	6
	Shirley Basin, WY	3	40-8781	Teton Exploration Drilling Co., Inc., Casper, WY	6
40-6659	Getty Oil Co. — Petrotomics Co., Shirley Basin, WY	3	40-8786	Uranium Resources, Inc., Richardson, TX	7
40-7580	Fansteel, Inc., North Chicago, IL	3	40-8793	Conoco, Inc., Denver, CO	7
40-8027	Kerr-McGee Nuclear Corp.,		40-8820	Amax Environmental Services, Inc.,	•
40-0021	Oklahoma City, OK	3	40-0020	Golden, CO	7
40-8084	Rio Algom Corp., Moab, UT	4	40-8824	Target Research, Inc., Wharton, NJ	7
40-8102	Exxon Co. USA, Houston, TX	4	Domestic Licer Docket 50	sing of Production and Utilization Facilities	
40-8111	Kennecott Copper Corp., Salt Lake City, UT	4	50-3	Indian Daint Station Italy	-
40-8153	Lebanon Steel Foundry, Lebanon, PA	4		Indian Point Station, Unit !	7
40-8355	Amax Speciality Metals Corp.,		50-10	Dresden Nuclear Power Station, Unit 1	8
	Parkersburg, WV	4	50-13	Babcock & Wilcox Co. Critical Facility	9
40-8380	Rocky Mountain Energy Co., Broomfield, CO	4	50-20	Massachusetts Institute of Technology Research Reacter	9

Docket	Name	Page	Docket	Name	Page
50-22	Westinghouse Test Reactor	9	50-247	Indian Point Station, Unit 2	36
50-27	Washington State Univ. Research Reactor	9	50-249	Dresden Nuclear Power Station, Unit 3	41
50-29	Yankee-Rowe Nuclear Power Station	9	50-250	Turkey Point Plant, Unit 3	43
50-54	Union Carbide Research Reactor	12	50-251	Turkey Point Plant, Unit 4	45
50-57	State Univ. of New York Research Reactor	12	50-254	Quad-Cities Station, Unit 1	47
50-62	Univ. of Virginia Research Reactor	12	50-255	Palisades Nuclear Plant	49
50-70	General Electric Test Reactor	12	50-259	Browns Ferry Nuclear Power Station, Unit 1	51
50-72	Univ. of Utah Research Reactor	13	50-260	Browns Ferry Nuclear Power Station, Unit 2	54
50-83	Univ. of Florida Training Reactor	13	50-261	H. B. Robinson Plant, Unit 2	56
50-133	Humboldt Bay Power Plant, Unit 3	13	50-263	Monticelio Nuclear Generating Plant	58
50-142	UCLA Training Rector	13	50-264	Dow Chemical Co.	60
50-148	Univ. of Kansas Research Reactor	14	50-265	Quad-Cities Station, Unit 2	60
50-151	Univ. of Illinois Research Reactor	14	50-266	Point Beach Nuclear Plant, Unit 1	62
50-155	Big Rock Point Nuclear Plant	14	50-267	Fort St. Vrain Nuclear Generating Station	66
50-160	Georgia Institute of Technology Research Reactor	17	50-269	Oconee Nuclear Station, Unit 1	67
50-170	National Naval Medical Center	17	50-270	Oconee Nuclear Station, Unit 2	69
50-182	Purdue Univ. Research Reactor	18	50-271	Vermont Yankee Nuclear Power Station	71
50-184	National Bureau of Standards Reactor	18	50-272	Salem Nuclear Generating Station, Unit 1	73
50-186	Univ. of Missouri Research Reactor	18	50-275	Diablo Canyon Nuclear Power Plant, Unit 1	76
50-188	Kansas State Univ. Research Reactor	18	50-277	Peach Bottom Atomic Power Station, Unit 2	79
50-192	Univ. of Texas Research Reactor	18	50-278	Peach Bottom Atomic Power Station, Unit 3	81
50-199	Manhattan College Research Reactor	18	50-280	Surry Power Station, Unit 1	82
50-201	West Valley Reprocessing Plant	18	50-281	Surry Power Station, Unit 2	85
50-206	San Onofre Nuclear Station, Unit 1	19	50-282	Prairie Island Nuclear Station, Unit 1	87
50-208	Columbia Univ. Research Reactor	22	50-285	Fort Calhoun Station, Unit 1	89
50-213	Haddam Neck Plant	22	50-286	Indian Point Station, Unit 3	90
50-219	Oyster Creek Nuclear Power Plant	23	50-287	Oconee Nuclear Station, Unit 3	93
50-220	Nine Mile Point Nuclear Station, Unit 1	26	50-289	Three Mile Island Nuclear Station, Unit 1	96
50-223	Univ. of Lowell Research Reactor	28	50-293	Pilgrim Nuclear Power Station, Unit 1	101
50-228	Aerotest Radiography & Research Reactor	28	50-295	Zion Nuclear Power Station, Unit 1	102
50-237	Dresden Nuclear Power Station, Unit 2	28	50-296	Browns Ferry Nuclear Power Station, Unit 3	106
50-244	Robert Emmet Ginna Nuclear Plant, Unit 1	30	50-298	Cooper Nuclear Station	107
50-245	Millstone Nuclear Power Station, Unit 1	34	50-301	Point Beach Nuclear Plant, Unit 2	108

Docket	t	Name	Page	Docket	Name	Page
50	0-302	Crystal River Nuclear Plant, Unit 3	111	50-352	Limerick Generating Station, Unit 1	199
50	0-304	Zion Nuclear Power Station, Unit 2	113	50-353	Limerick Generating Station, Unit 2	201
50	D-30S	Kewaunee Nuclear Power Plant	116	50-354	Hope Creek Nuclear Station, Unit 1	203
50	0-306	Prairie Island Nuclear Station, Unit 2	118	50-355	Hope Creek Nuclear Station, Unit 2	204
50	0-309	Maine Yankee Atomic Power Plant	119	50-358	William H. Zimmer Nuclear Station, Unit 1	204
50	0-311	Salem Nuclear Generating Station, Unit 2	122	50-361	San Onofre Nuclear Station, Unit 2	206
50	0-312	Rancho Seco Nuclear Generating Station	126	50-362	San Onofre Nuclear Station, Unit 3	209
50	0-313	Arkansas Nuclear One, Unit 1	129	50-363	Forked River Nuclear Station, Unit 1	210
50	0-315	Donald C Cook Nuclear Power Plant, Unit 1	131	50-364	Joseph M. Farley Nuclear Plant, Unit 2	210
50	D-316	Donald C. Cook Nuclear Power Plant, Unit 2	134	50-366	Edwin I. Hatch Nuclear Plant, Unit 2	213
50	0-317	Calvert Cliffs Nuclear Power Plant, Unit 1	137	50-367	Bailly Generating Station	215
50	0-318	Calvert Cliffs Nuclear Power Plant, Unit 2	141	50-368	Arkansas Nuclear One, Unit 2	216
50	0-320	Three Mile Island Nuclear Station, Unit 2	144	50-369	William B. McGuire Nuclear Station, Unit 1	218
50	0-321	Edwin I. Hatch Nuclear Plant, Unit 1	146	50-370	William B. McGuire Nuclear Station, Unit 2	221
50	0-322	Shoreham Nuclear Power Station	148	50-373	LaSalle County Station, Unit 1	222
50	0-323	Diablo Canyon Nuclear Power Plant, Unit 2	152	50-374	LaSalle County Station, Unit 2	226
50	0-324	Brunswick Steam Electric Plant, Unit 2	154	50-382	Waterford Generating Station, Unit 3	228
50	D-325	Brunswick Steam Electric Plant, Unit 1	159	50-387	Susquehanna Steam Electric Station, Unit 1	230
50	0-327	Sequoyah Nuclear Plant, Unit 1	164	50-388	Susquehanna Steam Electric Station, Unit 2	234
50	D-328	Sequoyah Nuclear Plant, Unit 2	166	50-389	St. Lucie Plant, Unit 2	235
50	D-329	Midland Plant, Unit I	168	50-390	Watts Bar Nuclear Plant, Unit 1	238
50	0-330	Midland Plant, Unit 2	172	50-391	Watts Bar Nuclear Plant, Unit 2	241
50	0-331	Duane Arnold Energy Center	176	50-395	Virgil C. Summer Nuclear Station, Unit 1	244
50	0-333	James A. Fitzpatrick Nuclear Power Plant	178	50-397	WPPSS Nuclear Project, Unit 2	246
50	0-334	Beaver Valley Power Station, Unit 1	180	50-400	Shearon Harris Nuclear Power Plant, Unit I	248
50	0-335	St. Lucie Plant, Unit 1	182	50-401	Shearon Harris Nuclear Power Plant, Unit 2	251
50	0-336	Millstone Nuclear Power Station, Unit 2	184	50-402	Shearon Harris Nuclear Power Plant, Unit 3	254
50	0-338	North Anna Power Station, Unit 1	186	50-403	Shearon Harris Nuclear Power Plant, Unit 4	254
50)-339	North Anna Power Station, Unit 2	189	50-404	North Anna Power Station, Unit 3	254
50	0-341	Enrico Fermi Atomic Power Plant, Unit 2	192	50-405	North Anna Power Station, Unit 4	254
50	0-344	Trojan Nuclear Plant	194	50-409	La Crosse Boiling Water Reactor	255
50	0-346	Davis-Besse Nuclear Power Station, Unit 1	195	50-410	Nine Mile Point Nuclear Station, Unit 2	257
50	0-348	Joseph M. Farley Nuclear Plant, Unit 1	197	50-412	Beaver Valley Power Station, Unit 2	258

Docket	Name	Page	Docket	Name	Page
50-413	Catawba Nuclear Station, Unit 2	258	STN-50-485	Sterling Power Nuclear Project, Unit 1	303
50-414	Catawba Nuclear Station, Unit 2	261	STN-50-488	Perkins Nuclear Station, Unit 1	303
50-416	Grand Gulf Nuclear Station, Unit 1	263	STN-50-489	Perkins Nuclear Station, Unit 2	303
50-417	Grand Gulf Nuclear Station, Unit 2	267	STN-50-490	Perkins Nuclear Station, Unit 3	304
50-423	Millstone Nuclear Power Station, Unit 3	269	STN-50-491	Cherokee Nuclear Station, Unit 1	304
50-424	Alvin W. Vogtle Nuclear Plant, Unit 1	269	STN-50-492	Cherokee Nuclear Station, Unit 2	304
50-425	Alvin W. Vogtle Nuclear Plant, Unit 2	270	STN-50-493	Cherokee Nuclear Station, Unit 3	304
50-434	Surry Power Station, Unit 3	271	STN-50-498	South Texas Project, Unit 1	304
50-435	Surry Power Station, Unit 4	271	STN-50-499	South Texas Project, Unit 2	305
STN-50-437	Floating Nuclear Plant	271	STN-50-508	WPPSS Nuclear Project, Unit 3	306
50-438	Bellefonte Nuclear Plant, Unit i	271	STN-50-509	WPPSS Nuclear Project, Unit 5	307
50-439	Bellefonte Nuclear Plant, Unit 2	274	50-513	WPPSS Nuclear Project, Unit 4	307
50-440	Perry Nuclear Power Plant, Unit 1	276	50-514	Pebble Springs Nuclear Plant, Unit 1	307
50-441	Perry Nuclear Power Plant, Unit 2	280	50-515	Pebble Springs Nuclear Plant, Unit 2	307
50-443	Seabrook Nuclear Station, Unit 1	284	STN-50-518	Hartsville Nuclear Plant, Unit 1	307
50-444	Seabrook Nuclear Station, Unit 2	286	STN-50-519	Hartsville Nuclear Plant, Unit 2	308
50-445	Comanche Peak Steam Electric Station, Unit 1	287	STN-50-520	Hartsville Nuclear Plant, Unit 3	308
50-446	Comanche Peak Steam Electric Station,	289	STN-50-521	Hartsville Nuclear Plant, Unit 4	309
30-140	Unit 2	207	50-522	Skagit Nuclear Power Project, Unit 1	309
STN-50-447	GESSAR-238	290	50-523	Skagit Nuclear Power Project, Unit 2	310
STN-50-454	Byron Station, Unit 1	291	STN-50-528	Palo Verde Nuclear Station, Unit 1	311
STN-50-455	Byron Station, Unit 2	293	STN-50-529	Palo Verde Nuclear Station, Unit 2	314
STN-50-456	Braidwood Station, Unit 1	295	STN-50-530	Palo Verde Nuclear Station, Unit 3	316
STN-50-457	Braidwood Station, Unit 2	296	50-537	Clinch River Breeder Reactor	318
50-458	River Bend Station, Unit 1	297	STN-50-546	Marble Hill Nuclear Station, Unit 1	325
50-459	River Bend Station, Unit 2	298	STN-50-547	Marble Hill Nuclear Station, Unit 2	326
50-460	WPPSS Nuclear Project, Unit 1	298	STN-50-553	Phipps Bend Nuclear Station, Unit 1	326
50-461	Clinton Power Station, Unit 1	299	STN-50-554	Phipps Bend Nuclear Station, Unit 2	326
50-462	Clinton Power Station, Unit 2	301	STN-50-556	Black Fox Station, Unit 1	327
50-466	Allens Creek Nuclear Station, Unit 1	301	STN-50-557	Black Fox Station, Unit 2	327
STN-50-470	CESSAR System 80	301	STN-50-566	Yellow Creek Nuclear Plant, Unit 1	327
		301	STN-50-567	Yellow Creek Nuclear Plant, Unit 2	327
		302	STN-50-584	Gibbsar, Gibbs & Hill	328

Docket	Name	Page	Docket	Name	Page
Domestic Lice	nsing of Special Nuclear Material — Docket 70		70-2748	Scioto Memorial Hospital, Portsmouth, OH	334
70-0007	ICN Pharmaceuticals, Inc.,	***	70-2789	Missouri, Univ. of, Columbia, MO	334
	Irvine, CA	328	70-2792	Lower Bucks Hospital, Bristol, PA	334
70-0025	Rockwell International Corp., Canoga Park, CA	328	70-2873	Puerto Rico, Univ. of, Mayaguez, PR	334
70-0027	Babcock & Wilcox Co., Lynchburg, VA	328	70-2942	Harper-Grace Hospitals, Detroit, MI	334
70-0033	Texas Instruments, Inc., Attleboro, MA	328	70-2944	Duke Power Co., Charlotte, NC	334
70-0036	Combustion Engineering, Inc., Windsor, CT	329	70-2946	Louisiana Power & Light Co., New Orleans, LA	334
70-0135	Babcock & Wilcox Co., Apollo, PA	329	70-2949	Arizona Public Service Co., Phoenix, AZ	334
70-0143	Nuclear Fuel Services, Inc., Erwin, TN	329	70-2955	Edlow International Co., Washington, DC	334
70-0223	California, Univ. of, Los Angeles, CA	330	70-2957	Florida Power & Light Co., Miami, FL	334
70-0278	Dow Chemical Co., Midland, MI	330	70-2968	Cleveland Electric Illuminating Co.,	354
70-0364	Babcock & Wilcox Co., Apollo, PA	330		Cleveland, OH	335
70-0371	UNC Naval Products, Inc., Uncasville, CT	330	Packaging of R	adloactive Material for Transport and Transport	stion
70-0398	Commerce, Dept. of, Washington, DC	331	of Radioactiv	ve Material Under Certain Conditions — Docket	71
70-0416	Colorado State Univ., Ft. Collins, CO	331	71-0030	General Atomic Co.	335
70-0633	Pan American World Airways, Inc., Patrick AFB, FL	331	71-0481	Monroe X-Ray Co., Inc.	335
70-0687	Union Carbide Corp., Tuxedo, NY	331	71-5908	Model: DOT-6M Type B, Babcock & Wilcox Co.	335
70-0753	Wheaton College, Wheaton, IL	331	71-5926	Model: GE-100, General Electric Co.	335
70-0754	General Electric Co., Pleasanton, CA	331	71-5939	Model: GE-1500, General Electric Co.	335
70-0820	United Nuclear Corp.,		71-6115	Model: R1010-0032, Energy, Dept. of	335
	Wood River Junction, RI	331	71-6346	Model: FSV-1, General Atomic Co.	335
70-0824	Babcock & Wilcox Co., Lynchburg, VA	332	71-6347	Model: FSV-3, General Atomic Co.	335
70-1100	Combustion Engineering, Inc., Windsor, CT	332	71-6574	Model: HN-200, Hittman Nuclear &	
70-1113	General Electric Co., Wilmington, NC	332	71.7701	Development Corp.	
70-1143	Westinghouse Electric Corp., Pittsburgh, PA	332	71-6601	Model: CNS 8-120, Chem-Nuclear Systems, Inc.	333
70-1151	Westinghouse Electric Corp., Pittsburgh, PA	333	71-6639	Model: MH-1A, Army, Dept. of	335
70-1201	Babcock & Wilcox Co., Lynchburg, VA	333	71-6677	Model: LP-12, Energy, Dept. of	335
70-1257	Exxon Nuclear Co., Inc., Richland, WA	333	71-6678	Model: LP-50, Energy, Dept. of	336
70-1510	Nuclear Assurance Corp., Atlanta, GA	333	71-6698	Model: NFS-4, Nuclear Fuel Services, Inc.	336
70-1621	Duquesne Light Co., Pittsburgh, PA	333	71-6703	Model: RG-1, General Atomic Co.	336
70-1739	Tri-State Motor Transit Co., Joplin, MO	334	71-6745	Model: FSV-2, General Atomic Co.	336
70-2116	Lawrence General Hospital, Lawrence, MA	334	71-9001	Model: IF-300, General Electric Co.	336
70-2650	St. John's Mercy Medical Center, St. Louis, MO	334	71-9010	Model: NLI-1/2, NL Industries, Inc.	336

Docket	Name	Page	Docket	Name	Pag
71-9034	Model. TRIGA-I, General Atomic Co	336	71-9091	Model: 30A & 30B, Gulf Nuclear Co.	33
71-9037	Model TRIGA-2, General Atomic Co.	336	71-9094	Model: CNS 14-195-H, Chem-Nuclear Systems, Inc.	13
71-9044	Model. GE-1600, General Electric Co	336			
71-9057	Model: FPD-100, General Atomic Co	336	71-9096	Model: CNS 21-300, Chem-Nuclear Systems, Inc.	33
71-9079	Model. HN-100, Series 2 & 2A, Hittman Nuclear & Development Corp.	336	71-9098	Model: UCC-20WC-2 & 2A, Union Carbide Corp.	33
71-9080	Model: 9080, Hittman Nuclear & Development Corp.	336	71-9111	Model: CNS6-80-2, Chem-Nuclear Systems, Inc.	11
71-9081	Model. CNS-1600, Chem-Nuclear Systems, Inc.	336	71-9150	Model: PAT-2, Energy, Dept. of	11
71-9086	Model: HN-100, Series 1, Hittman Nuclear & Development Corp.	336	71-9151	Model: HN-100, Series 3, Hittman Nuclear & Development Corp.	31
71 2000		•	71-9167	Model: Type B, Amersham Corp.	33
71-9089	Model HN-100S, Hittman Nuclear & Development Corp.	337	71-9964	Model: LP-12-1, Energy, Dept. of	1.3

ALPHABETIC ARRANGEMENT OF DOCKET ITEMS BY FACILITY NAME

Name	Docket	Page	Name	Docket	Page
Low Level Radwaste Disposal Sites - Docket 2	7				
Barnwell, SC, Chem-Nuclear Systems, Inc.	27-047	1	Melapai Resources Co., Phoenix, AZ	40-8771	6
Beatty, NV, U.S. Ecology, Inc.	27-010	1	NL Industries, Inc., Niagara Falls, NY	40-1202	2
Richland, WA, U.S. Ecology, Inc.	27-048	1	Ogle Petroleum, Inc., Casper, WY	40-8745	6
Sheffield, IL, U.S. Ecology, Inc.	27-039	1	Pathfinder Mines Corp., Riverton, WY	40-2259	2
Domestic Licensing of Source Material - Dock	et 40		Pathfinder Mines Corp., Shirley Basin, WY	40-6622	3
Air Force, Dept. of, Vandenberg AFB, CA	40-8577	5	Plateau Resources, Ltd., Grand Junction, CO	40-8698	6
Allied Chemical Corp., Morristown, NJ	40-3392	2	Rio Algom Corp., Moab, UT	40-8084	4
Amax Environmental Services, Inc., Golden, Co	0 40-8820	7	Rocky Mountain Energy Co., Broomfield, CO	40-8380	4
Amax Speciality Metals Corp.,	10.0005		Rocky Mountain Energy Co., Denver, CO	40-8697	6
Parkersburg, WV	40-8355	4	Silver King Mines, Inc., Casper, WY	40-8602	5
Army, Dept. of, Chambersburg, PA	40-8632	5	Stepan Chemical Co., Maywood, NJ	40-8610	5
Atlas Mineral, Inc., Denver, CO	40-3453	2	Target Research, Inc., Wharton, NJ	40-8824	7
Bear Creek Uranium Co., Casper, WY	40-8452	4	Tennessee Valley Authority, Chattanooga, TN	40-1341	2
Cleveland-Cliffs Iron Co., Cleveland, OH	40-8714	6	Teton Exploration Drilling Co., Inc.,		
Conoco, Inc., Denver, CO	40-8743	6	Casper, WY	40-8728	6
Conoco, Inc., Denver, CO	40-8793	7	Teton Exploration Drilling Co., Inc., Casper, WY	40-8781	6
Dow Chemical Co., Midland, M1	40-0017	1	Union Carbide Corp., Grand Junction, CO	40-0299	1
Energy Fuels Nuclear, Inc., Denver, CO	40-8681	5	Uranium Resources, Inc., Richardson, TX	40-8786	7
Exxon Co. USA, Houston, TX	40-8102	4	Western Nuclear Corp., Jeffrey City, WY	40-1162	2
Fansteel, Inc., North Chicago, IL	40-7580	3	Wyoming Mineral Corp., Lakewood, CO	40-8502	5
Getty Oil Co. — Petrotomics Co., Shirley Basin, WY	40-6659	3	Domestic Licensing of Production and Utilizati		•
Kennecott Copper Corp., Salt Lake City, UT	40-8111	4	Docket 50		
Kerr-McGee Chemical Corp.,	,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	•	Aerotest Radiography & Research Reactor	50-228	28
Oklahoma City, OK	40-2061	2	Allens Creek Nuclear Station, Unit 1	50-466	301
Kerr-McGee Nuclear Corp., Oklahoma City, Ol	K 40-8027	3	Alvin W. Vogtle Nuclear Plant, Unit 1	50-424	269
Kerr-McGee Nuclear Corp., Oklahoma City, Ol	K 40-8768	6	Alvin W. Vogtle Nuclear Plant, Unit 2	50-425	270
Lebanon Steel Foundry, Lebanon, PA	40-8153	4	Arkansas Nuclear One, Unit 1	50-313	129

Name	Docket	Page	Name	Docket	Page
Arkansas Nuclear One, Unit 2	50-368	216	Comanche Peak Steam Electric Station, Unit 1	50-445	287
Babcock & Wilcox Co. Critical Facility	50-13	9	Comanche Peak Steam Electric Station, Unit 2	50-446	289
Bailly Generating Station	50-367	215	Cooper Nuclear Station	50-298	107
Beaver Valley Power Station, Unit 1	50-334	180	Crystal River Nuclear Plant, Unit 3	50-302	111
Beaver Valley Power Station, Unit 2	50-412	258	Davis-Besse Nuclear Power Station, Unit 1	50-346	195
Bellefonte Nuclear Plant, Unit 1	50-438	271	Diablo Canyon Nuclear Power Plant, Unit I	50-275	76
Bellefonte Nuclear Plant, Unit 2	50-439	274	Diablo Canyon Nuclear Power Plant, Unit 2	50-323	152
Big Rock Point Nuclear Plant	50-155	14	Donald C. Cook Nuclear Power Plant, Unit 1	50-315	13 i
Black Fox Station, Unit 1	STN-50-556	327	Donald C. Cook Nuclear Power Plant, Unit 2	50-316	134
Black Fox Station, Unit 2	STN-50-557	327	Dow Chemical Co.	50-264	60
Braidwood Station, Unit 1	STN-50-456	295	Dresden Nuclear Power Station, Unit 1	50-10	8
Braidwood Station, Unit 2	STN-50-457	296	Dresden Nuclear Power Station, Unit 2	50-237	28
Browns Ferry Nuclear Power Station, Unit 1	50-259	51	Dresden Nuclear Power Station, Unit 3	50-249	41
Browns Ferry Nuclear Power Station, Unit 2	50-260	54	Duane Arnold Energy Center	50-331	176
Browns Ferry Nuclear Power Station, Unit 3	50-296	106	Edwin I. Hatch Nuclear Plant, Unit I	50-321	146
Brunswick Steam Electric Plant, Unit 1	50-325	159	Edwin I. Hatch Nuclear Plant, Unit 2	50-366	213
Brunswick Steam Electric Plant, Unit 2	50-324	154	Enrico Fermi Atomic Power Plant, Unit 2	50-341	192
Byron Station, Unit I	STN-50-454	291	Floating Nuclear Plant	STN-50-437	271
Byron Station, Unit 2	STN-50-455	293	Forked River Nuclear Station, Unit 1	50-363	210
Callaway Plant, Unit 1	STN-50-483	302	Fort Calhoun Station, Unit 1	50-285	89
Calvert Cliffs Nuclear Power Plant, Unit 1	50-317	137	Fort St. Vrain Nuclear Generating Station	50-267	66
Calvert Cliffs Nuclear Power Plant, Unit 2	50-318	141	General Electric Test Reactor	50-70	12
Catawba Nuclear Station, Unit 1	50-413	258	Georgia Institute of Technology Research		
Catawba Nuclear Station, Unit 2	50-414	261	Reactor	50-160	17
stem 80	STN-50-470	สกา	GESSAR-238	STN-50-447	290
			Gibbsar, Gibbs & Hill	STN-50-584	328
			Grand Gulf Nuclear Station, Unit 1	50-416	263
			Grand Gulf Nuclear Station, Unit 2	50-417	267
			H. B. Robinson Plant, Unit 2	50-261	56
			Haddam Neck Plant	50-213	22
			Hartsville Nuclear Plant, Unit 1	STN-50-518	307
			Hartsville Nuclear Plant, Unit 2	STN-50-519	308

308 309 203 204 13 7 36	Nine Mile Point Nuclear Station, Unit 1 Nine Mile Point Nuclear Station, Unit 2 North Anna Power Station, Unit 1 North Anna Power Station, Unit 2 North Anna Power Station, Unit 3	50-220 50-410 50-338 50-339	26 257 186 189
203 204 13	North Anna Power Station, Unit 1 North Anna Power Station, Unit 2 North Anna Power Station, Unit 3	50-338 50-339	186
204 13 7	North Anna Power Station, Unit 2 North Anna Power Station, Unit 3	50-339	
13 7	North Anna Power Station, Unit 3		189
7			
	Month Asses Dames Station Timber	50-404	254
36	North Anna Power Station, Unit 4	50-405	254
	Oconee Nuclear Station, Unit 1	50-269	67
90	Oconee Nuclear Station, Unit 2	50-270	69
178	Oconee Nuclear Station, Unit 3	50-287	93
197	Oyster Creek Nuclear Power Plant	50-219	23
210	Palisades Nuclear Plant	50-255	49
18	Palo Verde Nuclear Station, Unit 1	STN-50-528	311
116	Palo Verde Nuclear Station, Unit 2	STN-50-529	314
255	Palo Verde Nuclear Station, Unit 3	STN-50-530	31
222	Peach Bottom Atomic Power Station, Unit 2	50-277	7
226	Peach Bottom Atomic Power Station, Unit 3	50-278	8
199	Pebble Springs Nuclear Plant, Unit 1	50-514	30
201	Pebble Springs Nuclear Plant, Unit 2	50-515	30
119	Perkins Nuclear Station, Unit 1	STN-50-488	30
18	Perkins Nuclear Station, Unit 2	STN-50-489	30
325	Perkins Nuclear Station, Unit 3	STN-50-490	30
326	Perry Nuclear Power Plant, Unit 1	50-440	27
	Perry Nuclear Power Plant, Unit 2	50-441	28
9	Phipps Bend Nuclear Station, Unit 1	STN-50-553	32
168	Phipps Bend Nuclear Station, Unit 2	STN-50-554	32
172	Pilgrim Nuclear Power Station, Unit 1	50-293	10
34	Point Beach Nuclear Plant, Unit I	50-266	
184	Point Beach Nuclear Plant, Unit 2	50-301	10
		50-282	
			11
	269 58 18 17	Prairie Island Nuclear Station, Unit 1 Prairie Island Nuclear Station, Unit 2	Prairie Island Nuclear Station, Unit 1 50-282 Prairie Island Nuclear Station, Unit 2 50-306

Name	Docket	Page	Name	Docket	Page
Quad-Cities Station, Unit I	50-254	47	Susquehanna Steam Electric Station, Unit 1	50-387	230
Quad-Cities Station, Unit 2	50-265	60	Susquehanna Steam Electric Station, Unit 2	50-388	234
Rancho Seco Nuclear Generating Station	50-312	126	Three Mile Island Nuclear Station, Unit 1	50-289	96
River Bend Station, Unit 1	50-458	297	Three Mile Island Nuclear Station, Unit 2	50-320	144
River Bend Station, Unit 2	50-459	298	Trojan Nuclear Plant	50-344	194
Robert Emmet Ginna Nuclear Plant, Unit 1	50-244	30	Turkey Point Plant, Unit 3	50-250	43
Salem Nuclear Generating Station, Unit 1	50-272	73	Turkey Point Plant, Unit 4	50-251	45
Salem Nuclear Generating Station, Unit 2	50-311	122	UCLA Training Reactor	50-142	13
San Onofre Nuclear Station, Unit 1	50-206	19	Union Carbide Research Reactor	50-54	12
San Onofre Nuclear Station, Unit 2	50-361	206	Univ. of Florida Training Reactor	50-83	13
San Onofre Nuclear Station, Unit 3	50-362	209	Univ. of Illinois Research Reactor	50-151	14
Seabrook Nuclear Station, Unit 1	50-443	284	Univ. of Kansas Research Reactor	50-148	14
Seabrook Nuclear Station, Unit 2	50-444	286	Univ. of Lowell Research Reactor	50-223	28
Sequoyah Nuclear Plant, Unit 1	50-327	164	Univ. of Missouri Research Reactor	50-186	18
Sequoyah Nuclear Plant, Unit 2	50-328	166	Univ. of Texas Research Reactor	50-192	18
Shearon Harris Nuclear Power Plant, Unit 1	50-400	248	Univ. of Utah Research Reactor	50-72	13
Shearon Harris Nuclear Power Plant, Unit 2	50-401	251	Univ. of Virginia Research Reactor	50-62	12
Shearon Harris Nuclear Power Plant, Unit 3	50-402	254	Vermont Yankee Nuclear Power Station	50-271	71
Shearon Harris Nuclear Power Plant, Unit 4	50-403	254	Virgil C. Summer Nuclear Station, Unit 1	50-395	244
Shoreham Nuclear Power Station	50-322	148	Washington State Univ. Research Reactor	50-27	9
Skagit Nuclear Power Project, Unit 1	50-522	309	Waterford Generating Station, Unit 3	50-382	228
Skagit Nuclear Power Project, Unit 2	50-523	310	Watts Bar Nuclear Plant, Unit 1	50-390	238
South Texas Project, Unit 1	STN-50-498	304	Watts Bar Nuclear Plant, Unit 2	50-391	241
South Texas Project, Unit 2	STN-50-499	305	West Valley Reprocessing Plant	50-201	18
plant, Unit 1	50-335	182	Westinghouse Test Reactor	50-22	9
Init 2	50-389	235	William B. McGuire Nuclear Station, Unit 1	50-369	218
	ኖስ ደግ	12	William B. McGuire Nuclear Station, Unit 2	50-370	221
		303	William H. Zimmer Nuclear Station, Unit 1	50-358	204
		82	Wolf Creek Generating Station	STN-50-482	301

	Deskar	Dana	Namo	Docket	Page
Name	Docket	Page	Name Louisiana Power & Light Co., New Orleans, LA	70-2946	334
WPPSS Nuclear Project, Unit 4	50-513	307	Lower Bucks Hospital, Bristol, PA	70-2792	334
WPPSS Nuclear Project, Unit 5	STN-50-509	307		70-2789	334
Yankee-Rowe Nuclear Power Station	50-29	9	Missouri, Univ. of, Columbia, MO		
Yellow Creek Nuclear Plant, Unit 1	STN-50-566	327	Nuclear Assurance Corp., Atlanta, GA	70-1510	333
Yellow Creek Nuclear Plant, Unit 2	STN-50-567	327	Nuclear Fuel Services, Inc., Erwin, TN	70-0143	329
Zion Nuclear Power Station, Unit I	50-295	102	Pan American World Airways, Inc., Patrick AFB, FL	70-0633	331
Zion Nuclear Power Station, Unit 2	50-304	113	Puerto Rico, Univ. of, Mayaguez, PR	70-2873	334
Domestic Licensing of Special Nuclear Materi	al — Docket 70		Rockwell International Corp., Canoga Park, CA	70-0025	328
Arizona Public Service Co., Phoenix, AZ	70-2949	334	Scioto Memorial Hospital, Portsmouth, OH	70-2748	334
Babcock & Wilcox Co., Apollo, PA	70-0135	329	St. John's Mercy Medical Center, St. Louis, MO	70-2650	334
Babcock & Wilcox Co., Apollo, PA	70-0364	330	Texas Instruments, Inc., Attleboro, MA	70-0033	328
Babcock & Wilcox Co., Lynchburg, VA	70-0027	328	Tri-State Motor Transit Co., Joplin, MO	70-1739	334
Babcock & Wilcox Co., Lynchburg, VA	70-0824	332	UNC Naval Products, Inc., Uncasville, CT	70-0371	330
Babcock & Wilcox Co., Lynchburg, VA	70-1201	333	Union Carbide Corp., Tuxedo, NY	70-0687	331
California, Univ. of, Los Angeles, CA	70-0223	330	United Nuclear Corp., Wood River Junction, RI	70-0820	331
Cleveland Electric Illuminating Co., Cleveland, OH	70-2968	335	Westinghouse Electric Corp., Pittsburgh, PA	70-1143	332
Colorado State Univ., Ft. Collins, CO	70-0416	331	Westinghouse Electric Corp., Pittsburgh, PA	70-1151	333
Combustion Engineering, Inc., Windsor, CT	70-0036	329	Wheaton College, Wheaton, IL	70-0753	331
Combustion Engineering, Inc., Windsor, CT	70-1100	332	Peckaging of Padinactive Material for Transport and Transportation		
Commerce, Dept. of, Washington, DC	70-0398	331	General Atomic Co.	71-0030	335
Dow Chemical Co., Midland, MI	70-0278	330	Model: 30A & 30B, Gulf Nuclear Co.	71-9091	337
Duke Power Co., Charlotte, NC	70-2944	334	Model: 9080, Hittman Nuclear & Development		
Duquesne Light Co., Pittsburgh, PA	70-1621	333	Corp.	71-9080	336
Edlow International Co., Washington, DC	70-2955	3 334	Model: CNS 14-195-H, Chem-Nuclear Systems, Inc.	71-9094	337
Exxon Nuclear Co., Inc., Richland, WA	70-1257	333	Model: CNS 21-300, Chem-Nuclear Systems,		
Florida Power & Light Co., Miami, FL	70-2957	334	Inc.	71-9096	337
General Electric Co., Pleasanton, CA	70-0754	331	Model: CNS 8-120, Chem-Nuclear Systems, Inc.	71-6601	335
General Electric Co., Wilmington, NC	70-1113	332	Model: CNS-1600, Chem-Nuclear Systems, Inc.	71-9081	336
Harper-Grace Hospitals, Detroit, MI	70-2942	334	Model: CNS6-80-2, Chem-Nuclear Systems, Inc.	71-9111	337
ICN Pharmaceuticals, Inc., Irvine, CA	70-0007	7 328	Model: DOT-6M Type B, Babcock & Wilcox		
Lawrence General Hospital, Lawrence, MA	70-2116	334	Co.	71-5908	335

Name	Docket	Page	Name	Docket	Page
Model: FPD-100, General Atomic Co.	71-9057	336	Model: LP-12, Energy, Dept. of	71-6677	335
Model: FSV-1, General Atomic Co.	71-6346	335	Model: LP-12-1, Energy, Dept. of	71-9964	337
Model: FSV-2, General Atomic Co.	71-6745	336	Model: LP-50, Energy, Dept. of	71-6678	336
Model: FSV-3, General Atomic Co.	71-6347	335	Model: MH-1A, Army, Dept. of	71-6639	335
Model: GE-100, General Electric Co.	71-5926	335	Model: NFS-4, Nuclear Fuel Services, Inc.	71-6698	336
Model: GE-1500, General Electric Co.	71-5939	335	Model: NLI-1/2, NL Industries, Inc.	71-9010	336 '
Model. GE-1600, General Electric Co.	71-9044	336	Model: PAT-2, Energy, Dept. of	71-9150	337
Model: HN-100, Series 1, Hittman Nuclear of Development Corp.	& 71-9086	336	Model: R1010-0032, Energy, Dept. of	71-6115	335
Model: HN-100, Series 2, 2A, Hittman Nuclea & Development Corp.	ar 71-9079	336	Model: RG-1, General Atomic Co.	71-6703	336
Model. HN-100, Series 3, Hittman Nuclear & Development Corp.			Model: TRIGA-1, General Atomic Co.	71-9034	336 -
	71-9151	337	Model: TRIGA-2, General Atomic Co.	71-9037	336
Model: HN-100S, Hittman Nuclear & Development Corp.	71-9089	337	Model: Type B, Amersham Corp.	71-9167	337
Model: HN-200, Hittman Nuclear & Development Corp.	71-6574	335	Model: UCC-20WC-2 & 2A, Union Carbide Corp.	71-9098	337
Model: 1F-300, General Electric Co.	71-9001	336	Monroe: X-Ray Co., Inc.	71-0481	335

DOCKETED ITEMS

LOW LEVEL RADWASTE DISPOSAL SITES

DOCKET 27-010 BEATTY, NV. U S ECOLOGY, INC.

210260304 PND-V-B2 044 on B21012, shipment of low level radwaste received from GE Vallecttos Nuclear Ctr containing box w/hole in side Administrative penalty of \$1500 levied Permit suspended indefinitely
FMDMAS.R D Region 5. Orfice of Director B2/10/19 1p

DOCKET 27-039 SHEFFIELD, IL. U.S. ECOLOGY, INC.

- 8210120320 Summary of 820908 steering committee meeting w/1DNS, State of IL USGS & US Ecology to discuss results of Phaso II portion or traitum migration study & to determine need for Phase II investigations Exhibits encl SIEFKEM, D.L. Low Level Waste Licensing Branch 82/09/20 HARKKINS, E.F. Low Level Waste Licensing Branch 6pp 156B9 236
- 62(012041) Notification of contract elecution, Mod 5 to "Sheffield Trench Cap Study " Contractor Univ of IL FLEENDR.C M Technical Assistance Contracts Branch FIN 8-6965-2 82/07/28 DAVIS J. SIEFREN, D Office of Nuclear Material Safety & Safeguards, Director 1p 15691 167
- --8210120419 Mod 5 revising task repts delivery schedule, increasing estimated cost revising voucher submittal & substituting updated Manual Chapter 3202, to "Sheffield Trench Cap Study "PORTER.F W Illinois, Univ of, Urbana-Champaign HAQAN,T F Division of Contracts FN 8-6945-2 82/09/28 4pp 15691148
- 62(0050095 Joint motion to continue proceedings until 830201 to provide add) time for settlement negotiations Certificate of S.c enct
 LESSY,R P Hearing Branch 3 WETTERHAIN,M J US Ecology,
 Inc (Formerly Nuclear Engineering) 62/10/01 Atomic Gafety and Licensing Board Panel 3pp 15604 236
- 8210080075 Order granting NRC & applicant joint motion to continue proceedings until 830201 COODHOPE, A C Atomic Safety and Licensing Board Panel 82/10/06 Office of the Executive Legal Director ip 15643 267

DOCKET 27-047 BARNWELL, SC. CHEM-NUCLEAR SYSTEMS, INC.

- R210120135 Consents to transfer of Licenses 46-13536-01 & 46-19524-01 rom Chem-Nuclear Bys.Inc to WMI Holdings.Inc All existing obligations to responsibilities under current license will be applicable to & binding upon subsidiary DAVIS.J 0 Office of Nuclear Material Safety & Gafeguards.Director 82/09/07 HUIZENGA.P Waste Management. Inc 2pp 15692-167
- E210120144 Confirms 820910 arrangements for J Davis 820921 site visit prior to attending 820923-24 meetings in Atlanta.GA PANOBURN.G C Low Level Waste Licensing Branch 82/09/13 PURVIS.J Chem-Nuclear Bystems. Inc. ip 1869
- 82(0120465 Trip rept of 820701-02 visit to Columbia, 8C to attend State of SC hearings on qualifications of Haste Mg6, Inc to conduct radioactive matls operations under licenses currently held by Chem-Nuclear, Inc PANOBURN, 0 C Low Level Haste Licensing Branch 82/07/17 HAWKINS.E F Low Level Haste Licensing Branch 4pp 18671 306

DOCKET 27-048 RICHLAND, WA, U.S. ECGLOGY, INC.

6210130130 PND-V-82-040 on 821004 notified that shipment of low level radwaste received on 820927 from Emith Kline & French Labs was in violation of DDT regulations 49CFR173 393(d) & 172 403(b) Vendor license suspended effective 820928 THCMAS:R D Region 5. Office of Director 82/10/05 (p. 15673 039)

DOMESTIC LICENSING OF SOURCE MATERIAL

DOCKET 40-0017 DOW CHEMICAL CO . MIDLAND. MI

- 821018002B Responds to FOIA request for seven categories of documents re Dow Chemical Co & incineration of low level radwasts Request for fee waiver granted Forwards listed documents FELTON, J M Division of Rules and Records 82/08/20 WILGON, A K Affiliation Unknown 2pp 1574B 002 24X Fiche 50-264.82/08/20, 821018002B
- --8210180239 Application for renewal of Mat1/Byproduct Licenses 21-00265-04.21-00265-02.21-00265-04.21-00265-07.6NM-1293. STB-527 & R-10B authorizing any byproduct mat1 between Atomic Numbers 3 & 83.tiltium.Pa-210 & Am-241 HDYLE.H R Dow Chomical Co 73/06/25 2pp 15748 115 24X Fiche 50-264.82/08/20.8210180028
- DOCKET 40-0299 UNION CARBIDE CORP , GRAND JUNCTION, CO
- 8210250019 Forwards "Investigation of Elevated Radioactivity Measurements Around Union Carbide Corp Inactive Tailings Area in Gas Hills.HY." per License Amend 10 WONG.T Union Carbide Corp 82/0//30 PETTENGILL,H Uranium Recovery Licensing Branch 1p 19808 260
- --8210250021 "Investigation of Elevated Radioactivity Measurements Around Union Carbide Corp Inactive Tailings Area in Cas Hills, HY " * Union Carbide Corp 82/07/30 10pp 15308 26i
- 8210190246 Forwards "Sepiannual ALARA Rept. Jan-June 1982," per License Condition 17 WONG. T Union Carbide Corp 82/09/03 LYON3. P. J. Uranium Recovery Licensing Branch tp 15759 001
- --8210190256 "Semiannual ALARA Rept. Jan-June 1982 " One oversize map encl Aperture card is available in PDR 4 Union Carbide Corp 82/09/03 531pp 15759 003
- 8210130607 Requests written declaration of intent or interest in two listed tallings situations resulting in pollution & contamination of groundwaters of State of WY FRANCIS.E Wyoming, State of 82/09/07 LINEHAN.J Uranium Recovery Licensing Branch 3pp 13692 335
- 8210220491 Forwards revised lower limits of detection for Ra-226 & Th-230 in water LYONS, P J Union Carbide Corp 82/09/22 PETTENOILL, H Division of Fuel Cycle & Material Safety 2pp 15786 321
- 8210210530 Requests detailed breakdown of revised reclamation cost estimate in order to complete evaluation of 820804 submittal Info should be provided by 821030 PETTENGILL.H J Uranium Recovery Licensing Branch 82/09/30 LYONG.P Union Carbide Corp 2pp 15782 323

- DOCKET 40-1162 WESTERN NUCLEAR CORP , JEFFREY CITY, HY
- 8210220123 Forwards IE Insp Rept 40-1162/82-02 on 820901 No noncompliance noted EROWI 0 0 Olvision of Vendor & Technical Programs 82/09/28 WELLER, T Hestern Nuclear, Inc (subs of Phelps Dodge Corp) 2pp 15778 141
- --B21022012B IE Insp Rept 40-1162/82-02 on B20901 No noncompliance noted flajor areas inspected U mill waste mgt activities SHQPENNIN H , CAIN.C L , EVERETT,R J Division of Vendor & Technical Programs B2/09/21 4pp 15778 143
- 8210220475 Submits review of Split Rock Hill 820630 annual technical evaluation of performance of tailings embankment Embankment performed as sipected No further action necessary GARCIA.P.J. Uranium Recovery Licensing Branch 82/10/05 Uranium Recovery Licensing Branch 2pp 15786-323
- DUCKET 40-1202 NL INDUSTRIES, INC , MIAGARA FALLS, NY
- 82:00:04:18 Forwards IE Insp Rept 40-1202/82-01 Inquiry conducted to determine whether formerly licensed site meets current criteria for release for unrestricted use kINNEMAN.J D Division of Engineering & Technical Programs 82/09/23 JACOBS.J L NL Industries. Inc. 2pp. 15570-217
- --8210010428 IE Insp Rept 40-1202/82-01 on B20595-0702 Inquiry conducted to determine whether formerly licensed site meets current criteria for release for unrestricted use Site meets criteria undansen. J H , KINNEMAN. J H Region 1, Office of Director 62/08/02 3pp 15570 219
- ---8210010434 Forwards "Summary of Radiological Survey of NL Industries Riagare Falls Plant," final rept JACOBS. J. L. Industries: Inc. 62/06/24 JOHANSEN, J. Region f. Office of Director 2pp 13570 222
- --8210010440 "Summary of Radiological Survey of NL Industries Niagara Falls Plant:" final rept LEIGH,D W NL Industries, Inc. 79/05/31 129pp 15570 224
- DOCKET 40-1341 TENNESSEE VALLEY AUTHORITY, CHATTANOOGA, IN
- 8210050422 FINAL ENVIRONKENTAL STATEMENT RELATED TO THE DECOMMISSIONING OF EDGEMONT URANIUM MILL Doctat No 40-1941 (Tennessee Valley Authority)

 9 Office of Nuclear Material Bafety & Safequards Director Nurec-0846 82/06/30 320pp Available at NRC \$9.00 15623 074
- DOCKET 40-2061 KERR-MCGEE CHEHICAL CORP , DKLAHOMA CITY, OK
- 8210270077 Forwards fee for 820806 application to amend License STA-583 to allow dismantling of Bldgs 2.10.11 & 21 SHELLEY, W J Kerr-McGee Corp 82/09/14 WEISS, D License Fee Management Branch 1p 15836 214
- --B21027008B Application for amend to License STA-583 to allow dismantling of Bldgs 2.10.11 t 21
 SMELLEY, W J Merr-Higee Corp B2/08/06 NIXON, W A Uranium Fuel Licensing Branch 2pp 15836 216
- --0210270091 Requests payment of amend fee, needed to process 620806 application for amend to License STA-583 to allow dismantling of 8165 2.10.11 & 21
 WEISS.D License Fee Management Branch 82/09/01 SHELLEY, W J
 Kerr-HcGee Corp ip 15836 215
- BRIO120187 Order designating IMSS Deputy Director to act as presiding officer to conduct hearing on Amend 5 Certificate of Svc and DAVIS.J O Office of Nuclear Material Safety & Safeguards, Director B2/10/05 Office of Nuclear Material Safety & Safeguards, Director 2pp 13631 235
- 8210150463 Requests info on hearing to be held per Commission 820806 Order CLI-82-21 Response should define rules for procedure, discovery & subposines & should establish schedule SPELMAN.H.J. Harold J. Spelman & Associates 82/10/12 HOYLE.J.C. Office of the Secretary of the Commission 10 15703 104

- 82(0280434 Responds to 920706 ltr commenting on DES se decommissioning of Kerr-McGee Rare Earths facility Final statement will recognize site as alternative storage/disposal site for other residues in Nest Chicago. IL CUNNINGHAMR E Division of Fuel Cycle & Moterial Bafety 83//10/15 CAMILLP C Environmental Protection Agency 2pp (5860 045
- 8210250315 Response to Kerr-McGee 820923 request for consolidation of License Amend & w/License Amend 5 for hearing purposes City does not object 5vc list encl SPELMAIN J West Chicago, IL SPELMAN, H J Harold J Spelman & Associates 82/10/22 Commissioners 3pp 15790 221
- DOCKET 40-2259 PATHFINDER MINES CORP , RIVERTON, WY
- 8210270054 Trip rept of 820826 site visit to templete annual insp FRANCIS,E , KEARNEY, B Pathfinder Mines Corp 82/08/26 Pathfinder Mines Corp 2pp 15836 lfi
- 82(0150607 Forwards "Quarterly Effluent Monitoring Rept.Apr June 1982." per License Conditions 51 & 54 NUGEHT.E L Pathfinder Mines Corp 82/08/31 5CARAND, R.A. Uranium Recovery Licensing Branch 1p 15715 320
- --8210150613 "Quarterly Efrivent Monitoring Rept. Apr-June 1982" " The eversite map encl Aperture card is available in PBR * Pathfinder Mines Corp 82/08/31 13pp 15715 321
- 8210130607 Requests written declaration of intent or interest in two listed tailings situations resulting in pollution to contamination of groundwaters of State of My FRANCIS.E Myoming State of 82/09/07 LINCHAN. Uranium Recovery Licensing Branch 3pp 15692 335
- 8210120514 Advises that equipment cost analysis tailings pend reclamation bond analysis & reclamation bend summary consistent w/approved reclamation plan for Pathfinder Lucky Mc Hill tailings pend SOLLENSERGER, D. PETTENOILL, H. J. Uranium Recovery Licensing Hiench 82/09/20 Uranium Recovery Licensing Branch 3pp 15672 072
- 9210220161 Forwards IE Insp Rept 40-2259/82-01 on 820727-29 & notice of violation BROWN, 0 D Division of Vendor & Technical Programs 82/09/27 NUGENT, EL Pathfinder Mines Corp 2pp 15778 098
- ~-8210220165 Natice of violation from insp on 820727-29 * Division of Vendor & Technical Programs 82/09/27 in 15778 060
- --8210220171 IE Insp Rept 40:2259/82-01 on B20727-29 Noncompliance duted failure of personnel to shower or monitor for contamination prior to leaving mill restricted area MHITTEM J. DROWN, R. C. EVERETT.R. J. Division of Vendor & Technical Programs 82/09/17 lipp 15778 061
- DOCKET 40-3392 ALLIED CHEMICAL CORP , MORRISTOWN, NJ
- 8210150600 informs that drawings in 920701 application for renewal of License SUB-326 are not proprietary CIPOLLA:A J Allied Chemical Corp 82709/17 PAGE,R O Uranium Fuel Licensing Branch ip 15716-336
- DOCKET 40-9459 ATLAS MINERAL, INC . DENVER. CO
- 8210260079 Forwards second quarter 1982 quarterly rept re sampling & analysis results of environ monitoring program per License Conditions 42,43 & 47 EDNARDS, D.L. Atlas Minerals 82/08/18 SCARAND, R.A. Uranium Recovery Licensing Branch 2pp 19810 257
- ---8210260080 Second quarter 1982 sampling analysis results of environ manitoring program • Atlas Minerals 82/08/18 70pp 15810 259
- 8210150596 Responds to NRC 820728 ltr requesting proposed site for relocation of background station used to monitor environ air quality Tables re wind direction chemical concentration & resident stposure enci.

 BLUBAUOH, R.E. Atlas Minerale.

- 8210210021 Reviews first quarter 1982 environ monitoring data & dose calculations for nearest receptor required by License Condition 47 Compliance w/40CFR190 stds will be determined when new site becomes operational LARCIA.P.J. PETTENGILL.H.J. Uranium Recovery Licensing Branch B2/09/20 Uranium Recovery Licensing Branch 4pp 15782 214
- 8210210521 Issues Amend 10 to License SUA-917 in response to 811204 request & revised by 820428 itr Amend adds Condition 54 delineating line of authority between radiation safety coordinator & ensite individual SMITA,R D Uranium Recovery Licensing Branch 82/09/30 Atlas Minerals 2pp 15782 311
- 8210210525 Recommends issuance of Amend 10 to License SUA-917 in response to 811204 request & revised by 820428 ltr Amend adds Condition 54 delineating line of authority between radiation safety officer & onsite individual GARCIA-P J , PETTEMSFLL-H J Uranium Recovery Licensing Branch 82/07/30 Uranium Recovery Licensing Branch 59p 15782 313
- DOCKET 40-6622 PATHFINDER MINES CORP . SHIRLEY BASIN. WY
- OC10250028 Forwards State of WY 820721 request for info re tailings seepage & 820727 response RUSSELL J E Pathfinder Mines Corp 82/07/29 PETTENGILL/H NRC No Detailed Affiliation Given 5pp 15798 343
- 82(015060) Forwards one oversize revised topographic map per License Condition 41 Aperture card is available in PDR SMITH, J C Pathfinder Mines Corp 82/08/06 Uranium Recovery Licensing Branch Ip 15715 335
- ECIO180415 Forwards "Subsurface Migration Update & Answers to NRC Questions" MRRDOZIES Pathfinder Mines Corp 82/08/06 SDLLENBERGER, D Utanium Recovery Licensing Branch (p. 15747-220
- --8210183420 "Subsurface Migration Update & Answers to NRC Questions " Eight oversize drawings enc! Aperture cards are available in PDR (JRBQCK, E.S., SMITH, J.C. Pathfinder Mines Corp. 82/03/31 /4pp 15747 221
- B_E 10070383 Forwards IE Insp Rept 40-6622/82-02 on 820713-16 & notice or violation SRCMLA D Division of Vendor & Technical Programs 82/08/13 PUSSELL J E Pathfinder Mines Corp 2pp 15633 318
- -8210070385 Notice of violation from insp on 820713-16

 Division of Vendor & Technical Programs 82/08/13 2pp
 15637 320
- --8210070374 IE Insp Rept 40-6622/82-02 on 820713-16 Noncompliance noted on 820715.audible alarm setpoint on survey instrument adjusted to level exceeding acceptable limit CAIN.C.L. MURRAY.B. EVERETT.R.J. Division of Vendor & Technical Programs 82/08/10 7pp 15633 322
- 82:0260013 Forwards revised environ QA program,per Amend 7 to License SWA-442 SMITH.J C Pathfinder Mines Corp 82/08/30 Uranium Recovery Licensing Branch 1p 15814 160
- ---8210260014 Revised environ QA program

 + Pathfinder Mines Corp 82/08/31 92pp 15814 161
- 8210290177 Forwards stability review for Number 5 embankment per Condition 42 of Amend 8 to License SUA-442 Rept gives strong evidence that Number 5 embankment functioning according to design features RUSSELL, J E Pathfinder Mines Corp 82/09/14 SOLLENBERO Uranium Recovery Licensing Branch 11pp 15876 233
- 6210120644 Advises that preliminary review of application for renewal of License SUA-442 complete General content acceptable but addl info will be needed Current license valid during period of review of renewal application PETEKOILL, H. J. Uranium Recovery Licensing Branch 62/09/20 RITCHIE, M. I. Pathfinder Mines Corp. ip 15684 233
- 8210220464 Ack receipt of 820903 ltr informing NRC of steps taken to correct violations noted in IE insp rept UROWW.0 D Region 4. Office of Director 82/09/27 RUBBELL, J E Pathfinder Mines Corp ip 15779 130

- --8210220476 Responds to NRC B20813 ltr re violations noted in IE insp rept Corrective actions high audible alarm setpoint reset Monthly surface contamination survey procedures improved RUSSELL, J E Pathfinder Mines Corp 82/09/03 BROWN, O D Region 4, Orfice of Director 2pp 15779 131
- DOCKET 40-6659 GETTY DIL CO PETROTOMICS CD , SHIRLEY BABIN, WY
- 8210220510 Forwards correspondence to & from State of WY rs unauthorized disposal of raduaste in U mill tailings disposal facilities PFAFF.S J Getty Oil Co (Petrotomics) 82/08/26 PETTENGILL.H J Uranium Recovery Licensing Branch 4pp 15786 119
- 8210210254 Forwards marked-up ltr from Getty Oil Co to State of WY indicating that requested info re wells & piezometers is on file at NRC Expresses desire for interagency cooperation ACKERMAN,W C Wyoming, State of 82/09/14 SMITH,D Division of Waste Management 4pp 15774 320
- 8210120628 Advises that remedial actions proposed by licensee in response to 811113 IE Mill Appraisal Rept 40-6659/B1-01 sufficient to correct weaknesses No licensing action will be required JONES, S. Z., OARCIA, P. J. Uranium Recovery Licensing Branch 82/09/20 Uranium Recovery Licensing Branch 2pp 15672 269
- 6210210527 Reviews environ monitoring data & 406FR190 dose calculations for Petrotomics Hill. in response to B20604 ltr NRC Loneurs W/results submitted by licensee
 JONES, S 7 , PETTENGILL, H J. Uranium Recovery Licensing Branch
 82/09/30 Uranium Recovery Licensing Branch 5pp 15782 31B
- DOCKET 40-7580 FANSTEEL, INC , NORTH CHICAGO, IL
- 8210280180 Ack receipt of 820908 ltr informing NRC of steps taken to correct violations noted in NRC 820813 ltr & notice of violation Addl info requested within 10 days BROWN, 0 D Division of Vendor & Technical Programs B2/10/25 PIERRET, J A Fansteel Metals (subs of Fansteel Inc.) (p
- ---8210280184 Responds to NRC 820813] tr & notice of violation Corrective actions portable radiation detection instruments calibr against two refs & lagged in lab log book PIERRET, J A Fansteel Metals (subs of Fansteel.Inc.) 82/09/00 BROWN.0 D Division of Vendor & Technical Programs ip 19537 020
- DOCKET 40-8027 KERR-MCGEE NUCLEAR CORP , OKLAHOMA CITY, OK
- 8210260543 Forwards application for amend to License SUB-1010 to construct & operate sludge calcining plant for purpose of converting raffinate sludge to readily disposable form SHELLEY, H J Kerr-McGee Corp 82/09/01 PAGE, R G Uranium Fuel Licensing Branch 3pp 15831 091
- --B210260548 Application for amend to License SUB-1010 to construct & operate sludge calcining plant for purpose of converting raffinate eludge to readily disposable form Oversize drawings encl Aperture cards available in PDR * Kerr-McGee Corp 82/09/01 133pp 1583; 094
- 8210260565 Forwards OX State Dept of Health, Industrial Waste Mgt Div B20824 ltr transmitting draft permit for use of deep disposal well for permanent disposal of treated raffinate, in ref to application for amend to License SUB-1010 SHELLEY, W J Kerr-McOes Corp 82/08/26 PAOE, R O Uranium Fuel Licensing Branch 6pp 15814 349
- 8210260576 Forwards initial comments on DK State Dept of Health draft permit for use of deep disposal well & replacement Page 1 to permit, correcting nitrogen limit Page should be inserted into 820826 Version SHELLEY, W J Kerr-McGee Chemical Corp (subs of Kerr-McGee Corp) 82/08/31 PAGE, R & Uranium Fuel Licensing Branch 3pp 13814 361
- 82102204B7 Responds to 820824 ltr outlining addl requirements for injection well permit Requests option to operate well at pressures equal to pump capacity of 400 psi Const methods & map of proposed monitoring location encl SHELLEY.W J Kerr-McGes Nuclear Corp 82/09/17 HENSCH.D A Oblahoma, State of 7pp 15786-325

- 8210270242 Forwards application for renewal of License SUB-1010 Renewal fee encl SHELLEY, W. J. Kerr-McGee Corp. 82/09/24 PAGE, R. G. Uranium Fuel Licensing Branch. Jpp. 15849 175
- --8210270247 Application for renewal of License SUB-1010 to refine U from yellowcake, to convert U to pure U herafilloride
 Thirty-five oversize drawings encl Aperture cards available in FDR
 SHELLEY, W J Kerr-McGee Corp 82/09/24 328pp 15849 178

DOCKET 40-8084 RID ALGOM CORP , MOAG, UT

8210210515 Reviews two const repts for 15-ft embankment raise in Rio Algom Corp lower tailings dam performed by Dames & Moore & Region 4 No further action required by licenses 9 MOOLSEY,R T , PETTEROILL,H J Uranium Recovery Licensing Branch 82/09/30 (Fanium Recovery Licensing Branch 4pp 15782 307

DOCKET 40-8102 EXXON CO USA, HOUSTON, TX

- 8210270195 Forwards "Environ Monitoring Data for Second Guarter, 1982," pursuant to License Condition 36, including close evaluation at nearest residence & results of environ monitoring program YARNICK, T.P. Erron Nuclear Co., Enc. (subs. of Exxon Corp.) 82/09/02 PETIENGILL, H.J. Uranium Recovery Licensing Branch. 1p. 15833-349
- --8210270197 "Environ Monatoring Data for Second Guarter, 1982 "
 * Erron Nuclear Co , Inc. (subs. of Erron Corp.) 82/09/02
 14pp 15835 350
- 8210240597 Forwards summary of airborne emissions of principal radiomoclides & "Semiamouel LARKA Rept. Jan-June 1982," pursuant to License Conditions 14 & 35 No liquid effluents discharged to unrestricted areas YARNICK, T F Exon Nuclear Co , Inc. (subs. of Exon Corp.) 82/09/03 Uranium Recovery Licensing Dranch Spp. 15830-240
- --8210260560 "Semiannual ALARA Rept. Jan-June 1982 "

 * Erron Nuclear Co., Inc. (subs. of Erron Corp.) 82/09/03
 75pp 15830 265
- 82(0120529 Advises that Erron general emergency action plans, submitted w/820526 ltr, are acceptable Condition if to License SUA-1139 should be Amended as listed JONES, 8 2 , PETTENDILL-H J Uranium Recovery Licensing Branch 82/09/23 Uranium Recovery Licensing Branch 2pp 15672 204
- B210120598 Natifies of issuance of Amend 3 to License SUA-1139, revising License Condition 25 resemble preparedness SKITH-R D Uranium Recovery Licensing Branch B2/09/23 Exxonorp ip 15672 350
- 8210150432 Advises that no additees for review of application for Amend 2 to License SUA-1139 required MILLER:NO License Fee Management Branch 82/10/07 OILCHRIST:J E Exam Corp ip 15715-359
- DOCKET 40-8111 KENNECOTT COPPER CORP , SALT LAKE CITY, UT
- 8210220066 Advises that NRC closed out license files when license expired in 1976 w/o closeout survey Facility meats NRC criteria for unrestricted use CARRICO, J B Licensing Management Branch 82/10/01 FOLSOM, B Kennecott

- --8210220080 Source Matl License SUA-1106 for Kennecott Copper Corp authorizing possession of 2,000 kg U MALAFO,J C Abomic Energy Commission 71/12/15 ip 15786 298
- --8210220086 Application for amend to License SVA-1106 licensing plant for storage only of refined product SPEDDEN,H R Kennecott Copper Corp 73/11/12 MALARO,J C Atomic Energy Commission 2pp 15786 259
- --82(0220089 Certificate of disposition of matts matt disposed in compliance w/10CFR20 4 Office of Nuclear Material Safety & Safeguards Director 76/12/17 1p 15786 260
- --8210220092 Confirms recent telcons re unrestricted use of facility Radiation surveys to be performed & results sent to NRC CARRICG.J D Licensing Management Branch 82/04/01 FOLSOM. D Kennecott Copper Corp 15pp 15786 281

DOCKET 40-8153 LEBAKON STEEL FOUNDRY, LEBANON, PA

- 8210270370 Application for renewal of Source Matl License SUB-1146authorizing possession of 56 kg U-235,enriched to less than O 4%, for use in area radiation sys ARNOLD M L Lebamon Steel Foundry 82/09/23 5pp 15835 001
- DOCKET 40-8355 AMAX SPECIALITY METALS CORP . PARKERSBURG. WV
- 8205240093 Forwards EIA of proposed site stabilization at AMAX, Inc NIZON, W A Uranium Fuel Licensing Branch 82/05/05 KERRIGAN, J AMAX, Inc 1p 15612 022
- --8205240010 Negative declaration re storage of contaminated soil un license PAGE:R G Uranium Fuel Licensing Branch 82/05/03 App 15612 023
- --8205240006 EIA supporting proposed site stabilization

 * Office of Nuclear Material Safety & Safeguards, Director
 82/04/30 90pp 15612 025
- DOCKET 40-8380 ROCKY MOUNTAIN ENERGY CO , BROOMFIELD. CO
- B2101B0398 Forwards "Groundwater Restoration Rept for Rocky Mountain Energy-Halliburton-Mono Power Nine Mile Lake R&D In Situ U Project " NEUMANN, M R Rocky Mountain Energy Co 82/08/30 NEUMANN, M R Uranium Recovery Licensing Branch ACKERMAN, W , GARLAND, B Wijomii State of 2pp 15747 001
- --B2101B0405 "Oroundwater Restoration Rept for Rocky Mountain Energy Halliburton-Mono Power Nine Mile Late R&D In Situ U Project "One oversize map encl Aperture card is available in PDR e Rocky Mountain Energy Co B2/06/21 216pp 15747 004

DOCKET 40-8452 BEAR CREEK URANIUM CD , CASPER, WY

- 8210150644 Forwards gradation results for Zone III sandstone in tailings disposal area in response to 820806 ltr Gradation tasts for Zone IV claystone also submitted MEDLOCK, R. L. Bear Creek Uranium Co. 82/08/20 BCARANO, R. A. FETTENGILLH J. Uranium Recovery Licensing Branch ISpp. 15715 292
- 8210260084 Forwards Self-Bond BCU399-01 to Permit 399 for Bear Creek U Co BRYAN,V J Wyoning, State of 82/08/20 FLORY,C Uranjum Recovi Licensing Branch 4pp 15814 149
- 8210280446 Forwards self-bond indemnity agreement to Permit 399 for Bear Creek U Mill between State of MY Dept of Environ Quality & Union Pacific Corp Vendor agreed to indemnify any Hability incurred by Bear Creek BRYAN, V. J. Wyoming: State of 82/08/30 FLGRY, C. Uranium Recove Licensing Branch 5pp 15858 350
- 8210120634 Reviews first quarter 1982 environ monitoring data 4 dose calculations for Bear Creek U Hill License Conditions 19, 49 & 54 satisfied.
 FLORY.C.A., PETTENGILL, H. J. Uranium Recovery Licensing Branch 82/09/20. Uranium Recovery Licensing Branch 5pp 15672 273

DOCKET 40-8502 WYOMING MINERAL CORP . LAKEWOOD, CO

- E.,10270180 Forwards "trigaray Mine Site, Bemiannual Activity & Monitoring Rept.Jan-June. 1982"
 COMPOY. B Wyoming Mineral Corp 82/08/25 Region 4, Office of Director 2pp 15835-332
- --8210270183 "Irigaray Mine Site, Semiannual Activity & Monitoring Rept, Jan-June, 1982 "
 - # Hyoming Mineral Corp 82/08/25 14pp 15835 334
- B210040338 Discusses amnonia-mitrate relationships applied to groundwater restoration at MY Mineral Corp Irigaray U Solution Mining Project in FES & responses to comments on DES LOGSDON,M J. LINEHAN, J. Uranium Recovery Licensing Branch B2/09/07 Uranium Recovery Licensing Branch Spp. 15597 182
- DOJKET 40-8577 AIR FORCE, DEPT OF, VANDENBERG AFB, CA
- e210270179 Forwards application for amend to License SUB-1289, reflecting changes in Mestern Space & Missile Ctr radiation protection committee & use of TLD Instead of film badges BDLLINGER.L J Air Force, Dept of, Radioisotope Committee B2/09/1/Division of Fuel Cycle & Material Safety 4pp 15835 023
- --B2(0270(B2 Application for amend to License SUB-1289, reflecting changes in Western Space & Missile Ctr radiation protection committee Personnel resumes encl HEIN7. E.L. Air Force Dept of, Radioisotope Committee B2/09/14 52pp 19835 027
- DUCKET 40-8602 SILVER KING MINES, INC , CASPER, MY
- 6210250054 Forwards "Preoperational Radiological Environ Monitoring Rept. Jan-June 1982" WOLFF, C.E. Silver King Himing, Inc. 82/08/27 SCARANG, R.A. Uranium Recovery Licensing Branch . 3pp. 15808-014
- --8210250056 "Preoperational Radiological Environ Monitoring Rept. Jan-June, 1982" 4 Silver King Mining, Inc. 82/08/27 109pp 15808 019
- 82(0270048 Forwards three warranty doeds per 820810 telcon All deeds to be assigned to Silver King Mine. Inc. as trustee for TVA Deeds Fulfill land ownership requirements MOLFF.C E Silver King Mining. Inc. 82/08/20 PANTELL.S Division of Fuel Cycle & Material Safety 16pp 15836-086
- DOCKET 40-8610 STEPAN CHEMICAL CO . MAYWOOD, NJ
- 8210260341 Forwards QA Program Insp Rept 99990001/82-13 on 620923 No noncompliance noted KINNEMAN.J D Region 1. Office of Director, 62/10/22 FIGRE/R A Maywood, NJ FIGRE/R A Fiore & Jaskot 2pp 15803-033
- --8210260345 GA Program Insp Rept 99970001/82-13 on B20923 No noncompliance noted Major areas inspected measurement of radiation levels & gathering of sediment samples in & along Coles Broak, Maywood, NJ JUHMNECN J. KINNEMAN, J. D. Region 1, Office of Director 82/10/21 6pp 19803 035
- --B210260352 Requests info on whether proposed stream clearance project would create hazard reliadioactive contamination in vicinity of brook Stytches encl FIDRE, R.A. Fibre & Jaskot 82/09/14 KINNEMAN, J.D. Region 1, Office of Director COSDLITO, F. New Jersey, State of 4pp 19803-041
- DOCKET 40-8632 ARMY, DEPT OF, CHAMBERSBURG, PA
- 8210270222 Forwards application to amend License SUC-1380 to allow staballoy to be used interchangeably w/depleted U when referring to U alloys
 TARAS, D N Army, Dept of, Headquarters Materiel Development & Readiness Command 82/08/27 Division of Fuel Cycle & Material Safety ip 15836-043

- --8210270227 Application for amend to License SVC-1380 to allow staballoy to be used interchangeably w/depleted U when referring to U alloys SMITH.L E Army.Dept of, Headquarters Materiel Development & Readiness Command 82/08/20 Division of Fuel Cycle & Material Safety 2pp 15836 044
- DOCKET 40-8681 ENERGY FUELS NUCLEAR, INC , DENVER, CO
- 8210220516 Submits questions re Amend B.Condition 18 to License SUA-1358 Rewording of composition of internal audit committee suggested to allow for reorganization DAKER.C E Energy Fuels Nuclear. Inc. 82/08/20 GILLEN.D Uranium Recovery Licensing Branch 2pp 15786 086
- 8210250034 Application for amend to License SUA-1358, revising representation on internal audit committee & recipient of semiannual ALARA audits BAKER, C E Energy Fuels Nuclear, Inc. 82/08/20 OILLEN, D Uranium Recovery Licensing Branch 2pp 15808 347
- 8210250006 Forwards "Effluent & Monitoring Rept.Apr-June 1982" BAKER C E Energy Fuels Nuclear, Inc 82/08/27 GILLEN,D Uranium Recovery Licensing Branch 1p 15808 130
- --8210250008 "Effluent & Monitoring Rept.Apr-June 1982 "
 * Energy Fuels Nuclear, Inc 82/08/27 45pp 15808 136
- 8210240017 Forwards "Semiannual ALARA Audit Rept for Energy Fuels Nuclear, Inc White Hesa V Hill, Blanding, UT " BAKER.C E Energy Fuels Nuclear, Inc 82/08/31 VINCELETTE, M D Energy Fuels Nuclear, Inc 1p 15814 305
- --8210260018 "Semiannual ALARA Audit Rept for Energy Fuels Nuclear, Inc White Mesa U Mill, Dlanding, UT " * Energy Fuels Nuclear, Inc 82/08/31 11pp 15814 306
- 8210260022 Application for amend to License SUA-1358, authorizing discharge of tailings into Cell 3 prior to completion of const of Cell 4 safety dike Progressive const of safety dike will contain vol of potential spill BAKER.C E Energy Fuels Nuclear. Inc. 82/09/02 GILLEN.D Uranium Recovery Licensing Branch. 3pp. 15814-318
- B210270209 Advises that schedule for initiation of const on Cell 3 safety dike at White Mesa will be delayed i wk beyond date set forth in B20408 ltr Completion of safety dike may be delayed until Spring 1983
 BAKER, C.E. Energy Fuels Nuclear, Inc. B2/09/03 GILLEN, D. Uranium Recovery Licensing Branch ip 15836-034
- 8210270439 Forwards "Tailings Cover Design Revision" in response to NRC 820812 request for info re application for amend to License 8UA-1338 Proposed reduction in thickness of tailings reclamation cover adequate DAKER.C E Energy Fuels Nuclear. Inc 82/09/03 GILLEN.D Uranium Recovery Licensing Branch in 18833 001
- --8210270439 "Tailings Cover Design Revision"

 * D'Appolonia Consulting Engineers, Inc 82/08/25 55pp 18833 003
- B210040363 Notification of B20913 meeting w/Energy Fuels Nuclear in Silver Bpring: MD to discuss White Mesa facility reclamation plan: associated costs & proposed surety arrangements QILLEN: D M Uranium Recovery Licensing Branch S2/09/09 LINEHAN: J J. PETTENDILL: H J. FLEMING: T.E NRC No Detailed Affiliation Given 2pp 15597 191
- 8210120641 Recommends no action be taken on licensee request for hearing on license amend to require surety for decommissioning & reclamation Issue may be mooted by licensee submittal of revised reclamation plan LINEHANJ J Uranium Recovery Licensing Branch 82/09/17 KLUCSIKJF Office of the General Counsel ip 15672 278
- 8210210532 Issues Amend 15 to License SUA-1358, in response to 820902 request Amend adds Item g to License Condition 26 allowing licensee to forego const of Cell 3 safety dike SMITH-R D Uranium Recovery Licensing Branch 82/09/30 Energy Fuels Nuclear, Inc. Ip 15782 325
- --B210210534 Recommends issuance of Amend 15 to License 8UA-1358, in response to 820902 request Amend adds Item g to License Condition 26 allowing licenses to forego const of Cell 3 safety dike GILEN, D M Uranium Recovery Licensing Branch 82/10/04 Uranium Recovery Licensing Branch 2pp 15782 326.

DOCKET 40-8697 ROCKY HOUNTAIN ENERGY CO , DENVER, CO

- 821028045; Advises that differences identified in two lab finding for potassium values due to different lab procedures or lab capabilities Differences in pH values due to NML reporting field values
 SCHHIYIDIEL.P Hyoming, State of 82/04/27 Hyoming, State of 4pp 15858 345
- 8210250043 Forwards corrected rept for radionuclide concentrations in Pattern 2 injection & production wells from 820401 stabilization samples for, "Reno Creek Pattern 2 Restoration Rept Addendum " NEUMANN.H R Rocky Mountain Energy Co 82/09/09 KALMAN.K Uranium Recovery Licensing Branch 2pp 15788 348
- 8210040344 Discusses review of Rocky Mountain Energy 1982 second quarterly rept for Reno Creek Bite No followsp actions necessary KALMAN, X L. LINEHAN, J Uranium Recovery Licensing Branch 82/09/10 Uranium Recovery Licensing Branch 2pp 15597 18
- DOCKET 40-8698 PLATEAU RESOURCES, LTD , GRAND JUNCTION, CO
- 3210260019 Confirms 820820 conversation re temporary suspension of production at Shootaring Canyon U processing facility Velloucake in sys presently being recovered Plant will resume milling & minang by late 1984 GERDEMAN.F H Plateau Resources, Ltd 82/08/24 FLEMING.T NRC No Detailed Affiliation Given lp 15814 317
- MCKET 40-8714 CLEVELAND-CLIFFS IRON CD . CLEVELAND, DH
- 3210220515 Notifies that Cleveland Cliffs surface discharge operation monitoring program complies w/requirements of NPDES Permit WY-0030783 No further action required PBHLE.JA . LINEHAN.JJ Uranium Recovery Licensing Branch 92/05/03 Uranium Recovery Licensing Branch ip 15786 088
- \$210220036 Advises that License SUA-1352 amended to revise License Condition 10 re authorized use of expanded ion exchange resin SCARANO,R A Uranium Recovery Licensing Dranch B2/08/30 LQUDERBACK,T E Cleveland-Cliffs Iron Co 2pp 15786 281.
- HOCKET 40-8728 TETON EXPLORATION DRILLING CO , INC , CASPER, WY
- 1210280412 Forwards Btate of MY Dept of Environ Quality, Land Quality Div 820519 itr accepting groundwater stabilization in N zone aquifer & advising of plugging of zone wells APPEL-R R Teton Exploration Drilling Co . Inc 82/08/23 ROSS, F W NRC No Detailed Affiliation Olven 3pp 15859 336
- 1210120494 Advises that proposed in-plant radiation safety program acceptable w/listed exceptions, Conditions 25 & 30 of License SUA-1373 should be revised as stated SULLENDERGER, D., PETTENOILL, H.J. Uranium Recovery Licensing Branch 82/09/16 RDBS, F.W. Uranium Recovery Licensing Branch 6pp 18479 AM

- 8210260577 Objects to conditions on commencement of mining in Unit 2 Collection of baseline water quality data in Unit 3 prior to mining unnecessary to insure environ protection of groundwater CATCHPOLE.0 J Ogle Petroleum, Inc. 82/09/02 FRANCIS.E Hyoming, State of 2pp 15830 139
- 821012059| Requests that second aquirer pump test be performed prior to licensing injection of lixiviant into Mining Unit 2 are zone to evaluate confining nature of lower claystone layer Previous test inadequate
 LINEHAN, J. Uranium Recovery Licensing Branch 82/09/10 Ogle Petroleum. Inc. ip 15672.351
- --8210120604 Responds to request to analyze Mine Unit 2 pump test & associated data Use of ratio method to determine vertical hydraulic conductivity of lower aquitard invalid WILLIAMS R E Williams-Robinette & Associates, Inc 82/09/10 Williams-Robinette & Associates, Inc 8pp 15672 352
- 8210280046 Forwards in-plant radon concentrations table for first holf of 1982, per NRC request SAVNDERS O A Oglo Petroloum, inc 82/09/10 SMITH.D Uranium Recovery Licensing Branch ip 15863 004
- --8210280049 "Radon Oas Concentration in uCi/ml." Jan-June 1982 4 Ogle Petroleum, Inc. 82/09/10 ip 15863 005
- DOCKET 40-8768 KERR-MCGEE NUCLEAR CORP , OKLAHOMA CITY, DK
- 8210040365 Discusses review of Kerr-McGes G-Sand Project quarterly rept for Jan-Mar 1982 To date, no serious events identified which necessitate change of operations or shutdown MESTBROOK, K B , LINEMAN, J J Uranium Recovery Licensing Branch 82/09/07 Uranium Recovery Licensing Branch App 15597 193
- DOCKET 40-8771 MELAPAT RESOURCES CO . PHOENIX. AZ
- 6210120536 Advises that no violation found during NRC 820406-07 preoperational safety insp FLEMINO, T.E., MARTIN, D.E. Uranium Recovery Licensing Branch 82/09/22 Uranium Recovery Licensing Branch ip 15672 216
- DUCKET 40-878: TETON EXPLORATION DRILLING CD . INC . CASPER, MY
- 8210270066 Expresses appreciation for opportunity to review & comment on DES for Teton Exploration Drilling Project Document adequate re compatibility w/local & regional comprehensive planning MATUSCHECK, R J. Housing & Urban Development, Dept. of 82/08/02 SCARRAND, R A. Uranium Recovery Licensing Branch 1p 15836-127
- 8210250032 Comments on application process to date Use of environ rept for NRC purposes similar to State of WY format will save considerable preparation time APPEL: R United Nuclear Corp 82/08/23 SCARAND, R A Uranium Recovery Licensing Branch 2pp 15808 345
- 8210260096 Forwards state agency comments on project DES Encl analyses support issuance of combined source & hyproduct mat! licenses subj to specific licensing conditions of other local state & federal stds & regulations HERSCHLERIE Wyoming. State of 82/08/26 BCARANO,R A Uranium Recovery Licensing Branch 9pp (5810-330
- --8210260099 Comments on DES Sentence that mobile fire units are maintained by Converse County Rural Fire Control Assoc should be added to Page 3-20
 LUNDELL.B.E Hyoning, State of 82/07/19 Uranium Recovery Licensing Branch 1p 15810 339
- 8210120619 Forwards safety evaluation supporting issuance of License SUA-1403 for commercial in situ leach U mine & recovery plant WIOCSEY,R.T., PETTENGILL.H.J. Uranium Recovery Licensing Branch 82/09/20 Uranium Recovery Licensing Branch ip, 13672 238
- --8210120624 Safety evaluation supporting issuance of License SUA-1403 for commercial in situ leach U mine & recovery plant.
 MOCLERY,R T , PETTENDILL,H J Uranium Recovery Licensing Branch 82/09/20 22pp. 15672:239

- DUCKET 40-8786 URANIUM RESOURCES. INC., RICHARDSON, TX
- 6210180354 Forwards response to NRC 820723 ltr re maifunctioning flow meters, radiological environ monitoring & as-built pond specs One oversize map encl Aperture card is available in PDR PELIZZA, M.S. Uranium Resources, Inc. 82/08/12 L. Uranium Recovery Liconsing Branch . 3pp. 15747-352 I INFHAN, J J
- --P210180359 'Pond Soil Analysis"

 * Affiliation Unknown 82/02/22 2pp 15747 357
- 8210250013 "North Platte Project Quarterly Rept. 820415-0715 "

 * Uranium Resources, Inc. 82/08/23 68pp 15808 183
- 8210120479 Approves licensee restoration of R&D wellfield using combination groundwater sweep & reinjection of reverse osmosis treated water Wells will be restored to proper levels at end of restoration
 WESTBROOK.F D , LINEHAN.J J Uranium Recovery Licensing Branch Uransum Recovery Licensing Branch 2pp
- DOCKET 40-8793 CONOCO, INC , DENVER, CO
- 8210040348 Discusses CONOCO. Inc request for withdrawal of Ruby Ranch In Situ V Project application Option of withdrawing application granted
 YOUNG, Y.A., LINEHAN, J.J. Uranium Recovery Licensing Branch 82/09/10 Uranium Recovery Licensing Branch 4pp 15597 187
- DOCKET 40-8820 AMAX ENVIRONMENTAL SERVICES, INC., GOLDEN, CD.
- adjacent property Guned by Chiyoda Steel Corp Authorization by Chiyoda Steel Corp Authorization by Chiyoda Steel Corp Authorization by Chiyoda to enter property & remove soil encl KEPPLER.P AMAX. Inc 82/08/31 NIXON,W NRC No Detailed Arfiliation Given 3pp 15808 349 8210250035 Advises that radioactive contaminated soil removed from
- DOCKET 40-8824 TARGET RESEARCH, [NC : WHARTON: NJ
- 8210270373 Forwards application for source matl license, authorizing possession of 6,000 kg U alloy, enriched to 79 8% U-23B, for use in assembling armorphiercing projectiles
 DAKUM.K E Target Research. Inc 82/09/15
 Cycle & Material Safety 1p 15835 220 Division of Fuel
- --8210270376 Application for license to possess 6.000 kg depleted U allow-enriched to 99 8% U-238, for use in assembling armor-piercing projectiles GUADAGNO.V Targot Research, Inc 82/09/14 17pp 15835 221

DOMESTIC LICENSING OF PRODUCTION AND UTILIZATION FACILITIES

- DOCKET 50-3 INDIAN POINT STATION, UNIT 1
- F Security, medical, emergency & fire protection plans
- 8210280148 Releases public version of rovised emergency plan implementing procedures
 FELTOR, J M Division of Rules and Records 82/10/12 RETINGS OF PIVISION OF Rules and Records 82/10/12 Docum Management Branch ip 15862 271 24% Fiche 50-003,82/10/12, 8210280148 Dac ument
- --8210280154 Forwards public version of revisions to Emergency Plan Implementing Procedures IP-1020 re airborne radioiodine determination & IP-1046 re util personnel responsibilities during Unit 3 emergencies O'TOOLE.J D Consolidated Edison Co of New York 82/10/01 HAYNES.R C Region 1. Office of Director 3pp 15862 272 24X Fiche 50-003,82/10/12,8210280148
- ~~8210280159 Public version of revisions to Emergancy Plan Implementing Procedures IP-1020 re-airborns radioteding determination & IP-1046 re util personnel responsibilities during Unit 3 emergencies * Consolidated Edison Co of New York 82/09/0: 15862 275 24X Fiche 50-003,82/10/12.8210280148

- O Advisory Committee on Reactor Safeguards reports & correspondence
- 8207180077 Forwards comments on PRA study dealing w/seismic hazard Validity of conclusions rest on quality of primary data bases & assumptions in both studies Repts are not valid risk assessments due to data base limitations POHEROY, P. W. Rondout Associates POMEROY, P. W. ACRS - Adv. Committee on Reactor Safeguards 82/08/24 OKRENT, D. ACR! Advisory Committee on Reactor Safeguards 7pp 15876 001 Fiche 50-003, 82/08/24, 8207180077 ACRS -
- P Operating license stage documents & correspondence
- B009080466 Forwards response to B00820 request for status rept re Zion/Indian Point task action plan Responsibilities are in area of severe accident mitigation features & not in interim operational actions portion MEYER, J F Reactor Systems Branch BO/08/25 NDVAK, T M / Director for Operating Reactors 2pp 03484 007 24X Fiche 50-003, 80/08/25, 8009080466 NOVAK, T M Assistant
- B010210036 Discusses SEP Branch review of sys environ qualification of safety-related electrical equipment for il SEP plants MCKENNA.E M Systematic Evaluation Program Branch B0/09/30 LAINAB.0 C Division of Licensing 2pp 03647 289 24% Fiche 50-003.80/09/30.8010210036
- 8210120103 Add1 response to FOIA request for nine categories of records generated by present NRC Commissioners primarily Chairman Palladino & Commissioner Roberts & White House Forwards App B documents FELTON.JM Division of Rules and Records 82/07/1: Critical Mass Energy Project 3pp 15690 117 24X Fiche 50-000, 82/07/12, 8210120103 82/07/12 UDELL R A
- --8210120188 Notifies that facility will be decommissioned by util rather than make ECCS mods to meet NRC criteria Util proposed research funding cannot be provided Recommends approval of proposed ltr to util ZECH, G NRC - No Detailed Affiliation Given ROBERTS, T M Commissioners ip 15690 140 Fichs 30-000, 82/07/12, 8210120103 81/11/05 tion Given 81/ 15690 160 24x
- 8210010401 Forwards application to amend Licenses DPR-26 & DPR-5, changing Tech Specs re facility organization & Unit 2
 Tech Specs 3 6 & 4 4 re containment isolation & Unit 2
 Tech Specs 3 6 & 4 4 re containment isolation valves 3 12 &
 4 12 in pipe lines Class I, II & III fees enc!
 0/TOOLE.J D Consolidated Edison Co of New York 82/08/31
 VARGA.B A Operating Reactors Branch 1 3pp 15572 211 24X
 Fiche 50-003, 82/08/31, 8210010401
- --B210010409 Application to amend Licenses DPR-26 & DPR-5, revising Tech Spec Figures 3 2 & 6 2-2 re facility organization for Units i & 2, respectively O'TOOLE, J D Consolidated Edison Co of New York 82/08/31 2pp 19372 214 24X Fiche 30-003,82/08/31,8210010401
- --8210010414 Proposed revisions to Tech Spec Figures 3 2 & 6 2-2, reflecting change in organizational structure to include position of operations superintendent Safety assessment entl * Consolidated Edison Co of New York 82/08/3 15572 216 24X Fiche 50-003,82/08/31,8210010401
- -82i0010425 Application to amend License DPR-26 revising Tech Specs 3 6 & 4 4 to establish requirements for action required when containment isolation valves are inoperable & reflect Changes to isolation valve provisions O'TOOLE.J D Consolidated Edison Co of New York 82/08/31 2pp 15572 222 24X Fiche 50-003.82/08/31.8210010401
- --8210010438 Proposed revisions to Tech Specs 3 6 & 4 4 establishing specific requirements for action during inoperability of containment isolation valves & reflecting changes & additions to isolation valve provisions Safety assessment encl # Consolidated Edison Co of New York 82/08/31 20pp 15572 224 24X Fiche 50-003.82/08/31,8210010401
- --8210010443 Application to amend License DPR-26, revising Tech Spec Sections 3 12 & 4 12 to defflect editorial change safety-related pipe lines & to efflect editorial change 0/TOOLE.J D Consolidated Edison Co of New York 82/08/31. 82/08/31. 2pp
- --B210010449 Proposed revisions to Tech Spec Sections 3 12 & 4 12, reflecting redesigned support sys for safesty-related pips lines & to effect editorial change Safety assessment encl.

 **Consolidated Edison Co of New York 82/08/31 18pp 15572 246 24X Fiche 50-003, 82/08/31, 8210010401

- à Inspection reports, IE Bulletins & correspondence
- ERCB19D23J IE Info Notice 80-35. Suppl 1. "Leaking & Distodged 1-125 Implant Seeds " Svc list encl COBO.L I Division of Fuel Facilities. Materials & Safeguards E2/10/06 Cansolidated Edison Co of New York Adapt 15761 250 24
- 82LB190238 IE Bulletin B2-03, "Stress Corrosion Cracking in Thick-Wall, Large-Dianeter, Stainless Steel, Recirculation Sys Paping at OWR Plants " Sve list encl DEYGUND.R C Director's Office, Office of Inspection and Enforcement 82/10/14 Consolidated Edison Co of New York 123pp 15810 125 24% Fische 50-000,82/10/14,8208190238
- DOCKET 50-10 DRESDEN NUCLEAR POWER STATION, UNIT 1

 F. Security, medical, emergency & fire protection plans
- 9209290125 Releases public version of revised generating station energency plan corporate command ctr emergency plan implementing procedure FFLTON.JM Division of Rules and Records 82/09/16 Document Management Branch 1p 15564 122 24X Fiche 50-000.82/09/16.
- --8209290189 Forwards public version of Revision 4 to generating station energency plan corporate command ctr Emergency Plan Inplementing Procedure EOF-3. "Environ/Emergency Coordinator " Receipt form encl PAJONEKI.J E Commonwealth Edison Co. 82/09/01 DENTON.H R NRC No Detailed Affelliation Oiven ip 15564 123 24X Fiche 50-000.82/09/16.8209290125
- --B209290225 Public version of Revision 4 to generating station energency plan componate command ctr energency plan inpliementing Procedure EUF-3. "Environ/Emergency Coordinator"
 PAJCHSKI, J E , LITERSKI, L A , FLESSNEK, S A Commonwealth Edison Co 82/08/31 lipp 15564 124 24X Fiche 50-000,82/09/16.
- 6210130376 Advises that installation of offsite dose calculation syspogram fully operational tracking model to operational A-model will be delayed until 821231 to complete prime computer installation
 SMARTZ.E D Commonwealth Edison Co 82/10/06 DENTON.H R Office of Nuclear Reactor Regulation, Director 2pp 15682 098 24X
 Fiche 50-000, 82/10/06-0210130376
- S210290047 Releases public version of revisions to Quad Cities, Zion & Dresdan emergency plan anneres & revised generating statum emergency plan telephone directory FELTOH, J M Division of Rules and Records 62/10/08 Document Management Branch ip 15877 313 24% Fiche 50-000,82/10/08, 8210290047
- --8210290060 Forwards public version of Revision 3 to Quad Cities & Zion emergency plan annexes. Revision 2 to Dresden emergency plan annex intervision 2 to Dresden emergency plan annex intervised generating station emergency plan telephone directory MODRE.R D Commonwealth Edison Co 82/07/30 DENTON, H R NRC -- No Detailed Affiliation Given 5pp 15977 314 24X Fiche 50-000, 82/10/08. B210290047
- --8210290077 Public version of Revision 3 to Guad Cities & Zion emergency plan annexes. Revision 2 to Dresden emergency plan annex & Revision 0 to Syron emergency plan annex & Revision 0 to Syron emergency plan annex > Commonwealth Edison Co 82/06/30 102pp 15877 319 24X Fiche 50-000.82/10/08.8210290047
- --821029008B Public version of revised generating station emergency plan telephone directory GALLE.D P Commonwealth Edison Co 82/08/12 43pp 15878 218 24X Fiche 50-000,82/10/08/8210290047
- 8210220358 Provides info re organization & performance of depts responsible for radiation protection activities, per 820702 commitment Training coordinator assigned in Apr 1982 to improve health physics training programs TRANH.TR Commonwealth Edison Co. 82/10/14 DENTON.HR Office of Nuclear Reactor Regulation, Director 9pp 15776-287 24X Fiche 50-000,82/10/14.8210220358
- 8210250170 Advises that plans k preparedness for offsite protection near facility adequate & will be applied in event of radiological emergency IL State & local plans approved subj to verification of adequacy of alerting & notification sys THOMAS.L. H Federal Emergency Hangement Agency 82/10/14 DIRCKS U Office of the Executive Director for Operations ip 15789:285 24% Fiche 50-010.82/10/14.8210250170

- P Operating license stage documents & correspondence
- 8210260526 Forwards Revision 3 of Chapter 9 of "Offsite Dose Calculation Manual" GULDER, J C Commonwealth Edison Co 82/10/06 CASE, E 0 Office of Nuclear Reactor Regulation, Director 2pp 15805 137 24X Fiche 50-000, 82/10/06, 8210260526
- --BZ10260542 Revision 3 of Chapter 9 of "Offsite Dose Calculation Manual "
 - **Communusaith Edison Co 82/09/30 83pp 15805 139 24x Fichs 50-000, 82/10/06, 8210260526
- 8210130326 Comments on proposed scope of Phase III of SEP as reflected in individual topic definitions appended to 820707 ltr Staff encouraged to develop & implement means to incorporate pasitive attributes of Phase III in licensee/NRC interface RACICHAR M SEP Owners Group KACICHAR M Northeast Nuclear Energy Co (subs of Northeast Utilities) 82/10/07 EISENHUT.D 0 Division of Licensing 7pp 19682 177 24X Fiche 50-000,82/10/07,82/10/30326
- 8210180195 Forwards "Final Status Rept in Preparation for Chemical Cleaning of Dresden 1," Sept 1982 RAVSCH.T J Commonwealth Edison Co 82/10/12 EISENHUT.D Q Division of Licensing 1p (5749 135 24X Fiche 50-010.82/10/12, 8210180195
- --8210180199 "Final Status Rept in Preparation for Chemical Cleaning Dresden 1." Sept 1981 Aperture cards available in PDR Dow Chemical Co DNS-D1-034 81/09/30 582pp 15749 []/(24% Fiche 50-010.82/10/12.8210180196
- O Inspection reports, IE Bulletins & correspondence
- 8210060329 Forwards IE Insp Repts 50-010/82-02.50-237/82-03 & 50-249/82-03 on 820119-0218 No noncompliance noted LITTLE, N 5 Division of Engineering & Technical Programs REED. C Commonwealth Edison Co 2pp 15615 331 24X Fiche 50-010, 82/09/22, 8210060329
- --0210060335 IE Insp Repts 50-010/82-02,50-217/82-03 & 50-249/82-03 o 820119-0218 No noncompliance noted Major areas inspected open & unresolved items & items of noncompliance reintegrated leak rate test REIMANN,F W. Region 3. Office of Director JACKIN, I N. Divisio of Engineering & Technical Programs 82/09/21 7pp 15415 37.2 24X Fiche 50-010.82/09/22.8210060329
- 8210150523 Forwards IE Insp Repts 50-010/82-13.50-237/82-17 & 50-249/82-18 on 820708-0809 & notice of violation STREETER.J F Division of Project & Resident Programs 82/09/28 REED.C Commonwealth Edison Co 2pp 15713 099 24X Fiche 50-010.82/09/28.8210150523
- --B210150530 Notice of violation from insp on 82070B-0809 STREETER, J. F. Division of Project & Resident Programs B2/09/20 1p 15713 101 24X Fiche 50-010.B2/09/28.B210150523
- --8210150538 IE Imap Repts 50-010/82-13,50-237/82-17 & 50-249/82-18 or 820708-0809 Noncompliance noted failure to issue & perform air pressure test procedure TOKOUE.T H. JORDAN.H J. HALKER,R D. Division of Project & Resident Programs 82/09/28 Bpp 18713 102 24X Fiche 50-010,82/09/28,8210150523
- 8210150539 Forwards IE Insp Repts 50-010/82-15,50-237/82-19 & 50-249/82-20 on 820830-0903 No noncompliance noted PAPERIELLO, C J Division of Emergency Freparedness & Operational Support 82/10/01 REED, C. Commonwealth Edison Co 2pp 15714 178 24X Fiche 50-010,82/10/01,8210150539
- --B210150543 IE Insp Repts 50-010/82-15, 50-237/B2-19 & 50-249/B2-20 or B20830-0903 & 09 No noncompliance noted Major areas inspected confirmatory measurements programs GC program for analytical measurements & environ monitoring program BCHUMACHER, M C , NICHOLSON, N A : JANUEKA: A © Division of Emergency Preparedness & Operational Support B2/09/30 7pp 15714 177 24X Fiche 50-010, 82/10/01, 8210150539
- 8208170233 IE Info Notice 80-35, Suppl 1, "Leaking & Dislodged I-125 Implant Seeds " Svc list encl COBB.L I Division of Fuel Facilities, Materials & Safeguards 82/10/06 Cansolidated Edison Co of New York 66pp 15761 250 24X Fichs 50-000, 82/10/06, 8208170233

- 9208190238 IE Bulletin 82-03. "Stress Corrosion Cracking in Thick-Wall-Large-Diameter. Stainless Steel Recirculation Sys
 Piping at BWR Plants " Svc list encl
 DEYGUNG.R C Director's Office. Office of Inspection and
 Enforcement 82/10/14 Consolidated Edison Co of New York
 123pp 15810 125 24X Fiche 50-000, 82/10/14,8208190238
- R Periodic operating reports & related correspondence
- 82:0180097 Forwards monthly operating repts for Sept 1982 SCOTT.D J Commonwealth Eduson Co 82/10/01 Director's Office, Office of Inspection and Enforcement 1p 15718 001 24X Fiche 50-010,82/10/01.8210180097
- --8210180100 Monthly operating repts for Sept 1982 SCHROEDER B A Commonwealth Edison Co 82/10/01 15718 002 24X Fiche 50-010, 82/10/01, 8210180097
- DOCKET 50-13 BABCOCK & HILCOX CO CRITICAL FACILITY

 F Security, medical, energency & fire protection plans
- 8210210194 Forwards IE Safeguards Insp Repts 50-013/82-03 & 70-0822/82-10 on 820930-1001 No noncompliance noted GlBSON.A F Division of Engineering & Technical Programs 82/10/15 ENGELDER.T C Babcack & Wilcox Go 2pp 15765 304 24X Fichs 50-013.82710/15.8210210194
- --8210210206 IE Safeguards Insp Repts 50-013/82-03 & 70-0824/82-10 on 820/30-1001 No noncompliance noted Major areas inspected physical protection of low enriched SNM Details withheld (ref 10CFR2 790)
 GODE.R · MCGUIRE.D R Division of Engineering & Technical Programs 82/10/15 ip 15765-306 24X Fichs 50-013,82/10/15,8210210194
- P Operating license stage documents & correspondence
- 8210040214 Details evaluation of discrepancy between electronically simulated reactor & channel periods revealed in calibr test performed on Log-N-2 channel No unsafe condition existed & no Tech Spec violation occurred OLSENA F Consolidation Coal Co 82/09/27 Standardization & Special Projects Branch 3pp 15583 120 24X Fiche 50-013, 62/09/27, 8210040214
- Q Inspection reports. IE Bulletins & correspondence
- 82:02:0194 Forwards IE Safeguards Insp Repts 50-013/82-03 & 70-0824/82-10 on 820930-1001 No noncompliance noted.
 GIBSON, A F Division of Engineering & Technical Programs 82/10/13 ENGELDER, T C Babcock & Wilcox Co 2pp 15765 304 24X Fiche 50-013,82/10/15,8210210194
- --9210210206 IE Safeguards Insp Repts 50-013/82-03 & 70-0824/82-10 on 820930-1001 No honcompliance noted Major areas inspected physical protection of low enriched SNM Details withheld (ref 10CFR2 790)
 OGDDE,R . MCGUIRE,D R Division of Engineering & Technical Programs 82/10/15 ip 15765 306 24X Fichs 50-013,82/10/15,8210210194
- DOCKET 50-20 MASSACHUSETTS INST OF TECH RES REACTOR

 F Security, medical, emergency & fire protection plans
- 9210190334 Forwards Revision 27 to SAR for MIT research reactor, arfecting physical security plan SAR withheld (ref 10CFR2 790)
 CLARK-L Massachusetts Institute of Technology 82/10/13
 TEDESCO.R L Assistant Director for Licensing 1p 15742 125 24X
 F1Che 50-020, 82/10/13, 8210190334
- DOCKET 50-22 WESTINGHOUSE TEST REACTOR
- O Inspection reports, IE Bulletins & correspondence
- 8210130420 Forwards "Annual Insp of Retired Westinghouse Testing Reactor per License IR-2 for 1982 " NARDIA J Westinghouse Electric Corp 82/09/30 Stendardization & Special Projects Branch ip 15680 264 24X Fiche 50-022,82/09/30,8210130420
- ---9210130426 "Annual Insp of Retired Westinghouse Testing Reactor per License IR-2 for 1982" Westinghouse Electric Carp 82/09/16 3pp 15680, 265. 24X Fiche 50-022, 82/09/30, 8210130420

- R Periodic operating reports & related correspondence
- 8210130420 Forwards "Annual Insp of Retired Westinghouse Testing Reactor per License TR-2 for 1982 " NARDI.A J Hestinghouse Electric Corp 82/09/30 Standardization & Special Projects Branch ip 15680 264 24X Fiche 50-022
- --8210130426 "Annual Insp of Retired Westinghouse Testing Reactor per License TR-2 for 1982" # Westinghouse Electric Corp 82/09/16 3pp 15680 265 24X Fiche 50-022,82/09/30.8210130420
- DOCKET SO-27 WASHINGTON STATE UNIV RESEARCH REACTOR

 Q Inspection reports, IE Bulletins & correspondence
- 8210190632 Forwards IE Insp Rept 50-027/82-02 on 820714-16 & 0810 No noncompliance noted

 BOOK, H E Division of Rediclogical Safety & Safeguards Program

 82/10/01 WILBONN E Washington, Univ of 2pp 15740 025 24X

 Fiche 50-027, 82/10/01, 8210190632
- DOCKET 50-29 YANKEE-ROHE NUCLEAR POWER STATION

 F Security, medical, emergency & fire protection plans
- B210060034 Forwards IE Safeguards Insp Rept 50-027/82-09 on 820802-05 No noncompliance noted MARTIN.T Division of Engineering & Technical Programs 82/09/27 HEIDER, L. H. Yankse Atomic Electric Co. 2pp 15615-051 24X Fichs 50-027, 82/09/27/8210060034
- --8210060049 IE Safeguards Insp Rept 50-029/82-09 on 820802-05 No noncompliance noted Major areas inspected testing & maint records.physical barriers in protected & vital areas & security sys power supply Details withheld (ref 10CFR73 21) DUNLAP.J.M., SMITH.O.C., CODY.A.T. Division of Engineering & Technical Programs 82/09/23 pp 15615 053 24X Fiche 50-029,82/09/27.8210060034
- 8210060306 Ack receipt of 820827 ltr informing NRC of steps taken to implement recommendations nated in IE Emergency Preparedness Appreisal Rept 30-029/81-20
 SMITH, 0 H Division of Emergency Preparedness & Operational Support 82/09/27 HEIDER, L H Yankee Atomic Electric Co ip 15619 230 24, Fiche 50-029, 82/09/29, 8210060306
- --8210060310 Responds to NRC 820630 ltr re findings noted in IE Emergency Preparedness Appraisal Rept 50-027/81-20 Corrective actions chemistry personnel placed on radio pager sys to afford earlier notification & response HEIDER, L H Yankes Atomic Electric Co 82/08/27 HAYNES, R C Region 1, Office of Director. & 2pp 15619-231 24X Fiche 80-029,82/09/29.8210060306
- 8210210345 Forwards Amend 73 to License DPR-3 & notice of issuance Amend incorporates guard training & qualification plan, in response to licensee BioAio & 1208 applications CRUTCHFIELD,D Gerating Reactors Branch 5 82/09/30 KAY, J A Yankee Atomic Electric Co 3pp 15782 352, 24X Fichs 50-029, 82/09/30, 8210210345
- --B210210552 Amend 73 to License DPR-3, requiring implementation of guard training & qualification plan within 60 days & qualification of all security personnel within 2 yrs CRUTCHFIELD,D Operating Reactors Branch 5 82/09/30, 5pp 15782-355 24X Fiche 50-029, 82/09/30, 8210210545
- ---8210210555 Notice of issuance of Amend 73 to License DPR-3 CRUTCHFIELD, D Operating Reactors Branch 5 82/09/30 2pp. 15782 358 24X Fichs 50-029,82/09/30.8210210545
- 8210220153 Ack receipt of 820927 ltr informing NRC of steps taken to correct violations noted in IE Safeguards Insp Rept 50-027/82-08.
 STAROSTECKI.R. Division of Project & Resident Programs B2/10/15 HEIDERI.H Yankee Atomic Electric Co ip 15778,090. 24X Fiche 50-027/82/10/15,8210220153

- --9210220157 Responds to MRC 820901 ltr re violations noted in IE Safeguards Insp Rept 50-029/82-08 Corrective actions withheld (ref 10CFR2 790) HEIDER, L H Vantee Atomic Electric Co 82/09/27 HAYNES, R C Region t, Dffice of Director 2pp 15778 091 24X Fiche 50-029, 82/10/15, 8210220153
 - Operating license stage documents & correspondence
 - 10040399 Requests processing of listed documents re SEP Topic 11-04 E. "Dam Integrity" SHITH: H. Operating Reactors Branch 5 82/09/17 Division of Technical Information & Document Control 2pp 15597 226 24) Fiche 50-029, 82/09/17, 8210040399
 - i0040132 Forwards safety evaluation & technical evaluation repts of licensee response to proposed design mods to degraded grid voltage Schadule for response requested within 30 days CRUTCHFIELD. D Operating Reactors Branch 5 82/09/27 KAY. J A Yankee Atomic Electric Co 2pp (5583 095 24% Fiche 50-029, 82/09/27, 82/0040632
 - 8210040139 Bafety evaluation re degraded grid voltage protection for Class IE sys Design acceptable subj to resolution of listed items * Operating Reactors Branch 5 82/09/27 7pp 15583 097 24% Fiche 50-029,82/09/27.8210040132
- -8209200475 "Proposed Design Mods & Tech Spec Changes on Grid Voltage Degradation for Yankee Rows Nuclear Power Station." technical syaluation rept SELANJ C Lawrence Livermore Laboratory FIN A-0250 UCID-19147 82/07/30 NRC - No Detailed Affiliation Given 13pp 15583 104 24X Fiche 50-029,82/09/27,8210040132
- 210120207 Forwards safety evaluation of SEP Topic JII-4 C reinternally generated missiles Generation of internal missiles within facility will not prevent safe shuddown CARUSO.R Operating Reactors Branch 5 82/09/29 KAY, J A Yankee Atomic Electric Co 28pp. 15652 155 24X Fiche 50-029,82/09/29,82/10120207
- 1210080098 Proposed Change 178 to License DPR-3,adding & deleting containment isolation valves, specifying equipment parameters, adding new equipment & recategorizing valves to accommodate mod implementation during refueling outage HEIDER-L H Yankee Atomic Electric Co 82/09/30 Office of Nuclear Reactor Regulation, Director 9pp 15640 244 24k Fiche 50-029, 82/09/30, 8210080098
- --8210080102 Proposed Tech Spec pages, adding & deleting containment isolation valves, specifying equipment parameters, adding new equipment & recategorising valves to accommodate mod implementation during refueling outage * Yantee Atomic Electric Co 82/09/30 22pp. 15640 253 24X Fichs 50-029, 82/09/30, 8210080078
- 8210120245 Forwards safety evaluation & technical evaluation repts of SEP Topics II-3, A, II-3 8, II-3 8 1 & II-3 C re hydrologic considerations Facility does not meet NRC criteria Deviations will be resolved in integrated safety assessment, CARUSO, R Operating Reactors Branch 5 82/09/30 RAY, J. A. Yanke, Atomic Electric Co. 31pp 15651 001 24X Fiche 50-029, 82/09/30, 82/0120245
- --8208100269 "Hydrological Considerations (SEP, II-3 A,B,B 1,C,III-3 B)," technical evaluation rept SHERRER, J Franklin Institute/Franklin Research Center. NRC-03-79-118 TER-05257-426 92/08/06 BTALEY, Q NRC No Detailed Affiliation Given Bipp. 15651:032 24X 129,82/09/30,8210120245

- ~-8210210552 Amend 73 to License DPR-3, requiring implementation of guard training & qualification plan within 60 days & qualification of all security personnel within 2 yrs CRUTCHFIELD, D. Operating Reactors Branch 5 82/09/30 5pp 13782 355 24X Fiche 50-029, 82/09/30,8210210545
- --8210210555 Notice of issuance of Amend 73 to License DPR-3 CRUTCHFIELD.D Operating Reactors Branch 5 82/09/30 2pp 15782 358 24X Fiche 50-029,82/09/30.8210210545
- B210070169 Forwards topic difference summary for SEP Topic III-6, "Seismic Design Considerations" & updated difference summaries for Topics V-10 B.V-11 B.VII-3 & IX-3 re RHR sys & sys required for safe shutdown CARUSO, R. Operating Reactors Branch 5 B2/10/01 KAY, J. A. Yankre Atomic Electric Co. 7pp. 15627.001 24X Fiche 50-029, B2/10/01, B210070169
- 8210070085 Forwards drart safety evaluations of SEP Topics III-6 reseismic design considerations & SEP III-11 recomponent integrity Licensee proposal rededicated but shutdown syswall be evaluated during integrated assessment of facility CARUSO.R Operating Reactors Branch 5 82/10/04 KAY.J A Yankee Atomic Electric Co 20pp 15628 331 24X Fiche 50-029.82/10/04, 8210070085
- ---821007009["Seismic Design Bases & Criteria for Yankee Rowe Quiereting Station SEP " % Engineering Decision Analysis Company, Inc. EDAC 173-130 02 DRF 79/01/31 29pp 15628 351 24X Fiche 50-029,82/10/04, 8210070085
- --8210070094 "SEP, Review of Seismic Re-evaluation Program of Yankee Nuclear Power Station" * NRC - No Detailed Affiliation Given 82/09/30 85pp 15629 018 24X Fiche 50-029, 82/10/04, 8210070085
- --B210070099 "Technical Evaluation of Yankee Rows Power Station Seismic Design," Aug 1982 SRIDGES, T.L., BUSCH, S.L., THUMPSUN, T.R. EG&G, Inc. FIN A-6426 EGG-EA-6017 82/09/31 CHENO. T. Division of Licensing 253pp 15629 100 24x Fiche 50-029, 82/10/04,8210070Q05
- 8210130326 Comments on proposed scope of Phase III of SEP as reflected in individual topic definitions appended to 820709 ltr.
 Staff encouraged to devetop & implement means to incorporate positive attributes of Phase III in licensee/NRC interface KACICH:R H SEP Owners Oroup KACICH:R H Northeast Nuclear Energy Co (subs of Northeast Utilities) 82/10/07 CISENHUT D O Division of Licensing 7pp 15682 179 24X Fiche 50-000,82/10/07,8210130326
- 8210130401 Concurs W/content of systematic assessment of licenses performance board recommendations.per NRC B20703 itr Licenses action on primary vent stack monitor failures should be clarified to show thorough evaluation of LERs KAY.J Yankes Atomic Electric Co B2/10/08 STARQSTECKI.R Division of Project & Resident Programs 2pp 15482 070 24X Fiche 50-029.82/10/058.8210/130401
- 82:0150363 Responds to Generic Ltr 82-12 re plant working hours Plant policy re working hours should not be incorporated into Tach Specs due to loss of flexibility KAY. J A Yankee Atomic Electric Co 82/10/08 EISENHUT, D O Division of Licensing 2pp 15704 305 24X Fiche 50-027, 82/10/00, 82:0150363
- 8210180187 Clarifies 820804 request for add1 info re NUREO-0737.

 Item II B 3, "Post-Accident Sampling Sys " Guidance on meeting NUREO-0737 criteria discussed CRUTCHFIELD D Operating Reactors Branch 5 82/10/08 KAY, J A Yantee Atomic Electric Co 3pp 15719,130 24X
 Fiche 30-029,82/10/08,8210180187
- B210210123 Forwards evaluation of SEP Topic III-3 A. "Effects of High Mater Level on Structures," based on B20318 SAR Turbine & svc bidgs: screenwall & pumphouse unprotected from postulated flood condition CARUSO.R Operating Reactors Branch 5 B2/10/13 KAY.J A Yankee Atomic Electric Co. 7pp 15766 027 24X Fiche 50-027,82/10/13,8210210123
- B2101904B6 Application to amend License DPR-3, replacing 40 fuel essemblies to refuel for Core XVI operation & inserting cycle dependent parameters in Tech Spece HEIDER, L H Yankee Atomic Electric Co 82/10/15 Office of Nuclear Reactor Regulation, Director 2pp 1873B 165 24X Fiche 50-029, 82/10/15, 8210170686
- --B210190690 Proposed Tech Spec mod inserting cycls dependent parameter > Yankee Atomic Electric Co B2/10/15 25pp, 15738 167 24X Fiche 50-029,82/10/15,8210190686,

- 8210C80094 Application to amend App A of License DPR-3, consisting of Proposed Change 179, allowing increase in plant operating elexibility while maintaining sufficient RHR flow to ensure reactor vessel water temp does not exceed 140 F in Mode 6 HEIDER.L H Yankee Atomic Electric Co 82/10/15 Office of Nuclear Reactor Regulation, Director 2pp 15837 185 24X Fiche 50-029, 82/10/15, 8210280094
- --8210280103 Proposed Tech Spec Change 179, allowing increase in plant operating flexibility while maintaining sufficient RHR flow to ensure reactor vessel water temp does not exceed 140 F in Mode 6

 * Yankee Atomic Electric Co 82/10/15 4pp 15837 187 24X Fiche 50-029, 82/10/15, 8210280094
- O Inspection reports: IE Bulletins & correspondence
- 8210070097 Responds to FOIA request for eight categories of records re steam generators & steam turbines App A documents provided in R Udeli FOIA Request 81-313 Forwards documents listed in App D FELTON, J H Division of Rules and Records 82/08/10 LONG, D J Winthrop, Stimson, Putnam & Roberts 9pp 15645 063 24X Fiche 50-000, 82/08/10, 8210070007
- --B210070139 Forwards tabulated data on steam generator insp & maint at racilities Data should be provided to licensees
 IPPOLITO.T Operating Reactors Assessment Branch B2/04/01
 VAROA.B Operating Reactors Branch 1 CLARK.R Operating
 Reactors Branch 3 STOLZ.J Operating Reactors Branch 4 Spp
 15445 [3] 24X Fiche 30-000.B2/08/10.B210070007
- --8210070172 Forwards info re steam generator integrity & insps at all operating PMRs.per 750320 & 21 requests Details of insps, including defect indications, tube plugging criteria & tubes plugged uill not be provided except for Point Beach i GOLLER, K R Division of Reactor Licensing (NRR-1975 only) 75/03/24 MACCARY, R Division of Technical Review (NRR-1975 only) 5pp 15645 192 24X Fiche 50-000, 82/08/10, 8210070007
- 8210060034 Forwards IE Safeguards Insp Rept 50-027/82-09 on 820802-05 No noncompliance noted MARTIN.T T Division of Engineering & Technical Programs 82/09/27 HEIDER.L H Yankee Atomic Electric Co 2pp 15615-051 24X Fiche 50-029, 82/09/27, 8210060034
- --8210060049 IE Safeguards insp Rept 50-029/82-09 on 820802-05 No noncompliance noted Major areas inspected testing & maint records, physical barriers in protected & vital areas & security sys power supply Details withheld (ref 100FR73 21) DUNLAP, J M . SMITH, 0 C . GDDY, A T Division of Engineering & Technical Programs 82/09/23 ip 15615 053 24X Fiche 50-029, 82/09/27, 8210060034
- 8210060306 Ack receipt of 820827 itr informing NRC of steps taken to implement recommendations noted in IE Emergency Preparedness Appraisal Rept 50-029/81-20 SMITH.0 H Division of Emergency Preparedness & Operational Support 82/09/29 HEIDER,L H Yankee Atomic Electric Co ip 15619 230 24/ Fiche 50-029.82/09/29.8210060306
- --B210060310 Responds to NRC B20630 ltr re findings noted in IE Emergency Preparedness Appraisal Rept 50-029/81-20 Corrective actions chemistry gersonnel placed on radio pager sys to afford earlier notification & response
 HEIDER, L. H. Yankee Atomic Electric Co. B2/08/27 HAYNEB, R. C. Region 1, Office of Director 62pp 19619-231 24X
 Fiche 50-029/82/09/29/8210060306
- 82:0120272 Forwards avaluation of util response to BEP Topic III-3 C, "Inservice Insp of Water Control Structures " Present insp program does not conform w/Reg Guide 1 127 & should be modified to incorporate NRC recommendations CARUSO,R Operating Reactors Branch 5 82/10/04 KAY, J A Yanke Atomic Electric Co 10pp 15651 190 24X Fiche 50-027,82/10/04, 8210120272
- --8207190431 "Hydrological Considerations.Inservice Insp of Mater Control Structures (SEP III-3 C). Yankee Rowe Nuclear Power Station." technical evaluation rept SCHERRER, J Franklin Institute/Franklin Research Center NRC-03-79-118 TER-05257-544 82/07/15 STALEY.0 NRC No Detailed Affiliation Given 29pp 15651 200 24X Fiche 50-029,82/10/04.8210120272
- 8208190233 IE Info Notice 80-35, Suppl i, "Leaking & Dislodged I-125 Implant Sweds " Svc list encl COBBL I Division of Fuel Facilities, Materials & Safeguards 82/10/06 Consolidated Edison Co of New York 66pp 15761 250 24X Fichs 50-000, 82/10/06, 8208190233

- 8210130401 Concurs w/content of systematic assessment of licensee performance board recommendations.per NRC 820703 itr Licensee action on primary vent stack monitor failures should be clarified to show thorough evaluation of LERs KAY. J Yankee Atomic Electric Co 82/10/08 STAROSTECKI.R Division of Project & Resident Programs 2pp 15682 070 24X Fiche 50-029.82/10/08.8210130401
- 8210290147 Forwards IE Insp Rept 50-029/82-10 on 820802-0930 No noncompliance noted STARDSTECKI,R Division of Project & Resident Programs 82/10/08 HEIDER,L H Yankee Atomic Electric Co 2pp 15854 214 24X Fiche 50-029,82/10/08.8210290147
- --8210270157 IE Insp Rept 50-029/82-10 on 920802-0903 No noncompliance noted Major areas inspected review of plant operation, plant maint observation, plant events, LERs, licensee plant info rept, periodic & special repts & preparation for refueling COLLING. S J, OALLOR M Division of Project & Resident Programs 82/10/07 16pp 15954 216 24X Fiche 50-029, 82/10/08.8210290147
- 8208190238 IE Bulletin 82-03, "Stress Corrosion Cracking in Thick-Wall. Large-Diameter: Stainless Steel. Recirculation Sys Piping at BWR Plants " Svc list encl DEYOUNG.R C Director's Office. Office of Inspection and Enforcement 82/10/14 Consolidated Edison Co of New York 155p 15810 125 24X Fiche 50-000.82/10/14.8208190238
- 8210220153 Ack receipt of 820727 ltr informing NRC of steps taken to correct violations noted in IE Safeguards Insp Rept 50-027/02-08

 STAROSTECKI.R Division of Project & Resident Programs 82/10/15
 HEIDER.L H Yankee Atomic Electric Co ip 15778 090 24X
 Fiche 50-027.82/10/15.8210220153
- --8210220157 Responds to NRC 820701 ltr re violations noted in IE Safeguards Insp Rept 50-027/82-08 Corrective actions withheld (ref 10CFR2 770) HEIDER.L H Yankee Atomic Electric Co 82/09/27 HAYNES.R C Region 1, Defice of Director 2pp 15778 091 24X Fiche 50-029, 82/10/15.8210220153
- S Reportable occurrences. LERs & related correspondence
- 8210010008 Responds to FOIA request for 19 categories of documents re nuclear reactor events & safety problems Forwards documents listed in App A FELTON, J M Division of Rules and Records 82/06/28 UDELL.R A Critical Mass Energy Project 15pp 15727 009 24X Fiche 50-000, 82/06/28,8210010008
- --8109280175 Requests add1 info re loss of offsite power event on 810914. SANDS 8 F Director's Office 81/09/18 CARUSD R Operating Reactors Branch 5 ip 15730 250 24% Fiche 50-000,82/06/28, 8210010008
- --B210010161 Discusses potential problem re sequoyah reactor pressure notzle, supplementing 800222 memo Underclad cracks found by use of ultrasonic equipment Addl items of recent origin discussed Related info encl
 DENTON.H R Office of Nuclear Reactor Regulation, Director 80/02/28 AHEARNEJ Commissioners 9pp 15727 178 24X Fiche 50-000, 82/04/28, 8210010008
- 8210130230 Forwards LER 82-025/03L-0 AUTIO.H.A Yankse Atomic Electric Co 82/09/30 HAYNES,R C Ragion 1, Office of Director 1p 15675 269 24X Fiche 50-029,82/09/30,8210130230
- --8210130235 LER 82-025/03L-0 on 820831.gas leak developed in weld joining safety valve drain line to valve body on waste gas decay 2 drum safety valve Cause not stated Leaking weld isolated.ground out & rewelded RICE.D A Yanker Atomic Electric Co 82/09/30 Region 1, Office of Director 1p 15675 270 24X Fiche 50-029,82/09/30,8210130230
- 8210130218 Forwards LER 82-027/03L-0 AUTIG.H A Yanker Atomic Electric Co 82/10/01 HAYNEB,R C Region 1. Office of Director 1p 15675 235 24X Fiche 50-027,82/10/01.8210130218
- --8210130225 LER 82-027/03L-O on 820902.while in Mode 1.auxiliary boiler room sprinkler sys isolated to stop & repair gasket leak Caused by insufficient gasket contact w/valve*F8-V-739 Gasket replaced.

 MAY.E L Yankse Atomic Electric Co 82/10/01 Region 1. Office of Director ip 15675 236, 24X Fiche 50-029,82/10/01.

3210130519 Forwards LER 82-026/03L-0 AUTIO.H A Yantse Atomic Electric Co 82/10/01 HAYNEB,R C Region I. Office of Director 1p 15482 361 24X Fiche 50-027,82/10/01.8210130519

-B210130531 LER B2-026/03L-0 on B20902.while performing surveillance of low main coolant flow eye train A, boop 3, phase C relay failed to drop out when de-energized Caused by abnormal amount of friction between plunger & upper bushing FRENCH.L D Yantee Atomic Electric Co B2/10/01 Region 1. Office of Director 1p 15692 362 24% Fiche 50-029,82/10/01, 8210130519

1210260109 LER B2-032/01T on B21006.positive indication observed during shipping of second cycle fuel assembly B-578 Analysis shows assembly caused alight increase in reactor coolant activity during tore 15 operation AUTIO.H A Yantee Atomic Electric Co B2/10/07 HAYNES.R C Region 1. Office of Director ip 15799 116 24X Fiche 50-029.82/10/07.8210260109

210290267 Part 21 deficiency rept re-potential galling problem between stem & bonnet of 1 25-inch & larger A105 carbon steel & A182-F22 valves supplied Feb 1981-Aug 1982 Valves should be serviced & stem & Are bonnet replaced ISABELLE.L D Conval. Inc 82/10/11 HAYNES.R C Region 1, Office of Director 17pp 19854 202 24X Fiche 50-000.82/10/11.

210240105 RU 50-29/82-33 on B21009, main codiant pump 1 vent isolation valve weld discovered slightly moist Weld will be repaired during current refueling outsge
AUT10, H A Yantee Atomic Electric Co 62/10/12 HAYNES, R C
Region 1. Office of Director 1p 15799 119 24X
Fiche 50-029, 82/10/12, 8210260106

'10260165 Forwards LER 82-029/03L-0 AUTIO.H A Yanise Atomic Electric Co 82/10/13 HAYNES,R C Region 1, Office of Director 1p 15799 001 24X Fiche 50-029.82/10/13.8210260165

8210260169 LER 82-029/03L-0 on 820913.during refueling outage in Mode 5 while performing calibr of steam generator marrow-range level trip susstrip setpoint 3 found less than Yech Spec limit Caused by astpoint 6 for ft FRENCH.L D Yantee Atomic Electric Co 82/10/13 Region 1, Office of Director ip 15799 002 24X Fiche 50-029,82/10/13, 821026015

t0260428 LER B2-035/01T on B21013, reactor protection sys permissive sistables B/S 420 & B/S 423 found calibr out of tolerance caused by survaillance procedure inadequacy Bistables ecalibr UUTIO, HA Yankee Atomic Electric Co 82/10/13 HAYNES, R C legion 1. Office of Director. 1p 15806 293 24X tehe 50-029, B2/10/13, B210260428

0280085 LER 82-032 has been canceled IUTIO.H A Yantee Atomic Electric Co 82/10/20 HAYNES,R C legion 1. Office of Director 1p 15837 183 24X tche 50-029, 82/10/20,8210280085

KET 50-54 UNION CARBIDE RESEARCH REACTOR

Operating license stage documents & correspondence

0:30302 Forwards figures inadvertently omitted from 800523 pplication for renswal of License R-81 & addl minor hanges to Tech 89ess
OTM:N H Union Carbide Corp 82/09/29 BERNARD.H tandardization & Spacial Projects Branch 15pp 15670 318 24X ichs 30-034.82/09/29.8210120302

210130306 Proposed Tech Spec changes re fueled experiments to staffing, supplementing 800523 application to rense License R-Bi union Carbide Corp. 82/09/29 5pp. 15678-333 24X Fiche: 50-054.82/09/29.8210130302

KEY 50-57 STATE UNIV OF NEW YORK RESEARCH REACTOR Security, medical, emergency & fire protection plans

0010277 Forwards Revision 4 to security plan Revision withheld ref 10CFR2.790) ENRY.L. 0 New York, State Univ of, Buffalm 82/09/17 THOMAS, C tandardistation & Special Projects Branch. 1p 13573 121 24X 1che: 50-057, 82/09/17, 8210010277

DOCKET 50-42 UNIV OF VIRGINIA RESEARCH REACTOR

E NRC Safety Evaluation Report (SER), supple & correspondence

8210050377 9AFETY EVALUATION REPORT RELATED TO THE RENEWAL OF THE OPERATING LICENSE FOR THE UNIVERSITY OF VIROINIA OPEN-POOL RESEARCH REACTOR Docket No 50-062 Paylsion of Licensing NUREG-0928 92/09/30 77pp Available at NRC \$500 15626 030 24% Fich \$50-062,82/09/30,8210050377

P Operating license stage documents & correspondence

8210060086 Informs of minor mods made to ECCS piping Flexible piping installed on tank side of remote coupling to provide necessary movement for coupling alignment Repair will have no adverse effect on ability of ECCS to perform BRENIZER.J S Virginia Univ of 82/09/27 Standardization & Special Projects Branch 6pp 15615 038 24% Fiche 50-062, 82/09/27, 8210060086

B210080237 Forwards licensee B20929 ltr to ORNL requesting shipment of DDE-owned MTR type reactor fuel using MFIR spent fuel shipping cash BENNECHE,P E Virginia, Univ of B2/09/30 CARTER,R E Standardization & Special Projects Branch | 3pp | 15638 078 | 24X Ficha 50-062,82/09/30,8210800237

8210120475 Forwards Amend 15 to License R-66.EIA & notice of issuance/ negative declaration Amend Tenews OL for 20 yrs THOMAS.C O Standardization & Special Projects Branch B2/09/30 BRENIZER J 5 Virginia Univ of 2pp 15672 005 24X Fiche 50-062:82/09/30.8210120475

--8210120480 Amend i5 to License R-66 renewing OL for 20 yrs
THOMAS.C D Standardization & Special Projects Branch 82/09/30
34pp 15672 007 24% Fiche 50-062.82/09/30.8210120475

--8210120487 ElA supporting Amend 15 to License R-66 * Standardization & Special Projects Branch 82/09/30 3pp 15672 042 24X Fiche 50-062.82/09/30,8210120475

--8210120492 Notice of renewal of facility OL & negative declaration re Amend 15 to License R-66 THOMAS.C O Standardization & Special Projects Branch 62/09/30 2pp 15672 049 24X Fiche 50-062.82/09/30.8210120475

8210180014 Submits daily highlight for 820930 NRA issued 20-yr renewal of License R-66 CARTER: R E Btandardization & Special Projects Branch 82/10/01 CASE.E . CARTER: J Office of Nuclear Reactor Regulation, Director EISEN

OOCKET 30-70 GENERAL ELECTRIC TEST REACTOR

G Adjudicatory correspondence

8210200087 Notice of ASLB reconstitution OH Frye, chairman & H Foreman & GA Linenberger, members COTTER: 8 P Atomic Safety and Licensing Board Panel 82/10/14 2pp 15753 196 24X Fiche 50-070, 82/10/14, 8210200087

8210220343 Memorandum & order directing OE to file rept on intention to submit applications to renew OL & SNM license, within 15 days of svc of order FRYE, J H Atomic Bafety and Licensing Board Panel 82/10/21 General Electric Co 3pp i5776 265 24X Fiche 50-070,82/10/21,8210220343

P Operating license stage documents & correspondence

8210230110 Application to amend License TR-1, requesting add1 Tech Epec changes reflecting removal of irradiated SNM by eliminating tests re reactor bldg integrity GUNNINAMA, 0 E. General Electric Co. 82/10/12 TEDESCO, R L. Assistant Director for Licensing 2pp 15787 028 24X Ficha 50-070, 82/10/12, 8210250110

--8210250113 Proposed Tech Spec changes reflecting removal of irradiate SMM by eliminating tests re reactor bldg integrity * Ceneral Electric Co. 82/10/12 2pp. 15707 030 24% Fiche 50-070.82/10/12.9210250110

- DOCKET 50-72 UNIV OF UTAH RESEARCH REACTOR
- A Periodic operating reports & related correspondence
- 8210260224 Ack receipt of 820924 ltr forwarding revised annual operating rept for 1981
 SEIDLEW C Division of Resident, Reactor Project & Engineering Programs 82/10/22 JAC088,H R Utah Univ of ip 15799 156
 24x Fiche 50-072
- ~~8210260230 Forwards revised "Annual Operating Rept.1981"

 JACOBS.H R Utah. Uni. of 82/09/24 MADSEN.G L Region 4.

 Office of Director 1p 15799 157 24X Fiche 50~072, 82/10/22.

 8210260224
- --B210260234 Revised "Annual Operating Rept. 1981" SANDOUIST.G M. Utah. Univ of B2/07/24 2pp 15799 158 24% Fiche 50-072, 82/10/22, 8210260224

DOCKET 50-83 UNIV OF FLORIDA TRAINING REACTOR

- G Inspection reports, IE Bulletins & correspondence
- 8210010120 Forwards IE Insp Rept 50-089/82-02 on 820811-13 No noncompliance noted VERRELLI.D H Division of Project & Resident Programs 82/08/31 JACOBS.A M Florida. Univ of, Gainesville 2pp 15566 032 24X Fiche 50-083.82/08/31.8210010120
- --0210010122 IE Insp Rept 50-083/82-0P on 920811-13 No noncompliance noted Major areas inspected radiation protection PERM, WW . BARM. R.P. Division of Engineering & Technical Programs 92/08/30 3pp 15566 034 24% Fiche 50-083,82/08/31, 9210010120

DOCKET 50-133 HUMBOLDT BAY POWER PLANT, UNIT 3

- F Security, medical, emorgency & fire protection plans
- 6210010198 Forwards safeguards info or changes implemented in security plan info withheld (ref 10CR73 21)
 CRANE.P A Pacific Qas & Electric Co 82/09/23 DENTON,H R
 Dfrice of Nuclear Reactor Regulation, Director ip 15568 077 24X
 Fiche 50-133,82/09/23,8210010198
- G Adjudicatory correspondence
- 8210060189 Order extending time until B21012 for Commission to act to review Director's Decision DD-82-7 CHILKS J Office of the Secretary of the Commission 92/10/04 Commissioners 1p 15613 228 24X Fiche 50-133,82/10/04.
- 82:0150193 Advises that Commission declined review of Director's Decision DD-82-7 Time for Commission to act expired Decision became final agency action on 82/10/2 CHILKS J Office of the Secretary of the Commission 82/10/13 GUENTHER.R Affiliation Unknown ip 15707 259 24X Fiche 50-133.82/10/13.82/0150192
- P Operating license stage documents & correspondence
- 8210240359 Responds to Generic Ltr 82-12, "Policy on Factors Causing Fatigue of Operating Personnel at Nuclear Reactors "Elisting procedures comply w/policy statement CRANELP A Pacific Cas & Electric Co 82/10/21 MIRAQLIA, F J Licensing Branch 3 1p 15804 258 24% Fiche 50-133,82/10/21, 2010/20059
- O Inspection reports. IE Bulletins & correspondence
- 8208190233 IE Info Notice 80-35, Suppl 1, "Leaking & Dislodged I-125 Implant Seeds " Syc list encl COBB.L I Division of Fuel Facilities, Materials & Safeguards 82/10/06 Consolidated Edison Co of New York 64pp 19761 250 24X Fiche 50-000,82/10/06,8208190233
- 8208190238 IE Bulletin 82-03, "Stress Corresion Cracking in Thick-Natl. Large-Dismeter: Stainless Steel. Recirculation Sys Piping at BWR Plants "Svc list encl DEYGUNG.R C Director's Office, Office of Inspection and Enforcement 82/10/14 Consolidated Edison Co of New York 115pp 15810 125 24X Fiche 50-000, 82/10/14,8208190238

- R Periodic operating reports & related correspondence
- 8210250192 Forwards third quarterly status rept re plant operational status & util activities.per 820216 order Study re future disposition of plant uill be completed within 4 months of issuance of NRC final reactor safety policy statement OHLBACH.R., CRANE.P.A., LOCKE.R.F. Pacific Oas & Electric Co BZ/10/01 LAZO.R.H. SCHINK,D.R. LIMENBERGER.O. Atomic Safety and Licensing Board Panel 2pp 15787 336 24X Fiche 50-133,82/10/01,8210250192
- --8210250195 Third quarterly status rept for facility Certificate of Svc enci LOCKE.R F Pacific Gas & Electric Co 82/10/01 4pp 15787 338 244 Fiche 50-133,82/10/01,8210250192

DOCKET 50-142 UCLA TRAINING REACTOR

- F Security, medical, emergency & fire protection plans
- 8210290023 Partial response to FDIA request for documents re UCLA Lab & research reactors Forwards documents listed in App A FELTON.J M Division of Rules and Records 82/07/03 HIRSCH, D government Accountability Project 2pp 15864 195 24X Fiche 50-142,82/09/03,8210290023
- ~-8210290036 Requests that licensee submit new physical security plan to comply w/new regulations to 10CFR50.70 & 73 by 740107 SKOVHOLT.D J Atomic Energy Commission. Directorate of Licensing 73/11/30 HICKS.T E California. State of 1p 15864 259 24) Fiche 50-142.82/09/03.8210290023
- --8210290043 Forwards add1 info re physical security plan Info withheld (ref 10CFR2 790)
 ASHBAUGH, C E California. Univ of, Los Angeles 74/11/27
 GOLLER, K R Atomic Energy Commission, Directorate of Licensing 1p 15844 260 24X Fichs 30-142.82/09/03.8210290023
- --8210270051 Forwards SNM inventory info for nonpower reactor facilities Info withheld (ref 10CFR2 770) Authorization to retain inventory requested ASHBAUOH.C E California. Univ of, Los Angeles 76/01/30 OCLLER.K R Division of Operating Reactors 2pp 15864 263 24X Fiche 50-142,82/07/03.8210290023
- --8101200322 Notifies that since reactor operating & SNM storage sites are contiguous. Facility must implement interim Category I physical security requirements Compliance plan required by BIOL31

 MILLER.J R Standardization & Special Projects Branch 81/01/12

 MEOST, W F California. Univ of, Los Angeles ip 15865 093

 24X Fiche 50-142.82/09/03.8210270023

O Adjudicatory correspondence

- 8210080077 Response supporting Committee to Bridge the Cap B20720 motion for summary dismissal of NRC & util 820701 & 03 motions for summary disposition ABLB statements on use of summary disposition flagrantly disregarded by NRC & util 8HRLEY, 8 J Santa Monica, CA 82/10/06 Atomic Safety and Licensing Board Panel App 15640 193 24X Fiche 50-142,82/10/06,8210090077
- 8210120261 Response opposing Committee to Bridge the Gap 820920 motion to dismiss NRC & applicant 820901 summary disposition motions Extension until 82110 should be granted to allow Committee response W/Certificate of Svc WOODHEAD.C P Hearing Branch I 82/10/08 Atomic Bafety and Licensing Board Panel 26pp 15652 184 24X Fiche 50-142,82/10/08, 82/0120261
- 8210190456 Response opposing Committee to Bridge the Qap 820920 motion to dismiss NRC & util motions for summary disposition Commission rules preclude dismissel of summary disposition motions filed per schedule W/Certificate of Svc CORMIER W H Celifornia, Univ of, Los Angeles, 82/10/08 Atomic Bafety and Licensing Baard Panel 19pp 18703 132 24% Fiche 50-142,82/10/08,8210150456
- 8210250076 Forwards UCLA 821008 ltr to NRC amending Feb 1980 license renswal application Changes include reducing licensed limit on permissible inventory of fuel to less than 500 g enriched U-235 CORMIER. W H Californie. Univ. of. Los Angeles. 82/10/15 FRYEL J H., PARIB. O H. LUEBKE. E A Atomic Sefety and Licensing Board Panel 11sp 15789 352 24X Fiche 50-142.82/10/15.8210250076

8210250223 Hemorandum & order denying Committee to Bridge the Gap (CBG) 820920 motion to summarily dismiss NRC & util motions for summary disposition or alternative relief UCLA,NRC & CBG must furnish lists of citations of mati fact LUEBKE,E A: PARIS,O H: FRYE.J H: Atomic Safety and Licensing Board Panel 82/10/22 Committee to Bridge the Gap 12pp 15789 314 24X Fiche 50-142,82/10/22,8210250223

P Operating license stage documents & correspondence

- 8210130115 Requests amend to application for 10CFR70 license to reflect reduced inventory of unitradiated U-235 reactor fuel THOMAS.C Q Standardization & Special Projects Branch 82/09/27 WEOST.W F California Univ of Los Angeles ip 15696 082 24% Fiche 50-142.82/09/27.8210130115
- 82[020008] Application for amond to Feb 1980 renewal application for License R-71, replacing pages re reduction of permissible inventory of reactor fuel & altering purpose & function of safety high level radiation monitor HEOST. H F California. Univ of, Los Angeles 82/10/08 THOMAS, C O Standardization & Special Projects Branch 10pp 15753 198 24X Fiche 50-142,82/10/08,821020008]
- B210250076 Forwards UCLA B21008 ltr to NRC amending Feb 1980 incense renewal application Changes include reducing licensed limit on permissible inventory of fuel to less than 500 g enriched U-235 CORMIER.H H California, Univ of, Los Angeles 82/10/15 FRYE.J H , PARIS.Q H , LUEGHE.E A Atomic Safety and Licensing Board Panel lipp 15789 352 24X Fiche 50-142.82/10/15.8210250076

Q Inspection reports: IE Bulletins & correspondence

- B210270023 Partial response to FOIA request for documents re UCLA Lab & research reactors Forwards documents listed in App A FELTON.J M Division of Rules and Records B2/09/03 HIRSCH.D Government Accountability Project 2pp 15864 195 24X Fiche 50-142.82/09/03.8210270023
- --8210290048 Discusses ansp of activities authorized under License R-71 & SNM-974 on 790520 No noncompliance noted Hajor areas inspected control of SNM & selective exams of procedures & personnel interviews

 ENDELKEN.R H Region 5. Sam Francisco. Office of the Director 75/06/10 BROWN.R V California. Univ of Los Angeles ip 15864 262 24X Fiche 50-142.82/09/03.8210290023

DOCKET 50-148 UNIV OF KANSAS RESEARCH REACTOR

H General correspondence

- B208270090 FOIA request for six documents to Univ of KS research reactor
 ROBINSON B Affiliation Unknown B2/09/07 FELTON, J M Division of Rules and Records 2pp 15436 210 24X Fiche 50-148,82/09/07,8208290990
- 8208290097 FOIA request for documents re thiv of KS research reactor BARNES: C Affiliation Unknown 82/09/07 Docketing & Services Branch 1p. 15839 119 24X Fiche 50-148,82/09/07.8208290097
- 8210060437 Responds to FOIA request for six documents re Univ of KS research reactor Request referred to PDR for processing FELTON.J M Division of Rules and Records 82/09/13 ROBINSON, 8 Affiliation Unknown 1p 15636 212 24X Fiche 50-148,82/09/13,8210060437
- 8210280389 Responds to FOIA request for listed documents re Univ of KS research reactor Request referred to PDR for processing FELTON, J K Division of Rules and Records 82/09/14 BARNES, C Affiliation Unknown 1p 15859 120 24X Fiche 50-148,82/09/14,8210280389

DOCKET 50-151 UNIV OF ILLINOIS RESEARCH REACTOR

8 Reportable occurrences. LERs & related correspondence

8210130476 RO From 820103-0505 reactor operated under reactor operator u/expired license. Caused by oversight Unicensed operator in charge of operation for approx 50-h.Individual filing application for license BECK. O.P. Illinois, Univ. of, Urbana-Champeign 82/09/29 Division of Licensing 2pp 15682-161 24X Fiche 50-151-82/09/29, 8210130476

- DOCKET 50-155 BIG ROCK POINT NUCLEAR PLANT
- F Security, medical, emergency & fire protection plans
- 8210060222 Forwards addl fire protection info re associated circuits, alternate safe shutdown design & emergency condensor caustic attack in response to NRC 820430 ltr & NRC questions raised during 820908-09 site meeting concerning 10CFR50 App R VANDEMALLE.D J Consumers Power Co 82/09/28 CRUTCHFIELD.D Operating Reactors Branch 5 57pp 15620 062 24X Fiche 50-155,82/09/28,8210060222
- 8210080279 Confirms commitment to incorporate responses to IE Insp Rept 50-155/81-17 into emergency plan implementing procedures & requests approval to use general off control ctr as tamporary emergency operations facility VANDENALLE. D J Consumers Power Co 82/10/01 KEPPLER. J G Region J. Office of Director 5pp 15638 203 24X Fiche 50-155.62/10/01.
- 8210200027 Forwards emergency preparedness pamphlet for use in 5-mile emergency planning zone in Charleyolx County & part of Emnet County Pamphlet incorporates revisions & mods set forth in ASLB 820806 partial initial decision GALLO.J Isham, Lincoln & Beale GALLO.J Consumers Power Co 82/10/14 GLOCH-P B . PARISO H . SHON.F J Atomic Gafety and Licensing Board Panel 30pp 15756 147 24X Fiche 50-155,82/10/14.
- 8210250371 Provides add1 info on proposed shift technical advisor position based on review of plant administrative procedures & site emergency plan & implementing procedures Min shift provides necessary protection in event of emergency BORDING.T C Consumers Power Co 82/10/19 CRUTCHFIELD.D Operating Reactors Branch 5 2pp 15790 186 24X Fiche 50-155, 82/10/19, 8210250371

G Adjudicatory correspondence

- 8210010408 Motion for extension of time until 821011 to file petition for reconsideration %/or motion for clarification reemergency planning portions of ASLD 820914 decision
 Certificate of Svc encl
 GALLO.J Consumers Power Co GALLO.J Isham, Lincoln & Deale
 82/09/28 Atomic Safety and Licensing Noard Panel Spp
 13572 176 24X Fiche 50-155.82/09/28.8210010408
- 8210010446 Forwards util 820716 itr to NRC re future scheduling matters in spent fuel pool mod proceeding Related correspondence GALLO, J Isham, Lincoln & Beale GALLO, J Consumers Power Co 82/09/29 BLOCK, P B . PARIS. D H . SHON, F J Atomic Safety and Licensing Board Panel 4pp 15572 272 244 Fiche 50-155.82/09/29, 8210010446
- 82100400BI Forwards proposed findings of fact & conclusions of law on UNeill Contention II E 3 recriticality GODDARD, R J Hearing Branch 3 82/10/01 BLOCH, P B , SHON, F J , PARIS, O H Atomic Safety and Licensing Board Panel 1p 15504 212 24X Fiche 50-155, 82/10/01, 82/00400B1
- --8210040083 Proposed findings of fact & conclusions of law on O'Neill Contention II E-3 re-criticality OODDARD:R J Hearing Branch 3 82/10/01 10pp 15584 213 24X Fiche 50-155.82/10/01.8210040081
- 6210050232 Proposed snittal decision on criticality contention Certificate of Bvc encl CALLO.J. THGRNTON.P Consumers Power Co CALLO.J. Isham, Lincoln & Beale 82/10/01 28pp 15610 353 24X Fiche 50~155,82/10/01. 8210030232
- 8210050356 Proposed findings of fact & conclusions of law on criticality contention Certificate of Svc encl
 OALLO, J. THORNTON, P. Consumers Power Co. GALLO, J. Isham, Lincoln
 8210050356
 8210050356
- 8210060204 Motion to establish hearing dates during wk of 821115-19 to litigate Christa-Maria Contentions 2.9(1),9(6),9(8) & 9(9) & 0'Neill Contentions II A.II D & II E-4 Early resolution of issues serves interests of parties W/Certificate of 8vc OALLO, J Consumers Power Co OALLO, J Callo, J 82/10/01 Atomic Safety and Licensing Board Panel 8pp 15614 162 24X Fichs 50-155, 82/10/01, 8210060204
- 8210060192 Order deferring briefing of Christa-Maria exceptions to ASLB 820913 third partial initial decision & tolling time for filing exceptions to future partial initial decisions until svc of last decision Piecameal review unproductive TOMPKINB, B A Atomic Bafety and Licensing Appeal Panel 82/10/04 3pp 15613,290 24X Fiche 50-155,82/10/04,8210060192

- 8210130448 Forwards reply to intervenor proposed findings of fact & carclusions of law on O'Noill Contention II-C re cask drop
 - COPELAND, V G Isham, Lincoln & Beale COPELAND, V G Consumers Power Co 82/10/06 8LOCK.P B , PARIS D H , SHON, F J Atomic Safety and Licensing Board Panel 1p 15682 118 24X Fiche 50-155, 82/10/06, 8210130448
- --8210130457 Reply to intervenor proposed findings of fact & conclusions of law on O'Neill Contention II-C recask drop issue GALLO, J. COPELAND, V. G. Consumers Power Co. GALLO, J. Isham, Lincoln & Beale 82/10/07 9p. 15682 119 24X Fiche 50-155,82/10/06,8210130448
- -8210130471 inffidavit of TC Bordine re util commitments to upgrade visual acusty requirement for crane operators to comply w/stds of ANSI 830 2-1976, "Goverhead & Gantrys Cranes" to cross-ref maint procedures Certificate of Svc encl 80RDINE, T C Consumers Power Co 82/10/05 4pp 15682 128 24x Fichs 50-155, 82/10/06. 82/10130449
- 9210150300 Motion for extension of time until B21203 for util to demonstrate that deficiencies are remedied are not serious or are being remedied Util has diligently pursued steps to address deficiencies GALLO, J. Consumers Power Co. GALLO, J. Isham, Lincoln & Beale 82/10/12 Atomic Safety and Licensing Board Panel. 5pp. 15707-273 24% Fiche 50-155,82/10/12,8210150300
- --B210150307 Affidavit of RW Sinderman re util actions in response to ASLB 820914 initial decision Add1 time required to assemble 2 document info in namer consistent w/ASLB request Certificate of Svc enc1
 SINDERMAN R W Consumers Power Co 82/10/11 14pp 15707 278 24X Fiche 50-155.82/10/12.8210150300
- B210150341 Responses opposing licensee motion to fragment hearing intervenors would be denied right to be represented by counsel, noney would be wasted & fragmentation would violate intent of ASLAB order Certificate of Svc øncl
 SEMMEL, K Christa-Maila SEMMEL, H Antioch College of Law
 82/10/12 Atomic Bafety and Licensing Board Panel App
 15706 009 24X Fiche 50-155.82/10/12.8210150341
- 8210150470 Reply to Christa-Maria B20927 proposed findings of fact & conclusions of law on O'Neill Contention IIE-3 retribicality Contention w/o merit & should be dismissed Certificate of Sev encl GALLO, J. THORNTON, P. Consumers Power Co. GALLO, J. Isham, Lincoln & Beale B2/10/12 topp 15703-053 24X Fiche 50-155, 82/10/12: 8210150470
- 8210180206 Mption for clarification &/or petition for reconsideration of portion of ASLB 820914 partial initial decision re legal requirement of NUREG-0554 Term "relocation requirement" unclear Celtificate of Syc encl CALLO, J Consumers Power Co OALLO, J Isham, Lincoln & Beale 82/10/12 Atomic Safety and Licensing Board Panel App 15718 128 24X Fiche 50-155.82/10/12.8210180206
- 8210180342 Motion for extension of time until 821012 to file motion for clarification 2/or petition for reconsideration of ASLB 820914 partial initial decision Holiday to honor Columbus Day not considered in schedule GALLO.J Consumers Power Co GALLO.J Isham, Lincoln & Brale 82/10/12 Atomic Safety and Licensing Board Panel 2pp 15718 059 24X Fichs 50-155,82/10/12,8210180242
- G210150167 Memorialites G2100B telcon w/ASLB re NRC position on util B21001 motion to establish hearing dates NRC agrees to splitting hearing into two phases but dates pose unalterable conflict w/another hearing for ASLB chairman & NRC counsel COUDARD, R J Hearing Branch 3 B2/10/13 B10CH, P B, SHON, F J, PARISO H Atomic Safety and Licensing Board Panel 2pp 15707 180 24x Fiche S0-155,82/10/13,8210150167
- 8210150469 Forwards 0 Zech 821012 trip rept of 820928 site visit, sugmarting events & conversations ROBERTS.T M Commissioners 82/10/13 SEMMEL.H Antioch College of Law 8EMMEL.H Christa-Maria 3pp 15703 060 24X Fiche 50-155
- 8210200029 Forwards emergency preparedness pamphlet for use in 8-mile emergency planning ione in Charlevolx County & part of Emmet County Pamphlet incorporates revisions & mods set forth in ASLB 820806 partial initial decision GALLO, J Isham, Lincoln & Beale GALLO, J Consumers Power Co 82/10/14 BLOCH, PB. PARIS.O H. SHON, F J Atomic Safety and Licensing Board Panel 30pp 15756 149 24X Fiche 50-155,82/10/14,82000029

- 8210210349 Memorandum & order denying util 821001 motion to establish hearing dates & 821012 motion for clarification Hearing on issues delayed by applicant deferred Clarification motion not ripe for adjudication BLOCH, P 8 , PARIS, O H , SHON, F J Atomic Bafety and Licensing Board Panel 82/10/19 Consumers Power Co 3pp 15764 201 24% Fiche 50-155.82/10/19.8210210349
- 8210210381 Opposition to licensee motion to continue plant operations w/o compliance w/ASLB order on emergency planning Continued operation u/o adequate planning poses threat to lives & health of citizens W/Certificate of Svc SEMMEL.H . WIKTOR:D Christa-Maria SEMMEL.H . Antioch College of Law 82/10/21 Atomic Safety and Licensing Board Panel App 13765 153 24X Fiche 50-155,82/10/21.8210210381
- 8210220338 Memorandum & order granting util 821012 motion for extension of time until 821201 to comply w/ASLB 821014 order to demonstrate compliance w/Commission emergency planning requirements

 BLOCH, P B . PARIS, O H . SHON, F J Atomic Safety and Licensing Board
 Panel 8210021 Carolina Power & Light Co 3pp 19776 008

 24X Fiche 50-155,82/10/21,8210220338
- 8210250301 Advises that Region 3 will notify util to delete erroneous language in emergency preparedness pamphlet re respiratory protection measures Mode would not contrevene ABLB order GDDARD.R J Hearing Branch 3 82/10/22 BLOCH.P B PARIS.O II. SHON.F J Atomic Safety and Licensing Board Panel 2pp 15790 21/) 24X Fiche 50-155.82/10/22.8210250301
- B210290291 Confirms B21026 telcon Intervenor has not decided whether to file 10CFR2 206 petition to suspend or revoke license because of emergency planning concerns
 BACHMANN, R G Hearing Branch 1 B2/10/28 SEMMEL, H Antioch College of Law 1p 15854 072 24X Fiche 50-155.82/10/28, 8210.290.001
- J Insurance & indemnity information
- 8210050100 Submits responses to 820712 questions concerning additinsurance coverage re 820622 request for exemption BACON.J L Consumers Power Co 82/08/10 SALTZMAN.J Office of State Programs, Director 3pp 13603 298 24X Fiche 50-155.82/08/10.8210050100
- P Operating license stage documents & correspondence
- 8210280013 Responds to FOIA request for all internal non-public documents nemos, evaluation repts & other mati dealing w/ nuclear plant operations Forwards documents listed in App A FELTON J M D(vision of Rules and Records 82/09/17 MCINNIS, D News & Observer 5pp 15850 065 24X Fiche 50-000, 82/09/17, 8210280013
- --8208310034 Forwards draft info notice re-deficiencies in air filtration & ventilation sys Notice based on radioactive resin release at Pilgrim 1 & on four related events at other plants involving deficiencies in maint & testing of filter sys MATTBORR U Division of Bystems Integration (post 811005) 82/08/05 JORDAN. E Division of Engineering & Quality Assurance Spp 1984 024 24X Fiche 50-000.82/09/17.82102800017

- --8210070018 Draft "Offsite Dose Calculation Manual," Palisades Plant & Consumers Power Co. 82/09/24 55pp 15628 276 24% Fiche 50-000,82/09/29,8210070013
- 8210050425 Forwards "Evaluation of High Energy Pipe Break Inside Containment for Big Rock Point Nuclear Plant," in response to SEP Topic III-5 3 VANDEMALLE.D J. Consumers Power Co. 82/09/30 CRUTCHFIELD, D. Operating Reactors Branch 5 2pp. 15607-042 24X Ficha 50-195, 82/09/30, 8210050425
- --8210050427 "Evaluation of High Energy Pipe Break Inside Containment for Big Rock Point Nuclear Plant " GEBERIG V. MASERI R. RICCARDELLA, P. NUTECH (Nuclear Technology, Inc.) CPC-01-110 ROD 81/10/23 79pp 15507 044 24X Fichs 50-155,82/09/30,8210050425
- 8210040152 Comments on NRC draft safety evaluation of SEP Topic V-5, "RCPB Leakage Detection." per 820319 request Info missing from Tables I & 2 of 820319 submittal encl Detection sysmest intent of current licensing criteria VANDEMALLE, D J Consumers Power Co 82/09/30 CRUTCHFIELD, D Operating Reactors Branch 5 9pp 15614 047 24X Fiche 30-153,82/09/30,8210060152
- 8210060237 Forwards response to NRC request for add1 info on SEP Topic 111-2. "Wind & Tornado Loadings " App C supersedes 820803 submitted Drawing showing cross-section of south end of control room wall can be retrieved from NMSS VANDEMALLE, B J Consumers Power Co 82/09/30 CRUTCHFIELD, D Operating Reactors Braint 5 12pp 15619 327 24x Fiche 50-155, 82/09/30, 8210060239
- --8210060241 "Specs for Designing.Furnishing & Erecting Reinforced Contrate Chimney " # Bechtel Corp 3159 C-21 61/03/17 12pp 15619 339 24X Fitche 50-155,82/09/30.8210060239
- 821025009; Forwards draft safety evaluation & technical evaluation rept. "Design Codes. Design Criteria & Load Combinations (SEP 111-7 B). Big Rock Point." Util requested to respond to factual correctness of SER in 30 days CRUTCHFIELD. D. Operating Reactors Branch 5 B2/09/30 VANDEMALLE. D J Consumers Power Co lipp 15788 001 24X Fiche 50-155. B2/09/30. B210250091
- --8209160459 "Dusign Codes, Design Criteria & Loading Combinations (SEP III-7 B), Big Rock Point, "technical evaluation rept STILHELL.T Frantiin Institute/Frantiin Research Center NRC-03-79-118 TER-05257-317 82/09/13 PERSINKO, D NRC No Detailed Affiliation Given 216pp 15788 012 24% Fiche 50-155,82/09/30,8210250091
- 8210130326 Comments on proposed scope of Phase III of SEP as reflected in individual topic definitions appended to 820909 ltr Staff encouraged to develop 2 implement means to incorparate positive attributes of Phase III in licensee/NRC interface KACICH.R H BEP Owners Group KACICH.R M Northeast Nuclear Energy Co (subs of Northeast Utilities) 82/10/07 EISENNUT.D C Division of Licensing 7pp 19682 179 24% Fiche 50-000.82/10/07, 8210130326
- 8210150505 Advises of Franklin Research Ctr B20430 technical evaluation rept, "Containment Leskage Rate Testing-(A 04)." Exemptions for instrument pressure lines should be granted to significant degradation of penetration scale observad BORDINE, T C Carolina Power & Light Co 82/10/12 CRUTCHFIELD, D Operating Research TS, 2pp 15714 210 24X Fiche 50-153,82/10/12.8210150505
- 8210190459 Forwards current status of program to evaluate adequacy of averload & short-circuit protection for electrical circuits that pass through reactor containment per SEP Topic VIII-4 "Electrical Penetrations of Reactor Containment."

 TONER, K. A. Consumers Power Co. 82/10/12. CRUTCHFIELD, D. Operating Reactors Branch 5. 21pp. 13740-268. 24X Fiche 50-000, 82/10/12, 82/10/20459.
- 8210200041 Forwards safety evaluation of SEP Topic IX-5, "Ventilation Bys " Evaluation will be basic input to integrated safety assessment Aiso forwards "Review of Pesign & Operation of Ventilation Bys for SEP Plants," technical availation rept CRUTCHFIELD.D Operating Reactors Branch 5 NRC-03-79-118 B2/10/12 VANDEMALES.D J Consumers Power Co 9pp 15755; 358 24X Fighs 50-155, 62/10/12, 8210200041.
- --8208180082 "Review of Design & Operation of Ventilation Bys for SEP Plants," final technical evaluation rept HERRIOK.R.C. Franklin Institute/Franklin Research Center NRC-03-79-118, TER-C5257-414 82/08/13 BROWN.S NRC No Detailed Affiliation Given, 21sp 15756 005 24X Fich; 50-155, 82/10/12,8210200041

- 8210150469 Forwards 0 Zech 821012 trip rept of 820928 site visit, summar(sing events & conversations ROBERTS.T M Commissioners 82/10/13 SEMMEL, M Antioch College of Law SEMMEL, M Christa-Maila 3pp 15703 060 24X Fiche 50-155,82/10/13,8210150469
- 8210150533 Comments on 820812 final safety evaluation of SEP Topics V+11 A. "Requirements for Isolation of High & Low Pressure Sys" & V-11 B. "RHR Interlock Requirements" Core spray sys designed to perform function safely TOWER, K.A. Consumers Power Co. 82/10/13 CRUTCHFIELD, D. Operating Reactors Branch 5 App. 15713 145 24X Fiche 50-155,82/10/13,82/10/50533
- 8210250213 Forwards evaluation of SEP Topic III-4 C, "Internally Openerated Missiles," 5 related SER Facility meets acceptance criteria for topic Info will be basic input to integrated sarety assessment CRUTCHFIELD, D. Operating Reactors Branch 5 82/10/14 VANDEMALLE, D. J. Consumers Power Co. 25pp. 15/88 247 24X Fishe SO-155.82/10/14.8210250213
- B250220368 Forwards safety evaluation of NNRCG-0737. Item 11 E 4 .2. "Containment Isolation Dependability " Facility meets guidance Item resolved CRUTCHFIELD,D Operating Reactors Branch 5 B2/10/18 VANDEWALLE,D Consumers Power Co 5pp 15/79 187 24X Fishe 50-155. B2/10/18. B210220368
- 8210250323 Forwards Amend 54 to License DPR-6.safety evaluation & notice of issuance & availability Amend approves Tech Opec changes re NUREQ-0737.ltem [I F 1(3) on leak testing intervals CRUTCHFIELD, D. Operating Reactors Branch 5 82/10/18 VANDEWALLE, D. J. Consumers Power Co. 1p 15790-010 24X Fiche 50-155, 82/10/18.8210250223
- --8210250327 Amend 54 to License DPR-6, changing foch Specs re containment high radiation monitor requirement by TMI Action Item II F t(3) on leak testing intervals CRUTCHFIELD, D Operating Reactors Branch 5 82/10/18 10pp 15790 011 24X Fiche 50-155,82/10/18,82(0250323
- --9210250333 Safety evaluation supporting Amend 54 to License DPR-6 • Office of Nuclear Reactor Regulation, Director 82/10/10 Jpp 15790 021 24% Fiche 50-155-82/10/18-8210250323
- --8210250337 Notice of issuance & availability of Amend 54 to License DPR-6 CRUTCHFIELD: D Operating Reactors Branch 5 82/10/18 2pp 15790 024 24X Fichs 50-155, 82/10/18,8210250323
- 8210220117 Forwards QE turbine hydraulic control lever Diagram 2127316-A (ALTO), requested by Power Sys Branch during 821013 conference call per SEP Topic III-A B. "Turbine Missiles" TONER.K A Consumers Power Co 82/10/19 CRUTCHFIELD.D Operating Reactors Branch 5 2pp 15778 147 24X Fiche 50-155,02/10/19, 8210220117
- 8210270270 Forwards draft safety evaluation of SEP Topics III-6. "Seeismic Design Considerations" & III-11. "Cumponent Integrity " Licensee analyses of structures.burged piping & reactor coolant loop piping insdequate CRUTCHFIELD.D Operating Reactors Branch 5 82/10/19 VANDEMALLE, D Consumers Power Co 3App 15852 048 24X Fische 50-155.82/10/19,8210270270
- --8208110271 Forwards geotechnical review of spismic safety margin study in response to verbal request during 820524 meeting Range of soil shear module values used in parametric study by licenses adequately envelope expected values

 LEAR. 0 Hydrologic & Geotechnical Engineering Branch 82/07/30 RUSSELLW T Systematic Evaluation Program Branch 10pp 15852 108 24% Fichs 50-155, 82/10/19,8210270270
- --8205250010 Forwards "Seismic Review of Big Rock Point Nuclear Power Plant Containment Shell Structure.as Part of SEP "
 LO, T Lawrence Livermore Laboratory FIN A-0436 82/05/20 RUSSELL, W T Systematic Evaluatian Program Branch 1p 15852 118 24X Fiche 50-155, 82/10/19,8210270270
- --8205250020 "Beismic Review of Big Rock Point Nuclear Power Plants Cantainment Shell Structure, as Part of SEP " LIAM.C Y E940, Inc FIN A-0496 SRC-307 B2/04/30 NRC - No Detailed Affiliation Given 2Bpp 15852 119 24X Fiche 30-155,82/10/19,8210270270
- --8210270288 "Seismic Design," informal technical evaluation rept CALL,V B.: THOMPSON,Y R EQ&O, Inc FIN A-6426 EQQ-EA-6051 82/09/30 HERRINO.K Division of Licensing 52pp 15852 146 24X Fiche 50-155,82/10/19.8210270270

- ©210250310 Forwards safety evaluation of SEP Topic XV-19, "LOCA nicidents Resulting From Spectrum of Postulated Piping Breaks Within RCPB (Radiological) "Facility meets acceptance criteria CRUICHFIELD. O Operating Reactors Branch 5 82/10/20 VA.(DEMALLE, D J Consumers Power Co 10pp 15790 053 24X Fiche 50-155, 82/10/20 82/0250310
- #2210270269 Advises that NUREG-0737. Items II K 3 18 % II K 3 45 ro automatic depressorization sys. inapplicable to facility Therefore: items resolved CRUTCHFIELD.D Operating Reactors Branch 5 82/10/20 VANDEHALLE.D Consumers Power Co 4pp 15829 045 24X Fiche 50-155, 82/10/20, 8210270265
- 🕝 Inspection reports. IE Bulletins & correspondence
- 3210050336 Ack receipt of 820917 ltr informing NRC of steps taken to correct moncompliance noted in IE Insp Rept 50-155/82-12 SPESSARD.R L Division of Project & Resident Programs 82/09/24 DEWITT, B B Consumers Power Co ip 15610 098 24X Fiche 50-155,82/09/24.8210050336
- --0210050342 Responds to NRC 820817 ltr re-noncompliance noted in IF Insp Rept 50-155/82-12 Corrective actions unauthorized activity terminated on 820617 following review by operations superintendent VARBELIALLE, D.J. Consumers Power Co. 62/09/17 KEPPLER, J. O. Region 3. Office of Director 2pp 15610 099 24X Fiche 90-155, 82/09/24, 8210050336
- €3210080279 Confirms commitment to incorporate responses to IE Insp Rept 50-{55/61-17 into emergency plan implementing procedures & requests approval to use general ofc control ctr as temporary emergency operations facility VANDCHALLE.D J Consumers Power Co 82/10/01 KEPPLER.J G Region 3. Office of Director 5pp 15638 203 24X Fiche 50-155.82/10/01, 8210080279
- ET 20819023.1 IE Info Notice 80-35. Suppl 1, "Leaking & Disjodged I-125 Implant Seeds " Svc list encl C038.L I Division of Fuel Facilities. Materials & Safeguards 82/10/06 Consolidated Edison Co of New York 66pp 19761 250 24/ Fiche 50-000/82/10/06/82081902.33
- 3-210220233 Forwards evaluation of SEP Topic III-3 C. "Inservice Insp of Water Control Structures" Insp program needs mod to conform w/Reg Guide 1 127
 CRUTCHFIELD.D. Operating Reactors Branch 5 82/10/12
 VANDEMALLC.D.J. Consumers Power Co. 8pp 15775 104 24X
 Fishe 50-155.82/10/12.8210220233
- -0206300188 "Hydrological Considerations Inservice Insp of Water Control Structures, (SEP.II-3A.B.B.), C.III-3B.), "technical evaluation rept explosion rept explosion of the Control SCHERRER, J. Franklin Institute/Franklin Research Center NRC-03-79-118 TER-C5257-542 82/06/23 STALEY, O NRC No Detailed Affiliation Given 15pp 15775 112 24X Fiche 50-155,82/10/12.8210220233
- 208190238 IE Bulletin 82-03, "Stress Corrosion Cracking in Thick-Wall-Large-Diameter: Stainless Steel-Recirculation Sys Piping at BMR Plants" Svc list encl
 DEYOUND.R C Director's Office. Office of Inspection and
 Envorcement 82/10/14 Consolidated Edison Co of New York
 1 15pp 15810 125 24x Fiche 50-000.82/10/14/8208190238
- 210260220 Advises that spiked air particulate filter being forwarded to util for analysis per 820427 discussion Util results will to compared w/NRC analysis, in effort to close out open item in IE insp Rept 80-155/82-07

 PAPERIELLO, C J Division of Emergency Preparedness & Operational Support 82/10/20 HOFFMAN D P Consumers Power Co (p 1 5804 247 24% Fiche 50-155/82/10/20,8210240220
- 11 O240315 Ack receipt of 821015 Itr informing NRC of steps taken to Correct violations noted in IE Insp. Rept 80-155/82-09
 MORELIUS.C E Division of Project & Resident Programs 82/10/22
 DEWITTER B Consumers Power Co ip 15799 328 24X
 Fische 50-155, 82/10/22, 8210260315
- B210260316 Responds to NRC 820917 itr re violations noted in IE Insp Rept 50-155/82-09 Corrective actions training procedures & requirements revised & will be clarified by 830101 VANDEMALLE, D J Consumers Power Ca 82/10/15 KEPPLER. J G Region 3, Office of Director 6pp 15799 329 24X Fiche 50-155,82/10/22,8210260315

- 5 Reportable occurrences. LERs & related correspondence
- 8210080251 PND-III-92-099 on 820914. ABLB issued order delineating deficiencies in state offsite emergency preparedness Util given 1 month to demonstrate deficiencies remedied PAGLIARO. J. AXELSON. W. PAFERIELLO. C. Region J. Office of Director 82/09/20 ip 15508 118 24X Fich 50-155.82/09/20.8210080251
- T Hearing transcripts on non-antitrust matters
- 8210290360 Forwards signed original transcript of L Reiter deposition taken on 820917 W/o encl
 BACHMANN.R 0 Hearing Branch i 82/10/28 OALLO, J [sham: Lincoln & Beale OALLO, J Consumers Power Co ip 19853 089 24X
 Fiche 50-155,82/10/28,8210290360
- DOCKET 50-160 GEORGIA INST OF TECH RESEARCH REACTOR

 O Inspection reports, IE Bulletins & correspondence
- 8210220312 Ack receipt of 821004 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-160/82-02 VERRELLI.D M Division of Project & Resident Programs 82/10/14 CARLSON,M O Georgia Institute of Technology ip 15776 ti7 24x Fichs 50-160.82/10/14.8210220312
- --8210220319 Responds to NRC 82090B ltr re violations noted in IC Insp Rept 90-160/82-02 Corrective actions personnel counseled RUSSELL-J C Georgia Institute of Technology 82/10/04 VERRELLI.D M Division of Project & Resident Programs 3pp 15776 118 24X Fiche 50-160.02/10/14.8210220312
- --8210220325 Forwards 1E Insp Rept 50-160/82-02 on 820825-26 & notice of violation vERRELLI.D M Division of Project & Resident Programs 82/09/08 DAVIS.M V Georgia Institute of Technology 2pp 15776 121 24) Fiche 50-160, 82/10/14.8210220312
- --8210220330 Notice of violation from insp on 620825-26 * Division of Project & Resident Programs 02/09/08 ip 19774 123 24x Fiche 50-160.62/10/14.8210220312
- --8210220341 IE Insp Rept 50-160/82-0P on 820825-26 Noncompliance noted on 820513 irradiated matl removed from biological shield penetration H-12 w/o health physics supervised PERRY, N. N. BARR, K. Division of Project & Resident Programs 82/09/07 4p 19776-124 24X Fiche 50-160,82/10/14,8210220312

DUCKET 50-170 NATIONAL NAVAL MEDICAL CENTER

- O Adjudicatory correspondence
- 8210050273 Order scheduling 821015 prehearing conference in Bethesda.MD re remaining outstanding issues Proposed schedules should be presented HDYT.H F Atomic Safety and Licensing Board Panel 82/10/01 2pp 19609 191 24X Fiche 50-170.82/10/01.8210050273
- 8210150317 Becond supplemental response to first set of interrogationies Certificate of SVc encl Related correspondence
 MACKLIN-L Citizens for Nuclear Reactor Safety, Inc MACKLIN-L Institute for Public Representation 82/10/08 47pp 13701 270 24X Fiche 50-170, 82/10/08, 8210150317
- 8210150395 Provides info re counsel for Citizens for Nuclear Reactor Safety E Entwisle to continue as counsel L Macklin & Inst for Public Representation will withdraw as counsel effective 821215.

 MACKLIN L Institute for Public Representation MACKLIN L Citizens for Nuclear Reactor Safety. Inc 82/10/08 HOYT, H Atomic Safety and Licensing Board Panel 2pp 15704 052 24X Fiche 30-170.82/10/08.8210150395
- 8210220437 Forwards motion for encl protective order to protect against public disclosure or misuse of I Stillman address & telephone number

 MACKLIN.L. Institute for Public Representation MACKLIN.L.
 Citiens for Nuclear Reactor Eafety, Inc. 82/10/19 HBYT.H Atomic Safety and Licensing Board Panel 1p 19778 239 24X
 Fiche 50-170.82/10/19.8210220439.
- --8210220448 Motion for protective order to protect against public disclosure or misuse of I Stillman address & telephone number Proposed protective order & Certificate of Svc encl MACKLIN.L.W S. Citizens for Nuclear Reactor Safety.Inc. MACKLIN.L.W,S. Institute for Public Representation 82/10/19. Atomic Safety and Licensing Board Panel 5pp 15778 240 24X Fiche 50-170.82/10/19.8210220439

9210250235 Order granting Citizens for Nuclear Reactor Safety 821019 motion for protective order to protect against public disclosure or misuse of I Stillman address & telephone number
HOYT, H F Atomic Safety and Licensing Board Panel 82/10/21
Citizens for Nuclear Reactor Safety, Inc. 1p 15788 357 24X
Fiche 30-170, 82/10/21, 8210250235

8210280220 Provides dates when Citizens for Nuclear Reactor Safety would be available for plant tour MACKLIN,L Institute for Public Representation MACKLIN,L Citizens for Nuclear Reactor Safety.Inc 82/10/21 H0YT,H Atomic

Citizens for Nuclear Reactor Safety Inc 82/10/21 HDYT,H Atom Safety and Licensing Board Panel 2pp 15837 087 24X Fiche 30-170,82/10/21.8210280220

8210260425 First supplementary answers to interrogatories Certificate of Svc encl RICKARD,D C Armed Forces Radiobiological Research Institute 82/10/22 Citizens for Nuclear Reactor Safety, Inc 12pp 15806 038 24% Fichs 50-170,82/10/22.8210260425

H General correspondence

S210150200 Notice of change of address
ENTHISLE,E B Citizens for Nuclear Reactor Safety, Inc
ENTHISLE,E B Entwisle.E B 82/10/08 1p 15701 362 24X
Fiche 50-170,82/10/08.8210150200

T Hearing transcripts on non-antitrust matters

6210170238 Transcript of 821015 prehearing conference re license renewals in Bethesda MD Pp 652-738

* Atomic Safety and Licensing Board Panel 82/10/15 87pp 15742 230 24% Fiche 50-170.82/10/15.8210170238

DOCKET 50-182 PURDUE UNIV RESEARCH REACTOR

P Operating license stage documents & correspondence

- 8210050540 Forwards Amend 6 to License R-87 & safety evaluation Amend changes Tech Specs re drop times of shim safety rods & time intervals between meetings or surveillence action THOMAS.C O Standardization & Special Projects Branch 82/09/13 STANSBERRY.E R Purdus Univ 2pp 15637 204 24X Fiche 50-182, 82/09/13, 8210050540
- --B210030543 Amend & to License R~B7. changing Tech Spec limits on drop times of shim safety rods & changing certain surveillance intervals THOMAS. C O Standardization & Special Projects Branch B2/09/13 11ap 15637 206 24X Fiche S0-182.82/09/13.8210050540
- --8210050548 Safety evaluation supporting Amend 6 to License R-B/

 Office of Nuclear Reactor Regulation, Director 82/09/13 3pp
 15537 217 24X Fiche 50-182-82/09/13.8210050540

DOCKET 50-184 NATIONAL BUREAU OF STANDARDS REACTOR

- G Inspection reports, IE Bulletins & correspondence
- 8210270300 Forwards 1E Insp Rept 50-184/82-02 on 820708-10 & notice of violation STAROBTECKI.R Division of Project & Resident Programs 82/10/08 CARTER.R B Commerce. Dept. of, National Bureau of Standards 2pp 15855 036 24X Fiche 50-184.82/10/08.8210270300
- --8210270301 Notice of violation from insp on 820708-10 * Division of Project & Resident Programs 82/10/08. 1p 15855 038. 24% Fiche.50-184,82/10/08,8210290300
- --8210270304 IE insp Rept 50-184/82-02 on 820708-10 Noncompliance noted failure to instruct worker in precautions procedures, purposes & functions of protective devices used to minimize parsonal exposure to radioactive matl & radiation KINNEY.W W : KEIMIG.R R Division of Project & Resident Programs 82/09/28 9pp 19855:039 24X Fiche 50-184,82/10/08,8210290300

R Pariodic operating reports & related correspondence

8210130160 Forwards "Operations Rept 33, Jan-June 1982,"
CARTERR S Commerce Dept of National Bureau of Standards
82/09/30 THOMAS, C O Standardization & Special Projects Branch
1p 156/3 066 24X Fiche 50-184,82/09/30,8210130160.

--B210130163 "Operations Rept 33, Jan-June 1982 "
CARTER.R 8 Commerce, Dept of, National Bureau of Standards 82/09/30 5pp. 15673 067 24X Fiche 50-184,82/09/30,8210130160

DOCKET 50-186 UNIV OF MISSOURI RESEARCH REALTOR

- O Inspection reports, IE Bulletins & correspondence
- 8210050359 Forwards IE Insp Rept 50-186/82-01 on 820816-17 & notice of violation MILLER, J R Division of Engineering & Technical Programs 82/09/15 ALGER, D M Missouri, Univ of, Columbia 2pp 15609 001 24X Fiche 50-186,82/09/15,8210050359
- --8210050365 Notice of violation from insp on G20B16-17 MILLER, J.R. Division of Engineering & Technical Programs G2/09/15 2pp 15609 003 24% Fiche 50-186, G2/09/15, G210040 159
- --B2100503B0 JE Insp Rept 50-186/82-01 on B20B16-17 Noncompliance noted failure to perform surveys to post radiation & radioactive matis area & storage of radwaste at unauthory; my offsite facility LOVENDALE, P.C., GRANT, H.B., GREGER, L.R. Division of Engineering & Technical Programs B2/09/14 Spp 15409 005 24X Fiche 50-186, 82/09/15, 8210050059

DOCKET 50-188 KANSAS STATE UNIV RESEARCH REACTOR

R Periodic operating reports & related correspondence

8210190365 Submits list of facility procedure changes, tests & experiments for Oct 1981-Sept 1982, per 10CFR50 59(b)
FAMILE REARSAS State Univ 82/10/11 MILLER, J.R. Standag direction & Special Projects Branch 2pp 15/40 316 24X
F(che 50-188,82/10/11.8210190365

DOCKET 50-192 UNIV OF TEXAS RESEARCH REACTOR

- P Operating license stage documents & correspondence
- B210050174 Forwards description of mods to be made to reactor instrumentation & control sys Changes will modernize function or reliability of current console functions Phase i.Parts A & B of changes completed BAUER.T L. Texas. Univ of 82/07/30 HUNNICUIT Region 4, Director 14pp 15504 124 24X Fiche 50-192,82/07/30, pp. 1050173

DOCKET 50-199 MANHATTAN COLLEGE RESEARCH REACTOR

- P Operating license stage documents & correspondence
- 8210050341 Requests guidance on procedure for renewal of 10-yr titeman R-94. Which expires on 830930 KANE,R B Manhattan College 82/09/28 BERNARD,H Standardiration & Special Projects Branch 1p 15610 120 24X Fiche 50-199, 82/09/28,8210050341
- 8210260506 Responds to 820728 request for guidance in preparing application to renew license NRC evaluations of recent applications end W/o end!

 THOMAS: C O Standardisation & Special Projects Branch 82/10/14

 KANE. R 8 Manhattan College 2pp 15830 156 24X

 Fiche 90-199.82/10/14.8210260506

DOCKET 50-201 WEST VALLEY REPROCESSING PLANT

- Q Adjudicatory correspondence
- 82102605Bi Forwards NFS & NY State Energy R&D Authority B20716 juint ltr notifying of B20716 settlement date Bettlement satisfies all three conditions of Paragraph 8 A of License CSF-1 for termination of NFS authority & responsibility under license EDOAR.O L Morgan, Lewis & Bockius EDOAR.O L Nuclear Fuel Services, Inc. (subs. of Oetty Oil Co.) B2/07/16 CUNNINGHAM.B L. Division of Fuel Cycle & Material Safety Ip 15830 143 24% Fiche. 30-201, 82/07/16, 82102605Bi
- --B2102603B2 Notifies of 820916 settlement date Settlement satisfies all three conditions of Paragraph B A of License CSF-1 for termination of NFB authority & responsibility under license. JACK: A New York, State of. Energy Research & Development Administration DEUSTER, H Muclear Fuel Services. Inc. (subsoftest of Osty Dil Co.) 82/09/16 CUNNINDHAM, R E Division of Fuel Cycle & Material Safety. Ip 15830 144 24X Fiche 50-201,82/09/16.8210260581

- 8210070183 Informs that time for Commission to review ALAB-679 expired Commission declined review Decision became final agency action on 821001 CHILK S.J. Office of the Secretary of the Commission 82/10/05 Office of the Ejecutive Legal Director 1p 15634 261 24X Fichs 50-201.82710/05.08781
- Operating license stage documents & correspondence
- 3210210041 GEOMORPHIC PROCESSES AND EVOLUTION OF BUTTERMILK VALLEY AND SELECTED TRIBUTARIES.WEST VALLEY.NEW YORK BOOTHADOD, J. C., TIMSON, B. S., DUNNE,L A. New York, State of FIN B~6350 NUREC/CR~2862 82/07/31 Division of Health. Siting & Environment 117pp 15785-255 24X Fiche 50~201.82/07/31.
- 210260381 Forwards NFS & NY State Energy R&D Authority 820916 Joint ltr notifying of 820916 settlement date Settlement satisfies all three conditions of Peragraph 8 A of License CSF-1 for termination of NFS authority & responsibility under license EDGAR.G L. Horgan, Levis & Bockius EDGAR.G L. Nuclear Fuel Services, Inc. (subs. of Getty Di) Co.) 82/09/16 CUNNINGHAM.R E. Division of Fuel Cycle & Material Safety ip 15830 143 24X Fiche 50-201.82/09/16.8210260581
- -8210260582 Notifies of 820916 settlement date Settlement satisfies all three conditions of Paragraph 8 A of License CSF-1 for termination of NFS authority & responsibility under license JACK, R A New York, State of, Energy Research & Development Administration DEUSTER, R W Nuclear Fuel Services, Inc (subs of Cetty Dil Co) 82/09/16 CUNNINGHAM, R E Division of Fuel Cycle & Material Safety ip 15830 144 24X Fiche 50-201,82/09/16,8210260581
- C10180414 Notification of contract execution. Mod 4 to "West Valley Haste Burial" Contractor State Univ of NY. Albany JACOBS A Research Contracts Branch FIN B-6350 82/09/26 BATSON W . MICHOLSON J Office of Nuclear Regulatory Research, Director 1p 15745 275 24% Fishe 50-201.82/09/26.8210180414
- -8210180419 Mod 4, extending period of performance to 831231 to "West Valley Waste Durial" MAURER.R J New York, State of QUSTAVE.R P Division of Contracts FIN 8-6305 82/09/24 1280 13745 276 24X Fithe 50-201.82/09/26.8210180414
- OCKET 50-206 SAN ONOFRE NUCLEAR STATION, UNIT 1

 Security, medical, emergency & fire protection plans
- 210080210 Ack receipt of 820910 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-206/82-21 BIEHOP. T W Division of Resident, Reactor Project & Engineering Programs 82/10/04 FDGARTY, DJ Bouthern California Edison to ip 15640 080 24X Fiche 50-206.82/10/04.8210080210
- -8210080211 Responds to NRC 820812 ltr re violations noted in IE Insp Rept 50-206/82-21 Corrective actions nonfire retardant wood, orly rags & combustible debris rombved from areas & amend to include swengency light impairment prepared FOOARTY, D & Southern California Edison Co ENGELKEN, R H Region 5, Office of Director 5pp 15640 081 24X Fiche 50-206,82/10/04,8210080210
- 210190525 Forwards Revision 7 to physical security plan Revision withheld (ref 10CFR73 21)
 BASKIM:K P Southern California Edison Co 82/10/15 EIBENHUT, D 0
 Office of Nuclear Reactor Regulation: Director 1p 15740 035
 24X Fiche 50-206, 82/10/15, 6210170625

Operating license stage documents & correspondence

- *10280013 Responds to FOIA request for all internal, non-public documents, menos, evaluation repts & other math dealing w/ nuclear plant operations Forwards documents listed in App A FELTON.J H Division of Rules and Records 82/09/17 MCINNIS.D News & Observer 5pp 15860 045 24X Fiche 50-000, 82/09/17.
- 8210280082 "Dosimetry Placement for Steam Generator Workers" WARNOCK, R Institute of Nuclear Power Operations 82/01/31 13pp 15860 310 24X Fiche 50-000,82/09/17,8210280013
- 10050300 Forwards draft evaluation of SEP Topic III-7 B, "Design Codes, Design Criteria & Load Combinations " Response to factual correctness of SER & proposed schedule for resolution of open items requested within 30 days PAULSUN: U Operating Reactors Branch 5 82/09/21 DIETCH:R Southern California Edison Co lipp 15602 001 24X Fiche 50-206, 82/09/21, 8210050300

- ---8208170083 "Design Codes, Design Criteria & Loading Combinations (SEP.111-78), "technical evaluation rept STILHELL.T C Franklin Institute/Franklin Research Center NRC-03-79-118 TER-C525-7-318 82/08/13 PERSINKO.D NRC No Detailed Affiliation Given 222pp 15602 012 24X Fiche 30-206, 82/09/21.8210050300
- --0207300222 Draft "SEP Structural Review of San Onofre Unit 1 Containment Structure Under Combined Loads" Lo.T Lawrence Livermore Laboratory FIN A-0436 UCID-19141 DRFI 82/05/31 45pp 15602 234 24X Fiche 50-206.82/09/21.
- B210060003 Requests submittal of fees for 820625 application for Amend 62 to License DPR-62.permitting delay in safety injection sys hydraulic value testing MILLER.W C License Fee Management Branch 82/09/23 DIETCH.R Sauthern California Edison Co Ip 13636 266 24X Fiche 50-206.82/09/23.8210060003
- B210040062 Forwards safety evaluation rept & technical evaluation re main steam line break w/continued reedwater addition Analysis acceptable CRUTCHFIELD.D Operating Reactors Branch 5 82/09/27 DIETCH.R Southern Celiforn
- --8210040064 Bafety evaluation re main steam line break w/continued feedwater addition Licensee commitment acceptable w/installation of auxiliary feedwater motor driven pump w/pump runout protection a Office of Nuclear Reactor Regulation, Director 82/09/27 7pg 15584 180 24X Fiche 50-206.82/09/27,8210040062
- --8206030064 "PNR Main Steam Line Break W/Continued Feedwater Addition," technical evaluation rept VQSBURY.F W Franklin Institute/Franklin Research Center NRC-03-81-130 TER-05504-151 82/05/28 HEARN.P NRC No Detailed Affiliation Oliven 25pp 15584 187 24X Fiche 50-206,82/05/27.8210040062
- 8210040153 Advises that util proposed masonry wall test program acceptable, subj to satisfactory resolution of concerns delineated in encl evaluation Addl info requested no later than 30 days prior to proposed restart data PAULSGN.H Operating Reactors Branch 5 82/09/29 DIETCH.R Bouthern California Edison Co App 15582 341 24X Fiche 50-206.82/09/29.82/0040153
- 82(0040177 Forwards "Seismic Evaluation of Reinforced Concrete Masonry Walls. San Onofre Unit 1." Vol 5 Fuel Storage Bldg Soil Bacterill Condition Evaluation, per SEP Topic III-6 No eddl mode required to fuel storage bldg DASKIN.K P Southern California Edison Co 82/09/30 CRUTCHFIELD. D Operating Reactors Branch 5 1p 15582 045 24X Fiche 50-206.82/09/30.8210040177
- --B21004017B "Beismic Evaluation of Reinforced Concrete Masonry Walls, San Onofre Unit 1," Vol 5 Fuel Storage Bldg Soil Backfill Condition Evaluation * Computech Engineering Services, Inc. R943-02 V05 B2/09/30 159pp 15582 046 24X Fiche 50-206.82/09/30.8210040177
- 8210130276 Forwards abstract of paper on experience gained in evaluating effects of high energy line breaks at facility Paper will be presented at ASME Pressure Vessel & Piping Div & Analysis Committee 4th Natl Congress

 BASKIN'S P Southern California Edison Co 82/10/04 CHEN, P NRC No Detailed Affiliation Given 2pp 15678 165 24X

 Fiche 80-206:82/10/04.8210130276
- 8210260249 Provides add1 info supporting 820923 position that no fees are required for Amend 62 issued 820825 Surveillance program previously submitted w/Amend 57 for which appropriate fees applied BASKIN.K F Bouthern California Edison Co 82/10/04 MILLER.W & License Fee Management Branch ip 1979: 352 24X Fiche 50-206.82/10/04.8210260249
- B210070082 Discusses use of radwaste solidification sys Unit 2 license condition does not prevent util from using Chem-Nuclear Bys. Inc process to solidify wet solid radwaste produced at Unit 1 Bafety evaluation will be performed BASKIN.K P Bouthern California Edison Co 82/10/05 CRU(CHFIELD, D Operating Reactors Branch 3 2pp 13628 162, 24X Fiche 50-206,82/10/05,8210070082
- 8210080073 Informs that crans operating, maint & insp procedures implemented on 821001 per 820706 ltr: insuring compliance w/NURE9-0612 Cost & implementation schedule of Items 1-3 to be completed by 821215 due to vendor delays KRIEOER: R W Southern California Edison Co 82/10/05 CRUTCHFIELD, D Operating Reactors Branch 5 ip 15640 236 24% Fiche 30-204: 82/10/05:8210080093

- 821013008B Responds to 820825 ltr requesting info re SEP Topics [II-2 & III-4 A. "Mind & Tormado" be withheld Request cannot be approved until appropriate affidavit submitted CRUTCHFIELD.D Operating Reactors Branch 5 82/10/05 DIETCH.R Southern California Edison Ga 2pp 15673 124 24X Fiche 50-206.82/10/05,821013008B
- 8210180070 Forwards Amend 64 to License BPR-13, safety evaluation & notice of issuance & availability Amend revises App A Tech Specs & bases to reflect revised time intervals for entering various subcritical modes CRUTCHFIELD D Operating Reactors Branch 5 82/10/06 DIETCH.R Southern Callefornia Coison Co 3pp 15719 351 24X Fiche 50-206, 82/10/06, 8210180070
- --8210180073 Amend 64 to License DPR-13, revising App A Tech Specs & bases to reflect revised time intervals for entering various subcritical operational modes when limiting condition cannot be satisfied CRUTCHFIELD, D. Operating Reactors Branch \$ 82/10/06 7pp 15719 354 24X Fiche 50-206, 82/10/06.8210180070
- --8210180076 Safety evaluation supporting Amend 64 to License DPR-13 * Office of Nuclear Reactor Regulation, Director 82/10/06 Jpp 1\$719 361 24X Fiche 50-206.82/10/06.8210180070
- --B210180079 Notice of issuance & availability of Amend 64 to License PR-L3 CRUTCHFIELD, D Operating Reactors Branch 5 82/10/06 2pp 15720 QQL 24% Fiche 50-206.82/10/06/82/0180070
- 8210130324 Comments on proposed scope of Phase III of SEP as reflected in individual topic definitions appended to 820909 ltr.

 Staff encouraged to develop & implement means to incorporate positive attributes of Phase III in licensee/NRC interface MACICH.R M SEP Owners Group 82/10/07 EIEENHUT.D O Division of Licensing 7pp 13482 177 24X Fiche 50-000,82/10/07,8210130326
- 8210190065 Clarifies NRC 920630 request for addl info re TMI Item II B 3. "Post-Accident Sampling Bys " CRUTCHFIELD D Operating Reactors Branch 5 82/10/07 DIETCH,R Southern California Edison Co 3pp 15720 007 24X Fiche 50-206,82/10/07.82(0180065
- E210240214 Advises that final evaluation to determine applicability of EPRI program test results for power operated relief valves, safety valves & block valves, per TMI I tem II 0 I, will be sent by 821130 Delay due to need for add a nalyses KRIEOER, R W Southern California Edison Co 82/10/08 CRUTCHFIELD.D Operating Reactors Branch 5 1p 15804 265 24X Fiche 50-206, 82/10/08, 8210240214
- 8210150144 Submits updated schedules re NUREC-0737, Items II E 1 2, "Auxiliary Feedwater Initiation & Flow Indication."
 I A 1 3 1, "Limit Overtime," II D 1, "Performance Testing of PMR Relief & Safety Valves" & III D 3 4

 BASKIM.X P Southern California Edison Co 82/10/12
 CRUTCHFIELD.D Operating Reactors Branch 5 2pp 15697 292 24X

 Fiche 50-208, 82/10/12,8210150144
- 8210200023 Forwards draft evaluation of SEP Topic 1814 C. "Internally Camerated Missles " Facility adequately protected from Internally generated missles PAULSON. W Operating Reactors Branch 5 82/10/12 DIETCH.R Southern California Edison Co 33pp 19757 230 24X Fiche 50-206.82/10/12,8210200029
- B21015029B Notification of B21021 meeting w/util at plant site to discuss soil parameters re-seismic re-evaluation per SEP Topics III—6 & II-4 1
 PAULSON.W A Operating Reactors Branch 5 82/10/13 CRUTCHFIELD, D Operating Reactors Branch 5 2pp 15706 132 24X
 Fiche 50-206.82/10/13,821015029B
- 8210190671 Bummary of 821001 meeting w/util in Bethesda, MD re scope of seismic remevaluation program Addl info re vent stack, electrical equipment & instrument supports required PAULSON. # A Operating Reactors Branch 5 82/10/13 Operating Reactors Branch 5 5pp 15737 248 24% Fiche 50-206, 82/10/13, 8210190671
- 8210240448 Advises that safety-grade replacements for commercial grade anmeter & transducer have been received & will be installed prior to return to power from current outage Ungrades complete necessary compliance w/NUREO-0737, Item II E 1 2 8ASKIN,K P Southern California Edison Co 82/10/14 CRUTCHFIELD, D Operating Reactors Branch 5 1p. 15806 154, 24X Fiche-50-206, 82/10/14,8210260448

- 6210260272 Requests additime to complete proposed Tech Specs recontainment leakage testing, reflecting App J of 10CFR50, as requested in NRC 820803 ltr Proposed Tech Specs expected to be submitted by 821130 MRIEOER,R W Southern California Edison Co 82/10/15 CRUICHFIELD,D Operating Reactors Branch 5 ip 15801 351 24% Fiche 50-206,82/10/15,8210260272
- B210260229 Forwards request for add1 info to assist in NRC review of SEP Topic II-4 F. "Settlement of Foundations & Burled Equipment "Revised SAR incorporating appropriate revisions re soil conditions should be submitted CRUTCHFIELD.D Operating Reactors Branch 5 B2/10/18 DIETCH.R Southern California Edison Co 9pp 15799 139 24X Fiche 50-206.02/10/18.8210260229
- 8210260450 Forwards "Status of Category A Unresolved Safety Issues at San Onofre Nuclear Generating Station Unit 1" Rept provides description of each issue & discussion of NRC generic bases for continued operation & site specific considerations HEDFORD, N O Southern California Edison Co 82/10/20 CRUICHFIELD, D Operating Reactors Branch 5 40pp £5806 155 ,14x Fiche 50-206, 82/10/20, 8210260450
- 8210260472 Forwards supplemental info rept re NUREG-0612, "Control of Heavy Loads at Nuclear Power Plants" Rept contains commitments requiring changes to crane operating procedures to be implemented by 830115

 BASKIN, K.P. Sauthern California Edison Co. 82/10/21

 CRUTCHFIELD, D. Operating Reactors Brench 5 1p 15807 230 P4x Fiche 50-206, 82/10/21.8210260472
- --8210260477 "Control of Heavy Loads San Onofre Nuclear Generating Station Unit 1." supplemental info rept 4 Southern California Edison Co 82/10/31 22pp 15807 21 24x Fiche 50-206.82/10/21,8210260472
- B210290169 Forwards Amend 65 to License DPR-13.safety evaluation & notice of issuance & availability Amend incorporates NURGE-0737. Item If E i 1. "Auxiliary Feedwater Pumps & Vaives" into Tech Specs CRUTCHFIELD.D Operating Reactors Branch 5 82/10/22 DIETCH. (1 Southern California Edison Co. 3pp. 15854 189 24X Fiche 50-206. 82/10/22.8210290169
- --8210290175 Amend 65 to License DPR-13.incorporating NUREG-0737.ltm IT E 1 i. "Auxiliary Feedwater Pumps & Valves" into Tech Specs CRUICHFICED.D Operating Reactors Branch 5 82/10/22 5pp 15854 192 24X Fiche 50-206, 82/10/22.8210290169
- --8210290180 Safety evaluation supporting Amend 65 to Licenso DPR 13 < Office of Nuclear Reactor Regulation. Director 82/10/22 15pp 15854 197 24X Fiche 50-206.82/10/22,8210290169
- --8210290183 Notice of issuance & availability of Amend 65 to litente DR-13 CRUTCHFIELD.D Operating Reactors Branch 5 82/19/22 2pp 15854 212 24X Fiche 50-206,82/10/22,8210290169
- O Inspection reports: IE Bulletins & correspondence
- 821001000B Responds to F01A request for 19 categories of documents renuclear reactor events & safety problems Forwards documents listed in App A FELTON. J M Division of Rules and Records 82/06/28 UBCLL.R A Critical Mass Energy Project 15pp 15727 Q05 24% Fiche 50-000:82/06/28.821001000B
- --811191042 Comments on draft IE circular re MSIV failures to close Problem W/cantrol air for MSIV may be part of larger spectrum of problems for many valves MICHELSON, C Director's Office Gi/10/01 JDRDAN, E L Division of Resident & Regional Reactor Inspection ip I5730 335 24X Fiche 50-000, 82/06/28, 8210010008
- 82(0070007 Responds to FOIA request for eight categories of records restam generators & steam turbines App A documents provided in R Udell FOIA Request 81-313 Forwards documents listed in App B FELTON.J M Division of Rules and Records 82/08/10 LONO, B J Hinthrop, Stimson, Putnam & Roberts 9pp 13645 063 24X Fichs 50-000, 82/08/10, 8210070007
- --8210070139 Forwards tabulated data on steam generator insp & maint at factilities Data should be provided to licensees IPPOLITO.T Operating Reactors Assessment Branch 82/04/01 VAROA.S Operating Reactors Branch 1 CLARK.R Operating Reactors Branch 3 STOLZ.J Operating Reactors Branch 4 Spp 15645 131 24X Fiche 50-000, 82/08/10,8210070007

- -8210070172 Forwards info re steam generator integrity & insps at all operating PHRs.per 750320 & 21 requests Details of insps.
 Including defect indications, tube plugging criteria & tubes plugged uill not be provided escept for Point Deach (
 GDLLER K R Division of Reactor Licensing (NRR-1975 only)
 75/03/24 MACCARY.R B Division of Technical Review (NRR-1975 only)
 5pp 15645 196 24% Fiche 50-000.82/08/10.8210070007
- 210060264 Forwards IE insp Rept 50-206/B2-24 on 820802-31 No noncompliance noted BISHOP, T & Division or Resident, Reactor Project & Engineering Programs 82/09/17 PAPAY, L T Southern California Edison Co .pp 15619 309 244 Fiche 50-206.82/09/17.8210060264
- -8210060269 [E Insp Rept 50-206/82-24 on 820802-3] No noncompliance noted Major areas inspected plant operations during long-term shutdown, annual review of plant operations, monthly maint & surveillance activities & LER followup MILLER L. KIRSCH.DF Division of Resident, Reactor Project & Engineering Programs 82/09/16 App 15619 3[1 247 Fiche 50-206,82/09/17.8210060264
- COMMON TOWARDS IE Insp. Rept. 50-206/82-25 on 820830-0903 No noticempliance noted BISHCP. T. M. Division of Resident, Reactor Project & Engineering Programs 82/09/21 PAPAY. L.T. Southern California Edison Co. 2pp. 15619
- 8210060299 IE Insp Rept 50-206/82-25 on 820830-0903 No noncompliance noted Major areas inspected const activities associated wisersmic upgrading or safety-related structures & supports MAGNER, W. J. ZMETZIG.G. B. Division of Resident, Reactor Project & Engineering Programs 82/09/17. Spp. 15619-225-24X Fiche 50-206.82/09/21.8210060294
- *IO170232 Ark receipt of payment of civil penalties imposed on 820811 Proposed corrective action will be examined in future inspackE(RAD.) A Enforcement Staff 82/09/22 PAPAY.L T Southern falteornia Edison Co. 2pp. 15758-175 24X Fiche 50-206.82/09/22, 8210190322
- 10010049 Confirms 82102) mgt meeting in Rosemead.CA to discuss tystemafic discussment of licensee performance Anticipated meeting attenders & agenda encl CREWS.J. L. Division of Resident. Reactor Project & Engineering Programs 82/09/27 PAPAY.L T Southern California Edison Co Rep 15565 317 24% Fiche 50-206/82/09/27,8210010042
- 10250302 Forwards info per Item 3 of IE Guilletin 82-02, "Degradation or Threaded Fasteners in RCPB of PNR Plants "Repts required by Item 4 unli be submitted within 70 days of outlage corpletion HANNED, J G Southern California Edison Co 82/10/01 ENGELKEN, R H
- completion

 HANNED J G Southern California Editon Co 82/10/01 ENGELKEN, R H

 Region 5, Office of Director 5pp 15790 200 24X

 Fiche 50-206, 82/10/01, 8210250302
- 'IOO80210 Ack receipt of 820710 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-206/82-21 BISMOP.T W Division of Resident, Reactor Project & Engineering Programs 62/10/04 FOGARTY,D J Southern California Edison Co ip 15440 080 24% Fiche 50-206/82/10/04/8210080210
- G210080211 Responds to NRC 820812 ltr re violations noted in It Insp Rept 50-202/82-21 Corrective actions nonfine retardant wood, oily rags & combustible debris removed from areas & amend to include amergency light impairment prepared FOGARTY D J Southern California Edison Co 82/09/10 FNGELKEN,R H Region 5. Office of Director 5pp 15640 081 24X Fiche 50-206,82/10/04-8210080210
- 10080212 Ack receipt of 820907 ltr informing NRC of steps taken to correct violations noted in IE Insp. Rept 50-206/82-23
 BISHSP.T W Division of Resident. Reactor Project & Engineering Programs 82/10/04 PAPAVL T Southern California Edison Co. ip 15438 086 244 Fiche 50-206.82/10/04.8210080212
- 8210080214 Responds to NRC 820812 ltr re violations noted in IE Insp. Rept 50-206/82-23 Corrective actions station procedure amended to include instructions on drawing reactor coolant samples from all locations & double valve verification PAPAY.L T Southern California Edison Co 82/07/07 ENGELKEN.R H. Region 5.0 Effice of Director 3pp 15638 08/ 24X Fiche 50-206.82/10/04.8210080212
- OB190233 IE Info Notice BO-35, Suppl 1, "Leaking & Dislodged I-125 Implant Beeds" Svc list encl
 COBB. I Division of Fuel Facilities, Materials & Safeguards
 62/10/06 Consolidated Edison Co of New York 66pp 19761 250
 24X Fiche 50-000,82/10/06,8208190233

- 8208190238 IE Bulletin 82-03, "Stress Corrosion Cracking in Thick-Wall, Large-Diameter, Stainless Steel, Recirculation Sys Piping at BWR Plants " Svc list encl DEYQUNO, R C Director's Office, Office of Inspection and Enforcement 82/10/14 Consolidated Edison Co of New York 115pp [5810 125 24X Fiche 50-000, 82/10/14, 8208190238
- S Reportable occurrences, LERs & related correspondence
- 8210080124 Recommends that 810717 event reignition of gaseous waste decay tank should be considered for inclusion in NRC third quarterly AO rept to Congress for 1981 Details of event encl
 ORNSTEIN, H L Director's Office 81/08/06 MICHELSON, C
 Director's Office Jpp 15663 285 24X Fiche 50-206, 81/08/06, 8210080124
- S210010008 Responds to FOIA request for 19 categories of documents re nuclear reactor events & safety problems Forwards documents listed in App A FELTON.J M. Division of Rules and Records 82/06/28 UDELL.R A Critical Mass Energy Project 15pp 15727 005 24X Fiche 30-000 82/06/28,8210010008
- --8108130268 Forwards details re 810717 ignition of gaseous waste decay tank at facility Event should be included in Commission third quarterly AO rept to Congress for 1981
 GRMSTEIN.H L. Director's Office 81/08/06 MICHELSON.C
 Director's Office 3pp 15730 103 24X Fiche 50-000,82/06/28,8210010008
- --Biti300367 Operating Reactor Event Memorandum 81-32 on Bi0903, control room operator manually tripped reactor after transient from BRX power initiation by scam generator flow & level oscillator Caused by regulated power supply failure EISENHUT. De Division of Licensing 81/10/31 VQLLMER, R H Division of Engineering HANAUER, S H Division of Human Factors Safety MATTSON, R J Division of Safety Technology 9pp 15731 059 24X Fiche 50-000, BZ/06/28,8210010008
- --B201150180 Forwards draft FR notice re 810703 AO on failure of high pressure safety injection sys DIRCK8.W J Office of the Executive Director for Operations 81/12/08 CHILK.S J Office of the Secretary of the Commission
- 9210010260 PND-V-82-038A on 820922, one truckload of trace contaminated sewage dumped at Los Angeles County sewage treatment facility Contamination found in rinse truck Truck returned to licensee for decontamination Addl samples will be taken YUHAS.0. LENSLAMSKI.F Region 5. Office of Director 82/09/24 ip 15574 055 24X Fiche 50-206.82/09/24.8210010260
- 0210190490 Forwards revised LER 81-025/01X-2 Detailed event analysis encl RAY, H B Southern California Edison Co 82/10/06 ENGELKEN.R. H Region 5. Office of Director 2pp 15735 335 24X Fiche 50-206,82/10/06,8210190490
- --B210170506 Revised LER B1-025/01X-2 on B11025, while conducting to' shutdown valve testing, ball valve CV-534 did not close automatically on isolation signal Caused by failed relay closing circuit of each valve Relays replaced RAY.H B Southern California Edison Co B2/10/06 Re Office of Director ip 15735 337 24X Fiche 50-206.82 B210170490
- 8210250280 RD 82-025 on 821012 & 13. fire watch patrol posted lubrication oil reservoir area but not at post Time period exceeded 1-h interval by 30 minutes Caused by personnel misunderstanding RAY. H B Southern California Edison Co 82/10/14 ENGELK Region 5, Office of Director 2pp 15791 096 24X Fiche 50-204.82/10/14, 8210250280
- 8210280066 Forwards LER 82-023/03L-0 Detailed event analysis RAY, H B Southern California Edison Co 82/10/19 ENGELK Region 5, Office of Director 2pp 15837 249 24X Fiche 50-206.82/10/19, 8210280066
- ~-8210280068 LER 82-023/03L-0 on 820919, fire water crossije d during new const activities Caused by incorrect const digging process West fire water pump returned to svc ßack fire suppression hoses rigged RAY,H B. Southern California Edison Co 82/10/19 Re Office of Director ip 15837 251 24X Ficha 50-206.82 8210280066

V Operator Examinations

- 8210290314 Forwards "Improvements in Training & Requalification Programs as Required by TMI Action Items I A 2 1 & II B 4 for Ban Onofre Nuclear Generating Station. Unit 1." technical evaluation rept Training programs acceptable CRUTCHFIELD. D. Operating Reactors Branch 5 82/10/26 DIETCH.R Southern California Edison Co. 3pp. 15894 101 24X Fithe 50-206.82/10/26.8210290316
- --B210290320 "Improvements in Training & Requalification Programs as Required by TMI Action Items I A 2 1 & II B 4 for San Onofre Nuclear Oenerating Station, Unit 1," technical evaluation rept

 * Science Applications, Inc. NRC-03-82-094 SAI-184-029-17 B2/08/17 NRC NO Detailed Affiliation Given 15pp
 15854 104 24X Fiche 50-206, 82/10/26,8210290316

DOCKET 50-208 COLUMBIA UNIV RESEARCH REACTOR

- P Operating license stage documents & correspondence
- 8210270307 Advises that reactor has never been fueled or operated Fuel not on tampus No plans to activate reactor in near future Requests variance to 10CFR50.App E requirements until anticipated reactor startup MELKONIAN.E Columbia Univ 82/10/12 DENTON.H R Office of Nuclear Reactor Regulation. Director [p 15853 166 24X Fiche 50-208, 82/10/12,8210270309

DOCKET 50-213 HADDAM NECK PLANT

- P Operating license stage documents & correspondence
- 8209300326 Forwards "Geological & Seismological Biudies, Haddam NFCk Nuclear Station, Part I Responses to 1979 NRC info Request" & "Part II Responses to 1981 NRC info Request." in response to EEP Topics 11-4 & II-4 B COUNSIL, W O Connecticut Vankee Atomic Power Co 82/09/22, CRUTCHFIELD, D Operating Reactors Brench 5 2pp 13557-177 24X Fiche 50-213, 82/09/22,8209300324
- --8209300332 "Oeologica) & Sessmological Studies Haddam Neck Nuclear Station Part I Responses to 1979 NRC Info Request " Twelve oversize figures encl Aperture cards are available in PDR * Nestern Geophysical, 82/09/30 194pp 15557 181 24X Fiche 50-213,82/09/22,8209300326
- --8209300336 "Ocological & Seismological Studies-Haddam Neck Nuclear Station: Part II Responses to 1981 NRC Info Request " Nine ovesize figures encl Aperture cards are available in PDR # Western Geophysical 82/09/30 117pp 15558 Ot4 24X Fiche 50-213,82/09/22.8209300326
- 8210010207 Forwards "Haddam Neck Plant Procedure ADP 3 2-22-C RCB Venting of Moncondensible Gasss" & "Hillstone Nuclear Power Station RCB Venting Procedure OP 2378," in response to TMI Action Plan I tem II B I. "RCB High Point Vents" COUNSIL. H O. Connecticut Yankee Atomic Power Co COUNBIL, H O Northeast Nuclear Energy Co (subs of Northeast Utilities) COUNSIL, H O. Northeast Utilities 82/09/22 CRUTCHFIELD.D Operating Reactors Branch 3 CLARK, R A Operating Reactors Branch 3 3pp 15568 048 24X Fiche 50-000.82/09/22.8210010207
- --B210010210 Revision 2 to "Haddam Neck Plant Protedure ADP 3 2-22-C RCB Venting of Noncondensible Oases"

 * Connecticut Yankee Atomic Power Co. B2/08/26, 11pp 15568 031 24X Fiche 50-000.B2/09/22,8210010207
- --8210010214 Revision 2 to "Millstone Nuclear Power Station Unit 2 Plant Procedure DP 2398 RCS Venting Procedure " SCACE.6 E Northwast Nuclear Energy Co (subs of Northwast Utilities) 82/08/20 11pp 15566-062 24X Fithe 50-000.82/09/22.8210010207
- 8210010312 Requests that processing of B20812 license amend application be postponed Revised application changing radiological affluent Tech Specs will be docketed on or about 821115 for both facilities

 COUNBIL. H O Connecticut Yankee Atomic Power Co COUNBIL, H G. Northeast Nuclear Energy Co (subs of Northeast Utilities)

 COUNBIL. H O Northeast Utilities 82/09/22 CLARK.R A Operating Reactors Branch 3 CRUTCHFIELD.D, Operating Reactors Branch 5

 3pp 15574 047. 24X Fiche 50-000.82/09/22,8210010312

- 8210190663 Responds to open items re SEP Topic III-6 "Seismic Design Considerations," per 820622-23 meetings to discuss status of seismic re-evaluation program COUNSIL-N O Connecticut Yankee Atomic Power Co 82/09/27 CRUTCHFIELD. D Operating Reactors Branch 5 5pp 15738-213 243 Fiche 50-213.82/09/27.8210190663
- --8210190668 "Mechanical & Electrical Equipment Beismic Re-Evaluation Program, Haddam Neck Nuclear Generating Station." Interim rept 4 Stevenson & Associates 810182 | 82/06/30 224pp 15738 218 24X Fiche 30-213, 82/09/27, 8210190663
- 8210070010 Forwards summary of SEP topics for which facility does not meet current licensing acceptance rriteria CRUTCHFIELD.D Operating Reactors Branch 5 82/09/30 COUNSIL,H G Connecticut Yankee Atomic Power Co 45pp 15628 082 24X Fiche 50-213.82/09/30.9210070010
- 8210130331 Discusses revision of administrative procedures to incorporate revised working hour guidelines & provisions for authorizing deviations per 820208 & 0615 requests.TMI Item I A 1 3. "Shift Manning" & Generic Ltr 82-12 COUNSIL.H 0. COMPETTAL P. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). COUNSIL, W.O. Connecticut Vantee Atomic Power Co. 82/10/01 EISENRUT, D.G. Division of Licensing. 3pp. 15679-127. 24x Fichb. 50-000.82/10/01.8210130331
- 8210070404 Advises that review indicates requirements of NUREO-0/37 Items II E 4 2 & & [[E 4 2 7 re-containment isolation dependability have been met CRUTCHFIELD. D. Operating Reactors Branch 5 82/10/04 COUNSIL.W. Connecticut Yankee Atomic Power Co. 3pp 15633-314 24X Fiche 50-213,82/10/04,8210070404
- 8210120276 Forwards "Haddam Neck Plant Seismic Design," technical evaluation rept
 CRUTCHFIELD, D Derating Reactors Branch 5 FIN A-6426 112/10/04 COUNSIL. W G Connecticut Yankee Atomic Power Co 44pp 15654 201 24X Fiche 50~213,82/10/04,8210120296
- --B210120300 "Haddam Nock Plant Seismic Design," technical evaluation rept
 BRIDGES.T L , DUSCH.S L , MORTON,D K EG&G, Inc FIN A-6424
 EGG-EA-6016 B2/08/31 CHENG.T Division of Licensing 203pp
 15654 293 24X Fiche 50-213, 82/10/04, 8210120296
- 8210130205 Forwards safety evaluation of NUREG-0737.TMI Action life II E 1 2, "Auxiliary Feedwater Sys Automatic Initiation & Flow Indication (F-16,F-17).Haddam Neck Plant." technical evaluation rept CRUTCHFIELD.D Operating Reactors Branch 5 82/10/05 COUNSIL.W Q Connecticut Yankee Atomic Power Co 6pp 15675 271 24X Fiche 50-213.82/10/05.8210130205
- --B20B19017B "Auxiliary Feedwater Automatic Initiation & Flow Indicatic Haddam Neck Plant," technical evaluation rept KAUCHER, J E., FCRIMER, K. Franklin Institute/Franklin Research Center NRC-03-79-11B TER-05297-294 B2/0B/17 KCNDALL,R. WIGDOR,M NRC - No Detailed Affiliation Given 16pp 19675 2/s 24X Fiche 50-213.82/10/05/8210/30205
- 8210130326 Comments on proposed scape of Phase III of SEP as reflett+4 in individual topic definitions appended to 820909 ltm Staff encouraged to develop & implement means to incorporate positive attributes of Phase III in licensee/NRC interface KACICH-R M SEP Duners Group 82/10/07 EISEKHUT, D 0 Division of Licensing 7pp 15682 179 24% Fiche 50~000,82/10/07.8210130326
- B210210226 Forwards safety evaluation of licensee safety assessment of SEP Topic III-5 A. "Effects of Pipe Break on Btructures.Bys & Components Inside Contactment." Methodology & acceptance criteria appropriate to resolve issues in safety evaluation CRUTCHFIELD, D. Operating Reactors Brench 5 82/10/12 COUNDIL, W.C. Connecticut Vantse Atomic Power Co. 10pp 15766 321 24x Fiche 50-213, 82/10/12,8210210226
- 8210270200 Forwards summary of NRC positions on 26 unresolved safety (ssus; consisting of excerpts from NRC publications 5 repts to Congress & assessment of generic applicability Adequate basis exists to warrant continued plant operation COUNGIL.44 0 DPEKALJF Connecticut Yankee Atumic Power Co COUNGIL.44 0 Northeast Nuclear Energy Co (subs of Northeast Utilities) 82/10/13 CRUTCHFIELD.D Operating Reactors Brants 3 48pp 15824 254, 24X Fiche 50-000,82/10/13,8210270200
- 8210250363 Forwards *SEP Topic VII-1 A. Isolation of Reactor Protection Sys From Nonsafety Bys for Haddam Neck Plent, "final technical avaluation. CRUICHFIELD, D Operating Reactors Branch 5 FIN A-6425 82/10/20 GUUNSIL. N Q Connecticut Yankee Atomic Power Co 2pp 15790 151 24X Fiche 50-213,82/10/20.8210250363

- 8210250372 "SEP Topic VII-t A. Isolation of Reactor Protection Sys From Nonsafety Sys for Haddam Neck Plant," final technical evaluation
 MORKELL D J. UDY. A C. EGSO. Inc. FIN A-6425 EGG-EA-6033 E2/07/30 23pp 15770 153 24x Fiche 50-213, 02/10/20, 8210250363
- G. Inspertion reports: 16 Bulletins & correspondence
- 82(0070037 Responds to FOIA request for eight categories of records re steam generators & steam turbines App A documents provided in R Udeil FOIA Request 81-313 Forwards documents listed in App B FELICN. J M Division of Rules and Records 82/08/10 LONG, D J Winthrap. Stimson. Putham & Roberts 9pp 15645 063 24X Fishe 50-000, 82/08/10, 8210070007
 - P210070139 Forwards tabulated data on steam generator insp & maint at factilities Data should be provided to licensees [PPOLITO, T. Operating Reactors Assessment Branch 82/04/01 VARGA, S. Operating Reactors Branch 1 5pp 15645 131 24X Fiche 50-000,82/08/10.8210070007
 - 82100701'2 Forwards info ie steam generator integrity & insps at all nereting PURs, per 750320 & 21 requests Details of insps. including defect indications, tube plugging criteria & tubes plugged will not be provided except for Point Beach 1 GDLLER, K. R. Division or Reactor Licensing (NRR-1975 only) 75/03/24 MACCARY, R. Division of Technical Review (NRR-1975 only) 5pp 15445 194 24X Fiche 50-000,82/08/10,8210070007
- 5210010332 Ack receipt of 820513 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-213/82-03 Violation usl) be rescined due to misunderstanding retermination dates of contractor employees MARTIN. I T Division of Engineering & Technical Programs 62/09/23 CDUNSIL. N 9 Connecticut Yankee Atomic Power Co. 2pp 15569 164 24x Fiche 50-213,82/09/23,82(0010332)
- 5.10050374 Ack receipt of 820628 evaluation of SEP lopic III-3 C. Inservice Insp of Water Control Structures "No comments forwarded CDUNSIL W C Connecticut Yankee Atomic Power Co 82/09/24 (RUTCHFICLD, D Operating Reactors Branch 5 ip 15608 276 24X fichs 50-213, 82/09/24, 8210050376
- GE10150699 Forwards request for add1 info to complete review of B01104 response to IE Bulletin GO-11. "Masonry Wall Design" "Response expected within 60 days of ltr receipt (LARK.R A Operating Reactors Branch 3 82/09/28 COUNSIL.W Q (onnecticut Yankee Atomic Power Co COUNSIL.W Q Northeast Nuclear Energy Co (subs of Northeast Utilities) (3pp 15716 100 24X Fiche 50-000, 82/07/28, 8210150699
- E208190233 IE Info Notice 80-35, Suppl 1, "Leaking & Dislodged 1-12b Implant Seeds " Svc list encl (DBB.L I Division of Fuel Facilities, Materials & Safeguards E2/10/06 Consolidated Edison Co of New York 66pp 15761 250 24x Fiche 50-000, E2/10/06, E208190233
- 5-08190238 IE Bulletin 82-03, "Stress Corrosion Cracking in Thick-Wall, Large-Diameter, Stainless Steel, Recirculation Sys Piping at BMR Plants " Svc 11st encl DEYOUNG.R C Director's Office, Office of Inspection and Enforcement 82/10/14 Consolidated Edison Co of New York 115pp 15810 125 24X Fiche 50-000, 82/10/14, 8208190238
- 5210290189 Forwards IC insp Rept 50-213/82-17 on 820823-0928 No noncompliance noted STARGSTECKI.R Division of Project & Resident Programs 82/10/19, CQUNSIL.N O Connecticut Yankee Atomic Power Co 2pp 15853 313 24% Fiche 50-213,82/10/15.8210290189
- --8210270194 IE Insp Rept 50-213/82-17 on 820823-0926 No noncompliance noted Major areas inspected facility toursilog & record review surveillance & containment ent; REBELCHEKI, T., ELSASSER, T.C. Division of Project & Resident Programs 82/10/14 7pp 15853 315 24X Fiche 50-213,82/10/15,8210290189
- S Reportable occurrences. LERs & related correspondence
- 9210270245 Forwards LER 81-005/03L-0 GRAVES,R H Connecticut Yankes Atomic Power Co 81/05/18 ORIER, B Region 1. Philadelphia. Office of the Director (81/03/01) 1p 15822 341 24x Fiche 50-213,81/05/18,8210270245

- --B210270249 LER Bi-005/03L-0 on Bi0424, unattended welding cables found running through access in fire barrier, possibly preventing closure Caused by contractor failing to inspect fire barriers & failing to provide connectors in cables TEST, R Z Connecticut Yankee Atomic Power Co Bi/05/18 Region Philadelphia, Office of the Director (Bi/03/01) 2pp 15822 342 24X Fiche 50-213, Bi/05/18, B210270245
- 8210010008 Responds to FOIA request for 19 categories of documents re nuclear reactor events & safety problems Forwards documents listed in App A FELITON, J M Division of Rules and Records 82/06/28 UDELL.R A Critical Mass Energy Project 15pp 15727 005 24X Fichs 50-000: 82/06/28, 8210010008
- --BiliiBOOOI Recommends comprehensive assessment of plant operating conditions to detarmine specific predetermined time related sequences of occurrence to emergency buses SRP should be revised re design features
 ABHE.F Director's Office Bi/10/16 MICHELSON.C Director's Office 4pp 15731 049 24% Fiche 50-000.82/06/28.8210010008
- 8210100122 Forwards LER 82-006/03L-0 GRAVES,R H Comnecticut Vankee Atomic Power Co 82/10/05 HAYNES,R C Region 1, 0ffice of Director 1p 15721 277 243 Fiche 50-213, 82/10/05, 8210150122
- --82i0150128 LER 82-006/03L-0 on 820919, emergency dc battery bank II, cell 42. found leaking electrolyte through seam crack Inspervenied 11 more batteries w/cracks in same location Caused by cell plate expansion against jar & battery age QUINN. II D Connecticut Yankee Atomic Power Co 82/10/05 Region I. Office of Director 2pp 15721 278 24X Fiche 50-213, 92/10/05, 8210150122
- 8210280071 Forwards LER 82-007/03L-0 ORAVES,R H Connecticut Yankee Atomic Power Co 82/10/20 HAYNES,R C Region 1. Office of Director 1p 15837 247 24X Fiche 50-213.82/10/20.8210280071
- --8210280074 LER 82-007/03L-0 on 820927, operator received rod drive slave cycler failure/rod stop alarm-rendering all bank B subgroups inoperable Caused by master cycler relay hanging up due to poor relay contact hercury wetted contacts rewet QUINN:H D Connecticut Yankee Atomic Power Co 82/10/20 Region 1, Office of Director 1p. 15837 248 24X Fiche 50-213,82/10/20.8210280071

DOCKET 50-219 OYSTER CREEK NUCLEAR POWER PLANT

- F Security, medical, emergency & fire protection plans
- 8210220182 Ack receipt of 820812 ltr informing NRC of actions taken to improve amergency preparedness program per IE Emergency Preparedness Appraisal Rept 50-219/82-01 ALLAN.J M Region I. Office of Director. 82/10/12 FIEDLER.P II Oeneral Public Utilities QPU Service Corp 2pp 1577A 328 24X Fiche 30-219.82/10/12.8210220182
- --8210220187 Responds to IE Emergency Preparedness Appraisal Rept 50-219/82-01 Corrective actions training program developed, amergency control ctr moved away from control room & ventilation sys upgraded FIEDLER.P B, General Public Utilities - QPU Bervice Corp 82/08/12 SMITH,O H Division of Emergency Preparedness 9pp 15776.330, 24X Fiche 50-219.82/10/12.8210220182
- 8210250383 Forwards Revision 13 to physical security plan Revision withheld LAGOART.H U general Public Utilities GPU Service Corp. 82/10/19 Diffice of Nuclear Reactor Regulation. Director IP. 15790 136 24X Fiche 50-219.82/10/19.8210203893
- H General correspondence
- 8207180051 FOIA request for seven categories of info re nuclear matl transported by M Roh in Apr 1980 to Beatty, NV & General Public Utils submissions from 800101 per Price Anderson Act VAN BYUC, C Tomer, Parks, Beliger, Simonoff & Adourian, 82/08/24 FELTON, J M. Division of Rules and Records. 2pp 15760 196 24X Fiche 50-219,82/08/24,8207180051
- 8210190163 Partial response to FOIA request for seven categories of info re nuclear mat! transported by M Roh in Apr 1980 to Beatty.NV & General Public Utils submissions since 800101 per Price-Anderson Act re facility Forwards App A documents FELTON,J M Division of Rules and Records. 82/09/15, VAN 8YOC,C Tomar, Parks. 821gen. Simonoff & Adourien 2pp 18760,198 24X Fiche 50-219,82/09/15,8210190163

P Operating license stage documents & correspondence

- 8210010063 Informs that Erron Test Rept XN-NF-78-12, "Spray Cooling Heat Transfer Test Results, Phase-{I Facility & Test Data ENC 8x8 BHR Fuel," will be withheld per 10CFR2 790, in response to 820806 request CRUTCH-TELD. O Operating Reactors Branch 5 82/09/23 FIEDLER.P 8 General Public Utilities OPU Service Corp 3pp 15567 167 24X Fische 50-219.82/09/22.8210010063
- 8210010077 Forwards Mark I containment long-term program, plant-unique analysis repts for suppression chamber & vent sys & torus attached piping Safety relief valve piping analyses will be completed & forwarded by 821215
 FIEDLER, P. B. General Public Utilities GPU Service Corp. 82/09/24
 CRNICKFIELD. D. Operating Reactors Branch 5 2pp. 15566 093 24X
 Fiche 50-219,82/09/24,8210010077
- --8210010081 "Oyster Creek Nuclear Generating Station Hark I Containment Long-Term Program.Plant-Unique Analysis Rept.Suppression Chamber & Vent Sys" * MPR Associates, Inc. MPR-733 B2/08/31 300pp 15566-055 24X Fichs 50-219.92/09/24.8210010077
- --8210010085 "Ogster Creek Nuclear Generating Station Mark I Containment Long-Term Program, Plant-Vidue Analysis Rept. Torus Attached Piping "

 MPR Associates, Inc. YPR-734 82/08/31 157pp 15566 357 24X Fitche 50-217, 82/09/24, 82(0010077
- 6210040261 Forwards notice of consideration of issuance of amend to provisional QL, DPR-16,re increase in spent fuel storage capacity to 2.600 assemblies CRUTCHFIELD, D. Operating Reactors Branch 5 62/09/28 FIEDLER,P. B. General Public Utilities QPU Service Corp. 2pp. 15595 003 24X Fiche 50-219, 82/09/28, 82/0040261
- --B210040265 Notice of consideration of issuance of amend to provisional OL.DPR-16, re (increase in spent fuel storage capacity to 2,600 assemblies CRUFCHFIELD.D Operating Reactors Branch 5 82/09/28 4pp 15595 005 24X Fiche 50-219,82/09/28,8210040261
- 8210080053 Forwards INPO "Evaluation of Oyster Creek Nuclear Generating Station," per Moseley 810806 request & Stello 810626 memo SMITH.6 H Division of Emergency Pregaredness & Operational Support 82/09/29 TAYLOR.6 H Division of Reactor Programs ip 15643 037 24X Fiche 50-219,82/09/29,8210080063
- --8210080079 "Evaluation of Oyster Creek Nuclear Generating Station "
 s Institute of Nuclear Power Operations 81/12/31 33pp
 15643 038 24% Fiche 50-219.82/09/29.8210080063
- 8210270345 INTEGRATED PLANT SAFETY ASSESSMENT, SYSTEMATIC EVALUATION PROGRAM Obster Creek Nuclear Generating Station Docket 50-219 (CPU Nuclear Corporation And Jersey Central Power And Light Company)

 ** Division of Licensing NUREG-0822 DRFT 62/09/30 537pp 15850 146 24X Fiche 50-219.82/09/30.8210270345
- 8210130326 Comments on proposed scope of Phase III of SEP as reflected in individual topic definitions appended to 820909 itr Staff encouraged to develop k implement means to incorporate positive attributes of Phase III in licensee/NRC interface KACICH, R M SEP Owners Group 82/10/07 EISENHUT, D C Division of Licensing 7pp 13682 179 24% Fiche 50-000, 82/10/07, 8210130326

- 8210190502 Advises that company no longer performing analyses for LeviNuclear supplied fuel under irradiation in plant Util made
 separate arrangements Util utilizing or planning to utilize
 fuel for operating conditions outside analysed conditions
 OMSLEY.G F Exian Nuclear Co. Inc (subs of Exian Core)
 82210013 RUBENSTEINL S Assistant Director for Core & Plant
 Systems Ip [5740 198 24X Fiche 50-217.82/10/13.821019050]
- 8210200060 Forwards corrected FR notice of consideration of amend to License DPR-16 re spent fuel storage capacity published 821008 reflecting 821108 as deadline for requesting hearing CRUTCHFIELD D Operating Reactors Branch 5 82/10/13 HTC.DHH.P & General Public Utilities GPU Service Corp 4pp 15757,746 ,24s Fiche 50-219,82/10/13.8210200060
- 8210260182 Forwards Amend 63 to License DPR-16, safety evaluation R notice of issuance & availability Amend authorizes addition of control rod drive scram discharge vol high level & rod block to Tech Specs
 CRUTCHFIELD, D. Operating Reactors Branch 5 82/10/15 FIEDILM, P. D. General Public Utilities GPU Service Corp 2pp 15803, 130 , 41 Fiche 50-219, 82/10/15, B210260182
- --8210260185 Amend 63 to Liceuse DPR-16, authorizing addition of control rod drive sceam discharge vol high level & sciam trip hypothem rod block to Tech Specs
 CRUICHTIELD, D. Operating Reactors Branch 5 82/10/15 (3) p. 15803 232 24X Fiche 50-219, 82/10/15, 9210260182
- --8210260187 Safety evaluation supporting Amend 63 to License 10th 16 - Office of Nuclear Reactor Regulation, Director 62/10/15 , sp 15803 241 24X Fiche 50-219.82/10/15, 8210260182
- --8202010167 "Technical Evaluation Rept for BWR Scram Discharge Vol Long-Term Mods Oyster Creek Nuclear Generating Station " HUCHA,E Franklin Institute/Franklin Research Center NRC-03-81-130 TER-C5506-58 82/01/27 ECCLESTON, K NRC No Detailed Affiliation Given 55pp 15803 243 24X Fiche 50-219, 82/10/15, 8210260182
- --8210260191 Notice of issuance & availability of Amend 63 to (icen) # DR-16 CRUTCHFIELD, D. Operating Reactors Branch S. 82/10/15 Ppp 19803 298 24X Fiche 50-219.82/10/15.8210260182
- 8210210280 Submits add1 comments on SEP Phase II During final stages of SEP, NRC properly & effectively assessed safety intent of SRPs & evaluated ments of alternative proposals CLARK.P R General Public Utilities GPU Service Corp 62/10/18 CRUTCHFIELD.D Decrating Reactors Branch 5 2pp 15/63 148 343 Fiche 50-219, 82/10/18, 8210210280
- 8210230136 Forwards info re roactor protection sys power supply.in response to 820702 request for addl info Periodic functional testing will be performed on assemblies by removing motor generator set from distribution bus FIEDLER, P.B. General Public Utilities QPU Service Corp. 02/10/16/CRUTCHFIELD.D. Operating Reactors Branch 9 2pp. 19707-005 24x Fiche 50-219, 82/10/18,8210230134
- 8210250189 Requests approval of Tech Spec Change Request RB re adequaty of station electric distribution sys voltages & degraded grid protection for Class IE power sys.in response to Billoln itrs Voltage regulators provide no safety function FIEDLER.P B General Public Utilities GPU Service Corp 82/50/18 CRUCKFIELD.D Operating Reactors Branch 5 2pp 19700 286 244 Fiche 50-219, 82/10/18, 8210250189
- 8210290284 Submits corrections to discrepancies identified in util 821008 ltr re control room habitability One oversize drawing enci Aperture card is available in PDR FIEDLER, PB Oeneral Public Utilities QPU Service Corp 62/10/19 EISENUIT. D O Division of Licensing 2pp 15853 112 24X Fiche 50-219, 82/10/19.8210290254
- 8210270202 Advises of review of deviations to stated positions contained in NUREO-0737. Item II F 1 3. "Containment High Range Radiation Monitor" Monitors expected to be installed during Cycle II refueling outage CRUTCHFIELD.D Operating Reactors Branch 5 82/10/20 FIEDLER, P 8 General Public Utilities GPU Service Corp 2pp 15823 094 24K Fiche 50-219, 82/10/20,8210270202
- 8210250284 Notification of 821103 meeting w/util in Bethesda. HD to discuss core spray sparger effectiveness in steam environ at facility LOMBARDO. J. Operating Reactors Branch 5. 82/10/21 CRUTCHFIELD. D. Operating Reactors Branch 5. 3pp 15791 175 24K Fiche 50-219. 82/10/21, 8210250284

- 6210270004 Advises that response to NUREO-0737. Item II K 3 25, "Effect of Loss of AC Power on Pump Seals," acceptable, based on endorsement of BWR owners group position Mod to seal cooling for recirculation pumps not required CRUTCHFIELD. D. Operating Reactors Branch 5 82/10/22 FIEDLER, P B General Public Utilities GPU Service Corp 7pp 15815 353 24X Fiche 50-219, 82/10/22,8210270004
- Q Inspection reports, IE Bulletins & correspondence
- #210080015 Add1 response to FOIA request for 19 categories of info re nuclear reactor events 5 safety problems Formands documents listed in App A Documents in App B completely withheld (ref FOIA Exemption 5) FELTON, J M Division of Rules and Records 82/07/12 UDELL,R A Chitical Mass Energy Project 9pp 15665 027 24X Fiche 50-900, 82/07/12, 8210080015
- --8210080140 Systematic assessment of licensee performance notes re facility evaluation for Aug 19/9--Uul 1980 * NRC - No Detailed Affiliation Given 80/07/31 7pp 15648 008 24% Firshe 50-000,82/07/12,8210080015
- 8210070268 Forwards IE Insp Rept 50-219/82-20 on 820803-0907 % notice or violation STAROSTECKI.R Division of Project & Resident Programs 82/09/22 FIEDLER:P 8 General Public Utilities - GPU Service Corp 2pp 15634 148 24X Fiche 50-219,82/09/22,8210070268
- -9210070270 Notice of violation from 185p on 820803-0907 • Division of Project & Resident Programs 82/09/22 1 19534 150 24% Fiche 50-219,827/09/22,8210070268
- --8210070275 IE insp Rept 50-219/82-20 on 820803-0907 Noncompliance noted failure to follow equipment control procedures & prepare procedures consistent w/10CFR20 for work involving personnel radiation exposure COMGILL.C. THOMAS.J. TRIPP.L E Division of Project & Resident Programs 82/09/17 lOpp 15634 151 24X Fiche 50-219.82/09/22, 8210070260
- S210070341 Forwards IE Insp Rept 50-219/82-19 on 820802-06 No noncompliance noted MARTIN.T T Division of Engineering & Technical Programs 82/09/24 FIEBLER.P B General Public Utilities - GPU Service Corp 2pp 15634 092 24X Fiche 50-219.82/09/24.8210070341
- -8210070345 1E Insp Rept 50-219/82-19 on 820802-06 No noncompliance noted Hajor areas inspected licensee action on previous insp findings, radiation protection instrument calibr & training, pasting, labeling, ALARA program & radwaste program WRAY, J.R., RONE, C.A., GREENMAN, C.O. Division of Engineering & Technical Programs & 82/09/23 Hpp 15634-094 24X
 Fiche 50-219,82/09/24,8210070341
- 920B190233 IE info Notice 80-35, Suppl 1, "Leaking & Dislodged I-125 Implant Seeds " Svc list encl CDBB.L I Division of Fuel Facilities, Materials & Safeguards 62/10/06 Consolidated Edison Co of New York 66pp 15741 250 244 Fiche 50-000,82/10/04.8208190233
- G210250285 Requests relief from insplot listed welds using volumetric & surface exam methods Results of review of inservice insplant program requirements & justification for relief in inspecting 10 dissimilar metal welds encl
 FIEDLER.P B General Public Utilities GPU Service Corp 82/10/08
 CRUTCHFIELD.D Operating Reactors Branch 5 3pp 15791 172 24X
 Fiche 50-219.82/10/08.8210250285
- 6210190375 Ack receipt of 620831 ltr informing NRC of steps taken to correct violations noted in 1E Insp Rept 30-219/80-17 MARTIM T Division of Engineering & Technical Programs 62/10/12 FIEDLER.P B General Public Utilities OPU General Corp 2pp 15741 017 24X Fiche 50-219.82/10/12.8210190375
- --8210190398 Responds to NRC 820416 ltr reviolations noted in IE Insp. Rept 50-219/80-17 Corrective actions GA audit insp. program of health physics activities implemented & training & definitions of radiation protection steff improved FIEDLER.P B. General Public Utilities GPU Service Corp. 82/08/31 SMITH.G H. Division of Emergency Preparedness & Operational Support 15pp 15741 019 24X Fiche 50-219,82/10/12,8210190375
- 5210220182 Ack receipt of 620812 ltr informing NRC of actions taken to improve emergency preparedness program per IE Emergency Preparedness Appraisal Rept 50-219/82-01
 ALLAN, J M Region J, Office of Director 62/10/12 FIEDLER, P B Oeneral Public Utilities GPU Service Corp 2pp 15776 328 24X Fiche 50-219, 82/10/21,8210220182

- --8210220187 Responds to IE Emergency Preparedness Appraisal Rept 50-219/82-01 Corrective actions training program developed, emergency control ctr moved away from control room & ventilation sys upgraded FIEDLER,P B General Public Utilities - GPU Service Corp 82/08/12 SMITH.6 H Division of Emergency Preparedness 9pp 15776 330 24X Fiche 50-219.82/10/12.8210220182
- 8208190238 IE Bulletin 82-03, "Stress Corrosion Cracking in Thick-Wall, Large-Diameter, Stainless Steel, Recirculation Sys Pipfing at BMR Plants" Svc list encl
 DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/10/14 Consolidated Edison Co of New York 115pp 15810 125 24X Fiche 50-000, 82/10/14,8208190238
- S Reportable occurrences, LERs & related correspondence
- 82:10070438 Forwards angineering evaluation rept on 810827 shutdown cooling sys HX failure Failures diagnosd as fatigue failures due to flow induced vibration Event not considered AO Repairs to be complete by 81:012
 LANIK. 0 Director's Office 81/10/15 Director's Office 7pp 18637 337 24X Fichs 50-219,81/10/15:8210070438
- 921001000B Responds to FOIA request for 19 categories of documents re nuclear reactor events & safety problems Forwards documents listed in App A FELTON J M Division of Rules and Records 82/06/28 UDELL.R A Critical Mass Energy Project 15pp 15727 005 24X Fiche 50-000.82/06/28.8210010008
- --Bii0230085 Forwards engineering evaluation rept on shutdown conling syn HX failures which occurred in late Aug 1981 Failures diagnosed as fatigue failures due to flow induced vibration Recommends event not be considered AD LANIK, 0 F NRC No Detailed Affiliation Given 81/10/15 NRC No Detailed Affiliation Given 7pp 15731 042 24X Fiche 50-000,82/06/28,8210010008
- 8210130167 Ro on 820814, normal shutdown initiated to investigate higher than normal differential pressure readings in emergency svc water sys Caused by debris blockage consisting of live & dead animal matter Organisms removed & tubes cleaned FIEDLER.P B General Public Utilities QPU Service Corp 82/07/22 HAYNES.R C Region 1. Office of Director App 15673 047 24X Fiche 50-217, 82/07/22, 8210130167
- 8210070178 Forwards LER 82-049/03L-0 Detailed event analysis encl FIEDLER.P B General Public Utilities - OPU Bervice Corp 82/09/24 HAYNES.R C Region 1. Office of Director 3pp 15634 298 24X Fiche 50-219.82/09/24.8210070178
- --B210070161 LER 82-049/03L-0 on 920825. soven hydraulic anubbers failed functional testing after being replaced by certified functional spares Two snubbers had improper mati seals caused by seal degradation k/or worn poppet valves CHARTERINAL J General Public Utilities GPU Bervice Corp 62/09/24 Region 1. Office of Director ip 15634 301 24X Fiche 50-219,82/09/24 8210070178
- 821007023B Forwards LER B2-048/03L-0 Detailed event analysis encl FIEDLER.P B Queeral Public Utilities - OPU Service Corp 82/07/27 HAYNES.R C Region 1. Office of Director 3pp 15637 151 24X Fiche 50-219,82/09/27,8210070238
- --8210070241 LER 82-048/03L-0 on 820826, reactor water level instrumentation for one channel in each of several safety sys rendered inoperable as result of loss of ref column head and several problem of the several safety of RIOOLE, E I General Public Utilities OPU Bervice Corp 82/09/27 Region 1, Office of Director 1p 15637 154 24X Fiche 50-219, 82/09/27, 8210070238
- 8210130357 RO on 820829, reactor startup conducted w/inoperable rod worth minimizer Minimizer failed due to defective clock drive module in slot 4J of CPM unit, damaging several components All damaged components replaced FIEDLER, P. B. General Public Utilities QPU Service Corp. 8R/09/RB HAYNES, R. C. Region 1, Office of Director. 2pp. 15679-010. 24X Fiche 50-219, 82/09/28,8210130357
- 8210060374 PND-1-82-063 on 821001, anonymous phone caller notified licensee that bomb was set to go off in plant No bomb discovered in protected area COMGILL.C . TRIPP, MCCABE Region 1. Office of Director, 82/10/01 ip 15619 055 24X Fiche 50-219,82/10/01,8210060376
- 8210150098 Forwards LER 82-050/03L-0 Detailed event analysis encl FIEDLER.P B General Public Utilities - GPU Service Corp 82/10/01 HAYNES.R C Region i Office of Director 3pp 15701 178 24X Fiche 50-219, 82/10/01,821015009

- --8210150112 LER B2-050/03L-0 on 820828, reactor vessel pressurized in sicess of 110 paig offeactor water temp greater than 212 F Caused by inadequate Procedure A02 4 OOI Test procedure will be reviewed to redefine temp/pressure requirements SANTELLA: A Cemeral Public Utilities OPU Service Corp 82/10/01 Region 1. Office of Director (p. 15701 181 24X Fiche 50-219, 82/10/01.8210150098
- DUCKET 50-220 NINE MILE POINT NUCLEAR STATION, UNIT L F Security, medical, emergency & fire protection plana
- 8210010275 Forwards "Systematic Assessment of Licensee Performance (SALP), Nine Mile Point Nuclear Station Unit 1." for May 1991 Apr 1982.util 820728 ltr re performance improvements NRC 920530 request List of SALP 620708 meeting attenders encl HAYNES, R.C. Region 1, Office of Director 82/07/28 RHODE, G.K. Nigagra Mphauk Power Corp. 4pp 15568 327 24% Fiche 50-220, 82/09/28, 8210010275
- --8210010280 "Systematic Assessment of Licensee Performance, Nine Mile Point Nuclear Station Unit 1." for May 1981-Apr 1982 * Region 1. Office of Director 82/06/22 27pp 15568 331 24x Fiche 50-220,82/07/28.8210010275
- 8210060202 Ack receipt of 820324 ltr informing NRC of steps taken to improve items identified in Apps A:B & C of IE Emergency Preparedness Appraisel Rept 50-220/81-18 SHITH, G H Division of Emergency Preparedness & Operational Support 82/09/27 RHODE:O K Niagara Hohaw Power Corp 2pp 13614 018 24X Fiche 50-220-82/09/29,82100/29-82600202
- --8210060208 Responds to NRC 820222 ltr transmitting IE Emergency Preparedness Appraisal Rept 50-220/81-18 Descriptions of assessment/actions to be taken for improving items identified in Apps A/B & C of rept encl LEMPGES, T E Niagara Mohawk Power Corp 82/03/24 HAYNES, R C Region 1. Office of Director 22pp 156/14/020 24X Fiche 50-220, 82/09/29, 8210060202
- 821004029& Forwards review of safe shutdown analysis in response to 820426 request for add into re 100FR90.App R: Sections 111 0 & 111 L DC sys 125-volt analysis for breaker fuse coordination to be completed by 821231 MANGAN.C V Niagara Hohawk Power Corp 82/10/01 VASSALLO D B Operating Reactors Branch 2 ip 13596 001 24X Fiche 50-220,82/10/01.8210040276
- --8210040303 App R review of eafe shutdown analysis • Miagara Hohauk Power corp 82/10/01 441pp 15596 002 24X Fiche 50-220,82/10/01.8210040276
- 8210050083 Forwards "Dispersion Model Description for Nine Hile Point/ James A Fitpatrick Nuclear Stations." upgraded meteorological syx description per THI Action Item III A 2 BAYNE.J P Power Authority of the State of New York 82/10/01 VASSALLO, D B Operating Reactors Branch 2 2pp | 15604 255 24X Fiche 50-303, 82/10/01,8210050083

- P Operating license stage documents & correspondence
- 8210050014 Approves recirculation sys piping removal info required prior to safe-end replacement VASSALLO, D 8 Operating Reactors Branch 2 82/09/02 DISE, D PRIOR Magaza Mohauk Power Corp 3pp 15624 OSB 24X Fichs 50-220, 82/09/02, 8210050014
- 8210120632 Advises that 800421 request for title change of vice-president closed out since util advised change no longer required VASSALLO.D B Operating Reactors Branch 2 82/09/17 DISE.D & Niagara Mohaul Power Corp 2pp 15672 271 24X Fiche 50-220, 82/09/17, 8210120632
- 8210010033 Submits info re removal & replacement of reactor recirculation sys piping, per 620922 request Combined man rem exposure estimates bounded by original estimate of 2.905 man rem MANGAN.C V Niagara Mohawk Power Corp. 82/09/27 EISENHUT, D.C. Division of Licensing 2pp 13565 170 24X Fiche 50 220. ID/09/27/
- 8210040117 Forwards fee for Tech Spec changes re-containment is statum dependability in compliance w/requirements of NUREO-0737 & reactor recirculation safe-end replacements program Fee submittal in response to NRC 820825 itr MANDAN.C V Niagara Mohawk Power Corp 82/07/27 DIGOLN Licenst Fee Management Branch 2pp 15581 189 24% Fichs 50-220, N2/07/27, 8210040117
- 8210040182 Forwards "Nine Mile Point Unit 1 Station Power Distribution Sys (Class IE) Load Study & Frield Test." in response to NRC 810202 request Required motor rewinding & cable replacement will be performed during next scheduled refueling outage LEMPOES, T. E. Niagara Hohawk Power Corp. 82/09/27 VASGALID, B. Operating Reactors Branch 2 3pp. 15982 206 24X Fiche 50~220,82/09/27.8210040182
- --B210040183 "Mine Mile Point Unit | Station Power Distribution Tys (Cless IE) Load Study & Field Test " BLASIAKL J., RIBEIROJ , LAIRDIR C Niagera Mohawk Power (orp B1/12/10 96pp 15582 210 24X Fiche 90 220.82/09/2/.8/210040848.
- 8210010275 Forwards "Systematic Assessment of Licensee Performance (SALP). Name Hile Point Nuclear Station Unit 1." for May 1781 Apr 1982.util 820728 ltr reperformance improvements kNRC 820630 request List of SALP 820708 meeting attendees oncl HAYNES.R C Region 1, Office of Director 02/09728 RHRN1.U KNI49878 Mohawk Power Corp. 4pp. 15568 327 24X Fiche 50-220.82/09728.8210010275
- ~-8210010280 "Systematic Assessment of Licensee Performance, Pills Hile Point Nuclear Station Unit 1." for May 1981-Apr 1982 * Region 1. Office of Birector 82/06/22 27pp 15560 J/N 448 Fiche 50-220, 82/09/28, 8210010275
- --9210010287 Responds to radiological controls section of 820A2A systematic assessment of Ilcensee performance rept Commitments for performance improvements provided LEMPOES.T E Niagara Mohauk Power Corp 82/07/28 STAROSTECKI. Division of Project & Resident Programs App 15568 358 24% Fiche 50-220,82/09/28,8210010275
- --8210010294 Informs of 820708 meeting at site to discuss NRC 82084 is systematic assessment of licensee performance Discussion of efforts re radiological control activities should be prepared STARGSTECKI,R Division of Project & Resident Programs 82/04/30 LEMPOES,T E Niegara Mohawk Power Corp 2pp 15568-342 24X Fiche 50-220,82/09/28-8210010275
- 8210050260 Forwards 42 oversize drawings showing connection of alternate shutdown sys to normal shutdown sys in response to NRC 820426 Ity Aperture cands are available in PDR MANOAN.C V Niegera Hohauk Power Corp 82/09/30 VASBALLO, D & Operating Reactors Branch 2 ip 15603 001 24X Fiche 50-220.82/09/30.8210050260
- 8210050334 Notifies that proposed mods to automatic depressuritation sys logic will not be submitted until 821203 Delay needed to consider affects of listed analyses MANGAN.C V Niagara Mohawk Power Corp. 82/09/30 EIBENHUT. P. P. Division of Licensing 1p. 15601 348 24% Fiche 50-220, 82/09/30 8210050354
- 82(10050111 Forwards one oversize revised schedule for recirculation sys repairs at facility. Aperture card is available in PDR MANDAN.C V Niagara Mohauk Power Corp 82/10/01 VASSALLO, D B Operating Reactors Branch 2 ip 15603 002 24X Ficher 30-220, 82/10/01, 8210050111

- 82[0]30107 Submits addl info to 820727 ltr re analysis criteria for recirculation sys piping replacement Reanalysis criteria provides same margin as original criteria High energy line break would not affect engineered safeguard sys MANOAN, C V Niagara Mohawk Power Corp 82/10/05 EISENHUT, D 0 Division of Licensing 3pp 15673 101 24% Fiche 50-220,82/10/05,8210130107
- 8210280144 Informs that review of tachnical evaluation rept,
 "Comparison of Plant & Model Radiological Effluent Tech
 Specs & Plant Offsite Dose Calculation Manual.Nine Mile
 Point Nuclear Station Unit 1." will be completed by 821130
 LEMPOES.T E Niagara Mohauk Power Corp 82/10/25 VASSALLO.D B
 Operating Reactors Branch 2 1p 15837 135 24X
 Fiche 50-220.82/10/25.8210280144
- Q Inspection reports, IE Builetins & correspondence
- 8210080015 Add1 response to FOIA request for 19 categories of info re nuclear reactor events & safety problems Forwards documents listed in App A Documents in App B completely withheld (ref FOIA Exemption 5) FELTON.J H Division of Rules and Records 82/07/12 UDELL,R A
- FELTON, J.H. Division of Rules and Records 82/07/12 UDELL, R. Critical Mass Energy Project 9pp 15645 027 24X
 Fiche 50-000, 82/07/12, 8210080015
- --B210080139 Systematic assessment of licensee performance notes refacility evaluation for Feb 1980-Oct 1981 ** NRC - No Detailed Affiliation Given 81/01/31 Spp 15568 003 24% Fiche 50-000.82/07/12.8210080015
- 2210070337 Forwards IE Insp Rept 50-220/82-14 on 820801-31 & notice of violation STAROSTECKI, R Division of Project & Resident Programs 82/09/22 RHODE, G K Niagara Mohawk Power Corp 2pp 15434 073 24X Fiche 50-220,82/09/22,8210070337
- -9210070342 Notice of violation from insp on 820801-31 * Region 1, Office of Director 82/09/22 ip 19634 075 24X Fiche 50-220, 82/09/22, 8210070337
- -8210070350 IE Insp Rept 50-220/82-14 on 820801-31 Noncompliance noted failure to follow radiation work permit requirements for full face respirators HUBSON.B D , KIBTER.H B Division of Project & Resident Programs 82/09/17 8pp 15634 076 24% Fishe 50-220,82/09/22,8210070337
- 210010157 Ack receipt of 820818 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-220/82-10 MARTIN T T Division of Engineering & Technical Programs 82/09/24 RHODE G K. Niagara Mohawk Power Corp ip 15567 254 24X Fichs 50-220,82/09/24.8210010157
- -8210010165 Responds to NRC 820719 ltr re violations noted in IE Insp Rept 50-220/82-10 Corrective actions safety evaluation to procedures for reactor vessel recirculation norile safe-end replacement reviewed by site operations review committee LEMPGES: T E Niagara Mohawk Power Corp 82/08/18 MARTIN, T T Division of Engineering & Technical Programs 3pp 19867-255, 24X Fiche: 90-220, 82/09/24, 8210010157
- 'EOO10275 Forwards "Systematic Assessment of Licensee Performance (SALP). Nine Mile Point Nuclear Station Unit 1: " for May 1981 -Apr 1982.vtl 8 20728 itr re performance improvements & NRC 820630 request List of SALP 820708 meeting attendess encl HAYMES.R.C. Region 1. Office of Director 82/09/28 RHODE, 0 K Niagara Mohauk Power Corp. 4pp. 15568 327 24X Fiche 50-220, 82/09/28.8210010275
- 8210Di0280 "Bystematic Assessment of Licenses Performance, Nine Hile Point Nuclear Station Unit 1," for May 1981-Apr 1982 * Region 1, Office of Director 82/06/22 27pp 15568 331 24X Fiche 50-220, 82/09/28, 8210010275
- 9210010287 Responds to radiological controls section of 820522 systematic assessment of licensee performance rept Commitments for performance improvements provided LEMPGES-TE Niegara Mohawk Power Corp 82/07/28 STAROSTECKI, R Division of Project & Resident Programs 4pp 15568 358 24X Fiche 50-220,82/09/28,8210010275
- 3210010294 Informs of 820708 meeting at site to discuse NRC 820623 systematic assessment of licensee performance Discussion of efforts re radiological control activities should be prepared BTAR08TECKI, R. Division of Project & Resident Programs 82/06/30 LEMPQES.T E. Niagara Mohauk Power Corp. 2pp 15568 362 24X Fichs 50-220,82/09/28,8210010875

- 8210060202 Ack receipt of 820324 ltr informing NRC of steps taken to improve items identified in Apps A.B & C of IE Emergency Preparedness Appraisal Rept 50-220/81-18 SMITH, O H Division of Emergency Preparedness & Operational Support 82/09/29 RHODE, O K Niagara Mohawk Power Corp 2pp 15614 018 24X Fiche 50-220,82/09/29,8210050202
- --821006020B Responds to NRC 820222 Itr transmitting IE Emergency Preparedness Appraisal Rept 50-220/81-1B Descriptions of assessment/actions to be taken for improving items identified in Apps A.B & C of rept encl LEMPGES,T E Niagara Hohawk Power Corp B2/03/24 HAYNES,R C Region 1. Office of Director 22pp 15614 020 24X Fiche 50-220,B2/09/29.8210060202
- 8208190233 IE Info Notice 80-35, Suppl 1, "Leaking & Dislodged I-125 Implant Seeds " Svc list enci COBB.L | Division of Fuel Facilities, Materials & Safeguards 82/10/06 Consolidated Edison Co of New York 66pp 19761 250 24% Fiche 50-000, 82/10/06,8208190233
- 8210210255 Forwads IE Insp Rept 50-220/82-16 on 920824-27 No noncompliance noted MARTID.T I Division of Engineering & Technical Programs 82/10/06 RMDDE, 6 K. Niagara Mohawk Power Corp 2pp 15766 237 24% Fiche 50-220.82/10/06.8210210255
- 8210290103 Forwards IE Bafeguards (nsp. Rept. 50-220/82-18 on 020915-16)
 No noncompliance noted
 MARTIN: T Division of Enganeering & Technical Programs 82/10/08
 SUNSER, J J Niagana Mohauk Power Corp. 2pp. 15853-257 24X
 Fiche 50-220, 82/10/08, 8210290103
- --8210290107 IE Safeguards Insp Rept 50-220/82-18 on 820915-16 No noncompliance noted Major areas inspected organization & operation shipping & receiving storage & internal control physical inventory & records & repts COHEN. I. WOLTNER. E. GODY, A.T. Division of Engineering & Technical Programs 82/10/07 6pp 15853-257 24X Fichs 50-220, 82/10/08, 8210270103
- 0208190238 IE Bulletin 82-03, "Stress Carrosian Cracking in Thick-Wall, Large-Diemeter, Stainless Steel, Recirculation Sys Piping at BHR Plants " Svc list encl DEYGUNO, R C Director's Office, Office of Inspection and Enforcement 82/10/14 Consolidated Edison Co of New York 115pp 15810 125 24X Fiche 50-000, 82/10/14, 8208190238
- 8210260177 Ack receipt of 820915 ltr informing NRC of steps taken to correct violations noted in IE lines Rept 50-220/82-06 MARTIN.T T Division of Engineering & Technical Programs 82/10/21 RHODE.0 K Niagara Mohawk Pawer Corp ip 13799 042 24X Fiche 50-220.82/10/21,8210260177
- ---8210260184 Responds to NRC 820819 itr reviolations noted in IE Insp Rept 50-220/82-06 Corrective actions personnel surveyed, nase1 smears taken, meeting held w/personnel & disciplinary action taken LEMPOES: TE Niagara Mohawk Power Corp 82/09/15 MARTIN, T T Division of Engineering & Technical Programs 2pp 15799 04:3 24X Fiche 30-220,82/10/21,8210260177
- A Periodic operating reports & related correspondence
- 82:0130347 Forwards monthly operating rept for Sept 1982 LEMPGES, T E Niagara Mohawk Power Corp 82/10/06 Director's Office, Office of Inspection and Enforcement 1p 15679 134 24X Fiche 50-220,82/10/06,8210130347
- --8210130350 Honthly operating rept for Sept 1982 ROMAN,T W Niagara Mohawk Power Corp. 82/10/05 4pp 15679 135 24% Fiche 50-220,82/10/06,8210130347
- 8 Reportable occurrences, LERs & related correspondence
- 8210150135 Forwards LER 81-019/03L-0 BARTLETT, J Niagara Mohawk Power Corp 81/07/07 GRIER, 8 H Region 1, Philadelphia, Office of the Director (81/03/01) 1p 15697 085 24X Fiche 30-220, 81/07/07, 8210150135

- --8210150142 LER BL-0(9/03L-D on 810607.while performing local leak rate testing.1-inch Fisher isolation valve 39-11 of emergency condenser steam line drain sys failed to seat Gausad by worn seating & packing malls Valve repacted NE(LD, J. Niagara Hohawk Power Corp. 81/07/06 Region 1. Philadelphia, Office of the Director (81/03/01) ip 13697 086 24X Fiche 50-220,81/07/07.82(0150135
- 9210050284 Forwards LER 82-012/04L-0 LEMPCES,TE Naggra Hobauk Pour Corp 82/09/24 HAYNES,R C Region 1, Office of Director 1p 15621 071 24X Fiche 50-220,82/09/24,8210060284
- -8210060291 LER B2-012/04L-0 on 820831.1cmer limit of detection sensitivity not met for several radionuclides in analysis of fish samples. Tech Spec parameter too narrow for welding weight units conversion Tech Spec revision underway PATROW, N. Niagara Hohauk Power Corp. 82/09/24 Region L. Ottice of Director. Lp. 15621-072, 24x Fishe 50-220,82/09/24,8210060284
- 8210010007 PNO-1-82-0310 on 820924.eight ultrasonic indications found in earrgency condenser sys piping & four in shuddown cooling says piging Evaluation revealed indications due to piping geometry & not reportable KISTER.H. BRUNNER.E. Region L. Office of Director 82/09/27 ip 15565 162 24% Fiche 50-220.82/09/27.8210010007
- 8210280121 LER 82-001 has been canceled COLLINS, M. Niagara Hohawk Power Corp. 82/10/19 Region 1, Office of Director up 15837 022 24X Fiche 50-220,82/10/19,8210280121
- DOCKET 50-223 UNIV OF LOHELL RESEARCH REACTOR

 R Ferrodic operating reports & related correspondence
- 6210280183 Forwards monthly operating for June 1982 HALLACE.T Lowell. Univ of 82/10/21 Director's Office. Office of Inspection and Enforcement ip 15837 Oli 24X Fiche 50-223.82/10/21,8210280183
- --8210280186 Monthly operating mept for June 1982
 Lowell. Univ of 82/10/21 7pp 15837 012 24X
 Fiche 50-223.82/10/21,8210280183
- DOCKET 50-228 AEROTEST RADIOGRAPHY & RESEARCH REACTOR
 F Security, medical, emergency & fire protection plans
- 8210060126 Forwards (E Insp Rept 50-228/82-02 on 820830 & 0902 No noncompliance noted 300K.N E Division of Radiologica) Safety & Safeguards Program 82/09/15 NEMACHECK.R Accodest Operations 4pp 15614 320 24X Fiche 50-228
- --8210060131 IE Insp Rept 50-228/82-02 on 820830-0902 No noncompliance noted Major areas inspected radiation protection program: emergency planning program 2 environ monitoring program CILLIS.H., WENSLAMEN, P. A., BOOK, H. E. Division of Radiological Safety & Bafeguards Program 82/09/14 8pp 15614-324 24X Fiche 50-228,82/09/15,8210060126

- --B209290189 Forwards public version of Revision 4 to generating statics emergency Plan corporate command ctr Emergency Plan Inplementing Procedure EGF-3, "Environ/Emergency Coordinator " Receipt form encl PAJOMSKI, J E Commonwealth Edison Co B2/09/01 DENTON, H R NPC NO Detailed Affiliation Given 1p 15564 123 24X Fichs 50-000, B2/09/16, 8209290125
- --B209290225 Public version of Revision 4 to generating station emergency plan componete command ctr emergency plan Implementing Procedure EOF-3, "Environ/Emergency Coordinator"
 PAJOHSKI, J E , LITERSKI, L A , FLESSNER, S A Communwealth Edison Co. B2/08/31 lipp 15564 124 24X Fiche 50-000, 82/09/16, 82/0929/0125
- 8210010009 Forwards info to suppl 820701 request for exemption from Agg R per 820917 telcon Request applies to Sections III 0 2 a b III 0 3 b re installation of fire suppression sys RAUSCH.T J Commonwealth Edison Co 82/09/23 EISENHUT.D 0 Division of Licensing 8pp 15365 152 24X Fiche 50-000.82/09/23, 82/09/00097
- 92:0130376 Advises that installation of offsite dose calculation sysprogram fully operational tracking model & operational A-model will be delayed until 82:231 to complete prime computer installation SMARTZ.E D Commonwealth Edison Co 82/10/06 DENTON, H R Uffice of Nuclear Reactor Regulation, Director 2pp 15682 098 24X Fiche 50-000,82/10/06,8210130376
- 8210290047 Releases public version of revisions to Quad Cities, Zion by Desiden emergency plan annexes & revised generating station emergency plan telephone directory FELTON. J. B. Division of Rules and Records 82/10/08 Document Management Branch ip 15977 313 24X Fiche 50-000, 88/10/08, 8210290047
- --B210270060 Forwards public version of Revision 3 to Quad Cities & Iist emergency plan annexes. Revision 2 to Dreaden emergency plan annexes. Revision 0 to Byron emergency plan annex & revised generating station smergency plan telephone directory MODRE.R D Commonwealth Edison Co 82/07/30 DENTON.H R NRC No Detailed Affiliation Given 5pp 15877 314 24X Fichs 50-000, 82/10/08, 8210290047
- --8210290077 Public version of Revision 3 to Quad Cities & Zion emergency plan annexes, Revision 2 to Dresden emergency plan annex & Revision O to Byron emergency plan annex * Commonwealth Edison Co 82/06/30 102pp 15877 319 24X Fichs 50-000, 82/10/38, 8210290047
- --8210270088 Public version of revised generating station emergency plantalephone directory
 QALLE.D P Commonwealth Edison Co 82/08/12 43pp 15878 218
 24X Fiche 50-000.82/10/08.8210270047
- 8210220358 Provides info re organization & performance of depts responsible for radiation protection activities, per 820702 commitment Training coordinator assigned in Apr 1982 to improve health physics training programs TRAMMIT R Commonwealth Edison Co 82/10/14 DENTON.H.R Office of Nuclear Reactor Regulation, Director 9pp 19776 287 24X Fiche 50-000-82/10/14.0210220358
- 8210230170 Advises that plans & preparedness for offsite protection near facility adequate & will be applied in event of radiological amergency IL State & local plans approved subj to verification of adequacy of alerting & notification sys THOMAS-L M Federal Emergency Management Agency 82/10/14 DIRCKS W J GFfice of the Executive Director for Operations 19 13788 285 24X Fiche 50-010,82/10/14.8210250170
- Q Adjudicatory correspondence
- B210010257 Decision ALAB-695 affirming LBP-B1-37 & LBP-B2-65, sanctioning mod to OL for Unit 3 to permit installation of five high density spent fuel storage racks & authorizing issuence of amends to OLs, respectively TQMPKINS, B A Atomic Sefect and Licensing Appeal Panel B2/09/29 2pp 15574 056 24X Fiche 50-237, B2/09/29, B210010257
- P Operating license stage documents & correspondence
- 8210080001 Advises that board notification issued on 820903 rs use of auxiliary overhead crans rather than main overhead crans to move spent fuel pool racks should have been assued w/Number BN-82-92 MIRACLIA.F. Assistant Director for Safety Assessment 82/09/14 Atomic Safety and Licensing Board Panel 4pp 13668 341 24% Fiche 30-237.82/09/14.8210080001

DOCKETED ITEMS

- --8210080002 Board Notification 82-92 informs of util failure to carry out fuel pool rack removal & installation in manner described in testimony at hearings Auxiliary overhead crane used instead of redundant main overhead crane [PPOLITO, T.A. Assistant Director for Safety Assessment 82/09/03 Atomic Safety and Licensing Board Panel 2pp 15668 345 24X Fiche 50-237,82/09/14,8210080001
- --8209210383 Recommends board notification re util use of auxiliary crane instead of main redundant crane to install fuel racks, as described in testimony before ASLB Licensoe has committed to rollow testimony in completing remaining work IPPOLITO, T.A. Assistant Director for Safety Assessment 82/09/03 EISENHUT, D.O. Division of Licensing 2pp 15668 349 24X Fiche 50-237, 82/09/14.8210080001
- 8210050309 Forwards final safety evaluation of SEP Topic VI-4, 'Containment Isolation Sys " Evaluation will be basic input to integated safety assessment Differences from current criteria listed O CONNOR, P Operating Reactors Branch 5 82/09/24 DELGEORGE, Commonwealth Edison Co 28pp 15608 184 24X Fiche 50-237, 82/09/24, 8210050309
- 8210120105 Requests delay of implementation due dates re NUREO-0737, Items II B 2. "Plant Shielding," II B 3. "Post-Accident Sampling" & II F I I. "Noble Gas Effluent Monitor "SHARTZ.E D Commonwealth Edison Co 82/10/04 EISENHUT, D 0 BIVISION of Licensing Spp 15651 237 24X Fiche 50-000,82/10/04,8210120105
- 82:0190464 Informs that mods to SRP Section B 3 2 re SEP Topic VIII-3 B on dc power sys bus voltage monitoring & annunciation initiated Mods will provide Battery voltage indication in control room & will replace process computer RAUSCH.T J Commonwealth Edyson Co 82/10/05 O'CONNOR.P Operating Reactors Branch S 1p 15740 298 24Y Fiche 50-237.82/10/05.8210190464
- 8210260526 Forwards Revision 3 of Chapter 9 of "Offsite Dose Calculation Manual" ODLBENJC Commonwealth Edison Co 82/10/06 CASE,E G Office of Nuclear Reactor Regulation, Director 2pp 15805-137 24X Fiche 50-000-82/10/06-8210260526
- --8210260542 Revision 3 of Chapter 9 of "Offsite Dose Calculatio Manual" * Commonwealth Edison Co 82/09/30 83pp 15805 139 24X Fiche 50-000, 82/10/06, 8210260526
- 8210130326 Comments on proposed scape of Phase III of SEP as reflected in individual topic definitions appended to 820909 ltr Staff encouraged to develop & implement means to incorporate positive attributes of Phase III in licenses/NRC interface KACICH.R M SEP Owners Group 82/10/07 EISENHUT.D C Division of Licensing 7pp 15482 179 24% Fiche 50-000, 82/10/07, 8210130326
- 3210180059 Provides add1 guidance & clarification re 820806 request for add1 info per NUREG-0737. Item II B 3. "Post-Accident Sampling Sys " Detailed reliability analysis not required to satisfy NRC concerns CRUTCHFIELD, D Departing Reactors Branch 5 82/10/08 DELOEDROF, L Commonwealth Edison Co 3pp 15720 004 24X Fiche 50-000. 82/10/08.8210180059
- 1210190565 Responds to SEP Topic III-4 B, "Turbine Missiles " Visual & fiber optic exams revealed water cutting in line w/keyways on hub wheels RAUSCH.T J Commonwealth Edison Co 82/10/08 O'CONNOR,P Operating Reactors Branch 5 2pp 15736 135 24X Fiche 50-237, 82/10/08,8210190565
- 210190480 Forwards safety evaluation of licensee 820414 & 0511 responses to NUREO-0737, Item II E 4 2. "Purge/Vent Valve Isolation Dependability " Responses acceptable Topic review completed CRUICHFIELD, D. Operating Reactors Branch 5 82/10/13 DELOEORGE, L. Commonwealth Edison Co. 5pp. 15738 192 24X Fiche 50-237, 82/10/13, 82/10/13, 82/10/13.
- 210190445 Forwards supplemental response to Generic Ltr B2-05 re implementation status of NURGO-0737. Items II B 3.II F 1 2. II F 1 5 & II F 1 6. In response to 821006 request SWARTZ.E D Commonwealth Edison Co 82/10/14 EISEMHUT.D 0 Division of Licensing 5pp (574) 202 24% Fiche 50-000.82/10/14, 8210190445
- 210220335 Forwards info re NUREO-0737. Item II D 1, "Parformance Testing of BWR Safety/Relief Valves," per 820727 request Info adequately demonstrates applicability of results of BWR owners group generic test rept NEDE-24988-P to facility SWARTZ.E D Commonwealth Edison Co 82/10/15 EISENHUT, D Q Division of Licensing 17pp (5776 011 24X Fiche 50-237.82/10/15, 8210220335

- B210250203 Forwards preliminary draft of integrated plant safety assessment rept.Chapter 4, "Integrated Assessment Summary "
 Encl draft includes commitments submitted in response to NRC 820715 Itr & assessment meetings CRUTCHFIELD.D Operating Reactors Branch 5 82/10/15 DECDEORGE.L Commonwealth Edison Co 60pp 15789 204 24X Fiche 50-237, 82/10/15, 8210250203
- 8210250155 Forwards corrections to proposed Tech Spec Pages 1 2/2 2-1: 3, 3/4 3-5, supporting review of future reloads & revised Figure 3 5 1. Sheet i. providing extended MAPLHOR vs. exposure curves for ben'ier lead test assembly fuel RAUSCH.T J. Commonwealth Edison Co. 82/10/18 DENTON.H R. Diffice of Nuclear Reactor Regulation. Director 2pp 15788 233 24X Fache 50-000, 82/10/18, 8210250155
- --8210250177 Errata & Addenda Sheet 8, replacing Page 4-10 to "LDCA Analysis Rept for Dreaden Units 2 & 3 & Guad Cities ! & 2 Nuclear Power Stations"

 * General Electric Co NEDD-24[46A ERR 08 82/09/30 3pp 15788 239 24X Fichs 50-000, 82/10/18,8210250155
- B210250069 Provides add1 info re reactor water cleanup room area temp monitors Temp elements cause no automatic plant response beyond control room alarms RAUSCH, T. J. Commonwealth Edison Co. 82/10/19 £15ENHUT, D. Q. Division of Licensing 2pp 15787 081 24X Fiche 50-000, 82/10/19, 8210250069
- 8210260485 Provides add1 info re actuation of relief valve PRV 2-1201-80 on reactor water cleanup sys Existing configuration adequate to handle transient w/o either reactor scram or reactor water cleanup overpræssurization RAUSCH,T J Commonwealth Edison Co 82/10/19 0'CONNOR,P Operating Reactors Branch 5 2pp | 15807 257 24X Fiche 50-237.82/10/19.8210260485
- 8210260296 Forwards safety evaluation of BWR owners group generic response to NUREO-0737. Item II K 3 25. "Effect of Loss of AC Power on Pump Stats " Na mods to seal cooling for recirculation pumps required Item resolved CRUTCHFIELD.D Operating Reactors Branch 5 82/10/21 DELGEORGE, L Commonwealth Edison Co 7pp 15803 018 24X Fiche 50-237. 82/10/21.8210260296
- O Inspection reports, IE Bullstins & correspondence
- 0210040329 Forwards IE Insp Repts 50-010/62-02.50-237/62-03 & 50-249/62-03 on 620119-0218 No noncompliance noted LITTLE.W 9 Division of Engineering & Yochnical Programs REED.C Commonwealth Edison Co 2pp 15415 331 24X Fishe 50-010, 82/09/22.8210040329
- --8210060335 IE Insp Repts 50-010/82-02.50-237/82-03 & 50-249/82-03 on 820117-0218 No noncompliance noted Major areas inspected open & unresolved idems & items of noncompliance reintegrated leak rate test
 REIMANN.F W Region 3, Office of Director JACKIW.I N Division of Engineering & Technical Programs 82/09/21 7pp 15615 333 24X Fichs 50-010.82/09/22.8210060329
- 8210150523 Forwards IE Insp Repts 50-010/82-13,50-237/82-17 50-249/82-18 on 820708-0809 & notice of violation STREETER, J.F. Division of Project & Resident Programs REED.C. Commonwealth Edison Co. 2pp 15713 099 PAY Fiche 50-010,62/09/28,8210150523
- --B21015053B IE Insp Repts 50-010/82-13,50-237/82-17 & B20708-0809 Noncompliance noted failure to issue & air pressure test procedure TONOUE, T H. JORDAN, M J. WALKER, R D. Division of Resident Programs 82/09/28 Bpp 15713 102 2/Fichs 50-010,82/09/28,8210150523
- 8210060359 Ack receipt of 820910 ltr informing NRC of a correct violations noted in IE Insp Repts 50-237/81-550-249/81-32, 50-254/81-23, 50-265/81-23, 50-275/81-31 & 50-304/81-29 SPESSARDR L Division of Project & Resident Program REED, C Commonwealth Edison Co ip 15618 354 24 Fiche. 50-000. 82/10/01, 8210060359.
- --8210060367 Responds to NRC 820712 itr re violations n Repts 50-237/81-39,50-249/81-32,50-254/81-23,50-265 50-295/81-31 & 50-304/81-29. Corrective actions trai mgt priorities re plant availability will be conduc REED.C Commonwealth Edison Co 82/09/10 KEPPLE 3, Office of Director 13pp, 15618,355 24% Fiche,50-000,82/10/01,8210060359.

- 8210080178 Forwards listing of piping sys which fail to meet FSAR requirements, per JRC 800818 confirmatory action ltr IE Bulletin 79-14 operability evaluation updates until not be provided for Dresden & Guad Cities Final update by Dec 1982 RAUSCH.T.J. Commonwealth Edison Co. 82/10/01 KEPPLER.J.G. Regio 3. Defice of Director App. 15640 L59 24X Fiche 50-000.82/10/01.
- 8210150539 Forwards IE Insp Repts 50-010/82-15.50-237/82-19 & 2003037 Forwards IE into Reperson Control 30 237/02-37 00 2009/02-20 on 820830-0903 No noncompliance noted PAPERIELLO, C J Division of Emergency Preparedness & Operational Support B2/10/01 REED, C Commonwealth Edison Co 2pp 15714 175 24X Fiche 50-010, B2/10/01, B210150539
- --B210150543 IE lnsp Repts 50-010/B2-15.50-237/B2-17 & 50-249/B2-20 on 820830-0903 & 09 No noncompliante noted Major areas inspected confirmatory measurements program. GC program for analytical measurements & environ monitoring program SCHUMACHER. M. C., NICHOLEGON, N. A., JANUSKA, A. Ø. Bivision of Emergency Preparedness & Operational Support 82/09/30 7pp 15714 177 24X Fiche 50-010.82/10/01.8210150539
- 8210060266 Confirms 821103 enforcement conference at Region 3 oft re 0A aspects associated w/procurement, installation & use of non-qualified valve guides in electramagnetic relief valves at facilities
 SPESSARD.R L Division of Project & Resident Programs 82/10/04 REED, C Commonwealth Edison Co ip 15640 181 Fishs 50-000, 82/10/04, 821 0080190
- 8210080190 Confirms 821103 enforcement conference at Region 3 ofc re QA aspects associated m/procurement, installation & use of non-qualified valve guides in electromagnetic relief valves at facilities
 SPESGARD.R L Division of Project & Resident Programs 82/10/04
 REEO.C Commonwealth Edison Co 1p 15640 HB1 24X
 Fiche 50-000. 82/10/04, 9210080190
- 8208190233 IE Info Notice 80-35. Suppl 1. "Leating & Disladged 1-125 Implant Seeds " Syc list and COBB.L I Division of Fuel Facilities, Materials & Safeguard 82/10/06 Consolidated Edison Co of New York 66pp 1576 24X Fiche 50-000.62/10/06.8208190233 15761 250
- 8208190238 IE Bulletin 82-03, "Stress Corresion Cracking in Thick-ROBIFULUE IE BUILETIN BEPOS, "Extess Corrosion Cracking in Thick Walls Large-Diameter, Stainless Steel, Recirculation Sys Piping at BWR Plants " Syc list enci DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/10/14 Consolidated Edison Co of New York 115pp 15810 125 24x Fichs 50-000.62/10/14.8208190238
- R Periodic operating reports & related correspondence
- 8210180097 Forwards monthly operating repts for Sept 1982 SCOTT.D J. Commonwealth Edison Co. 82/10/01 Director's Office of Inspection and Enforcement ip 15718 OO: 24X Fiche 50-010.82/10/01.8210180097 Director's Office,
- --8210180100 Monthly operating repts for Sept 1982 SCHROEDER, B. A. Commonwealth Edison Co. 82/10/01 15718 002 24X Fiche 50-010,82/10/01,8210180097 2200
- S Reportable occurrences. LERs & related correspondence
- 8210150044 Forwards LER 81-059/03L-0 SCOTT. D J Commonwealth Edison Co 81/10/08 KEPPLER, J Q Reg 3, Chicago, Office of the Director (81/03/01) 1p 15701 126 Fiche. 50-237, 81/10/08, 8210150044 Region 26 24X
- --B210150049 LER 81-059/03L-0 on 8109(0, while conducting insp on pump 2A.CCSW outboard bearing found burned out Caused by lack of lubrication in sealed bearing learning replaced 21RMAS.K R Commonwealth Edison Co 81/10/08 Region 3. Chicago, Office of the Director (81/03/01) 2pp 15701 127 24X Fiche 50-237.81/10/08.8210150044.
- 82(0080915 Addl response to FOIA request for 19 categories of info re nuclear reactor events & safety problems Forwards documents listed in App A Documents (n App B completely withheld (ref FOLA Exemption 5]
 FELTON. J. M. Division of Rules and Records. 82/07/12 UDELL.R A
 Critical Mass Energy Project 9pp 15865 027 24X
 Ficha 50-000.82/07/12.8210080015
- --8210080197 NRC operations ctr usage chart re events at facilities * NRC No Datalled Affiliation Given 82/07/12, 1p 15668:221 24X Fiche 50-000.82/07/12.8210080015

- 8210040188 Forwards LER 92-040/03L-0 SCOTT, D J Commonwealth Edison Co 82/09/15 KEPPLER, J O Region 3. Office of Director Lp 15583 i64 24% Fiche 50-237,82/09/15, 82100401BB
- --8210040189 LER 82-040/03L-O on 820830. valve Z-1601-33A exhibited binding during movement while performing torus-drywell yacuum breaker operability test (DDS 1600-9) Cause not WEE, D T Commonwealth Edison Co 82/09/15 Region 7, Office e)
 Director 2pp 15583 165 24X Fiche 50-237,82/09/15,82/0940188
- 8210050227 Forwards LER 82-038/03L-0 SCOTTED J Commonwealth Edison Co 82/09/22 KEPPLER, J Q Region 3. Office of Director Lp 15611 026 24% Fiche 50-237,82/09/22.
- --8210050233 LER 82-038/03L-0 on 820829, during MSIV timing surveillants valves 2-203-60 & 2-203-10 had closed times of 2 25-5 & 2 67-s, respectively Caused by timing mechanism drift Valves
 - adjusted RMEE.S Commonwealth Edison Co 82/09/22 Region 3. Office o Director 2pp 15611 027 24% Fiche 50-237.82/09/22,8210050227 Region 3. Office of
- 8210040198 PNO-III-82-101 on 820824, plant tripped due to broken cooling water line to generator hydrogen cooling sys spraying water onto current transformer Line repaired & transformer
- 8210250268 Forwards LER 82-042/03L-0
- 82/10/12 KEPPLER, J G SCOTT.D J Commonwealth Edison Co 82/10/12 KEPPLER.J C Region 3, Office of Director 1p 15791 (45 24X Fiche 50-237,82/10/12, Region 8210250268
- --8210250278 LER 82-042/03L-O on 820930, control rod drive N-10 evertual 21022027B LEN 82-092/03.—O on 82073D, control rod drive N-10 overty.

 **alarm annunciated & rod position indication lost Caused by
 uncoupled inner filter Drive recoupled at greater than 207
 power Drive will be overhauled during next refueling outage
 **HOLLAND, P Commonwealth Edison Co 82/10/12 Region 3. Office
 of Director 2pp 15791 146 24% Fiche 50-237, 82/10/12. 8210250268
- 8210250283 Forwards LER 82-042/017-0 SCOTT.D J Commonwealth Edison Co 82/10/14 KEPPLER, J Q Hegac 3. Office of Director 1p 15791 102 24X Fiche 50-237,82/10/14. 8210250283
- --8210250296 LER 82-042/01T-0 on 821002, sightglass isolation & vent valves reported open w/no indication of excess makeup Calculations indicate leakage was in excess of Tech Spec Caused by operator error Valves closed HOLLAND.P Commonwealth Edison Co 82/10/14 Region 3 of Birector 3pp (579) 103 24X Fiche 50-237,82/10/14,8210250283 Region 3. Office
- DOCKET 50-244 ROBERT EMMET GINNA NUCLEAR PLANT, UNIT 1 F Security, medical, emergency & fire protection plans
- 82:0150621 Releases public version of revision to emergency plan implementing procedures FELYON, J H Division of Rules and Records 82/09/30 Docum Nanagement Branch ip 15717 064 24X Fiche 50-244,82/09/3G, 82:0150621
- --8210150643 Forwards public version of revision to emergency plan implementing procedures, including Procedure 8C-411 re NY Emplementing procedures including Procedure 8C-411 re NY
 State warning point test & Procedure SC-410 re insp of
 emergency equipment
 MAIER.J E Rochester Cas & Electric Corp 82/09/23
 CRUTCHFIELD.D Operating Reactors Branch 5 ip 15717 045 24
 Fiche 50-244,82/09/30.8210150621
- --8210150648 Public version of revision to emergency plan implementally procedures, including Procedure 80-411 re NY State warning point phone test & Procedure 80-410 re insp of emergency soulament
- 8210190580 Ack receipt of 820224 itr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-244/81-22 ALLANJ H Region i. Office of Director 82/10/07 MAIERJ E Rochester Gas & Electric Corp ip 15739 307 24% Fiche 50-244, 82/10/07, 8210190580

- --8210190591 Responds to NRC 811215 ltr re violations noted in IE Insp Rept 50-244/81-22 Corrective actions emergency plan training program will be realigned by 820115 to be consistent w/ functional area requirements HAIER.J E Rochester Gas & Electric Corp 82/02/24 HAYNES.R C Region 1. Office of Director 4pp 15739 308 24X Fiche 50-244,82/10/07.8210190580
- --8210190618 Responds to NRC 811215 Itr reviolations noted in IE Insp Rept 50-244/81-22 Corrective actions clarified required action, eliminated existing ambiguities, inconsistencies & errors for emergency functions MAIFR. J E Rochester Gas & Electric Corp 82/04/19 HAYNES. R C Region I, Office of Director 2pp 15739 312 24X Fiche 50-244,82/10/07.8210190580
- --821019043/ Responds to NRC 820520 ltr re violations noted in IE Insp Rept 50-244/81-22 Corrective actions committee established to evaluate & inventory supplies Rept will be submitted by 821231 MAIER, J E Rochester Cas & Electric Corp 82/06/30 SMITH, G H Division of Emergency Preparedness & Operational Support 22pp 15739 314 244 Fiche 50-244, 82/10/07, 8210170580
- --8210190647 Responds to NRC 811215 ltr re violations noted in IE Insp Rept 50-244/81-22 Corrective actions revision of Emergency Plan 8C-1 completed prior to startup after 1982 refueling shutdown MAIER, J E Rochester Gas & Electric Corp 82/10/07 HAYNES, R C, Region 1, Office of Director 1p 15739 336 24X Fiche 50-244,82/10/07,8210190580
- 6210290212 Ack receipt of 821015 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-244/82-15
 STARGSTECKLIR Division of Project & Resident Programs 62/10/25
 MAIER. J E Rochester Gas & Electric Corp 10 15853 279 24X
 Fiche 50-244.82/10/25.8210290212
- --8210290217 Responds to NRC 820914 ltr re violations noted in IE Insp Rept 50-244/82-15 Corrective actions situation reviewed & determined to be (solated case Further action unnecessary MAIER. J C Rochester Gas & Electric Corp 82/10/15 IRUNNER. E J Region I. Office of Director 2pp 15853 280 24X Fiche 50-244,82/10/25,8210290212

Adjudicatory correspondence

- 8210280060 Updates 820730 status rept on NRC issuances Final integrated plant safety assessment rept to be issued on 821029 Conversion safety evaluation rept & update to FEB to be issued in Nov YOUNG: M A Hearing Branch 4 82/10/26 OROSSMAN, H, LUEBKE, E A, COLE, R F Atomic Safety and Licensing Board Panel ip 15837 262 24X Fiche 50-244,82/10/26,8210280060
- O Advisory Committee on Reactor Safeguards reports & correspondence
- 8208290018 Summarizes 268th ACRS meeting on 820812-14 in Washington.DC re full power OLs for Grand Oulf I & Watts Bar I & II, systematic evaluation & integrated reliability assessment or Ginna & control room habitability SHEMYON.P ACRS Advisory Committee on Reactor Safeguards 82/08/04 PALLADING.N J Commissioners 3pp 15647 233 24X Ficho 50-000:82/08/26.8208290018
- B210180074 Forwards B20917 response to ACRS comments & recommendations per facility SEP review CRUTCHFIELD, D Operating Reactors Branch 5 82/10/07 MAIER, J E Rochester Gas & Electric Corp 2pp 15719 347 24X Fiche 50-244, 82/10/07. B210180074
- --8210180083 Responds to ACRS 62081B comments & recommendations re facility SEP review Draft NUREQ-0821 will be revised to reflect agreements DENTON, HR Office of Nuclear Reactor Regulation, Director 82/09/17 SHEWMON, PS ACRS - Advisory Committee on Reactor Safeguards 2pp 15719 349 24X Fiche 50-244,82/10/07, 6210180074
- P Operating license stage documents & correspondence
- B210010008 Responds to FDIA request for 19 categories of documents re nuclear reactor events & safety problems Forwards documents listed in App A FELTON, J H Division of Rules and Records B2/04/28 UDELL, R A Critical Mass Energy Project 15pp 15727 005 24X Fishe 50-000, B2704/28. B210010008

- --8003310179 Forwards NRC evaluation of use of four mixed oxide fuel assemblies for Cycle 10 Use of assemblies is acceptable w/no changes For future cycles NRC will require increase in nuclear uncertainty re total peaking factor CMECK, P S Reactor Safety Branch 80/03/11 ZIEMANN. D L Operating Reactors Barety Branch 2 (Pre 800428) 8pp 15727 036 24X Fichs 50-000,82/06/28,8210010008
- 8210120103 Add1 response to FOIA request for nine categories of recordugenerated by present NRC Commissioners, primarily Chairman Palladino & Commissioner Roberts & White House Forwards App B documents
 FELTON, J M Division of Rules and Records 82/07/12 UDELL, R A Critical Mass Energy Project 3pp 18670 117 24X
 Fiche 50-000, 82/07/12, 8210120103
- --B210120131 Agrees w/point raised in 820201 memo re NRC incident response program Points raised by staff will be addressed in rept on lessons learned at incident response ctr from facility event
 PALLADINO, N J Commissioners B2/02/16 RDBERTS, T M Commissioners ip 15690 13B 24X Fiche 50-000, B2/07/12, B210120103
- 8210070007 Responds to FOIA request for eight categories of records rp steam generators & steam turbines App A documents provided in R Udell FOIA Request 81-313 Forwards documents listed in App B FELTON, J M Division of Rules and Records 82/08/10 LONG, D J Winthrop, Stimson, Putnam & Roberts 9pp 15645 063 24X Fiche 50-000, 82/08/10, 8210070007
- ---8302170310 Forwards background summary of operating experience w/
 steam generators prior to 820125 tube rupture
 JOHNSTON. W V Assistant Director for Materials & Qualifications
 Engineering 82/01/28 LAINAS. © C Assistant Director for Bafety
 Assessment 5pp 15645 104 24X Fiche, 50-000, 82/08/10.
 8210070007
- --8203020267 Submits daily highlights for 820210 mapting w/util re requirements for restart Prior to restart.util should finish fiber aptic insp of secondary side of 8 steam generator & obtain designer opinion on effects of plugging LYDNS, J E Operating Reactors Branch 5 82/02/11 DENTON, H R . CARTER, J . EIBENHUT, D . NRC No Detailed Affiliation Given ip 15645 072 24X Fiche. 50-000.82/08/10.8210070007
- ---B203040502 Submits daily highlight re television insp of B steam generator revealing missing, partially missing & damaged tubes & presence of foreign objects Meeting WARC planned LYONS, J E. Operating Reactors Branch 5 B2/02/19 DENTON, H, CARTER, J, EIBENHUT, D NRC No Detailed Affiliation Given. 1, 15645-096 24X Fichs 50-000,82/08/10,8210070007
- --B203100573 Submits daily highlights he insplot ruptured tube using fiber optics Five-inch kite shaped rupture caused by stress corrosion linked to differential expansion between tube k tube wrapper wedge Tube being plugged LYONS, J.E. Operating Reactors Branch 5 82/02/08 DENTON, H. GARTER, J. FISENHUT. D. NRC No Detailed Affiliation Given ip 15645 091 24X Fiche 50-000,82/08/10,8210070007
- --B203110304 Submits highlights re fiber optic investigation of secondary side of B steam generator revealing damage to previously plugged tubes Preliminary indications show one tube severed investigation of peripheral area continuing.

 LYONS, J E Operating Reactors Branch 5 B2/02/12 DENTON.H CARTER, J : EISENRUT, D NRC No Detailed Affiliation Given Ip. 19545-094 24% Fiche 50-000, B2/08/10,8210070007
- --8203110339 Submits daily highlights re insp of periphery of B steam generator hot leg Insp results indicate approx 7-10 previously plugged tubes in peripheral area severly damaged TV insp planned for A & B generators.

 LYDNS, J E Operating Reactors Branch 5, 82/02/16 DENTON, H, CARTER, J, EIBENHUT, D NRC No Detailed Affiliation Given 2pp 13645 095 24X Fiche 50-000, 82/08/10,8210070007
- --8203110403 Forwards response to JD Dumele, chairman of Pollution Control Board, State of IL, questions in 820127 ltr
 JONNSTON.W. V. Assistant Director for Materials & Qualifications Engineering 82/02/22. LAINAS.Q. Assistant Director for Safety Assessment. 2pp. 15645 126 24X Fiche. 50-000, 82/08/10. 8210070007.

- --8206070250 Forwards Operating Reactors Assessment Branch input for finna restart safety evaluation rept. Section 5.re steam generator (nsp. program. failure analysis & repairs IPPOLITO. T. A. Operating Reactors Assessment Branch 82/05/18 CRUTCHFIELD. D. Operating Reactors Branch 5 45pp (5645-138-24X Fiche 50-000, 82/08/10, 8210070007
- ---8206290655 Forwards Hechanical Engineering Branch input to restart SER Sections 4 5 through 4 8.5 1.5 2.5 4.6 1 % 6 2, per 820423 request KNIGHT.J P Assistant Director for Components & Structures Engineering 82/06/15 LAINAS.O C Assistant Director for Safety Assessment 13pp 15645 183 24X Fiche 50-000.82/08/10.82/0074007
- --8210070030 Util handout from 820210 meeting w/NRC re 820125 steam generator tube rupture at facility * Rochester Gas & Electric Corp 82/02/10 17pp 15645 072 24X Fiche 50-000,82/08/10.8210070007
- --8210070068 Submits daily highlightine 820210 meeting w/util concerning requirements to be met prior to restart of facility No sufficient basis presented at this time to permit plant to return to operation
 LYONS.JE Operating Reactors Branch 5 82/02/11 DENTON.H.
 CARTER.J. EISENNUT.D NRC No Detailed Affiliation Given 1p
 15445 093 24X Fiche 50-000.82/08/10.8210070007
- --8210070073 Submits daily highlight re util 820219 press conference presenting update on recovery activities at facility Masting W/NRC scheduled for 820302 LYONS.JE Operating Reactors Branch 5 82/02/22 DENTON.H , CARTER.J . EISENHUT.D NRC No Detailed Affiliation Given Ip 15445 097 24X Fiche 50-000.82/08/10.8210070007
- ---B210070076 Submits daily highlight re B20301 meeting w/util & B20302 meeting w/Westinghouse in Bethesda MD to discuss recovery activities at facility & generic steam generator tube degradation respectively tyONB-JE Operating Reactors Branch 5 82/02/26 DENTON.H, CARTER-J, EISCHNUT.D NRC NO Detailed Affiliation Given ip 15645 098 24X Fiche 50-000, 82/08/10.8210070007
- --8210070080 Submits daily highlight re 820301 meeting w/util re proposed recovery program for facility NRC concurred w/proposal to remove small number of steam generator tube sections for metallurgical exam
 LYONSIJE Operating Reactors Branch 5 82/03/04 DENTON.H,
 CARTER.J, EISENHUT.D NRC NO Detailed Affiliation Given ip
 15645 099 24X Fiche 50-000,82/08/10.8210070007
- --B210070083 Submits daily highlight re util completion of cutting 3-inch hole in steam generator B on 82030B Burst tube & tubes R44054.R43054 to R43056 removed for metallurgical eram Heeting tentatively scheduled for 820322 LYONS-J.E Operating Reactors Branch 5 82/03/10 DENION.H. CARTER.J. FISENNUT.D NRC MO Detailed Affiliation Given ip 15645 100 24X Fiche 50-000.82/08/10.8210070007
- --8210070087 Bubmits daily highlight re 820323 meeting w/util & Westinghouse concerning status of proposed repair activities Twenty-four tubes removed from steam generator B Foreign object found in Hedge Area 4
 LYONS.J E Operating Reactors Branch 5 82/04/05 DENTON.H.
 CARTER.J. EISENHUT,D NRC No Detailed Affiliation Given 2pp 13645 101 24% Fiche 30-000, 82/08/10.8210070007
- --B210070090 Submits daily highlight re restart of facility Plant expected to be ready for operations above 5% power upon completion of startup physics testing on 820325 LYONS.JE Operating Reactors Branch 5 82/05/25 DENYON,H, CARTER.J, EISCHUTT.O NRC No Detailed Affiliation Given ip 15645 103 24X Fiche 50-000,82/08/10.8210070007
- --8210070121 Forwards preliminary estimate of leak rate vs time during Ginna 820125 steam generator tube rupture event & plot showing important parameters & status of sys IPPOLITIO.T A Operating Reactors Assessment Branch 82/02/05 RDE.J. NRC No Detailed Affiliation Given 3pp 15645 121 24X Fiche 50-000,82/08/10.8210070007
- --B2i0070135 Bevil rept input re Ginna 820125 steam generator tube rupture event NRC 16th monthly status rept to Congress ra THI-1 restart encl # NRC No Detailed Affiliation Given 82/03/11 3pp 15645 12B. 24X Fiche 50-000,82/08/10.8210070007
- --8210070165 Bevil rept input re removal of selected tube samples through two access ports drilled in side of steam generator to obtain metallurgical data for evaluation of steam generator B tube failure mechanism

 # NRC No Detailed Affiliation Given 82/04/08 2pp 15645 136 24X Fiche 50-000, 82/08/10,8210070007

- B210010444 Responds to NRC 820702 request for review of NURCO-0737, Item II B 3, "Post-Accident Sampling " Criterion will be adequately addressed by 830213 MAIER. J E Rochester Das & Electric Corp 82/07/23 CRUTCHFIELD, D Operating Reactors Branch 5 1p 15570 174 24X Fiche 50-244,82/07/23.8210010444
- 8210010357 Forwards application to amend App A of License DPR-18 & proposed Tech Specs to permit reorganization of plant staff HAIER.JE Rochester Gas & Electric Corp. 82/09/28 DENTON.H R Office of Nuclear Reactor Regulation. Director 1p. 15574-144 24x Fiche 50-244.82/09/28.8210010357
- --8210010365 Application to amend App A of License DPR-18.changing lech Specs to germit reorganisation of plant staff MAIER. J E Rochester Gas & Electric Corp 82/09/28 2pp 13574 145 24X Fiche 50-244.82/09/28.8210010357
- --8210010369 Proposed Tech Spec changes to permit reorganization of plant staff

 * Rochester Gas & Electric Corp 82/09/28 11pp 19574 147 24% Fiche 50-244,82/09/28,8210010357
- 82:0040281 Forwards application to amend License DPR-18, revising containment isolation boundary requirements
 MAIER.J E Rochester Gas & Electric Corp 82/09/28 DENTON, H H
 Office of Nuclear Reactor Regulation. Director 1p 15587 169 24K
 Fiche 50-244, 82/09/28, 8210040281
- --8210040284 Application to amend License DPR-18, revising containment isolation boundary table MATER.JE Rochester Gas & Electric Corp 82/09/28 4pp 15587 170 24X Fiche 50-244,82/09/28,821004028)
- --8210040288 Proposed change to Tech Spec Page 3 4-6 re containment isolation boundary table Safety evaluation encl * Rochester Gas & Electric Corp 82/09/28 3pp 15587 [74 24x Fiche 50-244, 82/09/28 821004028]
- B210050214 Notifies that except for occasional transient species, no federally listed or proposed threatened or endangered species exist in project inpact area, in response to 820902 request Federal list of endangered species enci HAMILTON, P.P. Interior. Dept of, Fish & Wildlife Service 82/07/20 CRUTCHFIELD, D. Operating Reactors Branch 5. 3pp. 15611 297 24X Fiche 50-244.82/09/28.8210050214
- 8210050059 Approves 800220 request for withholding info re use of mixed oride fuel assemblies for Cycle 10 from public disclosure (ref 10CFR2 790)
 CRUTCHFIELD,D Operating Reactors Branch 5 82/09/29
 WIESEMANN,R A Westinghouse Electric Corp 3pp 15609 171 24x
 Fiche 50-244,82/09/29,8210050059
- 8210130326 Comments on proposed scope of Phase III of SEP as reflected in individual topic definitions appended to 820709 ltr Staff encouraged to develop & implement means to incorporate positive attributes of Phase III in licensee/NRC interface MACIGH.R H SEP Duners Group 82/10/07 EISENHUT.D 0 Division of Licensing 7pp 15682 179 24X Fiche 50-000.82/10/07.8210130326
- B210180074 Forwards 820717 response to ACRS comments & recommendations per facility SEP review CRUTCHFIELD,D Operating Reactors Branch 5 82/10/07 MAIER. J E Rochester Oas & Electric Corp 2pp 15719 347 24X Fiche 50-244,82/10/07,8210180074
- --8210180083 Responds to ACRS 820818 comments & recommendations refact11ty SEP review Draft NUREO-0821 will be revised to reflect agreements

 DENTON, H R Defice of Nuclear Reactor Regulation, Director 82/09/17 GHEWMON, PS ACRS Advisory Committee on Reactor Safeguards 2pp 15719 349 24X Fiche 50-244,82/10/07,8210180074
- 8210180082 Forwards Amend 54 to License DPR-18, safety evaluation & notice of issuance & availability Amend approves provisions updating containment isolation valve in Table 3 4-1, to reflect plant says mod CRUTCHFIELD.D Operating Reactors Branch 5 82/10/07 MAIER, J E Rochester Oas & Electric Corp 2pp 15719 274 24X Fiche 50-244, 82/10/07, 8210180082
- --8210180087 Amend 54 to License DPR-18.approving provisions updating containment isolation valve in Table 3 6-1, to reflect plant sys mod CRUTCHFIELD.D Derating Reactors Branch 5 62/10/07 1p 15717 296 24X Fiche.50-244,82/10/07,8210180082
- --8210180090 Safety evaluation supporting Amend 54 to License BPR-1B + Office of Nuclear Reactor Regulation, Director 82/10/07 Dep 15719-300 24X Fiche 50-244,82/10/07,8210180082

- --8210180094 Notice of issuance & availability of Amend 54 to License PPR-18 CRUTCHF[ELD, D. Operating Reactors Branch 5 82/10/07 2pp 15717 303 24X Fiche 50-244,82/10/07.8210180082
- 8210180112 Forwards 821004 FR notice announcing ACRS Subcummittee on Extreme External Phenomena 821021 & 22 meetings in Santa Monica.CA to discuss flooding & seismic hazards CRUTCHFIELD, D. Operating Reactors Branch 5 82/10/07 MAIER, J C Rothester Oas & Electric Corp. 3pp. 15719 322 24X Fiche 50-244.82/10/07.8210180112
- 8210180149 Forwards Amend 55 to License DPR-18.safety evaluation & notice of issuance & availability Amend incorporates new License Condition 2 C(10) to confirm that next steam generator insp will be performed during refueling outage CRUTCHFIELD.D Operating Reactors Branch 5 82/10/08 MAIER.JE Rochester Cas & Electric Corp 2pp 15719 105 24X Fiche 50-244.82/10/08.8210180149
- --9210180153 Amend 55 to License DPR-18, incorporating new License Condition 2 C(10) to confirm that next steam generator inspinyodying eddy current & visual insps & water lancing will be performed during refueling outage CRUTCHFIELD, D Operating Reactors Branch 5 82/10/08 2pp 15719 107 24% Fiche 50-244, 82/10/08.8210180149
- --82i0180158 Safety evaluation supporting Amend 55 to License DPR-18
 4 Office of Nuclear Reactor Regulation, Director 82/10/08 3p
 15719 109 24X Fiche 50-244,82/10/08.8210180149
- --9210180161 Notice of issuance & availability of Amend 55 to License PRR-18 GRUTCHFIELD,D Operating Reactors Branch 5 82/10/08 2pp 15719 112 24X Fiche 50-244,82/10/08,8210180149
- 8210180181 Clarifies 820902 request for add1 info re NUREO-0737, Item II B 3, "Post-Accident Sampling Sys" Clarification section of 820902 ltr provides staff guidelines, not requirements on meeting NUREO-0737 criteria CRUTCHFIELD.D Deprating Reactors Branch 5 82/10/08 MAIER, J E Rochester Oas & Electric Corp 3pp 19719 145 24X Fiche 50-244, 82/10/08. 8210180181
- B210220105 Advises that review of util 810904 response to NUREG-0737, Item III D 3 4. "Control Room Habitability," completed Issue satisfactorily resolved except for single failure criterion of intake & exhaust ductwork CRUTCHFIELD D Operating Reactors Branch 5 82/10/18 MAIER, J E Rochester Oas & Electric Corp. 2pp. 15775 100 24X Fiche 50-244, 82/10/18, 8210220105
- --8209140027 Informs that info submitted by licensee in response to NUREO-0737. Item III D 3 4. "Control Room Habitability" acceptable HURPHY. D W Battolle Hemorial Institute, Pacific Northwest Laboratory FIN 8-2323 82/03/23 HULMAN. L Q Accident Evaluation Branch 2pp 15775 102 24X Fiche 50-244,82/10/18,8210220105
- D210250275 Forwards status rept re unresolved safety issues, per NRC 920617 request Info includes description of problem based on NRC documentation MAIER, J E Rochester Gas & Electric Corp 92/10/19 CRUTCHFIELD, D Operating Reactors Branch 5 47pp 15791 049 24x Fiche 50-244, B2/10/19, B210250275
- Q Inspection reports, IE Bulletins & correspondence
- 8210070007 Responds to FOIA request for eight categories of records re steam generators & steam turbines App A documents provided in R Udell FOIA Request 81-313 Forwards documents listed in App 8 FELTON.J M Division of Rules and Records 82/08/10 LONG.D J Winthrop, Stinson, Putnam & Roberts 9pp 15445 063 24X Fiche 50-000, 82/08/10,8210070007
- ---8210070038 Submits daily highlight re May 1981 insp of ruptured tube in Ginna steam generator Failed tube located in wedge area of steam generator LYDNS,J E. Operating Reactors Branch 5 82/02/04 DENTON,H, CARTER,J., EIBENHUT,D. NRC -- No Detailed Affiliation Given 1p 15445 090 24X Fiche 50-000,B2/08/10,8210070007
- --B210070139 Forwards tabulated data on steam generator insp & maint at facilities Data should be provided to licensees IPPOLITO.** Operating Reactors Assessment Branch 82/04/01 VARQA.B Operating Reactors Branch 5pp 15645

- --8210070172 Forwards info re steam generator integrity & insps at all operating PURs.per 750320 & 21 requests Details of insps. including defect indications tube plugging criteria & tubes plugged will not be provided except for Point Beach 1 GOLLER.K R Division of Reactor Licensing (RMR-1975 only) 75/03/24 HACCARY.R R Division of Perthical Review (NRR-1975 only) 5pp 15645 196 24X Fishe 50-000.62/08/10.6210070007
- 8208190233 IE Info Notice 80-35. Suppl 1. 'Leaking & Dislodged I-125 Implant Seeds '' Svc list oncl COBB.L I Division of Fuel Farilities. Materials & Safeguards 82/10/06 Consolidated Edison Co of New York 66pp 15/6/1250 24X Fichs 50-000.82/10/06 (2008)70233
- G210130439 Discusses results of eddy current fibe optics, video & visual insps Burst in inactive tube in B-steam generator inlet probably caused by reduction in wall due to wear & pressurization from primary side through leaking plug MAIER. J E Rochester Gas & Electric Corp 92/10/06 CRUTCHFIFLD. D Operating Reactors Branch 5 3pp 15692 010 24X Fiche 50-244, 82/10/06, 8210130439
- 8210210201 Forwards IE Insp Rept 50-244/82-16 on 820830 0903 No noncompliance noted MARTIN.T T Division of Engineering & Technical Programs 82/10/06 MARTIN.T T Division of Engineering & Technical Programs 82/10/06 MARTIN.T T Division of Engineering & Technical Programs 82/10/06 Fiche 50-244, 82/10/06.8210210201
- --8210210213 IE Insp Rept 50-244/82-16 on 820830 0703 No noncompliance noted Major areas inspected followup on previously identified insp findings, administrative centrals for design changes & mods & mod & design program BLUMBERG.N. BISSETT.P. CAPHTON.B I Division of Project & Resident Programs 82/10/05 7pp 15766 147 24X Fiche 50-244,82/10/06/8210210201
- 8210190580 Ack receipt of 820224 ltr informing NRL of steps taken to correct violations noted in IC Insp Rept 50-244/81-22 ALLANJ M Region 1. Office of Director 82/10/07 MA[FR.J C Rochester Oas & Electric Coip ip 15739 307 24x Fiche 50-244.82/10/07.8210190580
- --8210190591 Responds to NRC 811215 ltr re violations noted in Il Insp Rept 50-244/81-22 Corrective actions emergency plan training program will be realigned by 820115 to be consistent w/ functional area requirements MATER. J E Rochester Oas & Electric Corp 82/02/24 MAYNE's, R (Region 1. Office of Director 4pp 15739 308 24y Fiche 50-244.82/10/07.8210190580
- --8210190618 Responds to NRC 811215 ltr re violations noted in JL Insp Rept 50-244/81-22 Corrective actions clarified required action, eliminated existing ambiguities, inconsistencies & errors for emergency functions MAIER. J E Rochesfer Gas & Electric Corp 82/04/19 HAYNES, R (Region 1, Office of Director 2pp 157.39 312 24X Fiche 50-244,82/10/07,8210170580
- --8210190637 Responds to NRC 820520 itr re violations noted in II Insp Rept 50-244/81-22 Corrective actions committee established to evaluate & inventory supplies Rept will be submitted by 821231 MAIER, J.E. Rochester Gas & Electric Corp. 82/06/30 SMITH, 0 H Division of Emergency Preparedness & Operational Support. 22pp 15739-314 24X Fiche 50-244.82/10/0/.8210190580
- --8210190647 Responds to NRC 811215 itr reviolations noted in IE Insp Rept 50-244/81-22 Corrective actions revision of Emergency Plan 8C-1 completed prior to startup after 1982 refueling shutdown MAIER, J E Rochester Oas & Electric Corp 82/10/07 HAYNES, R C Region 1, Office of Director 1p 15739 336 24X Fiche 50-244,82/10/07.8210190580
- 8210180149 Forwards Amend 55 to License DPR-18 safety evaluation & notice of issuance & availability Amend incorporates new License Condition 2 C(10) to confirm that next steam generator insp will be performed during refueling outage CRUTCHFIELD D Operating Reactors Branch 5 82/10/08 MAIER, J E Rochester Gas & Electric Corp. 2pp 15719 105 24X Fichs 50-244, 82/10/08, 8210180149
- --821018D153 Amend 55 to License DPR-18, incorporating new License Condition 2 C(10) to confirm that next steam generator insprinvolving eddy current & visual insps & water lancing will be performed during refueling outage CRUTCHFIELD, D Derating Reactors Branch 5 82/10/08 2pp 13719 107 24X Fiche 50-244, 82/10/08, 8210180149

- -8210189161 Notice of issuance & availability of Amend 55 to License DPR-18
 CRUICHFIELD.D Operating Reactors Branch 5 82/10/08 2pp 15719 182 24X Fiche 50-244,82/10/08,8210180149
- 8210220344 Ack receipt of 820915 & 1005 ltrs informing NRC of steps taken to correct violations noted in IE Insp Rept 50-244/82-14
 STARDSTECKI.R Division of Project & Resident Programs 82/10/13
 MAIER.J E Rochester Cas & Electric Corp Ip 15777 355 24X
 Fiche 50-244,82101/13,8210220344
- --8210220352 Responds to NRC 620816 ltr reviolations noted in IE Insp. Rept 50-244/82-14 Corrective actions all four 480-volt safeguard buses tested & draft test procedure issued to offsite engineering dept for review MAIER. J E. Rochester Gas t. Electric Corp. 82/09/15 BRUNNER. E. J. Region 1. Office of Director 2pp. 15777 356 24X Fiche 50-244, 82/10/13, 8210220344
- --8210220360 Responds to NRC 820816 ltr re violations noted in IE Insp Rept 50-244/82-14 Corrective actions all four 480-volt safeguards buses tested to draft test procedure issued to off-site angineering dept for review MATER. J E Rochester Gas & Electric Corp 82/10/05 BRUNNER, E J Region I. Off-sice of Director 2pp 13777 358 24X Fiche 50-244,82/10/13.8210220344
- 8208190238 IE Bulletin 82-03, "Stress Corrosion Cracking in Thick-Wall, Large-Diameter, Stainless Steel, Recirculation Sys Piping at BWR Plants" Svc list encl
 DEYBUNG, R C Director's Office, Office of Inspection and Enforcement 82/10/14 Consolidated Edison Co of New York 115pp 15810 125 24% Fiche 50-000, 82/10/14, 8208190238
- 0210290171 Forwards IE Insp Rept 50-244/82-18 on 820901-0930 No noncompliance noted STAROSTECKI.R Division of Project & Resident Programs 82/10/14 MAIER.J E Rochester Ges & Electric Corp 2pp 15853 276 24X Fiche 50-244.82/10/14,8210290171
- --8210290173 IE Insp Rept 50-244/82-18 on 820901-0930 No noncompliance noted Hajor areas inspected plant operations, surveillance testing. LERs, licensed / nonlicensed employee training programs & followup or THE lessons learned implementation ZIMMERMAN, R.P. BAUNACK, W.H. KISTER, H.B. Division of Project & Resident Programs 82/10/13 11pp 15853 298 24X Fiche 50-244, 82/10/14, 8210290176
- 8210270212 Act receipt of 821015 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-244/82-15 STAROSTECKI.R Division of Project t Resident Programs 82/10/25 MAIER, J E Rochester Oas & Electric Corp 1p 15853 279 24X Fiche 50-244, 82/10/25,8210290212
- --8210290217 Responds to NRC 820914 | tr re violations noted in IE Insp Rept 50-244/82-15 Corrective actions situation reviewed 5 determined to be isolated case Forther action unnecessary HAIER. J E Rochester Cas & Electric Corp 82/10/15 BRUNNER.E J Region 1. Office of Director 2pp 15853 280 24X Fische 50-244/82/10/25/8210290212

- 8210190703 LER 82-022/017 on 821001.one tube of A steam generator inlet found w/crevice intergranular attack indication above plugging limit B steam generator inlet had 28 tubes above plugging limit b 2 w/stress corrosion Rept follows SKOW. B A Rochester Cas & Electric Corp 82/10/04 HAYNES, R C Region 1, Office of Director 1p 15736 154 24X Fiche 50-244, 82/10/04.8210190703
- 8210250334 Forwards LER 82-022/01T-0

 MAIER.J E Rochester Cas & Electric Corp 82/10/15 HAYNES,R C
 Region 1. Office of Director 1p 15790 001 24X
 Fiche 50-244, 82/10/15, 8210250334
- --8210250343 LER 82-022/01T-0 on 821001, eddy current exam of steam generator A inlet indicated one tube w/crevice intergranular attack indication above plugging criteria & 32 tubes on steam generator 8 w/indications All 33 tubes plugged BDDINE, J C Rochester Gas & Electric Corp 82/10/15 Region 1 Office of Director 2pp 15790 002 24X Fiche 50-244, 82/10/15.8210250334
- DOCKET 50-245 MILLSTONE NUCLEAR POWER STATION, UNIT 1

 F Security, medical, emergency & fire protection plans
- 8210040120 Discusses util compliance w/SEP Topic VIII-3 B. "DC Power Sys Bus Voltage Monitoring & Annunciation "Sufficient monitoring equipment provided in control room or locally to alert operators of dc sys trouble No mode needed COUNSIL.W O Northeast Nuclear Energy Co (subs of Northeast Utilities) COUNSIL.W O Northeast Utilities 82/09/23 CRUTCHFIELD. D Operating Reactors Branch 5 3pp 15381 204 24x Fiche 50-245,82/09/23,8210040120
- 8210210192 Forwards IE Insp Repts 50-245/82-17 & 50-334/82-19 on 820808-0925 No noncompliance noted STAROSIECKI, R Division of Project & Resident Programs 82/10/0/COUNSIL, W Q Northeast Nuclear Energy Co (subs of Northeast Utilities) 2pp 15766 041 24X Fiche 50-245,82/10/07,8210210102
- --8210210196 IE Insp Repts 50-245/82-17 & 50-336/82-19 on 820808-0925 k noncompliance noted Major areas inspected plant & refueling operations, equipment alignments & readiness, radiation protection & physical security SMEDLOSKY.J T. LIPINSKI.D R. ELASSER.T C. Division of Project L Resident Programs 82/10/05 | 15pp 15766-043 24X Fiche 50-245,82/10/07,8210210182
- P Operating license stage documents & correspondence
- 8210010312 Requests that processing of 820812 license amend application be postponed Revised application changing radiological effluent Tech Specs will be docketed on or about 821115 for both facilities
 CDUNBIL.W O Connecticut Yankee Atomic Power Co CDUNBIL.W Q
 Northeast Nuclear Energy Co (subs of Northeast Utilities)
 CDUNBIL.W O Northeast Utilities 82/09/22 CLARK.R A Operating Reactors Branch 3 CDUCHFIELD. Deprating Reactors Branch 5
 3pp 15574 047 24X Fiche 50-000.82/09/22.8210010312
- 52105011B Forwards summary of differences for SEP topics & description of intended actions Schedule provided for topics requiring addi info Topics will be addressed in detail in topics specific correspondence COUNBIL.H O Northeast Nuclear Energy Co (subs of Northeast Utilities) COUNSIL.H O Northeast Utilities 82/09/22. CRUTCHFIELD.D Operating Reactors Branch 5 48pp 15604 1802 Jair Fiche 50-245.82709/22.821005018
- 8210010320 Summary of 820915 meeting w/util in Bethesda,MD rs post-LOLA combustible gas control evaluation fuel/clad gap iodine release vs water radiolysis rates Calculational methodology presented in util 820806 submittal acceptable SHEA, J J Operating Reactors Branch 5 82/09/23 Operating Reactors Branch 5 6pp 15574 040 24X Fiche 50-245,82/09/23.8210910320
- 821Q050177 Comments on NRC evaluation of SEP Topic VIII-2, "Emergenty Unsite Power Sys" Protective trips of gas turbine interlacks should be bypassed under accident conditions unless bypassing trip would result in machine destruction CDUNBIL.H O Northeast Nuclear Energy Co (subs of Northeast Utilities) COUNBIL.H O Northeast Utilities 82/09/27 CRUTCHFIELD.D Operating Reactors Branch 5 4pp 15603 358 241 Fichs 30-245,82/09/27,8210050177
- 8210040233 Informs that SEP Topic V-6, "Reactor Vessel Integrity." meets current criteria Evaluation will be basic input to integrated safety assessment for facility. SHEALJ Operating Reactors Branch 5 82/09/29 COUNSIL.W 0 Northeast Nuclear Energy Co (subs of Northeast Utilities) 2pp 15581 360 24X Fiche,50-245,82/09/29,8210040233.

- 8210040293 Informs that licensee response to Item (a) of NRC 820628 ltr re SEF Topic III-5 B. 'Pipe Break Outside Containment," acceptable NRC draft evaluation factually correct & considered final NRC evaluation of topic SHEA. J. Operating Reactors Branch 5 82/09/29 COUNSIL.W 0 Northeast Nuclear Energy Co (subs of Northeast Utilities) 3pp [5587 IJ5 24X Fiche 50-245.82/09/29,8210040293
- SE1006004B Comments on NRC evaluation of SEP Topic 111-4 B, "Turbine Missiles" Current insp & testing schedules adequate to provide assurance that turbine missiles not safely concern COUNSIL-W G Northeast Nuclear Energy Co (subs of Northeast Utilities) COUNSIL-W G Northeast Utilities 82/09/29 CRUTCHFIELD.D Operating Reactors Branch 5 2pp 15614 332 24X Fiche 50-245,82/09/29,8210060048
- 8210040094 Responds to open items identified in 820630 safety evaluations for 6EP Topics III-6. "Seismic Design Considerations" & III-11. "Component Integrity " Corrections & status of IE Builetin 79-14 program made encl CDUNSIL.W G Northeast Nuclear Energy Co (subs of Northeast Utilities) COUNSIL.W G Northeast Utilities 82/09/29 CRUICHFIELD.D Operating Reactors Branch 5 9pp 15615 013 24X Fiche 50-245,82/09/29,8210060094
- 8210290405 Responds to request for estimate of amount of lodine released to coolant following LDCA Total care inventory of lodine both stable & radioactive isotopes approx 10 kg, w/variation depending on fuel burnup HULMAN.L G Accident Evaluation Branch 82/09/29 CRUTCHFIELD.D Operating Reactors Branch 3 3pp 15863 307 24X Fiche 50-245.82/09/29.8210290405
- F2101503B2 Advises that gas turbine generator bldg can adequately resist design basis tormado loadings.per SEP Topic III-2 re wind & tormado loadings Fechnical evaluation rept & final SER encl SHEA.J Operating Reactors Branch 5 B2/09/30 CDUNSIL,W G Northeast Nuclear Energy Co (subs of Northeast Utilities) 9pp 15710 244 24X Fithe 50-245.B2/09/30.B2101503B2
- --B206230020 'Wind & Tornado Loadings." technical evaluation rept BARRETT.D J., AGARWAL.R Franklin Institute/Franklin Research Center NRC-03-79-118 TER-0527-403 82/06/21 PERSINKO.D MRC - No Detailed Affiliation Given 120pp 15710 254 24X Fiche 50-245, 82/09/30.8210150382
- 6210130331 Discusses revision of administrative procedures to incorporate revisod working hour guidelines & provisions for authorizing deviations per 620208 & 0615 requests. TMI

 Ifem I A 1 3. "Shift Manning" & Generic Ltr 62-12

 COUNSIL W G. CAONETTA J.P. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). COUNSIL, W G. Connecticut Yankee Atomic Power Co. 82/10/01. EISCHUTT.D G. Division of Licensing. 3pp. 15679-127. 24X Fiche 50-000.82/10/01.8210130331
- 5210130073 Forwards request for addl info re containment purge & vent operability (B-24) necessary to complete review CRUTCHFICED.D Operating Reactors Branch 5 B2/10/05 COUNSIL.W O Northeast Nuclear Energy Co (subs of Northeast Utilities) 4pp 15673 115 24X Fiche 50-245,82/10/05.8210130093
- B210130326 Comments on proposed scope of Phase III of SEP as reflected in individual topic definitions appended to 820909 lit Staff encouraged to develop & implement means to interporate positive attributes of Phase III in licensee/NRC interface KACICH.R M SEP Owners Ordup 82/10/07 EISENHUT.D @ Division of Licensing 7pp 15862 179 24X Fichs 50-000.82/10/07.8210130326
- 8210220486 Forwards final evaluation of SEP Topic VI-4, "Containment Isolation Sys "Deviations from review guidelines listed Implementation of administrative controls on values recommended SHEALU Operating Reactors Branch 5 82/10/08 COUNSIL:W G Northeast Nuclear Energy Co (subs of Northeast Utilities) 34pp 15779 036 24X Fiche 50-245,82/10/08.8210220486
- 9210270200 Forwards summary of NRC positions on 26 unresolved safety issues consisting of excerpts from NRC publications & repts to Congress & assessment of generic applicability Adequate basis exists to warrant continued plant operation COUNSIL.W 0 . OPEKA.J F Connecticut Yankee Atomic Power Co COUNSIL.W 0 Northeast Nuclear Energy Co (subs of Northeast Utilities) 82/10/13 CRUICHFIELD.D Operating Reactors Branch 5 48pp 15824 354 24X Fiche 50-000.82/10/13.8210270200
- 8210240194 Discusses util review of rod control carcuitry Na Credible single failure could cause inadvertent movement of more than one control rod at time info should resolve concerns re SEP Topic IV-2, "React(vity Control Bys "COUNSIL-W O Northeast Nuclear Energy Co (subs of Northeast Utilities) COUNSIL-W O Northeast Utilities 82/10/14 CRUICHFIELD.D Operating Reactors Branch 5 2pp 15799 019 24X Fiche 50-245.82/10/14 8210260194

- 8210260414 Provides addl info re 2-phase degraded grid undervoltage protection scheme for Class IE power sys.in response to 820623 request Mods uill be deferred until 1984 refueling outage Next rept will be submitted during Jul 1983 COUNSIL.W O Northeast Nuclear Energy Co (subs of Northeast Utilities) COUNSIL.W O . OPERALJ F Northeast Utilities 82/10/14 CRUTCHFIELD D Operating Reactors Branch 5 6pp 19806 144 24X Fiche 50-245,82/10/14.8210260414
- 8210250124 Forwards draft integrated plant safety assessment rept Draft provided for SEP Subcommittee 821026-27 meeting CRUTCHFIELD, D. Operating Reactors Branch 5 82/10/15 COUNSIL, W. O. Northeast Nuclear Energy Co. (subs. of Northeast Utilities) 79pp 15787 164 24X Fiche 50-245,82/10/15.8210250124
- 8210260517 Forwards proprietary "STR Bundle Submittal, Millstone-1 Segmented Test Rod Bundle, Suppl 6." as app to 821015 Reload B license amend submittal Rept withheld (raf lOCFR2 790) COUNSIL, W O. OPEKA, J F Northeast Nuclear Energy Co. (subs. of Northeast Utilities) COUNSIL, W O. Northeast Utilities 82/10/15 CRUICHFIELD, D. Operating Reactors Branch 5 3pp 15805 228 24x Fiche 50-245, 82/10/15, 8210260519
- 8210260459 Forwards corrections to draft evaluation of SEP Topic III-1. "Classification of Structures, Components & Sys." in response to 820505 request COUNSIL.W 9. DISHOP,R W Northeast Nuclear Energy Co (subs of Northeast Utilities) COUNSIL.W 0 Northeast Utilities 82/10/19 CRUICHFIELD,D Operating Reactors Branch 5 13pp 15806 210 24X Fiche 50-245,82/10/19,8210260459
- 8210250219 Advises that SEP Topic VI-6 "Containment Leak Testing," considered complete to conduct integrated assessment Multi-plant Item A-4 review will be conducted independent of SEP SHEA. J Operating Reactors Branch 5 82/10/22 COUNCIL, W G Northeast Nuclear Energy Co (subs of Northeast Utilities) 1p 15786 344 24% Fiche 50-245, 82/10/22, 8210830219
- Q Inspection reports, IE Bulletins & correspondence
- 8210060233 Advises that masonry wall mods will be complete by Nov 1982 & const will be completed by June 1983, per IE Bulletin
 80-11
 COUNSIL. H C Northeast Nuclear Energy Co (subs of Northeast Utalities) CDUNSIL. H C Northeast Utilities E2/09/24
 HAYNES, R C Region 1. Office of Director 2pp 15620 000 24X
 Fiche 50-245, 82/09/24, 8210040233
- 8210150699 Forwards request for addlinfo to complete review of 801104 response to IE Bulletin 80-11. "Masonry Hall Design"
 Response expected within 60 days of ltr receipt
 CLARK,R A Operating Reactors Branch 3 82/09/28 COUNBIL, H 0
 Connecticut Yankee Atomic Power Co CDUNSIL. H 0 Northeast Nuclear Energy Co (subs of Northeast Utilities) 13pp 15716 100 24X
 Fichs 90-000.82/09/28,8210150699
- 821006004B Comments on NRC evaluation of SEP Topic 111-4 B, "Turbing Missiles" Current insp & testing schedules adequate to provide assurance that turbine missiles not safety concern COUNSIL.H 0 Northeast Nuclear Energy Co (subs of Northeast Utilities) COUNSIL.H 0 Northeast Utilities 82/07/27 CRUTCHFIELD,D Operating Reactors Branch 5 2pp 15614 332 24X Fiche 50-245,82/07/27.8210060048
- 8210070352 Ack receipt of 820914 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-245/82-10 & 50-336/82-14 MARTIN,T T Division of Engineering & Technical Programs 82/10/0 COUNSIL-W Q Northeast Nuclear Energy Co (subs of Northeast Utilities) ip 15634 051 24X Fiche 50-245,82/10/05,8210070352
- --8210070356 Responds to NRC 820813 itr reviolations noted in IL Insp. Repts 50-245/82-10 & 50-336/82-14 Corrective actions controlled documents updated & Unit 1 control room drawing deficiencies corrected COUNSIL.H Q Northeast Nuclear Energy Co (subs of Northeast Utilities) COUNSIL.H Q Northeast Utilities 82/09/14 MARTIN.T T Division of Engineering & Technical Programs 3pp 13584 032 24% Fiche, 50-245, 82/10/05, 8210070352
- 820B190233 IE Info Notice 80-35, Suppl 1, "Leaking & Dielooged I-125 Implant Seeds " Evo list encl COBB.L 1 Division of Fuel Facilities, Materials & Safeguards 82/10/06 Consolidated Edison Co. of New York 64pp 15761 250 24% Fiche 50-000, 82/10/06, B20B190233
- 8210210182 Forwards IE Insp Repts 50-245/82-17 & 50-336/82-17 on 820808-0925 No noncompliance noted STAROSTECKI.R Division of Project & Resident Programs 82/10/07 COUNSIL,N Q Northeast Nuclear Energy Co (subs of Northeast Ut(lities) 2pp 15766-041, 24X Fiche 50-245,82/10/07,8210210182

- --8210210196 IE Insp Repts 50-245/82-17 & 30-336/82-19 on 620808-0925 No noncompliance noted Hajor areas inspected plant & refueling operations, equipment alignments & readiness, radiation protection & physical security SMEDLOSKY, J. T., LIPINSKI, D.R., ELAGSFR, T.C. Division of Project & Resident Programs 82/10/05 15pp 15766-043 24X Fichs 50-245,82/10/07,8210210182
- 8208190238 iE Bulletin 82-03, "Stress Corrosion Cracking in Thick-Wall-Large-Diameter-Stainless Steel.Recirculation Sys Piping at BUR Plants" Svc list encl DEYGUNG.R C Director's Office, Office of Inspection and Enforcement 82/60/14 Compolidated Edison Co of New York 115pp 15810 125 24X Fichs 50-000.82/10/14.8208190238
- B210220479 Notification of B21029 meeting w/util in Bethesda. HD to discuss spray sparger crack indications detected during visual insplusing underwater television equipment SHEA: J D perating Reactors Branch 5 B2/10/21 CRUTCHFIELD. D Operating Reactors Branch 5 3pp 15779 075 24X Fiche 50-245, 82/10/21,8210220479
- S Reportable occurrences, LERs & related correspondence
- B21001000B Responds to FOIA request for 19 categories of documents re nuclear reactor events & safety groblems Forwards documents issted in App A FELTON, J M Division of Rules and Records B2/06/28 UDELL, R A Cristical Mass Energy Project 15pp 15727 005 24X Fiche 30-000, 82/06/28, 8210010008
- --8103190719 Operating Reactor Event Hemo Bi-27 recreaking in several ASME Code Class I & Class 2 piping sys Affected sys are isolation condenser. Shutdown cooling cleanup & LPCI subsystem Defective sections are under repair EISERHUY. D & Division of Licensing 81/03/05 VOLLMER, & Division of Engineering 4pp 15728 259 24X Fiche 50-000,82/06/28,8210010008
- 8210080015 Addi response to FDIA request for 19 categories of info re nuclear reactor events & safety problems Forwards documents listed in App A Documents in App B completely withheld (ref FDIA Exemption 5) FELTON.J M Division of Rules and Records 82/07/12 UDELL,R A Critical Mass Energy Project 9pp 15665 027 24X Fiche 50-000.82/07/12,8210080015
- --8206070106 Dperating Reactor Event Memo 82-01 re 810810 reactor scram w/water hammer event Study of Unresolved Safety Issue A-1 shows no other water hammer events in BMR isolation condensers EISENHUT, D Q Division of Licensing 82/05/25 VOLLMER, R H Division of Engineering MATTSON, R J Division of Safety Technology 7pp 15665 150 24X Fiche 50-000, 82/07/12, 921008045
- 6210070360 LER 82-019/OIP on 820725.while performing remate visual insp of core spray spargers.crack indication identified on one core spray sparger to Junction box welds, Addl info will be provided in 14-day followup rept MROCZKA.E J Northeast Nuclear Energy Co (subs of Northeast Utilities) MROCZKA.E J Northeast Utilities 82/09/27 HAYKEE.R C Region 1. Office of Director ip 15634 059 247 Fiche 50-245, 82/09/27, 8210070360
- 9210070304 LER 82-019/01P on 820928, three safety relief valves failed to open at required setpoint pressure during bench test Cause under investigation Three remaining safety relief valves will be removed & bench tested.

 NROCZNA:E J Mortheast Nuclear Energy Co (subs of Northeast Utilities) MROCZNA:E J Northeast Utilities 82/09/29 HAYNES:R C Region 1. Office of Director 1p 15634 245 24X Fiche 50-245, 82/07/29, 8210070304
- B210070250 Telecopy message of LER 82-020/01P on 620930.1TT Orinnell snubbers failed lociup & bleed rate requirements Snubbers with be made operable or replaced prior to reactor startup MRGCZKA.E J Northeast Nuclear Energy Co (subs of Northeast Utilities) MRGCZKA.E J Northeast Utilities B2/10/01 MRGCZKA.E J Northeast Utilities B2/10/01 MRYMES.R C Region 1. Office of Director 19 15634 287 24X Ficher 50-245.82/10/01.8210070250
- 8210210423 Forwards LER 82-018/01T-0 Detailed event analysis encl MRGCZKA: E.J. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). MRGCZKA: E.J. Northeast Utilities 82/10/12 HAYNES: R.C. Region in Offica of Director. 2pp 15763 087, 24X Fiche 50-245, 82/10/12, 82/0210425

- --8210210430 LER 82-018/017-0 on 820925, crack indication identified on one core spray sparger to junction but weld Caused by high weld residual stresses Stress corresion cracking may have initiated indication Sparger hold clamp will be installed THULLIS Northeast Utilities 82/10/12 Region In (liffice of Director ip 15763 069 24X Fiche 50-245,82/10/12,8210210425
- 8210220103 Forwards LER 82-021/03L-0 Detailed event analysis encl MROCZKA.E J Northeast Nuclear Energy Co (subs of Northeast Utilities) MROCZKA.E J Northeast Utilities 82/10/13 HAYNES.R C Region 1. Office of Director 2pp 15/78 1/9 ./4x Fiche 50-245, 82/10/13, 8210220103
- --8210220108 LER 82-021/03L-0 on 820913, diesel generator tripped durioperational readiness demonstration test Caused by broken ring type wire lug at current transformer secondary connection due to flexing during installation THULL.T S Northeast Nuclear Energy Co (subs of Northeast Utilisties) 82/10/13 Region 1. Office of Director in 15778 171 24X Fiche 50-245.82/10/13.8210220103
- 8210220112 Forwards LER 82-020/017-0 Detailed event analysis and MRGCZKA, E.J. MRGCZKA, E.J. MRCCZKA, E.J. MRCCZKA, E.J. MRCCZKA, E.J. Mrtheast Nuclear Energy Co. Isubs of Northeast Utsilities & 82/10/15 HAYNES, R.C. Region J. Hifter of Director Opp 15778 164 24% Fiche 50-245.82/10/15.62/03/11.
- --8210220116 LER 82-020/01T-0 on 820930, four IIT Orinnell shubbers fails to fall within recommended range Fuither analysis showed that only one snubber failed design acceptance range Caused by oil leakage through cracked reservoir THULL, T B Northwast Nuclear Energy Co (subs of Northwast Utilities) 82/10/15 Region 1, Office of Director 1p 15778 167 24% Fiche 50-245,82/10/15,8210220112
- 6210220195 Forwards LER 82-019/01T-0 Detailed event analysis enti-MRGCZKA,E J Northeast Nuclear Energy Co (subs of Northeast Utilities) MRGCZKA,E J Northeast Utilities 62/10/15 HAYNES,R C Region 1, Office of Director 2pp 15/// 1/0 .4s Fiche 50-245, 82/10/15, 9210220195
- --8210220201 LER 82-019/01T-0 on 820928, five safety relief valves failing to open at required setpoint Cause being investigated by UP. Two valves will be replaced or rebuilt Other three will be reworked to retested THULL, TS Northeast Nuclear Energy Co (subs of Northeast Utilities) 82/10/15 Region i. Office of Director ip 15777 272 24X Fiche 50-245, 82/10/15,8210220195
- DOCKET 50-247 INDIAN POINT STATION, UNIT 2
- F Becurity, medical, emergency & fire protection plans
- 8210060145 Forwards "Testing & Repair of Siren Portion of Alert I. Notification Sys for Indian Point Nuclear Power Generating Plant: per discussion at 820708 status meeting MECLY.J J Power Authority of the State of New York (12/6)///:, DAYIDDFF, D New York, State of 1p 15614 275 24X Fiche 50-247, 82/09/15, 8210060145
- -8210060148 "Testing & Repair of Siron Portion of Alert & Mutificati Sign for Indian Point Nuclear Power Generating Plant " * Power Authority of the State of New York 82/09/14 lipp 15614 294 24% Fithe 50-247,82/09/15
- 8210280148 Releases public version of revised emergency planting procedures
 FELTON, JM Division of Rules and Records 82/10/12 Decument
 Management Branch ip 15862 271 24X Fiche 50-00J, 62/16/12
 8210280148
- --8210280154 Forwards public version of revisions to Emergency Plan
 Implementing Procedures IP-1020 re airborne radioiodine
 determination & IP-1046 re util personnel responsibilities
 during Unit 3 emergencies
 0/TOOLE, J D Consolidated Edison Co of New York 92/10/01
 HAYNES, R C Region i. Office of Director 3pp 15842 2/J 24;
 Fiche 50-003,82/10/12.8210280148
- --8210280139 Public version of revisions to Emergency Plan lablear-trfrocedures IP-1020 re airborne radioiodine determination & IP-1044 re util personnel responsibilities during Unit 3 emergencies < Consolidated Edison Co of New York 82/09/01 | Japp 15862 275 24X Fithe 50-003,82/10/12.8210280148

- B210200019 Advises that serious deficiencies in emergency preparedness will not be corrected since State of NY & FEMA not addressing concerns of local officials by involvement in current changes HOLT.J Public Interest Research Group, New York POSNER.P Parents Concerned About Indian Point FLEISHER.Z S West Branch Conservation Association 82/10/15 PALLADINO,N J, AHEARNE, JF, GIIINSKY V Commissioners 5pp 15755 083 24% Fiche 50-247.82/10/15,8210200019
- Adjudicatory correspondence
- ELOBEROTHS Ack receipt of 800416 memo w/insp repts verifying interim actions required of facilities in 800211 confirmatory orders Requests verification that Item F 2 in orders is met frem E 5 in W Gammill 800317 memo should be F 5 NGAN. I M Assistant Director for Operating Reactors 80/06/13 BRYAN. S E Division of Reactor Operations Inspections ip 02765 285 24X Fiche 50-247,80/06/03.8006230788
- P2.10050235 Declines invitation to appear before Subcommittee on Energy Conservation & Power Subcommittee investigation is intrusion into ongoing regulatory proceeding & threatens independence of Commission MORGAN, C Morgan Associates MORGAN, C Power Authority of the State of Neu York 92/09/30 OTTINGER, R L House of Rep. Energy & Commerce 10pp 15619-360 24X Fiche 50-247, 82/09/30, 8210060235
- 6010040108 Order CLI-82-28, requesting ASL8 reconstituted by CLI-82-24 to estimate when recommendations called for by CLI-81-23 can be provided CHILK, S.J. Office of the Secretary of the Commission 82/10/01 Atomic Safety and Licensing Board Panel 1p 15560 350 24X Fiche 50-247, 82/10/01, 8210040108
- 6210050254 Memorandum & order restating contentions & establishing procedures based on Commission guidance GLEASCH.J.P. PARIS.O.H., SHON.F.J. Atomic Safety and Licensing Board Panel 82/10/01 42pp 15609 211 24X Fiche 50~247. 62/10/01.82105050254
- R210130335 Motion for ASLB to direct NRC to reschedule 821013 meeting would be a standa in Albuquerque. NM to either New York, NY or Washington, DC Intervener unable to attend meeting in NM WEISS, E.R. Union of Concerned Scientists WEISS, E.R. Public Interest Research Group, New York 82/10/07 Atomic Safety and Licensing Board Panel 3pp 15682 050 24% Fiche 50-247, 82/10/07, 8210130335
- --B210130337 Motion for Commission to direct that all future meetings on issues be held in NY or Washington, DC & that intervenors be given notice concurrently w/other parties
 WEISS,E R Union of Concerned Scientists WEISS,E R Public Interest Research Group, Neu York B2/10/07 Commissioners
 2pp 15682 053 24X Fiche 50-247.882/10/07.8210130335
- 6210180203 Reply to ASLB 821001 memorandum & order Plant should be totally reinspected w/appropriate tests of piping, electrical 3 control systemated List of parties should be shortened to active participants Certificate of Svc enci FLEISHER. X S West Dranch Conservation Association 82/10/11 4pp 15718 124 24X Fiche 50-247.82/10/11,8210180203
- 8210150072 Order denying UCS/NY PIRC B21007 motion to direct NRC to reschadule B21013 meeting in Albuquerque, NM to NY or Washington, DC Only Commission has jurisdiction over NRC partormance of administrative responsibilities PARIS, D H. SHON, F J. GLEASON, J P. Atomic Safety and Licensing Board Panet B2/10/12 Union of Concerned Scientists 3pp 15701 194 24X Fiche 50-247, 82/10/12, 8210150072
- S2[0]50141 Grder scheduling S2[10]3-04 prehearing conference in White Plains, NY re oral argument on responses to ASLB S2[0]01 memorandum 2 order restating contentions GLEASON, J P. Atomic Safety and Licensing Board Panel S2[10]12 2pp 15678 306 24% Fiche 50-247, S2[10]12, S2[0]50141
- 8210180138 Motion in response to ASLB 821001 order, requesting clarification & importance of term "discussion" & extension of time to determine position re issue of consolidation Certificate of Byc encl KAPLANAC New York, NY 82/10/13 Atomic Safety and Licensing Board Panel 7pp 15719 123 24X Fiche 50~247,82/10/13,8210180138
- 8210200069 Telegraphic order granting licensee request for extension of time to file responses to 821001 order All party responses due 821019 GLEASON, J.P. Atomic Safety and Licensing Board Panel 82/10/14 Power Authority of the State of New York ip 15757 280 24X Fiche 50-247, 82/10/14, 8210200069

- 8210200019 Advises that serious deficiencies in emergency preparedness will not be corrected since State of NY & FEMA not addressing concerns of local officials by involvement in current changes

 HOLT, J Public Interest Research Group, New York POSNER, P
 Parents Concerned About Indian Point FLEISHER, Z S West Branch
 Conservation Association 82/10/15 PALLADING, N J, AHEARNE, J F,
 OILINSKY, V Commissioners 5pp 15755 083 24X

 Fiche 50-247, 82/10/15, 8210200019
- 8210220389 Submittal of comments on ASLB 821001 memorandum & order & motion for ASLB to issue reformulated contentions on Commission Questions 3 & by 821115 & to restore Contention 6 2 Certificate of Svc encl TOSCANI.K Parents Concerned About Indian Point 82/10/15 Atomic Safety and Licensing Board Panel 2pp 15777 307 24X Fiche 50-247,82/10/15,8210220389
- 6210210390 Requests destruction of West Branch Conservation Assor 821011 reply to 821001 memorandum & order & substitution of enci version
 FLEISHER, Z B West Branch Conservation Association 82/10/18
 NRC No Detailed Affiliation Given 1p 15764 099 24X
 Fiche 90-247,82/10/18,8210210390
- --8210210397 Response to 821001 memorandum & order Certificate of Svc enci FLEISHER, Z S West Branch Conservation Association 82/10/13 4pp 15764 100 24X Fiche 50-247, 82/10/18,8210210390
- 8210200059 Response to ASLB 821001 order ASLB should narrow language or ASLB Question 1 1 2 adopt proposed schedule for continuation of proceeding Certificate of Svc encl MOJRE, J, MCOURREN, H J Hearing Branch 1 82/10/19 9pp 15757 290 24X Fiche 50-247,82/10/19,8210200059
- 8210220375 Request for mod of ASLB 821001 order, to permit Rockland County to continue presentation of witnesses re Commission Questions 3 & 4 prior to taking evidence on Questions 1,2,5,6,7
 6,7
 THORSENIE D Reckland County, NY 82/10/19 Atomic Safety and Licensing Board Panel 2pp 15779 187 24X Fiche 50-247,82/10/19,8210220375
- 8210220410 Joint response of intervenors to ASLB 821001 order Meaning of "discussion" of probability should be clarified & ASLB should immediately reformulate contentions on Questions 3 & 4 Certificate of Svc encl WEISS.E R. Union of Concerned Scientists WEISS.E R. Harmon & Weiss 82/10/19 Atomic Bafety and Licensing Board Panel 12pp 15778 313 24X Fiche 50-247,82/10/19.8210220410
- 8210250081 Proposed hearing schedule Certificate of Svc encl BRANDENBURG. II Consolidated Edison Co of New York MORGAN, C Power Authority of the State of New York MORGAN, C Morgan Associates 82/10/19 9pp 15787 049 24X Fiche 50-247.82/10/19, 8210250081
- 8210250216 Response to ASLB 821001 order reformulating contentions Opposes admission of new Contention 1 1.Contentions 2-1(a)~ (d).2 2(a) & 2 2(b) & ASLB Question 2 2 1 Notice of appearance & Certificate of Svc encl MORGAN.C Power Authority of the State of New York MORGAN.C Morgan Associates 82/10/19 Atomic Safety and Licensing Board Panel 35pp 15789 166 24X Fiche 50-247.82/10/19.8210250216
- 8210250245 Notice of appearance in proceeding BAUM, B.L. Power Authority of the State of New York DAUM, B.L. Morgan Associates 82/10/19 1p (5771-132 24X Fiche 50-247,82/10/19,8210250265
- 8210250287 Motion for order reversing ASLB 821001 memorandum & order re taking of testimony on Questions 3 & 4 & establishing schedule for presentation of testimony upon expiration of 120-day clock Certificate of Svc encl VETERE: A Westhester County.NY 82/10/19 Atomic Safety and Licensing Board Panel 7pp 15791 165 24X Fiche 50-247.82/10/19,8210250287
- 8210250324 Memorandum re ASLB 921001 order reformulating contentions
 Objects to new Contention I 1.Bases 1a & 1b.Contentions
 2 i(a):2 i(b):2 i(c):2 i(d):2 2(a) & 2 2(b) Certificate of
 Svc encl
 BRANDENBURO. B Commonwealth Edison Co B2/10/19 Atomic Safety
 and Licensing Board Panel 49:pp 15790 243 24X
 Fiche 50-247.82/10/19.8210250324
- 8210250099 Motion for leave to file memorandum in response to ASLB 821001 order i day late Methanical difficulties encountered w/word processing equipment Certificate of Evc encl BRANDENBURO. B Consolidated Edison Co of New York 82/50/20 Commissioners 6pp 15787 062 24X Fiche 50-247,82/10/20, 8210250099.

- 8210280242 Requests Commission issue order directing all meetings between NRC & Licensea be held in Washington, DC or NY, that intervenors receive notice of meetings concurrently w/utils & that intervenors be provided w/minutes of 821013 meeting WEI8SE R Harmon & Weiss WEISSE R Union of Concerned Scientists 82/10/25 PALLADINO, N J . AMERING, J . 01LINSHY, V Commissioners 2pp 15937 058 24X Fiche 50-247.82/10/25, 8210380242
- 8210280230 Advises that NRC does not intend to respond to intervenor motions filed in response to ASLB 821001 order until after 821103-04 prehearing conference MODRE.J E Hearing Branch I 82/10/27 OLEASON.J P , SHON,F J , PARIS.D H Atomic Safety and Licensing Goard Panel 1p 15837 082 24X Fiche 50-247.82/10/27,82/10/280230
- 8210280353 Response opposing UCS/NY PIRG B21012 motion to direct NRC to reschedule all future meetings on hearing issues in NY or Washington; DC NRC should be permitted flexibility to determine most appropriate location W/Certificate of Svc MCGURREN; H J Hearing Branch 1 92/10/27 Commissioners 9pp 15839 048 24% Fiche 50~247.82/10/27.6210280353
- 8210290271 Advises that literaces plan to address all matters raised in responses/motions re ASLB 821001 memorandum & order at 821103-04 prehearing conference 821103-04 prehearing conference 82ANDENBURG, B. Consolidated Edison Co. of New York MOROAN, C. Power Authority of the State of New York MORGAN, C. Morgan Associates 82/10/27 GLEASON, J.P., SHON, F.J., PARIS, D.H. Atomic 8afety and Literating Board Panet 2pp. 15853 012 P4X Fiche 50-247, 82/10/27, 8210290271

H General correspondence

- 8210250272 Requests substitution of SL Baum w/TR Frey on official syclist for proceeding Related correspondence COLARULLI.P F Power Authority of the State of New York 82/10/19 STUCKY.8 W Docketing & Services Branch 19 15791 190 24X Fiche 50-247,82/10/19, 82/0250272
- O Advisory Committee on Reactor Safeguards reports & correspondence
- 8207180077 Forwards comments on PRA study dealing w/seismic hatard Validity of conclusions rest on quality of primary data bases & assumptions in both studies Repts are not valid nisk assessments due to data base limitations FOMEROY.P W Rondout Associates POMEROY.P W ACRE Advisory Committee on Reactor Safeguards 82/08/24 DKRENT.D ACRE Advisory Committee on Reactor Safeguards 7pp 15876 001 24X Fiche 50-003.82/08/24.8207180077

- B007310117 Forwards request for addlinfo required to complete Franks, Research Ctr evaluation of adequacy of steam generator & reactor coolant pump supports Request should be sent to licensee HICHMANIA R Operating Reactors Assessment Branch B0/07/14 VARGAIS A Operating Reactors Branch I 7pp 03056 268 24% Fiche 30-247, 80/07/14,8007310117
- 8008050220 Requests LB Marsh be permitted to continue reviewing overpressure protection sys & associated Tech Specs NOVAR.T Assistant Director for Operating Reactors RRNST.H L Assistant Director for Technology Review 1P 03078 175 24X Fiche 50-247.80/07/30.8008050220
- 8008130744 Surmary of 800617 meeting w/utils in Dethesda.MD recontainment structural response to care molt accident sequences
 MEYER.J F Power Systems Dranch 80/07/31 Power Systems Drance
 3pp 03266 243 24% Fiche 50-247.80/07/31.8008130743
- 8009100104 Approves Tech Specs revision proposal re insp of hydraulic fluid of snubbers supplied by common reservoir & excessive fluid loss due to external tubing leakage BARRETTIL M Operating Reactors Assessment Branch 80/08/05 VARGA, S A Operating Reactors Granch 1 (Pre 800428) ip 03516 074 24% Fiche 50-247,80/08/05,8009100104
- 6009210627 Forwards request for add1 info re spent fuel pool retarting Info needed to complete review of util application for license amend RUBENSTEINLS Assistant Director for Core & Containment (water, 80/08/08 NOVAK,T M. Assistant Director for Operating Reduture 3pp. 03382 306 24% Fiche 30 247.80/08/08.8008210627
- 6007100100 Forwards recommendations on staff task action plan to be sent to licensees for review & response

 BARRETT, I Operating Reactors Assessment Branch (RO/OH/OH VAROA, S A)

 O3516 066 Departing Reactors Panch i (Pre 800428)

 Bpp

 24X Fiche 50-247.80/08/08.8009100100
- 6009030334 Forwards Reactor Fuel Section questions re LOPAR fuel an core previously containing HIPAR fuel Questions should be rorusarded to licensee RUBENSTEIN.L S. Assistant Director For Core & Contailment liveless 80/08/18 NOVAK.T M. Assistant Director For Operating Reactors 3pp. 03462-022 24X Fiche 50-247.80/08/18.8009030734
- 80090B0466 Forwards response to 800B20 request for status rept in Zion/Indian Point task action plan Responsibilities are in area of severe accident mitigation features & not in interim operational actions portion
 MEYER.J F. Reactor Systems Branch B0/08/25 NOVAK, F. M. Assistant Fiche 50-003.8070B/25.80090B0466
 Fiche 50-003.8070B/25.80090B0466

- 2010240644 Forwards safety evaluation re electrical override of manual actuation features for containment ventilation isolation &
 - other ESF sys OLSHKISKI.JA Operating Reactors Assessment Branch 80/10/06 VARGA.S A Operating Reactors Branch 1 3pp 03661 092 24X Fiche 50-247.80/10/06.8010240644
- 8/10270312 Advises that Franklin Research Ctr was notified to proceed by final evaluation of fracture toughness of steam generator. Freactor coolant pump supports Due to util 800828 request for delay, appropriate conservative assumptions will be made DLSHINGKI J A Operating Reactors Assessment Branch NRC-03-79-JIE 80/10/06 VAROALS A Operating Reactors Branch 1 2pp 03661 208 24X Fiche 50-247.80/10/06.8010270312 NRC-03-79-118
- POLITICOS4 Requests Instrumentation & Control Sys Branch evaluation of oil ilousa Requests instrumentation o Control by Branch evaluation util responses to questions le incore instrumentation tubes at facilities info will aid branch evaluation mitigation reatures re backfitting or severe mitigation features SPEIS.T P Ryactor Systems Branch 80/10/09 SATTERFIELD.R Instrumentation t Control Systems Branch ip 02227 001 24X Fiche 50-247 80/10/09 8011110084
- E010280098 Forwards NRC questions % ofil answers re backfitting of severe accident mitigation features Evaluation needed in two C.C.D.I P Neactor Systems Branch B0/10/17 SCHAUER, F P Fiructural Engineering Branch 1p 65767 184 24X Fiche 50-247, 80/10/17, 8010280078
- #011200025 Forwards Power Sys Branch evaluation of differences between Indian Point 2 & 3.in response to technical assistance request Requests meeting w/licensee prior to formal response to evaluation
 CHECP P S Assistant Director for Plant Systems B0/10/21
 NOVAN T Assistant Director for Operating Reactors 21pp
 03743 111 24X Fiche 50-247, 80/10/21, 8011200025 80/10/21
- HOLI210284 Forwards draft safety evaluation of licensee response to last Action Plan Item II E 12 Automatic initiation logic, instrumentation & associated circuitry & automatic feedwater + low indication channels meet safety-grade requirements SATIERFIELD.R Instrumentation & Control Systems Branch 80/10/22 VARGA. S Operating Reactors Branch 1 8pp 03744 123 24X Fiche 50-247.80/10/22.8011210284
- 0101050528 Forwards questionnaire to be completed by each near-term UL.

 / each licensed plant by 801107 Objective is to assess best
 collective judgment re extent of problems recently
 experienced at facility
 UMRDAN.E L. Office of Inspection / Enforcement, Office of the
 Directon 80/00/28 BRUNNER,E J. Region I. Philadelphia, Reactor
 Operations Nuclear Support Branch LEWIS.R C. Region 2. Atlanta,
 Reactor Operations Nuclear Support Branch HEISHMAN.R F. Region 3,
 Chicago, Reactor Operations Nuclear Support Branch 2pp 94581 186
 244 Fiche 50-24/,80/10/29,8101050528
- R011070227 Requests all operating reactor project managers to conduct telephone survey w/licensees to determine if plants are susceptible to svc water leaks Results of survey requested Buy 801031 OLSIAN: H Operating Reactors Branch 1 80/10/29 Operating Reactors Branch 1 1p 03715 124 24X Fiche 50-247,80/10/29,
- 60)11120679 Forwards response to request for determination of licensing basis for reactor pressure vessel & containment fan cooler sys re FSAR requirements & current NRC criteria Licensee must perform thermal & stress analysis of vessel LAINAS.G C Assistant Director for Safety Assessment 80/10/29 ETBENHUT, D @ Division of Licensing &pp 03719 357 24X Fiche 50-247.80/10/29,8011120679
- 8011100165 Submits revision of relative concentration for short-term release following an accident Facilities exclusion radius found to be 520 meters resulting in relative concentration equal to 00091 sec/cu meter in southwest direction HOUSTEN.R W Accident Evaluation Branch 80/10/30 VAROA.8 A Operating Reactors Branch 1 ip 65748 021 24X Fiche 50-247.80/10/30.8011100165
- 8207050085 FOIA request for eight categories of records re steam generators & steam turbines LONO.D J Winthrop, Stimson, Putnam & Roberts 82/07/13 Of of Administration 3pp 15645 060 24X Fiche 50-247.82/07/13,
- 6210070097 Responds to FOIA request for eight categories of records re steam generators & steam turbines App A documents provided in R_Udell FOIA Request 81-313 Forwards documents listed in App B FELTON, J M Division of Rules and Records 82/09/10 LONG, D J Winthrop, Stimson, Putnam & Roberts 9pp 15645 043 24X Fiche 50-000, 82/08/10, 8210070007

- 8210010401 Forwards application to amend Licenses DPR-26 & DPR-5, cholowol forwards application to amend Licenses DPR-26 & DPR-5, changing Tech Specs refacility organization & Unit 2
 Tech Specs 3 & & 4 4 re containment isolation valves 3 12 & 4 12 in pipe lines Class i, II & III fees encl
 0/TOGLE, J D Consolidated Edison Co of New York 92/08/31
 VAROA, S A Derating Reactors Branch i 3pp 15572 211 24X
 Fiche 50-003, 82/08/31,8210010401
- --8210010409 Application to amend Licenses DPR-26 & DPR-5, revising Tech Spec Figures 3 2 & 6 2-2 re facility organization for Units 1 & 2, respectively 0.7100LE.J D Consultated Edison Co of New York 82/08/31 2pp 15572 214 24X Fiche 50-003,82/08/31.8210010401
- --8210010414 Proposed revisions to Tech Spec Figures 3 2 & 6 2-2, reflecting change in organizational structure to include position of operations superintendent Safety assessment enc l * Consolidated Edison Co of New York 82/08/3 15572 216 24% Fiche 50-003,82/08/31,8210010401
- --8210010425 Application to amend License DPR-26, revising Tech Spacs 3 6 & 4 4 to establish requirements for action required when containment isolation valves are inoperable & reflect changes to isolation valve provisions
 U'TODLE, J D Consolidated Edison Co of New York
 15572 222 24X Fiche 50-003.82/08/31.8210010401 82/08/31 2pp
- --8210010438 Proposed revisions to Tech Specs 3 & & 4 4, establishing eloulu438 Proposed revisions to lech Specs 3 6 & 4 4,establisis specific requirements for action during inoperability of containment isolation valves & reflecting changes & additions to isolation valve provisions Safety assessment encl ex Consolidated Edison Co of New York 82/08/31 20pp 15572 224 24X Fiche 50-003.82/08/31.8210010401
- --8210010443 Application to amend License DPR-26, revising Tech Spec Sections 3 12 & 4 12 to defflect editorial change safety-related gipe lines & to efflect editorial change O'TODLE,J D Cansulidated Edison Co of New York 82/08/31 i 15572 244 24% Fiche 50-003,82/08/31,8210010401 82/08/31 2pp
- --8210010449 Proposed revisions to Teth Spec Sections 3 12 & 4 12, reflecting redesigned support sys for safety-related pipe lines & to effect editorial change Safety easessment encl * Consulidated Edison Co of New York 82/08/31 18pp 24X Fiche 50-003, 82/08/31, 8210010401
- 8210080049 Notification of 820929-30 meeting w/util & Franklin Research Ctr in Buchanan,NY to discuss contractor review of util radiological effluent Tack Specs
 THOMA.J D Operating Reactors Branch 1 82/09/23 VARQA.B A
 Operating Reactors Branch 1 2pp 66367 356 24X
 Fiche 50-247.82/09/23.8210080049
- 8210130602 Informs that review of 810731 response to Generic Ltr 81-01, "Qualifications for Insp.Exam & Testing & Audit Personnel," complete Commitments & exceptions to Revision 1 to Reg Quide 1 158 & Reg Quide 1 146 acceptable VARQA.S A Operating Reactors Branch 1 82/09/27 0'700LE, J D Consolidated Edison Co of New York 2pp 15872 347 24X Fiche 50-247.82/09/27,8210130602
- 8210130455 Forwards responses to Items 1.3.4 & 8 of NRC 820315 request for add1 info re control of heavy loads (NUREO-0612) Info addressing Items 2.5.6 & 7 will be submitted by 830131 O'TOOLE, J D Consolidated Edison Co of New York 83/09/30 VARCA, S A Operating Reactors Branch 1 7pp 15682 019 24X Fiche 50-247, 82/09/30, 8210130455
- 82:0120253 Forwards initial comments on Sandia Natl Lebs 820825 preliminary draft ltr rept on review & evaluation of probabilistic safety study, addressing wind, seismic, fire, pressurized thermal shock & fan cooler issues O'TOOLE, J D Consolidated Edison Co of New York BAYNE, J P P. Authority of the State of New York 82/10/06 VAROA, S A Operal Reactors Branch 1 62pp 13652 215 24X Fiche 50-247,82/10/06,8210120253 Operating
- 8210190693 Advises that results of 820920 svc water sys test prove that Indian Point probabilistic safety study reflect actual plant configuration Remaining plant improvements in 820305 ltr.szcept ATWS mod.to be complete by return to svc O'TOOLE.J D Consolidated Edison Co of New York 82/10/08 VARQA.6 A Operating Reactors Branch 1 2pp 15738 141 24X Fiche 50-247, 82/10/08, 8210190693
- 8210210032 Forwards request for addl info to complete review of TMI Item II K 3 25, "Power to Pump Seals" Areas of conformance or deviation from stated position should be identified & info re design & operation of cooling sys provided VAROA.S A Operating Reactors Branch 1 82/10/15 0'TODLE, J D Consolidated Edison Co of New York 3pp 15774 360 24X Fiche 50-247,82/10/15,8210210032

- 8210280242 Requests Commission issue order directing all meetings between NRC & licensee be held in Washington OC or NY, that intervenors receive notice of meetings concurrently w/utils bethat intervenors be provided w/minutes of 821013 meeting WEISS.E R Harmon & Heiss WEISS.E R Union of Concerned Scientists 82/10/25 PALLADINO, N J AMEARNE, J GILINEKY V Commissioners 2pp 15837 058 24X Fiche 50-247,82/10/25,8210290242
- 8210280230 Advises that NRC does not intend to respond to intervenor motions filed in response to ABLO 821001 order until after 821103-04 prehearing conference MOORE. J E Hearing Branch 1 82/10/27 QLEASON. J P . SHON, F J . PARIS. O H Atomic Safety and Licensing Board Panel ip 13837 082 24% Fiche 50~247.82/10/27.8210280230
- 8210280353 Response opposing UCS/NY PIRO 821012 motion to direct NRC to reschedule all future meetings on hearing issues in NY or Washington DC NRC should be permitted flexibility to deternine most appropriate location W/Certificate of Syc MCGURREN, H J Hearing Branch (82/10/27 Commissioners 9pp 15837 048 24x Fiche 50-247.82/10/27.8210280353
- 8210290271 Advises that licensees plan to address all matters raised in responses/mations re ASLB 821001 memorandum & order at 821103-04 prehearing conference DRANDENBURG, B. Consolidated Edison Co. of New York MORGAN, C. Pouer Authority of the State of New York MORGAN, C. Horgan Associates 82/10/27 GLEASCH.J.P., SHON, F.J., PARIS, D.H. Atomic Safety and Licensing Board Famel 2pp 13853-012 24X Fiche 50-247, 82/10/27, 8210290271

H Ceneral correspondence

1

1.15

- 8210250272 Requests substitution of SL Baym w/TR Frey on official syc List for proceeding Related correspondence
 COLARULLI.P F Morgan Associates COLARULLI.P F Power Authoraty
 of the State of New York 82/10/19 STUCKY, S W Docketing &
 Services Branch ip 15791 190 24X Fichs 50~247,02/10/19.
- Q Advisory Committee on Reactor Safequards reports & correspondence
- 8207180077 Forwards comments on PRA study dealing w/seismic hazard Validity of conclusions rest on quality of primary data bases & assumptions in both studies Repts are not valid risk assessments due to data base limitations
 POMEROY, P H Rondout Associates POMEROY, P W ACRS - Advisory Committee on Reactor Safeguards 82/08/24 OKRENT, D ACRS - Advisory Committee on Reactor Safeguards 7pp 15876 001 24X Fiche 50~003,82/08/24,8207180077

P Operating license stage documents & correspondence

- 8006240851 Discusses postulated fuel handling accident inside containment, based on licenses 770815 accident analysis analysis includes worst single failure during accident Sarety evaluation & containment purge sys Tech Specs encl BARRETTIL Operating Reactors Assessment Branch 80/06/06 VAROA. S Operating Reactors Branch 1 3pp 02767 167 2 Fiche 50-247.80/06/06/06/0851
- 8007010658 Operating Reactor Event Hemo 80-7 re nearly simultaneous trips of Units 2 & 3 Event was of negligible safety significance & trips were unrelated & coincidental EISENHUTID 0 Division of Licensing 60/06/13 VOLLHER, R H Division of Engineering MATEGUN, R J Division of Safety Technology HAMAUER, B H Division of Human Factors Bafety 2pp 02815 145 24X Fiche 50-247.80/06/13.8007010658
- 8007070448 Operating Reactor Event Mamb 80-8 relies of offsite power Effects of thunderstorm resulted in total loss of offsite power Emergency diesel generators functioned properly EISENHUT, D. G. Division of Licensing 80/06/13, VOLLMER, R. H. Division of Engineering 8085.D.F. Division of Systems Integration (pre 811005) HANAUER, S. S. Division of Human Factors Safety Bpp 02881 349, 24% Fiche 50-247,80/06/13,8007070448
- 8007150303 Notifies that review will be conducted of Offshore Power Bys short-term risk studies using various resources, in response to 800405 request Evaluation will be submitted by 800922 MATTEGN.R J Division of Bafety Technology, 80/07/02. EISENHUT, 0 Q Division of Licensing 2pp 02752 301 24X Fiche 50-247,80/07/02,8007150303
- 8007280312 Summary of 800625 masting w/util re implications of Class 9 accidents on liquid pathways at facility.

 CODELL, R Hydrologic & Geotechnical Engineering Branch 80/07/08 LEAR G, Hydrologic & Gotechnical Engineering Branch 5pp. 03016:253. 24X ficks 50-247,80/07/08,8007280312

- 8007310117 Forwards request for addl info required to complete Frankly, Research Ctr evaluation of adequacy of steam generator & reactor coolant pump supports Request should be sent to Licensee WICHMAN, K R Operating Reactors Assessment Branch 80/07/14 VARGA, S A Operating Reactors Branch 1 7pp 03056 268 24x Fiche 50-247, 80/07/14, 8007310117
- 8008050220 Requests LS March be permitted in continue reviewing OBJOURNMENT TO THE TOTAL THE STATE OF THE ST
- BOOR130744 Summary of BOO617 meeting w/utils in Bethesda.MD re containment structural response to core melt accident sequences
 MEYER.J F Power Systems Branch 80/07/31 Power S
 Jpp 03266 243 24% Fiche 50-247/80/07/31,8008130744 Power Systems Brans
- 6009100104 Approves Tech Specs revision proposal re insp of hydraulic rluid of snubbers supplied by common reservoir & excessive fluid loss due to external tubing leakage BARREITIL H Operating Reactors Assessment Branch 60/08/U% VARGAS A Operating Reactors Granch 1 (Pre 80042B) ip 03516 074 24X Fiche 50-247, 80/08/05.8009100104
- 8008210627 Forwards request for add1 info to spont fuel poul sereching Info heeded to complete review of util application for license amend CICENSE amend
 RUBENSTEIN.L S Assistant Director for Core & Containment Lysteas
 80/08/08 NOVAK,T M Assistant Director for Operating Reacture
 3pp 03382 306 24X Fichs 50-247,80/08/08.800821062/
- 8009100100 Forwards recommendations on staff task action plan to be sent to licensess for review 3 response
 BARRETT.L H Operating Reactors Assessment Branch (80/0)//(0)//
 VARGA, 8 Operating Reactors Branch 1 (Pre 800428) Upp
 03916 066 24X Fiche 80-247.80/00/08.8009100100
- 8009030334 Forwards Reactor Fue) Section questions retilPAR finel in core previously containing HIPAR fuel Questions should be forwarded to licenses
 RUGEISTEIN, L. S. Assistant Director for Core & Containment Lystem, B0/09/18 NQVAK,T M. Assistant Director for Operating Heartors
 3pp. 03462-022 247 Fiche 50-247,80/08/18.8007030314
- 8007080466 Forwards response to 800820 request for status rept rezion/Indian Point task action plan Responsibilities are in area of severe accident mitigation features & not in interior operational actions portion MEYER. J F. Reactor Systems Dranch 80/08/25 NEWAK. I H. Assa Director for Operating Reactors 2pp 03484 007 24X Fiche 50-003.80/08/25.8009080466 NEWARLT H ARREST
- 8010150103 Discusses union representative allegation re hardsame, to Anisoned Discusses union representative allegation re hardsens, to security guard personnel Add Jinfo necessary prior to HIK investigation of allegations with the Add Jinfo necessary prior to HIK MARD. W. J. Office of Inspection & Enforcement, Office of the Director 80/88/20 Office of Inspection & Enforcement, Heffet the Director 20p 03630 268 24X Fichs 50-247, 80/01/28, 100905507
- 8009250234 Submits description of work being done on analysis of releases from facilities Bimple I-D multicompartment thermal hydraulic code being written to analyse variety of 1909 designs Related data encl FENSTERNACHER Reactor Systems Branch 80/09/10 IPELIA PRACTOR Systems Branch 4pp 03589 257 24% Fishe 30 24 PROCES 009250234
- B010220234 Responds to B00917 request re control room review ###C to the detailse five add1 items to near-term OL requirements Item III D 3 4 requires analysis of control room habitability by B10101 HOUSTON R W Accident Evaluation Branch B0/09/25 VARGA S A Operating Reactors Branch i p 03560 001 24X Fiche 50-247,80/09/25,B010220234
- B010210783 Forwards recommendations for meeting auxiliary factively min flow requirements Licenses must demonstrate decay heat removal for 10 minutes w/o operator action or reset control valve throttled position CHECK,PS Assistant Director for Plant Bystems 80/09/28 NOVAK,TM Assistant Director for Operating Reactors 2pp 03647 104 24% Fiche 50-247,80/09/28,8010210780
- 8010240329 Discusses human factors control room design inspt geet Old 2002Y Discusses adman rations control room perion into a consoling of the consultation and the consultation is control for actions procedures by implementation schedule provided. Can Ed & PASNY control food design repts found incomplete MODRE, V.A. Division of Human Factors Bafety. 80/09/29 CLSHINSKI.J. Division of Licensing Spp. 03659-357 248 Fiche 50-247, 80/09/29, 8010240329.

- E010240644 Forwards safety evaluation re electrical override of manual actuation features for containment ventilation (solation to note ESF systems). Departure Reactors Assessment Franch 80/10/06
- 3010270312 Advises that Franklin Research Ctr was notified to proceed within evaluation of fracture toughness of steam generator a reactor coolant grop supports Due to util 800828 request for delay, appropriate conservative assumptions will be made OLSKINSPI. J A Operating Reactors Assessment Branch NRC-03-79-118 80/10/04 NRG-03 A Operating Reactors Branch 1 2pp 03col 208 24X Fiche 50-247,80/10/06,8010270312
- 3011110034 Requests Instrumentation & Control Sys Branch evaluation of util responses to questions to incore instrumentation tubes at facilities info will aid branch evaluation mitigation reatures re backfitting of severe mitigation features SPEIS 1 P Reactor Systems Branch 80/10/09 SATTERFIELD, R Instrumentation & Control Systems Branch ip 02227 001 24X Fishe 50-247, 80/10/09, 80(1110084
- OldEBOOR Forwards NRC questions & util answers re backfitting of severe accident mitigation features Evaluation needed in two uts
 SFEIS.T P. Reactor Systems Branch 80/10/17 SCHAUER, F.P. Structural Engangering Branch 1p 65767 184 24X
 Fiche 50-247, 80/10/17, 8010280098
- 10:11200025 Forwards Power Sys Branch evaluation of differences between Indian Point 2 & 3,in response to technical assistance request Requests meeting w/licensee prior to formal response to evaluation
 CHECK.P S Assistant Director for Plant Systems 80/10/21
 ACVAP.T Assistant Director for Operating Reactors 21pp
 03243 111 24X Fishe 50-247-80/10/21-80/1200025
- IO11210284 Forwards draft safety evaluation of licensee response to last Action Plan Item II E 1 2 Automatic initiation logic. Instrumentation & associated circuitry & automatic feedwater riou indication channels meet safety-grade requirements SATTERFIELD. R Instrumentation & Control Systems Branch BO/IO/22 VARCA. S Operating Reactors Branch 1 Bpp 03744 123 24X Fiche 50-247.80/10/22.8011210284
- OliO70227 Requests all operating reactor project managers to conduct telephone survey w/licensees to determine if plants are susceptible to svc water leaks Results of survey requested by BOlO31
 OLSHAMLL H Operating Reactors Branch 1 BO/10/29 Operating Reactors Branch 1 10 03715 124 24X Fiche 50-247,80/10/29,
- Oll120679 Forwards response to request for determination of licensing basis for reactor pressure vessel & containment fan cooler sys re FSAR requirements & current NRC criteria Licensee must perform thermal & stress analysis of vessel LAINAS. G C Assistant Director for Safety Assessment 80/10/29 EISENHUT, D G Division of Licensing 6pp 03719 357 24X Fiche 50-247.80/10/29,8011120679
- 011100165 Bubmits revision of relative concentration for short-term release following an accident Facilities exclusion radius round to be 520 meters resulting in relative concentration equal to 0 00051 sec/cu meter in southwest direction HUUSTON.R W Accident Evaluation Branch 80/10/30 VAROA.S A Operating Reactors Branch 1 ip 65768 021 24X Fiche 50-247,80/10/30.80[1100]85
- 207050085 FOIA request for eight categories of records re steam generators & steam turbines LONG, D. J. Winthrop, Stimson, Putnam & Roberts 82/07/13 Office of Administration 3pp 15645 040 24X Fiche 50-247,82/07/13,8207050085
- 210070007 Responds to FOIA request for eight categories of records re steam generators & steam turbines App A documents provided in R Vdell FOIA Request 81-313 Forwards documents listed in App B FELTON.J M Division of Rules and Records 82/08/10 LONG, D J Winthrop, Stimson, Putnam & Roberts 9pp 15645 063 24X Fiche 50-000, 82/08/10, 8210070007

- 82(00)0401 Forwards application to amend Licenses DPR-26 & DPR-5, changing Tech Spacs re facility organization & Unit 2
 Tech Spacs 3 6 & 4 4 re containment isolation valves 3 12 & 4 12 in pipe lines Class I.II & III fees encl
 G'TOOLE.J D Consolidated Edison Co of New York 82/08/31
 VARGA.S A Operating Reactors Branch 1 3pp 15572 211 24X
 Fiche 50-003,82/08/31.8210010401
- --B210010409 Application to amend Licenses DPR-26 & DPR-5. revising Te Spec Figures 3 2 & 6 2-2 re facility organization for Units 1 & 2. respectively O'TOOLE, J D Consolidated Edison Co of New York B2/08/31 2p 15572 214 24X Fiche 50-003.82/08/31.821001040:
- ---8210010414 Proposed revisions to Tech Spec Figures 3.2 & A.2-2, reflecting change in organizational structure to include position of operations superintendent Safety assessment encl

 * Consolidated Edison Co. of New York 82/08/31 App 15572 216 244 Fiche 50-003, 82/08/31,8210010401
- --0210010425 Application to amend License DPR-26, revising Tech Specs 3 6 & 4 4 to establish requirements for action required when containment isolation valves are inoperable & reflect changes to isolation valve provisions G*TODLE, J D Consolidated Edison Co of New York 82/08/31 2p 15572 222 24X Fiche 50-003, 82/08/31, 8210010401
- --821001043B Proposed revisions to Tech Specs 3 & & 4 4.establishing specific requirements for action during inoperability of containment isolation valves & reflecting changes & additions to isolation valve previsions Safety assessment encl * Consolidated Edison Co of New York 82/08/31 20pp 15572 224 24X Fiche 50-003.82/08/31.8210010401
- --8210010443 Application to amend License DPR-26, revising Tech Spec Sections 3 12 & 4 12 to defflect editorial change safety-related pipe lines to sefflect editorial change O'TOOLE.J D Consolidated Edison Co of New York 82/08/31 2; 15572 244 24% Fiche 50-003.82/08/31.8210010401
- --B210010449 Proposed revisions to Tech Spec Sections 3 12 & 4 12, reflecting redesigned support sys for safety-related pipe lines & to effect editorial change Safety assessment encl * Consolidated Edison Co of New York 82/08/31 18pp 15572 246 24X Fiche 50-003, 82/08/31,8210010401
- 8210080049 Notification of 820929-30 meeting w/util & Franklin Resear Ctr in Buchanan, NY to discuss contractor review of util radiological effluent Texh Specs THOMA, J.D. Operating Reactors Branch 1 82/09/23 VAROA, 8 A Operating Reactors Branch 1 2pp 66367 336 24X Fiche 50-247, 82/09/23, 8210080049
- 8210130602 Informs that review of 810731 response to Generic Ltr 81-4 "Qualifications for Insp.Exam & Testing & Audit Personnel," complete Commitments & exceptions to Revision 1 to Reg Quide 1 58 & Reg Quide 1 146 acceptable VARQA:B A Operating Reactors Branch 1 82/09/27 B'TODLE, J D Consolidated Edison Co of New York 2pp 15692 347 24X Fiche 50-247.82/09/27.8210130602
- 8210130455 Forwards responses to Items 1.3.4 & 8 of NRC 820315 requestor add1 info re control of heavy loads (NUREO-0612) Info addressing Items 2.5.6 & 7 will be submitted by 830131 O'TOOLE. J D Consolidated Edison Co of New York 83/09/30 VAROA:S A Operating Reactors Branch 1 7pp 15682 019 24X Fiche 50-247.82/09/30.8210130455
- 8210120253 Forwards initial comments on Sandia Natl Labs 820825 preliminary draft ltr rept on review & evaluation of probabilistic safety study, addressing wind, seismic, fire, pressurized thermal shock & fan coaler issues O'TOOLE, J D Consolidated Edison Co of New York BAYNE, J, P Pol Authority of the State of New York B2/10/06 VARQA, 8 A. Operat Reactors Branch 1 62pp. 15652 215 24X Fiche 50-247, B2/10/06, 8210120253
- 6210190693 Advises that results of 820920 svc water sys test prove t Indian Point probabilistic safety study reflect actual plant configuration Remaining plant improvements in 820905 itrrescept ATNS modito be complete by return to svc O'TOOLE, J D Consolidated Edison Co of New York 82/10/08 VAROA, S A Operating Reactors Branch 1 2pp 13738 141, 24X Fichs 50-247-82/10/08,8210190693
- BR10210032 Forwards request for add1 info to complete review of TMI Item II K 3.25, "Power to Pump Beals " Areae of conformance or deviation from stated position should be identified & info re design & operation of cooling sys provided VAROA: S A Operating Reactors Branch I 82/10/15 D'TOOLE, J D Consolidated Edison Co. of New York 3pp 13774 360 24% Fiche 50-247.82/10/15.8210210032

- 8210280428 Forwards safety evaluation of adequacy of station electric distribution sys voltages based on util 820709 ltm Sys voltages adequate Review closed VARGA, S.A. Operating Reactors Branch 1 82/10/18 0'TDDLE, J.D. Consolidated Edison Co. of New York 2pp 15860-019 24X Fiche 50-247, 82/10/18, 8210280428
- --8210280430 Bafety evaluation supporting adequary of station electric distribution sys voltages
 -- Office of Nuclear Reactor Regulation, Director 15860-021 24X Fiche 90-247-87/10/18-8210280428
- --8210280432 "Adequacy of Station Electric Distribution bys Voltages.
 Indian Point Nuclear Station, Unit 2 "
 UDY, A C. HEBER, D. A. 8090, Inc. FIN A-6429 EQQ-EA-5337 ROI
 62/07/30 PREVATIE, R.L. Division of Systems Integration (past
 811005) 14pp 15860 028 249 Fiche 50-247,82/10/18,8210280428
- 8210260332 Notifies of changes in estimated schedule of completion for TMT frems II F 1. "Noble Gas Monitoring." II B 3. "Post-Accident Sampling." & III D '4 4. "Control Room Habitability " Mads will be completed by end of refueling G-TODLE. J D Consolidated Edison Co of New York 82/10/19 WARGA. B A Operating Reactors Branch I 2pp 15802-357 24X Fiche 50-247, 82/10/19.8210280332
- a inspection reports. IF Hulletins & correspondence
- 0210080015 Add1 response to FOIA request for 19 categories of information reactor evonts & safety problems Forwards documents listed to App A Documents in App B completely withheld (ref FOIA Exemption 5)
 FELTON J (1 Division of Rules and Records 92/07/12 UDELL.R A Critical Mass Energy Project 9p 15665 027 24X
 Fithe 50-000. 92/07/12. D210080015
- --B2100B0137 Equation assessment of licensee performance notes refacility evaluation for 1780

 * NRC No Betailed Affiliation Given 80/12/31 7pp
 15667 350 24X Fiche 50-900, 82/07/12,82100B0015
- 62(0070097 Responds to FOIA request for eight categories of records re steam generators & steam turbines App A documents provided in A Udell FOIA Request 91-313 Forwards documents listed in App B FELTON, J M Division of Rules and Records 62/08/10 LONG, D J Winthrop, Stinson, Putnam & Roberts 9pp 19645 063 24X Fiche 50-000, 62/08/10, 62(007000)
- --8010070137 Forwards tabulated data on steam generator linsp & maint at facilities Data should be provided to licensess IPPOLITO. T. Operating Reactors Assessment Branch 82/Q4/Oi VARQA.S. Operating Reactors Branch 1 5pp 15645 131 24X Fiche 50-000,82/08/10,8210070007
- --8210070172 Forwards info re steem generator integrity & insps at all operating PHRs.per /50370 & 21 requests Details of insps. including defect indications tube plugging criteria & tubes plugged will not be provided except for Point Beach 1 GOLLER.K R Division of Reactor Licensing (NRR-1975 only) 75/03/R4 MACCARY.R Division of Technical Roview (NRR-1975 only) 5pp 15645 194 24X Fiche 50-000.62/08/10.8210070007
- 8210200078 Forwards stoam generator exam program for 1982 refueling/maint gutage O'TODLE-J D Commonwealth Edison Co 82/00/18 VARGA, 8 A Licensing Branch 1. 21pp 15753 178 24X Fiche 50~247.82/08/18, 8210200078
- B210060024 Forwards IE lnsp Rept 50-247/82-18 on B20B01-31 & notice of violation STAROSTECKI.R Division of Project & Resident Programs B2/09/17 O'TODLE: J D Consolidated Edison Co of New York 2pp 13615 054 24X Fiche 50-247.82/09/17.8210060024
- --B210060041 Notice of violation from insp on 820801-31 # Division of Project & Resident Programs 82/07/17 ip 15615 056 24% Fiche 30-247,82/07/17,8210060024

4

- --B210060046 IE Insp Rept 50-247/82-18 on B20801-31 Noncompliance noted failure to maintain containment integrity for isolation valves REDELOWSKI.T., KOLTAY.P., KISTER.H. Division of Project & Resident Programs. B2/09/16 iSpp 15615 057 24X Fiche 50-247,82/09/17,8210060024
- 8208170233 IE Info Notice 80-35. Buppl 1. "Lsaking & Dislodged I-125 Implant Beeds " Bvc list encl COBB.L I Division of Fuel Facilities. Heterials & Bafeguards 82/10/06 Consolidated Edison Co of New York 66pp 15761 250 24X Fishe 50-009.82/10/06.8208190233

- 8210130556 Ack receipt of 820915 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-247/82-14
 STAROSTECKI.R Division of Project & Resident Programs
 O'TODLE, J D Consolidated Edison Co of New York 1p 15883 304
 24X Fiche 50-247, 82/10/06, 8210130556
- --B210130559 Forwards response to NRC B20816 ltr re violations nated at IE Insp Rept 50-247/82-14 Corrective actions post-major tests/insp per CGL-51 will be ensured All post-maint activities after B2103 will be verified D'TOOLE. J Consolidated Edison to of New York B2/09/15 STARDSTECKI.R Division of Project & Resident Programs ip 15483 305 24X Firms 50-247, 82/10/04, 8210130556
- 8210210300 Forwards IE Insp Rept 50-247/82-19 on 820901-00 No honcompliance noted STAROSTECKI, R Division of Project & Resident Programs 82/10/07 O'TODLE, J D Consolidated Edison Co of New York 2pp 1576, 248 24X Fiche 50-247, 82/10/07, 8210210300
- --8210210307 IE insp Rept 50-247/82-19 on 820901-30 No noncompliance noted Major areas inspected licensee mpt changes operational safety verification, plant tours operability of ESF, safety sys challenges & LER followups
 REBELOUSKI.T. FOLEY.T. KISTER.H Division of Project & Resident Programs 82/10/06 17pp 15764 250 24X Fiche 50-247,82/10/07 8210210300
- 8208190238 IE Autletin 82-03, "Stress Cortosion Cracking on Ibica-Mallitarge-Diameter: Stainless Steel, Recirculation Sys Pipting at BMR Plants " Svc list encl DEYOUNG: R C Director's Office, Office of Inspection and Enforcement 82/10/14 Consolidated Edison Co of New York 115pp 15810 125 24X Fiche 50-000, 82/10/14, 8208190238
- S Reportable occurrences. LERs & related correspondence
- 621001000B Responds to FOIA request for 19 categories of documents re nuclear reactor events & safety problems Forwards documents listed in App A FELTON, J H Division of Rules and Records B2/06/28 UDHILR A Critical Hass Energy Project 50p 15727 005 24x Fiche 50-000, B2/06/28, 821001000B
- --B011120679 Forwards response to request for determination of licens basis for reactor pressure vessel & containment fan cooler sys re FSAR requirements & current NRC criteria Licensee must perform thermal & stress analysis of vossel LAINAS.G C Assistant Director for Bafety Assessment 80/L0/29 EISENBUT, D G Division of Licensing App 15728 045 24x Fiche 50-000.82/06/28.8210010008
- --8011240024 Forwards Containment Sys Branch discussion paper compar facility event w/current licensing criteria RUBENSTEIN.L. Assistant Director for Core & Containment Systems 80/11/07 LAINAS.G Assistant Director for Safety Assessment 6pp 15728 051 24X Fiche 50-000.82/06/28.8210010008
- --8101090276 Describes sequence of events leading to containment flo at Unit 2 Unit 3 should be allowed to return to gower operation pending long-term actions IE Info Notice 80-37 re containment cooler leaks & press release encl WDDUS.H W Office of Inspection & Enforcement, Office of the Director 80/11/13 JORDAN, E. L Office of Inspection & Enforcement. Office of the Director 6pp 15728 035 24x Fiche 50-000,82/06/28.8210010008
- --Bi03090387 Informs that Safety Program Evaluation Branch does not develop requirements for non-RCS leakage detection Branch avaluates proposed requirement adequacy in terms of cost-benefit analysis & possible adverse consequences MURLEY. T E Division of Safety Technology 81/02/27 EIEENHUT, D 0 Division of Licensing 2pp 15728 030 24% Fichs 50-000,82/06/28,8210010008
- 8210080015 Add1 response to FDIA request for 17 categories of infonuclear reactor events & safety problems.Forwards documents listed in App A Documents in App B completely withheld (ref FOIA Exemption 5)
 FELTON.J M. Division of Rules and Records 82/07/12 UDELL.R A Critical Mass Energy Project 9pp 15665 027 24X
 Fichs 50-000.82/07/12,8210080015
- --8205030617 Forwards "Engineering Evaluation of Indian Point Unit Flooding Event of 801017" LANNING U D Director's Office 82/04/22 MICHELSON, C Director's Office ip 15665 239 24X Fiche 50-000, 82/07/12, 8210080015
- --8205030619 "Engineering Evaluation of Indian Point Unit 2 Flood; Event of 801017 " LANNING,W D. Director's Office 82/04/30 25pp 15665 240. Fiche 50-000,82/07/12,8210080015.

- 82100A0396 Forwards LER 82-036/03L-0 O'TGOLE.7 D Consolidated Edison Co of New York 82/09/24 HAYKES.R C Region 1. Orfice of Director 1p 15615 326 24X Fiche 50-247,82/09/24,8210060396
- --210060400 LER 82-036/03L-0 on 820825, temporary change procedure authorized to permit simultaneous operation under load of two diesel generators during surveillance test-potentially reducing degree of redundancy Test procedure PTM-21 changed SMITH-M C Consolidated Edison Co of New York 82/09/24 Region I, Office of Director 2pp 15615 327 24% Fiche 50-247,82/09/24,8210060396
- 5210070361 Forwards LER 82-034/03L-0 0'TQQLE.J D Consolidated Edison Co of New York 82/09/27 HAYKES.R C Region I. Office of Director 1p 15634 060 24X Fiche 50-247, 82/09/27, 8210070361
- --8210070366 LER 82-034/03L-0 on 820828, during normal operation, charging pump 22 developed leak & was declared inoperable Gaused by defective gastet on cylinder head 4 Gasket replaced & pump returned to svc

 4 Consolidated Edison Co of New York 82/09/27 Region 1, Defice of Director 1p 15634 061 24X Fiche 50-247,82/09/27, 021007244
- 6210040141 Forwards LER B2-032/017-0 G'TDØLE-J D Consolidated Edison Co of New York 82/09/28 HAYNES.R C Region 1. Office of Director 1p 15583 088 24X Fiche 50-247, 82/09/28, 8210040141
- --8210040145 LER 82-032/01T-0 on 820817.blowdown outer isolation valve FCV 1215A failed closed due to failure of solenoid valve SOV 1315A caused by open circuit in pilot solenoid valve SQV 1315A cail Coil replaced F1TZPATRICK, B Consolidated Edison Co of New York 82/08/31 Region J. Office of Director 3pp 15583 087 24X Fiche 50-247.82/09/28.8210040141
- 8210130411 Forwards LER 82-035/03L-0 O'TOOLE.J D Consolidated Edison Co of New York 82/09/28 HAYNES.R C Region 1. Orfice of Director 1p 15680 241 24) Fiche 30-247, 82/09/28, 8210130411
- --B210J30419 LER 82-035/03L-0 on 820B29, nuclear power range instrumentation channel N41 became inoperative due to failure of power supply unit Cause of unit failure not stated Defective high voltage power supply removed NADIPURAN.P Consolidated Edison Co of New York 82/09/28 Regison 1. Office of Director ip 15680 242 24X Fiche 50-247,82/09/28,8210130411
- 8210290267 Part 21 deficiency rept re potential galling problem between stem & bonnet of 1 25-inch & larger A105 carbon steel & A182-F22 valves supplied Feb 1981-Aug 1982 Valves should be serviced & stem &/or bonnet replaced ISABELLE. L D Convai, Inc 82/10/11 HAYNES, R C Region 1, Office of Director 17pp 15854 232 24X Fiche 30-000:82/10/11, 6210290267
- 82:10250145 Forwards LER 82-039/03L-0 D'TOCLE.J D Consolidated Edison Co of New York 82/10/12 HAYNES.R C Region 1, Office of Director 1p 15787 354 24X Fiche 50-247, 82/10/12:8210250145
- ~-8210250149 LER 82-039/03L-0 on 820910, chemical sampling indicated 13 15% concentration of boric acid in storage tank 22 Boric acid transfer pump also out of svc for maint Cause not stated Contents diluted HTMRICHS, O Consolidated Edison Co of New York 82/10/12 Region 1, Office of Director 1p 15787 355 24X Fiche 50-247.82/10/12.8210250145
- T Hearing transcripts on non-antitrust matters
- 8210060232 Testamony of JD O'Toole before US House of Representatives Subcommittee on Energy & Conservation of Committee on Energy & Conmerce re role of public participation in NRC proceedings H/Certificate of Svc Related correspondence O'TOOLE.J D Consolidated Edison Co of New York 82/10/01 2ipp 15621 204 24X Fiche 50-247,82/10/01,8210060232

- DOCKET SO-249 DRESDEN NUCLEAR POWER STATION, UNIT 3

 F Security, medical, emergency & fire protection plans
- 8209290125 Releases public version of revised generating station emergency plan corporate command ctr emergency plan implementing procedure FELTON, J. M. Division of Rules and Records 82/09/16 Document Management Branch ip 15564 122 24X Fiche 50-000,82/09/16,8209290125
- ----B209290189 Forwards public version of Revision 4 to generating station emergency plan corporate command ctr Emergency Plan Implementing Procedure EDF-3, "Environ/Emergency Coordinator " Receipt form encl PAJOHBKI, J E Commonwealth Edison Co 82/09/01 DENTON, H R NRC No Datailed Affiliation Given Ip 13564 123 24X Fiche 50-000, 82/09/16, 8209290125
- --8209290225 Public version of Revision 4 to generating station emergency plan corporate command ctr emergency plan implementing Procedure EDF-3. "Environ/Emergency Coordinator"
 PAJONSKI, J E., LITERSKI, L A., FLESSNER, S. A. Commonwealth Edison Co. 82/08/31 lipp 15564 124 24X Fiche 50-000, 82/09/16, 8209290125
- 8210010009 Forwards info to suppl B20701 request for exemption from App R per B20917 telcon Request applies to Sections III G 2 a 5 III O 3 b re installation of fire suppression sys RAUBCH, T J Commonwealth Edison Co 82/09/23 EISENNUT, D Q Division of Licensing 8pp 15565 152 24X Fiche 50-000, B2/09/23, 8210010009
- 8210130376 Advises that installation of offsite dose calculation syspogram fully operational tracking model & operational A-model will be delayed until 821231 to complete prime computer installation SNARTZ.E D Commonwealth Edison Co 82/10/06 DENTON,H R Office of Nuclear Reactor Regulation, Director 2pp 15682 098 24X Fiche 50-000, 82/10/06, 8210130376
- 8210270047 Releases public version of revisions to Qued Cities, Zion & Dresden emergency plan annexes & revised generating station emergency plan telephone directory FELTON.J M Division of Rules and Records 82/10/08 Document Management Branch 1p 15877 313 24X Fiche 50-000, 82/10/08, 8210270047
- --8210290060 Forwards public version of Revision 3 to Quad Cities & Zion emergency plan annexes, Revision 2 to Dreaden emergency plan annex. Revision 0 to Byron emergency plan annex & revised generating station emergency plan telephone directory MODRE-R D Commonwealth Edison Go 82/07/30 DENTON, H R NRC No Detailed Affiliation Given 5pp 15877 314 24X Fishe 50-000, 82/10/08, 8210290047
- --8210290077 Public version of Revision 3 to Quad Cities & Zion emergency plan annexes, Revision 2 to Dresden emergency plan annex & Revision 0 to Byron emergency plan annex # Commonwealth Edison Co 82/06/30 102pp 15877 319 24X Fiche 50-000, 82/10/08.8210290047
- --8210270088 Public version of revised generating station emergency plan telephone directory GALLE,D.P. Commonwealth Edison Co. 82/08/12 43pp 15878,218 24X Fiche 50-000,82/10/08.8210290047
- 8210220358 Provides info re organization & performance of depts responsible for radiation protection activities, per 820702 commitment Training coordinator assigned in Apr 1982 to improve health physics training programs.

 TRAMM.T R Commonwealth Edison Co 82/10/14 DENTON.H R Office of Nuclear Reactor Regulation, Director 9pp 15776 287 24X Fiche 50-000,82/10/14,8210220358
- 8210250170 Advises that plans & preparedness for offsite protection near facility adequate & will be applied in event of radiological emergency IL. State & local plans approved sub; to verification of adequacy of alerting & notification sys THOMAS.L M Federal Emergency Hanagament Agency 82/10/14 DIRCKS,W J Dffce of the Executive Director for Operations ip 19788:285 24X Fiche 50-010,82/10/14,8210250170.
- O Adjudicatory correspondence
- 82:00:0257 Decision ALAB-695 affirming LBP-81-37 & LBP-82-65, sanctioning mod to OL for Unit 3 to permit installation of five high density spant fuel storage racks & authorizing issuence of amends to OLs.respectively.

 TOMPKINS.B A A Atomic Sefety and Licensing Appeal Panel 2pp 15574,056 24% Fiche: 50-237,82/09/29.82:00:10257

- P Operating license stage documents & correspondence
- 6210080001 Advises that board notification issued on 820703 re use of auxiliary overhead crame rather than main overhead crame to move spent fuel pool racks should have been issued w/Number 81-82-92 MIRAGLIA: F. Assistant Director for Safety Assessment 82/09/14 Atomic Safety and Licensing Board Panel 4pp 15668 341 24X Fiche 50-237, 82/09/14,8210080001
- --82i0080002 Board Notification 82-92 informs of util failure to tarry out fuel pool rack removal & installation in manner described in testimony at hearings Auxiliary overhead crane used instead of redundant main overhead crane IPPOLITO.T A Assistant Director for Safety Assessment 82/09/03 Atomic Safety and Licensing Board Panel 2pp 15668 345 24X Fiche 50-237.82/09/14.8210080001
- --B2092103B3 Recommends board notification re util use of auxiliary crane instead of main radundant crane to install fuel racks, as described in testimony before ASLB Licensee has committed to follow testimony in completing remaining work.

 IPPOLITO, T A Assistant Director for Bafety Assessment B2/09/03 EISENHUT.D Q Division of Licensing 2pp 1566B 349 24X Fichs 50-237.82/09/14.8210380001
- 6210120105 Requests delay of implementation due dates rm NUREQ-0737, Items II B 2. "Plant Shielding." II B 3, "Post-Accident Sampling" & II F 1 1, "Noble Oas Effluent Monitor " SHARTILE D Commonwealth Edison Co 82/10/04 EISENHUT, D 0 Division of Licensing Spp 15651 237 24% Fiche 50-000, 92/10/04, 8210120105
- 8210260526 Forwards Revision 3 of Chapter 9 of "Offsite Doze Calculation Manual" OLLDER, J C Commonwealth Edison Co 82/10/06 CASE, E 0 Office of Nuclear Reactor Regulation, Director 2pp 15805 137 24X Fiche 50-000.82/10/06
- --8210260542 Revision 3 of Chapter 9 of "Officite Dose Calculation Manual"

 * Commonwealth Edison Co 82/09/30 83pp 15805 139 24X Fiche 50-000.82/10/06.8210260526
- 8210kB0059 Provides addl guidance & clarification re 820806 request for addi info per NUREO-0737, Item II B 3, "Post-Accident Sampling Sys " Detailed reliability analysis not required to satisfy NRC concerns CRUTCHFIELD.D Operating Reactors Branch 5 82/10/08 DELQEOROS, L Companies of the Edison Co. Spp. 15720 004 24X Fiche 50-000, 82/10/08, 8210 180059.
- 82:0170680 Forwards safety evaluation of licensee 820414 & 0611 responses to NURSO-0737. Item II E 4 2. "Purge/Vent Valve Isolation Dependability " Responses acceptable Topic review completed CRUTCHFIELD. D Uperating Reactors Branch 5 82/10/13 DELOEORGE, L Commonwealth Edison Co 5pp 15739:192 24X Fiche-50-237, 82/10/13.8210190680
- 8210190445 Forwards supplemental response to Generic Ltr 82-05 re implementation status of NUREG-0737. Items II B 3.11 F 1 2, II F 1 5 & II F 1 6. In response to 821005 request SHARTZ.E D Commonwealth Edison Co 82/10/14. EISENHUT.D G Division of Licensing 5pp 15741 202. 24X Fichs 50-000.82/10/14. 8210170445
- 0210220335 Forwards info re NUREQ-0737, Item II D 1, "Performance Testing of BMR Safety/Relief Velves," per 620727 request.
 Info adequately damonstrates applicability of results of BMR owners group generic test rept NEDE-24988-P to facility SMARTZ.E D Commonwealth Edison Co. 82/10/15 EISENHUT, D 0. Division of Licensing 17pp 13776 Gii 24% Fiche 50-237,82/10/15,8210220335
- 8210250155 Forwards corrections to proposed Tech Spec Pages 1, 2/2, 2-1 & 3 3/4 3-5. supporting review of future reloads & revised Figure 3 5 1, Bheet I. providing extended MAPLHOR vs. exposure curves for barrier laed test assembly fuel RAUSCH: T. J. Commonwealth Edison Co. 82/10/18 DENTON: H. R. Defice of Nuclear Reactor Regulation. Director 2pp 15788, 233 24X Fiche: 30-000, 82/10/18, 8210250155
- --8210250177 Errate & Addenda Sheet 8, replacing Page 4-10 to "LOCA Analysis Rept for Dresden Units 2 & 3 & Guad Cities 1 & 2 Nuclear Power Stations"

 " General Electric Co NEDO-24146A ERR 08, 82/09/30 3pp, 15788-239, 24X Fiche.50-000,82/10/18:8210250155

- 8210250069 Provides addl info re reactor water cleanup room area ter; monitors Temp elements cause no automatic plant response beyond control room alarms RAUSCH T J Commonwealth Edison Co 82/10/19 EIGENHUT, D O Division of Licensing 2pp 15787 081 24X Fiche 50-000, 82/10/19 8210250069
- B210260296 Forwards safety evaluation of BMR owners group generic response to NUREO-0737. Item II K 3 25, "Effect of Loss of AC Power on Pump Seals " No mods to seal cooling for retirculation pumps required Item resolved CRUTCHFIELD. D Operating Reactors Branch 5 82/10/21 DC(QF4)25. Commonwealth Edison Co 7pp 15803 018 24X Fishe 50-2J7. B2/10/21, B210260296
- O Inspection reports. IE Bulletine & correspondence
- n-8210060335 IE Insp Repts 50-010/82-02,50-237/82-03 & 50 249/82 C1 c 820119-0218 No moncompliance noted Hajor areas inspected open & unresolved items & items of noncompliance reintegrated leak rate test rest REIMANN.F W. Region 3, Office of Director JACKIW, 1 N. Division of Engineering & Technical Programs 82/09/21 Jpp 1565 5): 24X Fichs 50-010.82/09/22.8210060329
- 8210150523 Forwards IE Insp Repts 50-010/82-13,50-237/82 1/ 1 50-249/82-18 on 820708-0809 % notice of violation STREETER, J F Division of Project % Resident Programs (ht/04/13 REED, C Commponesalth Edison Co 2pp 15713 099 24x Fiche 50-010,82/09/28,8210150523
- --B210150530 Notice of violation from insp on B20708-0009 STREETER, J.F. Division of Project & Resident Program, (D2767), 1 (p. 15713-10) 24% Fiche 50-010,82/09/28,8210100529
- --B21015053B IE Insp Repts 50-010/82-13,50-237/82-17 % 50 244/ft la 820708-0809 Noncompliance noted failure to issue & performatir pressure test procedure TONOUE,T M , JORDAN,M J , WALKER,R D Division of Project & Resident Programs 82/09/28 dpp 15713 102 24x Ffchs 50-010,82/09/28,8210155523
- 82100A0359 Ack receipt of 820910 itr informing NRC of steps team to correct violations noted in IE Insp Repts 50-237/81-19. 50-249/81-23.50-254/81-23.50-254/81-23.50-257/81-11 to 50-304/81-29. SPESSARD, R L Division of Project & Resident Programs DJ/EC/21 REED, C Commonwealth Edison Co in 15418 334 24x Fiche 50-004, 82/10/01/8210080359
- ~-8210060367 Responds to NRC 820712 Itr re-violations united in thi Repts 50-237/81-39, 50-249/81-32, 50-294/81-23, 50-26/811 2 1 50-295/81-31 & 50-304/81-29 Corrective actions training for mpt priorities re-plant availability will be conducted REED, C. Commonwealth Edison Co. 82/09/10 KERPIER, J. Q. #13 3, Office of Director 13pp 15618 355 24X
- 8210080178 Forwards listing of piping sys which fell to meas bear requirements; per NRC 800818 confirmatory action ltr If Bulietin 79-14 operability evaluation updates will not be provided for Dresden & Guad Cities Final update by Det \$46,2 RAUSCNLT J Commonwealth Edison Co 82/10/01 ΚΕΓΡΙΙΚ ; C 3, Office of Director 6pp 15640 159 24X Fichs \$0 Oc. 5 82×18210080178
- 8210150539 Forwards IE Insp Repts 50-010/82-15.50-237/82-19 t 50-249/82-20 on B20830-0903 No noncompliance noted PAPERIELLOC J Division of Emergency Properedness to Operation Support 82/10/01. REED, C. Commonwealth Edison Co Type 15714.175 24X Fiche 50-010.82/10/01.8210150539
- --8210150543 IE Insp Repts 50-010/82-15, 50-237/82-19 & 50 247/8: 820830-0903 & 09 No noncompliance noted Hajor areas inspected confirmatory measurements program QC program for analytical measurements to environ monitoring program SCHUMACHER, H.C., NICHOLSON, N.A., JANUSKA, A.O. Division of Emergency Preparedness & Operational Support 82/09/200 15714-177. 24X Fiche 50-010, 82/10/01, 8210150539
- 8210080190 Confirms 821103 anforcement conference at Region 3 a aspects associated w/procurement, installation & use of non-qualified valve guides in electromagnetic relief values at facilities.

 9PEBSARD.R.L. Division of Project & Resident Programs REED, C. Commonwealth Edison Co ip 15640:191, 24g Fiche, 30~000, 82/10/04, 8210080190

- 8208190233 IE Info Notice 80-35, Suppl 1, "Leaking & Dislodged I-125 Implant Seeds " Svc list encl CD8B.L I Division of Fuel Facilities, Materials & Safeguards 82/10/06 Consolidated Edison Co of New York 66pp 15761 250 24x Fiche 50-000, 62/10/06, 6208190233
- 8208190238 le Bulletin 82-03, "Stress Corposion Cracking in Thick-Wall, Large-Diameter, Stainless Steel, Recirculation Sys Piping at BMR Plants "Svc list encl DEYOUMO.R C Director's Office. Office of Inspection and Enforcement B2/10/14 Consolidated Edison Co of New York 115pp 15810 125 24x Fiche 50-000.82/10/14.8208190238
- R Periodic operating reports & related correspondence
- G210180097 Forwards monthly operating repts for Sept 1982 SCOTT.D J Commonwealth Edison Co 82/10/01 Director's Office. Office of Inspection and Enforcement ip 19718 001 24X Fiche 50-010.82/10/01.8210180097
- ~-8210180100 Monthly operating repts for Sept 1782 SCHRUEDER, B. A. Commonwealth Edison Co. 82/10/01 22pp 15718 002 24X Fiche 50-010, 82/10/01,8210180097
- S Reportable occurrences, LERs & related correspondence
- ©210150097 Forwards LER 81-026/03L-0 SCOTT, D J Commonwealth Edison Co 81/10/13 KEPPLER, J Q Regio 3, Chicago, Office of the Director (81/03/01) 1p 15701 182 24 Fiche 50-249, 81/10/13,8210150097
- --8210150102 LER 81-026/03L-0 on 810915, while shutting down rod P-10 should wrong position on rod worth minimizer Caused by several diode failures on two digital output printed circuit boards Boards removed, repaired & tested satisfactorily SCHROEDER, B. Commonwealth Edison Co. 81/07/27 Region 3, Chicago, Office of the Director (81/03/01) 2pp 15701 183 24X Fiche 50-249, 81/10/13, 8210150097
- E310270251 Forwards LER 81-040/01T-0 ECOTT.D J Commonwealth Edison Co 81/12/15 KEPPLER, J Q Region 3. Chicago, Office of the Director (81/03/01) 1p 15829 233 24X Fiche 50-249, 01/12/15,8210270251
- ---8210270254 LER Bi-040/01T-0 on Bi1201, when Rx pressure decreased to 32 psig.rad N-9 notched from position 02 to 04 & then to position 06 Cause unknown Mork request issued to check single notch control switch during next refueling outage SCHROEDER, B A Commonwealth Edison Co 81/12/07 Region 3, Chicago. Office of the Director (81/03/01) 3pp 15829 234 24X Fiche 50-249,81/12/15,8210270251
- --8210040127 LER 82-035/03L-0 on 820905 during testing of control rod drive H-4 for overtravel.overtravel alarm came up & position indication losts indication got control blade from drive Probably caused by inner filter becoming detached WMALEN.R Commonwealth Edison Co 82/09/16 Region 3, Office of Director 2pp 15381 208 24X Fiche 50-249,82/09/16,8210040126
- B210250306 Forwards updated LER 82-029/01X-1 SCOTT. D J Commonwealth Edison Co 82/09/22 KEPPLER, J O Region 3. Office of Director ip 15791 038 24X Fiche, 50-249, 82/09/22, 8210250306
- --8210250316 Updated LER 82-029/01X-1 on 820712, magnetrol switches 82C & 82D did not trip when tested for proper tripping upon water loading Cause not known Visual inspireview & waskly testing revealed no abnormalities Vendor review encl. WHALEN, R. Commonwealth Edison Co. 82/09/22, Region 3, Office of Director. 3pp. 15791 039 24X Fiche 50-249, 82/09/22, 8210250304
- 8210250328 Forwards updated LER 82-023/01X-1 8COTT, D J Commonwealth Edison Co 82/09/22 KEPPLER, J 0 Regio 3. Office of Director 1p 15790 082 24X Fiche 50-249,82/09/22, 8210250328
- --B210250348 Updated LER 82-023/01X-1 on B20510, no low power range monitor input to rod block monitor (RBM) noted during DDP 700-E3 Caused by shorted steering diodes on several RBM cards Defective diodes replaced MOROAN, W Commonwealth Edison Co 82/09/22 Region 3, Office of Director, 2pp 15790 083 24X Fiche 50-249,82/09/22,8210250328

- 8210130197 Forwards LER 82-034/03L-0 SCOTT.D J Commonwealth Edison Co 82/09/28 KEPPLER, J O Region J. Office of Director 1p 15674 117 24% Fiche 50-249,82/09/28, 8210130197
- --82i0i30201 LER 82-034/03L-0 on 82070L investigation revealed that substandard electromatic relief velve main valve disc guide sleeve utilized on ERV 3-203-3C Caused by personnel error in ordering sleeve Sleeve will be replaced HOLLAND. P. Commonwealth Edison Co. 82/09/28 Region 3. Office of Director 2pp 15674 118 24X Fiche 50-249.82/09/28. B210130197
- 8210190458 Forwards LER 82-036/03L-0 SCOTT,D J Commonwealth Edison Co 82/10/05 KEPPLER,J Q Region 3. Office of Director 1p 15735 319 24X Fiche 50-249,82/10/05, 6210190458
- --B210190471 LER 82-036/03L-0 on B20912, during startup at 45% power, annunciator 903-5N-4 indicated turbine pressure operator load rejection & turbine stop valve scrams bypassed on one subchannel of Channel A half scram circuitry TURNOUEST. Commonwealth Edison Co 82/10/05 Region 3, Office of Director 2pp 15735 320 24% Fiche 50-249,82/10/05,8210190458
- 8210190403 Forwards LER 82-037/03L-0 SCOTT, D J Commonwealth Edison Co 82/10/06 KEPPLER, J Q Region 3. Office of Director 1p 15740 356 24% Fiche 50-249, 82/10/060
- --8210190412 LER 82-037/03L-0 on 820922, transient in-core probe ball valve 3E would not reclose Caused by loss of tension in high tension spring in drive mechanism Valve closed & spring retensioned MOROAN.W Commonwealth Edison Co 82/10/06 Region 3, Office of Director 2pp 15740 357 24X Fiche 50-249,82/10/06,8210190403
- DOCKET 50-250 TURKEY POINT PLANT, UNIT 3
- F Security, medical, emergency & fire protection plans
- 8209170062 Forwards Revision 6 to physical security plan Revision withheld (ref 100FR73 21)
 UHRIO.R.E Florida Power & Light Co 82/09/08 EISENHUT, D & Division of Licensing 2pp 14910 069 24X Fiche 50-250, 82/09/08, 8209170062
- 8210190178 Releases public version of emergency plan implementing procedure FELTON, J M Division of Rules and Records 82/09/30, Document Management Branch 1p 15758 062 24X Fiche 50-250,82/09/30,8210190178
- --B21019018A Forwards public version of Emergency Plan Implementing Procedures 20104. "Emergency Roster," 20101. "Duties of Emergency Coordinator." 20107. "Fire/Explosion Emergencies" & 20127 "Duties of Assembly Area Bupervisor" UHRIO, R E Florida Power & Light Co. 82/09/24 0'REILLY, J P. Repion 2. Office of Director ip. 15758.063. 24X Fichs 50-250,82/09/30.8210190178
- --B210190194 Public version of Emergency Plan Implementing Procedures 20101. "Duties of Emergency Coordinator." 20104. "Emergency Roster." 20107. "Fire/Explosion Emergencies" & 20127. "Duties of Assembly Area Supervisor."

 > Fiorida Pawer & Light Co. 82/09/16. 50pp. 15758:064 24X Fiche 50-250.82/09/30.8210190178
- 8210190440 Extends invitation to observe 821019 demonstration of emergency response sys at Technology for Energy Corp. Knoxville. TN
 UHRIO.R E Floride Power & Light Co. 82/10/12 EISENHUT, D. G.
 Division of Licensing is 15741:186. 24X Fiche 50-000.82/10/12, 8210190440
- 8210250244 Forwards revisions to physical security plan, Revisions withhold (ref 10CFR73 21)

 KAMMER, D. 8 Tennessee Valley Authority 82/10/19 DENTON, H R

 Office of Nuclear Reactor Regulation, Director, 1p 15788, 345, 24X

 Fiche 50-250, 82/10/19, 8210250244
- 8210280291 Forwards Revision 1 to 10CFR30 App R fire protection review Revision corrects typographical errors in 820701 submittal UHRIO,R E. Floride Power & Light Co 82/10/22 EISENHUT,D, O Division of Licensing. 1p 13838/080, 24% Fiche 50-250,82/10/22,8210280291.

1 '

1

116 1

- --8210280293 Revision 1 to 10CFR50 App R fire protection review 4 Fibrida Power & Light Co 82/10/22 63gp 15838 CB1 24X 4 Fiorida Power & Light Co 82. Fiche 50-250, 82/10/22, 8210280271
- P Operating license stage documents & correspondence
- 8210070007 Responds to FOIA request for eight categories of records re steam generators & steam turbines App A documents provided in R Udell FOIA Request 81-313 Forwards documents listed in App B FELTON, J H FELTON, J.H. Division of Rules and Records 82/08/10 LONG, D.J. Winthrop, Stimson, Putnam & Roberts 9pp 15445 063 24X Fiche 50-000, 82/08/10, 8210070007
- 8210120521 Summary of exit interview following 820713-19 audit of pressurized thermal shock in-plant training programs & operating procedures
 GROTENHUIS, M Operating Reactors Branch 1 82/09/15 Operat
 Reactors Branch 1 5pp 15672 261 24X Fiche 50-250,82/09/15.
- 8210280013 Responds to FOIA request for all internal non-public documents remos, evaluation repts & other mati dealing w/ nuclear plant operations Forwards documents listed in App A FELTON J M Division of Rules and Records 82/09/17 MCINNIS D News & Observer Spp 15860 045 24X Fiche 50-000, 82/07/17.
- --8208310034 Forwards draft info notice re deficiencies in air filtration & ventilation sys Notice based on radioactive resin release at Pilgrim 1 & on four related events at other plants involving deficiencies in maint & tasting of filter eys MATTBON.R J Division of Systems Integration (post 81005) 82/08/05 JURDAN.E L Division of Engineering & Quality Assurance. 3pp 15861.024 24X Fiche 50-000.82/09/17.8210280013
- --82t0280100 Notifies that on 820224.C Alderson advised that rept sent re possible willful violation of reporting requirements & falsification of QA & guard qualification records at facilities
 REGNER, M E Office of Inspector & Auditor 82/03/01 Office Inspector & Auditor 1p 15861 037 24% Pichs 50-000,82/09/17. 8210280013
- 8210050589 Requests submittal of fees for 820505 request for Tech Spec clouddown requests summitted of feet for excellent request for sechanges red egnaded grid voltage & 820810 request for approval of mods to turbine runback sys
 BIOOS:R M License fee Management Branch 82/09/23 UHRIO. R.E
 Florida Power & Light Go ip 15626 290 24x Fiche 50-250, 82/09/23.8210050589
- 8210010292 Forwards response to NRC 920219 ltr requesting addl info re-anviron qualification of TMI action (tems contained in NUREO-0737 NUREG-0737 UHRÎG.R.E. Florida Power & Light Co. 82/09/24 VAR Operating Reactors Branch | 56pp 15573 125 24X Fiche: 50-250: 82/09/24:8210010292 VARGA, S. A.
- 8210060281 Forwards revised schedule for providing final response recontrol of heavy loads on Quideline 4 (special lifting devices) & Ouideline 7 (crans design) Only manufacturers can obtain requested info URRIGRE Florida Power & Light Co. 82/09/30, VARQA, 8 A. Operating Reactors Branch i. 2pp. 15621.162, 24X Fiche: 50-250.88/09/30,8810060281,
- 8210150407 Revised application for Amends 87 & 81 to Licenses DPR-91 & DPR-41, respectively, correcting typographical errors re DHR
- --8210150413 Gorrected pages to Tech Specs re DNR sys, replacing pages in 801230 submittal.

 * Florida Power & Light Co 82/10/11, 2pp, 15704.026 24X Fiche: 50-250.82/10/11.8210150407.
- B210150439 Advises that review of current status of nuclear power plant staff working hours par Generic Ltr B2-22 indicates requirements adequately enforced by incorporation in administrative procedures Amend to Tech Sect unnecessary. UMRIO,R.E. Florida Power & Light Co. 82/10/12, EISENHUT.D.Q. Division of Licensing. ip. 18705-004, 24X Fiche.50-250,82/10/12, 9210150439.
- GRIO190559 Forwards payment of proposed license amend fee re-redundancy in RHR sys. UHR10.R.E. Florida Fower & Light Co. 82/10/12. MILLER, W. C. License Fee Management Branch. 2pp. 15735:014. 24X Fiche: 50-250. 82/10/12.8210190559.

- B210270253 Forwards util B21012 ltr containing payment of license are: fee re redundancy in RHR sys requested in NRC B20816 ltr UHRIO.R E Florida Power & Light Co 82/10/21 DIGGS.R M License Fee Management Branch 1p 15828 278 24X Fiche 50-250.82/10/21. 8210270253
- Q Inspection reports. IE Bulletins & correspondence
- 8210070007 Responds to FDIA request for eight categories of records re steam generators & steam turbines App A documents provided in R_Udell FDIA Request 81-313 Forwards documents listed in FELTON.J M Division of Rules and Records 82/08/10 Winthrop, Stimson, Putnam & Roberts 9pp 15645 063 Fiche 50-000, 82/08/10,8210070007 LONG, D.J.
- --8210070137 Forwards tabulated data on steam generator insp & maint at facilities Data should be provided to licensess IPPOLITO.Y Operating Reactors Assessment Branch 82/04/01 VARRA, 8 Operating Reactors Branch 1 5pp 15645 131 24X Fichs 50-000,82/08/10,8210070007
- --B210070172 Forwards info re steam generator integrity & inspi at all ALOU/OI/X Forwards info re steam generator integrity & insp. at a operating PHRs, per 750320 & 21 requests Details of insps. including defect indications, tube plugging criteria & tube, plugged will not be provided except for Point Beach 1 QULLER, K R Division of Reactor Licensing (NRR-1975 only) 75/03/24 MACCARY, R Division of Technical Review (NRR-1975 only) 5pp 15645 196 24X Fiche 50-000, 82/08/10, 8210070007
- B210010316 Ack receipt of 820825 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-250/82-24 & 50-231/82-24 DANCE H C Division of Project & Resident Programs 02/09/13 UHRIO, R E Florida Power & Light Co 1p 15568 224 24x Fiche 30-250, 82/09/13, 8210010316
- --8210010321 Responds to NRC 820726 itr re violations noted in 1t 1*4, Repts 50-250/82-24 & 50-251/82-24 Corrective actions plant manager discussed need for increased control of activities affecting fire barrier penetrations w/const personnel UHRIG,R E Florida Power & Light Co 82/08/25 0/REILLY, J P Region 2. Office of Director 3pp 15568 225 24% Fiche 50-250.82/09/13.8210010316
- --8210010329 Forwards IE Insp Repts 50-250/82-24 & 50-251/82 24 on 820526-0625 & notice of violation LEMIS.R C Division of Project & Resident Programs 82/07/26 UHRIG.R E. Florida Power & Light Co 2pp 15568 228 24x Fiche 50-250.82/09/13.8210010316
- --9210010338 Notice of violation from insp on 820326-0625 LEWIS.R C Division of Project & Resident Programs 6 2pp 15568 230 24X Fiche, 50-250, 82/07/13,8210010316 02/07/25
- --8210010346 IE Insp Repts 50-250/82-24 & 50-251/82-24 on 820526 0431 Noncompliance noted inadequate corrective action allowed recurrence of reportable condition re failure to adhere to
- 8208190203 IE Info Notice 80~35, Suppl 1, "Leaking & Dislodged 1-125 Implant Seeds " Svc list encl COBB.C. I. Division of Fuel Facilities, Materials & Safeguards 82/10/06 Consolidated Edison Co of New York 64pp 15761 27 82/10/06 Consolidated Edison Co of New York &App 157&1 371 24X Fiche, 50-000, 82/10/06, 8208190233
- 8210220296 Ack receipt of 820927 itr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-250/82-80 & SO-751/782-28

 BO-751/782-28

 LEWIE R C. Division of Project & Resident Programs 82/10/08

 UHR10-R E Florida Power & Light Co 1p 15776 093 24x

 Fiche: 50-250, 82/10/08: 8210220296
- ---8210220304 Responds to NRC 820826 ltr re violations noted in 16 Irm Repts 50-280/82-28 & 50-281/82-28 Corrective actions access log established to control access to high radiation areas Alarm sys installed on Unit 3 RMR pit access gate UHRIGAR.E. Florida Power & Light Co. 82/09/27 O'REILLY.J FRegion 2. Office of Director 2pp. 13776-094. 24X Fiche.50-230,82/10/08.8210220296
- --8210220310 Forwards IE Insp Repts 50-250/82-28 & 50-251/82-28 es 820626-0725 & notice of violation.

 LEWIS.R.G. Division of Project & Resident Programs 82/08/24

 UHRIO.R E Floride Power & Light Co. 2pp 15776-096 24x

 Ficha: 50-250,82/10/08,8210220296
- --8210220317 Notice of violation from insp on 820626-0728 * Division of Project & Resident Programs. 82/08/26 15776: 098. 24% Ficher 50-250, 82/10/08, 8210220296 82/08/26 19

- --8210220329 IE Insp Repts 50-250/82-28 & 50-251/82-28 on 820626-0725 Noncompliance noted on 820701, ground level gates to Unit 4 RHR pit stairways.surveyed at dose rates exceeding 1,000, found open & unattended VGOT-LOMELL, R. JULIAN. C Division of Project & Resident Programs 82/08/24 Spp 15776 099 24% Fitche 50-250,82/10/08,8210220296
- 8210190356 Advises that util review of current nuclear plant staff working hours indicates that overtime restrictions meet intent of revised NRC policy Requirements incorporated in administrative procedures & need not be added to Tech Specs UHRIO.R E Florida Power & Light Co 82/10/12 EISENHUT.D O Division of Licensing 1p 15742 111 24X Fiche 50-250,82/10/12,8210190351
- 8208190238 IE Bulletin 82-03, "Stress Corrosion Cracking in Thick-Mall. Large-Diameter. Stainless Steel. Recirculation Sys Piping at BHR Plants " Svc list encl DEYOUND.R C Director's Office. Office of Inspection and Enforcement 82/10/14 Consolidated Edison Co of New York 115pp. 15810 125 24X Fiche 50-000.82/10/14.8208190238
- S Reportable occurrences, LERs & related correspondence
- 8210080104 Forwards "Engineering Evaluation of Feedwater Transient & Sys Pipe Break at Turkey Point Unit 3 on 801119," in response to request re Congressmen DB Fascell 810129 ltr MICHELSON.C Director's Office 81/03/02 REHM.T A Office of the Executive Director for Operatione 1p 15670 001 24X Fiche 50-250.81/03/02/28210080104
- 0210090252 Forwards LER 82-012/01T-0 WILLIAMS.J W Florida Power & Light Co 82/10/01 O'REILLY.J P Region 2. Office of Director p 15638 112 24X Fiche: 50-250, 82/10/01, 8210080252
- --8210080287 LER 82-012/017-0 on 820917, insp revealed that electrical penetration did not meet double barrier criteria of 10CFR50 & testability requirements of App J Causad by failure to properly document plant changes Plant change implemented PACE, P L Florida Power & Light Co 82/10/01 Region 2, Office of Director 3pp 15438 113 24X Fiche 50-250,82/10/01,
- 8210260116 Forwards LER 82-013/03L-0 WILLIAMB.JW Florida Power & Light Co 82/10/18 O'REILLY.J P Region 2. Office of Director 1p 15799 105. 24X Fiche 50-250, 82/10/18, 8210260116
- --8210240117 LER 82-013/03L-0 on 820917.steam turbine pressure control valve CV-3707 did not close completely, resulting in poor pressure & cauxing safety relief valve to trip auxiliary feedwater pump C Caused by foreign matter under valve seat PACE.P.L. Fiorida Power & Light Co 82/10/18 Region 2. Office of Director 3pp 15799 106 24X Fiche.50-250.82/10/18, 8210240114

DOCKET 50-251 TURKEY POINT PLANT, UNIT 4

- F Security, medical, emergency & fire protection plans
- 8209170052 Forwards Revision 6 to physical sacurity plan Revision withheld (ref 10CFR73 21) UHRIO, R E Florida Power & Light Co 82/07/08. EIRENHUT, D 9 Division of Licensing 2pp 14910,069 24X Fiche 50-250,82/09/08,8209170062
- 8210190178 Releases public version of emergency plan implamenting procedure FELTON.J M Division of Rules and Records, 82/09/30. Pocument Management Branch ip 15758 062 24X Fiche, 50-230, 82/09/30, 8210190178
- --9210190186 Forwards public version of Emergency Plan Implementing Procedures 20104, "Emergency Roster," 20101, "Duties of Emergency Coordinator," 20107, "Fire/Explosion Emergencies" & 20127 "Duties of Assembly Area Supervisor" UHRIO: R E Florida Power & Light Co 82/09/24 O'REILLY, J P. Region 2. Office of Director ip 15758 063 24X Fiche. 50-250.82/09/30.8210190178.
- --8210190194 Public version of Emergency Flan Implementing Procedures 20101, "Duties of Emergency Coordinator," 20104, "Emergency Roster," 20107, "Fire-Explosion Emergencies" & 20127, "Duties of Assembly Area Supervisor"

 # Florida Power & Light Co 82/09/30 50pp 15758-064 24X
 Fiche 50-250, 82/09/30, 8210190178

- 8210190440 Extends invitation to observe 821019 demonstration of amergency response sys at Technology for Energy Corp. Knoxville, TN UHRIO, R E Florida Power & Light Co 82/10/12 EISENHUT, D 0 Division of Licensing 1p 15741 186 24X Fiche 50-000, 82/10/12, 82/10190440
- 8210280291 Forwards Revision 1 to 10CFR50 App R fire protection review Revision corrects typographical errors in 820701 submittel UHR10.R E Floride Power & Light Co 82/10/22 EISENHUT.D Q Division of Licensing 1p 15838 080 24X Fiche 50-250,82/10/22,8210280291
- --8210280293 Revision 1 to 10CFR50 App R fire protection review * Florida Power & Light Co 82/10/22 63pp (5838 081 24X Fiche 50-250,82/10/22,8210280291
- P Operating license stage documents & correspondence
- 8210070007 Responds to FOIA request for eight categories of records re steam generators & steam turbines App A documents provided in R Udell FOIA Request 81-313 Forwards documents listed in App B FELTON J M Division of Rules and Records 82/08/10 LONG, D J Winthrop, Stimson. Putnam & Roberts 9pp 19645 063 24X Fiche 50-000, 82/08/10, 8210070007
- 8210280013 Responds to FOIA request for all internal non-public documents memos, evaluation repts & other matl dealing w/ nuclear plant operations Forwards documents listed in App A FELTON. J M Division of Rules and Records 82/09/17 McINNIS. D News & Observer 5pp 15860 065 24X Fiche 50-000.82/09/17. 8210280013
- --8210280100 Notifies that on BR0224.C Alderson advised that rept sent reposible willful violation of reporting requirements & falsification of GA & guard qualification records at facilities

 RESHER, H E Office of Inspector & Auditor 82/03/01 Office of Inspector & Auditor 82/03/01 Office of Selection & Auditor 82/03/01 Office of
- 8210050589 Requests submittal of fees for 820606 request for Tech Spec changes re degraded grid voltage & 820810 request for approval of mode to turbine runback sys
 D1008.R M License Fee Management Branch 82/09/23 UHRIO.R E
 Florida Power & Light Co 1p 15626 290 24X Fiche 50-250. 82/09/23,8210030589
- 8210010292 Forwards response to NRC 820219 ltr requesting addl info re environ qualification of TMI action (tems contained in NURCO-0737 UHRIO,R.E Florida Power & Light Co 82/09/24 VARCA,S A Operating Reactors Branch 1 56pp 15573 125 24X Fiche 30-250,82/09/24,8210010292
- B2100602Bi Forwards revised schedule for providing final response recontrol of heavy loads on Guideline 4 (special lifting devices) & Guideline 7 (crane design) Only manufacturers can obtain requested info UHRIO.R E Florida Power & Light Co B2/09/30 VARGA.8 A Operating Reactors Branch 1 2pp 15621 162 24X Fiche 30-250,82/09/30,8210060281
- 8210150407 Revised application for Amends 87 & 81 to Licenses DPR-31 & DPR-41: respectively, correcting typographical errors re DHR sys

 UHRIO,R E Florida Power & Light Co 82/10/11 EISENHUT, D 0

 Division of Licensing 1p 15704 025 24X Fiche 50-250,82/10/11.
 8210150407
- --8210150413 Corrected pages to Tech Specs re DHR systreplacing pages in 801230 submittal * Floride Power & Light Co 82/10/11 2pp 15704 026 24X Fiche 50-250.82/10/11.8210150407.
- B210150439 Advises that review of current status of nuclear power plant staff working hours per Ceneric Ltr B2-22 indicates requirements adequately enforced by incorporation in administrative procedures Amend to Tech B
- 8210190559 Forwards payment of proposed license amend fee re redundancy in RHR sys.
 UHRIG:R E. Florida Power & Light Co 82/10/12 HILLER:W O License Fee Managament Branch 2pp 15735 014 24X Fiche. 50-250, 82/10/12, 8210190559

- 8210220090 Advises that procedures/plans submitted for Unit 3 for steam generator repair project apply to Unit 4 & need not be resubmitted UHRIO, R E Fiorida Power & Light Co 82/50/15 EISENHUT.D C Division of Licensing ip 15778 183 24% Fiche 50-251,82/10/15, R210220090
- B210270253 Forwards util B21012 ltr containing payment of license amend fee re redundancy in RMR sys requested in NRC 920816 ltr UHRIO.R E Florida Fower & Light Co B2/10/21 DIGGS,R M License Fee Management Branch ip 15828 278 24X Fiche 50-250, 82/10/21, 8210270253
- Q Inspection reports, IE Builetins & correspondence
- 8210070007 Responds to FOIA request for eight categories of records resteam generators & steam turbines App A documents provided in R Udell FOIA Request 81-313 Forwards documents listed in App B FELTON, J K Division of Rules and Records 82/08/10 LONG, D J Winthrop, Stimson, Putnam & Roberts 9pp 15445 083 24X Fiche 50-000,82/08/10,8210070007
- --8210070139 Forwards tabulated data on steam generator insp & maint at facilities Data should be provided to licensess [PPOLITO.T Operating Reactors Assessment Branch 82/04/01 VAROA.S Operating Reactors of Branch 1 5pp 19645 131 24X Fiche 50-000.82/08/10.8210070007
- --8210070172 Forwards info re steam generator integrity & insps at all operating PHRs, per 750320 & 21 requests Details of insps, including defect indications, tube plugging criteria & tubes plugged will not be provided except for Point Beach i GOLLER, K.R. Division of Reactor Licensing (MRR-1975 only) 75/03/24 MACCARY, R.R. Division of Technical Review (MRR-1975 only) 5pp 15645 196 24X Fiche 50-000,82/08/10,8210070007
- 8210010316 Ack receipt of 820825 ltr informing NRC of steps taken to correct violations noted in EE Insp Repts 50-250/82-24 & 50-251/82-24 DANCE.H C Division of Project & Resident Programs 82/09/13 UHRIG.R E Florida Power & Light Co ip 19568 224 24X Fiche 30-250, 82/09/13.8210010316
- --8210010321 Responds to NRC 820726 ltr re violations noted in 1E Insp Repts 50-250/82-24 & 50-251/82-24 Corrective actions plant manager discussed need for increased control of activities affecting fire barrier penetrations w/const personnel UHRIG.R & Florida Power & Light Co 82/08/25 0'REILLY, J P Region 2. Office of Director 3pp 18568 225 24X Fiche 50-250,82/09/13.8210010316
- --8210010329 Forwards IE Insp Repts 50-250/82-24 & 50-251/82-24 on 820524-0625 & notice of violation LEWIS,R C Division of Project & Resident Programs 82/07/24 UMRIG.R E Florida Power & Light Co 2pp 15568 228 24% Fiche 50-250,82/09/13.8210010316
- --B2:001033B Notice of violation from insp on 820526-0625 LEMIS.R C Division of Project & Resident Programs 82/07/26 2pp 15568 230 24% Fiche 50-250.82/09/13:8210010316
- --8210010346 IE Insp Repts 50-250/82-24 & 50-251/82-24 on 820326-0625 Noncompliance noted inadequate corrective action allowed recurrence of reportable condition re failure to adhere to radiation work permit VOOT-LOWELL, R. JULIAN.C Division of Project & Resident Programs 82/07/26 App 15568 232 24X Fichs 50-250.82/09/13,8210010316
- 8208190233 IE Info Notice 80-35, Suppl 1, "Leaking & Dislodged I-125 Implant Seeds " Syc list encl COBBL 1 Division of Fuel Facilities, Materials & Safeguards 82/10/06 Consolidated Edison Co of New York 66pp 15761 250 24X Fichs 50-000,82/10/06.8208190233
- 8210220276 Ack receipt of 820727 ltr informing NRC of steps taken to correct violations noted in IE lnsp Repts 50-250/82-80 & 50-251/82-28 LEMIS.R C Division of Project & Resident Programs 82/10/08 UHR10.R E Florada Power & Light Co 1p 15776 073 24X Fiche 50-250.82/10/08/8210220276
- --B210220304 Responds to NRC 820826 ltr re violations noted in IE Insp. Repts 50-250/82-28 & 50-251/82-28 Corrective actions access log established to control access to high radiation areas Alarm sys (natailed on Unit 3 RMR pit access gate UMRIG.R E Florida Pover & Light Co 82/07/27 G'REILLY, J P. Region 2. Office of Director 2pp 13776 094 24X Fiche 50-250.82/10/08.8210220296

- --8210220310 Forwards IE Insp Repts 50-250/82-28 & 50-251/82-28 on 820626-0725 & notice of violation LEMB.R C Division of Project & Resident Programs 82/08/26 UHRIO.R E Florida Power & Light Co 2pp 15776 096 24X Fichs 50-250,82/10/08.8210220296
- --8210220317 Notice of violation from insp on 820626-0725 * Division of Project & Resident Programs 82/08/26 lp 15776 098 24% Fichs 50-250, 82/10/08.8210220296
- --B210220329 IE Insp Repts 50-250/82-28 & 50-251/82-28 on B20626-0725
 Noncompitance noted on S20701, ground level gates to Unit 4
 RHR pit stairways: surveyed at dose rates exceeding 1,000,
 found open & unattended
 YUOT-LOHELL, R. JULIAN, C Division of Project & Resident Programs
 B2/0B/24 5pp 15776 099 24X Fiche 50-250,82/10/08,8210220296
- 8210190351 Advises that util review of current nuclear plant staff working hours indicates that overtime restrictions meet intent of revised NRC policy Requirements incorporated in administrative procedures & need not be added to Tech Specs URRIG, R E Florida Power & Light Co 82/10/12 EISENHAY,D Q Division of Licensing ip 15742 iii 24X Fiche:50-250,82/10/12,871087351
- 9208190238 IE Bulletin 92-03, "Btress Corrosion Cracking in Thick-Wall, Large-Diameter, Stainless Steel, Recirculation Bys Piping at BMR Plants " Svc list encl DEYGUNG, R C Director's Office, Office of Inspection and Enforcement 92/10/14 Cansolidated Edison Co of New York 1/5pp 1/5810 125 24X Fithe 50-000, 82/10/14, 8208190238
- S Reportable occurrences. LERs & related correspondence
- 8209210425 Responds to FDIA request for eight categories of LERs Forwards documents listed in App A FELTON. J H Division of Rules and Records 82/08/20 ARNOLD. J Miami Herald 3pp 14946 262 24X Fiche 50-000,82/08/20,
- --B209210527 Forwards draft FR notice re AD pressure transients during shutdown at nuclear power plant for approval DIRCKS.W J Office of the Executive Director for Operations B2/07/29 CHILK.S J Office of the Bacretary of the Commission 11pp 14946 353 24X Fiche 50-000.82/08/20.8209210425
- 6210270083 Add1 response to FOIA request for eight categories of LHs Forwards documents listed in App A App B documents withheld tref FOIA Exemption 5)
 FELTON.J M Division of Rules and Records 82/09/20 ARNOLD.J Miami Herald 4pp 15836 221 24X Fiche 50-251.82/09/20, 6210270083
- --8210270096 Concurs w/draft Commission paper proposing facility low temp overpressure event as AD DENTON, H.R. Office of Nuclear Reactor Regulation. Director 81/06/16 MICHELSON.C Director's Office 2pp 15836 270 24x Fich
- --8206240119 Requests approval of AO determination on pressure transfe while unit shutdown in preparation for startup DIRCKS, W J Office of the Executive Director for Operations SECY-62-255 82/06/17 10pp 15836 272 24X Fiche 50-251, 82/09/20, 8210270083
- 8210060209 Forwards LER 82-013/03L-0 HILLIAMB.J W Fiorata Power & Light Co 82/10/01 O'REILLY,J P Region 2. Office of Director 1p 13614 043. 24X Fich: 50-231.82/10/01.8210060209
- 8210190376 PND-II-82-107 on 821010, unit shut down for scheduled refueling & maint for 6 months. All three steam generators will be replaced Licensee plans news release.
 LANDIS, K D , JULIAN, C A Region 2, Office of Director 82/10/12 15 15740:315 24X Fiche 50-251,82/10/12,8210190376

- DOCKET 50-254 QUAD-CITIES STATION. UNIT 1
- F Security, medical, emergency & fire protection plans
- 8-109290125 Releases public version of revised generating station emergency plan corporate command ctr emergency plan implementing procedure FELTON J H Division of Rules and Records 82/09/16 Document Hanagement Branch 1p 15564-122 24X Fiche 50-000.82/09/16.
- --8209290189 Forwards public version of Revision 4 to generating station evergency plan corporate command ctr Emergency Plan Implementing Procedure EOF-3, "Environ/Emergency Coordinator" Receipt form encl PAJOUSKI, J E Commonwealth Edison Co 82/09/01 DENTON, H R NRC No Detailed Affiliation Given 1p 15564 123 24X Fiche 50-000,82/09/16,8209290125
- --8209290225 Public version of Revision 4 to generating station energency plan corporate command ctr emergency plan Inplementing Procedure EDF-3, "Environ/Emergency Coordinator"

 PAJUHSKI, J E Commonwealth Edison Co B2/08/31 11pp 15544 124 24X Fiche 50-000, 82/09/16, 8209290125
- E210010009 Forwards info to suppl 820701 request for exemption from App R per 820917 teicon Request applies to Sections III 9 2 a & III 6 3 b re installation of fire suppression sys RAUSCH, T J Commonwealth Edison Co 82709723 EISENHUT, D 9 Division of Licensing 8pp 15565 152 24X Fiche 50-000,82/09/23,8210010009
- G210120546 Releases public version of rovised cover sheet to facility procedures
 FELTON.J M Division of Rules and Records 82/09/24 Document Hanagement Branch 1p 15672 219 24X Fiche 50-254,82/09/24,8210120546
- --0210120551 Forwards public version of revision cover sheet to facility procedures Completion of encl checklist requested MALIVIANAMIS,N Commonwealth Edison Co 82/09/15 DENTON,H R Office of Nuclear Reactor Regulation, Director Spp 15672 220 24X Fiche 50-254,82/09/24,8210120546
- 8210150487 Forwards IE Insp Repts 50-254/82-14 & 50-265/82-16 on 820823-25 & 0903 & 09 No noncompilance noted REPPLER.J G Region 3, Office of Director 82/09/30 REED.C Commonwealth Edison Co 3pp 15721 289 24X Fiche 50-294,82/09/30, 8210159487
- --B210150495 IE Insp Repts 50-254/82-14 & 50-265/82-16 on 820823-25 & 0703 & 09 No noncompliance noted Hajor areas inspected emergency preparedness exercise & liconsee actions on previously identified emergency preparedness items PHILLIPS.N P. SMITH.M J. AXELEON.W L. Division of Emergency Preparedness & Operational Support 82/07/29 15pp 15721 292 24X Fiche 50-254.82/09/30.8210150487
- 9210130376 Advises that installation of offsite dose calculation sysphogram fully operational tracking model & operational Anmodel will be delayed until 821231 to complete prime computer installation SWARTZ.E D Commonwealth Edison Co 82/10/06 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 15682 078 24X Fichs 30-000, 82/10/06,8210130376
- 8210290047 Releases public version of revisions to Quad Cities. Zion & Dreaden emergency plan annexes & revised generating station emergency plan telephone directory FELTON, J H Division of Rules and Records 82/10/08 Document Management Branch ip 15877 313 24X Fiche 50-000, 82/10/08, 8210290047
- --82i0290060 Forwards public version of Revision 3 to Quad Cities & Zipn emergency plan annexes, Revision 2 to Dreaden emergency plan annex Revision 0 to Buron emergency plan annex & revised generating station emergency plan telephone directory MODRE, R D Commonwealth Edison Co 82/07/30 DENTON, H R NRC No Detailed Affiliation Given 5pp 15877 314 24X Fiche 50-000, 82/10/08, 8210270047
- --B2iO290077 Public version of Revision 3 to Guad Cities & Zion emergency plan annexes. Revision 2 to Dresden emergency plan annex & Revision 0 to Byron emergency plan annex & Commonwealth Edison Co. B2/06/30 325pp 15877 319 24X Fiche 50-000, 82/10/90, 821029007.
- -- B2102900B8 Public version of revised generating station emergency plan telephone directory GALLE.D.P. Commonwealth Edison Co. 82/08/12 43pp 15878 218 24X Fiche 50-000,82/10/08,8210290047

- 8210190753 Forwards 820922 itr re late submittals of exercise scenarios & failure to adhere to FEMA Outdance Memo 17 If FEMA does not observe exercise, offsite authorities will not participate HIND. J A Division of Emergency Preparedness & Operational Support 82/10/12 REED, C Commonwealth Edison Co 2pp 15736 247 24X Fiche 50-254.82/10/12,8210190753
- --B2101907&0 Discusses concerns re late submittals of emergency exercise scenarios & failure to adhere to FEMA Guidance Memo 17
 Future exercise not meeting intent of advance notification guidance should be postponed or canceled
 BREHENV.P J Federal Emergency Management Agency 62/09/22
 KEPPLER.J G Region 3, Office of Director 1p 15736 249 24X
 Fiche 50-254,82/10/12,8210190783
- 8210280361 Releases public version of revised emergency plan implementing procedures FELTON.J M Division of Rules and Records 82/10/12 Document Management Branch Ip 15859 204 24X Fiche 50-254,82/10/12, 6210280341
- --8210280364 Forwards public version of revised emergency pian implementing procedures, including Procedures GEP 200-0 re emergency conditions, GEP 200-T1 re emergency action levels & GEP 330-3 re SFING control terminal operation KDVACK, T 8 , GERNER, L F Commonwealth Edison Co 82/07/23 DENTON, H R NRC No Detailed Affiliation Given 2pp 15859 205 24X Fiche 50-254,82/10/12,8210280361
- --8210280375 Public version of revised emergency plan implementing procedures, including Procedures QEP 200-0 re emergency conditions, QEP 200-T1 re emergency action levels & QEP 330-3 re SPIN9 control terminal operation & Commonwealth Edison Co. 82/09/23 21pp 15859 207 24X Fiche 50-254,82/10/12.821028036
- 8210220358 Provides info re organization & performance of depts responsible for radiation protection activities, per 820702 commitment Training coordinator assigned in Apr 1782 to improve health physics training programs TRAMM.T R Commonwealth Edison Co 82/10/14 DENTON, H R Office of Nuclear Reactor Regulation, Director 9pp 15776 287 24X Fiche 50-000, 82/10/14, 8210220358
- 8210250307 Responds to 820917 telcon request for info re fire protection safe shutdown rept Items 2 & 3 are preliminary results; subj to revision following engineering review RAUSCH, T J Commonwealth Edison Co 82/10/18 EISENHUT, D O Division of Licensing App 15790 215 24% Fiche 50-254,82/10/18,8210250309
- P Operating license stage documents & correspondence
- 8210050142 Requests that charcoal adsorber F64-DY#2 be counted within 2 wks of receipt.decay corrected to 790319 lavels & resturned Liquid beta analyses results received in NRC 820917 ltr will be incorporated in rept addendum PAPERIELLO.C J Division of Emergency Preparedness & Operational 8upport 82/09/28 KALIVIANAKIB,N Commonwealth Edison Co 1p. 15605 167 24% Fichs 50-254,82/09/28,8210050142
- 8210120105 Requests delay of implementation due dates re NUREO-0737, Items II B 2, "Plant Shielding," II B 3, "Post-Accident Sampling" & II F 1 i, "Noble Qas Effluent Honitor" SHARTZ.E D Commonwealth Edison Co 82/10/04 EJSENHUT, D 0 Division of Licensing 5pp 15651 237 24X Fiche 50-000, B2/10/04, 8210120105
- 8210260526 Forwards Revision 3 of Chapter 9 of "Offsite Dose Calculation Menual." QDLDEN, J C Commonwealth Edison Co 82/10/06 CASE, E G Office of Nuclear Reactor Regulation, Director 2pp 15805 137 24X Fiche: 50-000, 82/10/06, 8210260526
- --8210260542 Revision 3 of Chapter 9 of "Offsite Dose Calculation Hanual"

 * Commonwealth Edison Co 82/09/30 83pp 15805·139 24X Fiche 50-000,82/10/06,8210260526
- 8210160059 Provides addl guidance & ciarification re 820806 request for addl info per NUREG-0737, Item II B 3, "Post-Accident Sampling Bys " Detailed reliability analysis not required to satisfy NRC concerns CRUTCHFIELD.D Operating Reactors Branch 5 82/10/08 DELGEORGE, L. Commonwealth Edison Co 3pp 15720 004 24X Fiche: 50-000, 82/10/08, 82/10/08, 82/10/08

- 8210190780 Forwards "OE BWR Estended Load Line Limit Analysis for Guad Cities Nuclear Power Station Unit 1. Cycle 7 & Unit 2. Cycle 6" RAUSCH, T. J. Commonwealth Edison Co. 82/10/12 EISENHUT, D. G. Division of Licensing 1p 15736-206 24X Fiche 50-254, 82/10/12, 82/10/2006
- --8210190785 "GE BWR Extended Load Line Limit Analysis for Quad Cities Nuclear Power Station, Unit 1, Cycle 7 & Unit 2, Cycle 6 " 4 General Electric Co NEOD-22192 82/07/31 31pp 15736 207 24X Fiche 50-234, 82/10/12,8210190780
- 8210190445 Forwards supplemental response to Generic Ltr B2-05 re implementation status of NUREQ-0737, Items II B 3.II F 1 2. II F 1 5 & II F 1 6, in response to B21004 request SHARTZ.E D Commonwealth Edison Co B2/10/14 EISENHUT.D G Division of Licensing 5pp 15741 202 24% Fisch 90-000.92/10/14, 8210190445
- 8210250114 Application for amend to License DPR-29, changing safety relief actuating setpoint of Target Rock valve to 1.135 psig 5 changing setpoint of two electromatic relief valves to 1.115 psig RAUSCH.T.J. Commonwealth Edison Co. 82/10/18 DENTON, R. Office of Nuclear Reactor Regulation, Director 3pp 19787 032 24X Fiche 50-254, 82/10/18, 8210250114
- --8210250126 Proposed changes to Tech Specs changing safety relief actuating setpoint of Target Rock valve to 1,135 psig & setpoint of two electromatic relief valves to 1,115 psig * Commonwealth Edison Co 82/10/18 3pp 15787 035 24X Fiche 50-254,82/10/18.8210250114
- 8210250155 Forwards corrections to proposed Tech Spec Pages 1 2/2 2-1 & 3 3/4 3-5, supporting review of future reloads & revised Figure 3 5 1.8 heet 1, providing extended MAPLHOR vs exposure curves for barrier lead test assembly fuel RAUSCH. T J Commonwealth Edison Co 82/10/18 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 15789 233 24X Fiche 50-000, 82/10/18, 8210250155
- --8210250169 Revised proposed Tech Spec Pages 1 2/2 2-1 & 3 3/4 3-5, supporting review of future reloads & revised Figure 3 5 1, Sheet i providing subended MAPLHGR vs synasure curves for barrier lead test assembly fuel Supersedes 820819 version * Commonwealth Edison Co 62/10/18 4pp 15768 235 24X Fichs 50-000,62/10/18,6210250155
- ---8210250177 Errata & Addenda Sheet B. replacing Page 4-10 to "LOCA Analysis Rept for Dresden Units 2 & 3 & Quad Cities 1 & 2 Nuclear Power Stations"

 --- General Electric Co NEDO-24146A ERR 08 82/09/30 3pp 15788 239 24X Fiche 50-000, 82/10/16,8210250155.
- 8210250069 Provides addI info re reactor water cleanup room area temp monitors Temp elements cause no automatic plant response beyond control room alarma
 RAUSCH.T J Commonwealth Edison Co 82/10/19 EIBENHUT, D G
 Bivision of Licensing 2pp 15787 081 24X Fiche 50-000,82/10/19,8210250069
- Q Inspection reports: IE Bulletins & correspondence

1.

3411

- 8210150487 Forwards IE Insp Repts 50-254/82-14 & 50-265/82-16 on 820823-25 & 0903 & 09. No noncompliance noted KEPPLER. J O Region 3. Office of Director 82/09/30 REED, C Commonwealth Edison Co 3pg 15721 289 24% Fiche 50-254.82/09/30, 6210150487
- --0210150495 IE Insp Repts 50-294/82-14 & 50-265/82-16 on 820823-25 & 0903 & 09 No noncompliance noted Major areas inspected emergency preparedness exercise & licensee actions on previously identified emergency preparedness items PHILLIPB M P . SHITH M J . AKELSON W L Division of Emergency Preparedness & Operational Support 82/09/29 15pp 15721 292 24X Fiche 50-254,82/09/30.8210150487
- 8210060359 Ack receipt of 920910 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-237/81-39, 50-249/91-32, 50-254/81-23, 50-265/81-23, 50-295/81-31 & 50-304/81-29

 PESBARD, R L Division of Project & Resident Programs. 82/10/01 REED. C. Commonwealth Edison Co 1p, 15618 354 24X Fiche: 50-000, 82/10/01.8210060359
- ---8210060367 Responds to NRC 820712 ltr re-violations noted in IE Insp. Repts 50-237/81-39, 50-249/81-32, 50-254/81-23, 50-255/81-23, 50-295/81-31 & 50-304/81-29, Corrective actions training for mgt priorities re-plant availability will be conducted REED.C Commonwealth Edison Co 82/09/10 KEPPLER, J. 0 Region 3, Office of Director 13pp 15618.355 24X Fishe 50-000, 82/10/01, 8210060359.

- 8210080178 Forwards listing of piping sys which fail to meet FBAR requirements, per NRC 800B18 confirmatory action 1tr IE 8011stin 79-14 operability systuation updates will not be provided for Dresden & Quad Cities Final update by Dec 1982 RAUSCH. T J Commonwealth Edison Co 82/10/01 KEPPLER, J Q Regir J. Office of Director Opp 15640 157 24X Fiche 50-000, 62/10/01, 8210080178
- 8210080190 Confirms B21103 enforcement conference at Region 3 ofc re & aspects associated w/procurement installation & use of non-qualified valve guides in electromagnetic relief valves at facilities
 SPESSARD, R L. Division of Project & Resident Programs B2/10/04 REED.C Commonwealth Edison Co. (p. 15440-181-24X Fichs 50-000, B2/10/04, B210080190
- 820B190233 IE Info Notice 80-35. Suppl i, "Leaking & Dislodged I [21 Implant Seeds " Svc list enc! COBB.L I Division of Fuel Facilities. Materials & Safeguard's 82/10/06 Consolidated Edison Co of New York 66pp 15761 273 24X Fiche 50-000.82/10/06.8208190233
- 9208190238 1E Bulletin 82-03. "Stress Corrosion Cracking in Thick Wall-Large-Diameter, Stainless Steel Recirculation Sys Piping at BUR Plants "Svc list encl DEYGUNG.R C Director's Office. Office of Inspection and Enforcement 92/10/14 Consolidated Edison Co of New Yorl 115pp 15810 128 24X Fiche 50-000.82/10/14.8208170238
- R Periodic operating reports & related correspondence
- 8210130385 Forwards monthly operating repts for Bept 1982 RALIVIANAKIS, N Commonwealth Edison Co 82/10/01 Director s Office: Office of Inspection and Enforcement 1p 15680 139 /** Fiche 50-294, 82/10/01, 8210130386
- --8210130370 Monthly operating repts for Sept 1782 BUSS.R D Commonwealth Edison Co 82/10/04 13pp 13MO (14) 24X Fiche 50-254, 82/10/01, 8210130386
- S Reportable occurrences. LERs & related correspondence
- 8011060561 Discusses facility 770103 loss of air event & effect on scram capability Conservative analysis of data indicates short operator response time Immediate scram on loss of control rod driveline air header should be required LANIK. @ Darector's Office 80/10/20 HICHELSON, C Director's Office 3pp 15692 268 24X Fiche 50-254.8D/10/20.8011000561
- -8011060565 Forwards senior resident inspector 800829 memo re affect of facility 770103 loss of air event & its effect on scram capability KEPPLER.J O Region 3. Chicago, Office of the Director 80/u//2* MICHELSON. C Director's Office ip 15692 271 24X Fiche 50-254,80/10/20.8011060561
- --B01106056B Discusses facility 770103 loss of air event & effect exscram capability Event indicates that scram discharge vol.
 although filled to approx 59% capacity, was capable of accepting vol of water to shut down reactor safely CHRISSOTIMOS, N. Region 3, Chicago, Dffice of the Director B0/08/27 SPEBSARD, R. Region 3, Chicago, Reactor Operations Nuclear Support Branch 2pp 15692 272 24% Fichs 50-254,80/10/20.8011060561
- 8210050395 Forwards LER 82-026/03L-0 KALIVIANAKIS.N Commonwealth Edison Co 82/09/27 KFFPllR, J Region 3. Office of Director lp 15616 017 24X Fiche 50-294,82/09/27,8210060395
- --8210050405 LER 82-026/03L-0 on 820906, flange seal gasket leak wate found exceeding 30 SCFH & possibly exceeding Tech Spec limit of 36 72 SCFH for double-gasket seals Caused by seal gasket deterforation Pasket to be repaired/replaced MENDENHALL, E E Commonwealth Edison Co 82/09/27 Region 3. Office of Director 1p 15616 018 24X Fiche 50-254,82/09/27. 8210050395.
- 8210130324 Forwards LER 82-027/01T-0 KALIVIANAKIS.N Commonwealth Edison Co 82/09/28 KEPFLER, J Region 3. Office of Director 1p 15678 292 24X Fiche 50-254, 82/09/28, 8210130324
- --8210130328 LER 82-029/01T-0 on 820916, two small cracks found in heat affected zone of welds 128-F9 & F10 of reactor water cleanup ays piping Caused by athese corrosion Piping to be replaced w/stainless steel pipe & fittings prior to startup WILOUS, D Commonwealth Edison Co 82/09/28 Region 3. Office of Director, 4pp 15678 293. 24X Fiche 50-254,82/09/20.8210130324.

- E210130413 Forwards LER 82-027/03L-0 MAL[VIAMAKIE, N Commonwealth Edison Co 82/09/29 KEPPLER, J Region 3, Office of Director 1p 15680 243 24X Fiche 50-254, 82/09/29, 8210130413
- --B210130423 LER 82-027/03L-0 on B20902, electromagnetic relief valve main valve guides & piston rings inadvertently ordered as nonsafety-related Caused by inadequate implementation of procurement requirements frocedures revised TIETZ. G Commonwealth Edison Co B2/09/28 Region 3, Office of Director ip 15680 244 24% Fiche 50-254.82/09/29,8210130413
- 8210130501 Forwards LER 82-025/03L-0 KALIVIANAKIS.N Commonwealth Edison Co 82/09/29 KEPPLER, J Region 3. Office of Director 1p 15682 189 24X fithe 50-254.82/09/29.8210130501
- --6210130511 LER 82-025/03L-0 on B20907.1/2A standby gas treatment train heater found tripped during Procedure QDP 020-1 Caused by conservative switch setting due to inadequate setpoint differences Heater trip reset LIHOU.H Commonwealth Edison Co 82/09/27 Region 3. Office of Director 3pp 15682 190 24x Fiche 50-254.82/09/29.8210130501
- 5210130251 Forwards LER 82-031/03L-0 KALIVIANAKIS.N Commonwealth Edison Co 82/09/30 KEPPLER.J Region 3. Office of Director ip 15678 094 24X Fiche 50-254.82/09/30.8210130251
- --U210130253 LER D2-031/03L-0 on B20905.RCIC sys taken out of svc to uncouple turbine from pump Caused by need to perform scheduled turbine overspeed surveillance test LIHOU-H Commonwealth Edison Co 82/09/30 Region 3, Office of Director 1p 15678 095 24X Fiche 50-254.B2/09/30,B210130251
- 3210130466 Forwards LER 82-032/03L-0 PALIVIANAKIS.N Commonwealth Edison Co 82/09/30 KEPPLER, J Region 3. Office of Director ip 15602 136 24X Fishe 50-254.82/09/30.821013046
- -8210130473 LER 82-032/03L-0 on B20905.HPCI removed from svc w/o actuation of electromatic relief valves Caused by need to perform scheduled turbing overspeed surveillance test HPCI sys will be tested operable upon return to power LHCU.H Commonwealth Edison to B2/09/30 Region 3, Office of Director ip 15682 137 24X Fiche 50-254,82/09/30.8210130466
- P210130192 Forwards LER 82-030/03L-0 KALIVIANAKIS.N. Commonwealth Edison Co. 82/10/01 KEPPLER, J & Region 3. Office of Director 1p. 15674 100 24X Fiche 50-254, 82/10/01.8210130192
 - 8210130176 LER 82-030/03L-0 on 820705, while testing RHR svc water pump 1-1001-650, packing found burned Caused by excessive tightening in packing to limit leakage Mods installed to protect bearings from seal leakage SCHMITZMEYER. J Commonwealth Edison Co 82/07/05 Region 3, Office of Director 3pp 15674 101 24X Fiche 50-254,82/10/01,6210130192
- ©10190658 Forwards LER 82-020/03L-0 MALIVIANAKIE: N. Communealth Edison Co. 82/10/04 KEPPLER, J G Rogion 3. Office of Director 1p. 15737 267 24X Fiche 30-254, 82/10/04,8210190658
- -8210190700 LER 82-020/03L-0 on 820920 & 21.RCIC area high temp isolation 0[5-28.3 switches 1-1360-14A.1-1360-178 & 1-1360-16C. would not trip Cause not specifically determined Failed switches returned to manufacturer for analysis PREUSS.M Commonwealth £dison Co 82/10/04 Region 3. Office of Director 3pp 15737 268 24% Fiche 50-254.82/10/04.
- 210250148 Forwards supplemental LER 82-022/03L-1 KALIVIANAKIS N Commonwealth Edison Co 82/10/07 KEPPLER, J G Region 3. Office of Director ip 15787 360 24X Fiche 50-254, 82/10/07, 8210250148
- -8210250153 Supplemental LER 82-022/03L-1 on 820816, maint outage for 1/28 diesel fire pump exceeded 7-day limit Cause not stated Diesel pump wear rings replaced LIHOU.H Commonwealth Edison Co 82/10/07 Region 3, Office of Director ip 15787 361 24X Fiche 50-254, 82/10/07, 8210250148
- 210260467 PND-III-82-112 util notified that high density fuel storage racks installed do not meet design criteria for spacing due to bouing condition Handfacturer reanalyzed seismic response of racks & concluded bowed distance acceptable GROBE.J. WALKER, R. STREETER, J. Region 3, Office of Director 82/10/18 p 15804 237 24K Fiche 50-254,82/10/18,8210260467

- DOCKET 50-255 PALISADES NUCLEAR PLANT
- F Security, medical, emorgency & fire protection plans
- 8210050302 Updates status & schedule for responses to NUREG-0737. Items I D 2. "Plant Safety Parameter Display Console" & III A 2. "Improving Licensee Emergency Preparedness Long-Term "JOHNSON.B D Consumers Power Co 82/09/30 CRUTCHFIELD, D Operating Reactors Branch 5 2pp 15602 359 24% Fiche 30-255.82/09/30.8210050302
- 8210280058 Releases public version of revised emergency plan FELTON, J M Division of Rules and Rocards 82/10/08 Document Management Branch 1p 15862 (24 24X Fiche 50-255, 82/10/08, 8210280058
- --8210280061 Forwards public version of Revision 1 to emergency plan * Consumers Power Cp 82/09/24 NRC - No Detailed Affiliation Qiven 2pp 15862 125 24X Fiche 50-255.82/10/08.8210280058
- --8210280063 Public version or Revision 1 to emergency plan RANY, J Consumers Power Co 82/09/14 105pp 15862 127 24X Fiche 50-255, 82/10/00, 8210280058
- 8210280107 Submits response to NRC questions re util 820701 fire protection submittal JQHNSDN,8 D Consumers Power Co 82/10/25 CRUTCHFIELD,D Operating Reactors Branch 5 3pp 15837 191 24X Fiche 50-255,82/10/25,8210280107

G Adjudicatory correspondence

- 8210190480 Requests assistance in representing Oreat Lakes Energy Alliance in steam generator replacement proceeding Author deeply involved in Midland proceeding SIKCLAIR,M Great Lakes Energy Alliance B2/10/04 GARDE, & O
- 8210080082 Motion for indefinite continuance of proceeding Need for steam generator replacement alleviated due to better than expected corrosion performance of steam generator tubes. Future rate of corrosion unpredictable U/Certificate of Svc STEPTOE, P P Consumers Power Co STEPTOE, P P Isham, Lincoln & Beale 82/10/05 Atomic Safety and Licensing Board Panel App 15640 205 24% Fiche 50-259,82/10/05,8210080082
- \$210080099 Notice of appearance in proceeding STEPTOE.P P Consumers Power Co STEPTOE.P P Isham, Lincoln & Beale 82/10/05 ip 15440 275 24X Fiche 50-255,82/10/05, 8210080099
- B2102700B7 Response to applicant B21005 motion for indefinite continuance NRC does not object to motion Certificate of Byc encl
 BARTH.C A Hearing Branch 1 B2/10/25 Atomic Gafety and Licensing Board Panel 2pp 13822 338 24X Fiche 50-255, 82/10/25, 82102700B7
- P Operating license stage documents & correspondence
- 8210120033 Ack receipt of 820830 application proposing Tech Spec changes re ESF filtration sys Application provides supplemental info to 750306 pre-fee application No add) fee required Refund of 820830 application fee authorized MILLER.W O License Fee Management Branch 82/07/23 VANDEWALLE.D J Consumers Power Co. 1p 15689:202 24X Fiche 50-205.82/07/23,0210120033
- 8210050072 Discusses 820208 final assessment rept for SEP Topic IX-4, "Boron Addition Bys " Check valves 3408,3409 & 3410 should be added to Tech Spec Table 4 3 i Response requested within 45 days CRUTCHFIELD, D. Operating Reactors Branch 5 82/09/29 VANDEWALLE, D. J. Consumers Pawer Co 2pp 15403 186 24K Fiche 50-255,82/09/29,8210050072
- 8210070013 Forwards draft "Offsite Dose Calculation Manual" for facilities VANDEWALLE,D J. Consumers Power Co 82/09/29 CRUTCHFIELD,D Operating Reactors Branch 5 ip 15628 222 24X Fiche: 50-000,82/09/29,8210070013
- --8210070018 Draft "Offsite Dose Calculation Manual," Palisades Plant & Consumers Power Co 82/09/24 55pp 15628 276 24X Fiche. 50-000, 82/09/29, 8210070013

- 8210030265 Confirms that auxiliary feedwater sys mod provides for pumps P-8A & P-BC to be loaded on emergency diesel generators upon loss of offsite power JOHNSON, B D Consumers Power Co 82/09/30 CRUTCHFIELD, D Operating Reactors Branch 5 lp 19610 283 24X Fiche 50-255, 82/09/30, 8210050265
- 8210050302 Updates status & schedule for responses to NUREQ-0737, Items I D 2, "Plant Safety Parameter Display Console" & III A 2, "Improving Licenses Emergency Preparedness Long-Term " UDHNEON, B D Consumers Power Co 82/09/30 CRUTCHFIELD, D Operating Reactors Branch S 2pp 15602 359 24% Fiche 50-255, 82/09/30, 8210050302
- 8210120078 Submits info re failure of control rod to fully insert during testing in hot shutdown condition Locking paw & pin, piston guido tube, rack assembly & bavel gear housing replaced All defective uncoupling tools removed from svc UOHNSON, B D Consumers Power Co 82/10/06 CRUTCHFIELD, D Operating Reactors Branch 5 App 15651 246 24X Fiche 50-255, 82/10/06, 8210120078
- 8210120323 Forwards suppl to safety evaluation of BEP Topics II-3 A: II-3 B & II-3 C reanalyzing design basis surge level for facility Unresolved differences now considered acceptably resolved & topic reviews complete WAMBACH.T V Operating Reactors Branch 5 82/10/07 VANDEHALLE.D J Consumers Power Co. Spp 15653 033 24X Fiche 50-255, 82/10/07, 8210120323
- 8210130326 Comments on proposed scope of Phase III of SEP as reflected in individual topic definitions appended to 820909 ltr Staff encouraged to develop & implement means to incorporate positive attributes of Phase III in licensee/NRC interface KACICH.R M SEP Owners Group 82/10/07 EISENHUT.D 9 Division of Licensing 7pp 15682 179 24% Fiche 50-000,82/10/07,8210130326
- 8210190110 Provides addl guidance re purpose of NRC B20630 request for addl info concerning NUREQ-0737. Item II.B 3 re post-accident sampling sys CRUTCHFIELD.D Operating Reactors Branch 5 B2/10/07 VANDEWALLE.D J Consumers Power Co 3pp 15719 319 24X Fiche: 50~255, 82/10/07, 8210190110
- 8210130334 Forwards evaluations of open items identified in NRC 820212 ltr re SEP Topic III-7 B, "Dasign Codes.Design Criteria & Load Combinations." per util 820817 commitment Code change will not affect safety margin of plant structures VANDEWALLE.D J Consumers Power Co 82/10/08 CRUTCHFIELD.D Operating Reactors Branch 5 12pp 15679 140 24X Fiche 50-235.82/10/08.8210130334
- 8210170459 Forwards current status of program to evaluate adequacy of overload & short-circuit protection for electrical circuits that pass through reactor containment per BEP Topic VIII-4 "Electrical Penetrations of Reactor Containment"

 TONER.K.A. Consumers Power Co. 82/10/12 CRUTCHFIELD, D. Operating Reactors Branch 5 21pp 19740 268 24X Fichs 50-000.82/10/12, 8210170459
- 8210190535 Forwards summary of actions taken to address specific 820412 draft NUREO-0820 concerns re eccentric loads & valve functionability in small bore piping Summary of plans to perform addi analysis on control valve CV-3003 encitons Reactors Branch 5 51pp 15751 255 24X Fichs 50-255,82/10/13,82/0190535
- 82(0190546 Summarizes status of util commitment re SEP Topic IX-3, "Station Svc & Cooling Mater Sys " Analysis verifying that component cooling water tamp limits are not exceeded under postulated conditions will be submitted by 82(1)5 TOMER. K.A. Consumers Power Co. 82/10/15 CRUTCHFIELD.D. Operating Reactors Branch 5 2pp. 13751.361. 24X Pichs 50-255.82/10/15, 82(0)70546
- B210220186 Provides add1 info re control room toxic chamical analysis & self-contained breathing apparatus in response to NUREO-0737, Item III.D 3 4 on contol room habitability.per 820720 request

 JOHNSON.B D. Consumers Power Co 82/10/19, CRUTCHFIELD, D. Operating Reactors Branch 5. 9pp. 15777.284. 24X
 Fiche 50-255,82/10/19,8210220184
- 8210260179 Responds to 820817 request for removal of administrative limit on auxiliary feedwater flow rate to ateam generator. Limits discussed in NRC 801001 immediate action itr no longer appropriate New flow rates should be established. KEPPLER. J. 9 Region 3, Office of Director. 82/10/20, JCHNBON, B D Consumers Power Co. 1p. 15799:036 24X Fiche: 50-255, 82/10/20, 8210280179.

- 8210280276 Informs of new commitment dates for NUREG-0737, Items II F 1 1, II F 1 2, II F 1 3, II F 1 4 & II B 3 JUHNSON, B D Consumers Power Co 82/10/25 CRUTCHFIELD, D Operating Reactors Branch 5 3pp 15837 304 24X Fiche 50-255, 82/10/25, 82(0280276
- O Inspection reports: IE Bulletins & correspondence
- B2100B0015 Addi response to FOIA request for 19 categories of info re nuclear reactor events & safety problems Forwards documents listed in App A Documents in App B completely withheld (ref FOIA Exemption 5) FELTON.J M Division of Rules and Records B2/07/12 UNELL,R A Critical Mass Energy Project 9pp 15465 927 24X Fiche 50-000.82/07/12,8210080015
- --B2100B0144 Systematic assessment of licensee performance notes re facility evaluation for 790901-B00901 w NRC - No Detailed Affiliation Given 80/09/01 10pp 13668 015 24% Fiche 30-000.82/07/12.82100B0015
- 8210070007 Responds to FOIA request for eight categories of records seam generators & steam turbines App A documents provided in R Udell FOIA Request 81-313 Forwards documents listed in App B FELTON.J M Division of Rules and Records 82/08/10 LONG.D J Hinthrep, Stimson, Putnem & Roberts 9pp 15645 063 24X Fiche 80-000-82/08/10.0210070007
- --B210070172 Forwards info re steam generator integrity & (neps at all operating PMRs.per 750320 & 21 requests Details of intps. including defect indications tube plugging criteria & tubes glugged will not be provided except for Point Beach i OCLLER.K R Division of Reactor Licensing (NRR-1775 only) 75/03/24 MACCARY, R Division of Technical Review (NRR-1975 only) 5pp 15645 176 24X Fiche 50-000, 82/08/10, 8210070007
- 8210190421 Forwards IE Insp Rept 50-255/82-20 during Aug 1982 & notice of violation
 STRETER, J F Division of Project & Resident Programs 82/09/29 DEVITT, R B Consumers Power Co 2pp 19741 094 24X Fiche 50-255.82/09/29.8210190421
- --8210190427 Notice of violation from insp during Aug 1982 BTREETER.J F Division of Project & Resident Programs 82/07/29 1p 19741 036 24X Fiche 50-255.82/07/29.8210190421
- ~-B210190449 IE Insp Rept 50-255/82-20 during Aug 1782 Noncompliants noted on B20831 BBA Sequences Test Procedure T-157 revised during implementation & new steps involving bypass of safety functions performed w/a permission of shift supervisor JORGENBEN B L , HELLER J K , REVEG L A Division of Project t Resident Programs 62/07/29 7pp 15741 037 24X Fiche 50-255/82/09/29,8210190421
- B210190697 Forwards IE Mgt Meeting Rept 50-255/82-21 on B20909 No noncompliance noted REPPLER.J O Region 3, Office of Director 82/10/04 DEMITT.R B Consumers Power Go 2pp 15737 276. 24X Ficha 50-255.82/10/04, 02/10/04/05
- --8210190707 IE Mgt Meeting Rept 50-255/82-21 on 820908 No noncomplinated Major areas discussed current status of util program for meeting requirements of 810309 confirmatory order reregulatory improvement program
 JDROENSEN, B. L., SPESSARD, R. L. Division of Project & Regident Programs 82/10/01 3pp 15737 278 24X Fiche 50-255.82/10/18210190699.
- B208190233 IE Info Notice 80-35, Suppl i. "Leaking & Dislodged E-12: Implant Beede." Svc list encl.
 COSB.L. I Division of Fuel Facilities. Materials & Bafeguards
 82/10/06 Consolidated Edison Co of New York & &p. 13761 2
 24X Fiche 50-000.82/10/06.8208190233
- 8208190238 IE Bulletin 82-03, "Stress Corrosion Crecking in Thict-Wall, Large-Diameter, Stainless Steel, Recirculation 8us Piping at BWR Plents," Svc list encl DEYQUNO; R C Director's Office, Office of Inspection and Enforcement, 82/10/14, Consolidated Edison Co of New Yeel 115pp 15810:125, 24X Fiche, 50-000, 82/10/14, 8208190238
- B210260176 Ack receipt of supplemental B20929 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-255/82-07
 NORELIUS, C.E. Division of Engineering & Technical Propress, B2/10/18, DEWITT, R.B. Consumers Power Co. 1p. 15799 645 24 Ficher 50-255, 82/10/18, B210260176.

- --8210260183 Suppls response to NRC B20412 ltr re violations noted in IE Insp Rept 50-235/82-07 Corrective actions NBG-traceable hydrometer received & compared w/hydrometers used for surve(Ilance Calibr results encl JOHNISON, B D Consumers Power Co 82/09/29 KEPPLER, J G Region 3. Office of Director 2pp 15799 046 24% Fiche 50-255, 82/10/16.6210260176
- Periodic operating reports & related correspondence
- REPORT NOTE TO SERVICE TO SERVICE
- -8210130145 Menthiy operating rept for Sept 1982
 PETERSON.D A . VANDERBERG.D Consumers Power Co 82/10/04 4pp
 15673 091 24X Fiche 50-255, 82710/08, 8210130138
- Reportable occurrences, LERs & related correspondence
- 1210150146 Forwards LER 81~011/03L~0 HDFFMAN, D P Consumers Power Co 81/03/27 KEPPLER, J Q Region 3, Chicago, Dffice of the Director (81/03/01) ip 15697 083 24X Fiche 50-255, 81/03/27, 8210150146
- -8210150152 LER 81-011/03L-0 on 810304, diesel generator i-1 overspeed & low air pressure alarms actuated & would not reset after 16 cylinder leak test Caused by broken micro-switch due to high impact resulting from improper use of trip lever & Consumers Power Co 81/03/27 Region 3, Chicago, Office of the Director (81/03/21) ip 15697 084 24X Fiche 50-255,81/03/27,8210150146
- 210070415 Discusses abnormal wear encountered on ALOYCO swing check valves installed in low pressure safety injection sys IE should issue info notice to inform licensees of problem MICHELSON.C Director's Office 81/12/23 DEYOUND, R C Director's Office. Office of Inspection and Enforcement 5pp 15637 327 24X Fiche 50-255.81/12/23.8210070415
- 210010000 Responds to FOIA request for 19 categories of documents renuclear reactor events & safety problems Forwards documents listed in App A FELTON, J M Division of Rules and Records 82/06/28 UDELL, R, A Critical Mass Energy Project 15pp 15727 005 24X Fiche 50~000, 82/06/28, 8210010008
- -B201200453 Recommends issuance of info notice to inform licenspes of problems w/ALOVCO swing check valves as encountered at facility Abnormal wear reported in LER B1-037 MIGHELSON, C Director's Office B1/12/23 DEYOUNG, R C Director's Office D8/20/28/B210010008
- 210060213 Forwards LER 82-026/03L-0

 JOHNSON B D Consumers Power Co 82/09/29 KEPPLER: J O Region 3,
 Office of Director 1p 15615 097 24X Fiche 50-295:82/09/29,
 8210060213
- -8210060216 LER 82-026/03L-0 on 820901, determined that four fire doors mfg by Protective Matis Co not documented to confirm testing & approval by nationally recognized lab Caused by vendor failure to obtain certification following mods * Consumers Power Co 82/09/29 Region 3, Office of Director ip 15615 098 24X Fiche 50-255,82/09/29,8210060213
- 2[0]30146 Forwards LER 82-027/03L-0 JOHNEON, B. D. Consumers Power Co. 82/09/30 KEPPLER, J. Q. Region 3, Office of Director ip. 15673 084 24X Fichs, 50-255, 82/09/30, 8210130146
- -8210130156 LER 82-027/03L-0 on 820901, procedural inadequacies discovered which could cause reduction in degree of redundancy in containment cooling sys Procedures revised to require fans to be declared inoperable if stopped & Consumers Power Co. 82/07/30 Region 3, Office of Director ip 15673 085 24X Fiche 50-255,82/09/30,8210130146
- 210180186 Forwards LER 82-031/03L-0 JOHNSON B D Consumers Power Co. 82/10/06 KEPPLER. J O Region 3. Office of Director 1p 15718 177 24X Fiche 50-255, 82/10/06, 8210180186
- -8210180191 LER 82-031/03L-0 on 820909, 1-1 diesel generator water jackst heater found inoperable Caused by corposion of heater element. Heater replaced w/similar type element Mod devaloped to replace heater element © Consumers Power Co 82/10/06 Region 3, Office of Director ip 15718 178 24X Fiche 50-225,82/10/06,8210180186

- 8210190604 Forwards LER 92-028/03L-0 JOHNSON 8 D Consumers Power Co 82/10/11 KEPPLER. J Q Region 3, Defice of Director 1p 15739 357 24X Fiche 50-255, 82/10/11, 8210190604
- --B210190615 LER 82-028/03L-0 on B20915.boric acid heat trace circuit 401 (gravity feed line to charging pumps) failed Redundant channel remained operable Caused by failed heater element Heater element replaced

 * Consumers Power Co 82/10/11 Region 3, Office of Director 1p 15737 358 24% Fiche 50-255,82/10/11,8210190604
- 8210190620 Forwards LER 82-029/03L-0 JOHNSON, B D Consumers Power Co 82/10/11 KEPPLER, J G Region 3, Office of Director 19 15737 219 24X Fiche 50-255, 82/10/11, 8210190620
- --B210190628 LER B2-029/03L-O on B20916.T-82B (safety injection tank B)
 level reached Tech Spec limit of 198 inches three times in
 24-h period Caused by minor leakage past loop theck vaive &
 fill & drain valve Fill & drain cycled to stop leakage
 * Consumers Power Co 82/10/11 Region 3. Office of Director
 ip 15737 220 24X Fiche 50-255.82/10/11.8210190620
- 8210190639 Forwards LER 82-030/03L-0 JOHNSON, B D Consumers Power Co. 82/10/11 KEPPLER, J Q Region 3, Office of Director 1p 15740 044 24% Fiche 50-255, 82/10/11, 82/0190639
- --8210190649 LER 82-030/03L-D on 820927, boric acid heat trace circuit 432 failed Redundant channel remained operable Caused by blown fuse in controller Circuitry tested & fuse replaced Consumers Power Co B2/10/11 Region 3. Office of Director 1p 15740 045 24X Fiche 50-255,82/10/11,8210190639
- DOCKET 50-259 BROWNS FERRY NUCLEAR POWER STATION, UNIT 1
 F Security, medical, emergency & fire protection plans
- 8209170101 Forwards minor revisions to proposed physical security plan Revisions withheld (ref 10CFR73 21) MLL5s.L M Tennessee Valley Authority 82/08/31 DENTON, H R Office of Nuclear Resctor Regulation, Director, 2pp 14910 081 24X Fiche 50-259,82/08/31,8209170101
- 8210210034 STATION BLACKOUT AT BROWNS FERRY UNIT ONE-IODINE AND NOBLE OAS DISTRIBUTION AND RELEASE WICHNER, R P , MEBER, C F , LORENZ, R A Oak Ridge National Laboratory FIN 8-0452 NUREO/CR-2182 VO2 82/09/30 Division of Accident Evaluation 26/1pp. 15773, OO1 24X Fiche 50-259, 82/09/30, 8210210034
- 8210250236 Forwards security plan table of contents Table of contents withheld (ref 100FR3 21)

 KAMMERA D Fennessee Valley Authority 82/10/19 DENTON, H. R

 Office of Nuclear Reactor Regulation, Director 1p 15768 362 24x

 Fichs. 50-259, 82/10/19, 82/0250234
- O Adjudicatory correspondence
- 8210120291 Response to ASLAB 820920 order to provide any supplemental info re questions posed to util Authorization is for 5-yr storage of low level radwaste.w/o limit on use of modules for interim use on backup basis
 RAMSON.R.J Hearing Branch 4 82/10/08 8pp 15652 071 24X Fiche. 50-289: 82/10/08 8210120291.
- --8210120299 Affidavit of P Loysen re application for storage of low level radwasts No restriction requested or contemplated limiting use of modules only to interim use on backup basis LOYSEN, P Advanced Fuel & Bpent Fuel Licensing Branch 82/10/08 23pp 15652,079 24X Fiche, 50-259,82/10/08,8210120291.
- --B21012030B Affidavit of JR McGrath Timely request for renewal of facility license filed for Beatly, NV low level radwaste disposal facility NV State Board of Health voted not to renew facility license.

 MCGRATH.J.R Assistant Director for Btate Agreements Programs 82/10/08 2pp 15652, 102 24X Fiche. 50-259, 82/10/08, 8210120291
- --8210120316 Affidavít of SN Balomon Southeast Interstate Low Layel Radwaste Mgt Compact agreed to close Barnwell, SC facility on 921231 & open new site on 911231, Cartificate of Byc ancl. SALUMON, S. N. Assistant Director for State Agreements Programs, 82/10/08 4pp. 15652 104 24X Fiche: 50-239, 82/10/08, 8210120291

- 8210250063 Telecopy message of motion for ASLAB to grant 30-day extension to respond to ASLB 820920 order Time necessary to explore settlement possibilities of all matters in controversy PYLE.R B Pyle, R B 82/10/20 Docketing & Services Branch ip 15787 061 24X Fiche 50-259,82/10/20.821025063
- 8210260429 Motion for extension of time until 821121 to respond to 820920 order Time necessary to explore possibilities of settlement Certificate of Sec encl PYLE.R B Pyle. R B 82/10/20 Atomic Safety and Licensing Appeal Panel 2pp 15806 036 24X Fiche 50-259.82/10/20, 8210260429
- K Utility Final Safety Analysis Report (FSAR) & amends
- 8208170297 Chapter 2 to Browns Farry updated FSAR, "Bite "
 * Tennessee Valley Authority 82/08/12 346pp 14852 202 24X
 Fiche 50-259, 82/08/12, 8208170297
- P Operating license stage documents & correspondence
- 8210050268 Application to amend License DPR-33.revising Cycle 5 max critical power ratio values Error discovered in active fuel length used in original Cycle 5 analysis Approval requested by 821119 MILLS.L M Tennessee Valley Authority 82/09/21 DENTON.H R Office of Nuclear Reactor Regulation Director 2pp 15611 231 24X Fiche 50-259.82/09/21.8210050268
- --8210050271 Proposed Tech Specs re max critical power ratio * Tennessee Valleg Authority 82/09/21 3pp 15611 233 24X Fiche 50-259,82/09/21,8210050268
- 8210060301 Application to amend License DPR-33, updating curve of pressure vs temp to extend applicability through 5 0 effective full power yrs Approval of change requested by 821126 MILLS.L H Tempessee Valley Authority 82/09/23 DENTON.H R Office of Nuclear Reactor Regulation, Director 2pp 13619 29J 24X Fichs 50-259,82/09/23,8210060301
- --5210060304 Proposed Tech Bpec Figure 3 6-1, updating curve of pressure vs temp to extend applicability through 5 0 effective full power yrs

 * Tennessee Valley Authority 82/09/23 3pp [5619 295 24X Fiche 50-259, 82/09/23, 8210060301
- 8210070255 Forwards response to NRC request for add1 info on NUREO-0612, "Control of Heavy Loads of Nuclear Power Plants "
 MILLS.L M Tennessee Valley Authority 82/09/28 VASSALLO, D B Operating Reactors Branch 2 56pp 15635 243 24X Fiche 30-255, 82/09/28, 8210070285
- 8210080218 Forwards add1 info in response to NRC 820808 request re NUREO-0737, Item II K 3 24, "Adequacy of Space Cooling for HPC1 & RGIC," HELLBIL M Tennessee Valley Authority 82/10/04 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 15638:091 24X Fiche: 80-259, 82/10/04, 82(0080218
- 8210130142 Forwards description of final mods & changes to BMR scram sys & short-term interim commitments for Unit 2 Mods will be implemented for Unit 2 before startup from Reload 4 outage & subsequent Units 1 & 3 outages MILLS, L M Tennessee Valley Authority 82/10/06 DENTON, H, R Office of Nuclear Reactor Regulation, Director 4pp 15673 086, 24X Fiche 50-259,82/10/06,8210130142
- 8210250096 Forwards revision to 821006 implementing procedures MILLG.L M Tennessee Valley Authority. 82/10/15 DENTON:H R Office of Nuclear Reactor Regulation, Director. 1p 15793:058 24X Fiche:50-259,82/10/15.8210280096
- --8210250101 Revised implementing procedures.

 * Tennessee Valley Authority 82/10/15 16pp 15793.059 24X Fiche 50-259.82/10/15,8210250096
- Q. Inspection reports, IE Bulletins & correspondence
- 8210080015 Add1 response to FOIA request for 19 categories of info re nuclear reactor events & safety problems. Forwards documents listed in App A Documents in App B completely withheld (ref FOIA Exemption 5). FELTON J M Division of Rules and Records 62/07/12, UDELL.R A Critical Mass Energy Project 9pp. 15565 027 24X Fiche 30-000 82/07/12, 8210080015

- --8210080118 Systematic assessment of licensee performance notes refacility evaluation for Apr 1979-Mar 1980

 # NRC No Detailed Affiliation Qiven 80/03/31 App
 15667 315 24X Fiche 50-000, 82/07/12, 8210080015
- 8210150105 Notifies that corrective actions re IE Insp Rept. 50~239/81-13, 50~260/81-13 & 50~296/81-13 delayed Procedure BPM NB03 re exam of 6550 items to be revised by 820915 BDMER, J A Tennessee Valley Authority 82/07/13 D'REILLY, J P Region 2. Office of Director ip 15701 157 24X Fiche 50~297, 82/07/13, 8210150105
- 8210220151 Provides supplamental response to NRC ltr re violations noted in IE Insp Repts 50-259/82-10.50-260/82-10 % 50-256/82-10 Day of procedures Manual N82A3 will not be revised until 821001 due to scope of effort involved MILLG.L M Tennesses Valley Authority 82/08/18 0'REILLY, J P Region 2. Office of Director ip 15778 106 24X Fiche 50-259.82/08/18.8210220151
- B210010035 Confirms B2090B site meeting to discuss recent violations re radwaste shipments Agenda encl
 D'REILLY, J.P. Region 2, Diffice of Director B2/09/03 PARRIB, # 5
 Tennessee Valley Authority 2pp 15565 166 24X
 Fiche 50-259, 82/09/03,8210010035
- 8210010430 Forwards IE Insp Repts 50-259/82-25.50-260/82-25 & 50-296/82-25 on 820810-11 No noncompliance noted VERRELLI.D M Division of Project D Resident Programs G2/09/07 PARRISH G Tennessee Valley Authority 2pp 15570 211 24% Fiche 50-259.82/09/03.8210010430
- --B210010432 IE Insp Repts 50-259/82-25, 50-260/82-25 & 50-296/82-25 to B20810-11 No noncompliance noted Hayor areas inspected reactor secondary containment integrity problem & MBIV testing BROXS, E M. JAPE. F. Division of Engineering & Technical Programs B2/08/27 App 15570 213 24X Fiche 50-259, 82/09/03, 821001043)
- 8210150397 Forwards IE Insp Repts 50-259/82-28.50-260/82-28 to 820830-0903 No noncompliance noted VERRELLI.D M Division of Project & Resident Programs (82/07/20 PARRIS.H 0 Tennessee Valley Authority 2pp 15704 029 24X Fiche 50-259.82/09/20.8210150399
- --8210130406 IE Insp Repts 50-259/82-28,50-260/82-28 & 50-246/82-28 cn 820830-0903 No noncompliance noted Hajor areas inspected inservice insp program & inservice testing program review QIRARD, E H , BLAKE, J Division of Engineering & Technical Programs 82/09/16 4pp 15704 031 24% Fiche 50-259,82/09/20 8210150399
- 8210010097 Appraves revised commitment dates for Item 25 of App L to IE Insp Repts 50-259/81-19.50-260/81-19 & 50-294/81-19 & 1tem C 2 of App A to IE Insp Repts 50-259/82-12.50-260/82-12 & 50-294/82-12
 LEWIS.R C Division of Project & Resident Programs 82/09/22 PARRIS.H O Tennessee Valley Authority 1p 15565 001 24% Fiche 50-259.82/09/22.8210010097
- --8210010104 Requests extension to respond to App C. Item 23 in IE Inij Repts 80-259/81-19, 50-260/61-19 & 50-296/81-19 & Item C 2 in IE Inip Repts 50-289/82-12, 50-260/82-12 & 50-296/82-12 Responses will be submitted by 830101 & 821101, respectively MILLS.L.M. Tennessee Valley Authority 82/09/01 D'REILLY, J P Region 2. Office of Director ip 15565 002 24X Fiche 50-259, 82/09/22, 8210010097
- 8210010326 Forwards summery of 820908 enforcement meeting w/util to discuss corrective actions re leakage during shipment of low level waste & util plans for improving employee training O'RETLLY, J P Region 2, Office of Director 82/09/22 PARRIS.H & Tennessee Valley Authority 4pp 15569 188 24X Fiche: 50-259, 82/09/22,8210010326
- 8210010270 Ack receipt of supplemental 820701 ltr informing NRC of steps taken to correct Violation B noted in IE Insp Repts 50-257/81-26, 50-250/82-26 & 50-276/81-26 LEWIB.R C Division of Project & Resident Programs 82/09/24 PARRIS.H G Tennesses Valley Authority 1p 15573 183 24X Fiche. 50-259, 82/09/24,8210010290
- --B210010304 Forwards revised response to NRC B1102B itr re Violeties I noted in IE Insp Repts 50-259/82-26, 50-260/82-26 & 50-296/82-26 Corrective actions R factor returned to within limits & revision to Tech Base approved MILLB, L. M Tennessee Valley Authority 82/09/01 D'REJLLY. J F Repion 2, Office of Director 3pp 15573-184 24X Fichs 50-259, 82/09/24, 8210010290

ì

- 8210220370 Forwards IE Insp Repts 50-259/82-29, 50-260/82-29 & 50-296/82-29 on 820906-10 No noncompliance noted VERRELLI.D M Division of Project & Resident Programs 82/09/30 PARFIELS M G Tennessee Valley Authority 2pp 15779 220 24X Fiche 50-259, 82/09/30, 8210220390
- --8210220401 IE Insp Repts 50-259/82-29, 50-260/82-29 & 50-296/82-29 on 820906-10 No noncompliance noted Major areas inspected Unit 2 refueling & maint outage & procedural compliance of health physics-related practices by workers COLLINS.T R. BARR.K P Division of Engineering & Technical Programs 82/09/27 Spp 15779 222 24X Fiche 50-259,82/09/30,8210220390
- 6210080219 Forwards revised request for relief from Inservice Insp 7 re inaccessible welds in piping penetrations & under rigid pipe restreaints Dest effort visual exam will be performed during sys hydrostatic pressure test
 MILLS.L M Tennessee Valley Authority 82/10/04 DENTON.H R
 Diffice of Nuclear Reactor Regulation. Director 3pp 15638 083
 244 Fiche 50-259.82/10/04.8210080219
- B20B190233 IE Info Notice 80-35, Suppl 1, "Leaking & Dislodged I-125 Implant Seeds " Svc list ent! COBB.L I Division of Fuel Facilities, Materials & Safeguards " 82/10/06 Consoltdated Edison Co of New York 66pp 15761 250 24K Fiche 50-000, 82/10/06 8208190233
- 8210150218 Forwards update of present work & schedule for implementation of insps required under IE Bulletins 79-02 & 79-14 Phase II evaluation will not be completed until 84080:
 MILLS.L M Tennessee Valley Authority 82/10/07 D'REILLY, J P Region 2. Office of Director 2pp 15705 276 24X
 Fiche 50-259.82/10/07.8210150218
- 8208190238 IE Bulletin 82-03. "Stress Corrosion Cracking in Thick-Wall. Large-Diameter, Stainless Steel, Recirculation Sys Piping at BNR Plants " Svc list encl DEYGUNG.R C Director's Office, Office of Inspection and Enforcement B2/10/14 Consolidated Edison Co of New York 115pp 15810 125 24X Fiche 50-000, 82/10/14,8208190238
- 5 Reportable occurrences, LERs & related correspondence
- 6210120129 Advises of need for in-depth evaluation of potential for unacceptable interaction between control rod drive sys & nonessential control air sys Margin of safety inhorent in licensed design basis should be promptly restored MICHELSON, C. Director's Office BO/OB/18 DENTON, H.R. Office of Nuclear Reactor Regulation, Director 3pp 15692 150 24X Fiche 50-296,80/08/18.8210120129
- G209300170 Forwards LER 82-071/01T-0 GREEN.H J Tennessee Valley Authority 82/09/24 O'REILLY, J.P. Region 2, Office of Director 1p 19553 281 24X Fiche 50-259.82/09/24.8209300170
- --8209300175 LER 82-071/01T-0 on 820909, HPC1 condensate storage tank low level switches LS-73-56A & LS-73-56D failed to operate Caused by dirty & corroded level switches activating plates Plate points cleaned tRBY. B J Tennessee Valley Authority 82/09/24 Region 2, Office of Director 2pp 15553 282 24X Fiche 50-259, 82/09/24, 8209300170
- 8210060409 Forwards LER 82-067/03L-0 GREEN-H J Tennessee Valley Authority 82/09/30 D'REILLY, J P Region 2, Office of Director 1p 13615 319 24X Fiche 50-239,82/09/30.8210060409
- --8210060412 LER 82-067/03L-0 on 820901.during normal operation, while performing fire protection surveillance insp, heat detection ione 6 for spreader room A common to Units 1 & 2 found inoperable Caused by loose fire protection panel relay MURPMY. D E Tennessee Valley Authority 82/09/30 Region 2, diffice of Director 2pp 15415 320 24X Fiche 50-259,82/09/30, 8210060409
- 62:0060414 Forwards LER 82-06B/03L-0 GREEN.H J Tennessee Valley Authority 82/09/30 O'REILLY, J P Region 2. Office of Director 1p 15615 004 24X Fiche 50-259.82/09/30.8210060414
- --8210060422 LER 82-068/03L-0 on 820902, while performing primary containment isolation valve leak rate test. A hydrogen analyzer became inoperable Caused by failed hydrogen sample intet pump power relay contacts
 CARTER: 8 D Tennessee Valley Authority 82/09/30 Region 2, Office of Director 2pp 15615 005 24X Fiche 50-259, 82/09/30, 82(0060414

- 8210130565 Forwards LER 82-049/03L-0 GREEN H J Tennessee Valley Authority 82/10/05 O'REILLY, J P Region 2. Office of Director 1p 15683 110 24X Fiche 50-259,82/10/05,8210130565
- --8210130567 LER 82-069/03L-0 on 820907, during startup testing, rod sequence control sys found inoperable Caused by failure of GE sequence generator card Model 17589480AA Card replaced & testing satisfactorily completed IRBY. B J Tennessee Valley Authority 82/10/05 Region 2, Office of Director 2pp 15683 111 24X Fiche 50-239, 82/10/05, 8210/30565
- 8210130165 Forwards LER 82-072/03L-0 QREEN H J Tennesses Valley Authority 82/10/07 O'REILLY, J P Region 2. Office of Director 1p 15673 054 24X Fiche 50-259.82/10/07.8210130165
- --8210130169 LER 82-072/03L-0 on 820908, during startup, rod worth minimizer (RMM) applied rod blocks when rod 30-51 selected Caused by listing two rods twice in RMM sequence due to tuping error RMM sequence corrected & returned to svc NAVE.E Tennessee Valley Authority 82/10/07 Region 2, Defice of Director 2pp 15673 055 24X Fiche 50-259, 82/10/07, 8210130145
- 8210130172 Forwards LER 82-075/01T-0 OREEN, H J Tennessee Valley Authority 82/10/07 O'REILLY, J P Region 2, Office of Director 1p 15673 046 24X Fiche 50-259, 82/10/07, 8210130172
- -8210130176 LER 82-075/01T-0 on 820924, four degraded voltage relays, three timers & one loss-of-voltage relay found to be outside allowable Tech Spec setpoint range Caused by setpoint drift Relays recalibr & returned to svc CHRISTOPHER, W Tennessee Valley Authority 82/10/07 Region 2, Office of Director 2pp 15673 047 24X Fiche 50-259,82/10/07.8210130172
- 8210130427 Forwards LER 82-070/03L-0 GREEN.H J Tennessee Valley Authority 82/10/07 G'REILLY, J P Region 2, Office of Director ip 15681 160 24X Fiche 50-259, 82/10/07, 8210130427
- --8210130438 LER 82-070/03L-0 on 820908, while calibr reactor protection sys high-water level switches on scram discharge tank-level switch LS-82-45E operated at 27 gallons, contrary to Tech Specs Caused by calibr drift on level switch SL-305-EI-X IRDV.B J Tennessee Valley Authority 62/10/07 Region 2, Office of Director 3pp 15481 161 24X Fiche 50-259,82/10/07,8210130429
- 8210220053 Forwards LER 82-073/03L-0 QREEM, H J Tennessee Valley Authority 82/10/08 O'REILLY, J P Region 2. Office of Director 1p 15778 204 24X Fiche 50-259,82/10/08,8210220053
- --8210220057 LER 82-073/03L-0 on 820910.while performing maint on diesel generator A.fuel oil flowed out discharge filter drein valve when transfer pumps supplied oil to day tank Caused by personnel error Responsible person reinstructed PORTER.M R Tennessee Vallay Authority 82/10/08 Region 2. Office of Director Ip 15778 205 24% Fiche 50-257,82/10/08,8210220053
- 8210290054 Forwards followup LER 82-023/03X-2 OREEN H J Tennessee Valley Authority 82/10/13 O'REILLY, J P Region 2. Office of Director 1p 15854 050 24X Fiche 50-257, 82/10/13, 8210270054
- ~-B210290057 Followup LER B2-023/03X-2 on 820327, recirculation pump 1A tripped due to spurious generator starter relay operation Caused by Hi-temp relay trip Relay reset in 20 minutes & pump returned to avc No recurrence control planned CMRISTOPHER, W Tennessee Valley Authority B2/10/13 Region 2, Office of Director 3pp 15854 051 24X Fiche 50-259,82/10/13. 8210290054
- 8210290062 Forwards updated LER 82-042/03X-1 OREEN H J Tennessee Valley Authority 82/10/13 O'REILLY, J P Region 2, Office of Director 1p 15853 339 24X Fiche 50-259, 82/10/13, 8210290062
- --8210270066 Updated LER 82-042/03X-i on 820\(\)18, quarterly Surveillance Insp 3 2 8 for testing of HPCI & RCIC vacuum relief velves not performed per ASME Section XI Caused by personnel error Foreman masplaced performance reminder CAMPBELL.O. Tennessee Valley Authority 82/10/13 Region 2, Office of Director 2pp 15853 340 24X Fiche 50-259, 82/10/13, 8210270062

- 9210290317 Forwards updated LER 82-031/03X-2 GREEN H J Tennessee Valley Authority 82/10/13 O'REILLY, J P Region 2. Office of Director 1p 15853 080 24X Fiche 50-259, 82/10/13, 8210270317
- --B210270321 Updated LER 82-031/03X-2 on 820510 hydrogen analyzer B inoperable due to failure of hydrogen sample inlet pump Caused by failure of Allen Bradley relay Model 700-N400A1 contacts Relay investigation results expected 830215 CARTER: S Tennessee Valley Authority 82/10/13 Region 2. Office of Director 2pp 15853 CB1 24X Fiche 50-299.82/10/13. 8210290317
- 82:0290368 Forwards LER 82-077/03L-0 QREEN-H J Tennessee Valley Authoraty 82/10/15 O'REILLY. J P Region 2. Office of Director 1p 15853 083 24X Fiche 50-255, 82/10/15.8210270368
- --B210290371 LER 92-077/03L-0 on 820916.control rod 3B-39 declared inoperable due to fuse failure alarms & high-water level alarms indicating Gaused by control rod drive hydraulic control unit accumulator level switch being grounded MWRHY. DE Tennessee Valley Authority B2/10/15 Region 2, Office of Director 2pp 15853 084 24% Fiche 50-259.82/10/15.
- 8210260381 Forwards LER 82-076/03L-0 GREEN, H J Fennessee Valley Authority 82/10/19 0'REILLY, J P Region 2. Office of Director 1p 15803 359 24X Fiche 50-259, 82/10/19, 8210260381
- --8210260407 LER 82-076/03L-0 on 820925, turbine bldg roof vant monitor CAM 1-90-251 became inoperable Caused by failure of pump drive motor model 6K562C due to end of natural life Drive motor replaced,

 THDRPE, A A Tennessee Valley Authority 82/10/19 Region 2, Office of Director 2p 15803 360 24X Fiche 50-259, 82/10/19, 8210260381
- 8210260212 Forwards updated LER 82-067/03X-1 QREEN,H J Tennessee Valley Authority 82/10/20 O'REILLY, J P Region 2. Office of Director ip 15799 153 24X Fiche 50-259,82/10/20,8210260212
- --8210260222 Updated LER 82-067/03x-1 on 820901, heat detection zone 6 for spreader from A & preaction sprinkler automatic initiation circuit found inoperable Gaused by loss fire protection panel relay Relay repositioned & clipped in place HURPHY. D E Tennessee Valley Authority 82/10/20 Region 2, Office of Director 2pp 13799 184 24x Fiche 50-259, 82/10/20, 82/10260212
- T Hearing transcripts on non-antitrust matters
- 8210070133 Testimony of JW Hotton answering ASLAB questions on low level radwaste mgt options Availability of adequate space to dispose of low level wastes in next 5 yrs uncertain Certificate of Svc enci HUTTON, J W Tennessee Valley Authority 82/10/01 12pp. 15627 031 24% Fiche 50-259,82/10/01,8210070133
- DOCKET 50-240 BROWNS FERRY NUCLEAR POWER BTATION, UNIT 2 F. Security, medical, emergency & fire protection plans
- 8209170101 Forwards minor revisions to proposed physical security plan Revisions withheld (ref 100FR73 21) HILLS.L M Tennessee Valley Authority 82/08/31 DENTON:H R Office of Nuclear Reactor Regulation: Director. 2pp 14910 081 24X Fiche: 50-259:82/08/31.8209170101.
- 8210250236 Forwards security plan table of contents Table of contents withheld (ref 10CFR73 21)

 KAMMER.D B Tennesse Valley Authority 82/10/19 DENTON, H R
 Office of Nuclear Reactor Regulation, Director 1p 15788 362 24X

 Fiche 30-259.82/10/19.8210250236
- 8210250244 Forwards revisions to physical security plan Revisions withheld (ref 10CFR73, 21)
 KAMMER, D. B. Tennesses Valley Authority 82/10/17 DENTON, H. R. Diffice of Nuclser Reactor Regulation, Director 1p. 15788-345 24X
 Fiche. 50-250, 82/10/17, 8210250244

G Adjudicatory correspondence

- 8210120291 Response to ASLAB 820920 order to provide any supplemental info re questions posed to util Authorization is for 5-yr storage of low level radwaste, w/o limit on use of modules for interim use on backup basis RAWSON, R J. Hearing Branch 4 82/10/08 Bpp 15652 071 24x Fiche 50-259, 82/10/08,8210120291
- --8210120297 Affidavit of P Loysen re application for storage of lov level raduste No restriction requested or contemplated limiting use of modules only to interim use on backup basis LOYSEN.P Advanced Fuel 7. Spent Fuel Licensing Branch 82/10/68 23pp 13652 079 24X Fiche 50-259.82/10/08.8210120291
- ~-B21012030B Affidavit of JR McGrath Timely request for renewal of facility iscense filed for Bratig.NV low level radwaste disposal facility NS State Board of Health voted not to renew facility license MCGRATH, JR Assistant Director for State Agreements Programs 82/10/08 2pp 15852 102 24X Fiche 50-259, B2/10/08, B210120248
- ~-8210120316 Affidavit of SN Salomon Southeast Interstate Low Level Radwaste Mgt Compact agreed to close Barnwell.SC facelity on 721231 & open new site on 711231 Certificate of Svc encl SALOMON.S N Assistant Director for State Agreements Programs 82/10/08 4pp 15652 104 24X Fiche 50-259.82/10/08.82101202.1
- 82(0250063 Telecopy message of motion for ASLAB to grant 30-day extension to respond to ASLB 820920 order Time necessary to explore settlement possibilities of all matters in controversy PYLE.R B Pyle, R B 82/10/20 Docketing & Services Branch (g. 15787-061 24X Fiche 50-259,82/10/20.8210250063
- 8210260429 Motion for extension of time until B21121 to respond to 820920 order Time necessary to explore possibilities of settlement Certificate of Svc encl PMER B Pyle, R B 82/10/20 Atomic Safety and Licensing Appeal Panel 2pp 15806 036 24% Fiche 50-259,82/10/20. B210260429
- P Operating license stage documents & correspondence
- 8210070255 Forwards response to MRC request for addl info on NUREO-0612, "Control of Meavy Loads of Nuclear Power Plants"
 HILLS.L M Tennessee Valley Authority 82/09/28 VABSALLO, D & Operating Reactors Branch 2 56pp 15635 243 24X
 Fichs 50-259, 82/09/28, 8210070255
- 8210080218 Forwards add1 info in response to NRC 820808 request re NVREO-0737. Item II K 3 24. "Adequacy of Space Cooling for HPCI & RCIC" MILLS.L M Tennessee Valley Authority 82/10/04 DENION.H H Defice of Nuclear Reactor Regulation. Director 2pp 15608 091 24X Fiche 50-259.82/10/04.8210080218
- 8210130142 Forwards description of final mods & changes to DHR scrad sys & short-term interim commitments for Unit 2 Mods will be implemented for Unit 2 before startup from Reload 4 outage & subsequent Units 1 & 3 outages MILLS.L.M. Tennessee Valley Authority 82/10/06 DENTON.H R Office of Nuclear Reactor Regulation. Director 4pp 15673 086 24% Fiche 50-259.82/10/06.8210130142
- 8210250067 Application to amend License DPR-52 to accommodate Reload + Cycle 5 operation & outage-related mods Approval by 830112 requested to avoid impacting refueling & startup HILLS.L.M Tennesse Valley Authority 82/10/15 DENTON.H R Office of Nuclear Reactor Regulation, Director 2pp 15792 145 24% Fiche 50-260,82/10/15.8210250067
- --8210250070 Proposed Tech Spec changes, accommodating Reload 4.Cycle 5 operation & outage-related mods ** Tennesses Valley Authority 82/10/15 82pp 15792 147 24% Fiche: 50-260, 82/10/15,8210250067
- --8210250074 "Supplemental Reload Licensing Submittal for Browns Ferra Nuclear Plant: Cycle 5. Unit 2. Reload 4 " HILF. C. L. , ZARBIS, W. A. CHARNLEY, J. S. General Electric Co Y1003501A40 82/07/31 3&pp 15792 230 24X Fishe 50-260, 82/10/15, 8210250067

ì

1

--8210250077 Errata & Addenda Sheet 4 to NEDD-24088-1, "LOCA Analysis for Browns Ferry Nuclear Plant Unit 2 " • General Electric Co NEDD-24088-1 NO4 ERR 82/07/31 Bap |5792,255, 24% Fiche 50-260,82/10/15,8210250067

DOCKETED ITEMS

- --22[0250078 Errata & Addenda Sheet 5 to NEDD-24088-1, "LOCA Analysis for Browns Ferry Nuclear Plant.Unit 2"
 a General Electric Co NEDD-24088-1 NO5 ERR 82/08/31 2pp 15792 263 24% Fiche 50-260, 82/10/15,8210250067
- F210250076 Forwards revision to 821006 implementing procedures
 hILLS.L. M. Tennessee Valley Authority 82/10/15 DENTON,H R
 difice of Nuclear Reactor Regulation, Director 1p 15793 058 24X
 fiche 50-257, 82/10/15,8210250076
- -8210250101 Revised implementing procedures • Tennessee Valley Authority 82/10/15 16pp 15793 059 24X Fichs 50-259 82/10/15 8210250094
- 9 Inspection reports. IE Builetins & correspondence
- Rai0080015 Addi response to FOIA request for 19 categories of info re nuclear reactor events U safety problems Forwards documents listed in App A Documents in App B completely withheld (ref FOIA Exemption 5) FELION, J M Division of Rules and Records 82/07/12 UDELL,R A Critical Mass Energy Project 9pp 15665 027 24X Fiche 50-000.82/07/12.8210080015
- -8210080118 Systematic assessment of licensee performance notes refacility evaluation for Apr 1979-Mar 1980

 RRC No Detailed Affiliation Given 80/03/31 App 15667 315 24X Fiche 50-000, 82/07/12-8210080015
- 5210150105 Notifies that corrective actions re IE Insp Repts SO-259/01-13 50-260/01-13 50-276/01-13 delayed Procedure PPH M8063 re exam of CSGG items to be revised by 820915 DC-ER.J A Tennessee Valley Authority 82/07/13 O'REILLY, J Pegion 2. Office of Director 1p 15701 159 24X Fiche 50-259.82/07/13.8210150105
- E210220151 Provides supplemental response to NRC ltr re violations noted in IE insp Repts 50-259/82-10.50-260/82-10 & 30-275/82-10 Div of procedures Manual NB2AD will not be revised until 821001 due to scope of effort involved MILLS.L M Tennessee Valley Authority 82/08/18 0'REILLY, J P Region 2 Office of Disctor 1p 15778 106 24x Fiche 50-259.82/08/18.8210220151
- 65:100:0035 Confirms 820708 site meeting to discuss recent violations re radwaste shipments Agenda encl
 10'REILLY JP Region 2, Office of Director 82/09/03 PARRIS.H & Tennessee Valley Authority 2pp 15565 166 24X
 Fiche 50-259.82/09/03.8210010035
- #210010430 Forwards IE Insp Repts 50-259/82-25,50-260/82-25 & 50-294/82-25 on 820810-11 No noncompliance nated VERRELLI.D II Division of Project & Resident Programs 82/09/03 PARRES.I 6 Tennessee Valley Authority 2pp 15570 211 24X Fiche 50-259,62/09/03,8210010430
- -8210010432 IE Insp Repts 50-259/82-25,50-260/82-25 & 50-296/82-25 on 820910-11 No noncompliance noted Major areas inspected reactor secondary containment integrity problem & MSIV testing GRCCAS:E N. JAPE,F Division of Engineering & Technical Programs 82/08/27 4pp 15570 213 24% Fiche 50-259,82/09/03,8210010430
- E2:0150379 Forwards IE Insp Repts 50-259/82-28:50-260/82-28 & 50-296/82-28 on 820830-0903 No noncompliance noted VERRELLE, DM Division of Project & Resident Programs 82/09/20 PARRIS, H O Tennessee Valley Authority 2pp 15704 029 24X F(che 50-259:82/09/20:8210150399
- --8210150405 IE Insp Repts 50-259/82-28,50-240/82-28 & 50-276/82-28 on E20830-0903 No noncompliance noted Major areas inspected inservice insp program & inservice testing program review QIRARD.E H. BLAKE.J Division of Engineering & Technical Programs 82/09/16 4pp 15704 031 24X Fiche 50-259,82/09/20, E210150399
- 62:00:0077 Approves revises commitment dates for Item 25 of App C to IE Insp Repts 50-259/81-17, 50-260/81-17 & 50-294/81-17 & 1tem C 2 of App A to IE Insp Repts 50-259/82-12, 50-260/62-12 & 50-294/82-12
 LEWIS.R C Division of Project & Resident Programs 82/09/22 PARRIS.H G Tennessee Valley Authority ip 15565 001 24% Fiche 50-259, 82/09/22, 8210010097
- --8210010104 Requests extension to respond to App C. Item 25 in IE Insp Repts 50-259/81-19.50-260/81-19.50-296/81-19. \$10-296/81-19. \$10-296/82-12. \$10-296/82-12. \$20-296/

- 8210010326 Forwards summary of B20908 enforcement meeting w/util to discuss corrective actions re leakage during shipment of low level waste & util plans for improving employee training O'REILLY.J P Region 2. Office of Director 82/09/22 PARRIS.H G Tennessee Valley Authority 4pp 15569 188 24X Fiche 50-259.82/09/22.8210010326
- 8210010270 Ack receipt of supplemental 820701 ltr informing NRC of steps taken to correct Violation B noted in IE Insp Repts 50-237/61-26. S0-240/82-26 & 50-296/81-26 EBUIS.R C Division of Project & Resident Programs 82/07/24 PARRIS.H G Tennessee Valley Authority 1p 15573 183 24X Fiche 50-257, 82/07/24, 8210010270
- --8210010304 Forwards revised response to NRC 811028 ltr re Violation B noted in IE Insp Repts 50-259/82-26.50-260/82-26 & 50-276/82-26 Corrective actions R factor returned to within limits & revision to Tech Spec approved HILLS:L M Tennessee Vailey Authority 82/09/01 D'REILLY, J P Region 2. Office of Director 3pp 15573 184 24X Fiche 50-259, 82/09/24/8210010270
- 8210220390 Forwards IE Insp Repts 50-259/82-29,50-240/82-29 & 50-296/82-29 on 820904-10 No noncompliance noted VERRELLI, D H Division of Project & Resident Programs 82/09/30 PARRIS, H G Tennessee Valley Authority 2pp 15779 220 24X Fiche 50-259,82/09/30.8210220390
- --8210220401 IE Insp Repts 50-259/62-29, 50-260/82-29 & 50-296/82-29 on 820906-10 No noncompliance noted Major areas inspected Unit 2 refueling & maint outage & procedural compliance of health physics-related practices by workers COLLINS:T R . BARR.K P Division of Engineering & Technical Programs 82/09/27 5pp 15779 222 24X Fiche 50-259, 82/09/J0, 8210220390
- 8210080219 Forwards revised request for relief from Inservice Insp / re inaccessible welds in piping penetrations & under rigid pipe restraints Best effort visual exam will be performed during sys hydrostatic pressure test MILLS.L.M Tennessee Valley Authority 82/10/04 DENTON.H R Office of Nuclear Reactor Regulation, Director 3pp 18638 083 24X Fichs 50~259,82/10/04.8210080219
- 8208170233 IE Info Notice 80-35, Buppl 1, "Leaking & Dislodged I-125 Implant Seeds " Svc list encl COBB.L I Division of Fuel Facilities. Materials & Safeguards 82/10/06 Consolidated Edison Co of New York 66pp 15761 250 24X Fiche 50-000,82/10/06,8208190233
- 8210150218 Forwards update of present work & schedule for implementation of imaps required under IE Bulletins 79-02 & 79-14 Phase II evaluation will not be completed until 840801 MILLS.L.M Tennessee Valley Authority 82/10/07 O'REILLY.J P Region 2, Office of Director 2pp 15709 276 24X Fiche 50-259, 82/10/07.8210150218
- 8208190238 IE Bulletin 82-03, "Stress Corrosion Cracking in Thick-Wall, Large-Diameter, Stainless Steel, Recirculation Sys Piping at BMR Plants "Svc list encl. DEYQUNO,R C Director's Office, Office of Inspection and Enforcement 82/10/14 Consolidated Edison Co of New York 115pp 15810 125 24% Fiche 50-000 82/10/14 8208170238
- 8 Reportable occurrences, LERs & related correspondence
- 8210120127 Advises of need for in-depth evaluation of potential for unacceptable interaction between control rod drive sys & nonessential control air sys Margin of safety inherent in licensed design basis should be promptly restored MICHELSON.C Director's Office 80/08/18 DENTON.H R Office of Nuclear Reactor Regulation, Director 3pp 15692 150 24X Fichs 50-294, 80/08/18.8210120127
- 8210070490 Discusses 810406 deliberate pump trip Control switchen manipulated for two trains of circulating water sys resulting in pump trip FBI & util investigations failed to find culprit Event listed in safeguards watch list LANNING:W D. Director's Office 81/06/24 Director's Office. 1p 15644 358 24X Fiche 50-260,81/06/24,8210070490
- 8210010008 Responds to FOIA request for 19 categories of documents re nuclear reactor events & safety problems Korwards documents listed in App A. FELTON.J. H. Division of Rules and Records. 82/06/28 UDELL.R. A. Critical Mass Energy Project 15pp 15727.005 24X Ficher 50-000,82/06/28,8210010008

- --BIO7160079 Informs that manipulation of control switches for two trains of circulating water sys resulted in tripping of two circulating water pumps located in intake structure FOI (nvestigated & found no evidence of who operated switches LANNINO, W D Director's Office BI/06/24 Director's Office 1p 15729 250 24X Fiche 50-000,82/06/28,8210010008
- 8210260349 Forwards LER 82-029/03L-0 QREEM H J Tennesses Vailey Authority 82/10/19 G'RE(LLY, J P Region 2, Office of Director | p | 15802 347 24X Fiche 50-260-82/10/19, 8210260349
- --8210260353 LER 82-039/03L-0 on 82092) pinhole leak discovered in 3-inch fire protection line supplying water to cable-tray fixed water spray sys Caused by through-wall pitting corression attack Ultrasonic testing to be done by 830201 KECKETEEN.T Tennessee Valley Authority 82/10/19 Region 2, Office of Director 2pp 15802 348 24X Fiche 50-260,82/10/19, 8210200349
- 8210260417 Forwards LER 82-028/03L-0 GREEN.H J Tennesses Valley Authority 82/10/19 O'REILLY, J P Region 2. Office of Director 1p 15806 150 24x Fiche 50-260-82/10/19.8210260417
- ~-8210260446 LER 82-020/03L-0 on 920921, during refueling, turbine to reactor bidg doors 237 to 238 opened simultaneously, breaking secondary containment Caused by Folger Adams interlock sys faiture due to loose door latch screws
 TAYLOR.D Tennessee Valley Authority 02/10/19 Region 2.
 Office of Director 2pp 15806 151 24X Fiche 50-260,82/10/19,82(020417)
- T Hearing transcripts on non-antitrust matters
- 8210070133 Testimony of JW Hutton answering ASLAN questions on low level radwaste mgt aptions Avoitability of adequate space to dispose of low level wastes in next 5 yrs Uncertain Certificate of Svc encl HUTTON, JW Tennessee Valley Authority 82/10/01 12pp 15627 031 24X Fiche 50-259,82/10/01,8210070133
- DOCKET 50-261 H D ROBINSON PLANT, UNIT 2
 F Security, medical, emergency & fire protection plans
- 8210250202 Forwards scenario for 821014 small-scale emergency preparedness exercise
 ZIMMERNANAS R Carolina Power & Light Co 82/09/02 STOHR, J P
 Division of Emergency Preparedness & Operational Support 5pp
 15788 272 24X Fiche 50-261,82/09/02.8210250202
- 8210150396 Forwards IE Insp Rept 50-261/82-29 on 820816-19 No noncompliance noted LEWIS.R C Division of Project & Resident Programs 82/09/17 JUNES.J A Carolina Power & Light Co 2pp 15704 035 24X Fiche 30-261, 82/09/17, 8210150394
- --9210150401 IE Insp Rept 90-261/82-29 on 820016-19 No noncompliance mobed Hajor areas inspected radiological emergency preparedness CLINE.H E , JENKINS.O R Division of Emergency Preparedness & Operational Support 82/09/14 [15p] 15704 037 24X Fiche 50-261.82/09/17.8210150396

- --8210060354 "Radiation Shielding Analysis for HB Robinson Fechnical Support Ctr/Emergency Operating Facility " GRODE.R W. NATHAN.S.J. SCHMIDT.E.R. NUS Corp. RUS-4154 B2/06/30 54pp 15419 134 24X Fiche 50-261.82/10/04.8210060147
- H General correspondence
- 8210010028 Requests NRC direct all official correspondence to EE Utle, util vice-president due to 820930 retirement of JA Jones JONES JA Carolina Power & Light Co. 82/09/27 DENTON, HR Office of Nuclear Reactor Regulation, Director ip 15545-314 24 Fiche 50-000, 82/09/27, 8210010028
- 8210[30323 Requests changes to distribution list for NUREO-0020. "Licensed Operating Reactors - Status Summary Rept "
 21MMERMAN, S.R. Carolina Power & Light Co. 82/10/11 BFTEE.M P
 ADP Systems Development Branch. 2pp. 15683 361 24X
 Fiche 50-000.82/10/81.8210130323
- P Operating license stage documents & correspondence
- B2100B0015 Add1 response to FDIA request for 19 categories of info re nuclear reactor events & safety problems Forwards documents listed in App A Documents in App B completely withheld (ref FOIA Elemption 5) FELTON, J H Division of Rules and Records 62/07/12 Uncil, R A Critical Mass Energy Project 9pp 15665 027 24X Fiche 50-000, 82/07/12, 8210080015
- --8104220145 Provides results of discussion w/licensee to apparent problem u/proper sealing of containment purge valves. Licensee estimated that excessive leakage condition occurred at frequency of one time for every five valve cycles BANCE. H. C. Region 2, Atlanta. Office of the Director 7:1/10.27 JURDAN.E. L. Division of Reactor Operations Inspections 2pp 15668-165 24% Fiche 50-000, 87/07/12.8210080015
- 8210070007 Responds to FOIA request for eight categories of records resteam generators & steam turbines App A documents provided in R Udell FOIA Request 81-313 Forwards documents listed in App B FELTON, J K Division of Rules and Records 82/08/10 (QW, D J Winthrop, Stimson, Putnam & Roberts 9pp 15443 043 24x Fiche 50-000, 82/08/10.8210070007
- 8207180044 FOIA request for all internal non-public documents, means, evaluation repts & other mati dealing w/nuclear plant operations MCINNIS.D News & Observer 82/08/17 Office of Administration is 15860 064 24X Fiche 50-000.82/08/17, 8207180044
- 8210280013 Responds to FOIA request for all internal non-public documents, memos, evaluation repts & other math dealing w/ nuclear plant operations Forwards documents listed in App A FELTON, J N Division of Rules and Records 82/09/17 MCNNIH to News & Observer 5pp 15860 065 24X Fiche 50-000.82/09/17, 201028019
- --7908130654 Recommends licensee be requested to submit solid waster process control program & offsite dose calculation manual to aid in timely review of radiological effluent Tech Specs Forwards guidelines
 COLLINS, J T Effluent Treatment Systems Dranch 79/06/21
 SCHWERGER A Operating Reactors Branch 1 (Pre 791030) 10pp
 15860 092 24X Fiche 50-000,82/09/17.8210280013
 - 1107010140 Marked-up memo re B10323 engineering evaluation rept bn 810127 RCS leak Event & recommendations will be taken into consideration for further evaluation Info has been transmitted to utils DENTON.H R Office of Nuclear Reactor Regulation, Director 81/06/15 MICHELBON.C Director's Office 2pp 15860 229 24 Fiche 50-000,82/09/17.8210280013
 - | 108270422 Notifies that util B01201 request for license agent gas spent fuel pool storage expansion is acceptable Bafety evaluation to EIA imput encl

 KREQER, W E Assistant Director for Radiation Protection

 81/07/23 NOVAK, T Assistant Director for Operating Reactors

 Opp 15860 240 24X Fichs 50-000, B2/09/17, 8210280013
 - 3112020852 Forwards input to safety evaluation & EIA of proposed 5 % fuel pool storage capacity expansion Evaluation & appraisal based on info provided in 801201 ltr Proposed mod acceptable HOUSTON.R H Accident Evaluation Branch, 81/11/17, VAROA, & Operating Reactors Branch I 3pp 15860 246 24% Fiche. 50-000, 82/09/17, 8210280013

- --8201200658 Forwards technical evaluation of deviation in licensee B10303 response to requirements of NURCO-0737 Item II F 1-1 Yechnical evaluation should be forwarded to licensee for justification of deviations
 PREGER, W.E. Assistant Director for Radiation Protection 81/12/15 NOVAK.T M. Assistant Director for Operating Reactors 2pp. 15860-265 24X Fiche 50-000.82/09/17.8210280013
- --8201200662 "Add) Accident Monitoring Instrumentation," technical evaluation of response to Attachment 1 of Item II F 1 of NUREG-0737 Two major deviations from requirements unacceptable HUCHTON,R L Exxon Nuclear Co., Inc. (subs. of Exxon Corp.) 81/(1/02 Spp. 15860 767 24% Fiche 50-000,82/09/17,8210280013
- 8203220514 Forwards safety evaluation & EIA supporting util 820128 request to allow use of circulating water pimp discharge flow as backup source for dilution in calculating radioactive liquid effluent release when pump out of syc HOUSTON.R W Assistant Director for Radiation Protection 82/02/26 NOVAK, T M Assistant Director for Operating Reactors 7pp 15861 017 24X Fiche 50-000.82/09/17.8210280013
- ~-8205050480 Forwards audit of procedures & training for pressurized thermal shock Control room emergency procedures remain weighted toward core cooling & do not go far enough in addressing pressurized thermal shock issue MAZETIS, G R NRC No Detailed Affiliation Given 82/04/15 THOMPSON, H & Division of Human Factors Safety 38pp 15861 045 24% Fiche 50-000,82/09/17,8210280013
 - 820915010A Provides requested add1 info re 820730 power operated relief valve block valve failure Maint errors made during previous activities listed BRODM.E.J. LANNING.W.D. Reactor Operations Analysis Branch 82/08/25 SEYFRIT.K.V. Reactor Operations Analysis Branch 15861-344 24X Fiche 50-000,82/09/17.8210280013
- --0210200042 Responds to encl E Urley 701229 request for extension to submit draft effluent Tech Specs Request unacceptable Util reason for extension not valid Draft Tech Specs must be submitted by 790215

 COLLINS, J T Effluent Treatment Systems Branch 79/01/08
 SCHWENCER, A Operating Reactors Branch I (Pre 791030) 1p 15860 087 24X Fishe 50-000, 82/07/17,0210280013
- --8210280082 "Dosimetry Placement for Steam Generator Workers " WARNOCK, R Institute of Nuclear Power Operations 82/01/31 13pp 15860 310 24% Fiche 50-000.82/09/17.8210280013
- 9210010051 Ack receipt of 820823 ftr requesting temporary relief from cornitments re-training of shift technical advisors Program approved & request forwarded to NRR for evaluation O'REILLY, JP Region 2. Office of Director 82/09/20 JONES, J A Carolina Power & Light Co 1p 15565-322 24X
 Ficho 50-000, 82/09/20, 8210010051
- 6210290197 Requests add1 info documenting how each criterion of tUREO-0737.1rem II B 3, "Post-Accident Sampling Sys" has been satisfied, in order to conduct post-implementation review Schedule requested within 20 days VAROA.S A Licensing Branch I 82/09/24 JONES.J A Carolina Power & Light Co. 10pp | 15876 247 24X Fiche 50-241.82/09/24, 8210290197
- 82:10050039 Advises that response to 820318 request for add1 info re NUREG-0737. Item II B I. "RCS Vents." will be submitted & nonths before end of first refueling scheduled to begin in Dec 1783
 EURYL II Carolina Power & Light Co 82/10/01 VARGA, 8 A Operating Reactors Branch 1 ip 15605 192 24%
 Fiche 50-261, 82/10/01, 8210050009
- 0210060013 Application to amend License DPR-23 consisting of revision to Tech Specs providing three auxiliary feedwater pumps operable prior to exceeding RCS temp of 350 F EURYLL W Carolina Power & Light Co 82/10/01 VARGA, S A Operating Reactors Branch 1 2pp 15615 074 24X Fiche 50-261, 82/10/01, 8210060013
- ---8210060016 Proposed revision to Tech Apecs providing three auxiliary feedwater pumps operable prior to exceeding RCB temp of 350 F * Carolina Power & Light Co 82/10/01 5pp 15615 076 24X Fiche 50-261.82/10/01.8210060013
- 8210150264 Forwards add1 info re plant-specific homogeneous number densities for matls & fluid in reactor vessel core region, per 820917 request for info re pressurized thermal shock ZIMMERMAN.S R Carolina Power & Light Co 82/10/07 VARGA.S A Operating Reactors Branch 1 7pp 15703 254 24X Fiche 50-261.82/10/07.8210150264

- 8210150198 Responds to 820707 request for rept documenting pressurizer power operated relief valve & pressurizer safety valve failures per NUREG-0737. Item II K 3 3 No failures or challenges identified from 810401 to present ZIMMERHAN.8 R Carolina Power & Light Co 82/10/08 VARGA.8 A Operating Reactors Branch 1 2pp [5707 271 24X Fiche 50-261.82/10/08.8210150198
- 8210190709 Forwards "Supplemental Info for Degraded Orid Voltage Analysis CP & L.HB Robinson Nuclear Generating Station Unit 2 " (in response to BiO131 request re adequacy of electrical distribution sys voltage EURY, L W Carolina Power & Light Co 82/10/14 VARGA, S A Operating Reactors Branch 1 3pp 15737 287 24X Fiche 50-261, 82/10/14, 8210190709
- --8210190720 "Supplemental Info for Degraded Grid Voltage Analysis, CP&L, HB Robinson Nuclear Gonerating Station Unit 2" NARAYANI, I V, FIELDS, W W, CASEY, B J Ebasco Services, Inc (subs of Enserth Carp) 82/07/30 209pp 15737 290 24X Fiche 50-261,82/10/14,8210190709
- 8210260475 Application to amend License DPR-23-revising Tech Specs to clerify in-place testing criteria used on safety-related HEPA filter sys & compliance w/more recent ANSI std EURY.L W Carolina Power & Light Co 82/10/22 VARGA.S A Operating Reactors Branch 1 2pp 15806 228 24X Fiche 50-261-82/10/22-8210260475
- --8210260482 Proposed Tech Spec changes clarifying in-place testing criteria used on safety-related HEPA filter sys & compliance w/more recent ANSI std & Carolina Power & Light Co 82/10/22 2pp 15806 230 24% Fiche 50-261,82/10/22,8210260475
- 8210260508 Application for amend to License DPR-23, revising Tech Spec to clarify limiting conditions of operation for pressurizer code safety valves EURY.L W Carolina Power & Light Co 82/10/22 VARGA, 8 A Operating Reactors Branch 1 2pp 15805 133 24X Fiche 50-261.822/10/22,8210260508
- --8210240511 Proposed Tech Spec 3 1 1 3 re pressurizer code safety valves

 * Carolina Power & Light Co 82/10/22 1p 15805 135 24X Fiche 50-241,82/10/22,8210240508
- 8210290358 Requests extension until 821215 for submittal of schedule re TMI Item II I 3, "Post-Accident Sampling Sys" NRC 820924 request for addi info significantly expanded scope of work ZIMMERMAN.S R Carolina Power & Light Co 82/10/26 VARGA, S A Operating Reactors Branch 1 p 15853 047 24X Fiche 30-261.82/10/26.8210290358
- O Inspection reports, IE Bulletins & correspondence
- 8210070007 Responds to FOIA request for eight categories of records re steam generators & steam turbines App A documents provided in R Udell FOIA Request 81-313 Forwards documents listed in App B FELTON.J M Division of Rules and Records 82/08/10 LONG.D.J Winthrop, Stimson, Putnam & Roberts 9pp 15645 063 24X Fiche 50-000.82/08/10.8210070007
- --B210070139 Forwards tabulated data on steam generator insp & maint at facilities Data should be provided to licensees
 IPPOLITO.T Operating Reactors Assessment Branch 82/04/01
 VAROA: Operating Reactors Branch 1, 5pp 15645 131 24X
 Fiche 50-000,82/08/10.8210070007
- --B210070172 Forwards info re steam generator integrity & insps at all operating PMRs.per 750320 & 21 requests Details of insps. including defect indications. tube plugging criteria & tubes plugged will not be provided except for Point Beach i GOLLER, K R Division of Reactor Licensing (NRR-1975 only) 75/03/24 MAGCARY.R R Division of Technical Review (NRR-1975 only) 3pp 15645 196 24X Fiche 50-000.82/08/10.8210070007
- 8210010173 Forwards IE Insp Rept 50-261/82-30 on 820810-12 No noncompliance noted VERRELLI,D M Division of Project & Resident Programs 82/09/08 JONES,J A Carolina Power & Light Co 2pp 15568 132 24X Fiche 50-261,82/09/08
- --B210010176 IE Insp Rept 50-261/B2-30 on B20B10-12 No noncompliance noted Major areas inspected post-refueling startup tests & closeout of earlier enforcement item BURNETT.P T , JAPE,F Division of Engineering & Technical Programs B2/09/02 6pp 1556B-134 24X Fiche 50-261, B2/09/0B, B210010173

- 8210150394 Forwards IE Insp Rept 50-261/82-29 on 820816-19 No noncompliance noted LEWIS.R C Division of Project & Resident Programs 82/09/1 JONES.J A Carolina Power & Light Co 2pp 15704 035 24X Fiche 50-261.82/09/17.8210150396
- --8210150401 IE Insp Rept 50-261/82-29 on 820816-19 No noncompliance noted Major areas inspected radiological emergency preparedness CLINE, N E. JENKINS, O R Division of Emergency Preparedness & Operational Support 82/09/16 15pp 15704 037 24X Fiche 50-261,82/09/17.8210150396
- 8210150493 Requests add1 info re util response to IE Bulletin 80-ii.
 "Masonry Wall Design " Info required by 821122 to complete
 revieu
 VAROA,S A Operating Reactors Branch 1 82/10/04 JONES, J A
 Carolina Power & Light Co 4pp 15717 271 24X
 Ficha 30-261.82/10/04.8210150493
- B20B190233 IE Info Notice 80-35, Suppl 1. "Leaking & Dislodged 1-125 Implant Seeds " Svc list enc! CDBB.L I Division of Fuel Facilities, Materials & Safeguards B2/10/06 Consolidated Edison Co of New York & Sopp 15761 250 24X Fiche 50-000,82/10/06,8208190233
- 9208190238 IE Bullotin 82-03. "Stress Corrosion Cracking in Thick-Wall-Large-Diameter, Stainless Steel, Recirculation Sys Piping at BWR Plants " Svc list encl BEYOUND, R C Director's Office, Office of Inspection and Enforcement 82/10/14 Consolidated Edison Co of New York 115pp. 15810 125 24X Fiche 50-000, 82/10/14,8208190238
- 8210220495 Ack receipt of 821008 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-261/82-27 LEWIS.R C Division of Project & Resident Programs 82/10/18 UTLEY.E E Carolina Power & Light Co ip 13779 009 24X Fiche 50-261.82/10/18.8210220495
- --B210220499 Responds to NRC 820908 ltr re violations noted in IE Insp Rept 50-261/82-27 Corrective actions changes to plant operations manual included in permanent change book & operations revisions status list updated twice weekly STARKEY.R B Carolina Power & Light Co 82/10/08 O'REILLY.J P Region 2. Office of Director 4pp 15779 010 24X Fithe 50-261.82/10/18.8210220495
- --8210220500 Forwards IE Insp Rept 30-261/82-27 on 820711-0810 % notice of violation
 LEWIS, R C Division of Project & Resident Programs 82/09/08
 JONES, J A Carolina Power & Light Co 2pp 15779 014 24X
 Fiche 50-261,82/10/18

- 8210190240 Forwards updated LER 80-027/01T-1 STARKEY, R B Carolina Power & Light Co B2/10/11 O'REILLY.J P Region 2. Office of Director Ip 15742 196 24X F(che 50-26/; 82/10/11, 8210190240
- --8210190244 Updated LER 80-027/01T-1 on 801122.relay RT-9 in reactor protection train A failed to re-energize during periodic test of reactor protection logic Caused by shorting of lead usire connection to coil wires Relay replaced CDX-H T Carolina Power & Light Co 82/10/11 Region 2. Offic of Director 4pp 15742 197 24X Fiche 50-261.82/10/11,
- 8210290074 Forwards updated LER 81-031/017-1 STARKEY,R B Carolina Power & Light Co 82/10/22 O'REILLY,J P Region 2, Office of Director 1p 15854 028 24X Fiche 50-261.82/10/22.8210290074
- --821027007B Updated LER 81-031/01T-1 on 811201 during hot shutdoun pressurfire PORV block valve operators did not fully shut block valves closed by improper maint Valves closed manually COX.H T Carolina Power & Light Co 82/10/22 Region 2. Off of Director 3pp 15854 027 24X Fiche 50-261.82/10/22. 8210290734
- 8210290333 Forwards LER 82-013/03L-0 STARKEY,R B Carolina Power & Light Co B2/10/22 O'RETLLY.J P Region 2, Office of Director 1p 15853 103 24X Fiche 50-261,82/10/22,8210290333
- --8210270337 LER 82-013/03L-0 on 820923, svc water pump A failed to restart following periodic test Caused by failed control power fuses fosses replaced & pump started & retested COX.H T Carolina Power & Light Co 92/10/22 Region 2, Offic of Director 2pp 15853 104 24X Fiche 50-261.82/10/22, 8210270333

DOCKET 50-263 MONTICELLO NUCLEAR GENERATING PLANT

- F Security, medical, emergency & fire protection plans
- 8210150385 Forwards IE Insp Rept 50-263/82-09 on 820703-0828 Ne noncompliance noted STREETER: JF Division of Project & Resident Programs 82/09/28 LARBON C E Northern States Power Co 2pp 15703 272 24X Fiche 50-263,82709/28
- ---8210150386 IE Insp Rept 50-263/82-09 on 820703-0828 No noncompliance noted Major areas inspected LER followup, operational safety verification, fire protection/prevention, security personnel qualifications, operator overtime & onsite review committee BROWN, C H , MADISON, A L , WALKER, R D Division of Project & Resident Programs 82/09/28 5pp 15703 274 24X Fiche 50-263,82/09/28,8210150385

- --8210010046 Proposed Tech Specs re surveillance, reactor protection contoring sys, jet pump surveillance, organization & steam line area temp switch deviation

 * Northern States Power Co 82/09/24 60pp 15565 183 24x Fiche 50-263 82/09/24 8210010036
- 9210050377 Forwards application for amend to License DPR-22, App A Amend changes Pages 207 % 209 to remove 3-cycle per minute min source range monitor count rate when two or fewer adjacent assemblies exist in quadrant MUSOLF. D. Northern States Power Co. 82/09/30 Office of Nuclear Reactor Regulation. Director ip 15615 340 24X Fiche 50-263,82/09/30,8210060377
- --0210060360 Application for amend to License DPR-22.App A Amend changes Pages 207 & 209 to remove 3-cycle per minute min source range monitor count rate when two or fewer adjacent assemblies exist in quadrant HUSQLF.D Northern States Power Co 092/09/30 4pp 15615 341 24X Fiche 50-263, 82/09/30.8210060377
- --8210060386 Proposed Tech Specs 3/4 10, removing 3-cycle per minute min source range monitor count rate when two or fewer adjacent assemblies exist in quadrant * Northern States Power Co 82/09/30 2pp 15615 345 24X Fiche 50-263, 82/09/30, 8210060377
- 8210130261 Submits addl inforce application for single loop operation livense amend, in response to NRC 820920 request MAPLHGR reduction factors reviewed by GE & found applicable to Cyrle 10 MUSCLF.D Northern States Power CO 82/10/05 Office of Nuclear Reactor Regulation, Director ip 15676-014 24X Fiche 50-263,82/10/05,8210130261
- GE10130260 Discusses implementation of NRC guidelines for working hours, provided in Generic Ltr 82-12 Revised guidelines have been implemented, w/exceptions of 72-h per wk limitation & relief from control board duties
 MUSQLF, D. Northern States Power Co. 82/10/07 Office of Nuclear Reactor Regulation, Director 2pp. 15676-012 24X
 Fische 50-000, 82/10/07, 8210130260
- e210150364 Forwards response to request for info in Sections 2 2 % 2 3 of Generic Ltr 81-07 re overhead handling sys Revised 9 month submittal, "Control of Heavy Loads" & review of special lifting devices also encl MUSDLF.D. Northern States Power Co. 82/10/11 Office of Nuclear Reactor Regulation. Director. 16p. 15715-102 24X Fiche 50-263.82/10/11.8210150364
- --BRIO150377 "Evaluation of Conformance w/NUREG-0612 for Drywell/Reactor Vessel Head & Dryer/Separator Sling Lifting Devices "
 SMITH.S K. VUGELI'N NUTECH (Nuclear Technology, Inc.)
 K49-77-008 82/09/29 14pp 157(5 118 24X
 Fiche 50-263,82/10/11.8210150364
- --8210150500 "Design Spec for Reactor Vessel Head Lifting Device " FISCHER.L., VGGEL,T N. SMITH.J K Inc.) NSP-77-001 ROO 82/09/24 Fiche 50-263,82/10/11.8210150364
- --8210150504 "Evaluation of Selected Special Lifting Devices for Compliance ω/NUREG-0612"
 SMITH.J K., VOGEL.T N. NUTECH (Nuclear Technology, Inc.)
 NSP-77-007 ROO 82/09/24 12pp 15715 141 24X
 Fiche 50-263,82/10/11.8210150364
- --8210150309 "Design Spec for Dryer & Steam Separator Siing Lifting
 Device"
 FISHER, L. VOCEL, T N. SMITH, J K NUTECH (Nuclear Technology,
 Inc.) NSP-77-003 ROO 82/09/24 9pp 15715 153 24X
 Fiche 50-263,82/10/11/8210150364
- 6210190479 Informs that control room & technical support ctr habitability sys mod.per NUREO-0737. Item II D 3 4 will be delayed until 830515 due to need for design work, untimely matl delivery & low productivity Revised schedule enci MUSDLF. D Northern States Power Co 82/10/13 Office of Nuclear Regulation, Director 3pp 15740 263 24X Fiche 50-263. 82/10/13.8210190479
- 8210250320 Confirmatory action ltr relections util will undertake as result of 821014 meeting at Region 3 ofc relectack indications found on welds on recinculation syspiping KEPPLER. J O Region 3. Office of Director 82/10/19 LARBON.C E Northern States Power Co. 2pp 15790 224 24X Fiche 50-263.82/10/19.8210250320

- 8210260209 Forwards check to complete fee payment for Addendum 1 to 801010 license amend request MUSOLF, D Northern States Power Co 82/10/22 DIGOS, R M License Fee Management Branch 1p 15799 152 24X Fiche 50-263,82/10/22, 8210260209
- O Inspection reports. IE Builetins & correspondence
- 8210080015 Add1 response to FOIA request for 19 categories of info re nuclear reactor events & safety problems Forwards documents listed in App A Documents in App B completely withheld (ref FOIA Exemption 5) FELTON, J M Division of Rules and Records 82/07/12 UDELL, R A Critical Mass Energy Project 9pp 15665 027 24X Fiche 50-000/08/07/12.8210080015
- -8105280476 Requests that regions confirm licenses submittal of rept for satisfactory implementation of Item 4 of IE Bulletin 79-26, Revision 1
 JORDAN, E. L. Division of Resident & Regional Reactor Inspection 81/05/18 GRIER, B. H. Region 1, Philadelphia, Office of the Director (81/03/01) O'RELLY, J. P. Region 2, Atlanta, Office of the Director (81/03/01) KEPPLER, J. G. Region 3, Chicago, Office of the Director (81/03/01) Ip 15668 I30 24X Fiche 50-000, 82/07/12, 8210080015
- 8210150389 Forwards IE Insp Rept 50-263/82-09 on 820703-0828 No noncompliance noted STREETER, J F Division of Project & Resident Programs 82/09/28 LARSON, C E Northern States Power Co 2pp 15703 272 24X Fiche 50-263, 82/09/28, 8210150385
- --8210150386 IE Insp Rept 50-263/82-07 on 820703-0828 No noncompliance noted Major areas inspected LER followup, operational safety verification, fire protection/prevention, security personnel qualifications, operator overtime & onsite review committee BROWN, C H , MADISON, A L , WALKER, R D Division of Project & Resident Programs 82/09/28 5pp 15703 274 24X Fiche 50-263,82/09/28,8210150385
- 8210130166 Confirms plans for 821014 meeting in Olen Eliun, IL to discuss proposed corrective action for cracks in welds on endcap of recirculation Loop A SPESSARD, R L. Division of Project & Resident Programs 82/10/05 LARSON, C E. Northern States Power Co. ip 15673 053 24X Fiche 50~263,82/10/05.8210130166
- 9208190233 IE Info Notice 80-35, Suppl 1. "Leaking & Dislodged I-125 Implant Baeds " Svc list encl COBB.L I Division of Fuel Facilities. Materials & Safeguards 82/10/06 Consolidated Edison Co of New York 66pp 15761,250 24X Fiche 50-000,62/10/06,8208190233
- B208190238 IE Bulletin 82-03, "Stress Corrosion Cracking in Thick-Wall, Large-Diameter, Stainless Steel, Recirculation Sys Piping at BMR Plants " Svc list encl DEYQUNO, R C Director's Office, Office of Inspection and Enforcement B2/10/14 Consolidated Edison Co of New York 115pp 15810 125 24X Fiche 50-000, 82/10/14.8208190238
- 82:0250320 Confirmatory action ltr re actions util will undertake as result of 82:014 meeting at Region 3 ofc re crack indications found on welds on recirculation sys piping KEPPLER. J O. Region 3. Office of Director 82:10/19 LARSON.C E Northern States Power Co 2pp 15790 224 24X
- 8 Reportable occurrences, LERs & related correspondence
- 8210150174 Forwards LER 81-020/03L-0 MAYER.L O Northern States Power Co 81/08/24 KEPPLER, J O. Region 3, Chicago Office of the Director (81/03/01) ip 15707 193 24X Fiche 30-263.81/08/24/8210150174
- --8210150180 LER 81-020/03L-0 on 810724.main steam leak revealed in drain line to condenser Caused by piping leaking immediately downstream of 45 degree sibow due to erosion & impingement resulting from steam & water flow from restricting orifice.
 TOBIN.P A Northern States Power Co 81/08/24 Region 3, Chicago, Office of the Director (81/03/01) ip 13707 174 24X Fiche 50-263.81/08/24.8210130174.
- 8210050182 PNO-III-82-103 on 820928, radiographs of recirculation loop cap A revealed four cracks extending from weld root into adjacent heat-affected zone No through-well cracking evident Repair procedures under evaluation WALKER, JORDAN, M Region 3, Office of Director 82/09/28 lp. 15603 344 24X Fiche 50-263, 82/09/28, 8210050182

- 8210150396 Forwards IE Insp Rept 50-261/82-29 on 820816-19 No noncompliance noted LEUIS.R C. Division of Project & Resident Programs 82/09/1 JONES.J A Carolina Power & Light Co 2pp 15704 035 24X Fiche 50-261.82/09/17.8210150396
- --8210150401 IE insp Rept 50-261/82-29 on 820816-19 No moncompliance noted Major areas inspected radiological energency preparedness CLINE, W E . JENKING, D R Division of Energency Preparedness & Operational Support 82/09/16 19pp 15704 037 24% Fiche 50-261,82/09/17,8210150396
- 3210150493 Requests add1 info re util response to IE Bulletin 80-11.
 "Matonry Wall Design " Info required by 821122 to complete
 review
 VARCA: S A Operating Reactors Branch 1 62/10/04 JQME6. J A
 Carolina Fower & Light Co 4pp 15717 271 24X
 Fiche 50-261.82/10/04.8210150493
- 8208190203 IE Info Notice 80~35. Suppl 1. "Leaking & Distodged I-125 Implant Seed: "Svc list enc! COBp.L 1 Division of Fuel Facilities. Raterials & Rafeguards 82/10/06 Consolidated Edison Co of New York 66pp 15761 250 24% Fiche 50~000.82/10/06.8208190233
- 8208190238 IE bulletin 82-03. "Stress Corrosion Cracking in Thick-Wall, Large-Diameter, Stainless Steel, Recirculation Sys Piping at EWR Plants " Syc list encl BEYDUNG: R C Birector's Office of Inspection and Enforcement 62/10/14 Consolidated Edison Co of New York 115pp 15810 125 24X Fiche 50-000, 62/10/14, 6208190238
- B210220495 Ack recript of 821008 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-261/82-27 LEWBER C Division of Project & Resident Programs 82/10/18 UTLEV.E E Carolina Power & Light Co ip 15779 009 24X Fiche 50-261.82710/18.8210220495
- --8210220499 Responds to NRC 82090B ltr re violations noted in IE Insp Rept 50-261/82-27 Corrective actions changes to plant operating namual included in permanent change book & operations revisions status list updated twice weekly BTARKEY,R B Carolina Power & Light Co 82/10/08 D'REJLLY, J P Region 2. Office of Director App 15779 010 24X Fithe 50-261,82/10/18,8210220495
- --8210220500 Forwards IE Insp Rept 50-261/82-27 on 820711-0810 & notice of violation LEMIS,R C Division of Project & Resident Programs 82/09/08 JONES,J A Caroline Power & Light Co 2pp 15779 014 24X Fiche, 50-261,62/10/18,8210220495
- --B210220501 Notice of violation from insp on 820711-0810 & Division of Project & Resident Programs 82/09/08 2pp 15779-016 24X Fisha 59-261-82/10/18-8210220495
- --8210220504 IE Insp Rept 50-261/82-27 on 920711-0810 Noncompliance noted adequate review procedures not implemented for Maint Procedure HPI-10 for safety-related instrument valve Itneuge.

 WEISE, S. BURGER, C. Division of Project & Resident Programs 82/707/02 189p. 13779 018 2244 Fiche 50-261.82/10/18.8210220495
- R Periodic operating reports & related correspondence
- 8210130242 Forwards monthly operating rept for Bept 1982 STARKEY,R B Carolina Power & Light Co 82/10/08 DEYOUNG,R C Ulrector's Uffice, Office of Inspection and Enforcement 19 15678 096 24X Fiche 50-R61.82/10/08.8210130242
- --8210130244 Monthly operating rest for Sept 1982 NORRIGHE Carolina Power & Light Co 82/10/05 3pp 15678 097. 24% Fiche: 50-261.82/10/08.8210130242
- S Reportable occurrences. LERs & related correspondence
- 8210220265 Forwards LER 82-012/03L-0.
 STARKEY,R.B. Carolina Fower & Light Co B2/10/06 D'REILLY, J. P. Ragion 2. Office of birector. ip. 15775 202 24X
 Fiche 50-261,82/10/05.8210220265
- --B210220267 LER 82-012/03L-0.on 820906.at 94% power, letdown relief valve CVC-203 lifted & would not reseat Caused by water hanner cue to operator error in realignment of charging pump from recirculation to normal operation. Operator counseled. COK.K. T. Carolina Power & Light Co. 82/10/06. Region 2. Office of Director 3pp 15776 203 24% Fiche 50-261, 82/10/06. 8210220265.

- 8210190240 Forwards updated LER 80-027/017-1 STARKEY,R B Carolina Power & Light Co 82/10/11 [] Fill! Region 2, Office of Director ip 19742 196 24x Fiche 50-261, 82/10/11, 8210190240
- --B210170244 Updated LER 80-027/017-1 on 801122, relay Ht Y to 11 protection train A failed to recently the during periodic test of reactor protection logic Caused by shorting of [ci) time connection to coil wires Relay replaced COX.H T Carolina Power & Light Co 82/10/11 Bagics 2 of Director App 15742 197 24X Fiche 50 Mil. 11/150:11 8210170240
- 8210290074 Forwards updated LER 81-031/017-1 STARKEY,R 8 Carolina Power & Light Co 42/10/22 10/44||L' Region 2, Office of Director 1p 15854 028 34: Fithe 50-261, 82/10/22, 8210290074
- --B210290078 Updated LER 81-031/01T-1 on B11203 during bot at pressurizer PORV black valve operators did not full, and black valves Caused by improper maint Valves closes naturally COX-H T Carolina Power & Light Co B2/10/22 hequal of Director 3pp 15854 029 24X Fache 90 261.02/10/21 82/02/0074
- B210290303 Forwards LER 82-013/03L-0 STARKEY, R B Carolina Power & Light Co 80/10/-, 1, first Region 2. Office of Director 1p 15051 101 241 Fiche 50-261, 82/10/22, 8210290333
- --8210290339 LER 82-013/03L-0 on 820923; svt water pine A failtrestart following periodic test Caused by failed control power fuses ruses replaced & pump started & returned COX-HT Carolina Power & Light Co. MA/10/AR. Najira of Director 2pp 15853-104 24X Fiche 00 Ahlikalana Ra10290333
- DOCKET 30-263 MONTICELLO NUCLEAR GENERATINO PLANS
- F Security, medical, emergency & fire protection plans
- B210150385 Forwards IE Insp Rept 50-263/82-09 on D304 strong noncompliance noted STREETER J F Division of Project & Resident Programs for LARSON, C E Morthern States Power Co 2pp 15/0120, 30 Fiche 30-243, 82/09/28, 8210150385
- --8210150386 IE Insp Rept 50-243/82-09 on 840/81 Minite; -, noted Mayor areas inspected LER follows, operations at a trai, varification fire protection/provention actualty sers it qualifications operator overtime & onette teveral waster (ROSM), C. H. MADISON, A. L. MALKER, R. D. Division of Fregrid Resident Programs 82/09/28 5pp 15/01 8/4 44 Fiche 50-243,82/09/28,8210130385
- 8210260178 Requests that R Walker be added to link 1 (#). 'I to provide for unescorted access to vital to proteited areas KEPPLER, J O Region 3. Office of Director (0.//10). Id.: Northern States Fower Co. ip. 15799 160 244 Links (7. %). 82/10/20, 8210260198
- P Operating license stage documents & correspondents
- 8210040005 Responds to 820825 htm he spent fuel russes in the notification requirements of shipments of predactive resistance in 100FR73 37 MENCERN B Region 3: Office of Director MacGiffs 14 th Minnesota. State of 2pp 15577 262 24x higher as to 8210040005
- 8210010060 Forwards modified into to 820707 supplement) and supplement of the supple
- 8210010036 Forwards proposed amend to License OPA Addressing Space in areas of surveillance, reactor protection exists the systype pump surveillance, organization is steam time and temp switch deviation MUSCLF. D. Northern States Power Co. 82/09/24 Cffile at Reactor Regulation, Director 1p 15565 172 24s Fiche: 50-263, 82/09/24, 8210010036.
- --8210010041 Proposed amend to License DPR-J2. changing leta Section areas of surveillance-reactor protection menitating bit in pump surveillance-organization & steam line area between the deviation HUSDLF, D. Northern States Power Co. 82/09/24 1283 19, 24X Fiche 80-263,82/09/24,8210010036

- --8210010046 Proposed Tech Specs re surveillance, reactor protection monitoring sys, jet pump surveillance, organization & steam line area temp switch deviation

 # Northern States Power Co 82/09/24 40pp 15565 183 24X Fiche 50-263, 82/09/24, 8210010036
- 9210060377 Forwards application for amend to License DPR-22, App A Amend changes Pages 207 & 209 to remove 3-cycle per minute min source range monitor count rate when two or fewer adjacent assemblies exist in quadrant MUSQLF, D. Northern States Power Co. 82/09/30 Office of Nuclear Regulation, Director ip 15615-340 24X Fiche 50-263, 82/09/30, 8210060377
- --82100603BO Application for amend to License DPR-22. App A Amend changes Pages 207 & 209 to remove 3-cycle per minute min source range monitor count rate when two or fewer adjacent assemblises exist in quadrant MUSOLF. D. Northern States Power Co. 82/09/30 4pp 15615-341 24X Fiche 50-263, 82/09/30, 8210060377
- --8210050386 Proposed Tech Specs 3/4 10.removing 3-cycle per minute min source range monitor count rate when two or fewer adjacent assemblies exist in quadrant + Northern States Power Co 82/09/30 2pp 15615 345 24X Fiche 50-263,82/09/30,8210040377
- 82:0130261 Submits addl info re application for single loop operation license amend in response to NRC 820920 request MAPLHGR reduction factors reviewed by GE & found applicable to Cycle 10 MUSDLF, D. Northern States Power Co. 82/10/05 Office of Nuclear Reactor Regulation, Director ip 15676-014 24X Fiche 50-263.82/10/05.8210130261
- 8210130260 Discusses implementation of NRC guidelines for working hours, provided in Generic Ltr 82-12 Revised guidelines have been implemented, w/exceptions of 72-h per wk limitation & relief from control board duties MUSQLF, D. Northern States Power Co. 82/10/07 Office of Nuclear Reactor Regulation, Director 2pp. 15674-012 24% Fiche 50-000, 82/10/07, 8210130260
- B210150364 Forwards response to request for info in Sections 2 2 % 2 3 of Generic Ltr 81-07 re overhoad handling sys Revised 9 month submittal, "Control of Heavy Loads" & review of special lifting devices also enc!
 MUSULF.D Northern States Power Co 82/10/11 Office of Nuclear Reactor Regulation, Director into 15715 102 24X
 Fiche 30-263, 82/10/11.8210150364
- -8210150377 "Evaluation of Conformance w/NUREG-0612 for Drywell/Reactor Vessel Head & Dryer/Separator Bling Lifting Devices " SHITH, St. VOGELT N NUTECH (Nuclear Technology, Inc.) NSP-77-008 82/09/29 14pp 15715 118 24X Fiche 50-263.82/10/11.8210150364
- --8210150500 "Design Spec for Reactor Vessel Head Lifting Device " FISCHER. L. VOGEL, T. N. SMITH, J. K. NUTECH (Nuclear Technology, Inc.) NSP-77-001 ROO 82/09/24 9pp 15715 132 24X Fiche 50-263,82/10/11.8210150364
- --8210150504 "Evaluation of Selected Special Lifting Devices for Compliance ω/NUREG-0612"

 SMITH.J K., VOSELT N. NUTECH (Nuclear Technology, Inc.)
 NSP-77-007 RO 82/09/24 12pp 15715 141 24x
 Fichs 50-263.82/10/11.8210150364
- --8210150509 "Dosign Spec for Dryer & Steam Separator Sling Lifting Device" FISHER, L., VDOEL, T. N., SMITH, J. K. NUTECH (Nuclear Technology, Inc.) NSP-77-003 ROO 82/09/24 9pp 15715 153 24X Fiche 50~263,82/10/11,8210150364
- S210190479 Informs that control room & technical support ctr habitability sys modiper NNREO-0737. Item II D 3 4 will be delayed until 830515 due to need for design work-untimely mati delivery & low productivity Revised schedule encl MUSQLF.D Northern States Fower Co 82/10/13 Office of Nuclear Reactor Regulation, Director 3pp 15740 263 24X Fiche 50-263.82/10/13.8210190479
- 8210250320 Confirmatory action ltr relactions Util will undertake as result of 821014 meeting at Region 3 ofc recrack indications found on welds on recirculation sys piping KEPPLER, J.O. Region 3. Office of Director 82/10/19 LARSON, C.E. Northern States Power Co. 2gp 15790-224 24X Fichs 50-243, 82/10/19, 8210250320

- 8210260209 Forwards check to complete fee payment for Addendum I to 801010 lacense amand request MUSDLF.D Northern States Fower Co 82/10/22 DIGOS,R M License Fee Management Branch Ip 15799 152 24X Fiche 50-263,82/10/22, 8210260209
- Q Inspection reports. IE Bulletins & correspondence
- 8210080015 Addl response to FOIA request for 17 categories of info re nuclear reactor events & safety problems forwards documents listed in App A Documents in App B completely withheld (ref FOIA Exemption 5)
 FELTON. J M Division of Rules and Records 82/07/12 UDELL,R A Critical Mass Energy Project 9pp 15665 027 24X
 Fiche 50-000 82/07/12 8210080015
- ~8105280476 Requests that regions confirm licensee submittal of rept for satisfactory (mplementation of Item 4 of IE Bulletin 79-26. Revision I JGRDAN.E.L. Division of Resident & Regional Reactor Inspection 81/05/18 ORIER.B H Region I. Philadelphia. Office of the Director (81/03/01) O'REILLY-J P Region 2. Atlanta. Office of the Director (81/03/01) MEPPLER.J G Region 3. Chicago. Office of the Director (81/03/01) Ip 15668 130 24% Fiche 50-000.82/07/12.8210080015
- 8210150395 Forwards IE Insp Rept 50-263/82-09 on 820703-0828 No noncompliance noted STREETER, J F Division of Project & Resident Programs 82/09/28 LARSON, C E Northern States Power Co 2pp 15703 272 24X Fichs 50-263, 82/09/28, 8210150385
- --8210150386 IE Insp Rept 50-263/82-07 on 820703-0828 No noncompliance noted Major areas inspected LER followup: operational safety verification, fire protection/prevention, security personnel qualifications, operator overtime & onsite review committee BROWN.C H . MADISON.A L . WALKER.R D Division of Project & Resident Programs 82/09/28 5pp 15703 274 24X Fiche 50-263,82/09/28,8210150385
- 8210130166 Confirms plans for 821014 meeting in Olen Ellyn, IL to discuss proposed corrective action for cracks in welds on endcap of recirculation Loop A SPESSARD, R L Division of Project & Resident Programs 82/10/05 LARSON, C E Northern Status Power Co ip 15673 053 24X Fiche 50-263, 82/10/05, 8210130166
- 8208170233 IE Info Natice 80-35, Suppl 1, "Leaking & Disladged 1-125 Implant Seeds" Svc list encl COBB.L I Division of Fuel Facilities, Materials & Safeguards 82/10/06 Consolidated Edison Co of New York 66pp 15761 250 24X Fiche 50-000.82/10/06.8208170233
- 820B19023B IE Bulletin 82-03, "Stress Corrosion Cracking in Thick-Wall, Large-Diameter, Stainless Steel, Recirculation Bys Piping at BMR Plants "Svc list encl
 DEYOUNG, R C Director's Office, Office of Inspection and Enforcement B2/10/14 Consolidated Edison Co of New York
 115pp 15810, 125 24X Fichs 50-000. 82/10/16, 820B19023B
- 8210250320 Confirmatory action ltr re actions util will undertake as result of 821014 meeting at Region 3 ofc re crack indications found on welds on recirculation sy piping KEPPLER. J O Region 3. Office of Director B2/10/19 LARSON. C E Northern States Power Ca 2pp 15790 224 24X Fiche 50-263.82/10/19.8210250320
- 8 Reportable occurrences, LERs & related correspondence
- 8210150174 Forwards LER 81-020/03L-0 MAYERL D Northern States Power Co 81/08/24 KEPPLER, J G, Region J, Chicago. Dffice of the Director (81/03/01) 1p 15707 193 24X Fiche 50-263.81/08/24.8210150174
- --8210150180 LER B1-020/03L-O on 810724, main steam leak revealed in drain line to condenser Caused by piping leaking immediately downstream of 45 degree elbow due to erosion & impingement resulting from steam & water flow from restricting orifice TDBIN:P A Northern States Power Co B1/08/24 Region 3, Chicago. Office of the Director (81/03/01) 1p 15707 194. 24X Fiche 50-263,81/08/24,8210150174
- 8210050182 PNO-III-82-103.on 820928, rediographs of recirculation loop cap A revealed four cracks extending from weld root into adjacent heat-affected lone. No through-mail cracking evident Repair procedures under evaluation WALKER, JORDAN, M. Region 3, Office of Director 82/09/28 ip. 15603 344 24% Fiche 50-263,82/09/28,8210050182.

- 210080117 RD on 820928, crack indication in end cap of A recirculation riser confirmed by radiography Indications initially detected by ultrasonic etam during normal inservice insp. Remedial Measures under investigation SHAMLA-N A Northern States Power Co. 82/09/28 KEPPLER-J G Region 3. Office of Director ip 15540 204 24X Fiche 50-263, 82/09/28, 8210080117
- 210060258 Forwards LER 82-008/03L-0 MUSDLF.D Northern States Power Co 82/09/29 Region 3. Office of Director 1p 15621 067 24% Fiche 50-263,82/09/29,8210060258
- -8210060260 LER 82-008/031-0 on 820830.RCIC barameter condenser cooling water supply valve failed Caused by severed stem due to Rotork motor operator torque switch misadjustment Valve stem replaced HOJCHGUSKI, A v. Northern States Power Co. 82/09/29 Region 3. Office of Director ip 15621 968 24% Fiche 50-263,82/09/29, 8210060258
- 210190289 Ferwards LER 82-016/017-0 MUSDLF.D Northern States Power Cq 82/10/12 Region 3. Office of Director 1, 15742 175 24x Fichs 30-283,82/10/12.8210190289
- -8210190293 LER 82-016/017-0 on 820928, three indications in 22-inch diameter reactor recirculation sys riser manifold end cap confirmed as rejectable Caused by intergranular stress corrosion cracking End cap to be replaced HAMMER, S Northern States Power Co 82/10/12 Region 3, Office of Director 1p 15742 176 24X Fiche 50-263,82/10/12, 8210190289

OCKET 50-264 DOW CHEMICAL CO

- Insurance & indemnity information
- 2:004023i Forwards Endorsements 47 & 48 to NELIA Policy NF-160
 Endorsement 47 amends description of facility to include
 Lartin Lab
 COALWELL-T N Dow Chemical Co 82/09/29 SALTZMAN. J D Antitrust
 & Economic analysis Branch (Utility Finance) 3pp 19586 111 24X
 Fiche 50-264,82/09/29,8210040231

Operating license stage documents & correspondence

- 210180028 Responds to FDIA request for seven categories of documents re Dou Chemical Co & incineration of low level radwaste Request for fee waiver granted Forwards listed documents FECTON J M Division of Rules and Records 82/08/20 WILSON A K. Affiliation Unknown 2pp 15748 002 24X Fiche 50-264,82/08/20,8210180028
- -9210180239 Application for renewal of Matl/Byproduct Licenses 21-00265-06,21-00265-02,21-00265-04,21-00265-07,8NM-1253, 518-927 & R-108 authorizing any byproduct matl between Atomic Numbers 3 & B3. tritium.Po-210 & Am-241 HOYLE-H 8 Dow Chemical Co 73/06/25 2pp 15748 L15 24X Fiche-50-264,82/08/20.821018028

Reportable occurrences: LERs & related correspondence

210290202 RO on 821006, malfunction of Eberline AMS-O continuous air monitor pump caused pump to be inogerable for approx 1-h. No loss of significant signals indicated Pump repaired Changes to procedures or equipment under review RAMPY, L. W., KNOLL.F. J. Daw Chemical Co. 82/10/20 HILLER, J. R. Standardization & Bpscial Projects Branch 1p 15853 384 24X Fichs 50-264, 82/10/20, 8210290202

DCKET 50-265 QUAD-CITIES STATION. UNIT 2

- Security, medical, emergency & fire protection plans
- 209290125 Releases public version of revised generating station emergency plan corporate command ctr emergency plan implementing procedure FELTON-J M. Division of Rules and Records 82/09/16. Document Management Branch 1p. 15564:122 24X Fiche 50-000,82/09/16,8200290128
- -8209290189 Forwards public version of Revision 4 to generating station emergency plan corporate command ctr Emergency Plan Implementing Procedure EOF-3. "Environ/Emergency Coordinator." Receipt form enc! PAJONSKI, J E Commonwealth Edison Co 82/09/01 DENTON.H R NRC No Detailed Affiliation Given Ip 15564-123. 24X Fiche: 50-000, 82/09/16, 8209290125

- ---8207270225 Public version of Revision 4 to generating station emergency plan corporate command ctr emergency plan implementing Procedure EOF-3, "Environ/Emergency Coordinator"

 PAUDHSKI, J E Commonwealth Edison Co. 82/08/31 1[pp | 1554 124 24X Fiche 50-000, 82/07/16, 8207270125
- 8210010009 Forwards info to suppl 820701 request for exemption from \$\frac{p}{2}\$; R per 820917 talcon Request applies to Sections III 0 2 a \$\frac{k}{2}\$ it 0 3 b re installation of fire suppression sys RAUBCH.T J Commonwealth Edison Co 82/09/23 EISENNUT.P 0 Division of Licensing 8pp 15565 152 24X Ficha 50-000,82/09/63 8210010009
- B210120546 Releases public version of revised cover shoet to facility procedures FELTON J H Division of Rules and Records B2/09/24 Bacument Management Branch 1p 15672 219 24X Fiche 50-254, B2/09/24 B210120546
- --8210120551 Forwards public version of revision cover sheet to facil's procedures Completion of encl checklist requested KALIVIANAKIB,N Commonwealth Edison Co. 82/09/15 DENIGN.D H Office of Nuclear Reactor Regulation. Director App. 15/70 220 24X Fiche 50-254.82/09/24.8210120544
- 8210150487 Forwards IE Insp Repts 50-254/82-14 & 50-265/82 16 on 820823-25 & 0903 & 09 No noncompliance noted KEPPLER.J G Region 3. Office of Director 82/09/30 R[{0 < Componwealth Edison Co 3pp 15721 289 24X Fichs 50 294.
- --8210150495 IE Insp Repts 50-254/82-14 & 50-265/82-16 on 192012 1 25 4 0903 & 09 No noncompliance noted Major areas inspected emergency preparedness exercise & licensee actions on previously identified emergency preparedness items PHILLIPS M P Division of Emergency Preparedness & (Perational Support B2/09/29 15pp 15721 292 24X Fiche 50 254.82/09/50 8210150487
- 8210130376 Advises that installation of offsite dose calculation squ program fully operational tracking model & operational A model will be delayed until 821231 to complete prime computer installation SWARTZ.E D Commonwealth Edison Co 82/10/06 DENTON, H R (11f1) of Nuclear Reactor Regulation, Director 2pp 15682 049 241 Fiche 50-000, 82/10/06,8210130376
- 8210270047 Releases public version of revisions to Quad Cities. Ison't Dresden emergency plan annexes & revised generating station emergency plan telephone directory FELTON, J M Division of Rules and Records 82/10/00 Document Management Branch ip 15877 313 24X Fiche 50-000, 82/10/00 821027047
- --8210270060 Forwards public version of Revision 3 to Quad ('itles tl'emergency plan annexes.Revision 2 to Dreaden emergency plan annexes.Revised generating station of the Brown emergency plan annexes revised generating station emergency plan telephone directory MODRE/R D Commonwealth Edison Co 82/07/30 DEMION.H R Mais No Detailed Affiliation Given Spp 15877 314 24X Fiche 50-000.82/10/08.8210290047
- --B210290077 Public version of Revision 3 to Guad Cities & Jinh emergency plan annexes Revision 2 to Dresden emergency plan annex & Revision 0 to Byron emergency plan annex * Commonwealth Edison Co B2/06/30 325pp 15877 314 248 Fichs 50-000, B2/10/08 B210290047
- --821029008B Public version of revised generating station smergents; telephone directory GALE, DP Commonwealth Edison Co 82/08/12 43pp 150/B its 24X Fiche 50-000,82/10/08,8210290047
- 8210190753 Forwards 820922 ltr re late submittals of exercise scenarios & failure to adhere to FEMA Guidance Memo 17 If FEMA does not observe exercise offsite authorities will not participate
 HIND, J. A Division of Emergency Preparedness & Operational Busiess 82/10/12 REED. C Commonwealth Edison Co 2pp 15736 947 241 Fiche 50-254, 82/10/12,8210190753
- ---B210190760 Discusses concerns re late submittals of emergency frame, scenarios & failure to adhere to FEMA Guidance Memo 17 Foture exercise not meeting intent of advance notification guidance should be postponed or canceled BREHCHY.P. J Federal Emergency Management Agency 82/09/22 KEPPLER. J G Region 3, Office of Director ip 15736 249 24; Fiche 50-254,82/10/12/8210190753.

- 82102B0361 Releases public version of revised emergency plan implementing procedures FELTON.J.M. Division of Rules and Records 82/10/12 Document Management Branch 1p 15859 204 24X Fiche 50-254.82/10/12, 8210280361
- --B210280364 Forwards public version of revised emergency plan implementing procedures, including Procedures QEP 200-0 re emergency conditions, QEP 200-11 re emergency action levels & QEP 330-3 re SPINO control terminal operation KOVACK, T S. QERNER, L F. Commonwealth Edison Co. 82/09/23 DENFON, H R. NRC NO Detailed Affiliation Olven. 2pp. 15859 205 24X Fiche 50-294, 82/10/12, 8210280361
- --8210280375 Public version of revised emergency plan implementing procedures, including Procedures GEP 200-0 re emergency conditions, GEP 200-17 re emergency action levels & GEP 330-3 re SFING control terminal operation e Communwealth Edison Co 82/09/23 21pp 15859 207 24X Fiche 50-254, 82/10/12, 8210280361
- 6210220358 Provides info re organization & performance of depts responsible for radiation protection activities, per 820702 commitment Training coordinator assigned in Apr 1982 to improve health physics training programs

 IRAMM.T R Commonwealth Edison Co 62/10/14 DENTON, H R Office of Nuclear Reactor Regulation. Director 9pp 15776-287 24X Fiche 50-000.82/10/14.8210220358
- 8210250309 Responds to 820917 telcon request for info re fire protection safe shutdown rept Items 2 & 3 are proliminary results, subj to revision following engineering review RAUSCH, T J Commonwealth Edison Co 82/10/18 EISENHUT, D O Division of Licensing 6pp 15790 215 24X Fiche 50-254,82/10/18,8210250309
- P Operating license stage documents & correspondence
- G210050142 Requests that charcoal adsorber F64-DYM2 be counted within 2 uls of receipt decay corrected to 790319 levels & returned Liquid beta analyses results received in NRC B20917 itr will be incorporated in rept addendum PAPERIELLO.C J Division of Emergency Preparedness & Operational Support 92/09/28 KALIVIANAKIS.N Commonwealth Edison Co ip 15605 167 24% Fiche 50-254.82/09/28, B210050142
- 8210120105 Requests delay of implementation due dates re NUREO-0/37, Items 11 B 2, "Plant Shielding," II B 3, "Post-Accident Sampling" & II F I 1, "Noble Oas Effluent Monitor" SWARTZ-E D Commonwealth Edison Co 82/10/04 EISENHUT, D Q Division of Licensing 5pp 15651 237 24% Fiche 50-000,82/10/04,82/0120105
- 6210260526 Forwards Revision 3 of Chapter 9 of "Offsite Dose Calculation Manual" GOLDEN.J C Commonwealth Edison Co 82/10/06 CASE,E G Offsice of Nuclear Reactor Regulation, Director 2pp 15805 137 24X Fische 50-000, 82/10/06.8210260526
- G2101B0059 Provides add1 guidance & clarification re B20806 request for add1 info per NUREG-0737. Item II B 3, "Post-Accident Sampling Sys " Detailed reliability analysis not required to satisfy NRC concerns CRUICHFIELD. D Operating Reactors Branch 5 82/10/08 DELOEDROE, L Commonwealth Edison Co 3pp 24X Fiche 50-000.82/10/08, 82101B0039
- S210190780 Forwards "GE BWR Extended Load Line Limit Analysis for Guad Cities Nuclear Power Station Unit 1.Cycle 7 & Unit 2.Cycle 6 ' RAUSCH.T J Commonwealth Edison Co 82/10/12 EISENHUT, D G Division of Licensing ip 15736
- --8210190785 "OE BWR Extended Load Line Limit Analysis for Quad Cities Nuclear Power Station, Unit 1, Cycle 7 & Unit 2, Cycle 6." * General Electric Co NEDO-22192 82/07/31 3ipp. 15736-207 24X Fiche 50-254, 82/10/12,8210190780
- S210190445 Forwards supplemental response to Generic Ltr 82-05 re implementation status of NUREG-0737. Items II B 3. II F i 2, II F i 3. II F i 5 t II F i 4. in response to 821004 request SHARTZ. E D Commonwealth Edison Co 82/10/14 EISENHUT, D O Division of Licensing 5pp 24X Fiche 50-000, 82/10/14, 8210190445

- 8210250155 Forwards corrections to proposed Tach Spec Pages I 2/2 2-1 & G 3/4 3-5, supporting raview of future reloads & revised Figure 3 5 1, Sheet 1, providing extended MAPLHOR vs exposure curves for barrier lead test assembly fuel RAUSCH, T J Commonwealth Edison Co 82/10/18 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 15788 233 24X Fiche 50-000, 82/10/18, 8210250155
- --8210250177 Errata & Addenda Sheet 9. replacing Page 4-10 to "LOCA Analysis Rept for Dresden Units 2 & 3 & Quad Cities 1 & 2 Nuclear Power Stations" " General Electric Co NEDD-24146A ERR 08 82/09/30 3pp 15788 239 24X Fichs 50-000,82/10/18.8210250155
- 9210250069 Provides add1 info re reactor water cleanup room area temp monitors Temp elements cause no automatic plant response beyond control room alarms
 RAUSCH, T. J. Commonwealth Edison Co. 82/10/19 EISENHUT, D. O. Division of Licensing 2pp 15787 081 24% Fiche 50-000, 82/10/19, 8210250069
- Q Inspection reports, 1E Bulletins & correspondence
- 8210150487 Forwards 1E Insp Repts 50-254/B2-14 & 50-265/B2-16 on 820823-25 & 0903 & 09 No noncompliance noted KEPPLER.J O Region 3. Office of Director B2/09/30 REED.C Commonwealth Edison Co 3pp 15721 289 24X Fiche 50-254.82/09/30, 8210150487
- --8210150495 IE Insp Repts 50-254/82-14 & 50-265/82-16 on 820823-25 & O903 & O9 No noncompliance noted Major areas inspected emergency preparedness exercise & licensee actions on previously identified emergency preparedness items PHILLIPS M P , SMITH M J , AXELSON, W L Division of Emergency Preparedness & Operational Support 82/09/29 15pp. 15721 292. 24X Fiche 50-254,82/09/30,8210150487
- 8210060359 Ack receipt of 820710 ltr informing NRC of steps taken to correct violations noted in IE lnsp Repts 50-237/81-39, 50-247/81-32, 50-254/81-23, 50-265/81-23, 50-295/81-31 & 50-304/81-29
 SPEESARD.R L Division of Project & Resident Programs 82/10/01, REED.C Commonwealth Edison Co 1p 15618 354 24X
 Fiche 50-000, 82/10/01, 8210060359
- --8210060367 Responds to NRC 820712 ltr re violations noted in IE Insp. Repts 50-237/81-39, 50-249/81-32, 50-284/81-23, 50-265/81-23, 50-295/81-31 & 50-304/81-29 Corrective actions training for mgt priorities re plant availability will be conducted REED. C. Commonwealth Edison Co. 82/09/10 KEPPLER. J. O. Region 3. Office of Director 13pp 156/18 355 24X Fiche 50-000, 82/10/01.8210060339
- 8210080178 Forwards listing of piping sys which fail to meet F8AR requirements per NRC 800818 confirmatory action ltr IE Bulletin 79-14 operability evaluation updates will not be provided for Dreaden & Quad Cities Final update by Dec 1982 RAUSCH T J. Commonwealth Edison Co 82/10/01 KEPPLER, J G Region 3, Office of Director App 13640:159 24X Fiche: 50-000.82/10/01, 8210080178
- 8210060266 Confirms 821103 enforcement conference at Region 3 ofc re QA aspects associated w/procurement, installation & use of non-qualified valve guides in electramagnetic relief valves at facilities

 SPESSARD, R L Division of Project & Resident Programs, 82/10/04

 REED, C Commonwealth Edison Co ip 15640:181 24X

 Fiche 53-000, 82/10/04, 8210080190
- 8208190233 lE Info Notice 80-35. Suppl 1, "Leaking & Dislodged I-125 Implant Beeds " Svc list encl COBB.L I Division of Fuel Facilities, Materials & Safeguards. 82/10/06 Consolidated Edison Co of New York 66pp 13761.250 24X Fiche 50-000.82/10/06.8208190233
- 8208190238 IE Builetin 82-03, "Btress Corrosion Cracking in Thick-Wall, Large-Diameter, Stainless Steel, Recirculation Sys Piping at BMR Plants " Svc list encl DEVOUNG, R C Director's Office, Office of Inspection and Enforcement 82/10/14 Consolidated Edison Co of New York 115pp 15810-125 24X Fichs 50-000.82/10/14:8208190238
- R Periodic operating reports & related correspondence
- 8210130386 Forwards monthly operating repts for Bapt 1982, KALIVIANAKIS,N Commonwealth Edison Co 82/10/01. Director's Office, Office, of Inspection and Enforcement ip. 15680 339 24X Fiche, 50-254, 82/10/01,8210130386.
- --B210130390 Monthly operating repts for Bept 1982 BUSE.R.D. Commonwealth Edition Co. B2/10/04 13pp 15680 341. 24X Fiche.50-284.B2/10/01.B210130386

S Reportable occurrences. LERs & related correspondence

B210260467 PNO-III-82-il2 util notified that high density fuel storage racks installed do not meet design criteria for spacing due to boung condition Manufacturer reanalyzed seismic response of racks & concluded bound distance acceptable GROBE. J. HALKER. R. STREETER. Region 3. Office of Director 82/10/18 1p 15806 237 24x Fiche 50-254.82/10/18.8210260467

DOCKET 50-266 POINT BEACH NUCLEAR PLANT, UNIT 1

F Security, medical, emergency & fire protection plans

8210040119 Discusses revision of plant emergency response procedures specifying necessary precautions required before post-accident re-entry into auxiliary bldg or facade, in response to 820914 request for info re NUREO-0737. Item II 8 2 FAY; C W Wisconsin Electric Power Co 82/09/24 DENTON, H R Office of Nuclear Reactor Regulation, Director CLARK, R A Operating Reactors Branch 3 2pp 15581 201 24X Fiche 50-266.82/09/24.8210040119

8210050272 Forwards add1 info requested in NRC 820916 telcon to support util 820630 App R exemption request Eight oversize drawings encl Aperture cards are available in PDR FAY.C W Wisconsin Electric Power Co 82/09/29 DENTON, H R Office of Nuclear Reactor Regulation. Director CLARK.R A Operating Reactors Branch 3 13pp 15606 047 24X Fiche 50-266.82/09/29.8210050272

8210050054 Forwards add1 info re proposed mods for emergency support ctr FAY,C W Wisconsin Electric Power Co. 82/09/30 DENTON,H R Office of Nuclear Reactor Regulation, Director 16pp 15603 328 24X Fiche 50-266,82/09/30.8210050054

8210270256 Releases public version of revised emergency plan implementing procedures FELTON.J H Division of Rules and Records 82/10/08 Document Nanagement Branch 1p 15834 001 24X Fiche 50-266,82/10/08.

--8210270259 Forwards public version of revised emergency plan implementing procedures, including Procedures EPIP () reinitfal classification, EPIP () are estimation of source term & EPIP () 4 re radiological dose evaluation FAV.C W Wisconsin Electric Power Co 82/09/10 DENTON, HR Office of Nuclear Reactor Regulation, Director CLARK, R A Operating Reactors Branch 3 4pp | 15834 002 24X Fiche 50-266, 82/10/08, 8210270256

--8210270261 Public version of revised emergency plan implementing procedures including Procedures EPIP 1 1 re initial classification. EPIP 1 3 re estimation of source term & EPIP 1 4 re radiological dose evaluation

Wisconsin Electric Power Co 82/09/10 244pp 15834 006 24X Fiche 50-266,82/10/08.8210270256

8210130471 Forwards add1 info re 820630 requests for exemption from 10CFR50 App R concerning Fire Area 7, control room & vertical cable trays in response to 821001 & 06 telcons w/NRC W/16 oversite drawings Aperture cards in PDR FAY, C W Hisconsin Electric Power Co 82/10/11 DENTON, H, R Office of Nuclear Reactor Regulation, Director CLARK, R A Operating Reactors Branch 3 12pp 15734 350 24X Fiche: 50-266, 82/10/11.8210150471

O Adjudicatory correspondence

B210040125 Amend to HI Environ Decade B20810 petition to intervene including affidavits requesting HI Environ Decade to intervene on affiant behalf Certificate of Syc enci ANDERSON, P Wisconsin's Environmental Decade 82/09/28 Commissioners Spp 15581 196 24X Fiche. 50-266, 82/09/28, 8210040125

8210050251 Hemorandum & order granting summary disposition of all WI Environ Decade issues arcept issue of demonstration of adequacy of eddy current tasting to detect cracking BLOCM.P B . KLINE.J R . PAXTON.H C. Atomic Sefety and Licensing Board Panel. B2/10/01. Wisconsin's Environmental Decade. 19pp 13610 306. 24% Fiche 50-266.82/10/01.8210050251

B210050275 Decision ALAB-696 affirming ASLB B11105 order permitting plant to return to svc after refueling outage during which licenses planned to repair degraded steam generator by sleaving TOMPKING, B.A. Atomic Bafety and Licensing Appeal Panel B2/10/01, 34pp 15611: 197. 24X Fiche: 50-266,82/10/01,8210050275.

8210120267 Forwards documentation re steam generator replacement application filed prior to 820819 establishment of ABLB Documentation consists of steam generator repair repts & correspondence between licensee & Commission W/o encl RIDOWAY, D.A. Shaw, Pittman, Potts & Troubridge RIDOWAY, D.A. Wisconsin Electric Power Co. 82/10/07 KLINE, J.R., PAXTON, R.C. Atomic Safety and Licensing Board Panel 3pp 15652 327 24x Fiche 50-266,82/10/07.8210120267

8210200027 Notice of B21117-2D evidentiary hearing in Two Rivers, H1 ve adequacy of inservice nondestructive testing of sleeves proposed to be used to repair corroded steam generator tubes Prehearing conference to be held after hearing ULQCH, P B. Atomic Safety and Licensing Board Panel 62/10/15 1, 15756-325 24X Fichs 50-266,82/10/15,8210200027

8210200055 Response to WI Environ Decade 820928 amend to petition to intervene Decade established standing but affiant P Anderson must demonstrate authority to act on behalf of Decade Certificate of Svc encl
BACHMANN, R O . MCGURREN, H J Hearing Branch 1 82/10/18 Atcaig Safety and Licensing Board Panel 4pp 15753 006 24% Fiche 50-266.82/10/18.8210200055

6210250120 Notice of appearance in proceeding Certificate of Bvc enri ANDERBON,P Wisconsin's Environmental Decade 82/10/20 dpp 15787 116 24X Fiche 50-266.82/10/20,8210250120

82(0220242 Notice of relocation of 821117-20 hearing from Two Rivers b to Milwaukee, WI Limited appearance statements will be taken at original location on 821117 BLOCH P B Atomic Safety and Licensing Board Panel 82/10/21 [] 15775 351 24X Fiche 50-266,82/10/21,8210220242

8210260406 Ack receipt of B21018 ltr requesting documents Util will cooperate but is not required to respond since nonparties not entitled to discovery CHURCHILL.B W Shaw Pittman. Potts & Troubridge 82/10/22 ANDERSON.P Wisconsin's Environmental Decade 3pp 15803 319 14: Fiche 50-266.82/10/22.8310260406

8210280253 Advises that util requested to send FSAR Chapter 14 "Safrig Analyses" to MI Environ Decade, in ref to 821018 telcon Svc list encl Related correspondence CHURCHILL, B W Shaw, Pittman, Potts & Trowbridge CHURCHILL, B W Wiscomsin Electric Power Co 82/10/25 ANDERSON, P Wiscomsin's Environmental Decade 2pp 15839 027 24X Fiche 50-266.03/10/25 8210280253

K Utility Final Bafety Analysis Report (FSAR) & amends

8207290257 Chapter 4 to Point Beach updated FSAR. "RC8 "

* Wisconsin Electric Power Co 82/07/21 102pp 14921 074 24;
Fiche 50-266.82/07/21.8207290257

8207290279 Chapter 11 to Point Reach updated FSAR, "Waste Disposal & Radiation Protection Sys "

* Wisconsin Electric Power Co 82/07/21 126pp 14823 371 2*1 |
Fiche 50-266,82/07/21,8207290279

P Operating license stage documents & correspondence

8210210009 Recommends raview of design of interconection between redundant safety-related electrical load groups Design should be modified to assure full compliance w/Reg Guide to MICHELSON, C Director's Office 80/08/27, DENTON, N R Director's Office, 2pp 15782 209 24% Fiche 50-266, 80/08/27, B210210009

621001000B Responds to FDIA request for 19 categories of documents renuclear reactor events & safety problems Forwards documents listed in App A FELTON.J H Division of Rules and Records 82/06/20 UDELL-R A Critical Mass Energy Project 15pp 15727 005 24X Fiche: 50-000, 82/06/28, 8210010008

--8002i40204 Forwards avaluation of proposed Tech Specs change to agentiacility at 2250 on 2000 psia Proposed changes are acceptable Myo encil
CMECK.P S. Reactor Bafety Branch 79/12/26 BCHMENCER.A Operating Reactors Branch 1 (Pre 800428) 6pp 15727.030 241 Fiche 50-000.82/06/28.8210010008

8210070007 Responds to FOIA request for eight categories of records a steam generators & steam turbines. App A documents provided in R Udell FOIA Request 81-313 Forwards documents listed in App B FELTON, J. H. Division of Rules and Records 82/08/10 LONO. D J Winthrop, Stimson, Potnam & Roberts 9pp 15645 063 24X Fiche: 50-000, 82/08/10, 8210070007

- --7812200285 Summarires steam generator tube leak on 780920 & insp Leak rate reached 560 gpd at 5 00 AM, caused by two tubes w/cracks located w/in thickness of tube sheet & one tube w/leaky plug General cause plant conversion to AVT MODNAM, V S Engineering Branch (Pre 791030) 78/12/12 GRIMES, B K Assistant Director for Engineers & Projects (Pre 790623) 2pp 15645 244 24X Fiche 50-000,82/08/10,8210070007
- --7909280105 Discusses steam generator tube leak & inservice insp Steam generator caused by deep crevice cracking of three tubes within tube sheet Not leg tube tests indicated 52 tubes wideep crevice cracking in scress of 50% plugging limit MODNAH, V S Engineering Granch (Pre 791030) 79/08/17 EISENRUT, D G Division of Operating Reactors 3pp 15645 254 24X Fiche 50-000,82/08/10,8210070007
- --5004300616 Requests that util grovide BNL ω/tube samples for examination Forwards list of tubes fGRIAN,V S Engineering Branch 80/04/14 SCHWENCER, A Operating Reactors Branch i (Pre 800428) 2pp 15645-264 24X Fiche 50-000, 82/08/10, 8210070007
- -8009040493 Forwards safety evaluation of Aug 1980 steam generator insp Concludes generators may be operated safely per 791130 & 800103 orders PAMLICKI.S S. Materials Engineering Branch 80/08/08 CLARK.R A Operating Reactors Branch 2 ip 15645 309 24X Fiche 50-000,82/08/10.8210070007
- --2009040497 Safety evaluation supporting operation of steam generators per 791130 & 800103 orders * Material's Engineering Branch 80/08/08 7pp 15645 310 24X Ficha 50-000.82/08/10.8210070/007
- --Bli0290050 Advises that technical reviewers providing input for BER nust be available to testify at Bli029-31 hearings Schedule & agenda info encl
 CLARK-R A Decrating Reactors Branch 3 Bl/10/20 MURPHY-E ,
 FEHEMIAS-J , MD.T NRC No Detailed Affiliation Oven 3pp 15645 271 24X Fiche 50-000, 82/08/10.8210070007
- 3110300460 Requests evaluation by 811023 of util 810702 application for license amend to permit steam generator tube sleeving Info to be presented at ASLB 811027-30 hearing COLBURN, T O Operating Reactors Branch 3 81/10/19 BALLARD, R L Environmental Engineering Branch 1p 15645 270 24X Fichs 50-000,82/08/10.8210070007
- --BillO90062 Forwards safety evaluation for proposed steam generator sleeving demonstration covering radiation protection & AI ARA aspects
 AI ARA aspects
 AI ARE STATE Assistant Director for Radiation Protection B1/10/22 NOVAK.TA Assistant Director for Operating Reactors 4pp 15645 276 24X Fiche 50-000.82/08/10.8210070007
- --B111240071 Submits review of util request to demonstrate tube sleeving program Activities of proposed demonstration will not result in any significant environ impact BALLARD.R L Environmental Engineering Branch B1/10/23 CLARKIR A Operating Reactors Branch 3 ip 19645-280 24X Fiche 50-000, B2/08/10.8210070007
- --8202120129 Discusses environ review of application for steam generator tube sleeving program Environ impact insignificant DALLARD.R L Division of Engineering 82/01/25 CLARK.R A Operating Reactors Granch 3 ip 15645 282 24X Fiche 50-000.82/08/10.8210070007
- --8210070185 Responds to 750320 question concerning licensing action re
 Pacility steam generator tube rupture incident W/o encl
 preliminary results of tube insp performed by licensee. Tech
 Specs & related info
 GDLLER.K R Division of Reactor Licensing (NRR-1975 only)
 /5/03/31 OALLO, J Hearings Division Ip 15445-201 24X
 Fichs 50-000.82/08/10,8210070007
- --8210070187 Informs of incorrect info contained in third paragraph of Encl 2 to 750331 memo re facility steam generator tube rupture incident Corrected paragraph submitted QCLLER.K R Division of Reactor Licensing (NRR-1975 only) 75/04/09 QALLO, J Hearings Division 2pp 15645-202 24X Fichs 50-000.82/08/10.8210070007
- --8210070191 Requests technical assistance re 750226 steam generator tube leakage incident Review of encl info & current regulatory requirements re steam generator tube integrity requested by 750530 W/o encls

 LEAR. Ø Division of Reactor Licensing (NRR-1975 only) 79/04/18 SCHROEDER, F Division of Technical Review (NRR-1975 only) 3pp 15645 204 24X Fiche 50-000, 82/08/10, 8210070007

- --B210070205 Submits summary of findings & comments re facility steam generator tube leak incident & insp results contained in Annual Operating Rept 1976 Recommends that licensee be requested to submit insp program for next scheduled insp SHAO.L. C Engineering Branch (Pre 791030) 77/07/25 EISENHUT.D 0 Division of Operating Reactors 2pp 15645 235 24X Fichs 50-000,82/08/10.8210070007
- ~-B210070208 Forwards request for add1 info re 780524 steam generator tube leak.per LER 78-010/01T-0 LER does not clearly indicate evaluation of exact location

 ★ Engineering Branch (Pre 791030) 78/07/13 SCHWENCER, A Operating Reactors Wranch 1 (Pre 790625) 3pp 15645 241 24X Fiche 50-000, 82/08/10.8210070007
- ~~8210070217 Expresses appreciation for 791130 effort to perform essential licensing work on steam generator matter EIBENHUT.D 0 Division of Operating Reactors 79/12/03 TRAMMELL.C M Operating Reactors Branch 1 (Pre 800428) 1p 15645 257 24X Fiche 50-000.82/08/10.8210070007
- --8210070218 Forwards A Schwencer & CM Trammell statements re 791116 LER 79-017, per 791228 request SCHMENCER, A Operating Reactors Branch 1 (Pre 800428) 79/12/31 EISENHUT, D 0 Division of Operating Reactors 6pp 15645 258 24X Fiche 50-000,82/08/10.8210070007
- 8210040414 Forwards Amends 63 & 68 to Licenses DPR-24 & DPR-27, respectively, safety evaluation & notice of issuance & availability Amends revise inservice insp Tech 8pecs CLARK, R A Operating Reactors Branch 3 82/08/31 FAY.C W Wisconsin Electric Power Co 5pp 15597 134 24X Fiche 50-266,82/08/31.8210040414
- --B210040420 Amends &3 & 68 to Licenses DFR-24 & DFR-27, respectively, revising language of Tech Specs re inservice insperequirements of safety class components to conform U/100FR50 55 CLARK, R A Derating Reactors Branch 3 82/08/31 14pp 15597 139 244 Fiche 50-266, 82/08/31,8210040414
- --8210040425 Safety evaluation supporting Amends 63 & 68 to Licenses DPR-24 & DPR-27, respectively 4 Office of Nuclear Reactor Regulation, Director 82/08/31 App 15597 155 24% Fiche, 50-264, 82/08/31, 8210040414
- --8204210571 "Point Beach Nuclear Plant Units 1 & 2 Inservice Insp Program Tachnical Evaluation Rept" * Science Applications, Inc NRC-03-82-074 SAI-186-028-82 82704715 NRC - No Detailed Affiliation Given 20pp 15597 159 24X Fiche 50-266, 82/08/31, 8210040414
- --B210040427 Notice of issuance & availability of Amends 63 & 68 to Licenses DPR-24 & DPR-27, respectively CLARK, R A Operating Reactors Branch 3 82/08/31 3pp 15597 179 24X Fiche 50-266, 82/08/31, B210040414
- 8210030005 Advises that error analysis of reactor vessel water level instrumentation sys requested in NRC 820619 ltr will be available by 83015 FAY: C M. Hisconsin Electric Power Co 82/09/29 DENTON, H R Office of Nuclear Reactor Regulation, Director CLARK: R A Operating Reactors Branch 3 1p 15605 208 24% Fiche 50-266.82/09/29,8210050005
- 8210050055 Forwards info requested in NRC 820630 ltr re implementation of TMI Item 11 B 2, "Post-Accident Sampling Bys " Addl requirements re backup power sources for lab are beyond scope of original NUREO-0737 implementation schedule BURSTEIN, S Wisconsin Electric Power Co 82/09/30 DENTON, H R Office of Nuclear Reactor Regulation, Director CLARK, P A Operating Reactors Branch 3 2ipp 15603 307 24% Fiche 50-266,82/09/30,8210050055
- 8210050222 Application to smend Licenses DPR-24 & DPR-27, revising spent fuel pool poison surveillance specimen location & clarifying conditions for operating power-operated relief valves FAY.C W Hisconsin Electric Power Co 82/09/30 DENTON.H.R Office of Nuclear Reactor Regulation, Director, 3pp 15609,056, 24X Fiche, 50-266,82/09/30,8210050222
- --8210050231 Proposed Tech Bases revising spent fuel pool poison surveillance specimen location & clarifying condition for operating power-operated relief valves * Wisconsin Electric Power Co. 82/09/30 3pp, 15609-059 24X Fiche 50-266,82/09/30-8210050222

- 8210270426 Forwards Amends 64 & 67 to Licenses DPR-24 & DPR-27, respectively, safety evaluation & notice of issuance & availability Amends modify operation & surveillance testing requirements of containment purge supply & exhaust valves COLBURN, T O Operating Reactors Branch 3 62/10/04 FAY.C W Miscensin Electric Power Co 4pp 15863 143 24X Fiche 50-266, 82/10/04, 8210270426
- --8210270431 Amends 64 & 69 to Licenses DPR-24 & DPR-27, respectively, and if ying operation & surveillance testing requirements of containment jurge supply & exhaust isolation valves & terminology of Tech Spec 15 4 4 on testing CLARK-R A Operating Reactors Branch 3 82/10/04 12pp 15863 154 24X Fiche 50-266, 82/10/04, 8210270426
- --8210290436 Safety evaluation supporting Amends 64 & 69 to Licenses DPR-24 & BPR-27, respectively « Office of Nuclear Reactor Regulation. Director 82/10/04 Spp 19863 146 24X Fiche 50-266.82/10/04.8210290426
- ---B210290441 Notice of issuance & availability of Amends 64 & 69 to Licenses DPR-24 & DPR-27, respectively CLARK.R A Operating Reactors Branch 3 82/10/04 2pp 15863 151 24X Fiche 50-266.82/10/04.8210290426
- 8210120267 Forwards documentation re-steam generator replacement application filed prior to 820819 establishment of ASLB Documentation consists of steam generator repair repts & correspondence between licensee & Commission W/o encl RIDCHAY.D A Shaw, Pittman, Potts & Thowbridge. RIDCHAY.D A Wisconsin Electric Power Co 82/16/07 KLING.J R , PAXTON.H C Atomic Safety and Licensing Board Panel 3pp 19652-327 24X Fiche 50-266,82/10/07.8210120267
- 8210150430 Advises that refueling shutdown at end of Cycle 10 planned to begin 821022 Startup of Cycle 11 expected to occur in early Dec 1782 Cycle 11 reload core designed to operate under current nominal design parameters & Tech Specs FAY.C W Hisconsin Electric Power Co 82/10/11 DENTON.H R Office of Nuclear Reactor Regulation, Director CLARK.R A Operating Reactors Branch 3 2pp 15704 019 24X Fiche 50-266,82/10/11.8210150430
- 8210190284 Advises of mod to RCB gas vent sys to prevent operation of power operated valves during normal plant operation.psr 821012 telcon Physical restraining device fitted on an over valve operator switch FAY.C W Misconsin Electric Power Co 82/10/15 DENTON.H R Office of Nuclear Reactor Regulation. Director CLARK,R A Operating Reactors Branch 3 ip 15742 177 24X Fiche 30-266.82/10/15.8210190284
- 8210190519 Forwards responses to request for add1 info on Tech Spec Change Request 85 re operation when add1 steam generator tube plugging causes primary sys flow to drop below thermal design flow value
 FAY.C W this consin Electric Power Co 82/10/15 DENTON, H R
 Office of Auclear Reactor Regulation, Director CLARK.R A
 Operating Reactors Branch 3 Spp 15751 238 24X
 Fiche 80-266, 82/10/15, 8210190519
- 5210270274 Forwards Amends 65 % 70 to Licenses DPR-24 % DPR-27, respectively, safety evaluation & notice of issuance % availability Amend allows relaxation of monthly turbine stop & governor valve tests during end of cycle operation COLBURN, T 0. Operating Reactors Branch 3 82/10/15 FAY, C W Hisconsin Electric Power Co. 3pp. 15836 316 24X 98/210270274

a Licenses DPR-24 & DPR-27, respectively, nthly turbing stop & governor valve operation.

Branch 3 82/10/15 7gp //0/15,82/10/270274

* ** *> Licenses

10/15. 2pp

.0

Tech

- --B210260479 Proposed Tach Spec changes incorporating revisions readministrative control of high radiation areas
 # Wisconsin Electric Power Co 82/10/19 1p 15806 235 24x
 Fische 50-266:82/10/19.8210260476
- 8210280295 Application to amend Licenses DPR-24 & DPR-27, changing Isla Specs re requirements for periodic leakage rate testing of containment airlock doors Class I & II amend fees encl FAY.C W Misconsin Electric Power Co 82/10/21 DENTON-H R Office of Nuclear Reactor Regulation. Director 3pp 15837 272 24X Fichs 50-266.82/10/21.8210280295
- ~-8210280278 Tech Spec Change Request 82 changing requirements for periodic leakage mate testing of containment air lock doors 4 Wisconsin Electric Power Co 82/10/21 4pp 15837 275 24t Fishe 50-786.82/10/21.8210280275
- 8210290294 Provides results of confirmatory analysis demonstrating that unacceptable radioactive release from containment would not take place as result of small break LOCA in which operator action required Radioactive release negligible FAY.C W Wisconsin Electric Power Co 82/10/22 CLAMK.R A Operating Reactors Branch 3 ip 15853 135 24X Fiche 50-266.82/10/22.8210290294
- O Inspection reports. IE Bulletins & correspondence
- 8107270156 Forwards add1 info in response to IE Bulletin 80-11 re masonry walls Thirteen repts & 109 oversize drawings enc] Aperture cards are available in PDR FAY.C W Wisconsin Electric Power Co 81/07/17 DENTON.H R Office of Nuclear Reactor Regulation. Director CLARK, R Derating Reactors Dranch 3 19pp Available at NTIS 09151 026 24x Fiche 50-266.81/07/17.8107270156
- --8107270161 "Model Contribution to Dynamic Analysis Results "
 " Computer Engineering Services Inc R553 02 81/07/31 11534
 09151 045 24% Fiche 50-266.81/07/17.8107270156
- --BIO7270166 "Cyclic Loading Tests of Masonry Single Piers, Vol 1 Hizj to Width Ratio of 2" HIDALOD,P A , MAYES,R L , MCNIVEN.H D California, Univ of, Berkeley UCB/EERC-78/27 VOl 76/11/30 141pp Available at NTIS 09151 158 24X Fiche 50-266.81/07/17,8107270156
- --8107270169 "Cyclic Loading Tests of Masonry Bingle Piers, Vol 2 Heige to Width Ratio of 1 " CHEN.8 J. HIDALGO.P A. HAYES.R L. California, Univ. of. Berkeley UCB/EERC-78/28 VO2 78/12/31 188pp 09151 290 244 Fiche 50-266,81/07/17.8107270156
- --B107270174 "Cyclic Loading Tosts of Masonry Single Piers, Vol. J. Felg. to Width Ratio of 0.5."

 HIDALGO, F. A., MAYEB, R. L., MCNIVEN, H. D. California, Univ. of.
 Berkeley UCB/EERC-79/12 VOJ. 79/05/31 154pp Available at
 NTIS 09152 124 24% Fiche 50-266.81/07/17,8107270156
- --8107270178 "Shaking Table Btudy of Single-Story Masonry Houses, Vol 1 Test Structures 1 & 2 " GULKAN,P : MAYEB, R L : CLOUGH, R II California, Univ of, Bertelay UCB/EERC-79/23 VOI 79/09/30 275pp Available at NTIS 09152
- --8107270182 "Shaking Table Study of Bingle-Story Masonry Houses: Vol 2-Test Structures 3 & 4 " OULKAN, P. MAYES, R. L. CLOUGH.R H. California, Univ. of. Berieleg UCB/FERC-79/24 VOZ 79/09/30 300pp 09153 184 24X Fiche 50-266,81/07/17.8107270156
- --8107270185 "Shaking Table Study of Single-Story Hasonry Houses, Vol 3-Summary, Conclusions & Recommendations " CLOUGH, R. H., MAYES, R. L., OULKAN, P. California, Univ. of, Berleley UCD/EERC-79/25 VOJ 79/09/30 110pp Available at NTIS 09154 078 24X Fiche 50-266, 81/07/17, 8107270156
- --Bi0727018B "Cyclic Shear Tests of Hasonry Piers, Vol 1 ~ Test Results' MAYES.R.L + OMATE.Y , CLOUGH, R W California, Univ of, Barteleg EERC 76-8 76/05/31 105pp 09194 182 24X Fiche. 50-264. 81/07/17, 8107270156
- --8107270191 "Cyclic Shear Tests of Masonry Piers, Vol 2 -- Analysis of Test Results " MAYES, R L. OMATE, Y. CLOUCH, R W. California, Univ. of, Berkils EERC 76-16 76/06/30, 78pp 09154 288 24X Fiche: 50-286, 81/07/17, 8107270156
- --8107270194 "Strangth of Timber Roof Connections Subjected to Cyclic Loads "OULKAN,P, HAYES,R L, CLOUGH,R W California, Univ of, Beriels, UCB/EERC-78/17, 78/09/30 17ipp 09155 005 24X Fiche 50-266,81/07/17,8107270156

- --BIO7270196 'Literature Survey Transverse Strength of Masonry Walls " DIGATE, Y. MAZES, R. L. CHEN, S. J. California, Univ. of, Berkeley UCB/EERC-77/07 77/03/31 149pp 09155 140 24X Fiche 50-266.BI/07/17.BI07270156
- --Bi07270198 'Literature Survey Compressive, Tensile, Bond & Shear Strength of Masonry "
 MAYES R L. CLGUGH, R W California, Univ of, Berkeley EERC
 J5-15 75/06/30 212pp 09155 286 24X Fiche 50-266, 81/07/17,
- --8107270199 "State-of-the-Art in Seismic Shear Strength of Masonry Evaluation & Review" #AVES.R L . CLOUGH.R W Lalifornia, Univ of, Berkeley ECRC 75-21 75/10/31 147pp 09156 135 24X Fiche 50-266,81/07/17, 6107270156
- ©210070007 Responds to FOIA request for eight categories of records re steam generators & steam turbines App A documents provided in R Udell FOIA Request 81-313 Forwards documents listed in App D FELTON. J M Division of Rules and Records 82/08/10 LONG, D J Winthrop. Stimson. Putnam & Roberts 9pp 15645 063 24X Fiche 50-000.82/08/10.8210070007
- --7812200285 Eurmanites steam generator tube leak on 780920 & insp Leak rate reached 560 gpd at 5 00 AM caused by two tubes w/cracks located w/in thickness of tube sheet & one tube w/leaky plug General cause plant conversion to AVT NODNANIV 5 Engineering Branch (Pre 791030) 78/12/12 GRIMES.D K Assistant Director for Engineers & Projects (Pre 790625) 2pp 15645 244 24X Fiche 30-000,82/08/10,8210070007
- --7909280105 Discusses steam generator tube leak & inservice insp Steam generator caused by deep crevice cracking of three tubes within tube sheet Hot leg tube tests indicated 52 tubes w/ deep crevice cracking in excess of 50% plugging limit ADDNANLYS Engineering Branch (Pre 791030) 79/08/17 tisERHUT, 0 o Division of Operating Reactors 3pp 15645 254 24X Fiche 50-000 82/08/10.82(10070007
- -8210070137 Forwards tabulated data on steam generator insp & maint at facilities Data should be provided to licensees
 IPPOLITO. I Operating Reactors Assessment Branch 82/04/01
 VARGALS Operating Reactors Brasch 1 5pp 15645 131 24X
 Fiche 50-000,82/08/10.8210070007
- --82i0070172 Forwards into re steam generator integrity & insps at all operating PNRs, per 750320 & 21 requests Details of insps, including defect indications, tube plugging criteria & tubes plugged will not be provided except for Point Beach 1 GCLLER K R Division of Reactor Licensing (NRR-1975 anly) 75/03/24 MACCARY, R R Division of Technical Review (NRR-1975 anly) 5pp 15615 196 24X Ficho 50-000.82/08/10,8210070007
- --B210070205 Bubmits summary of findings & comments ie facility steam generator tube leak incident & insp results contained in Annual Operating Rept 1976 Recommends that licensee be requested to submit insp program for next scheduled insp EMAD.L C Engineering Branch (Pre 791030) 77/07/25 EISEMHUT.D 0 Division of Operating Reactors 2pp 15645 235 24X Fiche 50-000.82/08/10.8210070007
- --8210070228 Forwards evaluation of 800226 proposed steam generator insp & tube pulling program Recommends that program be revised to reflect listed cumments HOUNAN.V 5 Engineering Branch 82/08/10 SCHWENCER.A Operating Reactors Branch 1 (Pre 800428) 2pp 19645 268 24X Fichs 50-000.82/08/10.8210070007
- G210040414 Forwards Amends A3 & 6B to Licenses DPR-24 & DPR-27, respectively, safety evaluation & notice of issuance & availability Amends revise inservice insp Tech Specs CLARK, R A Derating Reactors Branch 3 G2/08/31 FAY, C W Nisconsin Electric Power Co Spp 15597 134 24X Fitchs 50-266, 62/08/31, 8210040414
- --8210040420 Amends 63 & 68 to Licenses DPR-24 & DPR-27, respectively, revising language of Tech Specs re inservice inspired united to conform w/10CFR50 95

 CLARK,R A Derating Reactors Branch 3 82/08/31 16pp 15597 139 24X Fiche 50-266, 82/08/31,8210040414
- --8210D40425 Safety evaluation supporting Amends 63 & 68 to Licenses DPR-24 b DPR-27, respectively 4 Office of Nuclear Reactor Regulation, Director 82/08/31 4pp 15597.155 24% Fiche 50-266.82/08/31.8210040414

- --8208210571 "Point Beach Nuclear Plant Units 1 & 2 Inservice Insp Program Technical Evaluation Rapt" ★ Brience Applications, Inc NRC-03-82-096 SAI-186-028-22 82/06/15 NRC - No Detailed Affiliation Given 20pp 15597 159 24X Fiche 50-266.82/08/31.8210040414
- ~-8210040427 Notice of issuance & availability of Amends 43 & AB to Licenses DPR-24 & DPR-27.isspectively CLARK.R A Operating Reactors Branch 3 82/08/31 3pp 13597 179 24X Fiche 50~266.82/08/31.8210040414
- 8210050186 Forwards IE Insp Repts 50-266/82-12 & 50-301/82-12 on 820503-04 & 0615 & notice of violation REPPLER, J O Region 3, Office of Director 82/07/15 BURSTEIN, 8 Wisconsin Electric Power Co 3pp 15611 115 24X Fiche 50-266/82/07/15,8210050186
- ~-8210050174 Notice of violation from insp on 820503-04 & 0615 KEPPLER, J G Region 3, Office of Director 82/09/15 3pp 15611 118 24X Fiche 50-266, 82/09/15, 8210050186
- --B210050205 IE Insp Repts 50-266/82-12 & 50-301-82-12 on 820503-04 & 0615 Noncompliance noted Failure to control access to high radiation areas & failure to follow approved procedures LOVENDALE.P C . HAGUE,R L . GREGER,L R Region 3. Diffice of Director 82/07/13 8pp 15611 121 24X Fiche 50-266.82/09/15, 8210050186
- 8210070033 Notifies that fees for 820820 application requesting relief from certain inservice insprequirements not remitted w/application Class III fee category appropriate DIOQS,R H License Fee Hanagement Branch 82/09/23 FAY.C W Wisconsin Electric Power Co ip 15645 346 24X Fiche 50-266.82/07/23.8210070033
- B210050256 Requests relief from ASHE Section XI, inservice insprequirements re frequency of reactor vessel interior exame FAY.C W Hisconsin Electric Fower Co. 82/09/29 DENTON.H R Office of Nuclear Reactor Regulation. Director CLARK.R A Operating Reactors Branch 3 4pp 15610 286 24X Fiche 50-266.82/09/29.8210050256
- 8210190669 Forwards IE Insp Repts 50-264/82-20 & 50-301/82-20 on 020914-16 No noncompliance noted LITTLE.N 8 Division of Engineering & Technical Programs 82/10/04 BURBTEIN.8 Wisconsin Electric Power Co 2pp 15738-152 24X Fichs 50-266, 82/10/04.0210190669
- --8210190475 1E Insp Repts 50-266/82-20 & 50-301/82-20 on 820914-16
 Na noncompliance noted Major areas inspected survaillance
 & calibr procedures & performance history
 HABSE, H A. PESCHEL, J M. HAWKING, F C Division of Engineering &
 Technical Programs 82/09/29 4pp 13738 154 24X
 Fiche 50-266, 82/10/04, 8210190669
- 8208190233 IE Info Notice 80-35, Suppl 1, "Leaking & Dislodged I~125 Implant Seeds " Syc list encl COBD, L I Division of Fuel Facilities, Motorials & Safeguards 82/10/06 Consolidated Edison Co of New York 66pp 15761 250 24X Fiche 50-000,82/10/06.8208190233
- 8210180067 Forwards Class III for re 820820 request for exemptions from certain inservice insprequirements Util considers imposition of 10CFR170 22 fees inappropriate as request does not involve license emend FAY.C H Hisconsin Electric Power Co 82/10/11. DENTON.H R Office of Nuclear Reactor Regulation. Director CLARK.R A Operating Reactors Branch 3 lp 15720.003 24X Fiche 50-266, 82/10/11.8210180067
- 8208190238 IE Bulletin 82-03, "Stress Corrosion Cracking in Thick-Wall-Large-Diameter. Stainless Steel-Recirculation Sys Piping at BMR Plants." Syc list encl DEYDUNG.R C Director's Office. Office of Inspection and Enforcement 82/10/14 Consolidated Edison Co of New York 115pp 15810 125. 24X Fiche 50-000.82/10/14.8208190238
- R Periodic operating reports & related correspondence
- 8210150150 Forwards monthly operating repts for 8ept 1982 FAY,C W Wisconsin Electric Power Co 82/10/11 Office of Nuclear Reactor Regulation, Director lp 15697 074 24X Fiche, 50-266 82/10/11,8210150150
- --8210150158 Monthly operating repts for Bept 1982.
 FAY:C W Hisconsin Electric Power Co 82/10/04 8pp 15697.075
 24X Fichs 50-266.82/10/11.8210150150.

- S Reportable occurrences, LERs & related correspondence
- 921025025B Forwards LEA 82-015/03L-0 FAY,C.W Misconsin Electric Pawer Co 82/10/13 KEPPLER.J Q Region 3, Office of Director ip 15791 148 24X Fiche 50-246, 82/10/13,821025025B
- --8210250262 LER 82-015/03L-0 on 920914. fluid level in gas stripper noted decreasing abnormally after stripper returned to svc following maint Caused by high stress low cycle failure of lap joint flange stub piece Lap joint flange replaced FAV.C W Misconsin Electric Power Co. 82/10/13 Region 3. Office of Director Spp. 15771 147 24X Fiche 50-266.82/10/13. 8210250258
- 8210250344 Forwards LER 82-016/01T-0 FAY, C H Hisconsin Electric Power Co 82/10/15 KEPPLER.J 0 Region 3. Office of Director 1p 15790 332 24X Fiche 50-266.82/10/15.8210250344
- --8210250352 LER 82-016/01T-0 on 821002.containment isolation velve 10V-3200C in suction line of radioactive gas & particulate monitoring sys failed to close Caused by failure of 3-way solenoid valve to cycle Valve closed & repaired FAY.C W Hisconsin Electric Power Co 82/10/15 Region 3. Office of Director 4pp 15790 333 24X Fiche 50-266.82/10/15. 82/10/250344
- T Hearing transcripts on non-antitrost matters
- 8210080052 Transcript of 821006 telephone conference to discuss rescheduling of hearing in Washington.DC Pp 1:342-1:352 * Atomic Safety and Licensing Board Panel 82/10/06 12pp 15643 284 24% Fiche 50-266.82/10/06.8210080052
- DOCKET 50-267 FORT ST VRAIN NUCLEAR GENERATING STATION
 F Security, medical, emergency & fire protection plans
- 8209150434 Releases public version of updated radiological emergency response plan. FELTON.J.H Division of Rules and Records 82/08/25 Document Managament Branch 1p 14890 193 24X Fiche 50-267, 82/08/25, 8209150434
- --B209180440 Forwards public version of updated radiological emergency response plant per 820315 request Enci revision is almost complete rewrite except for visitors ctr & RERP-FIELD procedures W/o enci WAREMBOURG, D Public Service Co of Colorada, 62/08/10 ROHRER, D Director's Office, Office of Inspection and Enforcement ip 14890 174 24% Fiche 50-247,82/08/23,8209150434
- 8210250083 Commits to ravising security plan & implementing Procedure APM 0-4 to provide for background investigation of outside contractor personnel at facility Screening program will be implemented within 60 days

 LEE.O R Public Service Co. of Colorado 82/08/25 GOLLING.J T Region 4, Defice of Director. 3pp (5787-083 24X Fiche 50-267, 82/08/28, 8210250083
- 8210210073 Releases public version of radiological emergency response plan implementing procedures. FELTON.J.H Division of Rules and Records 82/09/29 Document Management Branch ip 15774 (26 24X Fiche 50-267,82/09/29, 8210210073
- --B2102100B1 Forwards public version of radiological emergency response plan implementing procedures, including inplant/onsite ure & field monitoring

- 8210220404 Ack receipt of 820819 response to App A Iteme of [E Emergency Preparedness Appraisal Rept 50-267/92-01 Add1 info needed to complete evaluation of responso MADSEN, G L Division of Resident. Reactor Project & Engineering Programs 82/10/19 LEE, O R Public Service Co of Colorado 29 15779 160 24X Fiche 50-267, 82/10/19, 82/10220404
- P Operating license stage documents & correspondence
- 8210040114 Forwards info documenting satisfaction of each criterion of MUREO-0737. Item II B 3 repost-accident sampling sys ORNL investigation of source terms remains only open item MAREHBOURO Public Gervice Co of Colorado 82/07/27 CLARK.R A Operating Reactors Branch 3 40pp 15581 146 24X Fiche 50-267, 82/07/27, 8210040114
- 8210080256 Forwards "Radiochemical Analysis of First Plateout Prote from Fort St Vrain High-Temp Gas-Cooled Reactor" WAREMBOURG.D W Public Service Co of Colorado 82/09/2/ WUJNYCZ.O NRC - No Detailed Affiliation Olven 1p 15649 200 24X Fichs 50-247.82/09/27.8210080256
- 8210060273 Forwards suppl to EE-11-0002, Revision 2, "Addl Burveillants Requirements for PCRV Penetrations & Closures," & suppl to EE-22-0002, Revision 1, "Inservice Insp & Testing Program Addl Burveillance Requirements for Steam Generator " BREY, H L Public Service Co of Colorado 82/09/30 CLARK, R A Operating Reactors Branch 3 2pp 15621 IBO 24% Fiche 50-267, 82/09/30, 8210060273
- --0210060202 Suppl to EE-11-0002 Revision 2, "Fort St Vrain Addl Burveillance Requirements for PCRV Penetrations & Closurer" * Public Service Co of Colorado 62/09/28 12pp 15621 183 24% Fiche 50-267, 82/09/30,8210060273
- --8210060286 Suppl to EE-22-0002.Revision 1. "Fort St Vrain Inservise Insp & Testing Program Addl Surveillance Requirements for Steam Generator"

 * Public Service Co of Colorado 82/09/28 7pp 15621 144 24% Fiche 50-267.82/09/30.8210060273
- 82:0190701 Farwards "Fort St Vrain Accident Reanalysis Code (AFCA 3) Verification Following Region Dutlet Temp Redistribution." per 810210 meeting commitment Code accuratelly products transient behavior in temp redistribution configuration. RREY.H L Public Service Co of Colorado 82/10/06 NOVAN, I H Assistant Director for Operating Reactors 1p 15736 155 241 Fiche 50-267, 82/10/06, 8210190701
- --8210190706 "Fort St Vrain Accident Reanalysis Code (RECA 3) Verification Following Region Outlet Temp Redistribution " * Public Service Co of Colorado 82/10/06 42pp 13/J6 156 24X Fiche 30-267,82/10/06/8210190701
- B210270104 Forwards B21012 application to amond License DFR-34-revising surveillance requirements
 LEE.D R Public Bervice Co of Colorado B2/10/15 CLARK-R Assistant Director for Operating Reactors 2pp 15827-050 24#
 Fiche 30-267, 82/10/15, 8210270104
- --8210270113 Application to amend License DPR-34, changing Tech Epoca vainservice imap & testing program surveillance requirements LEE.O R Public Service Co of Colonado 82/10/12 9gp 15827 052 24X Fiche 50-267, 82/10/15, 8210270104
- ---8210270118 Proposed Tech Specs changes involving reserve shutdown tax surveillance, primary coolant sys surveillance requirements, tendon corroxion & anchor assemblies implementation schedule & SAR enci * Public Service Co of Colorado, 82/10/15 54pp 1562/ 061 24% Fiche 50-267, 82/10/15.8210270104
- Q. Inspection reports, IE Bulletins & correspondence
- 8210050226 Forwards IE Insp Rept 50-267/82-20 on 820801-31 No noncompliance noted MADBEN. 0. L. Division of Resident, Reactor Project & Engineering Programs 82/09/16 LEE, 0 R. Public Service Co. of Colorada 2s, 15608-309. 24X Fiche 50-267,82/09/16,8210050226

- -8210050239 IE Insp Rept 50-267/82-20 on 820801-31 No noncompliance noted Major areas inspected surveillance, maint, operational safety verification, previous insp findings, plant operations & procedures & repts
 DICKERSON M W . PLUMEE, G L . MESTERMAN, T F Division of Resident Reactor Project & Engineering Programs 82/09/10 13pp
 15408 311 24% Fiche 50-267, 82/09/16,8210050226
- 8210060273 Forwards suppl to EE-11-0002, Revision 2. "Add1 Surveillance Requirements for PCRV Penetrations & Closures," & suppl to EE-22-0002, Revision 1. "Inservice Insp & Testing Program Add1 Surveillance Requirements for Steam Generator "

 9REY, H C. Public Service Co of Colorado 82/09/30 CLARK, R A Operating Reactors Branch 3 2pp 15621 180 24X Fiche 50-267, 82/09/30, 8210060273
- --8210060282 Suppl to EE-11-0002, Revision 2, "Fort St Vrain Addl Surveillance Requirements for PCRV Penetrations & Closures " a Public Service Co of Colorado 82/09/28 12pp 15621 182 24X Fiche 50-267, 82/09/30, 8210060273
- --8210060286 Suppl to EE-22-0002, Revision 1, "Fort St Vrain Inservice Insp 2 Testing Program Add) Surveillance Requirements for Steam Cenerator "

 † Public Service Co of Colorado 82/09/28 7pp 15621 194 24x Fiche 50-267,82/09/30,8210060273
- 620B190233 IE Info Notice B0-35, Suppl 1, "Leaking & Dislodged I-125 Implant Seeds " Svc list encl COBD. Li Division of Fuel Facilities, Materials & Bafeguards 82710706 Consolidated Edison Co of New York 66pp 18761 250 24% Fache 50-000.82/10706.8208190233
- 8210280142 Forwards IE Insp Rept 50-267/82-19 on 820809~i3 & 0830~0903 & notice of violation MADSEM.C L Division of Resident. Reactor Project & Engineering Programs 82/10/06 LEE.OR Public Service Co of Colorado 2pp 15837
- --8210280145 Notice of violation from insp on 820809-13 & 0830-0903 + Division of Resident, Reactor Project & Engineering Programs 82/10/06 1p 1583 229 24X Fiche 50-267, 82/10/06, 8210280142
- --B210280149 IE Insp Rept 50-267/82-17 on B20809-13 & 0830-0903 Noncompliance noted failure to maintain test records of safety-related design changes REDAND,R T , MESTERMAN, T F Division of Resident, Reactor Project & Engineering Programs B2/09/29 9pp 15837 230 24X Fiche 50-267, 82/10/06, B210280142
- 8208190238 IE Bulletin B2-03. "Stress Corrosion Cracking in Thick-Wall, Large-Diameter, Stainless Steel, Recirculation Sys
 Plping at BUR Plants " Svc list encl
 DEYGUNG.R C Director's Office, Office of Inspection and
 Enrorcement 82/10/14 Consolidated Edison Co of New York
 115pp 15810 125 24X Fiche 50-000.82/10/14.8208190238
- 8210270104 Forwards B21012 application to amend License DPR-34, revising surveillance requirements
 LEE.O R Public Service Co of Coloredo 82/10/15 CLARK, R
 Assistant Director for Operating Reactors 2pp 15827 050 24X
 Fichs 50-267. 82/10/15. 8210270104
- --8210270113 Application to amend License DPR-34, changing Tech Specs re inservice insp & testing program surveillance requirements LEE,O R Public Service Co of Colorado 82/10/12 9pp 19827 052 24% Fiche 50-227,82/10/15,8210270104.
- --B210270118 Proposed Tech Specs changes involving reserve shutdown sys surveillance.primary coalant sys surveillance requirements, tendon corrosion & anchor assemblies Implementation schedule & SAR encl 4 Public Service Co of Colorado 82/10/15 54pp 15827 061 24X Fische 50-267.82/10/15.8210270104
- 9310220404 Ack receipt of 820819 response to App A items of IE Emergency Preparedness Appraisal Rept 50-267/82-01, Addl info needed to complete evaluation of response MADSEN.O L. Division of Resident. Reactor Project & Engineering Programs 82/10/19 LEE, OR Public Service Co of Colorado 2pp 13779 160 24% Fiche 50-267, 82/10/19, 8210220404
- R Periodic operating reports & related correspondence
- 8210130344 Forwards monthly operating rept for Bept 1982 WAREMBOURG, D. Public Service Co. of Colorado 82/10/06 Director's Office. Office of Inspection and Enforcement, 1p 15682-030 24X Fichs 30-267, 82/10/06, 8210130344

- --9210130349 Monthly operating rept for Sept 1982 MCBRIDE: L M Public Service Co of Colorado 82/10/06 Spp 15682 031 24X Fiche 50-267, 82/10/06, 8210130344
- 8210190655 Forwards monthly operating rept for Sept 1982
 WAREMBDURG, D. Public Service Co. of Colorado. B2/10/12
 QAMMILL, W.P. Assistant Director for Operating Reactors. 2pp
 15739, OBI 24X Fiche 50-267, B2/10/12, 8210190655
- --8210190667 Monthly operating rept for Sept 1982 Narrative summary encl MCBRIDE:L M Public Service Co of Colorado 82/10/06 9pp 15737 083 24X Fiche 50-267,82/f0/12.8210190655
- S Reportable occurrences, LERs & related correspondence
- 8210050331 Forwards LER 82-035/03L-0 Detailed event analysis encl WAREMBOURG-D Public Service Co of Colorado 82/09/23 COLLINS.J T Region 4. Office of Director 4pp 19602 354 24X Fiche 50-267, 82/09/23, 8210050331
- --8210050337 LER 82-035/03L-0 on 820827, engine i8 of standby generator set 1A rendered inoperable Caused by indicator lamp &/or lamp socket short circuiting causing 15 amp fuse to blow in angine 18,125-volt dc cranking circuit
 FULLER, C Public Service Co of Colorado 82/07/23 Region 4, Office of Director 1p 15502 358 24X Fiche 50-267,82/07/23, 8210050331
- 9210190537 Forwards LER 82-036/03L-0 Detailed event analysis encl (AREMBOURG, D Public Service Co of Colorado 82/10/08 COLLINS. J Y Region 4, Office of Director 3pp 15751 323 24X Fiche 50-267, 82/10/08.8210190537
- --B210190543 LER B2-036/03L-O on B2090B, one of two bearing water makeup pumps removed from svc Caused by need to rebuild mechanical seal due to normal wear Seal rebuilt FULCER.C Public Service Co of Colorado B2/10/08 Region 4. Office of Director is 19751 326 24X Fiche 50-267.82/10/08, 82/0190537
- 8210190547 PND-IV-82-037 on 821013 indication of increasing reactor bldg activity & decreasing regeneration train pressure occurred Caused by gaseous radioactivity leaking from flanged line in A purification train WESTERMAN.T F , MADSEN.G L Region 4, Office of Director 82/10/13 p 13781 360 24X Fiche 50-267, 82/10/13,8210190547
- DOCKET 50-269 OCONEE NUCLEAR STATION, UNIT 1
- F Security, medical, emergency & fire protection plans
- 8210010352 Forwards revision to safeguards contingency plan Revision withheld (ref 10CFR73 21)
 TUCKER,H B Duiz Power Co 62/09/17 DENTON,H R Office of Nuclear Reactor Regulation, Director ip 15574 139 24X
 Fiche 50~269,82/09/17,8210010352
- 8210260527 Agrees w/determination to locate fire hose stations outside affected fire areas Change from earlier commitment acceptable
 STGLZ.J F Operating Reactors Branch 4 82/09/23 TUCKER.H B
 Duke Fower Co 2pp 15830 189 24X Fiche 50-269,82/09/23.
 8210260527
- 8210040232 Application to amend Licenses DPR-98, DPR-47 % DPR-55 Amend requests delation of Tech Spac 6 4 2 re site emergency drill % definition of time within which redundant component test must be performed prior to performing maint per Tech Spac TUCKER.H, B Duke Power Co 82/09/27 DENTON, H R Office of Nuclear Reactor Regulation, Director 3pp 15986 104 24X Fiche 50-269, 82/09/27, 8210040232
- --8210040245 Proposed revision to Tech Spec Pages 3 3-4 & 6,4-1 re site emergency drill & time period within which redundant component test must be performed prior to performing maint 4 Duke Power Co. 82/09/27 4pp. 15586
- P Operating license stage documents & correspondence
- 8205130256 Forwards task force on pressurized thermal shock audit of Robinson plant re adequacy of in-plant training programs 6 operating procedures NRC will conduct similar audit at Brunswick plant.
 NOVAK: T M Assistant Director for Operating Reactors. 82/04/23, PARKER: H O Duke Power Co. 2pp 13089 038 24X Fiche. 50-249, 82/04/23, 8205130256

- 8210080036 Responds to FOIA request for documents re pins designed to hold neutron shielding pads in place under accident conditions Forwards documents listed on App A FELTON.J M Division of Rules and Records 82/08/13 EDDLEMAN.W Public Interest Research Oroup in North Carolina 2pp 15669 240 24X Fichs 50-269.82/08/13.8210080036
- --8210080044 Notification of 811009 meeting w/util in Bethesda, MD to discuss broken thermal shield bolts in Unit 1 HAONER, P C Operating Reactors Branch 4 81/10/05 STOLZ, J F Operating Reactors Branch 4 2pp 15669 268 24X Fiche 50-000, 82/08/13, 8210080036
- ---8208250417 Discusses broken core barrel assembly thermal shield bolts at Ocones 1 & applicability to other B&W plants Insp of Ocones 3 & other B&W plants w/thermal shield bolts made of same matls recommended GLSHINSKI, J A Division Division of Engineering & Technical Programs 82/03/29 EIBENHUT.D 9 Division of Licensing 4pp 15669 285 24X Fiche 50-000, 82/08/13,8210080036
- 8210040107 Advises that util response to MRC 820218 ltr w(1) be provided by 821008 Receipt of info from crane vendor & extraordinary analytical wort have delayed response TUCKER.H B Dute Power Co. 82/09/24 DENTOWHR Office of Nuclear Reactor Regulation, Director STOLZ.JF Operating Reactors Branch 4 Jp. 15581 024 24% Fiche 50-269.82/09/24.8210040107
- 8210040232 Applacation to amend Licenses DPR-38.DPR-47 & DPR-55 Amend requests deletion of Tech Spec 6 4 2 resite energency drill to definition of time within which redundant component test must be performed prior to performing maint per Tech Spec TUCKER.H D Dute Power Co 82/09/27 DENTON.H R Dffice of Nuclear Reactor Regulation, Director 870L7.J F Operating Reactors Branch 4 3pp 15586 104 24X Fiche 50-269.82/09/27.8210040232
- --8210040245 Proposed revision to Tech Spst Pages 3 3-6 & 6-1 re site emergency drill & time period within which redundant component test must be performed prior to performing maint * Duke Power Co 82/09/27 4pp 15586.107 24X Fiche 50-269,82/09/27.8210040232
- 8210190145 Forwards Amends 113,113 & 110 to Licenses DPR-38, DPR-47 & DPR-55, respectively, safety evaluation & notice of issuance & availability Amends revise Tech Specs to allow full power operation of Unit 3 during Fuel Cycle 7
 WAGNER, P.C. Operating Reactors Branch 4 82/09/29 TUCKER, H.D.
 Bute Power Co. 2pp. 15787 341 24X Fiche 50-249, 82/09/29. Duke Power Co 6210190145
- --8210190154 Amends 113,113 & 110 to Licenses DPR-38, DPR-47 & DPR-95, respectively, revising Tech Specs to allow full power operation of Unit 3 during Fuel Cycle 7 STOL7.J F Operating Reactors Branch 4. 82/09/29 31pp 15757 343 24X Fiche 50-269,82/09/29,8210190145
- --8210190161 Safety evaluation supporting Amends 113,113 & 110 to Licenses DPR-38.DPR-47 & DPR-53,respectively * Office of Nuclear Reactor Regulation, Director 82/09/29 82/09/29 App 24X Fiche 50-269-82/09/29,8210190145
- --8210170169 Notice of issuance & availability of Amends 113,113 & 110 to Licenses DPR-38.DPR-47 & DPR-55.respectively BTOL7.JF Operating Reactors Branch 4 82/09/29 2pp 15758 018 24X Fiche 50-269,82/09/29,8210190145
- 3210180323 Responds to 820913 ltr re reactor bldg purge sys Position given in 810707 & 17 ttrs remains unchanged Schedule for submitting info indicating purge sys meets operability requirements requested LAINAS, C C Assistant Director for Operating Reactors 82/09/30 Co 3pp 15745 334. 24X 10180323

ongoing NRC research program of sys Facility W MSSS plant Declines

Office of Division of /07, 8210130159

re adequacu of

Office of prating Reactors 8210180055

- -- 8210180060 Forwards partial response to Franklin Research Ctr draft technical evaluation rept re control of heavy loads, per
- B210210131 Responds to NRC 820908 ltr transmitting technical evaluator rept on emergency feedwater sys Sys may not meet all current criteria for seismic qualification but will remain functionally operable during OBE
 TUCKER, H B Duke Power Co BZ/10/13 DENYON, H R Office of
 Nuclear Reactor Regulation, Director STOL7. J F Operating Reactor,
 Branch 4 App 15766-356 24% Fiche 50-269, BZ/10/13, BZ10Z10131
- 8210210407 Application to amend DLs, revising Tech Spec C 1 allowing full gower operation of Unit 1 for interim period until appropriate safety valve ring settings can be implemented TUCKER. H B Dute Power Co 82/10/14 DENTON.H R Office of Nuclear Reaction Director STOLZ, J Operating Reacts. Branch 4 Bpp 15764 038 24X Fiche SO-269,82/10/14,6210210407
- --B210210411 Proposed revision to Tech Spec 3 1 allowing full power operation of Unit 1 for interim period until appropriate safety valve ring setting can be implemented 4 Dute Power Co 82/10/14 1p 15764 048 24X Fiche 50-269, B2/10/14, B210210407
- O Inspection reports. IE Bulletins & correspondence
- 8210070007 Responds to FOIA request for eight categories of records in steam generators & steam turbines App A documents provided in R_Udell FOIA Request 81-313 Forwards documents listed in FELTON, J M Division of Rules and Records 82/08/10 [DNG.D.J Winthrep, Stimson, Putnam & Roberts 9pp 15445 063 24X Fiche 50-000, 82/08/10,8210070007
- --8210070172 Forwards info re steam generator integrity & insps at all operating PWRs.per 750320 & 21 requests Details of insps. including defect indications, tube plugging criteria b tubes plugged will not be provided except for Point Boach (GOLLER:K R Division of Reactor Licensing (NRR-1975 anly) 75/03/24 MACCARV.R R Division of Technical Review (NRR-1975 only) 5pp 15645 196 24X Fiche 50-000.82/08/10.021807000/
- 8210150369 Forwards results of investigation of Item 7a of IC Insp. Repts 50-269/82-21.50-270/82-21 & 50-287/82-21 Deadtime values for gamma spectroscopy analyses of waste gas silver reclite certridges will cause only insignificant errors TUCKER. H B Duke Power Co 82/08/17 D'REILLY, J P Region 2 Diffice of Director 2pp 15704 267 24X Fiche 50-269, 62/08/17 8210150349.
- 8210010117 Forwards IE Insp Repts 50-269/82-33, 50-270/82-33 t 50-287/82-33 on 820817-20 No noncompliance noted DANCE, H C Division of Project & Resident Programs 82/09/02 TUCKER, H B Duke Power Co 2pp 15566 019 24X Fiche 50-269, 82/09/02, 8210010117
- --8210010124 IE Insp Repts 50-269/82-33, 50-270/82-33 & 50-287/82-33 on 820817-20 No noncompliance noted Major areas inspected action on previous enforcement matters auxiliary feedwater header repair & inservice insp procedures
 CROMLEV.B R., BLAKE, J Division of Engineering & Technical
 Programs 82/09/01 8pp 15566 021 24X Fiche 50-269.82/07/12
 8210010117
- 8210010198 Forwards IE Insp Repts 50-269/82-30, 50-270/82-30 & 30-287/82-30 on 820716-0810 No noncompliance noted DANCE, H C Division of Project & Resident Programs (82/09/10464) H D Duke Power Co 2pp 15567 258 24X Fiche 50-269, 82/09/02,8210010158 02/09/02
- --8210010166 IE Insp Repts 50-269/82-30, 50-270/82-30 & 50-287/82-30 r 820716-0810 No noncompliance noted Major areas inspected operations, surveillance testing, maint, NUREO-0737 mods & Programs 82/09/02 13pp 15567 260 24X Fiche 50-269.82/03.3
- 8210010458 Ack receipt of 820805 ltr informing NRC of steps tales to correct violations noted in 1E Insp Repts 50-269/82-23, 30-297/82-23 & 50-297/82-23 LEWIS:R C Division of Project & Resident Programs 82/09/17 TUCKER,H.B Duke Power Co 1p. 15570 182 24% Fiche. 50-269, 82/09/17,8210010458

- --8210010463 Responds to NRC 820712 ltr re violations noted in IE Insp. Repts 50-269/82-23.50-270/82-23 & 50-287/82-23 Corrective actions personnel counseled to valve 2HP-14 cut out & properly reinstalled TUCKER.H.B. Duke Power Co. 82/08/05 D'REILLY, J.P. Region 2, Office of Director 4pp 15570 183 24X Fiche 50-269.82/09/17, 8210010458
- --8210010468 Forwards IE Insp Repts 50-269/82-23.50-270/82-23 & 50-287/82-23 on 820510-0610 % notice of violation LEWIS,R C Division of Project & Resident Programs 82/07/12 PARKER,W G Duke Power Co 2pp 15570 187 24X Fiche 50-269,82/09/17.8210010458
- --8210010471 Notice of violation from insp on 820510-0610 • Division of Project & Resident Programs 82/07/12 2pp 15570 189 24X Fiche 50-269,82/09/17,8210010458
- --8210010474 IE Insp Repts 50-267/82-23.50-270/82-23 & 50-287/82-23 on 820510-0610 Noncompliance noted failure to follow procedures resulting in plant trip & inadequate procedure resulting in improper reassembly of safety-related valve ORDERS.W. FALCONER.D. BRYANT.J.C. Division of Project & Resident Programs 82/07/09 (2pp 15570 191 24X Fiche 50-269.82/09/17, 8210010458
- 63210[50253 Forwards IE Insp Repts 50-269/82-32, 50-270/82-32 & 50-287/82-32 on 820817-18 No noncompliance noted DANCE N C Division of Project 7 Resident Programs 82/09/17 TUCKER N B Duke Power Ca 2pp 15703 267 24X Fiche 50-269, 82/09/17.8210150253
- --8210150263 1E Insp Repts 50-269/82-32.50-270/82-32 & 50-287/82-32 on 820817-18 No noncompliance noted Major areas inspected lab QC & review of radiochemistry procedures & records EVANS.C D . MONTGOMERY.D M Division of Emergency Preparedness & Operational Support 82/09/15 3pp 15703 269 24X Fiche 50-269, 82/09/17.8210150253
- 8210150131 Forwards IE Insp Repts 50-269/82-35,50-270/82-35 & 50-287/82-35 on 820908-10 No noncompliance noted DANCE.H C Division of Project & Resident Programs 82/09/23 TUCKER.H B Duke Power Co 2pp 15698 312 24X Fiche 50-267,82/09/23.8210150131
- -- 8210150143 IE Insp Repts 50-269/82-35.50-270/82-35 & 50-287/82-35 on 820908-10 No noncompliance noted Hajor areas inspected RCS teatage calculations BURNETT.P T , JAPE.F Division of Engineering & Technical Programs 82/09/21 4pp 15698 314 24X Fiche 50-269.82/09/23, 8210150131
- ⇔210130290 Requests relief from inservice insp requirements
 (hydrostatic) of Section XI of ASME Boiler & Pressure Vessel
 Code
 TVCKER.H B Duke Power Co B2/10/04 DENTON, H R Office of
 Nuclear Reactor Regulation, Director STOLZ, J F Operating Reactors
 Branch 4 20pp 15678 243 24X Fiche 30-269, B2/10/04, B210130290
- 83208170233 IE Info Notice 80-35, Suppl 1, "Leaking & Dislodged I-125 Implant Seeds " Svc list encl COBUL I Division of Fuel Facilities, Materials & Safeguards 62/10/06 Consolidated Edison Co of New York 66pp 15761 250 24X Fiche 50-000.82/10/06,8208190233
- B210220426 Forwards Revision 5 to response to IE Bulletin 79-02, "Pipe Support Base Plate Designs Using Concrete Expansion Anchor Bolts"

 TUCKER.H B Dute Power Co 82/10/08 O'REILLY, J P Region 2, Office of Director 24pp 15778 273 24X Fiche 50-269,82/10/08, 82/10220426
- B210150285 EN-82-021A on 821012, order imposing civil monetary penalty issued to licensee Action based on failure to follow procedures affecting safe operation of facility BARBER.O. AXELRAD. J Director's Office. Office of Inspection and Enforcement 82/10/12 ip 15701 319 24X Fiche 50-269.82/10/12.6210150285
- B208190238 IE Bulletin 82-03, "Stress Corrosion Cracking in Thick-Walls Large-Diameter Stainless Steel, Recirculation Sys
 Piping at BWR Plants "Svc list encl
 DEYOUNG, R C Director's Office Office of Inspection and
 Enforcement 82/10/14 Consolidated Edison Co of New York.
 115pp 15810 125 24X Fiche 50-000-82/10/14,8208190238
- 4. Periodic operating reports & related correspondence
- 3210190544 Forwards monthly operating repts for Bept 1982 TUCKER:H B Duke Power Co 82/10/15 Director's Office of Inspection and Enforcement 1p 15751 343 24X Fichs 30-269, 82/10/15.8210190544

- --8210190552 Monthly operating repts for Sept 1982 REAVIS.J A Duke Power Co 82/10/15 16pp 15751 344 24x Fiche 50-269,82/10/15.8210190544
- S Reportable occurrences. LERs & related correspondence
- 8210150077 Forwards LER 81-001/O3L-0 Detailed event analysis and PARKER, W O Duke Power Co 81/02/04 O'REILLY, J P Region 2, Atlanta, Office of the Director (81/03/01) 3pp 15697 063 24) Fiche 50-269.81/02/04.8210150079
- --8210150084 LER 81-001/03L-0 on 810105, turbine trip from 70% full power occurred Caused by loss of excitation on generator field resulting from mismatch during personnel attempt to raise voit amperes reactive on Units 1 & 2

 JONES, J. L. Dute Power Co. 81/02/04 Region 2, Atlanta, Office of the Director (81/03/01) 1p 15697 066 24X

 Fiche 50-269,81/02/04,8210150079
- 8210010008 Responds to FOIA request for 19 categories of documents re nuclear reactor events & safety problems Forwards documents listed in App A FELTON.J M Division of Rules and Records 82/06/28 UDELL.R A Critical Mass Energy Project 15pp 15727 005 24X Fiche 50-000.82/06/28,8210010008
- --8210040374 Forwards LER 80-20/03L & RO 269/80-9 re failure to open auxiliary feedwater valve & failure of fire detection sys, respectively Addi attention may be warranted BENDER. H ACRS Advisory Committee on Reactor Safeguards 80/05/23 FRALEY. R F ACRS Advisory Committee on Reactor Safeguards 1p 15727 272 24X Fiche 50-000,82/06/28,8210010008
- 8210190653 PNO-[I-82-i1] on 821014. Unit 2 shut down after determining that pressurizer code safety valve design flow could not be fully maintained if called upon Seven-day outage required to change valves Exemption requested for Unit 1 IONATONIS.A. DANCE.H C Region 2. Office of Director 82/10/14 2pp 15749 036 24X Fiche 50-267. 82/10/14.8210190653
- 8210290395 Forwards LER 82-014/03L-0 Detailed event analysis encl TUCKER: H B Duke Power Co 82/10/14 O'REILLY, J P Region 2: Office of Director, 3pp 15893 043 24X Fiche 50-269,82/10/14, 8210290355
- --8210290365 LER 82-014/03L-O between 820816-0920, reactor bldg cooling unit fam iA tripped on low speed thermal overloads seven times Cause unknown fam under surveillance Fam motor may be replaced if cause of trips cannot be determined PETTY, J C Duke Power Co 82/10/14 Region 2, Office of Director ip 15853 046 24X Fiche 50-269,82/10/14.8210290355
- 8210290190 Forwards LER 82-015/03L-0 Detailed event analysis encl TUCKER.H D Dute Power Co 82/10/15 O'REILLY, J P Region 2. Office of Director 3pp 15853 287 24X Fiche, 50-269, 82/10/15, 8210290190
- --8210290197 LER 82-015/03L-0 on B20917, reactor protection sys trip pushbutton declared technically inoperable Caused by procedure deficiency which did not include required test.

 Necessary Procedures changed
 PETTY, J C Duke Power Co B2/10/15 Region 2. Office of Director ip 19853 290 24X Fiche 50-269,82/10/15,8210290190
- DOCKET 50-270 OCONEE NUCLEAR STATION, UNIT 2
- A Application/construction stage documents & correspondence
- 8210010008 Responds to FOIA request for 19 categories of documents re nuclear reactor events & safety problems Forwards documents listed in App A FELTON, J. M Division of Rules and Records 82/06/28 UDELL, R. A. Critical Mass Energy Project 15pp 15727 005 24X Ficher 50-000, 82/06/28, 8210010008
- --B204290048 Recommends prompt attention be given to problem of reactor coolent pump closure stud corrosion detected at facilities.
 Response by 820415 requested
 EISENHUT, D O Division of Licensing B2/03/24 HANAUER, B H
 Division of Systems Integration (post B11005) 3pp. 15745 270
 24X Fiche: 50-000, 82/06/28, 8210010008
- F Security, medical, emergency & fire protection plans
- 8210010352 Forwards revision to safeguards contingency plan Revision withheld (ref 10CFR73 21).

 TUCKER, H, B Duke Power Co 82/09/17. DENTON, H R Office of Nuclear Reaction Regulation, Director ip 15574 139 24X Fiche: 50-269, 82/09/17, 8210010332.

- 8210260529 Agrees w/determination to locate fire hose stations outside affected fire areas Change from seriter commitment
 - acceptable STOLZ,JF Operating Reactors Branch 4 82/09/23 TUCKER. Duke Power Co 2pp 15830 189 24% Fiche 50-269.82/09/23,
- 8210040232 Application to amend Licenses DPR-38.0PR-47 & DPR-55 Amend requests deletion of Tach Spec 6 4 2 te tite emergency drill & definition of time within which redundant component test must be performed prior to performing maint per Tech Spec TUCKER.H B Duke Power Co 82/09/27 DENTON.H A Offi Nuclear Reactor Regulation, Director 3pp 1586 104 Fiche 50-269.82/09/27.8210040232
- --8210040245 Proposed revision to Tech Spec Pages 3 3-6 & 6 4-1 re site emergency drill & time period within which redundant component test must be gerformed prior to performing maint 4 Duse Power Co 82/09/27 4pp 15586 107. 24% Fiche 50-269,82/09/27,8210040232

P Operating license stage documents & correspondence

- B2100B0036 Responds to FDIA request for documents re pins designed to hold neutron shielding pads in place under accident consistions forwards documents listed on App A FELTON, J M Division of Rules and Records 82/09/13 EDDLEMAN, W Public Interest Research Group in North Carolins 2pp 15669 240 24X Fichs 30-269,82/08/13,8210080036
- 8210040107 Advises that util response to NRC 820218 ltr will be provided by 821008 Receipt of info from crane vendor & estraordinary analytical work have delayed response TUCKER. H B Duke Power Co 82/09/24 DENTON H R Office of Nuclear Reactor Regulation, Director STOLZ, J. F Operating Reactors Branch 4 1p 15581 024 24x Fichs 50-269.82/09/24,8210040107
- 82(0040R32 Application to amend Litenses DPR-38: DPR-47 & DPR-55 Amend requests deletion of Tech Spec 6 4 2 re-site emergency drill & definition of time within which redundant component test worthiston or time blant which resumbant component east must be performed prior to performing maint per Tech Spec
 TUCKER H B Duke Power Go 62/09/27 DENTON H R Office of
 Nuclear Reactor Regulation, Director SIGL 2.J F Operating React
 Branch 4 3pp 13586 104 24% Fishe, 50-269, 62/09/27, 8210040232
- ~-8210040245 Proposed revision to Tech Spec Pages 3 3-6 & 6 4-1 re site emergency drill & time period within which redundant component test must be performed prior to performing maint & Duke Power Co 82/09/27 4pp 15586 107 24X Fiche 50-269,82/09/27,8210040232
- 8210190145 Forwards Amends 113,113 & 110 to Licenses DPR-3B, DPR-47 & DPR-55, respectively, safety evaluation & notice of issuance & availability Amends revise Tech Specs to allow full power operation of Unit 3 during Fuel Cycle 7
 WAGNER.P C Operating Reactore Branch 4 82/09/29 TUCKER, H B Duke Power Co. 2pp 15757 341 24X Fiche: 50-269, 82/09/29, 82/09/29, 8210190145
- --9210190154 Amends 113.113 & 110 to Licenses DPR-38, DPR-47 & DPR-59, respectively, revising Tech Spacs to allow full power operation of Unit 3 during Fuel Cycle 7 STOLE.1 JF. Operating Reactors Branch 4 82/09/29 31pp 15757:343 24X Fiche 50-269.82/09/29.8210190145
- --8210190161 Bafety evaluation supporting Amenda 113,113 & 110 to Licenses DPR-38,DPR-47 & DPR-55-respectively. Office of Nuclear Reactor Regulation, Director 82/09/29 15758 012 24X Fiche 50-269,82/09/29,8210190145. B2/09/29 600
- --B210190169 Notice of issuance & availability of Amends 113,113 & 110 to Licenses DPR-3B, DPR-47 & DPR-5B, respectively GYOLX.JF Gparating Reactors Branch 4 82/09/29 20p 18758 018 24X Fiche: 50-269, 82/09/29, 8210190145
- 82:0180323 Responds to 8209:3 itr re reactor bldg purge sys Position given in 8:07:07 & 17 ltre remains unchanged Bchedule for submitting info indicating purge sys meets operability requirements requested
 LAINAS.O.C. Assistant Director for Operating Reactors. 82/09/30.
 TUCKER, H. B. Dute Power Co. 3pp. 15745:334 24X
 Fiche 50-269,82/09/30,8210180323
- 8210180055 Responds to NRC 82060B request for add1 info re adequacy of station electric distribution sys voltages. Requested info expected by 821022.
 TUCKER, H B. Duke Power Co. 82/10/08. DENTON: H R. Office of Nuclear Reactor Regulation, Director. BTDLZ, J F. Operating Reactors Branch 4. 1p. 13720.010. 24% Fiche 50-269,82/10/08,8210180055.

- --8210180060 Forwards partial response to Franklin Research Ctr deels technical evaluation rept re control of heavy loads, per NURE0-0612
 - NUREG-0612
 TUCKER, H B Duke Power Co B2/10/08
 DENTON, H R Dffice of STOLZ, J F Operating
 Reactors Branch 4 Spp 15720 011 24X Fiche 50-269,82/10/02
- 8210210131 Responds to NRC 82090B itr transmitting technical evaluation rept on emergency feedwater sys Sys may not meet all current criteria for seismic qualification, but will remain Tricking for setting questivication, due will remain functionally operable during OBE TUCKER. H B Duke Power Co B2/10/13 DENTON, H R Office of Nuclear Reactor Regulation, Director STOLZ, J F Derating Reactor Branch 4 4pp 15766-356 24X Fiche 50-269, 82/10/13, 8210210131
- --82102104ti Proposed revision to Tech Spec 3 I allowing full power operation of Unit 1 for interim period until appropriate safety valve ring setting can be implemented a Duke Power Co 82/10/14 ip 15764 048 24% Fiche 50-269,82/10/14,8210210407
- Q Inspection reports: IE Bulletins & correspondence
- 8210070097 Responds to FOIA request for eight categories of records visteem generators & steam turbines App A documents provided in R Udell FDIA Request 81-313 Forwards documents listed (n APP B FELTON: J M FÉLTON.J M Division of Rules and Records 82/08/10 10NO, D J Winthrop, Stimson, Putham & Roberts 9pp 15645 063 24X Fiche 50~000.82/08/10.82/097007
- --8210070172 Forwards info re steam generator integrity & insps at all operating PMRs.per 750320 & 21 requests Details of insps. including defect indications, tube plugging criteria & tubes plugged will not be provided except for Point Beach & OOLLER.K R Division of Reactor Licensing (NRR-1975 only) 75/03/24 MACCARY.R R Division of Tachnical Review (NRR-1975 only) Spp. 15445 196 24X Fiche 50-000,82/08/10,8210070007
- 8210150369 Forwards results of investigation of Item 7a of IE Intp
 Repts 50-269/82-21.50-270/82-21 & 50-287/82-21 Deadtime
 values for gamma spectroscopy analyses of waste gas silver
 reolite cartridges will cause only insignificant errors
 TUCKER, H B Dute Power Co 82/08/17 O'REILLY, J P Region 2.
 Office of Director 2pp 13704 269 24X Fishe 50-269.02/09/17.
- 8210010117 Forwards 1E Insp Repts 50-269/82-33,50-270/82-33 & 50-287/82-33 on 820817-20 No noncompliance noted DANGE.H.C Division of Project & Resident Programs 82/09/8706KER,H B Duke Power Co 2pp 15566 019 24X Fiche: 50-269, 82/09/02, 8210010117 82/09/02
- --8210010124 IE Insp Repts 80-269/82-33, 30-270/82-33 & 50-287/82-33 Altotolica it Insp Repts 50-267/82-33, 50-270/82-33 & 50-287/82-33 on 820817-20 No noncompliance noted Major areas inspected action on previous enforcement matters, auxiliary feedwater header repair & inservice insp procedures CROMLEY, B R . BLAKE, J J Division of Engineering & Technical Programs 82/09/01 8pp 15566 021 24X Fiche 50-269.82/09/28210010117
- 8210010158 Forwards IE Insp Repts 50-269/82-30, 50-270/82-30 t 50-287/82-30 on 820716-0810 No noncompliance noted DANCE, M. C Division of Project t Resident Programs #22/09, TUCKER, M. B Duke Power Co 2pp 15567 \$58 24% Fiche 50-269, 82/09/02, 8210010158 82/09/02
- ---8210010166 IE Insp Repts 50-269/82-30.50-270/82-30 & 50-287/82-30: 820716-0810 No noncompliance noted Major areas inspected operations surveillance testing maint.NUREG-0737 mod; & prefuelling activities
 ORDERS, M. FALCUNER, D. BRYANT, J.C. Division of Project & Realst Programs. 82/07/02 13pg 15567 260, 24X Fiche 50-269, 92/01 821001015B.
- 8210010458 Ack receipt of 820805 ltr informing NRC of steps talen st correct violations noted in IE Inep Repts 50-269/82-23, 50-270/82-23 & 50-287/82-23 LEMIS,R.C. Division of Project & Resident Programs 82/09/17. TUCKER,H B Dute Power Co ip 15570.182, 24X Fiche: 50-269, 82/09/17, 8210010458

DOCKETED ITEMS

- --8210010463 Responds to NRC 820712 ltr re violations noted in IE Insp Repts 50-269/82-23,50-270/82-23 & 50-207/82-23 Corrective actions personnel counseled & valve 2HP-14 cut out & properly reinstalled TUCKER, H B Dute Power Co 82/08/05 O'REILLY, J P Region 2, Office of Director 4pp 15570 183 24X Fiche 50-269,62/09/17, 8210010458
- --B210010468 Forwards IE Insp Repts 50-269/82-23,50-270/82-23 & 50-287/82-23 on B20510-0610 & notice of violation LEWIS.R C Division or Project & Resident Programs 82/07/32 PARKER.N O Duke Power Co 2pp 15570 187 24X Fiche 50-269,82/09/17.8210010458
- --8210010471 Natice of violation from insp on 820510-0410 * Division of Project & Resident Programs 82/07/12 2p 15570 189 24% Fiche 50-249, 82/09/17.8210010458
- --8210010474 IE Insp Repts 50-269/82-23.50-270/82-23 & 50-287/82-23 on 820510-0610 Noncompliance noted failure to follow procedures resulting in plant trip & inadequate procedure resulting in inplant trip & inadequate procedure resulting in improper reassembly of safety-related valve GRDERS, W. FALCONER, D. BRYANT, J. C. Division of Project & Resident Programs 82/07/07 12pp 15570 191 24X Fiche 50-269, 82/09/17, 8210010458
- 6210150253 Forwards IE Insp Repts 50~269/82-32.50-270/82-32 & 50~287/82-32 on 820817-18 No noncompliance noted DANCE.H C Division of Project & Resident Programs 82/09/17 TUCKER.H B Duke Power Co 2pp 15703 267 24X Fiche 50~269.82/09/17.8210150253
- --8210150263 IE Insp Repts 50-269/82-32,50-270/82-32 & 50-287/82-32 on 820817-18 No noncompliance noted Major areas inspected lab QC & review of radiochemistry procedures & records EVAMS.C D , MONTGOMFRY, D II Division of Emergency Preparedness & Operational Support 82/09/15 3pp 15703 269 24X Fiche 50-269,82/09/17,8210150253
- 6210150131 Forwards IE Insp Regts 50-269/82-35,50-270/82-35 & 50-287/82-35 on 820908-10 No noncompliance noted DANCE. H C Division of Project & Resident Programs 82/09/23 TUCKER. H B Duke Power Co 2pp 15698 312 24X Fiche 50-269, 82/09/23,8210150131
- B210130290 Requests relief from inservice insp requirements (hydrostatic) of Section XI of ASME Boiler & Pressure Vessel Code TUCKER.H B Duke Power Co B2/10/04 DENTON,H R Office of Huclear Reactor Regulation, Director STOLZ.JF Operating Reactors Branch 4 20pp 15678 243 24X Fiche 50-269.82/10/04.8210130290
- 820B190233 [E Info Notice 80-35, Suppl], "Leaking & Dislodged I-125 Implant Seeds " Svc list encl COBB.L | Division of Fuel Facilities, Materials & Safeguards 82/10/06 Consolidated Edison Co of New York 64pp 15761 250 244 Fiche 50-000.82/10/06.8208190233
- 9210220424 Forwards Revision 5 to response to IE Bulletin 79-02, "Pipe Support Dase Plate Designs Using Concrete Expansion Anchor Bolts "
 TUCKER, K B Duke Power Co 82/10/08 O'REILLY, J P Region 2, Office of Director 24pp 15778 273 24X Fiche 50-269, 82/10/08, 8210220424
- 620Bi9023B IE Bulletin 82-03, "Stress Corrosion Cracking in Thick-Wall. Large-Diameter, Stainless Steel, Rectroulation Bys Piping at DNR Plants "Svc list encl pEYOUNG.R C Director's Office, Office of Inspection and Enforcement 82/10/14 Consolidated Edison Co of New York, 115pp 15810 125 24X Fiche 50-000, 82/10/14,820819023B
- R Periodic operating reports & related correspondence
- 8210190544 Forwards monthly operating repts for Bept 1982 TUCKER,H B Duke Power Co 82/10/15 Director's Office Office of Inspection and Enforcement ip 15751 343 24X Fiche 50-269, 82/10/15,8210190544
- --8210190552 Monthly operating repts for Sept 1982 REAVIS, J A Duke Power Co 82/10/15 16pp 15751 344 24X Fiche 50-269,82/10/15,8210190544

- S Reportable occurrences, LERs & related correspondence
- 8210190653 PND-II-82-111 on B21014. Unit 2 shut down after determining that pressurizer code safety valve design flow could not be fully maintained if called upon Seven-day outage required to change valves Exemption requested for Unit 1 IONATONIS: A. DANCE; H. C. Region 2. Office of Director 82/10/14 2pp 15740 036 24% Fiche 50-269.82/10/14.8210190653
- 8210170695 RO on 821014. Unit 2 core relief valves declared inoperable due to analysis prompted by BEW safety concern Unit 3 valves were offsite undergoing ring adjustment Immediate shutdown of Unit 2 commenced

 Duke Power Co 82/10/14 Region 2. Office of Director ip 15736 200 24X Fiche 50-270.82/10/14.8210190695
- 8210290083 Forwards LER 82-012/03L-0 Detailed event analysis enci TUCKER.H B Duke Power Co 82/10/15 D'REILLY, J P Region 2, Office of Director 2pp 15854 047 24X Fiche 50-270, 82/10/15, 8210270083
- --B2102900B7 LER 82-012/03L-0 on 820916, turbine driven emergency feedwater pump declared inoperable when trip/throttle valve 2MS-74 discovered tripped in closed position Cause not known Valve resut Video alarm will be repaired PETTY.J C Duke Power Co 82/10/15 Region 2, Office of Director 19 15854 049 24X Fiche 50-270, 82/10/15,82102900BJ
- DOCKET 50-271 VERMONT YANKEE MUCLEAR POWER STATION

 F Security, medical, emergency & fire protection plans
- 8210120346 Informs that Revision 6 to physical security plan acceptable Encl to 820720 itr transmitting revision withheld (ref 10CFR73 21) VASSALLO, D B Operating Reactors Branch 2 82/09/22 SINCLAIR, J D Vermont Yenkee Nuclear Power Corp 2pp 15691 101 24X Fiche 30-271, 82/09/22, 8210120346
- 8210210221 Forwards IE Sefeguards Insp Rept 50-271/82-15 on 820728-30 No noncompliance noted MARTIN,T T Division of Engineering & Technical Programs 82/10/04 SINGLAIR,J B. Vermont Yankee Nuclear Power Corp 2pp 15766 331 24% Fiche 50-271.82/10/04.8210210221
- --B210210238 IE Safeguards Insp Rept 50-271/B2-15 on B2072B-30 No noncomptiance noted Major areas inspected facility organization measurement & controls.shipping & receiving storage & internal control & physical inventory DELLA RATTA.A. WOLTNER.E F. 000V.A T Division of Engineering & Technical Programs B 82/09/30 7pp 15766 333 24X Fiche 50-271.82/10/04.8210210221
- B210270426 Releases public version of revised emergency plan FELTON, J M Division of Rules and Records 82/10/08 Document Management Branch 1p 15833 054 24X Fiche 50-271,82/10/08, B210270426
- --8210270430 Forwards public version of Revision 4 to emerge MARKT.D. i Varmont Yankee Nuclear Power Corp. MARKT.D Atomic Electric Co 82/09/90. Office of Nuclear Reac Regulation Director 2pp 15833 055 24X Fiche 50-27 8210270426
- --8210270432 Public version of Revision 4 to emergency plan MURPHY,W F Vermont Yankee Nuclear Power Corp 82/09/28 15833 057 24X Fiche 50-271,82/10/08,8210270426
- 8210180190 Forwards addi info requested in 820812 telcon re pr alternate shutdown sys Encl info addresses separate routing of cables for valves FCV 2-17 & FCV 2-18 & RHR valves VIO-17 & VIO-18 MARSOLAIS, L D Vermont Yankee Nuclear Power Corp 82/10/11 VASSALLO, D B Operating Reactors Branch 2 2pp 15719 118 Fichs 90-271, 82/10/12, 82/10/80190
- 8210220411 Ack receipt of 820908 itr informing NRC of steps to correct violations noted in 1E Inep Rept 50-271/82-05.
 ALLAN J. H. Region I, Office of Director 82/10/12 MURPH) Vermont Yankse Nuclear Power Corp. 1p. 15780 228 24% Fiche 50-271,82/10/12,8210220411
- --8210220418 Responds to NRC B20722 itr re violations noted in Rept 50-271/82-05 Corrective actions study performed to determine how intent of augmentation goals of NUREO-0654 could be achieved after declaration of emergency.

 MURPHY, W P Vermont Yankee Nuclear Power Corp. 82/09/08 SMITH, 0 H Division of Emergency Preparedness & Operation Support. 29pp 15780 229 24X Fiche 50-271,82/10/12,821

- 8210280136 Releases public version of emergency plan itrs of agreement FELTON, J N Division of Rules and Records 82/10/12 Document Management Branch 1p 15862 248 24X Fiche 50-271.82/10/12.8210280136
- --B210280438 Forwards public version of errata to Change 4 to emergency plan App E. consisting of itrs of agreement between licensee & States of VT.MA & NH.NDA.US Air Force & various local hosps & businesses Receipt form enci MARKT. D Vermont Yankee Nuclear Power Corp MARKT. D Yankee Atomic Electric Co 82/10/05 Office of Nuclear Reactor Regulation. Director ip 15862 249 24% Fiche 50-271.82/10/12, 8210280136
- -- 8210280143 Public version of strata to Change 4 to emergency plan App E. Consisting of Itrs of agreement between licensee & States of VT. (A& & Nik. (DAA.) (B Air Force & various local hosps & businesses • Vermont Yankee Muclear Power Corp. • Yankee Atomic Electric Co. 82/10/05 Plpp. 15862 250 24X Fiche 50-271.82/10/12.
- P Operating license stage documents & correspondence
- 8210210185 Forwards safety evaluation of methods used for analysis of physics & thermal-hydraulic performance
 VASSALLO.D B Operating Reactors Branch 2 82/09/15 SINCLAIR, J D
 Vermont Yankee Nuclear Power Corp 2pp 15774 270 24X
 Fiche 50-271.82/09/15.8210210185
- --B210210200 Safety evaluation supporting reload analysis methods based on review of technical repts submitted by util re analysis of physics & thermal-hydraulic performance BROOKS, H. HSILY. ROQUELY. U Office of Nuclear Reactor Regulation. Director B2/09/15 27pp 15774 272 24X Fichs 50-271.82/09/15.8210210185
- 8210210101 Forwards Amend 72 to License DPR-28, safety evaluation & notice of issuance & availability Amend Incorporates revised core thermal hydraulic limiting conditions of operation during Fuel Cycle 9 ACONEY V. Derating Reactors Branch 2. 82/09/16 SINCLAIR, J.B. Velmont Yankee Nuclear Fower Corp. 2pp. 15774-301 24X Fiche 50-271, 62/09/16. 8210210101
- --B210210112 Amend 72 to License DFR-2B, changing Tech Specs to incorporate revised core thermal hydraulic limiting conditions during Funl Cycle 9
 VASSALLO.D B Operating Reactors Branch 2 82/09/16 App 15774 303 24X Fiche 50-271.82/09/16.8210210101
- --8210210121 Safety evaluation supporting Amend 72 to 1.1cents DFR-28 * Office of Nuclear Reactor Regulation, Director 62/09/16 App 15774 307 24X Fiche 50-271,82/09/16,8210210101
- --6210210127 Notice of issuance & availability of Amend 72 to Lirense DPR-2B VASSALLO, D B Operating Reactors Branch 2 82/09/16 2pp 15774 311 24X Fiche: 50-271, 82/09/16,8210210101
- 8210040113 Comments on systematic assetsment of licensee performance rept.discussed at 820708 meeting Rept fair appraisal of activities for rept period MRPHY, BY Permont Yankee Nuclear Power Corp 82/07/28 STAROSTECKI, R Division of Project & Resident Programs 2pp 15581 144. 24X Fiche 50-271,82/09/28.8210040113
- 8210120343 Requests listing of submittals re inservice testing program within 30 days
 VASSALLO, B B Operating Reactors Branch 2, 82/09/28 SINCLAIR, J B Vermont Yankee Nutleer Power Corp 2pp 15691 039 24X
 Fichs 50-271,82/09/28,8210120343
- 82:0150447 Informs that revision to administrative section of Tech Specs re shift manning requirements & working hour guidelines not appropriate Guitable controls already imposed to will be subj to insp & enforcement by Region 1 MURPHY. W P Vermont Yankse Nuclear Power Corp 82/10/12 EISENHUT, 0 Q Division of Licensing ip. 15705 028 24X Fiche 50-271, 62/10/12, 82:0150447
- B210270356 Advises that util response to NUREO-0578 also satisfies NUREO-0737. Item II E 4 i. "Dedicated Hydrogen Penetrations " Item resolved. VABBALLO, D B Operating Reactors Branch & 82/10/14 BINCLAIR, J B Vermont Yankee Nuclear Power Corp ip 15834 359 24X Fithe. 30-271. 82/10/14, 8210270356.

- O Inspection reports. IE Bulletins & correspondence
- B21005044B Forwards request for additinfo based on review of 800/07 k 1110 responses to IE Builetin 80-11 re masonry wall dosign VASSALLO, D. B. Operating Reactors Branch 2 82/08/30 SINCLAIR. J & Vermont Yankee Nuclear Power Corp. Spp. 15612 357 24X
- 821007037& Forwards IE Insp Rept 50-971/82-16 on 820802-30 No noncompliance noted STARDSTECKI, R Division of Project & Resident Programs 82/09/24 SINCLAIR. J B Verment Yankee Nuclear Power Curp 2pp 15633 360 24% Fiche 50-271,82/09/24,821007037&
- --B210070393 IE Insp Rept 50-271/B2-16 on B20802-30 No noncompliance noted Major areas inspected previous insp findings, plant operations, physical security, operational surveillance, maint activities & safeguard sus operability RAYMOND.W J. OALLO.R M. Division of Project & Resident Programs B2/09/22 16pp 15634 001 24X Fithe 50-2/1, B2/09/24, B21007077p.
- B210010136 Advises that all future correspondence from Region | Uill be addressed to WP Kurphy Change will assure direct communication to senior licensee mgt re NRC insplindings, sufforcement actions or requests HAYNES.R C Region i. Office of Director B2/09/27 MURPHY.H P Vermont Yankee Nuclear Power Corp 3pp 15567 237 24X Fiche 50-2/1, B2/09/27, B210010136
- 9210150244 Forwards IE insp Rept 50-271/87-14 on 920704-30 & notice of violation
 STAROSTECKI,R Division of Project & Resident Programs 02/09/22
 SINCLAIR, J B Vermont Yankee Nuclear Power Corp 2pp 15704 331
 24X Fiche 50-271.82/09/27.8210150246
- --8210150298 Notice of violation from insp on 820706 30 # Division of Project & Resident Programs 82/09/27 lp 15704 336 24% Firke 50-271.82/09/27.8210150246
- --BRIO150274 IE Insp Rept 50-271/B2-14 on BRO706-30 Noncompliance noted failure to post hot spot radiation area per plant Administrative Procedure 0503 & Tech Epecs RAYMOND. W J , COLLINS.B J , GALLO.R M Division of Project & Resident Programs DR/07/21 20pp 15704 337 24x Fiche 50-271, 82/07/27.8210150246
- 82100401k3 Comments on systematic assessment of licenses performance rept.discussed at 82090B meeting Rept Fair appraisal of activities for rept period MURPHY.B P Vermant Yankee Nuclear Power Corp 82/09/20 STAROSTECKI.R Division of Project & Resident Programs 2pp 15581 144 24X Fiche 50-271,82/09/28,8210010113
- 8210210221 Forwards IE Safeguards Insp Rept 50-271/87-15 en 6207-8-3.
 No noncompliance noted
 MARTIN.T Y Division of Engineering & Technical Programs 62/10,
 SINOLAIR, J B Vermont Yankee Nuclear Power Corp 2pp 15765 211
 24X Fiche 50-271,82/10/04,8210210221
- --8210210238 IE Bafaguerds Insp Rept 50-271/B2-15 on 670788-10 Na noncompliance noted Major areas inspected facility organization, measurement & controls, shipping & receiving storage & internal control & physical inventory DELLA RATTA.A. WOLTNER: E F. GODY, A T. Division of Engineering Technical Programs & 82/09/30 7pp 15766-333 24X Fiche, \$0-271,82/10/04,8210210221
- 8208190233 lE Info Notice 80-35, Suppl 1: "Leaking & Dielogged 3-124 fmplant Seeds " Syr list entl Division of Fuel Facilities, Materials & Safeguards 82/10/06 Consolidated Edison Co of New York & Appl 15761 2' 24X Fiche 50-000.82/10/06.8208170233.
- 8210150267 EN-82-033 on or about 821015, notice of violation to hotics civil penalty will be (saued Action based on violation refailure of station personnel to promptly recognize changes in status of safety-related equipment CRAIG. J. AXECRAD. J. Region i. Office of Director 82/10/12 1 15703 244 24X Fiche 50-271, 82/10/12, 8210150267
- 8210720411 Ack receipt of 820908 ltr informing NRC of etaps taken; correct violations noted in IE Insp Rept 50-271/82-05 ALLAN.J M Region I. Office of Director 82/10/12 HURPHY, M p Vermont Yenkee Nuclear Power Corp ip 15780 228 24X Fithe 50-271.82/10/12.8210220411

- -8210220418 Responds to NRC 820722 ltr re violations noted in IE Insp Rept 50-271/82-05 Corrective actions study performed to determine now intent of augmentation goals of NUREG-0454 could be achieved after declaration of emergency MURPHY, H P Vermont Vankee Nuclear Power Corp 82/09/08 SMITH, O H Division or Emergency Preparedness & Operational Support 27pp 15780 229 24x Fiche 50-271,82/10/12,8210220411
- 8208190238 IE Bulletin 82-03. "Stress Corrosion Cracking in Thick-Hall-Large-Diameter. Stainless Steel. Recirculation Sys Piping at BWR Plants " Syc list encl DEYGUNO.R C Director's Office. Office of Inspection and Enforcement 82/10/14 Consolidated Edison Co of New York 115pp [5910-125 24x Fiche 50-000.82/10/14.8208190238
- A Periodic operating reports & related correspondence
- 5210130189 Forwards monthly operating rept for Sept 1982 HURPHY, W.P. Vermont Vankee Nuclear Power Corp. 82/10/08 Management Information Branch 1p 15674 107 24X Fiche 50-271, 82/10/08,8210130189
- --8210130193 Monthly operating rept for Sept 1982 BURGER, F J Vermont Yantoe Nuclear Power Corp 82/10/08 6pp 15674 108 24X Fiche 50-271,82/10/08,8210130189
- S Reportable occurrences, LERs & related correspondence
- 8210190022 Forwards LER 82-020/03L-0

 FELLETIER.J P Vermont Yanker Nuclear Power Corp 82/10/05

 HAYNES,R C Region 1, Office of Director 1p 15742 139 24X

 Fiche 50-27L 82/10/05.8210190022
- --8210190029 LER 82-020/03L-0 on 820902.indication on RHR 898 blinked on & off at 2.700 gpm flow rate Indication lost when valve shut Caused by loose wring on valve limit switch resulting in lost of position indication Connection tightened PELLETIER. J P Vermont Yankee Nuclear Power Corp 82/10/05 Region 1. Diffice of Director 3pp 15742 140 24X Fiche 50-271.82/10/05.8210190022
- B210210204 Forwards LER 82-021/03L-0
 PELLETIER, J P Vermont Yankee Nuclear Power Corp B2/10/12
 HAYNES, R C Region 1, Office of Director 1p 15766 343 24X
 Fiche 50-271, 82/10/12, 8210210204
- --8210210214 LER 82-021/03L-0 on 820914, while performing pump operability surve; llence on RCIC sys. RCIC turbine tripped on overspeed Caused by failure of electric governor module Module replaced Bad transistor found in tach generator PELLETIER. J. P. Vermont Yanker Nuclear Power Corp. 82/10/12 Region 1. Office of Director ip 15766-344 24X Fiche 50-271.82/10/12.8210210204
- DOCKET 50-272 SALEM NUCLEAR GENERATING STATION, UNIT 1

 F Security, medical, emergency & fire protection plans
- 8210250245 Forwards 1982 FEMA/NRC observed exercise scenario for B21013 exercise Revisions reflect changes agreed upon during 820420 neeting W/NRC & FEMA 2UPKG. J M Public Service Electric & Oas Co of New Jersey 82/09/16 HAYNES, R C Region 1, Office of Director 148pp 15789 002 24X Fiche 50-272,82/09/16.8210250245
- 6210240518 Forwards exemption from requirements of 10CFR50 48 re fire protection of safe shutdown capability VARGA: 8 A Operating Reactors Branch | 82/09/14 UDERITZ: R A Public Service Electric 8 Gas Co of New Jersey 3pp 15830 168 24X Fiche 50-272.82/09/16.8210240518
- --8210260521 Exemption from requirements of 10CFR50 48 re fire protection of safe shutdown capability
 EISENHUT.D 0 Division of Licensing 82/09/16 Public Service
 Electric & Gas Co of New Jersey App 15830 171 24X
 Fiche 50-272,82/09/16.8210260518
- --8210260524 Safety evaluation supporting licensee request for exemption from requirements of 10CFR50 48 re fire protection of safe shutdown capability

 Office of Nuclear Reactor Regulation, Director 82/09/16 3pp 15830 175 24X Fiche 50-272,82/09/16,8210260518
- 8210060431 Forwards exemption from requirements of Section IV F 1 of App E to 10CFR50, to allow next full-scale emergency preparedness exercise at facility to be conducted on or about 820929, granting 820709 request VARGA, S A Operating Reactors Branch 1 82/09/23 UDERITZ, R A Public Service Electric & Oas Co of New Jersey 3pp 15636 227 24% Fiche. 50-272, 82/09/23, 8210060431

- --8210060433 Exemption from requirements of Section IV F 1 of App E to 10CFR50.to allow next full-scale emergency preparedness exercise at facility to be conducted on or about 820929 Evaluation encl EISENHUT.D 0 Division of Licensing 82/09/23 Public Service Electric & Oas Co of New Jersey 5pp 15636 230 24X Fiche 50-272.82/09/23.8210060431
- P Operating license stage documents & correspondence
- 8210050485 Forwards documentation of satisfactory completion of requirements contained in 790921 ltr re TMI Action Item II E I I concerning auxiliary feedwater sys VAROA.6 A Operating Reactors Branch I 82/09/20 UDERITZ.R A Public Service Electric & Oas Co of New Jersey 3pp 15626 277 24X Fiche 50-272.82/09/20.8210050485
- --8210050470 "Suppl to Bafety Evaluation Rept for Salem Units 1 & 2 Implementation of Recommendations for Auxiliary Feedwater Sys "
 * Office of Nuclear Reactor Regulation, Director 82/07/20 Spp 15626 280 24X Fiche 50-272.82/07/20.8210050485
- G210130603 Advises that installed monitoring sys required by TMI Action Items II F 1 4.II F 1 5 & II F 1 6 acceptable & items considered closed VAROA.S A Operating Reactors Branch 1 B2/09/28 UDERITZ, R A Public Service Electric & Qas Co of New Jersey 2pp 15692 349 24X Fichs 50-272.82/09/28,8210130603
- 8210190047 Informs that util rod exchange methodology not approved because of calculational content of reactivity measurement. New submittal or return to boron dilution method requested VAROA.B A Operating Reactors Branch 1 82/09/29 UDERITZ.R A Public Bervice Electric & Gas Co of New Jersey 3pp 15761 041 24X Fiche 50-272.82/09/29.8210190047
- 8210190507 Application for amend to Licenses DPR-70 & DPR-75, revising core limits, fractional thermal power factor limit, performance of RCS water inventory balance & boron concentration & contained vol limits
 LIDEN, E. A. Public Service Electric & Gas Co. of New Jersey
 82210705 VARCA, S.A. Operating Reactors Branch i 2pp 15863 124
 24X Fichs 50-272, 82/10/05, 8210190507
- --8210190515 Proposed Tech Spece supporting application to amend Licenses DPR-70 & DPR-75, revising core limits, fractional power factor limit, performance of RCB water inventory balance & boron concentration & contained vol limits

 "Public Service Electric & Oas Co of New Jersey 82/10/05
 17pp 15863 126 24% Fichs 50-272,82/10/05,8210190507
- 8210270136 License Change Requests 82-17-20-21 & 22 to Licenses BPR-70 & DPR-75 Changes involve inservice insp of snubbers steam generator insp ports, containment ventilation valve insp & surveillance functional testing LINDEN,E A Public Service Electric & Oas Co of New Jersey BZ/10/07 VAROA,B A Operating Reactors Branch 1 3pp 15827 026 24X Fichs 50-272,82/10/07,8210270136
- --8210270142 Proposed Tech Spec changes re inservice insp of snubbers, installation of steam generator insp ports, pressure drop test & reactor trip instrumentation

 # Public Service Electric & Gas Co of New Jersey 82/10/07

 8pp 15827 029 24X Fiche 50-272,82/10/07,8210270136
- 8210180009 Advises that design changes satisfying concerns expressed in 820917 request for additinfore reactor protection sys/ESF actuation sys initiated Tech Specs will be modified to address setpoint changes
 LIDEN.E A Public Service Electric & Gas Co of New Jersey, 82/10/09, VAR9A.S A Derating Reactors Branch 1 ip 15720 024 24X Fiche 50-272,82/10/08,8210180009
- B210220275 Informs that review & plans re Cycle 5 reload core is expected to achieve burnup of 11500 MMD/MTU Startup physics testing will include control rod drive tests & droptime & critical boron concentration measurements
 LIDEN, E. A. 'Public Service Electric & Gas Co. of New Jersey
 82/10/14 VAROA, B. Operating Reactors Branch i 4pp. 15778 191
 24X Fiche 50-272,82/10/14,8210220275
- 8210270352 Forwards Amends 48 & 13 to Licenses DPR-70 & DPR-75, respectively, safety evaluation & notice of issuance & availability Amend revises process & effluent monitors to agree w/existing plant conditions
 ROSS.W J Operating Reactors Branch i 82/10/18 UDERITZ.R A Public Service Electric & Oas Co of New Jersey 2pp 15834 318. 24X Fiche 50-272, 82/10/18, 8210270352

- --8210270355 Amends 48 & 13 to Licenses DPR-70 & DPR-75, respectively, revising process & effluent monitors to agree w/existing plant conditions
 VARCA, S A Dereting Reactors Branch 1 82/10/18 14pp 15834 320 24X Fiche 50-272,82/10/18,8210270352
- --B210270360 Safety evaluation supporting Amends 48 & 13 to Licenses DPR-70 & DPR-75, respectively. + Office of Nuclear Reactor Regulation, Director 15834 334 24% Fiche 50-272.82/10/18.8210270352
- --8210270366 Notice of issuance & availability of Amends 48 & 13 to Licenses DPR-70 & DPR-75 respectively VAR9A.S A Operating Reactors Branch 1. 82/10/18 2pp 15934 340 24% Fiche 50-272,82/10/18.8210270352
- O Inspection reports. #E Bulletins & correspondence
- 8210080015 Addl response to FOIA request for 19 categories of info re nuclear reactor events & safety problems forwards documents listed in App A Documents in App B completely withheld (ref FOIA Exemption 5)
 FELTON, J M Division of Rules and Records 82/07/12 UDELL.R A Critical Mass Energy Project 9pp 15665 027 24X
 Fiche 50-000.82/07/12,8210080015
- --8210080150 Systematic assessment of litensee performance notes re facility evaluation for Sept 1979-Aug 1980 NRC - No Detailed Affiliation Oiven 80/08/31 8pp 13568 043 24X Fiche 50-000,82/07/12,8210080015
- 8210070007 Responds to FOIA request for eight categories of records resteem generators & steem turbines App A documents provided in R Udell FOIA Request 81-313 Forwards documents listed in App B FELTON.J H Division of Rutes and Records 82/08/10 LONG.D J Winthrop. Stimson, Putnam & Roberts 9pp 15645 063 24X Fiche 50-000.82/08/10.82/0070007
- --8210070837 Forwards tabulated data on stoam generator insp & maint at facilities Data should be provided to licensees
 IPPOLITO T Operating Reactors Assessment Branch 82/04/01
 VARRAGE Operating Reactors Branch 1. 5pp 15645 131 24X
 Fichs 50-000,82/08/10.8210070007
- 8210120328 Responds to violations noted in IE Insp Repts 50-272/82-17 b 50-311/82-17 on 820707-0803 Corrective actions administrative procedure will be revised so future temporary design changes are removed on timely basis UDERITI.R A Public Service Electric & Oas Co of New Jersey 82/09/28 HAYNES.R C Region 1. Office of Director STAROBIECKI.R Division of Project & Resident Programs 5pp 15652 125. 24X Fiche 50-272,82/09/28.8210120328
- 8210210146 Forwards IC Insp Rept 50-272/82-23 on 820831 & 0701-03 No noncompliance noted MARTIGUT T Division of Engineering & Technical Programs. 82/10/03 UDERITZ: R A Public Service Electric & Gas Co of New Jersey 2pp 15746 072 24X Fiche 50-272.82/10/05.8210210146
- --8210210162 IE Insp Rept 50-272/82-23 on 820831 & 0901-03 No noncompliance noted Major areas inspected inservice testing surveillance program for pumps & valves & containment penetration leakage testing surveillance REKITO.W A . BETTEMHAUSEN.L Division of Engineering & Technical Programs 92/09/29 5pp 15746 094 24X Fiche 50-272.82/10/05, 8210210146
- 8208190233 IE Info Notice 80-35, Suppl 1, "Leaking & Dislodged 1-125 implant Seeds " Svc list enc! CDBB.t I Division of Fuel Facilities, Materials & Safeguards 82/10/06 Caneolidated Edison Co of New York 66pp. 18761 250 24X Fiche: 50-000, 82/10/06, 8208190233
- 8210210435 Forwards IE Insp Repts 50-272/82-20 & 50-311/82-20 on 820816-20 No noncompliance noted MARTIN.T I Division of Engineering & Technical Programs. 82/10/04 UDERITZ, R A Public Service Electric & Gas Co. of New Jersey. 2pp 15743.036 24% Fiche 50-272.82/10/04,8210210435
- --8210210451 JE Insp Repts 50-272/82-20 & 50-311/82-20 on 820816-20 No noncompliance noted, Major areas inspected; qualification & treining, radiological surveys, radiation exposure permits, posting, licensee audits & exposure control HOSEY.C.M. ROME, C. A. PREENMAN, E. Q. Division of Engineering & Technical Programs B 27/97/30. Spp. 15763:038, 24% Fiche: 50-272, 82/10/06, 8210210435.

- 8210210464 Forwards IE Insp. Repts 50-272/82-25 & 50-311/82-24 an 820901-27 & notice of violation BTAROSTECKI.R Division of Project & Resident Programs 82/10 A UDERITY. A public Service Electric & Oas Co of New Jersey 2, 13763 018 24X Fiche 50-272,82/10/06.8210210464
- --8210210469 Notice of violation from insp on 820901-27 * Region 1, Office of Director 82/10/06 1p 15763 020 : Fiche 50-272, 82/10/06, 8210210464
- --8210210477 IE Insp Repts 50-272/82-25 & 50-311/82-24 on 820701-2*
 Noncompliance noted trip breakers closed w/o two operable source range instruments in svc & failure to submit 30-day LER NORRHOLM, L. J., SUMMERS, R., TRIPP, I. E. Division of Project & Resident Programs 82/10/04 15pp 15763 021 24X
 Fiche 50-272,82/10/06.8210210464
- 8210270136 License Change Requests 82-17-20-21 & 22 to Licenses 64-7 & DRR-75 Changes involve inservice insploy solubbers, steam generator insployers, containment ventilation valve insployers surveillance functional testing thindense A Public Service Electric & Gas Co. of New Jersey 82/10/07 VAROA, S.A. Operating Reactors Branch 1 3pp. 15927 C. 24X Fiche 50-272,82/10/07,8210270136
- --9210270142 Proposed Tech Spec changes re inservice insplot shall installation of steam generator insplorts.pressure drop test & reactor trip instrumentation

 A Public Service Electric & Oas Collor of New Jersey 92/10/63

 8pp 15927 029 24X Fiche 50-272,82/10/07.8210270135

a

6.

62

62

6<u>a</u> :

--:

- 8208190238 IE Bulletin 82-03, "Stress Corrosion Cracking in Thick-Wall, Large-Diameter, Stainless Steel, Recirculation Sys Piping at BNR Plants " Svc list encl DEYGUNG.R C Director's Office, Office of Inspection and Enforcement 82/10/14 Consolidated Edison Co of New York 115pp 15810 125 24X Fiche 50-000.82/10/14.8208190238
- 8210280221 EN-B2-034 on 821027 notice of violation & proposed imposition of civil penalty in amount of \$40,000 issued reinadequate vital physical area barrier RDSANG, R. AXELRAD, J. Director's Office, Office of Inspection and Enforcement 82/10/22 ip 15837 089 24X Fiche 50-272.82/17 2 8210280221
- R Periodic operating reports & related correspondence
- B210200005 Forwards monthly operating rept for Sept 1982
 HIDURA, H J Public Service Electric & Gas Co of New Jersey
 B2/10/10 Director's Office of Inspection and Enforcement
 1p 19757 201 24X Fiche 50-272,82/10/10,8210200085
- --8210200090 Monthly operating rept for Sept 1982 MILLER.L K Fublic Service Electric & Cas Co. of New Jersey 62/10/10 14pp 15757 202 24X Fiche 50-272,82/10/10.821000.2
- S Reportable occurrences: LERs & related correspondence
- 8210120369 Discusses consistent failure of solenoid valves in contennment fan coil unit soc water flow control valve Licensee investigation determined that overheated valves caused sticking Valves replaced CHIRAMAL M Director's Office 80/09/12 Director's Office L 15690 190 24x Fiche 50-272,80/09/12,8210120369
- B21001000B Responds to FDIA request for 19 categories of documents in nuclear reactor events & safety problems Forwards documents listed in App A FELTON, J. M. Division of Rules and Records 82/06/20 UBELL:R & Critical Mass Energy Project 15pp 15727 005 24% Fiche 50-000, 82/06/28, 9210010000
- 8210080015 Add1 response to FOIA request for 19 categories of infamous lear reactor events & sefety problems Forwards documents 1 (sted in App A Documents in App B completely withheld (ref FOIA Exemption 5)
 FELTON.J M Division of Rules and Records 82/07/12, UDELL.FA Critical Mass Energy Project 9pp 15665 027 24X
 Fiche 50-000, 82/07/12, 8210080015
- --8210080197 NRC operations ctr usage chart re events at faciliting NRC No Detailed Affiliation Given 82/07/12. ip 15889 E 24X Fiche 50-000.82/07/12,8210080015.

- 8210G10181 Forwards LER 82-069/03L-0 Detailed event analysis encl HICUPA: H J Public Service Electric & Gas Co of New Jersey 82/09/16 HAYNES: R C Region 1. Office of Director 3pp 15367 302 24x Fiche 50-272,82/09/16:8210010181
- --8210010192 LER 82-069/03L-0 on 820831.svc water leak discovered on charging pump 12 lube oil cooler outlet piping & pump declared inoperable Caused by erosion of piping by silt-laden svc water Pipe replaced HELLER.R Public Service Electric & Gas Co of New Jersey 82/07/16 Region 1. Office of Director 1p 15567 305 24% Fiche 50-272.82/09/16.8210010181
- 8210010383 Forwards LER 82-068/03L-0 Detailed event analysis encl MIDURA.H J Public Service Ejectric & Gas Co of New Jersey 82/09/16 HAYMES.R C Region 1. Office of Director 3pp 15589 193 24% Fiche 50-272,82/09/16,8210010383
- --8210010390 LER 82-068/03L-0 on 820827,100-ft slevation containment air lock declared inoperable after excessive leakage discovered gast inner door seals Caused by closing door w/excessive force Seal replaced Installation of snubbers proposed HELLER.R Public Service Electric & Gas Co of New Jersey 82/09/16 Region 1, Office of Director 1p 15569 176 24X Fiche 50-272,82/09/16.8210010383
- B210070305 Forwards LER 82-073/03L-0 Detailed event analysis encl MIDURA:H J Public Service Electric & Gas Co of New Jersey B2/09/22 HAYNES:R C Region 1. Office of Director 3pp 15634 107 24X Fiche 50-272, 82/09/22, 8210070305
- --8210070314 LER 82-073/03L-0 on 820906, calculation showed that quadrant power tilt ratio for bottom detector N42 exceeded max allowable (smit Caused by failed milliamp detector switch in current meter assembly Assembly replaced & channel tested FRAMM.R Public Service Electric & Gas Co of New Jersey 82/09/22 Region 1. Office of Birector 1p 15634 110 24% Fiche 50-272,82/09/32,82/0070305
- 121007036B Forwards LER 82-074/04L-0 Detailed event analysis encl HIBURALH J Public Service Electric & Gas Co of New Jersey B2/09/22 HAYMES.R C Region 1. Office of Director 3pp 13634 031 24X Fiche 50-272, 82/09/22, 821007036B
- -8210070375 LER 82-074/04L-0 on 820903, indication of unplanned release through plant vent received Three individuals contaminated during attempts to locate source Caused by door hitting against drain valve 107332, causing valve to loosen & open HELLERIR Public Service Electric & Gas Co of New Jersey 82/09/22 Region 1. Office of Director 1p 15634 034 24X Fiche 50-272.82/09/22.8210070368
- 210070380 Forwards LER 82-071/04L-0 Detailed event analysis encl HIBURALH J Public Service Electric & Oas Co of New Jersey 82/09/22 HAYNES.R C Region I. Office of Director 3pp 15633 356 24X fiche 50-272,82/09/22,8210070380
- -B210070398 LER 82-071/04L-0 on 820827, control operator discovered increasing level on plant yent radioactivity monitor & assued significant event notifications for unplanned releases Caused by primary coolant leakage from RCS filter FRAIM, R. Fublic Service Electric & Gas Co of New Jersey 62/09/22 Region i. Defice of Director ip 15633 359 24X Fiche 50-272, 82/09/22, 8210070380
- 210150058 Forwards LER 92-066/03X-1 Detailed event analysis encl MIDURA, H J Public Service Electric & Oas Co of New Jersey 82/09/27 HAYMES, R C Region 1. Office of Director Spp 15698 276 24X Fiche 50-272,82/09/29,8210150058
- -8210150066 LER 82-066/034-1 on 820825,100 ft elevation containment air lock outer door discovered not properly sealed Caused by seal damage due to personnel closing door w/excessive force Seal replaced & door tested satisfactorily HELLER.R Public Service Electric & Gas Co of New Jersey 82/09/27 Region i, Office of Director Ip 15698 279 24X Fiche 50-272,82/09/27,8210150058
- P10150071 Forwards LER 82-044/03X-1 Detailed event analysis encl MIDURA.H J Public Service Electric & Oas Co of New Jersey 82/09/29 HANYES.R C Region 1. Office of Director 3pp 15701 243 24X Fiche 50-272,82/09/29,8210150071
- 8210150075 LER 82-044/03X-1 on 820623, during rautine operation, vital ventilation control ctr 1C tripped, rendering control room emergency air conditioning fan 12 inoperable, Caused by setpoint drift & breaker icléY trip Steaker replaced HELLER, R Public Service Electric & Oas Co of New Jersey 62/09/29 Region i, Office of Director ip 15701 246 24X Fiche 50-272,82/09/29.8210190071

- 8210130111 Forwards LER 81-019/03X-1 Detailed event analysis encl MIDURA.H J Public Service Electric & Qas Co of New Jersey 82/09/29 HAYNES.R C Region 1. Office of Director 3pp 15697 070 24X Fiche 50-272.82/09/29/8210130111
- -B210150121 LER 81-019/03X-1 on B10221, fire alarm annunciation on Panel 1RP5 for waste gas compressor observed but no audible alarm heard Caused by failure of amplifier to discriminate sysnaise from announcement function Amplifier adjusted HELLER, R Public Service Electric & Oas Co of New Jersey 82/09/29 Region 1. Office af Director ip 15697 073 24X Fiche 30-272,82/09/29.8210150111
- B210150127 Forwards LER B2-067/03L-0 Detailed event analysis encl MIDURA: H J Public Service Electric & Oas Co of New Jersey B2/09/29 HAYNES: R C Region 1. Office of Director 3pp, 15698 324 24% Fiche 50-272.82/09/29.8210150127
- --8210150140 LER 82-047/03L-0 on 820712.no indication of syc water flow to containment fan coal unit ii noted while coil unit ii inoperable Caused by terminal screw on syc water flow transmitter breaking off Screw replaced FRAMM.R Public Service Electric & Oas Co of New Jersey 82/07/29 Region 1. Defice of Director ip 15698 327 24% Fiche 50-272,82/09/29,8210150127
- 8210150148 Forwards LER 82-051/03X-1 Detailed event analysis encl MIDURA: H J Public Service Electric & Oas '50 of New Jersey 82/09/29 HAYNEB: R C Region 1. Office of Director Jpp 15697 288 24X Fichs 50-272:82/09/29.8210150148
- --8210190155 LER 82-051/03X-1 on 820728, following reactor trip, level in auxiliary feed storage tank dropped below Tech Spec min Caused by binding of valve 1DR6 Velve manually cycled & tank level restored to normal Valve returned to remote mode HELLER, R Public Service Electric & Oas Co of New Jersey 82/07/27 Region 1, Office of Director ip 15477 291 24X Fiche 50-272,82/09/27,8210150148
- 8210210134 Forwards LER 82-070/03L-0 Detailed event analysis encl MIDURA: H J Public Service Electric & Gas Co of New Jersey 82/10/06 HAYNES: R C Region i. Office of Director 3pp 15766 120 24X Fiche 50-272,82/10/06:8210210134
- --8210210144 LER 82-070/03L-0 on 820912 & 14, pressurfizer pressure controller shifted to manual mode w/decreasing pressure Caused by intermittent problem in pressure controller or manual-auto station Manual-auto station replaced FRAHM.R. Public Service Electric & Gas Co of New Jersey 82/10/06 Region 1, Office of Director ip. 15766 123 24X Fiche. 50-272, 82/10/06, 8210210134
- 8210290216 Forwards corrected LER 82-016/04L-O Detailed event analysis encl MIDURA, H J Public Service Electric & Qas Co of New Jersey 82/60/06 HAYNES. R C Region 1, Office of Director. 3pp 15853-250 24X Fiche 50-272,82/10/04.8210290216
- --B210290218 Corrected LER B2-014/04L-0 on B20326, during gaseous release from waste gas sus, containment/plant vent monitors iRila. IRIZA & IRIZ8 incorrectly eligned Caused by operator failure to properly perform operating instruction, FRAHMIR Public Service Electric & Gas Co of New Jersey B2/04/13 Region 1 Office of Director ip, 15853 253 24X Fiche 50-272,82/10/06.8210270216
- 8210270310 Forwards corrected LER 82-050/04L-O Detailed event analysis encl
 MIDURA: H J Public Service Electric & Oas Co of New Jersey
 82/10/06 HAYNES: R C Region 1: Office of Director Spp.
 13853-090 24X Fiche 50-272,82/10/06,8210270310.
- --8210290314 Corrected LER 82-050/04L-0 on 820710. Atlantic loggerhead turtle found impinged on circulating water sys intake trash bars Caused by inability of turtle to actively avoid approach velocities to intake due to weakened state FRAHM.R Public Bervice Electric & Gas Co. of New Jersey. 82/08/06 Region 1. Office of Director 1p. 15853.073. 24X Fiche 50-272.82/10/06.8210270310
- 8210290353 Forwards corrected LER 82-045/04L-0 Detailed event analysis encl MIDURA, H J Public Service Electric & Gas Co of New Jersey. 82/10/06. MAYNES, R C Region 1, Office of Director Spp 15853 014 24X Fiche 50-272,82/10/06,8210290353
- --8210290361 LER 82-045/04L-0 on 920710; waste monitor tank contents sample discarded before composite samples assembled Caused by technician inadvertently pouring out sample. Personnel counseled te procedures Simulated sample made. FRAHM,R. Public Service Electric & Gas Co. of New Jersey 82/07/28 Region 1: Office of Director, 1p. 15853 017, 24X Fiche 50-272,82/10/06,8210270353

- DOCKET 50-275 DIABLO CANYON NUCLEAR POHER PLANT, UNIT 1
- A Application/construction stage documents & correspondence
- 821001000B Responds to FOIA request for 19 categories of documents re nuclear reactor events & safety problems.Forwards documents listed in App A FELTON.J M Division of Rules and Records 82/06/28 UDELL.R A Critical Mass Energy Project 15pp 15727 005. 24X Fiche 50-000.82/06/28.821001000B
- --BOOBO90265 Discusses addl required info to better define potential for cracking in reactor vessel nottles ROONAN, V B Assistant Director for Materials & Qualifications Engineering BO/05/05 TEDEBCORR L Assistant Director for Licensing 2pp 15727 176 24X Fiche 50-000, 82/06/28, 8210010008
- F Security, medical, emergency & fire protection plans
- 8210010406 Forwards application for amend to License DPR-76, revising security plan control of the security plan actific Gas & Electric Go 82/09/17 DENTON, H R Diffice of Nuclear Reactor Regulation, Director ip. 15572, 207, 24x Fiche. 80-275, 82/09/17, 8210010406.
- --B210010413 Application to amend License DPR-76, revising security plan Bafeguards info deleted. HAMEATIB.O A., CRANE.P. A. Pacific Oas & Electric Co. 82/09/17 3pp 15578:208. 24X Fiche 50-275.82/09/17,8210010406.
- B210210033 Releases public version of revised emergency plan implementing procedures.
 FELTON J.M. Division of Rules and Records 82/10/01 Document Management Branch Ip. 18782:091 24X Fiche: 50-275, 82/10/01, 8210210033.
- --B210210044 Forwards public version of ravised emergency plan implementing procedures; including Procedure EP M-3 rechioring release; EP M-5 re Taunani warning & EP M-8 recontainment emergency personnel hatch.

 CRANG.P.A. Parific Oas & Electric Co. B2/09/23, ENGELKEN, R H Region 5, Office of Director. 30, 15782:092, 24X Fiche. 50-275, 82/10/01, 9210210033
- --B210210048 Public version of revised emergency plan implementing procedures, including Procedure EP H-3 re chlorine release, EP H-5 re Teunani warning & EP H-8 re containment emergency personnel hetch.

 Pacific des & Electric Co. 82/09/13, 84pp. 15782:095, 24X Fiche: 80-276, 92/10/01.8210210033.
- GBIO150389 Suppl to GRO719 application for emend to License DPR-76 re security plan.Enci withheld (ref 10CFR73,21). CRANK.P.A. Pacific Oat & Blectric Co. 98/10/12. DENTON,H.R., MIRAOLIA Offices of Nuclear Reactor Regulation, Director, Spp. 18703:879. 84X Fiche:80-875.82/10/12.8210150389.

Q. Adjudicatory correspondence

- 92:0270449 Responds to 820512 petition requesting action under 100782.206. For reasons stated in enclosed Director's Desision, petition denied.
 DENION.H.R. Office of Nuclear Reactor Regulation, Director.
 82/09/22, REYNOLDS.J. Center for Law in the Fublic Interest. Spp. 188331464. SAX Ficher0-270.82/09/22.8810290449.
- == 8810390451 Director's Decision DD-82-10 denying Ctr for Law in Public Interest 880518 petition requesting NAC leave order to util to submit amond to DL to cover OA & QC issues, DENTON, M.R. Office of Nuclear Resciot Regulation, Director, 82/09/28, 7pp, 158431(7). 84X Fiche: 50-275, 82/09/29, 8210890449.
- BRIGO40102 Order extending time until BRIGO5 for Commission to act to review ALAB-681, OHILM:8. J. Office of the Secretary of the Commission. 82/07/00. Commissioners. Ip. 16581:025. 84X Fishe: 80-875,82/07/00. 8810040102.

8210050218 Reply to applicant & NRC 820924 briefs re status of prappeals from authorization of low power operation No adequate factual basis exists to support ASLD dismissal of Joint Intervenor OA contention as moot W/Certificate of Svc 824YNDDS, J R Joint Intervenors-Diablo Canyon REYNDDS, J R Center for Law in the Public Interest 82/09/30 Atomic Safand Licensing Appeal Penel 8pp 15611 237 24X Fiche 50-275, 82/09/30, 8210050218

Ė

- 8210060220 Reply brief to other party briefs re monthess of low g contentions Emergency planning issues & certain other issues mont Certificate of Svc encl LOCKE, R F Pacific Oas & Electric Co 82/09/30 Atomic Safand Licensing Appeal Penel App 15620 190 24x Fiche 50-275, 82/09/30, 8210060220
- 8210040097 Reply to Governor Brown & Joint Intervenors 820924 fill in response to ASLB 820902 order on moothess of low power issues Emergency planning issues & some low power contentions mooted Certificate of Syc and JUNES, B W. Hearing Branch 1 82/10/01 Atomic 8afety and Licensing Appeal Panel 9pp 15581 026 24% Fiche 50-275,827 8210040097
- 8210050180 Reply brief to util & NRC 820924 briefs re moothess of power issues, per AGLB 820902 order Issues not moot Controversy still exists & issue is of practical significance Certificate of Byc encl BROWN, H H California. Btate of BROWN, H H Kirkpatrick, Loc Hill, Christophar & Phillips 82/10/01 Atomic Gafety and Licensing Appeal Panel Spp 15603 245 24X Fiche 50-275, 82, 8210050180
- 8210060186 Request for leave to withdraw certain exceptions to AS B20831 initial decision ASLB 820927 clarification of & local jurisdiction acquiescence to preconditions res SOPs render exceptions unnecessary Certificate of Soc encl HAGGELL, D.F. Hearing Branch 1 62/10/04 Atomic Safety and Licensing Appeal Panel 5pp 19613 199 24% Fiche 50-275, 82, 8210060186
- 8210070145 Order extending time until 821008 for Commission to at review ALAB-681 (HILK, B. J. Office of the Secretary of the Commission 82/10/Commissioners. ip 15627 076 24X Fiche 50-279,82/10/05,
- 8210130272 Forwards Ban Luis Obispo County Board of Supervisors f action approving Ban Luis Obispo County nuclear power plant emergency response plan & State of CA Benate Bill 1473 amending govt code. Certificate of Svc encl CRANE.P.A Pacific Oas & Electric Co. BZ/10/06 BUCK.J H. JDKNBON.W.R. MODRET B Atomic Befety and Licensing Appeal Pi App. 15678.284, 24% Fiche 50-275.82/10/06.8210130272
- 8210120332 Order CLI-82-30 directing all nath security classifies be expunged from ALD-653 & underlying record info not essential to ABLAB opinion & expunction would not prejudice any party or public CHILK B. J. Office of the Secretary of the Commission 82/10/2 2pp. 18652:108. 24X Fiche 50-275,82/10/08,8210120332
- 8210130327 Order extending time until 821026 for Commission to at review ALAD-681.
 CMILK, 8.J. Office of the Secretary of the Commission. 82/10/1 Commissioners. 1p. 15678:282. 24X Fiche: 50-275.82/10/08.8210130327.
- 8210210422 Order extending time until 821105 for Commission to a review NRR Director 820922 denial of Joint Intervenors 10CRR2 204 request. CHILK, 8. J. Office of the Secretary of the Commission 82/10/: Commissioners. ip. 15763 CGD 24X Fiche: 50-275.82/10/18. 8210210422.
- 8210280245 Memorandum in response to util 820924 motion for clarification of ABLB 820831 initial decision. Decision supports conclusion of law on adequacy of offsite emergency planning. WOLF, J.F. Atomic Bafety and Licensing Board Panel 82/10/26 15837:036, 24X Fichs. 50-275, 82/10/26, 8210280245.

H. General correspondence

9210920363 Advises that 921010 ltr requesting util recalculate at safety systat plants will be sent to all parties OILINEMY, V. Commissioners. 82/10/20. BOHULKE, B. Affiliation Unknown. 1p. 15779; 201, 24% Fiche: 50-275, 82/10/20, 821022036;

- --82(0220369 Urgss util be forced to recalculate entire seismic safety sys at plant SCHULKE.S Affiliation Unknown 82/10/10 OILINGKY,V Commissioners 1p 15779 202 24X Fiche 50-275,82/10/20,82/0200743
- P Operating license stage documents & correspondence
- E210080350 Informs that procedure including proposed "Statement re Potential of Apparent Conflicts of Interest," meets requirements for independence Requests procedure be included in program mgt plans for Phase I & Phase II DENIGN.H R Office of Nuclear Reactor Regulation, Director 82/09/08 CODER.W E Teledyne Engineering Services ip 15663 316 24X Fiche 50-275,82/09/08,8210080350
- 8210010406 Forwards application for amend to License DPR-76.revising security plan
 CRANE, P A Pacific Gas & Electric Co 82/09/17 DENTON, H R
 Office of Nuclear Reactor Regulation, Director 1p 15572 207 24%
 Fiche 50-275, 82/09/17, 8210010406
- --B210010413 Application to amend License DPR-76, revising security plan Safeguards info deleted MANEATIS.4 A. CRANE.P A. Pacific Gas & Electric Co. 82/09/17 Jpp 15572 208 24X Fiche 50-275, 82/09/17, 8210010406
- 8210040429 Informs of decision to partially refund fees remitted w/ BOOS21 application to extend latest CP completion dates MILLER.W O License Fee Management Branch B2/09/21 FUNDUSH.M H Pacific Cas & Electric Co ip 15997 262 24X Fiche 50-275,82/09/21,8210040429
- \$210130056 Responds to \$20727 request for status rept on design verification program & briefing on proposed Phase II of program Info discussing background & current status encl DIRCKS,W J Office of the Executive Director for Operations 82/09/24 PALLADINO.W J, GLINSKY,V, AHEARNE, JF Commissioners 28pp 15692 284 24X Fiche 50-275.82/09/24.8210130056
- 8210010149 Provides guidance to assure independence of Teledyne Engineering Svcs while recognizing need for Communication between Teledyne & util DENION.H R Office of Nuclear Reactor Regulation, Director 02/09/29 COOPER.H E Teledyne Engineering Services Spp 15567 244 24X Fichs 50-275.82/09/29.8210010149
- 6210080191 Forwards Revision 2 to Procedure DCNPP-IDVP-PP-005,
 "Potential or Apparent Conflicts of Interest of
 Individuals " Words "engineering mgt" inadvertently omitted
 in Section 2 0 during retuping of Revision 1
 COOPER-W E Teledyne Engineering Services 62/09/29 DENTON, H R
 Office of Nuclear Reactor Regulation, Director ENGELKEN, R H
 Region 5, Office of Director MANEATIS, O A Pacific Oss & Electric
 Co 1p 15640 182 24X Fiche 50-275, 82/09/29, 8210080191
- --8210080193 Revision 2 to DCNPP-IDVP-PP-005, "Potential or Apparent Conflicts of Interest of Individuals"

 COCPER.W E Teledupe Engineering Services 82/09/29 Spp

 LSA40 183 24X Fiche 50-275,82/09/29,8210080191
- 8210050122 Forwards info addressing Sections 2 1.2 2.2 3 & 2 4 of Generic Ltr 81-07 re NUREO-0612. "Control of Heavy Loads"
 Section 2 (updates B10924 submittal Submittal addressing remaining required analyses expected by end of Feb 1983
 CRANELP A Pacific Gas & Electric Co 82/09/30 MIRAGLIA-F J
 Licensing Branch 3 176pp 15605 212 24X Fiche 50-275,82/09/30,8210050122
- 8210050144 Responds to Generic Ltr 82-12 re plant staff working hours
 Util administrative procedures address revised working
 hours
 CRANE,P A Pacific Gas & Electric Co 82/10/01 MIRAQLIA,F J
 Licensing Branch 3 1p 15605 161 24X Fiche 50-275,82/10/01,
 0210050144
- B210120278 forwards "Design Verification-Phase I." final rept & "Blume Internal Review (BIR) Independent Internal Reviews of Work Done by LR8/Blumw Engineers on Diablo Canyon Nuclear Power Plant "
 CRNNE.P A Pacific Oas & Electric Co 82/10/01 EIBENMUT.D.O Division of Licensing 2pp 19653 243 24X Fiche 50-275.82/10/01,8210120278
- ---9210120283 "Design Verification Phase 1.Final Rept "

 * Pacific Gas & Electric Co T1002745 R03 82/10/01 233pp
 15653 245 24x Fiche 50-275,82/10/01.8210120278

- --8210120285 "Blume Internal Review Independent Internal Review of Work Done by URS/Blume Engineers on Diablo Canyon Nuclear Power Plant: "final rept + URB Carp URS/JAB 8216 82/09/30 80pp 15654 117 24X Fiche 50-275, 82/10/01. 8210120278
- 8210080272 Notifies that program procedure for communication from & to independent design verification program will be revised to conform w/guidelines provided in 820929 ftr CGOPER.W E Teledyne Energy Systems 82/10/02 DENTON.H R Office of Nuclear Reactor Regulation, Director 2pp 15638 124 24X Fichs 50-275,82/10/02,8210080272
- 8210080078 Forwards interim technical rept "Independent Design Varification Program Verification Program for PG&E Corrective Action," Revision O DENISON.E Robert L Cloud Associates, Inc 82/10/05 DENTON,H R Office of Nuclear Reactor Regulation, Director ENGELKEN,R H Region 5, Office of Director MANEATIB, 0 E Pacific Gas & Electric Co 1p 15440 277 24X Fiche 50-275,82/10/05,8210080078
- --8210080080 "Independent Design Verification Program Verification Program for PO&E Corrective Action," Revision 0 DENISON,E Robert L Cloud Associates, Inc. P 105-4-839-008 ROD 82/10/05 61pp 15640 278 24% Fiche 50-275,82/10/05.8210080078
- 8210250167 Forwards "Diablo Canyon Nuclear Power Plant Independent Design Verification Program Program Plan. Revision 1, Adjunct Program for Evaluation of Const QA."

 COUPER. W. E. Teledyne Engineering Services 82/10/05 DENTON, H. R. Office of Nuclear Reactor Regulation. Director ENGELKEN, R. H. Region 5, Office of Director MANEATIS, O. A. Pacific Gas & Electric Co. 2pp. 15787 120 24% Fiche 30-275, 82/10/05, 8210250167
- --8210250171 "Diablo Canyon Nuclear Power Plant Independent Design Verification Program Program Plan, Revision 1. Adjunct Program for Evaluation of Const GA " * Teledyne Engineering Services 82/10/01 12pp 15787 122 24X Ficbs 50-279.82/10/05.8210250167
- 8210250168 Forwards RH Engalken 820915 memo re RF Reedy, Inc exit meeting concerning GA audits for consideration in evaluation of GA program EISENHUT, D 0 Division of Licensing 62/10/06 COOPER, W E Teledyne Engineering Services. 2pp 15808 009 24X Fiche 50~275, 82/10/06, 8210250168
- --B210250372 Summary of 820910 meeting w/util & RF Reedy, Inc re GA audit of in-house design ENOELKEN,R H Region 5, Office of Director 82/09/15 DENTON.H R Office of Nuclear Reactor Regulation, Director 5pp 15808-011 24X Fiche 50-275, 82/10/06, 8210250168
- B210250240 Forwards independent design verification program comments on Phase I final rept Rept should contain detailed descriptions of scope, criteria, methodology & models for all structures, sys & components
 COOPER, WE Teledyne Engineering Services B2/10/07 DENTON, H R
 Office of Nuclear Reactor Regulation, Director ENGELKEN, R H
 Region 5, Office of Director MANEATIB, Q A. Pacific Oas & Electric
 Co 16pp 15789 150 24% Fiche 50-279, 82/10/07, 8210250240
- 8210080123 Notifies of 821007 meeting w/util in Ban Francisco, CA to discuss status of Phases I & Il instrument test rig for verification of corrective action & NRC 820819 ltr re fuel load.

 ** Teledyne Energy Systems 82/10/08 Teledyne Energy Systems ip 15440 129 24X Fiche 50-275,82/10/08,8210080129
- 8210270446 Staff requirements mamo re 821007 affirmation/discussion & vote on extension of const completion dates for WPPBB, purging of classified mattl in ALAB-533 & amergency preparedness & risks associated w/fuel loading, CHILK,B J Office of the Secretary of the Commission. 82/10/08 Office of the Secretary of the Commission. 82/10/08 Fiche: 50-000, 82/10/08,8210270446
- B210190470 Provides info re ownership of Bechtel Power Corp FRIENO:H B Bechtel Corp BZ/10/11 MRAGLIAF J Licensing Branch 3 ip 15740 181 24X Fiche 50-275.82/10/11.8210190470.
- 8210270351 Advises that Bechtel Power Corp is entity responsible for work on project Ownership held by officers of Bechtel Group, Inc FRIEND, H. B. Pacific Gas & Electric Co FRIEND, H. B. Bechtel Corp 82/10/11 MIRRQLIAF. J. Licensing Brench 3 ip 15834-358. 24X Piche 50-275, 82/10/11, 8210270351
- B210150389 Supp) to 820719 application for amend to License DPR-76 re security plan Encl withheld (ref 10CFR73 21) CRANE.P.A Pacífic Ose & Electric Co 82/10/12 DENTON.H R , MIRAOLIA Office of Nuclear Reactor Regulation, Director, 2pp. 15703 279 24X Fiche 50-275,82/10/12,8210150389

- 8210230291 Clarifies 821007 statement of required systatuctures & components for plant operating modes for independent design verification program COOPER.W E Teledung Engineering Services 82/10/12 EISENHUT.D Q Division of Licensing App 15790 191 24X Fiche 50-275.82/10/12, 8210250291
- B210290097 Requests explanation of process & chronology of events in which Teledyne discussed const @A review of plant w/util. Bechtel & S&W info required to determine presence of conflict of interest Heeting requested BROWN, H H Kirkpatrack, Lockhart, Hill, Christopher & Phillips BROWN, H H California, State of B2/10/12 COOPER, W E Teledyne Engineering Services 2pp 15853 361 24X Fiche 50-275,82/10/12, 291029097
- 8210290214 Provides NRC recommendation re Phase II of independent design verfication program Phase II program plan & requirement that Phase II review/evaluations be completed prior to fuel load/low power decision approved DIRCKS.W J. Office of the Executive Director for Operations SECV-82-414 82/10/13 61pp 15876 261 24X Fiche 50-275.82/10/13.6210290214
- 8210190583 Advises that two former Bechtel employees will be retained on independent design verification program Individuals do not violate procedure on conflict of interest & will not verify work participated in as Bechtel employee COOPER, H E. Teledyne Engineering Services 82/10/14 DENTON, H R Befice of Nuclear Reactor Regulation. Director ENGELEEN, R H Region 5, Office of Director MNRATIS, OA Pacific Oas & Electric Co. 3pp 15791 184 24% Fichs 50-275,82/10/14,8210190583
- 8210190584 Provides preliminary response to 820701 request for review of seven points re validity of BNL results & generic implications in final rept concerning enalysis of facility COOPER.W E Teledyne Engineering Services 82/10/15 DENTON.H R Office of Nuclear Reactor Regulation, Director 3pp 15791 187 24X Fiche 50-275.82/10/15.8210190584
- 9210220371 Forwards add1 sections for Phase I final rept re design varification program per commitment made in 820820 ltr. Revision 4 to outline Phase 1 final rept & revision to sections previously submitted CRANE.P previously submitted CRANE.P A Parific Oas & Electric Co 82/10/15 EISENHUT.D G Division of Licensing 10ipp 15779 238 24% Fiche, 50-275, 82/10/15, 82/10.20371
- 9210250210 Identifies concerns resulting from review of URB/Blumo containment annulus structure model systuation Concerns resulted in issuance of EOI Files 3006 & 3007 MRAY.R Teledune Engineering Services 92/10/19 MANEATIS, Q A Pacífic Gas & Electric Ga App 15789 292, 24X Ficher 50-275, 82/10/15, 8210230210
- 9210250318 Comments on Region 5 820915 memo re Phase II of independent design verification program.per 821006 request Change in Phase II not indicated COPPER. H E Teledyne Engineering Services 82/10/15 EISENHUT. D Q Division of Licensing 3pp 15790 048 24X Fiche 50~275,82/10/15,8210250318.
- 8210280272 Notifies of planned 821101 meeting w/plant personnel to discuss audit logistic planning for activities performed since 820820 REEDY.R F. R F Reedy, Inc. 82/10/15 CODPER,W E Teledyne Engineering Services 3pp (5837-292 24X Fiche 50-275,82/10/15,

- O Inspection reports, IE Bulletins & correspondence
- 8210070007 Responds to FDIA request for eight categories of records; steam generators & steam turbines App A documents provided in R Udell FOIA Request 81-313 Forwards documents listed in App B FELTON, J M Division of Rules and Records 82/08/10 (PM D J Winthrop, Stimson, Putnam & Roberts 9pp 15645 063 24K Fiche 50-000, 82/08/10, 8210070007
- --B2\$Q070139 Forwards tabulated data on steam generator line & railities Data should be provided to licensees.

 IPPOLITO.T Operating Reactors Assessment Branch 82/04/01
 VAROA.S Operating Reactors Branch 1 5pp 19645 131 24E
 Fiche 50-000,82/08/10.8210070007
- 8210040133 Forwards IE Insp Repts 50-275/82-26 & 50-323/82-13 am 820726-30,0816-20 & 0830-0901 No noncompliance nated 815M0P. T W Division of Resident, Reactor Project & Engineering Programs 82/09/17 CRAME.P A Pacific Cas & Electric Co 591 15614 307. 24X Fiche 50-275.82/09/17.8210060133
- --8210060141 IE Insp Repts 50-275/8R-26 & 50-323/8R-13 on Naj26-2 0816-20 & 0830-0901 No noncompliance noted Major area; inspected site tour & mod to piping & electrical rateway supports resulting from revised annulus selimic spectra BURDOIN.JF. ZWETZIG.9 B Division of Resident, Seator Projri, Engineering Programs BZ/09/17 9pp 15614 311 24X Fichs 50-275,82/09/17.8210060133
- 8208190233 IE Info Notice 80-35, Suppl 1, "Leaking & Dislodged 1-13 Implant Seeds " Svc list encl COBB, L I Division of Fuel Facilities, Materials & Galequarde 82/10/06 Consolidated Edison Co of New York 66pp 19161 2V 24X Fachs 50-000,82/10/06,8208190233
- 8208190238 IE Builetin 82-03, "Stress Corrosion Cracking in Thick-Hall: Large-Diameter: Stainless Steel. Recirculation flys Piping at BMR Plants "Sve list enc! DEYGUNO: R C Director's Defice, Defice of Inspection and Enforcement 82/10/14 Consolidated Edison Co of New York 115pp 15810 125 24X Fiche 30-000: 82/10/14.82081902.80
- 8210280287 Forwards IE Insp Rept 50-275/82-29 on 820827-1002 1.3
 noncompliance noted
 BISHOP, T W Division of Resident, Reactor Project & Ingineers 2
 Programs 82/10/14 CRANE, P A Pacific Qas & Electric Co 4,1
 13829 010 24X Fiche 50-275,82/10/14.8210280287
- --8210280303 lE Insp Rept 50-275/82-29 on 820829-1002 No norceapile moted Major areas inspected plant operations, surveillence testing physical security, maint & TMI task action plan toms GARLSON, J B . MENDONCA, M M . KIRSCH, D F Division of Residers Reactor Project & Engineering Programs 82/10/13 3pp 15939 014 24% Fiche 50-275, 82/10/14, 8210280287
- 8210280324 Forwards IE Insp Repts 50-275/82-30 & 50 (2.1/Ud-)4 em 820914-16 No moncompliance noted BISHDP, T W Division of Resident, Reactor Project & Ingintering Programs 82/10/14 CRANE.P A Pacific Oas & Electric Co 73, 15839, 019 24X Fichs 50-275, 82/10/14, 8210280324
- --8210280330 IE Insp Repts 50-275/82-30 & 80-323/82-14 on flatel tisk; noncompliance noted Major areas inspected implementation of independence qualifications of personnel & implementation of A progress MORRILL.P.J. ECKHARDT.JH, 815KIOP.TH, Division of Haildert Reactor Project & Engineering Programs 82/10/08 åpp 18839.021. 24% Fiche 50-278, 82/10/14.8210280324
- ? Periodic operating reports & related correspondence
- 3210270319 Forwards "Diablo Canyon Nuclear Power Plant Indipendent Design Verification Program," semimonthly rept for Sept 1982 COOPER, H. E. Teledyne Engineering Services 82/09/24 @EKTC==1 Office of Nuclear Reactor Regulation, Director. ENGELER, R H. Region 5. Office of Director MANCATIB, OA Pacific Gal & Elect. Co. 1p. 15854, 119 24X Fishe 50-275, 82/09/24, 8210270319
- --8210270322 "Diablo Canyon Nuclear Power Plant Independent Daright Verification Program." semimonthly rept for Sept 1902 * Teledyne Engineering Services. 82/09/24 69pp 15034 12) . 28% Ficher 50-276.82/09/24.8210290319.
- 3210130151 Forwards "Bemimonthly Rept 23, Diablo Cenyon Verification Program," 820921-1004 CRANE,P A Pacific Gas & Electric Co 82/10/08 DENTON, M & Office of Nuclear Reactor Regulation, Director ENGELKEN, R H Region 5, Office of Director 1p. 15697 294, 24X Fiche: 50-275, 82/10/08,8210150151

- --8210150159 "Semimonthly Rept 23. Diablo Canyon Verification Program," 820921-1004 HIGH.J 8 Pacific Gas & Electric Co 82/10/08 51pp 15497 295 24X Fiche 50-275.82/10/08.8210150151
- 8210230197 Forwards "Independent Design Verification Program," semimonthly rept for Oct 1982 COOPER, H C Teledyne Engineering Services 82/10/08 DENTON, H R Office of Nuclear Reactor Regulation, Director ENSELKEN, R H Region 5, Office of Director MANEATIS, O A Pacific Oas & Electric Co 3pp 15789 264 24X Fiche 50-275.82/10/08,8210250197
- --8210250201 "Independent Design Verification Program," semimonthly rept for Oct 1982 * Teledyne Engineering Services 82/10/08 29pp 15789 267 24x Fiche 50-275.82/10/08,8210250197
- 8210250221 Advises that RL Cloud Associates, Inc has not issued open ten repts during prior reporting period

 DENISON.E Robert L Cloud Associates, Inc. 82/10/08 DENTON.H R

 Office of Nuclear Reactor Regulation, Director ENGELKEN.R H

 Region D. Office of Director MANEATIS, O A Pacific Oas & Electric

 Co. 1p. 15788 348 24% Fiche 50-275,82/10/08,8210250221
- 8210250247 Submits Semimonthly Progress Rept 20 for 820902-1008 No open item repts issued, but two open item repts identified individuals completed acceptable statements re potential or apparent conflicts of interest
 REEDY, R.F. R.F. Reedy, Inc. 82/10/08 DENTON, H.R. Office of
 Nuclear Reactor Regulation, Director ENGELKEN, R.H. Region 5,
 Office of Director MANEATIS, O.A. Pacific Gas & Electric Co.
 15788
- 8210250308 Forwards Oct 1982 semimonthly rept.consisting of Open Item PORSUSUBLE FORWARDS DET 1982 semimonthly rept, consisting of Open Item Repts 8007-8020

 EESTAK.F Stone & Hebster Engineering Corp. 82/10/08 DENTON, H R Office of Nuclear Reactor Regulation. Director ENGELKEN, R H Region 5. Office of Director MANCATIS.O A Pacific Oas & Electric Co 36pp 15790 097 24X Fiche 50-275,82/10/08,8210250308
- 8210280157 Forwards program managers 3rd Friday Oct 1982 rept re independent design verification program REEDY,R F R F Reedy, Inc. 82/10/15 COOPER.W E Teledyne Engineering Services Opp. 15807-215 24% Fiche 50-275.82/10/15, 8210280157
- 0210270236 Forwards "Diablo Canyon Verification Program," Semimonthly Rept 24 for 021005-18 per Commission Order CLT-01-30 CTANE.P A Pacífic Gas & Electric Co 02/10/22 DENTON.H.R Office of Nuclear Reactor Regulation, Director ENGELKEN,R H Region 5, Office of Director ip 15020 222 24X Ficho 50-275-02/10/22.0210270236
- --8210270240 "Diable Canyon Verification Program," Semimonthly Rept 24 for 821005-18 Pacific Gas & Electric Co 82/10/22 52pp 15828 223 24X
 Fiche 50-275,82/10/22,82/0270236
- 8210280211 Forwards "Diablo Canyon Nuclear Power Plant Independent Design Verification Program," semimonthly status rept for Oct 1982 CDDPEA.W E Teledyne Engineering Services 82/10/22 DENTON, H. R. Office of Nuclear Reactor Regulation, Director ENGELKEN,R H Region 5. Office of Director MANEATIB,O A Pacific Oas & Electric Co 2pp 15838 001 24% Fiche 50-275,82/10/22,8210280211
- ---8210280212 "Diablo Canyon Nuclear Power Plant Independent Design Verification Program," semimonthly status rept for Oct 1982 4 Teledyne Engineering Bervices 6: 24X Fiche 50-275,82/10/22,8210280211 82/10/22 76pp 15839.003
- S Reportable occurrences: LERs & related correspondence
- 8210250055 PNO-V-82-043 on 821016 unusual event declared when grass fire started in 500 kV switchyard On 821017. khree 500 kV circuits tripped resulting in lose of all offsite power Second unusual event declared STERNBERG.D M Region 5. Office of Director 92/10/16 ip 15787 100 24X Fiche 50-275,82/10/16.8210250055
- 8210290219 Forwards LER 82-009/01T-0 EHIFFER, J D Pacific Qas & Electric Co 82/10/18. ENGELKEN, R H Region 5. Office of Director is 15853 224. 24X Fiche 50-275, 82/10/18, 8210290219

- --8210290222 LER 82-009/017-0 on 821007, testing on auxiliary saltwater equarrouses LEM MS-DOFFORM -0 on MS21007, testing on auxiliary saltwater sys revealed sys susceptible to water hammer effects during anticipated operational transients Caused by water column separation b recombination at piping slope change KAEFER, M B Pacific Qas & Electric Co 82/10/19 Region 5, Office of Director 2pp 15853 227 24X Fiche 30-275,82/10/18, 221020219 Office of Director 8210290219
- T Hearing transcripts on mon-antitrust matters
- 8210290370 Unofficial transcript of 821020 public discussion of Phase II reverification program in Mashington.DC Pp 1-113
 Supporting documentation encl.
 Commissioners 82/10/20 144pp 15865-095 24X Fiche 50-275, 82/10/20, 8210290370
- 8210220416 Forwards transcript of Commission 821020 meeting to eluzzoels forwards transcript of Commission Baldad meeting to receive NRC briefing on proposed scape of Phase II of independent design verification program & 821017 meeting w/ util & participants re program & ECCY-B2-414 M/a entl CHILK.8 J Office of the Secretary of the Commission 82/10/21 Office of the Executive Legal Director 1p 15779 211 24X Fichs 30-275.82/10/21.8210220416
- DOCKET 50-277 PEACH BOTTOM ATOMIC POWER STATION, UNIT 2 J Insurance & indamnity information
- 8210060276 Forwards Endorsement 99 to NELIA Policy NF-140 & Endorsement 53 to MAELU Palicy MF-67 53 to MAELU Policy NF-67 BRADLEY.E J Philadelphia Electric Co 82/09/30. SALTZMAN, J Assistant Director for State & Licensee Relations 3pp. 15619 206 24% Fiche 50-277, 82/09/30, 8210060296
- P Operating license stage documents & correspondence
- 8210280013 Responds to FOIA request for all internal, non-public documents memos, evaluation repts to other matt dealing w/ nuclear plant operations Forwards documents listed in App A FELTON.JM Division of Rules and Records 82/09/17 MCINNIS, D News to Observer 5pp 15860 O65 24X Fichs 80-000,82/09/17. 8210280013
- --- B208310034 Forwards draft info notice re deficiencies in air filtration 208310034 Forwards draft info notice redeficiencies in air filtratic & ventifation sys. Notice based on radioactive resin release at Pilgrim 1 & on four related events at other plants involving deficiencies in maint & testing of filter sys. MATTSON: R J Division of Systems Integration (post 81005). 82/09/05 UDRDAN, E. L. Division of Engineering & Quality Assurance Spp 15861-024 24X Fiche. 50-000, 82/09/17,8210280013
- 8210050320 Forwards "Thermal Happing Rept 82-3 for 820818 for Thermal Monitoring Requirements:" per App 8 to ETS WILLERY:N B Philadelphia Electric Co 82/09/28 IPPOLITG, T. A Operating Reactors Branch 3 1p 13401:338 24X Fiche 50-277, 82/09/28, 8210050320
- --8210050321 "Thermal Mapping Rept 82-3 for 820818 for Thermal Monitoring * Philadelphia Electric Co 82/09/28 4pp 15601 359 24X Fichs 50-277,82/09/28,8210050320
- 82:10150282 Forwards "Rept of Plant Startup Following Fifth Refueling Outage." Feb 1982 ALDEN-H M. Philadelphia Electric Co 82/10/06. HAYNES.R C Regi 1. Office of Director ip. 15705:266 24X Fiche 50-277,82/10/06.
- --8210150292 "Rept of Plant Startup Following Fifth Refueling Outage," 820219
 - 02V417 ULRICH, H T Philadelphia Electric Co. 82/02/28 7pp. 15705 267. 24X Fiche: 50-277,82/10/04,8210150282.
- 8210260327 Submits info re potential problem w/ventilation systems associated w/battery & smergency suitchpear rooms, solution to problem & schedule for completion of necessary mode Mode will be completed by 821231 COONEY, M. J. Philadelphia Electric Co. 82/10/14 HAYNES, R. Region I. Office of Director Spp. 15803, 205 24X Fiche: 50-277, 82/10/14, 8210260327 HAYNES, R C.
- 8210200046 Forwards application to amend Licenses DPR-44 & DPR-56 to reflect mods required to meet criteria of NUREO-0661, App A. "Mark I Containment Long-Term Program." BRADLEY, E J Philadelphia Electric Co. 82/10/19 DENTON, H. R. Office of Nuclear Reactor Regulation, Director. 1p. 15756; 135. 24X Fiche: 50-277, 82/10/15, 8210200046

11.1

3 1

1

۱,

1

- --8210200063 Application to amend Licenses DPR-44 & DPR-56 to reflect mods required to meet criteria of NURCO-0661, App A. "Mark I Containment Long-Term Program " Afficavit & Certificate of Sve encl BAUER. E 0 , BRABLEY, E J Philadelphia Electric Co 82/10/15 7on 15756 136 24X Fishe 50-277.82/10/15.8210200046
- --8210200068 Proposed Tech Spec pages, reflecting mods required to meet criteria of NUREO-0661. App A, "Mark I Containment Long-Term Program"

 4 Philadelphia Electric Co 82/10/15 App 15756 143 24X
 Fiche 50-277.82/10/15.8210200046
- 8210210297 Submits add1 info re util 811229 response to NUREO-0803. "Safety Concerns Associated W/Pips Breaks in BWR Scram Sys." in response to NRC 820824 request DALTROFF.S L. Philadelphia Electric Co. 82/10/15 STOLZ.J F Operating Reactors Branch 4 10pp 15764 267 24X Fiche 80-277.82/10/15.8210210297
- 8210210330 Proposes 830131 as date for responding to NUREQ-0737, Etem II B 3. "Post-Accident Sempling Sys " DALTROFF, S L Philadelphia Electric Co 82/10/15 STOLZ, J F Operating Reactors Branch 4 2pp 13765 063 24X Fiche 50-277, 82/10/15, 8210210330
- 8210280196 Forwards response to draft technical evaluation rept recontrol of heavy loads Addl info requested in 820405 telcon oncl
 DALTROFF, 8 L Philadelphia Electric Co 82/10/25 STOLZ, J F Operating Reactors Branch 4 45pp 15839, 136 24X Fiche 50-277, 82/10/25, 8210280196
- --B210280198 "Structural Analysis of Peach Bottom Units 2 & 3 Reactor Pressure Vessel Head Brog. Shroud Head Assembly Brop & Steam Dryer Assembly Brop Conditions "HERRERA,M L. MOK.9 Deneral Electric Co 82-32 82/08/31 38pp 15839 181 24X Ficha 50-277.82/10/25.8210280196
- --B210280201 "Lifting Devices & Lifting Points Stress Analysis for Reactor Pressure Vessel Head Strongback, Stoam Dryer/
 Separator Siing & Svc Platform to Comply W/NURE0-0612 for Peach Bottom Units 2 & 3 "
 KONG-Y H Ceneral Electric Co NSE-50-0582 82/05/31 3ipp 15839 219 24X Fiche 50-277, 82/10/25,8210280196
- --B210280204 "Lifting Devices & Lifting Points Stress Analysis for Fuel Paol Oate Lifting Points. Hydraulic Tensioner Lifting Device & Lifting Points & Reactor Pressure Vessel Insulation Removal Lifting Device & Insulation Lifting Points "SZUMBKI,T J Philadelphia Electric Co NSEQ-72-0782 B2/07/31 27pp 15839 250 24X Fiche 50-277.82/10/25.8210280176
- O Inspection reports: IE Bulletins & correspondence
- 8210070317 Forwards IE Insp Repts 50-277/82-20 & 50-278/82-19 on 820816-20 & notice of violation MARTIN.T T Division of Engineering & Technical Programs 82/09/22 DALTROFF, 8 L. Philadelphia Electric Co 2pp 15634.135 24% Fiche 50-277.82/09/22.8210070317
- --8210070322 Notice of violation from insp on 820816-20.

 + Division of Engineering & Technical Programs 82/09/14 ip 15634 137 24X Fiche, 50-277, 82/09/22, 8210070317
- --8210070330 IE Insp Repts 50-277/82-20 & 50-278/82-19 on 820816-20 Mancapliance noted no notification given for alpormal degradation in primary containment, evidenced by unaccaptable local leak rate test results for nine isolation valves PULLANI, 8 V , BETIENHAUSEN, L Division of Engineering & Technical Programs 82/09/14 7pp 15634 138 24X Fiche, 50-277, 82/09/22, 8210070317.
- 8210150299 Forwards IE Insp Repts 50-277/82-19 k 50-278/82-18 on 820807-0915 No noncompliance noted 8TAROSTECKI,R Division of Project & Resident Programs, 82/09/27, DALTROFF,S L. Philadelphia Electric Co 2pp 15707 234 24X Fiche-50-277,82/09/27,8210150299
- --8210150302 IE Insp Repts 50-277/82-19 & 50-278/82-18 on 620807-0915. No noncompliance noted Major areas inspected operational safety-radiation protection, physical security-control room activities & IE bulletin followup.

 BLOUGH.A R., MCCANE.E C Division of Project & Resident Programs.

 B2/09/20 19pp. 15707 236 24% Fiche 50-277.82/09/27.8210150299.
- 8210070177 Forwards inservice insp rept completed during 820220-0702 refueling outage, Insp requirements met satisfactorilg. COUNEY. H. J. Philadelphia Electric Co. 82/09/29 HAYNEB, R. C. Region 1. Defice of Director. 1p. 15635 298. 24X Fiche. 50-277, 82/09/29, 8210070177.

- 8210150069 Submits final response to IE Bulletin Bi-Oj. "Surveille" of Mechanical Snubbers "Pacific Scientific Co manufactures 48 mechanical snubbers utilized at facility List of model numbers encl
 DALTROFF, S. L. Philadelphia Electric Co 82/10/04 HAYWES, R.C. Region 1. Defice of Director 2pp 15701 241 24X Fiche 50~277, 82/10/04.8210150069
- 820B190233 IE Info Notice 80-35, Suppl 1, "Leaking & Dislodged 1-121 Implant Seeds " Svc list encl COBD.L I Division of Fuel Facilities, Materials & Gafeguards 82/10/06 Consolidated Edison Co of New York 66pp 15761 25 24x Fiche 50-000,82/10/06,8208190233
- 8210130291 Ack receipt of 820929 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-277/82-14 & 50-278/82-14 BTAROSTECKI.R Division of Project & Resident Programs 02/10/66 DALTROFF, S.L. Philadelphia Elactric Co. ip 15678 347 24X Fiche 50-277, 82/10/06.8210130291
- --8210130276 Responds to NRC B20901 itr re-violations noted in [E 1rm Repts 50-277/82-14 & 50-278/82-14 Corrective actions defective locking machanism replaced & personnel instructed to be more forceful when checking locked doors DALTROFF.S L Philadelphia Electric Co 82/09/29 BTARM916(4) 4 Division of Project & Resident Programs 2pp (5678) 348 241 Fiche 50-277, 82/10/06, 8210130291
- 8208190238 IE Bulletin 82-03, "Stress Corrosion Cracking in Thick-Wall-Lerge-Diameter: Steinless Steel. Recirculation Sys Piping at BWR Plants "Svc list encl DEYOUNG: R C Director's Office, Office of Inspection and Enforcement 82/10/14 Consolidated Edison Co of New York 115pp 15810 123 24X Fiche 50-000, 82/10/14, 8200190238
- R Pariodic operating reports & related correspondence
- 8210150356 Forwards Thermal Mapping Rept 82-4 for 820907 for thereal monitoring requirements, per App 8 to ETB WILLSEY, W B Philadelphia Electric Co 82/10/08 JPPCUIIO, F A Operating Reactors Snanch 3 p 15704 277 24X Fiche 50-277, 82/10/08, 8210150354
- --B21015036B Thermal Happing Rept 82-4 for 820909 * Philadelphia Electric Co 82/10/08 4pp 15704 27H R41 Fiche 30-277,82/10/08.8210150356
- 8210220170 Forwards monthly operating repts for Bept 1982 COONEY, H J Philadelphia Electric Co 82/10/15 Director's Office. Office of Inspection and Enforcement 1p 15777 273 24s Fiche 50-277, 82/10/15,8210220190
- --8210220194 Monthly operating repts for Sept 1982 ALDEM.W M Philadelphia Electric Co 82/10/15 10pp 15/// 2/4 24X Fiche 50-277.82/10/15.8210220190
- 8 Reportable occurrences, LERs & related correspondence
- 8210060074 Forwards LER 82-027/017-0 Detailed event analysis enci COONEV.M J Philadelphia Electric Co 82/09/24 HAYNES.R C Region i. Office of Director 3pp 15615 047 24X Fiche. 50-277. 82/09/24.8210060074
- ---BR100600B3 LER B2-027/01T-0.on B20910.svc air valve to containent found open Caused by personnel failure to make entry in locked valve log book when valves opened Valve closed & locked CCCNEY,M,J Philadelphia Electric Co. 82/09/24 Region I: Effice of Director ip, 15615-050 24X Fiche, 80-277.82/09/24 B210060074
- 8210060353 LER 82-025/03L-0 on 820827, while performing surveiblance test: C RNR pump room C cooling fan would not start in automatic Caused by corroded contacts on C fan switch DPS 0400-16 Switch rewired & calibr COONEY, M J Philadelphia Electric CO 82/09/24 MAYNES, R C Region 1. Office of Director in p 15615 174. 24X Fiche 30-277, 82/09/24, 8210060353.

- 8210060047 LER 82-028/03L-0 on 820908.LIS-2-3-73B.reactor Lo-Lo-Lo containment spray interlock discovered out of calibr Caused by setpoint drift of Rosemont Model 1151 trip unit Device recalibr COONEY.M J Philadelphia Electric Co 82/09/27 HAYNES,R C Region i. Office of Director ip 15615 088 24X Fiche 30-277.82/09/27.8210060047
- 821CO60177 LER 82-0R6/03L-0 on 820831.RHR pump 2A failed to start during test on FR=2-10-143 Caused by uncharged breaker closing spring due to faulty closing latch monitoring switch in charging motor circuitry Switch replaced COCNEY.M J Philadelphia Electric Co 82/09/30 Region 1, OPPice oF Director 1p 15615 099 24X Fiche 50-277.82/09/30.8210060177
- 6210150400 LER 82-031/03L-0 on 820831.smoke detector 814 in emergency switchgear room B failed to calibr to Tech Spec limits Caused by faulty smoke detector Detector replaced COUNEY. S. J. Philadelphia Electric Co. 82/09/30 HAYNES, R. C. Region I. Office of Director ip 15704 028 24X Fithe 50-277.82/09/30,8210150400
- 6210150154 Forwards LER 82-030/01T-0 Detailed event analysis submitted COONEY.H J Philadelphia Electric Co 82/10/01 HAYNES,R C Region L Office of Director 3pp 15707 311 24X Fiche 50-277, 82/10/01.8210150154
- --8210150179 LER 82-030/017-0 on 820717. w/both units at power, small quantity of slightly contaminated water released from reconbiner bldg into stoim drain sys Caused by spurious action of Grinnell Model B fire suppression valve CCDNEY. N J Philadelphia Electric Co 82/10/01 Region 1, Office of Director ip 15707 314 24X Fiche 50-277,82/10/01, 6210150154
- 6210260112 LER 62-029/03L-0 on 620915, during power, supervisory alarm occurred indicating fire sys problems Investigation revealed heat detectors in startup switchgear bldg inoperable Caused by disconnected circuit breaker due to stripped screw COUNEY-M J Philadelphia Electric Co 82/10/14 HAYNES, R C Region 1. Office of Director in 15805 247 24X Fiche 50-277.82/10/14.8210260112
- 8210270366 PNO-I-82-068 on 821024.primary sys relief valve began cycling during startup after maint shutdown.causing sys swell which resulted in feed pump trip on high reactor water level followed by low lovel scram HPCI manually initiated MCCABE.E C , KEIMIO Region 1. Office of Director 82/10/25 ip 15853 034 24K Fiche 50-277.82/10/25.8210290366
- DOCKET 50-278 PEACH BOTTOM ATOMIC POWER STATION, UNIT 3
- J Insurance & indemnity information
- 0210060296 Forwards Endonsement 99 to NELIA Policy NF-140 & Endonsement S3 to MAELU Policy MF-67
 BRADLEY,E J. Philadelphia Electric Co. 82/09/30 SALTZMAN, J. Assistant Director for State & Licensee Relations 3pp 15619 206
- P Operating license stage documents & correspondence
- B207090201 Forwards application to amend License DPR~56, changing Tech Specs to reflect changes to ODYN computer code & including Revision 1 to "Supplamental Reload Licensing Submittal for Peach Bottom Unit 3, Reload 4"

 BRADLEY.E J Philadelphia Electric Co 82/07/06, DENTON, H R Dffice of Nuclear Reactor Regulation, Director 1p 13788, 113, 24x Fiche 50-278, 82/07/06,8207090201
- --8207090208 Application for amend to License DPR-56, changing Tech Space to reflect changes in analyses resulting from corrections to ODYN computer code
 DALTROFF, 8 Philadelphia Electric Co 82/07/06 6pp 13788.115, 24X Fiche 50-278,82/07/06,8207090201
- --9207090215 Tech Bpec Tables 3 5 K 2 & 3 5 K 3 & Figures 3 5 K 1 & 3 5 K 2. supporting application for amend to License DPR-56 * Philadelphia Electric Co. 82/07/06 App 13788 120 24X Fiche 50-278.82/07/06.8207090201
- --8207090224 Revision 1 to "Supplemental Reload Licensing Submittal for Peach Bottom Atomic Power Station Unit 3, Reload 4 " LEASER, J D . ENGEL, R E General Electric Co y1003J01A20 R01. 92/06/30 41pp 13788-124 24X Fiche 50-278, 82/07/06, 8207090201.
- 8210050320 Forwards "Thermal Mapping Rept 82-3 for 820818 for Thermal Monitoring Requirements," per App 8 to ET8
 WILLSEY,W B Philadelphia Electric Co 82/09/28 IPPOLITO, T. A Operating Reactors Branch 3 ip, 15401,358 24X
 Fiche 50-277,82/09/28,8210050320

- --8210050321 "Thermal Mapping Rept 82-3 for 820818 for Thermal Monitoring Requirements" * Philadelphia Electric Co 82/09/28 4pp 15501 359 24X Fiche 50-277, 82/09/28, 8210080320
- 6210240329 Submits info re potential problem w/ventilation sys associated w/battery & emergency switchgear rooms, solution to problem & schedule for completion of necessary mode Mode will be completed by 821231 CODNEY.M J Philadelphia Electric Co 82/10/14 HAYNES,R C Region 1, Office of Director 3pp 15803 205 24X Fiche 50-277, 82/10/14, 8210240329
- 8210200046 Forwards application to amend Licenses DPR-44 & DPR-56 to reflect mode required to meet criteria of NUREO-0661, App A. "Mark I Containment Long-Term Fragram" BRADLEY, E.J. Philadelphia Electric Co. 82/10/15 DENTON, H.R. Office of Nuclear Reactor Regulation, Director ip 15756 135 24X Fichs 50~277, 82/10/15, 8210200046
- --8210200063 Application to amend Licenses DPR-44 & DPR-56 to reflect mods required to meet criteria of NUREQ-0661.App A. "Hark I Containment Long-Term Program " Affidavit & Certificate of Svc encl BAUER.E 0 . BRADLEY.E J Philadelphia Electric Co B2/10/15 7pp 19756.136 24% Fiche 50-277,82/10/15.8210200046
- --B21020006B Proposed Tech Spec pages, reflecting mods required to mest criteria of NUREO-0661. App A. "Mark I Containment Long-Term Program"

 * Philadelphia Electric Co 82/10/15 App 15756 143 24X Fichs 50-277, 82/10/15, 8210200046
- 8210210297 Submits add) info re util 811229 response to NUREO-OBO3, "Safety Concerns Associated M/Pipe Breaks in BWR Scram Sys." in response to NRC 920824 request DALTROFF, B L. Philadelphia Electric Co. 82/10/15 8TOLZ, J, F. Operating Reactors Brench 4 10pp 15764 267 24X Fiche 50-277, 82/10/15, 8210210297
- 8210210330 Proposes 830131 as date for responding to NUREQ-0737. Item II B 3. "Post-Accident Sempling Sys "
 DALTROFF, 8 L Philadelphia Electric Co 82/10/15 STOLZ, J F Operating Reactors Branch 4 2pp 15765 063 24% Fiche 50-277, 82/10/15, 8210210330
- 8210220004 Forwards application to amend License DPR-56, requesting Tech Spec change to extend insp interval applicable to two inaccessible hydraulic snubbers RRADLEY, E.J. Philadelphia Electric Co. 62/10/19 DENTON, H.R. Office of Nuclear Reactor Regulation, Director ip 15778 219 24x Fiche 50-278, 82/10/19, 8210220006
- --8210220007 Application to amend License DFR-56, changing Tech Specs to extend insp interval applicable to two inaccessible hydraulic snubbers Certificate of Bvc anci BAUER, E G . BRADLEY, E J . Philadelphia Electric Co B2/10/19 6pp 15778 220 24X Ficha 50-278, 82/10/19, 8210220006
- 9210280196 Forwards response to draft technical evaluation rept re control of heavy loads Addl info requested in 820405 telcon encl DALTROFF, 8 L Philadelphia Electric Co 82/10/23 STOLZ, J F Operating Reactors Branch 4 45pp. 15839 136 24X Fiche 50-277, 82/10/25, 8210280196
- --B210280198 "Btructural Analysis of Peach Bottom Units 2 & 3 Reactor Pressure Vessel Head Drop. Shroud Head Assembly Drop & Steam Dryer Assembly Drop Conditions " HERRERAIM L. MOK.0 General Electric Co. B2-32 82/08/31 38pp 15839, 181 24X Fiche: 50-277,82/10/25,8210280196.
- --B210280201 "Lifting Devices & Lifting Points Stress Analysis for Reactor Pressure Vessel Head Strongback Steam Dryer/Separator Sling & Svr. Platform to Comply W/NUREQ-0612 for Peach Bottom Units 2 & 3 " KDNQ.Y.H. Oeneral Electric Co NSE-50-0882 82/05/31, 3ipp 15839 219 24X Fiche 50-277, 82/10/25, 8210280196
- --8210280204 "Lifting Devices & Lifting Points Stress Analysis for Fuel Pool Gate Lifting Points, Hydraulic Tensioner Lifting Device & Lifting Points & Reactor Pressure Vessel Insulation Removal Lifting Device & Insulation Lifting Points "
 SZUMSKI,T J. Philadelphia Electric Co., NBEO-72-0782, 82/07/31
 29pp 15839, 250 24X Fiche: 50-277, 82/10/25, 8210280196.

Q Inspection reports. IE Bulletins & correspondence

- 8210070317 Forwards IE Insp Repts 50-277/82-20 & 50-278/82-19 on 820816-20 & notice of violation MARTIN.T T Division of Engineering & Technical Programs 82/09/22 DALTROFF.S L Philadelphia Electric Co 2pp 15634 135 24X Fiche 50-277, 82/09/22, 8210070317
- --B210070330 IE Insp Repts 50-277/B2-20 & 50-278/B2-19 on 620816-20 Noncompliance noted no notification given for abnormal degradation in primary containment, evidenced by unacceptable local leak rate test results for nine isolation valves PULLANI.S V , BETTENHAUSEN.L Division of Engineering & Technical Programs. 82/09/14 7pp. 15634.138 24X Fichs 50-277,82/09/22,8210070317
- 8210070294 Forwards JE Insp Rept 50-278/81-28 on 811013-15
 HARTIN,T T Division of Engineering & Technical Programs 82/09/24
 DALTROFF,S L Philadelphia Electric Co 2pp 15634-218 24X
 Fiche 50-278,82/09/24,8210070296
- --8210070308 IE Insp Rept 50-278/81-28 on 811013-15 Noncompliance noted failure to follow radiation protection procedure & promptly notify NRC in accordance w/10CFRS0 72 NIMITZ,R L , GREENMAN,E O. Division of Engineering & Technical Programs. 82/07/26 18pp 15634 220 24% Fiche 50-278,82/09/24,8210070276
- 8210150299 Forwards IE Insp Repts 50-277/82-19 % 50-278/82-18 on 820807-0915 No noncompliance noted STAROBTECKI.R. Division of Project & Resident Programs 82/09/27. DALTROFF.8 L. Philadelphia Electric Co 2pp 19707 234 24X Fiche: 50-277.82/09/27.8210150299
- --8210150302 IE Insp Repts 50-277/82-19 & 50-278/82-18 on 820807-0915 No noncompliance noted Hayor areas inspected operational safety radiation protection, physical security, control room activities & IE builetin followup BLOUGH, A.R., HCCANE, E.C. Division of Project & Resident Programs 82/09/20 19pp 15707 236 24X Fiche 50-277, 82/09/27, 82/0150299
- 8208190233 IE Info Notice 80-35, Suppl (, "Leaking & Dislodged I-125 Implant Seeds," Svc list and. COSB-L I Division of Evel Facilities, Materials & Safeguards 82/10/04 Consolidated Edison Co of New York 66pp 15761 250 24X Fiche-50-000/82/10/06.8208190233
- 8210(30291 Act receipt of 820929 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-277/82-14 & 50-276/82-14.

 STAROSTECKI:R Division of Project & Resident Programs 82/10/06, DALTROFF:S L Philadelphia Electric Co. 1p. 15678 347 24X Fiche: 50-277, 82/10/06, 82(010029)
- --8210130296 Responds to NRC 820901 ltr re violations noted in IE Insp. Rapts 50-277/82-14 & 50-278/82-14 Corrective actions defective locking mechanism replaced & personnel instructed to be more forceful when checking locked dones, DALTROFFS L. Philadelphia Electric Co. 82/09/29, STAROSTECKI, R. Bivision of Project & Resident Programs, 2pp. 13678-348-24X Fiche 50-277, 82/10/06,8210130291.
- 8208190238 IE Bulletin 82-03, "Stress Corrosion Crecking in Thick-Wall-Large-Diameter, Stainless Steel-Recirculation SysPiping at BMR Flants " Syc list encl.

 DEYOUNG, R. C Director's Office, Office of Inspection and Enforcement. 82/10/14 Consolidated Edison Co. of New York 115pp 15810-125 24X Fiche. 50-000, 82/10/14, 8208190238
- 8210220006 Forwards application to amend License DPR-85, requesting Tech Spec change to extend insp interval applicable to two inaccessible hydraulic anobars. BRADLEY.E.J. Philadelphia Electric Co 82/t0/19 DENJON.H R. Office of Nuclear Reactor Resulation Director ip. 15778:219. 24x Fichs. 50-278, 92/10/19, 9210220006.
- ---8210220007 Application to amend License DPR-56, changing Tech Space to extend insp interval applicable to two inaccessible hydraulic snubbars. Certificate of Byc encl. BAUER: E. 0 . BRADLEY: E. J Philadelphia Ellectric Co. 62/10/19. 6pp. 15778: 220. 24X Fiche. 50-278, 82/10/19, 8210220006.
- R Periodic operating reports & related correspondence
- 8210150356 Forwards Thermal Happing Rept 82-4 for 820707 for thermal monitoring requirements, per App 8 to EYB HILLSEY.W S. Philadelphia Elactric Co 82/10/08. IPPOLITO, T A Operating Reactors Sranch 3. ip 13704:277. 24% Fiche. 50-277, 82/10/08, 8210150356.

- --8210150368 Thermal Mapping Rept 82-4 for 820909 Philadelphia Electric Co 82/10/08 4pp 15704 27g 24 Fiche 50-277.82/10/08/8210150356
- 8210220190 Forwards monthly operating rapts for Bapt 1902 CDONEY:M J Philadalphia Electric Co 82/10/15 Director's Office. Office of Inspection and Enforcement 1p 15777 273 P Fichs 50-277, 82/10/15, 8210220190
- --8210220194 Monthly operating repts for Sept 1982 ALDEN W M Philadelphia Electric Co 82/10/13 10pp 13777 24X Ficha 50-277,82/10/15,8210220190
- 8 Reportable occurrences, LERs & related correspondence
- E210070474 Discusses B10225 menual scram of reactor after ined." RHR relay logic A signal initiated simultaneous cloture of both recirculation pump discharge valves All battery ground tracing should be done w/ohmeter w/o fues. ASHE, F Director's Office B1/04/17 Director's Office B1/04/17 B210070474
- 821001000B Responds to FOIA request for 19 categories of doller. In nuclear reactor events & safety problems Forwards documents listed in App A FELTON. J M Division of Rules and Records 62/06/28 UDELL \$4 Critical Mass Energy Project 15pp 15727 003 241 Fiche 30-000.82/06/28.821001000B
- --B210050023 Discusses 810225 simultaneous closure of rectarvial discharge valves Event occurred while station personnel were attempting to remove ground associated w/A div of 123-veit dc subsystem
 ASHE.F Director's Office B1/04/17 Director's Office 2 15727 039 24X Fiche 50-000, 82/06/28.8210010008
- 8210060017 LER 82-015/03L-0. on 820822.drywell pressure retorfer his failed downscale Caused by blown fuse Fuse replaced begin operation verified COUNEY.H J. Philadelphia Electric Co. 82/09/21 HAYNES & C. Region 1, Office of Director ip 15615-087 24X Fiche. 30-278.82/09/21.8210060017
- DOCKET 50-280 BURRY POWER STATION, UNIT I
- F Security, medical, emergency & fire protection plans
- B210010156 Ack receipt of B20820 responses re emergency preparely deficiency items per 820406 confirmation of action it. Corrective action & plans will be examined during subsequent insps
 LEMIS.R.C. Division of Project & Resident Programs 82/24/13
 LEASBURG.R H Virginia Electric & Power Co 1p 18563 275 & Fiche 50-280, 82/09/10, 8210010156
- 8210010125 Forwards revised security training & qualification property plans withheld,
 LEABBURDOR H Virginia Electric & Power Co 82/09/17 % TO Diffice of Nuclear Reactor Regulation, Director, VARGA. S A Diperating Reactors Branch i p 15566'010 24X Fiche 50-000.82/09/17.8210010125
- 8210030076 Submits correction to 820628 Revision 3 to respect to NUREO-0737, from I.D. 2. "Safety Parameter Display Sys" Correction should be included in schedular exceptions pertaining to smergency response capabilities LEASBURG, R.H. Virginia Electric & Power Go. 82/09/29 DOTA DEFICE of Nuclear Reactor Regulation Director. EBEGAT.D B Division of Licensing ip. 15603:185 24X Fichs 50-000 \$3 > 82/0050076.
- 8210210030 Releases public version of changes to emerganty planimplementing procedure FELTON.J M Division of Rules and Records. 82/09/29 State Management Branch 1p. 15774:109. 24X Fichs.50-280.87/09/29 8210210030.

- --B210210053 Forwards public version of Change 1 to Emergency Plan Implementing Procedure EPIP-4 11, "Followup Offsite Release Assessment," Change 2 to emergency plan re NUREG-0654 cross-ref & Change 3 modifying Table 5 1

 DEWANDEL, E. P. Virginia Electric & Power Co. B2/09/17 NRC Detailed Affiliation Given 1p. 15774 110 24X

 Fiche 50-280, 82/09/29, 8210210050 NRC - No
- --8210210055 Public version of Change I to Emergency Plan Implementing Procedure EPIP-4 11. "Followup Offiite Release Assessment" Virginia Electric & Power Co 82/09/17 2pp 15774 111 24X Fiche SD-280,82/09/29,8210210050
- --8210210058 Public version of Changes 2 & 3 to emergency plan re NUREC-0654 cross-ref & Table 5 1, "Min Shift Manning Requirements," respectively Virginia Electric & Power Co 82/09/17 10pp 15774 113 24X Fiche 50-280,82/09/29.8210210050
- Operating license stage documents & correspondence
- 3210280013 Responds to FOIA request for all internal, non-public documents, mamos, evaluation repts & other mat1 dealing w/ nuclear plant operations Forwards documents listed in App A, FELTON, JM Division of Rules and Records 82/09/17 NCINNIS, D News & Observer Spp 15860 045 24% Fiche 50-000, 82/09/17. 8210280013
- --8208310034 Forwards draft info notice re deficiencies in air filtration & ventilation sys Notice based on radioactive resin release at Pilgrim i & on four related events at other plants involving deficiencies in maint & testing of filter sys MATTSON:R J Division of Bystems Integration (post 811005) 82/080/05 JORDAN:E L Division of Engineering & Quality Assurance 5pp 15861 024 24X Fiche 50-000,82/09/17,8210280013
- 1210120265 Informs of implementation status of NUREO-0737, Item II B 2, 'Plant Shielding" per NRC 820517 request All required work completed
- LEASBURG.R H Virginia Electric & Power Co 82/10/01 PENTON, H R Office of Nuclear Reactor Regulation, Director EISENHUT, D Q Division of Licensing 2pp 15451 230 24% Fiche 50-000,82/10/01. 8210120245
- 1210120297 Forwards errata to Topical Rept VEF-FRD-33, "VEPCO Reactor Core Thermal-Hydraulic Analysis Using COBRA IIIc/MIT Computer Code "
- LEASBURD, R H Virginia Electric & Power Co 82/10/04 DENTON, H R Office of Nuclear Reactor Regulation, Director EISENHUT, D O Division of Licensing 2pp 15652 330 24X Fiche 50-000,82/10/04,8210120297
- -0210120305 Errata to "VEPCO Reactor Core Thermal Hydraulic Analysis Using COBRA-IIIs/MIT Computer Code "

 Virginia Electric & Power Co VEP-FRD-33 ERR 82/10/04 1p
 15652 332 24X Fiche 50-000,82/10/04.8210120277
- 2:0120110 Forwards payment of requisite technical review fees for intervice imap & testing program
 LEASBUROR H Virginia Electric & Power Co 82/10/05 DENTON, H R
 Office of Nuclear Reactor Regulation, Director VARGA, 8, A
 Operating Reactors Branch I ip 15651 250 24X
 Fiche 50-280, 82/10/05,8210120110
- 210120258 Forwards payment of requisite technical review fees for relief requests from requirements of ABPE Section XI LEASBURGS H Virginia Electric & Pawer Co 82/10/05 DENTON, H R Office of Nuclear Reactor Regulation, Director VARGA, S A Operating Reactors Branch i 1p 15652 210 24X Fiche 50-280, 82/10/05, 82/10/20258
- 210200043 Application for amend to Licenses DPR-32 & DPR-37 consisting
- ELUZUOUSE APPLICATION for amend to Licenses DPR-32 & DPR-37 of proposed changes to Tech Specs modifying reporting & notification requirements
 LEASBURGER H Virginia Electric & Power Co 82/10/06 DE Office of Nuclear Reactor Regulation, Director VARGA, 8 A Operating Reactors Branch 1, 3pp 15757-225 24X
 Fiche 50-280, 82/10/06, 8210200043
- -8210200048 Proposed changes to Tech Specs modifying reporting & notification requirements * Virginia Electric & Power Co 82/10/06 2pp 15757 228 24X Fiche 50-280, 82/10/06, 8210200043
- 210270298 Ack receipt of 820915 application requesting relief from certain post-repair test requirements of ABME code Class III fee requested since review involves consideration of single THE FEQUENCY SINCE FOR MANAGEMENT BRANCH 82/10/15
 D1005.R H License Fee Management Branch 82/10/15
 Virginia Electric & Power Co 1p 15836-329 24X
 Fiche 50-280, 82/10/15, 8210270298 82/10/15 LEASEURG, R H.

- 8210220170 Forwards corrected drawing re 1 1/2-inch drain valve f-MS-74 Valve incorrectly labeled f-MS-208 in 820915 ltr LEASBURG.R H Virginia Electric & Power Co. 82/10/18 DENTON.H R Office of Nuclear Reactor Regulation. Director VARGA, S A Operating Reactors Branch 1. 2pp 19778 043 24X Fiche 50-280, 82/10/18,8210220170
- 8210220178 Comments on evaluation of significant dynamic loads in determining capacity of slings used per NUREG-0512 Rating can be safely expressed in terms of max static load LEASBURG.R H Virginia Electric & Power Co 82/10/18 DENTON, H R Office of Nuclear Reactor Regulation, Director EISENHUT, D Q. Division of Licensing 2pp 15777 293. 24X Fiche 50-000, 82/10/18, 6210720172 B210220178
- 8210280266 Informs that containment purge valve qualification program for 36-inch containment purge valves completed To ensure prevention of radioactive release, new automatic isolation valve will be installed LEASBURG, R H Virginia Electric & Power Co 82/10/25 DENTON, H R Office of Nuclear Reactor Regulation, Director VARGA, 8 A Operating Reactors Branch i 2pp 15837 316 24X Fichs 50-280, 82/10/25, 8210280266
- 8210280130 Informs that review of new fuel container lifting rig completed Rig does not comply w/Paragraph 3 2 1 1 of ANBI N14 6-1978 Proposed design mod for conformance being reviewed & wit1 be implemented by 840322 LEASBURG, R H Virginia Electric & Power Co 82/10/28 DENTON, H R Office of Nuclear Reactor Regulation. Director EISENHUT, D Q Division of Licensing ip 15837 163 24X Fiche 80-280,82/10/28,8210280130 DENTON, H R
- O Inspection reports, IE Bulletins & correspondence
- 8210080015 Add1 response to FDIA request for 19 categories of info re nuclear reactor events & safety problems Forwards documents listed in App A Documents in App B completely withheld (ref FDIA Exemption 8) FELTON.J M Division of Rules and Records 82/07/12 Critical Mass Energy Project 9pp 15665 027 24X Fiche 50-000, 82/07/12, 8210080015.
- --8210080154 Systematic assessment of licensee performance notes re facility evaluation for May 1979-Apr 1980 * NRC No Detailed Affiliation Given 80/04/30 6pp. 15668-051 24X Fiche: 50-000, 82/07/12,8210080015
- 8208260424 Ack receipt of util 820609 ltr & payment of civil penalty Based on review of incidents no basis for remission or nitigation of penalty identified LIEBERMAN, J Enforcement Staff 82/07/29 LEASBURG, R H Virgini Electric & Power Co Spp 15574 313 24X Fiche 50-280, 82/07/29, 8208260424
- --8206160306 Responds to NRC 820510 ltr re violations noted in IE Inap Rept 50-280/82-58 Corrective actions prestartup checklist will be performed by instrument supervisor & all employees counseled re procedural compliance
 LEABURGOR H Virginia Electric & Power Co 82/06/09
 DEYOUNO.R.C Director's Office. Office of Inspection and
 Enforcement App 15574 316 24% Fichs 50-280.82/07/29.
- --821001023B Forwards IE Insp Repts 50-280/82-04 & 50-281/82-04 on 820125-0224. Enforcement action sent separately on 820510 O'REILLY.O.P Region 2. Office of Director. 82/03/13 LEABBURG.R. H. Virginia Electric & Power Co. 2pp 15574, 320, Fiche 50-280, 82/07/29, 8208260424. 15574,320. 24X
- --8210010245 IE Insp Repts 50-280/82-04 & 50-281/82-04 on 820125-0226 Noncompliance noted failure to maintain operability of steam flow instrumentation & to follow GA manual & procedures for documenting inoperable steam flow instrumentation.

 BURKE, D. J. DAVIB, M. J. DANCE, H. C. Division of Project & Resident Programs. 82/04/08. Ppp. 15574.322 24X Fiche 50-280,82/07/27,8208260424.
- 8210070007 Responds to FDIA request for eight categories of records re steam generators & steam turbines. App A documents provided in R_Udell FDIA Request 81-313 Forwards documents lieted in App B FELTON, J M FELTON.J M Division of Rules and Records. B2/08/10. Winthrop. Btimson. Putnam & Roberts 9pp. 15645.063 Fichs.50-000, 82/08/10, 8210070007. 82/08/10. LONG, D J
- --8210070139 Forwards tabulated data on steam generator insp & maint at facilities Data should be provided to licensess IPPOLITO, T. Operating Reactors Assessment Branch. 82/04/01. VAROA.8 Operating Reactors Branch 1 5pp. 15645 131 24X Fiche: 50-000, 82/08/10, 8210070007.

- --8210070172 Forwards info re steam generator integrity & insps at all operating PHRs.per 750320 & 21 requests Details of insps. including defect indications, tube plugging criteria & tubes plugged will not be provided except for Point Beach 1 GOLLER.K R Division of Reactor Licensing (NRR-1975 only) 75/03/24 MACCARY.R R Division of Technical Review (NRR-1975 only) 5pp 15645 196 24X Fiche 50-000.62/08/10,8210070007
- 8210010156 Ack receipt of 820820 responses re emergency preparedness deficiency items per 820406 confirmation of action ltr Corrective action & plans will be examined during subsequent insps LEMIS,R C Division of Project & Resident Programs 82/09/10 LEASBURO,R H Virginia Electric & Power Co 1p 15565 325 24X Fiche 50-260,82/09/10.8210010156
- B210130427 Forwards "Inservice Insp Program, Interval 2,821222-921222"
 Relief requested from ASME Code, Section XI testing & Insp
 requirements
 LEASBURG, R H Virginia Electric & Fower Co 82/09/21 DENTON, H R
 Office of Nuclear Reactor Regulation, Director EISENHUY, D 0
 Division of Licensing 1p 15679 152 24X Fiche 50-280,82/09/21,
 2210120027
- ~-9210130431 "Inservice this Program Interval 2,621222-921222"
 4 Virginia Electric & Power Co 62/09/21 432pp 15679 153
 24X Fich#: 50~280,82/09/21,8210130427
- 8210220331 Forwards IE Insp Repts 50-280/82-25 & 50-281/82-25 on B20830-0903 No noncompliance noted DANCE, H C Division of Project & Revident Programs 82/10/04 LEABBURD, R H Virginia Electric & Power Co 2pp 15776 275. 24X Fiche 50-280, 82/10/04 8210220331
- ~-8210220356 IE Insp Repts 50-280/82-25 t 50-281/82-25 on 820830-0903 No noncompliance noted Major areas inspected followup on previous enforcement matters to unresolved items & followup on unplanned release of gaseous radioactivity HOSEY.C M. BARR.K P. Division of Engineering & Technical Programs 82/09/30 10pp 15776 277 24X Fiche: 50-280, 82/10/04, 8210220331.
- 8210120110 Forwards payment of requisite technical review fees for inservice insp & testing program LEASBURG, R H Virginia Electric & Power Co 82/10/05 DENTON: H R Office of Nuclear Reactor Regulation. Director VARGA: S A Operating Reactors Branch 1 to 15651 250 24X Fiche 50-200,82/10/05.8210120110
- 8208190233 IE Info Notice 80-35. Suppl 1: "Leaking & Dislodged 1-125 Implant Seeds " Svc list encl.

 CD88.L.I Division of Fuel Facilities: Materials & Safeguards 82/10/06 Consolidated Edison Co of New York 64pp. 15761 250 24X Fiche 50-000.82/10/06.8208190233
- 8208190238 IE Builetin 82-03, "Stress Corrosion Cracking in Thick-Wall, Large-Diameter, Stainless Steel, Recirculation Sys Piping at BMR Plants " See list encl DEYOUNG, R C Director's Office, Office of Inspection and Enforcement. 82/10/14 Consolidated Edison Co of New York, 1158p. 15810 125. 24X Ficha 30-000, 82/10/14,8288190238
- S. Reportable occurrences. LERs & related correspondence
- 8210150095 LER 81-022/03L-0 on 810703, low flow alarm observed for process vent sys Caused by process blower motors out of syc due to valve i-CM-21 leaking through to vent piping during attempt to drain mixed bed damineralizer IA for resin fill HILBON, J. L. Virginia Electric & Power Co. 81/07/31 Region 2, ector 2pp 15701 192 24% Fiche 50-280, 81/07/31.

- 8210150139 LER 81-029/03L-0 on B10808, while at 1007 power, individual rod position indicator for rod F 12 indicated erratically & 12 steps less than bank demand position Caused by poor electrical connection between coil & signal module HILBON, J L Virginia Electric & Power Co 81/08/28 Region | Philadelphia, Office of the Director (81/03/01) 2pp 15508 303 24X Fichs 50-280.81/08/28.8210150139
- 8210270212 Forwards LERs 81-069/03L.81-079/03L-0 & 81-072/03L-0 WILSON.J L Virginia Electric & Power Co B1/12/07 D'REILLY, J
 Regian 2, Atlanta, Office of the Director (81/03/01) 1p
 15827 042 24X Fichs 50-280.81/12/07.8210270212
- --B210270215 LER Bi-069/03L-0 on Billi5, discovered loss of flow the BM-GM-101 & 102 process vent monitors Caused by radiation monitor sample pump circuit breaker tripping Cause not determined Breaker reset & pump started WILBON, J. L. Virginia Electric & Power Co. B1/12/07 Region Atlanta, Dffice of the Director (Bi/03/01) 3pp. 15827 043 Fiche 50-280, B/1/2/07, B210270212
- --8210270220 LER 81-072/03L-O on 811108, motor operated va)ve 28692 to open when operated from control room during testing Cause undetermined Valve opened normally when tested later WILSON, J L. Virginia Electric & Power Co. 81/12/07 Region Atlanta, 0ffice of the Director (81/03/01) 2pp 15827 046 Fiche 50-280,81/12/07.8210270212
- --8210270224 LER 8i-073/03L-0 on BiliOB, isolation valve to recircul, spray RX A failed to close Cause undetermined Valve operated normally later Limit switch & torque settings eramined & found satisfactory
 WILBON, J L Virginia Electric & Power Co 8i/12/07 Regination to the Company of the Company of the Company of the State of the Director (8i/03/01) 2pp 19027 048, Fiche 30-280, Bi/12/07, 8210270212
- 8210050103 Forwards LER 82-086/03L-0 NILEON, J L Virginia Electric & Power Co 82/07/24 O'REILLY. Region 2, Office of Director 1p 15603 292 24X Fiche 50-280, 82/09/24,8210050103
- --8210050109 LER 82-084/03L-0 on 820827, radiation monitor RM-LU-II indicated 9 084 CPM w/o annunciation of alarm Caused by defective push button & setpoint drift Push button replaced & monitor recalibr HILSON, J. L. Virginia Electric & Power Co. 82/09/24 Regis Office of Director 2pp. 18603-293 24X Fiche 50-280, 82/09, 82/09, 82/00580103
- B210050073 Forwards LER 82~083/09L-0 & updated LER 82-084/01X-1 HILBON, J L. Virginia Electric & Power Co. 82/09/27 (1/RFILL). Region 2, Office of Director ip. 15603 175 24x Fiche 50~280,82/09/27,8210050071
- --8210050074 LER 82-083/03L-0 on B20831, performance of PT-27E This that amp reading for heat tracing panel 9, circuit 20, was below acceptance criteria Caused by excessive heat Heat tracing replaced & tested WILSON, J L Virginia Electric & Power Co B2/09/27 Region Office of Director 2pp 15603 176 24X Fiche 50-280, 82/09/8210050071
- --8210050078 Updated LER 82-084/01X-1 on 820808, venting of A charge pump resulted in max instantaneous release rate being exceeded Caused by failure to change radiation monitor setpoint alarms to reflect new vent sus flow rates WILBON-J L. Virginia Electric & Power Co. 82/09/27 Rejit Office of Director 3pp 15603 178 24X Fichs 50-200,92/09-8210050071
- 821003008) Forwards LERs 82-093/03L-0.82-054/03L-0 & 82-092/03L-0 WILBON, J L Virginia Electric & Power Co 82/09/27 O'REILLY. Region 2. Diffice of Director 1p 15604 244, 24X Fiche, 50-280, 82/09/27, 8210050081.
- --8210050086 LER 82-073/03L-0 on 820704, at 100% power, air bant if emergency diesel generator 1 found w/insufficient air pressure to start generator Caused by failure to reaet local low air pressure Bottles filled to 200 psi WILSON, J L Virginia Electric & Power Co 82/09/27 Regis Diffice of Director 2pp 15604 245. 24% Fiche, 30-280, 82/04. B210050081
- --8210050091 LER 82-054/03L-0 on 820905; unattended portable pus) i' to clean weterbox C suung around & flooded exc water pit containing exc water Valve MOV-8N-2028 grounded in open position Caused by operator error MOV-8N-2028 fried MILSON; J. Virginia Electric & Power Co 82/09/27 Rejif Office of Director 3pp 15604 247 24X Fiche 50-280,82/040 82:0050081

DOCKETED ITEMS

- --8210050092 LER 82-092/03L-0 on 820905.at full power, RPI F-8 observed fluctuating up to 15 steps Caused by exposure of containment side electrical genetration to excessive moisture & faulty signal Steam leak repaired MILSON, J L. Virginia Electric & Power Co. 82/09/27 Region 2, Office of Director 2pp. 15604-250, 24X Fiche 50-280, 82/09/27, 82/0050081
- 8210060361 Forwards LERs 82-087/03L-0 & 82-057/03L-0
 HILSON, J L Virginia Electric & Power Co 82/09/30 O'REILLY, J P
 Region 2, Office of Director 1p 15619 006 24X
 Fichs 50-280, 82/09/30, 8210060361
- --B210060372 LER 92-087/03L-0 on B20901 & 20, pump i-SW-P-10A experienced loss of suction power & on B20901.14 & 20, pump i-SW-P-10A experienced similar loss of suction Cause due to insufficient NPSH Svc water replaced Svc water pumps vented WILSON, J L Virginia Electric & Power Co B2/09/30 Region 2, Office of Director 3pp 15619 007 24X Fiche 50-280,82/09/30,62(0060361
- --82:0060398 LER 82-057/03L-0 on 820701.13.18 & 20.pump 2-8W-P-10A experienced loss of suction pressure & on 820913 & 14.pump 2-5W-P-10B experienced similar loss of suction Caused by insufficient NPSH Svc water reduced Svc water pump vented WILSON, J L Virginia Electric & Power Co 82/09/30 Region 2. Office of Director 3pp 15619 010 24X Fiche 50-280.82/09/30, 6210080361
- 8210130204 Forwards LERs 82-055/03L-0.82-096/03L-0 & 82-095/03L-0 WILSON, J L Virginia Electric & Power Co 82/10/04 D'REILLY, J P Region 2. Office of Director ip 15675 258 24X Fiche 50-280.82/10/04.8210130204
- --8210130208 LER 82-055/03L-0 on 820906, charging pump auxiliary oil pump A tripped loading to tripping of replacement pump/motor Auxiliary pump failure caused by open winding in motor Replacement tripping caused by undersized thermal overloads WILSON, J. L. Virginia Electric & Power Co. 82/10/04 Region 2, Office of Director. 2pp. 15675-259. 24X Fiche 50-280,82/10/04,821030204
- --B210130213 LER 82-096/03L-0 on 820916. w/unit at 99% power, PT-27C revealed that amp readings for heat tracing Panel 9.cfrcuit 19. was below acceptance criteria Caused by excessive heat Defective heat tracing replaced & tested WILSDM. J L. Virginia Electric & Power Co. 82/10/04 Region 2, Office of Director 2pp 15675 261 24% Fithe 50-280.82/10/04, 8210130204
- --8210130216 LER 82-095/03L-0 an 820911.w/unit at full power steam generator C level indication LI-1-495 drifted high Caused by body-bonnet leak on transmitter ref leg root valve Repairs uill be performed during next outage WILSON J L. Virginia Electric & Power Co 82/10/04 Region 2 Office of Director 2pp 15675 263 24X Fiche 50-280,82/10/04,8210130204
- 9210130500 Forwards LER 92-091/03L-0 UIL 90N, J. L. Virginia Electric & Power Co. 82/10/04 G'REILLY, J.P. Region 2. Office of Director 1p. 15682 186 24X Fiche 50-280, 82/10/04, 9210130500
- --8210130507 LER 82-091/03L-0 on 820905, water & sediment found in lube oil of charging pump 1-CH-P-1A Caused by leak in one tube of lube oil cooler Godler replaced, sil changed & pump returned to svc WILSON, J. L. Virginia Electric & Power Ca. 82/10/07 Region 2, Dffice of Director 2pp 15682 187 24X Fiche 50-280,82/10/04,82/10/130500
- 8210220392 Forwards updated LER 80-019/03X-1 & LERs 82-058/03L-0 & 82-099/03L-0 WILSOM, J L Virginia Electric & Power Co 82/10/08 O'REILLY, J P Region 2, Office of Director 1p 15779 212 24X Fiche 50-280, 82/10/08, 8210220392
- --8210220398 Updated LER B0-019/03X-1 on 800304, error discovered in vol of contaminated drain tanks for increasing tankage Caused by stroneous labeling Vols relabeled & other tanks evaluated for use in liquid waste release calculations
 WILSDN.J. L. Virginia Electric & Power Co 82/10/08 Region 2,
 Diffice of Director 3pp 15779 213 24X Fiche 50-280,82/10/08,
 8210220392
- --8210220408 LER 82-058/03L-0 on 820915, safety injection accumulator C round w/reduced boron concentration of 1, 924 ppm Caused by leakage through check valve 2-81-144 during sensitized pipe flush Flush stopped Valve to be reworked during outage HILSON, J L Virginia Electric & Power Co 82/10/08 Region 2, Office of Director 2pp 15779 216 24X Fiche 50-280,82/10/08,82/10/20392

- --8210220413 LER 82-079/03L-0 on 820920, radiation monitors RJ-0W-101 to 102, V0-103 & 104 & RM-LW-108 lost power for 10 minutes. Caused by blown supply fuse due to inadvertent shorting of control relay to ground fuse replaced.

 WILSON, J L. Virginia Electric & Power Co. 82/10/08. Region 2, Office of Director. 2pp. 15779 218. 24X Fiche 50-280, 82/10/08. 8210220392.
- 8210290267 Part 21 deficiency rept to potential galling problem between stem & bonnet of 1 25-inch & larger A105 carbon steel & A182-F22 valves supplied Feb 1781-Aug 1982 Valves should be serviced & stem &/or bonnet replaced ISABELLE, L D Conval, Inc 82/10/11 HAYNES, R C Region 1, Dffice of Director 17pp 13854 232 24X Fithe 50-000,82/10/11, 8210270267
- 8210220095 Forwards LERs 82-098/03L-0 & 82-053/03L-0
 HILBON, J. L. Virginia Electric & Power Co. 82/10/14 G'REILLY, J. P. Region 2. Office of Director ip. 15778 177 24X
 Fiche 50-280, 82/10/14, 8210220095
- --8210220097 LER 82-098/03L-0 on 820919. Liquid waste monitor RM-LW-108 alarm setpoint exceeded Tech Specs limit during performance of PT-26 1 Caused by defective log rate board. Defective parts replaced & meter calibr WILSON, J L Virginia Electric & Power Co 82/10/14 Region 2, Defice of Director 2pp 15778 178 24X Fiche 50-280, 82/10/14, 8210220095
- --8210220100 LER 82-053/03L-0 on 820914.pump 2-8H-P-10A lost suction pressure Caused by insufficient NPBH due to throttled svc water to air conditioning chillers Pump vented to restore NPBH HILSON, J. L. Virginia Electric & Power Co. 82/10/14 Region 2, Office of Director 3pp 15778 180 24% Fiche 50-280,82/10/14,8210220095
- 8210290264 Forwards LERs 82-100/03L-0, 82-102/03L-0, 82-103/03L-0 WILSON, J. L. Virginia Electric & Power Co. 82/10/22 O'REILLY, J. P. Region 2, Office of Director ip. 15853 128 24X Fichs 50-280, 82/10/22, 8210290264
- --8210270270 LER 82-100/03L-0 on 820722.pump 1--SWP-108 became airbound during use of air to clear sensing lines to water strainers in delta P gauges Caused by injecting air into syc water lines upstream of pump Personnel reinstructed WILBON. J L Virginia Electric & Power Co 82/10/22 Region 2, Office of Director 2pp 15853 127. 24X Fiche 50-280,82/10/22.8210270264
- --8210290276 LER 82-102/03L-O on 820923, discovered pin attaching snubber 1-8HP-HS8-35B to main steam line partially out & snubber cocked Gaused undetermined Snubber straightened & pins properly installed HILSON, J. L. Virginia Electric & Power Co. 82/10/22 Region 2, Office of Director 2pp 15853 131 24X Fiche 50-280, 82/10/22, 83109305/4
- --8210270282 LER 82-103/03L-0 on 820927.mmp readings for heat tracing panel 2 circuit 24D found below acceptance level Cause unknown Defective heat tracing replaced & design change initiated WILBON.J L Virginia Electric & Power Co 82/10/22 Region 2, Office of Director 2pp 15853.133 24X Fiche 50-280.82/10/22.8210290244.
- DOCKET 50-201 SURRY POWER STATION, UNIT 2

 F Security, medical, emergency & fire protection plans
- 8210010156 Ack receipt of 820820 responses re emergency preparedness deficiency items per 820406 confirmation of action itr Corrective action & plans will be examined during subsequent insps.

 LEMIS.R C Division of Project & Resident Programs 82/09/10 LEASBURG.R H. Virginia Electric & Power Co ip 15565 325 24X Fichs 50-280.82/09/10.8210010156
- 8210010125 Forwards revised security training & qualification plans Plans withheld LEASBURGO,R. H. Virginia Electric & Power Co. 82/09/17. DENTON, H. R. Office of Nuclear Reactor Regulation, Director VAROA, B. A. Operating Reactors Branch 1 1p. 15566 013 24X Fiche 50-000,82/09/17,8210010125
- 8210050076 Bubmits correction to 820628 Revision 3 to response to NUREO-0737. Item I.D 2, "Safety Parameter Display Bys."

 Correction should be included in schedular exceptions pertaining to emergency response capabilities

 LEABBURG.R H. Virginia Electric & Power Co. 82/09/29 DENTON, H R Office of Nuclear Research regulation. Director. EIBENHUT, D O Division of Licensing ip 15603 185 24% Fiche 50-000,82/09/29,82/0050076

- 8210210050 Releases public version of changes to emergency plan implementing procedure FRLTDN.J M Sivision of Rules and Records 82/09/29 Document Management Branch ip 15774 109 24X Fiche S0-280.82/09/29, 8210210050
- --8210210093 Forwards public version of Change i to Emergency Plan Implementing Procedure EPIP-4 11. "Followup Offsite Release Assessment," Change 2 to swergency plan re NUREG-0654 cross-ref & Change 3 modifying Table 5 i
 DEMANDEL E P Virginia Electric & Power Co 82/09/17 NRC No Detailed Affiliation Given ip 15774 110 24x
 Ficha 50-280,82/09/29.8210210050
- --8210210055 Public version of Change 1 to Emergency Plan Implementing Procedure EPIP-4 11. "Fullowup Offsite Release Assessment"
 Virginia Electric & Power Co. 82/09/17 2pp 19774 111 24X
 Fiche 50-280,82/09/29,8210210050
- --8210210058 Public version of Changes 2 & 3 to emargency plan re HUREO-0654 cross-ref & Table 5 i, "Min Shift Manning Requirements," respectively 4 Virginia Electric & Power Co 82/09/17 10pp 15774.113 24X Fiche, 50-280, 82/09/29, 8210210050
- P Operating license stage documents & correspondence
- 8210120265 Informs of implementation status of NUREO-0737, Item II 0 2, "Plant Shielding" per NRC 820517 request All required work completed LEASBURG, R H Virginia Electric & Power Co 82/10/01 BENTON, II R Office of Nuclear Reactor Regulation, Director EISENHUT, D Q Division of Licensing 2pp 15651 230 24X Fiche 50-000, 82/10/01, 8210120265
- 8210120297 Forwards errets to Topical Rept VEP-FRD-30, "VEPCO Reactor Core Thermal-Hydraulic Analysis Using COBRA IIIc/HIT Computer Code "
 LEABBURG.R H Virginia Electric & Power Co 82/10/04 DENTON, H R Office of Nuclear Reactor Regulation, Director EISENHUT, D 0 Division of Licensing 2pp 15652 330 24X Fiche 80-000, 82/10/04, 8210120297
- --8210120305 Errata to "VEPCO Reactor Core Thermal Hydraulic Analysis Using COBRA-IIIc/MIT Computer Code " * Virginia Electric & Power Co VEP-FRD-33 ERR 82/10/04 lp 13652 332 24X Fiche 30-000.82/10/04.82(0120297
- 8210200043 Application for amend to Licenses DPR-32 & DPR-37 consisting of proposed changes to Tech Bpecs modifying reporting & notification requirements.

 LEABBURG, R. H. Virginia Electric & Power Co. 82/10/06 DENTON, H. R. OPFLICE of Nuclear Reactor Repulation, Director VARDA, S. A. Operating Reactors Branch i 3pp. 15757 225 24X Fiche 50-280, 82/10/06, 8210200043
- --8210200048 Proposed changes to Tech Specs modifying reporting & notification requirements
 4 Virginia Electric & Power Co 82/10/06 2pp 15757 228 24x
 Fische 50-280: 82/10/06 9210200043
- 8210220178 Comments on evaluation of significant dynamic loads in determining capacity of slings used per NUREO-0612 Rating can be safely expressed in terms of mex static load LEASBURGOR H Virginia Electric & Power Co. 82/10/18 DENTON, H R Office of Nuclear Reactor Regulation, Director ESENHUT, D. 0 Division of Licensing. 2pp 15777, 293. 24% Fiche 50-000, 82/10/18, 8210220178
- 8210280266 Informs that containment purge valve qualification program for 36-inch containment purge valves completed To ensura prevention of radioactive release new automatic isolation valve will be installed.

 LEASSURG.R.K. Virginia Electric & Power Co. 92/10/25, DENTON, H.R. Office of Nuclear Reactor Regulation: Director. VARGA, 8. A Operating Reactors Branch 1. 2pp. 15837, 316, 24X Fiche 50-280, 82/10/25, 8210280266
- 8210280130 Informs that review of new fuel container lifting rig completed. Rig does not comply w/Paragraph 3.2 1 1 of ANSI Ni4 6-1978 Proposed design mod for conformance being reviewed & will be implemented by 840322 LEASBURG. R. H. Virginia Electric & Power Co. 82/10/28 DENYON, H. R. Office of Nuclear Reactor Regulation. Director. RISENHUT. D. 0 Division of Licensing 10. 13837-163. 24K Fichs. 50-280, 82/10/28, 8210280130

- Q Inspection reports, IE Bulletins & correspondence
- B210BB0015 Add1 response to fOIA request for 19 categories of 15/5 of nuclear reactor events & safety problems Forwards documents listed in App A Documents in App B completely withheld (ref FOIA Exemption 5)
 FELTON, J M Division of Rules and Records 82/07/12 UDELL # 3 Critical Mass Energy Project 9pp 15643 027 24%
 Fiche 50~000.82/07/12.8210080015
- ~-8210080154 Systematic assessment of licenses performance notes of facility evaluation for May 1979-Apr 1980

 NRC No Detailed Affiliation Given 80/04/30 hpp 15648 051 24 Fiche 50-000, 82/07/12.8210080015
- B20B260424 Ack receipt of util B20609 itr & payment of civil persity Based on review of incidents, no basis for remission or nitigation of penalty identified LIEBERHAN, J Enforcement Staff B2/07/29 LEASBURG, R N V//7. Electric & Power Co Spp 15574 313 24X Fiche 50 280,02/07/24 B20B260424
- --B206160306 Responds to NRC B20510 ltr reviolations noted in 11',
 Rept 50-280/82-88 Corrective actions prestartup checklysh
 will be performed by instrument supervisor & all employees
 counseled reprocedural compliance
 LEABBURG, R H Virginia Electric & Power Co B2/06/09
 DEYOUNG, R C Director's Office. Office of Inspection and
 Enforcement App 15574 316 24X Fiche 80-280.82/07/23
- --8210010238 Forwards IE Insp Repts 50-280/82-04 & 50 481/82 (4 r 820125-0226 Enforcement action sent separately on 020510 O'REILLY, J P Region 2, Office of Director 82/05/17 LEASBURG, R H Virginia Electric & Power Co 2pp 15574 32 , Fichs 50-280,82/07/27.8208260424
- --8210010245 tE insp Repts 50-280/82-04 & 50-281/82 04 on Prolet Someompliance noted failure to maintain operability of signs flow instrumentation & to follow 0A manual & procedures for documenting inoperable steam flow instrumentation BURKE, D J. DAVIS, M J. DANCE, H C. Division of Projett & Rep. Programs 82/04/08 9pp 15574 322 24X Fishs 50-200 42; 18208260424
- 8210070007 Responds to FOIA request for eight categories of receives steam generators & steam turbines App A documents processes in R Udell FOIA Request 81-313 Forwards documents listed an App B FELTON, J.M. Division of Rules and Records 82/400/10 11-25, Hinthrop. Btimson. Putnam & Roberts 9pp 15649 069 741 Ficher 50-000.82/08/10.8210070007
- --8210070139 Forwards tabulated data on steam generator tray & actilities Data should be provided to licensess IPPDLITO.T Operating Reactors Assessment Branch (27/6 to VAROA:8 Operating Reactors Branch i Dop 15645 [3] [4] Fishe 50-000,82/08/10,8210070007
- --B210070172 Forwards info re steam generator integrity & properting PMRs, per 750320 & 21 requests Details of traps including defect indications, tube plugging triteria & Later plugged will not be provided except for Point Basin & QOLLER, K. R. Division of Reactor Literaing (MRR 1975 & http: 75/03/24 MACCARY, R. Division of Technical Review (MRR 1975 only). Spp. 13645-176 24X Fithe S0-000-82/08/10 Batterial
- B210010156 Ack receipt of 820820 responses of smergenty pressure deficiency items per 820406 confirmation of action the Corrective action & plans will be examined during subsequent insps.

 LEMIS R C Division of Project & Resident Progress & \$7/231,1 LEMISURG.R.H Virginia Electric & Power Co is 15% \$ 3.5% \$ 7 Fiche, 50-280, 82/09/10.8210010156
- ~~9210220356 IE Insp Repts 50~280/82-25 to 50~281/82 25 on to compliance noted Major areas inspected follows an previous enforcement matters to unresolved Items b Fallows on unplanned release of gaseous radioactivity HDBEY.C N: BARR.K P Division of Engineering to Tesas tall Programs 82/09/30 10pp 15776 277 24x Fixes to ESC 10220331.

- DB190233 IE Info Notice BO-35, Suppl 1, "Leaking & Dislodged I-125 Implant Seeds " Svc list encl COS5.4 I Division of Fuel Facilities, Materials & Safeguards 22/10/06 Consolidated Edison Co of New York 66pp 15761 250 24x Firbs 30-000.82/10/06.8208190233
- OB190238 IE Bulletin 82-03, "Stress Corrosion Cracking in Thick-Wall, Large-Diameter, Stainless Steel, Recirculation Sys
 Piping at DNR Plants " Svc list encl
 DEYOUNG, R C Director's Office, Office of Inspection and
 Enforcement 82/10/14 Consolidated Edison Co of New York
 115pp 15810 125 24X Fiche 50-000, 82/10/14, 8208170238

Reportable occurrences, LERs & related correspondence

- 10150359 LER 81-042/03L-0 on 810719, containment spray chemical addition tank (CAT) level found below Tech Specs Caused by Jeaking valve MOV-CS-202B valve scheduled for repair during next outage Tank level restored WILSON.JL Virginia Electric & Power Co. 81/08/17 Region 2. Atlanta. Office of the Director (81/03/01) 2pp. 15704 315 24) Fiche 50-281.81/08/17.8210150359
- 10270212 Forwards LERs 81-069/03L,81-073/03L-0 & 81-072/03L-0 WILSON J L Virginia Electric & Power Co 81/12/07 O'REILLY, J P Region 2, Atlanta, Office of the Director (81/03/01) ip 15827 042 24X Fiche 50-280,81/12/07,8210270212
- ### 210270220 LER BI-072/03L-0 on 81110B, motor operated valve 2867B failed to open when operated from control room during testing cause undetermined Valve opened normally when tested later WILSON, J L Virginia Electric & Power Co 81/12/07 Region 2, Atlanta, Office of the Director (81/03/01) 2pp 15827 046 24X Fiche 50-280,81/12/07,8210270212
- E210270224 LER 8:-073/03L-0 on Biil08, isolation valve to recirculation spray HX A failed to close Cause undetermined Valve operated normally later Limit switch & torque settings examined & found satisfactory
 HILSOIL-J L Virginia Electric & Power Co 81/12/07 Region 2,
 Atlanta. Office of the Director (81/03/01) 2pp 15827 048 24X
 Fiche 50-280.81/12/07.0210270212
- :50080015 Add1 response to FOIA request for 19 categories of info re nuclear reactor events & safety problems Forwards documents 11 sted in App A Documents in App B completely withheld (ref FOIA Exemption 5)
- FELTON: J H Division of Rules and Records 82/07/12 UDELL,R A Critical Mass Energy Project 7pp 15665 027 24X Fiche 50-000,82/07/12,8210080015
- -8204120487 Discusses problems w/water in fuel oil tank Case done not have generic implications TREHARN K. Director's Office 82/04/06 MICHELSON, C. Director's Office Spp 15665 036 24X Fiche 50-000, 82/07/12, 821068048
- -8205180693 Forwards engineering evaluation of 820118 loss of reserva station svc transformer B TREHAN, N K Director's Office 82/05/10 MIGHELSON, C Director's Office 2pp 15666 089 24X Fiche 50-000,82/07/12, 8210030015
- 210050081 Forwards LERs 82-093/03L-0.82-054/03L-0 & 82-092/03L-0 WILSON.J L Virginia Electric & Power Co 82/09/27 0'REILLY.J.P Region 2. Office of Director 1p 15604 244, 24X Fiche 50-280.82/09/27,8210050081
- ~ P210050091 LER 82-054/03L-0 on 820905, unattended portable pump in use to clean waterbox C swung around & flooded svc water pit containing svc water Valve MOV-5W-202B grounded in open position Caused by operator error MOV-5W-202B dried WILSOW J.L. Virginia Electric & Power Co 82/09/27 Region 2, Office of Director 3pp 15404 247 24X Fiche 50-280, 82/09/27, 8210050081
- Q(CO60361 Forwards LERs 82-087/03L-0 & 82-057/03L-0
 WELSON, J L. Virginia Electric & Power Co 82/07/30 0'REILLY, J P.
 Region 2. Office of Director 1p 15617:006 24X
 Fich 50-280.82/07/30.8210060361
- -8210060398 LER 82-057/03L-0 on 820901, 13, 18 % 20, pump 2-8W-P-10A experienced loss of suction pressure % on 820913 % 14, pump 2-5W-P-10B experienced similar loss of suction Caused by insufficient NPBH Suc water reduced Suc water pump vented. WILEDMJ L Virginia Electric & Power Co 82/09/30 Region 2, Office of Director 3pp 15619 010, 24X Fiche 50-280, 82/09/30, R210060361

- 8210130204 Forwards LERs 82-055/03L-0.82-096/03L-0 & 82-095/03L-0 WILSON,J L. Virginia Electric & Power Co. 82/10/04 8'REILLY,J P. Region 2. Office of Director 1p. 15675 258 24X Fiche 50-280.82/10/04.82101302004
- --8210130208 LER 82-055/03L-0 on 820906, charging pump auxiliary oil pump A tripped leading to tripping of replacement pump/motor Auxiliary pump failure caused by open winding in motor Replacement tripping caused by undersized themal overloads WILSON, J L Virginia Electric & Power Co 82/10/04 Region 2. Office of Director 2pp. 156/5:259 24X Fiche 50-280, 82/10/04, 8210130204.
- B210220424 Forwards LER 82-056/03L-0.
 WILEON, J L Virginia Electric & Power Co 82/10/07 O'REILLY, J P
 Region 2, Office of Director 1p. 15778: 270 24X
 Fiche 50-281.82/10/07, 8210220424
- --8210220435 LER 82-056/03L-0 on 820907.pressure in nitrogen bottle supplying emergency air to PCV-MB-202A & 8 discovered & elow limit Caused by leaking nitrogen bottle connection Replacement bottle correctly installed.

 WILSON, J L Virginia Electric & Power Co 82/10/07 Region R. Gfice of Director. 2pp 15778 271 24X Fiche: 50-281,82/10/07.
- 821020392 Forwards updated LER 90-017/03X-1 & LERS 82-058/03L-0 & 82-077/03L-0 .
 MILSON, J. L. Virginia Electric & Power Co. 82/10/08 G'REILLY, J. P. Region 2, Office of Director. Ip. 15779 212 24X Fichs 50-280.82/10/08
- --8210220408 LER 82-058/03L-0 on 820915, safety injection accumulator C found w/reduced boron concentration of 1,924 ppm. Caused by leakage through check valve 2-81-144 during sensitized pipe flush Flush stopped Valve to be reworked during outage WILBON, J L Virginia Electric & Power Co 82/10/08 Region 2, Office of Director 2pp 15779 216 24X Fiche 50-280,82/10/08, 82/0220392
- 8210290267 Part 21 deficiency rept re potential galling problem between stem & bonnet of 1 25-inch & larger Ai05 carbon steel & Ai82-F22 valves supplied Feb 1981-Aug 1982 Valves should be serviced & stem &/or bonnet replaced IBABELLE, L D Conval, Inc 82/10/11 HAYNES, R. C Region 1, Office of Director 17pp 15854 232 24X Fiche, 50-000, B2/10/11, 82/10290267
- 82:0220095 Forwards LER* 82-098/03L-0 & 82-053/03L-0 HILBON, J. L. Virginia Electric & Power Co. 82/10/14, D'REILLY, J.P. Region 2. Office of Director. 15 15778:177. 24X Fiche 50-280.82/10/14,8210220095
- --8210220100 LER 82-053/03L-0: on 820914, pump 2-8W-P-10A lost suction pressure Caused by insufficient NP8H due to throttled svc water to air conditioning chillers. Pump vented to restore NP8H WILSON, J. L. Virginia Electric & Power Co. 82/10/14 Region 2, Office of Director 3pp. 15778:180 24X Fiche 50-280,82/10/14, 8210220095
- DOCKET 50-282 PRAIRIE ISLAND NUCLEAR STATION, UNIT 1
- F. Security, medical, emergency & fire protection plans
- 8210250200 Forwards scenario outline for 821014 emergency plan evaluation exercise, per NRC 820112 guidance 1tr. WARD,E C Northern States Power Co 82/09/01 Region 3, Office of Director 2pp 13788 277. 24X Fiche, 50-282, 82/09/01, 8210250200
- 8210040345 Forwards IE Insp Repts 50-282/82-15 & 50-306/82-15 on 820824-25 No noncompliance noted PAPERIELLO, C J Division of Emergency Preparedness & Operational Support 82/09/10 LARSON, C. E. Northern States Fower Co 2pp. 15393 335 24% Fiche: 50-282, 82/09/10, 8210040345
- --8210040354 IE, Insp Repts 50-282/82-15 & 50-306/82-15 on 820824-25 No moncompliance noted Major areas inspected previous deficiencies in prompt notification/warning sys. PATTERSON.J.P., AXELSON.H.L. Division of Emergency Preparedness & Operational Bupport 82/09/09. 4pp. 15593.358, 24X Fichs.50-282,82/09/10.8210040345
- 8210080184 Forwards revised Page 4 reflecting NRC guidance on activation of public alert & notification syste 821014 emergency plan exercise MARD: E.C. Northern States Power Co. 82/09/28 AXELSON: W.L. Region 3, Office of Director. 2pp. 15640:175 24X Fiche: 50-282,82/09/28,8210080184

- 8210120589 Notification of 821001 meeting w/licensee. BNL & Engineering, Planning & Mgt. Inc. in Bethesda. MD to discuss requests for exemption from 10CFR50. App R requirements re-fire protection
 DIANNI.D C Operating Reactors Branch 3 B2/09/26
 Operating Reactors Branch 3 2pp 15672 346 24X
 Fiche 50-282.82/09/28,8210120589 82/09/28 CLARK, R A
- 3210260374 Ack receipt of FEMA 820526 ltr re evaluation of office emergency preparedness for facility exercise & associated final exercise evaluations Offsite emergency preparedness difficiencies should be addressed by util
 HIND. J. A. Division of Emergency Preparedness & Operational Support
 82/10/21 GILBERYS. D. E. Northern States Power Co. 2pp. 15804 001
 24X Fiche 50-282.82/10/21.8210260374
- 3210270262 Forwards info clarifying 820630 rept. "Fire Protection Safe Shutdown Analysis in Compliance W/10CFR50, App R. Section III O & Substantive Basis for Exemption Requests," per 821001 meeting w/NRC HUSGUF, D Northern States Power Co B2/10/22
 Reactor Regulation, Director 132pp 15829 049 Office of Nuclear 15829 049 24X Reactor Regulation, Director 1: Fiche 50-202, 82/10/22, 8210270262

> Operating license stage documents & correspondence

- 3210040123 Submits supplemental info re util 820614 request for amend to Licenses DPR-42 & DPR-60 "LOCA ECCS Limiting Break & Exposure Sensitivity Analysis for ENC XN-1 & XN-2 Reloads at Prairie Island I "applies to both Units 1 & 2 MUSDLF-D Northern States Power Co 82/09/24 Office of Nuclear Regulation, Director ip 15581 203 24X Office of Nuclear Fiche 50-282, 82/09/24, 8210040123
- 8210050319 Forwards response to Core Performance Branch 820816 concerns re-methods of monitoring core power distributions for Cycle 7 operation MUSOLF, D Northe Cycle / operation MUSOLF, D. Northern States Power Co. 82/09/29 Off Reactor Regulation, Director. 13pp. 15610 268 24X Fiche 50-282, 82/09/29, 8210050319 Office of Nuclear
- 8210130260 Discusses implementation of NRC guidelines for working hours, provided in Generic Ltr 82-12 Revised guidelines have been implemented, w/exceptions of 72-h per wk limitation & relief from control board duties MUSDLF, D Northern States Power Co 82/10/07 Of Reactor Regulation, Director 2pp 15676 012 24X Fiche 50-000, 82/10/07, 8210130260
- 8210190422 Forwards "Analysis of Capsule P From Northern States Power Co Prairie Island Unit i Reactor Vessel Radiation Northern States Power Co. 82/10/12 (Reactor Regulation, Director, 1p 15741 044 24X Fiche 50-282-82/10/12-8210190422 Surveillance Program Office of Nuclear
- --B210190429 "Analysis of Capsule P From Northern States Power Co Prairie Island Unit 1 Reactor Vessel Radiation Surveillance Program " YANICKKO, B E , TRAN.K C , KAISER.W T Westinghouse Electric Corp WGAP-10102 B2/05/31 EBpp 15741 045 Z4X Fiche 50-282, B2/10/12,8210190422
- 8210260154 Advises that mods required by NUREO-0737. Item III D 3 4. "Control Room Habitability," will not be completed until 830315 due to delays in receipt of matl & sampling equipment
 MUSOLF, D Northern States Power Co 82/10/22 G:
 Reactor Regulation, Director Spp 15797.012 24X
 Fichs: 50-282.82/10/22.8210260154 Office of Nuclear

O Inspection reports: IE Bulletins & correspondence

- 62:0070007 Responds to FOIA request for eight categories of records re steem generators & steem turbines App A documents provided in R_Udell FOIA Request 6:-3:3 Forwards documents listed in App B FELTON: J. M FELTON, J. M. Division of Rules and Records. 82/08/10 LONG, D. J. Winthrop, Stimson, Putner & Roberts, 9pp 15645.063 24X Fiche: 50-000, 82/08/10, 8210070007
- --8210070139 Forwards tabulated data on steam generator insp & maint at facilities. Data should be provided to licensees IPPOLITO.T Operating Reactors Assessment Branch 82/04/01 VARGA-8 Operating Reactors Branch 1 5pp. 15645:131 24X Fiche 50-000.82/08/10.8210070007

- --B210070172 Forwards info re steam generator integrity 4 into, at all it operating PNRs, per 750320 & 21 requests Details of image, including defect indications, tube plugging criteria & tubes plugged will not be previded except for Point Beach 1 GULLER: K R Division of Reactor Licensing (NRR-1975 only) 75/03/24 MACCARY, R Division of Technical Review (RRR-1975 only) 5pp 15645 196 24X Fiche 50-000, B2/08/10.0210070007
- 9210040345 Forwards IE Insp Repts 50-282/82-15 & 50-306/82-15 on 820824-25 No noncompliance noted
 PAPERIELLO, C J Division of Emergency Preparedness & Operations
 Support 82/09/10 LARBON, C E Northern States Power Co 7;
 15593-356 24% Fiche 50-282,82/09/10.8210040345
- --8210040354 IE Insp Repts 50-282/82-15 & 50-306/82-15 on 020024-35 & 210040334 1E Insp Repts 30-282/08-13 a 00-30042-35 on 120024-35 c noncompliance noted Major areas inspected previous deficiencies in prompt notification/warning sys PATTERSON, J.P., AXELSON, J. E. D.V. Sion of Emergency Preparedress in Operational Bupport 82/09/09 4pp 15593 358 24x Fiche 50-282,82/09/10,8210040345
- 820B190233 IE Info Notice 80-35, Suppl 1, "Leaking & Dislodged 1-12 Implant Seeds " Syc list enc! CDB0.t I Division of Fuel Facilities, Materials & Bafaguards 82/10/06 Consolidated Edison Co of New York & http://doi.org/10.1008/10.1008
- 8210190432 Ack receipt of 820915 ltm informing NRL of steps taken to correct violations noted in IE Insp Repts 50-282/82-11 & 50-304/82-11 50-306/82-11 SPESSARD,R L Division of Project & Resident Programs LARSON.C E Northern States Power Co ip 15741 182 Fiche 50-282, 82/10/07, 8210190432 10/02/50/01
- --8210190439 Responds to NRC 820817 ltr re violations noted in 14 ltg. Repts 50-282/82-11 & 50-305/82-11 Corrective actions startup program changed to normalize flux difference channels LARSON, C E Chambers
 LARSUN, C E Northern States Power Co 82/09/15 SIRIFIFA
 Divisson of Project & Resident Programs 2pp 15741 [8]
 Fiche 50-282, 82/10/07/8210190432 STRIFTIAL J.F.
- 8210150249 Ack receipt of 820928 ltr informing NRC of stept taken to correct violations noted in IE Insp Repts 50-282/02-13 & 50-306/02-13 STREETER, J F Division of Project & Resident Programs 82/10/03 LARSON, C E Northern States Fower Co ip 15/04 361 24 Fische 50-282, 82/10/08,8210150249
- --8210150255 Responds to NRC 820702 ltr re violations noted in [E.f., Repts 90-282/82-13 & 50-306/82-13 Corrective actions dissel generator test procedures will be revised by 821201 & investigative rept will be discussed w/operators Division of Project & Resident Programs Ppp, 19704 322 417 Fiche 50-282,82/10/08.8210150249
- 8210280144 Forwards IE Insp Repts 50-282/82-16 & 50-305/82 16 on 820701-17 & notice of violation STREETER, J F Division of Project & Resident Programs DJ/[C/1] LARSON, C E Northern States Power Co 2pp 1583/ 179 248 Fiche, 50-282, 82/10/13, 9210280164
- --8210280168 Notice of violation from insp on 820901-17 STREETER, J F Division of Project & Resident Programs 62/12.1 1p 15837 201 24% Fiche 50-282.82/10/13,8210280164
- --8210280171 IE Insp Repts 50-282/82-16 & 50-306/82-16 on 820701-19 Noncompliance noted failure to post no smoking sign in safety-related squipment areas & operators found smoking DUBRY.N.E. REVESL. Division of Project & Resident Programs 82/10/12 6pp 15837 202 24X Fiche 50-282.82/10/13.836626 to
- 8208190238 IE Bulletin 82-03, "Stress Corrosion Cracking in Thitt-Wall. Large-Diameter. Stainless Steel. Recirculation Sys Piping at BMR Plants "Svc list encl DEYGUNO, R C. Director's Office, Office of Inspection and Enforcement. 82/10/14 Consolidated Edison Co of New Yere 115pp 15810,125 24X Fiche 50-000,82/10/14,8208199238
- S Reportable occurrences, LERs & related correspondence
- 8210150381 Forwards LER 81-011/01T-0 MAYER.L G Northern States Power Co 81/08/24 MEPP Region 3. Chicago, Dffice of the Director (81/03/01) 15704:065 24% Fiche 50-282.81/08/24,8210150381 KEPPLER, J & 1.0

- --B210150390 LER B1-011/01T-0 on B10812.D2 diesel generator tripped & locked out during operability test Caused by generator operating in unfamiliar mode & var & watt meters being confused by operator HUMSTAD.A A Northern States Power Co 81/08/24 Region 3, Chicago, Office of the Director (81/03/01) 2pp 15704 066 24% Fiche 50-282,81/08/24,8210150381
- E210130510 Forwards LER B2-016/03L-0 MUCDLF.D Northern States Power Ca B2/10/06 Region 3, Office of Director 1p 15682 256 24X Fiche 50-282,82/10/06,8210130510
- --B2(0130533 LER 82-016/03L-0 on 820906, spike occurred in RCS activity up to 1 38 uC1/g dose equivalent I-131 Caused by reactor trip 2 subsequent washout of fission product from existing fuel defects Region 9 fuel will be removed HUNSTAD.A A Northern States Power Co B2/10/06 Region 3, Office of Director App 15682 257 24X Fiche 50~282, B2/10/06, B210130510
- 8210250179 Forwards LER 82-019/03L-0 MUSOLF, D. Northern States Power Co. 82/10/15 Region 3, Dffice of Director ip 15788 296 24% Fiche 50-282/82/10/15,8210250179
- --8210250183 LER 82-019/03L-O on 820917. diesel cooling water pump 22 did not start on demand during testing Start attempt 7 minutes later successful Cause unknown In 5 days of testing.failure could not be reproduced MUNSTAD, A A Northern States Power Co 82/10/15 Region 3. Office of Director 1p 15788 297 24X Fiche 50-282,82/10/15,8210250179
- B210250364 Forwards LER B2-018/03L-0 MUSCLF.D Northern States Power Co 82/10/15 Region 3, Office of Director 1p 15790 177 24% Fiche 50-282,82/10/15,8210250364
- --8210250374 LER 82-018/03L-0 on 820915, discovered that two ventilation flow tests not performed as scheduled Caused by personnel error Tests rescheduled HURISTAD, A A Northern States Power Co 82/10/15 Region 3, Office of Director 1p 15790 178 24X Fiche 50-282,82/10/15.6210250344
- DOCKET 50-285 FORT CALHOUN STATION, UNIT 1
- A Application/construction stage documents & correspondence
- E21001000B Responds to FOIA request for 19 categories of documents re nuclear reactor events & safety problems Forwards documents listed in App A FELLTON, J M Division of Rules and Records 62/06/28 UDELL, R A Critical Mass Energy Project 15pp 15727 005 24X Fiche 50-000, 82/06/28, 8210010008
- --8204270048 Recommends prompt attention be given to problem of reactor coolant pump closure stud corrosion detected at facilities Response by B20415 requested EISENHUT.D G Division of Licensing 82/03/24 HANAUER.S. H Division of Systems Integration (post B11005) 3pp 15745 270 24% Fachs 50-000.82/06/28.8210010008
- F Security, medical, emergency & fire protection plans
- ECC917CO51 Forwards site security plan Revision 11 Revision withheld (nef 10CFR73 21)
 JONES, W. C. Omaha Public Power District 82/08/27 DENTON, H. R. Office of Nuclear Reactor Regulation. Director 1p 14910 097 24 Fiche 50-285,82/08/27,8209170051
- 6210220110 Notifies of emergency preparedness appraisal team 821108 site visit to close out Apps A & B items identified in IE Emergency Preparedness Appraisal Rept 90-285/82-27 on 811207-16
 SEIDLE: W C Division of Resident, Reactor Project & Engineering Programs 82/10/17 JONES,W C Omaha Public Power District 19 13778 168 24X Fiche 50-285.82/10/19.8210220110
- H General correspondence
- 6210060244 Requests that author be deleted from mailing list Further mailings should be sent to Metropolitan Planning Agency KIRSHEN, A H Kirshen, A H 82/09/30 TOURIGNY, E NRC No Detailed Affiliation Given ip 15619 320 24X Fiche 50-285, 82/09/30, 8210060244

- P Operating license stage documents & correspondence
- G210010008 Responds to FOIA request for 17 categories of documents re nuclear reactor events & safety problems Forwards documents listed in App A FELTON, J M Division of Rules and Records 82/06/28 UDELL. R A Critical Mass Energy Project 15pp 15727 005 24X Fiche 50-000, 82/06/28, 8210010008
- --8004i00i93 Forwards evaluation of facility for Cycle & operation All Tech Spec changes & safety analyses required for 1500 MH approved CHECK,P 8 Reactor Safety Branch 80/03/18 REID,R W Operating Reactors Branch 4 (Pre 800428) 34pp 15727 044 24X Fiche 50-000.82/06/28,8210010008
- 8210080015 Addl response to FOIA request for 19 categories of info re nuclear reactor events & safety problems Forwards documents listed in App A Documents in App B completely withheld (ref FOIA Exemption 5)
 FELTON, J M Division of Rules and Records 82/07/12 UDELL.R A Critical Mass Energy Project 9pp 15665 027 24X
 Fiche 50-000.82/07/12,8210080015
- ---8105040512 Discusses actions proposed as result of boric acid corrosion damage of stud boits & piping at PHR plants IE proposal & schedule for actions will be discussed at 810407 meeting in Bethesda. MD SNIEZEK, J H. Division of Resident & Regional Reactor Inspection 81/04/02 EIBENHUT, D O Division of Licensing ARLOTTO & A Division of Engineering Standards 3pp 1566B 127 24X Fiche 50-000, 82/07/12.8210080015
- B210050247 Forwards post-accident sampling sys status update & revised completion schedulo per NUREQ-0737. Item II B 3 Reasons for delay of TMI action plan mod discussed JONES W C Omaha Public Power District B2/07/30 CLARK, R A Operating Reactors Branch 3 3pp 15610 330 24X Fiche 50-285, 82/07/30, 8210050247
- 82100&0196 Advises of delay in receipt of motor curves from vendor per 820521 commitment to provide justification re adequacy of electrical distribution sys voltages Curves & evaluation scheduled for submittal by 821201

 JONES,W C Omaha Public Power District 82/10/01 CLARK,R A Operating Reactors Branch 3 ip 15614 009 24X Fiche 50-235, 82/10/01,82100&0196
- 8210270038 Forwards PNL final rept on 820608-10 audit of procedures & training addressing pressurized thermal shock issue Max & min subcooling margin curve, NDT & saturation curves should be available on single plot in control room CLARK-R A Operating Reactors Branch 3 82/10/12 JGNES, W C Omaha Public Power District 3pp 15877 278 24X Fiche 50-285, 82/10/12.8210290038
- --8210290041 "Audit of Fort Calhoun Procedures & Training that Address Pressurized Thermal Shock Issue," final rept CLARK.R O. AMES, K. RANKIN.H U. Battelle Memorial Institutu, Pacific Northwest Laboratory 82/06/30 28pp 15877 281 24X Fiche 50-285,82/10/12,8210290038
- 8210 conorm As form that that promoted achedule for fulfilling NUREO-

- --8210190349 IE Insp Rept 50-285/82-17 on 820830-0903 No nancompliance noted Major areas inspected housekesping/cleanliness, onsite review committee & calibr HURPHY.M E , FLIPPO.T.A . KUNNIGUTT.D M Division of Resident. Reactor Project & Engineering Programs 82/09/20 App 15742 114 24% Fiche 50-285.82/09/22,8210190347
- 8210190531 Forwards IE Insp Rept 50-285/82-16 on 820801-31 No noncompliance noted SEIDLE:NC Division of Resident, Reactor Project & Engineering Programs 82/09/22 JONES.H C Omaha Public Power District 2pp 15751 306 24X Fiche 50-285,82/09/22,8210190531
- --8210190539 IE Insp Rept 50-285/82-16 on 820801-31 No noncompliance noted Hajor areas inspected operational safety verifications survaillance testing meint, preparation for refueling & LER fallows YANDELL.i. A. HUNNICUTT.D M Division of Resident, Reactor Project & Engineering Programs 82/09/17 6pp 15751 308 24X Fiche 80-285.82/09/22.8210190531
- 3210070326 Ack receipt of 920629 ltr supplementing 811012 & 0904 ltrs informing NRC of steps taken to correct violations noted in IE Insp Rept 50-285/Bi-16
 SEIDLE:W C Division of Resident: Reactor Project & Engineering Programs 82/10/05 JONES.W C Omeah Public Power District ip 15434 085 24% Fishe 50-285.82/10/05.0210070326
- --8210070333 Responds to NRC 810805 ltr re violations noted in 1E Insp. Rept 50-285/81-16 Corrective actions all GA records will be entered into record mgt sys by 831231 Info updates 810904 & IGI2 responses

 JONES, H. C. Onaha Public Power District 82/06/29 SEIDLE, H. C. Division of Resident, Reactor Project & Engineering Programs 2pp 15634 086 24X Fiche 50-285, 82/10/05, 8210070326
- 1208190233 IE Info Notice 80-35, Suppl 1, "Leaking & Dislodged I-125 Implant Seeds " Syc list enc! COBB.L I Division of Fuel Facilities, Materials & Befoguards 82/10/06 Consolidated Edison Co of New York 66pp 15761 250 24X Fiche 50-000.82/10/06.8208190233
- 1208190238 IE Bulletin 82-03, "Stress Corrosion Cracking in Thick-Wall, Large-Diameter, Stainless Steel, Recirculation Sys
 Piping at BMR Plants "Syc list encl
 DEYDUNG.R C Director's Office, Office of Inspection and
 Enforcement 82/10/14 Consolidated Edison Co. of New York
 115pp 15810 125 24X Fiche 50-000,82/10/14,8208190238,
- 1210220110 Notifies of emergency preparedness appraisal team 821108 sate visit to close out Apps A & B items identified in IE Emergency Preparedness Appraisal Rept 50-285/82-27 on 811207-16
 EEIDLE: H C Division of Resident, Reactor Project & Engineering Programs 82/10/19 JONES: H C Omaha Public Power District 19 15778 168 24% Fiche 50-285,82/10/19,8210220110

Periodic operating reports & related correspondence

- 210190736 Forwards monthly operating rept for Gept 1982 JONES W C Omaha Public Power District. 92/10/12 DEYGUNG, R C Director's Office, Office of Inspection and Enforcement 1p 13736 242 24X Fiche, 50-285, 82/10/12, 8210190736

Reportable occurrences, LERs & related correspondence

- 210040186 Forwards LER 82-018/01T-0

 JONES W C Omaha Public Power District, 82/09/20 SEIDLE, W C Region 4, Office of Director, 1p 15581-352 24X Fiche 50-285,82/09/20,8210040186
- -9210040187 LER 82-018/01T-0 on 820917, review of electro-pneumatic (E/P) valve positioners revealed absence of analysis or test qualification data for Honeywell Model 67400-023 positioners Control circuit, solenoid valves to be nodffied MEMAFEEY,R F. Omaha Public Power District 82/09/17 Region 4, Office of Director. 4pp. 15581:353 24X Fiche 50-285,82/09/20,8210040186.
- 210130570 Forwards LER 92-017/03L-0
 JONEB W C Omsha Public Power District 82/09/29 SEIDLE W C
 Division of Resident, Reactor Project & Engineering Programs. ip.
 15679:109 24X Fiche 50-285,82/09/29,8210130570.

- 8210050301 Forwards LER 92-017/03L-0 Detailed event analysis subbite. JONES W C Dosha Public Power District 82/10/01 CLARKIR A Operating Reactors Branch 3 pg 15610 261 24X Fiche 50-289, 82/10/01,8210050301
- --8210050303 LER 62-017/03L-0 on B20830, control room operator natical valve position indication for inboard containment isolation valves, HCV-0208 & 8218 Caused by Valcor Engineering Coscience of Valves containing failed salenoid coils CORE, MR Omaha Public Power District B2/09/29 Region 4 Office of Director 4pp 15410 262 24% Fiche 50-295, 02/10/01 8210050301

V Operator Examinations

8210200077 Advises that util proposed schedule for fulfilling NUEEC-0737. Item I A 1 3, "Shift Hamming Requirements." has been delayed due to NRC not having graded exams for two innior reactor operator trainees New completion date is 830101 JONES. W C Omaha Public Power District 82/10/15 CLARK. R A Operating Reactors Branch 3 2pp 15755 354 24% Fichs 50-285, 82/10/15, 8210200077

DOCKET 50-286 INDIAN POINT STATION, UNIT 3

F Security, medical, emergency & fire protection plans

- 8210060091 Submits request for mods to emergency notification equal to upcoming relocation of emergency facilities
 BRONS.J C Power Authority of the State of New York 82/09/13
 SHITH.O H Division of Emergency Properations & Operational September 2pp 15614 359 24X Fiche 50~286.82/09/13.8210060091
- 8210060145 Forwards "Testing & Repair of Siren Portion of Alert & Notification Sys for Indian Point Nuclear Power Generating Plant," per discussion at 820008 status meeting RELLY, J Power Authority of the State of New York 6.2/GV/15 DAVIDOFF, D New York State of 1p 19614 295 24x Fiche 50-247, 82/09/15.8210060145
- --8210060148 "Testing & Regair of Siren Portion of Alert & Rolificat Sys for Indian Point Nuclear Power Generating Plant " 4 Power Authority of the State of New York 82/09/14 Ope 15614 296 24X Fiche 50-247, 82/09/15, 8210060145
- B210130047 Notification of B20924 meeting w/util in Bethewda.HD to discuss App R review THOMA,J O Operating Reactors Branch 1 B2/09/20 VARGA.S A Operating Reactors Branch 1 2pp 15696 282 24X Fiche 50-286, B2/09/20,B210130047
- 8210130604 Forwards Auxiliary Bys Dranch input to agenda for 926r.s meeting in Bethesda.MD to discuss App R & probabilistic rist assessment
 - VAROA.B A Operating Reactors Branch 1 82/09/21 Linclain L Power Authority of the State of New York 8pp 15692 351 24s Fiche 50-286:82/09/21,8210130604
- 8210040206 Ack receipt of 820902 ltr describing status of activities underway to correct significant deficiencies identified by FCMA in response to NRC 820803 ltr
 BMITH, 0 H Division of Emergency Preparedness & Operational E. pt. 82/09/27 BRONS, J C Power Authority of the State of New Yerk ip 15583 134. 24% Fiche 50-286, 82/09/27, 8210040206
- --B210040213 Forwards description of activities planned or undertal, correct deficiencies listed in FEMA 820730 interia findings re adequacy of radiological emprency response preparadoes of state & local govts.per NRC 820803 request BAYNE, J. P. Fower Authority of the State of New York 82/09/02 HAYNES, R. C. Region j. Office of Director lipp 13383 135 Tricke 50-284,82/09/27,8210040204
- 8210050079 Informs that installation of CRT terminal in emergency operations facility & video surveillance sys per THI Action Item III.A i 2 will be completed by end of current rafueling outage BAYNE.J.P Pawer Authority of the State of New York 62/09/50 VARQA.8.A Operating Reactors Branch i 2pp 15604 274 241 Fiche 50-286, 82/09/30, 8210050079.
- 8210190738 Forwards schedule for providing info requested in Nat 62. Itr re App R
 BAYNE, J P Power Authority of the State of New York 82/0/12
 VARQA, S. A Operating Reactors Branch 1 4pp 15736 258 241
 Fiche 50-286, 82/10/12,8210190738.

- 8210200019 Advises that serious deficiencies in emergency preparedness will not be corrected since State of NY & FEMA not addressing concerns of local officials by involvement in current changes
 HDLT.J Public Interest Research Group, New York KESSLER.J Rockland Citiens for Safe Energy SCHEINER.C A Westchester Peoples Action Coalition Inc. 82/10/15 PALLADINO.N J. ROBERTS.T M. ASSELSTING.J K Commissioners 5pp 15755 089 24X Fiche 50-247.82/10/15.8210200019
- G Adjudicatory correspondence
- BCO62307BB Ack receipt of 800416 memo w/insp repts verifying interim actions required of facilities in B00211 confirmatory orders Requests verification that Item F 2 in orders is met Item E 5 in W Commill B00317 memo should be F 5 NOVAK.T M Assistant Director for Operating Reactors 80/06/13 RYAH.S E Division of Reactor Operations Inspections 1p 02765 285 24% Fiche 50-247.80/06/03.8006230788
- 8210060235 Declines invitation to appear before Subcommittee on Energy Conservation & Power Subcommittee investigation is intrusion into ongoing regulatory proceeding & threatens independence of Commission MORGAN.C Morgan Associates MORGAN.C Power Authority of the State of New York 82/09/30 OTTINGER.R L House of Rep , Energy & Commerce 10pp 15619 360 24% Fiche 50-247.82/09/30,8210060235
- 8210040108 Order CLI-82-28, requesting ASLB reconstituted by CLI-82-24 to estimate when recommendations called for by CLI-81-23 can be provided CHILK.S J Office of the Secretary of the Commission 82/10/01 Atomic Safety and Licensing Board Panel 1p 15580 350 24% Fiche 50-247,82/10/01.8210040108
- 8210050254 Memorandum & order restating contentions & establishing procedures based on Commission guidance GLEASOR, JP. PARISIO H., SHON, FJ. Atomic Safety and Licensing Board Panel B2/10/01 42pp 15609 211 24X Fiche 50-247, 82/10/01.8210050254
- 6210130335 Motion for ASLB to direct NRC to reschedule 821013 meeting woutlis & Sandia in Albuquerque.NM to either New York.NY or Washington.BC Intervenor unable to attend meeting in NM WEISS.ER Union of Concerned Scientists WEISS.ER Public Interest Research Group. New York 82/10/07 Atomic Safety and Licensing Board Panel 3pp 15682 080 24X Fiche 50-247.82/10/07.8210130335
- --8210130337 Notion for Commission to direct that all future meetings on issues be held in NY or Washington, DC & that intervenors be given notice concurrently w/other parties NEISS.E.R. Union of Concerned Scientists WEISS.E.R. Public Interest Research Group, New York 82/10/07 Commissioners 2pp 15682 053 24X Fiche 50-247, 82/10/07, 8210130335
- G210180203 Reply to ASLB 821001 memorandum & order Plant should be totally reinspected w/appropriate toets of piping.electrical & control sys conducted List of parties should be shortened to active participants Certificate of Svc encl FLEIEMER.7 S West Branch Conservation Association 82/10/11 4pp 15718 124 24X Fiche 50-247.82/10/11.8210180203
- 8210150092 Order denying UCS/NY PIRO 821007 motion to direct NRC to reschedule 821013 meeting in Albuquerqua NM to NY or Hashington DC Only Commission has jurisdiction over NRC performance of administrative responsibilities PARIS, O H , SHON,F J , GLEASON, J P Atomic Safety and Licensing Board Panel 82/10/12 Union of Concerned Scientists 3pp 13701 194 24X Fiche 50-247,82/10/12,82(0150092
- 6210150141 Order scheduling 821103-04 prehearing conference in White Plains.NY re oral argument on responses to ASLB 821001 memorandum & order restating contentions GLEASON.J P Atomic Safety and Licensing Board Panel 82/10/12 2pp 15698 306 24X Fiche 50-247.82/10/12.8210150141
- 6210180138 Motion in response to ASLB 821001 order, requesting clarification & importance of term "discussion" & extension of time to determine position re issue of consolidation Certificate of Svc encl KAPLAN.C New York
- 8210200069 Telegraphic order granting licenses request for extension of time to file responses to 821001 order All party responses due 821019
 GLEASON.J P Atomic Safety and Licensing Board Panel 82/10/14
 Power Authority of the State of New York 1p 15757 280 24X
 Fiche 50-247, 82/10/14, 8210200069

- 8210200019 Advises that serious deficiencies in emergency preparedness will not be corrected since State of NY & FEMA not addressing concerns of local officials by involvement in current changes HOLT, J Public Interest Research Group, New York POSNER, P Parents Concerned About Indian Point FLEIGHER, 2 S Wost Branch Conservation Association 82/10/15 PALLADINO, N J , AHEARNE, J F , GILINSKY, V Commissioners 5pp 15755 089 24X Fiche 50-247, 82/10/15, 8210200019
- B210220389 Submittal of comments on ASLB B21001 memorandum & order & motion for ASLB to issue reformulated contentions on Commission Questions 3 & 4 by B21115 & to restore Contention 6 2 Certificate of Svc encl TOSCANIK Parents Concerned About Indian Point B2/10/15 Atomic Bafety and Licensing Baard Panel 2pp 15777 307 24X Fiche 50-247.82/10/15,8210220389
- 8210210390 Requests destruction of West Branch Conservation Assoc 821011 reply to 821001 memorandum & order & substitution of encl version FLEISHER, Z.S. West Branch Conservation Association 82/10/18 NRC - No Detailed Affiliation Given ip 15764 099 24X Fiche 50-247, 82/10/18, 8210210390
- --8210210377 Response to 821001 memorandum & order Certificate of Svc encl FLEISHER.Z 8 West Dranch Conservation Association 82/10/13 4pp 15744 100 24X Fiche 50-247, 82/10/18,8210210370
- 8210200059 Response to ASLB 821001 order ASLB should narrow language of ASLB Question 1 1 & adopt proposed schedule for continuation of proceeding Certificate of Svc encl MODRE, J. MCOUREN, H. J. Hearing Branch 1 82/10/19 9pp 15757 290 24% Fiche 50-247.82/10/19.8210200059
- 8210220375 Request for mod of ASLB 821001 order to permit Rockland County to continue presentation of witnesses re Commission Guestions 3 & 4 prior to taking evidence on Guestions 1,2,5,6 & 7
 THORSEN,E D Rockland County, NY 82/10/19 Atomic Safety and Licensing Board Panel 2pp 15779 187 24X Fiche 50-247,82/10/19,8210220375
- 8210220410 Joint response of intervenors to ASLB 821001 order Meaning of "discussion" of probability should be clarified & ASLB should immediately reformulate contentions on Guestions 3 & 4 Certificate of Svc encl MEISS.E R Union of Concerned Scientists MEISS.E R Harmon & Meiss 82/10/19 Atomic Safety and Licensing Board Panel. IRpp 15778 313 24X Fiche 50-247.82/10/19.8210220410
- 8210250081 Proposed hearing schedule Certificate of Svc encl
 BRANDENBURG. B Concolidated Edison Co of New York MORGAN, C
 Power Authority of the State of New York MORGAN, C
 Associates 82/10/19 9pp 13787 049 24X Fiche 50-247,82/10/19,
- 8210250216 Response to ASLB 821001 order reformulating contentions Opposes admission of new Contention 1 1.Contentions 2-1(a)-(d),2 2(a) & 2 2(b) & ASLB Question 2 2 1 Notice of appearance & Certificate of Bvc encl MORGAN.C Power Authority of the State of New York MORGAN.C Morgan Associates 82/10/19 Atomic Safety and Licensing Board Panel 35pp 15789 166 24x Fiche 50-247.82/10/19.8210250216
- 8210250265 Notice of appearance in proceeding BAUM 8 L. Power Authority of the State of New York BAUM 8 L Morgan Associates 82/10/19 1p 15791 152 24X Fiche 50-247, 82/10/19, 8210250265
- 8210250287 Motion for order reversing ASLB 821001 memorandum & order relating of testimony on Questions 3 & 4 & establishing schedule for presentation of testimony upon expiration of 120-day clock Certificate of 8vc encl VETERE, L A Westchester County, NY 92/10/19 Atomic 8afety and Licensing Board Panel 7pp 15791 165 24X Fiche 50-247, 82/10/19, 8270250997
- B210290324 Memorandum re ASLB 821001 order reformulating contentions Objects to new Contention 1 1.8ases is & 1b.Contentions 2 1(a).2 1(b).2.1(c).2 1(d).2 2(a) & 2 2(b).Certificate of 8vc encl
 BRANDENBURG.B Commonwealth Edison Co 82/10/19 Atomic Sefety and Licensing Board Panel 47pp. 15770 243 24% Fichs 50-247.82/10/19.8210250324.
- 8210250079 Motion for leave to file memorandum in response to ASLB 821001 order 1 day late Mechanical difficulties encountered w/word processing equipment Certificate of Svc encl BRANDENBURG. B Consolidated Edison Ca of New York. 82/10/20. Commissioners 6pp 15787 062 24X Fiche 50-247.82/10/20, 8210250079

- 8210280242 Requests Commission issue order directing all meetings between NRC & licensee be held in Mashington, DC or NV. that intervenors receive notice of meetings concurrently w/utils that intervenors be provided w/minutes of 821013 meeting WEISS.E R Harmon & Meiss WEISS.E R Union of Concerned Scientists 82/10/25 PALLADINO, N J . AMERANGAJ, GILINSKY, V Commissioners 2pp 15837-058 24X Fichs 50-247, 82/10/25, 8310360342
- 8210280230 Advises that NRC does not intend to respond to intervenor motions filed in response to ASLB 821001 order until after 821103-04 prehearing conference MODRE, J & Hearing Branch | 82/10/27, QLEASON, J P , SHON, F J , PARIS, D R Atomic 84fety and Licensing Board Panel | 19 15837 082 24X Fiche 50-247,82/10/27,8210280230
- 8210280353 Response apposing UC8/NY PIRO 821012 motion to direct NRC to reschedule all future meetings on hearing issues in NY or Hashington, DC NRC should be permitted flexibility to determine most appropriate location M/Certificate of Svc MCOURREN, H J Hearing Branch 1 82/10/27 Commissioners 9pp 15839 048 24% Fiche 50-247, 82/10/27, 82/10/20353
- B210290271 Advises that licensess plan to address all matters raised in responses/motions re ASLB B21001 memorandum & order at B2103-04 prehearing conference BRANDENBURGS B Consolidated Edison Co of New York MORGAN, C Power Authority of the State of New York MORGAN, C Horgan Associates B2/10/27 GLEASON, J P, SHON, F J, PARIS, O H Atomic Safety and Licensing Board Panel 2pp 15833 012 24% Fiche 50-247, 82/10/27, 9210290271

H General correspondence

- 8210190713 Informs that SS Zullo & RA Burne authorized to sign util ltrs to NRC BAYMEJ P Power Authority of the State of New York 62/10/13 Office of Nuclear Reactor Regulation, Director 2pp 15738 209 24X Fichs 50-000,82/10/13.8210190713
- B210250272 Requests substitution of SL Daum w/TR Frey on official svc list for proceeding Related correspondence COLARULLI.P F Morgan Associates COLARULLI.P F Power Authority of the State of New York 82/10/19 STUCKY.8 W Docketing & Services Branch 19 15791 190 24X Fiche 50-247.82/10/19, 8210250272
- O Advisory Committee on Reactor Safeguards reports & correspondence
- 8207180077 Forwards comments on PRA study dealing w/seismic hazard Validity of conclusions rest on quality of primary data bases & assumptions in both studies Repts are not valid risk assessments due to data base limitations POMEROY, P W Rondout Associates 82/08/24 OKRENT, D ACRS Advisory Committee on Reactor Safeguards 7pp 15876 001 24X Fiche 30-286, 82/08/24, 8207180077
- P Operating license stage documents & correspondence
- 8007010658 Operating Reactor Event Hemo 80-7 re nearly simultaneous trips of Unite 2 & 3 Event was of negligible safety significance & trips were unrelated & coincidental EISENHUT, D O Division of Licensing 80/06/13 VOLLMER, R H Division of Engineering MATTSDN:R J Division of Safety Technology. HANAUER: 8 H Division of Human Factors Safety 2pp 02815 145 24X Fiche 50-247,80/06/13,8007010658
- 8007280312 Summary of 800625 meeting w/util re implications of Class 9 accidents on liquid pathways at facility CODELL-R Hydrologic & Geotechnical Engineering Branch. 80/07/08 LEAR O Hydrologic & Geotechnical Engineering Branch 5pp 03016 253. 24% Fiche 50-247.80/07/08.8007280312
- 8008050220 Requests LB March be permitted to continue reviewing overpressure protection sys & associated Tech Specs NOVAK: T Assistant Director for Operating Reactors 80/07/30, ERNBT. M L Assistant Director for Technology Review 1P 03078.175. 24X Fiche, 50-247, 80/07/30, 8008050220,
- 8008130744 Summary of BD0617 meeting w/utils in Bethesder MD recontainment structural response to core melt accident sequences
 MEYER. J. F. Power Bystems Branch B0/07/31 Power Bystems Branch
 3pp 03266-243 24X Fiche 30-247, 80/07/31, 8008130744
- 8009100100 Forwards recommendations on staff task action plan to be sent to licensees for review & response.

 BARRETTL M. Operating Reactors Assessment Branch 80/08/08 VARGA.S. A Operating Reactors Branch 1 (Fre 800428) 8pp 03516 066 24% Ficher 50-247, 80/08/08, 8009100100.

- 8009080466 Forwards response to 800820 request for status rept re-Zion/Indian Point task action plan Responsibilities are in area of severe accident mitigation features & not in interia operational actions portion MEYER. J. F. Reactor Systems Branch 80/08/25 NOVAK. I. M. Atlis** Director for Operating Reactors 2pp 03484 009 24x Fichs 50-003.80/08/25.8009080466
- 8010150103 Discusses union representative allegation re hargsmark if security guard personnel Addi info necessary prior to NAC investigation of allegations HARD. H. Office of Inspection & Enforcement, Office of the Director 80/08/28 Office of Inspection & Enforcement, Office the Director 2pp 03630 268 24X Fiche 50-247, 80/08/29, 80/10150103
- 8009250234 Submits description of work being done on analysis of releases from facilities Simple 1-D multicompertment thereal hydraulic code being unitten to analyse variety of FVCB designs Related data encl FENSIERMACHER Reactor Systems Branch 80/09/10 SFE18,T P Reactor Systems Branch 4pp 03589 257 24% Fiche 50 247.80//f 8009250234
- B010220234 Responds to 800917 request re control room review ARC (1).

 1tr detailed five add1 items to near-term OL requirements

 Item III D 3 4 requires analysis of control room

 habitability by 810101

 HOUSTON: R W Accident Evaluation Branch 80/09/25 VARGA, 8 A

 Operating Reactors Branch 1 1p 03560 001 24%

 Fichs 50-247, 80/09/25, 8010220234
- 8010210783 Forwards recommendations for meeting auxiliary feedwals, min flow requirements Licensee must demonstrate decay heat removal for 10 minutes w/o operator action or reset control valve throttled position
 CHECK, P.S. Assistant Director for Plant Systems 80/09/20
 NOVAK, T.H. Assistant Director for Operating Reactors 299
 03647 104 24% Fiche 50-247,80/09/28,8010210783
- BOILIIOOBA Requests Instrumentation & Control Sys Branch evaluation util responses to questions re incore instrumentation tubes at facilities Info will aid branch evaluation mitigation features re backfitting of severe mitigation features.

 SPEIST P Reactor Systems Branch BO/10/09 BATTEMFIFID.R Instrumentation & Control Systems Branch ip 02927 001 243 Fiche 50-247, 80/10/09, 8011110084
- 806028009B Forwards NRC questions & util answers re backfitting of severe accident mitigation features Evaluation needed in two uts SPEIS,TP Reactor Systems Branch 80/10/17 8CHAULR,FP Structural Engineering Branch 1p 65747 184 24X Fiche 50-247,80/10/17,801028009B
- 80ii200025 Forwards Power Sys Branch evaluation of differences labor Indian Point 2 & 3. in response to technical assistance request Requests meeting w/licenses prior to formal response to evaluation CHECK.P 8 Assistant Director for Plant Systems 80/10/21 NDVAK.T Assistant Director for Operating Reactors 21.pp 03743 111 24% Fiche 50-247.80/10/21.8011200025
- B210070007 Responds to FOIA request for eight categories of receff; steam generators & steam curbines App A documents provided in R Udell FOIA Request 81-313 Forwards documents listed in App B FELTON, J M Division of Rules and Records 82/08/10 10942 \$ J Winthrop, Stimson, Putnam & Roberts 9pp 15645 063 341 Fiche 50-000, 82/08/10, 8210070007
- 8210050452 Requests comments on draft Sandia "Ltr Rept on Review Evaluation of Indian Point Probabilistic Safety Study" by 821001 Meeting to discuss comments will be held approx 821013 W/o encl VAROA: 8 A Operating Reactors Branch I 82/07/15 61HC AIR Le Power Authority of the State of New York 2pp 15626 248 24t Fiche 50-284: 82/09/15,8210050452
- B210040400 Notification of 820921 meeting w/util in Bethessa. MD to discuss proposed repair program for steam generator shell THOMA. J D Operating Reactors Branch 1 82/09/16 VARGA B A Operating Reactors Branch 1 19 15597 228 24X Fiche: 50-286.82/09/16.8210040400
- 8210050534 Requests reply to 800923 request for addl infers GA program VARSALS A Operating Reactors Branch i B2/09/21 SIMLAIR to Power Authority of the State of New York Fiche 50-286,82/09/21.8210050534

- B210290203 Requests results of evaluations analyses & detailed description of any ongoing or planned insp & plans & schedule for repair to steem generator Results requested within 30 days of receipt of ltr EISENHUTLB C Division of Licensing 82/09/24 SINCLAIR, L W Power Authority of the State of New York 3pp 15876 244 24% Fiche 50-286.82/09/24,8210290203
- G2:0130063 Summary of 920921 meeting w/util, Westinghouse: C-E & BMI reproblems u/steam generator tubes Util proposed to sleeve degraded tubes by plug remaining tubes
 Viewgraphs encl
 H-DMA-J O Operating Reactors Branch 1 82/09/28 Operating
 Reactors Branch 1 80pp 15694 276 24X Fiche 50-286, 82/09/28,
- 621CO60181 Forwards responses to 820315 request for addl info, Items 1.
 2.3 & 8 re control of heavy loads, per 820421 commitment
 Responses to Items 5.6 & 7 & supplemental response to Item
 2 will be provided by 821130
 8AYME. J P Power Authority of the State of New York 82/09/30
 VARGA-S A Operating Reactors Branch 1 9pp 15614 111 24X
 Fiche 50-286.82/09/30.8210060181
- 6210120253 Forwards initial comments on Sandia Natl Labs 820825 preliminary draft lit rept on review & evaluation of probabilistic safety study, addressing wind, seismic, fire, pressurited thermal shock & fan cooler issues

 D'TOCLE, J D Consolidated Edison Co of New York BAYNE, J P Power Authority of the State of New York 82/10/06 VARQA, S A Operating Reactors Branch i 62pp 15652 215 24% Fiche 50-247,82/10/06, 8210320253
- 6210150031 Forwards addit payment required for 820604 application to amend tech Specs re mgt organization structure, per NRC B20714 ltr Addit payment made under protest pending final determination of legality of fee schedule BANKE, J.P. Power Authority of the State of New York 62/10/08 MILLER, U.O. License Fee Management Branch Spp. 15701 265 24% Fache 50-000, 82/10/08, 8210150031
- 0210190728 Forwards info re NUREO-0737. Item II B 3. "Post-Accident Sampling Sys." per NRC 820630 ltr SANME.J P Power Authority of the State of New York 82/10/12 VARCA-S A Deprating Reactors Branch 1 2pp 15736 272 24X Fiche 50-286.82/10/12.8210190728
- --8210190734 "Response to 820630 NRC Info Request Concerning Post-Accadent Sampling" * Power Authority of the State of New York 82/10/31 24pp 15736 274 24% Fiche 50-286,82/10/12,8210190728
- E210220455 Forwards request for addl info re THI Item II K 3 25.
 Power to Purp Seals " Areas of conformance & deviation
 From stated position should be identified & info re design &
 Operation of affected cooling sys provided
 VARCA.5 A Operating Reactors Branch I 82/10/15 SINCLAIR.L.W
 Power Authority of the State of New York 3pp 15786 211 24X
 Fiche 50-286.82/10/15.8210220455
- E210210459 Forwards application to amend License DPR-64 & proposed Tech Spec changes re steam generator surveillance requirements

 BAYNE.J P Power Authority of the State of New York B2/10/18

 VARCA.S A Operating Reactors Branch 1 2pp 15762 236 24X

 Fichs 50-286.82/10/18.8210210459
- ---B2iD2iO470 Application to amend License DPR-64 changing Tech Specs re steam generator surveillance requirements BAYNE.J P Power Authority of the State of New York 82/10/18 2pp 15762 238 24X Fiche 50-286.82/10/18,8210210459
- --8210210473 Proposed Tech Spec changes re steam generator surveillance requirements + Power Authority of the State of New York 82/10/18 16pp 15762 240 24X Fiche 50-286,82/10/18.8210210459
- 8210250070 Forwards response to NRC 820924 request for info re girth weld repair program with the State of New York 82/10/25 EISENHUT. D Q Division of Licensing Sipp 15845 095 24X Fiche 50-286,82/10/29,8210280070
- @ Inspection reports. IE Bullatins & correspondence
- B210070007 Responds to FOIA request for eight categories of records resteam generators & steam turbines App A documents provided in R Udeli FOIA Request 81-313 Forwards documents listed in App B FELTON, J M Division of Rules and Records 82/08/10 LONG, D. J Winthrop, Stimson, Putnam & Roberts 9pp 15645 063 24X Fache 50-000, 82/08/10, 8210070007

- --8210070139 Forwards tabulated data on steam generator insp & maint at facilities Data should be provided to licensees IPPOLITO.T Operating Reactors Assessment Branch 82/04/01 VARGA:8 Operating Reactors Branch 1 5pp 15648 131 24X Fiche 50-000,82/08/10:8210070007
- 8210070214 Forwards IE Insp Rept 50-286/82-16 on 820816-0915 No nancompliance noted STAROSTECKI, R Division of Project & Resident Programs 82/09/23, BRONS, J C Power Authority of the State of New York 2pp 15634 246 24x Fiche 50-286,82/09/23,8210070214
- ~-82(0070216 IE Insp Rept 50-286/82-16 on 820816-0915 No noncompliance noted Major areas inspected plant operations, plant tour, surveillance, maint, purging & venting of containment, test & measurement equipment program
 FOLEY, T. KENNY, T. J. KISTER, H. Division of Project & Resident Programs 82/09/22 10pp 15634 248 24X Fiche 50-286,82/09/23,8210070214
- 8210290203 Requests results of evaluations, analyses & detailed description of any ongoing or planned insp & plans & schedule for repair to steam generator Results requested within 30 days of receipt of ltm.
 EISENHUT, D 0 Division of Licensing 82/09/24 SINCLAIR, L W Power Authority of the State of New York. 3pp 15876 244 24X Fiche 50-286,82/09/24,8210290203
- 8208190233 IE Info Notice 80-35, Suppl 1, "Leaking & Dislodged I-128 Implant Beeds " Svc list encl COBB, L I Division of Fuel Facilities, Materials & Bafeguards 82/10/06 Consolidated Edison Co of New York 66pp 13761 250 24X Fiche 50-000, 82/10/06, 8208190233
- 8208190238 IE Bulletin 82-03. "Stress Corrosion Cracking in Thick-Wall, Large-Diamster, Stainless Steel, Recirculation Sys Piping at BMR Plants " Svc list encl DEYDUNG.R C Director's Office. Office of Inspection and Enforcement 82/10/14 Consolidated Edison Co of New York 115pp 15810 125 24X Fiche 80-000, 82/10/14, 8208190238
- R Periodic operating reports & related correspondence
- 8210180088 Forwards monthly operating rept for Sept 1982 BRONSIJC Power Authority of the State of New York 82/09/12 Management Information Branch 1p 15719 340 24X Fiche.50-286:82/09/12:8210180088
- --82:0180071 Monthly operating mept for Sept 1982 AUTERING.L Power Authority of the State of New York 82/10/01 6pp. 15719 341 24X Fiche 50-286:82/09/12,82:0180088
- S Reportable occurrences, LERs & related correspondence
- 8210270267 Part 21 deficiency rept re potential gelling problem between stem & bonnet of 1 25-inch & larger A105 carbon steel & A182-F22 valves supplied Feb 1781-Aug 1782 Valves should be serviced & stem &/or bonnet replaced ISABELLE.L.D. Conval. Inc 82/10/11 HAYNEB.R.C. Region 1. Office of Director 17pp. 15854 232 24X Fiche 50-000,82/10/11. 8210290267.
- T Hearing transcripts on non-antitrust matters
- 8210040232 Testimony of JD D'Toole before UB House of Representatives Bubcommittee on Energy & Conservation of Committee on Energy & Conservation of Committee on Energy & Commerce re role of public participation in NRC proceedings H/Certificate of Byc Related correspondence.

 D'TOOLE, J D Consolidated Edison Co of New York 82/10/01 21pp 15621.204 24X Fiche 80-247.82/10/01.8210060232
- DOCKET BO-287 GCONEE NUCLEAR STATION, UNIT 3

 F Security, medical, emergency & fire protection plans
- 82(0010352 Forwards revision to safeguards contingency plan Revision withheld (ref 100FR73 21)
 TUCKER, H B Duke Power Co 82/09/17, DENTON, H R Office of Nuclear Reactor Regulation, Director 1p 15574,139 24X
 Fiche \$0-269,82/09/17,8210010352
- 8210260529 Agrees w/determination to locate fire hose stations outside affected fire areas Change from earlier commitment acceptable STGLZ:JF Operating Reactors Branch 4 82/09/23 TUCKER, H. B Duke Power Co 2pp 15830.189. 24X Fiche 50-269, 82/09/23, 8210260529

- 8210040232 Application to amend Licenses DPR-39.DPR-47 & DPR-55 Amend requests deletion of Tech Spec 6 4 2 re site emergency drill & definition of time within which redundant component test must be performed prior to performing maint per Tech Spec TUCKER.H B Dute Power Co 82/09/27 DENIGN.H R Dffice of Nuclear Reaction Regulation. Director 3pp 15586-104 24X Fiche 50-269.62/09/27,8210040232
- --8210040245 Proposed revision to Tech Spec Pages 3 3-6 & 6 4-1 re site emergency drill & time period within which redundant component test must be performed prior to performing maint a Duke Power Co 82/09/27 4pp 15586 107 24X Fiche 50-269:82/09/27.8210040232

P Operating license stage documents & correspondence

- B210080036 Responds to FOIA request for documents re pins designed to hold neutron shielding pads in place under accident conditions Forwards documents listed on App A FELTON.J H Division of Rules and Records B2/08/13 EDDLEMAN.W Public Interest Research Group in North Carolina 2pp 15669 240 24K Fichs 50-287.B2/08/13.B210080036
- ~-8210080047 Discusses work items to be accomplished after 820423 shutdown for extended refueling outage Lower thermal shield bolts will be replaced w/Income! X-730 studs & not assembly Unit 3 scheduled to return to operation on 820915 MAGNER.P C Operating Reactors Branch 4 82/06/15 DENTON.H R. CARTER.J. EISENHUT.D 9 NRC No Detailed Affiliation Given ip 15669 283 24X Fiche 50-000.82/08/13.8210080036
- B210040107 Advises that util response to NRC B20218 ltr will be provided by B2100B. Receipt of info from crane vendor & extraordinary analytical work have delayed response TUCKER, H B. Duke Power Co B2/09/24 DENTON, H R Office of Nuclear Reactor Regulation. Director STOLZ, J F Operating Reactors Branch 4 1p 15581 024 24X Fiche 50-269,82/09/24,8210040107
- 8210040232 Application to amend Licenses DPR-38.DPR-47 % DPR-55 Amend requests deletion of Tech Spec 6 4 2 re site emergency drill & definition of time within which redundant component test must be performed prior to performing maint per Tech Spec TUCKER.H B Duke Power Co 82/09/27 DENTON.H R Office of Nuclear Reactor Regulation. Director 57012.7.J F Operating Reactors Branch 4 3pp. 15586:104 24X Fiche 50-269.82/09/27.8210040232
- --8210040245 Proposed revision to Yech Spec Pages 3 3-6 & 6 4-1 re site emergency drill & time period within which redundant component test must be performed prior to performing maint. a Duke Power Co 82/09/27 4pp 15586 107 24X Fishe 50-249,82/09/27,8210040232
- 8210190145 Forwards Amends 113,113 & 110 to Licenses DPR-38,DPR-47 & DPR-55,respectively,safety evaluation & notice of assuance to availability Amends revise Tech Spacs to allow full power operation of Unit 3 during Fuel Cycle 7 (MAGNER,P C Operating Reactors Branch 4 82/09/29 TUCKER,H B Dute Power Co. 2pp 15757 341. 24X Fiche 50-269,82/09/29. 8210190145
- ---8210190154 Amends t13, i13 % 110 to Licenses DFR-38, DFR-47 % DPR-55, respectively, revising Tech Specs to allow full power operation of Unit 3 during Fuel Cycle 7 STOLZ, J F Operating Reactors Branch 4 82/09/29 Sipp 15757 343 24% Fiche: 50-269, 82/09/29, 8210190145
- --8210190161 Bafety evaluation supporting Amends 113,113 & 110 to Licenses DPR-38, DPR-47 & DPR-55, respectively + Defice of Nuclear Reactor Regulation, Director 82/09/29 App 15758 012. 24X Ficha 50-269,82/09/29,8210190145
- --8210190169 Notice of issuance & availability of Amends 113,113 & 110 to Licenses DPR-3B, DPR-47 & DPR-55, respectively STGLZ, J F. Operating Reactors Brench 4 82/09/29, 2pp 13738 OIE. 24X Fiche. 50-269, 82/09/29, 8210190145.
- B210210292 Advises that review of info on mods to emergency feedwater sys & repairs made to once-through steam generators complete. Plant may resume operation w/listed conditions LAINAB. O C Assistant Director for Operating Reactors B2/09/29. TUCKER. H. B Duke Power Co 3pp 15774: 347. 24X Fiche. 30-287. 82/09/29. B210210292
- --8210210299 Safety evaluation supporting steam generator repair & energency feedwater sys mods # 04fice of Nuclear Reactor Regulation, Director, 82/09/29, 7pp. 15774: 350. 24X Fiche, 50-287, 82/09/29, 8210210292.

8210180323 Responds to 820913 ltr re reactor bldg purge sús Positica given in 810707 & 17 ltrs remains unchanged Schedule for submitting info indicating purge sus meets operability requirements requested LAINAS, G C Assistant Director for Operating Reactors B2/C9/X TUCKER, H B Dute Power Co 3pp 15745 334 24X Fiche 50-269, 82/09/30.8210180323

1

- B210150519 Discusses NRR actions taken under Task Interface Agriss' B2-20 for steam generator autiliary feedwater header danage Licensee authorized to resume power operation at Oconee 3 EISENHUT, D O Division of Licensing B2/10/06 DLSHINGAL J Division of Engineering & Technical Programs ip 15717 261 24 Fiche 30-000, B2/10/06, B210150519
- --821015052B Forwards safety evaluation relonce-through steam gavery repair & emergency feedwater sys mod Licenses authorized to resume power operation LAINAS. G.C. Assistant Director for Operating Reactors 02/45.3 TUCKER. H.B. Duke Power Co. 2pp. 15717-262-24X Fiche 50-000. B2/10/06.8210150519
- --8210150535 Safety evaluation supporting resumption of power operation following once-through steam generator repair & emergency feeduator sy mods
 WAGNER, P. C., HAPIZ. A., RIDOELY, J. Assistant Director for Operations
- 8210130502 Advises that flow demonstration & water hammer tests.jer NRC 820929 itr.confirm that modified auxiliary feedwater sys satisfactory Sys supplies required amount of feedwater w/no evidence of water hammer phenomenon TUCKER.H B Dute Power Co 82/10/07 DENTON.H R (Iffice of Nuclear Reactor Regulation, Director STOLZ.J F Operating Rest Dranch 4 1p 15482 252 24% Fiche 50-287.82/10/07.021013057
- B210180055 Responds to NRC 820608 request for add1 info re adeq.acpr station electric distribution sys voltages Requested info expected by B21022 TUCKER.H B Dute Power Co B2/10/08 DENTON.H R (Iffice of Nuclear Reactor Regulation, Director STOLZ.J F Operating Fer' Branch 4 1p 15720 010 24% Fiche 50-269.82/10/08.0210160555
- --B210180060 Forwards partial response to Franklin Research Ctr 4's technical evaluation rept re control of heavy loads, per NUREG-0612 TUCKER, H B Duke Power Co 82/10/08 DENYON, H R Office of Nuclear Reactor Regulation, Director BTOLZ, J F Operating Reactors Branch 4 Spp 15720 011 24X Fiche 50-269, BJ/10 (6 8210180055
- 8210210131 Responds to NRC 820908 ltr transmitting technical w.al., rept on emergency feedwater sys Sys may not meet all current criteria for seismic qualification but will remain functionally operable during OBE TUCKER.H B Duke Power Co B2/10/13 DENYON.H R Office of Nuclear Reactor Regulation, Director STOLZ.JF Operators Fig. Branch 4 App 15766 356 24X Fiche 50-269.82/10/13.82102101
- 8210210407 Application to amend DLs.revising Tech Spec 3 i allowing full power operation of Unit 1 for interim period until appropriate safety valve ring settings can be implemented TUCKER. H B. Duke Power Co. 82/10/14 DENTON: R Office of Nuclear Reactor Regulation, Director STOLZ, J F. Operating January Branch 4. Spp. 15764-038 24X Fiche 50-269,82/10/14.821021081
- --B210210411 Proposed revision to Tech Spec 3 1 allowing full past operation of Unit 1 for interim period until appropriate safety valve ring setting can be implemented 4 Duke Power Co. B2/10/14 1p 15764 04B 24% Fiche: 50-269, B2/10/14, B210210407
- O Inspection reports, IE Bulletins & correspondence
- B210070007 Responds to FOIA request for eight categories of extensists steam generators & steam turbines App A documents provided in R Udell FOIA Request Bi-313 Forwards documents listed in App B.
 FELTON, J M Division of Rules and Records. 82/08/50 tCRR.0 J Winthrop. Stimson, Putnam & Roberts 9pp 15645 063 24% Fiche: 50-000. 82/08/10. 8210070007
- --8210070172 Forwards info re steam generator integrity & IRSPS SEL operating PWRs.per 750320 & 21 requests Details of insp. including defect indications, tube plugging criteria & tybes plugged will not be provided except for Point Beach 1 OOLLER: K.R. Division of Reactor Licensing (NRR-1975 enly) 75/03/24, MACCARY.R. Division of Technical Review (RRR-1875 only) 5pp. 15645 196, 24X Fiche 50-000,82/08/10.9210070307

- O150369 Forwards results of investigation of Item 7a of IE Inspiepts 50-269/82-21, 50-270/82-21 & 50-289/82-21 Deadtine alues for gamma spectroscopy analyses of waste gas silver colite cartridges will cause only insignificant errors UCHER.H B Dute Power Co 82/08/17 D'REILLY, J P Region 2. IEF:se of Director 2pp 19704 269 24% Fiche 50-269,82/08/17. 12/0150369
- O010117 Forwards IE Insp Repts 50-269/82-33.50-270/82-33 & iD-287/82-33 on 820817-20 No noncompliance noted lance. H C Division of Project & Resident Programs 82/09/02 UCKER.il D Duke Power Co 2pp 15546 019 24X tche 50-269, 82/09/02, 8210010117
- *210010124 IE Insp Repts 50-269/82-33.50-270/82-33 & 50-287/8R-33 on 820817-20 No noncompliance noted Major areas inspected action on previous enforcement matters, auxiliary feedwater header repair & inservice insp procedures CROWLEY, B R , BLAKE, J J Division of Engineering & Technical Programs 82/09/01 8pp 15564 021 24X Fiche 50-269,82/09/02,8210010117
- O010158 Forwards 1E Insp Repts 50-269/82-30, 50-270/82-30 & 10-287/82-30 on 820716-0810 No noncompliance noted PARCE.H C Division of Project & Resident Programs 82/09/02 UCKER.H B Dute Power Co 2pp 15567 258 24X iche 50-269, 82/09/02,8210010158
- *210010166 IE Insp Ropts 50-269/82-30,50-270/82-30 & 50-287/82-30 on 620716-0810 No noncompliance noted Major areas inspected operations, surveillance testing, maint, NUREG-0737 mods & refueling activities GROERS.W. FALCONER.D. BRYANT.J C Division of Project & Resident Programs 82/09/02 13pp 15567 260 24X Fiche 50-269,82/09/02,8210010158
- CO10498 Ack receipt of 820805 ltr informing NRC of steps taken to older violations noted in IE Insp Repts 50-269/82-23, >0-270/82-23 EMIS.R C Division of Project & Resident Programs 82/09/17 IUCKER.H B Duke Power Co ip 15570 182 24X Take 50-249.82/09/17.8210010458
- 3210010463 Responds to NRC 820712 ltr re violations noted in IE Insp Repts 50-269/82-23.50-270/82-23 & 50-287/82-23 Corrective actions personnel counseled & valve 2HP-14 cut out & properly reinstalled TUCKER.H B Duke Power Ca 82/08/05 O'REILLY, J P Region 2. Office of Director 4pp 15570 183 24X Fiche 50-269.82/09/17.6210010488
- 3210010468 Forwards IE Insp Repts 50-269/82-23.50-270/82-23 & 50-287/82-23 on 830510-0610 & notice of violation LEWIS.R C Division of Project & Resident Programs 82/07/12 FARKER, W O Duke Power Co 2pp 13570 187 24X Fiche 50-269.82/09/17.8210010458
- B210010474 IE Insp Repts 90-269/82-23,50-270/82-23 & 50-287/82-23 on 920510-0610 Noncompliance noted failure to follow procedures resulting in plant trip t inadequate procedure resulting in improper reassembly of safety-related valve URDERS.W., FALCONER.D., BRYANT.J.C. Division of Project & Resident Programs 82/07/09 12pp 15570 191 24X Fiche 50-269.82/09/17, 0210010488
- 10150253 Ferwards IE Insp Repts 50-269/82-32.80-270/82-32 & 50-267/82-32 on 620817-18 No noncompliance noted DANGE.H C Division of Project & Resident Programs 82/09/17 TUCKER.H B Duke Power Co 2pp 15703 267 24X Fiche 50-269.82/09/17.6210150253
- O210150263 IE Insp Repts 50-269/82-32,50-270/82-32 & 50-287/82-32 on 820817-19 No noncompliance noted Major areas inspected lab QC & review of radiochemistry procedures & records EVANS.C D. MONTOOMERY,D M. Division of Emergency Preparedness & Operational Support 82/09/15 Spp. 15703 269 24X Fiche 50-269,82/09/17,8210150253
- 10150131 Forwards IE Insp Repts 50-269/B2-35,50-270/B2-35 & 50-287/B2-35 on 820908-10 No noncompliance noted DANCE,H C Division of Project & Resident Programs 82/09/23 TUCKER,H B Duke Power Co, 2pp 15698 312, 24X Fiche 50-269, 82/09/23,8210150131

- 8210130290 Requests relief from inservice insp requirements
 (hydrostatic) of Section XI of ASME Boiler & Pressure Vessel
 Code
 TUCKER.H B Duke Power Co 82/10/04 DENTON.H R Office of
 Nuclear Reactor Regulation, Director BTOLZ.JF Operating Reactors
 Branch 4 20pp 15678 243 24X Fiche 50-269.82/10/04,8210130290
- 8208190233 IE Info Notice 80-35. Suppl 1. "Leaking & Dislodged I-125 Implant Seeds " Svc list ancl. COBB.L I Division of Fuel Facilities. Meterials & Safeguards B2/10/06 Consolidated Edison Co of New York 66pp 15761 250 24X Fiche 50-000.82/10/06.8208190233.
- 8210220426 Forwards Revision 5 to response to IE Bulletin 79-02, "Pipe Support Base Plate Designs Using Concrete Expansion Anchor Bolts"

 TUCKER-H B Duke Power Ca 82/10/08 O'REILLY, J P Region 2, Office of Director 24pp 15778 273 24X Fiche 50-269,82/10/08, 8210220426
- 8208190238 IE Bulletin 82-03, "Stress Corrosion Cracking in Thick-Wall, Large-Diameter, Stainless Steel, Recirculation SysPiping at BMR Plants " Svc list encl
 DEYGUNG, R C Director's Office, Office of Inspection and
 Enforcement 82/10/14 Consolidated Edison Co of New York
 115pp 15910 125 24X Fiche 50-000, 82/10/14, 8208190238
- R Pariadic operating reports & related correspondence
- 8210190544 Forwards monthly operating repts for Sept 1982 TUCKER.H B Duke Power Co 82/10/15 Director's Diffice of Inspection and Enforcement ip 18751 343 24X Fiche 50-269: 82/10/15, 8210190544
- --8210190552 Monthly operating repts for Sept 1982 REAVIS.J.A Duke Power Co 82/10/15 16pp 15751 344 24X Fiche 50-249,82/10/15,8210190544.
- 8 Reportable occurrences, LERs & related correspondence
- 8210120114 Advises of immediate need for imposing specific requirements re operational restrictions for Class IE 120-voltac vital instrument buses in operating plants MICHELSON.C Director's Office 80/07/15 DENTON.H R Office of Nuclear Reactor Regulation. Director 1p 15487-165 24X Fiche 50-000.80/07/15,8210120114
- 8210010008 Responds to FDIA request for 17 categories of documents renuclear reactor events & safety problems Forwards documents listed in App A FELTON, J H Division of Rules and Records 82/06/28 UDELL, R. A Critical Hass Energy Project 15pp 15727 005 24X Fiche 50-000, 82/06/28, 821001008
- 8210190447 PNO-11-82-108 on BR1010, increasing steam generator tube leakage indicated in 3A steam generator Reactor placed in hot shutdown. No abnormal radioactive releases identified IONATONISA. BRYANT, J. C. Region 2, Office of Director 82/10/12 ip 15740:169 24X Fiche 50-287.82/10/12,8210190447
- 8210190653 PNO-II-82-111 on 821014. Unit 2 shut down after determining that pressurizer code safety valve dasign flow could not be fully maintained if called upon Beven-day outage required to change valves Exemption requested for Unit 1 10NATONIS.A Region 2. Office of Director 82/10/14 2pp 24X Fichs. 50-287. 82/10/14, 8210190653.
- 8210190695 RO on B21014, Unit 2 core relief valves declared inoperable due to analysis prompted by B&W safety concern. Unit 3 valves were offsite undergoing ring adjustment Immediate shutdown of Unit 2 commenced.

 * Duke Power Co B2/10/14. Region 2. Office of Director. ip. 15736 200 24X Fiche: 50-270, 82/10/14, B210190695.
- 8210290308 Forwards LER 82-010/01T-0 Detailed event enalysis encl TUCKER. H B Duke Power Co 82/10/18 0'REILLY, J.P Region 2, Office of Director. 3pp 18853 018 24X Fiche. 50-287, 82/10/18, 8210270308
- --8210270313 LER 82-010/01T-0 on 821004, discovered that weekly boron waste storage tank boron sample not taken as scheduled, contrary to Tech Spac 4, 1 3 Caused by personnel not having access to posted schedule board Board replaced.

 PETTY, J C. Duke Power Co. 82/10/18, Region 2, Office of Director. ip. 15853 021 24X Fiche 50-287,82/10/18,8210270308

- DOCKET 50-289 THREE HILE ISLAND NUCLEAR STATION, UNIT 1
 F Security, medical, emergency & fire protection plans
- B210050491 Forwards exemption from annual emergency plan exercise requirements of 10CFR50.App E re level of govt participation STOLZ,JF Operating Reactors Branch 4 B2/09/14 HUK/LL,H D General Public Utilities ~ CPU Service Corp. 7pp 15626 291 24X Fiche 50-289,82/09/14.8210050491
- --B210030495 Exemption from annual emprgency plan requirements re level of govt participation in exercises EISENHUT,D Q Division of Licensing B2/09/14 General Public Utilities OPU Service Corp 4pp 15626 298 24X Fiche 50-289.82/09/14.8210050491
- 8210060228 Forwards revisions to fire hazards analysis rept & App R Section III 0 re safe shutdown evaluation HUKILL,H D General Public Utilities - CPU Service Corp 92/10/0 EISENNUT.D 0 Division of Licensing 2pp 15620 013, 24X Fiche 50-289, 82/10/01, 8210060228
- --8210060230 Revisions to fire hazards analysis rept & App R Section III O re safe shutdown evaluation • General Public Utilities - GPU Service Corp 82/10/01 32pp 15620 015 24X Fiche 50-289, 82/10/01.8210060228
- 821013024B Advises of dairy farm located approx 1 i miles east of TMI yielding fose commitment greater than six of seven present nik sampling stations Results of land census to be included in B30501 annual radiological environ operating rept HUKILL-H D Oeneral Public Utilities GPU Service Corp B2/10/04 HAYNES-R C Region 1. Office of Director 1s 15676 008 24X Fiche 50-289, 82/10/04, 8210130248
- 8210150202 Clarifies position re Artion 4 of IE Bulletin 79-21. "Temp Effects on Level Measurements "Inclusion of tables, curves or correction factors in emergency procedures will unnecessarily complicate procedures, HUKILL-H D General Public Utilities - GPU Service Corp 82/10/04 MAYNES, R C Region I, Office of Director 2pp 15701 334 24X Fiche: 50-289, 82/10/04, 8210150202
- E210130161 Responds to ASLAB Bli204 partial initial decision re alert & notification sys Siren sys for offsite alerting adequate, pending determination of compliance w/NREG-0654 & FEMA REP-1.

 KRIMM,R W Federal Emergency Hanagement Agency 82/10/06 GRIMES, B Division of Emergency Preparedness 5pp 15873 061, 24x Fiche 50-289, 82/10/06,8210130161
- 8210130320 Bubmits updated status rept on offsite emergency planning issues at facility Emergency preparedness brockures distributed Siren sys testing satisfactorily completed Communications drill held on quarterly basit KRIMM.R W Federal Emergency Management Agency 82/10/06 ORIMES. B K Division of Emergency Preparedness 2pp 15678.158 24X Fiche 50-289.82/10/06,8210130320

G Adjudicatory correspondence

- 6210070028 Board Notification 82-93 forwards RJ Hattson 620830 memoto DD Eisenhut notifying of results of Samiscale test on feed & bleed capability
 LAINAS-0. C Assistant Director for Operating Reactors 62/09/14
 Atomic Safety and Licensing Appeal Fanel 4pp 15645:317 24X
 Fiche 30-269.82/09/14,8210070028
- --9210070032 Requests all PHR licensing boards be informed of results of Semiscale feed & bleed test Unespected uncovery of core simulator occurred MATTSON.R.J. Division of Bystems Integration (post 811005). 82/08/30 EIBENRUT.D.J Division of Licensing 3pp. 15645-321 24X Fiche: 50-287, 82/09/14, 8210070028
- --8210070035 Recommends that board notification on Semiscale feed & blood experiments not be issued BASBETT.0 E Division of Accident Evaluation 82/08/23 SPEIG.T.P. Assistant Director for Reactor Safety 22pp 15645-324 24X Fiche: 50-289.82/09/14.8210070028.
- 8210010427 Memorandum & order granting licenses request to refer Aemodt 820903 motion to reopen evidentiery record to ASLAB AELAB lacks jurisfiction over subj matter 8MITH I.H. Atomic Batety and Licensing Board Penel 82/09/29 Metropolitan Edison Co. 8pp. 15369:355. 24X Fiche 50-289.82/09/29.

- 8210050176 Brief in support of exceptions to ASLB 810827 & 820727 partial initial decisions re mpt issues & reopened proceedings BRADFORDL , DORDSHOW, J Three Hile Island Alert 82/09/30 Atomic Safety and Licensing Appeal Panel 93pp 15404-025 Fichs 50-289, 82/09/30, 8210050176
- 6210050192 Brief on exceptions to ABLB B10827 & 820727 partial inhibital decisions on mgt issues training & integrity Certificate of Svc end AMDDT: M M Amodts. The 82/09/30 Atomic Safety and Licent. Appeal Panel 36pp 15609 256 24X Fiche 50-289,82/09/30, B210050192
- B210050237 Advises that TMI Alert unable to present full discussion is some issues in brief due to severe time constraints.

 BRADFORD, t. Three Hile Island Alert 82/09/30 EDLEB, Q J Aits, C Safety and Licensing Appeal Panel BUCK, J H , KOHL, C Alemic Sefer, and Licensing Board Panel 1p 15609 051 24X

 Fiche, 50-289, 82/09/30, 8210050237
- S210060210 Brief supporting UCS brief on exceptions to ASIB 820/27 partial initial decision ASIB cannot continue to rely on operator judgment, understanding & integrity to compensate for lack of reliable equipment Certificate of Svc sncl WEISS.E R Hetropolitan Edison Co WEISS.E R Harnon & Weiss 82/09/30 Atomic Safety and Licensing Appeal Panel 3659 15614 121 24X Fiche 50-289, 82/09/30, 8210060210
- 8210060218 Brief in support of exceptions to ASLB 820727 partial initial decision on reopened proceeding on operator cheating Centificate of Svc enc!
 ADLER,R H Pennsylvania, State of 82/09/30 Atomic Cafety **4
 Licensing Appeal Panel 45pp 15614 243 24X Fiche 50-289,
 82/09/30, 8210060218
- 6210070194 Forwards THI training program assessment, representing recent view of program & covering hearing topics GPU has made significant progress Recommendation for changes made M/o rept Svc list encl
 BLAKE, E. Bader, Pittman: Potts & Trowbridge BLAKE, L. I.
 Metropolitan Edison Co B2/10/05 EDLES, G J , BUCK, J H , FG.R. C s
 Atomic Bafety and Licensing Appeal Panel 4pp 19534 274 244
 Fiche 50-289, 82/10/05.8210070194
- 8210070143 Order scheduling 821107 hearings in Harrisburg.PA (peaks) will hear parties re ASLB 611214 & 820727 partial initial decisions & will hold public meeting on restart CHICK.8 J Office of the Secretary of the Commission (12/10/05) 3pp 15627 077 24X Fiche 50-289.82/10/06.8210070143
- 8210080094 Forwards licensee first annual progress rept on invisition of exact replica simulator Bid package delayed from Apr to Sept.1982 Installation expected in 1985 Svc list encl BLAKE, E. L. Shaw Pittman, Potts & Troubridge BIAME, t Matropolitan Edison Co. 82/10/06 EDLES, G. J. BUCK, J. H. NOIR Ct Atomic Safety and Licensing Appeal Panel 7pp 15640 277 2+1 Fiche 50-289, 82/10/06,8210080094
- 8210120274 Responds to 820914 Board Notification BH-02-93 re tests on feed & bleed & motion that ASLAB direct NRC to provide pertinent documentation UCB Exceptions 7-11,16,10-19 & 107 should be sustained W/Certificate of Bvc POLLARD, R. D. , WEISB, E. R. Union of Concerned Scientists Agic, ft Harmon & Weiss 82/10/07 Atomic Safety and Licensing Appending Panel 17pp 15652 297 24% Fiche 50-209,82/10/07,022012027%
- 9210130275 Advises that ltr-designated Individual O resigned water S21015 Individual O was NRC licensed control room operator whose performance on tests & exams was issue in reopened phase of proceeding Svc list enc!
 BLAKE, E.L. Shaw Pittman, Potts & Trowbridge BLAKE, E.|
 Metropolitan Edison Co. 82/10/07, EDLES, O.J., DUCK, J. 18, AC.-4, [4 Atomic Bafety and Licensing Appeel Panel Spp 15578 152 241
 Fisher 30-287, 82/10/07, 8210130275
- 8210120256 Forwards Commission 821006 order scheduling 821107 hearty in Harrisburg, PA, in response to 811216 request BICKHIT, L. Office of the General Counsel 82/10/08 1081 heart Stand Public Interest Resource Center 1p. 15692 Rig 217 Fiche 50-289, 82/10/08,8210120256
- 8210120314 Forwards Commission 821006 order advising of 821109 past to meeting in Harrisburg.PA BICKWIT.L. Diffice of the General Counsel 82/10/00 Mithick, JE Dauphin County, PA ip 15651 251 24X Fiche.50-289.82/10/08. 8210120314.
- 8210130288 Requests to make limited appearance statement at Computer B21109 meeting in Harrisburg.PA re lifting of immediate effectiveness orders HOFFHAN, J C Friends & Family of TMI. 82/10/08 CHILK.8 J CHI

- 8230210359 Motion to file brief supporting exceptions to ASLB 810807 & 820727 partial initial decisions out of time on 821002 Circumstances beyond intervenor control necessitate extension Certificate of Svc encl AAMODT, M M Asmodts, The 82/10/09 Atomic Safety and Licensing Appeal Panel 4pp 15763 342 24X Fiche 50-289,82/10/09, 8210210359.
- 8210180160 Advises that ltr-designated Individuals () & VV will not respond to UCS. Commonwealth of PA:TMI Alert & Aamodts briefs supporting exceptions TMI Alert Exceptions 23 & 24 & Aamodt Exception 133 waived V010T.H H Lepoeuf, Lamb, Leiby & MacRae 82/10/13 EDLES, O J . BUCK.J H . KOHL.C N Atomic Safety and Licensing Appeal Panel 15719 169 24% Ficho 50-289:82/10/13/8210180160
- 8210180180 Memorandum & Order CLI-82-31 directing IE to determine whether civil penalty proceeding should be instituted against licensee for acts uncovered in hearing & Off of Investigations to investigate alleged metl false statement CHILK.8 J Office of the Secretary of the Commission 82/10/14 10pp 15719 135 24X Fiche 50-289.82/10/14.8210180180
- 8210200033 Advises that licensee will file one consolidated brief, on 831104, in response to Commonwealth of PA,TMI Alert, UCB & Aamodt briefs supporting appellant exceptions re mgt issues. Svc list encl
 BLAKE.E L. Shaw. Pittman. Potts & Troubridge BLAKE.E L. Metropolitan Edison Co. 82/10/14 EDLEB.O J. BUCK.J H., KOHL.C N. Atomic Safety and Licensing Appeal Panel App. 15757 304 24X Fiche 50-289, 82/10/14, 8210200033
- 8210200006 Order directing NRC to respond to UCS 821007 motion, characterized as response to Board Notification BN-82-93, that NRC provide all documents re semiscale test on feed & biesd capability
 SHOEMAKER.C.J Atomic Safety and Licensing Appeal Panel 82/10/15
 Office of the Executive Legal Director 3pp 15753,208 24X
 Fiche 50-289,82/10/13.8210200006
- 8210200011 Order extending time until 821022 for Commission to act to review ALAB-685 CHILK:8 J Office of the Secretary of the Commission 82/10/15 Commissioners 1p 15753 211 24X Fiche 50-289, 82/10/15, 8210200011.
- 8210210378 Advises that author will represent Commonwealth of PA at 821109 oral presentations before Commission. By: list encl ADLER.R W Pennsylvania. State of 82/10/18 CHILK.B J Office of the Secretary of the Commission. 3pp 15769 147 24X Fiche. 50-289. 82/10/18, 8210210378
- 8210260400 Advises that NO Aamodt will represent Aamodt family at 821109 oral presentations in Harrisburg, PA
 AAMODI, M M Aamodts, The 82/10/19 CHILK, 8 J. Office of the Secretary of the Commission ip 15803, 103 24X
 Fiche 50-289, 82/10/19, 8210260400
- 8210210374 Notifies that licensee will appear at 821107 public hearing to make presentation & respond to questions re restart Licensee expects to reserve portion of time for rebuttal of other presentations Svc list encl
 TROWBRIDGE.O F Shaw, Pittman, Potts & Trowbridge TROWBRIDGE.O F Hetropolitan Edison Co. 82/10/20, PALLADINO.N J . OILINSKY, V . AHEARKE, J F . Commissioners App. 15762 014 24X
 Fiche 30-289.82/10/20.8210210374
- 8210210493 Order establishing arrangements for 821109 meetings in Harrisburg:PA re restart CHILK, B.J. Office of the Secretary of the Commission. 82/10/20. 3pp 15762.259 24X Fiche:50-289,82/10/20,8210210493.
- 8210220445 Advises that JH Cutching, JR Qoldberg & JR Gray will represent NRC at oral argument on whether to lift immediately effective shutdown orders in view of ASLB 820727 & 811214 partial initial decisions.

 ORAY, J. R. Hearing Branch 4, 82/10/20 CHILK, 8 J Office of the Secretary of the Commission 1p. 15778 338 24X Fiche: 50-289, 82/10/20, 8210220445.
- 9210220465 Advises that author will represent UCB at 821107 oral argument Certificate of Svc encl HEISS, E. R. Union of Concerned Scientists. 82/10/20 PALLADINO, N. J., AHEARNE, J., GILINGKY, V. Commissioners 4pp 15779;121 24X Fichs: 50-289, 82/10/20, 82/10/20445.
- 8210250325 Forwards Commissioners TM Roberts & V Gilinsky corrected separate views on Order CLI-82-31
 STUCKY,S W. Docksting & Services Branch. 62/10/21 Office of the Executive Legal Director. 1p. 15790.077. 24X Fiche 50-289, 82/10/21,8210250325

- --8210250332 Corrected separate views of Commissioners TM Roberts & V Gilinsky on Order CLI-82-31 ROBERT8.T M , GILINSKY.V Commissioners 82/10/21 4pp 15790 078 24X Fiche 50-289, 82/10/21, 8210250325
- 8210260433 Decision ALAB-698 affirming ASLB decision not to require predistribution of permanent record dosimeters & modifying decision on emergency support director SHOEMAKER.C J. Atomic Safety and Licensing Appeal Panel 82/10/22 67pp 15805 328 24X Fiche 50-289.82/10/22.8210260433
- 8210260449 Decision ALAB-697 affirming ASLB decisions on emergency planning w/condition that Commonwealth of PA agricultural info brochure be given to farmers in 10-mile plume exposure smergency planning ione SHOEHAKER, C. J. Atomic Bafety and Licensing Appeal Panel 82/10/22 50pp 15807.054 24% Fiche 50-289:82/10/22,8210260449
- 8210260468 Order CLI-82-32 advising that ASLAB should not be concerned about current status of compliance w/restart requirements Proceeding should determine necessary actions to protect public & progress of long-term items CHILK.8 J Office of the Secretary of the Commission 82/10/22 Atomic Safety and Licensing Appeal Panel 4pp 15806 224 24% Fiche 50-289,82/10/22.8210260468
- B210270090 Response to ASLAB 821015 order UCS requests for relief in 821007 response to Board Notification BN-82-93 should be denied All documents NRC considers relevant & matl re Semiscale tests served on UCS RAWSON.R J Hearing Branch 4 82/10/25 10pp 15815 302 24X Fiche 30-289.82/10/25.8210270090
- --B210270099 Affidavit of BW Sheron & ML Jensen re Semiscale S-SR-2 results Test results do not raise significant safety issue, do not exhibit any new phenomena & can be adequately predicted by existing computer codes W/Certificate of Svc SHERON, 3 W , JENSEN, H L Reactor Systems Branch B2/10/25 43pp 15815 311 24X Fiche 50-269, 82/10/25, 82/10/20090
- 8210280250 Confirms 821025 telcon in which Docketing & Svc Branch agreed to add name to svc list, as counsel for itr-designated Individuals D & VV Related correspondence MCBRIDE.H F. LeBosuf, Lamb. Leiby & HacRae 82/10/25 Docketing & Services Branch ip 15837 050 24X Fiche 50-289,82/10/25,8210280250
- 8210280360 Reply opposing UCS 821007 response to Board Notification 82-93 re Semiscale tests of feed & bleed & motion that AGLB direct NRC to provide documentation Feed & bleed capacity not essential to operation W/Certificate of Svc BAXTER.T A Hetropolitan Edison Co BAXTER.T A Shaw, Pittman, Potts & Troubridge. 82/10/25 Atomic Safety and Licensing Board Panel 9pp 15845 146 24X Fiche.50-289,82/10/25.8210280360
- 8210280265 Order allocating time for presentation of oral arguments on immediate effectiveness of ASLB 820727 & 811214 partial initial decisions Issues to be discussed in detail 11sted CHILK:8 J Office of the Secretary of the Commission 82/10/27 2pp. 15837.312 24X Fiche 50-289.82/10/27.8210280265

1 1

- 1

- 6210070440 Responds to 820825 itr transmitting constituent JB Hurst 820810 inquiry re restart Changes made as result of reopened proceedings will satisfy conterns DIRCMS.W J Office of the Executive Director for Operations 82/09/16 SPECTER.A Senate 4pp 15649 224 24X Fiche \$0-289,82/09/16,8210070440
- --8208010016 Requests response to constituent JR Hurst 820810 inquiries re restart proceedings SPECTER.A Sanate 82/08/25 NRG No Detailed Affiliation Given App 15649 228 24X Fichs 50-289,62/09/16,8210070440
- 8210210501 Responds to constituent J Doroshou 820820 1tr re ASLD partial initial decision on cheating TMI Alert filed exceptions to decision & presented views on restart to Commission DIRCKS, W J Office of the Executive Director for Operations 82709727 SPECTER, A Senats 9pp 15782 266 24X Fiche 50-289, 82709729, 8210210301
- 8210250015 Responds to constituent J Doroshow 820820 ltr re ASLB 820727 partial initial decision Commission is now deciding restart issues DIRCKS, W J Office of the Elecutive Director for Operations 82/09/29 PROXMIRE, W Senate 7pp 15808 128 24X Fiche 50-289, 82/09/29, 8210250015
- 8210280236 Opines that questions re operator exam cheating must be thoroughly investigated DRADFORD. L. Three Hile Island Alert 82/10/25 PALLADINO.N.J. GILINSKY.V. AHEARNE.J.F. Commissioners 2pp 15837-062 24X Fiche 50-289

J Insurance & indemnity information

- R210150147 Forwards Endorsements 53 & 54 to MAELU Policy MF-73 & Endorsements 61 & 62 to NELIA Policy NF-220 GERETY.H F General Public Utilities 0PU Service Corp 82/10/07 SALTZMAHJ Antitrust & Economic analysis Branch (Utility Finance) 5pp 1567/359 24X Fiche 50-289.82/10/07.8210150147
- O Advisory Committee on Reactor Safeguards reports & correspondence
- 8210090015 Addl response to FOTA request for 19 categories of info re nuclear reactor events & safety problems Forwards documents listed in App A Documents in App B completely withheld (ref FOTA Exemption 5) FELTON, J M Division of Rules and Records 82/07/12 UDELL,R A Critical Mass Energy Project 9pp 15665 027 24% Fiche 50-000,82/07/12,8210080015
- --B2100B0051 Forwards General Public Utils 820407 News Release 45-82 discussing suspected cause of TMI-1 steam generator tube degradation problem & proposed repairs Repairs estimated to be completed by Uct 1982 MAJOR.R ACRE Advisory Committee on Reactor Safeguards 82/04/20 KOELLER.D W ACRE Advisory Committee on Reactor Safeguards 82/04/20 KOELLER.D W ACRE Advisory Committee on Reactor Safeguards 82100B0015
- #210270410 Summary of ACRS Subcommittee on Metal Components #20607 meeting in Palo Alto.CA re status of Steam Generator owners group program & TMI-1 steam generator problems & mods

 ACRS Advisory Committee on Reactor Bafeguards #2/08/11

 ACRS Advisory Committee on Reactor Safeguards #2/08/12

 244 Fiche 50-289, 82/08/11, 8210270410

license stage documents & correspondence

k safety evaluation re mode and to inadvertent 'Oss of mentation power MICHELSON, C Director's 81/07/04.8210080026

> ories of documents re inds documents

12/06/28 UDELL.R.A

ng re reactor water layed to to util quirements for

ICHELBON. C Director's

- --8109180478 Forwards safety evaluation re mod to correct inadvistriopening of atmospheric dump valves on DMR plants during loss of instrument control sys non-nuclear instrumentation power ORNSTEIN.H Director's Office 81/09/04 HICHELERN.C Director's Office 2pp 15730 230 24X Fiche 50-000, 82/06/61 8210010008
- 8210080015 Addl response to FOIA request for 19 categories of infair nuclear reactor events & safety problems Forwards documents (isted in App & Documents in App & completely withheld (ref FOIA Exemption 5)
 FELTON, J M Division of Rules and Records 82/07/12 UT414.R4
 Critical Mass Energy Project 9pp 15665-027 24X
 Fiche 50-000.82/07/12.8210080015
- --8204200438 Forwards std order for BDE work "Evaluation of TM1-16'.

 Generator Corrosion"

 VOLLMER, R. H. Division of Engineering. FIN D-2505 D2/04/3

 FREMLING, A O Energy, Dept of 2pp 15445, 137 24x

 Fiche 50-000, 82/07/12, 8210080015
- --8204200442 Btd order for DDE work: "Evaluation of THI 1 Squar &FC, Corrosian." issued to DANL. VOLLMER, R H Division of Engineering FIN D-2506 2 82/24: 4 1p 15665 138 24% Fichs 50-000, 82/07/12.8210000010
- --BP04290237 Discusses info available re unit steam generators Tail repts, status updates & notebooks of info on tube fabrication, identification & operating history encl H/d encl NGVAK-T H Assistant Director for Licensing 82/04/05 EISENHUT, D 0 Division of Licensing 2pp 15669 321 241 Fiche 50-000.82/07/12-8210080015
- --8205280533 Recommends formal review of facility steem gamerater corrosion problem. Detailed discussion of rationals for request and 1
 JOHNSTON,W V Assistant Director for Materials t Qualification, Engineering 82/05/19 NOVAN,T Assistant Director for Carrier Reactors Spp 15665-146 24X Fiche. 50-000, 82/07/12,8215.5...!
- --8206140329 Discusses facility steam generator tube review Meeting licensee to discuss details of procedures to be followed proposed NRC will develop complimentary independent program intended to verify repair process.

 NOVAK, T & Assistant Director for Operating Hearing & \$2.00.4 EIEENHUT, B O Division of Licensing 2pp 15665-157 248 Fichs 30-000,82/07/12,8210080015.
- --8210080091 Forwards and order for DDE work. "Evaluation as tal-j: Generator:" issued to BNNL Period of performance estantas to 821015 w/no addition to NRC VOLLHER, R. H. Division of Engineering. FIN 8-2506 \$2,724/4 FREMLING, A 0 Energy Dept. of. ip. 15466 150 34% Ficher 50-000,82/07/12,8210080015
- --8210080076 8td order for DDE work "Evaluation of TR1 1 Stead Congretor," issued to BNHL. VOLLMER, R. H. Division of Engineering. FIN 8-2508 7 M7 24.4 ip 15666.181. 24 Fiche: 50-000: 82/07/12, 8210090015
- 8210050506 Recommends approval of deferral of implementation Father MUREO-0737. Items II B G. II F i. 4 valid 830331 or before restart. Approval of Item II B R 2 about 60 withheld until review completion.

 DIRCKS.M J. Office of the Executive Director for Operations 82/09/16 7pp 15624 033. 24% Fiche 50-299:88/09/16.68:52,5-4
- --8210050536 Informs that package or facility restart is rease tap Commission for approval of change in NUREO-0737 false 18 boron precipitation problem affects conformance w/regulations/deferral amounts to exemption SCINTOL Office of the Executive Legal Director \$2709.74 EISENHUT,D. 9. Division of Licensing App. 15624 043 3a; Fiche: 50-289,82/09/16.8210050506

- --B207050040 Requests NUREO-0737 requirement deferrals be addressed as outlined in Commission B10325 order Paper discusses staff plans for certifying completion of restart requirements on SECY-82-250 & describes approach to be taken on NUREG-0737 PALLADINO.N J Commissioners B2/07/27 DIRCKS.W J Office of the Executive Director for Operations in Available at NRC nrc 15624 048 24% Fiche 50-287,82/09/16.8210030504
- 6210240503 Provides Commission w/status of implementation of NUREG-0737 requirements on IMI-1 Recommends deferral of implementation dates for NUREG-0737. Items II B 3.II F I 4.II F I 5 & II F I 6 until 83033 or before restart DIRCKS. W J Office of the Executive Director for Operations SECY-82-384 82/09/16 14pp 15782 283 24X Fiche 50-289, 82/09/16. 8210210503
- 82:0050113 Forwards outline of Phase I ventilation separation program to meet short-term intent of ASLB 811214 order Program completed & sys turned over to plant operations Further details discussed in restart rept, Suppl 1, Part 2
 HUKILL.H D General Public Utilities GPU Service Corp 82/09/29
 STOLZ.J F Operating Reactors Branch 4 4pp 19603 297 24X
 Fichs 50-289.82/09/29,8210030113
- 6210050196 Forwards table listing 96 emergency feedwater sys/instrument air valves as suppl to 820914 ltr Valves structurally & operationally adequate during SSE stresses & normal loads HUKILL.H D Oeneral Public Utilities GPU Service Corp 82/09/29 STOLZ.J F Operating Reactors Branch 4 2pp 15609 292 24X Fiche 50-289.82/09/29.8210050196
- 8210070372 Advises that util has contracted w/Electronic Associates.Inc for basic principles trainer Contracted date of delivery is Dec 1982 HUKILL.H D General Public Utilities - OPU Bervice Corp 82/09/29 STOLZ.J F Operating Reactors Branch 4 Ip 15633 317 24X Fiche 50-289.82/09/29.8210070372
- 8210120043 Notification of 821013-14 meeting w/PNL, GRNL, Franklin Research Ctr. OH State & util in Bethesda MD to review status of steam generator recovery program JACCBB, R H Operating Reactors Branch 4 82/09/29 870LZ, J F Operating Reactors Branch 4 2pp 15689 205 24X Fiche 50-289, 82/09/29, 8210120043
- 6210/30206 Forwards application to amend License DPR-50 consisting of Tech Spec Change Request iiB.deleting App B Tech Specs HUKILL.N D General Public Utilities - GPU Service Corp 82/09/30 STGLZ.J F Operating Reactors Branch 4 ip 15674 127 24X Fichs 50-229.82/09/30.82/0130206
- --8210130210 Application to amend License DPR-50 consisting of Tech Spec Change Request 11B deleting App D Tech Specs Justification and: HUKILL, H D General Public Utilities - OPU Service Corp 82/09/30 3pp 15474 128 24% Fiche 50-289, 82/09/30, 8210130204
- 9210060342 Forwards "Assessment of Selected TMI-1 Training Progrems,"
 Vol 1 Rept concludes that util has made significant progress
 in past 3 yrs to expand TMI training capability & to improve
 quality of training programs
 ARNOLD, R C General Public Utilities GPU Bervice Corp 82/10/01,
 DENTON, H R Office of Nuclear Reactor Regulation, Director 1p
 15618 020 24X Fiche 50-289,82/10/01,8210060342
- --8210060348 "Assessment of Selected TMI-1 Training Programs," Vol 1 * Data Design Laboratories 82/09/10 301pp 15618 021 24X Fiche 50-289,82/10/01.8210060342
- 8210080043 Forwards status rept re procurement & installation of replica simulator.per 620827 mgt piping & instrumentation diagrams Second status rept will be provided in Oct 1983 HUKILL.H D General Public Utilities GPU Service Corp 82/10/04 STOLZ-J F Operating Reactors Branch 4 3pp 15443 281 24X Ficha 50-289, 82/10/04,8210080043
- 8210080308 Forwards first status rept re procurement & installation of replica simulator for TMI-1.per requirements of Paragraph SB3 (5) of 810827 mgt PID Next status rept will be provided in Oct 1983 HUKILL. HD General Public Utilities OPU Service Corp 82/10/04, STOLZ:JF. Operating Reactors Branch 4 3pp 15638:044 24X Fiche 50-289, 82/10/04,8210080308
- 8210130248 Advises of dairy farm located approx i,1 miles east of TMI yielding dose commitment greater than six of seven present milk sampling stations Results of land census to be included in 830501 annual radiological environ operating rept HUKILL.H D General Public Utilities GPU Service Corp 82/10/04, HANNES.R C Region 1, Office of Director ip 15676 008 24X Fiche 50-289, 82/10/04,8210130248

- 8210130548 Forwards Revision 1 to "TMI-1 Steam Generator Repair Safety Evaluation," submitted on 820820 as suppl to LER 81-13 Revisions do not affect previous conclusions Revision withheld (ref 10CFR2 790) HUKILL,H D General Public Utilities 0PU Service Corp. 82/10/05 EISENNUT.D Q Division of Licensing ip 15484 195 24X Fiche 50-289, 82/10/05,8210130548
- B210290162 Notification of date change for B21018-19 meetings w/wbil & consultants in Bethesda. MD to discuss results of steam generator repair qualification program, eddy current testing program & RCB cleaning
 JACOBS.R H Operating Reactors Branch 4 82/10/05. BYOLZ, J F Operating Reactors Branch 4 1p 15876 227 24X
 Fiche 50-289, 82/10/05, 8210270162
- 8210270342 Clarifies request for add1 info re TMI Item II B 3. "Post-Accident Sampling Sys"

 STOLZ, J F Operating Reactors Branch 4. 82/10/07 HUKILL, H D
 Ceneral Public Utilities GPU Service Corp 5pp 15851 347. 24X
 Fich
- 8210220249 Staff requirements memo re 821006 briefing on status of certification of licensee compliance w/restart requirements CHILK: 9 J Office of the Secretary of the Commission 82/10/12 Office of the Secretary of the Commission 1p 15786 210 24X Fiche 50-289, 82/10/12, 8210220249
- 82:0250092 Forwards operational GA plan for facilities FIEDLER.P B General Public Utilities - GPU Service Corp 82/10/12 CRUTCHFIELD.D Operating Reactors Branch 5 2pp 15792 265 24X Fiche 50-000.82/10/12.8210250092
- --8210250097 Operational GA plan for facilities KAYANAS,N C , LOND,R L , HUXILL,H D Oeneral Public Utilities --GPU Bervice Corp 1000-PLN-7200 01 R00 82/09/01 150pp 15792 267 24X Fiche 50-000, 82/10/12.8210250092
- 8210270015 Forwards documents to be placed in PDR. Documents respond to NRDC & Sierra Club 820917 third request for production of documents & Sierra Club 27th set of interrogatories, SWEENEY, M F Office of the Executive Legal Director 82/10/22 SCOTT, 8 Document Management Branch 4pp, 15818 092 24X Fiche 50-000, 82/10/22,0210270015
- --8210270020 "Greater Commitment Needed to Bolve Continuing Problems at THI," rept to Congress

 * General Accounting Office, EMD-81-106 81/08/26 122pp
 13818-076 24X Fiche: 50-000, 82/10/22: 8210270015
- B210270204 Forwards summary status rept for items needing NRC certification prior to restart.per 770807 order & notice of hearing.Date of equivalent timing for verification will be provided in future status summaries

 ARNOLD,R C General Public Utilities -- GPU Service Corp 82/10/25

 DENTON.H R Office of Nuclear Reactor Regulation. Director 3pg 15853 273 24X Fichs 30-289, 82/10/25,8210270204
- Q Inspection reports. IE Bulletins & correspondence
- 8210080015 Add1 response to FOIA request for 19 categories of info re

- ~-8210150232 IE Insp Rept \$0-289/82-13 on 820802-05,31 & 0901-03
 No noncompliance noted Major areas inspected actions on
 previous insp findings, reactor bidg flood level limitations,
 plant shielding design review & restart mode-implementation
 HAVERNAMP,D., EAPEN,P., FABAND,A. Division of Project & Resident
 Programs 82/10/01 20pp 15705 214 24X Fiche 50-289,82/10/01,
 8210150221
- 6210150202 Clarifies position re Action 4 of IE Bulletin 77-21, "Temp Effects on Level Measurements" Inclusion of tables curves or correction factors in swargency procedures will unnecessarily complicate procedures
 HUKILL.H D General Public Utilities QPU Bervice Corp 82/10/04
 HAYNES.R.C Region 1, Office of Director 2pp 15701 334, 24X
 Fiche 50-289, 82/10/04,8210150202
- 8210150076 Notifies that 820929 IE Insp Rept 50-289/82-14 was submitted w/erroneous Insp Rept Number 82-12 STAROSTECKI.R Division of Project & Resident Programs 82/10/05 HVKILL.H D Openral Public Utilities GPU Service Corp 19696 339 24X Fiche, 50-289, 82/10/05, 8210150076
- --8210150083 Forwards IE Insp Rept 50-289/82-14 on 820807-0907 No noncompliance noted.
 STARGSTECKI: R Division of Project & Resident Programs 82/09/29 HUKILL: H D. Ceneral Public Utilities GPU Service Corp 2pp 18696 340 24X Fiche 50-289, 82/10/05-8210150076
- ~-8210180091 IE Insp Rept 50~289/82~14 on 820807~0907 No noncompliance noted Hajor areas inspected plant operation, including steam generator repairs & restart mods CONTE.R. YQUNO.F. FASANO.A Division of Project & Resident Programs 82/09/21 opp 15696 342 24X Fichs 50~289.82/10/05, 8210150076
- B210210052 Forwards IE Insp Rept 50-269/62-16 on B20907-10 No noncompliance noted MARTIN-T T Division of Engineering & Technical Programs B2/10/05 HUKILL-K D General Public Utilities - QPU Service Corp 15762 018 24% Fiche:50-289.82/10/05:8210210052
- --8210210056 IE Insp Rept 30-289/82-16 on 820907-10 No noncompliance noted Major areas inspected licensee action re IMI Item I C 7 on feedback of operating experience k Item I C 6 on verification of teeting k maint activities MEYER.0 W : CAPHTON.D.L Division of Engineering & Technical Programs 82/09/29 App 15762 020 24X Fiche: 50-289,82/10/05,8210210052
- 8208190233 IE lnfo Notice 80-35, Suppl 1, "Leaking & Dislodged 1-125 Implant Seeds," Syc list encl. COSS.L I Division of Fuel Facilities, Materials & Safeguards 92/10/06 Consolidated Edison Co of New York 66pp 15761, 250, 244 Fichs 50-000, 82/10/06, 8208190233
- 8208170238 IE Bulletin 82-03, "Strass Corrosion Cracking in Thick-Wall-Large-Diameter. Stainless Steel, Recirculation Sys Piping at BMR Plants "Syt list encl GEYOUNG:R C Biretton's Office of Inspection and Enforcement 82710714. Consolidated Edition Co of New York. 115pp 18810.125 24% Fiche 50-000, 82710714, 8208179029
- 8210290068 Forwards IE Insp Rept 50-287/82-18 on 820720-24 No noncompliance noted.

 MARTINIT T. Division of Engineering & Technical Programs. 82/19/15

 HUMILL, H D. General Public Utilities QPU Service Corp 2pp
 15853, 342. 24x Fiche 50-287, 82/10/15, 8210290068
- --8210270072 IE insp Rept 50-287/82-18 on 820920-24 No noncompliance noted Hajor areas inspected-licenses action on previous insp items: procedures & representative records & interviews U/personnel BHAUS.E. NAPUDA.Q. CAFHTON.D.L. Division of Engineering & Technical Programs 82/10/08 10pp 15953-344 244 Fiche 50-284,82/10/15.8210270068
- R Periodic operating reports & related correspondence
- 8210070007 Responds to FOIA request for eight categories of records resteam generators & steam turbines. App A documents provided in R Udell FOIA Request 8:-313. Forwards documents listed in App B FELTON, J M. Division of Rules and Records 82/08/10. LONG, D J. Winthrop, Stimson, Putnam & Roberts. 9pp 15645:063 24X Ficher 50-000, 82/08/10, 8210070007

- --8210070135 Sevil rept input re Ginna 820125 steam generator till rupture event NRC 16th monthly status rept to Congress re TMC-1 restart encl 4 NRC - No Detailed Affiliation Given 82/03/11 3pp 15645 128 24x Fiche 50-000, 82/08/10,8210070007
- 8210260499 Forwards Revision 1 to "Effluent & Waste Disposal Semiannual Rept. Jan-June 1982" Revision reflects change in Fe-55 batch mode for second quarter HUXILL.H D General Public Utilities - GPU Service Corp B2/In HAYNES R C Region I. Office of Director is 1880á 136 24; Fiche 50-289, 82/10/15,8210260499
- --B210260505 Revision 1 to "Effluent & Waste Disposal Semiannus) t_{r.}
 Jan-June 1782 "

 * General Public Utilities GPU Service Corp B2/10/15 [1]
 15804 137 24X Fiche 50-289, 82/10/15,8210260499
- 5 Reportable occurrences, LERs & related correspondence
- B210010008 Responds to FDIA request for 19 catagories of documents nuclear reactor events & safety problems Forwards documents listed in App 4.

 FELTON, J H Division of Rules and Records 82/06/20 U3E11.8, Chitical Mass Rergy Project 15pp 15727 003 24X

 Fichs 50-000.82/06/28,8210010008
- --BilliBOOO! Recommends comprehensive assessment of plant operations to determine specific predetermined time related sequences of occurrence to emergency buses ERP should be revised be design features.

 ASH6.F Director's Office. Bi/10/16 MICHELSON, C Direct.-Office 4pg 15731 047 24X Fiche 50-000.82/06/28.826000.
- 9210130515 Forwards LER 92-013/03L-0 MUKILL-H D General Public Utilities - GPU Service Corp 92.0 HAYMES.R C Region 1. Office of Director ip 15682 278 24 Fiche 50-289, 82/07/29,8210130315
- --8210130526 LER 82-013/03L-0 on B20B30, plant effluent radiation (RM-L-7) had no sample flow Caused by open breater on sample pump BR-P-4 Breaker closed Operator surveillance program continued to ensure proper flow STEPHENBON, C.J. Oeneral Public Utilities OPU Bervice Corp. B2/09/29 Region 1. Defice and Director 2pp 15602 277 Fiche. 50-289, 82/09/29, 8210130315
- B210070245 PND-THI-B2-020 on B21005, game peacher apprehended pt property & turned over to state police & Oame Commission No vital areas threatened Security increased Licanses will issue press release HIEBE, J. BELLAMY, R. Region 1. Office of Director B2/10/0, 15634 306 24% Fiche 50~289, 82/10/06, 8210070265
- 8210260483 PNO-1-82-047 on 821022, kinetic expansion conduct; \$ 21 rows of tubes in 8 once-through steam generator Espansion involves controlled detonation within tube 90mm media attention expected CONTE, R. KEIMIO, R.; BTARDSTECKI, R. Region 1. Diffice of 01/4 B2/10/22 1p. 15806 232 24X Fichs 50-289, 82/10/22, 821020
- T Hearing transcripts on non-antitrust matters
- 8210130075 Porwards Commission determination statement withhelf transcript of 820910 restart proceeding CHILKS J Office of the Secretary of the Commission. 82307 Public Document Branch ip 15696 250. 24X Fiche 50-209.E 8210130075
- ~-82(0/30087 Commission determination withholding transcript d Commission 820910 discussion of contested issues in restite proceeding CHILK, B J Office of the Secretary of the Commission B7 in 15696: 251 24% Fiche 50-289, 82/09/28, 8210430075
- 8210270188 Transcript of 821006 public meeting or status of placetification on licensee compliance w/restart requirement on THI-1 in Washington. DC./pl-34 Commissioners 82/10/06 34pp 15835 276 24x Fiche. 50-287, 82/10/06, 8210270188.
- 821021042B Forwards transcript of Commission 921014 meeting?

 vessel water level indicator program Comments should be submitted by 821101

 CHILK.8 J. Office of the Secretary of the Commission 62.9

 Office of the Executive Legal Director, ip. 15762 272 27

 Fiche. 50-287, 82/10/15, 8210210428

DOCKETED ITEMS

- E2[0210434 Transcript of 82[014 public meeting in Washington, Dc Pp I-9; Vieugraphs re request for NRC approval of recommendations for implementation of NUREG-0737, Item II F 2 encl

 * Commissioners 82/10/14 91pp 15762 273 24X
 Fiche 50-269,82/10/15 82[02[0428
- 1 TINU WOLTERS REMOVE AND WINDLIS EGS-05 TEVE 2
- P Operating license stage documents > correspondence
- E-1008C015 Add1 response to FOIA request for 19 categories of info re nuclear reactor events & sarety problems Forwards documents listed in App A Documents in App B completely withheld (ref FOIA Exemption 5) FELTON J M Division of Rules and Records 82/07/12 UDELL R A Critical Mass Energy Project 9pp 15665 027 24X Fiche 50-000 82/07/12.8210080015
 - E203290028 Forwards "Engineering Evaluation of Salt Svc Water Sys Flow Blockage at Pilgrim Noclear Power Station by Blue Mussels (Mythius Edilus) "Further recommendations re sys fouling by aquatic organisms not needed IMBRO.E V Director's Office 82/03/18 MICHELSON, C Director's Office 2pp 15666-073 24% Fiche 50-000.82/07/12.8210080015
- --8203290031 Engineering Evaluation of Salt Syc Water Sys Flow Blockage at Pilgrim Nuclear Power Station by Blue Mussels (Mytilus Editus) "
 IMBRO. E (*) Director's Office 82/03/31 14pp 15666 075 24X
 Fiche 50-000.82/07/12.8210080015
- --8205:30:114 Advises that engineering evaluation of saltwater sys flow blockage by blue mussels indicates surveillance requirements in Tech Specs are not sufficient to demonstrate sys aperability "IICHELSONIC Director's Office 82/05/06 DENTONIH R Office of Nuclear Reactor Regulation, Director 3pp 15666-070 24X Fiche 50-000,82/07/12.8210080015
- PGLIVOACOBO Application for Proposed Change 82-11 to License DPR-35, changing Fech Specs 3 7 D 1 & 3 7 D 2 to permit operation in A between reactor modes when isolation valve is inoperable MARRIMGTON W D Boston Edison Co 82/09/30 VASSALLO, D B Operating Reactors Branch 2 2pp 15615 044 24X Fiche 50 -293, 82/09/30, 82/006080
- --0210060005 Proposed changes to Tech Specs 3 7 D 1 & 3 7 D 2 allowing aperation in & between reactor mode when isolation valve is inoperable & satisfying conditions for primary containment integrity

 9 Buston Edison Co 82/09/30 ip 15615 046 24X
 Fiche 50-293.82/09/30,8210060080
- GE10150444 Requests extension to submit Mark I containment program plant-unique analysis Delay due to need for extensive GA verification not previously identified by Teledyne Corp PORISI.A V Boston Edison Co 82/10/03 VASSALLO, D D Operating Reactors Branch 2 lp 15705 005 24X Fiche 50-293, 82/10/08, 82/10/50444
- 6210220015 Concurs w/LLL evaluation of util 820617 submittal redegraded protection for Class IE power sys Mods.procedures, operating restrictions & voltage schedules will ensure that Class IE equipment will not be exposed to degraded voltage vASSALLO.D B Operating Reactors Branch 2 82/10/08 MORISI.A V Soston Eduson Co 2pp 15786 226 24X Fithe 50-293,82/10/08,82:0220015
- --B2IOZZOO17 Safety evaluation supporting licensee conclusion that add1 protection not required for unit auxiliary transformer power source to Class IE buses PREVATTE.R Operating Reactors Branch 2 82/10/08 4pp 15786 228 24% Fiche 50-293,82/10/08,8210220015
- --B209130461 "Technical Evaluation Rept (Revision i) on Proposed Design Mods 5 Tech Spec Changes on Orid Voltage Degradation for Prigrim Nurlear Power Station, Unit i "

 SELAN-J C Lawrence Livermore Laboratory FIN A-0250 UCID-18689 RO1 B2/08/20 NRC No Detailed Affiliation given 13pp 15786 232 24% Fiche 50-293, 82/10/08,8210220015
- 8210250085 Forwards filing fee for 820930 proposed Tech Spec Change 82-11
 MORIGI, A V Boston Edison Co 82/10/15 VABSALLO,D B Operating Reactors Brench 2 1p 15787 075 24X Fiche 50-293,82/10/15, 8210250085

- @ Inspection reports. IE Bulletins & correspondence
- 8204160212 Responds to MRC 820118 notice of violation & proposed imposition of civil penalties Corrective actions containment atmospheric control sys made fully operable on 810605 & procedure re performance of analyses being reviewed STASZESKY, FM Boston Edison Co 82/03/19 DEYBUNG, R C Director's Office, Office of Inspection and Enforcement lipp 15611 275 24X Fichs 50-293,82/03/19.8204160212
- --B204160222 Forwards performance improvement program in response to NRC 820118 order modifying license, effective immediately Program details 18 to 24-month period that will result in demonstrated effective regulatory performance HARRINGTON H D Boston Edison Co 82/03/18 HAYNES, R C Region 1, Office of Director 3pp 15611 284 24X Fiche 50-293, 82/03/19,8204160212
- --8204160225 "Performance Improvement Plan" # Boston Edison Co 82/03/08 16pp 15611 287 24) Fiche 50-293,82/03/19,8204160212
- 8210080015 Add1 response to FOIA request for 17 categories of info re nuclear reactor events & safety problems Forwards documents listed in App A Documents in App B completely withheld (ref FOIA Exemption 5) FELTON, J M Division of Rules and Records 82/07/12 UDELL.R A Critical Mass Energy Project 9pp 15665 027 24X Fishe 50-000, 82/07/12,8210080015
- --8210080145 By stematic assessment of licensee performance notes re facility evaluation for Aug-Dec 1980 4 NRC - No Detailed Affiliation Oiven 80/12/31 10pp 15668 025 24% Fiche 50-000, 82/07/12,8210080015
- 8210070277 Forwards IE Insp Rept 50-293/82-23 on 820817-20 No noncompliance noted MARTIN I T Division of Engineering & Technical Programs 82/09/22 HARRINGTON W D Boston Edison Co 2pp 15634 162 24X Fiche 50-293,82/09/22,8210070277
- --8210070283 IE insp Rept 50-293/82-23 on 820817-20 No noncompliance noted Major areas inspected licensee action on previous insp finding, followup on IE Bulletin 81-01.surveillance of mechanical snubbers & Cycle & post-refueling startup tests PETRONE.C D. BETTENHAUSEN.L. Region 1. Office of Director 82/09/09 7pp 15634 164 24X Fiche 50-293.82/09/22,8210070277
- 8210010372 Confirms licensee actions taken in response to Revision 1 of performance improvement program discussed during 020024 mgt meeting Summary of areas needing clarification or corrections one!

 HAYNES,R C Region i. Office of Director 82/07/27

 HARRINOTON, W D Boston Edison Co 3pp 15579 087 24X

 Fiche 50-293, 82/09/27, 8210010372
- 8210150001 Forwards IE Insp Rept 50~293/82-22 on 820802-0906 & notice of violation STAROSTECKI.R Division of Project & Resident Programs 82/09/28 HARRINGTON, N P Boston Edison Co 2pp 15696 285 24x Fiche 50-293, 82/09/28, 8210150001
- --8210150003 Notice of violation from insp on 820802-0706 * Division of Project & Resident Programs 82/09/28 2pp 15696 287 24X Fiche 50-293,82/09/28,8210150001
- --8210150017 IE Insp Rept 50-293/82-22 on 820802-0906 Noncompliance noted failure to notify NRC within 1-h of reactor scram & to perform leak rate test required by limiting conditions for operation for inoperable alarm sys JOHNSON-J. EICHENHOLZ.H., ELSASSER,T. Division of Project & Resident Programs 82/09/22 20pp 15696 287 24X Fiche 50-293,82/09/28,8210150001
- 8210050166 Forwards response to request for further info re IE Bulletin 80-11 "Masonry Wall Design " Issues discussed include shear stress for safety-related shear walls, block pullutes, use of Branson formula, masonry wall cracks & allowable tension MORISI.A V Boston Edison Co 82/09/29 VASBALLO.D B Operating Reactors Branch 2 8pp 15605 114. 24% Fiche 50-293,82/09/29,8210090166
- 8210060150 Ack receipt of 820806 & 27 ltrs informing NRC of steps taken to correct violations noted in IE Insp Rept 50-293/82-12 STAROSTECKLAR Division of Project & Resident Programs, 82/07/30 HARRINGTON W D, Boston Edison Co ip 15615 081 24X Fiche 50-293,82/09/30,8210060150

- --8210060164 Responds to NRC 820707 ltr re violations noted in IE Insp. Rept 50-293/82-52 Corrective actions draft training plan written, interim administrative controls re Tech Specs implemented to operator requalification program revised HARRINGTON, W.D. Boston Edison Co. 82/08/27 STARGSTECKI.R. Othisian of Project & Resident Programs. 2pp. 15615-082 24X Fiche 50-293, 82/09/30-8210060150
- --B210060180 Responds to NRC 820707 ltm re violations noted in IE Insp.
 Rept 50-293/B2-12 Corrective actions add1 operator training
 implemented & reactor water level divergence issue
 incorporated into operator requalification program
 HARRINGTON, W.D. Boston Edison Co. B2/08/06 STAROSTECKI, R.
 Division of Project & Resident Programs 4pp 15615 084 24X
 Fiche 50-293.82/09/30.8210060150
- 821022052! Notification of 821005 meeting w/will in King of Prussia.PA
 to discuss licensee response to NRC order
 ELSASSER.T Division of Project & Resident Programs 82/09/30
 DIRCKS.W J Office of the Erscutive Director for Operations
 DEYOUNG.R C Director's Office, Office of Inspection and
 Enforcement MURRAY.JP Office of the Executive Legal Birector
 Ip 15786 076 24X Fiche 50-293.82/09/30.8210220321
- 8208190233 IE Info Notice 80-35, Suppl 1. "Leaking & Disjudged 1-125 Implant Seeds " Svc list encl COBB.L I Division of Fuel Facilities. Materials & Safeguards 82/10/06 Consolidated Edison Co of New York 66pp 15761 250 24X Fiche 50-000, 82/10/06,8208170233
- 8210190721 Completes response to 1E Bulletin 30-06, "ESF Reset Controls " Review of actions taken in compliance whoulletin revealed deficiencies in Temporary Procedure 81-6A re valve testing New best procedures developed MCRIBI.A V Boston Edison Co 82/10/07 MAYNES.R C Region 1. Office of Director 2pp 15/36 310 24X Fishe 50-293,82/10/07,82/0190721
- 8210290275 Parwards IE Insp Rept 50-293/82-25 on 820914-17 No nancompliance noted MARTIK: T Division of Engineering & Technical Programs 82/10/13 HARRINGTON D Boston Edison Co 2pp 19894 059 24% Fiche 50-293, 82/10/13, 8210290275
- --8210290280 IE Insp Rept 50-293/82-25 on 820914-17 No noncompliance noted Hajor areas inspected inservice insp program & drewing control.licenses actson on previous insp findings & licenses response to IE builetins
 KCBRCARTY.R A . BURR.J P Division of Engineering & Technical Programs 82/10/05 App 15854 061 24X Fiche 50-293,82/10/13,8210290275
- 8208190238 IE Bulletin 82-03, "Stress Corrosion Cracking in Thick-Wall-Large-Diameter, Stainless Steel, Rocirculation Sys Piging at BUR Plants " Svc list enc! BEYOUNG, R C Director's Office, Office of Inspection and BZ/10/14 Consolidated Edison Co of New York 115pp 19810 125 24% Fichs 30-000 82/10/14,8208190238
- 8 Reportable occurrences, LERs & related correspondence
- 8210120155 Informs of adequacy of Graft IE info notice. "Patential Failure of BHR Backup Manual Scram Capability" initiated by NRR. IE & GE subsequent to 800829 LER 80-039/017-0 CHIRAMAL.M Director's Office 80/12/18 Director's Office 1p 15692.179 24X Fiche 50-293,80/12/18,8210120155
- --8210120164 Forwards draft IE info notice, "Potential Failure of DWR
 Backup Manual Scram Capability," per 801208 meeting
 agreement
 LAINAS, O C Assistant Director for Safety Assessment 80/12/15
 JORDAN, E.L. Division of Resident & Regional Reactor Inspection
 4pp 15692 160 24% Ficha 50-293, 80/12/18, 8210120155
- 8210040100 Forwards LER 82-037/03L-0 MATHIB, C J Boston Edimon Co 82/09/22 HAYNES, R C Region 1, Defice of Director 1p 15580 354 24% Fiche 50-293, 82/09/22, 8210040100
- --8210040105 LER 82-037/03L-0 on 820823, three monthly functional surveillances performed in slight excess of allowable 25% tolerance Caused by personnel oversight Senior lavel compliance review implemented Proposed test aids planned. WHITNEY, 0 0. Boston Edison Co. 82/09/22 Region 1, Diffice of Director 200 15580;355 24% Fiche.50-293.82/09/22,6210040100
- 8210060023 Forwards LER 62-034/03L-0
 MATHIB.C J. Boston Edison Co. 82/09/24 HAYNES, R C. Region & Office of Director is 15415 072 24x Fiche 50-293, 62/09/24, 821006023

- --8210060030 LER 82-034/03L-0 on 820826; both HPCI area smote detector systaken out of syc for corrective maint Maint required due to mateture from steam leak condensing inside detector, causing false smoke indication Detectors replaced 2 located LHITMEY.O G Doston Edison Co. 82/09/24 Region 1, 0/1,1c cd Director ip 15615 0/3 24X Fiche 50-293,82/09/24,82100/01.73
- 6210070245 Forwards LER 82-036/031-0
 MATHIS.C J Boston Edison Co 82/09/29 HAYNES.R C Region LOffice of Director Ip 15637 142 24X Fiche 50-293, 82/09/24
 8210070245
- --B210070247 LER B2-036/03L O on B20903 during 75% power, main that it, flow indicator B went to 0 % three other steam flows increased Cause suspected to be valve stem separation flow popped Valve repair plan will be implemented after outlage WHITHEY, 0 0 Beston Edison Co B2/09/29 Region I. Uffice to Director 1p 1563/143 24% Fiche 50-293, 82/09/29/2000/2019
- 8210070340 Forwards LER 82-035/03L-0

 MATHIS. C. J. Boston Edison Co. 82/07/29 HAYNES. R. C. Regium 3

 Office of Director 1p. 15634 066 24% Fichs 50-29 18.709/27.

 2010070340
- --8210070346 LER 82-035/03L-0 nn 820830, during HPC1 surveillanti (til gland seal condenser gasket Failed Caused by overpressure of gasket during startup Gasket mati changed to rubber bonded asbestos Unit tested & returned to svc HHITNEY, O G Boston Edison Co 82/09/29 Region 1, (41, 4 p Director in 15634 067 24% Fiche 50-293.82/09/29/8/8/8/07/10)
- 82(0130472 Forwards updated LER 82-003/99X-1
 MATHIS: C J Boston Edison Co 82/09/30 HAYNES: R C Region 1.
 Office of Director Ip 15682 132 P4X Fiche 50-09 (10/09/3)
- --8210130479 Updated LER 82-002/99X-1 on 820901.util organisation revised Tech Specs being reviewed for submittal to NAL Updated reorganization chart encl NHITMEY.0 0 Goston Edison Co. 82/09/20 Region I, Office I Director Spp 15682 133 24X Fiche 50-293.02/09/30 02001542;
- 8210190235 Forwards updated LER 82-0.14/03X-1 MATHIS,C J Boston Edison Co 82/10/01 HAYNES,R C Region I Dffice of Director 1p 15737 239 24X Fiche 50-491.11/10/01 6210190235
- ---B210170237 Updated LER 82-034/034-1 on 8208P6. buth HP(1 area report detector sys made inoperable Coused by need for corrective maint due to false smoke indication resulting from condensation inside detectors Detectors removed & replaint HHTMEY, 6 G Boston Edison Co. 82/10/01 Region 1. HITMER BORNEY, 6 BOSTON Edison Co. 82/10/01 Region 1. HITMER BORNEY, 6 BOSTON Edison Co. 82/10/01 Region 1. HITMER BORNEY, 6 BOSTON Edison Co. 82/10/01 Region 1. HITMER BORNEY, 6 BOSTON Edison Co. 82/10/01 Region 1. HITMER BORNEY, 6 BOSTON Edison Co. 82/10/01 Region 1. HITMER BORNEY, 6 BOSTON EDISON CO. 82/10/01 Region 1. HITMER BORNEY, 6 BOSTON EDISON CO. 82/10/01 Region 1. HITMER BORNEY, 6 BOSTON CO. 82/10/01 Region 1. HITMER BOSTON CO. 82/10/01 Region Region Region 1. HITMER BOSTON CO. 82/10/01 Region Region
- B210280129 Forwards LER 82~039/03L=0

 MATHIB: C. J. Boston Edison Co. 82/10/20 HAYNEB: R. C. Rygion J.
 Office of Director 1p 15837 117 24X Ficho 50~29% (82/10/2~)

 R210280129
- --8210280131 LER 82-039/03L-0 on 820920, timing tegts of three react water cleanup isolation valves 1201-2.-5 & -80 not completed within allowed time Caused by operational constraints requiring testing at reduced power WHITMEY, 0 0 Boston Edison Co 82/10/20 Region 1. (Mills of Director 2pp 15837 118 24X Fiche 50-293, 62/10/20, 62/0242)
- 8210280146 Forwards LER 82-040/03L-0
 MATHIB.C J Boston Edition Co 82/10/20 HAYNES, N.C. Pepien 1
 Office of Director 1p 15837 225 24X Fiche 50-293.82/10/a*
 8210280146
- --8210280150 LER 82-040/031-0 on 820920, found reactor protestion initiation function of turbine stop valve completed | day interested by decision to defer that due to MBIV D intrinsiation Tracking sys implemented to prevent recurrents MHITMEY, O Q Boston Edison Co 82/10/20 Region I. Office Director 1p 15837 226 24X Fiche 50-293, 82/10/20.821026014
- DOCKET 50-295 ZION NUCLEAR POWER STATION, UNIT I F Security, medical, emergency & fire protection plans
- 8209290125 Releases public version of revised generating status emergency plan corporate command ctr emergency plan implementing procedure FELTON.J M Division of Rules and Records 82/09/16 Detailed Re

- --B209270187 Forwards public version of Revision 4 to generating station emergency plan corporate command ctr Emergency Plan Implementing Procedure EOF-3. "Environ/Emergency Coordinator " Receipt form enci PAJDMGKIJ E Commonwealth Edison Co 82/07/01 DENTON,H R NRC No Detailed Affiliation Given 1p 15364 123 24% Fichs 50-000,82/09/16,8209270125
- --8209290225 Public version of Revision 4 to generating station emergency plan corporate command ctr Emergency Plan Implementing Procedure EUF-3: "Environ/Emergency Coordinator"
 PAJUHSKI.J E Commonwealth Edison Co 82/08/31 lipp 15554 124 24X Fiche 50-000, 82/09/16.8209290125
- E2100B0029 Releases public version of revision to emergency plan implementing procedure FELTON. JM Division of Rules and Records 82/09/22 Document Hanagement Branch 1p 15669 307 24X Fiche 50-295,82/09/22, 82100B0029
- --8210080030 Forwards public version of Revision 3 to Emergency Plan Implementing Procedure EPIP 550-3, "Radiological Supplies for Medical Emergencies" Receipt form encl PLIML, G. Commonwealth Edison Co. 82/09/07 DENTON, H.R. NRC No Detailed Affiliation Given ip 15669 308 24% Fiche 50-275,82/09/22,8210080029
- --82iGOBOO3i Public version of Revision 3 to Emergency Plan Implementing Procedure EPIP 550-3, "Radiological Supplies for Medical Emergencies" Procedure change request form encl a Commonwealth Edison Co 82/09/03 8pp 15669 309 24X Fiche 50-295,82/09/22,82iOOBOO29
- B210050207 Forwards revised exemption requests from provisions of 10CFR50. App R.Section III 0.2 re post-fire shutdown capability.per 820917 telicon LENTINE.F 0 Commonwealth Edison Co 82/10/01 DENTON.H R Office of Nuclear Reactor Regulation. Director 30pp 15611.086 24X Fiche 50-295.82/10/01.8210050207
- 8210130376 Advises that installation of offsite dose calculation sysprogram fully operational tracking model & operational A-model will be delayed until 821231 to complete prime computer installation SHARTZ.E D Commonwealth Edison Co 82/10/04 DENTON, H R Office of Nuclear Psactor Regulation, Director 2pp 15682 098, 24X Fiche 50-000, 82/10/04.8210130374
- 9210290047 Releases public version of revisions to Quad Cities, Zion & Dresden emergency plan annexes & revised generating station emergency plan telephone directory FELTON.J M Division of Rules and Records 82/10/08 Document Management Branch 1p 15877 313 24X Fiche 50-000, 82/10/08, 82/10290047
- --8210270060 Forwards public version of Revision 3 to Quad Cities & Zion emergency plan annexes, Revision 2 to Dresden emergency plan annexes, Revision 0 to Byron emergency plan annex & revised generating station emergency plan telephone directory HOORE, R D Commonumeaith Edison Co 82/07/30 DENTON, H R NRC No Detailed Affiliation Given 5pp 15877 314 24X Fiche 50-000,82/10/08,8210270047
- ---9210290077 Public version of Revision 3 to Quad Cities & Zion emergency plan annexes. Revision 2 to Dresden smergency plan annex & Revision 0 to Byron emergency plan annex * Commonwealth Edison Co 92/06/30 325pp 15877 319. 24X Fiche 50-000,82/10/08.8210290047
- --8210270088 Public version of revised generating station emergency plan telephone directory GALLE.D P Commonwealth Edison Co 82/08/12 43pp 15878 218 24X Fiche 50-000,82/10/08:8210270047
- B210280117 Releases public version of revised emergency plan implementing procedure. FELTON.J M Division of Rules and Records 82/10/12 Document Management Branch ip 19842 241 24X Fiche 50-275.82/10/12, B210280117
- --8210280120 Forwards public version of Revision 2 to Emergency Plan Implementing Procedure EPIP 150-1. "Stores Director" Receipt form enci. PLIML-0 Commonwealth Edison Co 82/09/17. DENTON, H, NRC - No Detailed Affiliation Given ip 15862 242 24X Fiche 50-295,82/10/12.821028017
- --8210280126 Public version of Revision 2 to Emergency Plan Implementing Procedure EPIP 150-1: "Stores Director," Procedure change request form ancl * Commonwealth Edison Co 82/09/16 5pp 15862 243 24X Fiche. 50-275, 82/10/12, 8210280117

- 8210280419 Releases public version of revised emergency plan implementing procedure FELTON.J M Division of Rules and Records 82/10/12 Document Management Branch Ip 15860 001 24X Fiche 50-295.82/10/12.8210280419
- --B210280424 Forwards public version of Revision 5 to Emergency Plan Implementing Procedure 110-1, "Station Director" Procedure change request & receipt forms encl
 PLIML: O Commonwealth Edison Co B2/09/17 DENTON: H R NRC No Detailed Affiliation Oiven 2pp 1980 002 24X
 Fiche 50-295.82/10/12/8210280619
- --8210280427 Public varsion of Revision 5 to Emergency Plan Implementing Procedure 110-1, "Ghation Director" Revised index encl * Commonwealth Edison Co 82/09/16 9pp 15860 004. 24X Fiche 50-295, 82/10/12, 8210280419
- 8210280442 Releases public version of revised emergency plan implementing procedure FELTON.J M Division of Rules and Records 82/10/12 Document Management Branch ip 15899 001 24X Fiche 50-275,82/10/12, 8210280442
- --8210280445 Forwards public version of Revision 4 to Emergency Plan Implementing Procedure EPIP 530-2, "Environ Emergency Kit & Emergency Operations Facility Radiological Equipment" Receipt form and PLTML.0 Commonwealth Edison Co. 82/09/10 DENTON, H.R. NRC Np. Detailed Affiliation Given in 15859 002 24X Fiche 50-295, 82/10/12, 8210280442
- --8210280447 Public version of Revision 4 to Emergency Plan Implementing Procedure EPIP 550-2, "Environ Emergency Kit & Emergency Operations Facility Radiological Equipment" Procedure change request form encl # Commonwealth Edison Co 82/09/09 App 15859 003 24X Fiche 50-295,82/10/12,8210280442
- B21022035B Provides info re organization & performance of depts responsible for radiation protection activities, per B20702 commitment Training coordinator assigned in Apr 1782 to improve health physics training programs
 TRAMMIT R Commonwealth Edison Co 82/10/14 DENTON, H R Office of Nuclear Reactor Regulation, Director 9pp 15776 287, 24X Fiche: 50-000, 82/10/14,8210220388
- 9210280405 Notification of 821028-29 meetings w/util & ENL in Bethewda, MD to discuss & resolve questions on proposed exemption to App R WIOGINTON, D Operating Reactors Branch 1 82/10/22, VARGA, B. A. Operating Reactors Branch 1. 2pp 15859, 327 24X Fiche 50-295, 82/10/22,8210280405
- H General correspondence
- 8210210235 Comments on facility operation NRC should deny util permission to use high burnup nuclear fuel Evidence supporting continued operation of facility should be provided to public QUIGO.C Pollution & Environmental Problems. Inc. 82/10/11. Director's Office, Office of Inspection and Enforcement Spp 15766 259. 24x Fishs 50-295,82/10/11,8210210235
- J Insurance & indemnity information
- 8210060283 Forwards Endorsements 60 % 51 to NELIA Policy NF-201 & MAELU Policy NF-64, respectively GSTER.J Commonwealth Edison Co 82/10/01 BALTZMAN, J. Assistant Director for State & Licenses Relations. 3pp 15621.073. 24X Fiche' 50-299, 82/10/01.8210060283
- O Advisory Committee on Reactor Safeguards reports & correspondence
- 8210270408 Comments on probabilistic risk assessment per 811221 matl. General methods & principles employed in analysis of possible earthquake shaking & site appear to apply modern state of art techniques.

 TRIFUNAC.M D Bouthern California, Univ. of. TRIFUNAC.M.D. ACRB Advisory Committee on Reactor Safeguards 82/02/23 QRIEBMEYER.J M. ACRS Advisory Committee on Reactor Safeguards 3pp. 15832,353,24X Fiche.50-295,82/02/23,8210270408
- P Operating license stage documents & correspondence
- 8007150303 Notifies that review will be conducted of Offshore Power Sys short-term risk studies using various resources in response to 800605 request Evaluation will be submitted by 800922 MATTSON.R.J. Division of Safety Technology 80/07/02 EISENHUT,D O. Division of Licensing 2pp 02752:301, 24X Fichs 30-247,80/07/02.8007130303

- BOOB130744 Summary of 800617 meeting w/utils in Sethesda. HD re containment structural response to core melt accident
 - sequences
 MEYERJF Power Bystems Branch 80/07/31 Power Bystems Branch
 3pp 03286 243 24% Fichs 50-247-80/07/31-8008130744
- 8007100100 Forwards recommendations on staff task action plan to be sent to licensess for review & response.

 BARRETT, L. H. Operating Reactors Assessment Branch 60/08/08 VAROA: 8 A Operating Reactors Branch (Pre 800428) 8pp 03516 066 24% Fichs 50-247.80/08/08.6009100100
- 8009250234 Submits description of work being done on analysis of releases from facilities. Simple I-D multicompartment thermal hydraulic code being written to analyse variety of FVCS designs Related data entl FENSIERHACHER Reactor Systems Branch 80/09/10 SPEIS, T P Reactor Systems Branch 4pp 03589 257 24X Fiche 50-247,80/09/10,8009250234
- 8010220234 Responds to 800917 request rs control room review NRC 800507 itr detailed five addl items to near-term DL requirements Item III D 3 4 requires analysis of control room habitability by 810101 HOWSTON, R W Accident Evaluation Branch 80/09/25 VARCA, 8 A Generating Reactors Granch I 1p 03560 001 24X Fichs 50-247,80/09/25,8010220234
- 8010210036 Discusses SEP Branch review of sys environ qualification of safety-related electrical equipment for ii SEP plants MCKENNA:E M Systematic Evaluation Program Branch 80/09/30 LAINAB; C Division of Licensing 2pp 03647 289 24X Fichs: 50-003, 80/09/30:8010210036
- BOISTIOUB4 Requests Instrumentation & Control Sys Branch evaluation of util responses to questions re incore instrumentation tubes at facilities Info will aid branch evaluation mitigation features re backfitting of severe mitigation features SPEIS.TP Reactor Systems Branch BO/10/07 BATTERFIELD.R Instrumentation & Control Systems Branch ip 02227 00: 24X Fiche SO-247.80/10/07.8011110084
- 80;0280098 Forwards NRC questions & util answers re backfitting of severe accident mitigation features Evaluation needed in two uts SPEIB.TP Reactor Systems Branch 80/10/17 SCHAVER,FP Structural Engineering Branch ip 65767 184 24X Fiche 50-247.80/10/17.80t0200098
- 8210070007 Responds to FOIA request for eight categories of records resteam generators & steam turbines App A documents provided in R Udell FOIA Request 81-313 Forwards documents listed in App B FELTON.J M Division of Rules and Records 82/08/10 LONG, B J Winthrop. Stimson, Putnem & Roberts 9pp 15645-063 24X Fichs 50-000, 82/08/10, 8210070007
- 9209160503 Buppls 920831 Itr re 820908 meeting at Region 3 ofc Recent operation of Unit 2 w/two inoperable auxiliary feeduater pumps added to agenda KEFPLER, J. G. Region 3, Office of Director. 82/09/03 REED, C Commonwealth Edison Co ip 14904:087 24X Fiche 50-295,82/09/03, 8209160503
- 8210040218 Requests reaffirmation of technical basis for operation at 100% power Bignificant financial penalties incurred due to operation in overly conservative manner.

 STIEDE.H.L. Commonwealth Edison Co. 82/09/27 DEYOUNO, R.C. Director's Office. Office of Inspection and Enforcement 3pp 15583 [15. 24% Fiche 50-295,82/09/27,8210040218
- 9210050270 Forwards single Class III amend fee for proposed change to License DPR-39 LENTINE-F.C. Commonwealth Edison Co. 82/09/27, DENTON: # R. Office of Nuclear Reactor Regulation, Director ip 15609:186, 24X Fiche 50-295, 82/09/27, 8210050270,

- 8210120105 Requests delay of implementation due dates re MORED :?,"
 Items II 8 2. "Plant Shielding." II 8 3. "Post-Accident
 Sampling" & II F 1 1. "Noble Oas Effluent Monitor "
 SMARTZE D Commonwealth Edison Co 82/10/04 EIGENHUT, D q
 Davisson of Licensing Spp 15651 237 24X Fiche 50-009.82/1; >
 8210120105
- 8210260526 Forwards Revision 3 of Chapter 9 of "Offsite Dose Calculation Manual" Office Commonwealth Edison Co 82/10/06 CASE, E 9 Off, a Nuclear Reactor 82/10/06 gaston, Director 2pp 15805 137 24% Fishe 50-000, 82/10/06
- --8210260542 Revision 3 of Chapter 9 of "Offsite Dose Calculation Manual"

 * Commonwealth Edison Co 82/09/30 83pp 15805 139 241
 Fiche 50-000,82/10/04,8210260526
- 82(0220399 Supple 820414 response to Franklin Resparch Ctr 8HC.11, technical evaluation rept re control of heavy loads (NUREO-0612), per 820824 & 25 telicons
 LENTINE, FO Commonwealth Edison Co 82/10/12 DENIGN H R of Nurlear Reactor Regulation, Director 3pp 15777 327 2(c) Fiche 50-295.827(07)2.8210220399
- 8210190443 Forwards addl info re NUREO-0737. Item II D 3. *Post-Accident Sampling Sys." in response to NRC 820722 Itr Util currently pursuing possibility of developing procedura to estimate core damage via Westinghouse owners group SMARTZE D Commonwealth Edison Co 82/10/13 FISTMHUI D ¢ Division of Licensing 15pp 19741 187 24X Fiche 50-393.69.
- 8210270344 Notification of B21115-16 meetings w/util in Clentils, to discuss bases for current inservice testing proposed exemption, including alternatives to required inspecting HIGGINTON, D. Operating Reactors Branch 1 82/10/22 VASDA, \$ s. Operating Reactors Branch 1 2p 15851 354 24X Fiche 50-295, 82/10/22, 8210270344
- Q Inspection reports, IE Bulletins & correspondence
- --8210050107 Notice of violation from insp on 820300-31.010) :4 67
 KEPPLER, J G Region 3. Office of Director 82/07/09 3jg
 15605.024 24X Fiche 50-295.82/07/09.8210050103
- --8210050112 IE Insp Rept 50-295/82-09 on 820300-31.0407 (8 % 2) Moncompilance noted individual received whole body radiated dose in excess of three rem & failure to adequately survey & evaluate radiation levels beneath reactor vessel MILLER.D E , OREGER,L R Division of Engineering & Technical Programs. 82/06/11 14pp 15605 027 24X Fiche 50-293 8/1 8210050105
- 8210070007 Responds to FOIA request for eight categories of FILLIP' team generators & steam turbines App A documents provided in R Udeli FOIA Request 81-313 Forwards documents listed in App B FELTON, J M Division of Rules and Records. 82/08/10 LOW 1/ Winthrop, Btimson, Putnam & Roberts 7pp 15645 063 241 Fichs 50-000, 82/08/10, 8210070007.

Θ.

8.

8

- --B210070139 Forwards tabulated data on steam generator image burfacilities. Data should be provided to licensees. IPPOLITO. T. Operating Reactors Assessment Branch. B2/04/01 VAROA.S. Operating Reactors Branch I Upp. 15649 131 20 Fiche. 50-000.82/08/10.8210070007.
- --B210070172 Forwards info re steam generator integrity & initial operating PHRs:per 750320 & 21 requests Details of initial including defect indications, tube plugging criteria & twee plugged will not be provided except for Point Deach & OULLER:K R. Division of Reactor Licensing (NRR-1975 only) 75703/24 HACCARV:R R. Division of Technical Review (NRR-17001) 5pp 15645-176. 24X Fiche 50-000,82/08/10.921000000
- 821019056B Forwards IE Enforcement Conference & Insp Rept 30-244 & 50-304/82-17 on 820717-0909 & notice of violation SPEBBARD, R L. Division of Project & Resident Programs REED. C Commonwealth Edison Co. 2pp. 15736 112 24X Fiche 30-293, 82/09/30, 821019056B,
- --8210190579 Notice of violation from insp on 820717-0831 ** Division of Project & Resident Programs. B8/09/30 15736: 113 24% Fiche: 50-295, 82/09/30, 8210190348

- -8210190599 IE Enforcement Conference & Insp Repts 50-295/82-19 & 50-304/82-17 on 820717-0909 Noncompliance noted failure to follow 800229 confirmatory order requiring expeditious shutdown whenever auxiliary feedwater sys inoperable MATERS, J.R., SCHNEIDER, G.O., REVES, L. Region 3, Office of Director 82/09/22 9pp 15736 114 24X Fiche 50-295,82/09/30, 8210190568
- B210060359 Ack receipt of B20910 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-227/81-39, 50-24/81-23, 50-254/81-23, 50-265/81-23, 50-295/81-31 & 50-304/81-29 SPESSARD, R L Division of Project & Resident Programs B2/10/01 REED.C Commonwealth Edison Co Ip 15618 354 24X Fiche 50-000, 82/10/01, 8210060359
- --8210060367 Responds to NRC 820712 ltr re violations noted in IE Insp Repts 50-237/81-39,50-249/81-32,50-254/81-23,50-265/81-23, 50-275/81-31 & 50-304/81-29 Corrective actions training for most priorities re plant availability will be conducted REED.C Commonwealth Edison Co 82/09/10 KEPPLER, J O Region 3. Office of Director 13pp 156/8 355 24X Fiche 50-000,82/10/01.8210060359
- *210080178 Forwards listing of piping sys which fail to meet FBAR requirements, per NRC 800818 confirmatory action ltr IE Bulletin 79-14 operability evaluation bydates will not be provided for Dresden & Quad Cities Final update by Dec 1982 RAUSCH.T J Commonwealth Edison Co 82/10/01 KEPPLER, J O Regio 2, Defice of Director App 15640 159 24X Fichs 50-000,82/10/01,8210080178
- 210190617 Forwards IE Insp Rept 50-295/82-21 on 820908-10 No soncompliance noted
 LITTLE:N S Division of Engineering & Technical Programs 82/10/05 REED.C Commonwealth Edison Co 2pp 18739 094 24X
 Fiche 50-293,82/10/05.8210190617
- -8210190626 IE insp Rept 50-295/82-21 on 820908-10 No noncompliance noted Major areas inspected Cycle 7 control rod drop time tests, control rod drive & position indication checks & reactor thermocouple/resistance temp device cross-calibr ROSINSON, D L. JACKIN-I N Region 3. Office of Director 82/10/01 4pp 15739 096 24X Fiche 50-295.82/10/05.8210190617
- 108190233 IE Info Notice 80-35, Suppl 1, "Leaking & Dislodged I-125 Implant Seeds " Svt list encl COBB.L I Division of Fuel Facilities, Materials & Safeguards 82/10/06 Consolidated Edjson Co of New York 66pp 15761-250 24% Fiche 50-000,82/10/06,8208190233
- *10190613 Ack recupt of 820910 itr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-295/82-14 & 50-304/82-13 Interpretation of Tech Spec 1 o D unacceptable SPESSARD, R L Division of Project & Resident Programs 82/10/07 REED, C Commonwealth Edison Co ip 15739 361 24X Fiche 50-295, 82/10/07, 8210190613
- 8210190424 Responds to NRC 820813 ltr re violations noted in IE Insp. Repts 50-275/82-14 & 50-304/82-13 Disputes NRC classification of 820625 reactor trip Trip inadvertent interpretation of Tech Spec 1 0 D encl STIEDE: W. Commonwealth Edison Co. 82/09/10 KEPPLER. J 9 Region 3. Office of Director 4pp 15740 001 24% Fichs 50-295,82/10/07,8210190613
- O8190238 IE Bulletin 82-03, "Stress Corrosion Cracking in Thick-Wall-Large-Diameter. Stainless Steel, Recirculation Bys Piping at BMR Plants" Svc list encl
 DEYOUNO.R C Director's Office, Office of Inspection and
 Enforcement 82/10/14 Consolidated Edison Co of New York
 115pp 15810 125 24% Fiche 50-000, 82/10/14, 8208190238
- 10270344 Notification of 821115-16 meetings w/util in Olen Ellyn/IL to discuss bases for current inservice testing proposed exemption, including alternatives to required insparent victor (1001) of the control of the
- Periodic operating reports & related correspondence
- | CO150405 Forwards monthly operating rapts for Sept 1982 |RAESSER.K.L. Commonwealth Edison Co. 82/10/06 Director's | Office, Office of Inspection and Enforcement 1p 15704 003 243 | Tiche 90-295,82/10/06,8210150405.
- 3210150411 Monthly operating repts for Sept 1982 AUSTIN.6 Commonwealth Edison Co 82/10/06 11pp. 15704'004 24X Fiche 50-295:82/10/06:8210150405.

- 8 Reportable occurrences, LERs & related correspondence
- 8210120182 Discusses findings of numerous failures of containment isolation valves All failures resulted from inoperable ASCO Series 8320 solenoid valves, usually due to oil in air supply Valves undergoing qualification LANNING, W D Director's Office 80/08/22 Director's Office 2pp 15692 216 24x Fiche 50-295.60/08/22,8210120182
- 8210070429 Discusses 810115 superoid valve failure Failure of valve to shift attributed to impurities in oil settling on valve surface Valves replaced No further action recommended ASHE, F Director's Office 81/11/10 MICHELSON, C Director's Office 4pp 15644 317 24X Fiche 50-275,81/11/10.8210070429
- B210070422 Recommends IE issue info notice to inform licenses of possible inadequate surveillance for proper tuning of output capacitance for certain inverters Recommendation based on B10505 & 20 sola output transformer shorts HELTEMES, C J Director's Office. B1/12/10 JORDAN.E L Division of Resident & Regional Reactor Inspection. 4pp 15644 285 24X Fiche 50-275, 81/12/10, 8210070422
- 8210010008 Responds to FOIA request for 19 categories of documents renuclear reactor events & safety problems Forwards documents listed in App A FELTON, J M Division of Rules and Records. 82/06/28 UDELL.R.A Critical Mass Energy Project 15pp (5727 005 24% Fiche 50-000, 82/06/28, 8210010008)
- --Bi11270314 Discusses LER 81-002/03X-1.dtd B10430,re inoperable solenoid valves. Cause found to be impurities in internal mechanisms Valves replaced w/Kesne valves & solenoids w/higher strength coil Findings to be incorporated in instrument air study ABHE,F Director's Office, B1/11/10 MICHELSON,C Director's Office 3pp 15731 109 24X Fiche 50-000.82/06/28,8210010008
- 8210080088 PNO-III-82-106 on 820930, while operating at full power, one of two main feedwater pumps failed Reactor control rod drive sys failed to insert rods automatically Caused by faulty circuit board Circuit board replaced REYES, L., STREETER, J., SPESSARD, R. Region 3, Office of Director 82/10/01 1p 15640 222 24% Fiche 50-295,82/10/01,8210080088
- 8210190689 Forwards LER 82-027/03L-0 ORAESSER, K. L. Commonwealth Edison Co. 82/10/05 KEPPLER, J & Region 3, Office of Director ip 15738 143 24X Fiche 50-295, 82/10/05,8210190689
- --8210190715 LER 82-027/03L-0 on 820905,1C containment spray diesel driven pump found completely void of engine jacket water. Caused by leak in jacket water heater due to corresion Heater replaced w/pipe plug New heaters ordered SHRM,K Commonwealth Edison Co 82/10/05 Region 3, Office of Director ip 15739 144 24X Fiche 50-295,82/10/05,8210190689
- 8210190483 Forwards LER 82-028/03L-0 GRAESBER, K. L. Commonwealth Edison Co. 82/10/08 KEPPLER, J 0 Region 3, Office of Director ip 15740 264 24X Fiche: 50-293, 82/10/08,8210170483.
- --8210190493 LER 82-028/03L-0 on 820910, during surveillance at 100% power, RHR miniflew control valve switch iFIC-610A failed & would not close miniflew valve at 1000 gpm as designed Caused by switch out of tolerance Mod initiated BINOGELI.B L Commonwealth Edison Co 82/10/08 Region 3, Office of Director ip 15740 267 24% Fiche, 50-295, 82/10/08, 8210190483
- 8210260399 Forwards LER 82-030/03L-0 QRAESSER: K L Commonwealth Edison Co 82/10/19, KEPPLER, J Q Region 3, Office of Director. 1p 19803 327 24X Fiche 50-295, 82/10/19, 8210260399.
- --B21026041i LER B2-030/03L-0 on B20919, charging flow found 30 gpm less than letdown flow Increased demand on charging flow control valve did not increase flow rate Caused by fatigue Rotating alement replaced Investigation ongoing BIN09ELI.B.L. Commonwealth Edison Co B2/10/19 Region 3, Office of Director 3pp 19803-328. 24X Fiche 50-295,82/10/19, 8210260399
- 8210260233 Forwards LER 82-029/03L-0 ORAEBSER,K L. Commonwealth Edison Co. B2/10/20 KEPPLER.J. 9 Region 3, Office of Director Ip. 15803:029 24x Fiche: 50-295,82/10/20,8210260233

DOCKETED ITEMS

- --8210260254 LER 82-029/03L-0 on 820920.logic relay NC41H-XA associated w/power range X10X reactor trip for train A malfunctioned nonconservatively Caused by plunger pin shifting to one side & binding against relay housing ROHDE.JE Commonwealth Edison Co 82/10/20 Region 3, Defice of Director ip 15903 030 24X Fichs 50-295.82/10/20, 8210260293
- DOCKET 50-296 BROWNS FERRY NUCLEAR POWER STATION, UNIT 3
 F Security, medical, emergency & fire protection plans
- 8209170101 Forwards minor revisions to proposed physical security plan Revisions withheld (ref 100F873 21) HILLS.L M Tennessee Valley Authority 82/08/31 DENTGN, H R Office of Nuclear Reactor Regulation, Director 2pp 14910 081 24X Fiche 50-259.82/08/31.8209170101
- 8210290236 Forwards security plan table of contents Table of contents withheld (ref 1905R73 21)

 KARMER, D S Tennesses Valley Authority 82/10/19 DENTON, H R

 Office of Nuclear Reactor Regulation, Director 1p 15788 362 24;

 Fichs 50-259, 82/10/19, 8210250236
- 8210250244 Forwards revisions to physical security plan Revisions withheld (ref 10CFR73 21)

 KAMMER.D S Tennessee Valley Authority 82/10/19 DENION.H R

 Office of Nuclear Reactor Regulation, Director 1p 15788 345 24

 Fiche 50-250, 82/10/19, 8210250244

G Adjudicatory correspondence

- 8210120291 Response to ASLAB 820920 order to provide any supplemental info re questions posed to util Authorization is for 5-ur storage of low level raduasts.w0 limit on use of modules for interim use on backup basis RAMBON.R J Hearing Branch 4 82/10/08 8pp 15652 071 24X Fiche 50-259.82/10/08,9210120291
- --8210120299 Affidavit of P Loysen re application for storage of low level raduaste No restriction requested or contemplated limiting use of modules only to interim use on backup basis LOYSEN.P Advanced Fuel & Spent Fuel Licensing Branch 62/10/08 23pp 19652 079 24X Fiche 50-259.82/10/08.8210120291
- --8210120308 Affidavit of JR McGrath Timely request for renswal of facility license filed for Beatly.NV tow level radwaste disposal facility NV State Board of Health voted not to renew facility license MCGRATH, JR Assistant Director for State Agreements Programs 62/10/08 2pp 15452 102. 24X Fiche 50-259.82/10/08.8210120291
- --8210120316 Affidavit of SN Balomon Southeast Interstate Low Level Radwaste Mgt Compact agreed to close Barnwell, SC facility on 921231 & open new sits on 911231, Certificate of Syc encl, SALOMON, BN Assistant Director for State Agreements Programs 82/10/08 4pp 15652 104. 24X Fiche. 50-239, 82/10/08, 8210120291
- 8210250063 Telecopy message of motion for ASLAB to grant 30-day extension to respond to ASLB 820920 order. Time necessary to explore settlement possibilities of all matters in contraversy

 PYLE.R B Pyle. R B. 82/10/20 Docketing & Services Branch ip 15787-061 24X Fiche 50-259, 82/10/20.8210250063.
- 8210260427 Motion for extension of time until 821121 to respond to 820720 order Time necessary to explore possibilities of settlement Certificate of Buc encl PYLE:R 8 Pyle: R.8 82/10/20. Atomic Safety and Licensing Appeal Panel 2pp 15806 CG6 24x Fiche 50-257.62/10/20. 8210260429

P Operating license stage documents & correspondence

- 8210070255 Forwards response to NRC request for add1 info on NUREC-0612. "Control of Heavy Loads of Nuclear Power Plants "
 HILLS: L. H. Tennessee Valley Authority. 82/09/28 VASBALLO, D B Operating Reactors Branch 2 Sépp. 15635 243 26X
 Fiche 50-259.82/09/28.8210070255
- 8210080218 Forwards add1 info in response to NRC 820808 request re NUREO-0737. Item II K.3.24. "Adequacy of Space Cooling for HPCI & RCIC " ITEM AUTHORITY 82/10/04 DENION.H. R Office of Nuclear Resctor Regulation. Director. 2pp. 15538-091. 24X Fiche: 30-237.82/10/04.8210080218.

- 8210130142 Forwards description of final mods & changes to BHR scray sys & short-term interim commitments for Unit 2 Mods will be implemented for Unit 2 before startup from Reload 4 outage & subsequent Units i & 3 outages
 MILLS:L M Tennessee Valleg Authority 82/10/06 DENTON.H R
 Office of Nuclear Reactor Regulation. Director 4pp 15673 084
 24X Fiche 50-259.82/10/06.8210130142
- 8210250076 Forwards revision to 821006 implementing procedures
 HILLS-L M Tennessee Velley Authority 82/10/15 DENTON-H R
 Office of Nuclear Reactor Regulation, Director ip 15793 018 7
 Fichs 50-257-82/10/15,8210250096
- --8210250101 Revised implementing procedures
 # Tennessee Valley Authority 82/10/15 14pp 15793 059 24c
 Ficher 50-259, 92/10/15, 8210250096
- O inspection reports. IE Bulletins & correspondence
- 8210080015 Addi response to FOIA request for 19 categories of informuclear reactor events & safety problems Forwards documents listed in App A Documents in App B completely withheld (ref FOIA Exemption 5)
 FELTON-J M Division of Rules and Records 82/07/12 UDELL-R A Critical Mass Energy Project 9pp 15665 027 24X
 Fiche 50-000.82/07/12.8210080015
- --8210080118 Systematic assessment of licensee performance notes ry facility evaluation for App 1979-Mar 1980 NRC - Na Detailed Affiliation Given 80/03/31 App 15667 315 24X Fiche 50 000, 82/07/12,8210080015
- 8210150105 Notifies that corrective actions re IE Insp Repts 50-259/8i-13, 50-260/8i-13 & 50-296/8i-13 delayed Procedure DPM NBOE3 re exam of CSSO (tems to be revised by G20915 DOMER, J A Tennessee Valley Authority 82/07/13 O'REFLLY, J P Region 2, Office of Director ip 15701 159 24X Fiche 50-259, 82/07/13, 8210150105
- 8210220151 Provides supplemental response to NRC ltr re violations noted in IE Insp Repts 50-259/82-10, 50-260/82-10 & 50-296/82-10 Div of procedures Manual N82/3 will not be revised until 821001 due to scope of effort involved MICLB/L H Tennessee Valley Authority 82/08/18 @'REICLY.JP Region 2, Office of Director ip 15778 106 24X Fiche; 50-259, 82/08/18, 8210220151
- 8210010035 Confirms 820708 site meeting to discuss recent violatios re radwaste shipments Agenda encl O'REILLY, J.P. Region 2. Office of Director 82/09/03 PARRIS, H.G. Tennessee Valley Authority 2pp 15565 166 24X Fiche 50-259, 82/09/03, 8210010035
- 6210010430 Forwards IE Insp Repts 50-259/82-25, 30-260/82-25 & 50-276/82-25 on 820810-11 No noncompliance noted VERRELLI, D M Division of Project & Resident Programs 62/09/0 PARRIEL H O Tennessee Valley Authority 2pp 15570 211 24% Fiche 50-259, 82/09/03, 8210010430
- --8210010432 IE Insp Repts 50-297/82-25, 50-240/82-25 & 50-296/82-2 820810-11 No noncompliance noted Major areas inspected reactor secondary containment integrity problem & MSIV testing 8ROOMS.E H , JAPE.F. Division of Engineering & Technical Froj. 82/08/27 4pp 15970 213 24X Fiche 50-259, 82/09/03, 82(00)
- 8210150399 Forwards IE Insp Repts 50-259/82-28, 50-260/82-28 & 50-296/82-28 on 820830-0903 No noncompliance noted VERRELLI, D M Division of Project & Resident Programs 82/09/8/PARRIS, H 9 Tennessee Valley Authority 2pp 15704 029 24% Fiche: 50-259, 82/09/20, 8210150399
- --8210150406 IE Insp Repts 50-259/82-28.50-260/82-28 & 50-296/82-36 820930-0903 No noncompliance nated Major areas inspacted inservice insp program & inservice testing program review OTRARD, E H , BLAKE, J Division of Engineering & Technical Programs. 82/09/16 4sp 15704-031 24X Fiche 50-259.62/07/8210150399.
- 8210010097 Approves revised commitment dates for Item 25 of App Ct IE Insp Repts 50-259/81-19, 50-260/81-19 & 50-296/81-19 & Item C.2 of App A to IE Insp Repts 50-259/82-12, 50-260/82-12 & 50-276/82-12.

 LEWIS.R C. Division of Project & Resident Programs 82/09/22 PARRIS.H Q. Tennessee Valley Authority. 1p 15565 001 24X Fiche: 50-259, 82/09/22, 8210010097

1

- --0210010104 Requests extension to respond to App C. Item 25 in IE Insp Repts 50-259/81-19.50-260/81-19 & 50-296/81-19 & Item C 2 in IE Insp Repts 50-259/82-12.50-260/82-12 & 50-296/82-12 Responses will be submitted by 030101 & 021101. respectively MILLS.L.M Jennessee Valley Authority 02/09/01 0'REILLY, J P Region 2. 0ffice of Director 1p 15565 002 24X Fiche 50-259, 02/09/22.0210010097
- 210010270 Ack receipt of supplemental 820901 ltr informing NRC of steps taken to correct Violation B noted in IE Insp Repts 50-259/61-26.50-260/62-26 & 50-299/61-26. ENTS.R C Division of Project & Resident Programs 82/09/24 PARRIS.N C Tennessee Valley Authority 1p 15573 183 24X Fiche 30-259,82/09/24.8210010270
- -8210010304 Forwards revised response to NRC 811028 ltr re Violation B noted in IE Insp Repts 50-259/82-26.50-260/82-26 & 50-276/82-26 Corrective actions R factor returned to within limits & revision to Tech Spec approved MILLS-L K Tennessee Valley Authority 82/09/01 D'REILLY, J P Region 2. Office of Director 3pp 15573 184 24X Fiche 50-259, 82/09/24.8210010270
- 110220390 Forwards IE Insp Repts 50-259/82-29,50-240/82-29 & 50-296/82-29 on 820904-10 No noncompliance noted WERRELLI.D M Division of Project & Resident Programs 82/09/30 PARRISIN G Tennessee Valley Authority 2pp 15779 220 24X Fiche 50-259, 82/09/30, 8210220390
- B210220401 IE Insp Repts 50-259/82-29, 50-260/82-29 & 50-276/82-29 on B20706-10 No nancompliance noted Major areas inspected Unit 2 refueling & maint outage & procedural compliance of health physics-related practices by workers CGLLINS.TR, BARR.KP Division of Engineering & Technical Programs 82/09/27 Spp 15779 222 24X Fiche 50-259, 82/09/30, B210220390
- 10080217 Forwards revised request for relief from Inservice Insp 7 retraccessible welds in piping penetrations & under rigid pipe reatraints Best effort visual exam will be performed during sys hydrostatic pressure test dILLS.L M Tennesses Valley Authority 82/10/04 DENTON.H.R 3ffice of Nuclear Reactor Regulation. Director 3pp 15638 083 N4x Fiche 50-259,82/10/04.8210080219
- /8190233 IE Info Notice 80-35, Suppl 1. "Leaking & Dislodged I-125 rplant Seeds " Svc list encl
 OBB. L | Division of Fuel Facilities, Materials & Safequards
 '2710/06 Consolidated Edison Co of New York 66pp 15761 250
 '44 Fiche 50-000,82/10/06,8208190233
- O150218 Forwards update of present work & schedule for mplementation of insps required under IE Bulletins 79-02 & 9-34 Phase II evaluation will not be completed until 40801
 ILLS.L M Tennessee Valley Authority 82/10/07 0'REILLY, J Pegion 2. Office of Director 2pp 15705 276 24X sche 50-259, 82/10/07,8210150218
- 3190238 IE Bullatin 82-03, "Stress Corrosion Cracking in Thickall. Large-Diameter, Stainless Steel, Recirculation Sys spring at BUR Plants " Sve list encl EYOUNG-R C Director's Office, Office of Inspection and offorcement 82/10/14 Consolidated Edison Co of New York ISpp 15810 125 24X Fiche 50-000, 82/10/14, 8208190238

reportable occurrences, LERs & related correspondence

- M20129 Advises of need for in-depth evaluation of potential for acceptable interaction between control rod drive sys & nessential control air sys Mergin of safety inherent in censed design basis should be promptly restored CHELSON.C Director's Office 80/08/18 DENTON, H. R Office of clear Reactor Regulation, Director 3pp 15692, 150 24X che. 50-296, 80/08/18, 8210120129
- O1000B Responds to FOIA request for 19 categories of documents reclear reactor events & safety problems, Forwards documents sted in App A LTON. J H Division of Rules and Records. 82/06/28 UDELL.R.A itical Hass Energy Project 15pp 15727 005 24X cha 50-000,82/06/28,8210010008.

- --8112210338 Forwards description of events & resulting action re high circulating current associated w/inverter output due to lack of circuit tuning IE circular or info notice should be issued to address issue
 HELTEMES.C J Director's Office 81/12/10 JORDAN,E L
 Director's Office 4pp 15731 361. 24X Fiche 50-000,82/06/28,8210010008
- --8210060082 "Bummary of Ofc of Analysis & Evaluation of Operational Data Analysis & Evaluation of Browns Ferry Unit 3 Partial Failure to Scram Event of 800628"

 LANIK. O Director's Office 81/11/30 22pp 15731 263 24X Fiche 50-000, 82/06/28, 8210010008
- 8210080015 Addl response to FDIA request for 19 categories of info re nuclear reactor events & safety problems Forwards documents listed in App A Documents in App B completely withheld (ref FOIA Exemption 5)
 FELTON, J M Division of Rules and Records 82/07/12 UDELL, R A Critical Mass Energy Project 9pp 15665 027 24X
 Fiche 30-000.82/07/12.8210080015
- --B210080197 NRC operations ctr usage chart re events at facilities 4 NRC No Detailed Affiliation Olven 62/07/12 1p 15468 22: 24X Fiche 50-000, B2/07/12, B210080015
- 8210060265 Forwards LER 82-042/03L-0 OREGA H J Tennesses Valley Authority 82/09/28 O'REILLY, J P Region 2, Office of Director. 1p 15621 0/4 24X Fichs 50-296.82/09/28.8210060265
- --8210060270 LER 82-042/03L-0 on 820831, diesel generator 3C right bank air starters failed to develop min rom Caused by loose bolts on right bank air start valve 853-3 Bolts tightened PORTER, M.R. Tennessee Valley Authority. 82/09/28 Region 2, Office of Director 2pp 15621 077 24% Fiche 50-296,82/09/28,8210060265
- 8210130157 Forwards LER 82-043/03L-0 QREEN.H J Tennessee Valley Authority 82/10/07 O'REILLY, J P Region 2. Office of Director 1p. 15673 077. 24X Fichs 50-276.82/10/07.8210130157
- --8210130162 LER 82-043/03L-0 on 820909,480-volt reactor motor operated valve board 3DN motor-generator set removed from svc when generator/flywheel ball bearing became noisy Caused by lack of adequate lubricant film on bearing Bearing replaced AARON,J,A Tennessee Valley Authority 82/10/07 Region 2, Office of Director 2pp 15673 078 24X Fiche 50-296,82/10/07, 8210130157
- 8210270231 Forwards updated LER 82-037/01X-1 GREEN.H J Tennessee Valley Authority 82/10/14 O'REILLY, J.P. Region 2. Office of Director 1p 15853 231 24X Fiche:50-296.82/10/14.8210290231
- --8210270232 Updated LER 82-037/01X-1 on 820824, during instrumentation calibr for core standby cooling sys suppression chamber, calibr valve on level switch LB-73-57A found open rendering switches inoperable Caused by open valve Valve closed IRBV-8 J Tennessee Valley Authority BZ/10/13 Region 2, Office of Director 2pp 15853.232 24X Fiche 50-296,82/10/14, 2210790231
- T Hearing transcripts on non-antitrust matters
- 8210070133 Testimony of JM Hutton answering ASLAB questions on low level radwaste mgt options Availability of adequate space to dispose of low level wastes in next 5 yrs uncertain Certificate of Svc encl HUTTON, J W Tennessee Valley Authority 82/10/01, 12pp 15627 031 24X Fiche 50-259,82/10/01,8210070133
- DOCKET 50-298 COOPER NUCLEAR STATION

 F Security, medical, emergency & fire protection plans
- 8210010058 Forwards rept of change to safeguards plan, Revision O. Rept withheld (ref 10CFR2.790 & 10CFR73.21). PILANT, J. M. Nebraska Public Power District. 82/09/13. VASSALD, D.B. Operating Reactors Branch 2 1p 15567:153 24X Fiche 50-298,82/09/13.8210010058
- 8210130318 Forwards changes to Revision 1 to safeguards plan, Changes withheld (ref 10CFR2 790 & 10CFR79 21)
 PILANT.J.M. Nebraska Public Power District 82/10/04, VASSALD, D. B. Operating Reactors Branch 2 2pp 15678 160 24X
 Fiche: 50-298,82/10/04,8210130318

- 8210180320 Forwards OE proprietary unique analysis repts for facility Repts withheld (ref 10CFR2 790) SIEGEL-B. Operating Reactors Branch 2 82/10/04 BUSRAMONIAN, N Franklin Institute/Franklin Research Center ip 15746,018 24X Fiche 50-295.82/10/04.8210180320
- 8210260217 Forwards response to NRC 820809 ltr forwarding notice of violation & proposed imposition of civil penalty & order modifying bicense Magnitude of enforcement action not warranted JONES.C R. Nebresta Public Power District 82/10/07 DEYCUNG.R C Director's Office, Office of Inspection and Enforcement. 84pp 13804 081. 24X Fiche 50-298,82/10/07.8210260217.
- 8210220254 Submits update to B20416 response to Osneric Ltr 82-05, confirming operability & installation of post-TMI requirement per NUREO-0737, Item II F 1 re accident monitoring instrumentation, noble ges & iodine particulate PILANT. J H Nebreska Public Power District B2/10/18 EISENHUT, D Q Division of Licensing 1p 15774 228 24X Fiche 50-278, 82/10/18, 8210220254
- 8210240278 Forwards IE Sefequards Insp Rept 50-278/82-28 on 920830-0901. Notice of violation withheld (ref 10CFR72 21). MADSEN. O L. Division of Resident, Reactor Project & Engineering Programs, 82/10/22 PILANT, J H. Nabrasia Public Power District, 2pp 15801-358 24X Fiche, 50-278, 82/10/22, 82/0740298
- --8210260301 lE Safaguards Rept 50-298/82-28 on 820830-0901 Noncompliance noted, details withheld (ref 100FR73 21)
 CALDHELL: R A . KELLY. J A F. 82/10/14 lp. 15801.360 24% Fiche 50-298.82/10/22.8210260298

P Operating license stage documents & correspondence

- 8210120584 Forwards order modifying 810113 order.sxtending completion date for installation of plant mode needed to comply w/NUREO-0661.app A to start of feel Cyle 9.

 VASBALLD.D.B. Operating Reactors Branch 2 62/09/15, PILANT, J H. Nebraeka Febile Power District. 2pp. 15684:209 24X Fiche:50-298.82/09/15.8210120584.
- --8210120590 Order modifying 8:01:0 order, extending completion date for installation of plant mode needed to comply w/NUREQ-066: App 4 to start of Fuel Cycle 9. EISENHUT, D. Q. Division of Licensing, 82/09/15. Nebraska Public Power District, 5pp. 15684:211. R4X Fiche: 50-298, 82/09/16.
- 8210270308 informs that integration of NUAEG-0737, Item II. M. 3.27
 "Gemmon Ref Level" & Item 1.D.1. "Control Room Design
 Review," per outil 820930 commitment will eliminate operator
 confosion resulting from changing water level.
 VA88ALLO.D.3. Operating Reactors Branch 2. 82/io/i2. PILANT, J. M.
 Nebraska Fubi Co Fower Dietrick. 2pp. 15836:337. 24X
 Fiche: 80-298, 82/i0/12,8210270308.
- 8210220254 Submits update to 920416 response to Generic Lir 82-05, confirming operability & installation of post-TMI requirement per NUREG-0737, Iben II.F. i re-accident monitoring instrumentation, noble gas k loding particulats, PILANT, J. M. Nabraska Public Power District. 82/10/18, SISENNIT, D. O. Division of Licensing, Sp. 19776: P28, 24X Fiche: 50-278, 82/10/18.8210220204.
- 8210260028 Forwards revisions to 820329 Relief Requests RP-02 & RP-04 rs inservice insp/testing requirements for pumps & valves. PILANT.J.M. Nebresks Public Fewer District. 82/10/19. VASSALLO, D.S. Operating Resctors Branch 2. 4pp. 15799; 344, Rex Fiche: 80-278, 82/10/19, 8210260328.
- B210290323 Submits justification for continued plant operation rs QE dc mater controllers. Fallure of QE controllers due to hersh environ will not affect safe shutdown Controllers will perate satisfactorily after expanse to redistion does. PILANT. J. M. Nebraska Public Fower District. 82/10/22. VASSALIG. D. B. Operating Reactors Branch E. ip. 18883: Q&A. Piche: 80-298, 82/10/22, 8210240323.

Q. Inspection reports: IE Bulletins & correspondence

9208170233 IK Into Notice 80-35, Suppl 1, "Leaking & Dielodged I-125 Implant Seeds," Svc list encl. COSB.L. I. Division of Fuel Facilities, Haterials & Safaguards. S2/10/06. Contolidated Edison Co. of New York. 64pp. 18761:250. S4X Fishe:50-000.82/10/04,8208170232.

- 8210260217 Forwards response to NRC 820809 ltr forwarding notice of violation & proposed imposition of civil penalty & order modifying license Magnitude of enforcement action not warranted JONES.C R Nebraska Public Power District 82/10/07 negyments.
- WATTANTES
 JONES. C. R. Nebraska Public Power District 82/10/07 DEYDUMD, P.C.
 Director's Office. Office of Inspection and Enforcement 81pp
 15804 081 24% Fichs 50-278, 82/10/07, 8210240217
- 9208190238 IE Bulletin 82-03, "Stress Corrosion Cracking in Thick-Wall, Large-Diameter, Stainless Steel, Recirculation SysPiping at BWR Plants" Syc list encl
 DEYOUND, R C Director's Office, Office of Inspection and
 Enforcement 82/10/14 Consolidated Edison Co of New York
 115pp 15810 125 24X Fiche 50-000, 82/10/14, 8208190238
- 8210220130 Ack receipt of 820910 ltr informing NRC of steps totan to correct violations noted in IE Insp Rept 50-278/82-14 MADSEN/O L Division of Resident, Reactor Project & Engineering Programs 82/10/14 PILANT, JM Nebraska Public Power District ip 15778 118 24x Fiche 50-298,82/10/14,8210220130
- -8210220136 Responds to NRC 820813 ltr re violations noted in IE | Rept 50-278/82-16 Corrective actions entry ways into affected area posted locked or observable to radiographs: Disciplinary action taken re Procedure 7 4 4.Revision 12 PILANT.J M Nebraske Public Power District 82/09/10 MADSEN.G L Division of Resident, Reactor Project & Engineering Programs 3pp 15778 119 24% Fiche 50-298, 82/10/14, 8210721%
- 8210260328 Forwards revisions to 820329 Relief Requests RP-02 ± 67 to inservice insp/testing requirements for pumps & valves PLLANT.J M Nebraska Public Power District 82/10/19 VASSALLO, D B Operating Reactors Branch 2 4pp 15799 344 TH Fiche: 50-298, 82/10/19, 8210260328
- 8210260278 Forwards IE Safeguards Insp Rept 50-278/82-28 on 820830-0701 Notice of violation withheld (ref 1007873 21) MADSEN, O.L. Division of Resident: Reactor Proyect & Engineering Programs 82/10/22 PILANT, U.M. Nebraska Public Power District 2pp 15801 358 24X Fiche 50-278,82/10/22,82/0260278
- --8210260301 IE Bafequards Rept 50-298/82-28 on 820830-0901 Nantty noted details withheld (ref 100FR73 21) CALDMELLAR A., KELLY, J A F Region 4, Defice of Director 82/10/14 lp, 15801 360 24X Fiche 50-298, 82/10/22, 82102
- 8. Reportable occurrences, LERs & related correspondence
- 8210010008 Responds to FDIA request for 17 categories of documental nuclear reactor events % safety problems Forwards documents listed in App A FELTON, J H DEVision of Rules and Records 82/06/28 UDELL, FL Critical Hass Energy Project. 15pp 15727, 003 24X Fiches 30-000, 82/06/20, 8210010008.
- DOCKET 30-301 POINT BEACH NUCLEAR PLANT, UNIT 2

 F. Security, medical, emergency & fire protection plans
- 8210040119 Discusses revision of plant emergency response preciding specifying necessary precautions required before post-accident resently into auxiliary bldg or facade in response to 820914 request for infor re NUREG-0737. Item II D. 2. FAY.C.W. Hisconsin Electric Power Co. 82/09/24 DENTON-HR DFFICE of Nuclear Reactor Regulation Director. CLARA-R A Operating Reactors Branch 3. 2pp 15581.201. 24X Fich: 50-266.82/09/24,8210040119
- 8210080272 Forwards add1 info requested in NRC B20916 telcen to support util 820630 App R exemption request. Eight overtite drewings encl. Aperture cards are available in PDR. FAY.C. M. His consin Electric Fower Co. 82/09/29. DENYON: H R Deffice of Nuclear Reactor Regulation. Director CLARK: R A Dperating Reactors Branch 3 13pp. 15606-047. 24X Fiche: 50-266: 82/09/29, 8210030272.
- 8210080054 Forwards add1 into re proposed mods for emergenty swarf ctr.
 FAY: C. H. Hisconsin Electric Power Co. 82/09/30. DENTON, H. R. Office of Nuclear Reactor Regulation, Director. 169p 18603 32 24X Fiche: 50-266, 82/09/30, 8210050054.
- 8210270256 Releases public version of revised emergency plan implementing procedures. FELTON.J.M. Division of Rules and Records. 82/10/08. Decime Management Branch. 1p. 15834.001. 24X Fiche: 50-266,82/10/04 8210270256.

- --8210270259 Forwards public version of revised emergency plan implementing procedures, including Procedures EPIP 1 1 re initial classification, EPIP 1 3 re estimation of source term & EPIP 1 4 re radiological dose evaluation FAY.C W. Histonsin Electric Power Co. 82/09/10. DENTON, H.R. Office of Nuclear Reactor Regulation. Director CLARK.R.A. Operating Reactors Branch 3 4pp. 15834 002 24X. Fiche 50-264, 82/10/08, 8210270256
- B210150471 Forwards add1 info re 820630 requests for exemption from 1CCFR59 App R concerning Fire Area 9.control room & vertical cable trays, in response to 821001 & 04 tolcons w/N.2C W/16 aversize drawings Aperture cards in PDR FAY.C H Hisconsin Electric Power Co 82/10/11 DENTON, H R Office of Nuclear Reactor Regulation. Director CLARK, R A Operating Reactors Branch 3 12pp 15734 350 24X Fische 50-266, 82/10/11, 8210150471

G Adjudicatory correspondence

- 8210050251 Kemorandum % order granting summary disposition of all WI Environ Decade issues except issue of demonstration of adequacy of eddy current testing to detect cracking BLOCH, P B , KLINE, J R , PAXTON, H C Atomic Safety and Licensing Board Panel 82/10/01 Wisconsin's Environmental Decade 19pp 15610 306 24X Fiche 50-266, 82/10/01, 8210050251
- B210200027 Notice of B21117-20 evidentiary hearing in Two Rivers, HI re adequacy of inservice nondestructive testing of sleeves progosed to be used to regain corroded steam generator tubes Prehearing conference to be held after hearing BLOCH.P B Atomic Safety and Licensing Board Panel 82/10/15 ip 15756 325 24X Fiche 50-266,82/10/15.8210200027
- 8210220242 Notice of relocation of 821117-20 hearing from Two Rivers.WI to Milwavkee, WI Limited appearance statements will be taken at original location on 821117
 BLOCK PB Atomic Safety and Licensing Board Panel 82/10/21 ip 15775 351 24X Fichs 50-266.82/10/21.8210220242

P Operating license stage documents & correspondence

- 8210210009 Recommends review of design of interconection between red undant safety-related electrical load groups Design should be modified to assure full compliance w/Reg Guide 1 A MICHELSON, C Director's Office 80/08/27 DENTON, H R Director's Office 80/08/27 DENTON, H R Director's Office 80/08/27, 8210210009
- E2100:0000 Responds to FDIA request for 19 categories of documents re Auclear reactor events & safety problems Forwards documents Listed in App A FELTON.J M Division of Rules and Records 82/06/28 UDELL.R A Cratical Mass Energy Project 15pp 15727 005 24X Fiche 50-000.82/06/28/8210010008
- --8002140204 Forwards evaluation of proposed Tech Specs change to operate facility at 2250 or 2000 psia Proposed changes are acceptable W/o encil CHECK.P S Reactor Safety Branch 79/12/26 SCHWENCER.A Operating Reactors Branch 1 (Pre 800428) 6pp 15727 030 24X Fiche 50-000,82/04/28,8210010008
- 8210070007 Responds to FOIA request for eight categories of records resteam generators & steam turbines App A documents provided in R Udell FOIA Request 81-313 Forwards documents listed in App B
 FELTON, JM Division of Rules and Records 82/08/10 LONG, D J
 Winthrop, Stimson, Putnam & Roberts 9pp 15645 063 24X
 Fiche 50-000, 92/08/10, 9210070007
- ~-Bi E0290050 Advises that technical reviewers providing input for SER must be available to testify at 811027-31 hearings Schedule & agenda info enci
 CLARK:F A Operating Reactors Branch 3 81/10/20 MURPHY.E.
 NEHEMIAS.J. MO.T. NRC No Detailed Affiliation Given 3pp
 1 5645 271 24X Fiche 30-000, 82/08/10.8210070007.

- 8210040414 Forwards Amends A3 & 68 to Licenses DPR-24 & DPR-27, respectively, safety evaluation & notice of issuance & availability Amends revise inservice insp Tech Space CLARK, R A Operating Reactors Branch 3 82/08/31 FAY, C W Misconsin Electric Power Co Spp 15597 134 24X Fiche 50-266, 82/08/31.8210040414
- --8210040420 Amends 63 & 6B to Licenses DPR-24 & DPR-27, respectively, revising language of Tech Specs re inservice insport requirements of safety class components to conform WIOCFRSO 35 CLARK, R A Operating Reactors Branch 3 82/08/31 16pp 1557 137 24% Fichs 50-266, 82/08/31,8210040414
- --8210040425 Safety evaluation supporting Amends 63 & 68 to Licenses DPR-24 & DPR-27, respectively → Office of Nuclear Reactor Regulation, Director 82/08/31 4pp 15597 155 24X Fichs 30-266.82/08/31.8210040414
- --B210040427 Notice of issuance & availability of Amends 63 & 68 to Licenses DPR-24 & DPR-27, respectively CLARK, R A Operating Reactors Branch 3 82/08/31 3pp 15597 179 24X Fiche 50-266, 82/08/31,8210040414
- 8210030005 Advises that error analysis of reactor vessel water level instrumentation sys requested in NRC 820619 ltr will be available by 83015
 FAY.C W Hisconsin Electric Power Co 82/09/29 DENYON, H R Office of Nuclear Reactor Regulation, Director CLARK, R A Operating Reactors Branch 3 ip 15605 208 24%
 Fiche 50-266, 82/09/29, 8210030005
- 8210030055 Forwards info requested in NRC 820630 ltr re implementation of TMI Item II 8 2, "Post-Accident Sampling Sys " Add1 requirements re backup power sources for lab are beyond scope of original NUREO-0737 implementation schedule BURSTEIN, S Wisconsin Electric Power Co 82/09/30 DENTON, H R Office of Nuclear Reactor Regulations Director CLARK, P A Operating Reactors Branch 3 21pp 15603 307 24X Fiche 50-266, 82/09/30, 8210050055
- 8210050222 Application to amend Licenses DPR-24 & DPR-27, revising spent fuel pool poison surveillance specimen location & clarifying conditions for operating power-operated relief valves FAY, C W Misconsin Electric Power Co 82/09/30 DENTON, H R Office of Nuclear Reactor Regulation, Director, 3pp 15609 056 24% Fiche 50-266,82/09/30,8210050222
- --8210050231 Proposed Tech Specs revising spent fuel pool poison surveillance specimen location & clarifying condition for operating power-operated relief valves # Wisconsin Electric Power Co 82/09/30 3pp 15609 059 24X Fiche 50-266.82/09/30.8210050R22
- 8210290426 Forwards Amends 64 & 69 to Licenses DPR-24 & DPR-27, respectively, safety evaluation & notice of issuance & availability Amends modify operation & surveillance testing requirements of containment purge supply & exhaust valves COLBURN.TO Operating Reactors Branch 3 82/10/04 FAY.C W Misconsin Electric Paumer Co 4pp 15863 143 24% Fiche 50-266, 82/10/04, 8210290426
- --8210270431 Amends 64 & 67 to Licenses DFR-24 & DFR-27, respectively, modifying operation & surveillance testing requirements of containment purge supply & exhaust isolation valves & terminology of Yech Spec 15 4.4 on testing, CLARK, R A Operating Reactors Branch 3 82/10/04 12pp 15863,154 24% Fiche 50-266,82/10/04,8210270426
- ---8210270436 Safety evaluation supporting Amends 64 & 67 to Licenses DPR-24 & DPR-27, respectively 4 Office of Nuclear Reactor Regulation, Director 82/10/04 5pp 15863 146 24X Fiche 50-266, 82/10/04/8210270426
- --8210270441 Notice of issuance & availability of Amends 64 & 69 to Licenses DPR-24 & DPR-27.respectively CLARK.R A Operating Reactors Branch 3 82/10/04 2pp. 15863 151 24X Fiche 50-266, 82/10/04.8210270426
- 8210190284 Advises of mod to RCB gas vent sys to prevent operation of power operated valves during normal plant operation per 821012 talcon Physical restraining device fitted on or over valve operator switch FAY.C W Wisconsin Electric Power 60 82/10/15 DENTON.H.R Office of Nuclear Reactor Regulation, Director .CLARK.R.A Operating Reactors Branch 3 1, 15742:177 24X Fiche 50-266.82/10/15.8210170284

- 8210270294 Forwards Amends 65 & 70 to Licenses BPR-24 & BPR-27, respectively, safety evaluation & notice of issuance & availability Amend allows relaxation of monthly turbine stop & governor valve tests during end of cycle operation COLBURN.TO Operating Reactors Branch 3 82/10/15 FAY.C W Wisconsin Electric Pouer Co 3pp 15836 316 24X Fiche 50-266.82/10/15.8210270294
- --B210270297 Amends 65 & 70 to Licenses DPR-24 & DPR-27, respectively, allowing relaxation of monthly turbine stop & governor valve tests during end of cycle operation CLARK, R A Operating Reactors Branch 3 82/10/15 7pp 15836 319 24X Fiche 50-266,82/10/15,8210270294
- ---8210270302 Safety evaluation supporting Amends 65 % 70 to Licenses DPR-24 & DPR-27, respectively 4 Office of Nuclear Reactor Regulation, Director 82/10/15 2pp 15836 325 24% Fiche 50-266/92/10/15.8210270294
- --8210270303 Notice of issuance & availability of Amends 65 & 70 to Licenses DPR-24 & DPR-27, respectively CLARK, R A Operating Reactors Branch 3 82/10/15 2pp 19836 327 24X Fich: \$0-266, 82/10/15,8210270294
- 8210260476 Application to amend Licenses DFR-24 & DFR-27, revising Tech Spec re administrative control of high radiation areas FAY, C W Hisconsin Electric Power Co 82/10/19 DENTON, H R Office of Nuclear Reactor Regulation. Director 2pp 15806 233 24X Fiche 50-266, 82/10/19,8210260476
- --8210260477 Proposed Tach Spec changes incorporating revisions re administrative control of high radiation areas • Misconsin Electric Power Co 82/10/19 ip 15806 235 24X Fithe 50-266.82/10/19.821026076
- G210280295 Application to amend Litenses DPR-24 & DPR-27, changing Tech Specs re requirements for periodic leatage rate testing of containment atrlock doors Class I & II amend fees encl FAY.C W Wisconsin Electric Power Co 82/10/21 DENTON.H R Office of Nuclear Readors regulation. Director 3pp 15837 272 24X Fiche-50-266,82/10/21,8210280295
- ~-8210280298 Tech Spec Change Request 82, changing requirements for periodic leakage rate testing of containment air lock doors + Wisconsin Electric Power Co 82/10/21 4pp 15837 275 24X Fiche 50-266,82/10/21,8210280295
- 8210270274 Provides results of confirmatory analysis demonstrating that unacceptable radioactive release from containment uould not take place as result of smell break LOCA in which operator action required Radioactive release negligible FAY.C H. Hisconsin Electric Power Co 82/10/22 CLARK, R A Operating Reactors Breach 3 ip 15653 105 24X Fiche 50-266,82/10/22,8210270274
- O Inspection reports. IE Bulletins & correspondence
- 8107270156 Forwards add1 info in response to IE Bulletin 60-il re masonry walls Thirteen repts & 109 oversize drawings encl Aperture cards are available in PDR FAYs.U Hisconsin Electric Power Co. 81/07/17. DENTON,H R Office of Nuclear Reactor Regulation. Director. CLARK,R Operating Reactors Branch G. 19pp. Available at NTIS 09151.026 24X Fiche 50-266.81/07/17.8107270156
- --8107270161 "Model Contribution to Dynamic Analysis Results "

 * Computech Engineering Services Inc R553 02, 81/07/31 115pp
 09151-045 24K Fiche 50-266/81/07/17/8107270156
- --8107270166 "Cyrlic Loading Tests of Masonry Bingle Piers, Vol 1 Height to Width Ratio of 2 " HIDALOG.? A , HAYEB,R.L , MGNIVEN,H D California, Univ of, Berkeley UCB/EERC-78/27 Vol 78/11/30 Hipp Available at NTIS 09151-158 24X Fiche 50-266.81/07/17.8107270136
- --8107270169 "Cyclic Loading Tests of Hesonry Bingle Piers, Vol 2 Height to Width Ratio of 1."

 CMEN.B J : HIDALGO.P A : MAYEB.R L California, Univ of, Bertsley. USP/EERC-78/28 VO2 78/12/31. 188pp 09151 298 24X Fiche. 50-266.81/07/17.8107270356
- --8107270174 "Cyclic Loading Tests of Mesonry Bingle Plers, Vol 3 Height to Width Ratio of 0,5."
 HIDALGO,P A, MAYES,R L, MCNIVEN,H D California, Univ of, Berieley UCB/EERC-79/12 VO3 79/05/31. 154pp Available at NTIS 09152 124. 24X Ficher 50-266.81/07/17.8107270156.

- --8107270178 "Shaking Table Study of Single-Story Masonry Houses, Vall --Test Structures 1 & 2 "

 GULKAN, P. KAYES, R. L. CLONGH. R. W. California, Univ. of, Seriell, UCQ/EERC-79/23 VOI 79/09/30 275pp Available at NYIS

 09152 277 24X Fiche 50-246, 81/07/17, 8107270154
- --B107270182 "Shaking Table Study of Single-Story Masonry Houses, bpl 2-Test Structures 3 & 4 " GULKAN, P. MAYES, R. L. CLCUUGH, R. W. Callfornia, Univ. of, Berheley, UCB/EERC-79/24 VO2 79/09/30 300pp 09153 184 24X Fishe 50-266, 81/07/17, 8107270156
- --8107270185 "Shaking Table Study of Single-Story Masonry Houses:Val)
 Surmary, Conclusions & Recommendations "
 CLOUGH R W , MAYES R L , OULKAN P California. Univ of Bertaly,
 UCB/EERC-79/23 V03 79/09/20 110pp Available at NTIE
 09134 078 24X Fiche 50-266.81/07/17.8107270156
- --810727018B "Cyc)ic Shear Tests of Masonry Piers, Vol 1 Test Fagulty":

 MAYES, R L . CMATE. Y . CLOUGH, R W California, Univ of, Serialsg
 EERC 76-8 76/03/31 105pp 09154 182 24X
 Fiche 50-266, 81/07/17, 8107270156
- --B107270191 "Cyclic Shear Tests of Masonry Piers, Vol 2 Analysis of Test Resolts "

 MAYES, R L. GMATE, Y. CLGUOH, R W. California, Univ. of, Qeriples
 EERC 76-16 76/06/30 78pp 09154 288 24X
 Fiche 50-266, 81/07/17, 8107270156
- --Bi07270194 "Strength of Timber Roof Connections Bubjected to Cyclic Loads "

 OULKAN.P., MAYES.R.L., CLOUGH.R.W. California, Univ. of, Bereiv, UCB/EERC-78/17 78/09/30 171pp 09155 005 24X Fiche 50~266.81/07/17.8107270156
- --8107270195 "Literature Survey Transverse Strength of Hasoniy Walls" OMATE,Y, MAYES,R L., CHEN,S J. California, Univ. of, Derielia, JUGB/EERC-77/07 77/03/31 149pp 09155 140 24X Fiche 50-264,81/07/17.8107270155
- --8107270198 "Literature Survey Compressive Tensile Bond & Sher Siter of Masonry "
 MAYES R L . CLOUGH, R H California, Univ of Dertaley EERC 75-15 75/06/30 212pp 09155 286 24X Fiche 50-266,81/07/|18107270136
- --8107270197 "State-of-the-Art in Seismic Shear Strength of Hair-s, Evaluation & Review "

 MAYES: R L . CLOUGH: R W California: Univ of, Berteley Eff.
 75-21 75/10/31 147pp 09156 135 24X Fiche 50-266.81/072/198107270156
- 82:0070007 Responds to FDIA request for eight categories of rerofd's steam generators & steam turbines App A documents provided in R Vde11 FGIA Request 81-313 Forwards documents listed in App B.

 FELTON, J M Division of Rules and Records 82/08/10 LOWD, D J Winthrop, Stimson, Putnam & Roberts 9pp 15645 060 24K Fiche 50-000, 82/08/10, 8210070007
- --8210070139 Forwards tabulated data on steam generator into be admit facilities Data should be provided to licenses IPPOLITO.T Operating Reactors Assessment Branch 82/04/01 VARGA-8 Operating Reactors Branch 1. 5pp 15645 131 241 Fiche 50-000,82/08/10,8210070007
- --8210070172 Forwards info re steam generator integrity & impossion operating PMRs, per 750920 & 21 requests Details of inigs, including defect indications, tube plugging criteria & jubet plugged will not be provided except for Point Deach I GOLLER.K R Division of Reactor Licensing (MRR-1975 only) 75/09/24, MACCARY, RR Division of Technical Review (MR-1910 only) 5pp 15645 196 24X Fiche 50-000, 82/08/10, 0210070007
- 8210040414 Forwards Amends 63 & 68 to Licenses DPR-24 & DPR-27, respectively, safety evaluation & notice of issuance & availability Amends revise inservice insp Tech Spect CLARK, R A Dperating Reactors Branch 3, 82/08/31 FAY, Wisconsin Electric Power Co Spp. 15597 134 24X Ficher 50-266, 82/08/31,8210040414
- --8210040420 Amends 63 & 68 to Licenses DPR-24 & DPR-27.respectively revising language of Tech Specs re inservice inspared prequirements of safety class components to conform W/10CFRSO. 55
 CLARK. R.A. Operating Reactors Branch 3 82/08/31 16pp 13597 139 24X Fiche. 50-266/82/08/31.8210040414
- --8210040425 Bafety evaluation supporting Amends 63 & 68 to Litered DPR-24 & DPR-27, respectively.

 **Office of Nuclear Reactor Regulation, Director 13597:155. 24% Fichs 50-266.82/08/31,8210040414

- --P202210571 "Point Beach Nuclear Plant Units 1 & 2 Inservice Insp Program Technical Evaluation Rept" Science Applications, Inc NRC-03-82-094 GAI-184-028-22 B2/05/15 NRC - No Detailed Affiliation Given 20pp 15597 159 24X Fiche 50-266,82/08/31.8210040414
- ~~P210040427 Notice of issuance & availability of Amends 63 & 68 to Licenses DPR-24 & DPR-27.respectively CLARY.R A Operating Reactors Branch 3 82/08/31 3pp 24X Fiche 50-266,82/08/31,8210040414
- 8210050186 Forwards IE Insp Repts 50-266/82-12 & 50-301/82-12 on 820503-04 & 0615 & notice of violation PEPPLER. J 0 Region 3. Office of Director 82/09/15 BURSTEIN, 8 Wisconsin Electric Power to 3pp 15611 115 24X Fiche 50-266, 82/09/15, 8210050186
- --9210050194 Notice of violation from insp on 820503-04 & 0615 XEPPLER. J G Region 3. Office of Director 62/09/15 3pp \$5611 118 24X Fiche 50-266. 82/09/15.8210050186
- --8210050205 IE Insp Repts 50-266/82-12 & 50-301-82-12 on 820503-04 & Obi5 Noncompliance noted failure to control access to high radiation areas & failure to foliou approved procedures LOVENDALE,P C , HAGUE,R L , GREGER,L R Region 3, Office of Director 82/07/13 8pp 15611 121 24X Fiche 50-266.82/09/15, B210050186
- 8210050256 Requests relief from ASME Section XI, inservice insprequirements re-frequency of reactor vessel interior exam FAY. C Is Misconsin Electric Power Co 82/09/29 DENTON, H R Office of Nuclear Reactor Regulation, Director CLARK, R A Operating Reactors Branch 3 4pp 15610 286 24X Fiche 50-266, 82/09/29, 8210050256
- 8210190669 Forwards IE Insp Repts 50-266/82-20 & 50-301/82-30 on 820914-16 No noncompliance noted LITTLE-N S Division of Engineering & Technical Programs 82/10/04 BURSTEIN,S Wisconsin Electric Power Co 2pp 15738 152 24X Fishe 50-266, 62/10/04, 8210190669
- --8210190675 IE Insp Repts 50-266/82-20 & 50-301/82-20 on 820914-16
 No noncompliance noted Major areas inspected surveillance
 & calltr procedures & performance history
 HASSF,R A , PEGCHEL,J M , HAWKINS,F C Division of Engineering &
 Technical Programs 62/09/29 App 15738 154 24X
 Fichs 50-266,82/10/04,8210190669
- 8208190203 IE Info Notice 80-35, Suppl 1, "Leaking & Dislodged I-125 Implant Seeds" Byc list encl CUBB.t. I Division of Fuel Facilities, Materials & Safeguards 82/10/06 Consolidated Edison Co of New York 66pp 15761 250 24
- 8208190238 IE Bulletin 82-03, "Stress Corrosion Cracking in Thick-Wall, Large-Diameter, Stainless Steel, Recirculation Bys Piping at BWR Plants " Svc list encl DEYOUND, R C Director's Office, Office of Inspection and Enforcement 82/10/14 Consolidated Edison Co, of New York 135pp 15810 125 24X Fiche 50-000, 82/10/14, 8208190238
- A Periodic operating reports & related correspondence
- B210150150 Forwards monthly operating repts for Sept 1982 FAV.C N Misconsin Electric Power Co B2/10/11 Office of Muclear Reactor Regulation, Director Ip 15697 074 24X Fiche 50-266, B2/10/11,8210150150
- --8210150158 Monthly operating repts for Sept 1982 FAY. C.W. Wisconsin Electric Power Co 82/10/04 8pp 15697 075 24X Fiche 50-266:82/10/11.8210150150
- S Reportable occurrences, LERs & related correspondence
- B210120380 Advises that operator action necessary to protect B&W plants from excessive feedwater transients B&W plants do not employ high steam generator level turbine or reactor trips to protect against transients CRESNELL, J S Director's Office. B0/09/12 HICHELSON, C. Director's Office 34pp 15689 286 24% Fiche 50-327, 80/09/12, 8210120380
- 9210060325 Forwards updated LER 82-005/01T-0 FAY.C W Hisconsin Electric Power Co 82/09/28, KEPPLER, J Q. Region 3, Office of Director ip 15616 022 24X Fiche 50-301.82/09/28,8210060325

- --B210060333 Updated LER 82-005/017-1 on B20727, discovered 2 of 3 level instruments on C boric acid storage tank powered from common source Cause not determined due to poor early maint of documents Wiring corrected FAY. C W Wisconsin Electric Power Co 82/09/28 Region 3, Office of Director 5pp 15616.023 24X Fiche 50-301,82/09/28,8210060328
- T Hearing transcripts on non-antitrust matters
- 8210080052 Transcript of 82100b telephone conference to discuss rescheduling of hearing in Washington, DC Pp 1,342-1,352 * Atomic Safety and Licensing Board Panel 82/10/06 12pp 15543 284 24X Fiche 50-266,82/10/06,8210080052
- DOCKET 80-302 CRYSTAL RIVER NUCLEAR PLANT, UNIT 3

 F Security, medical, emergency & fire protection plans
- 8210270229 Forwards IE Bafeguards Insp Rept 50-302/82-17 on 820706-09 & notice of violation. Notice of violation & rept details withheld (ref 100FR70. 21)
 LEWIS.R C Division of Project & Resident Programs 82/07/26
 HANCOCK, J A Florida Power Corp 2pp. 15823.007 24X
 Fiche 50-302, 82/07/26, 8210270229
- --8210270239 IE Safeguards Insp Rept 50-302/82-17 on 820705-09 Noncompliance noted failure to initiate adequate compensatory measures Details withheld (ref 10CFR73 21) PERNY, C. NCOUIRE, D. R. Division of Engineering & Technical Programs 82/07/22. 1p 15823 009. 24% Fiche.50-302,82/07/26,8210270229
- 8210260370 Ack receipt of 820825 ltr informing NRC of steps taken to correct violations noted in IE Safeguards Insp Rept 50-302/82-17 Encl containing safeguards info withheld (ref 10GR73 21)
 LEWIS.R C Division of Project & Resident Programs 82/09/17 HANCOCK.J A Florida Power Corp 2pp. 15804 255 24X
 Fiche 50-302.82/09/17.8210260370
- --8210260377 Forwards response to NRC 820726 ltr re violations noted in IE Safeguards Insp Rept 50-302/82-17. Details withheld (ref 10CFR73 21 & 10CFR2 770)

 BAYNARD, P.Y. Florida Power Corp. 82/08/29 O'REILLY, J.P. Region 2, Office of Director ip. 15804 257 24% Fiche 50-302, 82/09/17. 8210260370
- 8210010379 Ack receipt of 820907 ltr informing NRC of steps taken to correct emergency planning deficiencies noted in IE Insp. Rept 50-302/82-08

 LEMIS.R.C. Division of Project & Resident Programs B2/09/20. HANCOCK, J.A. Florida Power Corp. 1p. 15573-053 24X

 Fiche 50-302, 82/09/20, 8210010379.
- 8210010044 Ack receipt of 820901 itr informing NRC of steps taken to correct emergency preparedness deficiency noted in IE
 Emergency Preparedness Appraisal Rept 50-302/81-14
 LEWIS.R C Division of Project & Resident Programs 82/09/22.
 HANCOCK.J A. Florida Power Corp ip 19568-320 24X
 Fiche 80-302, 82/09/22, 8210010044
- --8210010049 Responds to NRC 810911 itr re emergency preparedness deficiency noted in IE Emergency Preparedness Appraise1 Rept 50-302/81-14. Corrective actions new meteorological tower to be built west of plant.

 MARDIS.D G. Florida Power Corp. 82/09/01 O'REILLY, J. P. Region 2. Office of Director ip 15565 321. 24X Fiche, 50-302, 82/09/22, 8210010044
- 8210260008 Releases public version of revised radiological amergency response plan
 FELTON, J.M. Division of Rules and Records. 82/10/05, Document Management Branch. 1p. 15811, 001. 24x Fiche 50-302, 82/10/05, 8210260008,
- --B210260010 Forwards public version of Revision 1 to radiological emergency response plan, in response to NRC 820408 ltr BAYNARD, P Y. Fiorida Power Corp. 82/09/28. 0'REILLY, J. P. Region 2, Office of Director ip 15811 002. 24X Fiche: 50-302, 82/10/05, 821026008
- --8210260012 Public version of Revision 1 to radiological emergency response plan.
 4 Florida Power Corp. 82/08/27, 388pp. 15811 003 24X Ficha: 50-302.82/10/05,8210260008

- 8210260309 Ack receipt of 821015 ltr informing NRC of steps taken to correct violations noted in IE Safeguards Insp Rept 50-302/92-17 -302/02-17
- LEMIS.R C Division of Project & Resident Programs & HANCOCK. J A Florida Pever Corp ip 15802 361 24X Fiche 30-302, 82/10/22,82/0260307 82/10/22
- ~-8210260310 Responds to NRC 820917)tr reviolations noted in IE Safeguards Insp Rept 50-302/82-17 Corrective actions withheld (ref 10CFR2 790 & 10CFR23 21)
 BAYNARD, P y Florida Power Corp 82/10/15 0'REILLY, J P Region 2, Office of Director ip 15902 362 24X Ficha 50-302,82/10/22. 8210260309
- P Operating license stage documents & torrespondence
- 8210180010 Forwards request for add1 info re Unresolved Safety Lasue B-24 rs operability of purge valves STGLZ, J F Operating Reactors Branch 4 B2/09/20 HANCOCK, J A Florida Power Corp 7pp 15717 353 24X Fiche 50-302, B2/09/20, Florida Power Corp B2(0180010
- 8210180035 Advises that plant emergency feedwater automatic initiation E flow indication sys comply w/NRC long-term safety-grade requirements w/exception re control room indication of overriding automatic initiation capability STOLZ-J F Operating Reactors Branch 4 82/09/27 HANCOCK, J A Florida Power Corp 7pp 13746 260 24% Fiche 50-302,82/09/27, 031018002 8210180035
- --8208190290 "Auxiliary Feedwater Sys Automatic Initiation & Flow Indication, Crystal River Unit 3," technical evaluation rept KAUCHER. J E Franklin Institute/Franklin Research Center NRC-03-79-118 TER-25257-282 82/09/17 KENDALL, R NRC No Data(led Affiliation Given 16pp. 15746 267. 24X Fiche 50-302,82/09/27,8210180035
- 8210060198 Submits update to 801106 responses to interim reliability evaluation program study recommendations No further comments offered BAYNARD, P Y Florida Power Corp 82/09/29 BTDLZ. J F Operat Reactors Branch 4 5pp. 15614 010 24X Fiche 50-302, 82/09/29.
- 8210060263 Submits primary test results re yearly goal for containment purging time, per TMI Action Item II E 4 2, based on data collected during 30-day test period which began on 820723 BAYNARD.P Y Floride Power Corp. B2/09/29 BTDLI, J.F. Operating Reactors Branch 4 2pp [582] 063 24% Fiche 50-302,82/09/29, 8210040263
- 8210150216 Requests exemption from 10CFR50 44(c)(3)(iii) requiring reactor vessel head high point vent Alternative methods for vent performance provided in util 810130 submittal, in response to NUREG-0737, Itam II 8.11
 BAYNARD, P Y Florida Power Corp 82/10/12. 8TOLZ, J F Operati Reactors Stanch 4 3pp 15705:283 24X Fiche 50-302,82/10/12, 0210480014 Coerating 9210150216
- 8210190691 Provides add1 info re dose calculations for NUREQ-0737. Item
 II B 2. " Besign of Flant Shielding & Environ Qualifications
 of Equipment for Spaces/Bys Which May Be Used in PostAccident Operations "
 Y Florida Power Corp 82/10/12 STOLZ. J F Operating
 - Y Florids Power Corp 82/10/12 STOLZ, J F Operating 'ranch 4, 2pp 15736 201 24% Fichs, 50-302, 82/10/12,

'erm work schedule re NUREQ-0630. "lodels for LOCA Analysis," not is to incomplete short-term d W/MC approval of rept
trp 62/10/14 LAINAS, 0 C, Assistant
1. 1p. 15738-145 24X

> fvisors licensed at senior : & NUREQ-0737. rent candidates

EISENHUT, D Q Division IND. 82/10/18.

itian

Operating /10/18

- 8210260436 Forwards revision to 820219 submittal re calculations & measurements of bus voitages used to demonstrate adequate of electrical distribution sys BAYNARD.P Y Florids Power Corp 82/10/19 STOLZ, J F 82/10/19 STOLZ, J F Florida Power Corp Reactors Branch 4 45pp 15806 246 24X Fithe 50-30R:62/10/19. B210260436
- 8210260422 Requests concurrence w/interim plan to maintain lines for chemistry control in once-through steam generators in high energy line state during each startup until Refuel U Condition reported in LER 82-058 Amend fee will be sent BAYNARD, P Y Florida Power Corp 82/10/22 SYOLX, J F Oprial Reactors Brench 4 2pp 15806 312 24X Fiche 50-302, 82/10/22 8210260422
- 8210260454 Updates status of safe-end task force action plan Task force activities expected to be concluded by 821231 Final rept & recommended implementation plans will be submitted by BAVNARD, P.Y. Florida Power Corp. 82/10/22 BTOLI, J.F. Daggate Reactors Brench 4 3pp. 15807 120 24X Fiche 50-302, 82/10/22 R2102A0454
- 8210260497 Submits responses to Encl 1. Questions 1 & 2 in MRC 82.77 litr re Generic Item 8-24, "Operability of Purge Valves"
 Wiffive oversize drawings Aperture cards are available in BAYNARD, P.Y. Florida Power Corp. 82/10/22 STOLZ. J.F. Spera Reactors Branch 4 3pp. 15805-244 24X Fiche 50-302,02/10/22 8210260497 Operat. 4
- Q Inspection reports: IE Bulletins & correspondence
- 8210080015 Addi response to FOIA request for 19 categories of infanuclear reactor events & safety problems Forwards documents listed in App A Documents in App B completely withheld in FDIA Elemption 5) FELTON.J M Division of Rules and Records 82/07/12 UDELL, # a Critical Mass Energy Project 7pp 15665 027 24% Fiche 50-000,82/07/12,8210080015
- --8210080125 Systematic assessment of licenses performance note; re facility evaluation for May 1979-Apr 1980 * NRC - No Detailed Affiliation Given 80/04/30 15667 327 24X Fiche 30-000, 82/07/12, 8210080015
- 8210270229 Forwards IE Safeguards Insp Rept 50-302/B2-17 on 020147 & notice of violation Notice of violation & rept details withheld (ref 10CFR73 21) HANCOCK, J A Florida Power Corp 2pp 15823 007 24x Fiche 50-302, 82/07/26, 8210270229 82/07/21
- --BR10270239 IE Bafeguards Insp Rept 50~302/B2-17 on 040706 07 Noncompliance noted failure to initiate adequate compensatory measures Details withheld (ref 100FR73 21) PERNY.C., NGOURE, D.R. Division of Engineering & Yachaicel Programs 82/07/22 ip 15823 009 24X Fiche 50 302.67/: a 8210270229
- 8210260970 Ack receipt of 820825 ltm informing NRC of steps tales to correct violations noted in IE Safeguards Insp Rept 50-302/82-17 Encl containing safeguards into withheld trafformers at HANCOCK, J A Florida Power Corp 2pp 15804 255 24x Fiche 50-302, 82/09/17, 8210260370. 02/09/11
- --B210260377 Forwards response to NRC 820726 ltr re violations the IE Safeguards Inap Rept 50-302/82-17 Details withheld tref 10CFR73 21 & 10CFR2 790)
 BAYNARD, P Y. Florida Power Corp B2/08/25 D'REIM, Y J P F, 2. Défice of Director ip 13804 257 24X Fiche 50-302.8234
- 8210010379 Ack receipt of 820907 ltr informing NRC of sleps select correct emergency planning deficiencies noted in IE Insp. Rept 50-302/82-08 HANCOCK. J. A Florida Power Corp ip. 15573 053. 241 Fiche 50-302, 82/09/20, 8210010379.
- 8210010044 Ack receipt of 820901 ltr informing NRC of steps talest correct emergency preparedness deficiency noted in IC Emergency Preparedness Appraisal Rept 50-302/81-14 LEWIS.R.C. Division of Project & Resident Programs 82/04/32 HANCOCK, J. A. Florida Power Corp ip 15565:320 24x Fiche 50-302,82/09/22.8210010044

- --E210010049 Responds to NRC 810911 ltr re emergency preparedness deficiency noted in IE Emergency Preparedness Appraisal Rept 50-302/81-14 Corrective actions new meteorological tower to be built west of plant MARDIS.D G Florida Power Corp 82/09/01 0'REILLY, J P Region 2, Office of Director ip 15565 321 24X Fiche 50-302,82/09/22,82(0010044
- 8208190233 16 Info Notice 80-35, Suppl t: "Leaking & Dislodged I-125 Implant Seeds" Svc list encl COBB.L I Division of Fuel Facilities, Materials & Safeguards. 82/10/06 Consolidated Edison Co of New York 66pp 15761 250
- 9208190238 IE Bulletin 82-03, "Stress Corresion Cracking in Thick-Hall, Large-Diameter, Stainless Steel, Recirculation Sys
 Piping at SNR Plants " Svc list encl
 DEYGUNG.R C Director's Office, Office of Inspection and
 Enforcement 82/10/14 Consolidated Edison Co of New York
 115pp 15810 125 "24X Fiche 50-000, 82/10/14, 8208190238
- 8210260309 Ack receipt of 821015 ltr informing NRC of steps taken to correct violations noted in IE Safeguards Insp Rept 50-302/82-17
 LEWIS.R C Division of Project & Resident Programs 82/10/22.
 HANCOCK.J A Florida Power Corp Ip 15802 361 24X
 Fiche 50-302. 82/10/22,8210260309
- --8210240310 Responds to NRC 820917 ltr re violations noted in IE Safeguards Insp Rept 50-302/82-17 Corrective actions withheld (ref 10CFR 790 & 10CFR73 21) BAYNARD, P Y Florida Power Corp 82/10/15 O'REILLY, J P Region 2. Office of Director 1p 19802 362 24X Fichs 50-302, 82/10/22, 8210260309
- S Reportable occurrences, LERs & related correspondence
- 8004020420 Discusses decay heat closed cycle cooling water pump motor being out of spec Gaused by inadequate lubrication Problem highlights vulnerability of nuclear power plants to inadequate lubrication Specs & work order encl ORMSTEIN.H L Director's Office 80/03/20 MICHELSON, C Director's Office 4pp 15649 239 24% Fiche 50-302,80/03/20,8001020420
- 82:01203BO Advases that operator action necessary to protect I&W plants from excessive feedwater transients I&W plants do not employ high steam generator level turbine or reactor trips to protect against transients CRESNELL.J & Director's Office 80/09/12 MICHELBON,C Director's Office 34pp 15689 286 24X Fiche 50-302,80/09/12, 62:0120380
- 8010230435 Forwards summary of 800930 transient, alligator clip event While at 100% power, instrument test leads fell causing feedwater runback & control rod insertion ORNSTEIN.H L Director's Office 80/10/08 MICHELSON, C Director's Office 3pp 15692 265 24% Fiche 50-302, 80/10/08, 8010230435
- 3012290iiB Discusses conclusions of engineering evaluation of strem generator overfill transients at C-E & Hestinghouse plants LAMNINO. H D Director's Office B0/10/29 MICHELBON, C Birector's Office 3pp 15672 262 24X Fich
- 32100:0008 Responds to FOIA request for 19 categories of documents renuclear reactor events & safety problems Forwards documents
 listed in App A
 FELTON, J M Division of Rules and Records 82/06/28 UDELL, R. A
 Critical Mass Energy Project 15pp 15727 005 24X
 Fiche 50-000, 82/06/28, 82:00:10008
- --B106150555 Informs that ESFAS relay failure reviewed to determine significant number of failures, safety consequences & qualifications of ESFAS relays Failure considered simply isolated event & does not warrant further action EAINAS.0 C Assistant Director for Safety Assessment 81/05/05. EISENHULD 0 Division of Licensing 2pp 15730 137 24X Fiche 50-000,82/04/28,8210010008
- --8109080417 Concludes that no addl actions are required re engineered safeguards relay failures Various relays, including new Crydon relays, should be monitored as watch list items Failures after Sept 1981 outage should be reviewed CHIRAMALM Director's Office 81/08/28 MICHELSON, C Director's Office 2pp 13730 128 24% Fiche 50-000, 82/06/28, 8210010008

- --8210010161 Discusses potential problem re Sequoyah reactor pressure nozzle supplementing 800222 memo Underclad cracks found by use of ultrasonic equipment Addl stems of recent origin discussed Related sno encl
 DENTON.H R Office of Nuclear Reactor Regulation, Director 80/02/28 AMEARNE.J., OILINSKY,V., KENNEDY,P. Commissioners 7pp 15727 178 24X Fiche 50-000,82/06/28,8210010009
- 9210130310 Forwards LER 92-045/03L-0

 HANCOCK, J A Florida Power Corp 82/10/01 D'REILLY, J P Region
 2, Office of Director 1p 15678 338 24x Fiche 50-302, 82/10/01,
 8210130310
- --B210130319 LER B2-045/03L-0 on B20704, emergency feedwater ultrasonic flow indicator FW-313-FI discovered insperable & train B arbitrarily declared insperable Caused by failed power supply. Power supply replaced & indicator repaired FORD, E W Florida Power Corp 82/10/01 Region 2, Office of Director 2pp 15678 339 24X Fiche 50-302, 82/10/01, 8210130310
- 9210130520 Forwards LER 82-057/03L-0 HANCUCK, J A Florida Power Corp 82/10/01 D'REILLY, J F Region 2, Office of Director 1p 15682 352 24% Fiche 50-302.82/10/01. 8210130520
- --B210130530 LER 82-057/03L-0 on B20527.containment isolation valve in svc water sys (SWV-49) not stroke time tested following maint Caused by personnel failure to include stroke time testing in work request Maint planners instructed FORP.E W Florida Power Corp. B2/10/01 Region 2. Office of Director 2pp 15682 353 24X Fiche 30-302,82/10/01,8210130320
- 8210190677 Forwards LER 92-058/01T-0 LUTKEHAUS, T C Florida Power Corp 82/10/08 O'REILLY, J F Region 2. Office of Director 1p 15738 162 24X Fiche 50-302,82/10/08, 8210190677
- --8210190687 LER 82-098/017-0 on 820924, valve lineups identified which allow once through steam generator drain lines to be used for bloudown operations & also allows high energy fluid through lines Caused by inadequate review of sys design WILSDN.K.R. Florida Power Corp. 82/10/08 Region 2, Office of Director 2pp 15738 163 24X Fiche 50-302,82/10/08,8210190677
- 8210190271 PNO-II-82-313 on 821014.rise in airborne radioactivity levels in reactor bldg detected Caused by leak in vicinity of reactor coolant drain tank Unit shut down & will be out of svc for about 3 wks to investigate & repair leak ROGGE, J.F., BROWNLEE, V.L. Region 2, Office of Director 82/10/15. 2p 15737 241 24% Fiche 50-302,82/10/15,8210190271
- 8210220052 Forwards LER 82-059/03L-0.

 HANCOCK, J A Florida Power Corp 82/10/15 O'REILLY, J P Region 2. Office of Director 1p 15778 207 24% Fiche 50-302,82/10/15,82/0220052
- --8210220056 LER 82-059/031-0 on 820915 valve DHV-111 on decay heatline B failed to control flow Caused by inoperable flow switch Switch replaced & calibr & DHV-111 functionally tested w/satisfactory results.

 HUGHES,P. 0 Florida Power Corp 82/10/15 Region 2, Office of Director 2pp 15778: 208 24% Fiche: 50-302,82/10/15,8210220052
- 8210290186 RD 82-058.high energy lines exist in reactor bldg Study on restraining lines for pips whip completed. Alternatives under review Requests approved to maintain lines until Refuel 5 BAYNARD. PY Florida Power Corp 82/10/22 STOLZ. J. F. Operating Reactors Branch 4 2pp 15853 309 24% Fiche 50-302, 82/10/22, 8210290186
- 8210290312 Informs that special rept supposedly encl in 821001 submitted LER 82-045 determined to be more useful as basis of Tech Spec change request to be submitted at later date. BAYNARD, P Y Florida Power Corp. 82/10/25. 0'REILLY, J P. Region 2. Office of Director is 15853.158 24X Fiche 50-302,82/10/25. 8210290312
- DOCKET 50-304 ZION NUCLEAR POWER STATION, UNIT 2 F Security, medical, emergency & fire protection plans
- 8209290125 Releases gublic version of revised generating station emergency plan corporate command our emergency plan implementing procedure.
 FELTON, J M. Division of Rules and Records 82/09/16 Ducument Management Branch 1p. 15564,122 24X Fiche: 50-000,82/09/16,8209290125.

- --B209290189 Forwards public version of Revision 4 to generating station emergency plan corporate command ctr Emergency Plan Implementing Procedure EDF-3, "Environ/Emergency Coordinator "Receipt form enc!
 PAJOHSKI.J E Commanwealth Edison Co 82/09/01 DENTON, H R NRC No Detailed Affiliation Given 1p 15564.123 24X Fishe 50-000, 82/09/16, 8209290125
- --8209290225 Public version of Revision 4 to generating station emergency plan corporate command ctr Emergency Plan Implementing Procedure EOF-3, "Environ/Emergency Coordinator" Commune EOF-4, "Environ/Emergency Coordinator" PA/GMSKI. J E Commune elth Edison Co 82/09/31 11pp 1554 124 24X Fiche 50-000, 82/09/16,8209290125
- 8210080029 Releases public version of revision to emergency plan implementing procedure FELTON, JH Division of Rules and Records 82/09/22 Document Management Branch ip 15649 207 24X Fiche 50-295,82/09/22.
- --B210080030 Forwards public version of Revision 3 to Emergency Plan Implementing Procedure EPIP 550-3. "Radiological Supplies for Medical Emergencies " Receipt form enci PLEML.0 Commonwealth Edison Co 82/09/07 DENTON, H R NRC No Betailed Affiliation Given ip 15569-308 24X Ficher 50-295,82/09/22,82(0080029
- --8210080031 Public varion of Revision 3 to Emergency Plan Implementing Procedure EPIP 550-3, "Radiological Supplies for Medical Emergencies " Procedure change request form encl. + Commonwealth Edison Co 82/07/03 Bpp 15669 309 24X Fiche 50-295,82/09/22,8210080029
- B210050207 Forwards revised exemption requests from provisions of 10CFR50, App R, Bection 1f1.0 2 re post-fire shutdown capability, per 820917 telcon
 LENTINE, F G Commonwealth Edison Co B2/10/01 DENYUN, H R Dffice of Nuclear Reactor Regulation, Director. 30pp. 15611 086 24X Fiche 50-295, B2/10/01, B210050207.
- 8210130376 Advises that installation of offsite dose calculation sysphogram fully operational tracking model & operational A-model will be delayed until 821231 to complete prime computer installation
 EMART7.E D Commonwealth Edison Ca 82/10/06 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 15682 078 24X Fiche 50-000, 82/10/06, 8210130376
- 8210290047 Releases public vertion of revisions to Qued Cities, Zion & Dresden emergency plan annexes & revised generating station amergency plan telephone directory. FELTON, J H Division of Rules and Records B2/10/08 Document Management Branch ip. 15877 313 24X Fichs 50-000, 82/10/08, 8210290047.
- --B210290060 Forwards public version of Revision 3 to Quad Cities & Zion emergency plan annexes Ravision 2 to Dreaden emergency plan annex. Revision 0 to Byron emergency plan annex & revised generating station emergency plan telephone directory MODRE, R. D. Commonwealth Edison Co. 82/07/30. DENTON, H. R. NRC No Detailed Affiliation Given 5pp. 15977 314 24X Fiche 50-000,82/10/08,8210290047
- --8210370077 Public version of Revision 3 to Quad Cities & Zion emergency plan annexes. Revision 2 to Dresden smergency plan annex & Revision 0 to Byron smergency plan annex * Commonwesth Edison Co 82/06/30 325pp 15877,317 24X Fithe, 50-000, 82/10/08, 8210270047.

- 8210280419 Releases public version of revised emergency plan implementing procedure FELTON.J H Division of Rules and Records 82/10/12 bottseth Hanagement Branch 1p 15860 001 24X Fiche 50-275,62/10/12. 8210280419
- ~-8210280424 Forwards public version of Revision 5 to Emergency Filal Implementing Procedure 110-1. "Station Director " Procedure inchenge request & receipt forms encl PLINL. G Commonwealth Edison Co 82/09/17 DENTON. NR NRC 1 Detailed Affiliation Given 2pp 15860 002 24X Filaton 50-29 5.82/10/12.8210280419
- ~-8210280427 Public version of Revision 5 to Emergency Plan Implessor Procedure 110-1, "Station Director " Revised index enci * Commonwealth Edison Co. 82/09/16 5pp 15860 004 24x Fiche 50-295,82/10/12,8210280419
- 8210280442 Releases public version of revised emergency plan implementing procedure FELTON.J M Division of Rules and Records 82/10/12 December Management Branch, is 15859 001 24X Fiche 50-295,82/10/12.
- --8210280445 Forwards public version of Revision 4 to Emergency Play , Implementing Procedure EPIP 550-2, "Environ Emergency Kit & Emergency Operations Faculity Radiological Equipment Receipt form encl PLIML O Commonwealth Edison Co 82/09/10. BENTON IR Not 1 Detailed Affiliation Given 1p 15859 002 24x Fiche 50-295.82/10/12.8210280442
- ~-8210280447 Public version of Revision 4 to Emergency Plan Implementing Procedure EPIP 550-2. "Environ Emergency X1% & Emergency Operations Facility Reduced to logical Equipment " Procedure change request form enci # Commonwealth Edison Co 82/09/03 8pp 15057 003 241 Fiche 50-295,82/10/12.8210280442
- B21022035B Provides info re organization & performance of dapta responsible for rediation protection activities, per 820702 commitment Training coordinator assigned in Apr 1982 to improve health physics training programs.

 TRAMM.T.R Commonwealth Edison Co 82/10/14 DENTON, HR D27, of Nuclear Reactor Regulation, Director 9pp 15776 287 241 Fiche 50-000, 82/10/14,8210220358
- 8210280405 Notification of 821028-29 meetings w/util & BNL in Beltala MD to discuss & resolve questions on proposed exemption to App R WIGOINTON. D Operating Reactors Branch 1 82/10/22 VARGA.9 a Operating Reactors Branch 1 2pp 15859 327 24X Fiche 50-295, 82/10/22.8210280405
- H General correspondence
- 8210210235 Comments on facility operation NRC should deny util permission to use high burnup nuclear fuel Evidence supporting continued operation of facility should be provided to public GUIGO.C Pollution & Environmental Problems. Inc B2/10/13 Director's Office, Office of Inspection and Enforcement 5pp 15766.259 24X Fiche 50-295.82/10/11,8210210235
- O Advisory Committee on Reactor Safeguards reports & correspondent
- 8210270408 Comments on probabilistic risk assessment per Bil221 math. General methods & principles employed in analysis of possible earthquake shaking & site appear to apply modern state of art techniques.

 TRIFUNAC.N D Bouthern California, Univ of TRIFUNAC.N D AMAINSTRUCTURE COMMITTEE ON Reactor Safeguards 82/02/23 GRIEGETF. ACRE Advisory Committee on Reactor Safeguards 3pp 15972 20 24X Ficher 30-299.82/02/23, 8210270408.
- P. Operating license stage documents & correspondence
- 8007150303 Notifies that review will be conducted of Offshore Jewil short-term risk studies using various resources, in respend to 800605 request Evaluation will be submitted by 800922 MATTSON.R J. Division of Bafety Technology 800077/02 EIBENHUT, D. Q. Division of Licensing. 2pp. 02952 301, 244 Fiche 50-247, 80/07/02, 8007150303.
- 8210070007 Responds to FDIA request for eight categories of emericant steem generators & steem turbines App A documents provided in R Udell FOIA Request Bi-313 Forwards documents listed in App B.
 FELTON: J M Division of Rules and Records 82/08/10 LOM. BJ Hinthrop. Stimson: Putnem & Roberts 9pp. 1545:063 241 Fiche: 50-000. 82/08/10, 8210070007

- -8203110403 Forwards response to JD Dumele, chairman of Pollution Control Board, State of IL, questions in 820127 ltr
 JOHNSTON, H V Assistant Director for Materials & Qualifications
 Engineering 82/02/22 LAINAS, Q Assistant Director for Safety
 Assessment 2pp 15645 126 24X Fiche 50-000, 82/08/10, 8210070007
- 239160503 Supple 820831 ltr re 820908 meeting at Region 3 ofc Recent operation of Unit 2 w/two inoperable auxiliary feedwater pumps added to agends MEPPLER.J G Region 3. Office of Director 82/09/03 REED.C Commonwealth Edison Co ip 14904 087 24X Fiche 50-295.82/09/03, 5209160503
- 210040218 Requests reaffirmation of technical basis for operation at 100X power Significant financial penalties incurred due to operation in overly conservative menner STIEDE, W.L. Commonwealth Edison Co. 82/09/27 DEYGUNO, R.C. Director's Diffice, Office of Inspection and Enforcement 3pp 15593 115 24X Fiche 50-275, 82/09/27, 8210040218
- 210080111 Forwards completion status & revised schedule for improvements made to control room display since 1980 rept, per 80029 confirmatory order LENTINE, FO Commonwealth Edison Co 82/10/04 DENTON, HR Office of Nuclear Reactor Regulation, Director 4pp 15640 022, 24X Fiche 50-275, 82/10/04, 8210080111
- 2:0120105 Requests delay of implementation due dates re NUREO-0737, Items II B 2. "Plant Shielding," II B 3, "Post-Accident Sampling" & II F 1 1. "Noble Gas Effluent Monitor "SHARTZ-E D Commonwealth Edison Co 82/10/04 EISENHUT, D Q Division of Licensing Spp 15651 237 24% Fiche 50-000.82/10/04. 8210820105
- '10260526 Forwards Revision 3 of Chapter 9 of "Offsite Dose Calcutation Manual" GOLDEN, J C Commonwealth Edison Co 82/10/06 CASE,E Q Office of Nuclear Reactor Regulation, Director 2pp 15805 137 24X Fiche 50-000, 82/10/06, 8210260526
- 0210260542 Revision 3 of Chapter 9 of "Offsite Dose Calculation Hanual"

 " Commonwealth Edison Co 82/09/30 83pp 15805 139 24X
 Fisha 50-000, 82/10/04, 8210260526
- 10220399 Supple 820414 response to Franklin Research Ctr 811005 draft
- technical evaluation rept re control of heavy loads (NUREO-0612), per 820824 & 25 telcons LENTINE, F O Commonwealth Edison Co 82/10/12 DENTON, H R Office of Nuclear Reactor Regulation, Director 3pp 15777 329 24% Fiche 50-295, 82/10/12,8210220399
- 10190443 Forwards add1 info re NUREO-0737, Item II B 3, "Post-Accident Sampling Sys:" in response to NRC 820722 ltr Util currently pursuing possibility of developing procedure to estimate core damage via Westinghouse owners group SHARTZ, E D Commonwealth Edison Co 82/10/13 EISENHUT, D 0 Division of Licensing 15pp 15741 187 24X Fiche 50-295, 82/10/13, 8210190443
- 10270344 Notification of 821115-16 meetings w/util in Olen Ellyn/IL to discuss bases for current inservice testing proposed exemption, including alternatives to required insps WIGGINTON D Operating Reactors Branch i 82/10/22 VAROA, 8 A Operating Reactors Branch i 2pp 15851,354 24X Fiche 50-275,82/10/22,8210270344

Inspection reports, IE Bulletins & correspondence

- 10070007 Responds to FOIA request for eight categories of records re steam generators & steam turbines. App A documents provided in R Udell FOIA Request 81-313 Forwards documents listed in App. B
- App B
 FELTON.J H Division of Rules and Records 82/08/10. LONG.D.J.
 4/fithrop. Stimson, Putnam & Roberts, 9pp. 13645.063 24X
 Fiche 50-000, 82/08/10, 8210070007
- 3210070139 Forwards tabulated data on steem generator insp & maint at facilities Data should be provided to licensees IPPDLITO.T Operating Reactors Assessment Branch 92/04/01 VAROA.B Operating Reactors Branch 1 5pp 15645 131. 24X Fiche 50-000,82/08/10,8210070007.
- 3210070172 Forwards info re steam generator integrity & insps at all operating PWRs, per 750320 & 21 requests, Details of insps. including defect indications, tube plugging criteria & tubes plugged will not be provided except for Point Basch i. GOLLER.K R Division of Reactor Licensing (NRR-1975 only) 75/03/24 MACCARY.R R Division of Teactor Licensing (NRR-1975 only) 5pp 15645 196 24X Fichs 50-000, 82/08/10, 8210070007.

- 821019056B Forwards IE Enforcement Conference & Insp Repts 50-295/82-19 & 50-304/82-17 on 820717-0909 & notice of violation SPESSARD, R L Division of Project & Resident Programs REED, C Commonwealth Edison Co 2pp 15736 112 24X Fiche 50-295, 82/09/30, 8210190568
- --8210190579 Notice of violation from insp on 820717-0831 * Division of Project & Resident Programs 82/09/30 ip 15736 li3 24X Fiche 50-275, 82/09/30, 8210190588
- --8210190599 IE Enforcement Conference & Insp Repts 50-295/82-19 & 50-304/82-17 on 820717-0709 Noncompliance noted failure to follow 800229 confirmatory order requiring expeditious shutdown whenever auxiliary feedwater sys inoperable MATERS, J R, SCHNEIDER, O O, REYEG, L. Region 3, Dffice of Director 82/09/22 9pp 15736,114. 24% Fiche.50-295,82/09/30,8210190568
- 8210060359 Ack receipt of 820910 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-237/81-39, 50-249/81-32, 50-254/81-23, 50-255/81-23, 50-275/81-31 & 50-304/81-29 SPESSARD,R L Division of Project & Resident Programs, 82/10/01 REED, C Commonwealth Edison Co Ip 15618 354 24X Fiche, 50-000, 82/10/01, 8210060359
- --B210060367 Responds to NRC B20712 ltr re violations noted in IE Insp Repts 50-237/81-39, 50-249/81-32, 50-254/81-23, 50-265/81-23, 50-295/81-31 & 50-304/81-29 Corrective actions training for mgt priorities re plant availability will be conducted REED.C Commonwealth Edison Co B2/09/10. KEPPLER, J O Region 3, Office of Director 13pp 15418 355 24X Fiche 50-000, B2/10/01, B210040359
- 8210080179 Forwards listing of piping sys which fail to mest FBAR requirements, per NRC 800818 confirmatory action ltr. IE Bulletin 79-14 operability evaluation updates will not be provided for Dresden & Quad Cities Final update by Dac 1982. RAUSCH.T.J. Commonwealth Edison Co. 82/10/01 KEPPLER.J G. Region 3, Office of Director App 15640:157. 24X Fichs 50-000,82/10/01,8210080178
- 820B190233 IE Info Notice 80-35, Buppl 1, "Leaking & Dislodged I-125 Implant Seeds " Bvc list encl CDBB, L. J. Division of Fuel Facilities, Materials & Safeguards 82/10/06 Consolidated Edison Co. of New York 66pp 15761 250, 24X Fichs 50-000,82/10/06.8208190233
- 8210190619 Act receipt of 820910 itr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-293/82-14 & 50-304/82-13 Interpretation of Tech Spec 1 0.D unacceptable SPESSARD, R L Division of Project & Resident Programs 82/10/07 REED, C Commonwealth Edison Co. 1p 15739 361 24X Fiche 50-293,82/10/07,8210190613
- --8210190624 Responds to NRC 820813 ltr re violations noted in IE Insp. Repts 50-295/82-14 & 50-304/82-13. Disputes NRC classification of 820625 reactor trip. Trip inadvertent Interpretation of Tech Spec 1 0 D encl.
 STIEDE, W. L. Commonwealth Edison Co. 82/09/10 KEPPLER, J. Q. Region 3, Office of Director. 4pg 15740, Oot. 24X Fich # 50-295, 82/10/07, 8210190613.
- 8208190238 IE Bulletin 82-03, "Stress Corrosion Cracking in Thick-Wall, Large-Diameter, Stainless Steel, Recirculation Sys Piping at BWR Plants " Svc list encl DEYOUNG, R C. Director's Office, Office of Inspection and Enforcement 82/10/14 Consolidated Edison Co. of New York 115pp. 15810 125 24% Fiche 50-000, 82/10/14,8208190238
- 8210270344 Notification of 821115-16 meetings w/util in Olen Eliun, IL to discuss bases for current inservice testing proposed exemption: including alternatives to required insps. WIOGINTON.D. Operating Reactors Branch 1. 82/10/22, VARGA, B. A. Operating Reactors Branch 1. 82/10/22, VARGA, B. A. Fiche: 50-295, 82/10/22, 8210270344
- R Periodic operating reports & related correspondence
- 8210150405 Forwards monthly operating regts for Sept 1982, GRAESSER.K. L. Commonwealth Edison Co. 82/10/06. Director's Office. Office of Inspection and Enforcement ip. 15704.003 24X Fiche: 50-275, 82/10/06. 8210150405
- --8210150411 Monthly operating repts for Bept 1982. AUSTIN.9 Commonwealth Edison Co 82/10/06. 11pp. 15704:004. 24X Fiche.50-295.82/10/06.8210150405.

S Reportable occurrences, LERs & related correspondence

- 8210070422 Recommends IE issue info notice to inform licensee of possible inadequate surveillance for proper tuning of quiput capacitance for certain inverters Recommendation based on 810505 & 28 sola output transformer shorts HELTEMEE.C J Director's Office 81/12/10 JORDAN.E Division of Resident & Regional Reactor Inspection 4pp 15644 285 24X Fiche-50-295,81/12/10.8210070422
- 821001000B Responds to FOIA request for 19 categories of documents re nuclear reactor events & safety problems Forwards documents listed in App A FELTON.J M Division of Rules and Records. 82/06/28 UDELL.R A Critical Mass Energy Project 15pp 15727 005 24X Fiche 30-000.82/06/28.8210010008
- --Bi12210538 Forwards description of events & resulting action re high circulating corrent associated w/inverter output due to lack of circuit tuning IE circular or info notice should be issued to address issue
 HELTEMES.C. J. Director's Office 81/12/10, JORDAN, E.L.
 Director's Office 4pp 15731 361 24X Fiche.50-000,82/06/28,8210010008
- --8203090469 Responds to request to evaluate Bil2ii trip of two inservice auxiliary freedwater pumps from low suction Installation of time relay on starting circuitry of motor driven Auxiliary feedwater pumps will eliminate problem ZUKOR.D Director's Office BZ/02/24 NICHELSON.C Director's Office 3pp 15750 359 24% Fiche 50-000.82/06/28.8210010008
- --8210050075 Summary of 810513 operating reactor events meeting LAINAS, C C Assistant Director for Safety Assessment BI/05/18 EISENUT.D O Assistant Director for Licensing App 15729 160 24% Fichs.50-304;82/06/28:8210010008
- 92[0040116 Forwards LER 92-02]/03L-0 QRAEBSER, K L Commonwealth Edison Go 82/09/24 KEPPLER, J 0 Region 3, Office of Director 19 1558[19] 24X Fiche 50-304, 82/09/24, 8210040[16
- --B210040121 LER 82-021/03L-0 on 820827, during running of 2A turbine driven auxiliary feedwater pump, flow observed on pump 2 discharge header Caused by improper procedure implementation Procedure will be revised JOHNSON, O Commonwealth Edison Co 82/09/24, Region 3, Office of Director ip 15581 192 24X Fiche 30-304,82/09/24, 8210040116
- 8210060262 Forwards LER 82-022/03L~0 GRAEGSER,K. L. Commonwealth Edison Co. 82/09/30 KEPPLER,J Q Region 3, Office of Director 1p. 15621 045 24X Fiche 50-304,82/09/30.8210060262
- --BR10060267 LER 82-022/03L-0 on BR20903, containment spray diesel-driven pump 20 failed to start during remots control room startup for machanical maint Caused by sticty underspeed switch in closed position due to impurities Switch telf-cleaned SHIM. K Commonwealth Edison Co. 82/09/30 Region 3, Office of Director in 15521 066 24% Fiche 50-304,82/09/30,8210060262
- --8210180175 LER 82-023/03L-0 on 820907.28 steam generator level channel 2L-549 did not track Caused by failure of transmitter (Fixcher/Porter 1302495kBABBB-NS). Transmitter replaced Investigation ongoing CANTHELL-P E Commonwealth Edison Co 82/10/07 Region 3, Office of Director ip 15718 183 24X Fiche: 50-304, 82/10/07, 8210180167
- B210260219 Forwards LER 82-024/01T-0 0RAEBSER, K. L. Commonwealth Edison Co. 82/10/19, KEPPLER, J. & Region 3, Defice of Director. ip 15804:262. 24X Fiche. 50-304, 82/10/19, 8210260219
- --B210260223 LER 82-024/01T-0 on 820928, while taking RCS solid, dilution occurred via incorrect makeup when containment integrity was not intact w/shutdown margin Caused by personnel error Operator reinstructed T'MIEMI.W B. Commonwealth Edison Co. 82/10/19. Region 3, Office of Director. 299 15804:269, 24X Fiche, 30-304,82/10/19, 8210240219

- DOCKET 50-305 KEWAUNEE NUCLEAR POWER PLANT
- F Security, medical, emergency & fire protection plans
- 820917006i Forwards draft vital area definition rept for facility Div of Safeguards will review technical basis for rept during 820927-1001 site visit W/o encl VAROA.5 A Operating Reactors Brench 1 82/09/08 Olesser.C w Wisconsin Public Service Corp ip 14910 106 24x Fiche 50-205.829/09/08.8209170061
- B210120505 Ack cooperation in planning Div of Safeguards 020927-11: regulatory effectiveness review Team will evaluate overall effectiveness of security program to determine if safeguards regulations yield acceptable level of protection EISENHUT.D 0 Division of Licensing 82/09/20 01656,ER.C Wilsonsin Public Service Corp 5pp 15672 076 24X Fiche 30-305,82/09/20,8210120505
- 8210080201 Forwards IE Safety Evaluation Rept 50-305/82-17 (urlrg), 1982 No noncompliance noted HIND, J A Division of Emergency Preparedness & Operational E.pp. 82/09/22 GIESLER, C W Hisconsin Public Service Corp 2pp 15640 090 24X Fiche 50-305,82/09/22,8210080201
- --8210080204 IE Safety Evaluation Rept 50-305/82-17 during Aug 162 No noncompliance noted Major areas inspected emergency plan dtd Nov 1981 PAGLIARO, J A . AXELSON.W L Division of Emergency Preparational Operational Support 82/09/20 32pp 15440 092 24x Fiche 50-305.82/09/22.8210080201
- 8210130300 Forwards Revision 3 to security force training b qualification manual Revision withheld (ref 10GFR2 740) OIESLERIC W Misconsin Public Service Corp 82/09/29 DEMICA | Office of Nuclear Reactor Regulation, Director 2pp 156/0 2-1 24X Fiche 50-305.82/09/29, 8210130300
- 8210030102 Forwards IE Befeguerde Insp Rept 50-305/82-16 on 62082-2 & notice of violation Notice of violation withheld (ref 100FR73 21)

 HILLER, J. R. Division of Engineering & Technical Programs 62 Proceedings of the SD-305, 82/07/30, 8210050102
- --8210050110 IE Safeguards Insp Rept 50-305/82-14 on 62002 27
 Noncompliance noted failure to certify qualifications for security force members, Details withheld (ref 100F873 2):
 BELANOER, J. L. (REED. J. R. Region 3. Office of Director \$2.54)
 1p. 15603 297 24X Fiche 50-305,82/09/30.8210050102
- B210130581 Provides info re changes to facility fire protection commitments Revised and schedule submitted in Attachment (of util 820804 ltr should be considered most current & accurate schedule
 OIESLERIC W Wisconsin Public Bervice Corp 82/10/00 CANCAOffice of Nuclear Reactor Regulation. Director 2pp 15679 CM 24X Ficha 50-305,82/10/08,82(0)30581
- 8210280423 Forwards one-time exemption from 10CFR50 App E.requiry emergency preparedness exercise be conducted annually EISENHUT, D O Division of Licensing 82/10/15 GIEBLER.C w Misconsin Public Service Corp 2pp 15860 014 24x Fiche: 50-305, 82/10/15, 8210280423
- --8210280425 One-time exemption from 10CFRSO App E. requiring 40° pemergency preparadness exercise Next exercise schedulif for 831101 EISENHUT, D Q Division of Licensing 82/10/15 Whitehit Public Service Corp 3pp 15860 016, 24% Fiche 50-305.62/128210280423
- P Operating license stage documents & correspondence
- 8210010179 Application to amend License DPR-43, revising Tith Setting reorganization of nuclear dept OIESLER.C. W. Misconsin Public Service Corp. 82/09/27 DM.: Nuclear Reactor Regulation, Director. 2pp. 15567:287 281 Fiche, 30-305, 82/09/27,8210010179.
- --8210010186 Proposed Tech Specs reflecting organisation intitor, corporate nuclear engineering staff, clarifying frequent; et meetings & line of authority for nuclear safety review a audit committee & showing functional responsibilities # Wisconsin Public Service Corp. 82/09/27 13pp 15567 孝 24X Fiche: 50-305,82/09/27,8210010179

- B210G60312 Advises that analyses of plant-specific safety & relief valve discharge piping per NUREO-0737. Item II D i require more time than proposed in B20712 ltr Item resolution will be identified & implementation schedule provided by B21115 GIESLER.C W Misconsin Public Service Corp 82/09/27 EISENRUT.D O Division of Licensing Ip 15619 189 24X Fiche 50-305, B2/09/27, B210060312
- 8210130600 Informs that review of 810831 & 0915 responses to Generic Letter 81-01. "Qualifications for Insp.Exam & Testing & Audit Personnel," completed Commitments & exceptions to Pevision 1 to Reg Quides 1 58 & 1 146 acceptable VARGA. S A Operating Reactors Branch 1 82/09/28 OIESLER, C W Wisconsin Public Service Corp 2pp 15692 345 24X Fiche 30-305, 82/09/28, 8210130600
- 6210210395 Forwards safety evaluation of Ceneric Issue B-24, "Containment Purging During Normal Plant Operation "
 ft/JREG-0737, Item II E 4 2 will be completed by purge & vent
 review Technical evaluation encl
 VAROA: S A Operating Reactors Branch 1 82/09/30 GIESLER, C W
 Hiscomain Public Service Corp 9pp 15772 314 24X
 Fiche 50-305, 82/09/30, 8210210395
- --8210210403 Safety evaluation of containment purging & venting during normal operation Request for add1 info re GA program encl ** NRC No Detailed Affiliation Given 82/09/30 4pp 15772 323 24X Fiche 50-305, 82/09/30, 8210210395
- --8210210410 Safety evaluation of facility override of containment purge isolation Licenses should demonstrate that override condition automatically removed upon clearing initial signal or provide sys level annunciation 4 MRC No Detailed Affiliation Given 82/09/30 2pp 15772 327 24X Fichs 50-305, 82/09/30, 8210210375
- --8010070320 "Technical Evaluation of Electrical Instrumentation & Control Design Aspects of Override of Containment Purge Valve Isolation & Other Engineered Safety Features for Kewaunee Nuclear Power Plant "
 HACKETT. D 8 E080, Inc E00-1183-4168 60/09/30 NRC No Detailed Affiliation Given 23pp 15772 329 24X Fichs 50-305,82/09/30.8210210395
- B210070108 Comments on MRC proposed generic requirements for steam generators Opposes requirements, favoring mgt control program courrently in effect Program should be at volition of util mgt & notice requirements
 OIESLER.C W Wisconsin Public Service Corp 82/10/04
 IPPOLITO,T A Operating Reactors Assessment Branch App
 15628 070 24X Fiche 50-305,82/10/04.8210070108
- 8210190489 Forwards progress update on implementing NUREO-0737, Items II B 3.II B 4.II F 1 3.II F 1 & & III D 3 4 GIESLER, C H Wisconsin Public Service Corp 82/10/14 EISEXHUT, D G Division of Licensing 4pp 15735 331 24X Fiche-50-305,82/10/14,8210190489
- O Inspection reports, IE Bulletins & correspondence
- 8210070007 Responds to FDIA request for eight categories of records re steam generators & steam turbines App A documents provided in R Udell FOIA Request 81-313 Forwards documents lieted in App B FEELTON.J M Division of Rules and Records 82/08/10 LONO,D J Winthrop, Stimson, Putnam & Roberts 9pp 15645 063 24X Fiche 50-000,82/08/10,8210070007
- --B210070139 Forwards tabulated data on steam generator insp & maint at facilities Data should be provided to licensees
 [PPOLIYO, T Operating Reactors Assessment Branch 82/04/01
 VAROA.S Operating Reactors Branch 1 5pp 15645, [31 24X
 Fiche 50-000, 82/08/10, 8210070007
- --9210070172 Forwards info re steam generator integrity & insps at all operating PMRs.per 750320 & 21 requests Deteils of insps. including defect indications, tube plugging criteria & tubes plugged will not be provided except for Point Beach I OOLLER.K R Division of Reactor Licensing (MRR-1975 only) 73/03/24 MACCARY.R Division of Technical Review (MRR-1975 only) 5pp 15645 196 24% Fiche SO-000.82/08/10.8210070007
- 82:0080201 Forwards IE Bafety Evaluation Rept 50-305/82-17 during Aug [982 No noncompliance noted HEND.J A Division of Emergency Preparedness & Operational Bupport 82/09/22 91ESLER,C W Wisconsin Public Service Corp 2pp 85640 090. 24X Fiche 50-305,82/09/22,8210080201

- --8210080204 IE Safety Evaluation Rept 50-305/82-17 during Aug 1982
 No noncompliance noted Major areas inspected emergency
 plan dtd Nov 1981.
 PAGLIARD, J A , AXELSON, W L Division of Emergency Preparedness &
 Operational Support 62/09/20 32pp 15640:092 24X
 Fiche 50-305, 82/09/22, 8210080201
- 8210060328 Forwards util 820917 response to NRC 820715 questions re IE 8011etin 80-04: inadvertently sent to Region 3 GIEBLER, C W Hisconsin Public Service Corp 82/09/29 VARGA, B A Operating Reactore Branch 1 ip 15619:028 24X Fiche, 50-305, 82/09/29, 8210060328
- 8210050102 Forwards IE Bafaguards Insp Rept 50-305/82-16 on 820823-27 & notice of violation Notice of violation withheld (ref 100FR73 21)
 MILLER.J R. Division of Engineering & Technical Programs 82/09/30 GIESLER.C.W Misconsin Public Service Corp 2pp 15603 275 24X Fiche 50-305,82/09/30.8210050102.
- --8210050110 IE Safepuards Insp Rept 50-305/82-16 on 820823-27 Noncompliance noted failure to certify qualifications for security force members Details withheld (ref 100FR73 21) SELANDER.J L. CREEDJ R Region 3. Office of Director 82/09/28 ip 18603 297 24% Fiche 50-305,82/09/30,8210050102
- 8210080174 Forwards confirmatory measurements program data addendum shaet for IE Insp Rept 50-305/82-08, closing out Open Item 50-305/82-08-01.
 PAPERIELLO, C. J. Division of Emergency Preparedness & Operational Support 82/10/05 01ESLER, C. W. Wisconsin Public Service Corp 1p 15640 157 24X Fiche 50-305, 82/10/05, 82/10/05, 82/10/05
- --8210080177 Addendum to IE Insp Rept 50-305/82-08 consisting of confirmatory measurements program data sheet re 8r-89 & Sr-90 samples Bamples below comparison limits * Region 3. Office of Director 82/10/05 ip. 15440 i58 24X fiche 50-305,82/10/05.8210080174
- 8208190233 IE Info Notice 80-35, Suppl 1, "Leaking & Dislodged I-125 Implant Seeds " Syc list encl CDBb. L I Division of Fuel Facilities, Materials & Safeguards B2/10/06 Consolidated Edison Co of New York 66pp. 15761 250 24X Fichs 50-000,82/10/06,8208190233.
- 8210190532 Confirms schedule for 821018 enforcement conference at Region 3 ofcs to discuss potential escalated enforcement actions re recent identification of capped containment pressure sensing lines

 KEPPLER. J O Region 3. Office of Director 82/10/13 MATHEWS. E. R

 Wisconsin Public Service Corp ip 15751 254 24X

 Fiche 30-305.82/10/19.8210190532
- 8210280223 Forwards IE Insp Rept 50-305/82-13 on 820701-0831 & notices of violation & deviation STREETER, J.F. Division of Project & Resident Programs 82/10/13 OIEBLER, C.W. Hisconsin Public Service Corp. 2pp. 15839 279 24X Fichs 50-305,82/10/13,8210280223
- --8210280226 Notice of violation from insp on 820701-0831 SYREETER, J F Division of Project & Resident Programs. 82/10/13 ip 15839 281. 24% Fiche, 50-305, 82/10/13, 8210280223
- --8210280229 Notice of deviation from insp on 820701-0831.
 BYREETER.J.F. Division of Project & Resident Programs
 B2/10/13
 19 15839 282 24% Ficher 50-305,82/10/13,8210280223.
- --8210280232 IE Insp Rept 30-305/82-13 on 820701-0831 Moncompliance noted failure to maintain control of combustible matts & to issue operations mano as of 820820 NCLSUN.R.L., REYES.L.A. Division of Project & Resident Programs 82/10/06 10pp. 15839.283 24X Fiche 50-305,82/10/13,8210280223
- B208190238 IE Bulletin 82-03, "Stress Corrosion Cracking in Thick-Wall-Large-Diamater-Stainless Steel-Recirculation Sys Piping at BMR Plants "Svc list encl DEYOUNO:R C Director's Office. Office of Inspection and Enforcement. B2/10/14 Consolidated Edison Co of New York 115pp 15810-125, 24X Ficher 80-000-82/10/14-820819023B.
- 82102&01&1 Confirms schedule for 821022 enforcement conference w/util to discuss potential escalated enforcement action re recent identification of capped containment pressure sensing lines. SPESBARD.R L Division of Project & Resident Programs 82/10/15 MATHEMS.E.R. Misconsin Public Service Corp. ip 19799 007. 24% Fiche. 50-305.82/10/15.82102&0161

B Reportable occurrences. LERs & related correspondence

- B210120182 Discusses findings re numerous failures of containment isolation valves All failures resulted from inoparable ASCO Series 8320 calencid valves.usually due to oil in air aupply Valves undergoing qualification
 LANNINO.H D Director's Office 80/08/22 Director's Office 2pp 19692 216 24X Fiche 50-295.80/08/22.8210120182
- 8210040136 Forwards LER 92-028/03L-0 & updated 81-036/03X-1 OIEBLER.C W Misconsin Public Service Corp 82/09/24 KEPPLER.J 0 Region J. Office of Director 1p 15582 317 24X Fiche 50-305,82/09/24,8210040156
- --8210040159 LER 82-028/03L-0 on 920825, damper on Train A failed open causing cone special ventilation fan to start automatically Caused by bad coil on solenoid controlling enhaust filter inlet damper Coil replaced BERNHOFT.6 L Hisconsin Public Service Corp 82/09/24 Region 3, Office of Director ip 15582 318 24X Fiche 50-305,82/09/24,8210040156
- --B210040162 Updated LER 81-036/03X-from 811103, notor drive auxiliary feedwater lube oil pump continued to run when pump IA stopped Caused by excessive wear & misslignment of switch linkage mechanism Worn parts replaced BELANT, J. L. Hisconsin Public Service Corp 82/09/21 Region 3, Office of Director 2pp 15582 319 24X Fiche 50-305,82/09/24, 8210040156
- 8210190393 Forwards LERs 82-029/01X-1 & 82-031/03L-0 GIESLER: C W Wisconsin Public Bervice Copp 62/10/11 XEPPLER.J @ Region 3, Office of Director. 1p 15742 107 24X Fichs 30-305, 82/10/11, 8210190353
- --8210190355 LER 82-029/01X-1 on 820927 discovered that monthly testing requirements exceeded for containment radiation monitors R-11 & R-12 Caused by postponement of test due to backup radiation monitor being out of sec & personnel overeight # Hisconsin Public Service Corp 82/10/11 Region 3. Office of Director. 2pp 15742 108 24X Fichs 50-305.82/10/11.8210190393
- --8210190354 LER 82-031/03L-0 on 820913, train IB of shield bldg vent failed to switch to recirculation mode after drawing vacuum Recirculation damper failed to open due to broten hydraulic pump on electro-hydraulic damper actuator. Operator replaced BERNHOFT. 8 L Misconsin Public Service Corp. 82/10/13 Region 3, Office of Director. 1p 15742 110 24X Fiche 50-305,82/10/11,8210190333
- 8210260260 Forwards LER 82-030/01T-0 OIESLER, C.W Hisconsin Public Service Corp 82/10/18 KEPPLER, J O Region 3, Office of Director ip 15799 348 24X Ficks 50-305, 82/10/18, 8210260260
- --B210260263 LER B2-030/01T-0 on B21004.sensing lines on all six containment pressure transmitters found capped off inside, rendering transmitters imperable. Caused by refueling caps inadvertently placed on ends of sensing lines Caps removed. MARCHI.M L. Wisconsin Public Service Corp. B2/10/18 Region 3. Office of Director ip 15797 349. 24% Fiche 50-305,82/10/18. B210200260

V Operator Examinations

Í,

8210050263 Describes implementation of senior reactor operator upgrade training to comply a/NUREG-0737, Item 1.A 2 i. "Senior Reactor Operator Qualifications " All potential candidates cannot be examined until Hay/June of 1983 OIESLERIC W Wisconsin Public Service Corp. 82/09/29, DENTON, H R Office of Nuclear Reactor Regulation. Director 3pg 15609: 193 24X Fiche: 50-305,82/09/29,8210050263

- --8210040354 IE Insp Repts 50-282/82-15 & 50-304/82-15 on 920324 Its noncompliance noted Major areas inspected previous deficiencies in prompt notification/warning sys PATTERSON, J.P. Division of Emergency Preparedness & Operation's Support 82/09/09 4pp 15593 358 24X Fiche 50-202.02/07; 8210040345
- 8210080184 Forwards revised Page 4 reflecting NRC guidance on activation of public alert & notification system 921034 emergency plan exercise WARDLE C Northern States Power Co 82/09/28 AXFIGN N FS., 3. Diffice of Director 2pp 13640 175 24X Fiche 30 202 02/03 38210080184
- 8210120589 Notification of 821001 meeting w/licenses. BML & frgitter, planning & Mgt. Inc in Bethesda. MD to discuss requests for examption from 10CFR50. App R requirements re fire protection
 DIJANNI. D C Operating Reactors Branch 3 82/09/20 (LARK P. a. Operating Reactors Branch 3 2pp 15672 346 24X Fiche 50-282. 82/09/28. 8210120589
- 8210260374 Ack receipt of FEMA 820526 ltm re evaluation of affairs emergency preparedness for facility exercise & associated final exercise evaluation Offsite emergency preparedness deficiencies should be addressed by util
 HIND, J. A. Division of Emergency Preparedness & Alperational 0 pp.
 82/10/21 OlloBerRs D. B. Northern States Power Co. 3pp. 13v-4
 24x Fiche-50-282,82/10/21,8210260374
- P Operating license stage documents & correspondence
- 8210040123 Submits supplemental info re util 820614 request for personal to Licenses DPR-42 & DPR-60 "LOCA ECCS Limiting Break & Exposure Sensitivity Analysis for ENC XN-1 & XN-2 Reloaf at Prairie Island I "applies to both Units i & 2 MUSCLF.D Northern States Power Co 82/09/24 Office & * * * , Reactor Regulation Director ip 15581:203 24x
- 8210130260 Discusses implementation of NRC guidelines for parity hours, provided in Generic Ltr 82-12 Revised guidelines take been implemented, w/exceptions of 72-h per wit limitation to relief from control board duties

 MUSDLF.D Northern States Power Co 82/10/07 (Iffice at the calcor Regulation, Director, 2pp. 15676 OLD 24x

 Fiche: 30-000, 82/10/07, 8210130260
- 8210260154 Advises that mods required by NUREQ-0737.ltqs [] t lt "Control Room Habitability," will not be completed until 830315 due to delays in receipt of matl 4 sampling equipment.

 NUBDLF.D Northern States Power Co 82/10/22 Uffile of ** w Reactor Regulation, Director 3pp. 15799 012 24x

 Fiche: 50-282, 82/10/22, 8210260154
- O Inspection reports, IE Bulletins & correspondence
- B210070007 Responds to FDIA request for eight categories (*) 26.7 is steam generators & steam turbines App A documents provines in R Udell FOIA Request 81-313 Forwards documents issues 14 App B FELTON, J. M Division of Rules and Records. B2/00/10 10-42 4 Hinthrop, Stimson, Putnam & Roberts 9pp. 15645 063 245 Fiche 50-000, 82/08/10, 8210070007
- ---B210070137 Forwards tabulated data on steam generator implies facilities. Data should be provided to licenses IPPDLITG.T. Operating Reactors Assessment Branch \$7.54 & VARQA:S Operating Reactors Branch 1 5pp | 15645 121 34 Fiche. 50-000, B2/0B/10, B210070007.

- --8210070172 Forwards info re steam generator integrity & insps at all operating PURs.per 750320 & 21 requests Details of insps. including defect indications, tube plugging criteria tubes plugged will not be provided except for Point Beach 1. GOLLER.K R Division of Reactor Licensing (NRR-1975 only) 75/03/24 MACCARY.R R. Division of Technical Review (NRR-1975 only) 5pp 15645 196 24X Fiche 50-000.82/08/10.8210070007
- 8210040345 Forwards IE Insp Repts 50-282/82-15 & 50-304/82-15 on 820824-25 No noncompliance noted PAPERIELLO, C. J. Division of Emergency Preparedness & Operational Support 82/09/10 LARSON, C. E. Northern States Power Co. 2pp 15593 356 24% Fichs 50-282/82/09/10,8210040345,
- --8210040354 IE Insp Repts 50-282/82-15 & 50-306/82-15 on 820824-25 No noncompliance noted Major areas inspected previous deficiencies in prompt notification/warning ays PATTERSON, J P , AXELSON, M L Division of Emergency Preparedness & Operational Support 82/09/09, 4pp 15593 358 24X Fiche 50-282,82/09/10,8210040345
- 8210130553 Forwards "Inservice Insp-Exam Summary, Prairie Island Nuclear Generating Plant-Unit II.820601-0709" HUSDLF.D Northern States Power Co 82/10/05 Office of Nuclear Reactor Regulation, Director ip 15683 118 24X Fiche-50-304,82/10/05,8210130563
- --9210130566 Inservice insp rept on 820601-0709 Rept summarizes exam results of balance-of-plant & eddy current exam of steam gamerator tubing ANDERSON. N T , SCHANEN, J F , DARLMAN, L C Northern States Power Co. 82/09/15 180pp 15683 119 24% Fiche 50-306, 82/10/05, 9210130563
- 6208190233 IE Info Notice 80-35, Suppl 1, "Leaking & Dislodged I-125 implent Seeds " Svc list encl COBB.L I Division of Fuel Facilities, Materials & Safeguards 622/10/06 Consolidated Edison Co of New York & Spp 15761 250 24X Fiche 50-000,82/10/06,6208190233
- 82:0190432 Ack receipt of 820915 ltr informing NRC of steps taken to correct violations noted in 1E Insp Repts 50-282/82-11 & SO-304/82-11 SPESSARD.R L Division of Project & Resident Programs 82/10/07 LARSON.C E Northern States Power Co ip. 13741 182 24X Fiche 50-282,82/10/07,8210190432
- --8210190439 Responds to NRC 820817 ltr re violations noted in IE Insp Repts 50-282/82-11 & 50-306/82-11 Corrective actions startup program changed to normalize flux difference channels LARSON.C E Northern States Power Co 82/09/15 BTREGTER.J F Division of Project & Resident Programs 2pp 15741 183 24X Fiche 50-282,82/10/07.8210190432
- 6210150249 Ack receipt of 820928 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-282/82-13 & 50-306/82-13
 STREETER. J F Division of Project & Resident Programs 82/10/08 LARBON, C. E Northern States Power Co. 1p 15704 361. 24% Fiche 50-282,82/10/08,8210150249
- --8210150235 Responds to NRC 820902 ltr re violations noted in IE Insp Repts 50-282/82-13 & 50-306/82-13 Corrective actions diesel generator test procedures will be revised by 821201 & investigative rept will be discussed w/operators LARSON.C E Northern States Power Co 82/09/28 STREETER, J F Division of Project & Resident Programs 2pp 15704, 362 24X Fiche. 50-282, 82/10/08, 8210150249
- 8210280144 Forwards IE Insp Repts 50-282/82-16 & 50-304/82-16 on 820701-17 & notice of vigiation STREETER, J. F. Division of Project & Resident Programs 82/10/13 LAREON.C. E. Northern States Power Co 2pp 15837 177. 24X Fiche, 50-282, 82/10/13, 8210280144
- --8210280171 IE Insp Repts 50-282/82-16 & 50-304/82-16 on 820901-17.

 Noncompliance noted failure to post no smoking sign in safety-related quipment areas & operators found smoking.

 DUBRY: N E., REYEB.L Division of Project & Resident Programs 82/10/12. App. 15837-202 24X Fiche. 50-282, 82/10/13, 8210280164
- 8208190238 IE Bulietin 82-03, "Stress Corrosion Cracking in Thick-Wall, Large-Diameter, Stainless Steel, Recirculation Sys Piping at BMR Plants, "Svc list encl DEYQUNG, R C Director's Office, Office of Inspection and Enforcement 82/10/14 Consolidated Edison Co. of New York 115pp. 13810, 125, 24X Fiche: 50-000, 82/10/14, 8208190238,

- S Reportable occurrences, LERs & related correspondence
- 8210190726 Forwards LER 82-017/03L-0 MUSDLF,D Northern States Power Co 82/10/08 Region 3, Office of Director 1p 15737-144 24X Fiche 50-306.82/10/08,8210190726
- ~-8210190745 LER B2-017/03L-0 on 820908, two undervoltage relays found to trip outside tolerance bend of 90 plus or minus 2% of nominal voltage Cause not stated Relays recallor HUNSTAD, A A Northern States Power Co. 82/10/08 Region 3, Office of Director 1p 13737 145 24% Fiche 50-306,82/10/08,8210190726
- DOCKET 50-309 MAINE VANKEE ATOMIC POWER PLANT

 F Security, medical, emergency & fire protection plans
- 8210070054 Forwards Amend 64 to License DPR-36 & notice of issuance & availability Amend requires meint of safeguards contingency & guard training & qualification plan
 HEITMER: K. L. Operating Reactors Branch 3 82/09/15 GARRITY, J H
 Maine Yankee Atomic Power Co 4pp 15646 351 24X
 Fiche 50-309, 82/09/15, 8210070054
- ~-8210070059 Amend 64 to License DPR-36.including requirement to maintain Commission approved guard training & qualification plan CLARK, R A Operating Reactors Branch 3 82/09/15 2pp 15646 355 24X Fiche: 50-309, 82/09/15.
- ~-8210070040 Notice of issuance & availability of Amend 64 to License BPR-36 CLARK.R A Operating Reactors Branch 3 82/09/15 2pp 15646 357 24X Fiche 50-309,82/09/15.8210070054
- 8210050013 Releases public version of Vol II of emergency plan FELTON.J M. Division of Rules and Records 82/09/16 Document Management Branch 1p 15622 221 24X Fiche 50-309,82/09/16,8210050013.
- ~-8210050015 Forwards public version of Vol II of emergency plan Receipt form enc! # Maine Atomic Power Co 82/08/30 EISENHUT, D O NRC -No Detailed Affiliation Given. 2pp 15622 222 24X Fiche 50-309,82/09/16,8210050013
- ~~8210050018 Public version of Vol II of emergency plan * Maine Yankee Atomic Power Co 82/07/12 21ipp 15622 224 24X Fiche 50-309,82/09/16,8210050013
- 8210210136 Forwards 1E Insp Rept 50-309/82-12 on 820726-30 No noncompliance noted ALLAN, J M Region 1. Office of Director 82/10/06 RANDAZZA, J B Maine Yankee Atomic Power Co 2pp 15766 107, 24X Fiche 30-309-82/10/26, 8210210136
- ~-8210210142 IE Insp Rept 50-309/82-12 on 820726-30 No noncompliance noted Major areas inspected followup of emergency preparendess thems from 810908-15 appraisal MOUNABLEJ. CROCKER:H W Division of Emergency Preparedness toperational Support. 82/09/30. 11pp. 15766 109 24X Fiche 50-309,82/10/06.8210210136
- 8210210313 Forwards IE Bafeguards Insp Rept 50-309/82-11 on 820719-21 & notice of violation
 MARTIN.T T Division of Engineering & Technical Programs B2/10/07
 RANDAZZA, J B Maine Yankee Atomic Power Co 2pp 15764-227 24X
 Fiche: 50~309, 82/10/07, 8210210313
- --8210210316 Notice of violation from insp on 820717-21 * Division of Engineering & Technical Programs 82/10/07 ip 15764 229 24X Fiche: 50-309, 82/10/07, 8210210313
- --8210210321 IE Bafeguards Insp Rept 50-309/82-11 on 820719-21.
 Noncompliance noted failure to establish SNM control & accounting procedures to assure that sources & detectors received, controlled, inventoried & shipped properly.
 KUBHNER, H L., CODY, A. T. Division of Engineering & Technical Programs 82/09/14 7pp. 15764, 230. 24X Fithe 50-309, 82/10/07, 8210210313
- B210130178 Ack receipt of B20527 ltr informing NRC of steps taken to correct violations noted in IE Safeguards Insp Rept 50-309/81-02 Corrective actions withheld (ref 100FR73 21). MARTIN T.T Division of Engineering & Technical Progrems B2/10/08 RANDAZZA, J.B. Maine Yankee Atomic Power Co 2pp. 15673 020 24% Fiche. 50-309, 82/10/08, 8210130178.

1.0

1 1

 Γ_1

- B210280087 Advises of recent changes to B20501 security plan, including moving portion of perimoter security fence & observation tour to provide add1 area within protected area Changes do not decrease effectiveness of plan GARRITY. J.H. Maine Yankur Atomic Power Co. 82/10/21 DENTON.H.R. Office of Nuclear Reactor Regulation. Director 1p. 15837-184 24X Fischs 50-309, 82/10/21, 8210280087
- G. Adjudicatory correspondence
- 8210050236 Response apposing NRC & util objections to Sensible HE Power 820830 addl specific contentions NRC & util stds sought to be imposed are unfairly & improperly restrictive of intervenor right to be heard MILLER.D S Sensible Maine Power HILLER.D S Miller.D S 82/09/30 Atomic Safety and Licensing Board Panel 13pp 15608 349 24X Fiche 50-309, 82/09/30, 8210050236
- B210060170 Response opposing NRC & util B20915 replies to State of ME 820830 addl contentions All contentions should be admitted Certificate of Svc encil ANRENS.P Maine, State of 82/09/30 Atomic Safety and Licensing Board Fanel 24pp 15613 240 24x Fiche 50-309,82/07/30,8210060190
- 8310080049 Forwards 10CFR2 Subpart B per 820926 request GUTIERREZ.J M Hearing Branch 3 82/10/01 MILLER.G 8 Hiller.D S 5pp 85643 030 24x Fiche 50-309.82/10/01.8210080049
- 8210130314 Answer opposing Sensible ME Power 820924 motion for clarification & mod of ASLD 820412 order on admissibility of contentions Filing is untimely & forbidden by regulations Certificate of Svc encl DIONAN.T 0. GAD.R K. Haine Vankee Atomic Power Co. DIONAN.T 0. Ropes & Gray 82/10/09. Atomic Safetic and Licensing Board Panel 4pp. 15678 151 24X Fiche 50-309,82/10/08.8210130314
- 6210150134 Forwards ASLB 820915 partial initial decision in Big Rock Point spent fuel pool amend proceeding Same procedure re EIS should be used in instant case GUTIERREZ. J M Hearing Branch 3 82/10/13 LAZO, R M . HAND, C H , MORRIS-P A Atomic Safety and Licensing Board Panel 2pp 15697 346 24X Fiche 50-309,82/10/13.8210150134
- 8210200065 Reply apposing NRC & applicant opposition to Sensible ME Power motion for util disclosure Hotiom should not be characterized as premature discovery Info requested basic & essential to proceeding Certificate of Svc encl MILLER.D S Sensible Maine Power MILLER.D S Miller.D S 802/10/13 Atomic Sefety and Licensing Board Panel 5pp 15757 201 24X Fiche 50-309/82/10/13/8210200065
- 9210150460 Response opposing Sensible HE Power 820924 motion for clarification & mod of ASLB 820412 order ruling on admissibility of Power proposed contentions Hotion merely repeats arguments already rejected Certificate of Svc encl CUTIERREZ. J H Hearing Branch 3 82/10/14 Atomic Safety and Licensing Board Panel App 15703 106 24X Fishe 50-309.82/10/14, 8210150460
- 8210240457 Forwards Safe Power for ME,EC Carrett,JB Green & J Jerabek request for issuance of show cause order to licensee MURRAY,P L Hurray, Plumb & Norray MURRAY,P L Safe Power for Maine 82/10/20 Director's Office of Africe of Inspection and Enforcement 1p. 15807 123 24X Fiche 50-309.82/10/20.8210260457
- --B210260465 Safe Power for ME,EO Garrett JB Green & J Jarabet request for issuance of show cause order to licensee Adequate financial backing must be shown to raise capital required to continue operations & to make capital investment MURRAY.P L Safe Power for Haine MURRAY.P L Murray, Plumb & Murray 82/10/20 Director's Office, Office of Inspection and Enforcement 6pg 13807 124 24% Fiche 50-307,82/10/20,8210260457
- 8210280227 Comments on ARC B21013 ltr to ASLB re contentions Decision on merits in Big Rock Point case does not affect admissibility of contentions in instant case AHRENS, P Maine. State of 82/10/20 LAZO, R M. HAND, C. H. MORRIS, P A Atomic Safety and Licensing Board Panel 3pp. 15837 083 24X Fiche 50-309, 82/10/20, 8210280227
- 8210290303 First set of interrogatories & requests for documents
 Certificate of Svc encl
 MILLER, D 8 Sansible Mains Power MILLER, D 8 Hiller, D 6
 82/10/25 Maine Yantes Atomic Power Co Spp 15853 170 24x
 Fiche 50-309, 82/10/25, 8210270303

- H General correspondence
- 8210260202 Requests response to listed questions re assignment of personnel during shutdown & nature of work personnel will be conducting at plant BARRONS. J Haine Nuclear Referendum Committee 82/10/21 CLARRYS A Operating Reactors Branch 3 lp 15804 270 24% Fiche 50-307.82/10/21,8210260202
- P Operating license stage documents & correspondence
- 8210040074 Advises that Items 1, 2 & 3 of NRC Confirmatory Action List 82-01 have been satisfied per util 820202, 22 & 0308 ltrs. Approval for facility restart requested GARRITY, J H. Waine Yankee Atomic Power Co. 82/03/12 HAYNES, 8 t. Region 1, Office of Director CLARK, R. A. Operating Reactors Erg. 3 2pp. 15581 141 24X Fiche 50-309, 82/03/12, 8210040074
- 821001000B Responds to FOIA request for 19 categories of documents in nuclear reactor events & safety problems Forwards documents listed in App A FELTON, J M Division of Rules and Records 82/06/20 UDELL.R & Critical Mass Energy Project 15pp 15727 005 24X Fiche 30-000 82/06/28/8210010008
- --8204270048 Recommends prompt attention be given to problem of file coolant pump closure stud corrosion detected at facilities Response by 820415 requested EISENHULD O Division of Licensing 82/03/24 HANAUER, 8 H. Division of 81stems Integration (post 811005) 3pp 66035 2.2 24X Fiche 50-000.82/06/28.8210010008
- 8210040077 Advises that refueling water storage tank level setpoint for automatic recirculation actuation signal should not be changed in short term.per 820727 itr OARRITY, J. H. Maine Yankee Atomic Power Co. 82/07/26 HANKS.RI Region 1, Office of Director 2pp 15581 270 24K Fiche 50-309, 82/07/28.8210040077
- 8210040217 Submits add1 info to 820727 ltr re refueling unter string tank temp upper limit & water level lower limit Reanalysis of NPBH for ECCS performance included safeguards pumps, fluid sys & calculations of piping sys

 GARRITY, J H Haine Yankee Atomic Power Co 82/07/29 INVNES IC

 Region 1, Office of Director 2pp 15583-118 24X

 Fiche 50-309, 82/07/29, 8210040217
- 8209210514 Requests add1 info re responses to NUREO-0737. Item III D 3 4. "Control Room Habitability " Response requested within 60 days of receipt of itr CLARK: R A Operating Reactors Dranch 3 82/09/01 GARRITY, J * Maine Yankse Atomic Power Co 2pp 14947 201 24X Fiche 50-309. B2/09/01.8209210514
- --B209210323 Informs of acceptability of control room habitallings on licensee responses to NUREG-0737. Item III D 3 4 Conclusion based on present plant sys & presumes implementation of effective HVAC mods MURPHY, D W Battelle Memorial Instituts, Pacific Northwest Leboratory, FIN B-2323 82/03/23 HULMAN, L 0 Accident Evaluation Branch 3pp 14947 203 24X Fiche 30-309,82/09/5. 8209210914.
- 8210050497 Forwards Amend 63 to License DPR-36, safety evaluation is notice of issuance & availability Amund changes Tech Specimaking limiting conditions for operation more restrictive increasing surveillance requirements for ventilation sys NELSON, C.C. Operating Reactors Branch 3 82/09/07 GARRITI, J. Haine Yankee Atomic Power Co. 3pp. 15626-304 24X Fiche: 50-309, 82/09/07. 8210050497.
- --B210050503 Amend 63 to License DPR-36, changing Tech Specs to site limiting conditions for operation more restrictive & increasing surveillance requirements for ventilation & filter sys.

 CLARK, R.A. Operating Reactors Branch 3 82/09/07 14;; 15626 307. 24% Fiche 50-309, 82/09/07, 8210050497
- --8210050505 Befety evaluation supporting Amend 63 to Litense PPI-7 * Office of Nuclear Reactor Regulation, Director 82/09/07 11pp 15626.321 24X Fiche, 50-309, 82/09/07, 8210050497
- --8210050509 Notice of issuance & availability of Amend 63 to little BPR-36 CLARK,R A Operating Reactors Branch 3 82/09/07 2pp 18628:332. 24X Fiche.50-309,82/09/07,8210050497

- 5210040413 Requests addl info re 810403 proposed mod to Tech Specs concerning snubber surveillance Response requested within 30 days CLARK.R A Operating Reactors Branch 3 82/09/14 GARRITY, J H Maine Vankee Atomic Power Co 2pp 15597 235 24X Fiche 50-309, 82/09/14, 8210040413
- B210040423 Advises that util response to NUREO-0737. Item II K 3 3 Reporting Relief & Safety Valve Failures & Challenges, " acceptable HEITNER, K. L. Operating Reactors Branch 3 82/09/15 QARRITY, J H Maine Yankee Atomic Power Co 2pp 15597 239 24X Fiche 50-309, 82/09/15, 8210040423
- E210070054 Forwards Amend 64 to License DPR-36 & notice of issuance & availability Amend requires maint of safeguards contingency & guard training & qualification plan
 HEITNER K L Operating Reactors Branch 3 B2/09/15 GARRITY, J H
 Maine Yankee Atomic Power Co 4pp 15646 351 24X
 Fiche 50-309, 82/09/15, 8210070054
- --8210070059 Amend 64 to License DPR-36, including requirement to maintain Commission approved guard training & qualification plan CLARK.R A Operating Reactors Branch 3 82/09/15 2pp. 15546-355 24X Fiche 50-307, 82/09/15.8210070054
- -- 8210070060 Notice of issuance & availability of Amend 64 to License OLARK, R A Operating Reactors Branch 3 82/09/15 2pp 15646 357 24X Fiche 50-309,82/09/15.8210070054
- 8210250267 Forwards audit rept re procedures & training on pressurised thermal shock containing specific recommendation for training program Requests summary of plans in response to recommendations within 45 days
 CLARK.R A Operating Reactors Branch 3 82/09/23 GARRITY, J H
 Haine Yankee Atomic Power Co 34pp 15807 341 24X
 Eiche 50-200 23/09/23 82/00/2007 Firhe 50-309, 82/09/23, 8210250267
- @210060171 Application for amend to Tech Specs App A re Cycle 7 core performance analysis RANDAZZA, J B Maine Yankee Atomic Power Co 82/09/29 Of Nuclear Reactor Regulation, Director 3pp 15614 068 24X Of fice of Fiche 50-309, 82/09/29, 8210060171
- -8210060173 Proposed changes to Tech Specs re Cycle 7 core performance
 - * Maine Yankee Atomic Power Co 82/09/29 35pp 15614 071 24X Fiche 50-309,82/09/29,8210060171
- B210290160 Notification of changed location for B21013 meeting w/utils in Bethesda, ND to discuss Cycle 7 reload package HEITNERK L. Operating Reactors Branch 3 B2/10/05 CLARK, R A Operating Reactors Branch 3 ip 15876 228 24x Fiche 50-309, 82/10/05, 8210290160
- B210270165 Notification of B21013 meeting w/utils in Bethesda,MD to discuss Cycle 7 reload package HEITMERK L Operating Reactors Branch 3 B2/10/05 CLARK, R A Operating Reactors Branch 3 2pp 15866 360 24X Fiche 50-309,82/10/05,8210270165
- 8210130252 Proposed Change 94 to License DPR-36.App A Mod renders RCB power-operated relief valves temporarily inoperable during hydrostatic testing when setpoint approached Approval requested prior to startup of Cycle 7
 RANDAZIA-J B Haine Yankee Atomic Power Co 82/10/07 CLARK,R A Operating Reactors Branch 3 3pp 15678 042 24X perating Reactors Branch 3 3pp 15678 042 24X iche 50-309.82/10/07.8210130252
- --8210130254 Proposed Tech Spec Pages 3 3-1 through 3 3-3-rendering RCS power-operated relief valves temporarily inoperable during hydrostatic testing when setpoint approached # Haine Yankee Atomic Power Co 82/10/07 3pp 15678 045 24X Fiche 50-309.82/10/07.8210130252
- 8210130283 Processed Change 95 to License DPR-36-modifying Tech Specs 210:30:203 Proposed Change 75 to License DPR-30-modifying leck apecs to satisfy generic concerns re containment purge & vent sys & tests required to verify valve operability for on-line purge & leakage rate of isolation valves RANOAZZA. J. B. Maine Yantee Atomic Power Co. 82/10/07 CLARK,R A. Operating Reactors Branch 3 3pp 15678:297 24X Fiche 50-309.82/10/07.8210130283
- ~-8210130286 Proposed Tech Spec changes re containment purge & vent sys L tests required to verify valve operability for on-line purge & leakage rate of isolation valves + Maine Yankee Atomic Power Co 82/10/07 5pp 15678 300 24X Fiche 50-309, 82/10/07.8210130283

- 8210130360 Application to amend App A of License DPR-36.consisting of Proposed Change 92, modifying Tech Specs to restrict operations when reactor protective sys channels & ESF operations when reactor protective sys themself & Ebractuation sys sensors bypassed.

 RANDAZZA.J B Maine Yanker Atomic Power Co. 82/10/07 CLARK.R A Operating Reactors Branch 3 2pp 15679 117 24X

 Fiche 50-309, 82/10/07, 82
- --8210130369 Proposed changes to Tech Spec 3 9 restricting operations when reactor protective sys channels & EBF actuation sys sensors bypassed
- 8210270008 Forwards Revision 2 to "Inservice Insp & Testing Program" GARRITY.J H Maine Yankee Atomic Power Co 82/10/12 CLARK.R A Operating Reactors Branch 3 ip 15822 134 24X Fiche 50-309.82/10/12.8210270008
- --8210270007 Revision 2 to "Inservice Insp & Testing Program"

 JONES, D.L. Maine Yankee Atomic Power Co. 82/09/21 133pp
 15822 135 24X Fiche 50-309, 82/10/12,8210270008
- 6210220203 Forwards addl info re "Environ Qualification of Sefety-Related Electrical Equipment," Item A 1 HM W/a encl OARRITY.J H Maine Yankee Atomic Power Co 82/10/18 CL6 Operating Reactors Branch 3 3pp 15776:354 24X Fiche 50-309,82/10/18,8210220203 CLARK, R A
- 82:0250098 Clarifies NUREO-0737. Item II B 4 1, "Training for Mitigating Core Damage." per NRC 820914 request All replacement licensed operators & shift technical advisors receive OARRITY.J H Maine Yankee Atomic Power Co 82/10/ Operating Reactors Branch 3 2pp 15787 109 24X Fiche 50-309,82/10/18,8210250078 82/10/18 CLARK, R A
- 8210220212 Informs that saturation monitor upgrading delayed due to equipment availability Rosembunt resistance temp detectors (RTD) will be used in conjunction w/ateam tables to provide adequate backup in case of loss of RTD indication OARRITY.J H Maine Yankee Atomic Power Co. 82/10/19 CLARK.R A. Operating Reactors Branch 3 2pp 15776-229 24X Fiche 50-309, 82/10/19, 8210220212
- 8210260420 Advises that installation of isolation valves in letdown, steam generator blowdown & auxiliary steam lines will not be completed during 1982 refueling due to late squipment delivery. Installation to be completed by next outage OARRITY, J H Maine Yankee Atomic Power Co. 82/10/21 CLARK, R A Operating Reactors Branch 3 p. 15806 314 24X Fiche 50-309, 82/10/21, 8210260420
- 821028016: Advises that seismic design review re auxiliary feedwater sys seismic qualification will not be completed as committed to in util 810805 ltr but in accordance w/plan presented in util 820621 ltr.

 QARRITY, J H Maine Yankee Atomic Power Co 82/10/22 CLARK, R A Sperating Reactors Branch 3 p 15837:209 24X Fiche 50-309,82/10/22,8210280161.
- O Inspection reports, IE Bulletins & correspondence
- 82:007:0007 Responds to FOIA request for eight catagories of records re steam generators & steam turbines App A documents provided in R_Udell FOIA Request 81-313 Forwards documents listed in App B FELTON: J M FELTON, J M Division of Rules and Records 82/08/10. LONG, D. J Winthrop, Btimson, Putnam & Roberts. 9pp 15645 063 24X Fiche: 30-000, 82/08/10, 8210070007
- --9210070172 Forwards info re steam generator integrity & insps at all operating PMRs.per 750320 & 21 requests Details of insps. including defect indications, tube glugging criteria & tubes glugged will not be provided except for Point Beach (). OOLLER.K R Division of Reactor Licensing (NRR-1975 only) 75/03/24 MaCCARV.R. Division of Technical Review (NRR-1975 only) 5pp. 15645.196 24X Fiche 50-000.82/08/10.8210070007.
- 82:0070357 Forwards IE Enforcement Conference Rept 50-309/82-14 on 820602 & 0714 No noncompliance noted Enforcement action pending & will be forwarded under separate cover.
 8TAROSTECKI.R Division of Project & Resident Programs 82/09/20 RANDAZZA.J B Maine Yankee Atomic Power Co 2pp 15634 062 24X Fiche. 50-309. 82/09/20, 82:0070357.
- --8210070381 IE Enforcement Conference Rept 50-309/82-14 on 820602 & 0714. No noncompliance noted, Major areas discussed NRC concerns re design change control & event reporting weaknesses identified in IE Insp Rept 50-309/82-05. SHETLAND, P. GALLO, R. Division of Project & Resident Programs 82/09/09, 2pp. 15634 064. 24X Fiche. 50-309, 82/09/20, 8210070337

- 8210060302 Responds to 820708 request for add1 info re control slament assembly & fuel assembly fretting wear inspa QARRITY, J H Haine Yankss Atomic Power Co. 82/07/28 CLARK, R A Operating Reactors Franch 3 4pp 15617 202 24X Fiche, 50-307, 82/07/28, 8210060302
- 8210150398 Forwards response to NRC request for add1 info re IE Bulletin 80-11, "Masonry Wall Design " All required mods installed by 820301. Math error detected which requires strengthening of wall will be accomplished at 1982 outage OARRITY, J H Maine Yankee Atomic Power Co 82/09/30 CLARK, R A Operating Reactors Branch 3 78pp 15703 286 24x Fiche 50-309, 82/09/30, 8210150398
- 820B190233 IE Info Notice 80-35, Suppl 1, "Leaking & Dislodged I-125 Implant Seeds " Svc list encl COBB.L I Division of Fuel Facilities, Materials & Safeguards 82/10/06 Consolidated Edison Co of New York & Sopp 15761 250 24X Ficha 50-000.82/10/06.8208190233
- 8210210136 Forwards IE Insp Rept 50-309/82-12 on 820726-30 No noncompliance noted ALLAN, J H Region 1, Office of Director B2/10/05 RANDAZZA, J B Maine Yankse Atomic Power Co 2pp 15766 107 24x Fiche 50-309, 82/10/06, 8210210136
- --B210210142 IE Insp Rept 50-309/82-12 on B20726-30 No noncompliance noted Major areas inspected follows of emergency preparandass items from B10908-15 appressal.

 HUNAS: E.J., CROCKER: H.W. Division of Emergency Preparedness & Operational Bupport B2/09/30 11pp 15766-109 24X

 Fiche 50-309.82/10/06.8210210136
- 8210210313 Forwards IE Safequards Insp Rept \$0-309/82-11 on 820719-21 to notice of violation

 KARTIN:T T Division of Engineering & Technical Programs E2/10/07

 RANDATZA:J B Maine Yantes Atomic Power Co 2pp 15764 227 24X

 Fichs 50-309:82/10/07:8210210313
- --8210210316 Notice of violation from insp on 820719-21

 * Division of Engineering & Technical Programs 82/10/07 ip 15764 229 24% Fiche 50-309.82/10/07.8210210313.
- --8210210321 IE Bafeguards Insp Rept 50-309/82-1t on 820719-21
 Noncompliance noted failure to establish SAM control &
 accounting procedures to assure that sources & detectors
 received controlled, inventoried & shipped properly
 KUSHMER.M.L., ODDY, A.T. Division of Engineering & Technical
 Programs 82/09/14 7pp. 15764-230. 24X Fiche 50-309,82/10/07,
 8210210313
- 8210130178 Ack receipt of 820327 itr informing NRC of steps taken to correct violations noted in JE Safeguards Insp Rept 50-309/81-02 Corrective actions withheld (ref 1007873 21). HARTINIT T. Division of Engineering & Technical Programs 82/10/08 RANDAZZA, J B. Mains Vanies Atomic Power Co 2pp 15673 020 24% Ficher 50-309, 82/10/08, 8210130178
- 821027000B Forwards Revision 2 to "Inservice Insp & Testing Program" GARRITY.J.H Mains Yankse Atomic Power Co 82/10/12 CLARK.R A. Operating Reactors Branch 3 1p 15822 134 24X Fichs 30-309, 82/10/12, 821027000B.
- --8210270009 Revision 2 to "Inservice Insp & Testing Program"
 JONES,D L. Maine Yankes Atomic Fower Co. 82/09/21, 133pp
 15822.135 24K Fiche.50-309,82/10/12,8210270008
- 8208190238 IE Bulletin 82-03, "Stress Corrosion Cracking in Thick-Well, Large-Diameter, Stainless Steel, Recirculation Sys Fiping at BWR Plants, " Svc list encl. DEYOUNG.R.C. Director's Office of Inspection and Enforcement. 82/10/14 Consolidated Edison Co of New York 115pp. 15810-125. 24X Fiche 50-000,82/10/14,8208190238
- 8210260144 Forwards addl info re IE Bulletin 80-11. Two addl mesonry walls identified in fuel bidg One wall located south of spent fuel pool & one wall adjacent to ventilation penthouse. Design adequacy will be re-evaluated.

 OARRITY. J. H. Maine Yankee Atomic Power Co 62/10/21. CLARK. R. A Operating Reactors Franch G. 2pp. 15799. 089. 24x

 Fiche 50-309. 82/10/21. 8210260144
- S Reportable occurrences. LERs & related correspondence
- 8210270165 Forwards LER 81-005/03L-0 WOOD,E C Haine Yankee Atonic Power Co 81/05/26 Region 1, Philadelphia, Upics of the Director (81/03/01), ip. 15822, 255 24X Fiche*50-209, 81/05/26, 8210270165

- --B210270177 LER Bi-005/03L-0 on Bi0509, one of three RAS actuation switches failed to close Caused by matl incompatibility Switch replaced w/improved model utilizing stainless sizel in place of brass w Haine Yantes Atomic Power Co 81/05/26 Region 1, Philadelphia: Office of the Director (81/03/01) ip 15022 356 24X Fiche 50-309,81/05/26.8210270165
- 8210290267 Part 21 deficiency rept re potential galling problem Selit stem & bonnet of 1 25-inch & larger A105 carbon steel & A182-F22 valves supplied Feb 1981-Aug 1982 Valves should be serviced & stem &/or bonnet replaced ISABELLE.L D Conval. Inc 82/10/11 HAYNES.R C Region | . Cit of Director 17pp 15854 232 24X Fiche 50-000.82/10/11, 82/10290267
- 8210210015 Forwards LER 82-027/03L-0

 M000.E C Maine Yankee Atomic Power Co 82/10/12 Region I, i
 Office of Director Ip 15766 021 24x Fiche 50-309,82/10/12,
 8210210015
- ---8210210019 LER 82-027/03L-0 on 920929, containment isolation illivities afety injection actuation signal steam generator bloudoun valve BD-T-027 failed to fully close Caused by loose scree lodged between disk & seating surface Parts replaced NELSON,R H Maine Vankee Atomic Power Co 82/10/12 Requiril Office of Director 1p 15766 022 24X Fiche 30-309,62/10/12 R210/10/13
- B210260193 Forwards LER 82-026/03L-0
 WDDD,E C Maine Yankse Atomic Power Co B2/10/18 Region 1.
 Office of Director ip 15804 272 24X Ficha 50-309,02/10/18
 8210260193
- --B210260200 LER 82-026/03L-0 on B20924 one steam generator safity a failed to operate & two valves operated above Tech Byrc limits during test Caused by instrument drift Cause of instrument drift unknown NELSON.R H Haine Yankee Atomic Power Co 62/10/10 Replice of Director 2pp 15804 273 24X Fiche 50-309.62/10.1 R210260193
- 8210260199 Forwards LER 82-028/03L-0 WOODLE C Maine Yankee Atomic Power Co 82/10/18 Region t Office of Director 1p 15799 148 24X Fiche 50-309,02/10/18 8210260199
- --8210260208 LER 82-028/03L-0 on 820929, containment isolation sign, reset resulted in unexpected opening of control element drive mechanism cooler return valve Caused by open colf in Agastat ESF reset panel valve suitch control reliay NELSON: R H Maine Yankse Atomic Power Co 82/10/18 Regist Office of Director 2pp 15799 149 24X Fiche 50-309,82/12 (8210260199
- 8210260327 LER 82-029/01T-0 scheduled eddy current tests of stars generator 2 tubes revealed small number of tubes ecceeding tube plugging limit
 OARRITY.-J H. Maine Yankee Atomic Power Co 82/10/18 Fagits Office of Director 1p 15801.362 24X Fiche 50-309,82/10/18 8210260387.
- 82:0290343 LER 82-029/017-1 eddy current tests on steam generaler? tubes revealed 10 tubes exceeding tube plugging limit Caver? by short radius bend tube degradation Condition also reported by similar C-E plant OARRITY. J H Maine Yankee Atomic Power Co 82/10/19 Rigisal Office of Director ip. 15853 028 24X Fiche 30-309,82/10/19 Regionard
- DOCKET 50-311 BALEM NUCLEAR GENERATING STATION, UNIT 2
 F Security, medical, emergency & fire protection plane
- 8210250245 Forwards 1982 FEMA/NRC observed exercise scenaric for & exercise Revisions reflect changes agreed upon during 82040 meeting w/NRC & FEMA ZUPKO, J. H. Public Service Electric & Qas Co. of New Jerses 82/09/16. HAYNEGR C. Region i. Office of Director 149;t 15789:002 24X Fiche 50-272, 82/09/16.8210250245
- 8210260518 Forwards exemption from requirements of 100FR30 48 ferrorection of safe shutdown capability VAROA.S.A. Operating Reactors Branch 1. 82/09/16 U0ERITALE Public Service Electric & Cas Co. of New Jersey 3pp 19806 H
- --8210260521 Exemption from requirements of 10CFR50 48 refire 1th of safe shutdown capability.
 EISENHUT, D. Q. Division of Licensing 82/09/16 Public BerElectric & Gas Co of New Jersey. 4pp. 15830 171 241
 Fiche: 50-272, 82/09/16, 8210260518.

- --9210269524 Safety evaluation supporting licenses request for exemption from requirements of 10CFR50 48 re fire protection of safe shutdown capability
 - # Office of Nuclear Reactor Regulation, Director 82/09/16 3pp 15830 175 24X Fiche 50-272,82/09/16,8210260518
- 9210050431 Forwards exemption from requirements of Section IV F 1 of App E to 10CFR50, to allow next full-scale emergency preparedness exercise at facility to be conducted on or about 820929, granting 820709 request VARCA.B A Operating Reactors Branch 1 82/09/23 UDERITZ, R A Public Service Electric & Gas Co of New Jersey 3pp 15636 227 24X Fiche 50-272,82/09/23,8210060431
- --8210060433 Exemption from requirements of Section IV F 1 of App E to 10CFR50.to allow next full-scale emergency preparedness exercise at facility to be conducted on or about 820929 Evaluation enci EISENHUT.D 0 Division of Licensing 82/09/23 Public Service Electric & Oas Co of New Jersey Spp 15636 230 24% Fiche 50-272,82/09/23,8210060431

P Operating license stage documents & correspondence

- B21003000B Responds to FOIA request for 19 categories of documents re nuclear reactor events & safety problems Forwards documents Listed in App A FELTON.J M Division of Rules and Records 82/06/28 UDELL.R A Critical Mass Energy Project 15pp 15727 005 24X Fiche 50-000.82/06/28.8210010008
- --8008050265 Discusses add1 required into to better define potential for cracking in reactor vessel noizles
 NDONAN, V 6 Assistant Director for Materials & Qualifications
 Engineering 80/05/05 TEDESCOR L Assistant Director for
 Licensing 2pp 15727 176 24X Fiche 50-000, 82/06/28, 8210010008
- --0203310087 Forwards memo re equipment malfunctions during 920114 turbine load reduction operation Following review of final rept from licensee & Region 1, will complete evaluation of event for generic implications MICHELON.C Director's Office 82/03/15 JORDAN.E L Division of Engineering & Quality Assurance ip 15745 050 24X Fiche 50-000.82/06/28.8210010008
- --8203310074 Summary of 820204 meeting re evaluation of sequence of events of Salem 820114 load reduction transient operators actions.lessons learned & future remedial actions to be taken
 TREMAN, N. K. Director's Office 82/02/22 MICHELBON, C. Director's Office 2pp 15734 034 24X Fiche 30-000.82/06/28, B210010008
- 8210050485 Forwards documentation of satisfactory completion of requirements contained in 790921 ltr re TMI Action Item II E i concerning auxiliary feedwater sys VARGA: S A Operating Reactors Branch I 82/09/20 UDERITZ, R A Public Service Electric & Oas Co of New Jersey 3pp. 15626 277 24% Fiche 50-272,82/09/20,8210050485
- --82±0050490 "Suppl to Bafety Evaluation Rept for Salem Units 1 & 2 Implementation of Recommendations for Auxiliary Feedwater Eys"

 Office of Nuclear Reactor Regulation, Director 82/09/20 3pp 15626 280 24X Fiche 50-272.82/09/20,8210030485
- B2:0130603 Advises that installed monitoring sys required by TMI Action I Eams II F 1 4-II F 1 5 & II F 1 6 acceptable & Items considered closed VARDA: S A Operating Reactors Branch I 82/09/20 UDERITZ, R A Publit Service Electric & Oas Co of New Jersey 2pp. 15672,347 24x Fichs 50-270.82/09/28.8210130603
- B210170047 Informs that util rod exchange methodology not approved because of calculational content of reactivity measurement New submittal or return to boron dilution method requested. VARGA: SA Operating Reactors Branch 1 B2/09/29 UDERITZ, RA Public Service Electric & Gas Co of New Jersey 3pp 15761 041 24X Fiche 50-272,82/09/29.8210190047
- 8210190507 Application for amend to Licenses DPR-70 & DPR-75, revising core limits, fractional thermal power factor limit, performance of RCS water inventory belance & boron concentration & contained vol limits.

 LIDEN.E A Public Service Electric & Gas Co of New Jersey 82/10/05 VARQA, S A Operating Reactors Branch 1 2pp 15863, 124 24X Fiche 50-272, 82/10/05, 82/0190507.

- ~-8210190515 Proposed Tech Space supporting application to amend Licenses DPR-70 & DPR-75 revising core limits, fractional power factor limit, performance of RCS water inventory balance & boron concentration & contained vol limits Public Service Electric & Oas Co. of New Jersey 82/10/05 17pp 1983 128 24X Fiths 50-272,82/10/05,8210190507
- 8210270136 License Change Requests 82-17-20-21 & 22 to Licenses DPR~70 & DPR-75 Changes involve inservice imap of snubbers.steam generator insp ports.containment ventilation valve (nep & surveillance functional testing LINDEN.E A Public Service Electric & Oas Co of New Jersey 82/10/07 VAROA.B A Derating Reactors Branch 1 3pp 15807 026 24X Fiche 50-272,82/10/07,8210270136
- ~-8210270142 Proposed Tech Spec changes re inservice insp of snubbers, installation of steam generator insp ports, pressure drop test & reactor trip instrumentation # Public Service Electric & Gas Co of New Jersey 82/10/07 8pp 15827 029 24% Fiche 50-272.82/10/07.8210270134
- 8210180007 Advises that design changes satisfying concerns expressed in 820917 request for addlinfo re reactor protection sys/E8F actuation sys initiated Tech Specs will be modified to address setpoint changes
 LIDEN,E A Public Service Electric & Oas Co of New Jersey
 82/10/08 VAROA,B A Operating Reactors Branch 1 ip 15720 024
 24X Fiche 50-272.82/10/08.821018D007
- 6210270352 Forwards Amends 48 & 13 to Licenses DPR-70 & DPR-75, respectively, safety evaluation & notice of issuance & availability Amend revises process & effluent monitors to agree w/existing plant conditions
 ROSS: W J Operating Reactors Branch i 82/10/18 UDERITZ,R A Public Service Elactric & Oas Co. of New Jersey 2pp 15834-318 24X Fiche, 50-272, 82/10/18, 8210270352
- --8210270355 Amends 48 & 13 to Licenses DPR-70 & DPR-75 respectively, revising process & effluent monitors to agree w/existing plant conditions VAROA. S A Operating Reactors Branch i 82/10/18 14pp. 15834 320 24X Fiche 50-272,82/10/18,8210270352
- --8210270360 Safety evaluation supporting Amends 48 & 13 to Licenses DPR-70 & DPR-75, respectively 4 Office of Nuclear Reactor Regulation, Director 82/10/18 6pp 15834 334 24X Fichs 50-272,82/10/18,8210270352
- --B210270366 Notice of issuance & availability of Amends 48 & 13 to Licenses DPR-70 & DPR-75, respectively VAROA.S A Operating Reactors Dranch 1 B2/10/18 2pp 18834 340 24% Fiche 80-272, 82/10/18,8210270352
- Q Inspection reports, 16 Bulletins & correspondence
- 8210080015 Add1 response to FOIA request for 17 categories of info re nuclear reactor events & safety problems. Forwards documents listed in App A Documents in App B completely withheld (ref FOIA Exemption 5).
 FELYON, J. M. Division of Rules and Records 82/07/12 UDECL, R. A. Critical Mass Energy Project 9pp 15665 027 24%
 Fiche 50-000, 82/07/12, 8210080015
- ---8210080150 Systematic assessment of licensee performance notes refacility evaluation for Sept 1979-Aug 1980

 * NRC No Datelied Affiliation Given 80/08/31 Spp 15668 043 24X Fiche-50-000,82/07/12.8210080015
- 8210070007 Responds to FOIA request for eight categories of records resteam generators & steam turbines App A documents provided in R Udell FOIA Request 81-313 Forwards documents listed in App B.
 FELTON, J H Division of Rules and Records 82/08/10, LONG, D J Winthrop, Stimson, Putnam & Roberts. 9pp 13645 063 24% Fiche 50-000, 82/08/10, 8210070007
- ~-B210070139 Forwards tabulated data on steam generator insp & maint at facilities Data chould be provided to licensees IPPOLITO.T Operating Reactors Assessment Branch. \$2/04/01, VAROA.B Operating Reactors Branch 1. 5pp. 15645.131, 24X Fiche 50-000,82/08/10,8210070007.
- 8210120328 Responds to violations noted in IE Insp Repts 50-272/82-17 & 50-311/82-17 on 820707-0803, Corrective actions administrative procedure will be revised so future temporary design changes are removed on timely basis UDERITY. RA Public Service Electric & Oas Co. of New Jersey. 82/09/28. HAYNES, RC Region 1, Office of Director. 87ARDSTECKI, R Division of Project & Resident Programs. 5pp 15452:125 24X Fiche. 50-272, 82/09/28. 8210120328

- 8210060302 Responds to 820708 request for addition of control element assembly & fuel assembly fretting wear insys
 OARRITY.J H. Maine Yantse Atomic Power Co. 82/09/28 GLARK.R. A
 Operating Reactors Branch 3 490 15619 202 24X
 Fiche 50-309.82/09/28.8210060302
- 8210150398 Forwards response to NRC request for addl info re IE Bulletin 80-11, "Masonry Hell Design " All required mods installed by 820301 Math error detected which requires strangthening of well will be accomplished at 1982 outage QARRITY, J H Maine Yankes Atomic Power Co 82/09/30 CLARK, R A Operating Reactors Branch 3 78pp 15703 286 24% Fiche 50-309, 82/09/30, 8210150378
- 820Bi90233 IE Info Notice 80-35, Suppl 1: "Leaking & Dislodged I-125 implant Stads " Svc list encl COBB.L I Division of Fuel Facilities, Materials & Safeguards 82/10/06 Consolidated Edison Co of New York 66pp 13761 250 24X Fichs 50-000:82/10/06:8208190233
- 8210210136 Forwards IE Insp Rept 50-309/82-12 on 820726-30 No noncompliance noted ALLANJ H Region 1. Office of Director 82/10/06 RANDAZZA, J B Haine Yankee Atomic Fower Co 2pp 15766 107 24X Fiche 50-309:82/10/06:8210210136
- --8210210142 IE Insp Rept 50-307/b2-12 on 820726-30 Ne noncompliance noted Major areas inspected followup of energency preparendess items from 810908-15 appreisal HOUNAGE J. CRUCKER.H W Division of Emergency Preparedness & Operational Support 82/09/30 11pp 13766 109 24% Fiche 50-309, 82/10/04, 8210210136
- B210210313 Forwards IE Befeguerds Insp Rept 50-307/82-81 on 820719-21 binotice of violation in B20719-21 binotice of violation of Engineering & Technical Programs B2/10/07 RANDAZZA, J Bina Yantee Atomic Power Co. 2pp. 15764-227 24X Fiche 50-309,82/10/07.8210210313.
- --8210210316 Notice of violation from insp on 820719-21 a Division of Engineering & Technical Programs 62/10/07 ip 15764 229 24% Fiche 30-309,82/10/07,8210210313
- --8210210321 IE Safeguards Into Rept 50-309/82-11 on 820719-21 Noncompliants noted failure to establish SNN control & accounting procedures to assure that sources & detectors received controlled inventoried & shipped properly KUSHNER-H L , CODY.A T. Division of Engineering & Technical Programs 82/09/14. 7pp 15764.230, 24X Fiche-50-309.82/10/07, 8210210313
- 8210130178 Atk receipt of 820527 ltr informing NRC of steps taten to correct violations noted in IE Safeguards Imap Rept 50-309/81-02 Corrective actions withheld (ref 100FR73.21). HARTIN T T. Division of Engineering & Technical Programs 82/10/08 RANDAZZAJ S Maine Yankee Atomic Power Co 2pp 15673 020 RAX Fiche: 50-309.82/10/08,8210130178
- 821027000B Forwards Revision 2 to "Inservice Insp & Yesting Program"

 CARRITY, J H Heine Yantee Atomic Power Co 82/10/12 CLARK: R A.

 Operating Reactors Branch 3 19. 15822 134. 24X

 Fiche. 50-309-82/10/12,821027008
- ~-8210270009 Revision 2 to "Inservice Insp & Testing Program"

 JONES, D.L. Maine Yankse Atomic Power Co 82/09/21, 103pp

 19822:195, 24X Fiche: 50~309, 82/10/12, 8210270008.
- 8208190238 IE Bulletin 82-03. "Stress Corrosion Cracking in Thick-Wall, Large-Diameter: Stainlass Steal, Recirculation Sys Piping at BHR Plants " Syc list encl DEYOUNG, S. C. Director's Office: Office of Inspection and Enforcement. 82/10/14 Consolidated Edison Co. of New York 115pp. 13810:125 24X Fiche 50-000,82/10/14,8208170238
- B210260144 Forwards add1 info re IE Bulletin 80-11 Two add1 mesonry walls identified in fusi bids One wall located south of spent fuel pool & one well adjacent to ventilation penthouse Design adequacy will be re-evaluated GARRITY. J.H. Haine Yantee Atomic Power Co. 82/10/21. CLARK. R.A. Operating Reactors Branch 3. 2pp. 15799-089 24X Fiche. 50-309. 82/10/21. 8210260144.
- S Reportable occurrences, LERs & related correspondence
- B210270165 Forwards LER 81-005/031-0 WOOD, E.C. Maine Yankes Atomic Power Co. 81/05/26, Region 1, Philadelphia, Office of the Director (81/03/01) 1p. 15822: 355. 24X Fiche. 50-009, 81/05/24, 8210270165

- --9210270177 LER 81-005/03L-0 on 810509, one of three RAS attaction switches failed to close Caused by math incompatibility Suitch replaced w/improved model utilizing stain)ess ited in place of brass a Haine Yankee Atomic Power Co Bi/05/26 Region 1. Philadelphia. Office of the Director (81/03/01) ip 15022 J/224 Fitch 50-209, 81/05/26, 8210270165
- 8210290267 Part 21 deficiency rept to potential gallang problem 16's stem & bonnet of 1 25-inch & larger A105 carbon steel & A182-F22 valves supplied Feb 1981-Aug 1982 Valves should be serviced & stem &/or bonnet replaced IRABELLE, L D Convel. Inc B2/10/11 HAYNES, B & Region 1, G of Director 179p 15854 232 24X Fiche 50-000,82/10/11, 2010090067
- 8210210015 Forwards LER 82-027/03L-0 MODD.E C Maine Yankse Atomic Power Co 82/10/12 Region 1. Office of Director 1p 15766 021 24X Fichs 50-309,82/10/12 8210210015
- --9210210018 LER 62-027/03L-0 on 920929; containment isolation vira safety injection actuation signal steam generator blowicum valve 8D-7-32 failed to fully close Caused by loose treat Indeed between disk & seating surface Parts replaced NRLSON, R H Hains Yankee Atomic Power Co 82/10/12 Regulation of Director 1p 15766 022 24% Fische 30-109, 82/12/12 8210210015
- 0210260193 Forwards LER 82~026/03L-0 W000/E C Haine Yankse Atomic Power Co 82/10/10 Region & Office of Director 1p 15804 272 24% Fiche 50-309/B2/10/18 B210260193
- 8210240199 Forwards LER 82-0R8/03L-0 HODDLE C Mains Vankes Atomic Power Co 82/10/10 Region' Office of Director in 15799 148 24X Fiche 50 70% NJ/10/11
- --8210260208 LER 82-028/03L-0 on 820929, containment isolation e.g. reset resulted in unexpected opening of control element drive machanism cooler return valve Caused by open coil in Agastat EBF reset panel valve switch control relay NELBOUR R H Hains Yankse Atomic Power Co 82/10/10 Ret. Office of Director 2pp 15799.149 24X Fiche 50 NGV. 62/1/ 8210260199
- 8210260327 LER 82-029/01T-0 scheduled eddy current tests of siest generator 2 tudes revealed small number of tubes exceeding tube plugging limit OARRITY, J. H. Haine Yankee Atomic Power Co. 82/10/18 Festive of Director ip. 15801-362, 24X Fichs. 50-309-84/10/18 8210260327
- 8210290343 LER 82-029/017-1.eddy turrent tests on steam generally tules revealed 10 tubes exceeding tube plugging limit Caulil by short radius bend tube degradation Constitute also reported by similar C-E plant OARRITY.J.H. Heine Vankes Atomic Power Co. 82/10.19 Pag. Office of Director 1p. 15853 028. 24% Fiche 50-307.82/11 8210290343.
- DOCKET 50-311 BALEN NUCLEAR GENERATING STATION, UNIT 2
 F Becurity, medical, emergency & fire protection plans
- 8210250245 Forwards 1982 FEMA/NRC observed exercise scinarie full arercise. Revisions reflect changes agreed upon during 820423 , meeting w/NRC & FEMA RUPKO, J.M. Public Bervice Electric & Oas Co. of New Jerses 82/09/16. HAYNES, R.C. Region 1, Office of Director 14849 15789: 002. 24X Fiche: 50-27R, 82/09/16, 8210250245
- B210260518 Forwards exemption from requirements of 106f830 & 1117 protection of safe shutdown capability VARQA.S.A. Operating Reactors Branch 1. B2/09/16 UDEF1111 Public Gervice Electric & Oas Co of New Jerssy 3ss 1202 & 24K Fiche: 50-272, 82/09/16, 8210260518
- --8210260321 Exemption from requirements of 10CFB30 48 rr 41/2 pc. of taffs thutdown capability EIBENHUT. D 0 Division of Licensing. 82/09/16 Pastic F Eisectric & Osa Co of New Jarrey 4pp. 15830 171 \$41 Fishe: 50-272, 82/09/16, 8210260518.

- --8210269524 Safety evaluation supporting licenses request for exemption from requirements of 10CFR50 48 re fire protection of safe shutdown capability
 - Office of Nuclear Reactor Regulation, Director 82/09/16 3pp 15830 175 24X Fiche 50-272,82/09/16,8210260518
- B210050431 Forwards exemption from requirements of Section IV F 1 of App E to 100FR50 to allow next full-scale emergency preparedness exercise at facility to be conducted on or about 820929, granting 820709 request VAROA: S A Operating Reactors Branch I 82/09/23 UDERITZ, R A Public Service Electric & Oas Co of New Jersey 3pp 15636 227 24X Fiche 50-272, 82/09/23, 8210060431
- --B210060433 Exemption from requirements of Section IV F 1 of App E to 10CFR50, to allow next full-scale emergency preparedness exercise at facility to be conducted on or about 820729 Evaluation encl EISENHUT, D 0 Division of Licensing 82/09/23 Public Service Electric & Oas Co of New Jersey 5pp 15636 230 24% Fiche 50-272, 82/09/23, 8210060431

P Operating license stage documents & correspondence

- E21001000B Responds to FDIA request for 19 categories of documents re nuclear reactor events & safety problems Forwards documents listed in App A FELYON, J M Division of Rules and Records 82/06/28 UDELL,R A Critical Mass Energy Project 15pp 15727 005 24X Fische 50~000.82/06/28.821001000B
- --B008050265 Discusses addit required info to better define potential for cracking in reactor vessel hourles
 NOONAN.V S Assistant Director for Materials & Gualifications
 Engineering 80/05/05 TEDESCO.R L Assistant Director for
 Licensing 2pp 15727 176 24X Fiche 50-000.82/06/28.8210010008
- --8203310089 Forwards memo re equipment malfunctions during 820114 turbine load reduction operation Fallowing review of final rept from licenser & Region i.will complete evaluation of event for generic implications
 MICHELSON.C Director's Office 82/03/15 JORDAN, E L Division of Engineering & Quality Assurance 1p 15745 050 24X Fiche 30-000,82/06/28.8210010008
- --8203310094 Summary of 820204 meeting re evaluation of sequence of events of Salem 820114 load reduction transient, operators actions, lessons learned & future remedial actions to be taken

 TREHAN, N K Director's Office 82/02/22 MICHELSON, C
 Director's Office 2pp 15734 036 24X Fiche 50-000, 82/06/28, 8210010008
- 8210050485 Forwards documentation of satisfactory completion of requirements contained in 790921 ltr rs TMI Action Item II E 1 concerning auxiliary feedwater sys VARGA.8 A Operating Reactors Branch 1 82/09/20 UDERITZ.R A Public Service Electric & Oas Co of New Jersey 3pp 15626 277 244 Fiche.50-272:82/09/20.8210050485
- --8210050490 "Suppl to Safety Evaluation Rept for Salem Units i & 2 Implementation of Recommendations for Auxiliary Feedwater Sys "
 - Office of Nuclear Reactor Regulation, Director 82/09/20 3pp 15626 280 24X Fiche 50-272.82/09/20,8210050485
- 8210100603 Advises that installed monitoring sys required by TMI Action Items II F 1 4, II F 1 5 & II F 1 6 acceptable & items considered closed VARCAS A Operating Reactors Branch 1 92/09/28 UDERITZ, R A
- VARION 5 A Operating Reactors Branch 1 92/09/28 UDERITZ, R A Public Service Electric & Gas Co of New Jersey 2pp. 15692:349 244 Fiche 50-272,82/09/28,8210130603
- B210190047 Informs that util rod exchange methodology not approved because of calculational content of reactivity measurement New Submittal or return to boyon dilution method requested VARQA, S. A. Operating Reactors Branch 1 B2/09/29 UDERITZ, R. A. Public Service Electric & Oes Co. of New Jersey 3pp. 15761 041 24X Fiche 50-272,82/09/29,8210190047.
- 8210190507 Application for amend to Licenses DPR-70 & DPR-75, revising core limits, fractional thermal power factor limit, performance of RCS water inventory balance & boron concentration & contained vol limits
 LIDEN.E A Public Service Electric & Gas Co of New Jersey 82/10/05 VARQA: S A Operating Reactors Branch 1 2pp. 15863.124, 24X Fiche 50-272,82/10/05,8210190507

- --8210190515 Proposed Tech Specs supporting application to amend Licenses DRR-70 & DRR-75 revising core limits, fractional power factor limit, parformance of RCB water inventory balance & boron concentration & contained vol limits

 * Public Service Electric & Oas Co of New Jersey. 82/10/05
 17pp 15863 126 24% Fichs 50-272, 82/10/05, 82/10/9507
- 8210270136 License Change Requests 82-17-20-21 & 22 to Licenses DPR-70 & DPR-75. Changes involve inservice insp of snubbers, steam generator insp ports, containment ventilation valve insp & surveillance functional testing
 LINDEN.E A Public Service Electric & Gas Co of New Jersey.
 82/10/07 VARQA.E A Operating Reactors Branch 1 3pp 15827 026
 24X Fich, 50-272,82/10/07,8210270136
- --B210270142 Proposed Tech Spec changes to inservice insp of snubbers, installation of steam generator insp ports, pressure drop test & reactor trip instrumentation # Public Service Riectric & Oas Co of New Jersey 82/10/07 8pp 15827 029 244 Fiche 50-272, 82/10/07.8210270136
- 8210180007 Advises that design changes satisfying concerns expressed in 820917 request for addl info re reactor protection sys/E6F actuation sys initiated Tech Specs will be modified to address setpoint changes
 LIDEN,E A Public Service Electric & Oas Co of New Jersey
 82/10/08 VARQA,S A Operating Reactors Branch 1 lp 15720.024
 24X Fiche 50-272.82/10/08.8210180007
- 8210270352 Forwards Amends 48 & 13 to Licenses DPR-70 & DPR-75, respectively, safety evaluation & notice of issuance & availability Amend revises process & effluent monitors to agree w/existing plant conditions.

 ROSB: W J Operating Reactors Branch I 82/10/18 UDERITZ, R A Public Service Electric & Oas Co. of New Jersey 2pp 19834 318 24X Fiche 50-272,82/10/18,8210270352
- --8210270355 Amends 48 & 13 to Licenses DPR-70 & DPR-75, respectively, revising process & effluent monitors to agree w/existing plant conditions VAROA:8 A Operating Reactors Branch 1. 82/10/18 14pp 15834 320 24X Fiche 50-272, 82/10/18,8210270352
- --8210270360 Safety evaluation supporting Amends 48 & 13 to Licenses DPR-70 & DPR-75, respectively * Office of Nuclear Reactor Regulation, Director 82/10/18, App. 15834 334 24X Fichs 50-272.62/10/18,8210270352
- --8210270366 Notice of issuance & availability of Amends 48 & 13 to Licenses DPR-70 & DPR-75, respectively VAROA, B A Operating Reactors Branch 1 82/10/18 2pp 15834 340 24% Fiche: 50-272, 82/10/18,8210270352
- Q Inspection reports: IE Bulletins & correspondence
- 8210080015 Add1 response to FOIA request for 17 categories of info re nuclear reactor events & safety problems Forwards documents listed in App A Documents in App B completely withheld (ref FOIA Exemption 5)
 FELTON.J M. Division of Rules and Records, 82/07/12 UDELL.R A Critical Mass Energy Project 9pp 15665:027 24X
 Fiche 50-000.82/07/12.8210080015
- --8210080180 Systematic assessment of licensee performance notes re facility evaluation for Sept 1979-Aug 1980 • NRC - No Detailed Affiliation Given 80/08/31 Spp 15668 043 24X Fiche:50-000, 82/07/12, 8210080015
- 8210070007 Responds to FOIA request for eight categories of records resteam generators & steam turbines. App A documents provided in R Udell FOIA Request Bi-313 Forwards documents listed in App B FELTON J. M Division of Rules and Records. 82/08/10. LONG. D J. Winthrop. Stimson, Putnew & Roberts, 9pp. 15645-063 24X Fichs 50-000, 82/08/10, 8210070007
- --B210070139 Forwards tabulated data on steam generator insp & maint at Accilities. Data should be provided to licensees.

 IPPOLITO.T. Operating Reactors Assessment Branch 82/04/01.

 VAROA.B. Operating Reactors Branch 1 3pp 15645:131 24X

 Ficher 50-000,82/08/10.8210070007
- 8210120328 Responds to violations noted in IE Insp Repts 50-272/82-17 to 50-311/82-17 on 820707-0803 Corrective actions. administrative procedure will be revised so future temporary design changes are removed on timely basis.

 UDERITZ.R.A. Public Bervice Electric & Ges Co. of New Jersey.

 82/09/28 HAYNES.R.C. Region 1, Diffice of Director STAROBIECKI.R.
 Division of Project & Resident Programs. Spp. 15652, 125 24X

 Fichs 50-272, 82/09/28, 8210120328

14

1

1 ,

| 1

11

- B20B190233 IE Info Notice 80-33, Suppl 1: "Leating & Dislodged I-125 Implant Seeds " Syc list encl COBB.t I Division of Fuel Facilities, Materials & Safeguards 82/10/06 Consolidated Edison Co of New York 65pp 15761 250 24X Fiche 50-000.82/10/06, 920B190233
- 8210210435 Forwards IE Insp Repts 50-272/82-20 & 50-311/82-20 on 820814-20 No noncompliance noted MARTIN.T T. Division of Engineering & Technical Programs 82/10/06 UDERITZ.R A public Service Electric & Gas Co of New Jersey 2pp 15763 036 24x Fiche 50-272,82/10/06,8210210405
- --8210210451 IE Insp Repts 50-272/82-20 & 50-311/82-20 on 820816-20 No noncompliance noted Hajor areas inspected qualification & training radiological surveys radiation exposure permits, posting. If censee audits & exposure control HOSEY. C M. ROWE, C A. GREENHAN, E Q. Division of Engineering & Tachnical Programs 82/09/30 Spp 15763 OSB 24X Fiche 50-272,82/10/06.8210210435
- 8210210464 Forwards IE Insp Repts 50-272/82-25 & 50-311/82-24 on 920901-27 & notice of violation STAROBIECKI.R Division of Project & Resident Programs. 82/10/06 UDERITI.R A Public Service Electric & Gas Co of New Jersey 2PP 15763 018 24X Fiche 50-272,82/10/06,8210210464
- --8210210469 Notice of violation from insp on 820901-27 ** Region 1, Office of Director 82/10/06 ip 15763,020 24X Fichs-50-272,82/10/06,8210210464
- --8210210477 IE Insp Repts 50-272/82-25 & 50-311/82-24 on 820901-27
 Noncompliance noted trip breaters closed w/o two operable
 source range instruments in svc & failure to submit 30-day
 LER
 NORRHOLH, L. J. SUMMERS, R. TRIPP, L. E. Division of Project &
 Resident Programs 82/10/04 i5pp 15763 921 24X
 Fiche 50-272,82/10/06,8210210464
- B210270136 License Change Requests B2-17-20-21 k 22 to Licenses DPR-70 k DPR-75 Changes involve inservice insp of snubbers, steam generator insp ports, containment ventilation valve insp k surveillance functional testing LINDEN, E A Fublic Bervice Electric & Gas Co of New Jersey B2/10/07 VARGAS, A Deparating Reactors Branch 1 3pp 15827 026 24X Fiche: 50-272, 82/10/07, B210270136
- --8210270142 Proposed Tech Spec changes re inservice insp of snubbers, installation of steam generator insp ports, prossure drop test is reactor trip instrumentation

 * Public Service Electric & Gas Co of New Jersey 82/10/07

 * Bpp 15827 029. 24X Fiche 50-272,82/10/07,8210270136
- 820B19023B IE Bulletin 82-03, "Stress Corrosion Cracking in Thick-Hall.Lerge-Diameter, Stainless Steel, Recirculation Sys Piping at BMR Plants " Svc list encl. DEYOUNDER C Director's Office. Office of Inspection and Enforcement. 82/10/14. Consolidated Edison Co of New York 115pp 15810-125 24X Ficher 50-000, 82/10/14, 820819023B
- 8210280221 EN-B2-034 on 821027, notice of violation & proposed imposition of civil penalty in amount of \$40,000 issued re inadequate vital physical area berrier ROSANO.R., AXELRAD, J Director's Office, Office of Inspection and Enforcement 82/10/22 ip 15837 089 24% Fiche 50-272,82/10/22, pays 080021
- R Periodic operating reports & related correspondence
- 8210200010 Forwards monthly operating rept for Bept 1982 MIDURALH J Public Bervice Electric & Qas Co. of New Jersey. ice, Office of Inspection and Enforcement. 30-311.82/10/10.8210200010

f New Jersey. 2/10/10,8210200010

- 8210010008 Responds to FOIA request for 19 categories of documents renuclear reactor events & safety problems Forwards documents listed in App A FELTON.J N Division of Rules and Records 82/06/28 UDELL.R A Critical Nass Energy Project 15pp 15727 005 24X Fiche 30-000:82/06/28,8210010008
- --8210050124 Summary of 810610 operating reactor events meeting LAINAS.O C Assistant Director for Safety Assessment 01/06/a7 ; EIBENNUT.D O Division of Licensing 5pp 15729 217 241 Fiche 50-000, 82/06/28.8210010008
- 8210010045 Forwards LER 82-095/03L-0 Detailed event analysis encl MIDURA,H J Public Service Electric & Cas Co of New Jerrey 82/09/16 HAYNES,R C Region 1, Office of Director Spp 15565 137 24X Fiche 50-311,82/09/16,8210010045
- --8210010047 LER 82-095/03L-0 on 820831, surveillance revealed that (...
 not placed in valve 21 MS46 of auxiliary feedwater systems
 line 23 Caused by sheared off stud which attaches valve dist
 to hanger Engineering analysis conducted
 HELLER, R Public Service Electric & Cas Co of New Jersey
 82/09/16 Region 1, Office of Director 1p 15365 140 246
 Fiche 50-311,82/09/16.8210010045
- 8210010123 Forwards LER 82-092/017-0 Detailed event analysis and MIDURA: H J . HELLER: R Public Service Electric & Qas Co of New Jersey B2/09/16. HAYNES: R C Region 1. Office of Director 1,13566 014 24X Fiche 50-311.82/09/16.8210010123
- --B210010128 LER 82-092/01T-0 on 820908, svc water leak discovered at containment fan coil unit 21 Caused by erosion of motor cooling coils Motor cooler replaced & fan coil tested satisfactorily
 HELLER: R Public Service Electric & Gas Co of New Jarsey
 82/09/16 Region 1. 0ffice of Director ip 15566 010 248
 Fiche 50-311.82/09/16.8210010123
- 8210010144 Forwards LER 82-096/03L-0 Detailed event analysis and MIDURA, H J Public Service Electric & Oas Co of New Jersis 82/09/16 HAYMES, R C Region 1, Dffice of Director 3pp 15567 240 24% Fiche 50-311,82/09/16,8210010144
- --B210010150 LER 82-096/03L-0 on B20B3; containment fan coll thit 27 declared inoperable when operator received indication of low seve water flow Caused by silt buildup in cooling coils flow control valve cycled & unit tested satisfactorily HELLER.R Public Bervice Electric & Oas Co of New Jersey B2/09/16 Region 1. Office of Director ip 15567 243 F41 Fiche 50-311,82/09/16.8210010144.
- B210010237 Forwards LER 82-090/03L-0 Detailed event analysis and MIDURA.H. J Public Service Electric & Qas Co of New Jerus 82/09/16 HAYNES.R C Region 1. Office of Director 3pp 15574 018 24X Fiche 50-311,82/09/16,8210010237.
- --8210010239 LER 82-070/03L-0 on 8208R2, operator discovered less entra 100-ft elevation containment air lock outer door Caused by rubber seal partially leaving retaining groups due to personnel closing door w/excessive force Seal replaced HELLER, R Public Service Electric & Cas Co of New Jersty 882/07/16 Region in Office of Director ip 15574 021 attacks.
- 8210010344 Forwards LER 82-074/03L-0 Detailed event analysis set MIDURA, H J. Public Service Electric & Oat Co of New Jerse 82/07/16 HAYNES, R C. Region in Office of Director Sep 15557-227. 24X Fiche 50-311,82/09/16,8210010344
- --8210010355 LER 82-094/03L-0 on 820825,2C vital bus underveltegring failed to trip at required setpoint Causad by setpoint drift Channel declared operable & Action Statement 3.3 % Action 14 terminated HELLER, R Public Service Electric & Qas Co of New Jerse B2/09/16. Region i, Diffice of Director 1p. 15569 232 744 Fiche: 50-311, B2/09/16, B210010344
- B210010407 Forwards LER B2-08B/O3L-0 Detailed event analysis intl MIDURA.H.J Public Service Electric & Oas Co. of New Jersey B2/09716 HAYNES,R.C Region 1. Office of Director 3pp 15572-203. 24X Fiche 50-311.B2/09/16.B210010407
- --8210010412 LER 82-088/03L-0 on 820824, containment fan teil weit 2d declared inoperable after low svc water flow observat Causal by air regulator being out of adjustment. Air regulator adjusted & fan coil unit satisfactorily tested.

 HELLER, R Public Service Electric & Gas Co. of New Javast 82/09/16 Region i, Office of Director ip 18572 206 24 Fiche. 50-311, 82/09/16. 8210010407

- B210010419 Forwards LER 82-093/01T-0 Detailed event analysis encl HIDURA.H J Public Service Electric & Gas Co of New Jersey B2/09/16 HAYNES.R C Region 1. Office of Director 4pp 15569 338 24% Fiche 50-311.B2/09/16.B210010419
- --8210010423 LER 82-093/01T-0 on 820910, containment fan coil unit 21 declared inoperable when svc water leak discovered Caused by erosion of cooling coil Leaking coil blanked off Design change submitted to replace coils w/erosion resistant matl HELLER.R Public Service Electric & Gas Co of New Jersey 82/09/16. Region 1. Office of Director 1p 15569 342 24% Fische 50-311,82/09/16.8210010419
- 8210010455 Forwards LER 82-102/03L-0 Detailed event analysis encl MIDURA:H J Public Service Electric & Gas Co of New Jersey 82/09/16 HAYNES;R C Region 1. Diffice of Director 3pp 15570 001 24x Fiche 30-311,82/09/16,8210010455
- --B210010461 LER 82-102/03L-0 on B20823.130-ft elevation containment air lock declared inoperable after excessive leakage discovered past inner door seals Caused by closing door w/excessive force Seal replaced installation of snubbers proposed HELLER:R Public Service Electric & Cas Co of New Jersey B2/09/16 Region 1. Office of Director ip 15570 004 24% Fiche 50-311.82/09/16.8210010455
- 8210070221 Forwards LER 82-101/01T-0 Detailed event analysis encl MIDURA: H J Public Service Electric & Gas Co of New Jersey 82/09/22 HAYNEB:R C Region 1, Office of Director App 15537 156 24X Fichs 50-311, B2/09/22, 8210070221
- --E210070231 LER 82-101/01T-0 on 820916, svc water leakage discovered in cooling coils of containment fan coil unit 21 Gaused by excessive erosion of cooling coils by silt Goils repaired New design coils will be installed during next refueling FRAHH,R Public Service Electric & Cas Co of New Jersey 82/09/22 Region 1. Office of Director ip 15637:160 24X Fiche 50-311,82/09/22.8210070221
- B210070246 Forwards LER B2-099/03L-0 Detailed event analysis encl MIDURA: H J Public Service Electric & Gas Co of New Jersey B2/09/22 H4VNES, R C Region 1. Office of Director 3pp 15634 293 24x Fiche 50-311.62/09/22.8210070246
- --8210070248 LER 82-099/03L-0 on 820902, control room operator received indication of low svc water flow on containment fam coil 23 Caused by silt buildup in cooling coils 8vc water flow control isolation valve cycled HELLER.R Public Service Electric & Qas Co of New Jerasy 62/09/22 Region 1, Office of Director ip 15434 294 24x Fiche 50-311,82/09/22,8210070246
- B210070249 Forwards LER 82-100/01T-0 Detailed event analysis encl MIDURAHH J Public Service Electric & Gas Co of New Jersey B2709722 HAYNES,R C Region 1, Office of Director 4pp 15834 288 24X Fiche 50-311,82709722,8210070249
- --B210070252 LER 82-100/01T-0 on 820915,4vc water leak of approx 0 3 gpm discovered on cooling coil of containment fan coil 22 Caused by excessive erosion of cooling coil by silt in svc water. Leaking coil repaired FRAHN.R Public Bervice Electric & Gas Co of New Jerssy. 62/09/22 Region 1 Office of Director ip 15634 292 24X Fiche 50-311,82/09/22.8210070249
- 8210070254 Forwards LER 82-061/03X-1 Detailed event analysis encl MIBURA:H J Public Service Electric & Gas Co of New Jersey 82/09/22 HAYNES:R C Region 1. Office of Director 3pp 15634 283 24X Fiche 50-311.82/09/22.8210070254
- --821007025B LER 82-061/03/-1 on 820716.steam generator level channel II indication erratic Caused by leakage past packing on Root valve 218F28 Valve repacked & leakage stopped FRAMH.R Public Service Electric & Oas Co of New Jersey 82/09/22 Region in Office of Director ip 15634,286 24X Fiche 50-311,82/09/22.8210070254
- 8210070351 Forwards LER 82-078/03L-0 Detailed event analysis encl MIDURA: H J Public Service Electric & Gas Co. of New Jersey 82/07/22 HAVNES, R C Region 1, Office of Director 2pp 15534 047 24X Fiche 50-311.82/09/22,8210070351
- --B210070359 LER 82-098/03L-0 on 820701.indication of low syc water flow received on containment fan coil unit 21 Caused by silt build-up in cooling coils 8vc water flow control valve cycled & coil unit tested satisfactorily HELLER.R Public Service Electric & Qas Co of New Jersey B2/09/22 Region 1. Office of Director ip 15634 050 24X Fiche 50-311,82/09/22.8210070351

- 8210070371 Forwards LER 82-012/03X-1 Detailed event analysis encl HIBURA.H J Public Service Electric & Gas Co of New Jersey 82/09/22 HAYNES.R C Region 1. Office of Director 3pp 15633.027 24X Fichs 50-311,82/09/22,8210070371
- --8210070377 LER 82-012/03X-1 on 820209, steam generator level channel 2 displayed erratic behavior, indicating drift Apparently caused by intermittent ground on signel lead, Ground aliminated by lifting leads while traubleshooting problem FRAHM.R Public Service Electric & Oas Co of New Jersey 82/09/22 Region 1. Office of Director ip 15634 030 24% Fiche 50-311,82/09/22,8210070371
- 8210130164 Forwards LER 82-103/03L-0 Detailed event analysis encl MIDURA,H J Public Service Electric & Qas Co of New Jarsey 82/09/29 HAYNES,R C Region i. Office of Director 3pp 15673 057 24X Fichs 50-311,82/09/29,8210130164
- --8210130170 LER 82-103/03L-0 on B20704, while running auxiliary alarm summary, control breaker alarm observed for containment spray pump 21 Gaussed by upened 4 ky breaker HL contact Breaker racked out & pump declared operable FRAHM-R Public Service Electric & Gas Co of New Jersey 82/09/29 Region 1. Office of Director ip 15673.060 24X Fiche 50-311,82/09/29,8210130164
- 82:0130219 Forwards LER 82-097/03L-0 Detailed event analysis encl MIDURA.H J Public Service Electric & Qas Co of New Jersey 82/09/29 HAYNES,R C Region 1, Office of Director 3pp 15675 265 24X Fiche 50-311,82/09/29,8210130219
- ---8210130227 LER 82-097/03L-0 on 820910.RCS water inventory not performed within specified time interval Caused by failure of surveillance to make allowance for routine unavoidable transients precluding inventory performance FRAHM.R Public Service Electric & Gas Co of New Jersey 82/09/29 Regaon i. Office of Director ip 15675 268 24X Fiche 50-311.82/09/29.8210130219
- 8210130340 Forwards LER 82-105/03L-0 Detailed event analysis encl MIDURA, H J Public Service Electric & Oas Co of New Jersey 82/09/29 HAYNES, R C Region 1, Office of Director 3pp. 15682 046 24X Fiche 50-311,82/09/29,8210130340.
- --8210130345 LER 82-105/03L-0 on 820908, svc water flow to containment fan coil unit 22 found less than required by Tech Specs. Caused by silt deposited in cooling coils restricting svc water flow Pressure control valve cuted to flush out silt FRAHM.R Public Service Electric & Oas Co of New Jersey 82/09/29 Region 1. Office of Director ip 15682 049 24X Fiche 50-311,82/09/29,8210130340
- 821013035i Forwards LER 82-107/01T-0 Detailed event analysis encl MIDURA, H J Public Service Electric & Oas Co of New Jersey 82/09/29 HAYNES, R. C Region 1. Office of Director 4pp 15680 315, 24X Fichs 50-311,82/07/29,8210130351
- --B2i0i30358 LER 82-109/01T-0 on B20923.svc water leakage of approx 0 6 gpm discovered on containment fan coil unit 21 cooling coil Caused by erosion by silt in svc water Leaks repaired w/blanked fiange & Beliona metal filler.
 FRAHM.R. Public Service Electric & Gas Co of New Jersey B2/09/29 Region 1 Office of Director ip 15680-319 24X Fiche 50-311,82/09/29,8210130351
- 8210150057 Forwards LER 82-086/03L-0 Detailed event analysis encl MIDURA,H J Public Service Electric & Oas Co of New Jersey. 82/09/29 HAYNES,R. C Region 1. Office of Director 3pp 15698 300 247 Fiche 50-311.82/09/29,8210150057
- --8210150065 LER 82-086/03L-0 on 820915, water observed dripping from oil level sightglass on syc water pump motor Caused by failed motor bearing oil cooler due to accelerated erosion & corrosion Failed cooler repaired.

 FRAHMIR Public Service Electric & Oas Co. of New Jersey 82/09/29 Region i, Office of Director ip. 15698,303. 24X Fiche 50-311,82/09/29,8210150087.
- 8210150109 Forwards LER 82-104/03L-0. Detailed event analysis encl MIDURA: H J. Public Service Electric & Oas Co of New Jersey. 82/09/29 HAYNES, R C. Region i. Diffice of Director 3pp. 15697 059 24X Fiche 50-311,82/09/29,8210150109
- --B210150118 LER 82-104/03L-0 on 8209D8, vital bus 2A would not transfer automatically from one 4 kV transformer to another. Caused by dirt in undervoltage relay Relay cleaned FRAHMAR. Public Service Electric & Qas Co of New Jersey 82/09/29. Region 1. Office of Director. 1p 18697 062 24X Fiche 50-311, 82/09/29, 8210150109

- 8210190088 Forwards LER 62-073/017-0 HIBURA.H J Public Service Electric & Cas Co of New Jersey 82/09/30 HAYNES.R C Region 1. Office of Director 1p 15701 198 24x Fiche 50-311.82/09/30.8210150088
- --8210150093 LER 82-073/01T-0 on 820813 during containment entry,1 5 gpm syc water leak discovered on containment fan coil Unit 23 Caused by failed cooling coil due to erosion by salt particles Leak repaired w/Beliona metal filler FRAHM.R Public Service Electric & Gas Co of New Jersey 82/08/16 Region 1. Office of Director ip 13701 199 24X Fiche 50-311,82/09/30.8210150088
- 8210150097 Forwards corrected LER 82-075/01T-0 MIDURA,H J Public Service Electric & Qas Co of New Jersey 82/09/30 HAYNES,R C Region 1. Office of Director 1p 15707 302 24% Fichs 50-31; 82/09/30.8210150099
- --8210)50320 Corrected LER 82-075/017-0 on 820814.1 gpm svc water leak discovered bn containment fam coil unit 22 Cause not determined. Unit repaired by blanking flanges in svc water piping to coil New design coils will be installed FRAHM.R Public Service Electric & Qas Co of New Jersey 82/08/18 Region 1. Office of Director ip 15707-303 24X Fiche 50-311,82/09/30.8210150099
- 8210150311 Forwards corrected LER 82-074/01T-0 HIDURA:H J Public Service Electric & Qas Co of New Jersey 82/09/30 HAYNES:R C Region 1, Office of Director 1p 15701.343 24X Fiche 50-311.82/09/30.8210150311
- --8210150337 Corrected LER 82-074/017-0 on 820813, control operator discovered increased leakage to containment sump Caused by coil feaflures due to sile particles in svc water Leak repaired by blanting flanges FRAMM, R Public Service Electric & Cas Co of New Jersey 82/08/18 Region i, Office of Director ip 15701:344 24X Fiche 50-311,82/09/30,8210150311
- 82(0070243 Telecopy message of LER 82-111/01P on 821002, during routine power operation, we water leak discovered inside containment bldg on containment fan coil unit 23 Cause undetermined Rept will be submitted per 1E 3011atin 80-24 MIDURA, H J Public Service Electric & Oas Co of New Jersey 82/10/04 HAYNES, R C Region 1, Defice of Director 1p 15649 243 24% Fiche: 50-311,82/10/04,8210070243
- 8210080241 LER 82-113/01P on 821005, during routine operation, svc water leak discovered inside containment on fan coil 22 Cause unknown investigation in progress Rept will be submitted per IE Bulletin 80-24 MIDURA-H. J Public Service Electric & Cas Co of New Jersey 82/10/06 HAVMEGR C Region 1, Office of Director 1p 15638 077 24% Fiche-50-311,82/10/06.8210080241
- 8210080296 LER B2-112/01P on B21005, svc water discovered leating at rate of 1 gallon per minute inside containment bldg on fan coil unit 21 Cause not stated Leak (solated Investigation continuing Detailed rapt forthcoming HIDURAH J Public Bervice Electric & Cas Co of New Jersey B2/10/06 HAYNES, R C. Region 1, Office of Director 1p. 1563B: 295 24X Fiche 50-311,82/10/06,8210080276
- 8210250053 Forwards LER 82-106/03L-O Detailed event analysis and MIDURALH J fublic Service Electric & Oas Co of New Jersey 82/10/04 HAVBER C Region 1, Office of Director 3pp 13787.086 24X Fiche 50-311.82/10/06.8210250053
- --9210250057 LER 82-106/03L-0 on 820913,sir broken links discovered on circulator travelling screen 2tA Possibly caused by stress-induced crecking. Links replaced Design change request issued to consider stainless steel links FRAHMIR. Public Service Electric & Oas Co of New Jersey. 82/10/06 Region 1. Office af Director. 1p 15787.089 24X Fiche 50-311,82/10/06.8210250053.
- 8210250382 Forwards LER 82-108/03L-0 Detailed event analysis encl. MIDURA: H. J. Public Service Electric & Gas Co. of New Jersey 82/10/06. HAYNES: R C Region 1, Office of Director. App 15790.072. 24X Fiche.50-311.82/10/06.8210250382
- --8210250389 LER 82-108/03L-0 on 820915 & 17.RPI 104 discovered reading preater than 12 steps lower than bank demend indication. Caused by combination of RPI module calibr drift & change in actual rod position signal output.
 FRAMM.R. Public Service Electric & Qas Co. of New Jersey 82/10/06 Region 1, Office at Director, ip. 15790:076. R4X Fiche:50-3i1.82/10706.8210250382

- 8210190644 LER 82-119/01P on 821008.1 gpm svc water leat discovered to containment fan cuil unit 21 Leak isolated Investigation in progress Betailed rept will be submitted per IE Bulletin 80-24
 HIDURA: H Public Service Electric & Oas Co of New Jersey 82/10/12 HAYNES: R C Region 1, Office of Director Jp 15737 213 24X Fache 50-311.82/10/12.8210190644
- 82(019065) LER 82-120/01P on 82(011,0 5 gpm svc water leak discovered on containment fan coil unit 21 Leak isolated Investigation in progress Detailed rept will be submitted per IE Bulletin 80-24
 MIDURA.H J Public Service Electric & Cas Co of New Jersey 82/10/12 HAY/IES,R C Region 1. Office of Director 1p 15737 212 24X Fichs 50-311, 82/10/12, 82(019065)
- 9210280123 Forwards LER 113/01T-0 Detailed event analysis encl MIDURA.H J Public Service Electric & Gas Co of New Jersey 82/10/15 HAYNES.R C Region I. Office of Director App 15837 158 24X Fiche 50-311.82/10/15.8210280123
- -821028012B LER 82-113/01T-0 on 821005, small svc water leak districted on cooling coils of containment fan coil unit 22 Caused by erosion of cooling coils by silt in svc water Coil repaired w/Belzona metal filler FRAHM.R Public Service Electric & Oas Co of New Jersey 82/10/15 Region 1. Office of Director ip 15837 162 241 Fiche 50-311,82/10/15,8210280123
- 8210280152 Forwards LER 82-112/01T-0 Detailed event analysis entl MIDURA: H J Public Service Electric & Gas Co of New Jersey 82/10/15 HAYNES, R C Region 1, Office of Director Jpp 15837 221 24% Fiche 50-311,82/10/15,8210280152
- --8210280156 LER 82-112/01T-0 on 821005, svc water leak of 1 0 gra free flange in piping discovered on containment fan coil unit 21 Caused by removal of blank following Belzona repair Flange retorqued FRAHM: R Public Service Electric & Gas Co of New Jersey 82/10/15 Region 1, Office of Director 1p 15037 228 248 Fichs 50-311,82/10/15,8210280152
- G210260335 LER 62-122/01P on 621018, svc water leak of approx 0 4 grs discovered on containment fan coil unit 24 Leak isolated Detailed rept to be submitted HIDURA.H J Public Service Electric & Oas Co of New Jersey 82/10/19 HAYNES, R C Region 1, Office of Director ip 15804 275 24% Fichs 50-311, 62/10/19, 8210260335
- DOCKET 50-312 RANCHO SECO NUCLEAR GENERATING STATION

 F Security, medical, emergency & fire protection plans
- G210010057 Provides clarification of B20920 telcon re TMI Action Itsa III A 1 f Radiological surveys that cannot be performed by MRC-supplied equipment will be performed by util staff MATTIMOE. J J Bacramento Municipal Utility District 62/09/22 EISCHMUT. D Q Division of Licensing 2pp 15565 117 24x Ficke, 50-312, 82/09/22, 8210010057
- B210270314 Forwards Amend 40 to License DPR~54 & notice of Issuance & availability Amend adds License Condition 2 C (10) reimplementation of IAEA safepuards
 BTOLZ.J F Operating Reactors Branch 4 B2/09/29 MATTIMOS.J J Sacramento Municipal Utility District 4pp 15836 341 24X Ficher 30~312,82/09/29,8210270314.
- --8210270317 Amend 40 to License DPR-54, adding License Condition 2 to re implementation of IAEA safeguards STOLTJF Operating Reactors Brench 4 82/09/29 5pp 15836.345. 24X Fiche 50-312,82/09/29,8210270314
- --8210270320 Notice of issuance & availability of Amend 40 to Litting DRR-54 8TOLZ: J.F. Operating Reactors Branch 4 82/09/29 2pp 15836 350 24X Fiche: 50-312, 82/09/29, 8210270314.
- 8210190228 Forwards "Systematic Assessment of Licenses Performance, St. Rancho Seco," for Jul 1981-Sept 1982 Performance analyses for listed functional areas requested by 821112 STERNBERO, D. M. Division of Resident, Reactor Project & Engintering Programs. 82/10/14 YOUNO.T. CANTER. H. D'BRIEN. J. Rigion 5. Office of Director 2pp 13742 201 24X Fiche-50-312,82/10/14.
- --8210190231 *Bystematic Assessment of Licenses Performance, SMD Bytak Beco, " for Jul 1981-Sept 1982 * Region 5. Office of Director. 82/10/31, 24pp 15742 203 A Fichs 50-312, 82/10/14, 8210190228

- 8210250355 Forwards Amend 11 to security plan Amend withheld fref 100FR73 21) MATTIMOE.J J Sacramento Municipal Utility District 82/10/15 STGLZ.JF Operating Reactors Branch 4 1p 15787 048 24X Fiche 50-312, 82/10/15.8210250055
- Adjudicatory correspondence
- E210040073 Order directing NRC to provide results of NRC reviews of util revised reliability analysis of proposed mods to auralizing feedwater sys & Brooshaven rept on analysis by E21201 TOPPKINS.B A Atomic Safety and Licensing Appeal Panel E2/09/30 2pp 15581 035 24X Fiche 50-312.82/09/30.8210040093
- E210190370 Motice of RL Black withdrawal of appearance & RP Lessy appearance in proceeding Certificate of Svc encl PLACK.R L . LESSY.R P Hearing Branch 3 82/10/15 4pp 15741 207 24X Fiche 50-312,82/10/15.8210190370
- 62101903Bi Advises that NRC will provide results of reviews of reliability study of modified auxiliary feedwater sys by 821201 even though util intends to install sys in mid-1984, not Jan 1983, as anticipated 8LACK.R L. Hearing Branch 3 82/10/15 ROBENTHAL, A B, KOHL, C N, 8UCK.J K Atomic Safety and Licensing Appeal Panel 2pp 15740 346 24% Fiche 50-312,82/10/15,8210190381
- P Operating license stage documents & correspondence
- 8210180195 Forwards safety evaluation supporting adequacy of station electrical distribution voltages based on 820421 submittal Requests verification of test schedule within 45 days of ltr receipt STOLZ-JF Operating Reactors Branch 4 82/09/20 HATTIMOE, JJ Sacramento Nunicipal Utility District 3pp 15747 329 24X Fiche 50-312, 82/09/20, 8210180195
- --8210160201 Safety evaluation supporting adequacy of station electric distribution sys voltages sub; to completion of proposed nods

 4 Operating Reactors Branch 4 82/09/20 7pp 15747 332 24X
 Fishe 50-312,82/09/20,8210180195
- --8205170006 "Technical Evaluation of Adequacy of Station Electric Distribution Sys Voltages for Rancho Seco Nuclear Generating Station Unit 1." selected issues program WHITE.R L. Lawrence Livermore Laboratory FIN A-0250 UCID-19113 81/11/10 Assistant Director for Operating Reactors 14pp Available at NTIS \$5.00 15747 339 24X Fiche 50-312,82/09/20,8210180195
- E210190594 Application to amend License DPR-54, revising Tech Specs to allow for replacement of existing fuel storage racks w/high density poisoned storage racks MATTIMUE, J J Sacramento Municipal Utility District 82/09/28 Division of Licensing 2pp 15739 [06 24X Fiche, 50-312, 82/09/28, 82/09/09594
- --8210190598 Proposed Tech Specs allowing for replacement of existing fuel storage racks w/high density poisoned storage racks
 * Sacramento Municipal Utility District 82/09/28 ip. 15739 108 24X Fiche 50-312,82/09/28,8210190594
- --8210190603 "Licensing Rept for Spent Fuel Storage Capacity Expansion "

 ★ Sacramento Municipal Utility District 82/06/30 165pp
 15739 110 24% Fiche 50~312,82/09/28,8210190594
- 8210270314 Forwards Amend 40 to License DPR-54 & notice of issuance & availability Amend adds License Condition 2 C (10) resumplementation of IAEA safeguards
 STOLZIJF Operating Reactors Branch 4 82/09/29 MATTIMDE, J J Sacramento Municipal Utility District 4pp 15836 341 24X Fiche 50-312, 82/09/29, 8210270314
- --8210270317 Amend 40 to License DPR-54, adding License Condition 2 C (10) re implementation of IACA safeguards STOLZ-J F Operating Reactors Branch 4 82/09/27 Spp. L5836 345 24X Fiche 50-312, 82/09/29, 8210270314
- --8210270320 Notice of issuance & availability of Amend 40 to License DPR-54
 SYCLI.JF Operating Reactors Branch 4 82/09/29. 2pp
 15836 350 24% Fiche 50-312.82/09/29.8210270314.
- B210050220 Forwards "Transient Assessment Rept for Rancho Seco Reactor Trip on B10807," per request HATTINGE.J J Sacramento Municipal Utility District 82/09/30 HINGR.S Operating Reactors Branch 4 44pp, 15611 029 24X Fiche,50-312,82/09/30,8210050220

- 8210130175 Advises that diesel generator room supply & exhaust fans will be moved to Block 4 to resolve NRC concerns arising from sequencing auxiliary feedwater pump onto bus at 35-x Na diesel generator sequential loading test will be performed MATTIMOE. J Bacramento Municipal Utility District 82/10/05 STOLZ.JF Operating Reactors Branch 4 3pp. 15673 026 24X Fiche 50-312,82/10/05.8210130175
- 8210150519 Discusses NRR actions taken under Task Interface Agreement 82-20 for steam generator auxiliary feedwater header damage Licensee authorized to resume power operation at Occores 3
 EISENRUT, D. Q. Division of Licensing 82/10/06 OLSHINSKI, J. Division of Engineering & Technical Programs ip 15717 261 24X Fiche 50-000, 82/10/06. B210150519
- 8210190331 Forwards add1 info requested 820712 re TMI Item II B 3, "Post-Accident Sampling Sys "
 MATTIMOE.J J Sacramento Municipal Utility District 82/10/13
 STOLZ.J F Operating Reactors Branch 4 19pp 18742 046 24X
 Fiche 50-312,82/10/13,8210190331
- 8210190228 Forwards "Systematic Assessment of Licensee Performance, BMUD Rancho Seco," for Jul 1981-Sept 1982 Performance analyses for listed functional areas requested by 821112 STERNBERG, D M Division of Resident, Reactor Project & Engineering Programs 82/10/14 YOUNG, T. CANTER, H. D'GRIEN, J. Region 5, Office of Director 2pp 19742 201 24X Fiche 50-312,82/10/14, 8210190228
- --8210190231 "Systematic Assessment of Licensee Performance, SMUD Ranchu Seco," for Jul 1981-Sept 1982 * Region 5, Office of Director 82/10/31 24pp 15742 203 24X Fiche 50-312,82/10/14,8210190228
- 8210190381 Advises that NRC will provide results of reviews of reliability study of modified auxiliary feedwater sys by 821201 even though util intends to install sys in mid-1984, not Jan 1983, as anticipated DLACK, R. L. Hearing Branch 3 82/10/15 ROSENTHAL, A. B., KDHL, C. N., BUCK, J. H. Atomic Safety and Licensing Appeal Panel 2pp 15740 345 24X Fiche 50-312, 82/10/15.8210190381
- 82i0250074 Responds to B&W potential deficiency rept re effects of ring settings on Dresser safety valves Two Model 3i757A Dresser valves operable per Tech Boes Short inlet pipe configuration expected to remain stable during B&W testing MATTIMGE.J.J. Sacramento Municipal Utility District 82/10/19. STOLZ.J.F. Operating Reactors Branch 4 2pp 15787 07: 24X Fiche 50-312,82/10/19.8210250094
- 8210260231 Documents util position re safety valve operability. Valve performance cannot be quantitatively determined for given ring settings Preliminary B&W evaluation confirms util position pending more rigorous analysis per NUREG-0737 MATTIMOE. J. J Sacramento Municipal Utility District 82/10/21 STOLZ: J F. Operating Reactors Branch 4 ip 15803 229 24% Fiche 50-312. H2/10/21. 821026021
- 8210280228 Comments on NRC safety evaluation of NUREO-0737, Items
 II E i 2 1 k II E i 2 R re auxiliary feedwater automatic
 initiation & flow indication, transmitted by 820907 ltr
 Safety grade flow instrumentation info due by Jan 1983
 MATTIMOE, J. J. Sacramento Municipal Utility District 82/10/22
 STOLZ, J. Deprating Reactors Branch 4 2pp 15837:028 24X
 Fiche 50-312,82/10/22,8210280228.
- 8210280163 EN-B2-020A notice of order imposing civil monetary penalty issued to util Proposed action was based on two items of noncompliance Both items resulted from failure to properly return safety-related squipment to svc CRAIG.J. AXELRAD.J. Director's Office. Office of Inspection and Enforcement 82/10/26 ip. 15837:208. 24X Fiche 50-312.82/10/26, 8210280163
- Q Inspection reports, IE Bulletins & correspondence
- 8210010008 Responds to FOIA request for 19 categories of documents re nuclear reactor events & tafety problems, Forwards documents listed in App A. FELTON, J. M. Division of Rules and Records 82/06/28 UDELL, R.A. Critical Mass Energy Project. 15pp. 15727 005. 24X Fiche 50-000, 82/06/28, 8210010008.
- --Biii191042 Comments on draft IE circular re MBIV failures to close Problem W/control air for MBIV may be part of larger spectrum of problems for many valves MICHELSON,C Director's Office. Bi/10/01, JORDAN,E.L. Division of Resident & Regional Reactor Inspection 1p. 15700:335, 24X Fiche. 50-000, 82/05/29, 8210010008.

- 8210080015 Add1 response to FGIA request for 19 categories of info re nuclear reactor events & safety problems Forwards documents listed in App A Documents in App B completely withheld (ref FGIA Exemption 5)
 FELTON, J M Division of Rules and Records 82/07/12 UDELL.R A Critical Mass Energy Project 9pp 15665 027 24X
 Fiche 50-000, 82/07/12, 6210080015
- --B210080148 Systematic assessment of licenses performance notes re facility evaluation for 790415-800415 e NRC - No Detailed Affiliation Oliven 80/04/15 8pp 15468 035 24X Fichs 50-000, 82/07/12, 8210080015
- 821G07G007 Responds to FOIA request for eight categories of records re steam generators & steam turbines App A documents provided in R Udell FOIA Request 81-313 Forwards documents listed in App B FELTON, J H Bivision of Rules and Records 82/G8/10 LON9, D J Winthrep, Stimson, Putnam & Roberts 9pp 15645 063 24X Fiche 50-000-02/08/10,8210070007
- --8210070172 Forwards info re steam generator integrity & insps at all operating PMRs, per 750320 & 21 requests Details of insps. including defact indications, tube plugging criteria & tubes plugged will not be provided except for Point Beach i GOLLER,K R Division of Reactor Licensing (NRR-1975 only) 75/03/24 MACCARY,R R Division of Technical Review (NRR-1975 only) 5pp 15645 196 24X Fiche 30-000, 82/08/10, 8210070007
- 8210040330 Forwards JE Insp Rept 50-312/82-35 on 820804-0914 No noncompliance noted STERNBERG, D M Division of Resident, Reactor Project & Engineering Programs 82/09/23 MATTIME: J, Secremento Municipal Utility District 2pp 154:9 036 24X Fichs 50-312,82/09/23,8210040330
- --8210060336 IE Insp Rept 50-312/82-35 on 820804-0914 No noncompliance noted Major areas inspected operational safety verification, surveillance observations, mgt meeting & LER followup CANTER, H L . 0'ARIEN, J . YOUNG, T Division of Resident, Reactor Project & Engineering Programs 82/09/22 8pp 15619 038 24X Fiche 50-312,82/09/23,8210060330
- 8210190505 Forwards IE Insp Rept 50-312/82-33 on 820907-10 No noncompliance noted BOOK.H C Division of Radiological Bafety & Safeguards Program 82/09/30 MATTIMOE.J J Sacramento Municipal Utility District 2pp 15739 275 24X Fiche 50-312,82/09/30.8210190605
- --8210190612 IE Insp Rept 50-312/82-33 on 820907-10 No roncompliance noted Major areas inspected organization & staffing, transportation activities, glant tour & health physics appraisal followup of computer based multichannel analyser NORTH-H 8 MENSLAMSKI,F A BOOK-H E Division of Radiological Safety & Safeguards Program 82/09/29 10pp 15739 277 24X Fiche 50-312,82/09/30.8210190605
- 8210070278 Ack receipt of 820824 ltr Informing NRC of steps taken to correct violations noted in IE Insp Rept 50-312/82-20 STERNSERO, D. Division of Resident, Reactor Project & Engineerins Programs 82/10/04 MATTIME, J. Sacramento Municipal Utility District 1p 15634 171 24X Fiche 50-312.82/10/04, 8210070278
- --8210070287 Responds to NRC 820729 ltr re violations noted in IE Insp Rept 50-312/82-20 Corrective actions:01ison Shaker not maintained by Centration Engineering therefore EII G-6 not applicable NCR-8-2671 dispositioned on 820327 MATTIMOE.J J Sacramento Municipal Utility District 82/08/24 ENOBLEMEN.R H Region 5. Office of Director 2pp 15634 172 24X Fiche 50-312,82/10/04,8210070278
- 8210070270 Ack receipt of 820720 itr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-312/82-32 STERNBERO, D H Division of Resident, Reactor Project & Engineering Programs. 82/10/04 MATTIMED D H Sacramento Huncipal Utility District 1p 15634 180. 24% Fiche 50-312.82/10/04.8210070270
- ---8210070274 Responds to NRC 820901 itr re-violations noted in IE Insp. Rept 50-312/82-32 Corrective actions, all GA Class I Tech Epecs on overall contract spacs will include statement re-10CFR21 regulations
 HATTIMOE, J. J. Sacramento Hunicipal Utility District 82/09/20.
 BTERNBERO, D. M. Division of Resident. Reactor Project & Engineering Programs 2pp 15634 181 24x Fiche 50-312.82/10/04.8210070290
- 8210070319 Ack receipt of 820909 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-312/82-28 STERNBERG, D.M. Division of Resident, Reactor Project & Engineering Programs 82/10/04. MATTIMOE, J., Bacramenta Municipal Utility District 1p. 15634 lio. 24% Fiche 50-312,82/10/04,8210070319.

- --8210070331 Responds to NRC 820816 ltm re-violations noted in it in Rept 50-312/82-28 Corrective actions QA manual revised to define commercial grade spare parts & receiving inspare performed on all Class I & commercial grade spare parts MATTIMOE. J J Sacramento Municipal Utility District 82/09/09 SIERNIBERO. D M Division of Resident, Reactor Project & Enginter Programs 2pp 15634 111 24X Fiche 50-312:82/10/04,821007031
- 8208190233 IE Info Notice 80-35, Suppl 1, "Leaking & Dislodged 1-125 Implant Seeds " Syc list encl CDBp.t. I Division of Fuel Facilities, Materials & Safeguards 82/10/06 Consolidated Edison Co of New York 46pp 137612-24
- 820B19023B IE Bulletin 82-03, "Stress Corrosion Cracking in Thick-Hall-Large-Diameter, Stainless Steel, Recirculation Sys Piping at BHR Plants " Svc list encl DEYQUNO, R C Director's Office, Office of Inspection and Enforcement B2/10/14 Consolidated Edison Co of New York 115pp 15810 125 24X Fiche 50-000, 82/10/14, 8208190238
- 8210190228 Forwards "Systematic Assessment of Licensee Performance.S Rancho Seco." for Jul 1981-Sept 1982 Performance analyses for listed functional areas requested by 821118 STERNBERG.D H Division of Resident. Reactor Project & Engineer: Programs 82/10/14 YOUNG.T. CANTER.H., O'BRIEN.J. Region 5 Office of Director 2pp 15742 201 24X Fiche 50-312.82/10/14. 8210190228
- --8210190231 "Systematic Assessment of Licensee Performance, SAJD Pi-Seco." for Jul 1981-Sept 1982 * Region 5. Office of Director 82/10/31 24pp 15742 203 Fiche 50-312, 82/10/14/8210190228
- R Periodic operating reports & related correspondence
- 8210190278 Forwards monthly operating rept for Sept 1902 RODRIGUEZ.R J Bacramento Hunicipal Utility District 82/10/13 Director's Office Office of Inspection and Enforcement 1p 15742 178 24% Fichs 50-312,82/10/13.8210190278
- --0210190289 Monthly operating rept for Sept 1902 CDLOMBD.R Bacramento Municipal Utility District 82/10/08 & 15742 179 24X Fiche 50-312,82/10/13,8210190278
- S Reportable occurrences, LERs & related correspondence
- 6210120114 Advises of immediate need for imposing specific requirements re operational restrictions for Class IE 120-volt ac vital instrument buses in operating plants HICHELSON.C Director's Office 80/07/15 DENTON, H R Office 8 Nuclear Reactor Regulation, Director 1p 15689 165 24x Fiche 50-000, 80/07/15,8210120114
- B012290118 Discusses conclusions of engineering evaluation of state generator overfill transients at C-E & Westinghouse plants LANNINO, H D. Director's Office 80/10/29, HICHELSON, C Directs Office. 3pp 15672 262 24X Fiche 50-000, 80/10/29, 8012290119
- 8210070412 Discusses problems caused by entry of desiccant into instrument & control air lines Util should examine sys & detarmine source & extent of contamination MICHELSON, C Director's Office 81/09/15 DENTON, H Offices Nuclear Reactor Regulation, Director STELLO, V Director's Office of Inspection and Enforcement 5pp 19697 301 24X Fiche. 50-312, 81/09/15, 8210070412.
- 821001000B Responds to FOIA request for 19 categories of documents:
 nuclear reactor events & safety problems Forwards documents
 listed in App A
 FELTON. J H Division of Rules and Records 82/06/28 USELL, R &
 Critical Mass Energy Project 15pp 15727 005 24X
 Fiche 50-000, 82/06/28, 821001000B
- --8109280036 Immediate action memo re desiccant contemination of air lines. Recommends issuance of bulletin requiring all licensess experienced w/air sys contamination to furnish info MICHELSON.C Director's Office 81/09/15 DENTON, H.R. Office Nuclear Reactor Regulation, Director 2pp 15730 241 248 Fiche 80-312,82/06/28,8210010008
- --B201300388 Discusses loss of HPI lube oil cooling at facklist failure of monthly operability test of HPI to detect clogging of qualified lube oil coolers Test deficiency say be more critical than event Issue to be addressed by IE PELLET. J. Director's Office. B2/01/13, MICHELBON.C Director DIRECTO

- 6210250386 Forwards LER 82-026/04T-0 Detailed event analysis submitted MATTIMDE, J Sacramento Municipal Utility District 82/10/15 ENGLEVEN, R H Region 5, Office of Director 1p 15790 090 24X Fiche 50-312, 82/10/15, 8210250386
- --B210250390 LER 82-026/04T-0 on 821006, review of plant effluent records disclosed pH reading of 6 2 for less than 15 minutes on 820918 Caused by leaks at two elbows in acid line running rrom storage tank to turbine bldg Leaks repaired COLOMBD.R U Sacramento Municipal Utility District 82/10/14 Region 5, Office of Director 1p 15790 091 24X Fiche 50-312.82/10/15.8210250386
- 8210250139 PND-V-82-042 on 821016.RCS leakage of 1 15 gpm into reactor coolant drain sys through RCS loop drain valves discovered Leakage stands at 0 49 gpm Media interest expected VQU.0.T. CANTER.H Region 5, Office of Director 82/10/18 15787 119 24% Fiche 50-312.822/10/18.8210250138
- DOJAET 50-313 ARKANSAS NUCLEAR ONE, UNIT 1
- F Security, medical, emergency & fire protection plans
- 8210010175 Forwards IE Safeguards Insp Repts 50-313/82-25 & 50-348/82-22 on 820818-20 No noncompliance noted SEIDLE-W Division of Resident. Reactor Project & Engineering Programs 82/09/16 CAVANAUGH. M Arkansas Power & Light Co 2pt 15547 282 24X Fichs 50-313/82/09/16/8210010175
- 8210190497 Forwards IE Insp Repts 50-313/82-11 & 50-368/82-09 on 820518-20 No noncompliance noted EFIDLE.W C Division of Resident, Reactor Project & Engineering Programs 82/09/28 CAVANAUGH.W Arkansas Pawer & Light Co 2pp
- --8210190516 IE Insp Repts 50-313/82-11 & 50-368/82-09 on 820518-20 No noncompliance noted Major areas inspected license performance b capabilities during full-scale exercise of amergency plans & procedures
 ROMRER. D. M. HUNNICUIT. D. M. Division of Resident, Reactor Project & Engineering Programs 82/09/24 17pp 15735-346 24X Fiche 50-313/82/09/28/8210190497
- B210070395 Updates Bi1021 response to Generic Ltr B1-04, "Emergency Procedure & Training for Station Blackout Events " Seal return isolation is possible during blackout & is provided for in procedures

 MARSHALL JR Arkansas Power & Light Co B2/10/04 EISENHUT, D O Division of Licensing 2pp 15663 341 24X Fiche 50-313,82/10/04, 8210070395
- 821C150073 Forwards add! info re safe shutdown capability, in response to NRC 820703 request MARSHALL.JR Arkansas Power & Light Co 82/10/05 CLARK,R.A Operating Reactors Branch 3 STOLX,JF Operating Reactors Branch 4 72pp 15496 349 24X Fiche 50-313.82/10/05.8210150073
- B210280108 Releases public version of amend to emergency plan FELTON.J M Division of Rules and Records 82/10/12 Document Managament Branch 1p 15862 236 24X Fiche 50-313.82/10/12. B210280108
- --8210280112 Forwards public version of Amend 6 to amergency plan MARSHALL. J. R. Arkansas Power & Light Co. 82/10/04 COLLINS. J. Region 4. Office of Director DENTON. H. R. Diffice of Nuclear Reactor Regulation, Director 1p. 15862-237 24X Fiche 50-313,82/10/12,8210280108
- --8210280114 Public version of Amend 6 to emergency plan • Arkansas Power & Light Co 82/09/20 3pp 15862.238 24X Fiche 50-313.82/10/12.8210280108

- 8210260178 Ack receipt of 820727 ltr requesting add1 time to respond to violations noted in Emergency Preparedness Appraisal Repts 50-316782-32 & 50-366782-21 Response to App C due by 830501.

 SEIDLE-H C Division of Resident, Reactur Project & Engineering Programs 82/10/19 CAVANAUGH. M Arkansa Power & Light Co ip 15797 037. 24X Fiche 50-313,82/10/19,8210260178
- ---B210260180 Responds to NRC B20625 itr re App C to IE Emergency Preparedness Appraisal Repts 50-313/82-22 & 50-368/82-21 Deficiencies resolved in emergency plan amends & implementing procedure revisions CAVANAUGH, W Artansas Power & Light Co 82/09/29 COLLINS, J T Region 4, Office of Director 4pp 15799,038 24X Fiche 50-313,82/10/19.8210260178
- P Operating license stage documents & correspondence
- 821001000B Responds to FOIA request for 19 categories of documents re nuclear reactor events & safety problems Forwards documents listed in App A FELTON, J M Division of Rules and Records 82/06/28 UDELL.R A Critical Mass Energy Project 15pp 15727 005 24X Fiche 50-000.82706/28.821001000B
- --8106100203 Discusses evaluation of HPBI pump operability w/o svc water Operability of HPBI pumps w/o svc water not adequately justified based on info submitted by licensee IMBRO.E Director's Office 81/05/22 Director's Office 4pp 15729 185 24X Fiche 50-000.82/06/28.8210010008
- 8210190008 Responds to 820831 submittal re Tech Spec revision for snubber surveillance License amend application should be submitted to incorporate applicable portion of 801120 model Tech Specs within 60 days CLARK,R A Operating Reactors Brench 3 82/09/21 CAVANAUGH,W Arkansas Power & Light Co 2pp 15740.301 24X Fiche 50-313,82/09/21,8210170008
- 8210290140 Forwards Amend 69 to License DPR-51, safety evaluation & notice of issuance & availability Amend revises Tech Brecs to require chlorine detection & protection capability for control room VISSING.0 8 Operating Reactors Branch 4 82/09/21 CAVANAUCH, WARKARSAS Power & Light Co 2pp 15876 209 24X Fiche 50-313, 82/09/21.8210290140
- --B210290143 Amend 69 to License DPR-51, amending Tech Specs to require chlorine detection & protection capability for control room STCLZ, J F Operating Reactors Branch 4 B2/09/21 Spp. 15876:211 24% Fiche 50-313,82/09/21,8210270140
- --8210290146 Safety evaluation supporting Amend 69 to License DFR-51 * Office of Nuclear Reactor Regulation, Director 82/09/21 2pp 19876 219 24X Fiche 50-313,82/09/21,8210290140
- --B21029014B Notice of issuance & availability of Amend 69 to License DPR-51.
 STOLZ.J F Operating Reactors Branch 4 82/09/21 2pp 15876-221 24X Fiche 50-313,82/09/21,8210290140.
- 8210040107 Application for amend to License DPR-51, changing 820317 Tech Spec change request to allow higher steam line break instrumentation & control sys setpoint.

 CAVANAUOH: W. Arkanses Power & Light Co. 82/09/29 STOLZ. J F. Operating Reactors Branch 4 2pp 15381 017. 24X Fiche. 50-313, 82/09/29, 8210040109
- ---8210040111 Proposed revised Tech Spsc 3.4 2 re steam line break instrumentation & control sys + Arkansas Power & Light Co 82/09/29 5pp 15581:019. 24X Fiche:50-313.82/09/29.8210040109.
- 8210150002 Forwards response to 820120 & 0301 requests for addl info re RCB high point vents Credible missiles generated by failure of RCB vent valves not postulated based on valve design. Leak detection provided for by monitoring pressure.

 MARSHALL.JR Arkansas Power & Light Co 82/10/06 BTOLZ.JF.

 Operating Reactors Branch 4 CLARK.R.A. Operating Reactors Branch 3 4pp. 15696 309 24X Ficher 50-313,82/10/06,8210150002.
- 82:0150494 Submits info re status of waste gas sys & schedule for installation of redundant hydrogen/oxygen analyzers.
 Conceptual diagram of proposed upgraded waste gas sys redundant analyzer panel encl.
 MARSHALL.J R. Arkansas Power & Light Co. 82/10/12 STOLY.J F.
 Operating Reactors Branch 4 CLARK.R.A. Operating Reactors Branch 3 4pp. 15714.184. 24X Fizhe 50-313.82/10/12.8210150494.

- 8210220114 Formalizes proposals made at 820729 meeting u/BtW owners group to NUREO-0737. Item II K 3 30. "Revised Small Break LOCA Methods to Show Compliance w/10CFR50, App K "MARSHALL, J R Arkansas Power & Light Co. 82/10/13 DENTON, H R Office of Nuclear Reactor Regulation, Director 15pp. 15778 149. 24X Fiche 50-313, 82/10/13, 82/10220114
- 8210250206 Discusses operability of Dresser Hodel 31739A pressurizer safety in util & vendor documentation Ring settings should not cause valve chatter & mechnical damage Analytical models being developed for plant-specific data MARSHALL.J R Arkansas Power & Light Co 82/10/19 STOLZ.J F Operating Reactors Branch 4 2pp 15769 306 24% Fiche 50-313, 82/10/19, 8210250206
- 8210260192 Forwards addi response to 820618 open items re emergency feedwater sys.per 820722 Itr Functional test required every 18 months causes addition of heavily oxygenated water into once-through steam generator.
 HARSHALL.J R Arkansas Power & Light Co 82/10/20 STGLZ.J F Uperating Reactors Branch 4 App 15799 021 24X Fiche: 50-313, 82/10/20, 8210260192
- O Inspection reports, IE Bulletins & correspondence
- 6210080015 Addl response to FOIA request for 19 categories of info re nuclear reactor evants & safety problems Forwards documents listed in App A Documents in App B completely withheld (ref FGIA Exemption 5) FELTON.J H Division of Rules and Records 82/07/12 UDELL.R A Critical Mass Energy Project 9pp 15665 027 24X Fiche 50-000.82/07/12,8210080015
- --8210080112 Systematic assessment of licenses performance notes refacility evaluation for 790101-800819

 w NRC No Detailed Affiliation Given 80/08/19
 8pp 13667 291. 24X Fiche 50-000, 62/07/12.8210080015
- 8210070007 Responds to FOIA request for eight categories of records resteam generators & steam turbines App A documents provided in R Udell FOIA Request Bi-3i3 Forwards documents listed in App S FELTON, J M Division of Rules and Records. 82/08/10 LONO, D J Hinthrop, Stimson, Putnam & Roberts 9pp 13645 063 24X Fiche 50-000,82/08/10,8210070007.
- ---B210070172 Forwards info re steam generator integrity & insps at all operating PWRs.per 750320 & 21 requests Details of insps. including defect indications, tube plugging criteria & tubes plugged will not be provided except for Paint Beach 1 OCLLER.K R Division of Reactor Licensing (NRR-1975 only) 75/03/24 MACCARY.R Division of Technical Review (NRR-1975 only). 5pp 13645:196 24X Fiche 50-000.82/08/10,8210070007.
- 8210010175 Forwards IE Safeguards Insp Repts 50-313/82-25 & 50-368/82-22 on 820818-20 No noncompliance noted SEIDLEW C Division of Resident: Reactor Project & Engineering Programs 82/09/16 CAVANAUGH W Arkenses Power & Light Co 2pp 13567 282 24X Fiche: 50-313,82/09/16,8210010175
- --821001017B IE Safeguards Insp Repts 50-313/82-25 & 50-368/82-22 on 820818-20 No noncompliance noted Hajor areas inspected; security organization mgt.physical berriers & access control of packages Details withheld (ref 10CFR2 770). EVANB.C A: KELLY, J.A.F. Division of Vendor & Technical Programs 82/09/14. 1p 15567.284. 24X Fiche:50-313.82/09/16.8210010175.
- 8210190497 Forwards IE Insp Rapts 50-313/82-11 & 50-368/82-09 on 820518-20. No noncompliance noted SEIDLE:W C Division of Resident: Reactor Project & Engineering Programs 82/09/28 CAVANAUOH.W. Artamsas Power & Light Co. 2pj 15735:344 24X Fichs 50-313,82/09/28,8210190497.
- --B210190516 IE Insp Repte 50-313/82-11 & 50-368/82-09 on B20518-20 No noncompliance noted Major areas inspected: licensee performance & capabilities during full-scale exercise of emergency plans & procedures.

 ROMRER, D M , HUNNIGUTT, D M. Division of Resident, Reactor Project & Engineering Programs. 82/09/24. 17pp 15735-346 24% Fiche 50-313, B2/09/28, 8210190497.
- 8210120246 Ack receipt of 820211 itr informing NRC of steps taten to correct violations noted in IE Insp Repts 50-313/81-30 & 50-348/81-29.

 BEIDLE: W C Division of Resident, Reactor Project & Engineering Programs, 82/10/01 CAVANAUGH: W Artansas Power & Light Co 1p. 15652-110 24% Fiche. 50-313.82/10/01, 8210120246.

- --82i0120252 Responds to NRC 820104 ltr re violations noted in IE [*;; Repts 50-313/81-30 & 50-388/81-29 Corrective actions forest training sessions will be conducted w/appropriate station personnel to stress importance of individual responsibility MARSHALL, J.R. Ariansas Power & Light Co. 82/02/11 MADSEN.Q L. Division of Resident, Reactor Project & Engineering Program Cy, 15652 iii. 24X Fichs 50-313,82/10/01.8210120246
- 8210220270 Forwards IE Insp Repts 50-313/82-12 & 50-368/82-25 on 820524-27 No noncompliance noted SEINLE, W C Division of Resident. Reactor Project & Engineering Programs 82/10/05 CAVANAUGH.W Arkansas Power & Light Co 2, 15775 001 24X Fichs 50-313.82/10/05.8210220270
- --B21022028! IE Insp Repts 80-313/B2-12 & 50-369/BR-25 on B20324-27 s, noncompliance noted Major areas inspected radiochemistry program.including organization, staffing, training program. sample collection & sample treatment & analysis NICHOLAS, J. B., MURRAV. B. Region 4. Office of Director B2/09/14 25pp 15775 003 24X Fiche 50-313,82/10/05,8210220270
- B20B190233 IE Info Notice 80-35, Suppl i, "Leaking & Dislodgef f I: Implant Seeds " Bvc list encl COBP.L I Division of Fuel Facilities, Materials & Bafeguards 82/10/06 Consolidated Edison Co of New York 66pp 15761 (1) 24% Fishe 50-000/82/10/06,820B190233
- B210120241 Ack receipt of B20715 ltr informing NRC of steps talen is correct violations noted in IE Insp Repts 50-313/80-20 & 50-348/80-20 SEIDLE: U Division of Resident: Reactor Project & Engineering Programs 82/10/06 CAVANAUGH: W Arkansas Power & Light Co I; 15652 113 24% Fishs 50-313.82/10/06/8210120241
- 8208190238 IE Bulletin 82-03, "Stress Corrosion Cracking in Thitl-Mall.Large-Diameter, Stainless Steel, Recirculation Sys Piping at DUR Plants "Svc list enc! DEYOUNG.R C Director's Office. Office of Inspection and Enforcement 82/10/14 Consolidated Edison Co of New York 115pp. 15810 125. 24X Fiche 50-000, 82/10/14, 8208190238
- 8210220377 Categorizes open items identified in IE Emergency Preparedness Repts 50-313/82-11 & 50-368/82-07 by need for immediate consideration & type of response acceptable Notification of expected response date due within 10 days EEIDLE, N. C. Daysision of Resident, Reactor Project & Engineering Programs 82/10/17 CAVANAUON, M. Arkansas Power & Light Ce. 6, 15779 175 24X Fiche 50-313,82/10/17,8210220377
- 8210260178 Ack receipt of 820929 ltr requesting addl time to respir violations noted in Emergency Preparedness Appraisal Repts 50-313/82-22 & 50-368/82-21 Response to App C due by 830501 SEIDLE, W. C. Division of Resident, Reactor Project & Engineering Programs 82/10/19 CAVANAUDH.W Arkansas Power & Light to 1: 15799:037 24X Fiche 50-313,82/10/19,8210240178
- --8210260180 Responds to NRC 820425 ltr re App C to 1E Empryshity
 Preparedness Appraisal Repts 50-313/82-22 & 50-368/82-21
 Deficiencies resolved in emergency plan amends &
 implementing procedure revisions
 CAVANAUGH. M. Arkansas Power & Light Co 82/07/24 COLLING J.
 Region 4. Office of Director 4pp 15799 038 24X
 Fiche: 50-313, 82/10/19, 8210260178
- S Reportable occurrences. LERs & related correspondence
- 8210120380 Advises that operator action necessary to protect 34V 341 from excessive feedwater transients, 88W plants do not eapled high steam generator level turbine or reactor trips to protect against transients CREBWELL, J. S. Director's Office 80/09/12 MICHELGON, C Director's Office 34pp 13689; 286 24X Fiche 50-302, 80/09/12 8210120360.
- 8012290118 Discusses conclusions of engineering evaluation of state generator overfill transferts at C-E & Westinghouse plants LANNING, M D. Director's Office. 80/10/29 MICHESON C Streets Office. 3pp. 15692.262 24X Fiche 50-000, 80/10/29, 80122018
- 82:0070104 Speech entitied "Pressure Boundary Degradation Dui to Fu Seal Failure at AR Nuclear One," presented at ninth meeting of Committee on Safety of Nuclear Installations on 81:103-04 in Peris France. LANNINO, W. D. : BROWN.E J. Director's Office 81/11/03 99: 15447:174. 24X Fiche 50-313.81/11/03.8210070104

DOCKETED ITEMS

- 9210010008 Responds to FOIA request for 19 categories of documents re nuclear reactor events & safety problems Forwards documents listed in App A FELTON, J M Division of Rules and Records 82/04/28 UDELL, R A
 - FELTON. J H Division of Rules and Records 82/06/28 UDELL.R A Critical Mass Energy Project 15pp 15727 005 24X Fiche 50-090.82/06/28,8210010008
- --B111040084 "Pressure Boundary Degradation Due to Pump Seal Failure of Arkansas Nuclear One "
 LARNING.W D , BROWN,E J Director's Office B1/11/03 6pp
 15731 079 24X Fiche 50-000, 82/06/28.8210010008
- --R2031G0549 Recommends explicit verification that seismic qualification for all protective devices used in control & protection circuitry for diesel generator units performed widevices in energized/de-energized & tripped/nontripped states MICHELSON, C Director's Office B2/02/24 VOLLMER, R H Division of Engineering MATTSON, R J Division of Systems Integration (post B11005) 2pp 15732 320 24% Fiche 50-000, B2/06/28, S250010008
- 82:0120145 "Abnormal Transient Operating Ouidelines as Applied to Apr 1981 Overfill Event at AR Nuclear One Unit 1" PELLETI L. Reactor Operations Analysis Branch 82/08/31 19pp 24X Fiche 50-313.82/08/31.8210120145
- 6210130513 Forwards LER 82-025/03L-0
 MARSHALL-J R Arkansas Power & Light Co 82/09/26 BEIDLE, W C
 Division of Resident, Reactor Project & Engineering Programs 1;
 15682 238 24X Fiche 50-313,82/09/26,8210130513
- --8210130522 LER 82-025/03L-0 on 820828, electrical jumpers discovered across trip contacts or shutdown bypass high pressure trip bistables for A & D reactor protection sys channels Gaused by personnel error Jumpers removed ROGERS.P Arkansas Power & Light Co 82/09/26 Region 4, Office of Director 2pp 15682 239 24X Fiche 30-313, 82/09/26, 8210130513.
- 8210130212 Forwards LER 82-027/03L-0 MARSHALL, JR Arkansas Power & Light Co 82/09/30 BEIDLE, W C Division of Resident, Reactor Project & Engineering Programs ip 15475 237 24X Fiche 50-313,82/09/30,8210130212
- --8210130214 LER 82-027/03L-0 on 820714.RCS leak rate calculated at 3 4 gpm. In excess of Teck Bpec Caused by low breakway torque valves, deteriorated gasket & eroded manuay cover All defective parts repaired or replaced ROGERS.P Artansas Power & Light Co 82/07/30 Region 4, Dffice of Director 2pp 15675 238 24X Fiche 50-313.82/07/30. 8210130312
- 9210130382 Forwards LER 82-026/03L-0 MARSHALL, J R Arkansas Power & Light Co 82/07/30 SEIDLE, W C Division of Resident, Reactor Project & Engineering Programs ip 15680 336 24X Fiche 50-313,82/07/30,8210130382
- --8210130388 LER 82-026/03L-0 on 820901, installed hose ree! (HR-49) found not visually inspected per Tech Specs Caused by lack of communication, leading to omission of HR-49 from insperocedures HR-49 inspected & procedure revised ROGERS, P. Arkansas Power & Light Co. 82/09/30. Region 4, Uffice of Director 2pp. 15680-337 24X Fiche 50-313,82/09/30, 8210130382
- B210190517 Forwards LER 82-028/03L-0 MARSHALL, JR Arkansas Power & Light Co B2/10/07 SEIDLE, W C Division of Resident, Reactor Project & Engineering Programs ip 15751 244 24% Fiche 50-313,82/10/07,8210190517
- --B210190526 LER 82-028/03L-Q on 820909, dissel driven fire pump (P-68) failed to start when using B battery bank during surveillance Cause by normal end of svc life Batteries charged & later replaced ROGERS.P Arkansas Power & Light Co 82/10/07 Region 4, Office of Director 2pp 15751 245 24% Fiche 50-313,82/10/07, 8210190517
- DOCKET 50-315 DONALD C COOK NUCLEAR POWER PLANT, UNIT 1

 F. Security, medical, emergency & fire protection plans
- B210060387 Forwards IE Insp Repts 50-315/82-08 & 50-316/82-08 on B20412-16.0514 & Oái0 Deficiencies referred to Oft of Investigation for review & investigation MORELIUS.C E Division of Engineering & Technical Programs. B2/09/22. DDLAN.J E Indiana & Michigan Electric Co 2pp 15615 350 24X Fiche 50-315,82/09/22.8210060387

- --8210060393 IE Insp Repts 50-315/82-08 & 50-316/82-08 on 820412-16.0514 & 0610 Deficiencies noted inadequate fire protection of safe shutdown capability, inaccurate statements, inadequate procedure for alternate safe shutdown & inadequate lighting GROBE, J A , STONE, J C , HAUGHNEY, C J Division of Engineering & Technical Programs 82/09/17 27pp 15615 352 24% Fiche. 50-315,82/09/22,8210040387
- 8210080129 Releases public version of revised emergency plan procedures FELTON, J M Division of Rules and Records 82/09/22 Document Management Branch ip 13863 293 24X Fiche 50-315,82/09/22, 8210080129
- ---B2100B0132 Forwards public version of Revision 1 to Emergency Plan Procedures PMP 20B1 EPP 012, "Offsite Radiological Monitoring" & Revision 1 to PMP 20B1 EPP 026, "Use of Stable Iodine for Thyroid Blocking During Radiation Emergency " # Indiana & Michigan Electric Co B2/07/13 NRC No Detailed Affiliation Olven 1p 15663 274 24X Fiche 50-315.82/07/22, 8210080129.
- --8210080136 Public version of Revision 1 to Emergency Plan Procedures PMP 2081 EPP 012, "Offsite Radiological Monitoring" & Ravision 1 to PMP 2081 EPP 026, "Use of Stable Iodine for Thyroid Blocking During Radiation Emergency " Index encl " Indiana & Michigan Electric Co 82/09/13 20pp 15663-295 24% Fiche 50-315,82/09/22,8210800129
- 8210010362 Forwards revision to modified amended security plan re key & lock control program Revision withheld (ref 10CFR73 21)
 HUNTER, R S Indiana & Michigan Electric Co 82/09/27 DENTON.H R
 Defice of Nuclear Reactor Regulation. Director 2pp 15574, 158
 24X Fiche 50-915, 82/09/27. 82100103362
- 8210150594 Releases public version of revision to plant manager procedure/emergency plan procedure FELTON. J M Division of Rules and Records 82/09/30 Document Management Branch ip 15716:350 24X Fiche 50-315.82/09/30, 8210150594
- --8210150604 Forwards public version of Revision 3 to Plant Manager Procedure/Emergency Plant Procedure App A. "Telephone Numbers for Key Plant Personne1"

 # Indiana & Michigan Electric Co 82/07/23 NRC No Detailed Affiliation Given 1p 15716 351. 24X Fiche 50-315,82/07/30,82101503904
- --8210150614 Public version of Revision 5 to Plant Manager Procedure/ Emergency Plan Procedure App A, "Telephone Numbers of Key Plant Personnel" * Indiana & Michigan Electric Co 82/09/23 21pp 15716.352 24X Fiche 50-315.82/09/30.8210150594
- 8210190036 Releases public version of procedure temporary sheet to emergency plan procedure FELTON, J. M. Division of Rules and Records 82/10/01. Document Management Branch. 1p 15761 034 24X Fiche 50-315,82/10/01,82/0190036
- --8210190040 Public version of procedure temporary sheet to
 Emergency Plan Procedure PMP 2081 EPP 020. "Activation &
 Operation of Technical Support Ctr " Revised index encl
 VINCE, S. SIMMS.R., CAMPBELL, D. Indiana & Michigan Electric Co
 82/09/17 2pp 19741 035. 24X Fiche 50-315,82/10/01,8210190036
- 821019052 Forwards FEMA 820909 ltr.final evaluations of offsite emergency preparedness exercises conducted on 801009 & 820330 for State of MI & Berrien County & State of MI response. Recommendations for offsite preparedness requested HIND.J A. Division of Emergency Preparedness & Operational Support 82/10/12. HERINO.R F American Electric Power Service Corp HERING.R.F Indiana & Michigan Electric Co. 2pp 15737.147 24X Fiche 50-315, 82/10/12.8210190652
- 8210280378 Releases public version of revision to emergency plan procedure. FELTON.J.M Division of Rules and Records 82/10/12 Document Management Branch 1p 15859 238 24% Fiche.50-315,82/10/12, 8210280378.
- --B2102803B0 Forwards public version of Revision 3 to emergency plan procedure App B re hosp assistance plan a Indiana & Michigan Electric Co 82/10/O1. NRC No Detailed Affiliation Given ip 15859 239. 24X Fithe. 50-315,82/10/12,8210280378
- --B2102803B3 Public version of Revision 3 to emergency plan procedure App B re hosp assistance plan. * Indiana & Michigan Electric Co. 82/10/01. 17pp. 15859:241 24X Fiche: 50-315, 82/10/12, 821028037B.

- 8210280399 Releases public version of revised emergency plan procedures. FELTON, J M Division of Rules and Records. 82/10/12 Document Management Branch 1p 15859 261 24X Fiche 50-315,82/10/12. 8210280399.
- ~-8210280408 Forwards public version of revised emergency plan procedures, including Procedures PMP 2081 EPP 004 reprotective action guides & protective actions & PMP 2081 EPP 009 to health physics procedures Indiana & Michigan Electric Co. 82/09/29, NRC ~ No Detailed Affiliation Given Ip 15859,262 24X Fiche-50-315,82/10/12, co.07290399
- --B210280413 Public version of revised emergency plan procedures, including Procedure PMP 2081 EPP 004 Te protective action guides & protective actions & PMP 2081 EPP 009 Te health physics procedures Procedures index end a Indiana & Michigan Electric Co 82/09/29 57pp 15839;263 24X Fiche.50-315,82/10/12.8210280379

[Financial information

- 8210070279 Forwards Annual Financial Rapt for 1981 & projected cash flow for 1982 HERINO, R. F. Indiana & Michigan Electric Co. 82/10/04 DENTON, H. R. Office of Nuclear Reactor Regulation, Director 2pp 15634, 185 24X Fich
- --8210070286 "ID & Ml Electric Co.Annual Financial Rept 1981 "

 * American Electric Power Service Corp * Indiana & Hichigan
 Electric Co 82/10/04 32pp 15634 187 24X
 Fiche: 50-315, 82/10/04, 8210070279
- J Insurance & indemnity information
- 8210040313 Forwards Endorsement 54 to NELIA Policy NF-206 & Endorsement 44 to MAELU Policy MF-79
 BUCKLES. J. Marsh & Kchennan, Inc. / M & M. Nuclear Consultants, Inc.
 Div 82/09/27 SALTZMAN, J. Assistant Birector for State & Licensee Relations 3pp, 15586 168 24% Fiche 50-315.82/09/27,8210040313
- P Operating license stage documents & correspondence
- 821005053B Forwards Amends 59 & 42 to Licenses DPR-58 & DPR-74, respectively, tafety evaluation & notice of issuance & availability Amends revise Tech Boecs to reflect installation or replacement of valves to improve operation CILIMBERO, R & Operating Reactors Branch 1. B2/09/09. DOLAN, J Indiana & Michigan Electric Co 2pp 15637-172 24X Fiche 50-315,82/09/09,8210050538
- --8210050541 Amends 57 & 42 to Licenses DPR-58 & DPR-74, respectively, revising Tech Specs to reflect installation or replacement of values to promote improved operation VARGA-S A. Operating Reactors Branch 1 82/09/09 26pp 15637 174 24X Fiche 50~315,82/09/09.8210050538
- --8210050544 Bafety evaluation supporting Amends 59 & 42 to Licenses DPN-58 & DPR-74-respectively * Office of Nuclear Reactor Regulation, Director 82/09/09, 2pp 18637, 200 24% Fishs: 50-315,82/09/09,8210050538
- --8210050546 Notice of issuance & availability of Amends 59 & 42 to Licenses DPR-58 & DFR-74, respectively. GRUTENHUIS, M. Uperating Reactors Branch 1 82/09/09 Rop. 13627-202. 24X Fithe 50-315, 82/09/09,8210030538.
- 8210040415 Forwards Amends 61 & 44 to Licenses DPR-58 & DPR-74, respectively, safety evaluation & notice of issuance & to reflect revised PDC-11 ancedures

- ~-8210040419 Notice of issuance & aveilability of Amends 61 & 44 t, Licenses DPR-58 & DPR-74, respectively VAROA. S.A. Operating Reactors Branch 1 92/09/15 2pp 15597, 132 24X Fiche 50-315, 82/09/15, 8210040415
- 8210040428 Forwards request for addl info re hydrogen control jesuis for ice condenser plants Response requested by 821015 VAROA: B A Operating Reactors Brench | 82/09/16 DOLAM,J Indiana & Michigen Electric Co 10pp 15597 252 24X Fiche 50-315, 82/09/16,8210040428
- 8210120557 Forwards Amend 62 to License DPR-58 & notice of issuance & availability Amend extends until 821009; permissibly operation in Modes 2 & 3 w/one safety injection pump inaperable VAROA: B A Operating Reactors Branch 1 82/09/17 DOLAN J Indiane & Michigan Electric Co 3pp 15684 218 24X Fiche 50-313, 82/09/17, 8210120557
- --8210120560 Amend 62 to License DPR-58, extending until 823009 permissible aperation in Modes 2 % 3 w/one safety injection gump inoperable VAROA.6 A Operating Reactors Branch 1 82/09/17 App 15684 221 24X Fiche 50-315, 82/09/17, 8210120557
- --8210120565 Notice of issuance & availability of Amend 62 to Lice of DPR-58
 VAROA, S. A. Operating Reactors Branch 1 82/09/17 2pp 13684 225 24X Fiche 30-315,82/09/17,8210120557
- 8210040212 Discusses inconsistency in ECCS analysis Yech Spet val.r.F
 70 F used as temp for safety injection flow water determined
 nonconservative Refueling water storage tank temp raised to
 80 F per Tech Spec requirement
 SMITH.W 0 Indiana & Michigan Electric Co 82/09/24 REPPLER.J;
 Region 3, Office of Director ip 15583 123 24X
 Fiche. 50-315, 82/09/24,8210040212
- 8210050138 Forwards documents as Phase I b of response to Section 21 of Encl 3 to DO Eisenhut 801222 ltr re control of heavy loads Westinghouse analysis of lifting arrangement for reactor years I head & Upper internals expected by 830315 HUNTER: R 8 Indiana & Michigan Electric Co 82/09/29 DEMICH office of Nuclear Reactor Regulation. Director 31pp 15406 027 24X Ficher 50-315,82/09/29,8210050138
- 8210050159 Application for amend to Licenses DPR-SB & DPR-74 prepii ;
 Tech Spec changes for placement of new post-acrident
 containment hydrogen monitoring sys to satisfy NUREO-0737.
 Item II F 1,6 & to remove existing equipment from svc
 HUNTER:R S Indiana & Michigan Electric Co 92/09/29 DENION AI
 Office of Nuclear Rescot Regulation. Director 2pp 15503 149
 24X Fiths 50-315,82/09/29,8210050159
- --8210050160 Proposed Tech Spec 3/4.6 4 re combustible gas control # Indiana & Michigan Electric Co 82/09/29 3pp 15803 151 24X Fiche 50-315.82/09/29.8210050159
- 8210050349 Forwards add1 info re hydrogen mitigation & control it facilities Util continues to work w/TVA & Duke Power Co toward completion of executive summary rept on fice condenser hydrogen R&D program HWNTER:R S Indiana & Michigan Electric Co 82/07/30 MENTOA NI Office of Nuclear Reactor Regulation. Director 126pp 15510/3/24X Fiche 50-315,82/07/30,8210050349
- 8210080174 Comments on regulatory performance improvement profits Comments can be dealt w/by revising program description to take full credit for mot review efforts Util views on comments will be discussed at meeting scheduled for 82:014 KEPPLER. J. O. Region 3. Office of Director 82/10/01 20LAN. J. American Electric Power Service Corp DOLAN. J. E. Indiana brill a Electric Go. 2pp 15640 188 24X Piche 50-315.82/10/01.6210963
- 8210060253 Discusses 820707 mgt meeting & forwards Bystematic Assessment of Licensee Performance Repts 50-315/82-16 & 50-316/82-16 KEPPLER.J.O Region 3. Office of Director 82/10/04 DOLAN.JE American Electric Power Co. Inc. DOLAN.JE Indiana & Alchsign Power Co. 3pp. 13620,198. 24X Fichs 50-315,82/10/04.921008039
- --8210060254 Systematic Assessment of Licensee Performance fepts
 50-315/82-16 % 50-316/82-16 on 801001-820401 Major arest
 examined: util regulatory performance
 w Region 3. Office of Director. 82/06/30 7pp. 15620 201 24;
 Fiche: 50-315, 82/10/04, 8210060203,

- --8210050256 Responds to NRC B20625 Systematic Assessment of Licensee Performance Repts 50-315/82-16 & 50-316/82-16 Toelve previously trained operators hired & computerized radiation exposure maint sys & security access control sys installed HUNTER, B Indiana & Michigan Electric Co 82/07/27 KEPPLER, J O Region 3, Office of Director 35pp 15620 208 24X Fiche 50-315,82/10/04,8210060253
- 9210150491 Confirms 820922 telcon re masonry walls Addl info required within 45 days to complete review VARGA.8 A Operating Reactors Branch i 82/10/04 DOLAN.J Indiana & Michigan Electric Co 3pp 19717 275 24X Fiche 50-315,82/10/04,8210150491
- 8210250340 Forwards Amends 63 & 45 to Licenses DPR-58 & DPR-74, respectively, safety evaluation & notice of issuance & scallability Amend revises Tech Specs changing turveillance requirements for boron & safety injection sys CILIMERO, R. Depressing Reactors Granch 1 82/10/04 DDLAN, J Indiana & Michigan Electric Co 2pp 15807 259 24X Fache 50-315, 82/10/04, 8210250340
- --B210250393 Amends 43 & 45 to Licenses DPR-58 & DPR-74, respectively, changing Tech Spers re surveillance requirements for boron & safety injection sys & updating core flux VARGA. B A Operating Reactors Branch i 82/10/04 73pp 15807 261 24X Fiche 50-315,82/10/04,8210250340
- --B210250394 Safety evaluation supporting Amends 63 & 45 tp Licenses DPR-58 & DPR-74: respectively • Office of Nuclear Reactor Regulation, Director 82/10/04 5pp 15807 334 24X Fiche 50-315,82/10/04,8210250340
- --8210250395 Notice of issuance & availability of Amends 63 & 45 to Licenses DPR-50 & DPR-74, respectively VARON. S A Operating Reactors Branch i 82/10/04 2pp 15807 339 24X Fiche 50-315, 82/10/04, 8210250340
- B210150434 Forwards safety evaluation re main steam line break w/continued feedwater addition & contractor technical evaluation rept W/o technical evaluation rept WARGA: A Derrating Reactors Branch 1 B2/10/05 DDLAN, J Indiana & Michigan Electric Co 2pp 15716 090 24X Fiche 50-315, 82/10/05, 8210150434
- --9210150437 Safety evaluation re main steam line break w/continued feedwater addition

 Operating Reactors Branch 1 82/10/05 7pp 15716 092 24X Fiche 50-315,82/10/05,82/0150434
- 6210220476 Submits followup to 820907, 17 & 24 ltrs re emergency relief requests from Tech 8pec 3 5 2 Repairs of north safety in jection pump completed within alloted relief time granted by Amand 62 Amand fee enci HUNTER: R 8 Indiana & Michigan Electric Co 82/10/15 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 15779 001 24X Fiche 50-315, 62/10/15, 8210220478
- 8210250228 Forwards proprietary responses to five of 16 questions per NRC 820730 request for addi info re hydrogen control issues for ice condenser plants.particularly CLASIX computer program Responses withheld (ref 10CFR2 770) HUMIER: R B Indiana & Michigan Electric Co 82/10/15 DENTON.H R Office of Nuclear Reactor Regulation. Director 2pp. 15789 339 24x Fiche 50-315,82/10/15,8210250228
- 8210220393 Advises that util will reload w/Mestinghouse i5x15 optimized fuel assemblies during Cycle 8 scheduled for 830831 Meeting w/NRC requested on 82103 to clearly define 11censing review schedule HUNTER: R S Indiana & Michigan Electric Co 82/10/18 DENTON, H R Office of Nuclear Reactor Regulation. Director 3pp 15777, 309 24X Fiche 50-315,82/10/18,8210220393
- BR10260081 Notification of BR1103 meeting w/utils in Bethesda.MD to discuss use of Westinghouse optimized fuel assemblies in Cycle 8 operation HI09INION.D. Operating Reactors Branch 1 82/10/21 VAROA, 8 A Operating Reactors Branch 1 3pp 15814 321 24X Fiche 50-315.82/10/21.8210260081.
- O Inspection reports. IE Bulletins & correspondence
- B210070007 Responds to FOIA request for eight categories of records re steam generators & steam turbines App A documents provided in R Udell FOIA Request 81-813 Forwards documents listed in App B FELTON, J. M Division of Rules and Records 82/08/10, LONG, D J Winthrop, Stimson, Putnam & Roberts: 9pp 15645:063 24X Fiche. 50-600, 82/08/10, 8210070007

- --8210070139 Forwards tabulated data on steam generator insp & maint at facilities Data should be provided to licenses
 IPPOLITO,T Operating Reactors Assessment Branch 82/04/01
 VAROA-S Operating Reactors Branch 1 Spp 15645
- 8210060387 Forwards IE Insp Repts 50-315/B2-0B & 50-316/82-0B on 820412-16:0514 & OáiO Deficiancies referred to Ofc of Investigation for review & investigation on NORELIUS.C E Division of Engineering & Technical Programs 82/09/22 DOLAN.J E Indiana & Michigan Electric Co 2pp 15615 350 24% Fiche 50-315.82/072.8210060387
- --8210060393 IE Insp Repts 50-315/82-08 & 80-316/82-08 on 820412-16.0514 & 0610 Deficiencies noted inadequate fire protection of safe shutdown capability, inaccurate statements, inadequate procedure for alternate safe shutdown & inadequate lighting ORDBE, J A. STONE, J C. HAUDHNEY, C. J. Division of Engineering & Technical Programs 82/09/17 27pp 15615 352 24X Fichs 50-315,82/09/22,8210060387
- 8210050274 Ack receipt of 820914 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-315/82-12 & 50-316/82-12 STREETER, J F Division of Project & Resident Programs 82/09/24 DDLAN, J E American Electric Power Service Corp DDLAN, J E Indiana & Michigan Electric Co 1p 15609 187 24% Fiche 50-315.82/09/24.8210050274
- --B210050276 Responds to NRC 820816 ltr re violations noted in IE Insp Rapts 50-315/82-12 & 50-316/82-12 Corrective actions plant manager will issue memo to plant depts by 820930 re procedures for installation of new design changes HERINO, R F Indiana & Michigan Electric Co 82/09/14 KEPPLER, J C Region 3, Office of Director 3pp 15609 188 24x Fiche 50-315,82/09/24.8210050274
- 8210060253 Discusses 820707 mgt meeting & forwards Systematic Assessment of Licensee Performance Repts 50-315/82-16 & 50-316/82-16 KEPPLER, J G Region 3. Office of Director 82/10/04 DOLAN, J E American Electric Power Co , Inc DDLAN, J E Indiana & Michigan Power Co 3pp 15620 198 24X Fichs 50-315,82/10/04,8210060253
- --8210060254 Bystematic Assessment of Licensee Performance Repts 50-315/82-16 & 50-316/82-16 on 801001-820401 Major areas examined util regulatory performance * Region 3, Office of Director 82/06/30 7pp 15620 201 24x Fiche, 50-315, 82/10/04, 8210060253
- --8210060256 Responds to NRC 820625 Systematic Assessment of Licensee Performance Repts 50-315/82-16 & 50-316/82-16 Tweive previously trained operators hired & computerized radiation exposure maint sys & security access control sys installed HUNTER, R S Indiana & Michigan Electric Co 82/07/27 KEPPLER, J Q Region 3, Office of Director 35pp 15620 208 24X Fiche, 50-315, 82/10/04, 8210060283
- 8208190233 IE Info Notice 80-35, Suppl 1, "Leaking & Dislodged I-125 Implant Seeds " Svc list encl COBB.L I Division of Fuel Facilities, Materials & Bafeguards 82/10/06 Consolidated Edison Co of New York 66pp 15761 250 24X Fiche 50-000,82/10/06.8208190233
- 8208190238 IE Bulletin 82-03. "Stress Corrosion Cracking in Thick-Wall. Large-Diameter: Stainless Steel. Recirculation Sys
 Piping at BHR Plants " Svc list encl.
 DEYGUNO.R C Director's Office. Office of Inspection and
 Enforcement 82/10/14 Consolidated Edison Co of New York
 115pp 15810 125. 24X Fiche 50-000, 82/10/14, 8208190238
- 8210150388 EN-81-047A on 821014 order imposing civil monetary penalty in amount of \$52,000 issued to licensee he violations concerning fire protection program & containment integrity. One violation withdrawn & two modified CRAIQ, J. AXELRAD, J. Director's Office, Office of Inspection and Enforcement 82/10/14 ip 15721 307 24X Fiche 50-315,82/10/14,8210150388
- R Periodic operating reports & related correspondence
- 8210190676 Forwards Sr-89 & Sr-90 data not completed by contractor until after due date for submittal of semiannual radioactive effluent release rept for Jan-June 1982 HUNTER: 8 Indiana & Michigan Electric Co: 82/10/01 KEPPLER: J G Region 3, Office of Director 2pp 15738:197. 24X Fichs: 50-315.82/10/01.8210190676
- --8210190695 "Effluent & Waste Disposal Semiannual Rept-1982, Qaseous Effluents-Elevated Release," Sr-89 & Sr-90 data omitted from original 820827 submittal * Indiana & Michigan Electric Co. 82/10/01. 10pp. 15738.199. 24X Fiche: 50-315,82/10/01.8210190676.

- S Reportable occurrences, LERs & related correspondence
- 8210080015 Add1 response to FOIA request for 19 categories of info re nuclear reactor events & safety problems Forwards documents listed in App A Documents in App B completely withheld (ref FOIA Elemption 5) FELTON.J H Division of Rules and Records 82/07/12 UDELL:R A Critical Mast Energy Project 7pp 15645-027 24X Fiche 30-000.82/07/12.8210080015
- --B210080197 NRC operations ctr usage chart re svents at #2cilities * NRC - No Detailed Affiliation Olven B2/07/12 ip 15668 221 24X Fichs 50-000, B2/07/12, B2100B0015
- 8210040073 Forwards LER 82-076/03L-0 SMITH.W O Indiana & Michigan Electric Co 82/09/22 KEPPLER.J O Region 3. Office of Director ip 15883 193 24X Fiche 50-315.82/09/22.8210040073
- --8210040075 LER 82-075/03L-0 on 920823, inverter for emergency diesel generator 4B failed lawing only centrifugal charging pump in ave w/o emergency power supply Cause not stated Charging pump shifted & inverter repaired

 DRAPER.D M Indiana & Michigan Electric Co 62/09/22 Region 3, Office of Director ip 15583 194 24% Fiche, 50-315, 82/09/22, 82(0040073
- 82:0040199 Forwards LERs 82-077/017-0 & 82-078/03L-0 SMITH.H.Q Indiana & Michigan Electric Co 82/09/24 KEPPLER.J Q Region 3. Office of Director 1p 15583 131 24X Fiche 50-315.82/09/24.8210040199
- --8210040203 LER 82-078/03L-0 on 820825 unplanned gas release detected by vant stack gaseous monitor R-26 reading Caused by water overflowing from liquid waste holdup tanks into room vents & vent sys

 KRAUSE, D. Indiana & Michigan Electric Co. 82/09/24 Region 3, Office of Director ip 15583 132 24X Fiche: 50-315, 82/09/24, application of the common of
- --B210040205 LER B2-077/01T-O on B20910 required surveillance tasting following installation of design change on control room ventilation sys had not been performed Gaused by unresolved status of design change sys issues
 BEILKAM. T P Indiana & Michigan Electric Co B2/09/24 Region 3, diffice of Director 19 15583 133, 24X Fiche 50-315,82/09/24.
- 8210040300 Forwards LER 82-079/01T-0 BMITH, W Q. Indiana & Michigan Electric Co 82/09/29 KEPPLER, J Q Region 3, Offica of Director. ip 15619 298, 24X Ficha 30-315.82/09/29.8210060300
- --B210060307 LER B2-079/01T-0 on B20913, during low power physics testing program following end of Cycle & refueling, unit entered Made 2 w/overpower & avertemp delta-T bistable in monconservative configuration Caused by unclear procedure FALMER, R. A. Indiana & Michigan Electric Co 82/09/29, Region 3. Office at Director App. 15617 279 24% Fiche: 50-315, 82/09/29, 8210060300
- 8210190749 Forwards LER 82-080/01T-0 SMITH.W 0 Indians & Michigan Electric Co 82/10/07 KEPPLER.J. 0 Region 3. Office of Director ip. 15737.092, 24X Fiche 25-315.82/10/07.8210190749
- --8210190757 LER 82-080/01T-0 on 820923, discovered analysis for safety injection flow water temp used value of 70 F Value of 80 F used in containment spray water temp analysis. Action talen to maintain restorage water temp above 80 F BELLMAN, T P Indiana & Michigan Electric Co 82/10/07 Region 3, Office of Director. 4pp. 15737 093 24X Fiche:50-315, 82/10/07,8210190749
- 82:0190572 Forwards LERs 82-081/03L-0 & 82-082/03L-0 SMITH, W G. Indiana & Michigan Electric Co. 82/10/08 KEPPLER, J. Q. Region 3. Office of Director 1p. 15736:099 24X Fiche: 50-315.82/10/08.8210190572.
- --B210190578 LER 82-081/03L-0 on B20908, during routine turbine bldg tour, operator discovered CD dissel room carbon dioxide (CO2) system telested w/no names on entry beard & no personnel in room. Caused by personnel arror Proper use of CO2 sys discussed. PALMER.R.A. Indians & Michigan Electric Co. B2/10/08. Region 3. Office of Director 1p. 15736.100. 24X Fichs.50-315.82/10/09.8210190572.

- --8210190588 LER 82-082/03L-0 on 820908, low pressure carbon dioxidis, for AB diesel generator room discovered isolated w/no fire watch posted contrary to Tech Specs Responsible individual undetermined Personnel trained in fire door PIEHL, R H Indiana & Hichigan Electric Co 82/10/08 Report Office of Director ip 15736 101 24X Ficha 50-315,82/10/09 8210190572
- 8210190266 Forwards LERs 82-083/03L-0 & 82-085/03L-0 SMITH, W O Indiana & Michigan Electric Co 82/10/12 KEPPLEF, J E Ragion 3, Office of Director ip 15742 189 24X Fichs 50-315, 82/10/12, 8210190266
- --8210190277 LER 82-083/03L-0 on 820921, during hot standby following refueling, leak observed on isolation value CS-422N Gaused by failure of 2-inch Orinnell Grade M diaphragm Diaphragm raplaced HINER, D 0 Indiana & Michigan Electric Co 82/10/12 Argita 3, Office of Director ip 15742 190 24X Fiche, 50-315, 92/12:13 8210190266
- --8210190287 LER 82-085/03L-O on 820927, during hot standby following refueling, steam generator 2 stop dump valve MRV-221 removed from svc Caused by need to correct seat leakage Valve disc, seat & stem replaced HIZNER, D O Indiana & Michigan Electric Co 82/10/12 Rep. 1 3, Office of Director 1p 15742 191 24X Fiche 50-315,82/11; 12 82/10190266
- 8210190340 Forwards LER 82-084/04L-0 SHITH, N O Indiana & Michigan Electric Co 82/10/12 KEPPLER, J¢ Region 3. Office of Director 1p 15742 123 24X Fiche, 50-315, 82/10/12,8210190340
- --8210190342 LER 82-084/04L-0 on 820912, unplanned gas release 4 steitr, elevated went stack gaseous monitor Caused by leat on wasting as oxygen analyzer Leak repaired NURPHY, C.E. Indiana & Michigan Electric Co. 82/10/12 Rejum 3, Office of Director 1p 15742 124 24% Fiche 50-315.82/10.3 8210190340
- 8210190380 Forwards LERs 82-086/03L-0, 82-087/03L-0 & 82-088/03L-5 SMITH, W @ Indiana & Michigan Electric Co 82/10/13 KEPPLCR.J. & Region 3, Office of Director ip 19740 359 24X Fiche 50-315, 82/10/13, 8210190380
- --8210190389 LER 82-086/03L-0, on 820914 & 16, supply breater for heat trace circuits found tripped Cause unknown. Monitoring of panel will continue until cause can be determined PALMER.R. A Indiana & Michigan Electric Co 82/10/13 Reg.s 3, Office of Director ip 15740 360 24% Fiche, 50-315, 82/10, 8210190380
- --B210190404 LER B2-087/03L-0 on B20920, containment gaseous radiatis monitor channel (ERB-1305) failed high-forcing removal of containment air particulate monitor channel from svc Caused by defective 1/0 card Card replaced PALMER, R. A. Indiana & Michigan Electric Co. B2/10/13 Regia. 3, Office of Director ip 15740.361. 24X Fiche 50-315.82/16.2 8210190380
- --8210190415 LER 82-088/03L-0 on 820916, safety valve Sv-1 for state generator 3 found leaking Cause not stated Seat leakage during plant heatup not uncommon Leakage stopped by sagging valve for short period of time HIZNER, D Q. Indiana & Michigan Electric Co 82/10/13 Region 3, Defice of Director, 1p 15740 362 24X Fiche 50-315.82/10.38210190380
- DOCKET 50-316 DONALD C COOK NUCLEAR POWER PLANT, UNIT 2
 F. Security, medical, emergency & fire protection plans
- 8210060387 Forwards IE Insp Repts 50-315/82-08 & 50-315/82-06 an 820412-16,0514 & 0610 Deficiencies referred to Ofc of Investigation for review & investigation. NORELIUB, C E. Division of Engineering & Technical Programs 82/07/22 DOLAN, J. E. Indians & Hichigan Electric Co. 249 15615-350 24% Fichs. 50-315,82/09/22,8210060387
- --8210060393 IE Insp Repts 50-315/82-08 & 50-316/82-08 on 820412-162 & 0610, Deficiencies noted inadequate fire protection of safe shutfown capability inaccurate statements: inadequate procedure for alternate safe shutdown & inadequate lighting GROBE, J.A., CHAN.T.L., EBERLY, R Division of Engineering & Technical Programs, 82/09/17 27pp. 15615:392, 24% Fiche:50-315,82/09/22,8210060387.

- 2:00:00127 Releases public version of revised emergency plan procedures FELTON. J M Division of Rules and Records 82/09/22 Document Management Branch 1p 15663 293 24X Fiche 50-315,82/09/22, 8210080129
- E210080132 Forwards public version of Revision 1 to Emergency Plan procedures PMP 2081 EPP 012, "Offsite Radiological Monitoring" & Revision 1 to PMP 2081 EPP 026, "Use of Stable 1 addine for Thyroid Blocking During Radiation Emergency " Indiana & Michigan Electric Co 82/09/13 NRC No Detailed Affiliation Given ip 15663 274 24x Fiche 50-315.82/09/22, 82/10080127
- 8210089136 Public version of Revision I to Emergency Plan Procedures PMP 2081 EPP 012, "Offsite Radiological Monitoring" & PMP 2081 EPP 024, "Use of Stable Lodine for Thyroid Blocking During Radiation Emergency " Index encl a Indiana & Michigan Electric Go 82/09/13 20pp 15663 295 24X Fiche 50-315, 82/09/22, 8210080129
- 10010352 Forwards revision to modified amended security plan re key & lock control program Revision withheld (ref 10CFR73 21)
 HUMIERR S Indiana & Michigan Electric Co 82/09/27 DENTON, H R
 Office of Nuclear Reactor Regulation, Director 2pp 15574 158
 24x Fiche 50-315,82/09/27,8210010362
- 10150594 Releases public version of revision to plant manager procedure recedure/emergency plan procedure reference by the procedure recedure recedence rece
- B210150604 Forwards public version of Revision 3 to Plant Manager Procedure/Emergency Plan Procedure App A. "Telephone Mumbers for Key Plant Personnel" # Indiana & Michigan Electric Co B2/09/23 NRC No Detailed Affiliation Given ip 15716 351 24X Fiche 50-315,82/09/30, \$\processrc 15.5554
- 3210150616 Public version of Revision 5 to Plant Manager Procedure/ Emergency Plan Procedure App A, "Telephone Numbers of Key Plant Personnel" # Indiana & Michigan Electric Co 82/09/23 21pp 15716 352 24X Fiche 50-315.82/09/30.8210150594
- IO190036 Releases public version of procedure temporary sheet to pmergency plan procedure "ELTON: J K Division of Rules and Records 82/10/01 Document Sanagement Branch 1p 15761 034 24X Fiche 50-315:82/10/01. 3210190036
- 3210190040 Public version of procedure temporary sheet to Emergency Plan Procedure PMP 2081 EPP 020. "Activation & Operation of Technical Support Ctr " Revised index encl. VINCE.8, SIMMS,R. CAMPRELL,D. Indians & Michigan Electric Co. E2/09/17. 2pp 13761 035 24X Fiche 50-315.82/10/01,8210190036
- Of 90552 Forwards FEMA 820909 ltr.final evaluations of offsite 'mergency preparedness exercises conducted on Bioloop & 120330 for State of MI & Berrien County & State of MI exponse Recommendations for offsite preparedness requested (IND. J A Division of Emergency Preparedness & Operational Support 12/10/12 HERINO,R F American Electric Power Service Corp (ERINO,R F Indiana & Michigan Electric Co 2pp 15737:149, 24X Teche 50-315, 82/10/12, 8210190652
- OZE0378 Releases public version of revision to emergency plan rocedure ELTON, J M Division of Rules and Records 82/10/12 Document [Amagement Branch 1p 15859 238 24X Fiche 50-315, 82/10/12,)210280378.
- 210280380 Forwards public version of Revision 3 to emergency plan
 Procedure App B re hosp assistance plan

 ★ Indiana & Michigan Electric Co 82/10/01 NRC No Detailed
 Affiliation Given ip 15859 239 24X Fiche 50-315,82/10/12,
 □210280378
- 210280383 Public version of Revision 3 to emergency plan procedura App 8 re hosp assistance plan * Indiana & Michigan Electric Co 82/10/01 17pp. 15859,241. 24X Fiche 50-315,82/10/12,8210280378
- O280399 Releases public version of revised emergency plan
 FDCedures
 FTON, J M Division of Rules and Records 82/10/12 Document
 Anagement Branch ip 15859 261 24X Fiche 50-315, 82/10/12,
 PLO280399

- --8210280408 Forwards public version of revised emergency plan procedures including Procedures PMP 2081 EPP 004 reprotective action guidas & protective actions & PMP 2081 EPP 007 re health physics procedures # Indiana & Michigan Electric Co 82/07/27 NRC No Detailed Affiliation Oliven 1p 15859 262 24X Ficha 50-315,82/10/12.
- --8210280413 Public varsion of revised emergency plan procedures, including Procedure PMP 2081 EPP 004 re protective action guides & protective actions & PMP 2081 EPP 009 re health physics procedures Procedures index encl # Indiana & Michigan Electric Co 82/09/29 57pp 15859 263 24X Fichs 50-315,82/10/12,8210280399
- I Financial information
- 8210070279 Forwards Annual Financial Rept for 1981 & projected cash flow for 1982 HERINO,R F Indiana & Michigan Electric Co 82/10/04 DENTON.H R Office of Nuclear Reactor Regulation, Director 2pp 13634,185. 24X Fiche 50-315,82/10/04,8210070279
- --8210070286 "ID & HI Electric Co. Annual Financial Rept 1981."

 * American Electric Power Bervice Corp * Indiana & Michigan Electric Co 82/10/04 32pp. 15634 187 24X
 Fiche 50-315,82/10/04,8210070279
- J Insurance & indemnity information
- 8210040313 Forwards Endorsement 54 to NELIA Policy NF-206 & Endorsement 44 to MAELU Policy MF-79 SUCKLES, J. Marsh & McLennan, Inc., M. & M. Nuclear Consultants, Inc. Div. 82/09/27, SALTZMAN. J. Assistant Director for State & Licensee Relations 3pp 15386.168 24X Fiche. 50-315, 82/09/27, 8210040313,
- P Operating license stage documents & correspondence
- 9210050538 Forwards Amends 59 & 42 to Licenses DPR-58 & DPR-74, respectively, safety evaluation & notice of issuance & availability Amends revise Fech Specs to reflect installation or replacement of valves to improve operation CILINBERO,R.L. Operating Reactors Branch 1. 92/09/09 DDLAN,J. Indiana & Michigan Electric Co. 2pp 15637 172 24X Fiche 50-315,82/09/09,8210050538
- --B210050541 Amenda 59 & 42 to Licenses DPR-58 & DPR-74, respectively, revising Tech Bacs to reflect installation or replacement of valves to promote improved operation VAROA: 8 A Operating Reactors Branch | B2/07/09 26pp. 13537, 174 24X Fichs 50-315, B2/07/09, B210050538.
- --8210050544 Bafety evaluation supporting Amends 57 & 42 to Licenses DPR-58 & DPR-74, respectively.
 4 Office of Nuclear Reactor Regulation, Director 15637:200 24X Fichs 50-315.82/09/09.8210050838
- --8210050546 Notice of issuance & availability of Amends 59 & 42 to Licenses DPR-58 & DPR-74:respectively GROTENHUIS, M. Operating Reactors Branch i 82/09/09 2pp. 18537 202. 24X Fiche 50-315, 82/09/09,8210050538.
- 8210040415 Forwards Amends 61 & 44 to Licenses DPR-58 & DPR-74, respectively, sefety evaluation & notice of issuance & availability. Amends revise Tech Specs to rePlect revised LDCA enalysis for Unit i & Suppl 2 to PDC-II procedures. GILIMBERG:R L Operating Reactors Branch i. 82/07/15. DDLAN.J. Indiana & Mishigan Electric Co. 2pp 15597.098 24X Fiche: 50-315.82/09/15.8210040415
- --8210040417 Amends 61 & 44 to Licenses DPR-58 & DPR-74, respectively, revising Tech Specs to reflect revised LOCA analysis for Unit 1 & implementation of Suppl 2 to PDC-II power distribution control procedures for Units 1 & 2. VARCA.S A. Operating Reactors Branch 1. 82/09/15. 29pp 15597. 100. 24% Fiche. 50-315. 82/09/15. 8210040415.
- ---8210040418 Befety evaluation supporting Amends 61 & 44 to Licenses DPR-58 & DPR-74, respectively " Office of Nuclear Reactor Regulation, Director, 82/09/15, 3pp, 15597 129. 24X Fichs. 50-315,82/09/15,8210040415,
- --8210040417 Notice of issuance & availability of Amenda 61 & 44 to Licenses DPR-58 & DPR-74: respectively. VARQA:S.A Operating Reactors Branch 1. 82/09/15. 2pp 15597: 132 24% Fichs: 50-315. 82/09/15,8210040415

- 8210040428 Forwards request for add1 info re hydrogen control issues for ice condenser plants Response requested by 821015 VARQA.S A Operating Reactors Branch 1. 82709716 BOLAN.J Indiana & Michigan Electric Co 10pp 15597
- 821005013B Forwards documents as Phase I b of response to Bection 2 i of Encl 3 to DO Eisenhut 801222 ltr re control of heavy loads Nestinghouse analysis of lifting arrangement for reactor vessel head & upper internals expected by 830315 HUNTER.R 8 Indiana & Michigan Electric Co. 82/07/27 DENTON.H R Office of Nuclear Reactor Regulation. Birector. 31pp 15606 027 24X Fiche: 50-015, 82/07/29, 8210050138
- B210050159 Application for amend to Licenses DPR-58 & DPR-74, proposing Tach Spec changes for placement of new post-accident containment hydrogen monitoring sys to satisfy NURES-0737. Item II F. 1 & & to remove existing equipment from svc MUNTER.R S Indiana & Michigan Electric Co 82/09/29 DENTON.H R. Office of Nuclear Reactor Regulation. Director 2pp 15605 149 24X Fiche 50-315.82/09/29,8210050159
- --8210050160 Proposed Tech Spec 3/4 6 4 re combustible gas control * Indiana & Michigan Electric Co 82/09/29 3pp 15605 151 24X Fiche 50-315.82/09/29.8210050159
- 8210120230 Forwards proprietary Suppl 1 to XN-NF-82-37(P), "DC Cook Unit 2.Cycle 4 SAR, Thermal-Hydraulic Analysis," providing add1 analysis of steady-state thermal margins during Cycle 4 operation Rept withheld (ref 10CFR2 790) CHANDLER, J C Exxon Nuclear Co, Inc (subs of Erxon Corp.) 82/09/29 E186NHUT, D Q Division of Licensing 4pp 15656-079 24X Fiche SO-316,82/09/29,8210120230
- 821005021: Second suppl to 820407 application for Cycle 4 reload & uprate license amend Further changes to App A Tech Specs necessary to allow Cycle 4 operation w/Erron Nuclear Cofurl at 3,411 MHt
 HUNTER,R B Indiana & Michigan Electric Co 82/09/30 DENTON.H R
 Office of Nuclear Reactor Regulation. Director 11pp. 15611 246
 24% Fichs 50-316,82/09/30,8210050211.
- 82:0050349 Forwards add1 info re hydrogen mitigation & control at facilities Util continues to work w/TVA & Duke Fower Cotoward completion of executive summary rept on ice condenser hydrogen R&D program
 HUNTER,R 8 Indiana & Michigan Electric Co 82/09/30 DENTON,H R
 Office of Nuclear Reactor Regulation, Director 126pp. 13410.126
 24X Fiche 50-315.82/09/30.8210050349
- 8210080194 Comments on regulatory performance improvement program Comments can be dealt w/by revising program description to take full credit for mgt review afforts Util views on comments will be discussed at meeting scheduled for 821014 XEPPLER.J O. Region 3. Office of Director 82/10/01 DOLAN.J E. American Electric Fower Service Corp DOLAN.J E. Indians & Michigan Electric Co. 2pp 19640 188 24X Fiche: 50-315,82/10/01,8210080194
- 8210060253 Discusses B20707 mgt meeting & forwards Systematic Assessment of Licensee Performance Repts 50-315/82-16 & 50-316/82-16. KEPPLER, J. G. Region 3, Office of Director 82/10/04 DDLAN, J.E. American Electric Power Co., Inc. 3pp. 15620, 198 24X Fiche, 50-315, 82/10/04, 8210060253.
- --B210060254 Systematic Assessment of Licenses Performance Rapts 50-315/82-16 & 50-316/82-16 on 801001-820401. Hajor areas examined util regulatory performance ** Region 3. Office of Director. 82/06/30 7pp 15620.201. 24x Fiche: 50-315, 82/10/04, 8210060253
- --8210060256 Responds to NRC 820625 Systematic Assessment of Licensee Performance Repts 50-015/82-16 & 50-016/82-16. Tuelve previously trained operations hired & computarized radiation exposure maint sys & security access control sys installed HUNTER:R S Indiana & Michigan Electric Co. 82/07/27. XEPPLER:J G. Region 3, Office of Director. 35pp. 15620.208. 24X Fiche: 50-015, 82/10/04, 8210060253
- 82(0150491 Confirms 820922 telcon re masonry walls. Addl info required within 45 days to complete review VAROA,8 A. Operating Reactors Branch 1. 82/10/04. DOLAN, J Indiana & Michigan Electric Co. 3pp 15717:275. 24X Fiche: 50-315, 82/10/04, 8210150491.
- 8210230340 Forwards Amends 63 & 45 to Licenses DPR-38 & DPR-74, respectively, safety evaluation & notice of issuance & availability. Amend reviess Tech Space changing surveillance requirements for boron & safety injection sys CILIMBERO, R. L. Operating Reactors Branch 1, 82/10/04 DOLAN, J. Indiana & Michigan Electric Co. 2pp. 15807:259, 24X Fiche: 50-315, 82/10/04, 8210250340.

- --B210250393 Amends &3 & 45 to Licenses DPR-58 & DPR-74, respectively changing Tech Space re surveillance requirements for boron & safety injection sys & updating core flux VAROA: B & Dperating Reactors Branch 1 BZ/10/04 73pp 15807 261 24% Fiche 50-315.82/10/04,8210250340
- --8210250394 Safety evaluation supporting Amends 63 & 45 to Cicanes DPR-58 & DPR-74 respectively Office of Nuclear Reactor Regulation, Director B2/10/04 5pp 15807 334 24X Fiche 50-315.82/10/04.8210250340
- --8210250395 Notice of issuance & availability of Amends 63 % 45 %
 Licenses DPR-58 & DPR-74, respectively
 VAROA, S.A. Operating Reactors Branch 1 82/10/04 2pp
 13807 339 24X Fiche 50-315, 82/10/04,8210250340
- BQ1013C434 Forwards tafety evaluation re main steam line break w/continued feedwater addition & contractor technical avaluation rept H/o technical evaluation rept H/o technical evaluation rept VARQA-S A Operating Reactors Branch 1 82/10/05 DDLAN, J Indiana & Michigan Electric Co 2pp 13716.090 24X Fiche, 50-315, 82/10/05, 8210150434
- --B210150437 Bafety evaluation re main steam line break w/continus feedwater addition # Operating Reactors Branch 1 82/10/05 7pp 15716 092 200 Fiche 50-315, 82/10/05, 8210150434
- 8210130123 Forwards proprietary "Users Manual for PTSPHR2-FORTRAN Program for Simulation of PHR Plant Transients" & Suppl 1 to manual Affidavit supporting proprietary classification of documents enci Manuals withheld (ref 100FR2 770)

 OMSLEY, 0 F Exxon Nuclear Co. Inc (subs of Exxon Corp)

 82/10/08 THOMAS. CO 0 Standardization & Special Projects Branc)

 4pp 15673 097 24X Fiche 50-316,82/10/08,8210130123
- 8210150033 Forwards Revision 1 to XN-NF-82-32(P), "Plant Transient Analysis for DC Cook Unit 2 Reactor at 3,425 MHt," including DNB analysis method changes to support Cycle 4 operation Revision withheld (ref 100FRZ 790) OMSLEY,0 F Exxon Nuclear Co., Inc. (subs. of Exxon Corp.) 82/10/08 EISENHUT,D O Division of Licensing 1p 15715 287 24X Fiche 50-316,82/10/08,8210150033
- 8210250228 Forwards proprietary responses to five of 16 questions per NRC 820730 request for add1 info re hydrogen control issues for ice condenser plants, particularly CLABIX computer program Responses withheld (nef 100FR2, 790) HUNTER, R 8 Indiana & Michigan Electric Co 82/10/15 DENION H4 Office of Nuclear Reactor Regulation, Director 2pp 15789 337 24X Fiche 50-315, 82/10/15, 8210250228.
- Q Inspection reports, IE Bulletins & correspondence
- 8210070007 Responds to FOIA request for eight categories of records a steam generators & steam turbines App A documents provided in R Udell FOIA Request 81-313 Forwards documents listed in App B.
 FELTON, J H Division of Rules and Records B2/08/10 L0R0,0 J Hinthrop, Stimson, Putnam & Roberts, 9pp 15445,063 24X Fiche: 50-000-62/08/10,8210070007
- --8210070139 Forwards tabulated data on steam generator insplicable facilities. Data should be provided to licensees IPPOLITO, T Operating Reactors Assessment Branch 82/04/01 VAROA:8 Operating Reactors Branch 1 5pp 15645,131 24K Fiche 50-000.82/08/10.8210070007
- 8210040387 Forwards IE Insp Repts 50-315/82-08 & 50-316/82-08 of 620412-16,0514 & Oái0 Deficiencies referred to Dfc of Investigation for review & investigation for review & investigation NORELIUS, C E. Division of Engineering & Technical Programs 82/09/22. DLAN.J E. Indiana & Michigan Elactric Go 299 13615,330 24K Fiche 50-315,82/09/22.8210060387
- --8210060393 IE Insp Repts 50-315/82-08 & 50-316/82-08 on 920412-182 & 0610 Deficiencies noted inadequate fire protection of 14fe shutdown capability, inaccurate statements, inadequate procedure for alternate safe shutdown & inadequate lighting GROBE, J. A., STONE, J.C., HAUGHNEY, C. J. Division of Engineering Technical Programs 82/09/17 27pp 15615-352 24% Fiche, 50-315, 82/09/22, 8210060387.
- 8210030274 Ack receipt of 820914 ltr informing NRC of steps tates to correct violations noted in 1E Insp Repts 50-315/82-12 k 50-316/82-12.

 STREETER, J.F. Division of Project & Resident Programs 82/89/M DOLAN, J.E. American Electric Power Service Corp. DOLAN, J.E. Indiana & Michigan Electric Co. 1p. 15609:187. 24X Fiche: 50-315, 82/09/24, 8210050274

- --E210030276 Responds to NRC 820816 ltr re violations noted in IE Insp Repts 50-315/82-12 & 50-316/82-12 Corrective actions plant canager until issue memo to plant depts by 820930 re procedures for installation of new design changes HERING: R F Indiana & Michigan Electric Co 82/09/14 KEPLER. J G Region 3. Office of Director 3pp 15609 188 24x Fiche 50-315,82/09/24,8210050274
- 8210050253 Discussed B20707 mgt meeting & forwards Systematic Assessment of Licensee Performance Repts 50-315/82-16 & 50-315/82-16 & SEPPLER, J G Region 3, Office of Director 82/10/04 DOLAN, J E American Electric Power Co , Inc DOLAN, J E Indiana & Michigan Power Co 3pp 15620 198 24X Fiche 50-315,82/10/04,8210060253
- --8210060254 Systematic Assessment of Licensee Performance Repts 50-315/82-16 & 50-316/82-16 on 801001-820401 Major areas examined util regulatory performance, * Region 3, Office of Director 82/06/30 7pp 15620 201 24x Fiche 50-315,82/10/04,8210060253
- --B210060256 Responds to NRC 820625 Systematic Assessment of Licensee Ferformance Repts 50-315/82-16 & 50-316/82-16 Twelve previously trained operators hired & computerized radiation exposure maint sys & security access control sys installed F/UNIER.R 5 Indiana & Michigan Electric Co B2/07/27 KEPPLER.J G Region 3. Office of Director 35pp 15620-208 24X Fiche 50-315,82/10/04,8210060253
- -208190233 IE Info Notice 80-35, Suppl 1, "Leaking & Dislodged I-125 lmplant Seeds " Svc list encl COBB.L (Division of Fuel Facilities, Materials & Safeguards 82/10706 Consolidated Edison Co of New York 66pp 15761 250 24X Fiche 50-000,02/10/06.8208190233
- 1208190238 1E Bulletin 82-03, "Stress Corrosion Cracking in Thick-Hall-Large-Diameter-Stainless Steel.Racirculation Sys Piping at BUR Plants "Svc list encl DEYGUNO.R C Director's Office, Office of Inspection and Enforcement 82/10/14 Consolidated Edison Co of New York 115pp 15810 125 24% Fiche 50-000, 82/10/14,8208190238
- 210150368 EN-Bi-047A on 821014, order imposing civil monetary penalty in amount of \$52,000 issued to licenser re violations concerning fire protection program & containment integrity One violation withdraum & two modified CRAIG.J. AXELRAD.J Director's Office. Office of Inspection and Enforcement 82/10/14 ip 15721 307 24X Fiche 50-315.82/10/14, 8210150388
- Periodic operating reports & related correspondence
- 210190676 Forwards Sr-89 t Sr-90 data not completed by contractor until after due date for submittal of semiannual radioactive effluent rolease rept for Jan-June 1982 HUMIER, R S Indiana & Michigan Electric Co 82/10/01 KEPPLER, J G Region 3. Office of Director 2pp 19738 197 24X Fiche 50-315,82/10/01,8210190676
- -8210190685 "Effluent & Waste Disposal Semiannual Rept-1982, Gaseous Effluents-Elevated Release." Br-89 & Sr-90 data omitted from original 820827 submittal andiana & Michigan Electric Co 82/10/01 10pp 15738 199 24% Fiche 50-315.82/10/01,8210190676
- Reportable occurrences. LERs & related correspondence
- 210040321 Forwards LERs 82-072/03L-0 & 82-075/03L-0 SMITH.H 6 Indiana & Michigan Electric Co 82/07/22 KEPPLER.J 9 Region 3. Office of Director 1p 15586 171 24X Fiche 50-316.82/07/22.8210040321
- 8210040327 LER 82-072/03L-0, on 820824, reactor trip occurred as result of facilure in 120-volt ac vital bus Caused by burned out resistor (Ri) & diode (Di) on oscillator board & associated fuse Dscillator board & fuse replaced PALMER: R A Indiana & Michigan Electric Co. 82/09/22 Region 3. Office of Director 1p. 15586 172 24X Fiche. 50-316, 82/09/22, 8210040321
- 8210040330 LER 82-075/03L-0 on 820824, following reactor trip, RCS dose equivalent & I-131 concentration exceeded i.0 uCi/g steady state limit. Caused by inadvertent removal from svc of chemical & vol control sye mixed bed demineralizer. PALMER.R A Indiana & Michigan Electric Co 82/09/22 Region 3, Office of Director App 15586 173 24X Fiche 50-316. 82/09/22.8210040321
- '10040201 Forwards updated LER 82-064/03X-1 SMITH-, H Q Indiana & Michigan Electric Co 82/07/23 KEPPLER, J. Q. Region 3. Office of Director. 1p 15583'161 24X Ficha: 50-316, 82/07/23, 8210040201

- --8210040209 Updated LER 82-064/03X-1 on 820724. Loop 3 overtemp Delta-T trip setpoint found high Caused by setpoint drift New module installed calibr & verified operational Loop returned to svc PALMER, R.A. Indiana & Michigan Electric Co. 82/09/23 Region 3, Office of Director 1p 15583 162 24X Fiche 50-316,82/09/23, 8210040201
- 8210060277 Forwards LER 92-076/03L-0 SMITH:N 0 Indiana & Michigan Electric Co 82/09/29 KEPPLER, J Q Region 3. Office of Director 1p 15621 168 24X Fiche 50-316, 82/09/29, 8210060277
- --B210060313 LER 82-076/03L-0 on 820915, discovered diesel room AB carbon diexide sys isolated w/no personnel in room Cause not stated Bigns posted cautioning personnel to reatore carbon diexide sys when exiting Administrative action taken LAMP. H 5 Indiana & Michigan Electric Co 82/09/29 Region 3, Office of Director 1p 15621 169 24X Fiche 50-316,82/09/29, 821006027
- 8210080189 PNO-III-82-105 on 820930. Pacifity shut down for 3 days to repair weld crack in 1-inch feedwater drain between containment penetration for steam generator 1 & last feedwater check valve. REVES, L. STREETER, J. SPESSARD, R. Region 3, Office of Director 82/10/01 ip. 15640.180 24X Fiche 50-316,82/10/01,8210080189
- 8210180120 Forwards LERs 82-077/03L-0 & 82-078/03L-0. SNITH-W 0 Indiana & Michigan Electric Co 82/10/05 KEPFLER, J 0 Region 3. Office of Director 1p 15717-325 24X Fiche 50-316, 82/10/05, 8210180120
- ---8210180123 LER 82-077/03L-0 on 820907, equalizing valve on inner door of upper containment personnel airlock found leaking slightly during containment antry Cause unknown Valve actuating mechanism adjusted PIEHL, R H, Indiana & Michigan Electric Co 82/10/05. Region 3, Office of Director 1p 15719 326 24X Ficha 50-316,82/10/05,82/10/80120
- ---B210180127 LER 82-078/O3L-0 on 820918 & 20.RCB dose equivalent I-131 concentration exceeded 1 0 uCi/g steady-state limit Caused by RCS dose equivalent I-131 spiked to max of 1 76 uCi/g PALMER.R A Indiana & Michigan Electric Co B2/10/O5 Region 3. Office of Director App 15719 327 24X Fiche 50-316, 82/10/O5.8210180120
- 8210190727 Forwards LER 82-080/03L-0 SMITH-W 0 Indiana & Michigan Electric Co 82/10/08 KEPPLER.J Q Region 3. Office of Director 1p 15736 298 24X Fiche 50-316.82/10/08.8210190727.
- DUCKET 50-317 CALVERT CLIFFS NUCLEAR POWER PLANT, UNIT I
- 8203050387 Forwards IE Insp Repts 50~317/82-02 & 50~318/82-02 on 820106-0202 & notice of violation STAROSTECKIR. Division of Project & Resident Programs 82/02/16 LUNOVALL,A.E Baltimore Oas & Electric Co 2pp 12134 298. 24X Fiche: 50~317, 82/02/16, 8203050387
- --B210190714 IE Insp Repts 50-317/82-02 & 50-318/82-02 on H20106-0802 Noncompliance noted failure to adequately control special processes associated w/repair of saltwater piping & failure to properly neutralize regenerative waste ARCHITZEL.R.E., MCCABE.E.C. Division of Project & Resident Programs. 82/02/12. 11pp 15751 024 24% Fiche: 50-317.82/02/16.8203050387
- 8210210544 Releases public version of revised emergency response plan implementing procedures.
 FELTON, J. M. Division of Rules and Records. 82/07/R3 Document Management Branch. 1p 15782 330. 24X Fiche 50-317.82/07/23, 8210210544.
- --8210210545 Forwards public version of revised emergency response plan implementing procedures, including Procedures EPIP 5.5 re exercises, test & drills & EPIP App B. 2 re maps & charts * Baltimore, Oss & Electric Co 82/09/15. CLARK, R. A Operating Reactors Branch 3 ip 15782:331, 24X Fiche: 50-317, 82/09/23, 8210210344

- --8210210551 Public version of revised emergency response plan implementing procedures including Procedures EPIP 3 5 re-exercises, test & drills & EPIP App B 2 re-maps & charts List of effective pages encl • Baltimore Gas & Electric Co Ficha 50-317, 82/09/23, 8210210544 82/09/15 20mg 15782 332 24X
- 8210120134 Forwards third suppl to 790914 fire protection safety evaluation, resolving Item 3 2 1, Fire Hazards Analysis "Ninety-day period to inform of installation schedule for Minety-day garios to inform of installation schedule for source range flux monitoring instrumentation acceptable CLARK, R.A. Operating Reactors Branch 3 82/09/27 LUNDVALL, A.E. Baltimore Gas & Electric Co. 1p. 15492 157. 24X Fiche 50-317, 82/09/27, 8210120134
- --B210120139 Safety evaluation canciluding that proposed five protection design meets requirements of App R to IOCFR50. Items III G 3 & III L re safe shutdown in event of fire FIGRAVANTE.N. MARRISON.O., JAFE.D. Decrating Reactors Branch I B2/09/27 9pp 15692 158 24X Fiche.50-317.82/09/27,8210120134
- 8210150423 Application for amend to Licenses DPR-53 & DPR-49 consisting of Revision 10 to security plan, allowing devitalization of vital areas during cold outages Plan withheld (see 100FR73 21) tre: 100FR/3 211
 BOMMAKER,N J Baltimore Gas & Electric Co 82/10/07, CLARK,R A Operating Reactors Branch 3 3pp. 15704,021 24K
 Fiche 50-317,82/10/07,9210150423
- 8210180005 Submits update of util progress in closing THE Action Items I C 1/11 F 1 & 111.A 1 2.

 LUNDVALL.A E Baitimore Gas & Electric Co 82/10/12 CLARK.R A. Operating Reactors Branch 3 3pp 15720 028 24X

 Fiche 50-317.62/10/12.8210180005
- P Operating license stage documents & correspondence
- 8210010008 Responds to FOIA request for 19 categories of documents re nuclear reactor events & safety problems Forwards documents listed in App A PELTON, J H Division of Rules and Records 82/06/28 Critical Mass Energy Project 15pp. 13727:005 24X Fiche: 50-000, 82/06/28, 8210010008 82/06/28 UDELL.R A
- --8204270048 Recommends prompt attention be given to problem of reactor coolent pump closure stud corrosion detected at facilities Response by 820415 requested EISENHUT, D. G. Division of Licensing. 82/03/24. HANAUER, S. H. Division of Bystems Integration (post 811005). 3pp 66035 222 24X Fichs 50-000, 82/06/28, 8210010008
- 8210080015 Add1 response to FDIA request for 19 categories of info ra nuclear reactor events & safety problems Forwards documents listed in App A Documents in App B completely withheld (ref FDIA Exemption 5) FELTON, J M Division of Rules and Records B2/07/12 Critical Mass Energy Project, 9pp. 13665,027, 24X Fiche 50-000, 82/07/12,8210080015 82/07/12, UDELL.R A
- --8210080064 Trip rept of 820207 visit to NRR in Bethesda, MD & 820208-10 site visit re installation of 10-inch automatic isolation valve in main feedwater sys Spec 6750-M-253 for nuclear carbon steel gate-globe & check valves & related info encl. BERRDENR 0. EGAG. Inc. 82/03/22 47pp 15665:192, 24: Fiche: 50-000, 82/07/12, 8210080015

- --8210070117 Amends 75 & 56 to Licenses DPR-53 & DPR-69, respective ALOUVUILY Amends /3 % 36 to Licenses DPN-53 & DPR-69, respectors-ting typographical errors re inservice insp & valve testing & allowing start up of reactors w/inoperable but isolated power operated relief valves CLARK, R & Operating Reactors Branch 3 82/09/20 34pp 15645 009 24x Fiche 50-317, 82/09/20,8210070106
- -- 8210070125 Safety evaluation supporting Amends 75 & 56 to Licens DPR-53 & DPR-69 respectively JAFFE, D H Diffice of Nuclear Reactor Regulation, Director 82/09/24 4pp 15645 043 24% Fiche 50-317,82/09/20,821007
- --8210070130 Notice of issuance & availability of Amends 75 % 5& 1 Licenses DPR-33 & DPR-69, respectively CLARK.R A Operating Reactors Branch 3 82/09/20 2pp 15545 047. 24X Fiche 50-317, 82/09/20,8210070106
- 8210180124 Forwards proprietary & nonproprietary versions of "Risiof Eddy Current Testing on Ouide Tubes at Calvert Cliffs I After Cycle 5"
 LUNDVALL, A E Baltimore Gas & Electric Co 82/09/22 CLARK, R Operating Reactors Branch 3 2pp 15719 097 24X
 Fiche 30-317, 82/09/22, 8210180124
- --8210180133 Nonproprietary version of "Results of Eddy Current Te on Ouide Tubes at Calvert Cliffs I After Cycle 5" e Combustion Engineering. Inc CEN-216(B) B2/08/31 7pp 15719 097 24X Fiche 50-317.82/09/22.8210180128
- B210270412 Forwards Amends 77 & 58 to Licenses DPR-53 & DPR-69, taspectively, safety evaluation & notice of issuance & availability Amends revise Tech Spec Table 3 7-4 which lists anubbers that require periodic insp & testing
 JAFFE.D H Operating Reactors Branch 3 82/09/23 LUNDVALL:A
 Baltimore Cas & Electric Co 3pp 15863 273 24X
 Fiche 50-317.82/09/23.8210290412
- --8210270428 Amends 77 & 58 to Licenses DPR-58 & DPR-69, respective revising Tech Spec Table 3 7-4 which provides lists of safety-related hydraulic shock suppressors (snubbers) which require periodic insp & testing CLARK, R A Operating Reactors Dranch 3 82/09/23 26pp 15863:276 24X Fiche 50-317, 82/09/23,8210290412
- --8210270437 Bafety evaluation supporting Amends 77 & 58 to Licenti DRR-53 & DRR-69, respectively * Office of Nuclear Reactor Regulation, Director 15843:302 24X Fiche 50-317,82/09/23,8210290412
- --8210270444 Notice of issuance & availability of Amends 77 L 58 to Licenses DPR-58 & DPR-59.respectively CLARK.R A Operating Reactors Branch 3 82/07/23 2pp 15863:305. 24X Fiche 50-317.82/07/23.8210270412
- 8210130338 Application to amend Licenses DPR-53 & DPR-69, revising Tech Speck re pressuriser limiting condition for operation & associated surveillance requirements.

 LUNDVALL: A E Baitimore Oas & Electric Co 82/09/29 CL/
 Operating Reactors Branch 3 3pp 15680 268 24x

 Fiche 50-317:82/09/29:8210130338. 82/09/29 CLARK, R A
- --8210130342 Proposed Tech Specs 3 4 4 4 4 4 re RCS pressurizer # Baltimore Oas & Electric Co 82/09/29, 44pp 15680 271 Fiche. 50-317,82/09/29/,9210130338
- 8210150423 Application for amend to Licenses DPR-53 & DPR-69 (ensity of Revision 10 to security plan, allowing devitalization of vital areas during cold outages. Flan withheld (ref 10CFR73, 21) BOWNAKER, N. J. Baltimore Cas & Electric Cu 82/10/0 Operating Reactors Branch 3 3pp. 18704-021 24X Fiche: 50-317, 82/10/07, 8210150423. 82/10/07. CLARKIR A
- 82:0180005 Submits update of util progress in closing TME Action lies I C. 1, II. F 1 & III. A 1 2. LUNDVALL. A. E Baltimore Oas & Electric Co. 82/10/12 CLARKER A Operating Reactors Branch 3, 3pp 15720; 028 Fiche: 50-317, 82/10/12, 8210180005.
- 8210200108 Notification of 821025 meeting w/util in Bethesdard I. discuss control of heavy loads, JAFFE.D H Operating Restors Brench 3. 82/10/18 CLARKA A Operating Reactors Branch 3. 2pp 15767,304, 24X Fiche: 50-317,82/10/18,8210200108

- 1 Inspection reports, IE Bulletins & correspondence
- E2030503B7 Forwards 16 Insp Repts 50-317/82-02 & 50-318/82-02 on 620106-0202 & notice of violation STARD51ECKI, R Division of Project & Resident Programs 62/02/16 LUCOVALL, A E Baltimore Gas & Electric Co 2pp 12134 298 24X Fiche 50-317, 62/02/16, 820305038
- --R210190702 Natice of violation from insp on 820106-0202 STAROSTECKI, R Division of Project & Resident Programs 82/02/16 29P L5751 022 24X Fiche 50-317,82/02/16,8203050387
- --8210390714 IE Insp Repts 50-317/82-02 & 50-318/82-02 on 820106-0202
 Noncomptiance noted failure to adequately control special
 processes associated w/repair of saltwater piping & failure
 to properly neutralize regenerative wasts
 ARCHITZEL, R E , KCCA8E, E C Division of Project & Resident
 Programs 82/02/12 lipp 15751 024 24X Fiche 50-317,82/02/16.
 8203050387
- E2:0070007 Responds to FOIA request for eight categories of records re steam generators & steam turbines App A documents provided in R Udell FOIA Request B1-313 Forwards documents listed in App B FELTON. J M Division of Rules and Records 62/08/10 LONG, D J Winthrop, Stimson, Putnam & Roberts 7pp 15645 063 24X Fiche 50-000.62/08/10.8210070007
- --8210070172 Forwards info re steam generator integrity & insps at all operating PURs.per 750320 & 21 requests Details of insps. including defect indications tube plugging criteria & tubes plugged will not be provided except for Point Beach i GOLLER.K R Division of Reactor Licensing (NRR-1975 only) 75/03/24 MACCARY, R Division of Technical Review (NRR-1975 only) 5pp 15645 196 24X Fishe 50-000,82/08/10.8210070007
- 6210060079 Forwards IE Insp Repts 50-317/82-06 & 50-318/82-06 on E20315-16 & notice of violation MARTIN, T T Division of Engineering & Technical Programs 82/09/17 LUNDVALL, E Baltimore Oas & Electric Co 2pp 15614 345 24X Fiche 50-317,82/09/17,8210060099
- --B210060104 Notice of violation from insp on 820315-16

 Division of Engineering & Technical Programs B2/09/17 2pp
 15614 347 24X Fiche 50-317,82/09/17,8210060099
- -- P210060127 IE Insp Repts 50-317/82-06 & 50-318/82-06 on 820315-16
 Noncompilance noted failure to establish adequate
 procedures, failure to follow radiation protection procedures
 & failure to make necessary radiological surveys
 PLUMLEE, K E , QREENMAN, E Q Division of Engineering & Technical
 Programs 82/09/17 10pp 15614 349 24X Fiche 50-317,82/09/17,8210060097
- E21007010& Forwards Amends 75 & 56 to Licenses DPR-53 & DPR-69, respectively, safety evaluation & notice of issuance & availability Amends correct typographical errors retriestry to the 5 valve testing JAFFE, D H Operating Reactors Branch 3 82/09/20 LUNDVALL, A E Baltimore Gas & Electric Co 3pp 15645 006 24X Fiche \$0-317.82/09/20.8210070106
- --6210070117 Amends 75 & 56 to Licenses DPR-53 & DPR-69, respectively, correcting typographical errors re inservice insp & valve testing & allowing start up of reactors w/inoperable but isolated power operated relief valves CLARK, R A Operating Reactors Branch 3 82/09/20 34pp, 15645 009 24X Fiche 50-317,82/09/20,8210070106
- B210180124 Forwards proprietary & nonproprietary versions of "Results of Eddy Current Teating on Guide Tubes at Caivert Cliffs I After Cycle 5"
 LUMBYALL.A E. Baltimore Gas & Electric Co 82/09/22 CLARK.R A Operating Reactors Branch 3 2pp 15719 097. 24X Fich# 50-317.82/09/22,8210180124
- --B210180133 Nonproprietary version of "Results of Eddy Current Testing on Guide Tubes at Calvert Cliffs I After Cycle 5 "
 « Combustion Engineering, Inc. CEN-216(8) 82/08/31 7pp 15719 099 24X Fiche 50-317.82/09/22.0210180124.
- 8210150214 Forwards IE Insp Repts 50-317/82-23 & 50-318/82-19 on 820810-0914 & notice of violation STAROSTECKI.R Division of Project & Resident Programs 82/09/27 LUNDVALL.A E Baltimore Cas & Electric Co 2pp 15705-234, 24% Fiche: 50-317, 82/09/27, 8210150214

- --8210150235 IE Insp Repts 50-317/82-23 & 50-318/82-19 on B20810-0914 Noncompliance noted radiological event not declared nor appropriate response taken & procedures not properly implemented ARCHITZEL.R E. TRIMBLE.D C. MCCABE, E. C. Division of Project & Resident Programs 82/09/27 18pp. 15705 238 24X Fiche 50-317,82/09/27.8210150214
- 8210060240 Forwards notice of violation re IE Insp Repts 50-317/82-07 & 50-318/82-07 on 820413-0511 Violation A re operation w/hydrogen analyzers insperable needs no response Violation B re inadequate review requires full response STAROBIECKI.R. Division of Project & Resident Programs 82/07/27 LVNDVALLA E Baltimore Gas & Electric Co 3pp 15619 322 24X Fiche 50-317,82/09/29,8210060240
- --8210060243 Notice of violation from insp on 820413-0511 Noncompliance noted plant operated w/hoth hydrogen analyzers inoperable plant operating safety review committee performed inadequate review on 800924 & approved revision w/o correct criteria * Region 1. Defice of Director 82/09/29 2pp 15619:325 24x Fiche 50-317,82/09/29.8210060240
- 8210070159 Requests approval for excluding reactor vessel closure studs at facilities, per IE Builetin 82-02 & Reg Ouide 1.65
 Bulting matl complies w/recommended matls
 LUNDVALL, A E Baltimore Qas & Electric Co 82/10/01 DEYOUNO, R C Director's Office, Office of Inspection and Enforcement 3pp
 15627 013 24X Fichs 50-317, 82/10/01, 82107-70159
- 8208190233 IE Info Notice 80-35, Suppl 1, "Leaking & Dislodged I-125 Implant Beeds." Svc list encl COBB. L I Division of Fuel Facilities, Materials & Bafeguards 82/10/06 Consolidated Edison Co of New York. 64pp 15761 250 24X Fiche 50-000,82/10/04.8208190233
- 8210130099 Ack receipt of 820917 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-317/82-20 & 50-318/82-17 MARTIN.T T Division of Engineering & Technical Programs 82/10/06 LUNDVALL, A E Baltimore 0ss & Electric Co 1p 15673 104 24X Fiche 50-317, 82/10/06,8210130099
- --8210130103 Responds to NRC 820319 ltr re-violations noted in IE Insp. Repts 50-317/82-20 & 50-318/82-17 Corrective actions: Operating Instruction.AU Procedure 2 & Instruction 302 revised
 LUNDVALLA E Baltimore Gas & Electric Co 82/09/17, MARTIN.T T. Division of Engineering & Technical Programs 4pp 15673 105 24X Fiche 50-317.82/10/06.8210130099
- 8210190797 Ack receipt of 820913 1tr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-317/82-18 & 50-318/82-16.
 SYAROSTECKI: R Division of Project & Resident Programs 82/10/12 LUNDVALL: A E Baltimore Gas & Electric Co. 1p 15736 314 24X Fiche 50-317, 82/10/12.8210190797
- --B210190803 Responds to NRC 820816 itr re violations noted in IE Insp Repts 50-317/82-18 & 50-318/82-16 Corrective actions Instruction-112 revised to ensure assential equipment will not be inadvertantly removed from svc FTI-107 also revised LUNDVALL.A E Baltimore Oas & Electric Co 82/09/15 STAROSTECKI,R Division of Project & Resident Programs 2pp 15736 315. 24X Fiche: 50-317, 82/10/12, 8210190797
- 8208190238 IE Bulletin 82-03, "Stress Corrosion Cracking in Thick-Wall-Large-Diameter Stainless Steel Recirculation Sys Piping at BWR Plants." Sec list encl DEYOUND.R C. Director's Office. DPFice of Inspection and Enforcement. 82/10/14. Consolidated Edison Co of New York. 115pp 15810:125. 24% Piche. 50-000, 82/10/14. 8208190239.
- R Periodic operating reports & related correspondence
- 8210210328 Forwards monthly operating repts for Sept 1982 LOTITO.E M Baltimore Cas & Electric Co. 82/10/15. Director's Office. Office of Inspection and Enforcement ip. 15762 003. 24X Fiche 50-317, 82/10/15.8210210328
- --8210210457 Monthly operating repts for Sept 1982. LOTITO.E. Baltimore Gas & Electric Co. 82/10/15. 10pp. 15762.004. 24X Fiche: 50-317, 82/10/15, 8210210328.
- 5 Reportable occurrences, LERs & related correspondence
- 8210280305 Forwards LER 81~019/03L-0 RUSBELL,L.S. Baltimore Cas & Electric Co. 81/04/10 ORIGR.B H, Region 1, Philadelphia. Office of the Director (81/03/01). 1p. 13838-361 24X Fichs.50~317.81/04/10.8210280305

- 210280203 Forwards LER 81-023/03L-0 RUSSELL.L B Baltimore Gas & Electric Co 81/04/16 GRIER, B H Region 1. Philadelphia. Office of the Director (81/03/01) 1p 15837 270 24% Fichs 50-317,81/04/16,8210260203
- -8210280205 LER 81-023/03L-0 on 810317, ventilation exhaust damper in cable spreading room did not shut Caused by reversal of Units 1 & 2 control circuits Control & indication circuits reworted HEIBEL, R P Baltimore Oas & Electric Co 81/04/16 Region 1. Philadelphia, Office of the Director (81/03/01) 1p 15837 291 24% Fiche 50-317, 81/04/16, 8210280203
- 210280263 Forwards LER 81~021/03L-0 RUSSELL, L B Baltimore Qas & Electric Co. 81/04/16 ORIER, 8 H Region 1, Philadelphia, Office of the Director (81/03/01) 1p 15837 307 24X Fiche: 50-317, 81/04/16, 8210280263
- -8210280267 LER 61-021/03L-0 on 810320, w/coolant charging pump 12 inoperable due to sticking discharge raisef valve, pump 13 taken out of svc for repair Caused by loss of nitrogen pump 13 Valve rapaired & desurger charged MENDERICH, R. L. HUSEBY, D. E. Baltimore Cas & Electric Co. 81/04/16 Region 1. Philadelphia. Office of the Director (81/03/01) 2pp. 15837-308 24X Fiche 50-317.81/04/16. 8210280263
- 210280296 Forwards LER 81-020/03L-0 RUSSELL,L 8 Baltimore Cas & Electric Co 81/04/16 GRIER, 8. H Region 1. Philadelphia, Office of the Director (81/03/01). Ip 18837 279 24X Fiche 30-317,81/04/16,8210280296
- -8210280301 LER Bi-020/03L-0 on Bi0320 containment normal sump drain, 1-MQV-5463, exceeded max closing time of 13-6 Caused by valve operator open limit switch out of adjustment Bultch adjusted.

 DAVIS,8 H. RIZZO,P O Baltimore Oas & Electric Co Bi/04/16 Region i, Philadelphia, Office of the Director (Bi/03/01). ip 15837 280 24% Fiche 30-317.81/04/16.8210280296
- 8210280249 Forwards LER 81-022/03L-0 RUSSELL.L.8 Baltimore Ons & Electric Co 81/04/23 ORIER.B H Region I: Philadelphia: Office of the Director (81/03/01). ip 15837.051 24X Fiche.50-317.81/04/23.8210280249
- --B210260255 LER B1-022/03L-0 on B10324,ESF actuation sys degraded voltage relay found inoperable, Caused by bind in relay output contacts Contact lever streightened & spring tension increased to hold postbioned lever # Baltimore Gas & Electric Co. B1/04/23. Region 1, Philadelphia, Office of the Director (81/03/01), 2pp. 15837-052 24X Fiche 50-317,81/04/23,8210280249
- 8210270279 Forward: LER 81-024/03L-D RUSBELL, L.B Baltimore Gas & Electric Co. 81/05/01, GRIER. B. H Region 1. Philadelphia. Defice of the Director (81/03/01) 1p 15828, 285. 24X Fiche: 50-317, 81/05/01, 8210270279
- --82(0270280 LER 81-024/03L-0 on 810404.during routine shutdown MBIV 12 closing time exceeded Tech Specs Caused by contemination of valve actuation sys hydraulic fluid resulting in aticking check valves Finer filters will be used.

 DAVIS, S.M., WEIR, P.J. Baltimore Gas & Electric Co. 81/05/01 Region i, Philadelphia Office of the Director (81/03/01). 1p 15828-286. 24X Fiche 50-317,81/05/01,8210270279
- 8210280318 Forwards updated LER 81-021/03L-1 RUBSELL,L B Baltimore Cas & Electric Co 81/03/12. QRIER, B. H Region I, Philadelphia. Office of the Director (81/03/01) ip 15838; 358 24X Fiche: 50-317, B1/05/12, B210280318
- --8210280332 Updated LER 81-021/03L-i:on 810320, discharge relief valve for coolent charging pump 12 lifted & stuck open during testing following mainty-endering second pump inoperable. Caused by pump discharge desurger losing nitrogen precharge * Baltimore Que & Electric Co. 81/05/12, Region i, Philadelphia, Office of the Director (81/03/01), 2pp. 15838, 359, 24X Fiche 50-317, 81/05/12, 8210280318
- 8210270266 Forwards LER 81-032/03L-0 RUBBELLL B. Baltimore Cas & Electric Co. 81/05/20. QRIER, B.H. Region 1. Philadelphia, Office of the Director (81/03/01) 1p. 15827:043. 24% Fiche:50-317.81/05/20.8210270266.

- --B210270269 LER B1-032/03L-0 on B10420, reactor protective ags charmal highpower thermal margin/low pressure & axial shape index trip units bypassed Caused by need to replace transmitter j-TT-112D which drifted high LAGIEWERE, J S , RIZZO, G Baltimore Cas & Electric Co 81/05/24 Region 1, Philadelphia, Office of the Director (B1/03/01) 1; 15827 044 24X Fiche 50-317,81/05/20,8210270266
- 8210270274 Forwards LER 81-033/04T-0 RUSSELL.L B Baitimore Oas & Electric Co 81/05/20 QRIER, H Region 1, Philadelphia, Office of the Director (81/03/01) ip 15823-001 24x Fiche 50-317, 81/05/20, 8210270274
- --B210270275 LER Bi-033/04T-0 on Bi0506, during normal operation, buts, operator discovered waste neutralizing Tank 12 drain valve leaking Caused by small amounts of particulate matter looped between valve seat & wedge Valve flushed & closed & Baltimore Qas & Electric Co Bi/05/20 Region I, Philadelphia, Office of the Director (Bi/03/01) 2pp 15823 CC; 24X Fiche 50-317.81/05/20.8210270274
- 8210270252 Forwards LER 81-030/03L-0 RUSBELL, L. B Baltimore Oas & Electric Co 81/05/22 GRIER, B H Region 1, Philadelphia, Office of the Director (81/03/01) ip 15827 231 24X Fichs 50-317, 81/05/22, 8210270252
- --8210270257 LER 81-030/03L-0 on 810424, reactor protection sys (hard containment pressure trip unit & ESF actuation sys channe) ID containment pressure sensor placed out of syc to replace E/E convertor Isolator failure might be due to mod work a Baitimore Que & Electric Co 81/05/22 Region 1, Philadelphia, Office of the Director (81/03/01) ip 15829 20 24X Fiche 50-317.81/05/22.8210270252
- 8210270276 Forwards LER 81-031/017-0 Detailed event analysis encl RUBBELL, L B Baltimore Oas & Electric Co 81/05/22 QRIER 9 H Region 1, Philadelphia, Office of the Director (81/03/01) 2pp 15828 282 24X Fiche 50-317,81/05/22.8210270276
- --B210270278 LER 81-031/01T-0 on B10518.both auxiliary bldg 10-ft elevation fire hose stations isolated w/o water supply. Caused by instructional error & operator unfamiliarity w/isolation valves Personnel counseled.

 # Baltimore Oas & Electric Co 81/03/22 Region 1. Philadelphia. Office of the Director (81/03/01) 1p [5828 2.4 24X Fiche 50-317.81/05/22.8210270276
- 8210270272 Forwards LER 81-031/03L-0 RUSSELL.L B Baltimore Cas & Electric Co 81/06/01 CRIER.1 H Ragion I, Philadelphia, Office of the Director (81/03/01) 1 15828-280 24% Fiche 30-017.81/06/01.8210270272
- ~-8210270273 LER 81-031/03L~0 on 810508 during attempt to put esergingles i generator 11 back in svc after FCR 80-1013 installation, generator failed to reach rated speed Causef by sticking fuel racks & operating linkages Linkages repaired LAOJEMBKI, J 8. HUSEBY, D E. Baltimore Oas & Electric Co. 81/06/01 Region 1. Philadelphia. Office of the Director (81/03/01), ip 15828 281 24X Ficher 50-317.81/04/01.821027XT.
- 8210270244 Forwards LER 81-035/03L-0 Detailed event analysis entl RUSBELL,L B Baltimore Cas & Electric Co B1/06/05 ORIER, 3 M Region 1, Philadelphia, Office of the Director (81/03/05) 2; 15822 344. 24% Fichs 50-317,81/06/05:8210270244
- --8210270248 LER 81-035/03L-0 on 810506; one cell of 125-volt it vinta chase battery 12 found below Tech Spec min Cause unknown Cell disconnected & will be replaced 4 Battimore Cas & Electric Co. 81/06/05 Region 1, Philadelphia, Office of the Director (81/03/01) 19 15922 544 24X Fiche: 50-317,81/06/05,8210270244.
- 8210080017 "Rept on Calvert Cliffs Unit 1 Loss of Svc Hater on 80028 IMBRO,E.V Director's Office. 81/12/31 40pp 15669:007 (4) Fiche. 50-317.81/12/31.8210080017
- 8210040142 Forwards LER 82-051/03L-0 RUBSELL,L R Baltimore Oas & Electric Co. 82/07/24 KAYES:Ef Region 1: Office of Director 1p 15583 085, 24X Fichs. 50-317: 82/09/24: 8210040142.
- --B250040144 LER 82-051/03L-0. on B20827.plant air header iselational inside containment.i-PA-1040. found open. Caused by valve being inadvertently left open while securing plant at the containment on B20822 Standing instruction issued LA01EMBKI.J S. Baltimore Qas & Electric Co 82/09/24 Rep. 1. Office of Director. 2pp 15583-086. 24x Fiche 50-317. B2/09/24, B210040142.

- E210060385 Forwards LER 82-053/03X-1 & corrected Prompt Rept RO 82-53
 Repts approgriate for Unit 1 only
 FUSSELLL B Baltimore Qas & Electric Co 82/09/27 HAYNES,R C
 Region 1. Office of Director 1p 15615 347 24X
 Fiche 50-317, 82/09/27, 82/0060385
- --8210050390 LER 82-053/03.-i on 820910, hydrogen analyzer D-AE-6519 adjusted out of callbr during initial training exercise, rendering unit inoperable Caused by erroneous adjustment step in chemistry procedure Procedure revised BILLS.J M Baltimore Gas & Electric Co 82/09/27 Region 1, Office of Director ip 15615 348 24X Fiche 50-317, 82/09/27, 82
- --82:0050394 Corrected RO B2-53 on 920910, during Mode i operation, hydrogen analyser unintentionally adjusted out of calibr, rendering unit inoperable Instrument recalibr & returned to wide Rept applicable to Unit i only RUSSELL-L B Baltimore Oas & Electric Co 82/09/13 HAYNES,R C Region 1. Office of Director ip 15615 349 24% Fiche 50-317.82/09/27.8210060385
- 8210130461 Forwards LER 82-056/03L-0 RUSSELL.L B Baltimore Gas & Electric Co 82/09/30 HAYNES,R C Region 1. Office of Director 1p 15682 138 24X Fiche 50-317, 82/09/30, 8210130461
- --8210130465 LER 82-056/03L-0 on 920707, containment particulate & gaseous RMS sample pump tripped & would not restart Caused by failure of shaft coupling due to excessive wear created by corrosion of pump vanes Coupling replaced LAGIENSKI, J S. LUDWIO, P. G. Baltimore Oas & Electric Co. 82/09/30 Region i. Office of Director ip 15692 139 24X Fiche 50-317,82/09/30,8210130461
- 8210130543 Forwards updated LER 82-023/01X-1 RUSSELL.L B Baltimore Gas & Electric Co 82/09/30 HAYNES.R C Region 1. Office of Director ip 15682 279 24X Fiche 50-317.82/09/30.8210130543
- --8210130558 Updated LER 82-023/01X-1 on 820514.unplanned dilution of RCB in excess of 0.5% delta K/K experienced Caused by perforated six tubes in steam generator 11 % 1 tube in steam generator 12 Tube support plate rim cut HENDERLICH, R. L. JENNINGS, R. T. Baltimore Gas & Electric Co 82/09/30 Region 1. Office of Director App 15682 280 24X Fishe 50-317.82/09/30.8210130543
- 821013056B Forwards LER 82-054/03L-0 RUSSELL.L B Baltimore Gas & Electric Co 82/09/30 HAYNES,R C Region 1. Office of Director ip 15679 114. 24X Fiche 50-317,82/09/30,8210130568
- -- G210130576 LER 82-054/03L-0 on 820831.12 auxiliary feedwater pump governor linkage vibrated loose, rendering pump inoperable Caused by loose nut connecting governor lever to connecting rod backed off pin causing pin to come out Pin reinserted JUNGE: M A , L'HEUREUX: R W Baltimore Gas & Electric Co 82/09/30 Region 1, Office of Director ip 15479 115 24X Fáche 50-317,82/09/30,8210130568
- 8210190290 Forwards updated LER 80-041/01X-1 RUSSELL-L B Baltimore Oas & Electric Co 82/10/06, HAYNES.R C Region 1. Office of Director ip 18742 172 24X Ficha 50-317,82/10/06,8210190290
- -- B210190296 Updated LER 80-041/01X-1 on 800821,5 minutes after sVC, water head tanks went from normal operating level to full isophase bus duct cooling low flow alarm received Caused by air compressor failure due to cracked after cooler tubes DAVISS M . HUSEBY.D E Baltimore Oas & Electric Co 82/10/05 Region 1. Office of Director 2pp 15742 173 24X Fiche 50-317,82/10/06,8210190290
- B210190730 RQ on 820827, oyster samples showed datectable levels of concentration of Ag-110m Caused by natural tendency of cysters to concentrate environ silver Radioactive releases for first half of 1982 within allowable limits, FU-RHANN Q R. Baltimore Oas & Electric Co 82/10/11 HAYNEB, R C Region i. Diffice of Director 2pp 15736 270 24X Fiche 50-317, 82/10/11, 8210190730
- B210250154 Forwards LER 82-052/03L-0. RUSSELL.L. B Baltimore Cas & Electric Co 82/10/13 HAYNES:R C Region I, Office of Director Ip 15789, 230 24X Fiche 50-317, 82/10/13, 9210250154.

- --8210250160 LER 82-052/03L-0 on 820913 & 20. emergency diesel generator 11 failed to achieve required rom within 10-s Caused by loose connector on speed switch 0-88-4848 Connector tightened & lock-wired PAVIS, 0 8 , BASSO, L F Baitimore Gas & Electric Co 82/10/13 Region 1, Office of Director 2pp 15788 231 24% Fiche 50-317,82/10/13.8210250154
- DOCKET 50-318 CALVERT CLIFFS NUCLEAR POWER PLANT, UNIT 2

 A Application/construction stage documents & correspondence
- 8210180039 Forwards fee for 820830 Class III license amend request for relief from inservice insp program requirements FABRIZIO, R.F. Baltimore Oas & Electric Co. 82/10/13 MILLER, W.O. License Fee Management Brench ip 15/20 020 24% Fiche 50-318, 82/10/13, 8210180039.
- F Security, medical, emergency & fire protection plans
- 8203050387 Forwards IE Insp Repts 50-317/82-02 & 50-318/82-02 on 820106-0202 & notice of violation.
 8TAROSTECKI.R Division of Project & Resident Programs 82/02/16 LUNDVALL.A.E Baltimore Cas & Electric Co 2pp 12134 298, 24X Fiche 50-317, 82/02/16, 8203050387
- --8210190714 IE Insp Repts 50-317/82-02 & 50-318/82-02 on 820106-0202 Noncompliance noted failure to adequately control special processes Associated w/repair of saltuater giping & failure to properly neutralize regenerative waste ARCHITZEL.R & Division of Project & Resident Programs 82/02/12 11pp 24% Fiche 50-317.82/02/16.8203050387
- 8210210544 Releases public version of revised emergency response plan implementing procedures FELTON.J M Division of Rules and Records 82/09/23 Decument Management Branch ip 15782 330 24X Fiche 50-317,82/09/23, 8210210544
- --B210210546 Forwards public version of revised emergency response plan implementing procedures, including Procedures EPIP 5 5 re exercises, test & drills & EPIP App B 2 re maps & charts # Baltimore Gas & Electric Co B2/09/15. CLARK.R A Operating Reactors Branch 3 ip 19782 331 24X Ficher 50-317,82/09/23. 6210210544
- --B210210551 Public version of revised emergancy response plan implementing procedures including Procedures EPIP 5 5 reexercises test & drills & EPIP App B 2 re maps & charts List of effective pages encl.

 # Baltimore Gas & Elactric Co B2/09/15 Qopp 15782 332 24x Fiche 50-317, 82/09/23, 8210210544
- 8210120134 Forwards third suppl to 790914 fire protection safety evaluation, resolving Item 3 2 1, "Fire Hazards Analysis "
 Ninety-day period to inform of installation schedule for source range flux monitoring instrumentation acceptable CLARK, R.A. Operating Reactors Branch 3 82/09/27 LUNDVALL, A. E. Baltimore Gas & Electric Co. ip. 15692, 157 24X
 Fiche 50-317, 82/09/27, 8210120134
- --8210120137 Bafety evaluation concluding that proposed fire grotection design meets requirements of App R to 10CFR50, Items III 0.3 & III.L re safe shutdown in event of fire FIDRAVANTE, M., HARRISON, O. JAFFE, D. Operating Reactors Branch 1.82/09/27 9pp 15692-158 24X Fiche 50-317,82/09/27,8210120134.
- 8210150423 Application for amend to Licenses DPR-53 & DPR-67 consisting of Revision 10 to security plan, allowing devitalization of vital areas during cold outages Plan withheld (ref 100FR73 21)

 BOMMAKER, N J Baltimore Cas & Electric Co. 82/10/07 CLARK, R, A. Operating Reactors Branch 3 3pp. 15704, 021 24X Ficher 30-317, 82/10/07, 8210150423.
- 8210180005 Submits update of util progress in closing TMI Action Items I C.1. II F 1 & III. A. 1 2
 LUNDVALLA E. Baltimore Oas & Electric Co 82/10/12. CLARK, R. A. Operating Reactors Branch 3 3pp 13720.028 24X
 Fiche. 50-317, 82/10/12, 8210180005
- P Operating license stage documents & correspondence
- 8210010008 Responds to FDIA request for 19 categories of documents renuclear reactor events & safety problems Forwards documents listed in App A FELTON, J M Division of Rules and Records 82/06/28 UDELL, R. A. Critical Mass Energy Project 15pp. 15727 005. 24X Fiche 50-000, 82/06/28, 8210010008

- --8204290048 Recommends prompt attention be given to problem of reactor coolent pump closure stud corrosion detected at facilities Response by 820415 requested EISENHUI, D.Q. Division of Licensing 82/03/24 HAKAUER.8 H Division of Systems Integration (post 811005) 3pp 66035 222 24X Fiche 50-000,82/06/28,8210010008
- 8210080015 Add1 response to FOIA request for 19 categories of info re nuclear reactor events & safety problems Forwards documents listed in App A Documents in App B completely withheld tref FOIA Exemption 5 | FELTON, J. H. Division of Rules and Necords 82/07/12, UDELL, R A Critical Mass Energy Project 9pp 15665 027 24% Fiche 50-000, 82/07/12, 8210080015
- --B210080064 Trip rept of 820207 visit to NRR in Bethesda.MD & B20208-10 site visit re installation of 10-inch automatic isolation valve in main fraduater sys Spec 6750-H-253 for nuclear carbon steel geterglobe & check valves & related info encl BEARDEN.R 9 E0609. Inc 82/03/22 47pp 15665 192 24X Fiche-50-000.82/07/12.8210080015
- 8210070104 Forwards Amends 75 % 56 to Licenses DPR-53 & DPR-59, respectively, safety evaluation & notice of issuance & availability Amends correct typographical errors reinservice insp. & valve testing "AFFE.D H Operating Reactors Branch 3 82/09/20 LUNDVALL.A E Baltimore Oas & Electric Co 3pp 15645.006 24X Fiche: 50-317, 82/09/20, 8210070106
- --B210070117 Amends 75 & 56 to Licenses DPR-53 & DPR-69, respectively, correcting typographical arrors re inservice insp & valve testing & allowing start up of reactors w/inoperable but isolated power operated relief valves CLARK-R A. Operating Reactors Branch 3 62/09/20 34pp 15645 009 24X Fiche 30-317.82/09/20.8210070106
- ~-8210070125 Safety evaluation supporting Amends 75 & 56 to Licenses PRR-53 & DPR-69, respectively JAFFE, D H Office of Nuclear Reactor Regulation, Director 82/09/24 4pp 15645,043 24X Fiche 50-317,82/09/20,9210070106
- ~~8210070130 Notice of issuance & availability of Amends 75 & 56 to Licenses DPR-53 & DPR-69, respectively CLARK, R A Operating Reactors Branch 3 82/09/20 2pp 13545 047 24X Fiche 50-317, 82/09/20, 8210070106.
- 8210290412 Forwards Amenda 77 & 58 to Licenses DPR-53 & DPR-69, respectively, safety evaluation & notice of issuance & availability. Amends revise Tech Spec Table 3 7-4 which lists snubbers that require periodic insp & testing JAFFE, D H Operating Reactors Branch 3 82/09/23 LUNDVALL: A E Battimore Oas & Electric Co Spp. 15863, 273 RAX Fiche 50-317, 82/09/23, 8210290412
- --8210290428 Amends 77 & 58 to Licenses DPR-58 & DPR-69, respectively, revising Tech Spec Table 3 7-4 which provides lists of safety-related hydraulic shock suppressors (snubbers) which require periodic inso & tasting CLARK.R A Operating Reactors Branch 3, 82/09/23 26pp 19863:276 24X Piche:50-317.82/09/23.8210290412
- --8210270437 Safety avaluation supporting Amends 77 & 58 to Licenses DPR-53 & DPR-69, respectively • Office of Nuclear Reactor Regulation, Director, 82/09/23 Spp 15863-302 24% Fiche 50-317.82/09/23.8210290412.
- --8210290444 Notice of issuance & availability of Amends 77 & 58 to Licenses DPR-58 & DPR-69: respectively CLARK, R A. Operating Reactors Branch 3. 82/09/23 2pp 15863.305. 24X Fiche 50-317, 82/09/23, 8210290412.
- 8210130338 Application to amend Licenses DPR-53 & DPR-69, revising Tech Specs to pressurizer limiting condition for operation & associated surveillance requirements.
 LUNDVALL:A E. Beltimore Oas & Electric Co 82/09/29, CLARK:R.A Operating Reactors Branch 3, Spp 15680 269, 24X Fiche: 50-317, 82/09/29, 8210130338
- --8210130342 Proposed Tech Specs 3 4 4 4 4.4 re RCS pressurizer.

 * Beltimore Que & Electric Co. 82/09/29. 44pp. 15680.27i. 24x
 Fiche: 50-317,82/09/29,8210130338
- B210150423 Application for amend to Licenses DPR-53 & DPR-69 consisting of Revision to to security plantallowing devitalization of vital areas during cold outages, Plan withheld (ref 10CFR73, 21)
 BOWMAKER.N.J. Baltimore Oas & Electric Co. B2/10/07, CLARK.R A. Operating Reactors Branch 3 Spp 15704:021 24X
 Fiche: 50-317: B2/10/07: B210150420.

- 8210180005 Submits update of util progress in closing TMI Action Items 1 C 1.II.F 1 & III A 1 2 LUNDVALL.A E Baltimore Gas & Electric Co 82/10/12 CLARK.R A Operating Reactors Branch 3 3pp 15720 028 24x Fiche 50-317.82/10/12,6210180005
- 8210220378 Application to amend License DPR-69, changing BTB for operation of Cycle S at rated power of 2,700 MHt LUNDVALL.A E. Baltimore Gas & Electric Co 82/10/15 CLARK,R a Operating Reactors Branch 3 2pp 19760 017 24x Fiche 30-318.92/10/15.8210220378
- ~-8210220385 Proposed ST9 changes for Cycle 5 operation at rated proposed 2.700 NWt * Beltimore Oss & Electric Co 82/10/15 152pp 15780 024 24; Fichs 50-318,82/10/15,8210220378
- B21020010B Notification of 821025 meeting w/util in Bethesda, MB to discuss control of heavy loads JAFFE, D.H. Operating Reactors Branch 3 82/10/18 CLARK, R.A. Operating Reactors Branch 3 2pp 15767 304 24X Fiche 30-317, 82/10/16, 8210200108
- 8210260299 Forwards Cycle 5 reload amend fee LIPPOLD.W J Baltimore Oas & Electric Co 82/10/21 CLARK.R A Operating Reactors Branch 3 ip 15803 211 24x Fiche 30-318.82/10/21.8210260299
- Q Inspection reports, IE Bulletins & correspondence
- 82030503B7 Forwards IE Insp Repts 50-317/82-02 & 50-318/82-02 on 820106-0202 & notice of violation STAROSTECKI.R Division of Project & Resident Programs 82/82/16 LUNDVALL, A E Baltimore Oas & Electric Co 2pp 12134 298 241 Fiche 50-317, 82/02/16,8203050387
- --8210190702 Notice of violation from insp on 820106-0202 87AROBTECKI.R Division of Project & Resident Programs 82/02/15 2pp 15751 022 24X Fiche 50-317.82/02/16.8203050387
- --8210190714 IE Insp Repts 50-317/82-02 & 50-318/82-02 on 320104-0X2
 Noncompliance noted failure to adequately control special
 processes associated w/repair of saltwater piping & failure
 to properly neutralize regenerative wasts
 ARCHITZEL.R E : MCCABE.E C Division of Project & Resident
 Programs 82/02/12 lipp 15751 024 24X Fiche 50-317/82/02/16
 8203050387
- 8210060099 Forwards IE Insp Repts 50-317/82-06 & 50-318/82-06 pn 820315-16 & notice of violation, MARTIN, T, T Division of Engineering & Technical Programs 82/04 LUNDVALL, A, E Baltimore Qas & Electric Co 2pp 15614 345 ; Fiche, 50-317, 82/09/17, 8210060099
- --8210060104 Notice of violation from insp on 820315-16 * Division of Engineering & Technical Programs 82/09/17 2; 15614 347 24X Fiche 50-317,82/09/17,8210060099
- --8210060127 IE Insp Repts 50-317/82-06 & 50-318/82-06 on 820315-16 Noncompliance noted failure to establish adequate procedures, failure to follow radiation protection procedures & failure to make necessary radiological surveys PLUMILEE.K E., OREENNAN.E. O Division of Engineering & Technice Programs. 82/09/17 10pp 15614 349 24X Fiche 50-317.82/01 8210060099
- B210070106 Forwards Amends 75 & 56 to Licenses DPR-53 & DPR-69, respectively, safety evaluation & notice of issuance & availability. Amends correct typographical errors reinservice insp & valve testing.

 JAFFE, D. H. Operating Reactors Branch 3 82/09/20 LUNOVALLAF Bithors Oas & Electric Co. 3pp. 13645 006 24X Fiche; 50-317,82/09/20,8210070106
- --B210070117 Amends 75 & 36 to Licenses DPR-53 & DPR-69, respectively correcting typographical errors re inservice insp & valve testing & allowing start up of reactors w/inoperable but isolated power operated relief valves CLARK, R A. Operating Reactors Branch 3 B2/09/20 15645:007. 24X Fiche. 50-317, 82/09/20. B210070104
- B210150214 Forwards IE Insp Repts 50-317/82-23 & 50-318/82-19 en 820810-0914 & notice of violation STAROSTECKI.R Division of Project & Resident Programs 62/09/27 LUNDVALL.A E. Baltimore 9as & Electric Co 2pp 15705 234 211 Fiche 50-317, 62/09/27, 8210150214
- --8210150226 Notice of violation from insp on 820810-0914 ** Division of Project & Resident Programs. 82/09/27, 291 15705-226 24% Fish:50-317,82/09/27,8210150214

- --8210150235 IE Insp Repts 50-317/82-23 & 50-318/82-19 on 820810-0914 Honcompliance noted radiological event not declared nor appropriate response taken & procedures not properly implemented ARCHITZEL,R E, TRIMBLE,D C., MCCABE,E C Division of Project & Resident Programs 82/09/27 18pp 15705 238 24X Fiche 50-317,82/09/27,8210150214
- B210060240 Forwards notice of violation re IE Insp Repts 50-317/82-07 t 50-318/82-07 on 820413-0511 Violation A re operation whydrogen analysers inoperable needs no response Violation B re sneadequate review requires full response STAROSTECKI, R Division of Project & Resident Programs 82/09/29 LUNOVALL, A E Baltimore Oas & Electric Ca 3pp 15619 322 24X Fichs 50-317, 82/09/29, 82/006020
- 8210070159 Requests approval for excluding reactor vessel closure stude at facilities,per IE Bulletin 82-02 & Reg Ouide 1 &5 Bolting math complies w/recommended maths LuviDVALL,A E Baltimore Gas & Electric Co 82/10/01 DEYOUNG,R C Director's Office, Office of Inspection and Enforcement 3pp 15527 013 24X Fiche 50-317,82/10/01,8210070159
- 8209190203 IE Info Notice 80-05, Suppl 1, "Leaking & Dislodged I-125 Irplant Seeds " Svc list encl COBB.L I Division of Fuel Factlities, Materials & Safeguards 82/10/06 Consolidated Edison Co of New York 66pp 19761 250 24x Fiche 50-000,82/10/06.8208190203
- P210130099 Ack receipt of 820917 ltr informing NRC of steps taken to correct violations noted in 1E Insp Repts 50-317/82-20 & 50-318/82-17

 MARTIN T Division of Engineering & Technical Programs 82/10/06

 LUNDVALL A E Baltimore Oas & Electric Co 1p 19673 104 24X

 Fiche 50-317.82/10/06.8210130099
- --B210130103 Responds to NRC B20819 ltr re violations noted in IE Insp Repts 50-317/82-20 & 50-318/82-17 Corrective actions Operating Instruction, AD Procedure 2 & Instruction 302 revised UNIDVALL, A E Bultimore Gas & Electric Co 82/09/17 MARTIN, T T Division of Engineering & Technical Programs 4pp 15673 105 24X Fiche 50-317, 82/10/06,8210130099
- 6210190797 Ack receipt of 820915 ltr informing NRC of steps taken to correct violations maked in IE Insp Repts 50-317/82-18 & 50-318/82-16 Act of Project & Resident Programs 82/10/12 LUMBVALL, A.E. Baltimore Oas & Electric Co. 1p. 15736-314, 24X Fiche 30-317, 82/10/12, 8210190797
- ---0210190803 Responds to NRC 020816 itr re violations noted in IE Insp Repts 50-317/82-10 & 50-316/82-16 Corrective actions Instruction-112 rovised to ensure essential equipment will not be inadvertently removed from svc FTI-107 also revised. LUNDVALL.A E Baltimore Oas & Electric Co 82/09/15 STAROSTECKI,R Division of Project & Resident Programs 2pp 15736 315 24X Fiche 50-317, 02/10/12,0210190797
- 82:018039 Forwards fee for 820830 Class III license amend request for relief from inservice insp program requirements. FARRIZIO,R F Baltimore Gas & Electric Co 82/10/13 MILLER,W U License Fee Kanagement Branch ip 15720 020 24X Fiche 50-318,82/10/13,8210180039
- B208190238 IE Bulletin B2-03, "Stress Corrosion Cracking in Thick-Wail: Large-Diameter, Stainless Steel: Recirculation Sys Piping at BMR Plants "Syc list enci DEYOUNO.R C Director's Office, Office of Inspection and Enforcement 82/10/14 Consolidated Edison Co of New York 115pp 15810 125 24X Fiche 50-000, 82/10/14,8208190238
- R Periodic operating reports & related correspondence
- 8210210328 Forwards monthly operating repts for Sept 1982 LOTITO.E M Baltimors Gas & Electric Co 82/10/15 Director's Dffice. Office of Inspection and Enforcement 1p. 15762 003 24X Fiche 50-317.82/10/15,8210210328
- --B210210457 Monthly operating repts for Bept 1982 LOTITO, E Baltimore Cas & Electric Co. 82/10/15. 10pp 15762 004 24X Fiche 50-317,82/10/15,8210210328
- S. Reportable occurrences, LERs & related correspondence
- B210280194 Forwards LER 81-014/03L-0 RUSSELL, L B Baltimore Oas & Electric Co 81/04/03 GRIER, B H. Region 1, Philadelphia, Office of the Director (81/03/01) ip. 15837-030 24X Fiche 50-318-81/04/03-8210R80194

- --8210280200 LER 81-014/03L-0 on 810305,4-tV buses 21 & 24 ESF actuation sys degraded voltage relays found out of calibr Cause unknown Trip setpoints readjusted fislays will be tested at increased frequency DAVIS,9 M. RIZZO,P O Baltimore Gas & Electric Co 81/04/03 Region 1. Philadelphia. Office of the Director (81/03/01) 2pp 15837 031 24X Fichs 50-318,81/04/03,8210280194
- 8210280279 Forwards LER 81-013/03L-0 RUSSELL,L B Baltimore Cas & Electric Co B1/04/03 GRIER, B H Region 1, Philadelphia, Office of the Director (81/03/01) 1p 15837 044 24X Fiche 50-318.81/04/03.8210280279
- --8210280284 LER BI-013/03L-0 on Bi0304, while installing instrumentation, temporary shunt opened, causing loss of power to low prassure safety injection gump 22 & momentary loss of shutdown cooling flow Caused by opened lead on one and of shunt HENDERLICH, R L RIZZO, P 0 Baltimore Oas & Electric Co BI/04/03 Region I. Philadelphia, Diffice of the Dir.ctor (BI/03/01) 2pp 15837 045 24X Fichs 50-318,81/04/03, B210280279
- 8210280191 Forwards LER 81-012/03L-0 RUSSELL.L B Baltimore Oas & Electric Co B1/04/08 ORIER, B H Region 1, Philadelphia, Office of the Director (81/03/01) 1p 15837 064 24x Fiche 50-318,81/04/08.8210280191
- --B210280195 LER 81-012/03L-0 on 810309, while personnel were exiting containment bidg via normal personnel hatch, both doors were open simultaneously Caused by broken cam follower in door operator Maint on clutches incorporated into procedures a Baltimore Qas & Electric Co 81/04/08 Region 1, Philadelphia, Office of the Director (81/03/01) 2pp 15837 045 24X Fiche 50-318,81/04/08,8210280191
- 8210280336 Forwards LER 81-015/03L-10 ROBSELL.L B Baltimore Cas & Electric Co 81/04/17 GRIER, B H Region 1, Philadelphia, Office of the Director (81/03/01) 1p 18838 324 24X Fiche 50-318,81/04/17,8210280336
- --B2102B0341 LER 81-015/03L-0 on 810319, results of routine sample of boric acid storage tank 21 revealed boric acid concentration greater than Tech Bpc 1 Limit, reducing borated warer sources to one Cause undetermined

 # Baltimore Oas & Electric Co 81/04/17 Region 1.
 Philadelphia, Office of the Director (81/03/01) 2pp 15838 325 24% Fichs 50-318.81/04/17,8210280336
- B210270237 Forwards LER 81-022/03L-0 RUSBELL, L B Baltimore Cas & Electric Co 81/05/15 GRIER. B H Region 1, Philadelphia, Office of the Director (81/03/01) 1p 15828 275 24X Fiche 50-318,81/05/15,8210270237
- --8210270241 LER 81-022/03L-0 on 810419, during power increase, containment gaseous & particulate radioactivity monitoring sys sample failed Caused by broken motor coupling Motor coupling replaced

 a Baltimore Qas & Electric Co 81/05/15 Region 1.
 Philadelphia, Office of the Director (81/03/01) 2pp 15828 276 24% Fiche 50-318,81/05/15,8210270237
- 8210040216 Forwards LER 82-042/03L-0 RUSBELL,L B Baltimore Gas & Electric Co 82/09/23 HAYNES,R C Region 1, Office of Director 1p 19586 132 24X Fiche. 80-318. 82/09/23. 8210040216
- --B210040226 LER B2-042/03L-0 on 820824, inner door on normal personnel hatch to containment would not shut completely Caused by broken cam follower to handwheel Inner door repaired Matls upgraded MENDERLICH, R.L., WEIR, P.J. Baltimore Gas & Electric Co. B2/09/23 Region 1, Deflice of Director 1p 15586 133 24X Fiche 50-318, 82/09/23, 8210040216
- 8210040066 Forwards LER 82-041/03L-0 RUSSELL,B Baltimore Gas & Electric Co 82/09/24 HAYNES,R C Region 1, Office of Director 1p 15581 235 24X Fiche 50-318,82/09/24,8210040066
- --8210040069 LER 82-041/03t-0 on 820826, excessive leak rate discovered past containment personnel air lockout & door gasket. Caused by decrease in force holding door shut Door operating mechanism adjusted to increase pressure
 JUNGE, M. A. Baltimore Oas & Electric Co. 82/09/24 Region 1,
 Office of Director 1p 15581, 236, 24X Fiche, 30-318, 82/09/24,
 8210040066.
- 8210040211 Forwards LER 82-040/03L-0 RUSSELL,L. B Baltimore Qas & Electric Co B2/09/24 HAYNES,R C Region 1. Office of Director 1p 15587.177 24X Fichs. 50-318, 82/09/24, 8210040211

- --8210040217 LER 82-040/03L-0 between 820825 t 26, pressurfier level deviated slightly from progress level by more than 5% during normal startup operations Caused by loading of main turing generator. RCB temp surings of 10 degrees not uncommon JUNGE.HA WEIR-P J Baltimore Cas & Electric Co 62/09/24 Region 1, Office of Director. 19 15587 178 24X Fiche 50-318, 82/09/24, 8210040211
- B210190730 RD on B20827, dister samples showed detectable levels of concentration of Ag-110m Caused by natural tendency of disters to concentrate environ silver Radioactive releases for first half of 1982 within allowable limits FUHRMAN, OR Baltimore Gas & Electric Co. 82/10/11 HAYNES, R C Region 1. Diffice of Director 2pp 15736 270 24X Fiche 30-317, 82/10/11, 8210190730
- 8210250088 Forwards LER 82-044/03L-0 RUSSELL,t. B. Baltimore Gas & Electric Co 82/10/15 HAYNES,R C Region 1. Office of Director 1p 15787 058 24X Fiche 50-318,82/10/15,9210250089
- --8210250095 LER 82-044/03L-0 on 820915, emergency diesel generator 21 tripped during testing Caused by common low jacket cooling water pressure switch isolation valve left closed following maint Valves opened PAVIS.0 B . BASSOL F Baltimore 02s & Electric Co B2/10/15 Region I, Office of Director 2pp 15787 059 24X Fiche.50-318,82/10/15.8210250088
- 8210280134 Forwards LER 82-046/03L-0 RUSSELL,L B Baltimore Gas & Electric Co. 82/10/20 HAYNES,R C Region i, Office of Director 1p 15837 239 24X Fiche 30-316, 82/10/20, 8210280134.
- --8210280141 LER 82-046/03L-0 on 820920, reactor protective sys channel C trip unit for high pressurizer gressure tripped due to failed low trip bistable power supply Model DRA15-750/15-7508 Cause unknown Power supply replaced LA0IEMSKI,J B. RAYNOR,J W. Baltimore Cas & Electric Co. 82/10/20 Region 1. Office of Director ip 15837 240 24% Fiche 50-318,82/10/20,8210280134
- DOCKET 50-320 THREE NILE ISLAND NUCLEAR STATION, UNIT 2 F Security, medical, emergency & fire protection plans
- 8210050491 Forwards exemption from annual emergency plan exercise requirements of 10CFR50.App E re level of govt participation STOLI.J F Operating Reactors Branch 4 82/09/14 HUKILL.H B General Public Utilities OPU Bervice Corp. 7pp 15624 291 24) Fiche 30-289.82/09/14.8210050491.
- --8210050495 Exemption from annual amergency plan requirements re level of govt participation in exercises EIGENHUT.O O. Division of Licensing 82/09/14. Oeneral Public Utilities QPU Service Corp 4pp 15626 298 24X Fiche: 50-289, 82/09/14, 8210050491
- 8210190180 Notification of contract execution "TNI-2 Fire Protection Evaluation: "awarded to Rolf-Jensen & Associates, Inc., FLEENOR.C. Technical Assistance Contracts Branch FIN B-8632 82/09/29 VOLLMER.R H. NOLAN.F. Division of Engineering. Ip 13738:118 24X Fiche: 50-320,82/09/29.8210190180
- --8210190185 Contract. "TMI-2 Fire Protection Evaluation: " awarded to Rolf Jensen & Associates, Inc. HEBB.W A Rolf Jensen & Associates: Inc. HATTIA.M J. Technical Assistance Contracts Branch. FIN 8-8632 82/09/29. Spp. 13758: 139. 24X Fiche. 50-320, 82/09/29, 8210190180

O Adjudicatory correspondence

- 821004002! Notice of withdrawal of appearance in proceeding. LEWIS, B H Hearing Brench 2 82/09/29. 2pp 15581:260. 24X Fiche 50-320.82/09/29.8210040021.
- 8210150486 Motion to modify Tech Space formally to conform w/820924 amend of NRR Director 800211 order-allowing separation of fuel handling bldg air cleanup exhaust sys & suxiliary bldg air cleanup exhaust sys & suxiliary bldg air cleanup exhaust sys Tech Spaces. M/Certificate of Svc. MILCOVE.M N Hearing Brench 2 82/10/14. Atomic Safety and Licensing Board Panel. 170p 15714 193 24X Fiche. 50-320, 82/10/14, 8210150486

- 8210210266 Response to NRC 821014 motion to conform proposed Tech Spattached to NRR 800211 order w/820924 amend to order Licensee does not oppose motion, assuming formal amend awaits outcome of prospective hearing W/Certificate of Svc RIDONAY, D. A. Metropolitan Edison Co. RIDONAY, D. A. Shaw, Pitter Potts & Troubridge 82/10/18 Atomic Safety and Licensing Bear Panel 5pp. 15766 232 24X Fiche 50-320, 82/10/18 8210210266
- 8210210173 Motion to extend period of time for Commission to revise ALAB-472 Certificate of Svc encl TROMBRIDGE.0 F Metropolitan Edison Co TROMBRIDGE.0 F Shaw. Pittman. Potts & Trouberidge 82/10/20 Commissioners 4pp 15766
- --8210210177 Request for extension to 821115 to file motion for reconsideration & mod of 820715 ALAB-672 Certificate of 8vc encl TROMBRIDGE, OF Metropolitan Edison Co Pittman, Potts & Trombridge 82/10/20 Atomic Safety and Licensing Appeal Panel 5pp 18766 064 24X
- B210220313 Order granting util B20914 request for leave to file petition for reconsideration of portion of ALAB-492 sub; to Commission granting util B20914 request to extend period for sua sponta review TOMPXINS.B A Atomic Sefety and Licensing Appeal Panel B2/10/20 Hetropolitan Edison Co 2pp 15776 177 24X Fichs 50-320, 82/10/20.821020313
- 8210270176 Hemorandum & order granting NRC motion to conform propose.

 Tech Specs to NRR Director 820924 order amending 800211

 order, separating fuel handling bidg air cleaning exhaust sys
 & auxiliary bidg air cleanup exhaust sys Tech Bapes

 HOLF, J F, PARIS, O H, SHON, F J Atomic Safety and Licensing Boar,
 Panel 82/10/25 Office of the Executive Legal Director 3pp
 15823 011 24X Fiche 50-920, 82/10/25, 82/0270176
- 8210270170 Order extending time until 821112 for Commission to act in review ALAB-692 CHILK.S. J. Office of the Secretary of the Commission 82/10/28 Commissioners ip 15822 348 24X Fiche 50-320,82/10/26, 8210270170
- J Insurance & indemnity information
- 8210150147 Forwards Endorsements 53 & 54 to MAELU Policy MF-73 & Endorsements 61 & 62 to NELIA Policy NF-220 GERETY, H F General Public Utilities OPU Service Corp 82/10/01 SALTZMAN, J Antitrust & Economic analysis Branch (Utility Finesca) 5pp 15697 359 24X Fiche 50-289,82/10/07,8210150147
- P Operating license stage documents & correspondence
- 8210050466 Requests installation of speakerphone at THI info ofc KERR, V S Telecommunications Branch 80/01/30 ACCARDQ, V 8-11; Pannsylvania 1p 15625-236 24X Fiche 50-320,80/01/30,82105648
- B2100B0061 Comments on info gleaned from preoperational testing legics entries of 770905-12 Installation of reactimeter in all plants prior to startup testing suggested Logbook entries enci. CRNBTEIN, H L Director's Office B1/07/16 Director's Office 25pp 15669 326 24% Fiche 50-320, 81/07/16, 82100B0061
- 8210120406 "Recently Evaluated Preoperational Test Precursor of IM-2 Accident," for presentation at ANS 1982 Power Div Topical Meeting in Charleston, 8C, 820328-31 ORNSTEIN, H L. Director's Office. 82/03/31 24pp. 15691 143 24 Fiche 50-320, 82/03/31, 8210120406.
- 8210Q10D0B Responds to FOIA request for 19 categories of decuents II nuclear reactor events & safety problems Forwards documents listed in App A FELTON, J M Division of Rules and Records 82/04/28 UDELL.R & Critical Mass Energy Project 15pp 15727.005. 24X Fiche 50-000, 82/04/28, 8210010008.
- 8210060473 Requests submittal of implementation schedules for completing removal of EPICOR-II prefilter & submerged demineralizer sys ion exchange wastes, for defueling reactor core & for removal of reactor coolant wastes DENTON, H. R. Office of Nuclear Reactor Regulation, Director 82/07/08 ARNOLD, R.C. General Public Utilities GPU Servici (*): 3pp. 15536-220 24X Fiche 50-320, 82/09/08, 8210060473.
- 9210050537 Speech entitied. "Regulatory Aspects of TMI Cleans," LO,R, BELLAMY,R TMI Program Office, 82/09/20, 6pp. 15537:44 24X Fichs: 50-320, 82/09/20, 8210050537

- 8210260535 Forwards amend of order, safety evaluation & proposed Tech Spets Amend Changes Tech Specs to allow for operations to prepare for recovery mode activities SttDER.B J THI Program Office 82/09/24 KANGA.B K General Public Utilities - GPU Service Corp 2pp 15830 333 24X Fische 50-320.82/09/24.8210260535
- ~~ 8210260538 Amend of order changing Tech Specs to define which equipment would provide adequate ventilation capability for fuel handling & auxiliary bldps
 CASELE Q Office of Nuclear Reactor Regulation, Director 82/09/24 General Public Utilities OPU Service Corp 4pp 15830 335 24X Fiche 50-320,82/09/24.8210260535
- ~-8210260547 Safety evaluation supporting Tech Specs change defining equipment to provide adequate ventilation capability for fuel handling & auxiliary bldgs

 d Office of Nuclear Reactor Regulation, Director 82/09/24 5pp £5830 339 24X Fiche 50-320.82/09/24.8210260535
- ~~8210260552 Proposed Tech Spec changes re fuel handling auxiliary bldg air ventilation rleamup sys * Office of Nuclear Reactor Regulation, Director 82/09/24 3pp L5930 344 24X Fiche 50-320.82/09/24.8210260535
- 8210270328 Informs that proposal to conduct extended decontamination effort acceptable Procedures used to implement decontamination effort subj to approval Rationale for approval & discussion of evaluation encl SN/DER.8 J TMI Program Office 82/09/24 KANOA.8 K Oeneral Public Utilities GPU Service Corp 7pp 15834 351 24X Fiche 50-320.82/09/24.8210270328
- 8210190052 Requests attendance at 820928 meeting to discuss actions to obtain actual RCS gas space info & future plans for establishing inert gas atmosphere in drained RCS portions which need not be vented BARRETT.L H TMI Program Office 82/09/27 KANGA, 8 K General Public Utilities GPU Service Corp 2pp 15761 044 24X Fighe 50-320, 82/09/27, 8210190052
- 82:0040200 Informs of newly established dairy farm yielding calculated dose or dose commitment greater than several farms currently monitored by land use census Farm added to radiological monitoring program KANGA.8 K General Public Utilities GPU Service Corp 82/09/28. SEYDER.8 J TMI Program Office ip 15583 163 24X Fiche 50-320.82/09/28.8210040200
- 821G070220 Advises of installation of pressure relief device for longterm storage of spent submerged demineralizer sys liner vent hoses KANQA-B K General Public Utilities - CPU Service Corp B2/1C/04 BARRETT.L H THI Program Office 2pp 15637 161 24X Fiche 50-320-82/10/04:8010070220
- B210070365 Notifies of planned operations which will cause containment waste uater inventory to exceed 50,000 gallens, in response to INRC 820420 ltr
 KANGA.B K Deneral Public Utilities QPU Service Corp. 82/10/04
 BARREIT, L M TMI Program Office ip 15634 035 24X
 Fiche 50-320,82/10/04.8210070365
- B210:30583 Revision i to Recovery Operations Plan Change Request

 18. Revision will permit opening of both equipment hatch
 air tock doors in order to allow excessive length tools &
 equipment to be transported into containment
 KANGA.8 K General Public Utilities CPU Service Corp
 BARRETTL H TMI Program Office 12pp 15679 063 24X
 Fiche 50-320.82/10/06.8210130583
- --B2101305B4 Tech Spec 4 6 i re primary containment integrity General Public Utilities -- GPU Service Corp B2/10/06. 2pp 15679 075 24% Fiche 50-220. 82/10/06. B2101305B3
- B210830279 Provides info on schedules for removal of EPICOR II prefilters, submerged demineralizer sys ion exchange wastes & reactor coolant purification sys ion exchange wastes, per NRC B20908 itr & util 820921 response Syc list enc! ARNOLD,R C. General Public Utilities OPU Service Corp 82/10/08 DENTON.H R Office of Nuclear Reactor Regulation, Director 5pp 19682 174 24% Fiche 50-320,82/10/08,8210130279
- 82(0150043 Provides results of sempling program to determine RC8
 hydrogen evolution, in response to 820927 Itr Based on
 preliminary evaluation, combustible gas mixture will not
 occur in loop high points in foreseeable future
 KANCA.8 K General Public Utilities QPU Service Corp 82/10/08
 BARRETT, LH THI Program Office 3pp 15701 129 24X
 piche: 50-320, 82/10/08, 8210150043

- 8210150085 Forwards polar crans functional description & response to Item 4 of 820401 ltr re crans maint Checklist of specific items for crans maint to be evaluated KAN9A.B K General Public Utilities CPU Service Corp 82/10/12 BARRETT.L N TMI Program Office. 27pp 15701 214 24X Fiche 50-320.82/10/12.8210150085
- 8210190570 Forwards Revision 0 to "Safety Evaluation for Submerged Demineralizer Sys Liner Recombiner & Vacuum Outgassing Sys "
 Sys satisfactorily tested by Rockwell Hanford Operations KANGA, II K General Public Utilities GPU Service Corp 82/10/13 BARRETT, L H TMI Program Office 2pp 15736 103 24X Fiche 50-320, 82/10/13.8210190570
- ---8210190577 Revision O to "Safety Evaluation for Submerged Demineralizer Sys Liner Recombiner & Vacuum Outgassing Sys " « General Public Utilities - OPU Service Corp 82/10/31 7pp 15736 105 24X Fiche 50-320, 82/10/13, 8210190570
- 8210200012 Advises of status of EPICOR prefilter liner inserting Analyses indicate that hydrogen generator rate can be adequately determined for nonairtight liners by concentration of hydrogen at initial sampling & leak rate KANOA-B K General Fublic Utilities ~ GPU Service Corp 82/10/14 BARRETT.L H TMI Program Office 2pp 15752 328 24X Fiche 50-320, 82/10/14,8210200012
- O Inspection reports. IE Bulletins & correspondence
- 8210260225 Ack receipt of 820902 itr in response to violations noted in IE Insp Rept 50-320/82-06 Info not previously available to inspector during insp Recent investigation revealed new facts that could alter item of noncompliance STAROBTECKI.R Division of Project & Resident Programs B2/09/28 KANOA! B K Owneral Public Utilities OPU Service Corp. 2pp 15830 349 24X Fiche 50-320,82/09/28,8210240225
- --B210260236 Responds to NRC 820730 itr re-violations noted in IE Insp. Rept 50-320/82-06 Apparent violation re-broken lid holddown ring on drum happened during transport Util not responsible KANGALB K General Public Utilities OPU Service Corp B2/09/02 HAYNEB,R C Region i, Office of Director App 15830 351 24X Fiche 50-320,82/09/28,8210260225.
- B20B190233 IE Info Notice 80-35, Suppl 1, "Leaking & Dislodgad I-128 Implant Seeds " Svc list encl COBR.L I Division of Fuel Facilities, Materials & Bafeguards B2/10/06 Consolidated Edison Co. of New York 66pp. 15761 250 244 Fichs 50-000 B2/10/06, B208170233
- 8208190238 IE Bulletin 82-03, "Stress Corrosion Cracking in Thick-Mali, Large-Diameter, Stainless Steel, Recirculation Sys Piping at BWR Plants " Syc list encl DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/10/14 Consolidated Edison Co of New York 113pp 19810 125 24X Fiche: 50-000, 82/10/14, 8208190238
- R. Periodic operating reports & related correspondence
- 8210070063 Forwards TMI Program Ofc weekly status rept for wk of 820829-0903 BARRETT.LH TMI Program Office. 82/09/03 DENTON.HR. Office of Nuclear Reactor Regulation, Director SNYDER.D.J TMI Program Office 8pp. 15649 186 24X Fiche: 50-320,82/09/03,8210070063
- 8210070150 Forwards TMI Program Oft weekly status rept for wk of 820904-11.
 BARRETT, L H TMI Program Office. 82/09/13 DENTON, H. R. Diffice of Nuclear Reactor Regulation, Director SNYDER, B. J TMI Program Office opp. 15644-359, 24X Fiche. 50-320, 82/09/13, 8210070150
- 8210190127 Forwards TMI Program Ofc weekly status rept for wk of 820912-18.

 BARRETT, L. H TMI Program Office 82/09/20, DENTON, H. R. Office of Nuclear Reactor Regulation, Director 7pp 15761:230 24X Fiche 50-320, 82/09/20, 8210190127
- 8210190012 Forwards TMI Program Ofc weekly status rept for wk of 820919-25. 8ARRETT, L.H. TMI Program Office 82/09/27. DENTON, H.R. Office of Nuclear Reactor Regulation. Director 7pp. 15760:321 24X Fiche 50-320, 82/09/27, 8210190012
- 8210070226 Forwards results of program to detect radioactive water leakage to groundwater at facility. Data includes computer graphs of bultium concentrations, computer tables of gamma scan data & first & second quester strontium results KANGA: B K. General Public Utilities GPU Bervice Corp 82/10/06 BARRETT, L.H TMI Program Office 40pp. 15634:308 24X Fiche: 50-320, 82/10/06;8210070226.

- S Reportable occurrences, LERs & related correspondence
- BO12290118 Discusses conclusions of engineering evaluation of steam generator querfill transients at C-E & Hestinghouse plants LANNING, H D Director's Office 80/10/29 MICHELBON C Director's Office 3pp 15692 262 24X Fiche 50-000, 80/10/29, 8012290118
- 8210150280 Forwards LER 81-013/01L-0 HOVEY.O K Metropolitan Effson Co 81/06/08 ORIER.B H Region I. Philadelphia. Office of the Director (81/03/01) ip 15701 340 24X Fiche 50-320.81/06/08.8210150280
- --B210150289 LER 81-013/01L-0 on 810508, incore thermocouple Li1 exhibited erratic behavior Cause undetermined due to condition of incore instrumentation Condition monitored to determine long-term effect on safety CHAPLIN.S D Hetropolitan Edison Co 81/06/05 Region 1, Philadelphia, Office of the Director (81/03/01) 2pp 15701.341 248 fiche 50-320,81/06/08.8210150280
- 8210080024 Forwards chronology of 770905-12 events in which steam bubble formed during preoperational testing GRNSTEIN.H L Director's Office 81/07/08 MICHELSON.C Director's Office 9pp. 15669 294 24X Fiche 50-320.81/07/08.8210080024.
- 8210010008 Responds to FOIA request for 19 categories of documents re nuclear reactor events & safety problems Forwards documents listed in App A FELTON. J M Division of Rules and Records 82/06/28 UDELL.R A Critical Mass Energy Project 15pp 15727 005 24X Fiche 50-000.82/06/28.8210010008
- --8210010161 Discusses potential problem re sequoyah reactor pressure norrie, supplementing 800222 memo Undercied Cracks found by use of ultrasonic equipment Addl items of recent origin discussed Related into encl DENTON. H R Office of Nuclear Reactor Regulation, Director 80/02/28 AREARNE, J Commissioners 9pp 15727 178 24X Fiche 50-000, 82/06/28, 8210010008
- --B210040374 Forwards LER 80-20/03L & RO 249/80-9 re failure to open auriliary faedwater valve & failure of fire detection sys, respectively Addi attention may be warranted BENDER, M. ACRS Advisory Committee on Reactor Bafeguards 80/05/23 FRALEY,R F ACRS Advisory Committee on Reactor Bafeguards 1p 19727 272 24X Fiche. 50-000, 82/06/28, 8210010008
- --B210050161 Forwards add1 info re events at facility during preoperational testing on 770905-12 Failure of condensate polishers caused resin to clog strainers from closed cooling water pumps

 ORNBIEIN H L Director's Office 81/07/08 MICHELSON, C Director's Office 9pp. 13729 346 24% Fiche. 50-000, 82/06/28, 8210010008.
- --B210060460 "Recently Evaluates Preoperational Test Precursor of TMI-2 Accident," presented at ANS 1982 Power Div topical meeting on 820328-31 CRNSTEIN.H L Director's Office 82/03/28, 24pp 15745 049 24X Fiche 50-000,82/06/28,8210010008.
- 8210070265 PNO-TMI-82-020-on B21005.game poacher apprehended on util property & turned over to state police & Game Commission.No vital areas threatened Security increased Licensee will issue press release WIEEE.J. BELLAMY,R Region 1, Office of Director 82/10/06 ip 15604 306 24% Fiche 50-289;82/10/06;8210070265.
- 8210280124 LER 82-008 has been canceled. COLLINS.M General Public Utilities - QFU Service Corp. 82/19/19. Region 1, Office of Director. 1p f5837.021, 24X Fiche 30-320.82/10/19.8210280124
- 8210280127 LER 82-002 has been canceled COLLINS M General Public Utilities OPU Service Corp. 82/10/19. Region 1. Office of Director. 1p 15837 023 24X Fiche 50-320.82/10/19.8210280127.
- DOCKET 50-321 EDWIN I HATCH NUCLEAR PLANT, UNIT 1

 F Security, medical, emergency & fire protection plans
- 8210190013 Releases public version of revised emergency plan implementing procedurs FELTON.J.M Division of Rules and Records 82/09/29 Document Management Branch. 1p 15760.328. 24X Fiche: 50-321, 82/09/29, 8210190013.

- --8210190016 Forwards public version of Revision 4 to Emergency f Implementing Procedure HNP-8026, "High Radiation Area Entrance Control" SORRELL,E G Georgia Power Co 82/09/23 Office of Nucle Reactor Regulation, Director ip 15760 329 24x Fiche 50-321,82/09/29,8210190013
- --8210170017 Public version of Revision 4 to Emergency Plan Repli Procedure HNP-8026. "High Radiation Area Entrance Control" 4 Opengia Power Co 82/09/22 12pp 15760 330 24x Ficha 50-321:82/09/29.8210170013
- 8210190042 Releases public version of pages to emergency plan FELTON, J M Division of Rules and Records 82/10/01 Docum Management Branch ip 15761 037 24X Fiche 50-321,82/10/01, 8210190042
- --8210190046 Forwards public version of Pages M-1 & M-2 to parging plan SORRELL.E C Georgia Power Co 82/09/22 Office of Nucli Reactor Regulation, Director 1p 15761 038 24X Fiche 50-321.82/10/01.8210190042
- --B210190051 Public version of Pages M-1 & M-2 to energency plan * Georgia Power Co B2/03/31 2pp 15761 039 24X Fichs 50-321.82/10/01.8210190042
- 8210080227 Forwards IE Safeguards Insp Repts 50-321/82-31 & 50-366/82-29 on 820920-23 No noncompliance noted DANCE: H C Division of Project & Resident Programs 82/10/04 KELLY: R J Ceorgia Power Co 2pp 15638 057 24X Fiche 50-321-82/10/06-8210080227
- --B2100B0228 IE Bafeguards Insp Repts 50-321/82-31 & 50-366/82-29 B20920-29 No honcompliance noted Hajor areas inspected physical barraers, lighting, assessment atds, detection adds, access control & vehicles Deteils withheld (ref 10CFR73 2)1 MODRE, D E . MCGUIRE, D R Division of Engineering & Technical Programs B2/10/05 ip 15638 059 24X Fiche 50-321,82/10 B2100B0227
- P Operating license stage documents & correspondence
- 8210120099 Lists LERs re HPCI & RCIC sys failures not included in NURCO/CR-1205 on LERs related to pumps Probabilistic Analysis Branch should correct classification deficiencies CRNSTEIN, H L Director's Office 80/07/10 BERNERD, R H Probabilistic Analysis Staff (Pre 801119) 2pp. 15689 170 2-Fiche 50-021, 80/07/10,8210120099
- 8210050330 Forwards schedule for qualification testing of analog transmitter trip sys.in response to 801001 request OUCHALL T Georgia Power Co 82/09/28 EISENHUT.D 0 Office Nuclear Reactor Regulation, Director 3pp 15610 258 24X Fiche 50-321,82/09/28,8210050330
- 8210150327 Application to amend License DPR-57, consisting of inler change to Tech Spec re maint of secondary containment for period of upcoming refueling outage Proposed mod allows more efficient access to torus area by workers SECKMAN.J T. Georgia Power Co 82/10/06 Dffice of Nuclear Reactor Regulation. Director 3pp 15701 323 24X Fiche: 50-321.82/10/06.8210150329
- --8210150333 Proposed temporary changes to Tech Spac re meint of secondary containment for period of upcoming refueling outage

 * Ceorgia Power Co. 82/10/06. 8pp 15701 376 24x
 Fiche 50-321, 82/10/06. 8210150329
- Q Inspection reports, IE Bulletins & correspondence
- 8210010113 Forwards IE Insp Repts 50-321/82-26 & 50-366/82-25 en 820809-13, No noncompliance noted DANCE, H C Division of Project & Resident Programs 82/09/07 KELLY: R J Georgia Power Co 2pp 15567 206 24X Fiche 50-321, 82/09/07, 8210010113
- ---821001011B IE Insp Repts 50-321/82-26 & 50-366/82-25 on 82080*:118 noncompliance noted Major areas inspected lab GC program chemistry & radiochemistry procedures.airborne efficient sampling & accountability & mobile lab.

 EVANB. C D , MONTOCHERY. D M Division of Emergency Preparational Bupport. 82/09/02 11pp 13567 208 24X Fiche 50-321,82/09/07.8210010113
- 8210010235 Forwards IE Insp Rept 50-321/82-27 on 820818-19 M9 noncompliance noted DANCE, H. C. Division of Project & Resident Programs 82/09/69 KELLY, R. J. Georgia Power Co. 2pp. 15574-022 24X Fiche: 50-321, 82/09/08, 8210010235.

ž

- --8210010240 IE Insp Rept 50-321/82-27 on 820818-19 No noncompliance noted Major areas inspected followup of RO 50-321/82-60 re 820703 reactor trip JAPE.F. HERDITA R Division of Engineering & Technical Programs 82/09/02 7pp 15574 024 24X Fiche 50-321,82/09/08,8210010235
 - 62/09/02 7pp 15574 024 24% Fiche 50~321, 82/09/08, 8210010
- B2:00:0309 Forwards IE Insp Repts 50-32:1/82-28 & 50-366/82-26 on 820727-0827 No noncompliance noted EANCE, H C Division of Project & Resident Programs 82/09/10 EELLY, R J Georgia Power Co 2pp 15568 274 24X Fishe 50-32:1.82/09/10.8210010309
- --8210010327 IE Insp Repts 50-321/82-28 & 50-366/82-26 on 820727-0827 No nancompliance noted Major areas inspected Tech Spec corpliance, operation performance, overall plant operations, GA practices & station & corporate mgt practices GOCRS.R F , HOLMES-RAY, P , GROWNLEE, V L Division of Project & Fesident Programs 82/09/10 App 19568 276 24X Fiche 50-321,82/09/10,8210010309
- 8210010019 Ack receipt of 820907 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-321/82-19
 O'REILLY, J P Region 2. Diffice of Director 82/09/16 KELLY, R J Georgia Power Co ip 13565 300 24% Fiche 50-321,82/09/16. 6210010019
- --8210010022 Responds to NRC 820806 itr re violations noted in IE Imsp. Repts 50-321/82-19 & 50-366/82-19 Corrective actions procedures being revised to include tighter controls on changes to fuel movement data packages

 BECKHAM, J T Georgia Power Co 82/09/07 D'REILLY, J P Region
 2. Office of Director 3pp 15565 301 24% Fiche 50-321,
 B2/09/16,8210010019
- --8210010025 Forwards IE Insp Repts 50-321/82-19 & 50-346/82-19 on 820421-0925 & notice of violation 0.4ELLLY.J P Region 2, Office of Director 82/08/06 KELLY.R J Georgia Power Co 2pp 15565 304 24X Ficha 50-321.82/09/16.
- --8210010029 Notice of violation from insp on 820421-0525 4 Region 2, Office of Director 82/08/06 ip 15565,306 24X Fiche 50-321,82/09/16,8210010019
- --8210010031 IE Insp Repts 50-321/82-19 & 50-366/82-19 on 820421-0525 Noncompilance noted fuel loaded into core w/o all control rods fully inserted RODERS.R F Division of Project & Resident Programs EROWNLES.V L Region 2, Office of Director 82/07/29 7pp 15565 307 24% Fiche 50-321,62/09/16,8210010019
- 3210040047 Ack receipt of check in payment of civil penalty proposed on B20713 Corrective measures described in 820812 & 0707 ltrs will be examined in future insp AYELRAD. J A Director's Office, Office of Inspection and Enforcement 82/07/23 KELLY, R J Georgia Power Co 2pp 15577 290 24% Fiche 50-321.82/07/23,8210040047
- 320B:50233 IE Info Notice 80-35, Suppl i, "Leaking & Dislodged I-125 Implant Seeds" Byo list end GOIB.t. I Division of Fuel Facilities, Materials & Safeguards 622/10/06 Consolidated Edison Co of New York 66pp 15761:250 24x Fiche 50-000,82/10/06,8208190233
- #210080227 Forwards IE Safaguards Insp Repts 50-321/82-31 & 50-366/82-27 on 820920-23 No moncompliance noted. DAY(CE, H C Division of Project & Resident Programs 82/10/06 MELLY, R J Georgia Power Co 2pp 15638; 057 24X Fische 50-321,82/10/06,8210080227
- -82\$0080228 IE Safeguards Insp Repts 50-321/82-31 & 50-366/82-29 on 620920-23 No noncompliance noted Hajor areas inspected physical barriers, lighting, assessment aids, detection aids, access control & vehicles Details withheld (ref 10CFR73 21), HOORE, D E : MCGUIRE; D R Division of Engineering & Technical Programs 62/10/05 ip 15438 059, 24X Fiche 50-321,82/10/06, 6210080227
-)208190238 IE Bulletin 82-03, "Stress Corrosion Cracking in Thick-Hall, Large-Diameter, Stainless Steel, Recirculation Sys Piping at BWR Plants "Syc list encl DEYQUNOR C Director's Office, Office of Inspection and Enforcement 82/10/14 Consolidated Edison Co of New York, \$ (5pp 15810 125 24% Fiche 50-000, 82/10/14, 8208190238
- 1240220277 Act receipt of 820927 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-321/82-24 & 50-366/82-22 LEMIS.R C Division of Project & Resident Programs 82/10/14 KELLY.R J Georgia Power Co ip. 15775 028. 24X Fiche 50-321.82/10/14.8210220277

- --8210220287 Responds to NRC 820823 ltr re violations noted in IE Insp. Repts 50-321/82-24 & 50-366/82-22 Corrective actions written plan will be prepared to schedule & integrate lecture series to meet addl training needs.

 GUCWA, L. T. Georgia Power Co. 82/09/27 O'REILLY, J. P. Region 2, Office of Director 4pp. 15775 029 24X Fichs 50-321,82/10/14, 8210220227
- --8210220292 Forwards IE insp Repts 50-321/82-24 & 50-366/82-22 on 820726-30 & notice of violation LEWIS,R C Division of Project & Resident Programs 82/08/23 KELL/R J Georgia fewer Co 2pp 15775 033 24X Fiche 50-321,82/10/14.8210220277
- --8210220299 Notice of violation from insp on 820726-30 * Division of Project & Resident Programs 82/08/23 2pp 18775 035 24% Fiche 50-321,82/10/14,8210220277
- --8210220307 IE Insp Repts 50-321/82-24 & 50-366/82-22 on 820726-30 Noncompliance noted failure to provide GA indoctrination & scheduled preplanned lecture series based on evaluation of annual licensed operator exams SKINNER, P H , JACKSON, L H , UPRIGHT, C M Division of Engineering & Yechnical Programs 62/06/19 8pp 15775 037 24X Fiche 50-321.82/10/14/8210220277
- R Periodic operating reports & related correspondence
- 8210130129 Forwards monthly operating repts for Sept 1982 NIX.H C Georgia Power Co 82/10/07 Director's Office Office of Inspection and Enforcement 1p 15673 029 24X Fiche 50-321.82/10/07.8210130129
- --B210130132 Monthly operating repts for Sept 1982 SMITH.J A Georgia Power Co B2/10/07. 9pp 15673 030 24X Fiche 50-321.82/10/07.8210130129
- S Reportable occurrences, LERs & related correspondence
- 8210120171 Discusses 910406 discovery that undervoltage relays of second offsite source would not operate preventing closure of all dissel generator breaters Licensee will be proposing design mod to correct problem of non-class IE interlock CHIRAMALM Director's Office 81/04/21. Director's Office 3pp. 15692;202 24X Fiche 50-321,81/04/21,8210120171.
- 8210010008 Responds to FDIA request for 19 categories of documents re nuclear reactor events & safety problems Forwards documents listed in App A FELTON.J M Division of Rules and Records. 82/06/28 UDELL.R A Critical Mass Energy Project 15pp 15727 005 24X Fiche 50-000.82/06/28.8210010008
- --S103120107 Summary of 810107 operating reactor events meeting W/o enclagenda LAIMAS, O Division of Licensing, 81/01/19 EISENHUT, D Q Division of Licensing 3pp 15727 361, 24X Fiche 50-000, B2/06/28,8210010008
- --8104290103 Discusses IE daily rept for 810406 re alternate offsite source interlock w/emergency diesel generators at Unit 1 Licensee will propose mod to correct non-Class IE interlock preventing automatic operation of safety sys CHIRAMAL M Director's Office 81/04/21 Director's Office, 3pp. 15729 041 24X Fichs 50-000, 82/06/28, 8210010008
- --8210010083 Recommends ACRS action on recent LERs re HPCI failt auto start after MSIV failure & single cooling supply line on RHR pump motors BEHNERT.P ACRS Advisory Committee on Reactor Safeguard: 80/06/13 KERR:W ACRS Advisory Committee on Reactor Safeguards ip 15727 138 24X Fiche 50-000,82/06/28.8216
- 8210130256 Forwards LER 82-074/03L-0 NIX,H C Georgia Power Co 82/09/28 O'REILLY,J.P Region Office of Director. ip 15678 048. 24X Fiche 50-321,62/09/: 0210130254
- --8210130258 LER 82-074/03L-0 on 820901. HPCI steam pressure con switches A: C & D actuated at less than 107 3 psig Caused by component failure due to setpoint drift Switches calibr & function tested TIPPS, B, B Georgia Power Co 82/09/28 Region 2: Offic Director 2pp 15678 049 24X Fiche: 50-321, 82/09/28, 8210
- 8210220384 Forwards LER 82-071/03L-0. NIX,H C Georgia Pawer Co. 82/09/28. D'REILLY,J,P Region Office of Director Ip 15779 167 24X Fiche:50-321,82/09/ 8210220384

- --B210220388 LER 82-071/03L-0 on 820931 primary containment atmosphere concentration 02 exceeded Tech Spec requirements Caused by personnel failure to secure standby gas treatment sys in time while venting drywell Personnel counseled TIPPS, 8 B Ocargia Power Ca 82/09/28 Region 2, Office of Director 2pp 15779 168 24X Fiche 50-321, 82/09/28, 8210220394
- 8210220219 Forwards LER 82-082/03L-0 NIK-H C Georgia Power Co 82/10/07 O'REILLY, J P Region 2, Office of Director 19 15776:242 24X Fiche: 50-321,82/10/07, 8210220219
- --B210220222 LER B2-082/03L-0 on 820911,LPCI A inverter tripped Unit placed in 7-day limiting condition for operation. Caused by failure of output filter capacitor Six fuses & 2 output filter capacitors replaced Inverter placed in svc on 820913 TIPPS.S B Georgia Power Co 82/10/07 Region 2. Office of Director ip 15776 243 24X Fiche 30-321,82/10/07,8210220219.
- 8210290327 Forwards updated LER 80-016/03X-1 NIX.H C Osorgia Power Co 82/10/12 O'RE(LLY.J F Region 2, Office of Director 1p 15853 108 24X Fichs 50-321,82/10/12, 2210290327
- --B210270334 Updated LER 80-0i6/03X-i on 800129, investigation of IE Bulletin 79-27 revealed that breaker control power to swing diesel B motor control trifed by non-Class IE vital ac sys Caused by design error SUMNER, H L Georgia Power Co 82/10/12 Region 2, Office of Director 1p 15853 107 24X Fiche 50-321, 82/10/12, 8210270327
- 8210290373 Forwards updated LER 82-054/03X-1 NIX.H C Georgia Power Co 82/10/12 Region 2, Diffice of Director 1p 15853 022 24X Fiche 50-321,82/10/12,8210290373
- --8210290375 Updated LER 82-054/03X-i on 620428, at 100X power, RHR synuster pump C failed operability & flow requirements Caused by normal wear to impeller seal & casing wear rings Pump removed rebuilt, installed & tested successfully TIPPS, 8 B Georgia Power Co 82/10/12 Region 2, Office of Director ip 15853 023 24X Fiche 50-321, 82/10/12, 8210270373
- 8210290096 Forwards LER 82-083/03L-0 NIX.H C. Georgia Power Co 82/10/14 G'REILLY, J P Region 2, Office of Director 1p 15853 359, 24X Fiche 50-321,82/10/14, 8210290096
- --8210290105 LER 82-083/03L-0, on 820915.00 review disclosed installation of non-0 part in level switch on A loop core spray discharge line Caused by ineffective administrative procedures. Part ordered Required 0 functions not affected TIPPS.8 B Georgia Power Co 82/10/14 Region 2. Office of Director 1p 15853 360 24% Fiche.50-321.82/10/14.8210270096
- 8210270262 Forwards LER 82-086/03L-0 NIX, H C. Osongia Power Co 82/10/14 O'REILLY, J P Region 2, Office of Director ip 15854 074 24X Fiche. 50-321, 82/10/14, 6210270362
- ---8210290272 LER 82-086/O3L-0 on 820917.attempt to place torus cooling in svc failed due to lack of svc water flow Caused by loose bolts in valve operator coupling allowing coupling spring pin to break Pin replaced & bolts tightened TIPPS, B B Georgia Power Co 82/10/14 Region 2, Office of Director ip 15854.093 24X Fiche.50-321.82/10/14.8210290262
- 8210290326 Forwards LER 82-084/03L-0 NIX.H C Georgia Power Co. 82/10/14 O'REILLY.J P Region 2. Office of Director 1p. 15853 062 24X Fiche 50-321.82/10/14. 8210290324
- --8210290329 LER 82-084/03L-0 on 820916, channel B main steam line radiation monitoring instrument failed Cause unknown Spare instrument installed, calify t tested TIPPS, 8.B Georgia Power Co. 82/10/14 Region 2, Office of Director 1p 15853 063 24X Fiche 50-321,82/10/14,8210290326.
- 8210290349 Forwards LER 82-091/03L-0 NIX.H C Georgia Power Co 82/10/21 G/REILLY, J P Region 2, Office of Director 1p 15853.026 24X Fiche 50-321.82/10/21, 8210290349.
- --B210290359 LER 82-091/03L-0 on 820928, spet release order change to liquid radwaste monitor instrument FT&C procedure lacked plant review board evaluation Caused by personnel error TIPPS 8 B Georgia Power Co 62/10/21 Region 2, Office of Director ip 15853-027 24X Fiche 50-321.82/10/21,8210290349

- DOCKET 50-322 SHOREHAM NUCLEAR POWER STATION
- A Application/construction stage documents & correspondence
- B21001000B Responds to FOIA request for 19 categories of documents in nuclear reactor events & safety problems Forwards documents listed in App A FELTON.J M Division of Rules and Records 62/06/28 UDELL.R.A Critical Mass Energy Project 15pp 15727 005 24x Fiche 50-000.82/06/28.8210010008
- --B00B050265 Discusses addl required info to better define potential cracking in reactor vessel notices a NONAN, V S Assistant Director for Materials & Qualificatic S Engineering B0705/05 TEDESCO.R L Assistant Director for Licensing 2pp 15727 176 24X Fiche 50-000.B2706/20.B2100/EP
- B20B290099 FOIA request for documents re shipment of radicactive as' mfg by OE at Hilmington: NC. transported by Tri-State Hiter Transit: which traveled through NY on or about B20725 to received at facility SHARISON: B S New York: State of B2/09/14 Office of Administration ip 15758 242 24X Fiche 50-022, 82/09/14.
- 8210050488 Forwards requests for add1 info re instrumentation L control.containment sys & environ qualification of safety-related electrical equipment Scheduls for submitting required info requested within 7 days W/o encis SCHMENGER. A Licensing Branch 2 82/09/20 POLLOCK. N G Ling Island Lighting Co 3pp 15626 286 24X Fiche 80-322,92/07/2. 8210050488
- 8210190019 Responds to FOIA request for documents re shipment of radioactive matl mfg by GE at Wilmington.NC & transported by Tri-State Motor Transit to facility on 820723 Forwards DOF/NRC Form 741 handwritten note FELTON.J M Division of Rules and Records 82/10/06 CHARISON New York, State of 1p 15758 243 24X Fiche 50-322.82/10.15
- 8210280240 Provides NRC responses to Judge Morris 820914 quehtis*based on NRC 820629 response to earlier ASLB info requists Questions involve Unresolved Safety Issues A-44, A-46, A-42 h A-24. THI Item 1 A i. i & Item 63 REPKA-D A Hearing Branch 3 82/10/06 BRENNER.L. CARPENTS HORRIS.P.A Abonic Safety and Licensing Board Panel 17pp 15845:177 24X Fiche 30-322, 82/10/06, 8210280240
- B210210510 Responds to B20831 request to delay installation of his radiation signal for purge valves. (NUREO-0737. Item II E 4 2(7)) until fuel load Justification insufficient Re-evaluation requested SCHMENCER: A Licensing Branch 2 B2/10/13 POLLOCK-H 6 Ls*; Island Lighting Co 2pp 15782 278 RAX Fiche 50-322.82/10/13 9210210510
- E NRC Safety Evaluation Report (SER), supple & correspondents
- 8210190385 Forwards NRC 821013 response to util justification fir? installation of high radiation closure signal for purgs valves info relevant to SER Open Item II E 4 2 & Suffoli County Contention 23 H/o encl.

 REPNA-ID A Hearing Branch 3 82/10/15 BRENNER.L. CAPENTA.

 HORRISP A Atomic Safety and Licensing Board Fanel 239 13741 214. 24X Ficher 50-322, 82/10/15, 8210190385
- F Security, medical, emergency & fire protection plans
- 8210150055 Forwards IE Emergency Preparedness Appreheal fight % 35 BZ-18 on 820820-0702. App A. significant emergency preparedness findings & App D improvement items BHITH. O. H. Division of Emergency Preparedness & Operational Salat 82/09/30 POLLOCK. M. S. Long Island Lighting Co. 1031 15%. 3 24X Fiche 50-322. 82/09/30. 8210150055
- --B210150059 IE Emergency Preparedness Appreisal Rept 50-322/82-Js B20820-0902 Corrective actions required to complete emergency preparedness training program TERC.N.M., CROCKER.H W Division of Emergency Preparifets h Operational Support B2/09/30 40pp 15701 071 241 Fichs. 50-322, 82/09/30, 8210150085

- 62:0280033 Releases public version of revised info for facility energency plan
 FELTON, J M Division of Rules and Records 82/10/08 Document Management Branch ip 15857 145 24X Fiche 50-322,82/10/08, 8210280033
- ~-8210280036 Forwards public version of revised info for facility emergency plan, including updated cross-ref list, revised plan pages & radiological emergency evacuation plan Revised plan pages will be included in next amend SMITH-J L Long Island Lighting Co 82/09/24 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 19857 146 24X Fishe 50-322,82/10/08.8210280033
- -- E210280039 Forwards public version of revised info for facility erergency plan including updated cross-ref list, revised plan pages & radiological emergency evacuation plan Revised plan pages will be included in next amend SMITH.J L Long Island Lighting Co B2/09/01 DENTON, H R Office of Nuclear Reactor Regulation. Director 2pp 19857 148 24X Fiche 50-322,82/10/08,8210280033
- --8210280041 Public version of radiological emergency evacuation plan, consisting of updated cross-ref list-revised pages & offsite dose assessment methodology Thirteen oversite maps encl Aperture cards available in PDR MAGNUS.D Long Island Lighting Co MAGNUS.D KLD Associates, Inc 82/08/27 213pp 15857 150 24X Fiche 50-322,82/10/08, 8210280033
- B210290125 Forwards IE Insp Rept 50-322/82-24 on 820907-10 No noncompliance noted MARTIN, T T Division of Engineering & Technical Programs 82/10/9 POLLEGK.M S Long Island Lighting Co 2pp 15853 322 24X Fiche 50-322,82/10/15,8210270125
- G. Adjudicatory correspondence
- B2OB290094 FOIA request for CRAC & CRAC 2 analyses for facilities CURRAN, D Harmon & Weiss B2/09/10 Office of Administration 1p 15626 239 24% Fiche 50-000,82/09/10, 8208290094
- 82:02:0036 Stipulation of Suffoli County Contention 25/8horeham Opponents Coalition Contention 19(a) re preservice & inservice insp & reactor prossure vessel integrity Certificate of Svc encl BURDENICK.8 M Hearing Branch 3 IRHIN.D P Long Island Lighting Co. SHAN,J T Shoreham Opponents Coalition 82/09/17 ilpp 15755 345 24x Fiche 50-322,82/09/17.8210200036
- 8210040011 Forwards NRC 820903 ltr to util transmitting IE Insp Rept 50-322/82-14 BORDENICK.B M Hearing Branch 3 82/09/27 BRENNER,L, CARPENTER,J L, MORRIS,P A Atomic Bafety and Licensing Board Panel 4pp 15581 328 24X Fiche 50-322,82/09/27,8210040011
- B2:C010395 Supplemental status rept on Emergency Planning Contentions &C & 7A per ASLB B20907 supplemental preheating conference order Certificate of Syv encl MCMURRAY.C M Suffolk County, NY MCMURRAY.C M Kirkpatrick, Lockhart, Hill, Christopher & Phillips B2/09/28 5pp. 15569 239 24X Fiche 50-322,B2/09/28,B210010395
- 8210010386 Supplemental memorandum & order granting util motion to compel discovery on Suffolk County emergency planning documents Executive privilege does not apply to county emergency planning steering committee meeting minutes BRENNER. L Atomic Safety and Licensing Board Panel 82/09/29 Suffolk County, NY App 15574.140, 24X Fiche 50-322,82/09/29, 8210010356
- B2100505B2 Responds to FOIA request for CRAC & CRAC 2 analyses for facilities No analyses exist for Shoreham Nuclear Plant Analyses for CRBR furnished under FOIA 82-344
 FELTON.J H Division of Rules and Records 82/09/29 CURRAN.D Harmon & Weiss 1p 15626 240 24X Fiche 50-000.82/09/29, 82 10050582
- B2 (0040063 Forwards NRC 820916 ltr to util % util 820812 ltr to NRC re #E Insp Rept 50-322/82-13 BORDENICK.B M Hearing Branch 3 82/09/30 BRENNER.L, CARPENTER.J L, MORRIS.P A Atomic Safety and Licensing Board Panel 4pp 15581 237 24X Fichs 50-322.82/09/30.8210040063

- 8210050189 Notice of relevant & matl new info re type of accident involving internal flooding which may lead to higher probability than calculated in draft probabilistic risk assessment Certificate of Svc encl
 BROWN.H H Suffolk County. NY BROWN.H H Kirkpatrick. Lockhart.
 Hill. Christopher & Phillips 82/09/30 6pp 15603 301 24X
 Fiche 50-322,82/09/30.8210050189
- 8210050383 Motion to suppl sponsorship of Suffolk County testimony on Contentions 12-15 re compliance w/NRC OA/QC requirements.

 Add1 witnesses will bring relevant expertise to proceeding Certificate of Syc 2 prof qualification encl
 LANPHER.L C Suffolk County, NY LANPHER.L C Kirkpatrick,
 Lockhart. Hill, Christopher 2 Phillips 82/09/30 Atomic Safety
 and Licensing Board Panel 16pp 15608 235 24x
 Fiche 50-322, 82/09/30,8210050383
- 8210050243 Forwards NRC 820913 ltr to util transmitting IE Mgt Meeting Rept 50-322/82-25 on 820826 BORDENICK, B H Haaring Branch 3 82/10/01 BRENNER, L . CARPENTER, J L ., MORRIEJ, J L Atomic Safety and Licensing Board Panel 4pp 15611 178 24X Fiche 50-322, 82/10/01. 8210050243
- 8210060187 App B to ASLB 820907 supplemental prehearing conference order on Phase 1 re emergency planning, listing admitted Phase 1 contentions

 Atomic Safety and Licensing Board Panel 82/10/04 16pp 15613: 212 24X Fiche 50-3R2.82/10/04.8210060187
- 821028025| Forwards IE Emergency Preparedness Appreisal Rept 50-322/82-18 BLACK,R L Hearing Branch 3 82/10/04 BRENNER,L, CARPENTER,J L, MORRIS,P A Atomic Safety and Licensing Board Panel 2pp. 15838 204 24% Fiche 50-322,82/10/04,821028025|
- 8210120307 Motion for further ASLB direction on conduct of QA cross-examination Steps listed to ensure fair & efficient litigation of QA issues Certificate of Svc enci EARLEY.A F Long Island Lighting Co EARLEY.A F Hunton & Williams. 82/10/05 Atomic Sefety and Licensing Board Panel.
- 8210280234 Forwards 1E Insp Rept 50-322/82-23 BORDENICK, B H Hearing Branch 3 82/10/06 BRENNER, L , CARPENTER, J L , MORRIS, P A Atomic Safety and Licensing Board Panel 4pp 15837 067 24% Fiche 50-322, B2/10/06, B210280234
- 8210280240 Provides NRC responses to Judge Morris 820914 questions based on NRC 820629 response to earlier ABLB info requests Questions involve Unresolved Bafety Issues A-44.A-44.A-42 & A-24.TMI Itam i A i i k Itam 63 REPKA.D A Hearing Branch 3 82/10/06 BRENNER.L , CARPENTER.J L , MORRIS, P A Atomic 83efty and Liconsing Board Penel 17pp. 15845:177 24X Fiche 50-322.82/10/06.8210280240.
- 8210150234 Notifies that North Shore Committee Against Nuclear & Thermal Pollution & util have resolved Committee Contentions EP 11(D)(F)(E) & EP 12(A) Committee will not file testimony on Contentions EP 11(A)(B)(C) but will cross-examine SHAPIRO.R Cammer & Shapiro SHAPIRO.R North Shore Committee Against Nuclear & Thermal Pollution B2/10/OB. BRENNER.L , CARPENTER.J L , MORRIS.P A Atomic Safety and Licensing Board Panel 1p 15706 060 24X Fichs 50-322,82/10/08.8210150234
- 8210280209 Forwards Region i 820927 ltr to util re IE Insp Repts 50-322/82-10 & 50-322/82-11 & util 820701 & 19 Itrs.
 BORDENICK-B H Hearing Branch 3 82/10/08 BRENNER, L, CARPENTER, J., MORRIS, P. A Atomic Safety and Licensing Board Panel 4pp 15837 091. 24% Fiche 50-322,82/10/08,8210280209
- 8210150117 Advises that NMSS recommended Buffolk County not pursue 820916 request re NRC initiation of discussions w/F81 to explore ways to make F81 fingerprint identification svc available to util 80RDENICK.8 M Hearing Branch 3 82/10/12 MILLER,M 8 Kirkpatrick, Lockhart Hill. Christopher & Phillips. MILLER,M 8, 804601k County, NY. 2pp. 15698:016, 24X Fiche, 50-322,82/10/12,82/0181117
- 82i0130279 Forwards written testimony on Phase I amergency planning Contentions EP 1(B).2(A).2(B).4.5(A).5(B).7(B).10(B).10(C).11(A).11(B).11(C).13 4 Stipulations will be tent as soon as received.4/o testimony CHRISTMAN.J.N Long Island Lighting Co. 82/10/12 BRENNER.L. CARPENTER.J.H., MORRIS,P.A. Atomic Safety and Licensing Board Panel 4pp. 157i5:055, 24X Fiche:50-322.82/10/12.8210150279
- --8210130276 Forwards proposed settlement agreements on Emergency Planning Contentions I(A).3.5(C).7(A).6.9.10(A).11(D).11(E).11(F) & 12(A) HOCLESKEY,K.E. Hunton & Williams 82/10/12 BRENNER,L. HORRIS,P.A., CARPENTER,J H Atomic Safety and Licensing Board Panel. ip 15715 059 24X Fiche 30-322,82/10/12,8210150279.

- --8210150309 Stipulation on Suffolk County Contention EP 1(A) re effect of weather on sirens Util documented that effects of BLACK.R L Hearing Branch 3 MCCLEBKEY.K E Long Island Lighting Co SHAPIRD.R North Share Committee Against Nuclear & Thermal Pollution B2/10/12 6pp 15715 060 24x Fiche 50-322, B2/10/12, B210150279 extreme weather taken into consideration in design of
- --8210150324 Stipulation on Suffolk County Contention EP 3 re federal resources Plant emergency plan to be amended to respond to concerns
 BLACK,R L Hearing Branch 3 MCCLESKEY, K E Long Island Lighting
 Co SHAPIRO,R North Shore Committee Against Nuclear & Thermal
 Pollution 82/10/12 App 15715 066 24K Fiche 50-322,82/10/12,
 8210150279
- --B210150337 Stipulation on Suffork County Contention EP 5(C) renotification of response organization & emergency personnel Plant smergency plan to be amended as listed BLACK,R L. Hearing Branch 3 KCLLESKEY,K E. Long Island Lighting Co. SHAPIRG,R. North Shore Committee Against Nuclear & Thermal Pollution B2/10/12 4pp 15715 070 24X Fiche 50-322,82/10/12,8210150279.
- --8210150351 Bigolation on Suffolk County Contentions EP 7(A) & EP 8 re onsite response organization & emergency operations facility, respectively Plant emergency plan to be amended as BLACK,R L Hearing Branch 3 MCCLESKEY,K E Long Island Lighting Co SHAPIRO,R North Shore Committee Against Nuclear & Thermal Pollution 82/10/12 4pp 15715 074 24X Fiche 50-322.82/10/12,8210150279
- --8210150345 Stipulation on Suffolk County Contention EF 9 re radiological exposure Plant emergency plan to be amended as BLACK,R L Hearing Branch 3 MCCLESKEY,K E Long Island Lighting Co SHAPIRO,R. North Shore Committee Against Nuclear & Thermal Pollution 82/10/12 7pp 15715.078 24X Fiche.50-322.82/10/12.8210150279
- ≥1013003/3 Stipulation on Suffelk County Contention 10(A) re field monitoring team Fourth replacement field monitoring team will be available to replace or relieve other three teams BLACK, R L Hearing Branch 3. HCCLESKEY, K E Long Island Lighting Co SHAPIRO.R. North Shore Committee Against Nuclear & Thermal Pollution 82/10/12 App. 15715.085, 24% Fiche:30-322,82/10/12.8210150279 --8210150393 Stipulation on Suffolk County Contention 10(A) re field
- 230130402 Stipulation on North Shore Committee Against Nuclear & Thermal Pollution Contention EP (1(0)) re redundant power supplies Backup diesel generator power provided to radios used by util as backup communication BLACK, R. L. Hearing Branch 3 MCCLESKEY, K.E. Long Island Lighting Co. SHAPIRO, R. North Shore Committee Against Nuclear & Thermal Pollution 62/10/12 3pp 15715 088 24X Fiche 50-322,82/10/12,8210150279 --8210150402 Stipulation on North Shore Committee Against Nuclear &
- --8210150410 Btipulation on North Bhore Committee Against Nuclear & Thermal Pollution Contention EP ii(E) re communications through baspers Util commits to training personnel reresponse to bespers if telephone sys overloaded.

 BLACK.R.L. Hearing Branch 3 MCCLESKEY, K E Long Island Lighting Co BHAPIRO, R. North Shore Committee Against Nuclear & Thermal Pollution 82/10/12 3pp. 15715 091 24X Fiche 50-322,82/10/12,8210150279.
- --8210150422 Bipulation on North Bhore Committee Against Nuclear & Thermal Pollution Contention EP 11(F) re communication through nat1 elect warning sys, Concerns re coverage & Icad Capecity recoived.

 BLACK.R L Hearing Branch 3. MCCLESKEY.K E Long Island Lighting
 Co SHAPIRO.R North Shore Committee Against Nuclear & Thermal
 Pollution 82/10/12 2pp 15715 094 24X Fiche: 50-322, 82/10/12,
 8210150279.
- --8210150527 Stipulation on North Shore Committee Against Nuclear & 210150527 Stigulation on North Shore Committee Against Nuclear & Thermal Poliution Contention EP 12(A) re personnel assignments re communication notification Util cummits to provide seven communicators Certificate of Svc encl BLACK,R. L. Hearing Branch 3. MCCLESKEY,K.E. Long Island Lighting Co. SHAPIRO,R. North Shore Committee Ageinst Nuclear & Thermal Poliution 82/10/12 ápp. 15715 096. 24% Fiche 50-322,82/10/12,8210150279.
- 8210200076 Notification of corrections to Suffolk County Exhibits 51 & LANPHER, L C Suffelk County, NY. LANPHER, L C. Kirtpatrick, Lockhart, Hill, Christopher & Phillips. 82/10/12. 3pp 15754:173 24% Fichs. 50-932,82/10/12, 3821020076.

- -- 8210200083 Response opposing Requests 1 & 3 in util 821005 motion for 210200033 Response opposing Requests 1 & 3 in util 821005 acti further ASLB direction on conduct of cross-examination Hatls designated for use are relevant Opposes predetermined deadline by which County cross-examination must be complete LANPHER.L C Suffolk County, NY LANPHER.L C Kirkpatrick, Lockhart, Hill. Christopher & Phillips 82/10/15 Atomic and Licensing Board Panel 45pp 15754 176 24X Fichs 50-322,82/10/12.8210200076 Atonic Safeta
- --8210200089 Submittal of GA/GC info in Subparagraphs (a)-(c).Page 15 of util 821005 motion for further ASLB direction conduct of or util Majoud motion for further hold direction conduct of CA cross-eramination Certificate of Svc encl LANPHERL C Suffall County, NY LANPHERL C Kirkpatrict. Lockhart, Hill, Christopher & Phillips 82/10/11 189pp 15734 221 24% Fiche 50-322, 82/10/12,8210200076
- 8210200003 Response to Suffolk County 821002 motion to suppl GA witten panel Request is out of time is impermissible attempt to suppl County direct testimony & is different from earlier approved game! suppls Cartificate of Svc and!
 ELLIS.T 8 Long Island Lighting Co ELLIS.T 8 Hunton & Hilliams
 82/10/14 Atomic Safety and Licensing Board Panel [2pp
 15754,348 24X Fiche 50-322,82/10/14,8210200003
- 8210180099 Notice of withdrawal of appearance in proceeding Certificate of Bvc encl BLACK,R L Fiche. 50-322,82710/15,8210180099
- 8210190395 Forwards NRC 821013 response to util justification for late installation of high radiation closure signal for purge valves info relevant to SER Open Item II E 4 2 & Suffolk County Contention 23 H/o encl
 REPKA-D A Hearing Branch 3 82/10/15 BRENNER.L. CARPENTER.J L
 HURRIBS-P A Atomic Safety and Licensing Board Panel 2pp
 15741 214 24X Fiche 50-322.82/10/15.8210190385
- 8210250058 Forwards stipulation re Buffolk County Phase I Contention EP 6 MCHURRAY, C M. Kirkpatrick, Lockhart, Hill, Christopher & Phillips MCHURRAY, C M. Buffolk County, NY B2/10/19 ERENNER, L., CARPENTER, J H., MORRISH, P. A. Atomic Bafety and Licensing Board Part, lp 15787 094 24X Fiche 50-322,82/10/19,8210250058
- --B210250059 Stipulation on Suffolk County Contention EP & retraining emergency personnel Hading River fire dept trained per util emergency plan Certificate of Bvc encl BORDENICK.B Hearing Branch 3 McCLEGKEY.K E Long Island Lighting Co BHAPIRO,R North Shore Committee Against Nuclear to Thermal Pollution 82/10/15 Spp 15787 095 24X Fiche 50-322, 82/10/19.8210250058
- 8210270283 Forwards Buffolk County Deputy Executive F Jones 821020 memo to Suffolk county legislators re brief slippage in date memo to Surrolk county legislators re orier slippage in case scheduled for completion of county radiological emergency response plan. Related correspondence HCMURRAY.C. M. Kirkpatrick, Lockhart. Hill. Christopher & Phillips MCMURRAY.C. M. Buffolk County, NY 82/10/26 BRENNER.L. CARPENTER.J. H., MORRIS.P. A. Atomic Bafety and Licensing Board Paril 2pp 15854 047 24X Fiche 50-022, 82/10/26/8210290283
- H General correspondence
- 8210070034 Provides responses to constituent T Hayes 820611 questions re fuel storage & transport
 DIRCKB: M J Office of the Executive Director for Operations 82/09/17 CARREY, M, House of Rep. 17pp 15645 347 24X
 Fiche 50-322:82/09/17.8210070034.
- cturedutur forwards Hiddle Country Central Bohool Board 821004 resolution opposing plant opening until acceptable safety std can be met & acceptable evacuation plan developed AMAKO, V. Buffolk County, NY B2/10/07 NRC NO Detailed Affiliation Given. 2pp. 15803.317 24X Ficha 50-322,82/10/07.8210260409. 8210260409 Forwards Middle Country Central School Board 921004
- Q Inspection reports, IE Bulletins & correspondence
- 8210040258 Ack receipt of 820701 & 19 ltrs informing NRC of stage line to correct violations noted in IE Insp Repts 50-322/82-10 &
 - 50-322/62-11

 MARTIN T. T. Division of Engineering & Technical Programs
 POLLOCK M B Long Island Lighting Co 2pp. 15589-070

 Fiche 50-322, 62/09/27-6210040258.
- --8210040274 Responds to NRC 820524 ltr re violations noted in IE ${\rm Im}^{-1}$ Rept 50-322/82-10.Corrective actions procedure for less rate test panel retometer calibr revised. Severity Level V violation contested FOLLOCK.M S Long Island Lighting Co 82/07/01. MARTIN.T T Division of Engineering & Technical Programs 5pp. 15589 080 24X Fiche. 50-322,82/09/27.8210040258

DOCKETED ITEMS

- --8210040361 Responds to NRC 820618 ltr re violations noted in IE Insp Rept 50-322/82-11 Corrective actions scope & frequency of battery svc modified POLLOCK,M S Long Island Lighting Co 82/07/19 MARTIN,T T Division of Engineering & Technical Programs 4pp 15589 085 24X Fiche 50-322,82/09/27,8210040258
- 8210150055 Forwards IE Emergency Preparedness Approisal Rept 50-322/ 82-18 on 820820-0902, App A. significant emergency preparedness findings & App D improvement items SMITH, O H Division of Emergency Preparedness & Operational Support 82/09/30 POLLOCK, H 8 Long Island Lighting Co 10pp. 15701 061 24% Fiche. 50-322, 82/09/30, 8210150055
- --5210150059 IE Emergency Preparedness Appraisal Rept 50-322/82-18 on 520820-0902 Corrective actions required to complete emergency preparedness training progress TERC:N N . CROCKER,H W Division of Emergency Preparedness & Operational Support 82/09/30 40pp 15701 071 24X Fichs 50-322,82/09/30,8210150055
- 6210050243 Forwards NRC 620713 ltr to util transmitting IE Mgt Meeting Rept 50-322/82-25 on 620826 BURDENICK, BM Hearing Branch 3 82/10/01 BRENNER, L., CARPENTER, J. L., HORRIS, J. L. Atomic Safety and Licensing Board Panel 4pp 15611 178 24X Fiche 50-322.82/10/01.8210050243
- 6208190233 IE Info Notice 80-35, Suppl 1, "Leaking & Dislodged I-125 Implant Seeds " Svc list encl COBB. L 1 Division of Fuel Facilities, Materials & Safeguards 62/10/06 Consolidated Edison Co of New York 66pp 15761 250 24X Fiche 50-000,82/10/06,8208190233
- 2210290350 Forwards IE Insp Rept 50-322/82-22 on 820823-27. No moncompliance noted MARTIN, I T Division of Engineering & Technical Programs 82/10/06 FOLLOCK.H S Long Island Lighting Co 2pp 15853 067 24X Fiche 50-322, 82/10/06, 8210290350
- --BR10290356 IE Insp Rept 50-322/82-22 on 820823-27 No noncompliance noted Hajor areas inspected preoperational test program status, including program implementation, procedure review, procedure verification, test witnessing & evaluation results NICHOLAS, H H, BETTENHAUSEN, L Division of Engineering & Technical Programs 82/10/05 9pp 15853 069 24X Fiche 50-322.82/10/06, 8210290350
- B210290341 Forwards IE Insp Rept 50-322/82-21 on 820729 No noncompliance noted MARTINIT T Division of Engineering & Technical Programs 82/10/12 FOLLOCKIMS Long Island Lighting Co 2pp 15853 056 24X Fiche 50-322, 82/10/12, 8210290341
- --8210290344 IE Insp Rept 50-322/82-21 on 820729 No noncompliance noted Major areas inspected health physics personnel training & qualification program HHIYE, J.R., OREENMAN, E.G., Region 1, Office of Director 82/10/08 4pp 15853 058 24X Fiche 50-322,82/10/12,8210290341
- 8208190238 IE Bulletin B2-03, "Stress Corrosion Cracking in Thick-Wall. Large-Diameter. Stainless Steel, Recirculation Sys
 Piping at BWR Plants " Bvc list encl
 DEYGUNO,R C Director's Office, Office of Inspection and
 Enforcement B2/10/14 Consolidated Edison Co of New York.
 115pp 15810 125 24% Fiche 50-000.822/10/14,9208190238
- B210290084 Forwards IE Insp Rept 50-322/82-19 on 820719-0813 & notice of violation MARTIN.T T Division of Engineering & Technical Programs 82/10/15. PBLLOCK.M 8 Long Island Lighting Co 2pp 15854 032 24X Fiche 50-322,82/10/15,8210290084
- --8210290089 Notice of violation from insp on 820719-0813 * Division of Engineering & Technical Programs 82/10/15 ip. 15854 034 24X Fiche 50-322, 82/10/15, 8210290084
- -- B210270093 IE Insp Rept 50-322/82-17 on 820719-0813 Noncompliance noted two radiographs did not have required penetrameters & proper dispositions KERCK.H W . HARRIB.R H . DIERR.J P. Region 1. Office of Director 82/09/19 10pp 15854 035 24K Fiche 50-322,82/10/15.8210270084
- B210290125 Forwards IE Insp Rept 50-322/82-24 on 820907-10 No moncompliance noted MARTINIT Toivision of Engineering & Technical Programs 82/10/15 POLLOCK, M8 Long Island Lighting Co 2pp 15853, 322, 24X Fiche: 50-322, 82/10/15,8210290125

- --8210270132 IE Insp Rept 50-322/82-24 on 820907-10 No noncompliance noted Hajor areas inspected actions on previous inspected findings & fire protection/prevention program in areas of administrative controls & cable separation requirements RICHARDS.8 A , PLISCO.L R , BETTENHAUSEN, L Region 1, Office of Director 82/09/29 7pp 13853 324 24X Fiche 50-322,82/10/15,8210290125
- 8210260134 Ack receipt of 821007 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-322/82-15 STARDSTECKI.R Division of Project & Resident Programs POLLOCK.M S Long Island Lighting Co 2pp 15779 093 24X Fichs 50-322.82/10/20.8210260134
- --B210260141 Responds to NRC 820830 ltr re violations noted in IE Insp Rept 50-322/82-15 Corrective actions startup mgt meeting held 820917 to review documentation for all testing & PT 654 007 revised to incorporate exceptions POLLOCK.M B Long Island Lighting Co 82/10/07 STAR08YECKI.R Division of Project & Resident Programs 7pp. 15797.095 24X Fiche: 50-322,82/10/20,8210260134
- S Reportable occurrences, LERs & related correspondence
- 82:0070384 Deficiency rept re analogue controllers supplied by Bailey Controls Co Initially reported on 820827. Circuit will be completed prior to fuel lead, per E & DCR F-42213 & CCF M50/06 MILLIOAN.M H Long Island Lighting Co 82/09/28, ORIER, B. H Region 1, Office of Director 3pp. 15633 346 24% Fiche 50-322. 82/09/28, 8210070384
- 8210280285 Interim deficiency rept re jacket water pump shaft failures on emergency standby diesel generators Initally reported on 820917 Design mods to jacket water pump shaft-impeller assembly underway Alterations to shaft expected MILLIOAN.M H Long Island Lighting Co 82/10/15 HAYNES.R. C Region 1. Office of Director 3pp. 15837 040. 24X Fiche 50-322,82/10/15,8210280285
- T Hearing transcripts on non-antitrust matters
- 8210150168 Testimony of MG Schiffmacher & MF Renz re Phase I emergency planning Contention 1(B) on prompt notification sys.Prof qualifications encl. SCHIFFMACHER, W, RENZ, W F Long Island Lighting Co. 82/10/12 21pp 15707 315. 24X Fiche 50-322,82/10/12,8210150168.
- --8210150178 Testimony of RE Linnemenn & ML Miele re Phase I emergency planning Contention 2(A) on adequate medical sycs Prof qualifications & supporting documentation encl. LINNEMANN, R E, MIELE, M L Long Island Lighting Co. LINNEMANN, R E Radiation Management Corp. B2/10/12 32pp. 15707:336 24X Fiche 50-322,82/10/12,8210150168
- --8210150188 Testimony of NJ DiMascia & E Lieberman re Phase I emergency planning Contention 2(8) on ground transportation to hosp Prof qualifications & supporting documentation encl One aperture card available in PDR DIMASCIO,N. J. LIEBERMAN, E. Long Island Lighting Co. LIEBERMAN, C. K.D. Associates, Inc. 82/10/12, 45pp. 15708-006 24X Fiche 50-322,82/10/12,8210150168
- --8210150206 Testimony of B Aidikoff, HM Blauer, M Cordaro, E Lieberman & J Rivello re Phase I emergency planning Contention 4 on protective actions. Prof qualifications & supporting documentation encl Six aperture cards available in PBR AIDIKOFF, B, BLAUER, H K, CORDARO, M Long Island Lighting Co 82/10/12, 170pp. 13708.051. 24X Fiche. 50-322,82/10/12, 8210150168
- --8210150223 Testimony of MC Cordaro, RR Dynes, D8 Mileti & J Rivello re Phase I emergency planning Contention 5(A) on role conflict Frof qualifications enci CORDARO, M. C. DYNES, R. R., MILETI, D. S. Long Island Lighting Co 82/10/12 78pp 15708 222, 24X Fiche, 50-322, 82/10/12, 8210150168
- --8210190240 Testimony of NJ DiMascio & E Limberman re Phase I emergency planning Contention 5(8) on traffic congestion affecting onsite amergency workers & offsite util personnel reporting to site Prof qualifications & supporting documentation encl. DIMASCIO.N J., LIEBERMAN.E. Long Island Lighting Co LIEBERMAN.E. KLD Associates, Inc. 82/10/12 34pp. 1570B.299, 24X Fiche.50-322,82/10/12,8210150168
- --8210150250 Testimony of HM Blauer, H Cordero & J Rivello re Phase I mergency planning Contention 7(B) on ability to augment procedures within 30 minutes Prof qualifications & supporting documentation encl.
 BLAUER, H. M., CORDARO, M., RIVELLO, J. Long Island Lighting Co. 82/10/12 40pp. 15708:333. 24X Fiche: 50-322,82/10/12,8210150168.

- --8210150257 Testimony of HK Blauer, MC Cordaro & JF Schmitt re Phase I enulous restiment of HM Blauer, MC Cordaro & JF Schmitt re Phase amergency planning Contention 10(B) on real time monitors Prof qualifications & supporting documentation encl BLAUER, H M . CORDARO, M. C . SCHMITT, JF Long Island Lighting Co 82/10/12 289pp 15709 031 24X Fiche 50-322, 82/10/12, 8210150168
- SCHMITT.J F , BARON.J 8 Long Island Lighting Co BARON.J 8 Stone & Hebster Engineering Corp 82/10/12 30pp 15709 321 24X Fiche 50-322.82/10/12.8210150168
- --8210150272 Testimony of MF Renz & P Friedman re Phase I emergency planning Contention (1(A).(B) & (C) on communications woodfisits response organizations Prof qualifications & supporting documentation enci RENX.W F. FRIEDMAN.P Long Island Lighting Co 82/10/12 57pp 15709:351 24X Fiche 50-322.82/10/12.8210150168
- --8210150281 Testimony of JA Notaro & RL Poltrino re Phase I emergency planning Contention 13 on interim safety parameter display sys Prof qualifications & supporting documentation enci NOTARO, J A , POLTRINO, R. L. Long Island Lighting Co POLTRINO, R L. Bione & Webster, Inc. 82/10/12 43pp 15710 046 24X Fiche 50-322,82/10/12,8210150168
- -- 6210150290 Testimony of JB Baron MC Cordaro NJ Diffactio, JN Hamawi, LP Pocaluska & JF Schmitt re Phase I emergency planning Contention 14 on accident & dose assessment models M/ Convention 14 on accident & dose assessment models M/
 Certificate of Svc Five aperture cards available in PDR
 BARON, J 8 , CORDARD, M C , DIMASCID, N J Long Island Lighting Co
 82/10/12 117pp 15710 126 24X Fiche 50-322,82/10/12,
 8210150168
- 8210150370 Transcript of 821012 hearing in Bethesda, MD Pp 11,309-11.484 Supporting documentation entl 1.484 Supporting documentation entl 2.484 Atomic Bafety and Licensing Board Panel B2/10/12 194pp 18704 069 24X Fiche 50-322.82/10/12.8210150370
- 8210260232 Testimony of AC Kanen, JR Johnson, 8 Cole & KT Eritson on Contentions EP 28 & 58 re traffic congestion issues. KANEN, A C. JOHNBON, J. H., CCLE. 8 Suffolk County, NY 62/10/12 337pp. 15802 001 24X Fiche 50-322, 82/10/12,8210260232
- --8210260239 Testimony of KT Erikson & 8 Cole on Contention EP 5A re rale conflict ERIXBON.K T , COLE.B Buffolk County, NY. ERIKSON.K T Yalw Univ B2/10/12 95pp 15802 178 24X Fiche 50-322,82/10/12. B210260232
- --8210260242 Testimony of QC Minor on Contentions EP 108 % EP 10C re radiation monitoring & EP 14 re dose assessment MINOR.O Suffolk County, NY 82/10/12 13pp 15802.273. 24X Fiche 50-322,82/10/12:8210260232
- --8210260246 Testimony of FC Finlayson on Contention EP 14 re-accident assessment & dose assessment models.Certificate of Byc encl. FINLAYSON, F. C Buffolk County, NY 82/10/12 50pp 15802:286. 24% Fiche 50-322, 82/10/12, 8210260232.
- 8210150166 Transcript of 821013 hearing in Bethesda, MD.Pp 11, 485-11, 667. * Atomic Sefety and Licensing Board Panel 82/ 15698 025. 24% Fiche 50-322.82/10/13,8210150166 82/10/13, 188pp.
- 8210180037 Transcript of 821014 hearing in Bethesda, MD Pp 11,670-11.882 Supporting documentation encl.

 * Atomic Safety and Licensing Board Panel 82/10/14, 299pt 15720:327, 24X Fiche.50-322, B2/10/14, B210180037
- 8210190338 Transcript of 821015 hearing in Bethesda, MD Pp 11,883-* Atomic Safety and Licensing Board Panel. 82/10/15 138pp 15742.322 24% Fiche: 50-322,82/10/15,8210190338
- 8210270004 Transcript of 821027 hearing in Bethesda. MD # Atomic Safety and Licensing Board Panel. 82/10/27 174pp. 15856:331 24X Fiche.50-322.82/10/27.8210290004.

- DOCKET 50-323 DIABLO CANYON NUCLEAR FOWER PLANT, UNIT 2 A Application/construction stage documents & correspondence
- 8210010008 Responds to FOIA request for 19 categories of documents as noclear reactor events & safety problems Forwards documents noclear reason.

 Jisted in App A

 FELTON, J H Division of Rules and Records 02/06/20 UDELL,R A

 October Hass Energy Project 15pp 15727 005 24X
- Critical Hass Energy Project 15 Fiche 50-000, 82/06/28, 9210010008
- --8008050265 Discusses addl required info to better define potential erroracking in reactor vessel nozzles
 NOONAN, V S Assistant Director for Materials & Qualifications
 Engineering 80/05/05 TEDESCO.R L Assistant Director for
 Licensing 2pp 15727 176 24% Fiche 50-000.82/06/28.8210010005
- 8210040429 Informs of decision to partially refund fees remitted w/ 800821 application to extend latest CP completion dates MILLER. W O License Fee Management Branch 82/09/21 FURBUSH.M Pacific Gas & Electric Co ip. 15597 262 24X Fiche 50-275.82/09/21.8210040429
- 8210130056 Responds to 820727 request for status rept on design verification program & briefing on proposed Phase II of program Info discussing background & current status encl DIRCHS.N J Office of the Executive Director for Operations 82/09/24 PALLADINO.N J. GILINSKY.V., AHEARNE.J F Commission 15692 284. 24X Fichs 50-275.82/09/24.8210130056 Commissioners
- 82(0050144 Responds to Generic Ltr 82-12 re plant staff working hours. Util administrative procedures address revised working CRANE.P A Pacific Gas & Electric Co 82/10/01 MIRAGLIA.F J Licansing Branch 3 lp 15605 161 24X Fiche 50-275,82/10/01, 8210050144
- 8210250168 Forwards RH Engelken 820915 memo re RF Reedy, Inc esit meeting concerning GA audits for consideration in evaluation of GA program ELEENHUT, D. O Division of Licensing 82/10/06 COOPER, WE Teledyne Engineering Bervices. 2pp 15808 009 24X Fiche 50-275, 92/10/06, 9210250168
- --8210250392 Summary of 820910 meeting w/util & RF Reedy, Inc re GA as or in-house design
 enockKen.R H Region 5. Office of Director 82/09/15
 DENTON.H R Office of Nuclear Reactor Regulation. Director 5,1
 15808-011. 24% Fiche 50-275.82/10/06.8210250168
- B210250240 Forwards independent design verification program commiss: Phase I final rept Rept should contain detailed descriptions of scope criteria, methodology & models for all structures. sys & Components
 CODPER W.E. Teledyne Engineering Services 82/10/07 DENION R 8
 Deffice of Nuclear Reactor Regulation. Director ENGELKEN, 8 H
 Region 5. Defice of Director MANEATIS. G.A. Pacific 0ss & Elithi
 Co. 16p. 1879:
- 8210080123 Notifies of 821007 meeting w/util in Ban Francisco.CA to discuss status of Phases I & II. instrument test rig for verification of corrective action & NRC 820819 ltr re fuel load.
 - Teledyne Energy Systems 82/10/08 Teledyne Energy System tp. 15640 129 24X Ficher 50-275,82/10/08,8210080123
- 8210290446 Staff requirements memo re 821007 affirmation/discussion vote on extension of const completion dates for WPPSS, purging of classified math in ALAB-653 & emergency preparedness & risks associated wifuel loading CHILK, S. J. Office of the Secretary of the Commission 82/10/06 Office of the Secretary of the Commission 2pp 15863 189 24 Fichs 50-000, 82/10/08, 8210290446.
- 8210190470 Provides info re ownership of Bechtel Power Corp FRIEND.H B Bechtel Corp. 82/10/11. MIRAQLIA.F. J. Licensing Branch 3. ip 15740.181 24X Fiche 50-275.82/10/11.8210190470
- 8210270351 Advises that Bechtel Power Corp is entity responsible for work on project Ownership held by officers of Bechtel Oroup, Inc Group: Inc FRIEND, H B Pacific Oas & Electric Co FRIEND, H B Bechtet (up 82/10/11, MIRAQLIA: F.U. Licensing Branch 3 ip. 15834-358 20 Fiche: 50-275, 82/10/11, 8210270351
- 8210150389 Suppl to 820719 application for amend to License PR-75 rescurity plan Encl withheld (ref 100FR73 21).

 CRANE, P. A. Pacific Qas & Electric Co. 82/10/12. DENTON, N.R., NIRAOLIA Office of Nuclear Reactor Regulation, Director 239 15703; 279 24% Fiche 50-275, 82/10/12, 8210150389.

- E210250291 Clarifies B21007 statement re required sys, structures & components for plant operating modes for independent design **ertfication program COOPER.W E Teledyne Engineering Services 82/10/12 EISENHUT, D O Division of Licensing App 15790 191 24X Fiche 50-275, B2/10/12, P210250291.
- 5210290097 Requests explanation of process & chronology of events in which Teledyne discussed const GA review of plant w/util, Bethtel & S&W Info required to determine presence of confiltst of interest Meeting requested ERGHN, H H Kirkpatrick, Lockhart, Hill, Christopher & Phillips BROWN, H H California, State of 82/10/12 COOPER, W E Teledyne Engineering Services 2pp 15859 361 24% Fiche 50-275,82/10/12,8210290097
- 5210290214 Provides NRC recommendation re Phase II of independent design verfication program Phase II program plan & requirement that Phase II review/evaluations be completed prior to fuel load/low power decision approved DIRCKS:H J Office of the Executive Director for Operations SECV-82-414 82/10/13 61pp 15876 261 24X Ficha 50-275, B2/10/13,8210290214
- 8210190593 Advises that two former Bechtel employees will be retained on independent design verification program Individuals do not violate procedure on conflict of interest & will not verify work participated in as Bechtel employee CODERS. WE Teledyne Engineering Services 82/10/14 DENTON, H.R. Office of Nuclear Reactor Regulation, Director ENGELKEN, R.H. Region 5. Office of Director MANEATIS. O.A. Pacific Qas & Electric Co. 3pp. 15791 184 24X Fiche 50-275, 82/10/14, 8210190583
- 8210170584 Provides preliminary response to 820701 request for review of seven points re validity of INL results & generic implications in final rept concerning analysis of facility COOPER.W E Teledyne Engineering Services 82/10/15 DENTON,H R Office of Nuclear Reactor Regulation, Director 3pp 15791 187 24% Fiche 50-275,82/10/15,8210170584
- 8210250210 Identifies concerns resulting from review of URS/Blume containment annulus structure model evaluation Concerns resulted in issuance of EDI Files 3006 & 3007 WRAY, R Teledyne Engineering Bervices B2/10/15 MANEATIS, 0 A Pacific Oas & Electric Co 4pp 1578B 292 24X Fichs 50-275, 82/10/15, 8210250210
- 6210250318 Comments on Region 5 820915 memo re Phase II of independent design verification program.per 821006 request Change in Phase II not indicated COPPER.W E Teledune Engineering Services 82/10/15 EISENHUT.D.O Division of Licensing 5pp. 15790 048 24X Fiche 50-275,82/10/15,82/10/250318
- F Security, medical, emergency & fire protection plans
- 8210210033 Releases public version of revised emergency plan implementing procedures FELTON-J N Division of Rules and Records 82/10/01 Document Hanagement Branch ip 15782 091 24X Fiche 50-275,82/10/01,8210210033
- --8210210044 Forwards public version of revised emergency plan implementing procedures, including Procedure EP M-3 re chlorine release, EP M-5 re Tsunami warning & EP M-8 re containment emergency personnel hatch CRAME, P A Pacific Gas & Electric Co 82/09/23 ENGELKEN, R H Region 5, Office of Director 3pp 15782 092 24X Fiche 50-275,82/10/01,8210210033
- -- 8210210048 Public version of revised emergency plan implementing procedures, including Procedure EP H-3 re chlorine release, EP H-5 re Tsunami warning & EP H-8 re containment emergency personnel hatch

 Pacific Oas & Electric Co 82/09/13 84pp. 15782 095. 24X
 Fiche 50-278,82/10/01/8210210033
- 8210150389 Suppl to 820719 application for amend to License DPR-76 re security plan. Encl withheld (raf 10CFR73 21), GRANE, P.A. Pacific Gas & Electric Co. 82/10/12, DENTON, H.R Office of Nuclear Reactor Regulation, Director, 2pp 15703, 279 24x Fiche 50-275,82/10/12,8210150389
- O Adjudicatory correspondence
- 92: 02:90449 Responds to 820512 petition requesting action under 10GFR2 206 For reasons stated in enclosed Director's Decision: petition denied DENTON: HR Office of Nuclear Reactor Regulation. Director 92:097/22. REYNOLDB. J. Center for Law in the Public Interest 5pp. 15863:166 24X Fiche: 50-275, 82/09/22, 82/02/0449

- --B21027045: Director's Decision DD-82-10 denying Ctr for Law in Public Interest B20512 petition requesting NRC issue order to util to submit amend to DL to cover GA & GC issues DENTON, H R Dffice of Nuclear Reactor Regulation, Director B2/09/22 7pp 15863 171. 24X Fiche 50-275, B2/09/22, B210290449
- --8210290454 Notice of issuance of Director's Decision DD-82-10 under 100FR2 206 denying petition by Ctr for Law in Public Interest request to require util to submit amend to DL to cover GA & GC issues DENTON,H R Office of Nuclear Reactor Regulation, Director 82/09/22 3pp 10863 178 24X Fiche 50-275,82/09/22,8210270449
- 8210040102 Order extending time until 821005 for Commission to act to review ALAB-681
 CHILK.8 J Office of the Becretary of the Commission 82/09/30
 Commissioners 1p 15581 025 24X Fiche 50-275,82/09/30,8210040102
- 821005021B Reply to applicant & NRC 820924 briefs re status of pending appeals from authorization of low power operation No adequate factural basis exists to support ASLB dismissal of Joint Intervenor OA contention as most W/Certificate of Svc. REYNOLDB, J R Joint Intervenors-Diablo Canyon REYNOLDB, J R Center for Law in the Public Interest 82/09/30 Atomic Bafety and Licensing Appeal Panel Bpp 15611 237 24X Fichs 50-279, 82/09/30, 821005021B
- 8210060220 Reply brief to other party briefs re mootness of low power cantentions Emergency planning issues & certain other issues moot Certificate of Svc encl LOCKE.R F Pacific Gas & Electric Co 82/09/30 Atomic Befety and Licensing Appeal Panel 6pp. 15620.190. 24X Fiche 50-275, 82/09/30, 8210060220.
- 8210040097 Reply to Oovernor Brown & Joint Intervenors 820924 filings in response to ASLB 820902 order on mootness of low power issues Emergency planning issues & some low power contentions mooted Certificate of Svc encl
 JONES, B. W. Hearing Branch 1 82/10/01 Atomic Safety and Licensing Appeal Panel 9pp 15591 026 24X Fiche: 80-275, 82/10/01, 8210040097
- 8210050180 Reply brief to util & NRC B20924 briefs re monthess of low power issues, per ABLB 820902 order Issues not moot. Controversy still exists & issue is of practical significance Certificate of Svc encl.

 BROWN,H.H. California: State of. BROWN,H.H. Kirkpatrick, Lockhart, Hill. Christopher & Phillips B2/10/01 Atomic Safety and Licensing Appeal Panel Spp 15603 345 24X Fiche: 80-275, 82/10/01, 8210050180
- 8210060186 Request for leave to withdraw certain exceptions to ASLB 820831 initial decision ASLB 820927 clarification of & local jurisdiction acquiescence to preconditions re SOPs render exceptions unnecessary Cartificate of Svc encl HASEELL, D.F. Hearing Branch 1 82/10/04 Atomic Bafety and Licensing Appeal Panel 5pp. 13613 193 24X Fiche 50-275,82/10/04,8210060186
- B210070145 Order extending time until B2100B for Commission to act to review ALAB-681.
 CHILK, B J Office of the Secretary of the Commission B2/10/05 Commissioners 1p. 15627 076 24X Fiche. 50-275,82/10/05,8210070145.
- 8210130272 Forwards San Luis Obispo County Board of Supervisors 820927 action approving San Luis Obispo County nuclear power plant emergency response plant & Stats of CA Senate Bill 1473 amending govt code. Certificate of Svc enci CRANE.P A Pacific Gas & Electric Co 82/10/06 BUCK, J. H., JOHNBON, M.R. NORDE, T.S. Atomic Safety and Licensing Appeal Panel. 6pp 15678 284, 24X Fiche 30-275,82/10/06.8210130272
- 8210120332 Order CLI-82-30 directing all natl security classified info be expunded from ALAB-653 & underlying record. Info not essential to ASLAB opinion & expunction would not prejudice any party or public.
 CHILK.S.J. Office of the Secretary of the Commission 82/10/08 2pp. 15652-108. 24X Fiche 50-275,82/10/08,8210120332.
- 8210130327 Order extending time until 821026 for Commission to act to review ALAB-681 Hills, S.J. Office of the Secretary of the Commission. 82/10/08. Commissioners Ip. 15678 282. 24X Fiche: 50-275,82/10/08,8210130327.
- 8210210422 Order extending time until 821105 for Commission to act to review NRR Director 820922 deniel of Joint Intervenors 100FR2, 206 request, CHILK, 8 J. Office of the Secretary of the Commission 82/10/18, Commissioners, 1s, 15763,083 24K Fichs, 50-275,82/10/18, 8210210422

- 1

11

11

3

8210280245 Hemorandum in response to util 820924 motion for clarification of ABLB 820831 initial decision Decision supports conclusion of law on adequacy of offsite energency planning. MCLF, J.F. Atomic Safety and Licensing Board Panel 82/10/26 2pp 15837 056 24X Fiche 50-275,82/10/26.8210280245

H Ceneral correspondence

- 8210220363 Advises that 821010 ltr requesting util recalculate saismic safety sys at glants will be sent to all parties OILINEXY,V Commissioners 82/10/20 80HULKE,9. Affiliation Uninoun is 15779 201 24K Fiche 50-275.62/10/20.8210220363
- --8210220369 Urges util be forced to recalculate entire seismic safety sys at plant SCHULKE, B. Affiliation Unknown 82/10/10 OILINSKY,V Commissioners (p. 15779-202 24X Fiche 50-275,82/10/20, 8210820363,
- Q Inspection reports. IE Bulletins & correspondence
- 8210040133 Forwards IE Insp Repts 50-275/82-26 & 50-323/82-13 on 820724-30.0814-20 & 0830-0901 No noncompliance noted BIBHOP. TW Division of Resident, Reactor Project & Engineering Programs 82/09/17 CRANE.P.A. Pacific Cas & Electric Co 2pp 15614 307. 24X Fiche-50-275,82/09/17.8210060133
- --8210060141 IE Insp Repts 50-275/82-26 & 50-323/82-13 on 820726-30, OB16-20 & OB30-0901 No noncompliance noted Major areas inspected size tour & mod to piping & electrical raceway supports resulting from revised announce steads spectra BURDOIN.J F , ZMETZIG.O B Division of Resident, Reactor Project & Engineering Programs. 82/09/17 9pp 15514 311 24X Fichs 50-275,82/09/17,8210060133
- 820B190233 IE Info Notice 80-35, Suppl 1, "Leaking & Dislodged I-125 Implant Seeds " Svc list encl CDBB.L 1 Division of Fuel Facilities, Materials & Safaguards 82/10/06, Consolidated Edison Co of New York & Spp 15761 250 24X Fiche: 50-000,82/10/06,8208190233
- 8208190238 IE Builstin B2-03, "Stress Corrosion Cracking in Thick-Wall, Large-Diameter, Stainless Steel, Recirculation SysPiping at BWR Plants " Swy list encl
 DEYGONO, R C Director's Office, Office of Inspection and Enforcement 82/10/14, Consolidated Edison Co of New York
 115pp 15810 128, 24% Fiche, 50-000, 82/10/14, 9208190238
- 6210280324 Forwards LE Insp. Repts 50-275/62-30 & 50-323/62-14 on 820914-16 No moncompliance noted BISHGP.T H Division of Resident, Reactor Project & Engineering Programs 82/10/14 CRANE.P A Pacific Qas & Electric Co 2pp 15839 019 24K Fiche 50-275, 62/10/14.8210280324
- --B210280330 IE Insp Repts 50-275/82-30 & 50-323/82-14 on 820914-16 No noncompitance noted Major areas inspected implementation of independent verification program including independence qualifications of personnel & implementation of GA program HORRILL-P J., ECKHARDI.J H., BIRHIDP.T N. Division of Resident, Reactor Project & Engineering Programs. B2/10/08 6pp 15839 021. 24X Fiche: 50-275, 82/10/14, 8210280324
- R. Periodic operating reports & related correspondence
- 9210250247 Bubmits Bemimonthly Progress Rept 20 for 820902-1008. No open item repts issued, but two open item repts identified Individuals completed acceptable statements repetential or apparent conflicts of interest REEDY.R F R.F Reedy. Inc. 82/10/08 DENTON.H R. Office of Nuclear Reactor Regulation. Director. ENGELKEN.R H Region 5. Office of Director MANEATIG. 9 A. Pacific Gas & Electric Co. 2pp. 15788 342. 24% Fiche 50-275, 82/10/08,8210250247.
- 8 Reportable occurrences, LERs & related correspondence
- B210250055 PNO-V-82-043 on B21016.unusual event declared when grass fire started in 500 kV switchyard On B21017.three 500 kV circuits tripped.rssulting in loss of all offsite power. Second unusual event declared.
 STERNBERG.D. M. Region 5. Office of Director. B2/10/16. ip. 15787:100. 24X Fiche: 50-275.82/10/16.8210250055.
- T Hearing transcripts on non-antitrust matters
- 8210290370 Unofficial transcript of 821020 public discussion of Phase II reverification program in Hashington, DC, Pp 1-113 Supporting documentation encl. P Commissioners, 82/10/20, 144pp. 13865 095, 24x Fiche: 50-275, 82/10/20, 8210290370.

- 8210220416 Forwards transcript of Commission 821020 meeting to receive NRC briefing on proposed scope of Phase IJ of independent design verification program & 821019 meeting w/ util & participants re program & SECY-82-414 W/o ancl CHILK-8 J Office of the Secretary of the Commission 82/10/21 Office of the Executive Legal Director 1p 15779 211 24X Fiche 50-275, 82/10/21,8210220416
- DOCKET 50-924 BRUNSHICK STEAM ELECTRIC PLANT, UNIT 2

 F Security, medical, emergency & fire protection plans
- 8209140148 Forwards "Fire Protection of Cable Spreading Rosm," evaluating quantity of transient combustibles necessary to cause ignition of most limiting cable Info supple 810306 exemption request HOME, P. W. Caroline Power & Light Co. 62/09/08 DENTON, H.R. Office of Nuclear Reactor Regulation, Director 2pp. 14762 001 24x Fiche 50-324, 62/09/08, 8209140148
- --8209140153 "Fire Protection of Cable Spreading Room" 4 Carolina Power & Light Co 82/08/31 61p 14782 004 24r Fiche 50-324,82/09/08,8209140148
- 8210060316 Forwards revised Bections 5 & 6 to "Safe-Bhutdown Capability Assessment & Proposed Mods"
 ZIMBERMAN, B R Carolina Power & Light Co 82/10/01 DENTON, H R
 Office of Nuclear Reactor Regulation, Director ip 15616 033 &c
 Fiche 50-324, 82/10/01, 8210060316
- 8210130295 Forwards responses to BNNL & NRC Questions 1-6 re util 820804 radiation shielding study for proposed emergency operations facility/technical support ctv Written concurrence requested by 821025 ZIMMERHAM.8 R Carolina Power & Light Ca 82/10/11 VASSALLO.0 J Operating Reactors Branch 2 3pp 15678 240 24X Fiche 50-324.82/10/11.8210130295
- 8210220489 Ack receipt of 821006 1tr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-324/82-30 & 50-324/82-30 WERRELLI,D M Division of Project & Resident Programs G2/10/18 UTLEY, E E Carolina Power & Light G 1p 15777 0S7 24X Ficks 50-324, 82/10/18/8210220489
- --B210220492 Responds to NRC 820907 ltr re violations noted in IE I-;
 Repts 50-324/82-30 & 50-325/82-30 Corrective actions
 technician counseled re compliance w/Maint Instruction
 MI-10-2J Fire Protection Procedure FP-14 will be revised
 DIETZ.C R Carolina Power & Light Co 82/10/06 O'REJLLY, JP
 Region 2. Office of Director 2pp. 15779 088 24X
 Fiche 50-324, 82/10/16, 8210220489
- --8210220496 Notice of violation from insp on 820715-0815 ** Division of Project & Resident Programs 82/09/07 1/ 15779:092 24% Fichs:50-324, 82/10/18,8210220489
- --8210220503 IE Insp Repts 50-324/82-30 & 50-325/82-30 on 620715-033 :
 Nancompliance noted on 820805, safety-related equipment Meint
 Instruction MI 10-2J incorrectly performed & Fire Protection
 Procedure FP-14 Step III A improperly implemented on 82076
 MYERB: D D , GARNER: L. W., CHABE: J Division of Project & Resist's
 Programs 82/09/03, 9pp. 15779 093 24X Fichs 50-324,82/10/11
 6210220489
- 8210280275 Forwards corrected pages to rept submitted in conjuction w/820708 cable spread room examption request & Pages A.3-7-A 3-10 inadvertently omitted.
 ZIMMERMAN, 8 R Capoline Power & Light Ca 82/10/22 DEMICH.H R Office of Nuclear Reactor Regulation, Director 1p 15837 295 24 Fichs. 50-324, 82/10/22,8210280275
- ---8210280278 Corrected & edd1 pages to "Fire Protection of Calle Spreading Room." * Caroline Power & Light Co 82/10/22 Spp 15837 298 241 Fiche: 50-324, 82/10/22, 8210280275
- H General correspondence
- B21001002B Requests NRC direct all official correspondence to EE VIII. util vice-president, due to B20730 retirement of JA Jones JONES, J A Carolina Power & Light Co B2/07/27 DENYON, H R. Office of Nuclear Reactor Regulation, Director, ip. 15385 314 M Fiche: 50-000, B2/07/27, B21001002B

- 82:0130323 Requests changes to distribution list for NUREG-0020, 'Licensed Operating Reactors - Status Summary Rept " ZIMMEMMAN'S R Caroline Power & Light Co 82/10/11 BESSE, M R ADP Systems Development Branch 2pp 15683 361 24X Fiche 50-000, 82/10/11, 82:0130323
- P Operating license stage documents & correspondence
- 8207180044 FOIA request for all internal non-public documents, memos, evaluation repts & other math dealing w/nuclear plant operations MCINIS.D. News & Observer 82/08/17 Office of Administration ip 15860 064 24X Fiche 50-000,82/08/17,8207180044
- 6210040006 Forwards revised Tech Specs to Amend 72 to License DPR-62. correcting errors in total peaking factor values for Cycle 5. VASSALLO,D B Operating Reactors Branch 2 82/08/30 JONES,J A
- VASSALLO, D.B. Operating Reactors Branch 2 82/08/30 JONES, J.A. Carolina Pawer & Light Co. 2pp. 15577 275 24K Fiche 50-324, 82/08/30, 8210040006
- --8210040007 Revised Tech Specs to Amend 72 to License DPR-62 correcting errors in total peaking factor values for Cycle 5

 Operating Reactors Branch 2 82/08/30 ip 15577 277 24X
 Fiche 50-324,82/08/30,8210040006
- 8210120626 Advises that proposed interim changes for shift technical advisor training program acceptable up to Apr 1783 VASSALLO, D B Operating Reactors Branch 2 82/09/15 JONES, J A Carolina Power & Light Co 3pp 18672 266 24X Fichs 50-324, 82/09/15, 8210120626
- 8210280013 Responds to FDIA request for all internal non-public documents memos evaluation repts & other matl dealing w/ nuclear plant operations Forwards documents listed in App A FELTOW. J M Division of Rules and Records 82/09/17 MCINNIS.D News & Observer 5pp 15860 065 24X Fiche 50-000,82/09/17.
- --7905270357 Augmented offgas sys shall be used at all times & util should be informed COLLINS.J T Effluent Treatment Systems Branch 79/05/03 TPPOLITO.T A Operating Reactors Branch 3 (Pre 790525) 1p 15860 087 24X Fiche 50-000.82/09/17.8210280013
- --7912280014 Advises of util 791025 interim commitment for demonstrating compliance w/400FR190 Commitment acceptable.but must include direct radiation per section 6 of NUREO-0473.Revision 2 BANGART: Effluent Treatment Bystems Branch 79/11/23 IPPOLITOT Operating Reactors Branch 3 (Pre 800428) ip. 15860 088 24K Fishe 50-000.82/09/17.8210280013
- --B101140002 Confirms 801126 teleon re possible willful violation of reporting requirements IE lacks specific details necessary to make referral determination WARD, W J Office of Inspection & Enforcement, Office of the Director 80/12/02 FORTUNA: Office of Inspector & Auditor \$p\$ 15860 055 24% Fiche: \$0-000, 82/09/17, 8210280013
- --8104290774 Notifies that applicant should be informed that major change to raduaste treatment sys will require 10CFR50 90 review Requests info to show conformance w/App I & mod can meet acceptance criteria of SRP in NUREG-0800

 GAMMILLLW P Effluent Treatment Systems Branch 81/04/06 EPPOLITO.T A. Operating Reactors Branch 2. 1p. 15860-226 24X Fichs 50-000,82/09/17,8210280013
- --B1 12020885 Forwards request for add1 licensee info re proposed second expansion of spent fuel pool & estimate of vol of solid waste generated by scrapping existing racks Info needed by B1iliB

 KREGER.W E Assistant Director for Radiation Protection B1/10/27. NOVAK.T Assistant Director for Operating Reactors 2pp 15860 231 24X Fiche.50-000,82/09/17.8210280013
- -- 31 12300287 Forwards Effluent Treatment Sys Branch safety evaluation input re spent fuel pool expansion application.per review of util 800416 submittal KREOSR. W E Assistant Director for Radiation Protection 81/11/27. NOVAK. IT I Assistant Director for Operating Reactors. 13pp 15860 249 24% Fiche 50-000,82/09/17,8210280013
- --B2011202B0 Advises that Billi2 ltr recommended improvement of dose impact calculation methodology & licensee accepted by Bill25 ttr Other edit changes assured new methodology use every 31 days & nuclide dose factor inclusion in ETB.

 GAMMILL.W P Radiological Assessment Brench Bi/12/08 FPPOLITO: TA Operating Reactors Branch 2 ip. 15840 264 241 Fiche 50-000, 82/09/17, 8210280013

- --8203080197 Advises that replacing Phrase 12 "Consecutive Months" w/phrase "Galandar Yr" in Tech Bpec 2.5.2 b acceptable Change would reduce recordseeping HDUSTON, R W Assistant Director for Radiation Protection 82/02/11 NDVAK, T M Assistant Director for Operating Reactors 2pp 15861 014 24X Fiche 50-000,82/09/17,8210280013
- --8205170128 Advises that review of NUREO-0737, Item II F 1, has been satisfactorily completed & considered closed HQUSTON, R W Assistant Director for Radiation Protection 82/04/16 NOVAK, T M Assistant Director for Operating Reactors, ip 18861 040 24% Fiche 50-000, 82/09/17, 8210280013
- --8206220591 Submits background info on conversation w/util re 820116 loss of RHR syc water event at facility.LER 82-005/01T MOLF.T R Director's Office 82/06/04 RUBIN.9 Director's Office 5pp. 15861 326 24X Ficher 50-000.82/07/17,8210280013
- --9207120140 Trip rept of 820324 visit to facility re aquipment environ qualification problems List of site visit/meeting participants & related info encl EL-ZEFTANY.M., WOLF, T R Director's Office 82/07/04 MICHELBON.C Director's Office 12pp 15861-314 24X Fiche 50-000,82/09/17.8210280013
- --8210280021 Recommends that facility commands to conform w/STS
 EIBENHUT, D. G. Division of Operating Reactors 76/07/06.
 GOLLER, K. R. Assistant Director for Operating Reactor Projects (Pre 771030). 3pp 15960-074 24X Fiche 50-000,82/07/17.8210280013
- --8210280024 Advises that util 780518 response re proposed plans for correcting problems concerning augmented offgas sys unacceptable Effluent Tech Specs should be amended COLLING.J Y Effluent Treatment Systems Branch 78/06/02 LEAR.G Operating Reactors Branch 78/06/02 Operating Reactors Branch 78/06/02 15960 077 24X Fiche 50-000.82/09/17.8210280013
- ---8210280027 Notifies that commitment schedule for implementing operable augmented offgas sys unacceptable Thermal recombiners for use in EWR offgas sys will not satisfy criteria COLLINS.J T Effluent Treatment Systems Branch. 78/09/06 IPPOLITO.T Operating Reactors Branch 3 (Pre 800428) 3pp 15860 079 24X Fichs 50-000, 82/09/17,8210280013.
- ---8210280031 Requests technical assistance to review recent events at facilities & to assess safety & environ significance STELLO, V Division of Operating Reactors, 78/08/03 MULLER, D Division of Site Safety & Environmental Analysis 2pp. 15860.084 24X Fiche 50-000.82/09/17,8210280013
- ---8210280047 Notifies that potential for criminality found re Region 4 investigation resulting from W Ward 801202 memo congrning facility FORTUNA:R A Office of Inspector & Auditor 80/12/03. Office of Inspector & Auditor 80/12/03. Office 82/09/17.8210280013
- --8210280095 Assumes responsibility for review of Case 81-17 for criminality No criminality indicated Case should be closed.

 BMITH, R M Office of Inspector & Auditor, 82/08/24 Office of Inspector & Auditor, 82/08/24 Office of September 1986 Office 09 Offi
- --8210280100 Notifies that on 820224,C Alderson advised that rept sent repossible willful violation of reporting requirements & falsification of GA & guard qualification records at facilities

 RESNER,M E Office of Inspector & Auditor 82/03/01 Office of Inspector & Auditor. 1p 15861 039. 24X Fiche, 50-000, 82/09/17, 8210280013.
- 8210010051 Ack receipt of 820823 itr requesting temporary relief from commitments re training of shift technical advisors. Program approved & request forwarded to NRR for evaluation O'REILLY, J.P. Region 2, Office of Director 82/09/20 JONES, J. A Carolina Power & Light Co. 1p 15565:322, 24x Fiche 50-000, 82/09/20, 8210010051
- 8210050362 Application to amend Licenses DPR-71 & DPR-62, revising Tech Specs to clarify requirements for verifying operability of scram discharge vol vent & drain valves. Class I & II license amend fees encl EURY, L W Garoline Fower & Light Co 82/09/29, VASBALLD, D B Operating Reactors Branch 2 2pp 15608:345 24X Fiche:50-384,82/09/29,8210050362
- --B21005037i Prposed Tech Spec 4, i. 3, i. i re surveillance requirements verifying operability of scram discharge vol vent & drain valves.

 « Caroline Power & Light Co 82/09/29 2pp 15608,047 24x Fiche: 50-324,82/09/29,8210050362.

- 8210270110 Advises that plant venting capability acceptable to resolve RMREO-0737. THI Item II B 1 re high point vents VASSALLO,D B Operating Reactors Branch 2 82/10/01 JONES.J A Carolina Power & Light Co 3pp 15866 338 24X Fiche 50-324,82/10/01,8210270110
- --8210290113 "Operating Reactors TMI Lessons Learned, NUREC-0737 Response Evaluations (Program II):Project 1,RCS Vents for Brunswick 1 & 2," final technical evaluation rept Laurence Livermore Laboratory FIN A-0246-2 82/07/15 BUTCHER.E., BARNIART.B Division of Licensing 4pp 15866 341 24X Fiche 50-324,82/10/01.8210290110
- 8210150030 Forwards submittal schedule for responses to NRC 820909 issues re THI Action Items II F 1.4.5 & & & II E 4 2 7. Tach Spac revisions, containment vent & purge, electrical distribution sys voltages & control of heavy loads ZIMMERMAN, 8, R Carolina Power & Light Co 82/10/12 VASSALLO, D 3 Gperating Reactors Branch 2 2pp 15701-268 24X Fiche 50-324, 62/10/12, 6210150030
- 8210260244 Advises that response to NRC 820827 request to justify differences between existing control room & NURED-0737. Item III D 3 4 suggestions will be provided by 830131. Requests re-evaluation of improvement cost-benefits SURY.L N Caroline Fouer & Light Co 82/10/21 VASSALLO.D B Operating Reactors Branch 2 1p 15799 353 24X Fiche 50-324.82/10/21,8210260244
- 82(0260323 Application for amend to Licenses DPR-71 & DPR-62.clarifying portions of 810321 submittal re hydraulic snubber surveillance EURY.L W Garolina Power & Light Co 82/10/21 VASSALLO.D B Operating Reactors Branch 2 2pp 15799 338 24X Fiche 50-324.82/10/21.8210260323
- --8210260325 Revised Tech Specs re hydraulic snubber survaillance + Carolina Power & Light Co 82/10/21 2pp 15799 340. 24) Fiche 50-324,82/10/21.8210260323
- 8210260405 Hithdraws request for amend to Licenses DPR-71 & DPR-62, revising Tech Spec re reportability of inoperable reed switches in rod position indication syst to reduce number of routine LERs EURY-L W Carolina Power & Light Co 82/10/22 VASSALLO.D B Operating Reactors Branch 2 2pp. 15806-239, 24X Fiche 30-324, 82/10/22,8210260405
- ~-8210260410 Proposed revisions to Tech Spec & 9 i re monthly reportability of safety/relief valve challenges. Tech Spec supersedes 820407 submittal.

 * Carolina Power & Light Co. 82/10/22 2pp. 15806 241 24X Fiche. 80-324,82/10/22,8210260405
- Q Inspection reports: IE Bulletins & correspondence
- 8210080015 Addl response to FOIA request for 17 categories of info re nuclear reactor syents & sefety problems Forwards documents listed in App A Bocuments in App B completely withheld (ref FDIA Exemption 5) FELTON.J M Division of Rules and Records. 82/07/12 UDELL.R A Critical Mass Energy Project 9pp. 15665.027 24X Fiche 50-000.82/07/12.8210080015
- --B210080122 Bystematic assessment of licensee performance notes refacility evaluation for Apr 1979-Har 1980.

 NRC No Detailed Affiliation Given 80/03/31 Apr 15667 321 24K Fiche 50-000, 82/07/12, 8210080015.
- 8210010132 Forwards IE Insp Repts 30-324/62-31 & 50-325/82-29 on 820809-13 No noncompliance noted VERRELLI.D.H Division of Project & Resident Programs 82/09/01, JONES, J A Carolina Power & Light Co. 2pp 15567:230, 24X Fiche: 50-324, 82/09/01,8210010132
- --B210010137 IE Insp Repts 50-324/B2-31 & 50-325/B2-29 on B20B09-13 No noncompliance noted. Major areas inspected ALARA, radigactive mat1 transportations radioactive liquid effluent monitoring & nat1 control ALBRIOHT, R. H., BARR, K. P. Division of Engineering & Yechnical Programs 82/08/31 5pp. 15567 232. 24% Fiche: 50-324, 82/09/01, 8210010132
- B210010112 Forwards summary of B20824 enforcement meeting at Region 2 ofc re status of action items contained in B20702 & 20 confirmation of action itrs
 O'REILLY, J. P. Region 2, Office of Director. B2/09/03 JONES, J.A.
 Carolina Power & Light Co. 1p. 13566-029 24X
 Fiche 50-324.82/09/03,8210010112

- --8210010126 Summary of 820824 meeting w/util in Atlante, GA re status of action items contained in 820702 & 20 confirmation of action ltrs Util committed to formally submit long-term program details in Nov 1982

 LEMIS.R C Division of Project & Resident Programs 82/09/03

 Division of Project & Resident Programs 2pp 13566 030 24%

 Fiche 50-324,82/09/03.8210010112
- 8210010170 Ack receipt of 820816 response to 820716 notice of violation of civil penalties Rept on major program objectives to be submitted by 821101 should provide sufficient info re testing aspects of training programs AXELRAD. J Enforcement 8taff 82/09/15 JONES. J A Carolina fc. 17 & Light Co 2pp 15568 109 24X Fiche 50-328.82/09/15,8210410172
- --8210010193 Forwards IE Insp Repts 50-324/82-02 & 50-325/82-02 en 820106-07. Enforcement action addressed to util (n 820715 ltr LEWIS.R C Division of Project & Resident Programs 82/07/16 JONES, J A Carolina Power & Light Co 2pp 15568 124 24K Fiche 50-325, 82/09/15, 8210010170
- 8210010171 Ack receipt of B20702 & 0903 ltrs informing NRC of strys taken to correct violations noted in IE Insp Repts 50-0324/82-18 & 50-0325/82-18 VERRELLI, D M Division of Project & Resident Programs 82/09/16 JONES, J A Carolina Power & Light Co 1p 15568 091 24X Fiche 50-324, 82/09/16.8210010171
- --8210010183 Suppls 920702 response to NRC 820604 itr re violations rin IE Insp Repts 50-324/82-18 & 50-325/82-18 Corrective actions responsible operators counseled & 1A-1 bettsry charger clearance removal reviewed DIETZ.C R Carolina Power & Light Co 82/09/03 G'REILLY.J F Region 2. Office of Director. 3pp 15568 092 24X Fichs 50-324,82/09/16/8210010171
- --8210010188 Responds to NRC 820604 ltr re violations noted in IE 1/1; Repts 50-324/82-18 & 50-325/82-18 Corrective actions double verification program established on 820601 DIETZ, C.R. Carolina Power & Light Co. 82/07/02 O'REILLY, J.F. Region 2, Office of Director 2pp. 15568 095 24X Fiche 50-324,82/09/16,8210010171
- --B210010194 Forwards IE Insp Repts 50-324/82-18 & 50-325/82-18 en 820415-0515 & notice of violation LDMG-F.J Division of Project & Resident Programs 82/05/04-UDMES,J A. Carolina Power & Light Co 2pp 15568 097 241 Fiche
- ---8210010199 Notice of violation from insp on 820415-0515 * Region 2, Office of Director 82/06/04 ip 15588 099 241 Fiche 50-324,82/09/16,8210010171
- --8210010205 IE Insp Repts 50-324/82-18 & 50-325/82-18 on 920415-05.3 Noncompliance noted Operating Procedure DP-43 & tag readysl for Clearance 1-457 inadequately implemented MYERB, D. Q., QARNER, L. W., BURGER, C. W. Division of Project & Resident Programs 82/06/04, 9pp 15368 100 24X Fiche, 50-324, 82/09/16, 8210010171
- 8210010336 Advises that IE Insp Rept 50-325/82-36 was inedvariable labeled 50-325/82-30 VERBELLI, D.M. Division of Project & Resident Programs 82/09/16 JONES, J.A. Canoline Power & Light Co. ip 15571 001 241 Fichs: 50-324, 82/09/16, 8210010336
- --8210010340 Forwards IE Insp Repts 50-324/82-32 & 50-325/82-36 Pa 820824-27. No nencompliance noted VERRELLII.D. M Division of Project & Resident Progress 62/09/.3 JONES, J. A. Caroline Power & Light Co. 2pp 15578 002 247 Fiche: 50-324/82/09/16/8210010336
- --8210010350 IE Insp Repts 50-324/82-32 & 50-325/82-36 on \$20824 27 k noncompliance noted. Major areas inspected, pre-startup reviews, comporate nuclear safety reviews, post-maint testing & plant mods involving Tech Bacc changes FREDRICKSON,P., JACKSON,L.H., UPRIGHT,C.H. Division of Engineer & Technical Programs. 82/09/10 4pp 15571 004 24X Fiche: 50-324,82/09/16,8210010336

- 8210010391 Ack receipt of 820907 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-324/82-25 & 50-325/82-25
 - LEMIS.R C Division of Project & Resident Programs 82/09/2 JONES J A Carolina Power & Light Co ip 15572 269 24X Fiche 50-324.82/09/22.8210010391 82/09/22
- --B210010399 Responds to NRC B20813 ltr re violations noted in IE Insp. Repts 50-324/82-25 & 50-325/82-25 Corrective actions plant operating procedures rewritten & signoffs added Operations engineer responsible for procedure changes
 DIETZ.C.R. Carolina Power & Light Co. 82/09/07 O'REILLY, J.P. Region 2. Office of Director 2pp 15572 270 24X
 Fische 50-324,82/09/22,8210010391
- --B210010405 Forwards IE Insp Repts 50-324/82-25 & 50-325/82-25 on B20615-0715 & notice of violation LEWIS.R C Division of Project & Resident Programs 82/08/13 JONES J A Carolina Power & Light Co 2pp 15572 272 24X Fiche 50-324,82/09/22,8210010391
- --8210010410 Notice of violation from insp on 820615-0715 * Division of Project & Resident Programs 82/08/13 2pp 15572 274 24X Fiche 50-324,82/09/22,8210010391
- --B210010415 IE Insp Repts 50-324/82-25 & 50-325/82-25 on B20618-0715 Noncompliance noted failure to implement & maintain operating procedures for startup & shutdown HYERS.D Q. GARNER.L W., STETKA.T Division of Project & Resident Programs 82/08/12 13pp 15572 276 24X Fiche 50-324.82/09/22, 8210010391
- 32:0150100 Ack receipt of 820913 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-324/82-26 & EOFFECT VIOLATIONS NOTED IN IC 1809 NEWS STATES SO-325/82-26

 LEHIS R C Division of Project & Resident Programs 82/09/24

 JONES J A Carolina Power & Light Co ip 15701 164 24X

 Fiche 50-324.82/09/24.8210150100
- -8210150106 Responds to NRC 820817 ltr re violations noted in IE linsp Repts 50-324/82-26 & 50-325/82-26 Corrective actions new comprehensive post-testing program being developed DIETZC R Carolina Power & Light Co 82/09/13 O'REILLY, J P Region 2, Office of Director 2pp 15701 165 24X Fiche 50-324,82/09/24,8210150100
- -8210150113 Forwards IE Insp Repts 50-324/82-26 & 50-325/82-26 on RIO1501t3 Forwards IE insp Nepts OU-GRIVE AD GOVERNMENT BEROPHICAL BEROPH BEROP 82/08/17
- -8210150120 Notice of violation from insp on 820712-16 + Division of Project & Resident Programs 82/08/ 15701 169 24X Fiche 50-324,82/09/24,8210150100 82/08/17 20p
- -8210150132 IE Insp Repts 50-324/82-26 & 50-325/82-26 on 820712-16. Noncompliance noted failure to provide measures to preclude bypassing required testing EXINNER: PH. JACKSON.L H., UPRIGHT.C M. Division of Engineering & Technical Programs 82/08/19 7pp 15701:171 24X Fiche 50-324,82/09/24,8210150100
- 210150108 Forwards IE Insp Repts 50-324/82-35 & 50-325/82-35 on B20908-10 No noncompliance noted VERRELLI,D M Division of Project & Resident Programs 82/09/24 JGNES,J A Carolina Power & Light Co 2pp 15701 149 24X Fiche 50-324,82/09/24,8210150108
- -8210150114 IE Insp Repts 50-324/82-35 & 50-325/82-35 on 820908-10 No noncompliance noted Major areas inspected review & evaluation of changes to inservice insp program & program for document control & data retention COLEY.J L., BLAKE.J J Division of Engineering & Technical Programs 82/09/21 3pp 15701 151 24X Fiche 50-324,82/09/24,82(0150108
- 210150162 Forwards IE Insp Repts 50-324/82-33 & 50-325/82-31 on B20901-03 & 10 No noncompliance noted VERRELLI,D M Division of Project & Resident Programs B2/09/24 JONES,J A Carolina Power & Light Co 2pp 15707-304 24X Fiche 50-324,82/09/24,8210150162
- -8210150170 IE Insp Repts 30-324/82-33 & 50-325/82-31 on 820901-03 & 10. No noncompilance noted Major areas inspected IE Bulletin 79-14. "Setsmic Analysis for As-Built Safety-Related Piping Bys "
 ANO. W P , BLAKE, J Division of Engineering & Technical Programs
 82/09/23 5pp 15707 306 24% Fiche. 50-324, 82/09/24, 8210150162

- 8210150008 Ack raceipt of 820819 & 0915 ltrs informing NRC of steps taken to correct violations noted in IE Insp Repts 30-324/82-23 & 30-325/82-23 LEMISI.R.C Division of Project & Resident Programs 82/09/30 JONES. J A. Carolina Power & Light Co 1p 15698 349 24X Fiche 50-324.82/09/30.8210150008
- --8210150016 Revises response to NRC ltr re violations noted in IE Insp. Repts 50-324/82-23 & 50-325/82-23 Corrective actions assessment of inservice insp. program in progress Violation will be fully addressed by 821231
 DIETZ.C R Carolina Power & Light Co 82/09/15 D'REILLY.J P. Region 2. Office of Director 2pp 15698 350 24X
 Fiche 50-324, 82/09/30, 8210150008
- --92i0150023 Responds to NRC 920719 ltr re violations noted in 1E Insp Repts 50-324/82-23 & 50-325/82-23 Corrective actions post-maint testing program revised & inservice insp program Under review
 DIETZ,C R Carolina Power & Light Co 82/08/19 D'REILLY, J P
 Region 2. Dffice of Director 3pp 15678 352 24X
 Fiche 50-324,82/09/30,8210150008
- --8210150034 Forwards IE Insp Repts 50-324/82-23 & 50-325/82-23 on 820415-18 & notice of violation LEWIS.R C Division of Project & Resident Programs 82/07/19 JONES:J A Carolina Power & Light Co 2pp 15498.355 24X Fiche 50-324,82/09/30,8210150008
- --8210130040 Notice of violation from insp on 820615-18 LEHIB.R.C Division of Project & Resident Programs (2pp. 15698 357 24% Fiche 50-324.82/09/30.821015008 82/07/19
- --6210150063 IE Imap Repts 50-324/82-23 & 50-325/82-23 on 820615-18 Noncompliance noted failure to re-establish baseline data for RHR svc water pump & to include main steam giping in inservice insp program BLAKE, J. J. ECONOMOS, N Division of Engineering & Technical Programs 82/07/15 4pp 15698 359 24X Fiche 50-324, 82/07/30, 8210150008
- 8210220139 Forwards IE Insp Repts 50-324/82-38 & 50-325/82-38 un #20907-10 No noncompliance noted.

 VERRELLI, D.M. Division of Project & Resident Programs 82/10/04

 JONES, J.A. Carolina Power & Light Co. 2pp 15778 107 24X

 Fiche: 50-324, 82/10/04, 8210220139.
- --8210220147 IE Insp Repts 50-324/82-38 & 50-325/82-38 on 820707-10 No nancompliance noted Major areas inspected followey insp of NRC & license identified tasks to be completed prior to HATTENER, H L , KRUO, H E , JAPE, F Division of Engineering & Technical Programs 82/09/30 Spp 15778 109 24X Fiche 50-324,82/10/04.8210220139
- 8210220169 Forwards IE Insp Repts 50-324/82-36 & 50-325/82-33 on 820815-0915 No noncompliance noted VERRELLI, DM Division of Project & Resident Programs 82/10/04 JONES, J A Carolina Power & Light Co. 2pp 15778.045, 24X Fiche 50-324,82/10/04.8210220169
- --8210220173 IE Insp Repts 50-324/82-36 & 50-325/82-33 on 820815-0915 No noncompliance noted Major areas inspected review of LERs, operational safety verification & audit of surveillance & maint activities.

 HYERB, D 0 : OARNER, L W : BURGER, C : Division of Project & Resident Programs : 82/10/01 Spg. 15778 047 24X Fiche: 50-324,82/10/04,8210220169
- 8210130036 Ack receipt of 820816 & 0924 ltrs informing NRC of steps taken to correct violations noted in IE insp Repts 50-324/82-20. & 50-325/82-20. LEWIS.R C. Division of Project & Resident Programs. 82/10/05. JONES.J.A. Carolina Power & Light Co. 1p 15701:135 24X Fiche.50-324.82/10/05.8210150036.
- --921015003B Supple 820816 response to NRC 820719 ltm re violations noted in IE Insp Repts 50-324/82-20 & 50-325/82-20 Add1 info re revision to Procedure GGAB 80-1 to assure timely corrective actions to future audit findings provided.

 DIETZ, C. R. Carolina Power & Light Co. 82/09/24 O'REILLY, J. P. Region 2, Office of Director. 2pp 15701-136. 24X Fiche 50-324,82/10/05,8210150036
- --8210150045 Responds to NRC 820719 ltr re violations noted in IE Insp. Repts 50-324/82-20 & 50-325/82-20 Corrective actions. Frocedure COAD 80-1 revises & frequency of plant audits increased to reduce audit scope. DIETZ, C.R. Carolina Power & Light Co. 82/08/16. D/REILLY, J.P. Region 2: Office of Director Spp 13701, 138 24X Fiche, 50-324, 82/10/05, 8210180036

- -8210150052 IE Insp Repts 50-324/82-20 4 50-325/82-20 on 820407-08 Noncompliance metal failure to establish measures to assure groungt corrections to adverse GA conditions & failure to distribute audit within required timeframs BELISLE, GA, UPRIGHT, CH Division of Engineering & Technical Programs 82/07/15 4pp 15701 149 24X Fache 50-324,82/10/05,8210150036
- 8210150288 Ack receipt of 820914 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-324/62-21 & 50-324/62-21 & 50-324/62-21 & 50-324/62-21 & 50-324/62-21 & 50-324/62-21 & 50-324/62-21 & 50-324/62-210/05/8210150288
- --8210150295 Responde to NRC 820818 itr re violations noted in IE Insp Repts 30-324/82-2t & 50-325/82-2t Corrective actions relief valves which can communicate w/primary containment added to Type C testing program in review of leakage continuing DIETZ-C R Carplina Power & Light Co B2/09/14 J'REFLLY, J P Region 2, Office of Director 2pp 15706 127 24% Fichs 50-324.82/10/05,8210150288
- B20B190233 IE Info Notice 80-35. Suppl 1, "Leaking & Dislodged I~125 Implant Seeds " Bvc list and COBB.L I Division of Fuel Facilities. Materials & Sefeguards 82/10/06 Consolidated Edison Co of New York 66pp 15761 250 24% Fich 80-000.82/10/04,820B190233
- 820Bi9023B IE Bulletin 82-03, "Stress Corrosion Cracking in Thick-Wall, Large-Diameter: Stainless Steel. Recirculation Bys Piping at BWR Plants" Svc list encl DEYDUNG.R C Director's Office. Office of Inspection and Enforcement B2/10/14 Canacillated Edison Co of New York 1158p 15810 125 24X Fiche 50-000, 82/10/14:8208190338
- 8210220489 Ack receipt of 821006 ltr informing NRC of steps taken to correct violations noted in LE Insp.Repts 50-324/82-30 to 50-325/82-30 VERBELLI, D.M. Division of Project & Resident Programs 82/10/18 UTLEV.6 E. Carolina Power to Light Co. (p. 15779-087 24X Fichs 50-324,82/10/18,8210220489
- --8210220492 Responds to NRC 820907 ltr re violations noted in IE Insp. Repts 50-324/82-30 & 50-325/82-30 Corrective actions technician counseled re compliance w/Maint instruction ffil-0-2J fire Protection Procedure FP-14 will be revised DIETZ.C R Carolina Power & Light Co. 82/10/06 g/PEILLY.J P. Region 2. Office of Director 2pp 15777 098 24% Fichs 50-324,82/10/18,6210220489
- ~-8210220494 Forwards IE Insp Repte 50-324/82-30 & 50-325/82-30 on 820715-0815 & notice of violation VERRELLI,D M Division of Project & Resident Programs 82/09/07. JONES:J. A Carolina Power & Light Co 2pp 15779 090 24X Fiche 50-324,82/10/18,8210220489
- --8210220496 Notice of violation from insp on 820715-0815 * Division of Project & Resident Programs, 82/09/07 1 15779,092 24X Fiche; 50-324,82/10/18,8210220489
- --8210220503 IE Insp Repts 50-324/82-30 & 50-325/82-30 on 820715-0815 Noncomptionee notes: on 820805, safety-related equipment Haint Instruction KI 19-2J incorrectly performed & Fire Protection Procedure FP-14 Step III A improperly implemented on 820718 MYERS.D U , GARNER.L.N , CHASE.J. Division of Project & Resident Programs 82/09/03 9pp 15779 093. 24X Fiche 50-324,82/10/18,8210220489
- 8 Reportable occurrences, LERs & related correspondence

1

K.

1)

- 8210150291 Forwards LER 81-016/03L-0, DIETZ.G.R Carolina Power & Light Co 81/02/27 HAYNES, J.P. Region 2. Atlanta, Office of the Director (81/03/01) ip, 13706,129. 24% Fiche: 30-324.81/02/27.8210130291.
- --B210150308 LER B1-016/03L-0; on B10207, primary containment atmospheric cause and analyzer indicated upscale Caused by deterioration of inlet robber bubing due to aga, allowing ambient air to enter & six w/analyzer sample flow PABTVA.M.J. Carolina Power & Light Co. B1/02/27. Region 2, Atlants, Office of the Biretter (81/03/01) 2pp 15706-130. 24% Fiche 50-324,81/02/27,8210150271.

- B210150041 Forwards LER 81-032/03L-0
 DIETZ.C & Garolina Power & Light Co B1/03/25 D'REILLY, J P
 Region 2. Atlanta, Office of the Director (81/03/01) 3p
 L5701 132 24X Fiche 50-324.81/03/25,821015004
- --B210150046 LER 81-032/03L-0 on 810223, while performing requires in as result of diesel generator 2 being out of ever for maint diesel generator 3 declared inoperable due to low control air pressure Caused by misaligned valve diese PARTWARM U Carolina Power & Light Co 81/03/25 Regist 2 Atlanta. Office of the Director (81/03/01) 2pp 13701 133 Resistants Office 50-324,81/03/25,8210150041
- RZ10070416 Trip rapt of B10617 site visit to collect info ## loss ## RHR Daffie plate dividing water box of RHR HX IA Failed allowing swc water to bypass HX tubes Caused by ### repaired differential pressure across baffle plate.

 IMBRO.E., OIANELLI, J Director's Office B1/07/22 Director's Office B1/07/22, B216070418 :
- 8210070442 Discusses 810714 dissel generator trip caused by operator of temp control manual bypass valve LgR did not control manual bypass valve LgR did not contain sufficient info Further action recommended CHIRAMAL. H Director's Office 81/12/07. MICHELSON. C Direct. Office 1p 15637-345 24X Fiche 50-324, 81/12/07,8210070442
- 821001000B Responds to FDIA request for 19 categories of dotuments in nuclear reactor events & safety problems Forwards documents listed in App A FELTON. J H Division of Rules and Records B2/06/20 UEEL.F4 Critical Mass Energy Project 15pp 15727 005 24x Fiche 90-000.82/06/28.8210010008
- --810730016B Discusses findings gathered during 810617 sale wises of facility loss of RHR capability during Apr & May 1981 Util has committed to mod of wash screen wash sus by 1982 Attendance Ifst chlorinator outage info & drawings entl IMDRO.E Director's Office 81/07/22 Director's Office 1970 15730 056 24% Fiche 50-000.82/06/28,8210010908
- 8209150164 "Brunswick Nuclear Power Station Unit 2 Loss of RHR 5.1 Water on 820116 Engineering Evaluation Rept " WOLF TR Reactor Operations Analysis Branch 82/08/31 1739 15511 263 24% Fiche 50-324,82/08/31,8209150164
- 821001017D Ack receipt of 820816 response to 820716 notice of vij';
 & groposed imposition of civil penalties Rept on major
 program objectives to be submitted by 821101 should provide
 sufficient info re testing aspects of training programs
 AXELRAD, J Enforcement Staff 82/09/15 JONES J A Cyraling to
 & Light Go 2pp 15568 109 24X Fiche 50-325,82/09/15,8210; T
- --B210010205 IE Insp Repts 50-324/B2-02 & 50-325/B2-02 on B20105: Nancompliance noted Unit 1 instrument D-1 inoperable & Isval channel not tripped between 611226-31 GARNERIL , JULIAN.C. BURGER.C Division of Project & Resumance Programs 82/05/13. App 15568 126 24K Fiche 50-325.82%
- 8210010298 Forwards updated LER 82-083/03L-1.
 DIETZI C R Carolina Power & Light Co 82/09/21 O'REFLLY.JF
 Region 2. Office of Director ip 15568;325, 24%
 Fiche. 50-324,82/09/21,821001029
- --8210010303 Updated LER 82-083/03L-1 on 820715, performants of N % revealed that drywell to torus vacuum breakers X18A,C & E were leaking excessively, caused by accomulation of dirk, scale & silicone base sealant on valve stating surfaces PABTVA:N J Carolina Power & Light Co 82/09/21 Regist Defice of Director, ip 15368-326 24X Fiche 30-328,82007-8210010298
- 8210010473 Forwards LER 82-107/03L-0 DIETZ: C R. Carolina Power & Light Co 82/09/24, G'REILLY.Jf Region 2: Office of Director 1p 15572:170 24X Fiche 50-324:82/09/24,821001043
- --B210010475 LER 82-107/03L-0. on B20826/review of fire protection dioxide sys surveillance procedures indicated storage sittle weighing device had not undergone periodic calibr Cavest by failure to recognize accuracy restraint needs. PABTVA:M.J. Carolina Power & Light Co. B2/09/24 Regist?, Office of Director. 1p. 15572 171, 24X Fiche 50-324,82/877 8210010473

- 8210060320 Forwards updated LER 82-107/03L-1 DIET7.C R Capplina Power & Light Co 82/07/29 O'REILLY, J P Region 2. Office of Director ip 15619 015 24X Fiche 50-324,82/09/29,8210060320
- --8210060327 Updated LER 82-107/03L-1 on 820826, review of fire protection carbon dioxide sys surveillance procedures indicated storage bottle weighing device did not have periodic calibr Caused by failure to recognize need for accuracy restraints.

 PASTVA:N J Carolina Power & Light Co 82/09/29 Region 2, Office of Director 1p 15619 016 24X Fiche 50-324, 82/09/29, 8210060320
- 8210080221 Forwards LER 82-095/03L-0 DIETZ.C R Carolina Power & Light Co 82/09/29 O'REILLY.J P Region 2, Office of Director in 15638 047 24X Fiche 50-324,62/09/29,8210080221
- --8210080230 LER 82-095/03L-0 on 820903, discovered that most recent ILRT exceeded specified testing interval Caused by improper scheduling Scheduling program revised to reflect correct scheduling criteria PASTVA:M J Carolina Power & Light Co 82/09/29 Region 2, Office of Director ip 15638 048, 24X Fiche 50-324,82/09/29, 8210080221
- B210190754 Forwards LER 82-106/03L-0 Detailed event analysis encl D1ETZ.C R Carolina Power & Light Co B2/10/08 O'REILLY.J P Region 2. Office of Director 2pp 15737 097 24X Fiche 50-324, B2/10/08, B210190754
- --8210190762 LER 82-106/03L-0 on 820917, while reviewing surveillance procedures, determined that emergency bus degraded voltage channel function test not sufficient to verify operability of emergency bus degraded voltage relays Test revised PASTVA.M J Carolina Power & Light Co 82/10/08 Region 2, Office of Director ip 15737 099 24X Fiche 50-324,82/10/08.
- 82:0190300 PND-II-82-109 on 82:010, steam & water leak of 20 to 40 gallons per minute found in cracked weld of honsafety-related heater drain pipe Plant shut down 80s 2-D could not be manually transferred from generator to transformer HEHL-C W . BURGER.C W Region 2. Office of Director 82/10/12 2pp 15742 159 24X Fiche 50-324,82/10/12,82:10190300
- 8210190659 PND-II-82-110 on 821010 relief valve failed to reclose after testing u/reactor critical Reactor manually scrammed & unusual event declared Caused by failure of actuation solenoid Unit in cold shutdown during repairs.

 HEPL.C W . BURGER.C W Region 2. Office of Director. 82/10/12 ip 15737 146 24% Fiche 50-324,82/10/12,8210190459
- 8210260269 Forwards corrected LER 82-108/02L-0
 DIETZ.C R Carplina Power & Light Co 82/10/14 O'REILLY, J. P
 Regison 2. Office of Director ip 15803 226 24X
 Fiche 50-324.82/10/14.8210260269
- --B21026031B Corrected LER 82-108/03L-0 on B20921 discovered fire house station RW-49 inoperable due to disconnected hose Cause unknown Hose reconnected Retraining programs will be revised to stress correct use of fire fighting equipment PASTVA.M J Carolina Power & Light Co B2/10/14 Region 2. Office of Director 2pp 15803 227 24% Fiche 50-324.82/10/14. B210260269
- 8210190748 Forwards LER 82-108/03L-0 DIETZ.C R Carolina Power & Light Co 82/10/15 D'REILLY, J. P Region 2. Office of Director Ip 15737, 083. 24X Fiche 50-324, 82/10/15, 8210190748
- --E210190759 LER 82-108/03L-0 on 820921, fire hose station RW-49 inoperable due to disconnected fire hose Cause not stated Hose reconnected Employees instructed re use of fire fighting equipment for nonemergency use PASTVA: M J. Carolina Power & Light Co 82/10/15 Region 2, Office of Director ip 15737 084 24X Fiche 50-324,82/10/15,8210190788.
- 9210250205 Interim Part 21 rept Detailed status of corrective actions taken will be sent by 821020
 SARSTEN.0 E United Engineers & Constructors: Inc. (subs of Raythson Co) 82/10/15 Director's Diffice, Office of Inspection and Enforcement ip 15797 151 24X Fiche 50-324,82/10/15,8210260205
- 3210290336 Fr Wards updated LER 82-018/03L-2
 DIETZ.C R Carolina Fower & Light Co 82/10/15 O'REILLY.J.P
 Region 2, Office of Director ip 15853 053, 24x
 Fiche 50-324,82/10/15,8210290336

- --8210270342 Updated LER 82-018/03L-2 on 820120, drywell floor drain flow integrator 1-016-FG-K601 continuously indicated swmp flow w/no pumps running Caused by integrator square root converter & flow transmitter out of calibr PASTVA.M J Carolina Power & Light Co 82/10/15 Region 2, Office of Director 2pp 15853 054 24X Fiche 50-324,82/10/15, 8210270336
- 8210290243 Forwards LER 82-112/03L-0 DIETZ. C R Carolina Power & Light Co 82/10/21 O'REILLY, J P Region 2, Office of Director ip 15853 120, 24X Ficha 50-324, 82/10/21, 8210290243
- --B210270246 LER B2-112/03L-O on B20929, suppression chamber water temprecorder 2-CAC-TR-778 discovered intermittently recording temps on chart recorder Caused by out of adjustment recorder print actuation solenoid Solenoid adjusted.

 PASTVA.H J Carolina Power & Light Co 82/10/21, Region 2, Office of Director ip 15853 121 24X Fiche 50-324,82/10/21, B210290243
- 8210290079 Forwards LER 82~113/03L-0 DIETZ-C R, Carolina Power & Light Co 82/10/22 O'REILLY, J P Region 2. Office of Director 1p 15854:012 24X Fiche-50-324, 82/10/22,0210290079
- --8210270097 LER 82-113/03L-0 on 821003, during reactor startup coolant analysis, reactor coulant conductivity exceeded Tech Specs Caused by breakdown of reactor water cleanup sys resins Resins allowed to decompose & reactor conductivity reduced PASTVA: H J Caroline Power & Light Co 82/10/22 Region 2, Office of Director Rap 15854 013 24X Fiche 50-324; 82/10/22, 8210290079
- DOCKET 50-325 BRUNSWICK STEAM ELECTRIC PLANT, UNIT 1

 F Security, medical, emergency & fire protection plans
- 820914014B Forwards "Fire Protection of Cable Byreading Room," evaluating quantity of transient combustibles necessary to cause ignition of most limiting cable info suppls 610304 exemption request HOME.P W Carolina Power & Light Co 82/09/08, DENTON, H R Office of Nuclear Reactor Regulation, Director, 2pp 14782,001 24X Fiche: 50-324,82/09/08,8209:40148
- --8209140153 "Fire Protection of Cable Spreading Room" * Caroline Power & Light Co 82/08/31. 61p 14782 004. 24X Fiche: 50-324,82/09/08.8209140148
- 8210040316 Forwards revised Sections 5 & 6 to "Bafe-Bhutdown Capability Assessment & Proposed Mods" ZIMMERMAN. B R Caroline Power & Light Co 82/10/01 DENTON, H R Office of Nuclear Reactor Regulation: Director. 1p. 13616:033 2/4X Fiche 50-324, 82/10/01, 8210060316
- --8210060323 Revised Sections 5 & 6 to "Safe-Shutdown Capability Assessment & Proposed Mode" " Carolina Power & Light Co 82/10/01 706pp 15616:034 24x Fiche:50-324,82/10/01:8210060316.
- 8210130295 Forwards responses to BNHL & NRC Questions in 6 ms util 820804 radiation shielding study for proposed emergency operations facility/technical support ctr Written concurrence requested by 821025
 ZINMERNANISR Carolina Power & Light Co 82/10/11 VABBALLO, D IS Operating Reactors Branch 2 3pp. 15678 240 24X
 Fiche. 50-324, 82/10/11, 8210130275
- 8210220489 Ack receipt of 821006 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-024/82-30 & 50-024/82-30 & VERRELLI, D M Division of Project & Resident Programs UTLEV.E E Caroline Power & Light Co. lp. 15779 087. 24X Fiche, 50-024, 82/10/18, 9210220487
- --8210220492 Responds to NRC 820907 ltr re violations noted in IE Insp. Repts 50-324/82-30 & 50-325/82-30. Corrective actions. technician counseled re compliance w/Maint Instruction Mi-10-2V Fire Protection Procedure FP-14 will be revised DIETZ, C.R. Caroline Power & Light Co 82/10/06 O'REILLY, J. P. Region 2, Office of Director 2pp 15779 088, 24X Fiche 50-324, 82/10/18, 8210220489
- --8210220496 Notice of violation from insp on 820715-0815. * Division of Project & Resident Programs. 82/09/07. 1p 15779.092. 24X Fiche.50-324.82/10/18.8210220489.

- --8210220503 IE Inep Repts 50-324/82-30 & 50-325/82-30 on 820715-0815
 Noncompliance nuted on 820805.*afsty-related equipment Haint
 Instruction HI 10-2J incorrectly performed & Fire Protection
 Procedure FP-14 Step III A improperly implemented on 820718
 HYERS D D . BURGER C Division of Project & Resident Programs
 82/09/03 9pp 15779 093 24% Fiche 50-324,82/10/18,8210220489
- 8210280275 Forwards corrected pages to rept submitted in conjuction w/820908 cable spread room examption request & Pages A 3-7-A 3-10 inadvertently omitted zinkERHAN.8 R Carolina Power & Light Co 82/10/22 DENTON.H R Office of Nuclear Reactor Regulation. Director 1p 19837-295 24X Fichs 50-024:82/10/22,8210280275
- --8210280278 Corrected & add1 pages to "Fire Protection of Cable Spreading Room"

 4 Carolina Power & Light Co 82/10/22 8pp 15837 296 24X
 Fiche 50-324.82/10/22.8210280275

H General correspondence

- 8210010028 Requests NRC direct all official correspondence to EE Utley, util vice-president due to 820930 retirement of JA Jones
 JONES: JA Carolina Power & Light Co 82/09/27 DENTON, H R
 Office of Nuclear Reactor Regulation, Director ip 15565 314 24X
 Fiche 50-000.82/09/27,8210010028
- 8210130323 Requests changes to distribution list for NUREG-0000, "Licensed Operating Reactors Status Summary Rept"
 ZIHMERMAN.B R Carolina Power & Light Co 62/10/11 BEEZE, M R, ADP Systems Development Branch 2pp 13683 361 24X Fichs 50-000, 82/10/11, 8210130323
- P Operating license stage documents & correspondence
- 8207180044 FDIA request for all internal non public documents, memos, availuation repts & other mati dealing w/nuclear plant operations
 MCINRIG.D Reus & Observer 82/08/17 Office of Administration is 15860-064 24X Fiche 50-000.82/08/17, 8207180044
- 8210120626 Advises that proposed interim changes for shift technical advisor training program acceptable up to Apr 1983, VASSALLO,D B Operating Reactors Branch 2 82/09/15 JONES,J A Carolina Power & Light Co 3pp 15672 266 24X Fiche 50-324,62/09/15,8210120626
- 8210280013 Responds to FDIA request for all internal non-public documents, memos: evaluation repts to ther math dealing with nuclear plant operations Forwards documents listed in App A. FELTON, J. M. Division of Rules and Records 82/09/17, MCINNIB, D. News & Observer 5pp 15860-065 24X Fiche 50-000.82/09/17, 8210280013
- --7905290397 Augmented offgas sys shall be used at all times & util should be informed COLLING, J.T. Effluent Treatment Bystems Branch 79/05/03 IPPOLITO T.A. Operating Reactors Branch 3 (Pre 790625) 1p 13860 087. 24X Fiche, 50-000, 82/09/17, 8210280013
- --7912280014 Advises of util 791025 interim commitment for demonstrating compliance u/40CFR190 Commitment acceptable, but must include direct radiation per section 6 of NUREO-0473, Revision 2 BANGARI, R Effluent Treatment Bystems Branch 79/11/23 IPPOLITO, T. Operating Reactors Branch 3 (Pre 800428) 19 15860 088 24X Fichs 50-000, 82/09/17, 8210280013.
- --Bi0ii40002 Confirms B0ii26 telcon re possible willful violation of reporting requirements IE lacks specific details necessary to make referred datermination HARD.W.J. Office of Inspection & Enforcement, Office of the Director 80/12/02 FORTUMA, Office of Inspector & Auditor ip 15860 095 24X Fiche.50-000.82/09/17.8210280013
- --BIO4290774 Notifies that applicant should be informed that major change to redwaste treatment sys will require IOCFR30 90 review Requests info to show conformance w/App I & mod can mast acceptance criteria of SRP in NOREO-OBOO.

 ONMILL.N P. Effluent Treatment Bystems Branch. 81/04/06 [PPOLITG.T.A. Operating Reactors Branch 2. 1p. 15860:226. 24X Fiche: 50-000, 82/09/17, 8210280013
- --Bii2020885 Forwards request for add1 licenses info re proposed second expansion of spent fuel pool & estimate of vol of solid waste generated by scrapping existing racks Info needed by SIII8 KREGER, W. E. Assistant Director for Radiation Protection, 81/10/27 NOVAK, T. Assistant Director for Operating Reactors, 2pp 15860;231 24X Fiche 50-000, 82/09/17, 8210280013.

- --8112300287 Forwards Effluent Treatment Bys Branch safety evaluating the spent fuel pool expansion application, per review of util 800416 submittal KREOER,W E Assistant Director for Radiation Protection 81/11/27 NOVAK,T M Assistant Director for Operating React 13pp 15860 249 24X Fiche 30-000, 82/09/17, 8210280013
- --B201120280 Advises that Billi2 itr recommended improvement of disparation calculation methodology & licenses accepted by Bill25 itr Other edit changes assured new methodology use every 31 days & nuclide dose factor inclusion in ETB GAMMILL.W P. Radiological Assessment Branch. Bi/12/08 IPPDLITO.TA Deprating Reactors Branch 2 ip 15860 264 Fiche 50-000, 82/09/17, 8210280013
- --B203080197 Advises that replacing Phrase 12 "Consecutive Honths' w/phrase "Calendar Yr" in Tech Spec 2 5 2 b acceptable Change would reduce recordseeping HOUSTON, R W. Assistant Director for Radiation Protection B2/02/11 NOVAK, T M. Assistant Director for Operating React: 2pp 15861 014 24X Fiche 50-000, B2/07/17, B210280013
- --8205170128 Advises that review of NUREG-0737, Item II F 1. has bee satisfactorily completed & considered closed HOUSTON,R H Assistant Director for Radiation Protection B2/04/16 NOVAK,T H Assistant Director for Operating Reaction 15861 040 24% Fiche 50-000,82/09/17,8210280013
- --8206220591 Submits background info on conversation w/util re 82 loss of RHR syc water event at facility.LER 82-005/017 WOLF.T R Director's Office 82/06/04 RUBIN.5 Director's Office 50-000.82/09/17.821028001
- --8207120140 Trip rept of 820324 visit to facility re equipment graulification problems List of sits visit/meeting participants & related info encl EL-YEFTAWY. M. WOLF.T R Director's Office 82/07/06 MICHELSON.C Director's Office 12pp 15861 314 24x Fichs 50-000,82/09/17,8210280013
- --8208310034 Forwards draft info notice re deficiencies in air filt & ventilation sys. Notice based on radioactive resin release at Pilgram i & on four related events at other plants involving deficiencies in maint & testing of filter sys. MATTBON.R J. Division of Systems Interaction (post 811605) 82/08/05 JORDAN.E L. Division of Engineering & Quality Assurance 5pp 15861 024 24X Fiche 50-000,82/09/17.821079:
- --8209150162 Forwards "Brunswick Nuclear Power Station Unit 2 Less: Bvc Water on 82016 - Engineering Evaluation Rept " Evint is of minor significance & should not be classified as AD HOLF, T R Director's Office 82/08/25 MICHELBON C Directs: Office 1p 15861 931 24X Fiche 50-000,82/09/17,8210260013
- --8210280024 Advises that util 780518 response re proposed plans for correcting problems concerning augmented offgas systematic problems concerning augmented offgas systematic problems for the second by a mended COLLING, J T Effluent Treatment Systems Branch 78/06/02 LEAR, 0 Operating Reactors Branch 3 (Pre 800428) 2pp 15860.077 24X Fiche. 50-000, 82/09/17, 8210280013
- --B2102B0027 Notifies that commitment schedule for implamenting agree, augmented offgas sys unacceptable Thermal recombiners for use in BHR offgas sys will not satisfy criteria COLLINS.J T Effluent Treatment Bystems Branch 78/09/06 IPPOLITO.T Operating Reactors Branch 3 (Pre 80042B) 3pp 15860.079. 24X Fiche 50-000, 82/09/17, 82102B0013
- --B210280047 Notifies that potential for criminality found re Regiss investigation resulting from W Ward 801202 memo controling facility
 FORTUNA, R.A. Office of Inspector & Auditor 80/12/03 Office of Inspector & Auditor 80/12/03 Office of Inspector & Auditor 19 15860 096, 24X Fiche 50-000, 82/09/17.8210280013
- --B210280095 Assumes responsibility for review of Case B)-17 for criminality No criminality indicated Case should be closed SMITH.R.M. Office of Inspector & Auditor B2/08/24 Office H Inspector & Auditor ip 15861 027 24X Fiche 50-000,82/05/17, 8210280013
- --B210280100 Notifies that on B20224,C Alderson advised that replant possible willful violation of reporting requirements & falsification of GA & guard qualification records at facilities.

 RESNER,M E Office of Inspector & Auditor B2/03/01 Office in Inspector & Auditor & Auditor

- 82:0010051 Ack receipt of 820823 ltr requesting temporary relief from commitments re training of shift technical advisors Program approxed & request forwarded to NRR for evaluation O'REILLY, J P Region 2, Office of Director 82/09/20 JONES, J A Carolina Power & Light Co 1p 15565 322 24X Fische 50-000, 82/09/20, 8210010051
- B210050362 Application to amend Licenses DPR-71 & DPR-62 revising Tech Specs to clarify requirements for verifying operability of scram discharge vol vent & drain valves Class I & II license amend fees enc! EURY, L W Carolina Power & Light Co 82/07/29 VASSALLO, D B Operating Reactors Dranch 2 2pp 15408 345 24X Fishe 50-324, 82/09/29, 8210050362
- --B210050371 Prposed Tech Spec 4 1 3 1 1 re surveillance requirements verifying operability of scram discharge vol vent & drain valves
 Carolina Power & Light Co B2/09/29 2pp 15608 347 24X Fiche 50-324,82/09/29,8210050362
- 8210270110 Advises that plant venting capability acceptable to resolve MUREG-0737. TMI Item II B I re high point vents VASSALLO.B B Operating Reactors Branch 2 82/10/01, JONES, J A Carolina Power & Light Co 3pp 15846 338 24X Fiche 50-324.82/10/01.6210270110
- --8210290113 "Operating Reactors TMI Lessons Learned, NVREG-0737
 Response Evaluations (Program II)) Project 1.RC8 Vents for
 Brunswick 1 & 2." final technical evaluation rept
 + Lawrence Livermore Laboratory FIN A-0246-2 82/07/15
 BUTCHER.E , BARNHARTIB Division of Licensing 4pp 15866-341
 24X Fiche 50-324, 82/10/01, 8210270110
- B210:50030 Forwards submittal schedule for responses to NRC 820909 issues re TMI Action Items II F 1.4.5 & 6 & II E 4 2 7. Tech Spec revisions, containment vent & purge, electrical distribution sys voltages & control of heavy loads IIEMERMAN.S R Carolina Power & Light Co 82/10/12 VASSALLO, D B Operating Reactors Branch 2 2pp 15701 268 24X Fische 50-324, 82/10/12, 8210150030
- B210260244 Advises that response to NRC B20B27 request to justify differences between existing control room & NUREO-0737. Item III D 3 4 suggestions will be provided by B30131 Requests re-evaluation of improvement cost-benefits
 EURY, L W Carolina Power & Light Co B2/10/21 VASSALLO, D B
 Operating Reactors Branch 2 1p 15797 353 24X
 Fiche 50-324, 82/10/21, 8210260244
- B210260323 Application for amend to Licenses DPR-71 & DPR-62 clarifying portions of B10521 submittal re hydraulic snubber surveitlance EURY.L W Carolina Power & Light Co 82/10/21 VASSALLO.D B Operating Reactors Branch 2 2pp 15799 338 24X Fiche 50-324, B2/10/21,8210260323
- --B210260325 Revised Tech Specs re hydraulic snubber surveillance # Carolina Power & Light Co B2/10/21 2pp 15799.340 24x Fichs 50-324,82/10/21.B210260323
- 8210240405 Hithdraws request for amend to Licenses DPR-71 & DPR-62, revising Tech Spac re reportability of inoperable reed switches in rod position indication sys to reduce number of routine LERs

 EURY.L W Carolina Power & Light Co 82/10/22 VABBALLO,D. B
 Operating Reactors Branch 2 2pp 15806 237 24X

 Fische 50-324,82/10/22,8210260405
- --8210260410 Proposed revisions to Tech Spec 6 9 1 re monthly reportability of safety/relief valve challenges. Tech Spec supersedes 820407 submittal
 ** Carolina Power & Light Co 82/10/22 2pp 15806 241 24X Fichs 50-324,82/10/22,8210260405.
- 3 Imspection reports, IE Bulletins & correspondence
- 3210080015 Addl response to FOIA request for 19 categories of info re nuclear reactor events & safety problems Forwards documents 1 isted in App A Documents in App B completely withheld (ref FOIA Exemption 3) FELYON.J M. Division of Rules and Records 82/07/12 UDELL,R A Critical Mass Energy Project 9pp 15645 027 24X Fiche 50-000.82/07/12,8210080015
- --- B2100B0122 Systematic assessment of licensee performance notes re #acility evaluation for Apr 1979-Mar 1980 e NRC - No Detailed Affiliation Given 60/03/31. 6pp 13667 321. 24X Fiche. 30-000, 82/07/12/8210080015

- 8210010132 Forwards IE Insp Repts 50-324/82-31 & 50-325/82-29 on 820809-13 No noncompliance noted VERRELLI,D H Division of Project & Resident Programs 82/09/01 JONES, J A Carolina Power & Light Co 2pp 15567.230 24X Fichs 50-324,82/09/01.8210010132
- --8210010137 IE Insp Repts 50-324/82-31 & 50-325/82-29 on B20809-13 No noncompliance noted Major areas inspected: ALARA; radioactive mat! transportation, radioactive liquid effluent monitoring & mat! control
 ALBRIGHT.R H , BARR.K P Division of Engineering & Technical Programs 82/08/31 5pp 15567:232. 24X Fiche 50-324,82/09/01,8210010132
- 8210010112 Forwards summary of 820824 enforcement meeting at Region 2 ofc restatus of action items contained in 820702 to 20 confirmation of action ltrs
 O'REILLY, J.P. Region 2. Office of Director 82/09/03 JONES, J.A.
 Carolina Power & Light Co. 1p. 15566 029 24X
 Fiche 50-324.62/09/03.8210010112
- --8210010126 Bunmary of 820824 meeting w/util in Atlanta, GA re status of action items contained in 820702 & 20 confirmation of action ltrs Util committed to formally submit long-term arogram details in Nov 1982

 LEMIS, R C Division of Project & Resident Programs 82/09/03

 Division of Project & Resident Programs 22/09/03

 Fiche 50-324,82/09/03,8210010112
- 8210010170 Ack receipt of 820816 response to 820716 notice of violation & proposed imposition of civil penalties, Rept on major program objectives to be submitted by 821101 should provide sufficient info re testing aspects of training programs AXELRAD, J. Enforcement Staff. 82/09/15 JONES, J.A. Carolina Power & Light Co. 2pp. 15568 109. 24X Fiche 50-325,82/09/15,8210010170
- --8210010173 Forwards IE Insp Repts 50-324/82-02 & 50-325/82-02 on 820106-07 Enforcement action addressed to util in 820715 ltr LEMIB.R.C Division of Project & Resident Programs. 82/07/16 JONES.J A Carolina Power & Light Co 2pp 15568:124. 24X Fichs 50-325.82/07/15,8210010170
- --B210010206 IE Insp Repts 50-324/82-02 & 50-325/82-02 on B20106-07 Noncompliance noted Unit 1 instrument D-1 inoperable & level channel not tripped between B11226-31. OARNER, L , JULIAN, C , BURGER, C Division of Project & Resident Programs B2/05/13 6pp 15568 126 24X Fiche 50-325,82/09/15, 8210010170.
- 8210010171 Ack receipt of 820702 & 0903 ltrs informing NRC of steps taken to correct violations noted in IE Insp Repts 50-324/82-18 & 50-325/82-18 VERRELLI, D M Division of Project & Resident Programs 82/09/16 JONES, J A Carolina Power & Light Co. ip. 15568 091, 24X Fiche 50-324,82/09/16,8210010171
- --8210010183 Suppls 820702 response to NRC 820404 ltm re violations noted in IE Insp Repts 50-324/82-18 & 50-325/82-18 Corrective actions:responsible operators counseled & IA-1 battery charger clearance removal reviewed DIETZ, C R Carolina Fower & Light Co 82/09/03 O'REILLY, J. P. Region 2, Office of Director. 3pp 15568:092, 24X Fiche 50-324,82/09/16,8210010171
- --8210010188 Responds to NRC 820604 ltr reviolations noted in IE Insp Repts 50-324/82-18 & 50-325/82-18, Corrective actions: double verification program established on 820601 DIETZ,C R Carolina Power & Light Co, 82/07/02. O'REILLY, J. P Region 2: Office of Director. 2pp 15568:095 24X Fiche: 50-024,82/09/16:8210010171
- --8210010194 Forwards IE Insp Repts 50-324/82-18 & 50-325/82-18 on 820415-0515 & notice of violation LONG, F.J. Division of Project & Resident Programs 82/06/04, JONES, J. A. Carolina Power & Light Co. 2pp 15568:097, 24X Fichs:50-324,82/09/16.8210010171.
- --8210010199 Notice of violation from insp on 820415-0515, * Region 2, Office of Director 82/06/04 ip 15568:099, 24X Fiche 50-324,82/09/16:8210010171
- --8210010205 IE Insp Repts 50-324/82-18 & 50-325/82-18 on 820415-0515. Noncompliance noted Operating Procedure OP-43 & tag removal for Clearance 1-459 inadequately implemented MYERS, D. O. OARNER, L. W., BURGER, C. W., Division of Project & Resident Programs 82/06/04. 9pp 15568:100 24X Fiche:50-324,82/09/16,8210010171

- 8210010336 Advises that IE Insp Rept 50-325/82-36 was inadvartently labeled 50-325/82-30 VERRELLI.D H Division of Project & Resident Programs 82/09/84 JUNES, J A Carplina Power & Light Co 1p 15571 001 24X Fiche 50-324, 82/09/16,8210010336
- --8210010340 Forwards IE Insp Repts 50-324/82-32 & 50-325/82-36 on 820824-27 No moncompilance noted VERRELLI.D H Division of Project & Resident Programs 82/09/10 UDNES.J A Carolina Power & Light Co 2pp 15571 002 24X Fiche 50-324.82/09/16.8210010336
- --8210010350 IE Insp Repts 50-324/82-32 & 50-325/82-36 on 820824-27 No noncompliance noted Major areas inspected pre-startup reviews, corporate nuclear safety reviews, post-maint testing & plant mode involving Tech Spec changes FREDRICKSON,P , JACKSON,L H , UPRIGHT,C M Division of Engineering & Technical Programs 82/09/10 4pp 15571 004 24X Fiche, 50-324,82/09/16,8210010336
- 8210010391 Ack receipt of 820907 ltr informing NRC of staps taken to correct violations noted in IE Insp Repts 50-324/82-25 & 50-325/82-25 LEHIB,R C Division of Project & Resident Programs 82/09/22 JONES, J A Caroline Power & Light Co ip 15572 269 24X Fiche 50-324; 82/09/22 8210010391
- --8210010399 Responds to NRC 820813 itr re violations noted in IE Insp. Repts 50-324/82-25 & 50-325/82-25 Corrective actions plant operating procedures rewritten & signoffs added Operations engineer responsible for procedure changes DIETZ, CR Carolina Power & Light Co 82/09/07 d'REILLY, J P. Region 2, Office of Director 2pp 15572 270 24X Fiche 50-324,82/09/22,8210010391
- --8210010405 Forwards IE Insp Repts 50-324/82-25 & 50-325/82-25 on 820615-0715 & notice of violation LEHIS.R C Division of Project & Resident Programs 82/08/13 JONES.J A Caroline Power & Light Co 2pp 15572 272 24X Fiche 50-324,82/09/22.8210010391
- --8210010410 Notice of violation from insp on 820415-0715 * Division of Project & Resident Programs 82/08/13, 2pp 15572-274 24X Fiche-50-324,82/09/22,8210010391
- --8210010415 IE Insp Repts 50-324/82-25 & 50-325/82-25 on 820615-0715 Noncomplience noted failure to implement & maintain operating procedures for startup & shutdown MYERS, D.O. GARNER, L. W. STETKA, T. Division of Project & Resident Programs 82/08/12 13pp 15572 276 24X Fiche, 50-324, 82/09/22, 8210010391.
- B210150100 Ack receipt of B20913 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-324/82-26 & 50-325/82-26 LEWIB:R C Division of Project & Resident Programs B2/09/24 JONES:J A Carolina Power & Light Co ip 15701 164. 24X Fiche 50-324: 82/09/24.8210150100
- --82i0150106 Responds to NRC 820B17 ltr re violations noted in IE Insp Repts 50-324/82-26 & 50-325/82-26 Corrective actions new comprehensive post-testing program being developed DIETZ.C R Carolina Power & Light Co 82/09/13 O'REILLY, J P Region 2. Office of Director 2pp. 13701:165, 24X Fiche 50-324,82/09/24,8210150100
- --8210150113 Forwards IE Insp Repts 50-324/82-26 & 50-325/82-26 on 820712-16 & notice of violation LEWIS.R C Division of Project & Resident Programs. 82/08/17 JONES.J A Carolina Power & Light Co. 2pp 15701:147 24X Fichs 50-324,82/09/24,8210150100
- --8210150120 Notice of violation from insp on 820712-16 # Division of Project & Resident Programs 82/08/17 2pp. 15701-169 24X Fiche-50-324,82/09/24-8210150100
- --8210150132 IE Insp Repts 50-324/82-26 & 50-325/82-26 on 820712-16 Noncompliance noted failure to provide measures to preclude bypassing required testing.

 8XINNER:P H . JACKBON.L.H.. UPRIGHT.C M. Division of Engineering & Technical Programs 82/08/19. 7pp 15701 171 24X Fiche 50-324,82/09/24,8210150100
- 8210150108 Forwards IE Insp Repts 50-324/82-35 & 50-325/82-35 on 820908-10 No noncompliance noted VERRELLI, D.M. Division of Project & Resident Programs. 62/09/24. JUNES, J.A. Carolina Power & Light Co. 2pp. 15701 149 24X Fiche 50-32 .82/09/24, 8210150108

- --8210150114 IE Insp Repts 50-324/82-35 & 50-325/82-35 on 820708-10 s; noncompliance noted Major areas inspected review & evaluation of changes to inservice insp program & program for document control & data retention COLEY.J L . BLAKE.J J Division of Engineering & Technical Programs 82/09/21 3pp 15701 151 24X Fiche 50-324,82/09/24 82(0150108
- 8210150162 Forwards IE Insp Repts 50-324/82-33 & 50-325/82-31 on 820901-03 & 10 No noncompliance noted VERRELLI.D M. Division of Project & Resident Programs 82/09/24 JONES.J A Carolina Power & Light Co 2pp 15707 304 24X Fiche 50-324.82/09/24.8210150162
- --8210150170 IE Insp Repts 50-324/82-33 & 50-325/82-31 on 820901-03 s No noncompliance noted Major areas inspected IE Bulletin 77-14. "Seismic Analysis for As-Built Safety-Releted Piping Sys"

 ANO. H P , BLAKE, J Division of Engineering & Technical Progress 82/09/23 5pp 15707 306 24X Fiche 50-324, 82/09/24, 82(015016)
- 821015000B Ack receipt of 820819 & 0915 ltrs informing NRC of elept taken to correct violations noted in IE Insp Repts 50-324/82-23 & 50-325/82-23 LEHIS:R C Division of Project & Resident Programs 82/09/30 JONES:JA Carolina Power & Light Co 1p 15698 349 24x Fiche 50-324.82/09/30.821015000B
- -8210150016 Revises response to NRC ltr re violation; noted in IE Ir., Repts 50-324/82-23 & 50-325/82-23 Corrective actions assessment of inservice into program in progress Violation will be fully addressed by 821231
 DIETZ.C R Carolina Power & Light Co 82/09/15 D'REILLY, J P Region 2. Office of Director 2pp 15698 350 24X
 Fichs 50-324, 82/09/30, 8210150008
- --8210150023 Responds to NRC 820719 litr re violations noted in IE [--]
 Repts 50-324/82-23 & 50-325/82-23 Corrective actions
 post-maint testing program revised & inservice insp program
 under review
 DIETZ. C R Carolina Power & Light Co 82/08/19 O'RE(LLY, J.P.
 Region 2. Office of Director 3pp 15698 352 24X
 Fiche 50-324,82/09/30,8210150008
- --8210150034 Forwards IE Insp Repts 50-324/82-23 & 50-325/82-23 on 820615-18 & notice of violation LEWIS,R C Division of Project & Resident Programs 82/07/19 JONES,J A. Carolina Power & Light Co 2pp. 1569R 355 241 Fichs 50-324,82/09/30,8210150008
- --8210150040 Notice of violation from insp on 820615-18 LEMIS.R C Division of Project & Resident Programs 82/07/19 2pp 15498 357 24% Fiche 50-324,82/09/30,8210150008
- --B210150063 IE Insp Repts 50-324/82-23 & 50-325/82-23 on B2015-19 Noncompliance noted failure to re-establish baseline data for RHR evc water pump & to include main steam piping in inservice insp program
 BLAKE.J J , ECONDMOS.N Division of Engineering & Technical Programs 82/07/15 4pp 15698 359 24X Fiche S0-324-82/09/31 8210150008.
- 8210220139 Forwards IE Insp Repts 50-324/82-38 & 50-325/82-38 on 820907-10 No noncompliance noted VERRELLI, D M Division of Project & Resident Programs 82/10/Ct JONES, J.A Caroline Power & Light Co 2pp 15778 107 24X Fiche: 50-324, 82/10/04,8210220139
- --8210220147 IE Insp Repts 50-324/82-38 & 50-325/82-38 on 820907-11% moncompliance noted Major areas inspected followup inspet NRC & licensee identified tasks to be completed prior to startup
 WHITENER H. L., KRUG,H. E., JAPE, F. Division of Engineering & Technical Programs, 82/09/30 5pp 15778 109 24X
 Fiche, 50-324,82710/04,8210220139
- 8210220169 Forwards IE Insp Repts 50-324/82-36 & 50-325/82-33 on 820815-0915 No noncompliance noted VERRELLI, D. M. Division of Project & Resident Programs 82/10/84 JONES, J. A. Carolina Power & Light Co 2pp 15778 045 241 Fiche: 50-324, 82/10/04, 8210220169
- --8210220173 IE Insp Repts 50-324/82-36 & 50-325/82-33 on 82085-ffilt noncompliance noted Major areas inspected, review of LERs, operational safety verification & audit of surveillance & maint activities

 HYERS, D D , GARNER, L W., BURGER, C. Division of Project & Miller, Programs. 82/10/01 Bpp 15778 047, 24X Fiche 50-324.82/10 \$210220169.

- 9210150036 Ack receipt of 820816 & 0924 ltrs informing NRC of steps taken to correct violations noted in IE Insp Repts 30-324/82-20 & 50-325/32-20 LEHIS.R C Division of Project & Resident Programs 82/10/05 JONES, J A Carolina Power & Light Co 1p 15701 135 24X Fiche 50-324, 82/10/55,8210180036
- --8210150038 Supple 820816 response to NRC 820719 ltr re violations noted in IE Insp Repts 50-324/82-20 & 50-325/82-20 Addl info re revision to Procedure CoAD 80-1 to assure timely corrective actions to future audit findings provided DIETZIC R Carolina Power & Light Co 82/09/24 O'REILLY, J P Region 2. Office of Director 2pp 15701 136 24X Fiche 50-324,82/10/05.82(0150036
- --8210150045 Responds to NRC 820719 ltr re violations noted in IE Insp Repts 50-324/82-20 & 50-325/82-20 Corrective actions Procedure CQAD 80-1 revised & frequency of plant audits increased to reduce audit scope DIETI-C R Carolina Power & Light Co 82/08/16 O'REILLY.J P Region 2. Office of Director 3pp 15701 138 24X Fichs 50-324,82/10/05,8210150036
- --8210150048 Forwards IE Insp Repts 50-324/82-20 & 50-325/82-20 on B20507-08 & notice of violation W/o notice of violation LEMIS:R C Division of Project & Resident Programs 82/07/19 JONES:J A Carolina Power & Light Co 2pp 15701 141 24X Fiche 50-324,82/10/05:8210150036
- --9210150052 IE Insp Repts 50-324/82-20 & 50-325/82-20 on 820607-08
 Noncompliance noted failure to establish measures to assure
 prompt corrections to adverse GA conditions & failure to
 distribute audit within required timeframe
 BELISLE.0 A., UPRIGHT, CM Division of Engineering & Technical
 Programs B2/07/15 4pp 15701 143 24X Fiche 50-324,82/10/05,
 9210150036
- 9210150288 Act receipt of 820714 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-324/82-21 & 50-325/82-21 VERRELLID M Division of Project & Resident Programs 82/10/05 JONES, J A Carolina Power & Light Co. 1p. 15706 126 24X Fiche 50-324,82/10/05,8210150288
- --9210130275 Responds to NRC 820818 ltr re-violations noted in IE Insp Repts 50-324/82-21 & 50-325/82-21 Corrective actions relief valves which can communicate w/primary containment added to Type C testing program & review of leakage continuing DIETX.C R Carolina Power & Light Co 82/09/14. O'REILLY, J P Region 2. Office of Director 2pp 15706.127 24X Fiche 50-324,82/10/05,8210150288
- POBITO233 IE Info Notice 80-35, Suppl i, "Leaking & Dislodged I-125 Implant Seeds " Syc list encl COBB.L. I Division of Fuel Facilities, Materials & Safeguards 82/10/06 Consolidated Edison Co of New York 66pp 15761 250 24X Fichs 50-000,82/10/06,8208190233
- 20Bi9023B IE Bulletin 82-03, "Stress Corrosion Cracking in Thick-Wall, Large-Diamster, Stainless Bteel, Recirculation Sys Piping at BNR Plants, "Svc list encl BEYOUNG.R C Director's Office, Office of Inspection and Endorcement 82/10/14 Consolidated Edison Co. of New York 185pp 15810 225 24X Fiche 50-000, 82/10/14, 820819022B
- 210220489 Ack receipt of 821006 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-324/82-30 & 50-325/82-30.

 VERRELLI.D.M. Division of Project & Resident Programs 82/10/18

 UTLEY, E E Carolina Power & Light Co ip 15779.087 24X

 Fichs 50-324,82/10/18,8210220489
- -8210220492 Responds to NRC 820907 ltr re violations noted in IE Insp Repts 50-324/82-30 & 50-325/82-30 Corrective actions: technician counseled re compliance w/Maint Instruction MI-10-2J Fire Protection Procedure FP-14 will be revised DIETZ.C.R. Caroline Power & Light Co. 82/10/06 O'REILLY: J P Region 2. Office of Director 2pp 15779 088 24X Fiche 50-324,82/10/18,8210220489
- B210220494 Forwards IE Insp Repts 50-324/82-30 & 50-325/82-30 on B20715-0815 & notice of violation.

 VERRELLIAD M Division of Project & Resident Programs 82/09/07 JCMES. J A Cerolina Power & Light Co 2pp 15779'090 24X Fiche. 50-324, 82/10/18, 8210220489
- -9210220496 Notice of violation from insp on 820715-0815 * Division of Project & Resident Programs. 82/09/07. ip 15779 092. 24X Fiche, 50-324, 82/10/18, 8210220489.

- --8210220503 IE Insp Repts 50-324/82-30 & 50-325/82-30 on 820715-0815 Noncompliance noted on 820805, safety-related equipment Maint Instruction MI 10-2J incorrectly performed & Fire Protection Procedure FF-14 Step III A improperly implemented on 820718 MYERS, D O . OARNER, L W . CHASE, J Division of Project & Resident Programs 82/09/03 9pp 15779 093 24X Fiche 50-324, 82/10/18, 8210220489
- 8 Reportable occurrences, LERs & related correspondence
- 8210070416 Trip rept of 810617 site visit to collect info re loss of RHR Baffle plate dividing water box of RHR HX 1A failed allowing svc water to bypass HX tubes Caused by sicessive differential pressure across baffle plate IMBRO, C. 01AHELLI, J. Director's Office 81/07/22 Director's Office 19ep 15697 308 24X Fiche 50-324.81/07/22.8210070416
- 8210010008 Responds to FOIA request for 19 categories of documents re nuclear reactor events & safety problems Forwards documents listed in App A FELTON.J M Division of Rules and Records 82/06/28 UDELL.R A Critical Mass Energy Project 15pp 15727 005 24X Fichs 50-000,82/06/28,8210010008
- --8107300168 Discusses findings gathered during 810617 site visit re facility loss of RHR capability during Apr & May 1981 Util has committed to mod of wash screen wash sys by 1983 Attendance list,chlorinator outage info & drawings encl IMBRO.E Director's Office 81/07/22 Director's Office 19pp 15730 056 24X Fiche 50-000.82/06/28,8210010008
- 8209160299 Forwards LER 82-095/031-0 DIETZ.C R Caroling Power & Light Co 82/08/31 D'REILLY.J P Region 2. Defice of Director 1p 14894 178 24X Fiche 50-325.82/08/31.8209160299
- --B209160311 LER 82-095/03L-0 on 820803, review revealed that RHR shutdown cooling suction valves 6008 & 6009 & vessel head spray valves 6022 & 6023 not tested on quarterly basis per inservice insprequirement Caused by program logic error POULK:R M Carolsna Power & Light Co 82/08/31 Region 2. Office of Director 1p 14894 179 24X Fiche 50-325, 82/08/31, 8209160299
- 8210010170 Ack receipt of 820816 response to 820716 notice of violation & proposed imposition of civil penalties Rept on major program objectives to be submitted by 821101 should provide sufficient info re testing espects of training programs AXELRAD. J Enforcement Staff 82/07/15 JONES, J A Carolina Power & Light Co 2pp 19368 109 24X Fiche 50-325,82/09/15,8210010170
- --8210010206 IE Insp Rapta 50-324/82-02 & 50-325/82-02 on 820104-07 Noncompliance noted Unit 1 instrument D-1 inoperable & level channel not tripped between 811226-31 GARNER, L Division of Project & Resident Programs 82/05/13 6pp 15568 126 24% Fiche 50-325,82/09/15,8210010170
- 8210280013 Responds to FOIA request for all internal non-public documents, memos, evaluation repts & other math dealing w/ nuclear plant operations Forwards documents listed in App A FELTON, J H Division of Rules and Records 82/09/17 McINNIS.D News & Observer 5pp 15860 065 24% Fiche 50-000,82/09/17,8210280013
- --7811200399 LER#1-7B-051 on radioactive release reviewed in response to 780803 request Finds LER does not indicate root cause of the event malfunction of concentrated weste tank heaters due to correction forwards recommendations for personnel COLLINS, J T Effluent Treatment Systems Branch 78/10/06 KNIGHTON, G. Environmental Evaluation Branch (Pre 790625) 3pp 15860 082 24X Fiche 50-000,82/09/17,8210280013
- 8210080181 Forwards LER 82-101/03L-0
 DIETZ.C R Carolina Power & Light Co 82/10/01 D'REILLY, J P
 Region 2, Office of Director 1p 15640 170 24X
 Fiche 50-325,82/10/01,8210080181
- --8210080183 LER 82-101/03L-0 on 820920, valve time testing not covered in operability test of loops A & B of LPCI/RHR sys PTS 08 2.20 & 26, Caused by personnel oversight during procedural development Procedures revised, PASTVA, M J Carolina Power & Light Co 82/10/01. Region 2, Office of Director ip. 15640:171. 24X Fiche 50-325, 82/10/01, 8210080181
- 8210080220 RO on 821001, analysis confirmed that pipe support P8-5647 could fail during selamic event Support upgraded to meet requirements
 DIETZ, C R Carolina Power & Light Co. 82/10/01 O'REILLY, J P. Region 2, Office of Director 1p 15639:090 24X Fiche: 50-323, 82/10/01.8210080220.

1

1 :.

. .

1

11.

H

94 J

11

9 R 4

램

,

- 8210130477 Forwards updated LER 82-093/03L-1 DIETZ.C R Carolina Power & Light Co 82/10/04 O'REILLY, J P Region 2. Office of Director 1p 15682 163 24X Fiche 50-025, 82/10/04, 8210130477
- --8210130483 Updated LER 82-093/03L-1 on 820813, review revealed inability of reactor protection sys logic functional test PT-01 1 10 to provide for electrical continuity testing of input signal contacts of backup scram logic circuitry solenoids PASTVA.M J Carolina Power & Light Co 82/10/04 Region 2, Office of Director 1p 15682 164 24X Fiche 50-325,82/10/04, R910130477
- 8210130489 Forwards updated LER 82-024/03L-1 DIETZ.C R Carolina Power & Light Co 82/10/04 O'REILLY.J P Region 2. Office of Director Ip 15484 193 24X Fiche 50-025: 82/10/04.8210130489
- --B210130497 Updated LER 82-024/03L-1 on 820214 & 0220.open position indication for drywell to suppression vacuum breaker X18H not achievable Caused by failure of vacuum breaker to stroke open fully Cause of 820220 event not detarmined PASTVA: M J Carolina Power & Light Co 82/10/04 Region 2, Office of Director 1p 15684 194 24X Fiche 50-325, 82/10/04, 8201030489
- 8210190666 Forwards LER 82-100/01T-0 DIET7.C R Carolina Fower & Light Co 82/10/11 O'RETLLY, J P Region 2, Office of Director Ip 15737 254 24X Fiche 50-325.82/10/11.8210190666
- --8210190674 LER 82-100/017-0 on 621001, determined that tailpipe for safety relief valve FOI3H could fail during seismic event AddI analysis not performed AddI support (PS-6647) added where tailpipe passes through deflector plate POULK, R M Carolina Power & Light Co 82/10/11 Region 2, Diffice of Director 1p 15737 255 24X Fiche 50-325, 82/10/11, 2210160644
- 6210290346 Forwards supplemental LER 62-024/03L-2 DIETT, C R Carolina Power & Light Co 82/19/13 O'REILLY, J P Region 2, Office of Director Ip 15853 106 24X Fiche 50-325, 62/10/13, 8210290346
- --8210290352 Supplemental LER 62-024/03L-2 on 620214, during periodic test discovered that open position indication for drywell to suppression vacuum breaker XIBM could not be achieved Caused by failure of vacuum breaker to fully stroke open PASTVA.M J Carolina Power & Light Co 62/10/13 Region 2. Office of Director 1p 15953 107 24X Fiche 50-325, 82/10/13, 8210290344
- G210260205 Interam Part 21 rept Detailed status of corrective actions taken will be sent by G21020 GARSIEN.G E United Engineers & Constructors, Inc. (subs. of Raythron Co.) G2/10/15 Director's Office, Office of Inspection and Enforcement ip 15799 151 24X Fiche 50-324, G2/10/15, B210260205
- 8210260294 RD while performing insplof fire dampers per 820518 commitment, discovered ventilation duct located at penetration seal D0-2-034 on 23-ft elevation of dissel generator bidg did not have insploor DIETZ, CR Carolina Power & Light Co 82/10/15, D'REILLY, J PRegion 2, Office of Director 1p 15803 025 24X Fiche 50-325, 82/10/15, 8210260294
- 9210290325 Forwards updated LER 82-001/03L-1 DIETZ.C R Carolina Power & Light Co 92/10/15 O'REILLY, J P Region 2. Office of Director 1p 15859 048 24X Fiche 50-025, 82/10/15, 8210290325
- --BR10270331 Updated LER B2-001/03L-1 on B2011B, surveillance revealed drywell equipment drain flow, 1-016-FQ-K603 continuously indicating sump flow w/no pumps running Caused by Integrator square root converter & flow transmitter out of callor. PABTVA.M J. Carolina Power & Light Co 82/10/15 Region 2. Office of Director 2pp 15853 049 24X Fiche 50-325,82/10/15,8210270325
- 8210260256 Forwards LER 82-104/03L-0 DIETZ.C.R Carolina Power & Light Co 82/10/18 O'REILLY, J P Region 2. Office of Director 1p 15803 101. 24X Fiche 50-225.82/10/18.8210260256
- --8210260266 LER 82-104/03L-0 on 821001, excess flow check valve f-821-F047c failed to seat & isolate as required Probably caused by line crud deposit in valve seat Line flushed & valve satisfactorily tested FASTVA.M J. Carolina Power & Light Co. 82/10/18 Region 2. Office of Director ip IS803-102 24X Fiche. 50-325, 82/10/18, 8210260286

- 8210260344 Forwards LER 82-103/03L-0 DIETZ.C R Carolina Power & Light Co 82/10/18 O'REILLY, J P Region 2, Office of Director 1p 15804 244 24x Fichs 50-225, 82/10/18, 8210260344
- --8210260369 LER 82-103/03L-0 on 920924, required semiannual functions test of primary containment air lock interlock mechanism not addressed in procedures Caused by personnel oversight during initial review of Tech Specs
 PASTVA,M J Carolina Power & Light Co 82/10/18 Region 2.
 Office of Director 2pp 13804 245 24X Fiche 50-325,82/10/18
 8210260344
- DOCKET 50-327 SEGUDYAH NUCLEAR PLANT, UNIT 1

 F Security, medical, emergency & fire protection plans
- 8209170068 Forwards revised pages to proposed physical security plan transmitted by 820823 ltr Pages withheld (ref 10CFR2 7901 MILLS.L.H Tennessee Vailey Authority 82/09/01 ADENSAM.E Licensing Branch 4 lp 14910 105 24X Fiche 50-327.82/09/01, 8209170068
- 8210060347 Forwards status rept of meteorological program for ravies a "Sequoyah Ruclear Plant Nowcast Manual "
 MELLS,L M Tennessee Valley Authority 82/10/01 ADENSAM.E Licensing Branch 4 5pp 18619 056 24X Fiche 50-327,82/10/01, 8210060347
- --8210060352 "Sequoyah Nuclear Plant Nowcast Manual "
 # Tannessee Valley Authority 82/09/30 70pp 15619 06; 24
 Fiche 50-327,82/10/01,8210060347
- 8210260245 Forwards IE Safeguards Insp Repts 50-327/82-26 & 50-328/82-26 on 821006-08 No noncompliance noted VERRELLI, D Division of Project & Resident Programs D2/10/22 PARRIS, H O Tennessee Valley Authority 2pp 15799 136 24x Fiche 50-327, 82/10/22, 8210260245
- --8210260265 IE Insp Repts 50-327/82-26 & 50-328/82-26 on 02100608 is noncompliance noted Major areas inspected review of security plan & implementing procedure: security organization-mgt/personnel/response Details withheld (ref 10CFR73 21) MODRE/D E . MCGUIRE/D R Division of Engineering & Technical Programs 82/10/22 ip 15779 138 24X Fiche 50-327,82/10/22. \$210260245
- P Operating license stage documents & correspondence
- 82:100:10008 Responds to FOIA request for 19 categories of documents in nuclear reactor events & safety problems Forwards documents listed in App A FELTON, J M Division of Rules and Records 82/06/28 UPELLRA Critical Mass Energy Project 15pp 15727 005, 24X Fiche 50-000, 82/06/28, 82:10010008
- --8008050265 Discusses addl required info to better define potential to cracking in reactor vessel notiles
 NOONAN, V B Assistant Director for Materials & Qualification
 Engineering 80/05/05 TEDESCO.R L Assistant Director for
 Licensing 2pp 19727 176 24X Fiche 50-000.82/06/28.821000.wd
- --Bi03050787 Discusses 810126 loss of annunciation event at facility Caused by capacitor shorting Licensee will review event at addressed in IE Bulletin 79-27. "Loss of Non-Class IE Instrumentation & Control Power Bus During Operation " CHIRAMAL! M Director's Office 81/01/30 Director's Office ip 15728 002. 24X Fiche. 50-000. 82/06/28, 8210010008
- 8210040426 Forwards request for add1 info re hydrogen control Coordinated util response suggested by mid-Dct 1982.since subj is generic to ice condenser plants W/o encl. NDVAK, T. M. Assistant Director for Licensing 82/09/17 PAPRIERE Tennessee Valley Authority. Ip 15597 251 24% Fiche 50-327, 82/09/17,8210040426
- 8210210542 Notification of 820727 meeting w/licensee in Saddq Dilwy of discuss proposed delays in licensee requirements
 STAHLE: C Licensing Branch 4 82/09/24 ADENBAM 6 0 Licensee
 Branch 4 2pp 15782 328 24X Fiche 50-327, 82/09/24, 821021032.
- 9210120284 Forwards "Executive Summary Rept on Adequacy of Persental Hydrogen Mittigation Sys for Sequeyah Nuclear Plant," in response to RL Tedesco 820413 ltr.
 MILLS.L H Tennesses Valley Authority, 82/09/27 ADENSALE Licensing Branch 4, 1p 15653 078, 24X Fiche: 50-327, 82/09/27, 8210120284

- --P210120289 "Erecutive Summary Rept on Adequacy of Permanent Hydrogen Mitigation Sys for Sequoyah Nuclear Plant " * Tennesser Valley Authority 82/09/30 Sipp 15653 079 24X Fiche 50-327,82/09/27.8210120284
- E21C050216 Informs that updated FSAR will be submitted in Jan 1983, in response to NRC request MILLS, L H Tennessee Valley Authority 82/09/30 ADENSAM, E Licensing Branch 4 ip 15611 236 24X Fiche 50-327, 82/09/30, 8210050216
- 6210190110 Forwards request for add1 info on equipment temp response to Audrogen burns Coordinated util response suggested since subj generic to ice condenser plants ADENSAM.E G Licensing Branch 4 B2/10/01 PARRIS, H 0 Tennessee Valley Authority 4pp 1576/ 226 24X Fiche 50-327, 82/10/01, 62:0190/110
- \$210130150 Forwards add1 info re 820715 application for amend of Licenses DPR-77 % DPR-79 concerning steam generator water level low-low reactor trip setpoint MILLS.L M Tennessee Valley Authority 82/10/07 DENTON.H R Office of Nuclear Reactor Regulation, Director 2pp 15673 082 24X Fiche 50-327.82/10/07.8210130150
- 6210180117 Forwards request for deferral of ASME Section XI requirement to hydrostatically pressure test replacement portions of essential raw cooling water sys Withree oversize drawings Aperture cards are available in FDR MILLS.L M Tennessee Valley Authority 82/10/13 ADENSAM, ELicensing Branch 4 7pp 15718 134 24X Fiche 50-327,82/10/13, 9210180117
- 6210260148 Forwards proprietary response to NRC 820809 request for info re CLASIX code Encl withheld (ref 10CFR2 790) FAMMER. D. S. Tennessee Valley Authority 82/10/18 ADENSAN, E. Licensing Branch 4 1p 15797 055 24X Fiche 50-327, 82/10/18, B210260148
- 8210260228 Forwards revised figures for incorporation into App B. peaking factor limit rept.to reload safety evaluation for Cycle 2 reload operations
 KAMMER.D B Tennessee Valley Authority 82/10/19 DENTGN.H R. Office of Nuclear Reactor Regulation, Director 7pp 15806 317 24X Fiche 50-327, 82/10/19, 8210260228
- Q Inspection reports. IE Bulletins & correspondence
- 5210070007 Responds to FOIA request for eight categories of records resteem generators & steem turbines App A documents provided in R Udell FOIA Request 81-313 Forwards documents listed in App 3 FELTON: / M Division of Rules and Records B2/08/10 LONG, D J Winthrop, Stimson, Putnam & Roberts 9pp 15645-063 24X Fiche 50-000, 82/08/10, 8210070007
- --8210070139 Forwards tabulated data on steam generator insp & maint at facilities Data should be provided to licensees IPPDLITO.T Operating Reactors Assessment Branch 92/04/01 VARGA.S Operating Reactors Branch 1 5pp 15645 131 24X Fishe 50-000.82/08/10.8210070007
- #21DOLO476 Forwards corrected notice of violation revising notice issued w/16 Insp Repts 50-327/82-18 & 50-328/82-18 on 820706-0805

 LEHIGAR C Division of Project & Resident Programs 82/09/17

 PARRIS.H O Tennessee Valley Authority 2pp 15572 172 24X

 Fiche 50-327, 82/09/17, 8210010475
- -8210010477 Corrected notice of violation from insp on 820706-0805 Noncompliance noted activities affecting safety-related function of critical systety-cures & components not accomplished per drawings

 Division of Project & Resident Programs 82/09/17 1p 15572 i74 24X Fiche 50-327,82/09/17.8210010476
- 210010130 Ack receipt of 820830 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-327/82-05 & 50-328/82-05 LEISIS.R C Davision of Project & Resident Programs. 82/09/20 PARRIS.H G Tennessee Valley Authority ip 15566 009 24X Fiche 50-327.82/09/20.8210010130
- -8210010135 Reponds to NRC 820807 ltr re violations noted in IE Insp. Repts 50-327/82-05 & 50-328/82-05 Corrective actions program initiated to schedule temporary employees for training in GA area KAMMER, D. 8. Tennessee Valley Authority 82/08/30. G'REILLY, J. P. Region 2. Office of Director . 3pp. 15566-010. 24X Fiche 50-327,82/07/20,8210010130.

- 8210150225 Act receipt of 820921 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-327/82-14 & 50-328/82-14 LEWIS.R C Division of Project & Resident Programs 82/10/05. PARRIS.H Ø Tennessee Valley Authority ip 15706 061 24X Fiche 50-327,82/10/05.82/0150225
- --8210150231 Responds to NRC 820820 ltr re violations noted in IE Insp Repts 50-327/82-16 & 50-328/82-16 Corrective actions delinquent QA audit findings identified & corrective action escalation program developed MILLS.L H Tennessee Valley Authority 82/09/21 D'REILLY, J P Region 2. Office of Director 5pp 15706.062 24X Fichs 50-327,82/10/05.8210150225
- --8210180237 Forwards IE Insp Repts 50-327/82-16 & 50-328/82-16 on 820712-16 & notice of violation LEMIS:R C Division of Project & Resident Programs 82/08/20 PARRIS:R O Tennesse Valley Authority 2pp 15706 067 24X Fiche 50-327,82/10/05,8210150225
- --8210150245 Notice of violation from insp on 820712-14 * Region 2, Office of Director 82/08/20, 2pp 15706 069 24X Fiche 50-327,82/10/05,8210150225
- --8210150256 IE Insp Repts 50-327/82-16 & 50-328/82-16 on 820712-16
 Noncompliance noted operations QA manual not reviewed by
 QA staff & no measures established to assure that QA
 procedures & revisions implemented
 BELISLE.O A . FREDRICKSON.P . UPRIGHT.C M Division of Engineering
 & Technical Programs 82/08/18 | 12pp | 15706 071 | 24X
 Fiche 50-327,82/10/05.8210150225
- 8208190233 IE Info Notice 80-35, Suppl 1, "Leaking & Dislodged I-125 Implant Seeds " Svc list enc! COBB.L I Division of Fuel Facilities, Materials & Bafaguards. 82/10/06 Consolidated Edison Co of New York 66pp 15761 250 24X Fiche 50-000: 82/10/06.8208190233
- 8208190238 IE Bullstin 82-03, "Stress Corresion Cracking in Thick-Wall, Large-Diameter: Stainless Steel, Recirculation Sys Piging at SWR Plants " Svc list and DEYOUNO, R C Director's Office, Office of Inspection and Enforcement 82/10/14 Consultated Edison Co of New York, 115pp. 15810 125 24X Fiche 50-000, 82/10/14, 8208190238.
- 8210220469 Ack receipt of 821005 ltr informing NRC of steps taken to correct violation noted in JE Insp Repts 50-327/82-19 & 50-328/82-19 LEWIS:R C Division of Project & Resident Programs B2/10/18 PARRIS:H G Tannesses Valley Authority ip 15779 103 24X Fiche 50-327.82/10/18.8210220469
- --8210220474 Responds to NRC 820703 ltr re-violation noted in IC Insp Repts 50-327/82-19 & 50-328/82-19 Corrective actions all affected analysts reminded to record data on TI-37 log sheet per Oassous Effluent Requirements Procedure 81-415 HILLB.L M Tennessee Valley Authority 82/10/05. D'REILLY.JP. Region 2. Office of Director 2pp 19779.104 24X Fiche 50-327,82/10/18.8210220469
- --8210220480 Forwards IE Insp Repts 50-327/82-17 & 50-328/82-17 on 820916-20 & notice of violation VERRELLI, D.M. Division of Project & Resident Programs. 82/09/03 PARRES.H 0 Tennesse Valley Authority 2pp 15777:106 24x Fiche.50-327,82/10/18,8210220469
- --8210220482 Notice of violation from insp on 820814-20 * Division of Project & Resident Programs 82/07/03, ip 15779.108 24% Fiche, 50-327, 82/10/18, 8210220449.
- --8210220485 IE Insp Repts 50-327/82-19 & 50-328/82-19 on 920816-20. Noncompliance noted on 820727, noble gas release rates not recorded on TI-37 log sheet B 35 for all effluent radiation monitors declared inoperable due to power failure. COLLINS, T R , BARRIK P Division of Engineering & Technical Programs 82/09/02 7pp 15779 109 24X Fiche 50-327, 82/10/18, 8210220469
- 8210260245 Forwards IE Safeguards Insp Repts 50-327/82-26 & 50-328/82-26 on 821006-08. No noncompliance noted, VERRELLID Division of Project & Resident Programs, 82/10/22 PARRIS, H 0 Tempsise Valley Authority 2pp 15799 (36, 24X Fiche, 50-327, 82/10/22, 8210260245
- --8210260265 IE Insp Repts 50-327/82-26 & 50-328/82-26 on 821006-08. No honcompliance noted. Major areas inspected: review of security plan & implementing procedure, security organization-mgt/personne1/response. Details withheld (ref 10CFR73, 21). MGGRE:D E.; MGGURE:D.R. Division of Engineering & Technical Programs. 82/10/22 ip 15799. 138 24X Fichs 50-327, 82/10/22, 8210260245

- S Reportable occurrences, LERs & related correspondence
- B21012038D Advises that operator action necessary to protect BtW glants from excessive feedwater transferts B&W plants do not employ high steam generator level turbine or reactor trips to protect against transferts CRESELL.J S Director's Office B0/09/12 MICHELSON.C Director's Office. 34pp 19889 286 24X Fichs 50-327.80/09/12.
- 8210070122 Discusses 810126 loss of annunciation Event began w/loss of non-Class IE sys which supplies power to common annunciators inverter failure caused by capacitor short resulting in two wave-shaping SCR failures CHIRAMAL, M Director's Office 81/01/30 Director's Office 19 15449 003 24X fiche 50-327.81/01/30.8210070122
- 821001000B Responds to FOIA request for 19 categories of documents re nuclear reactor events & safety problems Forwards documents listed in App A FELTON, J. B. Division of Rules and Records 82/06/28 UDELL, R. A Critical Hass Energy Project 15pp 15727 005 24X Fichs 50-000, 82/06/28, 8210010000
- --B010210037 Forwards 800505 memo re underclad cracking in reactor vessel norzies Review re safety aspects & compliance w/Bection IX of ABHE Code concludes that grablem should not be included on generic issues list BAER.R L Safety Program Evaluation Branch 80/07/17 KINTNER.L Licensing Branch 2 ip 15727 175 24% Fiche 50-000, 82/06/28, 8210010008
- --Billi80001 Recommends comprehensive assessment of plant operating conditions to determine specific predetermined time related sequences of occurrence to emergency buses SRP should be revised re design features
 ASHE,F Director's Office Bi/10/16 MICHELBON,C Director's Office App 15731 047 24X Fiche 50-000,82/06/28,8210010008
- --B210010161 Discusses potential problem re Bequoyah reactor pressure noizle supplementing 800222 mamo Underclad cracks found by use of ultrasonic equipment Addi Items of recent origin discussed Related info enci DENTON, HR Office of Nuclear Reactor Regulation, Director B0/02/28 AMERINEJ, OILLINSKY, V, KENNEDY, P Commissioners 9pp 15727 178 24X Fiche 50-000, 82/06/28,8210010008
- 8210080015 Add1 response to FOIA request for 19 categories of info re nuclear reactor events & safety problems Forwards documents listed in App A Documents in App B completely withheld (ref FOIA Exemption 5) FELTON, J M Division of Rules and Records 82/07/12 UDELL, R. A Cribical Mass Energy Project 9pp. 15645 027 24X Fiche 50-000.82/07/12.8210080015
- --820519042B Forwards enginearing evaluation rept, "Inadvartent Loss of Reactor Coolant Events at Begudyah Nuclear Plant.Units 1 & 2 " Rept contains recommendations which should be incorporated in ongoing Task Interface Agresment 81-15 LANNING.H.D Director's Office 82/05/11 HICHELSON.G. Director's Office 10 15876 140 24X Fiche 50-000,82/07/12,8210080015
- --B205190441 "Inadvertent Loss of Reactor Coolant Events at Sequoyah Nuclear Plant; Units 1 & 2," engineering evaluation rept LANNING, W D Director's Gefice. 82/05/31, 23pp 15666-096, 24X Fiche. 50-000, 82/07/12, 9210080015.
- --82:0080197 NRC operations ctr usage chart re events at facilities. 4 NRC - No Detailed Affiliation Given 82/07/12 ip 15648:221, 24X Fiche 50-000,82/07/12,8210080015.
- 8210010108 Forwards LER 82-107/01T-0 GREEN.H J. Tennessee Valley Authority, 82/09/24, O'REILLY, J.P. Region 2. Office of Director, 19. 15566.037, 24X Fiche 50-327,82/09/24,821001018
- --8210010115 LER 82-107/01T-0:an 820911, annulus door (A65) & access door (A64) left open causing both trains of amargency gas treatment sys to be declared inperable. Caused by inoperability of interlocks on doors,
 CARVER, A M , HARDINO, M R Tennessus Valley Authority,
 Region 2, Defice of Director, 3pp. 15546:038 24X
 Fiche. 50-327,82/09/24.8210010108
- 8210060217 Forwards LER 82-111/03L-0 OREEN.H.J. Tennessee Valley Authority 82/07/30, G'REILLY, J.P. Region 2. Office of Director, 1p. 15620:176, 24X Fiche: 50-327, 82/07/30, 8210060217

- --8210060221 LER 82-111/03L-0 on 820903.while in Mode 1, one contain pressure channel for remote shutdown monitoring instrumentation failed to meet surveillance requirements Caused by closed sense line isolation valve RODERS.H R., HARDINO.H R. Tennessee Valley Authority 82/09/3 Region 2. Diffice of Director ip 15620 197 24X Fiche 50-327.82/09/30.8210060219
- 8210130442 Forwards LER 82-108/03L-0 GREEN, H J Tennesses Vailey Authority 82/10/05 D'REILLY, J P Region 2, Office of Director 1p 15681 187 24X Fiche 50-327, 82/10/05, 8210130442
- -8210130452 LER 82-108/03L-0 on 820907, during Mode 1, level channel LT-63-50 on refueling water storage tank declared inoperable Caused by transmitter out of tolerance due to instrument drift Loop receibt ROBERS HR, HARDING HR Tennessee Valley Authority 82/10/0 Region 2, Office of Director ip 15681 188 24X Fiche 50-327,82/10/05,8210130442
- 8210130317 RD 82-003 on 820731, fire detector 74F in fire 20ne 70 alermed due to steam leak in spent resin storage tank area fire zone removed from svc until 820909 Steam leak repaired & zone placed back in svc QREEN, H J Tennessee Valley Authority 82/10/07 O'REILLY, J P Region 2, Office of Director 2pp 15678 341 24% Fiche. 50-327, 82/10/07, 8210130317
- 8210220081 Forwards LER 82-112/03L-0 GREEN,H J Tennesses Valley Authority 82/10/08 O'REILLY,JP Region 2. Office of Director 1p 15779 072 24x Fiche 50-327,82/10/08.8210220081
- --8210220085 LER 82-112/03L-0 on 820911, upper head injection sys faciard inoperable due to failure to meet surveillance requirements. Gaused by total dissolved nitrogen & air in accumulator exceeding 80 std cubic feet limit RODERS, H.R., HARDING, M.R. Tennessee Valley Authority 82/10/08 Region 2. Office of Director 2pp 15779 073 24% Fiche 50-327, 82/10/08, 8210220081
- 8210190712 RO 82-4 on 821012, biological shield blocks removed from equipment hatch for refueling outage, breaching fire barrier penetration Verification of fire detector operability stablished. GREEN H J. Tennessee Valley Authority 82/10/12 D'REILLY, J P Region 2, Office of Director 2pp 15738 139 24X Fiche 50-327, 82/10/12,8210190712
- 8210190378 Forwards LER 82-117/03L-0 OREEN.H J Tennessee Valley Authority 82/10/14 O'REILLY, JP Region 2. Office of Director 1p 13741 216 24X Fiche 30-327, 82/10/14/8210190378
- --8210190386 LER B2-117/03L-0 on 820914: during 81-220 test on five year 18-8 start circuit; time delay setpoint on relay 182 found out of 5% tolerance of 120-s Cause not stated Time delay setpoint readjusted to within 5% tolerance ROMINE.W D., HARDINO.M R. Tennesses Valley Authority 62/10/13 Region 2. Office of Director 1p 15741 217. 24% Fiche 50-327, 82/10/14,8210190378
- 8210290277 Forwards LER 82-116/03L-0 OREEN.H J Tennesse Valley Authority. 82/10/14 G'REILLY, JP Region 2. Office of Director 1p 15853 140 24X Fiche 50-327, 82/10/14/8210290277
- --8210290279 LER 82-116/03L-0 on 820916, both trains of RHR sys inspiral due to inadvertent closing of RHR suction valve 1-FCV-74-2 Caused by removal of power fuses to allow work on output relays RHR pump stopped & valve reopened w/auxiliary power ROOERG.H.R., HARDINGM R Tennessee Valley Authority. 82/10/14 Region 2, Office of Director. 2pp 15853 141. 24X Fiche 50-327, 82/10/14, 8210290277
- DDCKET 50-328 BEQUOYAH NUCLEAR PLANT, UNIT 2

 F. Becurity, medical, emergency & fire protection plans
- 820917006B Forwards revised pages to proposed physical security flat transmitted by 820623 ltr Pages withheld (ref 10CFR2.790). MILLS.L.M. Tennesses Valley Authority 82/09/01. ADENSAME Licensing Branch 4 ip. 14910:105 24X Fiche:50-327, 82/09/01, 820917006B.
- 8210060347 Forwards status rept of mateorological program for review?
 "Sequoyah Nuclear Plant Noucast Hanual."
 MILLS, L. M. Tennesses Valley Authority. 82/10/01. ADENSAME
 Licensing Branch 4. 5pp. 15619:056 24X Fiche: 50-327, 82/10/01,
 8210060347.

- --5210040352 "Sequoyah Nuclear Plant Nowcast Manual"

 * Tennesse valley Authority 82/09/30 70pp 15619 061 24X
 Fiche 50-327,82/10/01.8210060347
- E210280245 Forwards IE Safeguards Insp Repts 50-327/82-26 & 50-323/82-26 on 821006-08 No noncompliance nated CERRELLID Division of Project & Resident Programs 82/10/22 PARRIS.N G Ennessee Valley Authority 2pp 15799-136 24% Fische 50-327, 82/10/22, 8210260245
- P Operating license stage documents & correspondence
- E210040426 Forwards request for add1 info re hydrogen control Coordinated util response suggested by mid-Uct 1982, since subj is generic to ice condenser plants W/o encl AUVAK.T M Assistant Director for Licensing 82/09/17 PARRIS, H Q Tennessee Valley Authority ip 19597 251 24X Fiche 50-327, 82/09/17, 8210040426
- E210120284 Forwards "Executive Summary Rept on Adequacy of Permanent Mydrogen Hitzgation Sys for Sequogah Nuclear Plant," in response to RL Tedesco 820413 Itr HitLES,L M Tennessee Valley Authority 82/09/27 ADENSAM.E Licensing Branch 4 ip 15653 078 24X Fiche 50-327,82/09/27,8210120284
- --8210120289 "Executive Summary Rept on Adequaty of Permanent Hydrogen Mixigation Sys for Sequoyah Nuclear Plant" Fennessee Valley Authority 62/09/30 Sipp 15653 079 24X Fiche 50-327,82/09/27,8210120284
- 3210050216 Informs that updated FSAR will be submitted in Jan 1983, in response to MRC request MILLS.L M Tennessee Valley Authority 82/09/30 ADENSAM.E Licensing Brench 4 ip 15611 236 24X Fiche 50-327, 82/09/30, 8210050216
- 3210190110 Forwards request for add1 info on equipment temp response to hydrogen burns Coordinated util response suggested since tub; generate to ice condenser plants.

 ADEMSAM.E 0 Licensing Branch 4 82/10/01 FARRIS.H 0 Tennessee VAIIey Authority 4pp 15761 226 24X Fiche, 50-327, 82/10/01. 8210190110
- 1210130150 Forwards add1 info re 820715 application for amend of Licenses DPR-77 & DPR-79 concerning steam generator water level low-low reactor trip setpoint MILLS, LK Tennessee Valley Authority 82/10/07 DENTON, HR Diffice of Nuclear Reactor Regulation, Director 2pp, 15673 082 24% Fiche 50-327,82/10/07,8210130150
- (210180117 Forwards request for deferral of ASME Section XI requirement to hydrostatically pressure test replacement portions of essential raw cooling water sys W/three oversize drawings Aperture cards are available in PDR MTLLS,L M Tennessee Valley Authority 82/10/13 ADENSAM,E Licensing Branch 4 7pp 15718 134 24X Fiche 50-327,82/10/13,8210180117
- |210260148 Forwards proprietary response to NRC 820809 request for info rs CLASIX code Encl withheld (rs) 10CFR2 790)
 KAMMER.D 8 Tennessee Valley Authority 82/10/18 ADENSAM, E
 Licensing Branch 4 ip 15799 050 24X Fichs 50-327, 82/10/18, 8210240148
- Imspection reports, IE Bulletins & correspondence
- 210070007 Responds to FDIA request for eight categories of records resteam generators & steam turbines App A documents provided in R Udell FDIA Request 81-313 Forwards documents listed in App B FELYON.J M Division of Rules and Records 82/08/10 LONG, D J. Hinthrop, Stimson, Putnam & Roberts. 9pp 15645.063, 24X Fiche 50-000, 82/08/10, 9210070007.
- -B210070139 Forwards tabulated data on steam generator insp & maint at Pacilities. Data should be provided to licensees IPPOLITUR. To Operating Reactors Assessment Branch B2/04/01 VAROA.S Descripting Reactors Branch i 5pp. 15645-131 24X Fiche-50-000,82/08/10,8210070007

- 8210010474 Forwards corrected notice of violation, revising notice issued w/IE Inep Repts 50-327/82-18 & SO-328/82-18 on 820706-0805
 LENIS,R C. Division of Project & Resident Programs 82/09/17
 PARRIS,H 0 Tennessee Valley Authority 2pp 15572 172 24X
 Fiche 50-327,82/09/17,8210010476
- --8210010477 Corrected notice of violation from insp on 820706-0805
 Noncompliance noted activities affecting safety-related
 function of critical sys, structures & components not
 accomplished per drawings
 # Division of Project & Resident Programs 82/09/17 ip
 15572:174 24X Fiche 50-327,82/09/17,8210010476
- 8210010130 Ack receipt of 820830 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-327/82-05 & 50-328/82-05 LEWIS,R C Division of Project & Resident Programs 82/09/20 PARRIS.H © Tennessee Valley Authority ip. 15566 009 24X Fichs 50-327.82/09/20,8210010130
- --8210010135 Reponds to NRC 820809 ltr re violations noted in IE Insp Repts 50-327/82-05 & 50-328/82-05 Corrective actions program initiated to schedule temporary employees for training in GA area KAMMER. D B Tennessee Valley Authority 82/08/30 O'REILLY, J P Repion 2. Office of Director 3pp. 15566 010 24X Fiche 50-327, 82/09/20, 8210010130
- 8210150225 Ack receipt of 820921 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-327/82-16 & 30-328/82-16
 LEWIS,R.C Division of Project & Resident Programs 82/10/05. PARRIS.H 0 Tennessee Valley Authority 1p 15706:061. 24X Fichs 50-327,82/10/05,8210150225
- --8210150231 Responds to NRC 820820 ltr re violations noted in IE Insp Repts 50-327/82-16 & 50-328/82-16 Corrective actions delinquent GA audit findings identified & corrective action escalation program developed HILLS.L H Tennessee Valley Authority 82/07/21 0'REILLY, J. P Region 2. Office of Director 5pp 15706 062 24X Fiche. 50-327, 82/10/05, 8210150225
- --8210150237 Forwards IE Insp Repts 50-327/82-16 & 50-328/82-16 on 820712-16 & notice of violation LEWIS.R.C Division of Project & Resident Programs. 82/08/20 PARRIS.H O Tennesses Valley Authority 2pp 15706:067. 24X Fiche 50-327, 82/10/05, 8210150225.
- --8210150245 Notice of violation from insp on 820712-16 * Region 2. Office of Director 82/08/20. ≥pp. 15706.069. 24x Fichs 50-327.62/10/05.8210150225.
- --8210150256 IE Insp Repts 50-027/82-16 & 50-028/82-16 on 820712-16 Noncompliance noted operations GA manual not reviewed by GA staff & no measures established to assure that GA procedures & revisions implemented BELISLE.O A., FREDRICKEON.P., UPRIGHT.C N Division of Engineering & Technical Programs. 82/08/18. 12pp 15706.071. 24x Fiche 50-027,82/10/05,8210150225.
- 9208190233 IE Info Notice 80-35, Suppl 1, "Leaking & Dislodged I-128 Implent Seeds " Syc list encl COBB.L I Division of Fuel Facilities, Materials & Safeguerds, 82/10/06 Consolidated Edison Co of New York 66pp. 15761: 280 24X Fiche: 50-000,82/10/06, 8208190233
- 8208190238 IE Bulletin 82-03. "Btress Corroston Cracking in Thick-Wall, Large-Diameter, Stainless Steel, Recirculation Sys Piping at BWR Plants." Svc list encl.
 DEYOUND, R.C. Director's Office. Office of Inspection and Enforcement. 82/10/14. Consolidated Edison Co. of Naw York, 113pp 15810:125 24X Fiche 50-000, 82/10/14, 8298190238
- 8210220469 Ack receipt of 821005 itr informing NRC of steps taken to correct violation nated in IE Insp Repts 50-327/82-19 to 50-328/82-19.

 LEWIS.R C. Division of Project & Resident Programs. 82/10/18. PARRIS.H Q Tainessee Valley Authority. 1p. 15779:103. 24X Fiche. 30-327, 82/10/18. 8210220469
- --8210220474 Responds to NRC 820903 ltm re violation noted in IE Insp. Repts 50-327/82-19 & 50-328/82-19, Corrective actions all affected analysts reminded to record data on TI-37 log sheet per Gaseous Efficient Requirements Procedure 81-415 MILLS.L M Tennessee Valley Authority, 82/10/05, O'REILLY, J.P. Repian 2. Diffice of Director 2pp. 15779-104, 24X Fiche: 50-327, 82/10/18, 8210220469

- --8210220480 Forwards IE Insp Repts 50-327/82-19 & 50-328/82-19 on 820816-20 & notice of violation VERRELLI, D H Division of Project & Resident Programs. 82/09/03 PARRIS, H O Tennessee Valley Authority 2pp 15779 106 24X Fichs 50-327, 82/10/18, 8210220469
- --8210220492 Notice of violation from insp on 820816-20 # Division of Project & Resident Programs 82/09/03 ip 15779 108 24X Fiche 50-327,82/10/18,8210220469
- --8210220485 IE Insp Repts 50-327/82-19 & 50-328/82-19 on E20816-20 Noncompliance noted on B20727.noble gas release rates not recorded on TT-37 log sheet B 35 for all effluent radiation monitors declared inogenable due to power failure COLLINS.T R . BARR.K.P Division of Engineering & Technical Programs 82/09/02 7pp 15779 109 24X Fichs 50-327,82/10/18,8210220469
- 8210260245 Forwards IE Bafeguards Insp Repts 50-327/82-26 & 50-328/82-26 on 821006-08 No noncompliance noted, VERRELLI.D. Division of Project & Resident Programs, 82/10/22 PARRIS, H G Tennessee Valley Authority 2pp 15799 136, 24X Fiche 50-327, 82/10/22.8210260245
- --B210260265 16 Insp Repts 50-327/82-26 to 50-328/82-26 on 821006-08 No noncompliance noted Major areas inspected, review of security plan k implementing procedure; security organization-mpt/personnet/response Details withheld (ref 100FR73 21) MOORE, D.E., MCGUIRE, D.R. Division of Engineering to Technical Programs. 82/10/22 ip 15799.138 24X Fiche 50-327,82/10/22,8210260245
- 8 Reportable occurrences: LERs & related correspondence
- 82100B0015 Add1 response to FOIA request for 19 categories of info re nuclear reactor events & safety problems Forwards documents listed in App A. Documents in App B completely withheld (ref FOIA Exemption 5)
 FELTON, J M Division of Rules and Records 82/07/12 UDELL.R A Critical Mass Energy Project 9pp 15665:027 24X
 Fiche, 50-000:82/07/12,82100B0015
- --8205190428 Forwards engineering evaluation rept. "Inadvertent Loss of Reactor Coolent Events at Sequoyah Nuclear Plant Units 1 & 2 "Rept contains recommendations which should be incorporated in engoing Task Interface Agreement 81-13. LANNING.W D Director's Office 82/05/11. MICHELSON.C Director's Office 1p 15876-140. 24X Fiche.50-000,82/07/12,8210080015
- --B205190441 "Inadvertent Loss of Reactor Coplant Events at Sequoyah Nuclear Plant, Units 1 & 2." engineering evaluation rept LANNING, U D Director's Défice. 82/03/31. 23pp 15666 096. 24X Fiche, 50-000, 82/07/12: 8210080015
- 8210130572 Forwards LER 82-110/03L-0 OREEN.H J. Tennessee Valley Authority 82/10/05 D'REILLY, J P. Region 2. Office of Director 1p 15679:104 24X Fiche 50-328.82/10/05.8210130572

- --8210290094 LER 82-115/01T-0 on 821002, inner & outer doors of upper containment personnel airlock were open simultaneously due to letch ber blocking outer door open Caused by door swing operating chain being out of adjustment, Chain adjusted KTRK.O B , HARDINO,M R Tennessee Valley Authority 82/10/14 Region 2, Office of Director 2pp 15854 010 24X Fiche 50-328,82/10/14,8210290091
- 8210260188 Forwards LER 82-118/03L-0 OREEN.H J Tennessee Valley Authority 82/10/20 O'REILLY, J.P. Region 2, Office of Director ip 15799 032 24X Fichs 20-328.82/10/20,8210260188
- --8210260196 LER 82-118/03L-0 on 820921, diesel generator operability essential raw cooling water valves 1-FCV-67-66 & 68 failed to open on diesel generator 1A-A start signal Caused by circuit breakers being left open during testing ROMINE, W D . HARDING, M R Tennessee Valley Authority. 82/10/20 Region 2, Office of Director ip 15799 033 24X Fiche 50-328,82/10/20.8210260188
- 8210290274 Final rept for Deficiencies B & E & seventh interia rept for Deficiencies A & D re control of procurement activities Initially reported on BIO316 Final corrective actions noted Next rept expected by B30428 MILLS.L M Tennessee Valley Authority 82/10/21 O'REILLY, J.P. Region 2, Office of Director 4pp 15853 143 24% Fiche 50-000, 82/10/21, 8210290274
- DOCKET 50-329 HIDLAND PLANT, UNIT 1
- A Application/construction stage documents & correspondence
- 8207070419 Forwards application for Amend 106 to CP & DL applications, consisting of Revision 44 to FBAR Three hundred ninety-four drawings encl Aperture cards are available in PDR CDGK, J. W. Consumers Power Co. 82/06/28 DENTON, H. R. Dffice of Nuclear Reactor Regulation, Director 2pp 13796 028 24% Fiche 50-329, 82/06/28, 8207070419
- --8207070422 Application for Amend 106 to CF & DL applications, conslett of Revision 44 to FBAR COUK.J W Consumers Power Co 82/06/28 20pp 13796 030 24K Fiche 50-329, 82/06/28, 8207070419.
- 8210080015 Add1 response to FOIA request for 19 categories of information nuclear reactor events & safety problems Forwards documents listed in App A Documents in App B completely withheld (ref. FOIA Exemption 5) FELTON, J M Division of Rules and Records 82/07/12 UDELL, R A Critical Mass Energy Project 9p 15665 027 24% Fiche: 30-000.82/07/12.8210080015
- 8210010437 Provides add1 info to 820812 ltr re cooperative evaluation program w/NRC.per NRC 820720 request Program provides capability for rapid response to NRC concerns & supports near-term approval of Itam II K. 3.30. COOK, J. H. Consumers Power Co. 82/09/10 DENTON, H. R. Division of Licensing. 6pp 13570 205 24% Fiche 50-329, 82/09/10.8210010437
- 8210290228 Forwards Amend 108 to application for CPs & OLs, consisting of Revisions 6 & 3 to security plan & safeguards contingency plan; respectively, Plans withheld (ref 10CFR73 21).

 COOK, J \(\text{Consumers Power Co.} \) 82/09/23 DENTON, H R Division of Licensing 2pp 18853 284 24% Fiche 80-329, 82/09/23, 821020228
- --B210270227 Application for Amend 108 to application for CPs & OLs, consisting of revised drawings for security plan & safeguards contingency plan. Drawings withheld (ref 10CFR73.21)
 COOK J.W. Consumers Power Co. B2/09/28. 1p 15853-286 24X
 Fichs: 50-327, 82/09/23.8210270228.
- 8210220511 Forwards NPPSS 820825 & 0909 & CPC 820812 ltrs re 8kW puners group 820720 meeting w/NRC re resolution of NURED-0737-Item II K. 3.30 on small break LOCA methode Appropriate action should be taken ADENBAM. E O Licensing Branch 4. 82/10/04 SHERON. B. W Reacter Systems Branch. 1p. 15786:091. 24X Fiche: 50-000, 92/10/04, 9210220811
- 8210120276 Forwards independent design adequacy review & "Perforents' Objectives & Criteria for Const Project Evaluations." INPO preliminary rept.
 COOK.J.W. Dute Power Co. 82/10/05, DENTON, H.R. Defice of Nucleil Reactor Regulation, Director KEPPLER, J. G. Region 3, Office of Director. 30pp 15651:322 24X Ficha:50-329, 82/10/05, 8210180276

- -2210120281 "Performance Objectives & Criteria for Const Project Exalvations," preliminary rept & Institute of Nuclear Power Operations 82/09/30 67pp 15651 352 24% Fiche 50-329,82/10/05,8210120276
- RIO100267 Requests additinformentil position on Reg Quide i 58, Revision I, "Qualification of Nuclear Power Plant Insp. Elen & Testing & Audit Personnel"
 ACENSAM.E 0 Licensing Dranch 4 82/10/05 COCK, J W Consumer:
 Power Co 4pp 15746 007 24X Fiche 50-329,82/10/05,8210180267
- PiGl30264 Forwards Amend 109 to application for CPs & OLs, consisting of Revision 45 to FSAR (CCGX.J W. Consumers Power Co. 82/10/07 DENTON, H.R. Office of Ajelear Reactor Regulation, Director 3pp 15676-015 24X Fiche 50~329, 82/10/07, 8210130264
- \$210130266 Amend 109 to application for CPs & OLs, consisting of Pevision 45 to FBAR COCK, J W Consumers Power Co 82/10/11 2pp 15676 018 24X Fiche 50-329,82/10/07,8210130264
- 10150441 Discusses reasons why deletion of requirement for four point proof jacking of feedwater isolation valve pit is essential sert of remedial action to be achieved prior to excavation beneath feedwater isolation valve pit WARNICK.R F Region 3. Office of Director 82/10/08 MILLER.D B Consumers Power Co 2pp 15703 151 24X Fiche 50-329.82/10/08.
- 10190354 Forwards Affidavit of Evc re Amend 109 (Revision 45 to FSAR) to application for CPs & OLs SCALLIVAM,T J Consumers Power Co 82/10/15 DENTON,H R Office of Nuclear Reactor Regulation, Director 3pp 15740 318 24X Fiche 50-329,82/10/15,8210190364
- 10210294 Forwards Revision 1 to NUS-4146, "Analysis of Flammable Concentrations at Midland Nuclear Plant From Natural Gas Pipeline Breaks," in response to NRC 820823 request for
- SOUCK.) H Consumers Power Co 82/10/19 DENTON,HR Office of Nuclear Reactor Regulation, Director 9pp 15764 104 24X Fache 50-329,82/10/19,8210210294
- 8210210301 "Proposed Cas Pipeline Leak Detection Sys " SYONER,M A Stoner Associates. Inc 82/10/12 22pp 15744 112 24X Fiche 50-329,82/10/19,8210210294
- 8210210306 "Analysis of Flammable Concentrations at Midland Nuclear Plant From Natural Gas Pipeline Breaks," Revision i Baven oversize drawings encl Aperture cards available in PDR MATHAN. 8 J. FULFORD, P J. KAISER, 9 D NUS Corp NUS-4146 R01 E-2/10/07 58pp 15764 135 24X Fiche 50-329,82/10/19,8210210294
- NAC Safety Evaluation Report (SER), supple & correspondence
- 10010278 Forwards "Failure Mode & Effects Analysis of Midland Non-Nuclear Instrumentation & Integrated Control Sys." in response to FSAR Questions 30 56-30 97, Info completes review of SER Confirmatory Item 22 COCK.J W Consumers Power Co 82/09/23 DENTON.H R Office of Nuclear Reactor Regulation, Director 2pp 15574.077 24X Fichs 50-329, 82/09/23, 8210010278
- B210010284 "Failure Mode & Effects Analysis of Midland Non-Nuclear Instrumentation & Integrated Control Bys " ENZINNA:R B., WINKG:R W., BWARTZELL,B.D. Babcock & Wilcox Co BAN-1743 82/07/31 61pp 15574.079 24X Fiche.50-329,82/09/23, 8210010278
- 10190520 Forwards proprietary reactor test data per BER. in support of util position re estimates of full power yrs estimated to result in drop in upper shelf energy JH Taylor affidavit enct Test data withheld (ref 100FRZ 790 & 100FRZ 12) COOK.J H Consumers Power Co 82/10/05 DENTON:HR Office of Nuclear Reactor Regulation, Director 7pp. 15735 022 24X Fiche 50-329,82/10/05,8210190520
- LO200099 Natification of 821109 meeting w/util, Stoner Associates & PNUS in Bethesda, MD to discuss SER Open Item 1 re onsite natural gas pipeline.
 HERNAN, R W Licensing Branch 4 82/10/13 ADENBAM, E, 0 Licensing Branch 4 3pp 18767-317. 24X Ficher 50-329, 82/10/13, 8210200099
- g0270039 Notification of 821020 meeting w/util & Summit Nuclear in Bethesde.MD to discuss SER confirmatory Item 26 re independent sefety engineering group HEERNAN.R W. Licensing Branch 4 82/10/19 ADENBAH.E 0 Licensing Branch 4. 3pp. 15836:290 24X Fiche 50-329.82/10/19.8210270039.

- 8210210030 SAFETY EVALUATION REPORT RELATED TO THE OPERATION OF MIDLAND PLANT, UNITS 1 AND 2 Docket Nos 50-329 And 50-330 (Consumers Power Company) **Office of Nuclear Reactor Regulation, Director NUREO-0793 82/10/31 168pp Available at NRC \$9 50 15785 015 24X Fiche 50-329,82/10/31,8210210030
- F Security, medical, emergency & fire protection plans
- 8210130004 Releases public version of nuclear accident apps to emergancy preparedness plan
 FELTON, J M Division of Rules and Records 82/09/23 Docum
 Hanagement Branch 1p 15695 001 24% Fiche 50-329,82/09/23,
 8210130004
- --8210130005 Forwards public version of nuclear accident apps to Bay, Saginaw & Midland County, MI emergency preparedness ptems COOX.J W Consumers Power Co B2/09/08 DENTON,H R Office of Nuclear Reactor Regulation, Director 4pp 15695 002 24X Fiche 50-329,B2/09/23-8210130004
- -8210130007 Public version of nuclear accident apps to Bay, Baginaw & Hidland County, MI emergency preparedness plan From the Power Com 82/09/01 437pp 15695 006 24X Fiche 50-329, 82/09/23, 8210130004
- 8210270228 Forwards Amend 108 to application for CPs & OLs, consisting of Revisions & & 3 to security plan & safeguards contingency plan, respectively Plans withheld (ref 10CFR73 21) COOK, J W Consumers Power Co 82/07/23 DENTON, H R Division of Licensing 2pp 15853 284 24X Fiche 50-329, 82/09/23, 8210290228
- --8210290229 Application for Amend 108 to application for CPs & OLs, consisting of revised drawings for security plan & safeguards contingency plan Drawings withheld (ref 10CFR73 21) IOURICA (1) Consumers Power Co 82/09/28 1p 15853 286 24X Fiche 50-329,82/09/23,8210290228
- 8210080188 Informs that activities performed 820925 considered emergency measures to ensure safe fire protection of facility Remedial stop work order not violated MARNICK, F. Region 3, Diffice of Director 82/10/05 COOK, J.W. Consumers Power Co. 1p. 15640.179 24X Fiche 50-329,82/10/05,921009188. 8210080188
- O Adjudicatory correspondence
- 8210220274 Comments on petition for rulemaking PRM-50-328 re electromagnetic pulse in nuclear power plants Requests that 10CFR30 be amended to require provision for design features for protection against attacks & destructive acts MARSHALL,W H Maplaton Intervenors 82/08/31 Office of the Secretary of the Commission 2pp 15776 066 24X Fiche 50-329, 82/08/31, 8210220294
- 8210040057 Response opposing B Stamiris 820704 motion for partial initial decision on QA adequacy Underpinning excavation work will not be authorized unless NRC satisfied w/util QA proposals Certificate of Svc encl WILCOVE, N Hearing Branch 2 82/09/24 Atomic Safety and Licensing Board Panel 7pp. 15584.223 24X Fiche 50-329,82/09/24,8210040037
- 8210050221 Response to M Binclair resubmitted contention on Table S-3 Contention should be deferred until Commission issues policy statement Centificates of Bvc encl WEST, A. E. Consumers Power Co. WEST, A. E. Isham, Lincoln & Beale 82/09/28 Atomic Safety and Licensing Board Panel Bpp 15609,062 24X Fichs 50-329,82/09/28,8210050221
- 8210050223 Motion to compel M Sinclair to respond to applicant 820830 request for admission of truth of relevant matters of fact or alternatively/to deem matters of fact admitted Cartificate of Svc enci Related correspondence STEPTOE,P. Consumers Power Co. STEPTOE,P. Isham, Lincoln & Beale 82/09/28 Atomic Safety and Licensing Board Panel 5pp. 15410-337. 24% Fiche. 50-327, 82/09/28, 82/0050223
- --8210050229 Request for admission of truth of relevant matters of fact re Contention 5 Cartificate of Evc encl.
 MILLER, M. I Consumers Power Co. MILLER, M. I. Isham, Lincoln & Beale 82/08/30. Sinclair, M. 4pp 15610 344 24X
 Fiche: 50-329, 82/09/28, 8210050223.

- S210050230 Responses apposing B Stamiris 820913 addendum to 820824 cost benefit contention Good cause for late filing not demonstrated Certificate of Svc encl WEST.A E Consumers Power Co WEST.A E Isham, Lincoln & Beals 82/09/28 Atomic Eafsty and Licensing Board Pensl. Spp 15611 019 24% Ficha 50-329,82/09/28.8210050230
- 8210010062 Response apposing M Sinclair resubmitted Contention i Court of Appeals.DC Circust decision does not affect contention deferral Court stayed effect of decision until Commission policy statement issued Certificate of Svc ancl MILCOVE.H N Hearing Branch 2 82/09/29 Atomic Safety and Licensing Board Panel 5pp 15565 004 24X Fiche 50-327,82/09/27,82/0010062
- 8210010254 Memorandum memorializing 820927 telcon re board notification on soils remedial QA procedures that may effect ASLB consideration of B Stamin's motion for partiel initial decision on QA adequacy in soils remedial work HARBOUR. J Atomic Safety and Licensing Board Panel 82/09/29 2pp 18574 058 24X Fiche 50-329.82/09/29,8210010254
- 8210040018 Response to remainder of M Binclair revised contentions based on discovery No objection to Revised Contentions 6,24 & portions of 56 Opposes Contentions 34,43 & portions of 56. W/notice of appearance & Certificate of 8vc. WILCOVE, M N. WRIGHT, N A Hearing Branch 2. 82/09/30 Atomic Safety and Licensing Board Panel. 17pp 15581 280 24x Fiche 50-329,82/09/30,8210040018
- 8210050215 Response to M Sinclair 820920 revised contentions. Set II
 Objects to Contentions 34(a).37 & 43 & portions of
 Contentions & & 57 Util nanconformance rept & Certificate of
 Svc enc!
 STEPTOE.PP. Consumers Power to STEPTOE.PP. Isham, Lincoln &
 Beals. 82/09/30 Atomic Safety and Licensing Board Panel 13pp
 15611 073 24X Fiche 50-327,82/09/30.8210050215
- 8210050238 Forwards changed interrogetories as motion to compel discovery responses, addressing same issues as 820830 interrogatories W/o enci Related correspondence STAMIRIS. 8 Stamiris. 8, 82/09/30 Atomic Safety and Licensing Board Panel. 1p 15609 050 24X Fichs 50-329,82/09/30,8210050230
- 8210050240 Motion to compel answers from util to 820830 revised interrogatories re Contention 1b ASLB 820814 ruling on decommissioning supports need for comparative analysis of decommissioning estimates Related correspondence.

 STAMIRIS, B. Stamiris, B 82/09/30 Abomic Safety and Licensing Board Panel. 3pp 15610,336, 24X Fiche: 50-327,82/09/30,8210050240
- 8210040193 Response opposing M Sinclair resubmitted Contention 56 on etation blackout Contention lacks requisite basis & specificity to stand alone Certificate of Evc encl. BRUNNER, J E. Consumers Power Co. 82/09/30 Atomic Safety and Licensing Board Panel. App. 15614.237, 24X Fiche.50-329,82/09/30,8210060193
- 8210050246 Forwards AJ Boos 820930 revised affidavit, correctly identifying contention as Binclair Contention 6. Bvc list encl. Related correspondence.

 8RUNNER, J E. Consumers Power Co. 82/10/01 STAMIRIB, B. Stamiris, B 3pp 15609-081 24X Fiche, 50-029, 82/10/01, 8210050246
- 8210070378 Objections to util refusal to answer 8 Stamiris
 Interrogatories 6 through 11 & 18 Issues relevant to scope
 of contentions. Heeting should be scheduled to finalize
 decommissioning plans. Related correspondence.
 MARSHALL, H Haplaton Intervenors MARSHALL, H. Harshall, H. H
 82/10/02 Atomic Sefety and Licensing Board Panel. 2pp
 15633 248 24X Fiche: 50-329.82/10/02,8210070398
- 8210070132 Motion to compel util to answer second set of interrogatories based on new info Interrogetories are narrow in scope-based on new info in FES & directly relevant to admitted Contention 3. Related correspondence
 BISHOP, L. L. Sinclair, M. BISHOP, L. L. Bishop, L. E. 82/10/04
 Atomic Safety and Licensing Board Panel 3pp. 15627:043, 24X
 Fiche, 50-329, 82/10/04,8210070132.
- 8210070136 Responses to applicant & NRC 820903 & NRC 820910 responses to M Sincleir revised contentions Limiting Contention 31 to litigation of util compliance w/existing requirements Contention 32 amended.
 BIGHOP.L L. Sinclair.M. BISHOP.L L. Sishop. L.L. 82/10/04.
 Abomic Bafety and Licensing Sperd Panel. 11pp. 15627:020 24X Fiche: 30-327, 82/10/04, 8210070136.

- 8210060229 Order allowing M Sinclair to reply to NRC & util 820930 responses to Sinclair 820920 revised contentions by 821015 B B Stamiris may reply to applicant 820923 & 28 & NRC 820928 responses to Stamiris contention by 921016 BECHHOEFER, C Atomic Safety and Licensing Board Panel 82/10/0: STAMIRIS, B Stamiris, B SINCLAIR, M Sinclair, M 2pp 15620 24X Fiche 50-327, 82/10/05, 8210060229
- 8210070140 Response to request for production of documents BINCLAIR, M Sinclair, M SINCLAIR, M Bishop, L L 82/10/04 4 13527 080 24X Fichs 50-329,82/10/05,8210070140
- 8210080062 Advises that NRC will voluntarily respond to B Stadiria
 M Binclair 820913 & 20 interrogatories, respectively
 Objections to interrogetories for reasons other than
 noncompliance w/10CFR2 720(h) not waived
 WRIGHTIN A Hearing Branch 2 82/10/06 BECHHOEFER.C. IMRBOVG
 COMAN.F.P Atomic Safety and Licensing Board Pamel 2pp
 13643 277 24X Fiche 50~329,82/10/06.8210080062
- 8210130482 Notice of appearance in proceeding Certificate of Svt en STAHL, D M Consumers Power Co STAHL, D M Isham, Lincoln & Bea 82/10/06 4pp 15682 170 24X Fiche 50-327, 82/10/06, 8210330482
- 8210080066 Informs of agreements between perties re NRC request the util not take depositions of listed persons & discovery on M Sinclair & B Stamiris contentions alleging deficiencies in Zack Co GA PATON, W D Hearing Branch 2 82/10/07 BECHOEFER, C., COMAN, F. HARBOUR, J Atomic Safety and Licensing Board Panel 2pp 13643 035 24% Fiche 50-329, 82/10/07, 8210080066
- B210130304 Memorandum memorializing B21006 telcon re issuante of 62 issues to be considered at hearings identification of witnesses, discovery & new contentions
 BECHHOEFER.C Atomic Bafety and Licensing Board Panel 62/10/08 4pp 15678 343 24X Fithe 50-327-82/10/08-9210130304
- 8210130421 Notice of resumption of evidentiary hearings in consolidated CL/OM proceeding on 821027 & continuing on 821028-30 & 1010-05 to extent necessary Hearings to be held in Midland.MI BECHMOEFER.C Atomic Safety and Licensing Board Panel 92/10/09 p 15680 245 24X Fiche 50-329.82/10/08.8210130421
- 8210180212 Response to 8 Stamiris 820730 motion to compel responses revised interrogatories. Util has no objection to responding voluntarily to amended interrogatories Certificate of Byc encl. Related correspondence BRUNNER, J. E. Consumers Power Co. 82/10/12 Atomic Sefety and Licensing Board Panel 3pp 15718 103 24X Fiche 50-329,82/10/1; 8210180212
- 8210200061 Response opposing util 820928 motion to compet response to util 820830 requests for admissions from M Sinclair Sinclair 820914 response raised relevant objections Certificate of Bvc encl Related correspondence 8 IBHO? LL Sinclair. BIGHOP. LL Harmon & Weiss 82/[9/13 Atomic Safety and Licensing Board Panel 5pp 15754.135 24% Fiche 50-329,82/10/13,8210200061
- 8210200054 Roply to NRC & applicant responses to M Sincleir revisef Contentions 6.34:37.43:56 & 37. Contention 6. bases (e), (b) & (d)(4). Contention 43 & Contention 56. Basis 3, withdrawn Certificate of Svc encl
 BISHOP, L L Sinclair M BISHOP, L Harmon & Weiss B2/10/15
 Atomic Sefety and Licensing Board Panel 7pp 15755 076 24K
 Fiche. 50-329. 82/10/15.8210200054
- 8210210970 Response to util 820923 & NRC 820928 response to 8 Statir new contention based on FES. Gross misrepresentation of overall costs & benefits to public represented by cost/benefit analysis demands redress
 STAMIRIS. 8 Stamiris. 8. 82/10/15 Atomic Safety and Licensing Board Panel 9pp 15763.168 24X Fiche: 50-329, 82/10/15.821021637
- 8210200051 Lists sections of SER & BER Suppl 2 NRC will sponsor at testimony re issues to be covered at 821027-1105 heerings Testimony re issues to be addressed during second who hearings will be filed on 821022.
 WILCOVE, N. Heering Branch 2 82/10/18, BECHHOEFER, C. HARBOUR, J. COMAN, F.P. Atomic Befety and Licensing Board Panel 6pp. 15756-042 24% Fichs: 50-329, 82/10/18, 8210200051
- 8210210427 Order extending time until 821026 for Commission to Job le review ALAB-691
 CHILK/8. J Office of the Secretery of the Commission 82/10/18
 Commissioners, ip 15762:271 24X Fichs, 50-329, 82/10/18

- 8210210290 Notice of rescheduled evidentiary hearings for 821115-20 & 22-23 EECHODEFER, C. Atomic Safety and Licensing Board Panel 62/10/19 bs 15745-073 24X Fiche 50-329, 82/10/19, 8210210290
- 6210220381 Response opposing M Sinclair 821004 motion to compel applicant to answer Sinclair second set of interrogatories based on new info Interrogatories vague.incomprehensible & Irrelevant W/Certificate of Svc Related correspondence.
 ERUNNER.J E Consumers Power Co 82/10/19 Atomic Bafety and Licensing Board Panel 14pp 15780 176 24X Fiche 50-329,82/10/19,8210220381
- 8210220322 Memorandum & order rejecting WH Marshall B20910 contentions based on SER & dismissing Contention 5 GER contentions filed late w/o any justification Marshall failed to revise Contention 5 per ASLB 70023 order after FES issued SECHMOEFER.C Atomic Safety and Licensing Board Panel 82/10/20 MARSHALLW H Marshall WH 9pp 15776 029 24X Fiche 50-329, 82/10/20, 8210220322
- P210260364 Forwards LERs as attachments to NRC 820728 responses to M Sinclair interrogatories MFLCOVE.N N Having Branch 2 82/10/25 BISHOP.L L Harmon & Hesss BISHOP.L L Sinclair.M 1p 15804.165 24X Fache 50-329.82/10/25.8210260364
- 12:10260388 Forwards info in response to JW Cook 820914 ltr to H Denton re environ qualification of electrical & mechanical equipment
 WILCOVEM N Hearing Branch 2 82/10/25 BRUNNER, J E Consumers
 Power Go 4pp 15803 344 24X Fiche 50-329,82/10/25,8210260388
- 2:0270161 Order extending time until 821029 for Commission to act to review ALAB-691 CHILK. 8 J Office of the Secretary of the Commission 82/10/26 Commissioners ip 15823 010 24X Fiche 50-329,82/10/26 823 0270161

Utilaty Final Safety Analysis Report (FBAR) & amends

- 207070419 Forwards application for Amend 106 to CP & QL applications, consisting of Revision 44 to FBAR Three hundred ninety-four drawings encl Aperture cards are available in PDR COOK, J H Consumers Fower Co 82/06/28 DENTON, H R Office of Nuclear Resultation, Director 2pp 13796 028 24X Fiche 50-329, 82/06/28, 8207070419
- -8207070422 Application for Amend 106 to CP & GL applications, consisting of Revision 44 to FSAR COOK, J H Consumers Power Co 82/06/28 20pp 13796-030, 24X Fiche 80-329,82/06/28,8207070419
- 9207070428 Revision 44 to FSAR W/394 oversize P&IDs.electrical & instrumentation control drawings.piping isomatrics.revision sheets & facing sheets Aperture cards are evailable in PDR + Cansumers Power Co 82/06/30, 3933pp 13796 038 24X Fichs 50-329,82/06/28.8207070419
- '10130264 Forwards Amend 109 to application for CPs & OLs.consisting of Revision 45 to FSAR COOK.J B Consumers Power Co. 82/10/07 DENTON.H.R. Office of Nuclear Reactor Regulation, Director Spp. 15676.015 24X Fiche 50-329, 82/10/07,8210130264
- 8210130266 Amend 109 to application for CPs & OLs, consisting of Revision 45 to FBAR CODM, J W Consumers Power Co 82/10/11 2pp. 15676 018 24% Fichs: 50-329, 82/10/07, 8210130264
- 8210130267 Revision 45 to FBAR

 # Consumers Power Ca B2/09/30 626pp. 15676.020 24X
 Fiche 50-329, 82/10/07, 8210130264
- 10570364 Forwards Affidavit of Svc re Amend 109 (Revision 45 to FSAR) to application for CPs & OLe
 SULLIVAN, T J Consumers Power Co 82/10/15, DENTON, H. R. Office of Nuclear Reaction Regulation, Director 3pp 19740, 318 24X Fiche: 50-329, 82/10/15, 8210190364

Advisory Committee on Reactor Safeguards reports & correspondence

LO270417 Summary of ACRS Subcommittee on Midland Plant Units 1 & 2 320602 meeting in Washington DC re application for QL & ACRS - Advisory Committee on Reactor Sefeguards 82/08/16 ACRS - Advisory Committee on Reactor Sefeguards 25pp. 15833,287 24X Fiche 50-929.82/08/16,8210270417.

- 8210270433 Summary of ACRS Subcommittee on Midland Plant Units 1 & 2 820520-21 meetings in Midland.MI re application for OL * ACRS - Advisory Committee on Reactor Safeguards 82/08/14 ACRS - Advisory Committee on Reactor Safeguards 78pp 15835 059 24X fiche 50-229:82/08/16.8210270433
- 8210280034 Summary of 266th ACRS mosting on B20603-05 in Washington, DC re Midland OL review, pressure vessel integrity, seismir events in emergency planning, control room habitability & Subcommittee on Energy Research & Production questions * ACRS Advisory Committee on Reactor Safeguards B2/10/08 ACRS Advisory Committee on Reactor Safeguards 40pp 15862 297 24% Fiche 50-329,82/10/08,8210280034

Q Inspection reports. IE Bulletins & correspondence

- 8210080015 Addl response to FDIA request for 19 categories of info re nuclear reactor events & safety problems Forwards documents listed in App A Documents in App B completely withheld (ref FOIA Exemption 5) FELTON.J. H. Division of Rules and Records 82/07/12 UDELL.R.A Critical Mass Energy Project 9 pp 15665 027 24X Fiche. 50-000.82/07/12,8210080015
- ---8203040536 Comments on 011218 corrections to facility assessment contained in NUREG-0834 re hearings & discussion of systematic assessment of license performance Revision to NUREG inappropriate issue classed MOSELEY. N C Systematic Assessment of Licenses Performance Review Group 82/01/04 MESSMAN.R H NRC No Detailed Affiliation Given ip 15668 256 24% Ficher-50-000.82/07/12.8210080015
- --8203040538 Forwards performance element summary for Jul 1979-June 1980 in response to ABLB request for testimony on systematic assessment of license performance in general & facility assessment in particular WESBMAN,R H Director's Office. Office of Inspection and Enforcement 81/12/18 MOSELEY.N C Bystematic Assessment of Licensee Performance Review Group. 2pp. 15648-254 24X Fiche 50-000,82/07/12,8210080015
- --8210080161 Systematic assessment of licensee performance notes re facility evaluation for Jul 1979-June 1980 - NRC - No Detailed Affiliation Given 80/06/30 Spp. 15688 071 24% Fiche \$0-000,82/07/12,8210080015.
- 8210050139 Forwards IE Insp Repts 50-329/82-18 & 50-330/82-18 on 820713-0825 & notice of violation MARNICK, R. F. Region 3, Office of Director 82/09/22, COOK, J W. Consumers Power Co. 2pp 15605, 193 24X Fiche: 50-329, 82/09/22, 8210050139.
- --8210050144 Natice of violation from insp on 820713-0825.
 WARNICK: Region 3. Office of Director 82/09/22 3pp 15605:195 24X Fiche. 30-329,82/09/22. 8210050139.
- --8210050154 IE Insp Repts 50-329/82-18 & 50-330/82-18 on 820713-0825. Noncompliance noted failure to translate requirements into drawings in adequate procedure & failure to accomplish activities in accordance w/drawings GARDNER,R N . LANDSMAN,R B. . 8HAFER,W D Region 3, Office of Director, 82/09/21 7pp 15605-198 24X Fiche-50-329,82/09/22,8210050137
- 8208190233 IE Info Notice 80-35, Suppl 1, "Leaking & Dislodged I-IR5 Implant Seeds," Syc list encl COB5.L I Division of Fuel Facilities, Materials & Safeguards 82/10/06 Consolidated Edison Co. of New York 66pp 15761.230 24% Fichs.50-000.82/10/06.8208190233.
- 8210190739 Forwards IE Insp Repts 50-329/82-20 & 50-330/82-20 on 820820-0920. No noncompliance noted MARNICK: R F Region 3, Office of Director 82/10/06. CDBK, J M Consumers Power Co 2pp 15737,076 24X Fiche 50-329,82/10/06,8210190739
- --8210170750 IE Insp Repts 50-329/82-20 & 50-330/82-20 on 820820-0920, No noncompliance noted Major areas inspected: remedial soils work activities training for soils activities matte used by Zack Go & protective tagging procedures 8UR0E86,8 L., COOK, R.J., QARDNER, R N Region 3, Office of Director 82/10/06. Spp. 15737:078, 24X Fiche:50-329,82/10/06,8210190739
- 9208190238 IE Bulletin 92-03, "Stress Corrosion Cracking in Thick-Wall-Lenge-Diameter: Stainless Steel-Recirculation Bys Piping at SNR Plants "Svc list encl.
 DEYQUNG-R.C Director's Director of Inspection and Exponents 82/10/14. Consolidated Edison Co. of New York.
 115pp 15810-125. 24X Fiche: 50-000, 82/10/14, 8208190238

DOCKFIED HEMS

- 8210260190 Ack receipt of 820930 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-329/82-03, 50-330/82-03, 50-329/82-05, 50-330/82-05, 50-329/82-06 & 30-330/82-06 WARNICK, R F. Region 3, Office of Director 82/10/20 COOK. J W Consumers Power Co ip 15799 025 24X Fichs 50-329,82/10/20, 8210260190
- --8210260195 Responds to NRC 820426,0702 & 22 ltrs re violations noted in IE Insp Repts 50-329/62-03,50-330/82-03,50-329/82-05, 50-330/82-05,50-329/82-05, 50-330/82-06 Corrective actions additionated in initiated since soldier piles installed COOK,J W Consumers Power Co. 82/09/30 KEPPLER,J, 9 Region 3, Office of Director 4pp 15799 026 24X Fiche 50-329,82/10/20,8210260190
- 8210290377 Ack receipt of 820930 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-329/82-07 & 50-330/82-07. When the step is a consumer of the
- --8210290390 Responds to NRC 820715 ltr re-violations noted in IE Insp. Repts 50-329/82-07 & 50-330/82-07 Corrective actions QC will inspect all hangers installed prior to 810101 Sample of hangers installed after 820101 will also be inspected COOK-J W Consumers Power Co 82/09/30 KEPPLER, J @ Region 3, Office of Director ip 15853-009 24X Fiche 50-329,82/10/26,8210290377
- 8210290154 Ack receipt of 821015 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-329/82-06 & 30-330/82-06 WARNICKAR F Region 3, Office of Director 82/10/27 COOK, J W Consumers Power Co. ip 15853 336 24X Fiche 50-329,82/10/27, 2010/20164
- --8210270163 Responds to NRC 820426 ltr re-violations noted in IE Insp. Repts 50-327/82-06 & 50-330/82-06 Corrective actions: complete reinsp of electrical cables expected by end of Apr 1983 CCIOK, J. H. Consumers Power Co. 82/10/15 KEPPLER, J. G. Region 3, Office of Director 2pp 15853, 337 24X Fiche 50-329, 82/10/27, 8210270154
- R. Pariodic operating reports & related correspondence
- 821003024B "QA Program Mgt Corrective Action Repts.Nonconformance Repts.Quality Action Requests & Audit Finding Repts." Aug 1982 * Bechtel Corp 82/08/31 [,427pp 15598:001. 24X Fichs:50-329,82/08/31,8210050248
- 8210080115 Forwards 39th quarterly rept for Oct-Dec 1782, per ALAB-106. COOK.J.W. Consumers Power Co. 82/09/30 DEYOUNG, R. C. Director's Office, Office of Inspection and Enforcement 54pp 15440:024 24X Fichs. 50-329, 82/09/30, 8210080115.
- 8 Reportable occurrences. LERs & related correspondence
- 9210070107 Board Notification 82-94 informs of Zack Co-potential Part 21 rept on HVAC welder record discrepancies.

 NOVAK, T. M. Assistant Director for Licensing. 82/09/16. Atomic Safety and Licensing Board Panel. 4pp. 15649:202. 24X Fichs. 50-329. 82/09/16. 8210070107.
- 8210040337 PNO-III-82-100: on 820924, stop work order issued for angoing preparatory remedial soils work as result of insp which identified problems w/certification testing of GC personnel per confirmatory action its issued on 820927.
 OARDNER,R., 8HAFER,M., WARNICK,R. Region 3, Office of Director, 82/09/27 ip. (5883:130. 24% Fichs: 80-324, 82/09/27, 8210040337.
- 8210050143 Interim deficiency rept re accident temp effects on containment level measurement. Detailed design & analysis of mods continuing. Effort integrated N/Work required to selve SER Confirmatory Issue 16 (1E Bulletin 79-21).
 COOK. J. W. Consumers Power Co. 82/09/28. KEPPLER, J. Q. Ragion 3. Office of Director. 2pp. 15605:165. 24X Fichs: 50-329, 82/09/28. 8210050143.
- 8210240121 Interim Deficiency Rept 82-09 re quality program & mfg deficiency affecting Victoreen radiation monitoring equipment. Initially reported on 820917. Caused by poor workmanship & GA breakdown. Next rept expected by 820107. COOK. J. W. Consumers Power Co. 82/10/15 KEPPLER, J. 9. Region 3. Office of Director. Spp. 18799:068. 24X Fiche: 50-329, 82/10/15. 8210260121.

- 8210280076 Interim Deficiency Rept 9 re underrated terminal strips on Limitorque valve operators initially reported on BiOii5 Underrated terminal blocks replaced w/Marathon 300 series blocks Next rept will be sent by 830131 CODK, J W Consumers Power Co 82/10/22 KEPPLER, J O Region 3, Office of Director 11pp 15837 147 24X Fiche 50-329,82/10/22, 2010280074
- T Hearing transcripts on non-antitrust matters
- 8210130265 Testimony of AJ Hendron re evaluation of ultimate load carrying capacity of diesel generator bldg footings Prof qualifications, supporting documentation & Certificate of Svc encl
 HENDRON, A J Consumers Power Co HENDRON, A J Illinois, Univ of, Urbana-Champaign 82/10/08 119pp 15677 285 24X Fiche 50~327, 82/10/08, 8210130265
- 8210130494 Testimony of AJ Hendron re evaluation of seismic shakedown settlement of diesel generator bldg in event of earthquake Prof qualifications & supporting documentation ent. HENDRON. A J Consumers Power Co HENDRON. A J Illinois, Univ of, Urbana-Champaign 82/10/08 75pp 15684 014 24X Fiche 50-329,82/10/08,8210130494
- --8210130505 Testimony of DF Lewis on behalf of applicant re undergree, piping Affidavit & supporting documentation encl LEMIS.D F Consumers Power Co LEMIS.D F Bechtel Corp 62/10/07 80pp 15684 097 24X Fiche 50-329, 82/10/08,8210130496
- 82:0260527 Testimony of WO Corley re cracking in svc water pump structure CORLEY, W O Consumers Power Co CORLEY, W O Portland Coment Association 82/10/14 Sipp 15804 315 24X Fiche 50-329, 82/10/14.8210260527
- 8210260504 Testimony of A Boos,EM Burke, JP Gould & P Shunmugarel resve water pump structure, Aperture cards available in PDR BOOS, A . BURKE, E M . GOULD, J P . Consumers Pawer Co 82/10/25 80pp 15805 035 24X Fiche 50~329, 82/10/25, 8210260504
- DOCKET 50-330 HIDLAND PLANT, UNIT 2
- A Application/construction stage documents & correspondence
- 8207070419 Forwards application for Amend 106 to CP & OL applications, consisting of Revision 44 to FBAR Three hundred ninety-four oversize drawings enci Aperture cards are available in PDR COOK. J W Consumers Power Co 82/06/28 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 13796-028 24X Fiche: 30-327, 82/06/28, 8207070417
- --8207070422 Application for Amend 106 to CP & DL applications con of Revision 44 to FBAR COOK J.H. Consumers Power Cp 92/06/28 20pp 13796 030 : Fiche: 50-329, 82/06/28, 8207070419.
- 8210080015 Add1 response to FDIA request for 19 cetegories of info nuclear reactor events & safety problems Forwards documents listed in App A Documents in App B completely withheld (ref FOIA Exemption 5). FELTON.J. M Division of Rules and Records 82/07/12 UDELL.R J Critical Mass Energy Project 9pp 15665 027. 24X Fiche: 50-000. 82/07/12:8210080015.
- 8210010437 Provides add1 info to 820812 ltr re cooperative evaluate program w/NRC.per NRC 820720 request Program provides capability for rapid response to NRC concerns & supports near-term approval of Item II K. 3. 30. COOK.J. W. Consumers Power Co. 82/09/10. DENTON.H.R Division Licensing. 6pp. 15570-205 24X Fichs 50-329,82/09/10.821001043
- 8210290228 Forwards Amend 108 to application for CPs & GLs, consists of Revisions 6 & 3 to security plan & safeguards contingency plan, respectively, Plans withheld (ref 10CFR73 21) COOK.J W. Consumers Power Co 82/07/23 DENTON, H. R. Division Licensing. 2pp. 15853-284. 24X Ficher 50-329, 82/09/23, 821029029
- --8210270227 Application for Amend 108 to application for CPs & CLi consisting of revised drawings for security plan & safeguards contingency plan Drawings withheld (ref 10CFR73,21).

 COOK.J.W. Consumers Power Co 82/09/28, ip. 15953-286 241 Fiche: 50-329, 82/09/23, 8210270228.

- \$21022051 Forwards HPPSS \$20825 & 0907 & CPC \$20812 ltrs re B&W camers group \$20720 meeting w/NRC re resolution of MUREO-0737. Item II K 3 30 on small breat LUCA methods Apgropriate action should be taken ADENSAM. E Q Licensing Branch 4 \$22/10/04 \$HERON, B W Reactor Systems Branch 1p 15786 091 24X Fiche 50-000, \$2/10/04. \$220220511
- E210120276 Forwards independent design adequacy review & "Performance Objectives & Criteria for Const Project Evaluations." INPO preliminary rept CCGK.J W Duke Power Co 82/10/05 DENTON.H R Office of Nuclear Reactor Regulation, Director KEPPLER.J O Region J. Office of Director JOpp 1965; 322 24X Fichs 50-329,82/10/05,8210120276
- ~~8210120281 "Performance Objectives & Criteria for Const Project Evaluations," preliminary rept 4 Institute of Nuclear Power Operations 82/09/30 67pp 1565: 352 24X Fiche 50-329, 82/10/05,8210120276
- S210380267 Requests add1 info re util position on Reg Guide 1 58, Revision 1, "Qualification of Nucleer Power Plant Insp. Exam & Testing & Audit Personnel I" ADENSAM.E 9 Licensing Branch 4 82/10/05 COOK.J W Consumer Power Co 4pp 15746 007 24X Fiche 50-327,82/10/05,8210180267
- 5210130264 Forwards Amend 109 to application for CPs & OLs, consisting of Revision 45 to FBAR COCK.J H Consumers Power Co 82/10/07 DENTON.H R Office of Muclear Reactor Regulation, Director 3pp 15676 015 24X Fiche 50-329, 82/10/07,8210130264
- --82101302& Amend 107 to application for CPs & OLs.consisting of Revision 45 to FSAR COOK.J H Consumers Power Co 82/10/11 2pp 15676 018 24X Fiche 50-327,82/10/07.82101302&4
- E210150441 Discusses reasons why deletion of requirement for four point proof jacking of feedwater isolation valve pit is essential part of remedial action to be achieved prior to excavation beneath feedwater isolation valve pit HARNICK.R F Region 3, Office of Director 82/10/08 MILLER.D B Consumers Pawer Co 2pp 15703 151 24X Fiche 50-329,82/10/08. B210150441
- B210210274 Forwards Revision 1 to NUB-4146, "Analysis of Flammable Concentrations at Midland Nuclear Plant From Natural Gas Papeline Breaks," in response to NRC 820823 request for tinfo CODK. J W Consumers Power Co 82/10/17 DENTON, H R Office of Nuclear Reactor Regulation, Director 9pp 15764 104, 24% Fache 50-329, 82/10/19, 8210210274
- --8210210301 "Proposed Gas Pipeline Leak Detection Bys "
 STONER. M A Stoner Associates, Inc 82/10/12 22pp 15764 112
 24X Fiche 50-329,82/10/19,8210210294
- --B210210305 "Analysis of Flammable Concentrations at Midland Nuclear Plant From Natural Que Pipeline Breaks." Revision I Seven oversite drawings encl Aperture cards available in PDR. NATHAN.S J., FULFORD.P J. KAISER.O D NUS COPP NUS-4146 ROI 62/10/07 58pp 15764 135 24X Fiche 50-329,82/10/19,8210210294.
- MRC Safety Evaluation Report (SER), supple & correspondence
- 9250010278 Forwards "Failure Mode & Effects Analysis of Midland Mon-Nuclear Instrumentation & Integrated Control Bys." in response to FARR Guestions 30 56-30 59 Info completes review of SER Confirmatory Item 22 COOK. J & Consumers Power Co. 82/09/23 DENTON, H R Office of Muclear Reactor Regulation, Director 2pp 15574 077 24X Fiche 50-329, 82/09/23, 8210010278
- -8210010284 "Failure Mode & Effects Analysis of Midland Non-Nuclear Instrumentation & Integrated Control Sys " ENZINNAR S., WINKS,R.W., SHARTZELL,S.D. Babcock & Wilcox Co. BAM-1743 82/07/31 41pp 15574 079, 24X Fiche; 50-329, 82/09/23, 8210010278.
- 230190520 Forwards proprietary reactor test data per SER, in support of util position re estimates of full power was estimated to result in drop in upper shelf energy. JH Taylor affidavit encl Test data withheld (ref 10GFR2 790 & 10GFR9, 12) CODK. JH Consumers Power Co 82/10/05 DENTON. HR Diffice of Muclear Reactor Regulation, Director 7pp 15735,022, 24X Fiche 50-329,82/10/05,8210190520
- 210200099 Notification of 821109 meeting w/util, Stoner Associates & ANUS in Bethesda, MD to discuss BER Open Item 1 re onsite natural gas pipeline
 HERNANIR W Licensing Branch 4, 82/10/13, ADENSAM, E 0, Licensin Branch 4 3pp. 18767, 317 24X Fiche 50-329, 82/10/13, 8210200099.

- 8210270039 Notification of 821020 meeting w/util & Summit Nuclear in Bethesds, MD to discuss SER confirmatory Item 26 re independent safety engineering group HERNANA, W Licensing Branch 4 82/10/19 ADENBAM, E 0 Licensing Branch 4 3pp 15836 290 24X Fiche 50-329, 82/10/19,8210270039
- B210210030 SAFETY EVALUATION REPORT RELATED TO THE OPERATION OF MIDLAND PLANT, UNITS 1 AND 2 Docket Nos. 50-329 And 50-330. (Consumers Power Company) BOFFICE OF NUCLEAR Reactor Regulation, Director NUREG-0793 82/10/31 168pp Available at NRC. \$9 50 15785 015 24X Fiche 50-329, 82/10/31, 8210210030
- F Security, medical, emergency & fire protection plans
- 8210130004 Releases public version of nuclear accident apps to emergency preparedness plan FELTON, J M Division of Rules and Records. 82/09/23 Document Management Branch is 15695 001 24X Fiche: 50-329, 82/09/23, 8210130004
- --8210130005 Forwards public version of nuclear accident apps to Bay, Saginaw & Midland County, MI emergency preparedness plans COUK, J H Consumers Power Go 82/09/08 DENTON, H R Office of Nuclear Reactor Regulation, Director 4pp 15695.002 24X Fiche 50-329,82/09/29.8210130004
- --B210130007 Public version of nuclear accident apps to Bay, Baginaw & Midland County, MI emergency preparedness plan * Consumers Power Co B2/09/01 437pp 15695:006 24X Ficha 50-329, B2/09/23, B210130004.
- 8210290228 Forwards Amend 108 to application for CPs & OLs, consisting of Revisions 6 & 3 to security plan & safeguards contingency plan: respectively Plans withheld (ref 10CFR73 21).

 CODK.J W Consumers Power Co 82/09/23 DENTON, H R Division of Licensing. 2pp 15853-284 24X Fiche 50-329, 82/09/23, 8210290228
- --8210270227 Application for Amend 108 to application for CPs & DLs. consisting of revised drawings for security plan & safeguards contingency plan. Drawings withheld (ref 10CFR73 21)
 COOK. J M. Consumers Power Co 82/09/28, ip. 15853 286 24X
 Fiche 50-329, 82/09/23.8210290228
- 8210080188 Informs that activities performed 820725 considered emergency measures to ensure safe fire protection of facility Remedial stop work order not violated MARNICK.R F Region 3. Office of Director 82/10/05 COOK, J W Consumers Power Co. ip 15640 177 24X Fiche 50-327.82/10/05.8210080188
- O Adjudicatory correspondence
- 8210220294 Comments on petition for rulemaking PRM-50-328 re electromagnetic pulse in nuclear power plants. Requests that 10CFR30 be amended to require provision for design features for protection against attacks & destructive acts MARSHALL, W. H. Mapleton Intervenors 92/08/31 Office of the Secretary of the Commission. 2pp. 15776:066 24X Fiche. 50-329. 82/08/31. 8210220294
- 8210040057 Response opposing B Stamiris 820904 motion for partial initial decision on GA adequacy. Underpinning excavation work will not be authorized unless NRC satisfied w/util GA proposals. Certificate of Bvc encl WILCOVE: M N Hearing Branch 2, 82/09/24. Atomic Safety and Licensing Board Panel 9pp. 15584 223, 24X Fiche 50-329.82/09/24, 8210040057
- 8210050221 Response to M Sinclair resubmitted contention on Table 8-3 Contention should be deferred until Commission issues policy statement. Certificates of Svc encl MEST.A E. Consumers Power Co. WEST.A E. Isham, Lincoln & Beele 82/09/28 Atomic Safety and Licensing Board Penel. Bpp. 13609 062. 24X Fiche: 50-329, 82/09/28.8210050221.
- 8210050223 Motion to compal M Binclair to respond to applicant 820830 request for admission of truth of relevant matters of fact or alternatively, to deam matters of fact admitted Certificate of Svc encil Related correspondence.

 STEPTOE.P. Consumers Power Co. STEPTOE.P. Isham Lincoln & Beals. 82/09/28 Atomic Safety and Licensing Board Panel. Spp. 15610.339. 24X Fichar 50-329, 82/09/28, 8210050223.
- ---B210050227 Request for admission of truth of relevant matters of fact re Contention 5 Certificate of Bvc enci.

 MILLER: M. I. Consumers Power Co. MILLER: M. I. Isham, Lincoln & Beale, 82/08/30. Sinclair: M. 4pp. 15610:344. 24X

 Fiche: 50-329,82/09/28:8210050223.

- 8210050230 Responses opposing B Btamiris 620913 addendum to 820824 cost benefit contention Good cause for late filing not demonstrated Certificate of Svc encl WEBT.A E Congumers Power Co WEBT.A E Isham, Lincoln & Beale 82/09/28 Atomic Safety and Licensing Board Panel Spp 18611 019. 24X Fichs 50-329,62/09/28,6210050230
- 8210010062 Response opposing M Sinchair resubmitted Contention I Court of Appeals.DC Circuit decision does not affect contention deferral.Court stayed effect of decision until Commission policy statement issued Certificate of Syc encl WILCOVE.H N Hearing Branch 2 82/09/29 Atomic Bafety and Licensing Board Panel 5pp 15545 004 24X Fiche 50-329,82/09/29,8210010062
- 8210010254 Hemorandum memorializing 820927 telcon re board notification on soils remedial GA procedures that may affect ASLB consideration of B Stamiris motion for partial initial decision on GA adequacy in soils remedial work MARBOURLJ Atomic Bafety and Licensing Board Panel 82/09/29 2pp 15574 058 24X Fiche 50-327,82/09/29,8210010254
- B21004001B Response to remainder of M Sincleir revised contentions based on discovery No objection to Revised Contentions 6,34 & portions of 36 Opposes Contentions 34,43 & portions of 56 W/notice of apparance & Certificate of 5Vc, WILCOVE, M N. WRIGHT, N. Hearing Dranch 2 B2/09/30 Atomic Sifety and Licensing Board Panel 17pp 15581 280 24% Fiche 50-329,82/09/30,8210040018
- 8210050215 Response to M Sinclair 820920 revised contentions, Set 11
 Objects to Contentions 34(a),37 & 43 & partions of
 Contentions 5 & 57 Util nonconformance rept & Certificate of
 Svc encl
 Steptoe,PP Consumers Power Co STEPTOE,PP Isham, Lincoln &
 Beals 82/07/30 Abomic Sefety and Licensing Board Panel 13pp,
 15611:073 24X Fiche \$0-329,82/09/30,8210050215
- 8210050238 Forwards changed interrogatories as motion to compel discovery responses, addressing same issues as 820820 interrogatories M/o encl Related correspondence STAMRIG. 8. Stamiris, B. 82/09/30 Atomic Safety and Licensing Board Panel. 19 15609.050 24X Piche 50-329,82/09/30,8210050238
- 8210050240 Motion to compel answers from util to 820830 rayised interrogatories re Contantion ib ASLB 820814 ruling on decommissioning supports heed for comparative analysis of decommissioning estimates. Related correspondence STAMIRIS. 8 tamiris. B 82/09/30 Atomic Safety and Licensing Board Panel 3pp 13610:038 24X Fiche: 50-327, 82/09/30,8210050240
- 82:0060193 Response apposing M Binclair resubmitted Contention 56 on station blackout Contention lacks requisite basis & specificity to stand alone Certificats of 8vc encl BRUNNER.J E. Consumers Power Co 82/09/30 Atomic Safety and Licensing Board Panel. App 13614 237 24X Fiche.50-329,82/09/30, 6210040193
- 8210050246 Forwards AJ Boos 820930 revised affidavit, correctly identifying contention as Binclair Contention 6 Svc list entl. Related correspondence BRUNNERIJ. E Constymens Power Co. 82/10/01 STAMIRIS. B. Stamiris, B. 3pp. 15609 081 24X Fiche 50-329, 82/10/01, 8210050246
- 8210070378 Objections to util refusal to answer B Stamiris
 Interrogatories & through il & 18 Issues relevant to scope
 of contentions. Heeting should be scheduled to finelite
 decommissioning plans. Related correspondence.
 MARSHALL, W H Haplaton Intervenors. HARSHALL, W. H. Harshell, W. H.
 82/10/02. Atomic Sefety and Licensing Board Penel. 2pp.
 13633.248 24X Fiche.50-329,82/10/02.8210070398
- 8210070132 Motion to compel util to enswer second set of interrogatories based on new info Interrogatories are narrow in scope, based on new info in FES & directly relevant to admitted Contention 5. Related correspondence.

 BISHOP, L. L. Sinclair, M. BISHOP, L. L. Bishop, L. B2/10/04. Atomic Safety and Licensing Board Panel. 3pp. 13627:043 24X Fiche 50-327, 82/10/04.8210070132.
- 8210070134 Responses to applicant & NRC 820903 k NRC 820910 responses to M Sincleir revised contentions. Limiting Contention 31 to litigation of util compliance w/existing requirements. Contention 32 amanded 8184007. L. L. Sincleir. M. BIBHOP. L. L. Bibhop. L. L. B2/10/04. Atomic Safety and Licensing Soard Panel. 11pp. 15627:020 24X Fichs: 50-329, 82/10/04, 8210070196.

- 6210060227 Order allowing M Sinclair to raply to NRC & util 620930 rasponses to Sinclair 620920 revised contentions by 821015 B Stamiris may raply to applicant 820923 & 28 k NRC 620928 responses to Stamiris contention by 821015 BECHDEFER.C Atomic Safety and Licensing Board Penel 92/10/05 STAMIRIS B. Stamiris B SINCLAR.M Binclair, M 2pp 15620 010 24X Fichs 50-329.82/10/05.8210060229
- 8210070140 Response to request for production of documents.

 81NCLAIRM SinclairM BinclairM Bishop, L 82/10/06
 15827.080 24X Fiche 50-329,82/10/06,8210070140
- B2100B0062 Advises that NRC will voluntarily respond to B Stamiris & K Sinclair 820913 & 20 interrogatories, respectively Objections to interrogatories for reasons other than noncompliance w/10CFR2 720(h) not waived WRICHTIN A Hearing Branch 2 82/10/06 BECHNOEFER, C. HARBOUR, J. COMAN, F.P. Atomic Safety and Licensing Board Panel 2pp 15643:277 24% Fiche 50-329,82/10/06,82100B0062
- 8210130492 Notice of appearance in proceeding Certificate of Svt Intl STAHL, D M Consumers Power Co. STAHL, D M Isham, Lincoln & Beale 82/10/06, 4pp 15682 170 24X Fiche 50-329,82/10/06,8210130492
- 8210080066 Informs of agreements between parties re NRC request that util not take depositions of listed persons & discovery on M Bincleir & B Stamiris contentions alleging deficiencies in Zack Co GA PATON:N D Hearing Branch 2 82/10/07 BECHHOEFER.C., COMAN:F P. HARBOUR.J Atomic Safety and Licensing Board Pane) 2pp 15643 035 24% Fiche 50-327,82/10/07.8210080066
- 82i0130304 Hemorandum memorializing 82i004 telcon re issuance of BER. issues to be considered at hearings, identification of witnesses discovery & new contentions 8ECH-HOEFER.C Atomic Sefety and Licensing Board Panel 62/10/03 4pp 15678 343 24X Fichs 50-329,82/10/08,8210130304
- 8210130421 Notice of resumption of evidentiary hearings in consolidated DL/OH proceeding on 821027 & continuing on 821028-30 & 1010-05, to extent necessary Hearings to be held in Midland, MI BECHHOEFER, C Atomic Bafety and Licensing Board Pane) 82/10/08 pt 19580 245 24K Fiche 50-327, 82/10/08, 8210130421
- 8210180212 Response to B Stamiris 820930 motion to compal responses to revised interrogatories. Util has no objection to responding voluntarily to amended interrogatories. Certificate of Svc enci Related correspondence BRUNNER. J. E. Consumers Power Co. 82/10/12. Atomic Safety and Licensing Board Panel 3pp 15718 103 24% Fiche 50-329.82/10/12 6210180212
- 8210200051 Response opposing util 920928 motion to compal response to util 820830 requests for admissions from M Binclair Binclair 820914 response raised relevant objections Certificate of 820914 response raised relevant objections Certificate of 820914 response raised relevant objections Certificate of 820914 Buc Binclair, M BIGHOP, L L Harmon & Weiss 82/10/13 Atomic 8afety and Licensing Board Penel. Spp 13734-133 24% Ficher 30-329, 82/10/13, 82/0200061,
- 9210200054 Reply to NRC & applicant responses to M Binclair rivised Contentions 5.34,37,43,56 & 37 Contention 6.5ases (a),fb) & (d)f4).Contention 43 & Contention 56 Basis 3.withdrawn Certificate of Svc encl
 BISHOP.L L Binclair.M. BISHOP.L L Harmon & Heise 82/10/15
 Atomic Bafety and Licensing Board Panel 7pp 15755.076 24X
 Fiche: 50-327,82/10/15,8210200054.
- S210210370 Response to util 820923 & NRC 820928 rasponse to B Steely, new contention based on FES Orots misrepresentation of overall costs & benefits to public represented by cost/benefit analysis demands redress STAMIRIS.B. Stamiris. B 82/10/15 Atomic Sefety and Licensing Board Panel 9pp. 13763-168 24X Ficher 50-029, 82/10/15,8280210370
- 8210200051 Lists sections of BER & BER Suppl 2 NRC will spontes as testimony reliesues to be covered at 821027-1105 hearings. Testimony reliesues to be addressed during second whof hearings will be filed on 821022.

 MILCOVE.M.N. Hearing Branch 2, 82/10/18 BECHDEFER, C. HARBOUR, J. COMAN.F. F. Atomic Safety and Licensing Board Pappl dpp 13756:042 24X Fiche:50-329,82/10/18,8210200031
- 8210210427 Order extending time until 821026 for Commission to act to review ALAB-671. CHILK.B.J Office of the Secretary of the Commission 82/10/18 Commissioners. 1p. 15762:271 24X Fiche: SO-329.82/10/18. 8210210427.

- 8210210290 Notice of rescheduled evidentiary hearings for 821115-20 & 22-23 BECHHOEFER, C Atomic Safety and Licensing Board Panel 82/10/19 1p 15765 073 24% Fiche 50-329,82/10/19,8210210290
- 8210220381 Response opposing M Sinclair 921004 motion to compel applicant to answer Sinclair second set of interrogatories based on new info Interrogatories vague, incomprahensible & erralevant H/Certificate of Svc Related correspondence
 SRUNNERJE Consumers Power Co 82/10/19 Atomic Safety and
 Licensing Board Panel 14pp 15780 176 24X Fiche 50-329,82/10/19,
- 8210220322 Memorandum & order rejecting WH Marshall 820910 contentions based on SER & dismissing Contention 5 SER contentions filed late u/o any justification Marshall failed to revise Contention 5 per ASLB 790223 order after FEB Issued BECHNOFFER, C Atomic Safety and Licensing Board Panel B2/10/20 MARSHALL, W H Marshall, W H 79p 15776 029 24X Fiche 50-329, 82/10/20,8210220322
- 8210260364 Forwards LERs as attachments to NRC 820728 responses to M Sinclair interrogatories HILCOVE, MN Hearing Branch 2 82/10/25 DISHOP, L L Harmon & Heiss BISHOP, L Sinclair, M ip 15804 145 24X Fiche 50-329, 82/10/25, 8210240344
- 8210260388 Forwards info in response to JW Cook 820914 ltr to H Denton re environ qualification of electrical & mechanical equipment N Hearing Branch R 82/10/25. BRUNNER, J E Consume 4pp 15803 344 24X Fiche 50-327,82/10/25,8210260388 Power Co
- 8210270161 Order extending time until 821029 for Commission to act to review ALAB-691
 CHILK.S J Office of the Secretary of the Commission 82/10/26
 Condissioners ip 15823 010 24X Fiche 50-329,82/10/26
- K Utility Final Safety Analysis Report (FBAR) & amends
- G207070419 Forwards application for Amend 106 to CP & QL applications, consisting of Revision 44 to FSAR Three hundred ninety-four drawings and Aperture cards are available in FDR COUK. J H Consumers Power Co. 82/06/28 DENTON. H R Office of Nuclear Reactor Regulation, Director 2pp. 13776 028 24X Fiche 50-329, 82/06/28, 8207070419
- --820707042B Revision 44 to FBAR W/394 oversize P&IDs, electrical & instrumentation control drawings, piping isometrics, revision sheets & Facing sheets Aperture cards are evaluable in PDR < Consumers Power Co. 82/06/30 3983pp 13796,03B 24X Fiche 50-329,82/06/28,8207070419
- 8210130264 Forwards Amend 109 to application for CPs & OLs. consisting of Revision 45 to FBAR CORN.J R CONSUMERS OF SEVEN CONSUMERS OF SEVEN SEVEN CORN.J R CONSUMERS Power Co 82/10/07 DENTON,H R. Office of Ruclear Reactor Regulation, Director Spp. 15676-015. 24X Fiche 50-329,82/10/07.6210130264
- --0210130247 Revision 45 to FSAR
 * Consumers Power Co 82/07/30
 Fiche 80-329,82/10/07,8210130264 626pp, 15676.020 24X
- 6210190364 Forwards Affidavit of Svc re Amená 109 (Revision 45 to FSAR) to application for CPs & OLs

 SULLIVAN, T J Consumers Power Co 62/10/15 DENTON, H. R Qffice of Nuclear Reactor Regulation, Director 3pp 15740 318, 24X Fiche 50-329, 82/10/15, 8210190364
- O Advisory Committee on Reactor Safeguards reports & correspondence
- 8210270417 Summary of ACRS Subcommittee on Midland Plant Units 1 & 2 870602 meeting in Mashington DC = application for OL 870602 meeting in Mashington DC = application for OL 8 ACRS - Advisory Committee on Reactor Safeguards 82/08/16 ACRS - Advisory Committee on Reactor Safeguards 25pp, 1583: 24% Fiche 50-329,82/08/16,8210270417. 15833:297
- 8210270433 Summary of ACRS Subcommittee on Midland Plant Units 1 & 2 820520-21 meetings in Midland, MI re application for OL * ACRS Advisory Committee on Reactor Safeguards. 82/08/16 ACRS Advisory Committee on Reactor Safeguards. 78pp 15835 059 24% Fichs 50-329,82/08/16,8210270433
- B210280034 Summary of 266th ACRB meeting on B20603-05 in Washington.DC re Midland OL review.pressure vessel integrity.seismic events in emergency planning.control room habitability & Subcommittee on Energy Research & Production questions = ACRB Advisory Committee on Reactor Bafeguards 82/10/08. ACRS Advisory Committee on Reactor Bafeguards 82/10/08. 24X Fiche.50-329.82/10/08.8210280034.

G inspection reports, IE Bulletins & correspondence

- 8210080015 Addi response to FDIA request for 19 categories of info re nuclear reactor events & safety problems Forwards documents listed in App A Documents in App B completely withheld (ref FOIA Exemption 5). Folia Exemption 5). FELTON, J.M. Division of Rules and Records 82, Critical Mass Energy Project 9pp 15665 027 Fiche 50-000, 82/07/12, 9210080015
- --8203040536 Comments on Bii2iB corrections to facility assessment contained in NUREO-0834 re hearings & discussion of systematic assessment of license performance Revision to NUREO inappriate Issue closed MOBELEY. N.C. Systematic Assessment of Licensee Performance Rev MOSELEY.N C Systematic Assessment of Licensee Performance Review Group 82/01/04 WESSMAN, R H NRC - No Detailed Affiliation Given ip 15468 256 24X Fithe 50-000.82/07/12,8210080015
- --8203040538 Forwards performance element summary for Jul 1979-June 1980 in response to ASLB request for testimony on systematic assessment of license performance in general & facility assessment in particular.

 WEBSHAM,R H Director's Office, Office of Inspection and Emforcement 81/2/19 MOSELEY,N C Systematic Assessment of Licensee Performance Review Oroup 2pp 15668 254 24X Fiche 50-000,82/07/12,8210080015
- --8210080161 Systematic assessment of licenses performance notes re facility evaluation for Jul 1979-June 1980 * NRC No Detailed Affiliation Given 80/06/30 Spp 15868 071 24X Fiche 50-000,82/07/12,8210080015
- 8210050139 Forwards IE Insp Repts 50-329/82-18 & 50-330/82-18 on 820713-0825 & notice of violation WARNICK: R. Region 3. Office of Director 82/09/22 CQQX, J W. Consumers Power Co 2pp 15605 193 24X Fiche 50-329, 82/09/22, 8210050139
- --B210050146 Notice of violation from insp on 820713-0825, WARNICK.R F. Region 3, Office of Director 82/09/22 3pp 15505 195 24X Fiche 50~329,82/09/22,8210050139
- --8210050154 IE Insp Repts 80-329/82-18 & 50-330/82-18 on 820713-0825 Noncompliance noted, Failure to translate requirements into drawings, inadequate procedure & failure to accomplish activities in accordance w/drawings OARDNER, R N , LANDSHAN, R B , SHAFER, W D Region 3, Office of Director 82/09/21 7pp 15605 198 24X Fiche, 50-329, 82/09/22, 8210050137
- 8208170233 IE Info Notice 80-35, Suppl 1, "Leaking & Disloyed I-125 Implant Seeds "Byc list encl COBB.L I Division of Fuel Facilities, Materials & Safeguards, 82/10/06 Consolidated Edison Co of New York 66pp 15761:250 24X Fiche 50-000.82/10/06.8208190233
- 8210190739 Forwards IE Insp Repts 50-329/82-20 t 50-330/82-20 on 820820-0920 No noncompliance noted HARNICK, R.F. Region 3, Office of Director 82/10/06 C00K, J M Consumers Power Co 2pp 15737 076 24X Fiche: 50-329, 82/10/06.
- --8210190750 IE Insp Repts 50-329/82-20 & 50-330/82-20 on 820820-0920 No noncompliance noted Major areas inspected: remedial soils work activities training for soils activities matts used by Zact Co & protective tagging procedures BURGESG.B L , COOK,R J., OARDNER,R N Region 3, Office of Director 82/10/06 5pp 15737 078 24X Fiche 50-329,82/10/06,8210190739.
- 8208190238 IE Bulletin 82-03, "Stress Corrosion Cracking in Thick-Wall-Large-Diameter, Stainless Steel, Recirculation Sys Piping at BWR Piants " Svc list encl.
 DEYQUNG, R.C. Director's Office, Office of Inspection and Enforcement. 82/10/14. Consolidated Edison Co. of New York 195pp 15810 125. 24% Fiche. 50-000, 82/10/14, 8208190838
- 8210260190 Ack Peceipt of 820930 ltr informing NRC of steps taken to correct violations noted in IE lnsp Repts 50-329/82-03, 50-329/82-05, 50-330/82-05, 50-329/82-06 & 50-337/62-04. Solution 3, Office of Director. B2/10/20. COOK, J W HARRICK.R F. Region 3, Office of Director. B2/10/20. COOK, J W Consumers Power Co. 1p. 15797.025. 24X Fiche 50-329.82/10/20,
- -8210260195 Responds to NRC 820426.0902 & 22 ltrs re violations noted in IE Insp Repts 50-329/82-03.50-330/82-03.50-329/82-05.50-329/82-06 & 50-330/82-06. Corrective actions: addi controls initiated since soldier piles installed. COCK, J. W Consumers Power Co 82/09/30. KEPPLER, J Q. Region 3, Office of Director. App. 15799.026, 24% Fiche: 50-329,82/10/20, 8210250170

1.

H

1.

15

-

- 8210290377 Ack receipt of 820930 ltr informing NRC of eteps taken to correct violetions nated in IE Insp Repts 30-329/82-07 & 50-329/82-07 WARNICK, R.F. Region 3, Office of Director 62/10/26 COOK, J.W. Consumers Power Co. Ip. 15853-008 24X Fiche 50-329, 82/10/26, 8210290377
- --8210290380 Responds to NRC 820715 ltr reviolations noted in IE Insp. Repts 50-329/82-07 & 50-330/82-07, Corrective actions GC will inspect all hengers installed prior to 810101. Sample of hengers installed after 820101 will also be inspected COOK. J H Consumers Power Co. 82/09/30 KEPPLER. J O. Region 3. Office of Director ip 15853 009 24x Fiche 50-329,82/10/26. 8210920377
- 8210290154 Ack receipt of 821015 ltr informing NRC of steps teken to correct violations noted in IE Insp Repts 50-329/82-06 & 50-329/82-06 MARNICK, R F Region 3, Office of Director 82/10/27 COOK, J H. Consumers Power Co
- --B210270163 Responds to NRC B20426 itr re-violations noted in IE Insp Repts 50-327/B2-06 & 50-330/B2-06 Corrective actions: complete reinsp of electrical cables espected by end of Apr 1983 COOK, J. H. Consumers Power Co. 82/10/15 KEPPLER, J. Q. Region 3, Office of Director 2pp 15653, 337 24X Fiche: 50-329, 82/10/27, 8210270154.

R Pariodic operating reports & related correspondence

- 8210050246 "9A Program Mgt Corrective Action Repts, Nonconformance Repts, Quality Action Requests & Audit Finding Repts." Aug 1982
- * Bechtel Corp 82/08/31 1,427pp 15598 001 24X Fiche, 50-329, 82/08/31,8210050248
- 8210080115 Forwards 37th quarterly rept for Oct-Dec 1782, per ALAB-106 COOK, J. W. Consumers Power Co., 82/09/30, DEYOUNG, R.C. Director's Office, Office of Inspection and Enforcement 54pp 19640 026 24X Fiche 50-327, 82/09/30, 8210080115
- S Reportable occurrences. LERs & related correspondence
- 8210070107 Board Notification 82-94 informs of Zack Co potential Part 21 rept on HVAC welder record discrepancies. NOVAK,T N Assistant Director for Licensing 82/09/16 Atomic Bafety and Licensing Roard Panel 4pp. 15649 202 24X Fiche 50-329, 82/09/16,8210070107
- B210040337 PNO-III-B2-100 on B20924:stop work order issued for ongoing preparatory remedial soils work as result of insp which identified problems wicestification testing of QC personnel per confirmatory action lit issued on B20927 OARDNER.R. BHAFER.H. HARNICK.R. Region 3. Office of Director. B2/09/27. 1p 15983-130 24X Fiche.50-329.82/09/27, B210040337.
- 8210050143 Interim deficiency rept re accident temp effects on containment level measurement Detailed design & analysis of mode continuing, Effort integrated w/work required to solve BER Confirmatory Issue 16 (16 Bulletin 79-21).

 COOK, J. W. Consumers Power Co. 82/09/28, KEPPLER, J. O. Region 3, Office of Director 2pp. 15605 165 24X Fiche. 50-329, 82/09/28, 8210050143.
- 8210260121 Interim Deficiency Rept 82-09 re quelity program k mfg deficiency affecting Victoreen radiation monitoring equipment. Initially reported on 820917, Caused by poor workmanship & 64 breakdown Next rept expected by 820107 COCK, J W Consumers Power Co 82/10/15 KEPPLER, J O Region 3, Office of Director 8pp. 15799 068 24X Fiche. 50-329, 82/10/15, 8210260121.
- 8210280076 Interim Deficiency Rept 9 re underrated terminal strips on Limitorque velve operators Initially reported on 810115 Underreted terminal blocks replaced W/Marathon 300 series blocks. Next rept will be sent by 830131 COUK.J W. Consumers Power Co. 82/10/22 KEPPLER.J O. Region 3. Office of Director. 11pp. 15837 147. 24X Fiche 50-329,82/10/22,821028076.

T Hearing transcripts on non-antitrust matters

8210130265 Testimony of AJ Hendron re evaluation of ultimate load carrying capacity of diesel generator bldg footings. Prof qualifications, supporting documentation & Certificate of Svc encl.

HENDRON, AJ. Consumers Power Co HENDRON, A.J Illinois, Univ of, Urbane-Champaign 82/10/08 119pp, 15677:285, 24X
Fiche: 50-329, 82/10/08, 8210130265

- 8210130494 Testimony of AJ Hendron re evaluation of saismic shakedown sattlement of dissel generator bldg in event of sarthqueic Prof quelifications & supporting documentation ent HENDRON. A J Consumers Power Co HENDRON. A J Illinois, Univ cf. Urbana-Champaign 82/10/08 75pp 15684 014 24% Fiche 50-329,82/10/08,8210130494
- --B210130505 Testimony of DF Lewis on behalf of applicant re undergrowt piping Affidavit & supporting documentation encl LEMIB, D F Consumers Power Co LEMIB, D F Bechtel Corp B2/10/07 80pp 15684 077 24X Fiche 50-329.62/10/08.B210130494
- B210260527 Testimony of WO Corley re cracking in svc water pump structure CGRLEY.W O Consumers Power Co CGRLEY.W O Portland Cament Association 82/10/14 81pp 15804 315 24X Fichs 50-329, 82/10/14,8210260527
- 8210260504 Testimony of A Boos, EM Burke, JP Gould & P Shunmugarel resvouster pump structure Aperture cards available in PDR 8008, A : BURKE, E M : GOULD, J P Consumers Power Co 62/10/25 8009. 15805-035 24X Fiche 50-327, 82/10/25, 8210260504
- DOCKET 50-331 DUANE ARNOLD ENERGY CENTER

 F Security, medical, emergency & fire protection plans
- 8210120392 Releases public version of emergency response organization notification list FELTON.J M Division of Rules and Records 82/09/24 Decument Management Branch 1p 15691 108 24X Fiche 50-331,82/09/24,8210120392
- --8210120399 Forwards public version of emergency response organiializa notification list Encl list should be incorporated into Emergency Plan Implementing Procedure EPIP 1 2
 MEYER.K A Jows Electric Light & Power Co 82/09/13 DENION.H \$
 Office of Nuclear Reactor Regulation, Director 15pp 15691.109
 24X Fichs 30-031:82/09/24.8210120392
- 821005030B Forwards IE Bafeguards Insp Rept 50-331/82-10 on 020421-25 & notice of violation 4/a notice of violation MLLER.J R. Division of Engineering & Technical Programs 82/07/29 ARNOLD D lows Electric Light & Power Co 2pp 15610 090 241 Fiche. 50-331.82/09/29.8210050308
- --8210050311 IE Bafeguards Insp Rept 50-331/82-10 on 820621-25 Noncompliance noted failure to maintain adequate detection aids & to provide adequate access control Details withheld (ref 10DFR73 21) CHRIBTOFRR, 0, CREED, J R Region 3, Office of Director 82/09/27 2pp 15410 092 24% Fiche 50-331,82/09/29,8210050008
- 8210260461 Confirms rescheduling of 1983 annual exercise to 821027 RODT/L D. Iowa Electric Light & Power Co. 82/10/12 KEPPLER.J 9 Region 3. Office of Director 1p. 15806.223 24X Fiche.50-331.82/10/12.8210260461
- P. Operating license stage documents & correspondence
- 8210120038 Requests listing of all submittals re inservice testing program within 30 days in order to complete review VABBALLO,D,B. Operating Reactors Branch 2, 82/09/24, ARNOLD,D lows Electric Light & Power Co. 2pp 15689
- 8210130050 Requests remittance of add1 fee for review of 820820 application proposing Tech Spac change for delay in implementation of surveillance requirements for functional testing of mechanical subbers.
 DIGOS.R.M. License Fee Management Branch 82/09/28 ARMOLD.D Towa Electric Light & Power Co. 1p. 15694.360 24X Fiche: 50-331, 82/09/28, 8210130050.
- 8210130509 Forwards "Regulatory Parformance Improvement Program." in response to 820604 request for plan to upgrade regulatory parformance
 LTU, L. Jawa Electric Light & Power Co. 82/09/30 KEPPI,ER.J @
 Region 3, Office of Director 2pp. 15682.194. 24X
 Fiche: 50-931.82/09/30.8210130509.
- --8210130517 "Regulatory Performance Improvement Program "

 ** Inwa Electric Light & Power Co 82/09/30, 31pp, 15582 194
 24X Fiche 50-331,82/09/30,8210130509

- 'ZIQI50160 Responds to NRC 820809 ltr re schedule for providing addl
 info on NUREO-0737. Item II B 3. "Post-Accident Bampling "
 Updated comparison of post-accident sampling sys against
 criteria of NUREO-0737 uil be submitted 821101
 FQDT.L P Iowa Electric Light & Power Co 82/10/08 DENTON. H
 Office of Nuclear Reactor Regulation. Director 2pp 15698 304
 24x Fiche 50-331,02/10/08.0210150160
- -210250489 Forwards for review "MSIV Local Leak Rate Testing," per 10CFR50.App J & Reg Quide 10 1 MINECK.D L lowe Electric Light & Power Ca 82/10/15 DENTON, H R Office of Noclear Reactor Regulation, Director 10 15807 130 24X Fiche 50-331, 82/10/15, 8210260489
- -8210260495 "HSIV Local Leak Rate Testing "
 Iowa Electric Light & Power Co 82/10/15 93pp 15807 131 24% Fiche \$4-331.62/10/15.8210260489
- 12 10240138 Requests revision of scheduled commitment dates for PAJREO-0737, Item II F 1. "Accident Monitoring " Five of six Progineering mad packages completed Bys should be operational by end of Nov 1982 RODT, L b lower Electric Light & Power Co 82/10/18 DENTON, H R Office of Nuclear Reactor Regulation, Director 1p 15799 092 24X Fiche 50-331, 82/10/18,8210260138
- Imagestion reports. IE Bulletins & correspondence
- -210040202 Forwards IE (nsp Rept 50-331/82-15 on 820809-13.16 & 23 & notice of violation PAPERIELLO,C J Division of Emergency Preparedness & Operational Support 92/09/10 ARNOLD,D lows Electric Light & Pawar Co 2pp 15283
- --8210040204 Notice of violation from insp on 820809-13,16 t 23 PAPERIELLO, C J Division of Emergency Preparedness & Operational Support 82/09/08 ip 18883 148 24X Fiche 50-331,82/09/10, 8210040202
- --8210040208 IE Insp Rept 50-331/82-15 on 820809-13.16 & 23 Moncompliance noted failure to include gamma spectrometer in QC program & absence of callbr procedures

 JANUSKA: A 0 , RDZAK, 8 , SCHUMACHER, M C Region 3, Office of Director 82/09/08 12pp 15583 149 24% Fiche 50-331.82/09/10.
- 3210030306 Ack receipt of 820309 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-331/82-07 SPESSAD, R L Division of Project & Resident Programs. 82/09/24 ARROLD. Loue Electric Light & Power Co Ip 15610-084. 24X Fiche 50-331, 82/09/24,8210030306
- --8210030307 Responds to NRC 820810 ltr re violations noted in IE Insp Rept 50-331/82-07 Corrective actions operators retrained & re-examined, operations manual modified & integrated plant spereting instructions changed ROUT.L D Ioua Electric Light & Power Co 82/09/09 KEPPLER:J O Region 3. Office of Director 5pp 15610 085 24% Fiche 50-331.82/09/24,8210050306
- B210050309 Forwards IE Safeguards Insp Rept 50-331/82-10 on 820421-25 & notice of violation W/o notice of violation MILLER.J R Division of Engineering & Technical Programs. B2/09/29 ARNOLD, D lowa Electric Light & Power Co 2pp 13610 090 24% Fichs. 50-331, 82/09/29, 8210050308
- -- 8210050311 IE Bafeguards Insp Rept 50-331/82-10 on 820621-25
 Noncompliance noted failure to maintain adequate detection
 aids & to grovide adequate access control Details withheld
 (ref (OCFR73 21).
 CHRISTOFFER, 0., CREED, J. R. Region 3. Office of Director
 82/09/27 2pp 15610 092 24X Fichs 50-331,82/09/29,8210050308
- B210190360 Forwards IE Insp Rept 50-331/82-04 on 820208-12,0308-10 & 0525-28 & notice of violation MORELIUS, C E Division of Engineering & Technical Programs, 82/10/05 ARNICD, D Towa Electric Light & Power Co, 2pp. 15740 324 24% Fithe 50-331,82/10/05,8210190360
- --B210190362 IE Insp Rept 50-331/82-04 on 820208-12,0308-10 & 0525-28

 Nancampilance noted failure to meet Tech Spec requirements.
 Section 3 re facility audits & failure to implement
 requirements of IOCFR50 App B.Criterion XVIII & V.

 HULZMER,M M. SHAFER,W D. HAMKINS.F C. Division of Engineering &
 Technical Programs B2/10/01. 15pp. 15740-332. 24%
 Fiche-50-331,82/10/05,8210190360.

- B20B190233 IE Info Notice 80-35. Suppl i. "Leaking & Dislodged I-125 Implant Seeds," Svc list encl COBB.L I. Division of Evel Facilities, Materials & Bafaguards B2/10/06 Consolidated Edison Co of New York & App 15761 250 24X Fiche 50-000.B2/10/06.8208190233
- 8210130546 Forwards addl info re IE Bulletin 80-11; "Masonry Wall Design;" consisting of Revision 1 to 180-day final rept All outstanding requests for info answered Info demonstrates structural adequacy of masonry walls RDDT.L.D lowa Electric Light & Power Co 82/10/06 DENYON, H R Office of Nuclear Reactor Regulation, Director 62pp. 15682 290 24% Fichs 50-331.82/10/06.8210130546
- 8210250336 Forwards IR Insp Rept 50-331/82-11 on 820719-22 & notice of violation NORELIUS, C E Division of Engineering & Technical Programs 82/10/07 ARNOLD, D lows Electric Light & Power Go 2pp 15790 311 24X Fishe 50-331, 82/10/07, 8210250336
- --8210250342 Notice of violation from insp on 820719-22 NORELIUS.C E Division of Engineering & Technical Programs 82/10/07 2pp 15790 313 24K Fiche 50-331,82/10/07,8210250336
- --8210250350 IE Insp Rept 50-331/82-11 on 820717-22 Montempliance noted failure to establish ref speeds for inservice testing of RCIC & HPCI pumps & inadequate preoperational testing of most to RHR svc water sysperformed under Design Change 760 CONNAUCHTON, K. HAHKINS, F. C. Division of Engineering & Technical Programs 82/09/23 7pp 15790-315. 24X Fiche 50-331,82/10/07,8210250336
- 8210190643 Act receipt of 820928 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 90-331/82-08 STREETER, JF Division of Project & Resident Programs 62/10/13 ARNOLD, D lower Electric Light & Power Co ip 15737 214 24X Fiche 50-331.62/10/13.8210190643
- --8210170664 Responds to NRC 820827 ltr re violations noted in II: Inap Rept 50-331/82-08 Corrective actions administrative procedures to be revised to include monthly review of document change form log to identify changes ROOT.L D lows Electric Light & Power Co. 82/09/28, KEPPLER.J.G Region 3, Office of Director 2pp 15737 218 24x Fiche 50-331/82/10/13.8210170643
- 820B19023B IE Bulletin 82-03, "Stress Corrosion Cracking in Thick-Wall, Large-Diemeter, Stainless Steel, Recirculation flys Piging at BMR flants " Svc list ancl DEYGUNO, R C Director's Office, Office of Inspection and Enforcement 82/10/14, Consolidated Edison Cn of New York, 115pp. 15810-125, 24x Ficher 50-000, 82/10/14, B20819023B
- R Periodic operating reports & related correspondence
- 8210200093 Forwards monthly operating rept for Bept 1982 MINECK.D L. Inwa Electric Light & Power Co. 82/10/13 Director's Office, Office of Inspection and Enforcement 1p 18737 R16 24X Fiche: 50-331, 82/10/13, 8210200093.
- --8210200096 Monthly operating rept for Bept 1982 MATEGN.M & Ioua Electric Light & Power Co 82/10/13 7pp 15757:217 24X Fiche 50-331,82/10/13,8210200093
- 8. Reportable occurrences: LERs & related correspondence
- 8210010008 Responds to FDIA request for 19 categories of documents renuclear reactor events & safety problems Forwards documents listed in App A FELTON.J M Division of Rules and Records. 82/05/28, UDELL.H.A Critical Mass Entry Project 15pp. 15727:005. 24X Fiche:50-000, 82/06/28, 8210010008.
- ~-8203120103 Submits engineering evaluation re loss of river water systems. Inop. One toop of river water systems inoperable due to clogged filter.

 (MCLF: T.R. Director's Office, 82/03/01 Director's Office 3pp. 19793 154 24% Fiche: 50~000; 82/06/28, 8210010008.
- 8210040369 Forwards LER 82-056/01T-0.
 AINECK: D. L. Jose Electric Light & Power Co., 82/09/24 KEPPLER.J. Q. Region 3. Dffice of Director. ip. 15587.130, 24X Fiche: 50-331.82/09/24.8210040369.
- --8210040376 LER 82-056/01T-0: on 820912. HPIC area ttpam leak slarm activated by temp differential switch TDB-2250A: resulting from leak due to tasp difference between ventilation intake & exhaust. Caused by false signal due to resiston failure HILL: K.L. Towa Electric Light & Power Co. 82/09/24. Region 3, Diffice of Director. 3pp 15587. 132. 24% Fichs. 80-331, 82/09/24, 82/00400369.

- 8210130133 Forwards LER 82-057/03L-0 MINECK.D L faws Electric Light & Power Co 82/10/01 KEPPLER.J G Region 3, Office of Director 1p 15673 095 24X Fiche.50-331.82/10/01.8210130133
- --B210130137 LER 82-057/03L-0 on B20902, during normal operation, while investigating river water intake sys IC-102 trouble alarm, mode switch HB-2906B found in off position Caused by lack of procedures guidance Procedures under review HILL, K. Iowa Electric Light & Power Co 82/10/01 Region 3. Office of Director 1p 15673 096 24X Fiche 50-331,82/10/01,8210130133
- 8210130393 Forwards LER 82-058/03L-0 MINECK.D L fows Electric Light & Power Co 82/10/01 KEPPLER, J Q Region 3, Office of Director Ip 15680 360 24X Fiche 50-331, 82/10/01.8210130393
- --8210130398 LER 82-058/03L-O.on 820910, river water supply sys traveling screen IF-368 would not run in auto or continuous mode Caused by low discharge pressure for screen wash pump Permissive pressure switch PR-2903 recalibr
 HILL, K L Iowa Electric Light & Power Co 82/10/01 Region 3, Office of Director ip 15680 361 24X Fiche: 50-331,82/10/01,8210130393
- 8210130585 Forwards LER 82-057/03L-0 MINECK.D L Tows Electric Light & Power Co 82/10/01 KEPPLER.J G Region 3. Office of Director 1p 15679 061 24X Fiche-50-331, 82/10/01.8210130885
- --B210130590 LER 82-059/03L-0 on 920910, worker in reactor core isolation cooling (RCIC) room reported marked increase in room temp Caused by broken drive belt in RCIC room cooling unit IV-AC-15A due to random failure
 HILL, K L Iowa Electric Light & Power Co 82/10/01 Region 3, Office of Director 1p 15679 062 24X Fiche 50-331,82/10/01. 8210130585
- 8210230231 Forwards LER 82-063/03L-0 MINECK.D L. lowa Electric Light & Power Co. 82/10/11 KEPPLER.J G Region 3. Office of Director ip 15791 158 24X Fiche 50-331.82/10/11.8210230231
- --8210250261 LER 82-063/03L-0.on 820927. reactor bldg isolation damper 10-AD-1783, reducing transport of airborns contamination from reactor bldg, failed to close upon receipt of isolation signal Caused by rust on piston & cylinder HILL.K L. Towa Electric Light & Power Co. 82/10/08 Region 3. Office of Director ip 15791:159 24X Fiche. 50-331,82/10/11,8210250231
- 8210250289 Forwards LER 82-062/03L-0 MINECK,D L Idwa Electric Light & Power Co 82/10/11 KEPPLER.J G Region 3. Office of Director 19 15791 162 24X Fiche.50-331.82/10/11.8210250289
- --B210250300 LER 82-062/03L-0.on B20922, surveillance testing pressure differential switch PDS-4304, controlling reactor bldg to suppression chamber vacuum breaker CV-4304, tripped below Tech Spec 11mit, Caused by instrument drift Switch recalibr HILL.K L Iowa Electric Light & Power Co. B2/10/11 Region 3. Office of Director 1p 15791 163. 24X Fiche 50-331,82/10/11,8210230289
- 8210230384 Forwards LER 92-061/03L-0 MINECK,D L. Idwa Electric Light & Power Co 82/10/12 KEPPLER,J Q Region 3. Office of Director ip 15790.088 24X Fiche 50-331, 82/10/12.8210250384.
- --8210250387 LER 82-061/03L-0 on 820914.RHR svc water pumps 1P-22A & 1P-22D failed to meet Tech Bpec requirements Caused by excessive clearances between pump inpellers & casing wear rings due to pump wear. Impellers edjusted & pumps tested HILL.K L. Tame Electric Light & Power Co. 82/10/12 Region 3 Office of Director. 1p. 15790 089. 24X Fiche: 50-331.82/10/12, 82/10250384
- DOCKET 50-333 JAMES A. FITZPATRICK NUCLEAR POWER PLANT
 F Security, medical, emergency & fire protection plans
- 9210050083 Forwards *Dispersion Hodel Description for Nine Hile Point/ James A Fitzpatrick Nuclear Stations: * upgraded meteorological sys featription per TMI Action Item III A. 2 BAYNE, J. P. Power Authority of the State of New York. 82/10/01. VASSALD, D. B. Operating Reactors Branch 2 2pp. 18404:255 24X Fiche: 50-333, 82/10/01, 8210030083

- --8210050085 "Dispersion Model Description for James A Fitzpetrick/Nine Hile Point Nuclear Stations " Power Authority of the State of New York 82/10/01 17pp 15504 257 24X Fiche 30-333.82/10/01.8210050083
- 8210260334 Act receipt of 820805 ltr informing NRC of steps taken to correct violations noted in IE Health Physics Appraisa)
 Rept 50-333/80-20 Full ALARA program implementation prior to 1983 refueling outage understood
 MARTINIT T Division of Engineering & Technical Programs 82/10/21
 MCMEILL.C A Power Authority of the State of New York 2pp 13802 342 24X Fiche 50-333.82/10/21.8210260334
- --8210240338 Supply response to NRC 820120 & 0702 ltry re items noted in IE Health Physics Appraisal Rept 50-333/80-20 Corrective actions schedule for technician retraining established & engineering controls will be part of ALARA program MCNEILL, CA Power Authority of the State of New York 82/08/05 MARTIN, TT Division of Engineering & Technical Programs 3pp 15802 344 24X Fiche 50-333, 82/10/21,8210260334

H Gameral correspondence

- 82:01:90713 Informs that 68 Zullo & RA Burns authorized to sign util ltrs to NRC. BAYNE, J.P. Power Authority of the Btate of New York 82/10/13 Office of Nuclear Reactor Regulation, Director 2pp 15738, 209 24X Fiche 50-000,82/10/13,8210190713
- P Operating license stage documents & correspondence
- 8210290410 Discusses add1 considerations that should be addressed in future proposed Tech Spec mods to 115 kV offsite (reserve) ac power sys, in response to util 820914 request VASBALLO, D B Operating Reactors Branch 2 82/10/04 SINCLAIR.L W Power Authority of the State of New York 5pp 15863 250 24X Fiche 50-333, 82/10/04,8210270410
- 82:0150031 Forwards addl payment required for 820604 application to amend Yech Specs relegation and structure.per NRC 820714 itr Addl payment made under protest pending final determination of legality of fee schedule 8AYNE.J P Power Authority of the State of New York 82/10/08 MILLER.W 0 License Fee Management Branch 3pp 15701:265 24% Fichs: 50-000.82/10/08.8210150031
- 8210200028 Forwards 820226 submittal re results of review of NUREO-0612. "Control of Heavy Loads "
 BAYNE.J P Power Authority of the State of New York B2/10/15
 VASSALO, D. Licensing Branch 2 ip 15756 056 24X
 Fiche 50-333, 82/10/15,8210200028
- --8210200039 Forwards results of second phase review of heavy load handling operations & response to Sections 2 2,2 3 & 2 4 of Encl 3 to 801222 ltr Consequences of certain load drops do not meet NUREO-O612 guidelines.

 BAYNE, J P Power Authority of the State of New York, 82/02/26 VASSALLO, D Operating Reactors Branch 2 65pp 15756 057 24K Fichs 50-503.82/10/15/8210200028.
- S210200074 Forwards response to S20806 request for add) info #2
 NUREO-0737. Item II D. i, "Relief & Sefety Valve Test
 Requirements"

 BAYNE.J.P Power Authority of the State of New York 82/10/15
 VASBALLO.D B Operating Reactors Branch 2, 17pp 15757 263 24K
 Fiche: 50-333, 62/10/15, 8210200074
- Q Inspection reports, IE Bulletins & correspondence
- 8210080015 Add1 response to FOIA request for 19 categories of Info ra nuclear reactor events & sefety problems Formerds documents listed in App A. Documents in App B completely withheld (ref FOIA Exemption 5) FELTON, J M. Division of Rules and Records 82/07/12 UDELL,R A Critical Mass Energy Project. 9pp. 15665:027 24X Fiche 50-000,82/07/12,8210080015.
- --9210080134 Bystematic assessment of licensee performance notes #2 facility evaluation for Dec 1979-Nev 1980 # NRC No Detailed Affiliation Diven. 80/11/30 9pp 15647.349. 24X Fiche.50-000,82/07/12,8210080015.
- 8210040317 Forwards partial response to NRC 820414 request for additinfo to inservice inspiprogram. Response to Items 8 & 10 w[1] he provided by 821208 or approx 30 days after start of next scheduled outage
 8AYNC, J. P. Power Authority of the State of New York. 82/09/28
 VASSALLO, D. S. Operating Reactors Branch 2 10pp 13586 iB7 24E Fiche 30-333, 82/09/28, 8210040317.

- E210070362 Forwards Page 12A to 820914 IE Insp Rept 50-333/82-19, inadvertently omitted due to administrative error STAROSTECKIR Division of Project & Resident Programs 82/10/04 MCNEILL.C A Power Authority of the State of New York 19 15534 038 24X Fiche 50-333,82/10/04,8210070362
- --BR10070367 Page 12A to 1E Insp Rept 50-333/82-19 on 820914, inadvertently omitted from original rept * Region 1. Office of Director 82/10/04 ip 15634 039 24x Fiche 50-333, 82/10/04, 8210070362
- 8208190233 IE Info Notice 80-35. Suppl 1, "Leaking & Dislodged I-125 leplant Seeds " Svc list encl COSB.L | Division of Fuel Facilities, Materials & Safeguards 82/10/06 Consolidated Edison Co of New York 66pp 15761 250 24% Fiche 50-900,82/10/06.8208190233
- 8210150271 Ack receipt of 820917 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-333/82-15
 STARBBTECKI: R Division of Project & Resident Programs 82/10/07
 HCHELL.C A Power Authority of the State of New York 1p
 15703 237 24X Fiche 50-333.82/10/07.8210150271
- --8210150283 Responds to NRC 820820 ltr re violations noted in IE Insp Rept 50-333/82-15 Corrective actions solid radwaste sys procedure revised issue dates of maint procedures reviewed & security guards instructed to monitor more closely MCNETULE A Power Authority of the State of New York 82/09/17 STARGBTECKI.R Division of Project & Resident Programs 6pp 15703 238 24X Fiche 50-333, 82/10/07,8210150271
- 0210210100 Forwards IE Insp Rept 50-333/82-ii on 820701-30, No nencempliance nated STAROSTECKI, R Division of Project & Resident Programs. 82/10/07 FITZPARRICK, J Power Authority of the State of New York 2pp 15765 307 24X Fiche 50-333,82/10/07.8210210100
- --8210210115 IE Insp Rept 50-333/82-11 on 820901-30 No noncompliance noted Major areas inspected action on previous insp findings. LER review.operational safety verification. surveillance & maint observations & NUREG-0737 items LINVILLE, J. C., DOERFLEIN, L. T., KISTER, H. B. Region 1, Office of Director 82/10/06 12pp 15765 309 24X Fiche 50-333,82/10/07, \$210210100
- B20B190298 IE Bulletin 82-03, "Stress Corrasion Cracking in Thick-Wall, Large-Diameter, Stainless Steel, Recirculation Sys Piping at SNR Plants "Syc list encl DEYOUNG: R C. Director's Office, Office of Inspection and Enforcement 82/10/14 Consolidated Edison Co of New Yor's 115pp 15B10 125 24X Fichs. 50-000, 82/10/14, 8208190238
- 82101904ii Forwards inservice insp summery rept for Winter 1981-82 outage & two metallurgical analyses. "Metallographic Investigation of Type 304 Btainless Eteel Schedule 80 Fipe " Retults of insps acceptable EAYNE.J P Power Authority of the State of New York 82/10/15 VASSALLO.D B Operating Reactors Branch 2. 2pp 15743-103 24: Fische 30-333, 82/10/15, 82/0190411
- --B210190420 "Metallographic Investigation of Type 304 Stainless Steel Sichedule 80 Pipe " BUCHHEIT.R D Battelle Hemorial Institute, Columbus Laboratories, 62/03/25, 18pp 15743 105 24X Fiche 50-333,82/10/15,8210190411
- --B210170428 "Investigation of Flaws on Inside Surface of Type 304
 Stainless Stael Schedule SO Pipe "
 Bettelle Memorial Institute, Calumbus Laboratories 62/07/30,
 51pp 15743.123. 24% Fiche, 50-333,82/10/15,8210190411
- --8210190435 "Inservice Insp Summery & NIS-1 Data Rept, Winter 1981-82 Outage "

 SANCIC, D. BURNS, R. A. Power Authority of the State of New York 82/10/15 572pp. 15473.174 24X Fiche. 50-333,82/10/15, 821019041.
- B210260334 Ack receipt of 820803 ltr informing NRO of steps taken to correct violations noted in IE Health Physics Appraise!
 Rept 50-333/80-20 Full ALARA program implementation prior to 1783 refueling outage understood.
 MARTIN.T T Division of Engineering & Technical Programs 82/10/21 MCNEILL.CA Power Authority of the State of New York 2pp 15802:342. 24X Fichs 50-333,82/10/21,8210260334.
- --8210260338 Bupple response to NRC 820120 & 0702 ltrs re items noted in IE Health Physics Appraisal Rept 50-333/80-20 Corrective actions schedule for technician retraining established & engineering controls will be part of ALARA program MCNEILL, C. A., Power Authority of the State of New York, 82/08/05 MARTIN, T.T. Division of Engineering & Technical Programs, 3pp. 15802, 244. 24X Ficha 50-333, 82/10/21, 8210260334

- R Periodic operating reports & related correspondence
- 821020001B Forwards updated monthly operating rept for Jan 1982 MCNEILL,C A Power Authority of the State of New York B2/02/03 Management Information Branch ip 15756 122 24X Fiche 50-333, 82/02/03, 821020001B
- --8210200024 Updated monthly operating rept for Jan 1982 ZUFELT.E Power Authority of the State of New York 82/02/28 12pp 15756 123 24X Fiche 50-333,82/02/03,8210200018
- 8210120240 Forwards monthly operating rept for Sept 1982
 MCNEILL.C A Power Authority of the State of New York
 Director's Office. Office of Inspection and Enforcement 1p
 15652 116 24% Fiche 80-333,82/10/04.8210120240
- --8210120243 Monthly operating rept for Bept 1982 COOK, J. Power Authority of the State of New York 82/10/04 7pp 13552 117 24X Fiche 30-333,82/10/04.8210120240
- 8 Reportable occurrences, LERs & related correspondence
- 8210040324 Forwards LER 92-042/03L-0 HCNEILL, C A Power Authority of the State of New York 82/09/21 HAYNES: R C Region 1, Office of Director 1p 15586 185 24X Fiche 50-333.82/09/21.8210040324
- --8210040332 LER 82-042/03L-0 on 820826, testing of control rod hydraulic control unit accumulator pressure & level switches & pressure indication revealed &8 of 41; instruments out of calibr or not operating properly Caused by instrument drift KEITH.H N Power Authority of the State of New Yorl 82/09/21 Region 1. Office of Director 2pp 15586 186 24X Fithe 50-333,82/09/21.8210040324
- 8210060285 Forwards LER 82-043/03L-0 MCNEILL.C A. Power Authority of the State of New York 82/09/24 HAYNES, R C Region 1. Office of Director 1p 15621 069 24X Fiche 50-333, 82/09/24, 8210060285
- --B210060292 LER 82-043/03L-0 on B20902, MBIV D inboard 10% switch would not reset when tested to satisfy Tech Spec 3 i-1 Caused by drift between switch operator & striker plate Switch striker plate modified

 KEITH, H N Power Authority of the State of New York B2/09/24

 Region 1. Office of Director 1p 15621 070 24%

 Fiche 50-333, 82/09/24, 8210060285
- 8210220519 Discusses 820501 event re oscillation of frequency k output power in emargency dissel generator sys Root cause of dissel generator failures unknown Efforts on flow blockage of cooling water to safety sys adequately address problem CHIRAMALIM Reactor Operations Analysis Branch 82/10/01 SEYRITIK V Reactor Operations Analysis Branch 7pp 13786.077 24X Fiche 50-333.82/10/01.8210220519
- 8210190069 Forwards LER 82-044/03L-0
 MCNEILL, C A Power Authority of the State of New York 82/10/07
 HAYNES.R C. Region I. Office of Director 1p 15742 134 24X
 Fiche 50-333,82/10/07,8210190069.
- --8210190077 LER 82-044/O3L-0.on 820909, motor operator electrical breaker tripped while attempting to cycle LPCI injection valve Caused by electrical motor fault resulting in isolation failure created during attempted valve cycling FERNANDEI.W. Power Authority of the State of New York Region 1. Office of Director 1p 15742 135 24X Fiche 50-333, 82/10/07, 8210190069.
- 8210220255 FNO-I-82-066 on 821018, Quadrex Corp shielded van transporting four empty spent fuel racks to Oak Ridge.TN collided w/automobile in North Syracuse.NY Radiation surveys did not identify any damage to packaging CLEMONS.P. OREENMAN.E., BRUNNER.E Region i, Office of Director. 82/10/19, 1p. 15775 358 24X Fiche.50-333.82/10/19.8210220255
- 8210260170 Forwards LER 82-018/03X-1 MCNEILL, G.A. Power Authority of the State of New York 82/10/19 MAYNESS R.C. Region 1, Office of Director. ip 15799:050 24X Fithe 50-333, 82/10/19, 8210260170.
- --B210260175 LER 82-018/03X-1. on B20419, surveillance testing indicated four smote detectors inoperable Causad by failure to terminate connecting cabling properly due to inadequate procedure preparation to review Procedure to be revised.

 # Power Authority of the State of New York. B2/10/19 Region in Office of Director 4pp 15799.051 24X Fichs. 50-333, B2/10/19, B2/10260170

- 8210260306 RO on 820628, combustion in offgas sys observed Caused by improper valve lineup allowing more gas to recombiner than distriction flow rate could support Incident discussed w/shift supervisor & training will be developed MCNEILL, C A Fower Authority of the State of New York 82/10/19 HAYMEB, R C Region 1, Office of Director 3pp 15803 009 24X Fiche 50-333, 82/10/19, 8210260306
- 8210260378 Forwards Updated LER 82-028/03X-1 MCNEILL, C A Fowar Authority of the State of New York 82/10/19 HAYNES, R C Region 1, Office of Director ip 15804:252 24X Fiche 50-333, 82/10/19, 8210260378
- --8210260386 Updated LER 82-028/03X-1 on 820701, drywell equipment drain sump flow integrator found out of calibr & could not be adjusted Caused by abnormal friction in drive gear train New gears purchased to rebuild unit.

 Power Authority of the State of New York 82/10/19 Region 1, Office of Director 2pp 15804 253 24X Fiche 50-333, 82/10/19, 8210260378

DOCKET 50-334 BEAVER VALLEY FOHER STATION, UNIT 1

- F Security, medical, emergency & fire protection plans
- 8210010013 Forwards add1 info requested on 820725 re changes to guard training & qualification plan. Info withheld (ref 10CFR2, 770 & 10CFR2, 770 CAREY, J. J Duquesne Light Co 82/09/20 VAROA. B A Assistant Director for Operating Reactors. 1p 15565 147 24X Fiche. 50-334, 82/09/20, 8210010013
- 8210080045 Notification of 820930 meeting w/util in Betheeda.MD to discuss upgrading of meteorological sys TAM.P S. Operating Reactors Branch i. 82/09/23 VARQA.B A Operating Reactors Branch i 2pp 13669 317 24X Fiche.50-334,82/09/23,8210080045
- 8210180016 Releases public version of revised emergency preparedness implementing procedures FELTON.J M Division of Rules and Records 62/09/29 Document Management Branch ip 15717-318 24X Fiche 50-334,62/09/29, pp.1018/014
- 8210260122 Releases public version of revised emergency plan implementing procedures. FELTON.JR Division of Rules and Records. 82/10/08 Document Hanagement Branch 1p. 15812 031 24X Fiche:50-334,82/10/08.
- --8210260125 Forwards public version of revised emergency plan implementing procedures, including Procedures EPP/IP 1.1 re notification. 1.2 re communications & dissemination of info & 1.3 re turnover status checklist SIEBER. J D Duquesne Light Co 82/09/14. VAROA. 8.A. Operating Reactors Branch 1. 3pp. 15812.032. 24X Fichs. 50-334, 82/10/08. 8210260122
- --8210260127 Public version of revised emergency plan implementing procedures: including Procedures EPP/IP 1 ire notification, 12 re communications & dissemination of info & 1.3 re tunnover status checklist LACEY.W J Buquesne Light Co. 82/09/15, 834pp. 13812-035, 24x Fichar 50-334, 82/10/08-8210260122.
- 8210280411 Informs that proposed changes to access control program conteined in licenses 820702 ltr acceptable. Final approval cannot be granted until necessary changes to physical eccurity plan submitted.

 VAROA. S.A. Operating Reactors Branch 1 82/10/08, CAREY, J. J. Duquesne Light Co. 2pp. 15859 334, 24K Fiche: 50-334, 82/10/08, 8210280411.
- 8210260458 Forwards supplemental info per 821014 discussion clarifying exemptions previously documented in fire protection App R review Section 11.2. "Reactor Containment" & Section 11.6. "Primary Auxiliary Bidg."

 CARRY.J.J Duquesne Light Co. \$2/10/22 VARQA.S.A. Operating Reactors Branch 1 9pp 15806 200, 24% Fishe.50-334.82/10/22, 8210260458
- P Operating license stage documents & correspondence
- 8210120120 Advises that no further oft action planned re 800521 inoperability of RHR sys for 5-h since pipe crack study group will issue rept in 2 was Sys inoperability due to weld leak repair effort LANNING, H. D. Director's Office 80/08/04. Director's Office, ip 15692:254, 24% Fiche: 50-334,80/08/04,8210120120.

- 8210050487 Forwards request for additinfore proposed changes to Tech Specs for leak rate testing of certain isolation valvas using water in lieu of air or nitrogen Response requested within 30 days of receipt of itr VARQA.S A Operating Reactors Branch 1 82/09/21 CAREY. J Duquesne Light Co 3pp 15626 283 24X Fiche 50-334, 82/09/21, 8210050487
- 8210050165 Forwards util summary of efforts re rod position indication sys per 820713 commitment & 820720 ltr Westinghouse companion rept expected by mid-Oct CAREY. J Duquesne Light Co 82/09/29 VAROA.8 A Operating Reactors Branch 1 2pp 15605 122 24X Fiche 50-334,82/09/29,8210050145
- --8210050168 "Beaver Valley Power Station.Unit 1 Analog Red Position Indication Sys." special rept ORADA, K. D. BIEBER, J. D. Duquesne Light Co. 82/08/31 20pp 13505 124 24% Fiche 30-334.82/09/29.8210050165
- 8210130561 Forwards addl info re proposed changes to Tech Boece for leak rate testing of certain isolation valves using water in lieu of gas. In response to NRC 820921 request W/27 oversize drawings Aperture cards are available in PDR CAREV. J J Duquesne Light Co 82/10/05 VARQA. 8 A Operating Reactors Branch 1 35pp 15679 015 24X Fiche 50-334.82/10/05.8210130561
- 8210150312 Forwards "Cycle 3 Startup Test Rept "Rept summarizes test performed & verifies Cycle 3 reload core design data after criticality & calibr of excore instrumentation at several different power levels GAREY. J J. Duquesne Light Co 82/10/05 HAYNES.R C Region i. Office of Director ip 15701 345 24X Fiche 50-334,82/10/05. 8210150312
- --8210150316 "Cycle 3 Startup Test Rept "

 a Duquesne Light Co 82/10/05 5pp 15701,346 24x
 Fiche 50-334,82/10/05.8210150312
- 8210190747 Forwards add1 info re two-loop operation per NRC 820817 request. Westinghouse reviewing Question 7 against analysis CAREV. J. Duquesne Light Co. 82/10/08 VARCA. 8 A. Operating Reactors Branch 1. 6pp. 15737 135. 24X Fiche 50-034, 82/10/08, 8210190747
- 8210270267 Forwards revised application for amend to License DAR-66. consisting of Proposed Change Request 36.Revision 3. incorporating radiological effluent Tach Space into App A Offsite dose calculation manual & App B will follow CAREY, J. Duquesne Light Co 82/10/22 VAROA, B.A. Operating Reactors Branch 1. Ip 15828 287 24% Fiche 50-334,82/10/22,8210270267
- --B21027026B Revised application for emend to License DPR-66, incorporating proposed radiological effluent Tech Specs into App A.
 GAREY, J. J. Duquesne Light Co. B2/10/R2 ip 15828, 268 24X Fiche 50-334, B2/10/R2, B210270267.
- --8210270271 Proposed radiological effluent Tech Bpets
 # Duquesne Light Co 82/10/22 116pp 15828 289 24x
 Fiche 50-334,82/10/22,8210270267
- Q Inspection reports: IE Bulletins & correspondence
- 8210080015 Add1 response to FOIA request for 19 categories of inf nuclear reactor events & safety problems Forwards documents listed in App A Documents in App B completely withheld (ref FOIA Exemption 5), FELTON. J.M. Division of Rules and Records 82/07/12, UGELL, R Critical Mass Energy Project 9pp. 15665-027, 24X Fichel 50-000, 82/07/12, 8210080015.
- --B2100B0114 By stematic assessment of licensee performance notes factIIIty evaluation for Sept 1979-Aug 1980 NRC No Datailed Affiliation Given B0/08/21 16pp. 15667 299 24X Fiche: 80-000, 82/07/12, 82100B0015
- B210070007 Responds to FOIA request for eight categories of receives team generators & steam turbines App A documents provided in R Udell FOIA Request B1-313 Forwards documents listed in App B.
 FELTON.J.M. Division of Rules and Records. B2/0B/10 LOM,D. Winthrop. Btimson. Putnem & Roberts. 9pp 15645:063 24X Fiche: 50-000. 82/08/10, 8210070007
- --8210070139 Forwards tabulated data on steam generator insp & eat facilities. Data should be provided to licensess IPPOLIYO.T. Operating Reactors Assessment Branch, 82/04/01 VARQA.S. Operating Reactors Branch 1. 5pp. 15645.136. 24X Fiche: 50-000, 82/08/10.8210070007

- NPO233 IE Info Notice 80-35, Suppl i, "Leaking & Dislodged I-128 Filant Seeds " Svc list encl.

 33.L 1 Division of Fuel Facilities, Haterials & Safeguards 27/10/04 Consolidated Edison Co of New York 66pp 19761-250 14 Fiche 30-000.02/10/04.0208190233
- C210231 Forwards IE Insp Rept 50-334/82-21 on 820816-20 No categorial control of Engineering & Technical Programs. 82/10/06 ATTM T Y Division of Engineering & Technical Programs. 82/10/06 CAREY.J J Duquesne Light Co 2pp 15766 274 24X cthe 50-334,82/10/06:8210210231
- 210210236 IE Insp Rept 50-334/82-21 on 820816-20 No noncompliance roted Hajor areas inspected administrative controls for safety-related maint maint program & activities, surveillance testing & calibr programs & housekeeping & cleanliness testing & calibr programs & housekeeping & cleanliness StuMBERO.N. BISSETT.P., SHAUD.T. Region 1, Office of Director. 82/09/23 25pp 15766, 296. 24X Fiche: 50-334,82/10/06,8210210231
- Ol30015 Ack receipt of B20930 ltr informing NRC of steps taken to opract violations noted in IE lnsp Rept 50-334/D2-16.

 **TAROSTECKI.R Division of Project & Resident Programs 82/10/08.

 **APEV.J.y. Duquesne Light Co. 12. 13690.328 24X

 **Tache 50-334.82/10/08.8210150015.
- 221015001B Responds to NRC B20830 ltr re violations noted in IE Insp. Rept 50-334/82-16 Corrective actions: detector cables of R-NI41 reconnected in correct position & maint manual changed to insert caution re proper handling CAREY. J Duquesne Light Co. B2/09/30, BTAROBTECK1, R Division of Project & Resident Programs App. 18690, 329, 24% Fiche 50-334, 82/10/08, 8210150015
- IO220184 Advises that revised completion date for evaluation of calibr radiation beam uniformity is \$21031, per IC Health
 Physics Appraisal Rept 50-334/81-05.
 CAREY, J. Duquesne Light Co. 82/10/08 HAYNES, R.C. Region 1,
 Diffice of Director. 2pp 15776-244 24X Fiche 30-334,82/10/08,8210220184
- OB190238 IE Bulletin B2-03, "Btress Corrosion Cracking in Thick-Wall-Large-Diameter, Stainless Bleel, Recirculation Bys
 Figure at BHR Plants " Syc list encl
 DEYOUNDER O Director's Office, Office of Inspection and
 Enforcement B2/10/14 Consolidated Edison Co of New York
 115pp 15810 125 24X Fiche: 50-000, 02/10/14, 8208190238

Persodic operating reports & related correspondence

- 210050076 Forwards revised Page 4 of "1781 Rept of Facility Changes, Tests & Experiments "
 CAREY, J Duquesne Light Ca 82/07/23 HAYNGS, R C Region 1,
 Office of Director 1p 15615 327 24X Fiche 50-334,82/07/23,
 8210050076
- -821006038; Revised Page 4 of "1981 Rept of Facility Changes:Tests & Experiments."

 Duquesne Light Co 82/09/23 ip. 18615 330 24K Fiche 50-334,82/09/23,8210060076
- 210060088 Forwards NFDES discharge monitoring repts for Aug 1982 FEITKNECHT,C Duquesne Light Co. 82/09/28 REID:R W. Operating Reactors Branch 4. 2pp 15615 022 24X Fichs 50-334,82/09/28. 8210060088
- -8210060096 NPDES discharge monitoring repts for Aug 1982 STEEDLL L Duquesne Light Co 82/09/29 14pp. 15615:024 24X Fizhe 50-324,82/09/28,8210040088
- 5 Reportable occurrences, LERs & related correspondence
- 3210280307 LER 81-025/03L-0 on 810216, increased laskage from reactor coplant (RC) loop 1A RTD manifold hot leg valva RC-20 reported, Caused by attempted maint to repair valva. Temp channels returned to avc.

 LACEV.W B Duquesne Light Co 81/03/17 Region i, Philadelphia, Office of the Director (81/03/01) 2pp. 1887-283 24X Fiche 50-334, 81/03/17, 8210280307
- 8210040065 LER 81-028/00L-0 on 8102/9, during power operation results of surveillance test revealed reactor coolant leskage of 2,09 gpm Caused by failure of gland flange on valve Split gland flange used as mod to repair valve Mork completed 810221. LACEY.W S Duquesne Light Co. 8/03/20 Region i, Philadelphia, Office of the Director (81/03/01) 2pp. 15981,218. 24X Fiche 50-334,81/03/20,8210040065

- 8210280271 LER 81-027/03L-0.on 810218, at 98% power, all three chlorine detectors failed to meet min electrolyte drip rate criteria specified in surveillance test Caused by dirty wicks which prevented flow of electrolyte. Hicks cleaned, LACEY. H B. Duquene Light Co 81/03/20 Region 2, Atlanta, Office of the Director (81/03/01), 2pp. 13837 314 24% Fiche. 50-334, 81/03/20, 8210280271
- 8210280280 LER 81-025/031-0 on 810218, RCS loop flow channel indication failed to meet min flow surveillance theck requirement Caused by transmitter delta pressure transducer diaphragm leakage Transmitter replaced LACEY. W S Duquesne Light Co 81/03/20 Region i, Philadelphia, Office of the Director (81/03/01) 2pp 15837 047 24X Fiche 50-334, 81/03/20, 8210280280
- 8210130077 Forwards LERs 81-59/03L & 81-71/03L re tripping of battery charger output breaker 2 on thermal overload during surveillance testing Recommends that licenses complete appropriate analyses & mods to prevent recurrence HICHELBON.C Director's Office 82/02/23 HAYNES.R C Region J. Office of Director. 2pp 19696-245 24X Fiche 50-334,82/02/23, equal 2077
- 82:00:0008 Responds to FDIA request for 19 categories of documents renuclear reactor events & safety problems Forwards documents listed in App A FELTON, J M Division of Rules and Records 82/06/28 UDELL.R A Criffical Mass Energy Project 15pp 15727 005 24X Fiche, 50-000, 82/06/28, 8210010008
- --8210050124 Bunmary of Bi0610 operating reactor events meeting LAINAS, Q.C. Assistant Director for Bafety Assessment 81/06/17 EISENHUT, D. Q. Division of Licensing 5pp 15729, 217 24X Fiche. 50-000, 82/06/28, 8210010008
- ~-8210060432 Discusses inadequate switchgear cooling at facility
 Implications of event suggest that loss of ventilation sys
 could have potential safety significance requiring addl
 generic review by NRC
 MICHELSON.C Director's Office. 82/02/23 HAYNES.R.C Region 1,
 Office of Director. 2pp 15732.304 24X Fiche: 50-000, 82/06/28,
 8210010008
- 8210150199 Forwards LER 82-037/03L-0 LACEY.W. 8 Duquesne Light Co 92/09/27 HAYNES, R C Region 1. Office of Director, 2pp 15705, 262 24% Fiche 50-334, 82/09/27, 8210150149
- --8210180208 LER 82-D37/O3L-0 on 820921, steam generator 1A level protection channel III signal comparator LO-FW476A declarad inoperable due to faulty actuation & trip setpoint drift found during surveillance testing Hapan comparator replaced * Duquesne Light Co. 82/09/27 Region 1, Office of Director 2pp. 15703-264 24X Fiche, 50-334, 82/09/27, 8210180199.
- 8210150185 Forwards LER 82-035/03L-0 LACEY.M. B Duqueene Light Co. 82/09/30 HAYNES, R C. Region 1, Office of Director. 2pp. 15707 255 24X Fiche: 50-334, 82/09/30, 8210150185.
- --B210150201 LER 82-D35/03L-0 on 820917. delta flux exceeded required target band Caused by low heater drain tank level, leading to load reduction. Control rods borated out to return delta flux to within target band.

 LACEY.H S. Duquetne Light Co B2/09/30. Region 1. Office of Director 239. 19707.237 24X Fiche. 50-334, 82/09/30, 8210150185
- 8210190274 Forwards LER 82-034/03L-0 LACEY.W. B Duquerns Light Co. 82/10/04 HAYNEB.R C. Region I. Office of Director. 2pp. 15742 185. 24X Fiche: 50-334,82/10/04, 8210190274
- --8210190282 LER 82-034/03L-0: on 820715, during surveillance test containment vacuum pump failed required discharge flow rate. Caused by buildup of dirt & debris in discharge line. Line cleaned & suction & discharge filters replaced. LACEV.H. B. Duquesme Light Co. 82/10/04. Region 1, Office of Director 2pp 15742:187. 24x Piche 50-334.82/10/04,8210190274
- 8210210006 Forwards LER 82-032/03L-0
 LACEY, N. S. Duquesne Light Co 82/10/07. HAYNEB: R. C. Region 1:
 Office of Director 2pp 15766:023. 24X Fiche: 50-334, 82/10/07,
 8210210006.
- --BRIORIODIO LER 82-032/03L-0 on 820908, fire hose protection in intake structure lost when fire main ruptured in redundant underground supply leader Caused by overtorquing of flange setscrews initiating crack.

 **B Duquesne Light Co. 82/10/07 Region 1. Office of Director.

 **2pp 15766,025. 24% Fiche.50-334,82/10/07,8210210006.

- 8210210065 Forwards LER 82-033/03L-0 LACEY, H B. Duquesne Light Go 82/10/08 HAYNES, R C. Region I. Office of Director 2pp. 15765 341 24X Fiche 50-334,82/10/08,
- --8210210072 LER 82-033/03L-0 on 820911, operators unable to reclose steam supply trip valve TV-MS-1058 of turbins driven auxiliary feedwater pump FH-P-2 Caused by washer lodged in valve trim
- 8210260163 Forwards updated LER 81-091/01X-1.
 LACEY.N S Duquesna Light Co 82/10/11 HAYNES,R C Region 1.
 Office of Director. 2pp 15799 003 24X Fiche 50-334.82/10/11. 8210260163
- --8210260167 Updated LER 81-091/01X-1, on 811029, break in redundant underground 12-1nch supply header resulted in loss of fire water sys Caused by external finger corrosion along pips bottom Total sys piping change-out not warranted # Duquesna Light Co 82/10/11 Region 1, 0ffice of Director 2pp 1579:005 24X Ficha. 50-334, 82/10/11. 8210260163
- 8210260203 Forwards LER 82-040/03L-0 LACEY.H S Duquesne Light Co 82/10/14. HAYNES,R.C Region 1: Office of Director. 3pp. 15804 248 24X Fichs 50-334,82/10/14:
- --8210260226 LER 82-040/03L-0 on 820919, alarm status lights & visual display on core cooling monitor found extinguished, Caused by losse connection. Connection repaired Monitor to be tested & inspected in conjunction w/
- 8210260478 Forwards LER 82-036/03L-0 LACEY, W 8 Duquesne Light Co 82/10/14. HAYNES, R. C Region 1, Office of Director. 2pp 15807 253. 24X Fiche 50-334,82/10/14.
- --8210260487 LER 82-036/03L-0 on 820619, diesel engine cooling water inlet 210220487 LER 82-036/04.-0 on 820619,dessel engine cooling water in k outlet temps exceeded max allowable values rendaring diesel generator 2 inoperable Caused by fouling of cooling water HX tubes. Tubes cleaned. LACEY. HS Buquesne Light Co 82/10/14. Region i, Offics of Director 2pp. 15807-255. 24X Fichs 50-034,82/10/14.8210260478.
- 8210220447 FNO-I-82-065 on 821018, reactor tripped on high level in steam generator due to erratic operation of feedwater control valve.Resulting feedwater isolation tripped motor-driven main feedwater pumps & auxiliary pumps started. NORRHOLML . KEIMIO:R Region I. Office of Director. 82/10/18 lp. 15778 245. 24X Fiche:50-334.82/10/18.8210220447.
- DOCKET 50-335 ST, LUCIE PLANT, UNIT 1 F Security, medical, emergency & fire protection plans
- 8210010155 Forwards IE Insp Repts 50-335/82-28 & 50-389/82-37 on 820809-13.No noncompilance noted DANCE.H.C. Division of Project & Resident Programs 82/09/08. UHR10.R E Florida Power & Light Co. Epp. 15565:326 24X Fiche, 50-335, 82/09/08, 8210010155
- --8210010159 IE Insp Repts 50-335/82-28 & 50-389/82-37 on 820809-13 No noncompliance noted Major areas inspected:followup on emergency preparedness approfised at the exercise findings HUFFMAN-0, N., JENKINS, O.R. Division of Emergency Preparedness & Operational Support, 82/09/02 18pp. 15565:328, 24% Fiche.50-335.82/09/08.8210010155.
- 8210050559 Releases public version of emergency preparedness open Terms. J. K. Division of Rules and Records. 82/09/16. Docum Management Branch 1p 15637-220. 24X Fichs.50-335.82/09/16. 8210050559
- --8210050567 Bubmite public version of clarification of emergency preparadness planning open items of emergency action levels, staffing augmentation & unannounced drills.

 UHRIG.R.E Florida Four & Light Co. 82/09/03. EISENHUT, D. Q. Division of Licensing. 2pp. 15637:221. 24X Fiche: 50-335. 82/09/14, B210050559
- 8210190371 Forwards Revision 1 to 10CFR50.App R fire protection review, correcting typographical & editorfal arrors. WRRIO.R E florida Power & Light Co. 82/10/12, EIBENHUT, D. Q Division of Licensing. 1p. 15741:218. 24X Ficha: 50-335,82/10/12, 8210190371.

- --8210190374 Revision 1 to 10CFR50. App R firs protection revisue Florida Power & Light Co 82/10/12 200pp 15741 219 Florida Power & Light Co 82/ Fiche 50-335,82/10/12,8210190371
- 8210190440 Extends invitation to observe 821019 demonstration of emergency response sys at Technology for Energy Corp. Knorville, TN UHRIO, R E Fiorida Power & Light Co 82/10/12 EISENHUT, D Q Division of Licensing ip 15741
- 8210260376 Ack receipt of 821013 ltr informing NAC of steps taken to correct violations noted in IE Bafeguards Insp Rept 50-335/62-30
- 50-333-82-30 LEWIS, R C Division of Project & Resident Programs 82/10/22 UHRIGAR, E Florida Power & Light Co 1p 15806 138 24X Ficha 50-335, 82/10/22, 8210260376
- --82102&0391 Responds to NRC 820913 ltr re violations noted in IE 84feguards Insp Rept 50-335/82-30 Corrective actions withheld (ref 10CFR73 21) UHRIG.R E Fiorida Power & Light Co 82/10/13 O'REILLY, J P Region 2, Office of Director 1p 15804 139 24X Fiche 50-335,82/10/22.8210240374
- --8210260510 Forwards IE Safaguards Insp Repts 50-335/82-30 t 50-389/82-41 on 820816-20 t notice of violation Notice of violation & rept details withheld (ref 10CFR73 21) LEVIS.R C Division of Project & Resident Programs 82/09/ UNRIG.R E Florida Fower & Light Co. 2pp 15806 140 24X Fiche. 50-335, 82/10/22, 8210260376
- --8210260515 IE Safeguards Insp Rept 50-335/82-30 k 50-389/82-45 on 820816-20. Noncompliance noted failure to comply w/security plan re vahicle control. alarms & compensatory action Details withheld (ref 10GFR73 21). OCODE.R. BTANBERRY.W. HCOUIRE, D. R. Region 2, Office of Director 82/09/10 2pp 15806 142 24X Fiche-50-335,82/10/22,8210260376.
- P Operating license stage documents & correspondence
- 8210040043 Forwards Amend 53 to License DPR-67 k safety evaluation Amend deletes current Tech Spec requirements to periodically test insulation of certain Class IE electrical underground cables for environ damage CONNER. E. L. Operating Reactors Branch 3 82/09/21 UHRIG. R E Florida Power & Light Co 2pp. 15577; 278 24X Fiche 50-335, 82/09/21, 8210040043.
- --8210040044 Amend 53 to License DPR-67, deleting current Tech Bpec requirements to periodically test insulation of certain Class IE electrical underground cables for environ damage CLARK: R A Operating Reactors Branch 3 82/09/21 5pp 15577-280 24X Fiche 50-335,82/09/21.8210040043.
- --8210040046 Safety evaluation supporting Amend 53 to License DPR-A7 Office of Nuclear Reactor Regulation, Director 82/09/21 15577:285 24% Fiche: 50-335, 82/09/21, 8210040043
- 8210250048 Forwards corrected version of Amend 53 to License DFR-57 & safety evaluation. Tech Spec pages omitted from earlier version. CDNxER.E.L Operating Reactors Branch 3 82/09/21 UHRIG.R E Floride Power & Light Co 2pp. 15798:350, 24X Fiche. 30-335,82/09/21.8210250048
- ---B210250050 Corrected version of Amend 33 to License DPR-67 deleting requirement to test insulation of certain Class IE electrical undeground cables for environ demage. Tech Space omitted from earlier version. CLARK.R.A Operating Reactors Branch 3 82/09/21 7pp 15798:352, 24X Fiche 50-335,82/09/21.8210250048
- --- BZ10250051 Corrected version of safety evaluation supporting Amend 53 to License DPR-67
 * Office of Nuclear Reactor Regulation; Director. 82/09/21. 269
 15798-359. 24% Fiche: 50-335, 82/09/21, 8210250048
- 8210050061 Forwards 820930 cover ltr to Franklin Research Ctr re affl info concerning equipment qualification.per NRC 820217
- UHRIG.R.E Floride Power & Light Co 82/09/30. CL Operating Reactors Branch 3 4pp. 15603:238. 24X Fiche:50-335:82/09/30.8210050061.

- \$210050288 Informs that requirements stated in Genevic Ltr 82-12 restaff working hours adequately enforced by incorporation in afaintstrative procedures Amend to Tech Specs unnecessary at present time

 U-RIGIRE Florida Power & Light Co 82/09/30 EISENHUT, D 0.

 Division of Licensing 19 15619 212 24X Fiche 50-335.82/09/30, 8210060288
- E210260351 Notifies of acceptability of 920108 response to NUREO-0737. Item II k S 25, "Loss of AC Power to Reactor Coolant Pump Stals "
 CLARK.R A Operating Reactors Branch S 82/09/30 UHRIQ.R E Florids Power & Light Co 2pp 15830 347 24X
 Fich# 50-335.82/09/30.8210260551
- E310190310 Advises of request for proposal to provide criteria for special lifting devices to demonstrate equivalency w/
 Guideline 4 of NUREQ-0612, "Control of Heavy Loads " Addl the will be provided as soon as possible re 821007 telcon, UNRIO.R E Florida Power & Light Co 82/10/12 CLARK,R A Operating Reactors Branch 3 2pp 15742 148, 24X
 Fiche 50-335, 82/10/12,8210190310

G. Imagection reports. IE Bulletins & correspondence

- E210220451 Responds to B20B02 telcon request for add1 info re IE Insp Rept 50-335/82-17 Repts of inservice insps will be submitted within 90 days of completion Repts of previous insps available at corporate ofc H/o enci U4R10.RE Florida Power & Light Co B2/08/19, 0'REILLY, J P Region 2. Office of Director 2pp 15778, 246 24X Fische 50-335, 82/08/19, 8210220451
- 8210010155 Forwards IE Insp Repts 50-335/82-28 & 50-389/82-37 on E20809-13 No noncompliance noted DANCE, H C Division of Project & Resident Programs 82/09/08 WestO, R E Floride Power & Light Co 2pp 15565 326 24X Fiche 50-335, 82/09/08, 8210010155
- --8210010159 IE Insp Repts 50-335/82-28 & 50-389/82-37 on 820809-13 No noncompliance noted Major ereas inspected followup on emergency preparedness appraisal & exercise findings HUFFHAN, O N., JENKINS, O R. Division of Emergency Preparedness & Operational Support 82/09/02 18pp 15565 328 24X Fichs 50-335,82/09/08.8210010135
- G210010075 Ack receipt of B20813 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-335/82-17
 LEWIS:R C Division of Project & Resident Programs 82/09/15
 UHRIO:R E Florids Power & Light Co ip 15567 170 24X
 Fiche 50-335:82/09/15.8210010075
- --9210010078 Ack receipt of 820722 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-335/82-17 Supplemental response due by 820812 LEVIS.R C Division of Project & Resident Programs 82/08/13 UHRIG.R E Florida Power & Light Co. 1p 15567 171 24X Fáche 50-335,82/09/15.8210010075
- -- 8210010084 Ack receipt of & responds to violations noted in IE Insp Rept 50-335/82-17 on 820511-14 No proprietary info Corrective actions vendor requested to expedite issuance of steam generator insp info UHRIO.R E Fiorida Power & Light Co 82/07/22 O'REILLY, J P Region 2. Office of Director 2pp 15367 172 24X Fiche 50-335,82/09/15,8210010075
- --B210010092 Notice of violation from insp on 820511~14 = Division of Project & Resident Programs 82/06/18, ip 13567 176 24% Fiche 50-335,82/09/15,8210010075
- --B210010096 IE Insp Rept 50-335/82-17 on 820511-14 Nancompliance noted steam generator & other inservice insp repts not submitted in specified time

 QIRARDLE H , ECONOMOS N Division of Engineering & Technical

 Programs 82/06/11 7pp 15567-177 24X Fiche 50-335.82/09/15.
 B210010075
- B210010142 Ack receipt of 820825 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-335/82-01 DANCE: H C Division of Project & Resident Programs B2/09/17 LFRIGN.E F Florida Power & Light Co ip 15567:247 24X Fiche: 50-335, 82/09/17, 8210010142,

- --8210010193 Responds to NRC 820406 itr re-violations noted in IE Insp. Rept 50-335/82-01 Corrective actions personnel verbally reinstructed re-insp of design documents for proper erections (naplementation & documents tion UMRIO, R E Florids Power & Light Co. 82/08/25 O'REILLY, J.P. Region 2, Office of Director App 15547:248 24X Fiche 50-335,82/09/17.8210010142
- 8210150345 Forwards IE Insy Repts 50-335/82-31 & 50-389/82-38 on 820830-0903. No noncompliance noted.

 DANCE: H C. Division of Project & Resident Programs 82/09/22. URRIGA E Florida Power & Light Co 1p. 15704 322. 24X Fichs. 50-335: 82/09/22.8210150345
- --82;0150358 IE Insp Repts 80-335/82-31 & 50-389/82-38 on 820830-0903, No noncompliance noted Major areas inspected radioactive liquid & passous effluent releases, reactor coolant chemistry & radioactive transportation activities, WRAY, J R, BARR, K P, Division of Engineering & Technical Programs 82/09/17 10pp 15704 323 24X Fichs, 50-335, 82/09/22, 8210150345
- 8210080264 Forwards response to IE Bulletin 80-11, "Masonry Well Design," supplementing response to NRC 820805 request for addition. WRIO.R E Florida Power & Light Co 82/10/04 CLARK, R A Operating Reactors Branch 3. 37pp 15638, 129, 24X Fiche 50-335,827(10/64,8210080264)
- 8208190233 IE info Notice 80-35, Suppl 1: "Leaking & Dislodged I-125 Implant Seeds " Svc list ancl COSB.L I Division of Fuel Facilities, Materials & Safeguards. 82/10/06 Consolidated Edison Co of New York, 64pp 15761, 250. 24X Fiche 50-000,82/10/06,8208190233.
- 8208190238 IE Bulletin 82-03, "Stress Corrosion Cracking in Thick-Walf-Large-Diameter, Stainless Steel, Recirculation Sys Piping at EWR Plants." Syc list and.

 DEYOUND-R C Director's Office, Office of Inspection and Enforcement. 82/10/14 Consolidated Edison Co of New York.

 115pp. 15810-125 24X Fiche, 50-000: 82/10/14, 8208190238
- 8210220280 Act receipt of 820930 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 30-335/82-11 & 50-389/82-34
 DANCE.H.C Division of Project & Resident Programs 82/10/15. UHRIG.R E. Floride Power & Light Co 19, 15775:084. 24X
 Fiche 50-335,82/10/15,8210220280
- --B210220286 Responds to NRC 820701 ltr re violations noted in IE Insp Rept 50-335/82-11 Corrective actions. Equipment Clearance Order 1-8-30 corrected & personnel reinstructed. UHRIO: RE Florida Power & Light Co 82/09/30 O'REILLY, J. P. Repion 2. Office of Director. 2pp. 15775.085 24X Fiche 50-335,82/10/15,8210220280
- --8210220291 Forwards IE Insp Repts 50-335/82-11 k 50-389/82-34 on 820711-0810 & notice of Violation DANCE.H.C Division of Project & Resident Programs 82/09/01. UHRIO.R.E. Floride Power & Light Co 2pp. 15775:087. 24X Fiche: 50-335,82/10/15,8210220280.
- --8210220297 Notice of violation from insp on 820711-0810. * Division of Project & Resident Programs 82/09/01 ip 15775 OB9 24X Fiche: 50-335, 82/10/15, 8210220280.
- --9210220303 IE insp Repts 50-335/82-11 & 50-389/82-34 on 820711-0810 Noncompliance noted on 820805. Equipment Clearance Order L-8-30 incorrectly identified suction & discharge drain valves V-2317 & V-2327 for charging pump A ELROD. & A , 8185. H E., JULIAN.C. A. Division of Project & Resident Programs. 82/08/31 10pp. 15778:090 24X Fiche 50-335.82/10/15, 8210220280
- 8210260376 Ack receipt of 821013 itr informing NRC of steps taken to correct violations noted in IE Bafeguards Insp Rept 50-335/82-30.
 LEWIS, R C Division of Project & Resident Programs. 82/10/22. UMRIG.R E. Florids Power & Light Co. ip. 15806.138. 24X Fiche 50-335.82/10/22,8210260376.
- --8210240391 Responds to NRC 820913 ltr re violations noted in IE Safeguards Insp Rept 50-335/82-30, Corrective actions withheld (ref 10FR73.21), URRIG.R.E Florida Power & Light Co. 82/10/13 O'REILLY, J. P. Region 2. Office of Director, ip. 15806:139. 24X Fiche. 50-335, 82/10/22, 8210240376.

1 1

-

- --B210260510 Forwards IE Bafeguards Insp Repts 50-335/82-30 & 50-389/82-41 on 820816-20 & notice of violation Notice of violation & rept details withheld (raf 10CFR73 21) LEHIG.R C Division of Project & Resident Programs. 82/09/13 URRIO,R E Florids Power & Light Co 2pp 13806:140 241 Fiche: 50-335,82/10/22,8210260376
- --8210260515 IE Bafeguards Insp Rapt 50-335/82-30 & 50-389/82-41 on 820816-20 Noncompliance noted failure to comply w/security plan re vehicle control alarms & compensatory action Details withheld (raf 10CFR73 21).

 000DE, R. 8TANSBERRY, W. MCOUIRE, D. R. Region 2. Dffice of Director 82/09/10 2pp 19806-142 24X Fiche 50-335,82/10/22,8210260376
- 8 Reportable occurrences, LERs & related correspondence
- 8210150035 Forwards LER 81-002/03L-0 BCHMIDT, A D Florida Power & Light Co. 81/02/20. D'REILLY, J P Region 2, Atlanta, Office of the Director (81/03/01) 1p 15701.147 24X Fiche:50-335,81/02/20,8210150035
- --8210150039 LER 81-002/03L-0 on 810122, digital data processing system to the processing system of the processing system of control state of the processing system of the process of control state of the process of th
- 8210010164 Forwards LER 82-045/43X-0 WILLIAMB, J W Florids Power & Light Co 82/09/24 O'REILLY, J P Region 2. Office of Director ip 15567 279 24X Fiche 50-335,82/09/24,8210010164
- --8210010174 LES 82-045/43X-0 on 820913, wash trough used to decontaminate respirators & similar items found not draining into raduaste us Caused by error resulting from personnel turnover Drain rerouted Dump area surveys will continue. PACE, P. L. Florida Power & Light Co. 82/09/24 Region 2, Office of Director. 2pp 15567-280. 24X Ficha 50-335,82/09/24,82:0001644.
- 8210070425 "Rept on Baint Lucie I Natural Circulation Cooldown on BOO&11." IMBRO:E V. Director's Office. 82/09/24, 28pp 15644,289 24X Fiche 50-335,82/09/24,8210070425
- 8210130552 Forwards LER 82-040/03L-0 HILLIAMB.J W Florida Power & Light Co. 82/10/04. O'REILLY, J P. Region 2, Office of Director 1p. 15684-007 24X Fiche:50-035.82/10/04.8210130552
- --9210530362 LER B2-040/03L-0 on 820902, short caused generator breakers to open & synchronizing inhibit timer to start Caused by personnel short circulting relay during generator negative sequence relay testing. Protection design reviewed PACE, P Floride Power & Light Co. B2/10/04. Region 2. Office of Director. Sop. 15484:008 24X Fiche:50-335.82/10/04.
- 8210130455 Forwards LER 82-041/03L-0 WILLIAMS, J.W. Florida Power & Light Co. 82/10/05, O'REILLY, J.P. Region 2, Office of Director, 1p 13682; 147. 24X Fiche 50-33J.82/10/05, 8210130455.
- --B210130462 LER 82-041/03L-0 on B20907: at 99% power reactor/turbins trip occurred resulting in brief loss of vital buses & iodine spike. Caused by motor auxiliary contact initiating false loss of load & inhibit signals.

 PACE: P L. Fiorida Power & Light Co. B2/10/06. Region 2, Office of Director. App 15682: [48. 24% Fiche. 50-335, 82/10/06, B210130456.
- 8210260337 Forwards LER 82-044/03L-0 HILLIAMB.J.W. Florids Power & Light Co. 62/10/15. O'REILLY, J P. Region 2, Office of Director. 1p. 15803:178. 24X Fiche:30-335.82/10/15.8210260357.
- --8210260369 LER 82-044/03L-0:on 820923.pulse counting function for 21 control element assemblies found deleted during normal testing. Caused by personnel error. Methods for elerting operators investigated.
 PACE.P.L. Florida fower & Light Co. 82/10/15. Region 2: Office of Director 1p. 15803:179. 24X Fiche: 50-335, 82/10/15, 8210260357.

- DOCKET 50-336 HILLSTONE NUCLEAR POHER STATION, UNIT 2
 F. Security, medical, emergency & fire protection plans
- 8210210597 Informs of new format for submittals containing safeguards info Safeguards info should be submitted similar to proprietary info Cover Its should not contain safeguards info. Actual info should be in attachment CLARK.R A Operating Reactors Branch 3 82/09/29 CQUNBIL.W @ Northeast Nuclear Energy Co (subs of Northeast Utilities) 2pp 13784 316 24% Fiche.50-336.82/09/29.8210210387.
- --821021019A IE Insp Repts 50-245/82-17 % 50-336/82-19 on 820808-0725 hc noncompliance noted Hajor areas inspected plant & refueling operations, equipment alignments & readiness, radiation protection & physical security SHEDLOSKY.J T Division of Project & Resident Programs 82/10/05 15pp. 15766.043 24% Fiche 50-245,82/10/07,8210210182
- P Operating license stage documents & correspondence
- 8210280013 Responds to FOIA request for all internal non-public documents, mamos, evaluation repts & other matl dealing w/ nuclear plant operations, Forwards documents listed in App A FELTON, J. M Division of Rules and Records 82/09/17 HCNNIS, D News & Observer 5pp 15860 065 24X Fiche 50-000, 82/09/17, 8210280013
- ---0210280031 Requests technical assistance to review recent evants et pacilities & to assess safety & environ significance STELLO. V Division of Operating Reactors 78/08/03 HVLLER.D Division of Site Safety & Environmental Analysis 2pp 15860 004 24% Fichs, 50-000,82/09/17,8210280013
- 8210010207 Forwards "Haddam Neck Plant Procedure ADF 3 2-22-C RCS Venting of Moncondensible Gases" it "Hillstone Nuclear Power Station RCS Venting Procedure OP 2398," in response to THI Action Plan Item II B.i. "RCB High Point Vents" COUNSIL. W.O. Connecticut Yankee Atomic Power Co. COUNSIL. W.O. Northeast Nuclear Energy Co. (subs. of Northeast Utilities) COUNSIL. W.O. Northeast Nuclear Energy Co. (subs. of Northeast Utilities) Operating Reactors Branch 5 CLARK, R.A. Operating Reactors Branch 3. 3pp 15568:048 24X Fiche: 50-000, 82/09/22, 8210010207
- --8210010214 Revision 2 to "Millstone Nuclear Power Station Unit 2 Plan Procedure OP 2398 RCS Venting Procedure." 8CACE.8. Northeast Nuclear Energy Co (subs of Northeast Utilities) 82/08/20. 11pp 15568 062 24X Fiche 50-000, 82/09/22, 8210010207.
- 8210010312 Requests that processing of 820812 license amend application he postponed, Revised application changing radiological effluent Tech Specs will be docketed on or about 821115 for both facilities.

 CDUNSIL.H.O. Connecticut Yankse Atomic Power Co COUNSIL.H O Northeast Nuclear Energy Co. (subs of Northeast Utilities).

 CDUNSIL.H.O. Northeast Utilities 82/09/22. CLARK,R.A. Operating Reactors Branch 3. CRUTCHFIELD. Deprating Reactors Branch 5. 3pp. 15574-047. 24X Fiche 50-000.82/09/22.8210010312
- 8210050179 Application for amend to License DPR-65 revising Tech Spec 3.1 2.2 to require both boric acid tanks & corresponding facility dependent flow paths to be operable in modes in which operability is required for ECCB.

 CDUNBIL: W. 9. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). CDUNBIL: W. 9. Northeast Utilities, 82/09/24.

 CLARK,R.A. Operating Reactors Branch 3. 2pp. 15603:353 24X Fichs: 50-336,82/09/24,8210030179
- --8210050187 Proposed revision to Tech Spec 3.1.2 R. requiring both boric acid tanks & corresponding facility dependent flow paths to be operable in modes in which operability is required for ECCS.

 ** Northeast Nuclear Energy Co. (subs. of Northeast Utilities), 82/09/24. 3pp. 15603:355. 24X Fiche 50-336,82/09/24.8210050179
- 8210040237 Application to amend License DPR-65, revising Tech Spect F8 boric acid flow path requirements as utilized in reactivity control sus & ECCS.

 COUNSIL,W.O. Northeast Nuclear Energy Go. (subs. of Northeast Utilities). CDUNSIL,W.O. Northeast Utilities. 82/09/24.

 CLARK,R.A. Operating Reactors Branch 3, 2pp. 15619:331. 24X Fiche: 50-336. 82/09/24, 8210060237.

- -- 8210050238 Proposed Tech Specs restoring two boron injection Plaw paths & one associated heat tracing circuit * Mortheast Nuclear Energy Co (subs of Northeast Utilities) 82/09/24 4ps 15619 393 24X Fiche 30-336,82/09/24,8210060237
- \$210050090 Provides justification for addl time needed to complete valve mod resulting from plant shielding review, per NUMEG-0737, Item II B 2 Const for mod scheduled to begin in CONSISTERM II B 2 Const for mod scheduled to begin in early Jan 1983 Completion expected by Apriprior to startup COUNSIL. W O Northeast Nuclear Energy Co (subs of Northeast Utilities) COUNSIL. W O Northeast Utilities 82/09/28 CLARK. R A Operating Reactors Branch 3 2pp 15604 239 24X Fiche 50-336.82/09/28.8210050090
- 8210220020 Advises of resolution of seismic qualification of auxiliary feedwater sys Sys able to perform designed safety-related function after SSE to assure safe plant shutdown CLARK, R A Operating Reactors Branch 3 82/09/30 COUNSEL, W C Mortheast Nuclear Energy Co (subs of Northeast Utilities) 2pp 15786 309 24X Fiche 50-336,82/09/30,8210220020
- --8210220022 Bafsty evaluation supporting seismic qualification of auxiliary feedwater sys * Operating Reactors Branch 3 82/09/30 App 15786 311 24X Fichs 50-336.82/09/30, 8210220020
- 8210130331 Discusses revision of administrative procedures to incorporate revised working hour guidelines & provisions for authorizing deviations per 820208 & 0615 requests.THI Ttem I A 1 3, "Shift Hanning" & Deneric Ltr 82-12 COUNSIL.W Q, CAGNETYA.J P Northeast Nuclear Energy Co (subs of Northeast Utilities) COUNSIL.W Q Connecticut Yankee Atomic Power Co 82/10/01 EISEMHUT, D Q Division of Licensing 3pp 15679 127 24X Fiche 50-000.82/10/01.8210130331
- O Inspection reports: IE Bulletins & correspondence
- B210150699 Forwards request for add1 info to complete review of 801104 response to IE Bulletin 80-11. "Masonry Wall Dasign."
 Response expected within 60 days of 1tr receipt CLARKR A Operating Reactors Branch 3 82/09/28 COUNBIL. H.O. Commecticut Yankee Atomic Power Co. COUNBIL. H.O. Northeast Nuclear Energy Co. (subs of Northeast Utilities) 13pp 15716 100. 24X Fiche 50-000. 82/09/28, 8210150699.
- 8210070352 Ack receipt of 820914 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-245/82-10 & 50-336/82-14
 MARTIN,T.T Division of Engineering & Technical Programs 82/10/0
 COUNSIL,W O Northeast Nuclear Energy Co (subs of Northeast Utilities). 1p 15634 051 24X Fiche 50-245,82/10/05,8210070352. 82/10/05
- --8210070356 Responds to NRC 820813 ltr re-violations noted in IE Insp Repts 50-245/82-10 & 50-336/82-14 Corrective actions: controlled documents updated & Unit 1 control room drawing controlled documents updated or unit i controlled documents deficiencies corrected counsil. H O. Northeast Nuclear Energy Co (subs of Northeast Utilities) COUNGIL. H Q Northeast Utilities B2/09/14 MARTIN. T Division of Engineering & Technical Programs 3pp 15634 052 24X Fiche 50-245, 82/10/05, 8210070332
- 0200170233 IE Info Notice 80-35, Suppl 1, "Leaking & Dislodged 1-125 COMPOSED IT Info Notice BO-35, Suppl 1, "Leaking & Disidged i-Implant Seeds." By: list encl COMBR-L | Division of Fuel Facilities, Materials & Safeguards. 82/10/06 Consolidated Edison Co. of New York 66pp 15761 24X Fiche 50-000,82/10/06.8208190233
- 8210190472 Forwards inservice insp rept of insp conducted during Dec HRDGZKA: E J Northeast Nuclear Energy Co (subs of Northeast Utilities). 82/10/06 HAYNES, R G Region 1, Dffice of Director. 1p 15740 182 24x Fiche: 50-336,82/10/06 8210190472.
- ---BR10190474 Inservice insp rept on Dec 1981 to June 1982 for period Apr 1979 to Aug 1982 Rept describes exams performed on Class II piping sys. ** Northeast Nuclear Energy Co (subs. of Northeast Utilities). 82/08/13 12pp 15740 183. 24X Fiche 50-336.82/10/06.8210190472.
- 8210210182 Forwards IE Insp Repts 50-245/82-17 & 50-336/82-19 on SZOBOB-0925 No noncompliance noted.
 STAROBTECKI: R Division of Project & Resident Programs. 82/10/07.
 COUNBIL: W G Northeast Nuclear Energy Co (subs of Northeast Utilities) 2pp 19766.041. 24X Fiche.50-245.82/10/07.8210210182
- -- 8210210196 IE Insp Repts 50-245/82-17 & 50-336/82-19 on 820808-0925.No noncompliance noted Major areas inspected plant & refueling operations, equipment alignments & readiness radiation protection & physical security.

 SHEDLOSMY.J T, LIPINSKI,D R., ELABSER,T. C. Division of Project & Resident Programs 82/10/05 15pp. 15766'043. 24X
 Fiche 50-245,82/10/07.8210210182.

- 8208190238 IE Bulletin 82-03, "Stress Corrosion Cracking in Thick-Wall, Large-Diameter, Stainless Bteel, Recirculation Bys Piping at BMR Plants " Svc list encl DEYQUNO, RC Director's Office, Office of Inspection and Enforcement 82/10/14 Consolidated Edison Co of New York 115pp 15810;125 24X Fiche 30-000,82/10/14,8208190238
- 8 Reportable occurrences, LERs & related correspondence
- 8210090019 "Rept on Millstone Unit 2 Loss of 125-Volt DC Bus Event on CHIRAMAL, H. IMBRO.E. GIANELLI.J Director's Office 26pp 15669 047 24X Fiche 50-336.81/11/30.9210080018.
- 8210130065 Discusses investigation of relative frequency of valve overtravel angmalise that could result in potential centrifugal pump runout exceeding NPBH No safety problems observed in operation w/HPBI valves manually open IMBROLE V. Reactor Operations Analysis Branch 82/02/22 HICHELBON, C. Director's Office 4pp 13696:268 24% Fiche:50-336,82/02/22,8210130065.
- 8210010008 Responds to FOIA request for 19 categories of documents re nuclear reactor events & safety problems Forwards documents listed in App A Tisked in App A
 FELTON, J H Division of Rules and Records. 82/06/28 UDELL, R A
 Critical Mass Energy Project 15pp 15727-008, 24X
 Fiche: 50-000, 82/06/28, 8210010008
- --8112010310 "Rept on Hillstone Unit 2 Loss of 125-Volt DC Bus Event on 810102 CHIRAMAL, M., IMBRO, E., GIANELLI, J. Director's Office, 26pp 15731 065, 24X Fiche, 50-000, 82/06/28, 8210010008,
- --8210040430 Summarise investigation of LER 50-334/81-24 re relative products demanties investigation of LEK 50-336/81-25 re relative frequency of valve overtravel abnormalities that could result in potential centrifugal pump runout exceeding NPSH IMBRO,E.V Director's Office 82/02/22, MICHELSON.C. Director's Office 4pp. 15732 293 24X Fiche 50-000.82/06/28.8210010009
- 8210010376 Forwards LER 82-036/03L-0.
 MROCZKA, E.J. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). HROCZKA, E.J. Northeast Utilities. 82/09/22.
 HAYNEER, C. Region 1. Office of Director 1p. 13573-051. 24X
 Fichs 50-336-82/09/22.8210010376
- --8210010385 LER 82-036/03L-0 on 820825, at 100% power level during 210010385 LER 82-034/03L-0 on B20825, at 100% power level during routine packing replacement of charging pump, crack discovered in charging pump block Cause not determined. Pump block to be replaced & failure analysis performed. CRISCIONE, J L. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). 82/09/22. Region 1, Office of Director. 1p. 15573-052, 24% Fiche 50-336,82/09/22,8210010376.
- 8210130228 Forwards LER 82-037/03L-0. ANOCZKA, E.J. Northeast Nuclear Energy Co. (subs. of Northeast Utilities) MROCZKA, E.J. Northeast Utilities 82/10/01 HAYNES, R.C. Region 1. Office of Director. 1p. 13675:226 24X Fiche 30-336,82/10/01.8210130229
- --8210130232 LER 82-037/03L-0:on 820902, while at 100% power, quarterly survaillance test revealed blocking valve 2-RC-403 would not close Probable cause attributed to failure to adjust packing for proper valve function.

 STADNICK-B Northwast Nuclear Energy Co. (tubs. of Northwast Utilities), 82/10/01. Region 1. Office of Director. 1p. 15675; 227 24% Fiche-50-336, 82/10/01.8210130228
- 8210210155 Forwards LER 82-037/03L-0 ANGUZKA,E J. Northeast Nuclear Energy Co. (subs. of Northeast Utilities) HRUGZKA,E J Northeast Utilities 82/10/13, HAYNES,R C. Region 1, Office of Director 1p. 15766:075 24X Fichs 50-326,82/10/13,8210210155
- --8210210160 LER 82-039/03L-0. on 820914, packing for operator shaft in primary containment outer eir lock door leaked & test pressure could not be maintained Caused by normal cyclic wear. Packing tightened.

 KOMOSKY.G. Northeast Nuclear Energy Co. (subs of Northeast Utilities). 82/10/13, Region 1, 0ffice of Director, ip. 15766 076. 24X Fiche, 50-336, 82/10/13, 8210210155
- 8210220060 Forwards LER 82-038/03L-0. Detailed event analysis encl HROCZKA,E J. Northeast Nuclear Energy Co. (subs. of Northeast Usilities HROCZKA,E.J. Northeast Utilities 82/10/14, HAYNES,R.C. Region 1. Office of Director Rpp. 15778:197, 24X Fiche: 50-336, 82/10/14,8210220060

- --B210220064 LER B2-038/03L-0 on B20918, surveillance testing indicated activity of 0 99 uCi dose equivalent I-I31 in primary coolant Caused by small number of degraded fuel pins BORCHERT.R Northeast Nuclear Energy Co (subs of Northeast Utilities) B2/10/14 Region in Office of Director ip 15778 199 24X Fiche 50-336,82/10/14,8210220060
- 8210260432 Forwards LER 82-040/03L-0 MR0C2KA: E J Northeast Nuclear Energy Co (subs of Northeast Utilities). MR0C2KA: E J Northeast Utilities. 82/10/17 HAYMES: R C. Region 1, Office of Director 1p 15806.291. 24X Ficha: 50-336,82/10/17,8210260432
- --B210260441 LER B2-040/03L-0:on B2091B.acceptance criteria not met when containment personnel airlock test performed Caused by leaking gasket on inner airlock door. Oasket replaced & successful leak test performed BUFFY.B Northeast Nuclear Energy Co (subs of Northeast Utilities) B2/10/17. Replon i. Office of Director 1p. 15806 292 24X Fiche: 50-336,82/10/17.8210260432

DOCKET 50-338 NORTH ANNA POWER STATION, UNIT 1

- F Security, medical, emergency & fire protection plans
- 8210250208 Forwards "Full-Scale Emergency Exercise North Anna Power Station, Sept 1982, Exercise Manuel," per NRC 820129 1tr.
 LEABBURG, R. H. Virginia Electric & Power Co. 82/08/30 0'REILLY, J. P. Region 2, Office of Director. 1p 15791 205 24X Fiche: 50-338, 82/08/30, 8210250208
- --8210250212 "Fuil-Scale Emergancy Exercise, North Anna Power Station, Sept 1982: Exercise Manual " * Virginia Electric & Power Co 82/08/27 243pp 15791 206, 24X Fiche, 50-338, 82/08/30, 8210250208
- B210010125 Forwards revised security training & qualification plans Plans withheld. LEASBURG,R.H Virginia Electric & Power Co. 82/09/17. DENTON.H.R Office of Nuclear Reactor Regulation. Director. VARQA.S.A. Operating Reactors Branch 1. 1p 15566.013 24X Fiche 50-000.82/09/17.8210010125
- 8210130105 Releases public version of emergency response plans FELTON, J. M. Division of Rules and Records 82/09/28. Document Management Branch. 1p 15693-001 24X Fiche: 50-338,82/09/28, 8210130105.
- --B210130112 Forwards public version of emergancy response plans for Louise, Spotsylvania, Carolina, Hanover & Grange Counties, VA LEASBURG, R H. Virginia Electric & Power Co. 82/09/20 O'REILLY, J. P. Region 2. Office of Director. 1p. 15693, 002 24X Fiche, 50-338, 82/09/28, 9210130105
- --8210130114 Public version of facility emergency response plans consisting of radiological emergency response plans for Louisa.83potsylvania.Caroline.Hanover & Orange Counties, VA. * Virginia Electric & Power Co. 82/08/30. 432pp. 15693-004 24X Fiche.50-338.82/09/28.8210130105.
- 8210050076 Submits correction to 820628 Revision 3 to response to NUREO-0737. Item I D 2, "Safety Parameter Display Sys "Correction should be included in schedular exceptions pertaining to emergency response capabilities.

 LEASBURG, R. H. Virginia Electric & Power Co B2/09/29. DENTON, H. R. Office of Nuclear Reactor Regulation, Director. EIBENHUT, D. O. Division of Licensing. ip. i3603:185 24X Fiche. 50-000; 82/09/29, B210050076
- 8210050335 Forwards revised pages to App R post-shutdown review.Revised pages concern results of study which calculated time available after stuck open power operated relief valve event before unsafe condition reached.

 LEABURD.R.H. Virginia Electric & Power Co. B2/09/30. DENTON.H.R. Office of Nuclear Reactor Regulation, Director. CLARK.R.A. Operating Reactors Branch 3. 3pp 15610:095. 24X Fiche: 50-338, 82/09/30, 8210030335.
- 8210220454 Forwards IE Insp Repts 50-338/82-33 & 50-339/82-33 on 820918 No noncompliance noted, DANCE.H.C. Division of Project & Resident Programs, 82/10/04. LEASBURG.R.H. Virginia Electric & Power Co. 2pp. 15779;135 24X Fichs. 50-338, 82/10/04, 8210220454.

ή, μ

--8210220461 IE Insp Repts 50-338/82-33 k 50-339/82-33 un 820918.No noncompliance noted Major areas inspected, full-scale radiological exercise.

HUFFHANIG. N., MARBION.R. R., JENKINS.G.R. Division of Engineering & Technical Programs. 82/09/30. 11pp. 15779:137 24X
Ficha. 80-338.82/10/04.8210220454

O Adjudicatory correspondence

- 8210260348 Petition of Concerned Citizens of Louise County for leave to intervene & request for hearing re proposed license amend to authorize receipt & storage of Surry epent reactor fuel at North Anna Certificate of Svc encl DOUGHERTY, JB Dougherty, JB 82/10/22 Commissionere 8pp 15803 180 24X Fiche 50-338.82/10/22.8210260348
- 8210260355 Petition of Concerned Citizens of Louise County for leave to intervene & request for hearing re-proposed license amend authorizing increase in capacity of spent fuel pool Notice of appearance & Certificate of Svc encl DOUOHERTY,J B. Duugherty, J B. 82/10/22 Commissioners 7pp 15802,350 24X Fiche 50-338,82/10/22,8210260355
- 8210250367 Patition of County of Louisa, VA & Board of Bujervisors of County of Louisa, VA to intervene re proposed license amend to permit receipt & storage of 300 spent fuel assemblies from Burry Certificate of Bvc encl.

 COLEMAN, J. H. Louisa County, VA COLEMAN, J. M. Beveridge, Fairbants, & Diamond 82/10/22 Commissioners 13pp. 15803.111 24X Fitche, 50-338, 82/10/22, 8210260367
- 8210260373 Petition to intervene of County of Louisa, VA & Board of Supervisors of County of Louisa, VA re proposed license anend to expand fuel storage capacity Certificate of Svc encl COLEMAN, J & Louisa County, VA COLEMAN, J & Beveridge, Fairbants, & Diamond 82/10/22 Commissioners 15pp 15803 143 24X Fiche 50-338, 82/10/22, 8210260373
- B210280238 Notice of ASLS constitution. BJ Wolferchairman & J R] in a CA Ferguson, members LAZO, R M Atomic Befety and Licensing Board Panel 82/10/26 2pp 15837-060 24X Fiche 50-338, B2/10/26, B210280238
- 9210280300 Notice of ASLS constitution, BJ Wolferchairman & J Kline & OA Ferguson: Members LAZD, R M Atomic Bafety and Licensing Board Panel, 82/10/26, 259 15837 281, 24% Fiche, 50-338, 82/10/26, 9210280300.
- P Operating license stage documents & correspondence
- 8208090114 Application for amend to Licenses NPF-4 & NPF-7, authorizing receipt & storage of 500 spent fuel assemblies from Surry Units 1 & 2 Rept entitled "Spent Fuel Storage" enci LEASBURD.R. H. Virginia Electric & Pawer Co. 82/07/13, DENTON.H R Office of Nuclear Reactor Regulation, Director CLARK.R A Operating Reactors Branch 3, 2pp 15567,244, 24% Fiche: 50-338,82/07/13,8208090114.
- --B210010246 Proposed Yech Specs allowing receipt & storage of 500 spent fuel assemblies from Burry # Virginia Electric & Power Co. B2/07/13. 4pp 15569.246 24r Fichet 50-338,82/07/13,8208090114.
- --8210010247 "Spent Fuel Storage"

 * Virginia Electric & Power Co 82/07/31. 86pp 18569 251 24r
 Fiche. 50-338, 82/07/13, 8208090114.
- 8210040277 Advises of plans for const of new 230 kV transmission lins to connect North Anna power station to Louisa substation No Tech Spec or ETB change required.

 LEASBURGOR. M. Virginia Electric & Power Co 82/09/27 DENTON: HR Office of Nuclear Reactor Regulation. Director CLARK: R. A Operating Reactors Branch 3. 2pp. 15591.204 24X Fiche. 50-338: 82/09/27.8210040277
- --8210040285 Responds to util 761109 ltr informing that 740102 k 740408 ltrs did not constitute application for const of 230 kV transmission line from North Anna to Louisa Substation Ref to line has been removed from FEB addendum YOUNGELOOD. B. J. Environmental Projects Branch 2 76/11/24 PROFFITT, N. L. Virginia Electric & Power Co. 5pp 15591.206 241 Fiche: 50-338, 82/09/27, 8210040277.
- --8210040270 Advises that util 740102 & 750508 ltrs to NRC do not constitute application for const of 230 kV transmission lins from North Anna to Louisa. Application; if required, will be filed prior to OL issuance for Unit 2.

 PROFFITT, M. L. Virginia Electric & Power Co 75/11/09.

 RUSCHE, B. C. Office of Nuclear Reactor Regulation, Director YOUNGELOOD, B. J. Environmental Projects Branch 2. ip. 15591:212

 24X Fiche: 50-338, 82/09/27, 8210040277.
- --B210040297 Forwards add1 info & answers to questions in NRC 750820 ltr re 230 kV transmission line. PROFFITT. M. L. Virginia Electric & Power Co. 76/08/30, RUBCHE, B. C. Office of Nuclear Reactor Regulation, Director YOUNGBLOOD, B. J. Environmental Projects Branch 2. 6pp, 15591 213 24X Fiche: 50-338,62/09/27,6210040277.

- --8210040301 "Mgt of Transmission Line Rights of Way "

 * Enviro Audits 76/07/31 77pp 15591 219 24% Fiche 50-338.82/09/27.8210040277
- --8210040307 Requests add1 info by 760830 to complete assessment of environ impact of 230 kV transmission line
 YOWNORLOOD, B J Environmental Projects Branch 2, 76/08/20
 PROFFITT, W L Virginia Electric & Power Co 2pp 15591 296 24
 Fichs 30-338,82/09/27,8210040277
- --8210040315 Forwards one oversize topographical map & application to VA State Corp Commission for approval & certification of North Anna to Louisa transmission line in response to NRC 760630 request Aperture card is available in PRR PROFFITT.W L Virginia Electric & Power Co 76/07/06 RUSCHE.B C Office of Nuclear Reactor Regulation, Director 15591.278 24X Fiche 50-338.82/09/27.8210040277
- --B210040320 Advises of need for NRC evaluation of environ impact of const & operation of North Anna Gordonsville 230 kV transmission line, per util 740102 760608 ltrs. Addl info needed by 740707 YDUNOBLODD. B J Environmental Projects Branch 2 74/06/30 PROFFITT. W L. Virginia Electric & Power Co 2pp 15591 327 24X Fichs 50-338,82/09/27,8210040277
- --B210040325 Advises that proposed 230 kV transmission line between North Anna & Louise need not be evaluated in amend to environ rept for North Anna i & 2 Line is not part of North Anna utilitation facility

 RAGONE. B Virginia Electric & Power Co 74/01/02 MULLER, D R

 Atomic Energy Commission 2pp 15591 329 24X

 Fisch 50-338,82/09/27,8210040277
- 821G120215 Application to amend Licenses NPF-4 & NPF-7, revising Tech Specs re staff working hours Request does not involve Unravisued safety question per 100FR50 59 LFASBURG, R H Virginia Electric & Power Co 82/10/01 DENTON, H R Diffice of Nuclear Reactor Regulation, Director 1p. 15652:150 24X Fiche 50-338, 82/10/01, 8210120215
- --B210120225 Proposed Tech Boecs revising staff working hours Provision does not permit shift crew position to be unmanned upon shift change due to late on absent oncoming shift crewman.

 * Virginia Electric & Power Co 82/10/01 App 15652.151. R4X Fiche 50-338,82/10/01,8210120215
- 8210120265 Informs of implementation status of NUREQ-0737. Item II B 2, "Plant Shielding" per NRC 820517 request All required work completed LEASSURO.R H Virginia Electric & Power Co 82/10/01. DENTON.H R Office of Nuclear Reactor Regulation, Director EISENHUT, D 0 Division of Licensing 2pp 15651 230 24% Fichs 50-000.82/10/01.8210120265.
- 8210120277 Forwards errate to Topical Rept VEP-FRD-33, "VEPCO Reactor Core Thermal-Hydraulic Analysis Using COBRA IIIc/HIT Computer Code "
 LEASBURG, R. H. Virginia Electric & Power Co. 82/10/04 DENTON, H.R. Office of Nuclear Reactor Regulation, Director EISENHUT, D.Q. Division of Licensing 2pp 15652 330, 24X Fiche.50-000, 82/10/04, 83/101203037
- --82i0120305 Errata to "VEPCO Reactor Core Thermal Hydraulic Analysis Using COBRA-IIIc/MIT Computer Code "

 Virginia Electric & Power Co VEP-FRD-33 ERR. 82/10/04 lp. 15652 332 24X Fiche 50-000, 82/10/04-82i0120297
- 8210290042 Forwards safety evaluation & tachnical evaluation rept re analysis of main steam line break w/continued feedwater addition Analysis acceptable W/c technical evaluation, CLARK.R A Operating Reactors Branch 3 82/10/04. LEASBURG.R H Virginia Electric & Power Co 1p. 15877, 271 24X Pichs 50-338, 82/10/04, 8210290042.
- --8210270071 Safety evaluation re main steam line break w/continued feedwater addition Containment overpressurfization will not result & auxiliary feedwater pumps can function during event.

 # Office of Nuclear Reactor Regulation, Director 82/10/04. App 15977 272 24X Fiche. 30-338. 82/10/04, 8210270042
- 8210290414 Forwards Amend 42 to License NPF-4: safety evaluation & notice of issuance & availability Amend revises average RCS tenp at currently licensed thermal power level. ENGLE.C.R. Operating Reactors Branch 3 82/10/04 LEASBURG.R.H. Virginia Electric & Power Co. 4pp 15863: 255, 24X Fiche. 50-338.82/10/04.8210290414.

- --8210290416 Amend 42 to License NPF-4, revising avarage RCB temp from 580 3 F to 582 8 F at current licensed thermal power level of 2,785 HW CLARK, R A. Operating Reactors Branch 3. 82/10/04 9pp 15863 259. 24X Fiche 50-338,82/10/04,8210290414
- --8210290418 8afety evaluation supporting Amend 42 to License NPF-4

 4 Office of Nuclear Reactor Regulation, Director 82/10/04 3pp.
 15863 268 24X Fiche 50-338.82/10/04.8210290414.
- --8210290421 Notice of issuance & availability of Amend 42 to Litense NPF-4 CLARK,R A. Operating Reactors Branch 3 B2/10/04 2pp 15863:271 24X Fiche 50-338,82/10/04,8210290414
- 8210270238 Forwards documents providing details of exams & evaluations performed by util & Westinghouse on failure of guide tube support pins main loop isolation valve guide & RCS thermal steeves.

 LEABBURO, R H Virginia Electric & Power Co. 82/10/12 DENTON, H. R. Office of Nuclear Reactor Regulation, Director CLARK, R. A. Operating Reactors Branch 3 7pp 15829 180 24% Fiche 50-338, 82/10/12.8810270258
- --8210270260 "North Anna Unit 1 Loose Thermal Bleeve Safety Evaluation," Descriptions of impact of postulated blockage on 1981 model LOCA analysis & operator awareness surveillance program encl.

 * Westinghouse Electric Corp. 28630 1 82/09/30 44pp. 15829-187 24X Fiche 50-338, 82/10/12, 8210270258
- 8210220011 Submits addl info to 820713 request for amend to Licenses NPF-4 & NPF-7, Number of storage locations in nautron absorber spent fuel storage rack changed to 1,737 Fuel pool temps changed in Table 7 1 LEASBURO.R.H Virginia Electric & Power Co 82/f0/18 DENTON, H R Office of Nuclear Reactor Regulation, Director. CLARK, R A Operating Reactors Branch 3, Spp 15778 211 24% Fiche; 50-338, 82/10/18, 8210220011
- 8210220178 Comments on svaluation of significant dynamic loads in determining capacity of slings used per NUREO-0612 Rating can be safely expressed in terms of max static load £288URO;R H Virginia Electric & Power Co. 92/10/18 DENTON, H. R Office of Nuclear Reactor Regulation, Director. EIBENHUT, D. G. Division of Licensing. 2pp 15777:293 24X Fiche: 30-000, 82/10/18. 8210220178
- 6210260133 Forwards revised Table 7-1 to "Bummary of Info in Support of Increasing Spent Fuel Storage Capacity at North Anna Units i & 2 " Rept originally submitted w/820820 request for amend to Licenses NPF-4 & NPF-7 to replace storage racks LEASBURO.R H Virginia Electric & Power Go 62/10/21 DENTON.H R. Office of Nuclear Reactor Regulation, Director. CLARK.R A Operating Reactors Branch 3 2pp. 15799 102 24X Ficher 50-338, 82/10/21,8210260133.
- ~-8210260136 Revised Table 7-1 to "Summary of Info in Support of Increasing Spant Fuel Storage Capacity at North Anna Units 1 & 2."

 + Virginia Electric & Power Co. 82/10/21, 1p. 15799:104 24X Fiche: 50-338, 82/10/21, 8210260133
- 8210270160 Advises that work re removal of RCB flow splitter plates completed. Ltrs from Westinghouse supporting continued operation of facility w/splitter plates removed encl LEASBURG, R. H. Virginia Electric & Power Co. 92/10/25. DENTON, H. R. Office of Nuclear Reactor Regulation, Director. CLARK, R. A. Operating Reactors Branch 3. 74pp. 15830.044 24X Fiche: 50-338, 82/10/25.8210270160.
- 8210270204 Forwards Westinghouse "North Anna Unit i Steam Generator Impacted Tube Ends Recovery Evaluation," photographs of steam generator A & C demaged tube sheets & summaries of snd damage repairs & reactor coolant pump failure LEASBURG.R.H. Virginia Electric & Power Co. 82/10/26 DENTON, H R. Operating Reactors Branch 3. 2pp. 15822-268. 24X Fiche: 50-338, 82/10/26, 8210270204.
- --8210270208 "North Anna Unit 1 Steam Generator Impacted Tube Ends Recovery Evaluation " PAXSON,E., KELLER,H T., CHENO,W.W. Westinghouse Electric Corp. AEA-FRPE-282 82/10/31 68pp 15822:270 24X Fiche:50-338,82/10/26,8210270204.

1

ł

Q Inspection reports, IE Bulletins & correspondence

- 8210220200 Responds to NRC ltr re violations noted in IE Inep Repts 50-338/82-08 & 50-339/82-08 Corrective actions health physics technician counseled re correct procedures for antering high radiation area LEABURGOR H Virginia Electric & Power Co 82/07/29 O'REILLY, J. P. Region 2, Office of Director 5pp i5777:265, 24X Fiche 50-336, 82/07/29,8210220200
- \$210070007 Responds to FOIA request for eight categories of records resteem generators & steam turbines App A documents provided in R Udell FOIA Request \$9:-313 Forwards documents listed in App B FELTON.J. M Division of Rules and Records. 82/08/10 LONO.D J Winthrop. Stimson, Putnem & Roberts. 9pp 15645:063 24X Fiche 50-000, 82/08/10.8210070007
- --8210070139 Forwards tabulated data on steam generator insp & maint at facilities Data should be provided to licenses.

 IPPOLITO.T Operating Reactors Assessment Branch 82/04/01 VAROA:8. Operating Reactors Branch 1. 5pp 13645.131. 24X Fiche 50-000.82/08/10.8210070007
- 8210010221 Forwards IE Insp Repts 50-339/82-18 & 50-339/82-18 on 820709-0805. No noncompliance noted DANCE.K.C. Division of Project & Resident Programs. 82/08/31 LEASBURO.R.H. Virginia Electric & Power Co 2pp. 15567 338 24X Fichs 50-338, 82/08/31.8210010221.
- --8210010225 IE Insp Repts 50-338/82-18 t 50-339/82-18 on 820709-0805 No noncompliance noted, Major areas inspected LERs, refueling & outage activities, surveyllance & maint activities, operations & followup on significant events.

 OBHNSON, D. F. . SHYMLJCK, M. B. . JULIAN, C. Division of Project & Resident Programe 82/08/31 ipp, 15567:340 24X
 Fiche 50-338,82/08/31.8210010221
- --B210010314 IE Inep Repts 50-338/82-28 & 50-339/82-28 on B20816-19.No noncompliance noted Major areas inspected:thermal sleave removal, reactor collent loop stop valves, tep screw fractures & broken control rad guide tube support pine YORK-J.W. BLAKE-J.J. Division of Engineering & Technical Programs B2/09/02 opp 15569.319, 24X Fiche:50-338,82/09/03.8210010300
- 6210190187 Forwards IE Insp Repts 50-338/82-30 & 50-339/82-30 on 820831-0903 No noncompliance noted. BANCE.H C. Division of Project & Resident Programs. 82/09/23 LEASBURG.R.H Virginia Electric & Power Co 2pp. 15707-262 24X Fichs 50-338, 82/09/23, 8210150187.
- --8210190194 IE Inep Repts 50-338/82-30 k 50-339/82-30 on 820831-0903. No noncompliance hoted Major areas inspected.generator step-up transformer failure on 820822 k licenses recommendations k inspector follows items.

 RUFFIA B : CONLON.T.E. Division of Engineering & Technical Programs. 82/09/17. 4pp. 15707.264. 24X Fiche 50-338,82/09/23,8210150187.
- 8210220454 Forwards IE Insp Repts 50-338/82-33 & 50-339/82-33 on 820918. No noncompliance noted.

 DANCE.H.C. Division of Project & Resident Programs. 82/10/04. LEASBURGOR. H. Virginia Electric & Power Co. 2pp 15779:135. 24X Fichs. 50-338, 82/10/04, 8210220454.
- --8210220461 IE Inep Regts 50-338/82-33 k 50-339/82-33 on B20918.No noncompliance noted Major areas inspected full-scale radiological exercise.

 HAFFIAN.O. N. HARBTON.R.R., JENKINS.Q.R. Division of Engineering & Tachnical Programs. 82/09/30. 11pp. 15779:137. 24X
 Fichs.50-338.82/10/04.8210220454
- 8208190233 IE Info Notice 80-35, Suppl 1, "Leaking & Dielooged I-125 Implant Seeds," Svc list encl. CQBB,L.I. Division of Fuel Facilities, Materials & Gafeguards 82/10/06 Consolidated Edizon Co. of New York. 66pp. 13741-250, 24X Fiche. 50-000, 82/10/06, 8208190233.
- 8208190238 IE Bulletin 82-03. "Stress Corrosion Cracking in Thick-Hall.Large-Diameter Stainless Steel Recirculation Sysfiping at 84R Plants," Syc ligt encl.
 DEYOUNGR C. Director's Office. Office of Inspection and Enforcement. 82/10/14. Consolidated Edison Co. of New York 115pp 15810; 125. 24X Fiche: 50-000, 82/10/14, 8208190238.

- 8 Reportable occurrences. LERs & related correspondence
- 8009240202 Forwards analysis of 800523 trip & subsequent safety injection at facility Some operating nuclear plants lack controls restricting starting of electrical motors while emergency diesel generator is undergoing load tests HICKELBON.C Director's Diffice 80/08/20 JORDAN.E L Division ce Reactor Operations Inspections. 3pp 15670 018 24X Fiche 50-338,80/08/20,8009240202
- B210010008 Responds to FOIA request for 19 categories of documents re nuclear reactor events & safety problems, Forwards documents listed in App A FELTON, J. H. Division of Rules and Records 82/06/28 UDELL, R.A. Critical Mass Energy Project 15pp 13727 005 24X Fiche 30-000, 82/06/28, 8210010008
- --BiiiiBOOO1 Recommends comprehensive assessment of plant operating conditions to determine specific predetermined time related sequences of occurrence to emergency buses SRP should be revised re design features.

 ASHE-F Director's Office BI/10/16 MICHELSON.C Director's Office 4pp. 13731:049 24X Fiche: 50-000.B2/06/28,821001000B
- 8210010140 Forwards LER 82-058/03L-0 CARTHRIGHT.W R. Virginia Electric & Power Cd 82/09/22 O'REILLY, J.P. Region 2. Office of Director ip 15565 346 24X Fiche: 50-338, 82/09/22, 8210010140
- --8210010145 LER 82-058/03L-0. on 820826, manipulator crane area monitor RM-RMS-162 failed to meet acceptance criteria of periodic calibr & declared inoperable Caused by instrument drift greater than 3% response requirement Assembly replaced CARTHRIGHT. W. R. Virginia Electric & Power Co. 82/09/22 Region 20 Office of Director 3pp. 15565-347 24X Fiche 50-338, 82/09/22 B2109/22 B2109/22 B210010140
- 8210010163 Forwards LER 82-059/03L-0 CARTWRIGHT: W R. Virginia Electric & Power Co 82/09/22 U'REILLY.J P. Region 2: Office of Director ip. 15867 274 24X Fiche. 80-338: 82/09/22: 8210010163
- --B210010168 LER B2-059/03L-0. on B20827, ventilation vent B gaseque radiation detector response found to exceed calibr test acceptance criteria Caused by gradual deterioration of shotomultipliar tube & preempliffer. Parts replaced CARTHRIGHT, WR Virginia Electric & Power Co. B2/09/22 Region 2: Diffice of Director 2pp 15567-275 24X Fiche 50-338, 82/09/22, B210010163
- 8210010209 Forwards LER 82-05D/03L-0. CARTHRIGHT.W.R. Virginia Electric & Power Co. 82/09/22 O'REILLY, J.P. Region 2. Office of Director ip 13567 334, 24X Fiche-50-33B.82/09/22.8210010209,
- --9210010219 LER 82-050/03L-0'an 820826; fire doors A80-1 & A80-2 between Units 1 & 2 rod control rooms & auxiliary bldg & fire doors A57-1 & A57-2 between Units 1 & 2 cable vault rooms & auxiliary bldg found not in periodic teating program. CARTWRIGHT, N.R. Virginia Electric & Power Co 82/09/22, Region 2, Office of Director. 1p. 15567-335 24X Fiche 50-338,82/09/22,8210010209.
- 8210220227 Forwards LER 82-057/03L-0. CARTHRIGHT.W.R. Virginia Electric & Power Co 82/10/07 O'REILLY.J.P. Region 2. Office of Director, 1p 15775.126 24X Fiche: 50-338.82/10/07.8210220227.
- --8210220234 LER 82-037/03L-0.on 820710, setpoint for turbins impulse pressure comparator in instrument procedure found incorrect. Caused by typographical error during procedure revision. Procedure corrected & card recalibr CARTMRIOHT. H. R. Virginia Electric & Power Co. 82/10/07. Region 2, Odfice of Director 3pp. 13775-127. 24X Fiche. 50-338, 82/10/07, 8210220227
- 8210190264 Forwards LER 82-062/03L-0 CARTWRIGHT, W. R. Virginia Electric & Power Co. 82/10/12. O'REILLY, J. P. Region 2: Office of Director. 1p. 15742 192 24X Fiche: 50-338 82/10/12:8210190264.
- --8210190270 LER 82-062/03L-0; on 820917; cold leg injection line check valve found w/five corroded bolts. Caused by small lesk at body to bonnet gasket. Stude & bonnet gasket replaced. CARTHRIGHT. H. R. Virginia Electric & Power Co. 82/10/12, Regian 27 Office of Director. 2pp. 13742:193 24X Fiche: 50-338, 82/10/12, 8210190264.
- 8210190329 Forwards LER 82-061/03L-0.
 GARTHRIGHT W.R. Virginia Electric & Power Co. 82/10/12.
 O'REILLYJ,F. Region 2: Office of Director. 1p 15742:061. 24X
 Fiche; 50-338, 82/10/12. 8210190329.

- e2i0190337 LER 82-061/03L-0 on 820917, during chemistry log review, specific activity of primary coolant exceeded Tech Specs Caused by exgration of I-131 through pinhole leaks in fuel cladding Specific activity returned to acceptable limits CARTHRIGHT. WR. Virginie Electric & Power Co 82/10/12 Region 2. Office of Director 4pp 15742 062 24X Fiche 50-338, 82/10/12,8210190329
- 110290337 Forwards LER 82-065/03L-0 (ARTHR10HTN R Virginia Electric & Power Co 82/10/13 D'REZLCY, V P Region 2, Office of Director ip 15853 029, 24X Fichs: 50-338, 82/10/13, 8210290337
- 8210290347 LER 82-065/03L-0 on 820919, routine recalibr of pressurizer level transmitter LT-1-461, revealed transmitter out of tallibr Coursed by instrument drift Transmitter replaced. New transmitter calibr successfully CARTHRIGHT, N R Virginia Electric & Power Co 82/10/13 Region 2. Office of Director ip 15853 030 24X Fiche 50-338, 82/10/13, 82/10790337
- 210240270 Forwards LER 82-063/03L-0 CARTHRIGHT H R Virginie Electric & Power Co 82/10/19 D'REILLY, J.P. Region 2, Office of Director 1p 15803, 215 24X Fiche 50-338, 82/10/19, 8210260290
- -8210250293 LER 82-063/03L-0 on 820924, ambient temp signal conditioner & control room delta temp recorder responses found to exceed calibr procedure acceptance criterie. Caused by instrument drift instruments receibr CARTHRICHT, U.R. Virginia Electric & Power Co. 82/10/19 Region 2-07/10-06 Office of Office of Office of Section 3pp. 15803-216-24X Fiche. 50-338. 82/10/19, 82/10/260290
- OCKET 50-339 NORTH ANNA POWER STATION, UNIT 2

 Security, medical, emergency & fire protection plans
- *210250208 Forwards "Full-Scale Emergency Exercise North Anna Power Station.Sept 1982.Exercise Menual." per NRC 820129 ltm LEASBURG.R H Virginia Electric & Power Co 82/08/30 D'REILLY.J P Region 2. Office of Director 1p 15791.205 24X Fiche 50-338.82/08/30.8210250208
- --8210250212 "Full-Stale Emergency Exercise North Anna Power Station, Sept 1982: Exercise Manuel " " Virginia Electric & Power Co 82/08/27 243pp. 15791: 206 24x Fiche 50-338.82/08/30.8210250208
- B210030125 Forwards revised security training & qualification plans Flams withheld.
 LEASBURG, R H Virginia Electric & Power Co. 82/09/17, DENTON, H. R. Office of Nuclsar Reactor Regulation, Director ip 15346:013, 24X Fichs 50-000, 82/09/17, 8210010125
- B210130105 Releases public version of emergency response plans.
 FELTON, J M Division of Rules and Records 82/09/28 Document
 Management Branch ip 15693 001 24X Fiche. 50-338, 82/09/28,
 8210130105
- --8210130112 Forwards public version of emergency response plans for Louisa. Spotsylvania. Carolina, Hanover & Orense Counties. VA LEASBURO. R. H. Virginia Electric & Power Co 82/09/20 O'REILLY. J. P. Region 2. Office of Director. 1p 15693'002. 24% Fiche-50-338, 82/09/28, 8210130105.
- --B210:30:14 Public version of fecility emergency response plan, consisting of radiological emergency response plans for Louise. Bpotsylvania: Caroline; Hanover & Orange Counties, VA W Virginia Electric & Power Co B2/08/30 632pp 15693: 004, 24x Fiche: 50-338, 82/09/28, 8210130105.
- 8210050076 Submits correction to 820628 Revision 3 to response to NUREQ-0737. Item I D 2. "Safety Parameter Display Sys."
 Correction should be included in schedular exceptions gertaining to amergency response capabilities.
 LEABBURO, R H Virginie Electric & Power Co. 82/09/29. DENTON. H. R Office of Nuclear Reactor Regulation, Director. 1p. 24X
 Fiche: 50-000, 82/09/29, 8210050076.
- 8210050335 Forwards revised pages to App R post-shutdown review Revised pages concern results of study which calculated time available after stuck open power operated relief valve event before unsafe condition reached LEASBURO, R H. Virginia Electric & Power Co 82/09/30. DENTON: H R. Defice of Nuclear Reactor Regulation. Director. CLARK. R. A. Operating Reactors Brench 3 3pp. 15610.095, 24X Fische 50-338,82/09/30,8210050335

- 8210220454 Forwards IE Insp Rapts 50-338/82-33 & 50-339/82-33 on 820918 No noncompliance noted DANCE: H C. Division of Project & Resident Programs B2/10/04 LEASBURG: R W. Virginia Electric & Power Co. Rpp. 15779.135, 24X Fiche: 50-338.62/10/04.8210220454
- --8210220461 IE Insp Repts 50-339/82-33 & 50-339/82-33 on 820718 No noncompliance noted Major areas inspected full-scale rediciosical exercise.

 HUFFMAN.G N. Division of Engineering & Technical Programs 82/09/30. 11pp. 15779.137. 24X Fiche.50-338.82/10/04.8210220454.
- O Adjudicatory correspondence
- 8210260348 Patition of Conternsd Citizens of Louisa County for leave to intervene & request for hearing re proposed license amend to authorize receipt & storage of Surry spent reactor fuel at North Anna Certificate of Siv encl DOUGHERTY, J B Dougherty, J B 82/10/22 Commissioners Spp. 13503 180 24X Fiche 30-338,82/10/22,8210260348.
- 8210260355 Petition of Concerned Citizens of Louise County for leave to intervene & request for hearing re proposed license amend authorising increase in cepacity of spent fuel pool Notice of appearance & Certificate of Svc encl.

 DOUGHERTY, J. B. Dougherty, J. B. 82/10/22 Commissioners. 7pp 15802 350 24% Fishe 50-339, 82/10/22, 82/0260355.
- 82102&0367 Patition of County of Louisa, VA & Board of Supervisors of County of Louisa, VA to intervene re proposed license amend to permit receipt & storage of 30D spent fuel assemblies from Surry Certificate of Svc encl
 COLEMAN, J H Louisa County, VA COLEMAN, J H Beveridge, Fairbanks, & Diasond 82/10/22 Commissioners 13pp, 15803.111. 24%
 Fiche. 50-338, 82/10/22, 8210260367.
- 8210260373 Petition to intervene of County of Louisa.VA & Board of Supervisors of County of Louisa.VA re proposed license amend to aspand fuel storage capacity Certificate of Suc enci. COLEMAN.J.M Louisa County, VA COLEMAN.J.M Beveridge, Fairbanks, & Diamond. 82/10/22. Commissioners. 15pp 15803,143, 24X Fiche: 50-338.82/10/22,8210260373.
- 8210280238 Notice of ASLB constitution BJ Wolfe, chairman & J Kline & OA Ferguson, members LAZO, R. M. Atomic Safety and Licensing Board Panel, 82/10/26 2pp. 15837 O60 24% Fiche 50-338, 82/10/26, 8210280238
- 8210280300 Notice of ASLS constitution SJ Wolfe, chairman & J Kline & GA Ferguson, members.
 LAZO, R. M. Atomic Safety and Licensing Board Panel. 82/10/26. 2pp. 15837: 281. 24X Fiche 50-338, 82/10/26, 8210280300
- P. Operating license stage documents & correspondence
- 8210010008 Responds to FOIA request for 19 categories of documents re nuclear reactor events & safety problems. Forwards documents listed in App A FELTON.J M Division of Rules and Records. 82/06/28 UDELL.R.A. Critical Mass Energy Project. 15pp. 15727 005 24x Fichs.50-000.82/06/28.8210010008
- --8008050265 Discusses addl required into to better define potential for cracking in reactor yessel nozzles.

 NOONAMA V. B Assistant Director for Materials & Qualifications Engineering 80/05/05. TEDESCO.R.L. Assistant Director for Licensing. 2pp. 15727:176. 24X Fiche.50-000.82/06/26.8210010008.
- 8208090114 Application for amend to Licenses NPF-4 & NPF-7, authorising receipt & storage of 300 spent fuel assemblies from Surry Units 1 & 2. Rept entitled "Spent Fuel Btorage" encl. LEABSURGER.H. Virginie Electric & Power Cb 82/07/13, DENTON, H R, Office of Nuclear Reactor Regulation, Director. CLARK, R. A. Operating Reactors Branch 3, 2pp 15569:244, 24% Fiche: 50-338, 82/07/13, 8208090114.
- --8210010246 Proposed Tech Specs allowing receipt & storage of 500 spent fuel assemblies from Surry

 * Virginia Electric & Power Co 82/07/13 App. 15569.246. 24x Fiche: 50-338.82/07/13.8208090114.
- --8210010247 "Spent Fuel Storage,"
 4 Virginia Electric & Power Co. 82/07/21, 84pp. 15549,251, 24X
 Fiche 50-338,82/07/13,8208090114.

- 8210010103 Forwards application for amend to License NPF-7, to complete License Conditions 2 C(15)(h)(4) & 2 C(h)(15)(2) by end of second refueling outage LEABSURG.R H Virginia Electric & Power Co 82/09/27 DENTON, H R Office of Nuclear Reactor Regulation, Director CLARK, R A Operating Reactors Brench 3. Spp 15567.185 24%
- 8210040277 Advises of plans for const of new 230 kV transmission line to connect North Anne power station to Louise substation No Tech Spec or ETS change required LEASBURGOR H Virginis Electric & Power Co 82/09/27 DENTON, H R Office of Nuclear Reactor Regulation, Director CLARK. R A Operating Reactors Brench 3 2pp 15591 204 24% Fiche 50-338, 62/09/27, 8210040277
- --8210040285 Responds to util 761107 ltr informing that 740102 & 760008 ltrs did not constitute application for const of 230 %V transmission line from North Anna to Louisa Bubstation Ref to line has been removed from FEB eddendum YOUNOBLOOD, B J. Environmental Projects Branch 2 76/11/26 PROFFITT, W L. Virginia Electric & Power Co Spp 15591.204 24% Fichs 50-338,82/09/27,8210040277
- --B210040270 Advises that util 740102 & 740408 ltrs to NRC do not constitute epplication for const of 230 kV transmission line from North Anna to Louisa Application, if required, will be filed prior to OL issuance for Unit 2
 PROFFITT, W L, Virginia Electric & Power Co 74/11/09, RUBCHE, B C Office of Nuclear Reactor Regulation, Director YOUNDBLOOD, 8 J Environmental Projects Branch 2 ip 15591 212 24X Fiche. 50-339, 82/09/27, 8210040277
- --B210040297 Forwards add1 info & answers to questions in NRC 760820 ltr re 230 kV transmission line PROFFITT, W L Virginis Electric & Power Co. 76/08/30 RUSCHE, B C. Office of Nuclear Reactor Regulation, Director YUNORLO
- --8210040301 "Mgt of Transmission Line Rights of Way " * Enviro Audits. 76/07/31. 77pp 15371:217 24X Fichs 50-338,82/09/27.8210040277.
- --8210040307 Requests add1 info by 760830 to complete assessment of environ impact of 230 iV transmission line.
 YOUNDELOOD, B J Environmental Projects Branch 2 76/08/20
 PROFFIT, H L Virginia Electric & Power Co 2pp 15591.276 24X
 Fiche. 50-338, 82/09/27, 8210040277.
- --82:0040315 Forwards one oversize topographical map & application to VA State Corp Commission for approval & certification of North Anna to Louisa transmission line in response to NRC 760630 request Aparture card is available in PDR.

 PROFFITT, W L Virginia Electric & Power Co 76/07/06.

 RUSCHE, B C @ffice of Nuclear Reactor Regulation, Director 29ap.
 13591.298 24X Fiche: 50-339, 82/09/27, 8210040277.
- --B210040325 Advises that proposed 230 kV transmission line between North Anna & Louise need not be avaluated in amend to environ rept for North Anna i & 2. Line is not part of North Anna utilisation fecility.

 RACOMES Virginia Electric & Power Co 74/01/02 MULLER, D. R. Atomic Energy Commission. 2pp. 15591: 329 24X Fiche: 50-338, 82/09/27, 8210040277.
- 8210120215 Application to amend Licenses NPF-4 & NPF-7, revising Tech Specs Te steff working hours. Request does not involve unrevisued safety question per 100FR50. 59 LEABURG.R.H. Virginia Electric & Power Co. 82/10/01. DENTON, H R Office of Nuclear Reactor Regulation. Director. 1p. 15652.150. 24x Fiche 50-338, 82/10/01/8210120215.
- --8210120225 Proposed Tech Bpecs revising staff working hours. Provision does not permit shift crew position to be unmanned upon shift change due to late or absent oncoming shift crewmen.

 Virginia Electric & Power Co 82/10/01. 4pp 19652:151, 24x Fiche: 30-338,82/10/01.8210120215.
- 8210120265 Informs of implementation status of NUREO-0737. Item II. B.2, "Plant Shielding" per NRC 820517 request. All required work completed.

 LEASBURG.R.H. Virginia Electric & Power Co. 82/10/01, DENTON. H.R. Office of Nuclear Reactor Regulation, Director, 2pp. 15651-230. 24X Fiche. 50-000.82/10/01.8210120265.

- 8210120297 Forwards errata to Topical Rept VEP-FRD-33. "VEPCO Realist Core Thermal-Hydraulic Analysis Using COBRA IIIc/HIT Computer Code." LEABOURG.R H Virginia Electric & Power Co. 82/10/04 DENTON.K R Office of Nuclear Reactor Regulation, Director 2pp 15852 330 24X Fiche 50-000,82/10/04.8210120297
- --8210120305 Erreta to "VEPCO Reactor Core Thermal Hydraulic Analysis Using COBRA-Ilic/MIT Computer Code " • Virginia Electric & Power Co VEP-FAD-33 ERR 13632 332 24% Fiche 50-000.82/10/04.8210120297
- 8210270042 Forwards safety evaluation & technical evaluation rept ra analysis of main steam line breek w/continued feedwater addition Analysis acceptable H/o technical evaluation CLARK,R A Operating Reactors Dranch 3 82/10/04 LEASBURO,R X Virginia Electric & Power Co 1p 15877 271 24X Fiche 50-338,82/10/04,82/10270042
- --B210290071 Bafety evaluation re main stram line breek w/continued fredweter addition Contelment overpressurization will not result & auxiliary feedwater pumps can function during event
 - * Office of Nuclear Reactor Regulation, Director 82/10/04 6j; 15877 272 24X Fiche 50-338.82/10/04.8210290042
- 8210190321 Bubmits supplemental info re B20318 & 0927 requests for relief concerning License Condition 2 C(15)(h)(4) Qualified pressure switches unaveilable Nonqualified switches will be installed by B21031 Qualification expected by Jan 1993 LEABBURO,R H Virginia Electric & Power Co 82/10/13 DENTOM:H R Office of Nuclear Reactor Regulation. Director CLARK,R A Operating Reactors Brench 3 1p 15742.058 24X Ficher 30-339, 82/10/13, 8210190321
- 8210220011 Submits addl info to 820713 request for emend to Lichness NPF-4 & NPF-7 Number of storage locations in neutron absorber spant fuel storage rack changed to 1,737 Fuel pool temps changed in Table 7 1

 LEABBURG, R. H. Virginia Electric & Power Co. 82/10/18 DENTON, H. R. Office of Nuclear Reactor Regulation, Director CLARK, R. A. Operating Reactors Branch 3 3p 15778 211 24X Fiche: 50-338, 82/10/18, 8210220011
- 8210220178 Comments on evaluation of significant dynamic loads in determining capecity of slings used per NUREO-0612 Rating can be safely expressed in terms of mar static load LEABBURG, R H. Virginia Electric & Power Co. 82/10/18 DENTON.M.F. Office of Nuclear Reactor Regulation. Director 2pp 15777 273 24X Fiche 50-000.82/10/18.8210220178
- 8210260133 Forwards revised Table 7-1 to "Bummary of Info in Support of Increasing Spent Fuel Storage Capacity at North Anna Units is 2." Rept originally submitted w/820820 request for amend to Licenses NPF-4 & NPF-7 to replace storage racks LEASBURG.R H Virginia Electric & Power Co 82/10/21 DENTON.H R Office of Nuclear Reactor Regulation. Director CLARK,R A Operating Reactors Branch 3 2pp 15799:102 24X Fichs: 50-338, 82/10/21, 8210260133.
- --8210260136 Revised Table 7-1 to "Summary of Info in Support of Increasing Spent Fuel Storage Capacity at North Anna Unite 1 & 2 "

 ** Virginia Electric & Power Co. 82/10/21 1p 15799.104, 248 Fiche 50-338,82/10/21,8210260133
- Q Inspection reports, IE Bullstins & correspondence
- 8210220200 Responds to NRC ltr re violations noted in IE Imap Repts 50-339/82-08 & 50-339/92-08 Corrective actions health physics technician counseled re correct procedures for entering high radiation area.

 LEABBURG H. Virginia Electric & Power Co 82/07/29.

 0/REILLY, J.P. Region 2, Office of Director. 5pp 15777, 265 242 Fiche: 50-338, 82/07/29, 8210220200
- 8210070007 Responds to FOIA request for eight categories of recersiva steam generators & steam turbines. App A documents provided in R Udell FOIA Request 81-313. Forwards documents listed in App B.
 FELTON, J. M. Division of Rules and Records 82/08/10 LONG, D J Winthrop, Stimson, Putnam & Roberts, 9pp 15645, 063, 24% Fiche; 50-000, 82/08/10, 8210070007.
- --8210070139 Forwards tabulated data on steam generator inep & mist of facilities. Deta should be provided to licensess IPPOLITO, T. Operating Reactors Assessment Branch. 82/04/01 VAROA: S. Operating Reactors Branch 1. Spp. 15645.131 24X Fiche: 50-000, 82/08/10, 8210070007.

- 8210010221 Forwards IE Insp Repts 50-338/82-18 & 50-339/82-18 on 820709-0803 No noncompliance noted DAKCE.H C Division of Project & Resident Programs 82/08/31. LEASBURG.R H Virginia Electric & Power Co 2pp 15547 338 24X Fichs 50-338.82/08/31.8210010221
- --8210010225 IE Insp Repts 50-339/82-18 & 50-339/82-18 on 820709-0805 No noncompliance noted Major areas inspected LERs, refueling & outage activities, surveillance & maint activities, operations & followup on significant events JOHNSON, D.F., BHYHLOCK, M.B., JULIAN, C. Division of Project & Resident Programs 82/08/31 illpp 15367 340 24% Fiche 50-338,82/08/31,8210010221
- 8210010300 Forwards IE Insp Napts 50-338/82-28 & 50-339/82-28 on 920816-19 No noncompliance noted DANCE, H C Division of Project & Resident Programs 82/09/03 LEASBURG, R H Virginia Electric & Power Co 2pp 15568 317 24X Fichs. 50-336, 82/09/03.8210010300
- --8210010314 IE Insp Repts 50-338/82-28 & 50-339/82-28 on 820816-19 No noncompliance noted Major areas inspected thermal sleeve removal reactor coolant loop stop valves, cap screw fractures & braken control rod guide tube support pins YORK-J W. SLAKE, J J Division of Engineering & Technical Programs 82/09/02 6pp 15568 319 24X Fiche 50-338.82/09/03, 8210010300
- 8210150187 Forwards IE Insp Repts 50-338/B2-30 & 50-339/82-30 on 820831-0903 No noncompliance noted DANCE.H C Division of Project & Resident Progrems 82/09/23 LEASBURG.R H Virginia Electric & Power Co 2pp 15707-262. 24X Fiche 50-338,82/09/23,8210150187
- --8210150194 IE Insp Repts 50-338/82-30 & 50-339/82-30 on 820831-0903 No nancompliance noted Major areas inspected generator step-up transformer failure on 82082 & licensee recommendations & inspector failoury items
 RUFF.A B , CONLON.T E Division of Engineering & Technical Programs 82/09/17 4pp 15707-264 24X Fichs 50-338.82/09/23, 8210150187
- 8210220454 Forwards IE Insp Repts 50-338/82-33 & 50-337/82-33 on 820918 No noncompliance noted DANCE. H C Division of Project & Resident Programs 82/10/04, LEASBURGOR H Virginia Electric & Power Co 2pp 15779-185, 24x Fiche-30-338, 82/10/04, 8210220454
- --9210220461 IE Insp Repts 50-338/82-33 & 50-339/82-33 on 820918 No noncompliance noted Major areas Inspected full-scale radiological exercise HUFFMAN.0 N . MARBTON.R R . JENKINB.0.R. Division of Engineering & Technical Programs 82/09/30 | 1pp | 13779 137. 24X Fiche 50-338,82/10/04.8210220454
- 8208190233 IE Info Notice 80~35, Suppl i. "Leaking & Dislodged I-125 Implant Seeds " Svc list encl
 COBB-L I Division of Fuel Facilities, Materials & Safeguerds
 82/10/06 Consolidated Edison Co of New York 66pp 15761 250,
 24% Fiche 50-000,82/10/06.8208190233
- 8208190238 IE Bulletin 82-03. "Stress Corrosion Cracking in Thick-Hall.Large-Diameter. Stainless Steel. Recirculation Sys Piping at BHR Plants " Svc list encl DEYUUNO,R C Director's Office. Office of Inspection and Enforcement 82/10/14 Consolidated Edison Co of New York #15pp 15810 125 24X Fiche. 80-000. 82/10/14, 8208190238.
- S Reportable occurrences, LERs & related correspondence
- 8210080067 Trip rept of 810709 site visit to view extent of Samage caused by feilure of B phase main transformer Transformers not designed to withstend severe electrical short circuits inside transformer CHIRAMAL, M Director's Office 81/07/14, MICHELSON, C Director's Office 3pp 15670.012, 24X Fiche 50-339,81/07/14,8210080067
- 821001000B Responds to FOIA request for 19 categories of documents re nuclear reactor events & safety problems.Forwards documents listed in App A FELTON, J M Division of Rules and Records. 82/06/28. UDELL, R A Critical Mass Energy Project. 15pp. 15727,005 24X Fiche. 50-000,82/06/28,8210010008
- --8010210037 Forwards 800305 memo re undercied cracking in reactor vessel nozzles.Review re safety aspects & compliance w/8ection IX of ABME ode concludes that problem should not be included on generic issues list.

 BAER, R L Bafety Program Evaluation Branch 80/07/17 KINTNER, L L Licensing Branch 2. ip. 15727 175 24X Fiche 50-000,82/06/28,8210010008

- 8210080015 Add1 response to FOIA request for 19 categories of info re nuclear reactor events & safety problems Forwards documents listed in App A Documents in App B completely withheld (ref FOIA Exemption 5).

 FELION, J M Division of Rules and Records 82/07/12 UDELL, R. A Critical Mass Energy Project 9pp. 15655 027 24X

 Fichs 50-000, 82/07/12, 8210980015
- --8210080197 NRC operations ctr usage chart re events at facilities * NRC - No Detailes Affiliation Given 82/07/12 ip 15668:221 24X Fiche 50-000:82/07/12:8210080015
- 8207230301 Forwards LER 82-027/03L-0. CARTHRIGHT: Winginia Electric & Power Co 82/07/13 D'REILLY, J P. Region 2. Office of Director ip 13998 329 24X Fiche 30-339, 82/07/13, 8207233301
- --B207230303 LER B2-027/03L-0 on 820620 & 23 sxial flux difference want less than -5% from target on two occasions Caused by insbility to establish stable axial flux difference target in new core CARTHRIGHT, W. Virginia Electric & Power Co. 82/07/13 Region 2, Office of Director. 3pp. 13998-330 24% Fichs 50-339, 82/07/13.8207230301
- 8210010233 Forwards LER 82-059/03L-0 CARTWRIGHT.W R Virginia Electric & Power Co 82/09/22 G'REILLY,T P. Repion 2, Office of Director 1p 15574 031 24X Fiche 50-339,82/09/22,8210010233
- --82i0010236 LER 62-059/03L-O on 820830, steam generator B steam flow channel IV, providing steam line break & loss of heat sink arotection, failed high Cause not determined Channel placed in tripped condition Problem cleared during troubleshooting CARTHRIGHT, W R Virginia Electric & Power Co. 82/09/22 Region 2, Office of Director 3pp 15574 032. 24X Fiche 50-339, 82/09/22, 8210010233
- 8210080192 Forwards LER 82-061/03L-0 CARTHRIOHT.WR Virginia Electric & Power Co 82/09/30 O'REILLY, J.P. Region 2, Office of Director ip 15640:172 24X Fiche: 50-339, 82/09/30, 8210080182
- --8210080185 LER 82-051/03L-0 on 820903, low head safety injection pump 2-81-P-iA containment sump suction valve MOV-2850A failed to open during partiolic surveillance test Caused by power cord wrapped around valve operator flexible extension.

 CARTHRIGHT, W.R. Virginia Electric & Power Co. 82/09/30 Region 2, 0ffice of Director 2pp 15640 173 24X Fiche 50-339, 82/09/30,8210080182
- 8210220415 Ferwards LER 82-062/03L-0 CARTHRICHT: W R. Virginia Electric & Power Co. 82/10/07 O'RELLLY, J P. Region 2. Office of Director. 1p, 15778-355. 24X Fiche: 50-339, 82/10/07, 8210220415.
- --B210220421 LER 82-062/03L-0.on 820910 & 13, firs door 854-9 found not providing definitive seal for control ruom pressure boundary. Caused by out-of-plumb door installation Door removed, stops adjusted & door replaced CARTHRIGHT, M. R. Virginia Electric & Power Co 82/10/07 Region 2, Office of Director. 2pp 15778:356 24X Fiche: 50-339, 82/10/07:8210220415
- 8210220441 Forwards LER 82-060/03L-0. CARTHRIGHT: W R. Virginia Electric & Power Co. 82/10/07. O'REILLY.J.P. Region 2. Office of Director. 1p. 15778:353. 24X Fiche:50-339,82/10/07.8210220441.
- --8210220450 LER B2-060/03L-0; on 820914, w/Unit 2 at 98% power, fire door 854-9 between emergency switchgear room & cable vault found blocked open w/o fire watch. Cause unknown Block removed & door operability verified.

 CARTHRIGHT, W.R. Virginia Electric & Power Co 82/10/07. Region 2.0 Office of Director. ip. 15778: 354, 24% Fiche: 50-339, 82/10/07, 8210220441.
- 8210260281 Forwards LER 82-063/03L-0. CARTHRIGHT, W.R. Virginia Electric & Fower Co 82/10/19. CREILLY, J.P. Region 2. Office of Director, 1p 15801;352 24X Fiche: 50-339, 62/10/19, 8210260281.
- --B210260287 LER B2-063/03L-0:on B20926, individual rod position indication for rod B-08 in control bank D deviated from group demand position by greater than 12 steps w/no rod motion. Caused by instrument drift. Instrument recalibr. CARTHRIGHT, W.R. Virginia Electric & Power Co. B2/10/19 Region 2, Office of Director 2pp 15801:353, 24% Fiche:50-339, 82/10/19,8210260281.

- 8210260346 Forwards LER 82-065/03L-0 CARTHRIOHT: W R Virginia Electric & Power Co 82/10/19 O'REILLY, J P Region 2, Office of Director ip. 15803 188 24X Fiche: 50-339, 82/10/19, 8210260346
- --8210260360 LER 82-065/03L-0. on 821007, control power for A casing cooling pump found de-emergized due to open circuit breaker Cause unidentified Circuit breaker closed CARTHRIGHT. H. R. Virginia Electric & Power Co. 82/10/19 Region 2, Office of Director 2pp 15803:189 24X Fiche 50-339, 82/10/19, 8210260346
- DOCKET 50-341 ENRICO FERMI ATOMIC POWER PLANT, UNIT 2

 A Application/construction stage documents & correspondence
- 8210040377 Responds to 820715 ltr.Requests application be amended to include high drywall temp & design of level indication sys w/respect to leak or break of single instrument tap or sensing line Addl info needed to verify acceptability YOUNOBLOOD.B J Licensing Branch 1. 82/09/21. TAUBER, H Detroit Edison Co 4pp 15597.203. 24X Fiche 50-341.82/09/21.8210040377.
- 8210010456 Forwards "Inservice Testing Program" for pumps & valves for 120-month insp period beginning w/fuel load par 10CFR50 55a.Rept supersedes Revision O submitted w/G10803 itr TAUBER, H Detroit Edison Co 82/09/22 KINTNER, L Division of Licensing ip. 15570 011 24X Fiche, 50-341, 82/09/22, 8210010456
- --8210010460 "Inservice Testing Program "
 CLAUSG. J. M., MARTIN. J. B. NUTECH (Nuclear Technology, Inc.)
 DET-16-0201 R01 82/07/0B 161sp. 15570 012 24X
 Fiche 50-341.82/09/22:8210010456
- 8210120026 Summary of 820715 meeting w/util re facility QA concerning recent design & const deficiencies. Applicant considering another independent design review re core spray sys XINTNER, L. L. Licensing Branch 1 82/09/22. Licensing Branch 1 7pp 13689:189 24X Fiche 50-341.82/09/22.8210120026
- 8210120627 Forwards safety evaluation of plant-unique analysis rept for Mark I containment long-term program, technical evaluation rept of program audit & BNL technical evaluation of analysis rept LAINAB, G. Assistant Director for Operating Reactors. 82/09/23 NOVAK, T. M. Assistant Director for Licensing. 1p 15684.241 24X Fichs: 50-341, 82/09/23, 8210120627
- --8210120636 Bafety evaluation accepting plant-unique analysis rept for nment long-term program Possible im in single vent douncomer lateral load tified.

 >--1ed Affiliation Given 82/09/23 12pp.
 --he 50-341,82/09/23,8210120627.

t Long-Term Program - Structural ent, " technical

[nstitute/Franklin Research 82/08/25 NRC - No 584:254. 24X

- --8210120642 "Technical Evaluation of Fermi-2 Plant-Unique Analysis Rept " # Brookhaven National Laboratory NRC-20-82-213. BNL-04261. 82/09/30. NRC - No Detailed Affiliation Given 40pp 13684:300 24K Fiche:50-341,82/09/23.8210120627
- B210010289 Forwards Amend 44 to application for DL.consisting of Amend 44 to FBAR.
 LANDORAF, L. G. LeBoeuf, Lamb, Leiby & Hackae LANDORAF, L. G. Detroit Edison Co. 82/09/30 PENTON, H. Office of Nuclear Reactor Regulation, Director. 1p. 15573:187, 24X Fiche: 50-341, 82/09/30, 8210010289
- --B210010295 Amend 44 to application for CL, HEIDELC M. Detroit Edison Co B2/09/29, ip. 15573:188. 24X Fiche: 50-041, 82/09/30, 8210010289.
- 8210080046 Confirms points agreed upon at NRC Caseload Forecast Panel B20824-26 site visit to assess plant const schedule, TAUBER:H. Detroit Edison Co. 82/10/01, DENTON.H.R. Office of Nuclear Reactor Regulation, Director. 2pp. 15643:279. 24X Fiche: 50-341, 82/10/01. 8210080046.

- 9210130158 Forwards Cartificate of Svc certifying svc of Amend 44 to amended & substituted application for licenses MATERG.B R Detroit Edison Co 92/10/06 Diffice of Nuclear Reactor Regulation, Director 3pp 15673 074 24X Fich: 50-341.82/10/06.8210130158
- 8210180188 Responds to NRC request for clarification of util B20715
 Itr re errors in BMR water level indication, Existing
 emergency operating procedures adequate for successful
 termination of bounding event resulting in ref leg flashing
 TAUBER.H Detroit Edison Co B2/10/11 KINTNER.L Division of
 Licensing. 3pp 15719 120 24X Fiche 50-341.82/10/11.8210180188
- 8210220414 Submits schedule for resolution of open items re Mark 1 containment. If resolution not apparent within 3 months of fuel load, will will work w/NRC to provide adequate justification for interim operation TAUBER. H. Detroit Edison Co. 82/10/15 KINTNER. L. Division of Licensing. 3pp 15779,148 24X Fichs 50-341,82/10/15,8210220414
- 8210280222 Forwards Class II fee for application to amend CFPR-87 MATERS, B.R. Detroit Edison Co. 82/10/22 DIQQB, R.M. Licenss Fes Management Branch ip 15837 090 24% Fiche 50-341,82/10/22, 8210280222.
- E NRC Bafety Evaluation Report (SER), supple & correspondence
- 8210150639 Forwards status of addl Mark I containment issues for supplemental BER input; identified since Mark I containment long-term program LAINAS: 0 C Assistant Director for Operating Reactors. 62/10/06 NOVAK, T H Assistant Director for Licensing ip 15715 290 24: Fiche 30-34: 82/10/06.82:0150639
- F Becurity, medical, emergency & fire protection plans
- 8210250195 Forwards summary evaluation of Mar 1982 evacuation time estimates. Several deficiencies noted Enumeration of special facilities missing & should be provided URBANIK.T. Texas A & M Univ 82/09/23 SIMONDS.J Division of Emergency Preparedness ip 15788 304. 24% Fiche 50-341, 82/09/23 8210250195
- 8210130284 Forwards maps documenting location of NRC monitoring stations consisting of 3B offsite environ TLDs deployed around facility W/o enci.

 KREUB:R.E. Detroit Edison Co. 82/09/24. OEBTMANN:M J Region 3. Office of Director 1p. 15678 263 24X Fichs. 50-342,82/09/24, 8210130284.
- O Adjudicatory correspondence
- 8210040082 Forwards NRC response to Citizens for Energy & Employment 820904 answer. Name inadvertently omitted from Certificate of 8vc W/o encl.

 MODDHEAD, C.P. Hearing Branch 1. 82/09/30 MINOCK, J. Minock, J. MINOCK, J. Citizens for Energy & Employment. ip 15581: 266 241 Fiche: 50-341, 82/09/30, 8210040082
- K Utility Final Bafety Analysis Report (FBAR) & amends
- 8210010287 Forwards Amend 44 to application for OL, consisting of Aeend 44 to FBAR.

 LANDGRAF, L. C. LeBosuf, Lamb, Leiby & MacRae. LANDGRAF, L. C. Detrois Edison Co., 82/09/30. DENYON, H. R. Office of Nuclear Reactor Regulation. Director. 1p. 15573, 187. 24X Ficher 50-341, 82/09/30. 8210010289
- --8210010295 Amend 44 to application for CL HEIDEL,C. M. Detroit Edison Co 82/09/20 ip. 15573, 189 241 Fiche. 50-341, 82/09/30, 8210010289.
- --8210010297 Amend 44 to FSAR * Detroit Edison Co. 82/09/30. 80pp 15573:189 24X Fiche:50-341.82/09/30, 8210010289.

DOCKETED ITEMS

Advisory Committee on Reactor Bafeguards reports & correspondence

1027039B Comments on analyses evaluating capability of facility stological shield to withstand asymmetric loadings resulting from double ended pine broak at reactor vessel notice safe 1044.95 Prophyloga & 1204 requests 10045.7 Franklin Institute/Franklin Research Center ZUDANS, ZACES - Advisory Committee on Reactor Safeguards 80/05/30 ALDERNAL ACRE - Advisory Committee on Reactor Safeguards 5pp 18632 340 24X Fiche 50-341,80/05/30,8210270398

inspection reports. IE Bulletins & correspondence

10010456 Forwards "Inservice Testing Program" for pumps & valves for 120-month insp period beginning wifuel load per 100FR50 55a Rept supersedes Revision O submitted w/810803

IST RAUGER.H Detroit Edison Co. 82/09/22 KINTNER.L L Division of Licensing Ip 15570 011 24X Fiche.50-341.82/09/22.8210010456

8210010460 "Inmervice Testing Program " CLAUBS,J H , MARTIN,J B NUTCCH (Nuclear Technology, Inc.) DET-16-0201 RO1 B2/07/08, 161pp 15570-012 24X Fich: 50-341,82/09/22:8210010456

10130368 Forwards IE Insp Rept 50-341/82-11 on 620721-23 & 27-30 No 10130300 reveres it insp Hept 50-341/82-11 on 820721-23 & 27-30 No noncompliance noted of Engineering & Technical Programs 82/09/27, WELLS D Detroit Edison Co 2pp 15682:100. 24X Fichs 50-341/82/09/27, 8210130368

0210130374 IE Insp Rept 50-341/82-11 on 820721-23 & 27-30 No noncompliance noted Major areas inspected 10CFR50 55e repts, electrical hanger reimsp. OA records, relay coordination activities & deviation disposition request MAIULK R. WILLIAMS.C C Region 3, Office of Director 82/09/10 11pp 15682 102 24X Fiche 50-341,82/09/27,8210130368

Hollood Bubmitt list of tubes plugged in each steam generator following inservice inest (ROUSE,R P Toledo Editon Co 82/10/04 KEPPLER, J. O Region 3, Office of Director ip 15742 158 24X Fiche 50-341,82/10/04, 8210190303

00190233 IE Info Notice 80-35, Suppl 1. "Leaking & Dislodged I-125 leplant Seeds " Svc list encl (085). I. Division of Fuel Facilities, Materials & Safeguards. 82/10/06 Consolidated Edison Co of New York. 66pp. 15761: 250. 24X Fichs 50-900-82/10/06, 8208190233

200130184 Clarifies NRC position concerning procedures for admitting MRC personnel to facility Lists of authorized personnel

KEPPLER, J.O. Region 3. Office of Director. 82/10/06 WELLS, D. A. Detroit Edizon Co. 4pp. 15674:137 24X Fishe: 50-341,82/10/06. 9210130189

210250072 Forwards IE Insp Stept 50-341/82-12 on 820701-0831 & notice of violation.

BressARD.R L Division of Project & Resident Programs 82/10/07.

BressARD.R Detroit Edison Co 2pp 15789 341 24X

Fichs. 50-341, 82/10/07, 8210250072

9210250075 Notice of violation from insp on 820701-0831 SPESBARD.R L. Division of Project & Resident Programs. 82/10/07. 2pp 15787-343 24X Fiche 50-341.82/10/07.8210250072

-8210230080 IE Insp Hept 50-941/82-12 on 820701-0831 Noncompliance noted failure to accomplish activities per GA procedure to provide appropriate procedure & to perform resudit to verify corrective action implementation.

LITILE.B H , XONKLIN-J E Division of Project & Resident Programs 82/10/07 7sp. 15789.345. 24X Fiche: 50-341,82/10/07,8210250072

210150322 Forwards responses to IE Bulletin 79-15, "Long-Term Operability of Deep Draft Pumps," Responses will be incorporated in FBAR amend Related procedures also encl. TAURER; II Detroit Edison Co 82/10/11 KINNER, L. L. Office of Nuclear Reactor Regulation, Director 8pp 15702'001 24X Nuclear Reactor Regulation, Director Fiche 50-341, 82/10/11,8210150322.

-8210150326 "Qoulds Pumps, Inc Type I Menual, Emergency Equipment Byo Water Pumps, "
* Ooulds Pumps, Inc 77/07/14. 53pp 15702.009 24X Fiche 80-341, 82/10/11, 8210150322

-8210150330 "Coulds Pumps, Inc Type I Manual, Diesel Generator Svc Water

* Qoulds Pumps. Inc 77/11/22 91pp. 15702-062. 24X Fiche: 50-341, 82/10/11, 82/0150322.

~-8210150335 "Instruction Hanual, RHR 8vc Water Pumps, Enrico Fermi Atomic Power Plant Unit 2 " * Youlds Pumps, Inc 75/11/19 43pp 15702 154 24X Fiche 50-341.82/10/11,8210150322

~-8210150343 "Seigmic-Stress Analysis of ASME Section III Class 3 Pumps "
McDonald Engineering Analysis Co ME-229 75/09/03 54pp
15702, 209. 24X Fiche 50-341, 82/10/11, 8210150322

--8210150346 "Seismic-Stress Analysis ABME Section III Class 3 Pumps "
McDonald Engineering Analysis Co ME-230 75/09/03 56pp
15702-264 24X Fichs 50-341, 82/10/11, 8210150322

---8210150352 "Beismic-Stress Analysis Rept RHR Syc Water Pumps "

* McDonald Engineering Analysis Co. ME-146 74/01/28 40pp
15702 320 24X Fiche 50-341,82/10/11,8210150322

8210190696 Clarifies check valve info re inservice insp of pressure isolation valves, per 810603 itr Design features provide hetter protection than check valve position monitoring for sys Info will be included in future F88R amend TAUBER.H Detroit Edison Co 82/10/11 KINNER,L L Division of Licensing 2pp 15736 198 24X Fiche 50-341.82/10/11.8210190696

8208190238 IE Bulletin 82-03, "Stress Corrosion Cracking in Thick-Wall, Large-Diameter, Stainless Steel, Recirculation Sys Piping at BWR Plants " Svc list encl DEYQUNO, R C Director's Office, Office of Inspection and Enforcement, 82/10/14 Consolidated Edison Co of New York 115pp. 15810:125 24X Fiche 50-000, 82/10/14, 8208190238

8210260372 Ack receipt of 820924 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 30-341/82-08 MORELIUS, C E. Division of Project & Resident Programs 82/10/18 HELLS, D. A. Detroit Edison Co ip 15804-233 24X Ficha 50-341, 82/10/18, 8210260372

--B2102603B2 Responds to NRC 820B10 ltr re violations noted in IE Imsp Rept 50-341/82-08 Corrective actions snubber reduction grogram accepted & implemented on 820609. All documentation forwarded to NRC upon completion HELLB.D A Detroit Edison Co 82/09/24. BPESBARD.R L Division of Project & Resident Programs 5pp 15804-234, 24x Fiche 50-341,82/10/18,8210260372

8 Reportable occurrences, LERs & related correspondence

B210040127 Interim deficiency rept re defective 1-inch pipe couplings & caps mfg by Capital Mfg Co Initially reported on 620810 Installed couplings will be given visual insp & liquid penetrant exam Next rept expected by 630107 WELLS,D.A Detroit Edison Co. 82/09/09 KEPPLER.J C. Region 3. Office of Director. 2pp 15581-210. 24X Fichs 50-341,82/09/09,8210040127.

8210040084 Interim deficiency rept re load-carrying capability of certain drywell structural steel Intially reported on 820824, Fix involving reinforcing of affected members considered. Interim or final rept expected by 820120 WELLB. D. A Detroit Edison Co. 82/09/22 KEPPLER. J G. Region 3. Office of Director. ip. 15581 265. 24X Fiche: 50-341, 82/09/22, 8210040084.

8210190332 Final deficiency rept re cracking of 3/4-inch carbon steel pipe. Initially reported on 820430. Manufacturer installed eddy current tester to aid in GC of pipes. Faulty sections of pipe replaced WELLB, D. Detroit Edison Co. 82/09/24. KEPPLER, J. Q. Region 3, Office of Director. 3pp. 15742:088. 24X Ficher 50-341, 82/09/24, 8210190332

B210190657 Interim deficiency rept re defective pipe support strut swivel bearings. Initially reported on B20514.Add1 insprequirements for field inspectors will be developed per IE Circular 81-05 Next rept will be submitted by 820204. HELLB, D. A. Detroit Edison Co. B2/10/08 KEPPLER, J. Q. Region 3, Office of Director. 2pp 15737 147. 24X Fiche 50-341,82/10/08,8210190657.

8210250191 Final deficiency rept re stainless steel piping 8A 312TP316 & 8A 312TP316HF installed in lieu of required 8A 312TP316L. Initially reported on 820317 Deviation disposition requests written No instrument sample lines affected. MELLS, D. A. Detroit Edison Co. 82/10/12 KEPPLER, J. O. Region 3, Office of Director, 2pp. 15788, 29B. 24X Fiche, 50-341, 82/10/12, 8210250191.

- DOCKET 50-344 TROJAN NUCLEAR PLANT
- F Security, medical, emergency & fire protection plans
- 6210070012 Requests concurrence w/plan to issue license amend incorporating encl license condition re implementation of UB/IAEA sefeguards agreement Notification of info desired to be withheld requested within 30 days Encls withheld CLARK, R A Operating Reactors Branch 3 82/09/24 WITHERS, B D Portland General Electric Co 3pp 15646 223 24X Fiche 50-344, 82/09/24, 8210070012
- B210190020 Releases public version of revision to radiological smargency response glan implementing procedure FELTON.J M Division of Rules and Records. B2/10/01 Document Management Branch 1p 15761:001 24% Fiche-50-344.82/10/01.
- --8210190024 Forwards public version of Revision 3 to Radiological Emergency Response Plan Implementing Procedure EP-7, "Operation of Technical Support Ctr " Receipt form encl. PUZEY, A M Portland General Electric Co 82/09/22 CLARK, R A Office of Nuclear Reactor Regulation, Director ip 15761 002 24X Fiche 50-344,82/10/01,8210190020
- --8210190026 Public version of Revision 3 to Radiological Emergency Response Plan Implementing Procedure EP-7, "Operation of Technical Support Ctr" YWN07,C P Portland General Electric Co 82/09/20. 28pp 15761 003 24X Fiche 50-344,82/10/01,8210190020
- 8210280210 Forwards request for addl info re changes to physical security plan & safeguards contingency plan in response to 820719 it Encl withheld (ref 100FR73 21).

 CLARK.R A Operating Reactors Branch 3 82/10/26 WITHERS, 8 D Portland General Electric Co 1p 15837 106 24X Fichs 50-344, 82/10/26, 8210280210

P Operating license stage documents & correspondence

- 8210010053 Forwards systematic assessment of licensee performance data package to be used in preparing performance analyses Analyses should be prepared following format of encl NRC App 0516.Part VI.Section IV Analyses due 821008 STERNBERO, D H Division of Resident, Reactor Proyect & Engineering Programs 82/09/24, JOHNSON, P H. MALHROB, H H. CILLIS, H. Region 5, Office of Director 18pp 15565 119 24X Fiche 50-344.82/09/24, 8210010053
- B210040163 Advises that containment hydrogen monitors installed & calibr for hydrogen concentrations betwen 0 & 10% per TMI Action Item II F.1. Main steam line monitors installed, however, calibr delayed until B21101 dus to repairs.

 WITHERS.B D Portland General Electric Co B2/09/28, EISENHUT.D 0 Division of Liceneing 2pp 15582.032 24% Fiche 50-344.82/09/28, B210040163
- 8210150354 Bummary of B20928-30 mseting & sits visit w/util & Bechtel re masonry wall design Addl info requested re in-plane response effects on out-of-plane responses & documentation of verification of programs TRANMELL C M Operating Reactors Branch 3 82/10/05 Operating Reactors Branch 3. 5pp. 15715.353 24X Fiche.50-344,82/10/05,021018-050.

G. Inspection reports. IE Bulletins & correspondence

- 8210070007 Responds to FOIA request for eight categories of records resteam generators & steam turbines.App A documents provided in R Udell FOIA Request 81-313. Forwards documents listed in App 8.

 FELTON.J. M Division of Rules and Records. 82/09/10. LONG, D. J. Winthrop. 6timson, Putnam & Roberts 9pp 15645:063. 24X Fichs. 50-000, 82/08/10. 8210070007.
- --B210070139 Forwards tabulated data on steam generator insp & maint at facilities. Data should be provided to licenses.

 IPPOLITO.T. Operating Reactors Assessment Branch. 82/04/01.

 VARQA: 8 Operating Reactors Branch 1 5pp 15645:131. 24X

 Fiche: 50-000. 82/08/10. 8210070007
- 8210130597 Ack receipt of 820908 itr forwarding payment of civil penalty imposed by NRC 820812 order AXELRABJ. A Director's Office. Office of Inspection and Enforcement. 82/09/17. WITHERS, B.D. Portland General Electric Co. 2pp 15692:343 24X Fiche.50-344.82/09/17.8210130597.

- 8210010053 Forwards systematic assessment of licensee performance data package to be used in preparing performance analyses Analyses should be prepared following format of encl NRC App 0516, Part VI. Section IV Analyses due 821008 STERNBERO, D M Division of Resident, Reactor Project & Engineering Programs 82/09/24 JOHNSON, P H . MALHROB, M H . CILLIG. M Region 5, Office of Director 18pp 15565 117 24X Fiche 50-344,82/09/24,82/0010053
- 8210190549 Forwards IE Insp Rept 50-344/82-21 on 820712 No noncompliance noted STERNIERG, D.M. Division of Resident, Reactor Project & Engineering Programs 82/10/01 WITHERS, B.D. Portland General Electric Co 2pp 15735 001 24% Fichs 50-344, 82/10/01, 8210190549
- --8210190556 IE Insp Rept 50-344/82-21 on 820712 No noncompliance noted Major areas inspected program for welding pressurizer surge line ECKHARDT.J H., DDDDS.R T Division of Resident, Reactor Project & Engineering Programs 82/10/01 3pp 15735 003 24X Fiche 50-244,82/10/01.8210190549
- 8210080249 Ack receipt of 820923 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-344/82-24 STERNBERG, D M Division of Resident, Reactor Project & Engineering Programs 82/10/05 WITHERS, B D Portland General Electric Co ip 15638 093 24X Fiche 50-344.82/10/05.8210080249
- --B2100B0253 Responds to NRC 820903 ltr re violations noted in IE lnsp Rept 50-044/82-24 Corrective actions maint procedures revised to reflect change from motor to air operators on four auxiliary feedwater pump steam supply valves WITHERS.B D Portland General Electric Go 82/09/23 ENGELKEN.R H Region 5. Office of Director 4pp 15539 094 241 Fichs 50-344.82/10/05.82100B0249
- 8208190233 IE Info Notice 80-35, Supp) 1: "Leaking & Dislodged I-125 Implant Seeds " Svc list encl COBB.L I Division of Fuel Facilities, Materials & Safeguards. 82/10/06 Consolidated Edison Co of New York 64pp 13761: 250 24X Fich: 50-000, 82/10/06, 8208190233
- 821019073; Forwards IE Insp Rept 50-344/82-26 on 820809-9903 & notice of violation CREMS, J. Division of Resident, Reactor Project & Engineering Programs 82/10/06 WITHERS, B.D. Portland General Electric Co 2pp 15737 065 24X Fiche 50-344, 82/10/06, 8210190731
- ---8210190733 Notice of violation from insp on 820809-0903 DDDDB,R.T Division of Resident, Reactor Project & Engineering Programs B2/10/06 2pp 15737 067 24X Fiche 50-344,62/10/06, 8210190731.
- --B210190743 IE Insp Rept 50-344/82-26 on B20809-0903 Noncompliance noted safety injection sys actuation logic inoperable from B20818-20
 MALHROS,M.H., DODDS,R.T., Division of Resident, Reactor Project & Engineering Programs 82/09/16 7pp 15737-069 24X Fiche 50-344,82/10/06,82/10190731
- B210270413 Forwards safety evaluation of licensee 800430 & 920317 responses to IE Bulletin 80-04. "Analysis of PMR Main Steamline Break M/Continued Feedwater Action " Licensee responses acceptable CLARK.R A Operating Reactors Branch 3 82/10/07 UITHERS & D Portland General Electric Co Rpp. 15863 241 24X Fiche. 50-344, 82/10/07, 8210270413
- --B210290417 Bafety evaluation accepting licenses 800430 & B20317 enalyses of mein steamline break w/continued feedwater action No further action re IE Bulletin 80-04 required.

 * Office of Nuclear Reactor Regulation, Director 82/10/07 7p; 15863-243. 24X Fiche: 50-344, B2/10/07. 8210290413
- 8208190238 IE Bulletin 82-03, "Btress Corrosion Cracking in Thick-Wall, Large-Diameter, Stainless Steel, Recirculation Sys Piping at BWR Plants." Svc list encl.
 DEYGUNG, R. C. Director's Office, Office of Inspection and Enforcement, 82/10/14 Consolidated Edison Co of New York
 115pp 15810:125, 24X Fiche 50-000, 82/10/14, 8208190238
- B. Reportable occurrences, LERs & related correspondence
- B210250084 Forwards LER 82-018/03L-0 Detailed event analysis enci. YUNDT.C P., STEELE,R.L. Portland General Electric Co. B2/10/11. ENGELKEN,R H. Region 5. Office of Director 3pp. 15787:077 241 Fiche. 50-344, 82/10/11, 8210250084

- -- \$210250093 LER 82-018/03L-0 on 820918, during normal operation, steam pressure transmitter PT-524 on steam generator 8 failed high causing associated protection sys bistable to trip & steam flow instrument FI-522 to fail high Cause unknown 8AtR-0 0 Portland General Electric Co 82/10/11 Region 5, Office of Director 1p 15787 080 24X Fiche 50-344,82/10/11, 8210250084
- Q10250164 Forwards LER 82-017/03L-0 Detailed event analysis encl YUNDY.C P. BTEELE.R L. Portland General Electric Co. 82/10/11 ENGELXEN.R H. Region 5. Office of Director 3pp. 15787-330. 24X Fiche 50-344, 82/10/11.8210250164
- -B210250175 LER B2-017/03L-0 on B20916, boron concentration in north borst acid storage tank decreased below Tech Bpec level Caused by dilution due to two leaking valves South tank Level raised above STS limit Valves repaired BAIR.0 0 Portland General Electric Co B2/10/11 Region 5, Office of Director ip 15787 333 24% Fiche 50-344,82/10/11.
- Security, addical, emergency & fire protection plans
- 3210070003 Releases public version of revised administrative memo & revised emergency plan supporting procedures
 FELTON.JH Division of Rules and Records 82/09/17 Document
 Management Branch ip 15646 222 24X Fiche 50-346, 82/09/17.
 8210070003
- --8210070005 Forwards public version of Revision 17 to Administrativa Keen 42-17. "Radiation Monitoring Teams" & Revision 190 to whatgency plan supporting procedures index Receipt form encl Toledo Edison Co 62/09/08 NRC - No Detailed Affiliation Given 1p 15646 218 24% Fiche 50-346,82/09/17.82100700003
- --8210070006 Public version of Revision 17 to Administrative Memo 42-17.

 "Radiation Monitoring Teams" & Revision 150 to emergency
 plan supporting procedures index
 HURRAY.T D Taledo Edison Co 82/09/30 2pp 15646,219 24X
 Fichs 50-346,82/09/17,8210070003
- B210050205 Requests add1 info re intended use of drawings & reactor safeguards program prior to submittal of info requested in B20024 ltr Request appears to duplicate Sandia Nat1 Labs program CRQUSE.R P Toledo Edison Co 82/09/28 STOLZ, J F Operating Reactors Branch 4 ip. 15609 052 24X Fiche 50-346.82/09/28, B2100502035.
- 8210250286 Forwards IE Safety Evaluation Rept 50-346/82~26 on 820901-30 No noncompilance noted HINO. J A Division of Emergency Preparedness & Operational Support 82/10/07 CROUSE.R P Toledo Edison Co 2pp 15791.106 24X Fiche 50-346.82/10/07.8210250286
- --8210250297 IE Safety Evaluation Rept 50-346/82-26 on 820901-30 No moncompliance noted Major areas inspected site emergency plan PLOSKI, T J , AXELSON, W L , PAPERIELLO, C J Division of Emergency Preparedness & Operational Support 62/10/06 37pp 15791 108 24X Fiche 50-346.82/10/07.8210250286
- B210190623 Forwards revision to Industrial Security Plan AD 1808 Revision withheld (ref 100FR2 790) CRQUEE,R P Toledo Edison Co 82/10/12 STOLZ,J F Operating Reactors Branch 4 ip 15739,360 24X Fiche 50-346,82/10/12,8210190623
- P Operating license stage documents & correspondence
- 8210210348 Confirms 820916 telephone authorization of amend to License NPF-3 by adding one-time note to Tech Spec Table 4 3-11 resteam & feedwater rupture control sys instrumentation surveillance requirements

 LAINAB.0 C Assistant Director for Operating Reactors, 82/09/20, CROUSE.R.P. Toledo Edison Co. 2pp 15784:274 24X

 Fichs 50-346.82/09/20.8210210548
- --8210210550 Amended Tech Spec Table 4 3-11 re steam & feedwater rupture control sys instrumentation surveillance requirements.

 4 Assistant Director for Operating Reactors 82/09/20 1p. 13784 278 24X Fiche 50-246, 82/09/20, 8210210548
- --B210210553 Safety evaluation supporting change to Tech Spec Table 4 3-11 re steem & feedwater rupture control sys instrumentation surveillance requirements LAINAS, 9 C Assistant Director for Operating Reactors. 82/09/16, 1p. 15784: 279 24X Fiche: 50-346, 82/09/20, 9210210548

- --8210210556 Application for smargency change to Tech Spec Table 4, 3-11, extending steam line pressure low switch surveillance period by 96-h. until midnight 820916 Safety evaluation encl PETERS.R F Toledo Edison Co. 82/09/17 DEAGAZIO, A Office of Nuclear Reactor Regulation. Director 2pp 15784 280 24X Fiche 50-346,82/09/20.8210210548
- --8210210559 Proposed change to Tech Spec Table 4 3-11.extending steam line pressure - low switch surveillance period by 96-h, until midnight 620916 * Toledo Edison Co 82/09/17 ip 15784 282 24X Fiche 50-346,82/09/20.8210210548
- 8210120001 Requests add1 info re secondary water chemistry monitoring & control by 821108 Info pertains to 771003 proposed amend to delete existing Tech Spec on secondary water chemistry & incorporate model license condition
 870LI.J F Operating Reactors Branch 4 82/09/22 CROUSE.R P Toledo Edison Co 4pp 15689 183 24X Fiche.50-346.82/09/22, 82/0120001
- 8210040049 Informs that Class IV fee should be submitted for final review of 820715.30,0806 & 16 submittals DIO08.R K License Fee Management Branch. 82/09/23 CROUSE,R P Yoledo Edison Co. ip 15577 292 24X Ficher 50-346,82/09/23,
- 8210180025 Requests review of enci Franklin Research Ctr draft technical evaluation rept prepared on util 820101 responses to request for info re NUREO-0612, "Control of Heavy Loads at Nuclear Power Plants"

 DE AQAZIO, A W Operating Reactors Branch 4 82/09/23 CROUSE, R P Toledo Edison Co. 2pp 15717 278 24X Fiche 50-346, 82/09/23, 8210180025
- --8210180026 "Control of Heavy Loads (C-10), Toledo Edison Co.Davis-Bease Nuclear Power Station, Unit 1, " draft technical evaluation rept BOMBEROER, C Franklin Institute/Franklin Research Center, NRC-03-79-18 TER-05237-530 62/08/27 CLEMENSON, F NRC No Detailed Affiliation Oiven, 38pp 15717 280 24X Fiche 50-346, 82/09/23-8210180025
- 8210050304 Responds to 820727 ltr re NUREO-0737. Item II X 2 10. "Anticipatory Reactor Trip Bys (ARTS) " Adequate features available to alert operator to remove bypass when automatic bypass removal not required CROUSE, R F Toledo Edison Co 82/09/27 STOLZ, J F Operating Reactors Branch 4 2pp. 15610 266 24X Fiche 30-344, 82/09/29, 8210050304
- 8210050333 Advises that schedule for responding to NUREO~0737. Item II B. 3, "Post-Accident Sampling Sys." will be provided by Mar 1783, in response to 820721 request CROUSE.R.P. Toledo Edison Co. 82/07/27 BTOLZ, J.F. Licensing Branch 4. ip. 15610 094 24X Fiche 50-346.82/09/29.8210050333
- 8210050310 Forwards application to amend License NPF-3, revising Tech Spec Table 4 3-11 re steem & feedwater rupture control sys instrumentation surveitlance requirements CROUSE, R. P. Toledo Edison Co. 82/09/30. BTGLZ, J. F. Operating Reactors Branch 4 ip 15601:352 24X Fiche 50-346,82/09/30, 8210030310
- --8210050313 Application to amend License NPF-3, revising Tech Spec Table 4, 3-11 resteam & feedwater rupture control sys instrumentation surveillance requirements. CROUSE, R P Toledo Edison Co. 82/09/30 ip. 15601,353, 24X Fiche: 50-346,82/09/30.8210050310
- --B210050318 Proposed revision to Tech Bpec Table 4 3-11 re steam & feedwater rupture control sys instrumentation surveillance requirements. Bafety evaluation encl + Yoledo Edison Co 82/09/30 3pp 15601 354 24X Fiche 50-346,82/09/30,8210050310
- 8210150519 Discusses NRR actions taken under Task Interface Agreement 82-20 for steam generator auxiliary feedwater header damage, Licensee authorized to resume power operation at Oconse 3.
 EISENHUT, D. Division of Licensing 82/10/06 DLBHINSKI, J Division of Engineering & Technical Programs. 1p 15717.261 24x Fiche: 50-000, 82/10/06, 8210150519.
- 8210180135 Forwards fee for review of once through steam generator repairs & auxiliary feedwater sys mods.
 CROUSER.R. P Toledo Edison Co. 82/10/08 MILLER, W.O. License Feedwater Systems & Proc. 15719 338. 24X Fiche 50-346, 92/10/08, 8210180135.

- B210210225 Responds to 810629 ltr stating that no license amend application needed to incorporate model Teck Bjec for snubber surveillance Response unacceptable since ANSI/ABME GM-4 not completed Amend requested STOLZ-JF Operating Reactors Branch 4 B2/10/13 CROUSE, R P Toledo Edison Co 2pp 15774 338. 24X Fiche 50-346.82/10/13.8210210225
- 8210270319 Advises that proposed Tech Spec changes requested by 800410 ltr not received Model Tech Specs re definition of term "operable-operability" forwarded Proposed Tech Spec changes requested by 82110B STOLL.7 Poperating Reactors Branch 4 82/10/13 CROUSE.R P Toledo Edison Co 2pp 15836 352 24X Fiche 50-346.82/10/13.
- --8210270325 Model Tech Specs re definition of term "operable-operability" & limiting conditons for operations & associated bases Time to place plant in hot standby relaxed to 6-h & cold shutdown within subsequent 30-h & Operating Reactors Branch & 82/10/13 3pp 15836 354 24X Fichs 30-346,82/10/13.8210270319
- B210270372 Forwards Amend 46 to License NPF-3, safety evaluation a notice of issuance & availability Amend permits one-time extension to surveillance period for steam line pressure-low instrument
 STOLZIJF Operating Reactors Branch 4 B2/10/13 GROUSE, R P Toledo Edison Co. 2pp. 15834 250 24X Fiche 50-346, B2/10/13, 0210270372
- --8210270382 Amend 46 to License NPF-3, permitting one-time extension to surveillance period for steam line pressure-law instrument STOLZ, J.F. Operating Reactors Branch 4 B2/10/13 4pp 15834-253 24X Fiche 50-346-82/10/13
- --8210270386 Safety evaluation supporting Amend 46 to License NPF-3.

 * Office of Nuclear Reactor Regulation, Director 82/10/13 6pp
 15834 258 24X Fiche 50-346.82/10/13.8210270372
- --82102703B7 Notice of issuance & availability of Amend 46 to License NFF-3 STOLZ.JF Operating Reactors Branch 4 82/10/13 2pp 15834 261 24X Fiche 50-346,82/10/13.8210270372
- 8210210438 Forwards, under separate cover, application for amend to License NPF-3 Amend increases setpoint margin for power-operated relief valves: revises bases on auxiliary feedwater sys & alters trip setpoints to account for instrument arror CROUSE: RP Toledo Edison Co 82/10/14 8TOL2. J. F Operating Reactors Branch 4 18pp 15763 047 24% Fithe 50-346,82/10/14,82/0210488
- 8210260283 Application to amend License NPF-3, revising Tech Specs to reflect changes to setpoints for pressurizer electromatic relief & code safety valves, auxiliary feedwater sys & trip setpoints for borated water storage tank level MURRAY, T, D Toledo Edison Co 82/10/14 STOLZ, J F Operating Reactors Branch 4 18pp 15803, 124 24X Fiche 50-346, 82/20/14, 8210260283
- 8210220013 Responds to 820713 ltr requesting implementation schedule for mods to ECCB evaluation models Mods will be undertaken as extension of NUREO-0737. Item II K 3 31. Schedule will be provided 60 days after NRC approval of Item II K 3,30. CROUSE: R. P. Toledo Edison Co 82/10/19 NOVAK.T M Assistant Director for Operating Reactors Ip 15778 210 24X Fiche: 50-346, 82/10/19, 8210220013
- 8210290378 Forwards Amend 48 to License NPF-3, safety evaluation & notice of issuance & availability Amend changes calculational method to determine max allowable high flux trip setpoint when one or more safety valves inogerable DE AOAZIO, A W Operating Reactors Branch 4, B2/10/20, CROUSE, R. P. Toledo Edison Co. 2pp 15865:249 24% Fiche: 50-346,82/10/20, B210290378.
- --8210270382 Amend 48 to License NPF-3, reflecting change in calculational method for determining max allowable high flux trip tetpoint when one or more tafety valves on steam generator inoperable.

 STULI, J F Operating Reactors Branch 4 82/10/20. 7pp. 19865 252, 24X Fiche: 50-346,82/10/20,8210270378
- --8210290385 Bafety evaluation supporting Amend 4B to License NPF-3 * Office of Nuclear Reactor Regulation Director 82/10/20, 3pp 15865 259 24X Fiche: 50-344, 82/10/20, 8210290378
- --8210290387 Notice of issuance & availability of Amend 4B to Licensa NPF-3 STOLZ:J,F Operating Reactors Branch 4 82/10/20. 2pp. 15865 262. 24X Fiche: 50-346, 82/10/20,8210290378

- 8210260268 Responds to NRC 821007 itr requesting confirmation that manual valves used to isolate air start motors & fuel supply of emergency dissel generators during maint are controlled by locked valve procedure Procedure AD 1839 02 applicable CROUSE. P Toledo Edison Co 82/10/21 STOL.7. J Operating Reactors Branch 4 1p 15805 221 24X Fiche 50-346,82/10/21.
- Q Inspection reports, IE Bulletins & correspondence
- 8210080015 Add1 response to FOIA request for 19 categories of info re nuclear reactor events & safety problems Forwards documents listed in App A Documents in App B completely withheld (ref FOIA Examption 5)
 FELTON.J M Division of Rules and Records 82/07/12 UDELL.R A Critical Mass Energy Project 9pp 15/645 027 24X
 Fichs 50-000, 82/07/12, 8210080015
- --8210080128 Bystematic assessment of licensee performance notes refacility svaluation for Nov 1979-Oct 1980
 * NRC No Detailed Affiliation Given BO/10/30 15pp
 15667 334 24X Fiche 50-000, 82/07/12, 8210080015
- 8210060314 Responds to IE Bulletin 81-01, "Burveillance of Mechanical Snubbers " Snubbers inspected during recently completed refueling outage Nine snubbers identified as nonconforming CROUSE.R P Toledo Edison Co 82/09/14 KEPPLER.J O Region 3, Office of Director, opp 15619 216 24X Fiche 50-346,82/09/14, 8210060314
- 8210050253 Ack receipt of 820708 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-346/82-18
 STREETERJF Division of Project & Resident Programs BP/09/24
 CRCU8E-R P. Toledo Edison Co 1p 15610 271 24X
 Fiche 50-346,82/09/24,8210050253
- --8210050258 Responds to NRC 820810 ltr re violations noted in IE insp. Rept 50-346/82-18 Corrective actions operations supervisor discussed event w/shift supervisors stressing importance of strict procedure compliance & review of locked value status CROUSE/R P Toledo Edison Co 82/09/08 STREETER.J F Division of Project & Resident Programs 2pp 15610 292 24X Fiche 50-346,82/09/24.8210050253
- 8210080285 Ack receipt of 820907 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-344/82-03
 NORELIUS.C E Division of Engineering & Technical Programs
 82/10/04. CRCUSE.R P Toledo Edison Co ip 15638 315 24X
 Fiche 50-344, 82/10/04. 8210080285
- --8210080288 Responds to NRC 820816 ltr re violations noted in IE Inta Rept 50-346/82-03 Corrective actions GA program will be updated to include review of regulatory requirements & commitments CROUSE, R.P. Toledo Edison Co 82/09/07 NORELIUB, C E Oivisien of Engineering & Technical Programs 2pp 15638 316 24X Fiche 50-346,82/10/04,8210080285
- 8208190233 IE Info Notice 80-35, Suppl 1, "Leaking & Dislodges [-125 Implant Beeds," Svc list encl.

 COBD.L.I. Division of Fuel Facilities, Materials & Safeguards
 82/10/06 Consolidated Edison Co of New York 66pp. 15761 250
 24X Fiche 50-000,82/10/06,8208190233
- 8210250286 Forwards IE Bafety Evaluation Rept 50-346/82-26 on 820901-30 No noncompliance noted HIND, J A Division of Emergency Preparedness & Operational Bupport 82/10/07 CROUBER P Toledo Edison Co 2pp. 15791-106 24X Fiche 50-346, 82/10/07, 8210250286
- --8210250297 IE Safety Evaluation Rept 50-346/82-26 on 820901-30 No noncompliance noted Major areas inspected site emergency plan.
 PLOSKI:T J , AXELSON-W L , PAPERIELLO,C J Division of Emergency Preparedness & Operational Support, 82/10/06 37pp 15791 106 24X Fiche 50-346/82/10/07,8210250286
- 8208190238 IE Bulletin 82-03. "Btress Corrosion Cracking in Thick-Wall, Large-Diameter, Stainless Steel, Recirculation Syspiping at BMR Plants "Syclistent DEYOUNG, R C. Director's Office, Office of Inspection and Enforcement 82/10/14 Consolidated Edison Co. of New York 115pp 15810:125 24X Fiche, 50-000, 82/10/14, 8208190238
- 8 Reportable occurrences, LERs & related correspondence
- 8012290118 Discusses conclusions of engineering evaluation of steen generator overfill transients at C-E & Westinghouse plants LANNING.W D Director's Office 80/10/29, MICHELSON, C Directse's Office 3pp. 15692,262 24X Fiche 50-000:80/10/29.8012290188

- #21CO70115 Discusses LER 79-062/03L-1 re auxiliary feedwater sysprassure switches On 790321; several switches would not activate Failure caused by corrosion due to misapplication of static O ring switches
 CHIRAMAL: M Director's Office 81/12/07 MICHELSON, C Director's
 Offace 3pp 15649 216 24X Fiche 30-346, 81/12/07, 8210070115
- 8210070460 Concludes that problem of misapplication of static O ring disphregm-type switches is indigenous to Davis-Besse plant Corrective action to replace Buna-N switches w/stainless steel switches adequate CMIRAMAL'N Director's Office 81/12/07 MICHELSON, C Director's Cffice 3pp 15644 341 24X Fiche 50-344,81/12/07,8210070460
- \$210-010008 Respands to FOIA request for 19 categories of documents re roclear reactor events & safety problems Forwards documents listed in App A FELTON-J M Division of Rules and Records 82/06/28 UDELL R A. Crátical Mass Energy Project 15pp 15727 005 24x Fiche 50-000-82/06/28-8210010008
- --BilliB000: Recommends comprehensive assessment of plant operating conditions to determine specific predetermined time related sequences of occurrence to emergency buses SRP should be ravised re design features
 ASHE.F Director's Office 81/10/16 MICHELBON.C. Director's Office 4pp 15731 049 24X Fiche 50-000.B2/06/28.8210010008
- --B201190538 Evaluates LER 79-062/03L-1 re auxiliary feedwater sys pressure switches Hisapplication of static D-ring diaphragm type sustches was limited to facility Replacement w/stainless steel diaphragm switches seems adequate CHIRAMAL. M Director's Office 81/12/07 MICHELSON, C Director's Office 3pp 65825 291 24X Fiche 50-000, 82/06/28, B210010008
- 8210050323 Forwards LER 82-041/03L-0 MURRAY.T D Toledo Edison Co 82/09/22 KEPPLER.J 0 Region 3. Office of Director 19 15608 221 24% Fiche 50-046.82/09/22. 8210050323
- --82:0050327 LER 82-041/03L-0 on 820821, setpoints of three main steam safety valves found out of tolerance Caused by normal valve aging Two valves immediately reset & third valve adjusted at reduced main steam pressure.

 D'NEILL-J Toledo Edison Co 82/09/23 Region 3. Office of Director 3pp 15408 222 24X Fiche 50-346,82/09/22,8210050323.
- 8210050355 Forwards LER 82-042/03L-0 MURRAY.T D Toledo Edison Co 82/07/24 KEPPLER, J O Region 3 Office of Director ip 15609 042 24X Fiche 50-346,82/09/24, B210050355
- --B210050361 LER 82-042/03L-0 on 820827, once-through steam generator 1 fevel exceeded Tech Spec Limit on full-range instrumentation Caused by operator error during plant shutdown on 820823 Operators cautioned

 Tolsdo Edison Co. 82/09/24 Region 3, Office of Director 3pp 15509 043 24X Fichs 50-346, 82/09/24, 8210050355.
- 8210130356 Forwards LER 82-031/03X-2 MURRAY.T D Toledo Edison Co 82/09/28 KEPPLER, J O Region 3, Office of Director 1p 15679 012 24X Fiche 50-346,82/09/28, B210130356
- --B210130366 LER 82-031/03X-2 on 820625 & 0706. fire barrier doors 500 & 426 found slightly open On 820629, fire barrier & negative pressure door 302 found slightly open Caused by closure mechanism failure to seat doors tightly due to design error. WOLFE, Tolado Edison Ca 82/09/28, Region 3, Diffice of Director 2pp 15679 013 24X Fiche, 50-346, 82/09/28, 8210130356
- 8210130404 Forwards LER 82-043/03L-0 MURRAY, T D Toledo Edison Co 82/09/29, KEPPLER, J O Region 3, Office of Director ip 15681 164 24X Fiche, 50-346, 82/09/29, 8210130404
- B210130124 Forwards LER 82-044/03L-0 BURRAY.T D Toledo Edison Co 82/09/30 KEPPLER, J G. Region 3, Office of Director ip 15673 040 24x Fiche, 50-346, 82/09/30, 8210130124

- --8210130128 LER 82-044/03L-0 on 820916 review revealed that steam k feedwater rupture control sys monthly surveillance Procedure 8T 5031.14 not completed in time allotted in Tech Spacs Caused by personnel error Test completed WERNER, B U Teledo Edison Co 82/09/30 Region 3, Office of Director 3pp 15473 04: 24x Fiche 50-346-82/09/30.8210130124
- 8210180131 Forwards LER 82-045/03L-0 MURRAY, T D Toledo Edison Co 82/10/04 KEPPLER, J Q Region 3, Office of Director 1p 13717 335 24X Fiche 50-346, 82/10/04, 8210180131
- --8210180137 LER 82-045/03L-O on 820904.auxiliary feedbater pump 1-1; suction valve FW786 observed closed for no apparent reason w/o operator touching close button Cause unknown Valve reopened.
 LONG, J W Toledo Edison Co 82/10/04 Region 3, Office of Director 2pp, 15719 336 24x Fiche 50-346,82/10/04,8210180131
- 8210190254 Forwards LER 82-046/03L-0 MURRAY, T D Toledo Edison Co 82/10/07 KEPPLER, J Q Region 3, Office of Director 1p 15742 143, 24X Fiche 50-346,82/10/07, 8210190254
- --8210170261 LER 82-046/03L-0 on 820708, high decay heat flow alarm received Decay heat flow pump 2 & high pressure injection flow Pump 2 found not running Caused by failure af 24-vuit dc gower supply for buffer cards Power supply replaced IBLEY.T Toledo Edison Co 82/10/07 Region 3. Office of Director. 2pp 15742 144 24X Fichs 50-346.82/10/07.8210190254.
- 8210190358 Forwards revised LER 79-076/03X-1 MURRAY, T D. Toledo Edison Co 82/10/11 KEPPLER, J. Q Region 3. Office of Director 1p. 15742 098 24X Fiche 50-346, 82/10/11, 8210190358
- --8210190359 Revised LER 79-076/03X-1 on 79070B, core flood tank 1-1 level alarm received Caused by faulty amplifier in level transmitter LT-CF3B2; resulting in incorrect reading Amplifier replaced & transmitter recalibr BORYSIAK, M. RICHTER, L. Toledo Edison Co. 82/10/11. Region 3, Office of Director 2pp 15742 099 24X Fiche 50-346,82/10/11, 8210190358
- 8210250270 Forwards LER 92-047/03L-0 MURRAY.T D Toledo Edison Co 82/10/12. KEPPLER.J Q. Region 3. Office of Director. 1p 15791 045. 24X Fiche: 50-346, 82/10/12, 8210250270
- --B210250279 LER B2-047/03L-0 on B20913 & 15 containment radiation trip occurred Caused by component failure of output radiation monitor RE-2004 on safety features actuation sys Channel 1 Operational amplifier & output transistor replaced ELDRED. D T Taledo Edison Co B2/10/12 Region 3, Office of Director Spp 15791 046 24X Fiche 50-346, B2/10/12, B210250270,
- 8210250226 Forwards LER 82-048/03L-0 MURRAY, T. D Toledo Edison Co 82/10/14 KEPPLER, J G Region 3, Office of Director. 1p 15788:358 24X Fichs 50-346,82/10/14, 8210250226
- ~-8210250231 LER 82-048/03L-0 on 820917, during flushing of vent line on concentrate storage tank, open fire door 101a blocked w/ temporary hose. Caused by personnel error General orientation training modified to require training on fire doors SERIUK.P Toledo Edison Co. 82/10/14. Region 3, Office of Director Spp. 15788:359 24X Fiche:50-346,82/10/14,8210230226.
- 8210280075 Forwards LER 82-049/03L-0.
 MURRAY, T D Toledo Edison Co 82/10/19. KEPPLER, J Q. Region S.
 Office of Director 1p 15837-165. 24X Fiche 50-346,82/10/19,
 8210280075
- --8210280078 LER 82-049/03L-0 on 820920 & 22, Channels 2 & 3 on containment post-accident radiation monitor RE 459784 were reading high Caused by problem in microprocessor software.

 New set of software installed & faulty actuator replaced, ELDRED, D T Taledo Edison Co. 82/10/19 Region 3, Office of Director, 2pp. 15837 166. 24X Fiche: 50-346,82/10/19,8210280075
- DOCKET 50-348 JOSEPH M FARLEY NUCLEAR PLANT, UNIT 1
- F. Security, medical, emergency & fire protection plans
- 8210010196 Ack receipt of 820827 ltr re emergency exercise scheduled for Feb 1983 STOHR, J. Division of Emergency Preparedness & Operational Bupport. 82/09/17 MCDONALD, R P. Alabama Power Co. 1p. 15570 360 24X Fiche: 50-348, 82/09/17, 8210010196.

- 8210010195 Forwards Revisions 4 & 5 to security plan Revisions withheld CLAYTON, F L Alabama Power Co 82/09/21 VARGA, 8 A NRC No Datailed Affiliation Civan ip 15567 313 24X Fiche 50-348, 82/09/21, 8210010195
- 8210190066 Releases public version of revised emergency plan implementing procedures FELTON, J H Division of Rules and Records 82/10/01 Document Hanagement Branch Ip 15761 060 24X Fiche 50-348,82/10/01,8210190066
- --B210190073 Public version of emergency plan implementing procedures, including Procedures FNP-0-EIP-11 re handling of injured personnel & FNP-0-EIP-19 re site area emergency Procedure request forms enci
 4 Alabama Power Co B2/09/21 35pp 13761 061 24X
 Fiche 50-348, B2/10/01. B210190066
- 8210180004 Forwards IE Safeguards Insp Repts 50-348/82-23 & 50-364/82-22 on 820921-24 No nencompliance noted VERRELLI.D Division of Project & Resident Programs 82/10/12 MCDDMALD.R P Alabama Power Co 2pp 15720 025 24X Fiche.50-348.82/10/12.8210180004
- --8210180007 IE Bafeguards Insp Repts 50-348/82-23 & 50-364/82-22 on 820721-24 No noncompliance noted Major areas inspected security plan & implementing procedures & security organization Details withheld (ref 100FR73, 21) STANSBERRY, W W , MCOUIRE, D R Division of Engineering & Technical Programs 82/10/08 lp 15720 027 24X Fiche 50-348,82/10/12,8210180004
- 8210280158 Application for amend to Licenses NPF-2 & NPF-8, revising Tech Specs to require audit on emergency preparedness program every 12 months.psr 10CFR50, 54(t) & Generic Ltr 82-17 No amend fee required SER encl CLAYTON, F L Alabama Power Co 82/10/25 VARGAS A Dffice of Nuclear Reactor Regulation. Director 2pp 15837 194, 24X Fiche 50-348, 82/10/25,8210280158
- --8210280165 Proposed Tech Specs, Section 6 5 2 8 requiring audit of emergency preparadness every 12 months, per 10CFR50 54(t) & Generic Ltm 82-17 4 Alabama Power Co 82/10/25 3pp 15837-196, 24X Fiche 50-348,82/10/25,8210280158

M Antitrust correspondence

- 8210060179 Notifies of Debevoise & Plimpton change of address as of 821001 Affirmation of Svc encl * Debevoise & Plimpton 82/10/01 3pp. 15614 108. 24X Fiche 50-340, 82/10/01, 8210060179
- P Operating license stage documents & correspondence
- 821001000B Responds to FOIA request for 19 categories of documents re nuclear reactor events & safety problems. Forwards documents listed in App A. FELTON.J M. Division of Rules and Records 82/06/ZB UDELL.R.A Critical Mass Energy Project 15pp 15727.005 24X Fiche 50-000.82/06/28.82100100008.
- --8008050265 Discusses addl required info to better define potential for cracking in reactor vessel nozzles.

 NOONAN, V.S. Assistant Director for Materials & Qualifications Engineering. 80/05/05. TEDEBCG.R L Assistant Director for Licensing. 2pp 15727-176 24X Fiche: 50-000.82/06/28, 8210010008
- 8210010227 Confirms 820820 telcon arrangements re 820930 meeting w/util in Region 2 ofc to discuss fuel rod degradation resulting from baffle water-jet impingement Proposed agends encl. O'REILLY, J.P. Region 2. Office of Director. 82/09/03. MCDONALD, R.P. Alabama Power Co. 2pp 13567:336, 24x Fiche: 50-348, 82/09/03, 8210010227.
- 8210280158 Application for amend to Licenses NPF-2 & NPF-8, revising Tech Specs to require audit on emergency preparedness program every 12 months, per 10CFR50. 54(t) & Generic Ltr 82-17. No amend fee required. SER encl CLAYTON, F.L. Alabama Power Co. 82/10/25, VAROA, S.A. Office of Nuclear Reactor Regulation, Director 2pp. 15837.174, 24% Fiche: 50-348, 82/10/25, 8210280158.
- --8210280165 Proposed Tech Specs, Section 6, 5, 2, 8 requiring audit of amergency preparedness every 12 months, par 10CFR50, 54(t) & Generic Ltm 82-17

 * Alabama Fauer Co. 82/10/25, 3pp. 15837; 196, 24X
 Fiche: 50-348, 82/10/25, 8210280158,

- Q Inspection reports, IE Bulletins & correspondence
- 8210070007 Responds to FOIA request for eight categories of records resteam generators & steem turbines App A documents provided in R Udell FOIA Request 81-313 Forwards documents listed in App B FELTON, J M Division of Rules and Records 82/08/10 LONG, D J Winthrop, Stimson, Putnam & Roberts 9pp 15645 063 24X Fiche 50-000; 82/08/10; 8210070007
- --8210070137 Forwards tabulated data on steam generator insp t maint at facilities Data should be provided to licensees IPPOLITO, T Operating Reactors Assessment Branch 82/04/01 VAROA.S Operating Reactors Branch 1 5pp 15645 131 24% Fiche 50-000,82/08/10,8210070007
- 8210010204 Forwards IE Insp Repts 50-348/82-21 & 50-364/82-20 on 820802-06 No noncompliance noted panker. HC Region 2. Office of Director 82/08/30 MCDDNALD.R P Alabama Power Co 2pp 15567 314 24X Fiche 50-348,82/08/30,8210010204
- --821001020B IE Insp Repts 50-348/82-21 & 50-364/82-20 on 82080R-06.No noncompliance noted, Major areas inspected pipe supports & restraints & Types B & C containment leak rate testing BROOX8, E. JAPE, F. Division of Engineering & Technical Programs 82/08/25 4pp 15567 316 24% Fiche 50-348, 82/08/30, 8210010204
- B210010043 Concurs w/actions outlined in util B20B12 ltr re inspared in the ltr built of the ltr re inspared by IE Bulletin 79-13, except in areas of re-radiographing steam generator feedwater notile-to-pipe & weld retention of records
 LEMIB.R C Division of Project & Resident Programs B2/09/13
 HCDONALD.R P Alabama Power Co 2pp 15570 361 24X
 Ficha 50-348, 82/09/13, 8210010043
- 8210150072 Ack receipt of 820707 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-348/82-19 & 50-346/82-18

 DANCE,H C Division of Project & Resident Programs 82/10/04 MCDONALD,R P Alabama Power Co ip 15701 253 24X Fiche: 50-348, 82/10/04, 82/10150072.
- --8210150074 Responds to NRC 820818 ltr re violations noted in lE Insp. Repts 50-348/82-19 & 50-344/82-18 Corrective actions Form NRC-3 posted at low level radwaste bldg CLAYTON.F L Alabama Fower Co 82/09/09 DANCE.H C Region 2. Office of Director 2pp 13701 254 24X Fiche 50-348,82/10/04. 8210150072.
- --8210150078 Forwards IE Insp Repts 50-348/82-19 & 50-364/82-18 on 820726-30 & notice of violation DANCE.H C Division of Project & Resident Programs. 82/08/18 HCDDNALD.R.P Alabama Power Co 2pp 15701-256 24X Fiche. 50-348
- --8210150082 Notice of violation from insp on 820726-30
 * Division of Project & Resident Programs 82/08/19 15701 258 24% Fiche 50-348,82/10/04,8210150072
- --8210150086 IE Insp Repts 50-348/82-19 & 50-364/82-18 on 820724-30 Noncompliance noted Form NRC-3. "Notice to Employers." not posted in new low level waste storage facility. PEERY.W W. BARR.K P Division of Engineering & Tachnical Programs 82/08/16 5pp 15701.259. 24X Fiche 50-348.82/10/04.8210150072.
- B210220229 Forwards IE Insp Repts 50-348/82-22 & 50-364/82-21 on 820816-0915. No noncompliance noted DANCE,H G. Division of Project & Resident Programs 82/10/04 MCDDNALD,R P. Alabame Fouer Co 2pp 15776.233. 24X Fichs: 50-348, 82/10/04, 8210220229.
- --8210220232 IE Insp Repts 50-348/82-22 % 50-364/82-21 on 9208]6-0913
 No noncompliance noted Hajor ereas inspected: monthly
 surveillance & maint observation operational safety
 verification, plant trips & LERs,
 BRADFORD, H. H., BROHNLEE, V L. Division of Project & Resident
 Programs 82/10/04 7pp 15776 235, 24X Fiche 50-348,82/10/04,
 8210220229.
- 8208190233 IE Info Notice 80-35, Suppl 1, "Leaking & Dislodged I-125 Implant Beeds." Svc list encl.
 COB9.L L. Division of Fuel Facilities, Materials & Gafeguards
 82/10/06. Consolidated Edison Co. of New York. & App. 15761-220
 24X Fiche: 50-000, 82/10/04, 8208190233.
- 8210180004 Forwards IE Bafeguards Insp Repts 50-349/82-23 4 50-364/82-22 on 820921-24. No noncompliance noted. VERRELLI, D. Division of Project & Resident Programs. 82/10/12 MCDDMALD, R P. Alabame Power Co. 2pp. 15720.025, 24X Fiche: 50-348, 82/10/12, 8210180004.

- S200190238 IE Bulletin B2-03, "Stress Corrosion Cracking in Thick-Mall, Large-Diameter, Stainless Steel, Recirculation Sysfepang at BMR Plants "Svc list encl ECYOUNO, RC Director's Office, Office of Inspection and Enforcement B2/10/14 Consolidated Edison Co of New York 115pp 15810 125 24X Fiche 50-000, 82/10/14, 8208190238
- E210280410 Natification of 821029 meeting w/util.Franklin Research Ctr & Bechtei in Bethesda.MD to review calculations & cathodology re IE Bulletin 80-11. "Masonry Walls " AEEVESIE A Operating Reactors Branch 1 82/10/20 VARGA.B. Operating Reactors Branch 1 2pp 15859 332 24X Fithe 50-348, 82/10/20, 8210280410
- R Periodic operating reports & related correspondence
- E210190722 Forwards monthly operating sept for Sept 1982 CLAYTON, F. L. Alabama Power Co. 82/10/12 Management Information Stanch ip 15736 301 24% fiche 50-348, 82/10/12, 8210190722
- S Reportable occurrences, LERs & related correspondence
- E210070470 Discusses 810317 inadvertent actuation of safety injection sys Event caused by operator error during surveillance teating k raises concern of potential common mode failure for falsel engines w/turbocharges CH1RAMAL.H Director's Office 81/04/24 HICHELSON,C Director's Office 2pp 15644 349 24X Fiche 50-348,81/04/24,8210070470
- B21Q070111 Reviews purge valve info contained in T Austin 810306 memo Primary technical issue relates to valve operability during expected accident conditions Vital areas of concern not addressed in info include lower torque margin for closure BROWN.E J Director's Office 81/07/24 MICHELBON.C Director's Office 4pp 15646 359 24X Fiche: 50-348,81/09/24,8210070111
- 8210010098 Responds to FOIA request for 19 categories of documents re nuclear reactor events & safety problems Forwards documents Ilested in App A FELTONI, J M Division of Rules and Records 82/06/28 UDELL, R. A Critical Mass Energy Project 15pp 15727 005, 24X Fische 50-000, 82/06/28, 8210010008
- --BR10050027 Discusses proposed watch list item potential common mode failure of diesel generators AEOD sequence coding & search procedure (SCSP) will be revised to include "fire" as searchable item to enable monitoring of similar events CHERAMAL, M Office of Management and Program Analysis B1/04/24, MICHELSON, C Office of Management and Program Analysis 2pp 15729 044 24 Fiche: SO-000, 82/06/28, 821001000B
- B210010129 Forwards LERs B2-037/03L-0 & B2-052/03L-0 CLAYTON.F L Alabama Power Co 82/09/27 Region 2, Office of Director is 13567 227 24X Fiche.50-348.82/09/27,8210010129.
- --B2100(0139 LER 82-052/03L-0 on B20831, during control room emergency ventilation performance test, B train emergency air cleanup sys failed to meet acceptance criteria Caused by failure of charcoal filter to meet efficiency requirements, HAIRSTON, H. O Alabama Power Co 82/09/27 Region 2, Office of Director 1p 19567 228 24X Fiche 50-348, 82/09/27, 8210010129,
- --8210010147 LER 82-037/03L-0 on 820905.A train auto trip logic for high steam generator differential pressure declared inoperable when failed cord indication received by automatic tester Caused by failure of universal card.Card replaced HAIRSTON.H 0 Alabama Power Co 82/09/27 Region 2, Office of Director. 1p 15567 229 24X Fiche 50-348,82/09/27,8210010129.
- 8210190609 Forwards LER 82-053/03L-0 CLAYION.F L Alabama Power Co 82/10/08 Region 2, Office of Director. ip 15740 007. 24% Fiche, 50-348, 82/10/08, 8210190609.
- --B210190614 LER 82-053/03L-0.on 820912, containment atmosphere particulate redioactivity monitoring sys R-11 declared inoperable due to filter paper not advancing, Caused by failure of paper drive motor Motor replaced.

 HAIRSTON. H. Q. Alabama Power Co. 82/10/08. Region 2, Office of Director ip. 15740:008 24X Fiche: 50-348, 82/10/08, 8210190609

- 82:0260453 Forwards LERs 82-054/03L-0.82-055/03L-0.82-039/03L-0 & 82-040/03L-0 CLAYTON,F & Alabama Power Co 82/10/18 Region 2, Office of Director. 19 15806 175 24X Ficher 50-348,82/10/18,8210260453
- --8210260463 LER 82-054/03L-0 on 820920, flow transmitter FT-497 failed low Caused by failure of N.P printed circuit card in 7300 process control sys Card replaced & instrumentation loop associated w/transmitter returned to svc HAIRSTON:H Q Alabama Power Co 82/10/18 Region 2, Office of Director ip 18804 196 24X Fiche 50-348, 82/10/18, 8210240453
- --8210260470 LER 82-055/03L-0 on 820921, train B chlorine detector declared inoperable due to nonadvancing detector tape Caused by faulty tape drive motor. Motors & light diffusion disc replaced.

 HAIRBTON.H O. Alabama Power Co. B2/10/1B Region 2, Office of Director 1p 15806 197 24X Fiche-50-248, 82/10/18, 8210260459
- --8210260480 LER 82-039/03L-0 on 820919, svc water to component cooling water HX 2C isolated Caused by dislodged pin holding worm drive gear allowing differential pressure across valve disc to close valve Pin reinstalled & secured.
 HAIRSTON, H. O. Alabama Power Co 82/10/18 Region 2, Office of Director ip 15805-198 24X Fiche 50-348,82/10/18,8210260453
- --8210260490 LER 82-040/03L-0 on 820919, loss-of-voltage protection channel associated w/82F sequencer phase 2-3 declared inoperable Caused by failure of loss-of-voltage relay 27XF1 during testing Relay cleaned HAIRSTON.H O Alabama Power Co 82/10/18 Region 2, Office of Director ip 18806 199 24X Ficher 50-348,82/10/18,8210240453
- DOCKET 50-352 LIMERICK GENERATING STATION, UNIT 1
- A Application/construction stage documents & correspondence
- B210190134 Forwards questions re actions of DE River Basin Commission in Point Pleasant Diversion Project, per 820831 invitation.

 8CHWENCER.A. Licensing Branch 2 82/09/16 HANBLER, 0 Delaware River Basin Commission 5pp 15761.239 24X Fiche.50-352.82/09/16, 8210190134
- 8210050479 Forwards request for add1 info re environ review, Schedule for responding to questions requested within 7 days SCHMENGER, A Licensing Branch 2 82/09/21 BAVER, E O Philadelphia Elactric Ca 11pp 15626, 263. 24x Fiche: 50-352, 82/09/21, 8210050479
- 8210040362 Forwards responses to 820708 potentially generic concerns re adequacy of design margins of QE Mark II pressure suppression containment sys KEMPER. J. 8 Philadelphia Electric Co 82/09/30. BCHWENGER, A. Licensing Branch 2 SOpp 15589 02B. 24X Fiche 50-352, 82/09/30, 8210040362
- 8210050326 Forwards supplemental util comments on Del-Aware Unlimited request for suppension or revocation of CP & corrected Page 14 of 820703 comments.

 CONNER.T.B Conner & Wetterhahn 82/07/30, DENYON, H R, Office of Nuclear Reactor Regulation, Director 2(pp. 15608:162. 24X Fiche:50-352:82/07/30.8210050326
- 8210180311 Summary of 820624-25 meetings w/util in Pottstown.PA re applicant response to NRC 820323 info request concerning probabilistic risk assessment.Attendee list encl ABELSON.H Licensing Branch 2. 6pp 15746 011 24X Fiche 50-352,82/10/05,8210180311.
- 8210270167 Notification of 821019-22 meetings w/util & Bechtel in Ban Francisco, CA to discuss structural engineering design audit ABELSON.H Licensing Branch 2. 82/10/05. BCHHENCER.A. Licensing Branch 2. 4pp. 15876/230 24X Fiche: 50-352:82/10/05,8210290167.
- 8210130124 Forwards Revision 5 to "Probabilistic Risk Assessment" for facility, consisting of responses to NRC 820810 request for add1 info & corrections to typographical errors BRACLEY.E J. Philadelphia Elactric Co 82/10/12 BCHWENCER.A R. Licensing Branch 2, ip. 15704:134. 24X Fichs: 50-352, 82/10/12, 8210150124.
- ~~8210150133 Revision 5 to "Probabilistic Risk Assessment."

 * Philadelphia Electric Co 82/09/30. 214pp 15706; 136. 24X
 Fiche: 50-352, 82/10/12, 8210150126.
- 8210260158 Advises that response to Licanse Gualifications Branch 820901 request for add1 info will be submitted via FBAR revision in Dec.1982 BRADLEY.E.J. Philadelphia Electric Co. 82/10/22, 8CHWENCER.A. Licensing Branch 2, 2pp. 15799.010. 24X Fiche 50-352,82/10/22, 8210260188

- C Utility Environmental Report (ER), amends & correspondence
- 8210150397 Forwards Affidavit of Svc re distribution of Ravision 10 to FBAR & Revision & to environ rapt, per NRC 810706 ltr BRADLEY, E J Philadalphia Electric Co. 82/10/12 DENTON. H. R Office of Nuclear Reactor Regulation, Director 5pp 15703 281 24% Fiche 50-352,82/10/12,8210150397
- F Security, medical, emergency & fire protection plans
- 8209170149 Forwards util response to NRC 82072B comments on physical security plan Response withheld (ref 10CFR2 790), Affidavit requesting that response be withheld from public disclosure and BRADLEY, E. J. Philadelphia Electric Co. 82/09/13, DENTON, H. R. Office of Nuclear Reactor Regulation, Director, 4pp. 14907, 250 24X Fishs 50-332, 82/09/13, 8209170149
- Q Adjudicatory correspondence
- 8210180204 Application for approval of patition to amend Contentione V-22.V-23 & V-24 Info new & relevant Cartificate of Evc encl.

 809ARMAN, R. J. Del-Aware Unlimited, Inc. BUOARMAN, R. J. Bugarman, R. J. 82/09/20 Commissioners & pp. 15718-141 24X
 Fichs 50-352,82/09/20,8210180204
- --B21018020B Trial brief supporting request to amend Contentions V-22, V-23 & V-24 New info re Merrill Creek.DE River Basin Commission findings of inadequate water to supply diversions & Unit 2 cancelation evailable Certicate of SV encl BUOARMAN,R J Del-Aware Unlimited, Inc BUOARMAN,R J Bugarman, R J B2/09/20 Atomic Sefety and Licensing Board Panel 30pp 13734 320 24% Fiche 50-352.82/09/20.8210180204
- 8210010244 Response opposing DE River Basin Commission motion to quash subposna Intervenor does not seek add1 testimony from O Hansler but believes deposition inadmissible. Certificate of Svc encl Related correspondence
 SUGARMAN.R J Del-Aware Unlimited, Inc BUOARMAN.R J Sugarman, R J 82/09/27 Commissioners App. 15568: 280. 24X
 Fiche. 50-352.82/09/27.8210010244
- 8210180217 Motion to strike EH Bourguard testimony re impacts of intake of biological spacies. No expertise shown by witness re subjecter of testimony Related correspondence SUGARHAN: R.J. Bujarman: R.J. 82/09/27 Commissioners 2pp 15718. 101 24X Fiche 50-352: 82/09/27: 8210180217
 - for change of hearing schedule, for consolidation all uss & to strike NRC testimony, ABLB should inclusion to Commission Certificate of Byc

ted, Inc. SUGARMAN.R.J Sugarman, s. 16pp. 15718,064 24X

BUGARMAN, R J. 15718: 080.

- 8210180224 Motion to strike MT Masnik testimony due to prejudice, bias & fact that testimony not based on FEB Related correspondence SUGARMAN, R. J. Bel-Ausre Unlimited, Inc. SUGARMAN, R. J. Bugarman, R. J. B2/09/27, Commissioners, 3pp. 15718:061, 24X Fiche, 50-352, 82/09/27, 8210180224.
- 8210180203 Motion to strike J Lear testimony. Testimony shows extreme bias & goes beyond witness statement of purpose. Related correspondence, SUGARMAN. R. J. Bel-Aware Unlimited, Inc. BUGARMAN. R. J. Bugarman. R. J. 82/09/27 Commissioners. Spp. 15718:036. 24X Fiche: 50-032, 82/09/27, 8210180253.
- 8210040087 Advises that NRC witness A Policostro will be available to testify only on 821004-05. Testimony should be scheduled out of turn.

 HODBOON.A.P. Hearing Branch 2, 82/09/29, BRENNER, L., MORRIB, P.A., COLE, R. F. Atomic Bafety and Licensing Spand Panel. 2pp. 15581:037
 24X Fiche:50-392,82/09/29,8210040087.
- 8210030326 Forwards supplemental util comments on Del-Aware Unlimited request for suspension or revocation of CP 4 corrected Page 14 of 820903 comments. CONNER.T. B Conner 4 Metterhehn. 82/09/30. DENTON.H. R. Office of Nuclear Reactor Regulation, Director. 21pp. 15608;162. 24X Ficha: 50-352:82/09/30;82:0030326

- 8210050088 Response opposing Del-Aware 820927 motion to striks NRC testimony of J Lehr & MT Masnik, Del-Aware concerned wivelight to be accorded testimony, not requirements for receipt Notice of appearance & Certificate of Bvc encl HDDDDON, A.P. Hearing Branch 2 82710/01 Atomic Safety and Licensing Board Panel App 15604 276 24X Fiche, 50-352, 82/10/0 8210050088
- B210050197 Answer opposing Del-Aware Unlimited, Inc B20927 motion for mod to hearing schedule, for consolidation or to strike NRC testimony Del-Aware estopped from asserting impropristy or illegality of ABLB authority on cooling water contentions CONNER.T B Philadelphia Electric Co CONNER.T B Conner & Wetterhahn. 82/10/01 Atomic Bafety and Licensing Board Panel 2dpp. 15611.129 24X Fiche 50-352, 82/10/01, 8210050197
- 8210050382 Response in opposition to Del-Aware 820927 motion to stritestimony of EH Bourquard re design, configuration & const of Point Pleasant intake Assertions do not affect relevance of testimony or witness qualifications.
 CONNER, T B Philadelphia Electric Co CONNER, T B Conner & Wetterhahn. 82/10/01 Atomic Safety and Licensing Board Panel 4pp 13508 277 24% Fiche 50-352,82/10/01.8210050382
- 8210070199 Requests schedule for submitting discovery rept be postponed until all necessary parties available Counsel for all parties involved in hearing on water issues Related correspondence DORBEY, J. A. DORBEY, J. A. Limerick Ecology Action 82/10/04 BRENNER.L. COLE.R.F., MORRIS.P. A. Atomic Bafety and Licensing Board Panel 2pp 15634-267 24X Fiche 50-352.62/10/8210070199
- B210280207 Forwards Commonwealth of PA Public Util Commission B2082 order, Corps of Engineers B20924 notice of intent to issue permit & Commonwealth of PA Dept of Environ Resources B20902 permits HODDON, A P Hearing Branch 2. 82/10/13, BRENNER, L., KORRIS, P COLE, R F Atomic Bafety and Licensing Board Panel 79pp. 15839 057 24X Fiche 50-352, 82/10/13, 8210280207.
- 8210200040 Response opposing Del-Aware modified Contention V-24
 Contention goes beyond scope of contentions as initially
 submitted & lacks adequate basis & specificity
 Certificate of Svc encl.
 HODDON:A.P Hearing Branch 2 82/10/15 Atomic Safety and
 Licensing Board Panel 10pp 15755.094. 24X Fiche: 50-352.82/IC
 8210200040
- 8210200066 Answer opposing Del-Aware Unlimited, Inc revised proposed Contention V-24, Buby of contention previously litigated, rejected by ABLB & irrelevant Certificate of Byc encl CONNER, T.B. Philadelphia Electric Co., CONNER, T.B. Conner & Hetterhahn 82/10/15. Atomic Bafety and Licensing Board Panel 33pp. 15754: 140. 24X Fiche, 30-352, B2/10/15, B210200066
- 8210210383 Confirmatory memorandum & order extending time for util, & Limerick Ecology Action to file joint rept on informal discovery until 830124
 BRENNER: A homic Safety and Licensing Board Panel 82/10/20 15763-201. 24X Fiche. 50-352, 82/10/20, 8210210383.
- 8210220332 Confirming memorandum & order.confirming ABLS 821004 der of Del-Aware Unlimited.Inc 820927 motion to postpone hearings starting on 821004.ABLB will not be addressing ultimate cost/benefit during hearings. BRENNER.L Atomic Safety and Licensing Board Panel 82/10/20 Del-Aware Unlimited, Inc. 5pp. 15775.399. 24X Fiche: 50-352, 82/10/20.8210220332

- B210130465 Opposes issuance of OL DEAN,V, Affiliation Unknown 82/09/14, BRENNER,L. Atomic Bafe and Licensing Board Panel. 2pp. 15703:048. 24X Fithe: 50-302, 82/09/14, 8210130465
- K. Utility Final Bafety Analysis Report (FBAR) & amends
- 8210150397 Forwards Affidavit of Byc re distribution of Revision is FBAR & Revision 6 to environ rept.per NRC 810706 ltr BRADLEY.E.J. Philadelphia Electric Co 82/10/12. DENION.H.R Office of Nuclear Reactor Regulation, Director 5pp 15703.201 24X Fiche: 50-352,82/10/12.8210150397

- O Advisory Committee on Reactor Safeguards reports & correspondence
- 8207180085 Forwards comments on probabilistic risk assessment study in response to 820518 request Lack of completeness noted in consideration of initiating events Total of 3 man-days espended in review

espended in review DAVIB.P R ACRB - Advisory DAVIB.P R ACRB - Advisory Committee on Reactor Safeguards GZ/09/05 DKRENT, D ACRB - Advisory Committee on Reactor Safeguards 5pp 15852:038 24X Fiche 50-352,82/09/05,8207180085

- û Inspection reports, IE Bulletins & correspondence
- P210080015 Addl response to FOIA request for 17 categories of info re nuclear reactor events & safety problems Forwards documents listed in App A Documents in App B completely withheld (ref FOIA Exemption 5) 82/07/12 UDELL,R A

FELTON, J H Division of Rules and Records 82 Critical Mass Energy Project 7pp 19665, 027 Fiche 50-000, 82/07/12, 8210080015

- --- SI05040420 Discusses review of util response re inso rept unresolved (05040420 Discusses review of util response he inspiret unresolved them identified during post-tensioning fuel pool ginders Capacity of anchorage sys is capable of meeting design requirements Unresolved item can be closed UNROANE C. Director's Office 01/00/24 MARTIN.T T Region 1, Philadelphia. Office of the Director 2pp 15668 125 24X Fich : 50-000, 82/07/12, 8210080015.
- 8210040224 Forwards "Limerick Generating Station Unit i Preservice Insp Pragram Plan for Nuclear Piping Sys." Vols 1 & 2. in response to NRC 810706 supplemental request for add info KEMPER.J S Philadelphia Electric Co 82/09/24 BCHMENCER.A Licensing Branch 2 3pp 15591 331 24X Fiche 50-352.82/09/24, 8210408224
- --8210040228 "Preservice Insp Program Plan for Nuclear Piping Sys." Vols 1 & 2 Twenty-two oversize drawings entl Aperture cards are available in PDR are available in PDR 4 Nuclear Energy Bervice, Inc. 82/07/12 737pp. 15591.334 24X Fichs 50-352,82/09/24.8210040224
- 8210210069 Forwards IC Insp Repts 50-352/82-12 & 50-353/82-09 on B20908-10 No noncompliance noted
 MARTH.TT Division of Engineering & Technical Programs 82.
 KEMPER.J B Philadelphia Electric Co. 2pp. 15765.334 24X
 Fiche 50-352,82/10/05.8210210069
- --8210210082 IE Insp Repts 80-352/82-12 & 50-353/82-09 on 820908-10. No noncompliance noted Major areas inspected foundation & backfill maths supporting & proximate to safety-related structures VARELA, A A , DURR, J P Division of Engineering & Technical Programs 82/09/26 5pp. 15765-336 24X Fiche 50-352:82/10/05, 8210210069
- 9208190233 IE Info Notice 80-35, Suppl 1. "Leaking & Dielodged I-125 Implant Seeds." Svc list encl. COBB.L I Division of Fuel Facilities, Materials & Safeguards. 82/10/06 Consolidated Edison Co. of New York 66pp 18761.250 24% Fiche 50-000.82/10/06.8208190233.
- 8210290208 Forwards IE Insp Repts 50-352/82-11 & 50-353/82-08 on B20816-0917 No noncompliance noted
 STAROSTECKI, R Division of Project & Resident Programs B2/10/08
 KEMPER, J S Philadelphia Electric Co. 2pp. 15853-275 24X
 Fiche 50-352,82/10/08,8210290208
- --8210270210 IE Insp Repts 50-352/82-11 & 50-353/82-08 on 820816-0917 No honcompliance noted Major areas inspected electrical cable pulling-housekeeping-welding & small-bore pipe supports CHAUDHARY.8.K., HCCABE.E.C., Division of Project & Resident Programs 82/10/16. 2pp 15853 277. 24% Fichs 50-352,82/10/08,8210270208
- 8210220367 Ack receipt of B20921 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-352/82-10
 MARTIN-T.Y Division of Engineering & Technical Programs 82/10/1
 KEMPERIJ. 8 Philadelphie Electric Co. 1p. 15779-194 24X
 Fiche.50-352,82/10/13,8210220367. 82/10/13.
- --9210220374 Responds to NRC 820824 ltr re-violations noted in IE Insp Rept 50-352/82-10 Corrective actions: 100X insp of all Rept 30-302/82-10 Corrective actions: 1004 insp or ex-previously inspected instrument supports performed & treining course on instrument installation conducted. KEMPER.J B. Philadelphía Electric Co. B2/09/21. HA Region I. Office of Director. App 19779.195. 24K Fiche.50-952,82/10/13,8210220367. HAYNES, R. C.

- 8208190238 IE Bulletin 82-03, "Stress Corrosion Cracking in Thick-Wall, Large-Diameter, Stainless Steel, Recirculation Bys
 Piping at BMR Plants "Svc list encl
 DEYOUNG, R C. Director's Office, Office of Inspection and
 Enforcement. 82/10/14 Consolidated Edison Co of New York
 115pp 15810 125 24X Fiche: 50-000.82/10/14.8208170238.
- T Hearing transcripts on non-antitrust matters
- 8210060234 Transcript of 821004 hearing in Norristown, PA Pp 738-961 Bupporting documentation encl # Atomic Befety and Licensing Board Panel 82/1 15621 226 24% Fiche 50-352,82/10/04,8210060234 82/10/04 299pp
- 8210070097 Transcript of 821005 hearing in Norristown, PA Pp 962-1, 274 Rupporting documentation encl.

 # Atomic Bafety and Licensing Board Panel 82/10/05 360pp
 15829 354 24X Fiche 50-352,82/10/05,8210070097
- 8210080050 Transcript of 821006 hearing in Norristown, PA Pp 1,275-1,531. Supporting documentation enci e Atomic Safety and Licensing Board Panel 82/10/06 349pp. 15443-277 24% Fichs 50-332,82/10/06,8210080050
- 8210120183 Transcript of 821007 hearing in Norristown, PA Ps 1.532-1.728 * Atomic Bafety and Licensing Board Panel 82/1 15655.215 24X Fiche 50-352,82/10/07.8210120183 82/10/07 199pp.
- 8210130239 Transcript of 821008 OL hearing in Norristown, PA Pp 1,729-2.025 Supporting documentation encl * Atomic Safety and Licensing Doard Panel 82/10/08 323pp 156/4:162. 24X Fiche 50-352.82/10/08.8210130239.
- 8210200020 Transcript of 821018 hearing in Betheada, MD 8p 2,026-2,236 Eupporting documentation encl. * Atomic Safety and Licensing Board Panel 82/10/18 221pp 15756 331 24% Fiche 50-352,82/10/18,8210200020.
- 8210210104 Transcript of 821019 hearing in Bethesda, MD, Pp 2, 237-2, 505 Bupporting documentation encl # Atomic Safety and Licensing Board Panel 82/10/19. 283pp 15766-360 24X Fiche 50-352.82/10/19.8210210104.
- 8210250115 Transcript of 821021 hearing in Dethesda, MD Pp 2,738-3,077. Supporting documentation enci

 Atomic Safety and Licensing Board Panel 82/10/21, 375pp
 15793 074 24X Fiche 50-352,82/10/21,8210250115.
- 8210260130 Transcript of 821022 hearing in Bethesda, MD Pp 3, 078-3, 374 Supporting documentation and:

 # Atomic Bafety and Licensing Board Panel: 82/10/22, 303pp.

 15801 046 24X Fiche 50-352,62/10/22,8210260130.
- 8210270062 Transcript of 821025 hearing in Bathesda, MD. Pp 3,375-3,741 Supporting documentation enci • Atomic Safety and Licensing Board Panel, 82/1 15823-035. 24% Fiche: 30-352,82/10/25,8210270062 82/10/25 561pp.
- 8210280173 Transcript of 821026 hearing in Bethesda, MD Pp 3,742-4,038, Rupporting documentation enci.

 * Atomic Bafety and Licensing Board Panel. 82/10/26. 312pp.
 15842 136. 24X Fiche 50-352.82/10/26.8210280173.
- DOCKET 50-359 LIMERICK GENERATING STATION, UNIT 2
- A Application/construction stage documents & correspondence
- 8210190134 Forwards questions relactions of DE River Basin Commission in Point Pleasant Diversion Projection 820831 invitation. SCHHENGER, A. Licensing Branch 2. 82/09/16, HANBLER, Q. Delaware River Basin Commission 5pp. 13761: 239. 24% Fiche: 30-352, 82/09/16, 8210170134
- 8210050479 Forwards request for addl info re environ review Bchedule for responding to questions requested within 7 days 8CHMENCER.A. Licensing Branch 2. 82/09/21 BAUER, E, 0 Philadelphia Electric Co. 11pp. 15426:263. 24X Fiche. 50-352, 82/09/21, 8210050479.
- 8210040362 Forwards responses to 820708 potentially generic concerns re adequacy of design margins of 9E Mark II pressure suppression containment sys. KEMPER, J.S., Philadelphia Electric Co., 82/09/30, BCHHENCER, A. Licensing Branch 2, 30pg. 18589, 028, 24X Fiche 50-352, 82/09/30, 8210040362.

- 8210050326 Forwards supplemental util comments on Del-Aware Unlimited request for suspension or revocation of CP & corrected Page 14 of 820703 comments
 CONNER.T B Conner & Wetterhahn 82/09/30 DENTON, H R Office of Nuclear Reactor Regulation, Director 21pp. 15608 162 24X
 Fiche 50-352.82/09/30.8210050326
 - 010190741 Summanu of 800604-05 meetings whit[] in Pottstown PA va
- 8210180311 Summary of 820624-25 meetings w/util in Pottstown.PA re applicant response to NRC 820323 info request concerning probabilistic risk assessment Attendee list encl ABELGON.H Licensing Branch 2 82/10/05 Licensing Branch 2 6pp 15746 011 24% Fiche 50-352.82/10/05.8210180311
- 8210290167 Notification of 821019-22 meetings w/util & Bechtel in San Francisco, CA to discuss structural engineering design audit ABELBON. H Licensing Branch 2 82/10/05 8CHMENCER, A Licensing Branch 2 4pp 15876 230 24X Fichs 30-352,82/10/05,82/0290167
- 6210150126 Forwards Revision 5 to "Probabilistic Risk Assessment" for facility, consisting of responses to NRC 820010 request for add info & corrections to typographical errors RABDLEV. E. J. Philadelphia Electric Co. 82/10/12 SCHHENCER, A. R. Licensing Branch 2 ip 15704 134 24X Fiche 50~352,82/10/12,8210150124
- --8210150133 Revision 5 to "Probabilistic Risk Assessment" + Philadelphia Electric Co 82/09/30 214pp 15706 136 24X Fithe: 50-352, 82/10/12,8210150126
- 8210260198 Advises that response to License Qualifications Branch 820701 request for addl info will be submitted via FBAR revision in Dec. 1982
 8RADLEY.E J Philadelphia Electric Co 82/10/22 SCHWENCER, A Licensing Branch 2 2pp 15799 010 24X Fiche. 50-352, 82/10/22, 8210260159
- C Utility Environmental Report (ER), amends & correspondence
- G210130397 Forwards Affidavit of Bvc re distribution of Ravision 10 to FBAR & Revision 6 to environ reptager NRC B10706 ltr BRADLEY.E J Philadeiphia Electric Co B2/10/12 DENTON.H R Office of Nuclear Reactor Regulation, Director Spp 15703 281. 24X Fiche 30-392,82/10/12,8210150397
- F Security, medical, emergency & fire protection plans
- 8209170149 Forwards util response to NRC 82072B comments on physical security plan Response withheld (ref 10CFR2 790) Affidavit requesting that response by withheld from public disclosure and BRADLEY, E. J. Philadelphia Electric Co. 82/09/13 DENTON, H. R. Office of Nuclear Reactor Regulation, Director App. 14907 250, 24X Fichs. 50-352.82/09/13,8209170149.
- O Adjudicatory correspondence
- 8210180204 Application for approval of petition to amend Contentions V-22.V-23 & V-24 Info new & relevant Certificate of Sycanci.

 8UQARMAN.R J Del-Aware Unlimited, Inc. SUQARMAN.R. J Sugarman.
 - SUOARMAN, R J Del-Aware Unlimited, Inc BUQARMAN, R J Bugarman, R J, 82/09/20 Commissioners 6pp 15718, 141 24x Fiche, 50-392, 82/09/20, 8210180204
- --8210180208 Trial brief supporting request to amend Contentions V-22, V-23 & V-24, New Info re Merrill Greek.DE River Basin Commission findings of inadequate vater to supply diversions & Unit 2 cancelation available. Certicate of Syc encl. BUOARMAN.R. J But-Aware Unlimited, Inc. BUOARMAN.R. J Sugarman, R. J 82/09/20 Atomic Bafety and Licensing Board Panel, 30pp. 15734: 320. 24X Fiche. 50-352, 82/09/20, 8210180204.
- B210010244 Response opposing DE River Basin Commission motion to quash subposes Intervenor does not seek add1 testimony from O Hansler but believes deposition inadmissible. Certificate of Svc encl Related correspondence.

 SUGARMAN, R. J. Dal-Aware Unlimited, Inc. SUGARMAN, R. J. Sugerman, R. J. B2/09/27 Commissioners. Spp. 15548-280 24X

 Ficha: 50-352, 82/09/27, 8210010244
- 8210180217 Motion to strike EH Bourguard testimony re impacts of intels of biological species No expertise shown by witness re subj matter of testimony Related correspondence.

 8UGARMAN, R. J. Del-Aware Unlimited, Inc. SUGARMAN, R. J. Sugarman, R. J. 82/09/27, Commissioners. 2pp 15718.101, 24x

 Fiche. 30-352, 82/09/27, 8210180217

- 8210180223 Motion for change of hearing schedule for consolidation all water cooling issues & to strike NRC testimony ABLB should certify issue of inclusion to Commission Certificate of Sycenci Related correspondence
 SUOARMAN.R J Bel-Aware Unlimited. Inc BUOARMAN.R J Bugerman.
 R J 82/09/27 Commissioners 16pp 15718 064 24X
 Fiche 50-352.82/09/27,8210180223
- ~-8210180226 Brief supporting motion for suspension of proceedings to consolidation or to strike NRC testimany Issuance of initial decision before full NEPA consideration will substantially prejudice Del-Aware interests & public in general BUGARMAN, R. J. NEILL, J. M. Del-Aware Unlimited, Inc. SUGARMAN, R. J. 82/09/27 Commissioners 2ipp 15719, 080 24% Fiche 50-352, 82/09/27, 8210180223
- 8210180224 Motion to strike MT Masnik testimony due to prejudice bias b fact that testimony not based on FES Related correspondence SUGARMAN, R J Bugarran, R J 82/09/27, Commissioners 3pp 15718 061 24X Fiche 30-352, 82/09/27, 8210180224
- 8210180253 Motion to strike J Lear testimony Testimony shows extract bias & goes beyond witness statement of purpose Related correspondence, 8U0ARMAN.R J Bel-Aware Unlimited, Inc 8U0ARMAN.R J 8ugerman. R J 82/09/27 Commissioners 3pp 15718 056 24X Fichs 50-352, 82/09/27, 8210180253
- B2100400B7 Advises that NRC witness A Policostro will be available to testify only on 821004-05 Testimony should be scheduled out of turn
 HOBODDN, A P Hearing Branch 2 82/09/29 BRENNER, L, MORRIB, P A, COLE, R F Atomic Sefety and Licensing Board Panel 2pp 1558: 03/24X Fiche: 30-352, 82/09/29, 8210040087
- 8210030326 Forwards supplemental util comments on Del-Aware Unificited request for suppension or revocation of CP & corrected Page 14 of 820903 comments
 CONNER, T B Conner & Wetterhahn 82/09/30 DENION, H R Office of Nuclear Reactor Repulsition, Director 21pp 15608 162 24x
- 8210050088 Response opposing Del~Aware 820927 motion to strike NRC testimony of J Lehr & MT Mesnik Del-Aware concerned wwwsight to be accorded testimony not requirements for receipt Natice of appearance & Certificate of Svc encl HODODON: A P Hearing Dranch 2 82/10/01. Atomic Safety and Licensing Board Panel 6pp 15604 276 24X Fiche 50-332.82/10/01.
- 8210050197 Answer opposing Del-Aware Unlimited, Inc 820927 motion for mod to hearing schedule, for consolidation or to strike NRC testimony, Del-Aware estopped from asserting impropriety or illegality of ABLB authority on cooling water contentions CONNER, T B. Philadelphia Electric Co. CONNER, T B. Conner & Wetterhahn 82/10/01 Atomic Sefety and Licensing Soard Panel 26pp. 13611 129 24x Fiche 50-352, 82/10/01, 8210050197
- 8210050382 Response in opposition to Del-Aware 820927 motion to atrite testimony of EH Bourquard re design: configuration & const of Point Pleasant intake Assertions do not affect relevance of testimony or witness qualifications CONNER, T B. Philadelphia Electric Co. CONNER, T B. Conner & Hetterhahn 82/10/01 Atomic Safety and Licensing Board Panel 4pp 15608, 277 24% Fiche 50-352, 82/10/01,8210050382
- 8210070199 Requests schedule for submitting discovery rept be postponed until all necessary parties available. Counsy! for all parties involved in hearing on water issues. Related correspondence, DRREY, J.A. DORSEY, J.A. Limerick Ecology Actien B2/10/04 BRENNER, L., COLE, R.F., MORRIB, P.A. Atomic Bafaty and Licensing Board Panel. Rep. 15634.267 24X Fiche. 50-352, B2/10, 8210070199.
- 8210280207 Forwards Commonwealth of PA Public Util Commission B2001 order, Gorps of Engineers 820924 notice of intent to issue permit & Commonwealth of PA Dept of Environ Resources 820902 permits HDDDDON: A.P. Heering Brench 2 82/10/13 BRENNER.L., HORRIS: F. COLE.R.F. Atomic Bafety and Licensing Board Panel. 77pp 15839'057. 24% Fiche.30-352:82/10/13;6210280207.
- 8210200040 Response opposing Del-Awere modified Contention V-24
 Contention goes beyond scope of contentions as initially
 submitted & lacks adequate basis & specificity.
 Certificate of Evc encl.
 HDDODON: A.P. Hearing Branch 2, 82/10/15, Atomic Safety and
 Licensing Board Panel 10pp 15755:094, 24X Fiche 50-052,82/10,82/10200040.

- 8210200066 Answer opposing Del-Aware Unlimited, Inc revised proposed Contention V-24 Subj of contention previously litigated, rejected by ASLB & irrelevant Certificate of Svc encl CONNER, T B Philadelphia Electric Co CONNER, T B Conner & Hetterhahn 82/10/15 Atomic Safety and Licensing Board Panel 33pp 15754 140 24% Fiche 50-352, 82/10/15,8210200066
- 8210210383 Confirmatory memorandum & order extending time for util.NRC & Limerick Ecology Action to file joint rept on informal discovery until 830124

 BRENNER: L. Atomic Safety and Licensing Board Panel 82/10/20 3pp 15743 201 244 Fiche 50-352,82/10/20.8210210383
- 8210220332 Confirming memorandum & order, confirming ASLB 821004 denial of Del-Aware Unlimited Inc 820927 motion to postpone hearings starting on 821004 ASLB will not be addressing ultimate cost/benefit during hearings BRENNER, L Atomic Bafety and Licensing Board Panel 82/10/20 Del-Aware Unlimited, Inc 5pp 15775 359 24X Fiche 50-352, 82/10/20, 8210220332

- 0210150469 Opposes issuance of OL BEAN,V Affiliation Unknown 82/09/14 BRENNER,L Atomic Safety and Licensing Board Panel 2pp 15703 048 24X Fiche 50-352:82/09/14,8210150465.
- K Utility Final Bafety Analysis Report (FBAR) & amends
- 9210150397 Forwards Affidavit of Svc re distribution of Revision 10 to FSAR & Revision 6 to environ rept,per NRC 810706 ltr BRADLEY,E J Philadelphia Electric Co 82/10/12 DENTON,H R Office of Nuclear Reactor Regulation, Director 5pp 15703 281 24X Fichs 50-352,82/10/12,8210150397
- O Advisory Committee on Reactor Safeguards reports & correspondence
- 8207180085 Forwards comments on probabilistic risk assessment study in response to 820518 request Lack of completeness noted in consideration of initiating events Total of 3 man-days expended in review

 DAVIS.P R. Affiliation Unknown DAVIS.P R ACR8 Advisory Committee on Reactor Safeguards 82/09/05 OKRENT.D ACR8 Advisory Committee on Reactor Safeguards 5pp 15852 038 24X Fische 50-352.82/09/05.8207180085
- Q Inspection reports, IE Bulletins & correspondence
- B210040224 Forwards "Limerick Oenerating Station Unit 1 Preservice Insp Program Plan for Nuclear Piping Sys." Vols 1 & 2, in response to NRC 810706 supplemental request for add info KEMPER. J 8 Philadelphia Electric Co 82/09/24 SCHWENCER. A Licensing Branch 2 3pp. 15591 331 24X Ficher 50-352.82/09/24. 8210040224
- 9210210069 Forwards IE Insp Repts 50-352/82-12 & 50-353/82-09 on B20908-10 No noncompliance noted.

 MARTIN T T Division of Engineering & Technical Programs 82/10/05 KEMPER. J B. Philadelphia Electric Co 2pp 15765 334. 24X Fiche 50-352, 82/10/05. 8210210069.
- --B2102100B2 IE Insp Repts 50-352/82-12 & 50-353/82-09 on 820908-10 No noncompliance noted Major areas inspected foundation & backfill matts supporting & proximate to safety-related structures

 VARELALA A , DURR, J P Division of Engineering & Technical Programs. 82/09/26 Spp 15765-336 24X Fichs.50-352.82/10/05,8210210069.
- 8208170233 IE Info Notice 80-35, Suppl 1, "Leaking & Dislodged I-125 Implant Beads," Syc list encl.
 CD89.L I. Division of Fuel Facilities, Materials & Bafeguards 82/10/06, Consolidated Edison Co of New York 66pp. 15761 250, 24X Fiche. 50-000, 82/10/06, 8208190233
- 8210290208 Forwards IE Insp Repts 50-352/82-11 & 50-353/82-08 on 820816-0917 No noncompliance noted STAROSTECKI,R. Division of Project & Resident Programs, 82/10/08 KEMPER,J B Philadelphia Electric Co 2pp. 15853 275 24X Fiche.50-352,82/10/08,8210290208.
- --BR10290210 IE Insp Repts 50-352/82-11 & 50-353/82-08 on 620816-0917 No noncomplience noted Major areas inspected:electrical cable pulling housekeeping:welding k small-bors pipe supports CHAUDHARY.8, K., MCCABE.E. C Division of Project & Resident Programs 82/10/16. 2pp. 15853:277 24X Fichs.50-352,82/10/08,8210290208.

- 8208190238 IE Bulletin 82-03. "Stress Corrosion Cracking in Thick-Wall, Large-Diameter-Stainless Stoel, Recirculation Sys Piping at BWR Plants " Svc list enc! DEYGUNG.R C Director's Office, Office of Inspection and Enforcement 82/10/14 Consolidated Edison Co of New York 115pp 15810 125 24X Fichs 50-000.82/10/14.8208190238
- T Hearing transcripts on non-antitrust matters
- 8210060234 Transcript of 821004 hearing in Norristown.PA Pp 738-961 Supporting documentation entl * Atomic Safety and Literaring Board Panel 82/10/04 299pp 15621 226 24X Fiche 90-332,82/10/04.8210060234
- 8210070097 Transcript of 821005 hearing in Norristown, PA Pp 962-1, 274 Supporting documentation enci * Atomic Safety and Licensing Doard Panel 82/10/05 360pp 15629 354 24% Fiche 50-352, 82/10/05, 8210070097
- 8210080050 Transcript of 821006 hearing in Norristown, PA Pp 1,275-1,531 Supporting documentation encl * Atomic Safety and Licensing Board Panel 82/10/06 349pp 15643 297 24X Fiche 50-352.82/10/06.8210080050
- 8210120183 Transcript of 821007 hearing in Norristown.PA Pp 1.532-1.728 * Abomic Safety and Licensing Board Pane? 82/10/07 179pp 15655 215 24X Fiche 50-352.82/10/07.8210120183
- 8210130239 Transcript of 821008 QL hearing in Norristown.PA Pp 1.729-2.025 Supporting documentation enci * Atomic Safety and Licensing Doard Panel 82/10/08 323pp 15674 162 24% Fiche 50-352.82/10/08.8210130239
- B210200020 Transcript of B21018 hearing in Bethesda, MD Pp 2,026-2,236 Supporting documentation encl * Atomic Safety and Licensing Board Panel B2/10/18 221pp 15735-331 24% Fiche 50-352,82/10/18.8210200020
- 8210210104 Transcript of 821019 hearing in Bethesda, MD Pp 2,237-2,505 Supporting documentation encl * Atomic Safety and Licensing Board Panel 82/10/19 283pp 15766 360 24X Fiche 50-352,82/10/19.8210210104
- 8210250115 Transcript of 821021 hearing in Bethesda, MD Pp 2,738-3,077 Supporting documentation encl * Atomic Safety and Licensing Board Panel 82/10/21 374pp 15793 074 24% Fiche 50-352.82/10/21,8210250115
- 8210260130 Transcript of 821022 hearing in Bethesda, MD Pp 3,078-3,374 Supporting documentation encl * Atomic Safety and Licensing Board Panel 82/10/22 303pp 15801 046 24% Fiche 50-352,82/10/22,8210260130
- 8210270062 Transcript of 821025 hearing in Bethesda, MD Pp 3,375-3,741 Supporting documentation encl # Atomic Safety and Licensing Board Panel 82/10/25 55ipp, 18823 035 24% Fiche 50-352,82/10/25,8210270062,
- 8210280173 Transcript of 821026 hearing in Bathesda, MD, Fp 3, 742-4, 038 Bupporting documentation encl * Atomic Safety and Licensing Board Panel B2/10/26 312pp 15842 134 24X Fiche 50-352, 82/10/26, 8210280173
- DOCKET 50-354 HOPE CREEK NUCLEAR STATION, UNIT 1

 Q Inspection reports, IE Bulletins & correspondence
- 8210060318 Ack receipt of 820819 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-354/82-07 STAROSTECKI,R. Division of Project & Resident Programs. 82/09/30 MARTIN.T.J Public Service Electric & Gas Co of New Jersey. Ip 15616 026 24X Fichs 50-354,82/09/30,8210060318
- --8210060326 Responds to NRC 820722 ltr re violations noted in IE Insp Rept 50-354/82-07 Corrective actions vendor procurement quality supplier plan amended to require bend testing of Nelson studs per AWB Di. I requirements MARTIN.T J Public Bervice Electric & Cas Co of New Jersey. 82/08/19. HAYNES.R.C Region i. Office of Director. 4pp. 15416-029 24X Fiche 50-354.82/09/30.8210060318
- 8210210091 Forwards IE Insp Rept 50-354/82-10 on 820830-0903, No noncompliance noted.

 MARTIN, T. T. Division of Engineering & Technical Programs. 82/10/05 MARTIN, T. J. Public Service Electric & Ques Co. of New Jersey. 2pp 18765-321, 24X Fiche: 50-354,82/10/05,8210210091

- --8210210097 IE Insp Rept 50-354/92-10 on 820830-0903 No noncompliance noted Major areas inspected electrical & instrumentation review of design procedures & licensee sys to implement & control field design changes
 FINKELIA E , BETTENHAUSEN.L Division of Engineering & Technical Programs 82/09/23 App 15765 323 24X Fiche 50-354,82/10/05,6210210091
- B20B190233 IE Info Notice 80-35, Suppl 1, "Leaking & Disladged I-125 Implant Seeds " Syc list enc! COBB.L I Division of Fuel Facilities, Materials & Safeguards 82/10/06 Consolidated Edison Co of New York 66pp 15761 250 24X Fiche 50-000,82/10/06.8208190233
- 8210210109 Forwards IE Insp Rept 50-354/82-11 on 820908-10 & notice of violation
 MARTIN.T T Division of Engineering & Technical Programs 82/10/06
 MARTIN.T J Public Service Electric & Gas Co of New Jersey 2pp 15766 034 24% Fiche 50-354.82/10/06.8210210109
- --8210210117 Notice of violation from insp on 820908-10 * Region 1, Office of Director 82/10/06 1p 15766 036 24X Fiche 50~354,82/10/06,8210210109
- --8210210125 IE Insp Rept 50-354/82-11 on 820908-10 Noncompliance noted failure to follow procedure re reactor pressure vesse1 internal cleanliness during const ORAY.E H Region 1. Office of Director B2/10/04 App 13766 037 24X Fishe 50-354, 82/10/06, 8210210109
- 9208190238 IE Bulletin 82-03, "Stress Corrosion Cracking in Thick-Wall, Large-Diameter: Stainless Steel, Recirculation Sys Piping at BHR Plants " Svc list encl DEYDUND, R C Director's Office, Office of Inspection and Enforcement 82/10/14 Consolidated Edison Co of New York 115pp 15810 125 24X Fiche 50-000, 82/10/14.8208190238
- DOCKET 50-355 MOPE CREEK NUCLEAR STATION, UNIT 2

 G Inspection reports, IE Bullstins & correspondence
- 8208190233 IE Info Notice 80-35, Suppl i, "Leaking & Dislodged 1-125 Implant Seeds " Svc list encl COBB.L i Division of Fuel Facilities, Materials & Safeguards 82/10/06 Constitated Edison Co of New York 66pp 15761 250 24% Fiche 50-000,82/10/06.8208190233
- 6208190238 IE Bulletin 82-03, "Stress Corrosion Cracking in Thick-Wall.Large-Diameter.Stainless Steel, Recirculation Sys
 Piping at BNR Plants " Svc list encl
 DEYOUND, R C Director's Office. Diffice of Inspection and
 Enforcement 62/10/14 Consolidated Edition Co of New York
 115pp 15810 125 24% Fiche 50-000, 82/10/14.8208190238
- DOCKET 50-358 HILLIAM H ZIMMER NUCLEAR STATION, UNIT 1

 A Application/construction stage documents & correspondence
 - 344 Forwards request for addl info re seismic loading used in analysis of scram discharge vol piping BLOOD, B J Licensing Branch 1 82/07/23, BOROMANN, E. A. nnati Gas & Electric Co 3pp 15691 098 24X
 - 32 Amend 139 to application for OL, consisting of Revision B7 to ubmittal includes response to NRC 82070B & 22 ltrs remargins of Mark I & II containment sys & piping ion criteria, respectively
 NN.E A Cincinnati Gas & Electric Co B2/09/30 DENTON, H
 of Nuclear Reactor Regulation, Director 2pp 15609, 295, the SO-358, 82/09/30, 8210050332
 - 74 Forwards info addressing implementation of interim actions ntrol of heavy loads discussed in NUREQ-0612 All mactions will be completed prior to fuel loading at ty ...B R Cincinnati Oas & Electric Co. 82/10/07 DENTON, H of Nuclear Reactor Regulation, Director ip. 15678:310, 24X 50-338, 82/10/07:0210130274
 - 0297 Tech Specs 3 9 7 & 4 9 7 re crane travel spent fuel storage incinnati Gas & Electric Co 81/06/06 4pp 15678.311 24X e 50-358.82/10/07,8210130294
 - IB7 Forwards Centificate of 8vc for Amend 139 to application for e in form of Revision 87 to FSAR
 INN.E A Cincinnati Cas & Electric Co 82/10/09 DENTON, H, R
 of Nuclear Reactor Regulation, Director 2pp 15704, 056
 che 50-358, 82/10/08, 8210150387

- 8210180154 Forwards supplemental info to 820407 ltr re setalic qualification of equipment Info consists of rept. "Seismic Qualification Rept on ITE Series 5600 Metor Control Ctr "

 SYLVIA, 8 R Cincinnati Qas & Electric Co 82/10/13 DENTON, H R
 Office of Nuclear Reactor Regulation, Director ip 157;8 184
 Fiche 50-358, 82/10/13, 8210180154
- --8210180163 "Beismic Quelification Rept on ITE Beries 5600 Motor Cons Ctr." Revision 1 + Structural Dynamics Research Corp 11410 R01 82/10/07. 272pp 15718 185 24X Fiche 50-358, 82/10/13, 8210180154
- B210290330 Requests, within 20 days of receipt notarized list of all relevant documentation & repts prepared for 820708-09 meetings re welfer qualifications

 KEPPLER. J O Repion 3. Office of Director 82/10/27 BORGHARD. E A Cincinnati Cas & Electric Co 2pp 15853 051 24X Fiche. 50-358. 82/10/27. 8210290330
- E NRC Safety Evaluation Report (SER), suppls & correspondence
- 8210260498 Forwards revised rept "Selsmic-Stress Analysis of Horlackt Pumps," in response to SER Item 3 10 re specific concerns w/reactor bidg closed cooling water pumps (BDP2) BORGMANN.E A Cincinnati Cas & Electric Co 82/10/21 DENICH, M F Office of Nuclear Reactor Regulation, Director 1p 15806 324. 2 Fiche 50-358, 82/10/21, 8210260488
- --8210260493 "Seismic-Stress Analysis of Horizontal Pumps P MCDONALD, C K McDonald Engineering Analysis Co HE-884 82/08/30 9ipp 15806 325 24X Fiche 50-358,82/10/21,821026048
- G Adjudicatory correspondence
- 8210070402 Brief in support of revised exceptions to ASLD 820621 initial decision Certificate of Byc encl
 CONNER.T B Cincinnati Oas & Electric Co CONNER.T B Conner 4
 Wetterhahn 82/10/04 Atomic Safety and Licensing Appeal Panel
 57pp 13633 250 24X Fiche 50~358,82/10/04,8210070402
- 8210150449 Motion for leave to file reply brief to applicant & NRC responses to Miami Power Project 820820 petition to reconsider & vacate 820730 order directing ASLB to dismiss Project eight proposed contentions.

 BERNABELL Miami Valley Power Project BERNABELL Queernment Accountability Project 82/10/11 Commissioners ip 15703 [P 24x Fichs 50-338,82/10/11,B210150449
- --8210150437 Reply to applicant & NRC responses to Mizmi Valley Power
 Project 820820 petition to reconsider & vacate 820730 order
 directing ASLB to dismiss Project slight proposed
 contentions Cartificate of Svc enci
 DEVINE, T , BERNABELL , Mizmi Valley Power Project DEVINE, T
 Government Accountability Project 82/10/11 Commissioners
 40pp 15703 i65 24X Fichs 50-358,82/10/11,8210150449
- 8210210391 Forwards suppl to Miami Valley Power Project 820820 petiti; to suspend facility const DEVINE.T Miami Valley Power Project DEVINE.T Government Accountability Project 82/10/18 PALLADINO.N., OILINSKY.V., AHEARNE.J F. Commissioners 1p 15764 049 24X Fisher 50-358, 82/10/18, 8210210391
- --8210210400 Suppl to Miami Valley Power Project 820820 petition to suspend facility const. including add bases for immediate suspension of const & requested remedy Certificate of Size encl DEVINE, T. Hiami Valley Power Project DEVINE, T. Qovernment Accountability Project 82/10/18, Commissioners 30pp 13764 050, 24X Fiche, 50-358, 82/10/18, 8210210391
- 8210270277 Motion to strike Miami Valley Power Project 821011 Felly brief supplementing petition for reconsideration of Commission 820730 order & reply to NRC & util responses No permission given to file brief. Certificate of Byr encl WETTERHAMN, M. J. Cincinnati Cas & Electric Co. HETTERHAMN, M. J. Conner & Wetterhahn 82/10/26. Commissioners App. 15633 096 24X Fichs 50-358,82/10/26,8210270297

H General correspondence

8209270242 Forwards TH Applegate 1tr to NJ Palladino per telcon request. KEPPLER.J O Region 3. Office of Director 82/09/24 Hitkly,p Shaw. Pittman. Potts & Troubridge. 1p. 14974 165 24X Fiche 50-358.82/09/24.82092/0424

19

- 620927027; Comments on alleged NRC attempt to cover up teriousness of problems at facility Subj will be brought to attention of Congress & Administration of APPLEGATE.T W Affiliation Unknown 82/09/24 PALLADINO.N J Commissionners ip 14994 166 24X Fiche 50-358,82/09/24.
- 219050423 Add1 response to FOIA request for tape recordings of F Olt; 810223 & Obd4 interviews & any other recordings re Zimmer investigation Forwards three tapes of Govt Accountability Project 810226 meeting & R Daker 810303 interview M/o encis fELFON. J M Division of Rules and Records 82/09/29 HICKEY, J P Shaw, Pittman, Potts & Troubridge ip 15636 253 24x Fiche 50-358, 82/09/29,8210060423

Utility Final Sofety Analysis Report (FSAR) & amends

- 210090332 Amend 139 to application for OL. consisting of Revision 87 to FSAR Bubmittal includes response to NRC 820708 & 22 ltrs refestion margins of Mark I & II containment sys & piping libration criterial respectively UDROMANULE A. Cincinnati Oas & Electric Co. 82/09/30 DENTON.H Diffice of Nuclear Reactor Regulation. Director 2pp 15609 295 244 Fiche 50-386,82/09/30,82100500332
- CIOI503B7 Forwards Certificate of Svc for Amend 139 to application for literse in form of Rovision 87 to FSAR SORGHANN, E A Cincinnati Gas & Electric Co 82/10/08 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 15704 056 24% Fiche 50-358,82/10/08,8210150387
- 1 Inspection reports, IE Bulletins & correspondence
- 62(0080015 Add) response to FOIA request for 19 categories of info re nuclear reactor events & safety problems Forwards documents listed in App A Documents in App B completely withheld (ref FOIA Exemption 5)
 FELTON-J H Division of Rules and Records 82/07/12 UDELL,R A Critical Mass Energy Project 9pp 15645 027 24X
 Fiche 50~000.82/07/12.8210080015
- --8210080170 Systematic assessment of licensee performance notes re facility evaluation for Oct 1979-Bept 1980 4 NRC - No Detailed Affiliation Given 80/09/30 9pp 15668 107 24X Firhe 50-000,82/07/12,8210080015
- 8210080166 Forwards IE Insp Rept 50-358/82-14 on 820831 & 0901-02 & 07 No noncompliance noted PAFERIELLO,C J Division of Emergency Preparedness & Operational Support 82/09/22 BOROMANN,E A Cincinnati Gas & Electric Co 2pp 15640 144 24X Fiche 90-358,82/09/22,8210080166
- --B2100B0171 IE Insp Rept 50-35B/82-14 on 820B31 & 0901-02 & 07 No noncompliance noted Major areas inspected preoperational graviton monitoring & protection, and controls & internal audics & program implementation & results GESTHANN-M J . ROZAK.S . SCHUMACHER.M Region 3, Office of Director 82/09/21 Bpp 15640 146 24X Fiche 50-358,82/09/22,82100B0166
- G208170233 IE Info Notice 80-35, Suppl 1, "Leaking & Dislodged 1-125 Implant Seeds " Svc list enci CGBB.t. 1 Division of Fuel Facilities, Materials & Safeguards 62/10/06 Consolidated Edison Co of New York 66pp 15761
- 620B19023B IE Bulletin 82-03, "Btress Corrosion Cracking in Thick-Wall. Large-Diameter. Stainless Steel. Recirculation Sys Piping at BMR Plants " Svc list encl DEYGUNG.R C Director's Office, Office of Inspection and Enforcement 82/10/14. Consolidated Edison Co of New York \$15pp 19810 125 24% Fiche 50-000.82/10/14.8208190238
- 6210190635 Advises of 821019 enforcement conference meeting in Cincinnati OH to discuss recent insp findings.per 621012 telcom w/util KEPPLER. J O Region 3, Office of Director. 62/10/15 BORGMANN, E A Cincinnati Oas & Electric Co lp 15740 053 24X Fiche 50-358, 82/10/15, 8210190635
- B210290278 Ack receipt of B20723 & 0B24 ltrs informing NRC of addl steps taken to correct violations noted in NRC 820621 ltr & IE Insp Rept 50-358/81-27 NORELUUS, C E Division of Engineering & Technical Programs. B2/10/26 BDROMANN.E A Cincinnati Oas & Electric Co 3pp 15854 249 24% Fiche 50-358,82/10/26,8210290278

- --8210290281 Supplements \$20824 response to violations noted in IE Insp. Rept \$0-358/81-27 Twelve of 34 pipe lugs in process of penetrant exam Twenty-two remaining welds due penetrant inspected BORGMANN, E. A. Cincinnati Gas & Electric Co. 82/07/30 KEPPLER.J G. Region 3. Office of Director ip 15854 252 24X Fiche 50-358,82/10/26.8210290278
- --8210290285 Amends response to 820723 ltr per 820621 review & comments in initial 820223 response Sampling program for RHR sys inadequate BOROMANNIE A Cincimnati Qas & Electric Co 82/08/24 KEPPLER.J Q Region 3. Office of Director 4pp 15854 253 24x Fiche 50-358,82/10/26,8210290278
- --8210290290 Responds to 820602 ltr re review & comments per 820223 interim ltr concerning adequacy of shop & field welds Full compliance will be achieved by 821001 & will resolve mutual concerns for Items 1.2 & 6 of IE Insp Rept 50-358/81-27 BBRGMANN.E A Cincinnati Oas & Electric Co 82/07/23 NURELIUS.C E Division of Engineering & Technical Programs 5pp 15854 237 24X Fiche 50-358,82/10/26,8210290278
- 8210290330 Requests within 20 days of receipt notarized list of all relevant documentation & repts prepared for 820708-09 meetings re welder qualifications KEPPLER, J G Region 3. Office of Director 82/10/27 BORGMANN, E A Cincinnati Oas & Electric Co 2pp 15853 O51 24X Fiche 50-358,82/10/27,8210290330
- 8 Reportable occurrences, LERs & related correspondence
- B210050137 Interim deficiency rept re nonconforming Kerotest packless diaphregm seal valves Valves appear to be open per indication of handwheel position, but are actually closed Resolution undetermined final rept expected by 821115
 BORCHANN,E A Cincinnati Gas & Electric Co 82/09/20 KEPPLER, J G Region 3, Office of Director 2pp 15605 050 24X
 Fiche 50-358, B2/09/20, B210050137
- 821006027i Interim deficiency rept re Item M-33 fittings w/high-stress stamp Util performing documentation reviews & field walkdowns to identify field installed fittings which may be stamped improperly Next rept will be submitted 83013i BDROMANN.E A Clincinnati Gas & Electric Co 82/09/22 XEPPLER, J Q Region 3, Office of Director 29p 15621 083 24X Fiche 50-358,82/09/22.8210060271
- 8210130372 Interim deficiency rept re possible carbon steel in stainless welds Analysis of weld by Metcut. Inc scheduled to be completed 821008 Results will be provided to NRC by 821115
 80R0MANN.E A Cincinnati Que & Electric Co 82/09/22 KEPPLER, J G Region 3, Office of Director 2pp 15681 167 24X Fiche 50-358, 82/09/22, 8210130372
- 8210060358 Interim deficiency rept re Item M-46 on turning vane failures in HVAC sys Extension of 2 wks until 821014 requested to complete further analysis required for scheduled interim rept BORGMANN.E A Cincinnati Qas & Electric Co 82/09/30 KEPPLER, J G Region 3, Office of Director ip 15618 353 24X Fiche 50-358,82/09/30,8210060358
- 82:0150443 Interim deficiency rest re diesel generator control logic Initially reported on 820909 Preliminary engineering evaluation concludes that sequence can be corrected by tripping diesel generator w/ESF actuation signal BOROMANN,E A Cincinnati Gas & Electric Co 82/09/30 KEPPLER,J G Region 3. Office of Director 3pp 15703 153 24x Fiche 50-358,82/09/30,8210150443
- 8210060309 Deficiency rept re Item E-27 concerning improperly incorporated DDC Item determined not reportable per 10CFR50 55(a) BDRGMANN,E A Cincinnati Gas & Electric Co 82/10/01 KEPPLER,J Q Region 3, Office of Director 1p 15619 194 24X Fiche 50-358,82/10/01.8210060309
- 8210190627 PNO-III-82-111 on 821011.util issued stop work order for all assential work activities performed by Catalytic, Inc. involving structural steel & welding rework IE may meeting w/util planned during wk of 821018 to discuss insp findings SCHWEIBINZ.E , HUNTER:D . WARNICKR. Region J. Office of Director 82/10/13 1p 15740 033 24X Fiche 50-358.82/10/13,8210190627
- 8210260279 Interim deficiency rept re turning vane failures in HVAC sys Three addit failures discovered since 820702 Failures believed to be fatigue induced Failed vanes repaired Testing to continue Next rept by 830115
 BOROMANN.E.A Cincinnati Gas & Electric Co 82/10/13 KEPPLER, J O Region 5, Office of Director 2pp 15803 220 24X
 Fiche 50-358,82/10/13,8210260279

DOCKET 50-361 SAN ONOFRE NUCLEAR STATION, UNIT 2

- A Application/construction stage documents & correspondence
- 8210290063 Forwards "Evaluation & Action Plan for San Onofre Nuclear Oenerating Station Units 2 & 3 re IMI Incident " DRAKE, J H Southern California Edison Co 79/08/16 DENTON.H R Office of Nuclear Reactor Regulation, Director 2pp 15859 052 24/ Fiche 50-361, 79/08/16, 8210290063
- --8210290069 "Evaluation & Action Flan for San Onofre Nuclear Generating Station Units 2 & 3 re TMI Incident " + Southern California Editon Co 79/08/31 48pp 15859 054 24X Fiche 50-361.79/08/16.8210290063
- 8210010008 Responds to FOIA request for 19 categories of documents re nuclear reactor events & safety problems Forwards documents isted in App A FELTON, J M Division of Rules and Records 82/ Critical Mass Energy Project 15pp 18727 005 Fiche 50-000, 82/06/28, 8210010008 82/06/28 UDFLE R A
- cracking in reactor vassel notiles
 NOONAN,V S Assistant Director for Materials & Qualifications
 Engineering 80/05/05 TEDESCOR L Assistant Director for
 Licensing 2pp 15727 176 24% Fiche 30-000.82/06/28.8210010008
- F Security, medical, emergency & fire protection plans
- 8210190625 Forwards Revision 7 to physical security plan Revision withheld (ref 10CFR73 21)

 BASKIN.K.P. Southern Callifornia Edition Co. 82/10/15 EISENHUT.D.G.

 @ffice of Nuclear Reactor Regulation. Director 1p 15740 035

 24X Fiche 50-206.82/10/15.8210190625
- G Adjudicatory correspondence
- 62:0040009 Notifies that LJ Chandler will represent NRC at oral argument per ASLAB 820908 order SW Perry of FEMA will be CHANDLER.L J Hearing Branch 2 82/09/24 8afety and Licensing Appeal Panel 1p 15 Fiche 50-361.82/09/24.8210040007 SHEEMAKER C J Atomic 1p 15581 315
- 8210050267 Memorandum & order setting medical arrangements question for hearing Listed questions should be answered by all parties, providing expert testimony where required Issue of terminating procedures will be certified to Commission KELLEY, J.L. Atomic Safety and Licensing Board Panel 82/10/01 Bpp 15611 155 24X Fiche 50-361.82/10/01.8210050267
- 82:0060:84 Memorandum & order certifying question to Commission of feasibility of ASLB continuing proceeding initiated by ABLB KELLEY, J L KELLEY, J.L. Atomic Safety and Licensing Board Panel 82/10 Commissioners 4pp 15613 181 24% Fiche 50-361,82/10/05, 82/10/05 8210060184

- 8210180075 Brief re medical svcs issues certified by Commission order No advance planning required by 10CFR50 47(b)/(2) for medical svcs for general public Necessary arrangements can be made on ad hoc basis Certificate of Svc encl CHANDLER, L J Hearing Branch 2 82/10/14 Commissioners 28pp 15719 270 24X Fichs 50-361/82/10/14.8210180095
- 8210220240 Response supporting util 821008 objections to ASLB 621001 prohearing nemprandum & order re medical arrangements
 Scheduling of any hearing should await guidance from
 Commission, resolving certified issues W/Certificate of Svc
 CHANDLER, L. J. Hearing Branch 2 82/10/20 Atomic Safety and
 Licensing Board Panel 7pp 15775 131 24X Fiche 50-761,82/10/20,8210220240
- P Operating license stage documents & correspondence
- 8210010212 Forwards Amend 8 to License NPF-10, safety evaluation & notice of issuance & availability Amend changes date for operability of post-accident sampling sys to Jan 1983 & revises associated Tech Specs (per TMI Action Item [] 3) EISENHUT.D 0 Division of Licensing 82/09/17 DIETCH.R Bouthers California Edison Co COTTON.C D. BERNATH.L San Diego Oss & Electric Co 4pp 15567 320 24X Fichs 50-361,82/09/17,0210010212
- ~~8210010215 Amend 8 to License NPF-10, changing date for operability of post-accident sampling sys to Jan 1983 & revising associated Tech Specs (per Tril Action Item II 8 3) EISEMAUT, D @ Division of Licensing 82/09/17 5pp 1556/ 124 24X Fichs 50~361.82/09/17.8210010212
- --8210010222 Safety evaluation supporting Amend 8 to License NPF-10 * Office of Nuclear Reactor Regulation, Director 82/09/17 15547 329 24X Fichs 50-361.82/09/17.8210010212
- -- 8210010229 Notice of issuence & availability of Amend B to License KERRIGAN, J Licensing Branch 3 82/09/17 2pp 1554,/ .}32 241 Fiche 50-361,82/09/17.8210010212
- 8210210498 Confirms 820908 telephone authorization of Tech Spec changes as requested by 820907 & OB itrs re reactor coolant flow-low contained in Table 2 2-1 NOVAK. T M Assistant Director for Licensing 82/09/27 DIFT(H Southern California Edison Co COTTON, C D. DERNAHIL Ban Die Gas & Electric Co 3pp 15772 350 24X Fiche 50-161.82/09/2/. 82/09/27 DIFTCH R
- 8210040117 Proposed Change NPF-10-46 to Tech Spec 3 3 4 re turbine crouselity Proposed Change MP-10-96 to Tech Spec 3 3 4 Fe turbine overspeed protection Change will allow entry into Modes 3 & 2 while preventing possibility of turbine overspeed by requiring MSIVs & bypasses to be closed SASKIN. K.P. Southern California Edison Co. 82/09/30 MERRICAN. J.D. Licensing Branch 3 ip 15614 334 24X Fiche 50-361.02/09/30. B210060112
- --8210060119 Proposed Change NPF-10-46 to Tech Spec 3 3 4 allowing entra anto Modes 3 & 2 while preventing possibility of turbing oversaged Sauthern California Edison Co 92/09/30 to 18844-335 24r Fiche 50-361, 82/09/30, 8210060117
- 8210070164 Forwards evaluation of Unit 2 license conditions relative to potential applicability to Unit 3 license conditions in response to NRC request BASKIN.K P Southern California Edison Co 82/10/04 KIRRIGAN.J p Licensing Branch 3 App 15627 009 24X Fiche 50-361.82/10/04.8210070164
- 82100&03&8 Outlines augmented shift manning requirements for period of initial criticality of Unit 3, for 1-month period after initial attainment of 100% power on Unit 2 & to control rotation of operators between units, per 820920 meeting DIETCH/R Southern California Edison Co 82/10/05 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 13619 053 24X Fiche 50-361,82/10/05,8210060368
- 8210070082 Discusses use of radwaste solidification sys Unit 2 license condition does not prevent util from using Chem-Nuclear Sys, Inc process to solidify wet solid radwaste produced at Unit i Safety evaluation will be performed

 BASKIN.K P Southern California Edison Co 82/10/05
 CRUTCHFIELD, D Operating Reactors Branch 5 2pp 15628, 162 24t

 Fiche 50-206, 82/10/05, 8210070082
- B210130571 Forwards Amend ? to License NPF-10, safety evaluation & notice of issuance & availability, Amend changes Tach Specs to allow operation in Modes & & S w/turbine overspeed protection sys inoperable
 KERRIOAN.J Licensing Branch 3 82/10/07, DIETCH.R Southern
 California Edison Co COTTON.G D. BERNATH.L Ban Diego Gas L
 Electric Go 3pp 15679 090 24X Fiche 50-361.82/10/07,821013057

- --8210130573 Amend 9 to License NPF-10, changing Tech Specs to allow operation in Modes 2 & 9 w/turbine overspeed protection
 - Sys inoperable

 FERRIGAN: J Licensing Branch 3 82/10/07 4pp 15679 093 24X

 Fiche 50-361 82/10/07/8210130571
- --8210130577 Safety evaluation supporting Amend 9 to License NPF-10 * Office of Nuclear Reactor Regulation, Director 82/10/07 2pp 15679 097 24X Fiche \$0-361.82/10/07.8210130571
- --B210130582 Notice of issuance & availability of Amend 9 to License
 - Nº9F-10 NERGES:V Licensing Branch 3 82/10/07 5pp 15679 099 24X Fiche 50~361 82/10/07.8210130571
- \$210190560 Forwards corrected page to rept re small earthquake swarm which occurred on 811110 Revised info does not alter conclusions stated in rept DAS/III & P Southern California Edison Co 82/10/15 KERRIGAN, J D Licensing Branch 3 2pp 15736 137 24% Fiche 50-361,82/10/15, 6210190560
- 6210190534 Notifies that info gained during Unit 2 natural circulation test program will be incorporated into overall Unit 2 & 3 operating training program, per NOREO-0737, Item 1 & 1 Listed tests will not be repeated for Unit 3 SASKIN.F P Southern California Edison Co 82/10/18 KERRIGAN.J D Licensing Branch 3 2pp 15751 314 24X Fiche 50-361,82/10/18,8210190534
- 6210260416 Forwards Application 13 to amend License NPF-10, revising App A Tech Specs to change response time for ECCB miniflow valves

 DIETCH. R Southern California Edison Co 82/10/21 DENTON. H R

 Ofrice of Nuclear Reactor Regulation. Director 2pp 15806 294
 24X Fiche 50-361.82/10/21, 8210260416
- --8210260424 Application 13 to amend License NPF-10, revising App A Tech Specs to change response time for ECCS miniflow valves DIETCHLR Southern California Edison Co 82/10/21 10pp 15805 296 24X Fiche 50-361,82/10/21,8210260416
- -- El 210260435 Proposed Tech Specs 6 8 2,6 8 3,6 8 4,6 11,4 12 % 6 13 re administrative controls for revision in response time for ECCS miniflow valves

 4 Southern California Edison Co 82/10/21 6pp 15806 306 24X Fiche 50-361.82/10/21 8210260416
- O Inspection reports, IE Bulletins & correspondence
- 6216010042 Confirms 821021 mgt meeting in Rosemead, CA to discuss systematic assessment of licensee performance Anticipated meeting attendees & agenda encl CREMS, J. Division of Resident, Reactor Project & Engineering Programs 82/09/27 PAPAV.L T Southern California Edison Co Gpp 15565 317 24% Fiche 50-206.82/09/27,8210010042
- 8210190478 Forwards IE Insp Repts 50-361/82-27 & 50-362/82-19 on 820905-17 No noncompliance noted BISHOP. T W Division of Resident, Reactor Project & Engineering Programs 82/10/05 PAPAY.L T Bouthern California Edison Co

- 820B190238 IE Bulletin 82-03. "Stress Corrosion Cracking in Thick-Hall, Large-Diameter, Stainless Stool, Recirculation Sys Piping at BMR Plants, "Svc list encl DEYDUNO, R C Director's Office, Office of Inspection and Enforcement 82/10/14 Consolidated Edison Co of New York 115pp 15810 125 24X Fiche 50-000, 82/10/14.8209190238
- 8210250222 Ack receipt of 820929 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-361/82-25 & 50-362/82-16
 BISHOP.T W Division of Resident, Reactor Project & Engineering Programs 82/10/18 PAPAY,L T Southern California Edison Co I 15789 326 24% Fithe 50-361,82/10/18,8210250222
- --3210250227 Responds to NRC 820831 ltr re violations noted in IE Insp Repts 50-361/82-25 & 50-362/82-16 Corrective actions Operating Instruction 5023-2-4 revised on 820831 to include proper caution PAPAY.L T Southern California Edison Co 82/09/29 EMBELKEN.R H Region 5, Office of Director 4pp 15789 327 24x Fiche 50-361,82/10/18,8210250222
- S Reportable occurrences. LERs & related correspondence
- 82:0050151 Forwards LER 82-080/03L-O Detailed event analysis submitted RAY, H B Southern California Edison Co 82/09/22 ENGELKEN.R H Region 5, Office of Director 2pp 15609 053 24X Ficha 50-361, 82/09/22,82/0050151
- --8210050234 LER 82-080/03L-0 on B20823, during Made 4 feeder breaker testing after returning breaker 2A0101 to svc. feeder breaker 2A0104 failed to open Cause unidentified Event considered isolated No further attion deemed necessary RAY.H B Southern California Edison Co 82/09/22 Region 5. Office of Director ip 15409 055 24X Fiche 50-341,82/09/22,8210050151
- 8210050261 Forwards LER 82-076/03L-0 Detailed event analysis submitted RAY, H 9 Southern California Edison Co 82/07/23 ENGELKEN, R H Region 5, Office of Director 2pp 15609 176 24X Fiche 50-361, 82/09/23, 8210050261
- --8210050266 LER 82-096/03L-0 on 920825.ECCS subsystem high pressure safety injection pump 2P-017 failed to develop 1.400-psia discharge pressure during operability test Caused by excessive leakage past miniflow bypase valve 82-1204-MU-184 RAY.H B Southern California Edison Co 82/09/23 Region 5.0ffice of Director 1p 15609 198 24X Fiche 50-361,82/09/23.8210050261
- 82:0050381 Forwards LER 82-103/03L-0 Detailed event analysis submitted RAY.H B Southern California Edison Co 82/09/23 ENGELKEN.R H Region 5. Office of Director 2pp 15608 251, 24X Fiche 50-361, 82/07/23.8210050381
- ---8210050370 LER 82-103/03L-0 on 820825, but leg sample isolation valve 2HV-0517 breater 2BJ-23 tripped on overload in attempt to close valve during semiannual ESF subgroup relay test Caused by burned out operator motor Motor replaced RAY, H B Southern California Edison Co. 82/07/23 Region 5, Office of Director is 15608 253 24X Fiche 50-361, 82/07/23, 8210050381,
- 82:005000B Forwards LER 82-098/03L-0 Detailed event analysis submitted RAY.H B Southern California Edison Co 82/09/24 ENGELKEN.R H Region 5: Office of Director. 2pp 15605 205 24X Fiche 50-361.82/09/24.821005000B

- --8210050024 LER 82-097/03L-0 on 820825, condensate storage tank T-121 water level fell below Tech Spec limit Caused by inadequate makeup water control to tank & too restrictive Tech Spec limit Tech Spec change & automatic level control proposed RAY, H B Southern California Edison Co 82/09/24 Region 5, Office of Director ip 15604 345 24X Fiche 50-361,82/09/24, 8210050016
- --8210050029 LER 82-102/03L-O on 820829.condensate storage tank T-121 water level fell below Tech Spec limit Caused by imadequate makeup water control to tank & too restrictive Tech Spec limit Tech Spec change & automatic level control proposed RAY. H B Gouthern Celifornia Edison Co 82/09/24 Region 5. Office of Director ip 15604 346 24X Fiche 50-361,82/09/24. 8210050016
- -8210050032 LER 82-104/03L-0 on 820901, contensate storage tank T-121 water level fell below Tech Spec limit Caused by inadequate mateup water control to tank & too restrictive Tech Spec limit Tech Spec change & automatic level control proposed RAY. H B Southern California Edison Co B2/09/24 Region 5, Office of Director 1p 15604 347 24X Fiche 50-361,82/09/24, 221050014
- --B210050037 LER 82-106/03L-O on 820903, condensate storage tank T-121 water level fell below Tech Spec limit Caused by inadequate maker water control to tank & too restrictive Tech Spec limit Tech Spec change & automatic level control proposed RAY.H B Bouthern California Edison Co B2/09/24 Region 5, Office of Director ip 15604 348 24X Fiche 50-361,82/09/24, 8210050016
- --821005004i LER 82-108/03L-O on 820930, condensate storage tank T-12i water level fell below Tech Spec limit Caused by inadequate maker part control to tank & too restrictive Tech Spec limit Tech Spec change & automatic level control proposed RAY.H B Southern California Edison Co 82/09/24 Region 5, Office of Director 1p 15604 349 24X Fiche 50-361,82/09/24, 223080014
- --9210050044 LER 62-107/03L-0 on 82070A, condensate storage bank T-121 water level fell below Tech Spec limit Caused by inadequate makeup water control to tank & too restrictive Tech Spec limit Tech Spec change & automatic level control proposed RAY, H II Southern California Edison Co 82/09/24 Region 5, Office of Director ip 13604 350 24X Fiche 50-361,82/09/24,8210050016
- --8210090048 LER 82-110/03L-0 on 820912, condensate storage tank T-121 water level fell below Tech Spec limit Caused by inadequate makeup water control to tank & too restrictive Tech Spec limit Tech Spec change & automatic level control proposed RAY.H B Bouthern California Edison Co 82/09/24 Region 5, 0ffice of Director lp 15404 351 24X Fiche 50-361, 82/09/24, 8210050016

- --B210130274 LER B2-099/01T-0 on B20913. Train A control room emerging air cleanup sys failed to start after receiving spurious toxic gas isolation signal caused by improper positioning of kirk key on breaker 280418 of fan E418

 RAY.H B Southern California Edison Ca 82/09/27 Region 5. Office of Director ip 15678 354 247 Fiche 50-361.82/09/27. B210130269
- B210130278 Forwards LER 82-076/03L-1 Detailed event analysis submitted RAY, H B Southern California Edison Co B2/09/30 ENGELKEN, R H Region 5, Office of Director 2pp 15678 t6/ 24x
- --B210130285 LER 82-076/03L-1 on 820725, steam generator indicator 2PDI-0979-1 failed channel check test & was placed in types to condition prior to Mode 2 entry Caused by Inadvertently valved out indicator RAY.H B Southern California Edison Co 82/09/30 Reg 2 010 5. 0ffice of Director 1p 15678 169 24X Fiche 50 361,82/09/30,8201030278
- B210130497 Forwards LER B2-105/03L-0 Detailed event analysis submitted RAY, H B Southern California Edison Co B2/09/30 CNGFLML884 H H Region 5, Office of Director 2pp 15683 097 24x Fich 50-361 82/09/30, B210130499
- --B21013050B LER 82-105/03L-0 on B20831, during Mode 2 operation. aviiling feedwater pump 2P-504 declared inoperable Caused by leady threaded plug on pump discharge casing Threads cleaned, graffoll applied & plug reinstalled RAY, M B Southern California Edison Co 82/09/30 Region 5. Office of Director ip 15683 099 24% Fichs 50-161, 82/09/30, 8210130499
- 82:0130469 Forwards LERs 82-107/03L-0.82-119/03L-0.82-121/03L-0
 Detailed event analysis submitted
 RAY.H B Southern California Edison Co 82/10/03 [NQF] M6 Ft. R R
 Region 5. Office of Director 2pp 15682 155 24X
 Fiche 50-361.82/10/01,8210130469
- --8210130478 LER 82-107/03L-0 on 820902, condensate storage tank T-120 water level fell below Teth Spec limit while in Hode 2 Caused by inadequate makeup water control Corrective actions include better planning & Limbly water transfer RAY. H B Southern California Eduson Co 82/10/01 Region 5. Office of Director ip 15682 157 24X Fiche 50-1161, 122/10/01. 8210130449
- ---8210130485 LER 82-117/03L-0 on 820719, condensate storage tank [-120 water level fell below Tech Spec limit while in Node 2 Caused by inadequate makeup water control Corrective actions include better planning & timely water transfer RAY. H B Bouthern California Edison Co 82/10/01 Region 3. Office of Director ip 15682 158 24X Fiche 50-361, [LZ/10/0], R20130449
- --8210130493 LER B2-121/03L-0 on B20920, condensate storage tank 1-120 water level fell below Tech Spec limit while in Mode 2 Caused by inadequate makeup water control Corrective actions include better planning & timely water transfer RAY. H B Bouthern California Edison Co 82/10/01 Region 5. Office of Director ip 15682 157 24X Fiche 50-361. 12/1 C/01. 8210130467
- 8210190309 Forwards LERs 82-116/03L-0,82-117/03L-0 & 82-112/03L_0
 Detailed event analysis enc1
 RAYH B Southern California Edison Cp 82/10/08 ENGELMEN.R | Region 9, Office of Director 2pp 15742 | 150 24%
 Ficher 50-361,82/10/08,8210190309
- --8210190317 LER 82-116/03L-0 on 820917.condensate storage tank I-120 water level fell below Tech Spec limit Caused by inadequate makeup water control to tank T-121 & overly restrictive Tech Spec Limit Design & Tech Spec change groposed RAY.H B Southern California Edison Co. 82/10/00 Region 5. 02/10/00 Region 0309
- ~-B210190323 LER 82-117/03L-0 on 820918, condensate storage tamb 7-10 water level fell below Tech Spec limit Caused by inadequate makeup water control to tank T-121 & overly restrictive Tech Spec limit Design & Tech Spec change proposed RAY.H B Southern California Edison Co 82/10/08 Region 5 0ffice of Director 1p 15742'153 24X Fiche 50-361.827/10/8.
- ~-B210190328 LER B2-112/03L-0 on 820910, condensate storage tame 1-10 water level fell below Tech Spec limit Caused by inadequate makeup water control to tank T-121 % overly restrictive Tech Spec Limit Design & Tech Spec

- G210190250 PMO-V-B2-041 on B21006. Los Angeles Times investigative reporter contacted Region 5 re former Bechtel Power Corp GC inspector addit allegations concerning weiding practices Investigation of allegations planned MIRSCH, D F. BISHOP. T W. Region 5, Office of Director B2/10/14 Ip 15742 195 24X Fiche 50-361. B2/10/14. B210190250
- 8210250137 Forwards LER 82-11B/03L-0 Detailed event analysis submitted RAY, H B Southern California Edison Co 82/10/15 ENGELKEN, R H Region 5. Office of Director 2pp 157B7 002 24X Fische 50-361, 82/10/15, 8210250137
- --B210250140 LER 82-118/03L-0 on 820917, low nitrogen actuator pressure discovered in steam generator feedwater isolation valve 2HV-4052 Caused by leakage at plug to check valve located on accumulator Temporary instrument valve installed RAY.H B Southern California Edison Co B2/10/15 Region 5. Office of Director ip 15787 004 24X Fiche 50-361.82/10/15. G210250137
- 8210250207 Notifies that followup repts to LERs 82-094 & 82-103 will be provided by 821130 Delay due to add1 evaluation needed for corrective action RAY, H B Southern California Edison Co 82/10/15 ENGELKEN, R H Region 5, Office of Director ip 15787 362 24% Fich \$ 50-361,82/10/15,8210250207
- ©210259214 Forwards LER 82-115/03L-0 Detailed event analysis submitted RAY,H B Southern Celifornia Edison Co 82/10/15 ENGELKEN,R H Region 5. Office of Director 2pp 15768 289 24% Fiche 50-361.62/10/15.8210250214
- --0210250218 LER 82-115/O3L-D on 020916, during Mode 2 operation, control etement assembly 47 slipped & dropped in excess of 7 inches Caused by defective timing card Affected solid state chip replaced RAV.H B Sauthern California Edison Co 82/10/15 Region 5, Office of Director ip 1578B 291 24X Fiche 50-361,82/10/15,8210250214
- 6210250269 Forwards LER 82-113/03L-0 Detailed event analysis submitted RAN,H B Southern California Edison Co B2/10/15 ENGELKEN,R H Region 5. Office of Director 2pp 1579: 042 24X Fiche 50-341,82/10/15.8210250269
- --9210250273 LER 62-113/03L-0 on 820916, routine operator insp during gaseous waste processing revealed interstage rupture disc of waste gas compressor CO10 breached Caused by excess buildup of interstage pressure within compressor Disc replaced RAY, H 8 Southern California Edison Co 82/10/15 Region 5, Office of Director 1p 15791 044 24X Fiche 50-361, 82/10/15, 8210250269
- 8210280080 Forwards LER 82-114/01T-0 Detailed event analysis submitted RAV.H B Southern California Edison Co 82/10/19 ENGELKEN.R H Region 5, Office of Director 2pp 15837 168 24X Fiche 50-361.82/10/19.8210280080
- --9210280086 LER 82-114/01T-0 on 821017, during surveillance testing in Mode Accontainment cooling fan 2E-402 failed to start Caused by faulty fan breaker Breaker replaced RAY. H B Southern California Edison Co 82/10/19 Region 5, Office of Director 1p 15837 170 24X Fichs 50-361,82/10/19,8210280080
- T Hearing transcripts on non-antitrust matters
- B210130209 Transcript of 821006 oral argument in Ban Diego, CA Pp 1-144 ** Atomic Safety and Licensing Appeal Panel 82/10/06 145pp 15673 126 24X Fiche 50-361.82/10/06.8210130209
- V Operator Examinations
- 8210210184 Summary of 820914 & 20 meetings w/util re util 820802 request that NRC warve required written & gral tests & grant Unit 3 reactor operator & senior reactor operator licenses to currently licensed Unit 2 operators RODO, H Licensing Branch 3 82/10/01 Licensing Branch 3 6pp 15772 353 24X Fiche 50-361,82/10/01,8210210184
- DOCKET 50-362 SAN ONOFRE NUCLEAR STATION, UNIT 3
- A Application/construction stage documents & correspondence
- B210290063 Forwards "Evaluation & Action Plan for San Onofra Nuclear Gamerating Station Units 2 & 3 re TMI Incident " DRAKE,J H Southern California Edison Co 79/08/16 DENTON,H R Gifice of Nuclear Reactor Regulation, Director 2pp 15859-052 24X Fiche 50-361.79/08/16.8210290063

- --8210270069 "Evaluation & Action Plan for San Unofre Nuclear Generating Station Units 2 & 3 re TMI Incident "
 * Southern California Edison Co 79/08/31 48pp 15859 094 24X Fiche 50-361.79/08/16.8210290063
- 8210010008 Responds to FOIA request for 19 categories of documents re nuclear reactor events 5 safety problems Forwards documents listed in App A FELTON.J M Division of Rules and Records 82/06/28 UDELL.R A Critical Mass Energy Project 15pp 15727 005 24X Fiche 50-000.82/06/28.8210010008
- --8008050265 Discusses addl required info to better define potential for cracking in reactor vessel noirles
 NODNAN V B Assistant Director for Materials & Gualifications
 Engineering 80/05/05 TEDESCO.R L Assistant Director for Licensing 2pp 13727 176 24X Fiche 50-000,82/06/28.8210010008
- 8210050492 Discusses plan of action for issuance of DL Operator licensing & Tech Spec preparation could impact 821015 fuel load date Lists areas needing review to determine whether license conditions are required NOVAK,T M Assistant Director for Licensing 82/09/17 EISCHUIT.D @ Division of Licensing 2pp 15626 302 24X Fiche 50-362, 82/09/17.8210050492
- 8210180258 Notification of 820920 meeting w/util in Betheeda.MD to discuss operator staffing & licensing ROOD.H Licensing Branch 3 82/09/17 MERRIGAN.J Licensing Branch 3 4pp 15746 321 24X Fichs 50-362.82/09/17,8210180258
- 8210070164 Forwards evaluation of Unit 2 license conditions relative to potential applicability to Unit 3 license conditions in response to NRC request BABKIN F Southern California Edison Co 82/10/04 KERRIGAN.J Licensing Branch 3 4pp 15627 009 24X Fiche 50-361.82/10/04, 2010/2014
- 8210060368 Outlines augmented shift manning requirements for period of initial criticality of Unit 3.for 1-month period after initial attainment of 100% power on Unit 2 & to control rotation of operators between units, per 920720 moeting DIETCH.R Southern California Edison Co 92/10/05 DENTON. H R Office of Nuclear Reactor Regulation, Director 2pp 15619 053 24% Fiche 50-361,82/10/05.8210060368
- 8210190560 Forwards corrected page to rept re small earthquake swarm which occurred on 811110 Revised info does not alter conclusions stated in rept BAGKIN.X P Southern California Edison Co 82/10/15 KERRIGAN.J [Licensing Branch 3 2pp 15736 137 24X Fiche 50-361.82/10/15, 8210190560
- 8210190534 Notifies that info gained during Unit 2 natural circulation test program will be incorporated into overall Unit 2 & 3 operating training program.per NUREO-0737. Item 1 0 i Listed tests will not be repeated for Unit 3

 BABKIN.K P Bouthern California Edison Co 82/10/18 KERRIGAN.J D Licensing Branch 3 2pp 15751 314 24X Fiche 50-361.82/10/18.8210190534
- F Security, medical, emergency & fire protection plans
- 8210190625 Forwards Revision 7 to physical security plan Revision withheld (ref 10CFR73 21)
 868KIN,K P Bouthern California Edison Co 82/10/15 EIP
 Dffice of Nuclear Reactor Regulation, Director 1p 157
 24X Fiche. 50-206, 82/10/15, 8210190625
- G Adjudicatory correspondence
- B210040009 Notifies that LJ Chandler will represent NRC at or argument.per ABLAB B2090B order SW Perry of FEMA will be available CHANDLER.L J Hearing Branch 2 82/09/24 BHDEMAKER.C J Bafety and Licensing Appeal Panel 1p 15581 318 24X Fiche: 50-361, 82/09/24. 8210040009
- 8210050267 Memorandum & order setting medical arrangements questions should be answered by all parties, providing expert testimony where required Issue of termineting procedures will be certified to Commission KELLEY, J. L. Atomic Bafety and Licensing Board Panel 82/18pp 15611 155 24% Fiche 50-361.82/10/01.8210050267
- 8210040184 Memorandum & order certifying question to Commissifessibility of ASLB continuing proceeding initiated by ASLI 821001 order
 KELLEY, J. L. Atomic Sefety and Licensing Board Panel. 82/1 Commissioners. 4pp 13613 181. 24X Fiche 30-361,82/10/0:8210040184

- 8210130309 Objections to ASLB 821001 memorandum & order re medical arrangements Order proposes hearing on issues beyond scope of Commission emergency planning regulations & requires evidence beyond NUREG-0654 stds Declaration of Svc encl PIGOTT.D R Southern California Edison Co PIGOTT.D R Orrick, Herrington & Subcliffe 82/10/08 Atomic Safety and Licensing Board Panel 11pp 15678 170 24% Fiche 50-361, 82/10/08, 8210130309
- 8210150454 Position on ASLB request for Commission direction on whether to proceed to hearings Further hearings on medical sycs issue should be deferred pending Commission determination & issuance of guidance Declaration of Syc enc. PIGOTT, D.R. Bouthern California Edison Co. PIGOTT, D.R. Girick, Herrington & Sutcliffe 82/10/13 10pp 15703 112 24X Fiche 50~361, 82/10/13, 8210150454
- 8210150482 Brief re certified questions on definition L implementation of 10CFR50 47(b)(12) re medical sycs Applicant interprets 10CFR50 47(b)(12) as applying to individuals who are contaminated & traumatically injured. W/Declaration of Syc PICOTT. D R Sauthern California Edison Ca PICOTT. D R Orrick. Herrington & Sutcliffe 82/10/13 20pp 15703 008 24X Fichs 50-341.82/10/13,8210150482
- 8210150490 Brief re required medical svcs for general public in response to Commission Order CLI-82-27 Agrees w/ASLB re definition of contaminated injured individuals per 10CFR50 47(b) (12) Certificate of Svc encl MCCLUNG.C E GUARD MCCLUNG.C E Gallagher. P M MCCLUNG.C E Flemning. Anderson. McClung.C E Flemning. Anderson. McClung.C E 102/10/13 34pp 15713 110 24X Fiche 50-361.82/10/13.8210150490
- 8210180095 Brief re medical sycs issues certified by Commission order No advance planning required by 100FR50 47(b)(12) for medical sycs for general public Necessary arrangements can be made on ad hoc basis Certificate of Byc encl CHANDLER, L J Hearing Branch 2 82/10/14 Commissioners 24pp 15719 270 24X Fiche 50-361,82/10/14,8210180095
- 8210220240 Response supporting util 821008 objections to ASLR 821001 prehearing memorandum & order re medical arrangements 8cheduling of any hearing should await guidance from Commission, resolving centified issues W/Certificate of 8vc CHANDLER, L. J. Hearing Branch 2 82/10/20. Atomic Safety and Licensing Board Panel 7pp 15775 13t 24X Fichs 50-261,82/10/20, 82/10/20240
- Q Inspection reports, IE Bulletins & correspondence
- 8210060109 Forwards IE Insp Rept 50-362/82-17 on 820823-0903 No noncompliance noted BISHOP. T W Region 5, Office of Director 82/09/16 PAPAY, L T Southern California Edison Co 2pp. 15614 336 24X Fiche 50-362, 82/09/16, 8210060109
- ~-8210060124 IE Insp Rept 50-362/82-17 on 820823-0903 No noncompliance noted Major areas inspected operational staffing & staff training; comparison of as-built plant to FBAR description, test program records safety committee & test results SIEWART, J P Region 5. Office of Director KIRSCH.D F Division of Resident, Reactor Project & Engineering Programs 82/09/16 Spp 15614 338 24K Fithe 50-362,82/09/16,8210060109
- 8210010267 Forwards list of open items that require resolution before finding of readiness for operation may be endorsed by Region 5 per Insp Procedure 94300B Licensee established 821115 as fuel load data.
 ENGELEGISE H Region 5. Office of Director 82/09/24 TAYLOR, J M, Division of Resident, Reactor Project & Engineering Programs. 7pp 15573 114 24X Fiche 50-362,82/09/24.8210010267
- 8210010042 Confirms 821021 mgt meeting in Rosemead.CA to discuss systematic assessment of licensee performance Anticipated meeting attendees & agenda entl. CREMBIJ L Division of Resident, Seactor Project & Engineering Programs 82/09/27 PAPAY.L T. Southern California Edison Co. 3pp 15565:317 24X Fiche:50-206.82/09/27.8240010042
- 8210190478 Forwards IE Insp Repts 50-361/82-27 & 50-362/82-19 on 820905-17 No noncompliance noted BISHOP.T W Division of Resident, Reactor Project & Engineering Programs 82/10/05 PAPAYLLT Southern California Edison Co 4pp 15740:245. 24x Fiche 50-361.82/10/05.8210190478
- --8210190501 IE Insp Repts 50-361/82-27 & 50-362/82-19 on 820905-17. No noncompliance noted Major areas inspected TMI action plan requirements. Unit 2 Low power level testing data review & precritical testing data review KIRSGH.D F , MENDONCA.M. Division of Resident. Reactor Project & Engineering Programs. 82/10/05. 14pp 15740:249 24X Fiche: 50-361,82/10/05,8210190478

- 8208190233 IE Info Notice 80-35, Suppl 1, "Leaking & Dislodged I-125 Implant Speds " Svc list encl COBB.L I Division of Fuel Facilities, Materials & Safegvards 82/10/06 Consolidated Edison Co of New York 66pp 15761 25 24x Fiche 50-000.82/10/06.8208190233
- 8210250173 Forwards IE Insp Rept 50-362/82-20 on 820913-17 No noncompliance noted 800K.H E Division of Rediological Safety & Safeguards Program 82/10/08 PAPAY.L T Southern California Edison Co 2pp 15787 134 24% Fiche 50-362.82/10/08.8210250173
- --8210250178 IE Insp Rept 50-362/82-20 on 820913-17 No noncompliance npted Hajor areas inspected preoperational radiation protection program, McARA, environ monitoring program, solid, liquid & gaseous radwaste mgt & status of NUREG-0737 items CILLIS,M, WEMSLAWSKI,FA, BOOK,HE Division of Radiological Safety & Safeguards Program 82/10/08 16pp 15787 136 24x Fiche 50-362,82/10/08 8210250173
- 8208190238 IE Bulletin 82-03, "Stress Corrosion Cracking in Thick-Wall, Large-Diameter, Stainless Steel, Recirculation Bys Piping at BUR Plants " Svc list encl DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/10/14 Consolidated Edison Co of New York 119pp 15810 125 24X Fiche 50-000, 82/10/14,8208190238
- B210250222 Ack receipt of 820929 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-261/82-25 & 50-362/82-16
 BISHOP.T W Division of Resident, Reactor Project & Engineering Programs B2/10/18 PAPAY.L T Southern California Edison Cn: 15789 326 24X Fiche 50-361.82/10/18.8210250222
- --8210250227 Responds to NRC 820831 ltr re violations noted in It Im Repts 50-361/82-25 & 50-362/82-16 Corrective actions Operating Instruction 5023-2-4 revised on 820831 to include proper caution PAPAY-LT Southern California Edison Co 82/09/29 EAGELKEN.R H Region 5, Office of Director 4pp 15789 327 ; Fiche 50-361, 82/10/18, 8210850222
- 8 Reportable occurrences, LERs & related correspondence
- B210190250 PNO-V-G2-041 on B21006. Los Angeles Times investigative reporter contacted Region 5 re former Bechtel Power Corp GC inspector addl allegations concerning welding practices Investigation of allegations planned KIRSCH. D F , BISHOP. T N Region 5, Office of Director B2/10/14 p 15742 195 24X Fiche 50-361, B2/10/14, B210190250
- T Hearing transcripts on non-antitrust matters
- 8210130209 Transcript of 821006 oral argument in San Diego.CA Pp I-lA * Atomic Safety and Licensing Appeal Panel 82/10/06 145pp 15673 126 24X Fiche 50-361,82/10/06,8210130209
- V Operator Examinations
- 8210210184 Summary of 820914 & 20 meetings w/util re util 820802 request that NRC waive required writton & oral tests & grant Unit 3 reactor operator & senior reactor operator licenses to currently licensed Unit 2 operators RODD: H Licensing Branch 3 82/10/01 Licensing Branch 3 6pp 15772 353 24X Fiche 50-361,82/10/01,8210210184
- DOCKET 50-363 FORKED RIVER NUCLEAR STATION. UNIT 1

 A Application/construction stage documents & correspondence
- 8210070102 Forwards info resolving 14 Tech Spec open items discussed at 820713 meeting Marked-up Tech Specs encl BABKIN, K P Southern California Edison Co B2/10/04, KERRIGAN, J 1 Licensing Branch 3 36pp 15649 244 24X Fiche 50~363,82/10/04. B210070102
- DOCKET 50-364 JOSEPH M FARLEY NUCLEAR PLANT, UNIT 2

 A Application/construction stage documents & correspondence
- 8210010008 Responds to FOIA request for 19 categories of documents re nuclear reactor events & safety problems Forwards documents listed in App A FELTON.J M Division of Rules and Records. 82/06/28 UDELL.R A. Critical Mass Energy Project 13pp 18727 005 24X Fiche: 50-000, 82/06/28,8210010008

- --8008050265 Discusses addl required info to better define potential for cracking in reactor vessel notiles
 NOUNAR, V S Assistant Director for Materials & Qualifications
 Engineering 60/05/05 TEDESCO.R L Assistant Director for
 Licensing 2pp 15727 176 24X Fiche 50-000.82/06/28,8210010008
- F Security, medical, emergency & fire protection plans
- S210010196 Ack receipt of 820827 ltr re emergency exercise scheduled for Feb 1983 STONR.J Division of Emergency Preparedness & Operational Support 82/07/17 Mt.DONALD R P Alabama Power Co 1p 15570 360 24X Fiche 50-348, 82/09/17, 8210010194
- B210010195 Folwards Revisions 4 / 5 to security plan Revisions withheld CLAYTON:F L Alabama Power Co 82/09/21 VARGA:S A NRC No Detailed Affiliation Given ip 15567 313 24X Fiche 50-348:082/09/21.8210010195
- 8250190066 Releases public version of revised emergency plan implementing procedures FELTON, J H Division of Rules and Records 82/10/01 Document Management Branch ip 15761 060 24X Fiche 50-348.82/10/01, 18210190066
- --B210190073 Public version of emergency plan implementing procedures, including Procedures FNP-0-EIP-11 re handling of injured personnel & FNP-0-EIP-10 re site area emergency Procedure request forms encl
 4 Alabama Power Cu 82/09/21 35pp 15761 061 24X
 Fiche 50-340, 82/10/01.8210190066
- 6210180004 Forwards IC Safeguards Insp. Repts 50-348/82-23 & 50-364/82-22 on 820921-24 No noncompliance moted VERRELLI, D. Division of Project & Resident Programs 82/10/12 MCDDMALD.R P. Alabama Power Co. 2pp. 15720-025 24X Fiche 50-348, 92/10/12.8210180004
- --B210180007 IC Bafeguards Insp Repts 50-348/82-23 & 50-344/82-22 on G20921-24 No noncompliance noted Major areas inspected security plan & implementing procedures & security organization Details withheld (ref 10CFR73 21) STANSBERRY, W W Division of Engineering & Technical Programs 92/10/08 1p 15720 027 24X Fiche 50-348,82/10/12,8210180004
- ©210280158 Application for amend to Licenses NPF-2 & NPF-8, revising Tech Specs to require audit on emergency preparadness program every 12 months, per 100FR50 54(t) & Generic Ltr 02-17 No amend fee required SER encl CLAYTON.F L Alabama Power Co 82/10/25 VARGA.S A Office of Nuclear Reactor Regulation, Director 2pp 15837 174 24X Fiche 50-348, 62/10/25, 6210280158
- ---8210230165 Proposed Tech Specs, Soction 6 5 2 8 requiring audit of emergency preparedness every 12 months, per 10CFR50 54(t) & Generic Ltr 82-17

 4 Alabama Power Co 82/10/25 3pp 15837 176 24X fishe 50-348,82/10/25.8210280158
- M Antitrust correspondence
- B210060179 Notifies of Debevoise & Plimpton change of address as of B21001 Affirmation of Byc enc!

 * Debevoise & Plimpton B2/10/01 3pp 19614 10B 24X Fishe 30-348.82/10/01.8210060179
- P Operating license stage documents & correspondence
- B210010227 Confirms B20820 telcon arrangements re B20930 meeting w/util in Region 2 ofc to discuss fuel rod degradation resulting from baffle water-jet impingement Proposed agends enci O'REILLY, J P Region 2, Office of Director B2/09/03 MCDONALD, R P Alabama Power Co 2pp 15567 336 24X Fiche 50-348, B2/09/03, 8210010827
- 6210040038 Forwards Amend 17 to License NPF-B, safety evaluation & notice of issuance & availability Amend extends for one-time only-visual surveillance interval for inaccessible hydraulic snubbers until 821022 refusing outage REEVES.E A Operating Reactors Branch 1 82/09/22 CLAYTON.F L Alabama Power Co 2pp 15577 264 24X Fiche 50-364,82/09/22. 8210040038
- ---8210040039 Amend 17 to License NPF-B, extending for one-time only.

 visual surveillance interval for inaccessible hydraulic
 snubbers until next refueling outage scheduled to begin
 821022

 VAROA. B A Operating Reactors Branch 1 82/09/22 App
 15577 266 24K Fiche 30-324, 82/09/22, 8210040038

- --8210040040 Safety evaluation supporting Amend 17 to License NPF-8 * Office of Nuclear Reactor Regulation. Director B2/09/22 3pp 15577 270 24X Fiche 50-364.82/09/22.8210040038
- ~-8210040041 Notice of issuance & availability of Amend 17 to License NPF-8 VARGA.S A Operating Reactors Branch 1 82/09/22 2pp 15577 273 24X Fiche 50-364,82/09/22,8210040038
- 8210050066 Commits to functional testing of circuit breakers, completing outstanding issue re 820726 request for extension of License Condition 2 C (19)(b)
 CLAYTON,F L Alabama Power Co 82/09/27 VARGA,B A Office of Nuclear Reactor Regulation, Director 2pp 15603 227 24X
 Fiche 50-364, 82/09/27, 8210050066
- B210050089 Informs that installation of water tight fittings on Victoreen radiation detectors per TMI Action Item II F i will be delayed until next refueling outage, contingent upon receipt of mati
 CLAYTON.F L. Alabama Power Co. B2/09/30 VARQA.S A. Office of Nuclear Reactor Regulation, Director 3pp. 15604 241 24X
 Fiche 50-364.82/09/30.8210050089
- 8210130527 Forwards proprietary & nonproprietary versions of "Evaluation of Impact of Reduced Testing of Turbine Valves," WCAP-10161 & WCAP-10162, respectively Proprietary version withheld (ref 100FR2 790) CLAYTON, F.L. Alabama Power Co. 82/10/08 VAROA, S.A. Office of Nuclear Reactar Regulation, Director Spp. 15683 006 24X Fiche 50-364,82/10/08,8210130527
- --8210130535 Nonproprietary version of "Evaluation of Impact of Reduced Testing of Turbine Valves"

 RAHE, E P Hestinghouse Electric Corp WCAP-10142 82/09/30

 77pp 15483 011 24X Fiche 50-364,82/10/08,8210130527
- 8210150338 Application for one-time change to Tech Spec 3/4 4 7 2. modifying leak test acceptance criteria Change necessary to preclude potential for delay in return to power from refueling outage CLAYTON.F L. Alabama Power Co. 82/10/11 VARGA.S A. Office of Nuclear Reactor Regulation, Director 5pp 15705 344 24X Fiche 50-364.82/10/11.8210150338
- --8210150344 Proposed Tech Spec Pages 3/4 4-17 & 3/4 4-19 re RCS operational leakage & RCS pressure isolation valves Safety evaluation encl
 4 Alabama Power Co 82/10/11 App 15705 351 24X Fiche 50-364,82/10/11,8210150338
- 8210250090 Application to amend License NPF-8, deleting license conditions redundant to generic regulatory items Change does not involve unreviewed safety question Safety evaluation encl
 CLAYION.F L Alabama Power Co 82/10/19 VAROA, S A Office of Nuclear Reactor Regulation, Director 8pp 15787 101 24X Fiche 50-364, 82/10/19, 8210250090
- 8210260418 Advises that util confident that current emergency procedure provides adequate guidance for cooldown under natural circulation conditions Full compliance w/License Conditions 2 C (9)(b) & 2 C (12)(c) demonstrated CLAYTON.F L Alabama Power Co 82/10/21, VARGA, B A Office of Nuclear Resolutor Regulation, Director. 2pp 15806 315 24X Fiche 50-364,82/10/21,8210260418
- B210260437 Bubmits final documentation of full compliance w/License Condition 2 C (12)(b) re safety-grade means for RC9 depressurization per Technical Position RBB 5-1, Revision 1 CLAYTUN, FL Alabama Power Cd B2/10/21 VARGAS A Office of Nuclear Reactor Regulation, Director 2pp 15806 244 24% Fichs 50-364, 82/10/21, 8210260437
- B210280282 Advises that revised Westinghouse performance Code PAD-3 3 as described in WCAP-8270. Addendum 1, adequately defines fuel burnup for successive fuel cycles CLAYION.F L Alabama Fouer Co 82/10/22 VAROA, S A NRC No Detailed Affiliation Oliven 1p 15837 043. 24X Fiche 50-364, 82/10/22, 8210280282
- 8210280159 Application for amend to Licenses NPF-2 & NPF-8, revising Tech Specs to require audit on emergency preparedness program every 12 months, per 10CFR50 54(t), & Generic Ltr 82-17 No amend fee required SER encl CLAYTON, FL Alabama Power Co 82/10/25 VAROA, B. A. Office of Nuclear Reactor Regulation, Director 2pp 15837 194 24X Fiche, 50-348, 82/10/25, 8210280158

- --8210280165 Proposed Tech Specs, Section 6 5 2 8 requiring audit of emergency preparedness every 12 months, per 10CFR50 54(t) & Generic Ltr 82-17

 Alabama Power Co 82/10/25 3pp 15837 196 24X

 Fiche 50-348,82/10/25,8210280158
- O Inspection reports: IE Bulletins & correspondence
- 8210070007 Responds to FOIA request for eight categories of records restann generators & steam turbines App A documents provided in R Udell FOIA Request 81-313 Forwards documents listed in App B

FELTON, J M Division of Rules and Records 82/08/10 LONG, D J Winthrop, Btimson, Putham & Roberts 9pp 15645 063 24X Fiche 50-000, 82/08/10, 8210070007

- --B210070139 Forwards tabulated data on steam generator insp & maint at facilities Data should be provided to licensees IPPOLITO.T Operating Reactors Assessment Branch B2/04/01 VAROA.8 Operating Reactors Branch 1 3pp 15645 131 24X Fiche 50-000, B2/08/10. B210070007.
- 8210010204 Forwards IE Insp Repts 50-348/82-21 & 50-364/82-20 on 820802-06 No noncompliance noted DANCE, H C Region 2. Office of Director 82/08/30 HCDONALD, R P Alabama Power Co 2pp 15567 314 24X Fiche 50-348, 82/08/30, 8210010204
- --821001020B IE Insp Repts 50-348/82-21 & 50-364/82-20 on 820802-06 No noncompliance noted Major areas inspected pipe supports & restraints & Types B & C containment leak rate testing BROOKSE. JAPEF, Division of Engineering & Technical Programs 82/08/85 4pp 15567 316 24% Fiche 50-348, 82/08/30, 8210010204
- 8210010043 Concurs w/actions outlined in util 920812 ltr re insparequired by IE Bulletin 79-13.except in areas of re-radiographing steam generator Feedwater nozile-to-pipe & weld retention of records
 LEMIS.R C Division of Project & Resident Programs 82/09/13 MCDONALD.R F Alabama Power Co 2pp 15570 361 24X
 Fiche 50-348.82/09/13.8210010043
- 62101\$0072 Ack receipt of B20909 itr informing NRC of steps taken to correct violations noted in IE Insp. Repts 50-348/82-17 & 50-348/82-18 DANCE.H C Bivision of Project & Resident Programs 82/10/04 MCDDNALD.R P Alabama Power Co ip 15701 253 24X Fichs 50-348.82/10/04,8210150072
- ~~8210190074 Responds to NRC 820818 itr re violations noted in IE Insp Repts 50-3648/82-19 & 50-364/82-18 Corrective actions Form NRC-3 posted at low level radwaste bidg CLAYTON,F L Alabama Power Co 82/09/09 DANCE.H C Region 2. Office of Director 2pp 15701 254 24X Fiche 50-348,82/10/04, 8210150072
- ~~8210150078 Forwards lE Insp Repts 50-348/82-19 & 30-364/82-18 on 82072a-30 & notice of violation DANCE-H C Division of Project & Resident Programs 82/08/18 HCDONALD.R P. Alabama Power Co 2pp 15701 256 24% Fiche 50-348.82/10/04.8210150072
- --8210190082 Notice of violation from insp on 820724-30 **Bivision of Project & Resident Programs 82/08/18 tp 15701.258 24x Fiche 50-248.82/10/04.8210150072
- --8210150086 IE Insp Repts 50-348/82-19 & 50-364/82-18 un 820726-30 Noncompliance noted Form NRC-3. "Notice to Employees," not posted in new low level waste storage facility FEERY, W.W.. BARR. K.P. Division of Engineering & Technical Programs 82/08/16 5pp 15701 259 24X Fiche 50-348,82/10/04,8210150072
- 8210220229 Forwards IE Insp Repts 50-348/82-22 & 50-364/82-21 on 820816-0915 No noncompliance noted, DANCE-H C Division of Project & Resident Programs 82/10/04 MCDDNALD-R P Alebama Power Co 2pp 15776 233 24% Fichs 50-348
- --82i0220232 IE Insp Repts 50-348/82-22 & 50-364/82-21 on 8208i6-0915 No noncompliance noted Major areas inspected; monthly surveillance & maint observation operational safety verification.plant trips & LERs BRADFORD.M. H. BROWNLEE, V.L. Division of Project & Resident Programs 82/10/04 7pp 15776 235 24X Fiche 50-348,82/10/04,8210220229,
- B208190233 IF Info Notice 80-35. Suppl 1: "Leaking & Dislodged I-125 Implant Seeds " Svc list encl. COBB.L. I Division of Fuel Facilities: Materials & Bafeguards 82/10/06 Consolidated Edison Co of New York 66pp 15761 250 24X Fiche 30-000.82/10/06.8208190233

- 8210180004 Forwards IE Sareguards Insp Repts 50-348/82-23 & 50-364/82-22 on 820921-24 No nuncompliance noted VERRELLI,D Division of Project & Resident Programs 82/10/12 MCDONALD,R P Alabama Power Co 2pp 15720 025 24X Fiche 50-348, 82/10/12, 8210180004
- --B210180007 IE Safeguards insp Repts \$0-348/82-23 % 50-364/82-22 on 820921-24 No noncompliance noted Major areas inspected security plan & implementing procedures & security organization betails withheld (ref 100FR73 21) STANSBERRY, N N . MCGUIRE, D R Division of Engineering & Technical Programs 82/10/08 lp 15720 027 24% Fiche 50-348.82/10/12, 8210180004
- 8208190238 IE Bulletin 82-03, "Stress Corresion Cracking in Thick-Wall, Large-Diameter, Stainless Steel, Recirculation Sys Piping at BUR Plants " Svc list encl DEYOUNG, R C Director's Office of Inspection and Enforcement 82/10/14 Consolidated Chison Co of New York 115pp 15810 125 24X Fiche 50-000.82/10/14.8208190238
- 8210280410 Notification of 821029 meeting w/util Franklin Research (tr. b. Bechtel in Betheda. MD to review calculations & methodology re [E. Bulletin 80-11, "Masonry Walls." REEVES. E. A. Operating Reactors Branch | 82/10/20 VARGA. S. Operating Reactors Branch | 1 2pp 15859 332 24X Fiche 50-348. 82/10/20, 8210280410
- R Persodic operating reports & related correspondence
- 8210190767 Forwards monthly operating rept for Sept 1982 CLAYTON,F L Alabama Power Co 82/10/12 Management Information Branch 1p 19734 238 24% Fiche 50-364,82/10/12,821019076*)*
- 5 Reportable occurrences, LERs & related correspondence
- 9210070111 Reviews purge valve info contained in T Austin 810306 memo Primary thehnical issue relates to valve operability during expected accident conditions Vital area of concern not addressed in info include lower torque margin for closure BROWN,E J Director's Office 81/09/24 MICHELSON,C Director's Office 4pp 15646-359 24X Fichs 50-348.81/09/24,8210070111
- 8210010008 Responds to FOIA request for 17 categories of documents re nuclear reactor events & safety problems Forwards documents listed in App A FELTON, J H Division of Rules and Records 82/06/28 UDELL, R A Critical Mass Energy Project 15pp 15727 005 24x Fiche 50-000,82/06/28,8210010008
- --8210090124 Summary of 810610 operating reactor events meeting LAINA6.0 C Assistant Director for Safaty Assessment 81/06/1/ EISENHUT, D Q Division of Licensing 5pp 15729 217 24X Fiche 50-000,82/06/28.8210010008
- 8210010129 Forwards LER: 82-037/03L-0 & 82-052/03L-0 CLAYTON: F L Alabama Power Co 82/09/27 Region 2, Office of Director 1p 18567 227 24% Fich: 50-340:82/09/27.8210010129
- ---8210010147 LER 82-037/03L-0 on 820905.A train auto trip logic for high steam generator differential pressure declared insperable when failed cord indication received by automatic testpr Caused by failure of universal card Card replaced HAKRSTON.W 0 Alabama Power Co 82/09/27 Region 2, Office of Director 1p 15967 227 24X Fiche 50-348,82/09/27.0210010129
- 8210260453 Forwards LERy 82-054/03L-0182-055/03L-0,82-039/03L-0 & 82-040/03L-0 CLAYYON:F L Alabama Power Co 82/10/18 Region 2, Office of Director 1p 15806 195 24X Fiche 50-348,82/10/18,8210260453
- ~-8210260480 LER 82-039/03L-0 on 820919, syc water to component cooling water HX 2C isolated Caused by dislodged pin holding worm drive gear allowing differential pressure across valve disc to close valve Pin reinstalled & secured HAIRSTON, H 0 Alabama Power Co 82/10/18 Region 2, Uffice of Director ip 15806 198 24X Fiche, 50-348, 82/10/18, 8210260453
- --8210260490 LER 82-040/03L-0 on 820919, loss-of-voltage protection channel associated w/82F sequencer phase 2-3 declared inoperable Caused by failure of loss-of-voltage relay 27XF1 during testing Relay cleaned HAIRSTON, H. Q. Alabama Power Co. 82/10/18 Region 2, Office of Director Ip. 15806 199 24X Fiche 50-348,82/10/18,8210260453

- 용공 10290289 Forwards LER 82-033/03L-1 CLAYTDN.F L Alabama Power Co 82/10/19 Region 2. Office of Director 1p 15894 073 24% Fiche 50-364.82/10/19.8210290289
- -- E210290792 LER 82-033/03L-1 on 820817, breaker to containment isolation valve inadvertantly opened Caused by personnel error while implementing tagging order Breakers positioned & returned to svc
 HAIRSTON, W. G. Alabama Power Co. 82/10/19 Region 2, Office of Director Ip 15854-0/4 24X Fiche 50-364, 82/10/19, 8210270289
- GOCKET 50 366 EDWIN I HATCH MUCLEAR PLANT, UNIT 2

 F Security, medical, emergency & fire protection plans
- 日之10060275 Application to amend License NPF-5, deleting App A Tech Specs on bldg settlement と withdrawing 781201,790814 と 1008 submittals re differential と total settlement values based on consolidation settlement BECKHAM. J T Georgia Power Co 82/09/27 Office of Nuclear Reactor Regulation Director 5pp 15621 172 24X Fiche 50-366, 82/09/27, 8210060275
- --8210060278 Yech Specs 3/4 7 7 re penetration fire barriers 4 Georgia Power Co 82/09/27 ip 15621 177 24X Fiche 50 366,82/07/27,8210060275
- ©210190013 Releases public version of revised emergency plan implementing procedure FELTCN, J.M. Division of Rules and Records 82/09/29 Document flanagement Branch tp 15760 328 24X Fiche 50-321.82/09/29, 82/09/29.
- --8210190016 Forwards public version of Revision 4 to Emergency Plan Implementing Procedure HNP-8026, "High Radiation Area Entrance Control" SORRELL, C. Georgia Power Co. 82/09/23 Office of Nuclear Reactor Regulation, Director 1p. 15760-329 24X Fiche 50-321, 82/09/29,8210190013
- -- 8210190017 Public version of Revision 4 to Emergency Plan Implementing Pracedule HNP-8026. "High Radiation Area Entrance Control" e Georgia Power Co. 82/09/22 12pp 15760 330 24X Fiche 50-321,82/09/29,8210190013
- © 210190042 Releases public version of pages to emergency plan FELTON, J. M. Division or Rules and Records 82/10/01 Document Management Branch 1p 15761 037 24X Fiche 50-321,82/10/01, 8210190042
- 8210170046 Forwards public version of Pages M-1 & M-2 to emergency plan
 SURREILLE C Georgia Power Co 82/09/22 Office of Nuclear Reactor Regulation. Director ip 15761 038 24X Fiche 50-321,82/10/01.8210190042
- --8210190051 Public version of Pages H-1 & H-2 to emergency plan • Georgia Power Co 82/03/31 2pp 15761 039 24X Fiche 50-321,82/10/01,8210190042
- €210080227 Forwards IE Sateguards Insp Repts 50-321/82-31 &

 50-366/82-29 on 820920-23 No noncompliance noted

 DANCE, H C Division of Project & Resident Programs 82/10/04

 KELLY, R J Georgia Power Co 2pp 15638 097 24X

 Fiche 50-321, 82/10/06, 8210060227
- ---8210080228 IE Safeguards Insp Repts 50-321/82-31 & 30-366/82-29 on 820920-23 No noncompliance noted Major areas inspected physical barriers, lighting, assessment aids, detection aids, access control & vehicles Details withheld (ref 100FR73 21) MODRED E Division of Engineering & Technical Programs 82/10/05 1p 15638 059 24X Fiche 50-321,82/10/06,8210080227
- P Operating license stage documents & correspondence
- ©210060275 Application to amend License NPF-5, deleting App A Tech Specs on bldg settlement & withdrawing 781201,790814 & 1008 submittals re differential & total settlement values based on consolidation settlement BECKHAMS JT Georgia Power Co 82/09/27 Office of Nuclean Reactor Regulation. Director 5pp 15621 172 24X Fiche 50-366, 82/09/27, 8210060275
- ---8210060278 Tech Specs 3/4 / 7 re penetration fire barriers 4 Georgia Power Co 82/09/27 lp 15621 177 24X Fiche 50-364,82/09/27.8210060275

- 8210050330 Forwards schedule for qualification testing of analog transmitter trip sys.in response to 801001 request OUCHALT Georgia Power Co 82/09/28 EISENHUT.D 0 Office of Nuclear Reactor Regulation. Director 3pp 18610 258 24X Fiche 50-321.82/09/28.8210050330
- 8210060231 Forwards remittance & copies omitted from 820927 ltr re bldg settlement BECKHANLJ V Georgia Power Co 82/10/01 Office of Nuclear Reactor Regulation, Director fp 15620 012 24X Fiche 50-366,82/10/01,8210060231
- 8210120047 Application to amend App A of License NPF-5, changing Tech Spec Figures 3 2 3-1 & 3 2 3-2 to reflect changes in operating limit min critical power ratios resulting from reanalysis of pressurization transients by GE BECKHAM, J T Georgia Power Co 82/10/04 Office of Nuclear Regulation, Director 2pp 15651 242 24X Fiche 50-366, 82/10/04,8210120047
- --8210120050 Proposed Tech Spec Figures 3 2 3-1 & 3 2 3-2, reflecting changes in operating limit min critical power ratios # Georgia Power Co 82/10/04 3pp 15651 244 24X Fiche 50-366,82/10/04,8210120047
- 8210220290 Forwards corrected Page 6-4 for B20611 Tech Spec change request re designation of unit status for shift manning requirements Original submittal inadvertently reversed GUCHALL T Georgia Power Co 82/10/15 Office of Nuclear Reactor Regulation, Director 1p 15775 049 24X Fichs 50-366,82/10/15,8210220290
- --8210220278 Corrected Page 6-4 to 820611 Tech Spec change request re designation of unit status for shift manning requirements of Georgia Power Co 82/10/15 ip 15775 050 24X Fiche 50-364,82/10/15.8210220270
- Q inspection reports. [Ε Bulletins & correspondence
- 8210010113 Forwards IE Insp Repts 50-321/82-26 & 50-366/82-25 on 820809-13 No noncompliance noted DANCE H C Division of Project & Resident Programs 82/09/07 KELLYR J Georgia Power Co 2pp 15567 206 24X Fiche 50-321,82/09/07,8210010113
- --9210010118 IE Insp Repts 50-321/82-26 & 50-366/82-25 on 820809-13 No noncompliance noted Major areas inspected lab GC program chemistry & radiochemistry procedurest airborne effluent sampling & accountability & mobile lab EVANS.C D. HONTGOMERV.D M Division of Emergency Preparedness & Operational Support 82/09/02 lipp 15567 208 24x Fiche 50-321.82/09/07.8210010813
- 8210010309 Forwards IE Insp Repts 50-321/82-28 & 50-366/82-26 on 820727-0827 No noncompliance noted DANCE.H C Division of Project & Resident Programs 82/09/10 KELLY.R J Georgia Power Co 2pp 15968 274 24X Fichs 50-321,82/09/10,8210010309
- --8210010327 IE Insp Repts 50-321/82-28 & 50-366/82-26 on 820727-0827 No noncompliance noted Major areas inspected Tech Spec compliance noted Major areas inspected Tech Spec compliance, operator performance, overall plant operations, GA practices tation & corporate mgt practices ROSERS, R F , HOLMES-RAY, P , BROWNLES, V L Division of Project & Resident Programs 82/09/10 App 15568 276 24X Fiche 50-321, 82/09/10, 8210010309
- 8210010019 Ack receipt of 820907 itr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-321/82-19 O'REILLY, J P Region 2. Office of Director 82/09/16 KELLY, R J Georgia Power Co 1p 15565 300, 24X Fiche 50-321.82/09/14, 8210010019
- --8210010022 Responds to NRC 820806 ltr re violations noted in IE Insp Repts 50-321/82-19 & 50-366/82-19 Corrective actions procedures being revised to include tighter controls on changes to fuel movement data packages BECKHAM, J T Georgia Power Co 82/09/07 G'REILLY, J P Region 2, Office of Director 3pp 15565-301 24X Fiche 50-321, 82/09/16, 82:0010019
- --8210010025 Forwards IE Insp Repts 50-321/82-19 & 50-366/82-19 on 820421-0525 & notice of violation O'REILLY, J P Region 2. Diffice of Director 82/08/06 KELLY, R J Georgia Power Co 2pp 15565 304 24X Fiche 50-321,82/09/16,8210010019

- ~~8210010031 IE Insp Repts 50-321/92~19 & 50-366/82-19 on 820421-0525 Noncompliance noted fuel loaded into core w/o all control rods fully inserted RQGERS.R F Division of Project & Resident Programs rads fully inserted
 RGGERS.R F Division of Project & Resident Programs
 BROWNLEE, V L Region 2, Office of Director 82/07/
 15555 307 24x Fiche 50-321.82/09/16.8210010019 82/07/29 7ap
- 8210040047 Ack receipt of check in payment of civil penalty proposed on 820713 Corrective measures described in 820812 & 0907 ltrs will be examined in future insp. AXELRAD. J A Director's Office, Office of Inspection and Enforcement 82/07/23 XELLY,R J Georgia Power Co 2pp 15577 270 24X Fiche 50-321,82/07/23,8210040047
- 8208190233 lE Info Notice 80-35, Suppl 1. "Leaking & Dislodged I-125 Implant Seeds "Eye list encl COBS.L | Division of Fuel Facilities. Materials & Safeguards 82/10/06 Consolidated Edison Co of New York 46pp 1574 24X Fiche 50-000, 92/10/06, 8208190233
- 8210080227 Forwards IE Safeguards Insp Repts 50-321/82-31 & 50-366/82-29 on 820920-23 No noncompliance noted DANCE: H C Division of Project & Resident Programs 82/1 KELLY: R J Georgia Power Co 20pp 15638 057 24X Fiche 50-321.82/10/06.8210080227 82/10/06
- --8210080228 IE Safequards Imag Repts 50-321/82-31 & 50-366/82-29 on 210080228 IE Safeguards Insp Repts 50-321/82-31 & 50-326/82-29 on 820920-23 No poncompliance noted Major areas inspected physical barriers, lighting, assessment aids, detection aids, access control & vehicles Details withheld (ref 100FR73 21) MOURE, D E , MCQUIRE, D R Division of Engineering & Technical Programs 82/10/05 ip 15638 059 24% Fiche 50-321,82/10/06,8210080227
- 8208190238 IE Bulletin 82-03, "Stress Corrosion Cracking in Thick-Wall, Large-Diameter, Stainless Steel, Recirculation Sys Piping at BMR Plants " Svc list enc!

 DEYQUNO, R C Director's Office Office of Inspection and En
- 8210220277 Ack receipt of 820927 ltr informing NRC of steps taken to correct violations nated in IE Insp Repts 50-321/82-24 & 50-366/82-22 30-366/47-24
 EENIS.R C Division of Project & Resident Programs
 KELLY.R J Georgia Power Co ip 15775 028 24X
 Fithe 50-321,82/10/14.8210220277 B2/10/14
- --8210220287 Responds to NRC 820823 ltr re violations noted in IE Insp. Repts S0-321/82-24 & 50-366/82-22 Corrective actions written plan will be prepared to schedule b integrate lecture series to meet addl training needs

 QUCMA.L T Georgia Pawer Co 82/09/27 O'REILLY, J.P. Region 2, Office of Director 4pp 15775 029 24X Fiche 50-321,82/10/14,6210220277
- --8210220292 Forwards 1E Insp Repts 50-321/82-24 & 50-366/82-22 on B20726-70 & notice of violation LEHTS R C Division of Project & Resident Programs KELLY.R J Georgia Fower Co 2pp (5775 033 24) Fiche 50-321, 82/10/14, 8210220277 82/08/23
- --8210220299 Notice of violation from insp on 820724-30 Division of Project & Resident Programs 62/08/23 18775 035 DAX Fire 50-301-87/10/14-821020-30

- S Reportable occurrences, LERs & related correspondence
- 6210120171 Discusses 610406 discovery that undervoltage relays of second offsite source would not operate preventing closure second offsice source would not appraise, preventing closure of all diesel generator breakers Licensee will be proposing design mod to correct problem of non-Class IE interlock CHIRAMALIN Director's Office 81/04/21 Director's Office 3pp 15.692 202 24x Fiche 50-391.81/04/21,8210120171
- 8210010098 Responds to FUIA request for 19 categories of documents re nuclear reactor events & safety problems forwards documents listed in App A LISTERS IN APP A FELTONAL M Division of Rules and Records 82/06/28 UDCLL.h A Cribical Mass Energy Project 15pp 15/27 005 24x Fiche 50-000, B2/06/28.82300100008
- --8104270103 Discusses IE daily rept for 810406 re alternate offsite source interlock w/emergency diesel generators at Unit 1 Licensee will propose mod to correct non-Class IF interlock preventing automatic operation of safety sys CHTRAMAL, M Director's Office 81/04/21 Director 3pp 15729 041 24X Fiche 50-000-82/06/28.8210010008 Director's Office
- --9210010083 Recommends ACRS action on recent LERs ie HPCI failure to auto start after MSIV failure & single cooling supply line on RHR pump motors BOEHRERY,P ACRS Advisory Committee on Reactor Safeguards 80/06/13 KERR,W ACRS Advisory Committee on Reactor Safeguards ip 15727 138 24X Fiche 50-000,82/06/28,8210010008
- --8210010089 Discusses failures of HPCI & RCIC sys subsequent to 790601 event culminating in 790627 loss of both sys BBEHNERT.P ACRS Advisory Committee on Reactor Safeguards 79709706 KERR.W ACRS Advisory Committee on Reactor Safeguards 2pp 15727 142 24X Fiche 90-000.82706728, 8210010008
- -- 8210010095 Forwards PNO-79-139 re faiture of RCIC & JIPCI sus following PROTOGOPS Forwards PROLYTY-139 Te Failure of RCIC & HPCI sys Foltowing to the Part of Sector Service of RCIC & Foltowing Service of Reactor Service Service
- -- 8210010099 Requests detailed rapt on PNO-79-139 re failure of backup RENNEDY, R Commissioners 79/06/07 ODSSICK, V Office of the Executive Director for Operations 19 1972/153 24x Fiche 50-000, 82/06/28, 8210010008
- --B210010105 Reiterates 790607 request for detailed rept re failure of backup core cooling sys per PND-79-139 & PND-79-136
 Response requested by 790703
 KENNEDY:R T Commissioners 79/07/02 GDSSICK:L V (liffice of the Executive Director for Operations 1p 15727 154 24X Fiche 50-000, 82/06/28, 8210010008
- --B210010109 Forwards response to 790607 request for info re failure of backup cooling sys Corrective measures will be followed to assure reliable state of operational readiness STELLO.V Office of Inspection & Enforcement, Office of the Director 79/07/02 KENNEDY R T Commissioners 5pp 15727 157 24X Fiche 30-000.82/06/28,8210010008
- --B210040367 Requests info ro LER 80-111/03L-O concerning isolation of HPCI sys at facility Nature of nonrepetitive event questioned HPCILER, D.W. ACRS Advisory Committee on Reactor Safeguards 80/09/16 MCCRELESS, T. ACRS Advisory Committee on Reactor Safeguards 2pp 15727 261 24X Fiche 50-000,82/06/28, 8210010008
- 8210010094 Forwards LER 82-083/03L-0 NIX.H C Deorgia Power Co 82/09/21 D'REILLY, J P Region 2, Office of Director ip 15565 256 24X Fiche 50-366,82/09/21, 8210010094
- --8210010098 LER 82-083/03L-0 on 820825, w/plant in hot shutdown, reactor ALOUADMS LEM 82-083/03L-0 on 820825, w/plant in hot shutdown, reacts bldg to suppression chamber vacuum breaker had no closed indication & declared inoperable Caused by lonse limit switch mount bracket & out of adjustment actuator TIPPS, B B Quergla Power Co 82/09/21 Region 2, Office of Director 2pp 15565 257 24% Fiche 50-366, 82/09/21, 8210010094
- 8210050080 Forwards LER 82-091/03L-0 NIX-H C Georgia Power Co 82/09/23 O'REILLY, J P Region 2, Office of Director 1p 15604 252 24X Fiche 50-366,82/09/23.

- -8210059084 LER 82-091/03L-0 on 820825, during scram recovery, H ADS safety relief valve failed to open manually & digwell pressure & temp acceeded Tech Specs Cause unknown Pressure & temp returned to allowable levels
 1PPS S B Georgia Power Co 82/09/23 Region 2, Office of Director 2pp 19604 253 24% Fiche 50-366.82/09/23.8210050000
- E210060246 Forwards LER 82-090/03L-0 NIA,H C Georgia Power Co 82/09/23 O'REILLY, J P Region 2, Orfice of Director ip 15619 317 24X Fiche 50-366,82/09/23, 8210060246
- --8210060248 LER 82-090/03L-0 on 820831.during quarterly surveillante, B oxygen analyzer failed to calibr due to instrument rjuctuation Caused by worn pump head assembly on sample pumps Upper ". lower pump heads replaced Analyzer recalibr BUINER.H L Georgia Power Co 82/09/23 Region 2, Office of Director 2pp 15619 J18 24X Fiche 50-366, 82/09/23, 8210040244
- 8210040287 Forwards LER 82-100/031-0 N(X,H C Georgia Power Co 82/09/23 O'REILLY, J P Region 2, Office of Director 1p 15619 213 24X Fiche 50-366, 82/09/23, 0210040887
- -8210000289 LER 82-100/03L-0 on 820828, while performing RCIC turbine enhanced disphragm pressure instrument FTAC procedure, two inoperative switches discovered Caused by component failure due to water damage Switches replaced TIPPS.5 S Georgia Power Co 82/09/23 Region 2, Office of Director 2pp 19019-214 P4X Fishe 50-366, 82/09/23, 8210040287
- \$216060317 Forwards updated LER B2-079/03X-1
 NIA.H C Georgie Power Co 82/09/23 O'RETILY, J P Region 2,
 Oifice of Director 1p 15618 J45 24X Fiche 50-366,82/09/23,
 8210060317
- 8210060324 Updated LER 62-079/03X-1 on 820727 diesel generator C tripped affor 37 minutes of normal aperation during surveillance test Caused by failure of connecting rad bearing 8 Engine repaired TIPPS.5 8 Georgia Power Co 82/09/23 Region 2 Office of Director 2pp 15418 344 247 Fiche 50-366.82/09/23.8210060317
- 6210080234 Forwards LER 92-102/03L-0 NIGH C Georgia Powor Co 82/07/26 O'REILLY, J P Region 2: Office of Director 1p 15608 074 24X Fiche 50-366.82/07/28, 8210080234
- --B210080240 LER 82:102/03L-0 on B20830.w/unit steady-state at 2:258 NNT, discovered B20812 scheduled monthly fire hose station safety-related areas surveillance procedure not completed before B20819 grace period expiration TIPPS:8 8 Georgia Power Co 82/09/28 Region 2. Office of Director 2pp 15638 075 24X Fiche 50-366, B2/09/28. B210080234
- 3210130183 Forwards LER 82-101/03L 0 NIA, H C Georgia Power Co 82/09, 28 O'REILLY, J P Region 2, Office of Director 1p 15673 009 24X Fiche 50-366, 82/09/28, 8210130183
- --8210130185 LER 82-101/03L O on 820829, imboard MSIV in loop C failed closed Caused by improper stem to disk thread engagement Disk & stem assembly replaced in both C loop MSIVs Valves bested & returned to svc TIPPS, 9 8 Georgia Power Co 82/09/28 Region 2, Office of Director 2pp 15673 010 24% Fiche 50-364.82/09/28, 8210130183
- 8210130406 Forward4 LER 82-109/03L-0 NICH C Georgia Power Co 82/09/28 O'REILLY, J P Region 2, Office of Director ip 15680 261 24% Fiche 50-366,82/09/28, 8210130406
- --B210130414 LER 82-109/03L-0 on B2090B, performance of RCIC preventative maint procedure disclosed inoperability of RCIC trip & throttle valve A RCIC sys Caused by closure of turbine trip & throttle valve Trip & throttle valve opened TIPPS.5 B Georgia Poucr Co B2/09/28 Region 2. Office of Director 2pp 15480 242 24X Fiche 50-364/82/09/28,8210130404
- 9210130541 Forwards updated LER 82-00B/03X-2 NIX.H C Osongia Power Co 82/09/28 O'REILLY, J P Region 2, Office of Director 1p 15683 301 24X Fichs 50-366,82/09/28, 6210130541
- --8210130549 Updated LER 82-008/03X-2 on 820126, during steady-state operation; IS control rod drive accumulator low pressure alarm switches found in need of calibr Caused by instrument drift Setpoints reset Fill valves being overhauled TIPPS 8 Georgia Power Co 82/09/28 Region 2. Office of Director 2pp 15683 302 24X Fiche 50-366, 82/09/28, 8210130541

- 82:0130220 Forwards LER 82-1:0/03L-0 NIX,H C Georgia Pawer Co 82/09/30 O'REILLY,J P Region 2. Ottice of Director ip 15675 232 24X Fiche 50-366,82/09/30, 82:0130220
- --B210130223 LER B2-110/03L-0 820909 during steady-state operation performance of monthly drywell procedure disclosed integrator output outside acceptable range Caused by instrument drift Drywell equipment drain sump pumps secured TIPPS.S B Georgia Power Co B2/09/30 Region 2. Office of Director 2pp 15675 233 24X Fiche 50-366,82/09/30,8210130220
- B210190504 Forwards LER B2-107/03L-0 NI(, N C Georgia Power Co 82/10/05 O'REILLY, J P Region 2, Office of Director 19 15736 OO1 24X Fiche 50-366, 82/10/05, B210190504
- --8210170511 LER 82-107/O3L-0 on 820904, w/unit at 1,831 MWt, unreviewed spec release order discovered Caused by personnel oversight Personnel reinstructed on importance of complying w/Tech Spec & 8 3 c Procedure reviewed & signed TIPPS.S 8 Georgia Power Co 82/10/05 Region 2, Office of Director ip 15736 OO2 24X Fiche 50-366.82/10/05,8210190504
- 8210190595 Forwards LER 82-108/03L-0 NKA: H C Opengia Power Co 82/10/05 O'REILLY, J P Region 2, Office of Director 1p 15739 337 24X Fichs 50-366,82/10/05, 6210190595
- --8210190402 LER 82-108/03L-0 on 820907, discovered that monthly surveillance procedure re emergency buses 25,2F & 20 undervoltage relay instrument FT not performed by 820902 per Tech Specs Caused by personnel error Personnel counseled TIPPS:5 B Georgia Power Co 82/10/05 Region 2, Office of Director (p. 15739-338 24X Fiche 50-344,82/10/05,8210190595
- 8210290357 Forwards updated LER 79-098/01X-1 MIX.H C Georgia Power Co 82/10/07 O'REILLY, J P Region 2, Office of Director 1p 15853 086 24X Fishe 50-366,82/10/07, 8210290357
- --8210290364 Updated LER 79-098/01X-1 on 790902 plant engineering personnel reviewed wiring diagrams & confirmed problem w/HPCI cable separation Caused by design error HPCI cable rerouted per Design Change Request 79-380 on 810822 SUMNER, H L Georgia Power Co 82/10/07 Region 2, Diffice of Director 2pp 15853 087 24X Fiche 50-366,82/10/07,8210290357
- 8210290374 Forwards LER 82-111/03L-0 NIX,H C Georgia Power Co 62/10/12 O'REILLY,J P Region 2, Office of Director 1p 15853 010 24X Fiche 50-366.82/10/12, 6210360374
- --8210290381 LER 82-111/03L-0 on 820918, shift technical advisor ran P+1 (periodic core performance log) w/o benefit of OD-1 (low power range monitor) P+1 indicated FRP of 0 627 & core max fraction of limiting power density of 0 653 SUMMER, H L Georgia Power Co 82/10/12 Region 2, Office of Director ip 15853 011 24X Fiche 50-366, 82/10/12, 8210290374
- 8210290206 Forwards LER 82-105/03L-0 NIGH C Georgia Power Co 82/10/14 O'REILLY, J P Region 2, Office of Director 1p 15853 291 24X Fiche 50-366, 82/10/14, 8210290206
- --8210290207 LER 82-105/03L-0 on 820918, during selection of rods to increase power, rod out permissive light went out, Caused by blown power fuse Fuse replaced TIPPS: 8 B Georgia Power Co 82/10/14 Region 2, Office of Director (p 15853 292 24X Fiche 30-366,82/10/14,8210290206
- 8210290075 Forwards LER 82-106/03L-0 NIX,H C Georgia Power Co 82/10/19 D'REILLY,J.P Region 2: Diffice of Director 1p 15853 149 24X Fiche 50-366,82/10/19, 8210290075
- --8210290080 LER 82-106/03L-0 on 820922, during steady-state operation.
 RCIC sys supply valve position indicator lights found
 extinguished Caused by breaker being turned off Breaker
 turned on Investigation initiated
 TIPPS.S B Georgia Power Co 82/10/19 Region 2, Office of
 Director ip 15853 180 24X Fiche 50-366.82/10/19,8210290075
- DOCKET 50-367 BAILLY GENERATING STATION
 O Adjudicatory correspondence
- 8210040022 Notice of withdrawal of appearance in proceeding LEWIS, S. H. Hearing Branch 2 82/09/29 3pp 15581 257 24X Fiche 50-367, 82/09/29, 8210040022

- G Inspection reports, IE Bulletins & correspondence
- 6210050162 Forwards notice of site inspito be conducted on 821018 in conjunction w/ongoing restoration work per ASLB 820506 order terminating proceedings on application for CP extension SHORB.E M Northern Indiana Public Service Co. 82/10/01 DENTCH.IR Diffice of Nuclear Reactor Regulation, Director Spp. 15605-144 247 Fichs 50-367.02/10/01.8210050162
- S Reportable occurrences, LERs & related correspondence
- 8210050512 Responds to FDIA request for insp & enforcement records re accidents of F Lawson & H Dillon at facility. Union Electric CP & other NRC safety maths or manuals Forwards two documents Renaining records available in PDR FELTON, J M Division of Rules and Records 82/09/21 IGOE, M V Igoe, V M 2pp 15626-244 24X Fiche 50-000, 82/09/21.8210050512
- --8210050518 Region 3 daily rept for 780807 4 Region 3. Chicago. Office of the Director 78/08/07 ip 15626 246 24X Fiche 50-000.82/09/21.8210050512
- DOCKET 50-368 ARKANSAS NUCLEAR DNE, UNIT 2 F Security, medical, emergency & fire protection plans
- 8210010175 Forwards IE Safeguards Insp Repts 50-313/82-25 & 50-348/82-22 on 820818-20 No noncompliance noted SEIDLE, W.C. Division of Resident, Reactor Project ** Engineering Programs 82/09/16 CAVANAUGH, W. Arkansas Fower & Light Co. 2p 15567-292 24% Fiche 50-313,82/09/16.0210010175
- --8210010178 (E Safeguards Insp Repts 50-313/02-25 & 50-368/82-22 on 820319-20 No noncompliance noted Major areas inspected security organization mgt.physical barriers & access control of packages Details uithheld (ref 10CFR2 790) EVANS.C A Division or Vendor & Technical Programs 62/07/14 p 15567 284 24X Fiche 50-313.82/07/16.8210010175
- 8210190497 Forwards 1E Insp Repts 50-313/82~11 & 50-368/82-09 on 820518-20 No noncompliance noted SEIDLE,N C Division of Resident, Reactor Project & Engineering Programs 82/09/28 CAVANAUGH,N Arkansas Power % Light Co 2pg 24% Fiche 50-313,82/09/28.8210190497
- -8210190516 IE Insp Repts 50-313/82-11 % 50-368/82-09 on 620518-20 No noncompliance noted Hajor areas inspected licensee ince & capabilities during full-scale exercise of y plans & procedures

 ### Division of Resident, Reactor Project & Engineering 82/09/24 17pp 24X Fiche 50-313,82/09/28,8210190497

- 8210260178 Ack receipt of 820929 ltr requesting additime to respond to violations noted in Emergency Piepaledness Appraisal Repts 50-316/862-22 & 50-368/802-21 Response to App C due by 830301 SEIDLE.W C Division or Resident. Reactor Project & Engineering Programs 82/10/19 CAVANAUGH.W Arkansas Power & Light Co lp 15799 037 24X Fiche 50-313.82/10/19.8210260178
- --8210260180 Responds to NRC 820625 ltr re App C to IE Emergency
 Preparedness Appraisal Repts 50-313/82-22 & 50-368/82-21
 Deficiencies resolved in emergency plan amends &
 implementing procedure revisions
 CAVANAUGH, W. Arkansas Power & Light Co. 82/09/29 COLLINS. & f
 Region 4. Office of Director 4pp. 15799 OJB 24X
 Fiche 50-313, 82/10/19 8210260178
- P. Operating license stage documents & correspondence
- B21001000B Responds to FOIA request for 19 categories of documents re nuclear reactor events 7 safety problems Forwards documents listed in App A FELTON.J H Division of Rules and Records 82/06/28 UDELL.P A Critical Mass Energy Project 15pp 15727 005 24x Fiche 50-000, 82/06/28. 8210010008
- --B106100203 Discusses evaluation of HPSI pump operability w/o syc uater Operability of HPSI pumps w/o syc water not adequately justified based on info submitted by licensee IMBRO.C. Director's Office 81/05/22 Director's Office App 15727 185 24X Fiche 50-000.82/06/28.8210010008
- 8210190908 Responds to 820831 submittal re Tech Spec revision for snubber surveillance Liceuse amend application should be submitted to incorporate applicable pointon of 801120 model Tech Specs within 60 days CLARK, R.A. Operating Reactors Branch 3 82/09/21 CAVANAUGH, WARIANSAS Power & Light Co. 2pp. 15760-301 24X Fiche 50-313,82/09/21,8210190008
- 8210130409 Responds to NRC 810619 ltr transmitting Amend 24 to Dicense NRF-6 re-serred reactor confant pump shaft event reanalysis Event description & results of Cycle 2 serred rator event enci MARSHALL, J.R. Arkansas Power & Light Co. 82/10/05 CLARK, R.A. Operating Reactors Branch J. 8pp. 15681-010 24X Fiche 50-3468, 82/10/05, 8210130409
- B210200022 Provides preliminary info as result of fuel insp that revealed need to modify some Batch C fuel assemblies to provide add! space for avial growth of fuel rods SCHERER.A E Combustion Engineering, Inc 82/10/05 DEYDUNG, R C Director's Office, Office of Inspection and Enforcement 2pp 15755 004 24% Fiche 50-368,82/10/05.8210200022
- 8210150002 Forwards response to 820120 % 0301 requests for addl info re RCB high point yents Gredible missiles generated by failure of RCB vent valves not postulated based on valve design Leak detection provided for by monitoring pressure HARSHALL, J. R. Arkansas Fower & Light Co. 82/10/06 STOLZ, J.F. Operating Reactors Branch & CLARK, R.A. Operating Reactors Uranch 3 4pp 15696 309 24X Fiche 50 313,82/10/06,8210150002
- 8210150494 Submits info re status of waste gas sys & schedule for installation of redundant hydrogen/oxygen analyzers. Conceptual diagram of proposed upgraded waste gas sys redundant analyzer panel enci MARSHALL, J.R. Arkansas Power & Light Co. 82/10/12 STDLZ, J.F. Operating Reactors Branch 4 CLARK, R.A. Depending Reactors Branch 3 4pp (5714 184 24X Fiche 50-313,82/10/12,8210190494
- B210250159 Application to amend License NPF-6, changing Tech Specs to allow for removal of surveillance capsule & analysis of specimen CAVANAUGH.W. Arkansas Power & Light Co. B2/10/19 CLARK.R. A. Operating Reactors Branch 3 3pp 15787 313 24X Pichs 50-365.82/10/15,8210250159
- ---8210250161 Proposed Tech Spec change allowing for removal of surveillance capsuls & analysis of specimen

 Arkansas Power & Light Co 82/10/15 ip 15787 316 24y
 Fichs. 50-368, 82/10/15, 8210250159
- 8210270101 Forwards nine revised oversize P&IDs Drawing transmittal list encl Aperture cards are available in PDR 8HIVELY.C Arkaneas Power & Light Co 82/10/18 NRC - No Detailed Affiliation Given 2pp 15829 325 24x Fiche 50-368.82/10/18.8210270101

Q Inspection reports. IE Bulletins & correspondence

- 6210080015 Add1 response to FOIA request for 19 categories of infolia nuclear reactor events & safety problems Forwards documents listed in App A Documents in App B completely withheld (ref FOIA Elemption 5) FELTON J M Division or Rules and Records 82/07/12 UDELL.R A Critical Mass Energy Project 9pp 15645 027 24% Fiche 50-000.82/07/12.8210080015
- P2100B0112 Systematic assessment of licensee performance notes refacility evaluation for 790101-800B19
 + NRC No Detailed Affiliation Given 80/08/19 Bpp 15667 291 24X Firste 50-000, 82/07/15.82100B0015
- R2(00)0175 Forwards IE Safeguards Insp Repts 50-313/82-25 & 50-368/82-22 on 820918-20 No noncompliance noted SEIDLE W C Division of Resident, Reactor Project & Engineering Programs 82/09/16 CAVANAUGH W Arkansas Power & Light Co &p. 15567 282 24% Fiche 50-313,82/09/14,8210010175
- --8210010178 IE Safequards Insp Repts 50-313/82-25 & 50-368/82-22 un 820818 20 No noncompliance noted Major areas inspected security organisation mot physical barriers & access control or packages Details withheld tref 10CFR2 790) EVMI3, C A . KELLY, J A F Division of Vendor & Tochnical Programs 82/09/14 1p 15567 284 24% Fiche 50-313/82/09/16/8210010175
- 87:0190497 Forwards IE Insp Repts 50-313/82-11 & 50-368/82-09 on 820518-20 No noncompliance noted SEIDLE, N C Division or Resident, Reactor Project & Engineering Programs 62/09/28 CAVANAUOH, W Alkansas Power & Light Co 2p 15735 344 24X Fiche 50-313,82/09/28.8210190497
- 9210190516 If Insp Repts 50-313/82-11 t 50-368/82-09 on B20518-20 No noncompliance noted Major areas inspected licensee performance t capabilities during full-scale exercise of energoncy plans t pracedures
 ROHRER, D.M., HUNNICUTT D.M. Division of Resident, Reactor Project t Engineering Plograms 82/09/24 17pg 15735-346 24x
 Fichs 50-313,82/09/28,8210190497
- 0210120246 Ack receipt of 820211 ltr informing NRC of steps taken to correct violations noted in 1E thap Ropts 50-313/81-30 & 50-368/81-29
 SEIDLE-W C Division or Resident, Reactor Project & Engineering Programs 82/10/01 CAVANAUGH, W Arkansas Power & Light Co ip 15652 110 24x Fichs 50-313, 82/10/01, 8210120246
 - 8210127292 Responds to NRC 820104 itr re violations noted in It Insp Repra 50 313/81-30 / 50-368/81-27 Corrective actions formal training sessions will be conducted w/appropriate station personnel to stress importance of individual responsibility MARSHALL.J R Arkansas Power & Light Co 82/02/11 MADSEN.G L Division of Resident Reactor Project & Engineering Programs 2pp 15652 111 24X Fiche 50-313.82/10/01.8210120246
- 6210200222 Provides preliminary info as result of fuel insp that revealed need to modify some Batch C fuel assemblies to provide addl space for axial growth of fuel rads SCHERER.A E Cambustion Engineering. Inc 82/10/05 DEYOUNG.R C Director's Office. Office of Inspection and Enforcement 2pp 19783 004 24x fiche 50-368.82/10/05.8210200022
- 8210220270 Forwards IE Insp Repts 50-313/82-12 & 50-368/82-25 on 820524-27 No noncompliance noted SEIULE.H C Division of Resident, Reactor Project & Engineering Programs 82/10/05 CAVANAUOH.W Alkensas Power & Light Co 2pp
- --8210220281 IE Insg Repts 50-313/82-12 & 50-368/82-25 on 820524-27 No noncompliance noted Major areas inspected radiochemistry program, including organization, staffing, braining program, sample collection & sample treatment & analysis NICHOLAS. J B , MURRAY. B Region 4, Office of Director 82/09/09 25pp 19775 003 24X Fiche 50-313,82/10/05,8210220270
- 8208190233 JE Info Notice 80-35, Suppl 1, "Leaking & Dislodged I-125 implant Seeds " Svc list encl COBB.L I Division of Fuel Facilities, Materials & Safeguards 82/10/06 Consolidated Edison Co of New York 66pp 15761 250 24% Fiche 50-000,82/10/06,8208190233

- 8210120241 Ack receipt of 820715 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-313/80-20 & 50-368/80-20 SEIDLE:W C Division of Resident, Reactor Project & Engineering Programs 82/10/06 CAVANAUGH:W Arkansas Power & Light Co ip 19652 113 24X Fiche 50-313,82/10/06,8210120241
- --8210120247 Provides status update on gaseous radioactive waste sys mods.in response to violations noted in IE Insp Repts 50-319/80-20 & 50-366/80-20 High airborne activity incidents in auxiliary bldgs significantly reduced MARSHALL J R Arkansas Power & Light Co B2/07/15 BCIDLE, W C Division of Resident Reactor Project & Engineering Programs 3pp 19652 114 24X Fiche 50-313.82/10/06.8210120241
- 8208190238 IE Bulletin B2-03, "Btress Corrosion Cracking in Thick-Wall.Large-Diameter. Stainless Steel. Recirculation Sys Piping at BBR Plants " Svc list encl DEYOUNO.R C Director's Office. Diffice of Inspection and Enforcement 82/10/14 Consolidated Edison Co of New York 115pp 15810 125 24X Fichs 50-000.82/10/14.8208190238
- 8210220377 Categorizes upen items identified in IE Emergency Preparedness Repts 50-343/82-11 & 50-3468/82-09 by need for immediate consideration & type of response acceptable Notification of expected response date due within 10 days SEIDLE.W C Division of Resident, Reactor froject & Engineering Programs 82/10/19 CAVANAUGHW Arkansas Power & Light Co 4pp 15779 175 24X Fiche 50-313,82/10/19.8210220377
- 8210260178 Ack receipt of 820929 itr requesting additime to respond to violations noted in Emergency Preparedness Appraisal Repts 50-313/82-22 & 50-368/82-21 Response to App C due by 830501 SEIDLE:N C Division of Resident, Reactor Project & Engineering Programs 82/10/19 CAVANAUGH:N Arkansas Power & Light Co In 15799 037 24X Fiche 50-313,82/10/19,8210260178
- --8210260180 Responds to NRC 820629 ltr re App C to IE Emergency Preparedness Appraisal Repts 50-313/62-22 & 50-368/82-21 Deficiencies resolved in emergency plan amends & implementing procedure revisions CAVANAUGH, W Arkansas Power & Light Co 82/07/27 COLLINB, J T Region 4. Office of Director 4pp 15799 038 24X Fiche 50-313, 82/10/19, 8210260178
- 8 Reportable occurrences, LERs & related correspondence
- B012290118 Discusses conclusions of angineering evaluation of steam generator overfull transfents At C-E & Westinghouse plants LANNING.U D Director's Office B0/10/29 MICHELSON.C Director's Office 3pp [5692 262 24X Fiche 50-000,80/10/29.8012290118]
- 8210080028 Advises that Sept 1980 blockage of flow by silt to bearing oil coolers & seal water coolers of all high pressure safety injection pumps considered AD Util failed to justify pump operability w/o water IMBRD, E. Director's Office 81/05/22 Director's Office 4pp 15669 303 244 Fiche 50-368.81/05/22,8210080028
- 8210190009 Discusses repetitive failures of emergoncy feedwater flow valves at facility due to valve operator hydraulic problems Recommends that hydraulic valve operators be added to branch watch list IMBRO.E V Reactor Operations Analysis Branch 82/02/24 MIGHELSON.C Director's Office 3pp 15760 303 24X Fiche 50-368.82/02/24.8210190009
- 021001009B Responds to FOIA request for 19 categories of documents re nuclear reactor events & safety problems Forwards documents listed in App A FELTON, J M Division of Rules and Records 82/06/28 UDECL, R A Critical Mass Emergy Project 15pp 15727 009 24X Fiche 50-000,82/06/28,8210010008
- --8107010161 Discusses inoperability of instrumentation due to extreme cold weather IE should issue suppl to IE Bulletin 79-24 requesting Tech Spec changes which require daily surveillance during extreme weather MICHELSON.C Director's Diffice 81/06/15 DENTGN.H R Office of Nuclear Reactor Regulation, Director 5pp. 15727 208 24X Fiche 50-000, 82/06/28, 821001000B
- --8203120016 Discusses repetitive failures of emergency feedwater flow value as reported in LERs due to valve operator hydraulic problems LERs encl
 IMBRO,E V Director's Office 82/02/24 MICHELBON,C Director's Office 76pp 15732 308 24X Fichar50-000,82/06/28,8210010008

- 8210050346 Confirms 820922 teleon w/NRC resident inspector re discovery that clearance between top of fuel rods & bottom of upper flow plate on batch C fuel assemblies may not prevent pin contact Mod planned LER 82-030/017-0 will follow LEVINE, J M Arkansas Power & Light Co 82/07/23 COLLINS, J Region 4, Office of Director 1p 15610 125 24X Fiche 50-368, 82/07/23.8210050346
- 8210190545 Forwards LER 82-030/017-0
 MARSHALL, J R Arkansas Power & Light Co 82/10/06 SEIDLE, W C
 Division of Resident. Reactor Project & Engineering Programs | Ip
 15735 006 24X Fight 50-368,82/10/06.8210190545
- ~-8210190558 LER 82-030/017-0 on 820922 measurements revealed shoulder gap clearances on certain batch C fuel assemblies may not be sufficient to prevent pin contact Caused by design models & annealed guide tubes growing at lesser rate RODERS, P Arkansas Puder & Light Co 82/10/06 Region 4, Office of Director App 15735 007 24% Fische 50-368.82/10/06.82/10/90548
- --8210250298 LER 82-031/01T-0 on 821001 after disassembling emergency feedwater sump turbing steam supply check valve for insp. disc studinut washer & locking pin discovered missing Caused by vibration fatigue Parts replaced ROSERS, P. Ariansas Power & Light Co. 82/10/13 Region 4. Office of Director 4pp 15770-065 24X Fiche 50-368.82/10/13, 821025022
- 8210260120 Forwards LER 82-029/03L-0
 MARBHALL, J R Arkansus Power & Light Co 82/10/15 SEIDLE W C
 Division of Resident Reactor Project & Engineering Programs 1p
 15799 076 24% Fiche 50-368.82/10/15.8210260120
- ---8210260123 LER 82-029/03L-O on 820918 four electrical cables discovered pulled through fire curtain Caused by personnel error while performing station battery capacity test Personnel unaware of fire curtain in wall opening Maint personnel counseled ROGERS,P Arkansas Power & Light Co 82/10/15 Region 4. Office of Director 2pp 15799 077 24X Fiche 50-368 82/10/15, 6210240120
- 8210260474 PND-1V-82-038 insp of svc water sys identified deficiencies in pipe supports Deficiencies include hanger installation not in accordance w/design incorrect as-built drawings & workmanship defects
 JOHNSON W D Repion 4. Office of Director 82/10/20 ip 15804 294 24X Fiche 50~368.82/10/20.8210260474
- DOCKET 50-369 WILLIAM B MCGUIRE NUCLEAR STATION, UNIT 1

 A Application/construction stage documents & correspondence
- 0210010008 Responds to FDIA request for 19 categories of documents re nuclear reactor events \$ safety problems Forwards documents listed in App A FELTON, J M Division of Rules and Records 82/06/28 UDELL, R A Crifical Mass Energy Project 15pp 19727 ODS 24X Fiche 50-000, 62/06/28, 8210010008
- ~-8008050265 Discusses addl required info to better define potential for cracking in reactor vessel norties NODNAN.V S Assistant Director for Materials & Qualifications Engineering 60/05/05 TEDESCOR L Assistant Director for Licensing 2pp. 15727 176 24% Fiche 50~000.82/06/28,821001000B
- F Security, medical, emergency & fire protection plans
- 9210150006 Ack receipt of 920723 ltr informing NRC of steps taken to correct improvement items noted in IE Emergency Preparedness Appraisal Rept 50-367/92-06
 LEWIS.R C Division of Project & Resident Programs 82/09/13 PARKER.W C. Duke Power Co 1p 15698 214 24X Fiche 50-369, 82/09/13.8210150006
- --82t0150012 Forwards response to NRC 820625 ltr re improvement items noted in IE Emergency Preparedness Appraisal Rept 50-369/82-06 on 820301-12 Corrective actions lesson plans for emergency response training complete PARKER, M O Duke Power Co 82/07/23 D'REILLY, J. P. Region 2, Office of Director 10pp 15698 215 24X Fiche 50-369,82/08/13,8210150006

- --8210150020 Forwards IE Emergency Preparedness Appraisal Rept 50-369/82-04 on 820301-12 No violations deviations or amergency preparedness deficiencies noted O'REILLY, J. P. Region 2. Office of Director 82/06/25 PARKER, W. O. Duke Power Co. 7pp. 15698-225 24X Fiche 50-369, 82/08/13, 8210150006
- --B210150025 IE Emergency Preparedness Appraisal Rept 50-369/82-06 on 820301-12 No violations or deficiencies noted Major areas imagected evaluation of adequacy of emergency preparedness program Evaluation encl SIMONDS, G E. JENN INS, G R. Division of Emergency Preparedness & Operational Support 82/06/22 46pp 15698 226 24X Fiche 50-369,82/08/13,8210150006
- 8210150014 Forwards 1E Insp Rept 50-369/82-71 on 820830-0903 No noncompliance moted DANCE, H C Division of Project & Resident Programs 82/09/24 TUCKER, H B Dute Power Co 2pp 15698 333 34X Fiche 50-369, 82/09/24, 8210150014
- --8210150021 IE Insp Regt 50-369/82-31 on 820830-0903 No noncompliance noted Major areas inspected emergency preparedness MARSTON, R R , JENKINS, 0 R Division of Emergency Preparedness & Operational Support 82/09/23 tipp 15698 335 24X Fiche 50-369,82/09/24,8210150014
- B210190097 Releases public version of revised emergency plan implementing procedures FELTON. J. H. Division of Rules and Records B2/09/29 Document Management Branch 1p 15761 127 24X Fiche 50-369, B2/09/29, B210190097
- --8210190103 Forwards public version of levised emergency plan implementing procedure, including Procedure AP/O/A/5500/27 recare & transportation of contaminated injured individuals from site to offsite medical facility TUCKER, H B Duke Power Co 82/09/15 DENTON, H R Office of fluctual Reactor Regulation, Director 2pp 15761 128 24% Fiche 50-369, 82/09/29, 82/1019097
- --8210190108 Public version of revised emergency plan implementing procedures, including Procedure AP/0/A/5500/27 re care & transportation of contaminated injured individuals from site to offsite medical facility GLOVER, HS Duke Power Co. 82/08/30 92pp 15761 130 24X Fiche 50-369, 82/09/29, 8210190097
- B210070072 Notifies that local alarms missing from control room fire lanes will be installed by 830701.per Jan 1977 fire protection review Issue not considered significant safety concern TUCKER-H B Duke Power Go 82/09/30 DENTON,H R ADENSAM (G Office of Nuclear Reactor Regulation, Director 1p 15628 164 2/ Fiche 50-269, 82/09/30, 8210070072
- 8210180254 Responds to util 820520 ltr re Revision 13 to physical security plan Changes consistent w/provisions of 100cR50 54(p)
 ADEMSAME 0 Licensing Branch 4 82/09/30 TUCKER.H B Dute Power Ca 2p 15745 337 24% Fiche 50-369,82/09/30,0210180254
- B210150518 Forwards revised McQuire Nuclear Btation Fire Protection Review " Submittal supersedes all previous revisions TUCKER.N D Dute Power Co 82/10/07 DENTON.H R : ADENSAH.E G Office of Nuclear Reaction Regulation, Director ip 15714 219 24X Fische 50-369, 82/10/07, 8210150518
- --8210150522 Revised "McQuire Nuclear Station Fire Protection Review"

 * Duke Power Co 62/09/30 179pp 15714 220 24X
 Fiche 50-369,82/10/07.8210150518
- 8210270132 Reteases public version of revised emergency plan implementing procedures FELTON.J M Division of Rules and Records 82/10/08 Document Management Branch 1p 15835 136 24X Fiche 50-369,82/10/08. 8210270132
- ---8210270137 Forwards public version of revised emergency plan implementing procedures, including Procedure EP/O/A/5000/05 re notification of unusual event.EP/O/A/5000/06 re alert k EP/O/A/5000/08 re general emergency TUCKER, H B Duke Power Co 82/09/28 DENTON, H R Diffice of Nuclear Reactor Regulation, Director 2pp 15835 137 24X Fiche 50-369.82/10/08.8210270132
- --8210270144 Public version of revised emergency plan implementing procedures; including Procedure EP/0/A/5000/05 re notification of Unyoual event EP/0/A/5000/06 re alert & EP/0/A/5000/08 re general emergency QLOVER.M B , QLBERT.O D Duke Power Co 82/09/13 82pp 15835 139, 24X Fiche 50-369, 82/10/08, 8210270132

DOCKETED ITEMS

- B210280016 Releases public version of revised emergency plan FELTON J M Division of Rules and Records B2/10/12 Documen Management Branch Ip 15853 006 24X Fiche 50~369,82/10/12, B210280016
- --8210280017 Forwards public version of Revision 7 to emergency plan TUCKER.H B Duke Power Co 82/09/28 DENTON,H R Office of Nuclear Reactor Regulation, Director 2pp 15863 007 24X Fiche 50-369,82/10/12-8210280016
- --8210280020 Public version of Revision 7 to emergency plan MCINTOSH.H D. Duke Power Co. B2/09/30 28pp 15863 009 24) Fishe 50-369,82/10/12.8210280016

- 82:0130046 Responds to 820712 ltr request that NRC continue to send capies of correspondence to util an McGuiro Since McGuiro proceedings complete & documents in LPDR, request denied ADENSAM, E.O. Licensing Branch 4 82/09/28 RILEY, J.L. Carolina Environmental Study Group ip 15676-284 24X Fiche 50-000, 82/09/28, 82:10130046
- K Utility Final Safety Analysis Report (FSAR) & amends
- 82(0090254 Forwards application to amend License NPF-9 & CPPR-84, consisting of Revision 43 to FSAR & Revision 6 to "Evaluation of Effects of Postulated Pipe Failures Dutside Containment for McGuire Nuclear Station" TUCKER, H B Duke Power Co 82/10/01 DENTON, H R Office of Nuclear Reactor Regulation, Director ADENSAN, E & Licensing Branch 4 3pp 15595 032 24X Fiche 50-369, 82/10/01,8210040234
- --8210040273 Application to amend License NPF-9 & CPPR-84, consisting of Revision 43 to FSAR & Revision 6 to "Evaluation of Effects of Postulated Pipe Faitures Dutside Containment for McGuire Nuclear Station"
 TUCKER: H B Duke Power Co 82/10/01 16pp 15595 035 24X Fiche 50-369, 82/10/01.8210040254
- --8210040277 Revision 6 to "Evaluation of Effects of Postulated Pipe Failures Outside Containment for McGuire Nuclear Station" * Duke Power Co MDS/PDG-77-1 82/10/01 3pp 15595 051 24x Fiche 50-369.82/10/01.8210040254
- --8210040286 Revision 43 to FBAR Fourteen aperture cards available in PDR

 * Duke Power Co 82/10/01 303pp 15595 054 24X
 Fiche 50-369,82/10/01,8210040254
- 9210130262 Forwards figures to Revision 43 to FSAR included in 921001 application for Amend 69 to License NPF-9 & CPR-84 Subjusti inadvertently omitted TUCKER.H B Duke Power Co 82/10/07 DENTON,H R 0ffice of Nuclear Reactor Regulation, Director ADENSAM,E G Licensing Branch 1 p 15675 293 24% Fiche 50-369,82/10/07,9210130262
- --8210130263 Figures for Revision 43 to FBAR + Duke Power Co. 82/10/07 42pp 15675 294 24X Fiche 50-369.82/10/07.8210130262
- P Operating license stage documents & correspondence
- \$21001000B Responds to FOIA request for 19 categories of documents re nuclear reactor events & safety problems forwards documents listed in App A FELTON, J M Division of Rules and Records \$2706/28 UDELL, R A Critical Mass Energy Project 15pp 15727 005 24X Fiche 50-000.82706/28.821001000B
- B210040424 Forwards request for add1 info re hydrogen control Coordinated util response suggested by mid-Oct 1982, since subj is generic to ice condenser plants NOVAK.T M Assistant Director for Licensing B2/09/17 TUCKER.H B Duke Power Co 10pp 15597 241 24X Fiche 50-369, 82/09/17, B210040224
- 8210180389 Notifies that 770330 application requesting extension of const completion dates exempt from fee requirements since no review commenced on application prior to issuance of OL Refund forthcoming MILLER, W O License Fee Management Granch 82/09/24 PARKER, W C Duke Power Co ip 15746 359 24X Fiche 50-369.82/09/24, 8210180389

- 8210040254 Forwards application to amend License NPF-9 & CPPR-84, consisting of Revision 43 to FSAR & Revision 6 to "Evaluation of Effects of Postulated Pipe Failures Outside Containment for McGuire Nuclear Station" TUCKER, H B Duke Power Co 82/10/01 DENTON H R Office of Nuclear Reactor Regulation. Director ADENSAM, E G Licensing Branch 4 3pp 15595 032 24% Fiche 50-369, 82/10/01,8210040254
- --8210040273 Application to amend License NPF-9 & CPPR-84, consisting of Revision 43 to FSAR & Revision 6 to "Evaluation of Effects of Postulated Pipe Failures Dutside Containment for McGuire Nuclear Station"

 TUCKER.H B Duke Power Co 82/10/01 16pp 15595 035 24X Fiche 50-369,82/10/01,8210040254
- --8210040279 Revision 6 to "Evaluation of Effects of Postulated Pipe Failures Outside Containment for McGuire Nuclear Station" * Duke Power Co MOS/PDG-77-1 82/10/01 3pp 15595 051 74X Fiche 50-369, 02/10/01.8210040254
- 8210130262 Forwards figures to Revision 43 to FSAR,included in 871001 application for Amend 69 to License NPF-7 & CPPR-84 Subj. matl inadvertently omitted TUCKER. H B Duke Power Co 82/10/07 DENTON, H R Office of Nuclear Reactor Regulation, Director ADENSAM, E G Licensing Branch 4 lp 15675 293 24X Fiche 50-369,82/10/07.8210130628
- 8210130467 Responds to Orneric Ltr 82-16 re NUREO-0/37 Tech Specs for Unit 1 will be upgraded to latest NRC requirements 2 combined w/Unit 2 Tech Specs upon issuance of Unit 2 OL in Mar 1983
 TUCKER, H B Duke Power Co 82/10/07 DENTON, H R Office of Nuclear Reactor Regulation, Director ADENSAM, E Q NRC No Detailed Affiliation Given ip 15682 154 24x
 Fiche 50-369.82/10/07.8210130467
- 8210280407 Requests info demonstrating that Unit 2 equipment meets same sessmic & dynamic qualification requirements as Unit info requested by 821027

 ADENBAMIE 0 Licensing Branch 4 82/10/08 TUCKER.H B Duke Pow. Co. 2pp. 13859 327 24x Fiche 50-369.82/10/08,8210280407
- 8210250304 Forwards revised requests for relief from hydrostatic testing requirements on feedwater sys for steam generators & Unit 1 safety injection sys ASME Code Section XI impractical TUCKER:H B Dute Power Co 82/10/19 DENTON,H R Office of Nuclear Reactor Regulation, Director 8pp 15790 205 24X Fiche 50-369,82/10/19,8210250304
- 8210260331 Application for amend to License NPF-9, changing Tech Spet re containment penetration Type C leak rate tests Amend requires exemption from 100FR50. App J THIES, A C Duke Power Co 82/10/21 DENTON: H R Office of Nuclear Reactor Regulation. Director ADENSAM.E 0 Licensing Branch 4 3pp. 15803 178 24X Fiche 50-369.82/10/21,8210260331
- ---8210260336 Proposed change to Tech Spec 4 6 1 2d, requiring that Type C penetration tests be performed at 2d-month interval, deviating from 10CFR90.App J requirement to perform test during each refueling shutdown
 4 Duke Fower Co 82/10/21 4pp 15803 201 24X
 Fiche 50-369.82/10/21.8210260331
- a inspection reports, IE Bulletine & correspondence
- 82:0070007 Responds to FUIA request for eight categories of records resteam generators & steam turbines App A documents provided in R Udell FOIA Request 81-313 Forwards documents listed in App B.
 FELTON, J M Division of Rules and Records 82/08/10 LONG, D J Winthrop. Stimson, Putnam & Roberts 9pp 15645 063 24X Fiche 50-000,82/08/10,8210070007
- --8210070139 Forwards tabulated data on steam generator insp & maint at facilities Data should be provided to licensees IPPOLITO.T Operating Reactors Assessment Branch 82/04/01 VARGA:S Operating Reactors Branch | 5pp 15645 131 24X Fiche, 50-000, 62/08/10/8210070007
- 8210130006 Ack receipt of 820723 ltr informing NRC of steps taken to correct improvement items noted in IE Emergency Preparedness Appraisal Rept 50~367/82-06

 LEWIS.R C Division of Project & Resident Programs 82/08/13

 PARKEN.W O Duke Power Co 1p 156/98 214 24X

 Fiche 50~367.82/08/13.8210150006

- --8210150012 Forwards response to NRC 820625 ltr re improvement items noted in IE Emergency Preparedness Appreis 3Rept 50-369/82-06 on 820301-12 Corrective actions lesson plans for emergency response training complete PARKER.W O Duke Power to 62/07/23 0'REILLY, J P Region 2, Office of Director 10pp 15698 215 24X Fiche 50-369.82/08/13, 923155006
- --8210150020 Forwards IE Emergency Preparedness Appraisal Rept 50-369/82-06 on B20301-12 No violations, deviations or emergency preparedness defficiencies noted G'REILLY, J P Region 2, Office of Director 82/06/25 PARKER, H O Duty Power Co 7pp 15698 225 24X Fache 50-369, 82/08/13, 8210150006
- --B210150025 IE Emergency Preparedness Appraisal Rept 50-369/82-06 on B20301-12 No violations or deficiencies noted Hajor areas inspected evaluation of adequacy of emergency preparedness program Evaluation encl SIMONDS, 0 E . JENKINS, 0 R Division of Emergency Preparedness & Operational Support B2/06/22 46pp 15698 226 24X Fiche 50-369, 82/08/13, 8210150006
- 9210010424 Forwards IE Insp Repts 50-369/82-29 % 50-370/82-23 on 820726-0820 No noncompliance noted DAKCE.H C Division of Project & Resident Programs 82/09/08 TUCKER.H B Duke Power Co 2pp 15569 343 24X Fishe 50-269, 82/09/08.8210010424
- --8210010436 IE Insp Repts 50-369/82-29 & 50-370/82-23 on 820726-0820 No noncompliance noted Major areas inspected maint, surveillance hot functional test.operational safety verification, significant event following plant transients BENIS-P R , HOPKINS-P , DRYANT, J C DIVISION of Project & Resident Programs 82/09/08 6pp 15569-345 24X Fiche 50-369.82/09/08, 8210010424
- 8210010451 Forwards IE Insp Repts 50-369/82-28 t 50-370/82-22 on 820817-20 No noncompliance noted DANCE H C Division of Project t Resident Programs 82/09/08 TUCKER, H B Duke Power Co 2pp 18572 297 24X Fiche 50-369, 82/09/08, 8210010451
- --8210010459 IE Insp Repts 50-369/82-28 & 50-370/82-22 on 820817-20 No noncompliance noted Major areas inspected preoperational test procedure review & test uitnessing JOHNSON, A K., WHITENER, H.L., JAPE, F. Division of Engineering & Technical Programs 82/09/07 6pp 15572 299 24X Fiche 50-369,82/09/08.8210010451
- 8210010282 Ack receipt of IE Insp Rept 50-369/82-27 No proprietary info info TUCKER, H.B. Duke Power Co. 82/09/10 O'REILLY, J.P. Region 2, Office of Director 1p. 15573 109 24X Fiche 50-369, 82/09/10, 8210010282
- 8210010070 Ack receipt of IE Insp Repts 50-347/82-24 & 50-370/82-20 No proprietary info TUCKER, H B Dute Power Go 82/07/15 D'REILLY, J P Region 2, Office of Director ip 15545 257 24X Fiche 50-349, 82/09/15, 8210010070
- 8210150014 Forwards IE Insp Rept 50-369/82-31 on 820830-0903 No noncompliance noted DANCE.H C Division of Project & Resident Programs 82/09/24 TUCKER.H B Duke Pawer Co 2pp 15698 333 24X Fiche 50-369.82/09/28.8210150014

- 8210220202 Ack receipt of IE Insp Repts 50-369/82-28 & 50-3/0/82-22 No proprietary info TUCKER. H B Dute Pawer Co 82/10/08 O'REILLY, J F Region, Poffice of Director ip 15776 357 24X Fiche 50-369, 82/10/00, 8210220202
- 8210220204 Ack receipt of IE Insp Repts 50-369/82-29 \$ 50-170/82 \$ No proprietary info TUCKER.H B Duke Power Co 82/10/08 O'REILLY, J P Region 2 Office of Director 1p 15776 352 24X Fiche 50 369.82/18/08 8210220204
- 8208190238 IE Bulletin 82-03, "Stress Corrusian Cracking in Insti-Wall, Large-Diameter, Stainless Steel, Recirculation Bys Piping at BWR Plants" Svc list encl DEYOUND.R C Director's Office. Defice of Inspection and Enforcement B2/10/14 Consolidated Edison Co. of New York 115pp 15810 [25 24% Fiche 30-000; 82/10/14/8208170238
- A Periodic operating reports & related correspondence
- 8210190742 Forwards monthly operating rept for Sept 1782 TUCKER, H B Duke Power Co 82/10/15 Director's Office, Uffice of Inspection and Enforcement 1p 15737 085 24X Fiche 50-369, 82/10/15,8210190742
- --8210190751 Monthly operating rept for Sept 1982 REAVIS-J A Dube Power Co 82/10/15 Apr 15/3/ 086 24% Fiche 50-369.82/10/15.8210190742
- 5 Reportable occurrences, LERs & related correspondence
- G210010000 Responds to FDIA request for 19 categories of documents re nuclear reactor events % safety problems Forwards documents listed in App A FELTON.J M Division of Rules and Records S2/06/20 UDF(1.# A Critical Mass Energy Project 15pp 15727 005 24X Fiche 50-000.82/06/28.8210010008
- --BiiODSOOIB Requests addl info from util re BiO914 safety injectic a natural circulation event during performance of loss of control room test info needed includes data just prior to trip & up to 1-h following event SANDS, S.P. Director's Office Bi/O9/22 BIRKEL.R Licensing Brench 1 ip 15730 272 24X Fiche 50-000, 82/04/28, 82t0016CmJ
- ~-8210050124 Summary of 810610 operating leactor events meeting LAINAS, G C Assistant Director for Safety Assessment (\$1/06/1) EISENHUT, D G Division of Licensing 5pp 15729 21/ 24X Fichs 50-000, B2/06/28, 8210010008
- --8210010436 IE Insp Repts 50-369/82-29 & 50-370/82-23 on 820/26-0020 ks noncompliance noted Major areas inspected maint, surveillance, hot functional test, operational safety verification, significant event followup & plant transients BEMIS.P R , HOPKINS.P , BRYANT.J C Division of Project & Resident Programs 82/09/08 App 15569 345 24X Fichs 50-369.02/09/09 B210010424
- 8210130177 Forwards LER 82-069/03L-0 Detailed event analysis fmtl TUCKER-H B Duke Power Co 82/10/01 O'REILLY, J P Region 3 Office of Director 3pp 15673 022 24X Fiche 50-369.82/10/01. 8210130177
- --B210130180 LER B2-069/03L-0 on 820903, investigation of several spirit's fire detection sys zone alarms resulted in sys being declared inoperable Caused by water in data gathering panel creating ground condition affecting entire sys NARDBCI,P B Duke Power Co B2/10/01 Region 2, Diffice of Director ip 15673 025 24X Fiche 50-369,82/10/01.8210130177
- 9210220318 Forwards LER 82-070/03L-0 TUCKER, H B Duke Power Co 82/10/15 O'REILLY, J P Region 2. Office of Director 1s 15776 043 24X Ficke 50-369.82/10/15
 - --B210220327 LER B2-070/03L-D on B20916, one of two required only on analyzers failed to alarm after simulated high oxygen concentration generated Caused by misposition of toggle switch Switch returned to correct position MARDOCI.P. B Dute Power Co B2/10/15 Region 2. Office of Director Ip 13776 044 24X Fiche 50-369, B2/10/15, 8210220316

- DOCKET 50-370 WILLIAM B MCGUIRE NUCLEAR STATION, UNIT 2
- A Application/construction stage documents & correspondence
- RE1001000B Responds to FOIA request for 19 categories of documents renuclear reactor events & safety problems Forwards documents
 13sted in App A
 FF) FON.J H Division of Rules and Records 82/06/28 UDELL R A

TELTON. J II Division of Rules and Records 82/06/28 UDELL.R / Critical Mass Energy Project 15pp 15727 005 24X Fiche 50-000,82/06/28,8210010008

- --8008050265 Discusses add1 required info to better define potential for cracking in reactor vessel noizles NDCVAR.V S Assistant Director for Materials & Qualifications Engineering 80/05/05 TEDESCOR L Assistant Director for Licensing 2pp 15727 176 24X Fiche 50-000/82/06/28.8210010000
- 82/0040424 Forwards request for add1 info re hydrogen control coordinated util response suggested by mid-Oct 1982, since subjis generic to ire condenser plants HIDVAR.T II Assistant Director for Licensing 82/09/17 TUCKER.H B Buke Power Co. 10pp. 1959/ 241 24x Fiche 50-369,82/09/17.82/0040424
- 8210180389 Notifies that 790330 application requesting extension of const completion dates exempt from fee requirements since no review commented on application prior to issuance of OL Refund forthcoming
 MILLER. If O License Fee Management Branch 82/09/24 PARKER, IF C Dute Power to 1p 15746-359 24X Fishs 50-369.82/09/24.
 82/0180389
- 8210040254 Forwards application to amend License NPF-9 & CPPR-84, consisting of Revision 43 to FSAR & Revision 6 to Evaluation of Effects of Postulated Pipe Failures Outside Containment for McGuire Nuclear Station "
 10CKER.H B. Duke Power Co. 82/10/01 DENTON, H.R. Office of Nuclear Reactor Regulation. Director 3pp. 15595-032 24X Fiche 50-369, 82/10/01, 8210040254
 - 8910040273 Application to amend License NPF-9 & CPPR-84, consisting of Revision 43 to FEAR & Revision 6 to "Evaluation of Effects of Postulated Pipe Failures Outside Containment for McGuire Nuclear Station"
 TUCKER, H R Buke Power Co 82/10/01 16pp 15595 035 24X Fiche 50-369,82/10/01,8210040254
 - (210040279 Revision & to "Evaluation of Effects of Postulated Pipe Failures Dutside Containment for McGuire Nuclear Station" a Duke Power Co. MOS/PDG 77-1 82/10/01 3pp 15595 051 24X Fiche 50 369 82/10/01.8210040254
- 5210130262 Forwards figures to Revision 43 to FSAR, included in \$21001 application for Americ 69 to License NPF-9 & CPPR-84 Subjunctly inadvertently omitted TiukER, It b. Duke Power Co. 82/10/0/ DENTON, H.R. Office of Nuclear Reactor Regulation, Director in 24% Fiche 50-369, 82/10/07, 8210130262
- 821028040/ Requests info demonstrating that Unit 2 equipment meets same serbmic \$ dynamic qualification requirements as Unit 1 Info requested by 821027
 ADENSAM, E G Licensing Dranch 4 82/10/08 TUCKER, H 8 Duke Power Co 2pp 15859 327 24X Fiche 50~369,82/10/08.8210280407
- 6210180124 Forwards list of important differences in Unit 1 & 2 design features in support of review of proposed OL for Unit 2 TUCKER, H B Duke Power Co 82/10/11 DENTON-HR Office of Nuclear Reactor Regulation, Director ADENBAM E 0 Operating Reactors Branch 4 2pp 15719 333 24X Fiche 50-370.82/10/11, 6210180128
- E210250304 Forwards revised requests for relief from hydrostatic testing requirements on feedwater sys for steam generators & Unit 1 safety injection sys ASME Code Section XI impractical TUCKER: H B Duke Power Co 82/10/19 DENTON, H R Office of Nuclear Reactor Regulation, Director 8pp 15790 205 24X Firhe 50-369, 82/10/19.8210250304
- F Security, medical, emergency & fire protection plans
- 9210190097 Releases public version of revised emergency plan implementing procedures FELTON.J M Division of Rules and Records 82/09/29 Document Management Branch ip 15761 (27 24X Fiche 50-369.82/09/29, 82/019097

- --8210190103 Forwards public version of revised emergency plan implementing procedure, including Procedure AP/0/A/5500/27 recare & transportation of contaminated injured individuals room sate to offsite medical facility TUCKER. H B Duke Power Co 82/09/15 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 15761 128 24X Fiche 50-369.82/09/29.8210190097
- --8210190108 Public version of revised emergency plan implementing procedures, including Procedure AP/O/A/5500/27 recare & transportation of contaminated injured individuals from site to effsite medical facility GLOVER, MS Duke Power Co 82/08/30 92pp 15761 130 24X Fiche 50-169, 82/09/29, 8210190097
- 8210070072 Notifies that local alarms missing from control room fire zones will be installed by 830701.per Jan 1979 fire protection review Issue not considered significant safety concern TUCKER. H B Dute Power Co. 82/09/30 DENTON. H R. ADENSAM, E Q Office or Nuclear Reactor Regulation, Director ip 15628 164 24X Fiche 50-369, 82/09/30, 9210070072
- 82:0180254 Responds to util 820520 ltr ro Revision 13 to physical security plan Changes consistent w/provisions of 10CFR50 54(p) ADENSAM, E.O. Licensing Branch 4 82/07/30 TUCKER, H.B. Duke Power Co. 2pp. 15745 337 24X Fiche 50-367, 82/07/30, 8210180254
- 8210150518 Forwards revised McGuire Nuclear Station Fire Protection Review "Submittal supersedes all previous revisions TUCKER, H B Dute Power CO 82/10/07 DENTON, H R , ADENSAM E G Office of Nuclear Reactor Regulation, Director ip 15714 219 24% Fishe 50-369, 82/10/07,8210150518
- --8210150522 Revised "McQuire Nuclear Station Fire Protection Review "
 4 Duke Power Co 82/09/30 179pp 18714 220 24X
 Fiche 50-369.82/10/07.8210150518
- 8210270132 Releases public version of revised emergency plan implementing procedures FELTON, J M Division of Rules and Records 82/10/08 Document Management Branch ip 15835 136 24X Fichs 50-269,82/10/08, 8210270132
- --8210270137 Forwards public version of revised emergency plan implementing procedures. Including Procedure EP/O/A/5000/05 re notification of unusual event, EP/O/A/5000/06 re alert & EP/O/A/5000/08 re general emergency TUCKER. H B Duke Power Co 82/09/28 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 15835 137 24X Fiche 50-369, 82/10/08, 8210270132
- --B210270144 Public varsion of revised emergency plan implementing procedures, including Procedure EP/O/A/5000/05 re notification of unusual event, EP/O/A/5000/06 re alert & EP/O/A/5000/06 re general emergency gLOVER.M S , 03LBERT.O D Duke Power Co B2/09/13 82pp 15835 139 24X Ficher 50-369, 82/10/08, 8210270132
- 8210190740 Forwards evaluation of facility concerning applicable requirements of 1007850, App R Device locations & cable routes omitted due to similarity w/Unit 1
 TUCKER, H D Duke Power Co 82/10/12 DENTON, H, R Office of Nuclear Reactor Regulation, Director ADENBAM, E O Licensing Branch 4 Spp (5736-250-24X Fiche 50-370, 82/10/12, 8210190740
- 8210280016 Releases public version of revised emergency plan FELTON.J M Division of Rules and Records 82/10/12 Document Management Branch 1p 15863 006 24X Fiche 50-369.82/10/12, 8210280016
- --8210280017 Forwards public version of Revision 7 to emergency plan TUCKER.H B Duke Power Co 82/09/28 DENTON,H R Office of Nuclear Resctor Regulation, Director 2pp 15863 007 24X Fiche 50-364,82/10/12,8210280016
- --8210280020 Public version of Revision 7 to emergency plan MCINIOSH, N D Duke Power Co 82/09/30 28pp 15863 009 24X Fiche 50-369,82/10/12,8210280016

H General correspondence

8210130046 Responds to 820912 ltr request that NRC continue to send copies of correspondence to util on McGUITE Since McGUITE proceedings corplete & documents in LPDR request denied ADENSAM, E.O. Licensing Brench 4 82/09/28 RILEY, J.L. Carolina Environmental Study Oroup 1p 15696 284 24X Fiche 50-000, 82/09/28, B210130046

- K Utility Final Safety Analysis Report (FSAR) & amends
- 8210040254 Forwards application to amend License NPF-7 & CPPR-84, consisting of Revision 43 to FSAR & Revision 6 to "Evaluation of Effects of Postulated Pipe Failures Outside Contraction of Contraction (Contraction) Containment for McGuire Nuclear Station "
 TUCKER,H B Dute Power Co 82/10/01 DENTGN.H R Office of
 Nuclear Reactor Regulation, Director ADENSAM.E G Licensing Branch
 4 Jpp 15999 032 24X Fichs 50-369.82/10/01.8210040254
- --8210040286 Revision 43 to FSAR Fourteen aperture cards available in Duke Power Co 82/10/01 303pp 15595 054 24x

Fiche 50-369, 82/10/01, 8210040254

- 8210130262 Forwards figures to Revision 43 to FBAR, included in 821001 application for Amend 67 to License NPF-9 & CPR-84 Subj matl inadvertently omitted TUCKER.H B Dute Power Co 82/10/07 DENTON,H R Office of Nuclear Reactor Regulation. Director ADENSAME 9 Licensing Brand in 15475 293 24X Fiche 50-369,82/10/07.8210130262 Licensing Branch
- --8210130263 Figures for Revision 43 to FSAR * Duke Pouer Co 82/10/07 42pp 15675 294 24X Fiche 50-369,82/10/07.8210130262
- Q Inspection reports, IE Bulletins & correspondence
- 0210010424 Forwards IE Insp Repts 50~369/82-29 & 50~370/82-23 on 820726-0820 No noncompliance noted DANCE, H C Division of Project & Resident Programs TUCKER, H B Duke Power Co 20p 15569 343 24X Fiche 50-369,82/09/08,8210010424
- -8210010434 IE Insp Repts 50-369/82-29 & 50-370/82-23 on 820726-0820 No riodio43d it imp Repts 30-369782-47 % 20-370782-23 on 820728-0820 No moncompliance hoted Major areas inspected maint, surveillance, bot functional test operational safety verification, significant event followup & plant transients BEMIS.P R . MCPKINS.P . BRYANT.J C Division of Project & Resident Programa 82/09/08 App 15569 345 24X Fiche 50-369,82/09/08, 8210010424
- 8210010451 Forwards IE Insp Repts 50-369/82-28 & 50-370/82-22 on 820317-20 No noncompliance noted
 DANCE.H C Division of Project & Resident Programs 82/09/08
 TUCKER.H B Duke Power Co Zpp 15572 297 24X
 Fiche 50-369, 82/09/08.8210010451
- --8210010459 IE Insp Repts 50-369/82-28 & 50-370/82-22 on 820817-20 No noncompliance noted Major areas inspected preoperational test procedure review & test witnessing JDHNSDN.A H. WHITENER.H.L. JAPE.F. Division of Engineering & Technical Programs 82/09/07 6pp 15572 299 24X Fiche 50-369,82/09/08,8210010451
- 8210010090 Ack receipt of IE Insp Repts 50-369/82-26 & 50-370/82-20 No proprietary infa TUCKER.H B Duke Power Co 82/09/15 O'REILLY, J P Region 2, Office of Director 1p 15565 259 24% Fiche 50-369,82/09/15.
- 8210010387 Ack receipt of IE Insp Rept 50-370/82-19 No proprietary INFO
 TUCKER, H B Duke Power Co 82/09/15 O'REILLY, J P Region 2.
 Office of Director ip 15549 211 24K Fiche 50-370, 82/09/15. 8210010387
- 8210150053 Forwards IE Insp Rept 50-370/82-25 on 820831-0903 No Political Programs 12 stry Nept 5 Street Programs 82/09/22 TUCKER, H B Dute Power Co 2pp 15701 119 24X Fiche 50-370, 82/09/22, 8210150053
- --8210150062 IE Insp Rept 50-370/82-25 on 820831-0903 No noncompliance noted fajor areas inspected preoperational test procedure reviews & witnessing JOHNSON, A H. JAPE, F. Division of Engineering & Technical Programs 82/09/15 4pp 15791 121 24X Fiche 50-370,82/09/22,8210150053
- 8210010093 Ack receipt of IE Insp Rept 50-370/82-21 No proprietary TOCKER, H. B Duke Power Co 82/09/23 O'REILLY, J P Region 2, Office of Director ip 15565 003 24X Fiche 50-370, 82/09/23, 8210010093
- 8210150116 Forwards IE Insp Repts 50-369/82-32 & 50-370/82-25 on 820831-0903 No noncompliance noted
 DANCE: H C Division of Project & Resident Programs
 TUCKER, H B Duke Power Ca 2pp 15698 018 24X
 Fiche 50-369, 82/09/24, 8210150116

- --8210150123 IE Insp Repts 50-369/82-32 % 50-370/82-26 on 820831-0903 No noncompliance noted Major areas inspected licensee actions on previous enforcement matters. Dicensee identified items & hanger weld fabrication ECONOMOS.N. BLAKE, J.J. Division of Engineering & Technical Programs 82/08/22 Spp 15698 020 24% Fiche 50-369.82/09/24, 8210150116
- 8210220328 Forwards IE Insp Rept 50-370/82-28 on 820914-17 No noncompliance noted noncompliance noted
 DANCE, H C Division of Project & Resident Programs 82/09/29
 TUCKER, H B Dute Power Co 2pp 15776 | 145 24X
 Fiche 50-370, 82/09/29, 8210220328
- --8210220337 IE Insp Rept 50-370/82-28 on 820914-17 No noncompliance 21022037 IE Insp. Rept. 30-3/0742-26 on a2014-17 No noncompitan noted Hajor areas inspected preoperational toot procedure & task package reviews
 JOHNSON.A H Division of Project & Resident Programs JAPE.;
 Division of Engineering & Technical Programs 82/09/28 App.
 15776-147 24X Fithe 50-370,82/09/29,8210220328
- 8208170233 IE Info Notice 80-35, Suppl 1, "Leaking & Dislodged 1 125 Implant Seeds "Syr list encl CODBL I Division of Fuel Facilities, Materials & Gafeguards 82/19/06 Consolidated Edison Co of New York 66pp 1576 82/10/06 Consolidated Edison Co of New York 66pp 24% Fiche 50-600,82/10/06.8208170233
- 8210220202 Ack receipt of IE Insp Repts 50-369/82-28 & 50-370/82-22 No proprietary info
 TUCKER H B Duke Power Co 82/10/08 O'REILLY, J P Region 2,
 Orfice of Director 1p 15776 357 24X Fithe 50-349,82/10/08,8210220202
- 8210220206 Ack receipt of IE Inap Repts 50-369/02-29 & 50-370/82-23 No proprietary info TUCKER,H B Duse Power Co 82/10/0B O'REILLY, J P Region 2, Office of Director 1p 15776 352 24X Fishe 50-369,82/10/0B, 8210220206
- 9209190238 IE Bulletin 82-03, "Stress Corresion Cracking in Thick-Wall, Large-Diameter, Stainless Steel, Recirculation Sys Piping at BMR Plants " Svc list encl
 DEVOLNOIR C Director's Office Office of Inspection and
 Enforcement 82/10/14 Consolidated Edison Co of New York
 115pp 15810 125 24X Fiche 50-000.82/10/14.8208190238
- S Reportable occurrences, LERs & related correspondence
- 8210010424 Forwards IE Insp Repts 50-369/82-29 & 50-370/82-23 on 200726-0820 No noncompliance noted
 DANCE, H C Division of Project & Resident Programs
 TUCKER, H B Duke Power Co 2pp 15569 342 24X
 Fiche 50-369, 82/09/08. 8210010424
- --8210010436 IE Insp Repts 50-369/82-29 & 50-370/82-23 on 820726-0820 #10010436 IE Insp Repts 50-369/82-29 % 50-370/82-29 on 8207: moncompliance noted Major areas inspected maint, surveillance, hot functional test.operational safety verification, significant event followup & plant transients BEMIS.PR Division of Project & Resident Programs 82/0 App 15569 345 24% Fiche 50-369.82/09/08.8210010424
- 8210290045 Significant Deficiency Rept SD 370/82-05 re problem w/BSPS on-line testing circuits Initially reported on 820720 Test procedures revised to ensure relay test circuits in BSPS operate properly
 TUCKER.H B Duke Power Co 82/10/20 O'REILLY.J P Region 2.
 Office of Director 3pp 15893 331 24X Fiche 50-370,82/10/20,

DOCKET 50-373 LABALLE COUNTY STATION, UNIT 1

- A Application/construction stage documents & correspondence
- 8210010008 Responds to FOIA request for 19 categories of documents re nuclear reactor events & safety problems Forwards documents to nuclear reactor events & safety problems Forwards documents listed in App A
 FELTON, J M Division of Rules and Records 82/06/20 UDELL.R A
 Critical Mass Energy Project 15pp 15727 005 24x
 Fiche 50-000, 82/06/28, 8210010008
- --8008050265 Discusses addl required info to better define potential f DUBODACO DISCUSSES ABDI FEQUIFEC INTO LO DEVCET DETINE POVENTIAL F CPACKING In reactor vessel posiles NOONANIV S. Assistant Director for Haterials & Qualifications Engineering 80/05/05 TEDESCO.R L. Assistant Director for Licensing 2pp 15727-176 24X Fiche 50-000.82/06/28,8210010008

- f Security, medical, emergency & fire protection plans
- 8209270125 Heleases public version of revised generating station emergency plan corporate command ctr emergency plan implementing procedure FELION, JM Division of Rules and Records 82/09/16 Docum Management Branch ip 15564 122 24X Fiche 50-000,82/09/16.

Management Branch 8209290125

- -8209290189 Furwards public version of Revision 4 to generating station emergency plan corporate command ctr Emergency Plan Implementing Procedure EUF-3, "Environ/Emergency Coordinator" Receipt form encl PAJONSKI, J E Commonwealth Edison Co 82/09/01 DENIUN, H R NRC No Detailed Affiliation Given 1p 15564 123 244 Fich 50-000,82/09/16,8209290125
- 8209290225 Public version of Revision 4 to generating station emergency plan corporate command the Emergency Plan Implementing Procedure EGF-3, "Environ/Emergency Coordinator PAJDWSKI.J E Commonwealth Edison Co 82/08/31 15564 124 24X Fiche 50-000, 82/09/16,8209290125
- 1210()60379 Forwards IE Insp Rept 50-373/82-19 on 820317-19,24-26 & OldOp No noncompliance noted

 ITTLE.W S Division of Engineering & Technical Programs 82/09/21

 REFD, C Commonwealth Edison Co 2pp 15618 330 24X

 Fiche 50-373.82/09/21.82/0060379
- H2100603B4 IE Insp Rept 50-373/82-19 on 820317-19.24-26 & 0408 No noncumpliance noted Major areas inspected licensee action on previous this findings to fire protection program HENDEZ,R. GROBE, J. WILLIAMB.C.C. Division of Engineering & Technical Programs 82/07/14 13pp 15618 332 24X Fichs 50-373, 82/09/21, 82(00603/9
- F10050052 Ack receipt or 830723 ltr informing NRC of steps taken to correct violations noted in IE Safeguards Insp Rept 50-373/82-39
- NILLER, J.R. Division of Engineering & Technical Programs 82/09/30 REED, C. Commanuealth Edison Co. 2pp. 15605 188 24X Fiche 50-373,82/09/30.8210050052
- P210050056 Forwards response to NRC 820824 ltr re viplations noted in IE Safeguards Insp Rept 50-373/82-39 Response withheld (ref_10CFR73_21) DE(OEORGE, L O Commonwealth Edison Co 82/09/23 & Region 3, Office of Director 2pp 15605 190 24X Fiche 50-373,82/09/30.8210050052 KEPPLER, J G
- 10130376 Advises that installation of offsite dose calculation sus program fully operational tracking model & operational A-model will be delayed until 821231 to complete prime computer installation compover initaliation SWARTZIE D Commonwealth Edison Co 82/10/06 DENTON, H R D of Ruslear Reactor Regulation, Director 2pp 15682 098 24X Fiche 50-000 82/10/06 82/0130376 Difice
- 10270047 Releases public version of revisions to Quad Cities. Zion & Presiden emergency plan annexes & revised generating station emergency plan telephone directory FELTON. J M Division of Rules and Records 82/10/08 Document Management Branch ip 15877 313 24X Fiche 50-000,82/10/08, 8210270047
- 82102900m0 Forwards public version of Revision 3 to Quad Cities & Zion 2102/00/00 Forwards public version of Keysion 3 to Guad Cities & 210 emergency plan annores. Revision 2 to Dresden emergency plan annores. Revision 0 to Uyron omergency plan annore & revised generating station emergency plan telephone directory MODRE.R D Commonwealth Edison Co 82/07/30 DENTON.H R NRC - No Detailed Affiliation Given Spp 15877 314 24X Fiche 30-000.82/10/08.8210270047
- 821029008B Public version of revised generating station emergency plan telephone directory GALLE,D P Commonwealth Edison Co 82/08/12 43pp 15878 218 24% Fiche 50-000.82/10/08.8210290047
- 10220358 Provides info re organization & performance of depts 1022U39H Provides into re organization & performance ut depre-responsible for radiation protection activities,per 820702 commitment Training coordinator assigned in Apr 1782 to improve health physics training programs TRAMM, T.R. Commonwealth Edison Co. 82/10/14 DENTON.H.R. Dep of Nuclear Reactor Regulation, Director 9pp 15776-287 24X Fiche 50-000, 82/10/14, 8210220358

G Adjudicatory correspondence

- 8210040366 Responds to appeal re denial of FOIA request for four affidavits concerning allegations of improper const practices at facility Forwards requested info Page 4 of E Greve affidavit withheld (ref FOIA Exemption 7)
 DIRCKS.W J Office of the Executive Director for Operations 82/08/24 STEPTOE, P F Isham, Lincoln & Beals 2pp 15597 303 24% Fiche 50-373.82/08/24,8210040366
- --8210040375 Forwards four affidavits re safety problems at facility Proprietary info deleted from two affidavits DEVINE, T Institute for Policy Studies 82/05/11 FDRTUNA.R Director's Office, Office of Inspection and Enforcement 1p 15597 315 24X Fiche 50-373,82/08/24,8210040366
- --8207140491 Affidavit re results of sloppy concrete pours, holes & honeycombs in concrete Accumulated debris not disposed of prior to pour & too much concrete poured at one time Worker health not main concern of supervisors SHARTZ, D W Affilation Unknown 82/06/24 JOpp 15597 316 24% Fiche 50-373,82/08/24,8210040366
- --8207140494 Affidavit re safety-related const flaws in installation of pipes & supports Pipes & hanger supports not placed as specified GREVE.E Affiliation Unknown 62/04/22 App 15597 326 24X Fichm 50-373,82/08/24.8210040366
- ~-8207140497 Affidavit re damage to fire protection equipment such as sprinklers throughout plant during const Concerns raised over core dryllings of concrets reinforcement bars in containment walls & pedestal Hangers not as specified * Affiliation Unknown 82/04/21 6pp 19597 332 24X Fiche 50-373,82/08/24,8210040366
- --8207149500 Affidavit re sloppy workmanship leading to const damage Const crews core drilled through reinforcement bars, containment wall & reactor vessel pedestal around 694 foot elevation of Unit 1 4 Affiliation Unknown 82/04/21 3pp 19597 338 24X Fichs 50-373, 82/08/24 8210040366

- 82:0070042 Responds to 820816 ltr re third party review Forwards ltr responding to util selection of CF Braun & program for review of NAAC sys NOVAK, T M Assistant Director for Licensing 82/09/10 MGRELLA, S L Affiliation Unknown 2pp 15646-226 2 Fichs 50-373, 82/09/10, 8210070042
- --8210070045 Responds to 820813 ltr re third party review Forwards ltr responding to util selection of CF Braun & program for review of HVAC sys K/O stated encl NOVAK.T M Assistant Director for Licensing 62/09/10 DEVINE.T Affiliation Unknown ip 13646 228 24X Ficha 50-373,82/09/10, 8210070042
- --8210070051 Responds to 820813 ltr re third party review Forwards ltr responding to util selection of CF Braun & program for review of HVAC sys N/o stated encl NOVAK,T K Assistant Director for Licensing 82/09/10 HOWARD,A T Affiliation Unknown ip 19446 229 24X Fiche 50-373,82/09/10.8210070042
- --B210070055 Responds to 820824 ltr re third party review Forwards ltr responding to util selection of CF Braun & program for review of HVAC sys H/o stated encl NOVAK.T M Assistant Director for Licensing 82/09/10 900DIE.V B Illinois, Brate of 1p 15646 230 24X Fiche 30-373,82799/10 8210070042
- --8210070061 Responds to 820824 1tr re third party review Forwards 1tr responding to util selection of CF Braun & program for review of HVAC see N/o stated encl MOVAN.T M Assistant Director for Licensing 82/09/10 ROREM.B L Affiliation Unknown lp 15646 231 24X Fiche 50-373,82/09/10.9210070042
- --B210070066 Responds to B20B24 ltr re third party review Forwards ltr responding to util selection of CF Braun & program for review of HVAC sqs Revisions also encl NOVAK.T H Assistant Director for Licensing B2/09/10 000DL.E H Citizens Against Nuclear Power 1p 15646 232 24X Fiche 50-373,82/09/10,8210070042

P Operating license stage documents & correspondence

- 8208040341 Forwards INEL draft technical evaluation rept based on util response to 801222 generic ltr. "Control of Heavy Loads."
 Conference call to resolve open items planned in approx 4 wits W/o encl
 BCHWENCER.A Licensing Branch 2 82/07/02 DELGEORGE, L COmmonwealth Edison Co. 2pp 14978 002 24X Fiche 50-373, 82/07/02, 8208040341
- 6210010015 Discusses util 620824 & 27 technical proposals for independent HVAC sys review required by License Condition 2 C (33)(b) Selection of CF Braun as reviewer acceptable Listed comments on program should be considered MOVAK.T M Assistant Director for Licensing 82/09/08 REED.C Commonwealth Edison Co. 4pp 15577 242 24X Fiche 50-373,82/09/08,8210010015
- 8210040221 Forwards Revision 10 to "Mark II Design Assessment Rept" containing confirmatory assessment of containment design adequacy for pool dynamic loads developed in conjunction w/ long-term program described in NUREO-0808 SCHROEDER.C W Commonwealth Edison Co 82/09/24 SCHWENCER.A Licensing Branch 2 2pp 15587 179 24% Fiche 50-373,82/09/24.821004021
- --8210040223 "Mark II Design Assessment Rept." Revision 10 * Commonwealth Edison Co 82/09/30 82pp 15587 181 24X Fiche 50-373.82/09/24.8210040221
- 8210050097 Forwards evaluation of draft BWR owners group rept re alternative design mods of automatic depressurization sys (ADS) logic Incorporation of manual ADS inhibit switch w/timer recommended

 SCRROEDER: C W Commonwealth Edison Co 82/09/30 SCHWENCER: A Licensing Branch 2 30pp 15604 353 24X Fiche 50-373,82/09/30,82/09/30,82/09/30
- 8210130241 Responds to NRC 820706 request for addl info re high energy line breaks on postulated nonsafety power buses, nonsafety control sys or nonsafety sensors, including instrument line failures
 SCHROEDER.C W Commonwealth Edison Co 82/10/04 SCHHENCER.A Licensing Branch 2 11pp 15674 151 24X Fiche 50-373,82/10/04,8210130241
- 8210130233 Informs that EMD MI 9644 mod re diesel generator prelube oil pump mod is superior to NRC proposed fix & meets functional requirements of License Condition 2 C 21 b Prelube would degrade reliability of diesel generators SCHROEDER.C W Commonwealth Edison Co 92/10/06 SCHWENCER.A Licensing Branch 2 6pp 15675 220 24X Fiche 50-373,82/10/06,8210130233
- 8210260526 Forwards Revision 3 of Chapter 9 of "Offsite Dose Calculation Manual" OCLDEN. J C Commonwealth Edison Co 82/10/06 CASE, E 0 Office of Nuclear Reactor Regulation, Director 2pp 15805 137 24X Fiche 50-000,82/10/06.8210260526
- --8210260542 Revision 3 of Chapter 9 of "Offsite Dose Calculation Manual" Commonwealth Edison Co. 82/09/30 83pp 15805 139 24X Fiche 50-000, 82/10/06.8210260526
- 8210260151 Forwards supplemental response to EG&O draft technical evaluation rept of util 820622 itr re NUREO-0612, "Control of Heavy Loads at Nuclear Power Plants"
 SWARTZ-E D Commonwealth Edison Co 82/10/19 EISENHUT, D O Division of Licensing 17pp 15803 300 24X Fiche 30-373, 82/10/19, 8210260151
- O Inspection reports: IE Bulletins & correspondence
- 8210060379 Forwards IE Insp Rept 50-373/82-19 on 820317-19,24-26 & 0408 No moncompliance noted LITICE, W B Division of Engineering & Technical Programs 82/09/21 REED, C Commonwealth Edison Co 2pp 15618 330 24X Fiche 50-373,82/09/21,8210060379
- --8210060384 IE Insp Rept 50-373/82-17 on 820317-19,24-26 & 0408 No noncompliance noted Major areas inspected licensee action on previous insp findings re fire protection program HRNDEZ,R, QROBE,J, HILLIAMS,C C Division of Engineering & Technical Programs 82/09/14 13pp 15618 332 24X Fiche. 50-373, 82/09/21, 8210060379
- 8210190589 Forwards IE Hgt Meeting Repts 50-373/82-44 & 50-374/82-12 on 820830 & 0913 No noncompliance noted LITTLE, H 8 Division of Engineering & Technical Programs 82/09/29 REED: C Commonwealth Edison Co 2pp 15739 287 24X Fiche 50-373,82/09/29,8210190589

- --B21019060! IE Mgt Meeting Repts 50-373/82-44 & 50-374/82-12 on 820830 & 0913 No noncompliance noted Major areas discussed voids found in wall at 710 5-ft elevation on Column Line 16 JACKIM.! N , LIPINSKI.R Division of Engineering & Technical Programs 82/09/20 16pp 15739 289 24X Fiche 50-373,82/09/29,8210190589
- 8210050052 Ack receipt of 820923 ltr informing NRC of steps taken to correct violations noted in IE Safeguards Insp Rept 50-373/82-39
 MILLER, J.R. Division of Engineering & Technical Programs 82/09/30
 REED: Commonwealth Edison Co. 2pp 15605-188 24X
 Fiche 50-373-82/09/30-8210050052
- --8210050056 Forwards response to NRC 820824 ltr re violations noted in IE Safeguards Insp Rept 50-373/82-39 Response withheld (ref 10CFR73 21)
 DELOEDRGEL O Commonwealth Edison Co 82/09/23 KEPPLER.J C Region 3. Office of Director 2pp 15605 190 24X
 Fiche 50-373,82/09/30,8210050052
- 8210060266 Ack receipt of 820916 ltr informing NRC of steps taken to correct noncompliance noted in 1E Insp Rept 50-373/82-37 SPESSARD.R L Division of Project & Resident Programs 82/10/04 REED.C Commonwealth Edison Co 1p 15621 077 24X Fishe 50-373,82/10/04,8210060266
- --021006026B Responds to NRC B20B17 itr re-nuncompliance noted in II insp Rept 50-373/82-37 Corrective actions training conducted on B20709 w/entire instrument maint shop, covering LAP 300-9 & LIP 0M-02 which was documented for training records DELOEOREE. C Commonwealth Edison Co 02/07/16 KEPPLER, J 0 Region 3, Defice of Director 3pp 156/21 080 24x Fiche 50-373,82/10/04.8210060266
- 8210190682 Forwards IC Insp Rept 50-373/82-42 on \$20006-0901 No noncompliance noted LITTLE, W B Division of Engineering & Technical Programs D2/10/04 REED, C Commonwealth Edison Co 2pp 15738 146 24X Fiche 50-373, 82/10/04, 8210190682
- --8210190694 IE Insp Rept 50-373/82-42 on 820806-0901 No noncompliance noted Major areas inspected startup testing review of startup test results, complete review of safety relief valve & special startup test procedure MAURA, F. ROBINSON. D. JACKIW. I Division of Engineering & Technical Programs 82/09/29 4pp 15738 148 24X Fiche 50-373, 82/10/04, 8210190682
- 8208190233 IE Info Notice 80 35. Suppl 1. "Luaking & Disladged I-125 Implant Steeds " Svc list enc! CDB.L I Division of Fuel Facilities. Materials & Enfequency 82/10/06 Consolidated Edison Co of New York 66pp 15761 250 24% Fiche 50-000.82/10/06.8208170233
- 8210250105 Forwards IE Insp Repts 50-373/82-41 & 50-374/82-09 on 820802-31 & notice of violation STREETER, J F Division of Project & Resident Programs D2/10/07 REED, C Commonwealth Edison Co 2pp 15787 152 24X Fiche 50-373, 82/10/07, 8210250105
- ---9210250109 Notice of violation from insp on 820802-31 STREETERJF Division of Project & Resident Programs 82/10/07 Sp 15787 154 24% Fiche 50-373.82/10/07.82/10/250105
- --8210250116 IE Insp Repts 50-373/82-41 & 50-374/82-09 on 820802-31 Noncompliance noted unsupervised trainme performed reactivity manipulations GULDEMOND, W 0 . WRIGHT, 0 . MADISON, A Division of Project & Resident Programs 82/10/04 9pp 15787 155 24X Fiche 50-373, 82/10/07, 8210250105
- 820819023B IE Bulletin 82-03, "Stress Corrosion Cracking in Thick-Wall, Large-Diameter, Stainless Steel, Recirculation Sys Piping at DNR Plants " Svc list encl DEYOUND.R C Director's Office, Office of Inspection and Enforcement 82/10/14 Consolidated Edison Co of New York 115pp 15810 123 24X Fiche 50-000, 82/10/14, 8208190238
- 8210280122 Ack receipt of 820920 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-373/82-30 Corrective actions acceptable SPESBARD, R L. Division of Project & Resident Programs 82/10/22 REED, C Commonwealth Edison Co 2pp 15837 108 24X Fiche 50-373,82/10/22,8210280122
- --8210280125 Forwards response to NRC 820819 ltr re violations noted in IE Insp Rept 50-373/82-30 Corrective actions onsite review conducted on 820524 to determine abnormal trend in LERs associated wipersonnel errors # lifted leads relanded DELOEDROEL O Commonwealth Edison Co 82/09/20 KEPPLER, J 0 Region 3, Office of Director 7pp 15937 110 24X Fiche 50-373,82/10/22,8210280122

- R Periodic operating reports & related correspondence
- 8210130200 Forwards monthly operating rept for Sept 1982 DIEDERICH G J Commonwealth Edison Co 82/10/07 Hanagement Information Branch 1p 15675 243 24X Fiche 50-373,82/10/07. 8210130200
- --8210130215 Monthly operating rept for Sept 1982 ULCRICH J Commonwealth Edison Co 62/10/07 14pp 15675 244 24X Fiche 50-373,82,10/07,8210130200
- S Reportable occurrences LERs & related correspondence
- G_10040131 Forwards LER 02-098/03L-0 DIEDERICH: 0 J Commonwealth Edison Co 82/09/15 KEPPLER: J 6 Reginn 3, Office of Director 1p 15581 215 24X Fiche 50 373 82/09/15.8210040131
- U210040134 LER 82-098/03L-0 on 820826 discovered that rigid restraint installed on line [R167AB-1/2 Inch in place of snubber Caused by mechanical contractor design & installation error Snubber installed & evaluation completed SPENCER. O Commonwealth Edison Co 82/09/15 Region 3, Uffice or Director 2pp 15581 216 24X Fiche 50-373,82/09/15, 82:0040131
- #21(060251 Forwards LER #2 097/03L-0 DIEDERIUM, G J Commonwealth Edison Co #2/09/20 KEPPLER, J @ Region 3 Office of Director 1p 15621 201 24X Fiche 50 373.82:09/20.8210060251
- -93100A0252 LEA 82-099/O3L-0 on 820830.svc water liquid process radiation monitor drifted high 5 declared inoperative Caused by electronic failure of gamma detector Work request initiated to correct problem LUETIN Commonwealth Edison Co 82/097/20 Region 3, Office of Director 2pp 15821 202 24% Fiche 50-373,82/09/20,8210060251
- 8210190462 Forwards NPDES noncompliance repts PIEDERICH.G J. Commonwealth Edison Co. 82/09/29 KEPPLER, J.G. kegion 3, Office of Director. 2pp. 15951 141 24X Fichs 50 373 82/09/29,8210190462
- 8210190468 NPDFS noncompliance notification on 820801.total suspended solids & from in outfall ODIc low yet waste radwaste discharge tanks exceeded allowable limits Caused by mechanical problems w/radwaste evaporators a Commonwealth Edison Co 82/09/29 lp 15951 143 24X Fiche 30-373,82/07/27,8210190462
- -02(019048) NPDES noncompliance notification on 820910, oil & grease in outfell Olic low vot waste radwaste discharge tanks exceeded allowable limit Caused by mechanical failure of radwaste gvaporator resulting in poor quality water s Commonwealth Edison Co 82/09/29 lp 15740 (80 24% fiche 50 373,82/09/29,82/0190462
- 621019048/ Forwards NPDES noncompliance repts OIEDERICH, G J Commonwealth Edison Co 82/07/29 KEPPLER, J G Region J, Office of Director Rep 15738 325 24X Fiche 50 373,82/07/29,82(0190487
- -8210190494 NPDES noncompliance notification on 820903, total iron in outfall 001c low vol waste regeneration wastes solution discharge tank exceeded allowable limit Caused by temporary hydrogen peroxide sys hot operating property Commonwealth Edison Ca 8209/29 Ip 15735 327 24X Fichs 50-373,82/09/29.8210190467
- 6210170478 Forwards NPDES noncompliance repts
 DIEDERICH OJ Commonwealth Edison Co 82/09/29 KEPPLER, J G
 Region 3, Office of Director 2pp 19735 340 24X
 Fiche 50-373.82/09/29,8210170498
- --8210190503 NPDES noncompliance notification on 820913.pH at outfall Odic low vol waste wastewater treatment facility fell out of specs Caused by acid waste generated from Unit 2 const activities Work request initiated to install pH monitor Commonwealth Edison Co 82/09/29 1p 15735 343 24X Fiche 50-373.82/09/29.8210190498
- 8210170509 Forwards NPDES noncompliance repts
 DIEDERICH, 0 J Commonwealth Edison Co 82/09/29 KEPPLER, J G
 Region 3, Office of Director 2pp 15740 199 24X
 Fiche 50-373, 82/09/29, 8210170309

- --8210190514 NPDES noncompliance notification on 820914, total suspended solids & Fron et outfall Oolc low vol waste wastewater treatment facility exceeded allowable limits Caused by upset pH due to Unit 2 const activities Commonwealth Edison Co 82/09/29 Ip 15740 202 24X Fiche 50-373,82/09/29,8210190509
- 8210190522 Forwards NPDES noncompliance repts
 DIEDERICH, G J Commonwealth Edison Co 82/09/29 KEPPLER, J G
 Region 3. Office of Director 2pp 15751 319 24X
 Fiche 50-373, 82/09/29, 8210190522
- --8210190525 NPDES noncompliance notification on 820909, total iron at outfall Olic low vol waste wastewater treatment facility exceeded allowable limit Caused by upset ph due to Unit 2 const activities Work request initiated to install monitor 4 Commonwealth Edison Co 82/09/29 1p 15751 321 24X Fiche 50-373,82/09/29,8210190322
- 8210200002 Forwards NPDES noncompliance repts for facility DIEDERICH, G J Commonwealth Edison Co 82/09/29 KEPPLER, J G Region 3, Office of Director 2pp 15756 327 24X Fiche 50-373, 82/09/29, 8210200002
- --8210200007 NPDEB noncompliance notification on 820914, buildup of resin fines & other fine solids carried through strainers & sumps into discharge tank Cause not stated Regenerative waste solution discharge tank will be cleaned * Commonwealth Edison Co 82/09/29 ip 15756-330 24X Fiche 50-373,82/09/29,8210200002
- 8210130234 Forwards LER 82-107/03L-0 DIEDERICH O J Commonwealth Edison Co 82/09/30 KEPPLER, J G Region 3, Office of Director 1p 15675 216 24X Fiche 50-373, 82/09/30, 8210130234
- --8210130236 LER 82-107/03L-O on 820812 control rad drive pump A tripped off on low suction pressure & control rad drive pump B failed to start Caused by low CY storage tank lavel & valve (CD109 condengabe/CRD reject being abnormally closed WINTERHOFF, D Commonwealth Edison Co 82/09/30 Region 3, Office of Director 3pp 15675 217 24X Fiche 50-373,82/09/30, 82/030238
- 8210190344 Forwards LER 82-103/03L-0 DIEDERICH.0 J Commonwealth Edison Co 82/10/04 KEPPLER.J Q Region 3. Office of Birsctor ip 15737 245 24X Fiche 50-373,82/10/04,8210190344
- --8210190346 LER 82-103/03L-0 on 820919. Hi Rad alarm sounded Operator checked chart recorder & noticed A RHR svc water radiation monitor read gownscale Alarm caused by trie in power supply to monitor Power supply reset KAY. D Commonwealth Edison Co 82/10/04 Region 3, Dffice of Director 2pp 15737 246 24X Fiche 50-373, 82/10/04.8210190344
- 8210190050 Forwards LER 82-104/03L-0 DIEDERICH/O J Commonwealth Edison Co 82/10/05 KEPPLER: J Q Region 3, Office of Director 1p 15742 136 24X Fiche 50-373, 82/10/05, 8210190050.

- 8210190606 Revised Final Deficiency Rept B2-10 re RCIC underground piping Replacement piping work complete except for tie to Unit 1 RCIC sys inside bldg which requires 4-day outage Work will be completed during first available outage SCHRGEDER, C W Commonwealth Edison Co B2/10/08 KEPPLER, J G Region 3, Office of Director ip 15739 353 24X Fiche 50-373, 82/10/08, 8210170606
- B210250152 Forwards LER 02-102/03L-0 DIEDERICK, G J Commonwealth Edison Co 02/10/15 KEPPLER.J G Region 3, Office of Director 1p 15789 311 24X Fichs 50-373, 82/10/15, 8210250152
- -8210250163 LER 82-102/03L-O on 820916 reactor vessel low water level scram setpoint BPIS-1821-N0248 found out of calibr Caused by instrument drift Required talerance under revision Instrument to be calibr weekly WINTERHOFF.D Commonwealth Edison Co 82/10/15 Region 3, Defice of Director 2pp 15789 312 24X Fiche 50-373.82/10/15, 22/10/15
- 8210260210 Forwards LER 82-110/03L-0 DIEDERICH.O J Commonwealth Edison Co 82/10/18 KEPPLER.J 0 Region 3. Office of Director 1P 15804 266 24X Fiche 50-373.82/10/18.8210260210
- --8210260221 LER B2-110/O3L-O on 820920, standby liquid control tank level measured low Caused by evaporation Trending of evaporation rate initiated under AIR 1-82-513 Tank level raised * Commonwealth Edison Co 82/10/19 Region 3, Office of Director 2pp 15804 267 24% Fiche 50-373,82/10/18,8210260210
- 8210260227 Forwards LER 62-111/03L-0 DIEDERICH, 0 J Commonwealth Edison Co 82/10/18 KEPPLER, J Q Region 3, Office of Director 1p 15804 259 24X Fiche 50-373, 82/10/18, 8210260227
- --B21026023B LER B2-111/03L-0 on B20927.high airborne activity discovered in raduaste reboiler room Caused by insufficient weld penetration of tee between valves IB21-F532 to IB21-F532 Tee cut out & replaced Reboiler returned to svc Commonwealth Edison Co B2/10/18 Region 3. Office of Director 2pp 15804 260 24% Fiche 50-373.B2/10/1B.9210260227
- 8210260311 Forwards LER 82-108/03L-0 DIEDERICH, 0 J Commonwealth Edison Co 82/10/18 KEPPLER, J 0 Region 3, Office of Director 1p 15799 355 24X Fiche 50-373, 82/10/16,8210260311
- --9210260313 LER 92-108/03L-0 on B20920.LIS-NB-187.ADS accumulator backup N2 channel functional & calibr discovered not performed as specified by Tech Spec Caused by surveillance procedure not entered into program Procedure revised WINTERNOFF.D Commonwealth Edison Co 82/10/18 Region 3. Office of Director 2pp 15799 356 24X Fiche 50-373.82/10/18. B210240311
- 8210260115 Forwards LER 82-114/01T-0 DIEDERICH 6 J Commonwealth Edison Co 82/10/19 KEPPLER, J Q Region 3, Office of Director ip 15799 109 24X Fiche 50-373, 82/10/19, 8210260115
- --B21026011B LER 92-114/01T-0 on B21005, installed configuration of HVAC duct hanger 1382 did not match design Drawing M-1538 Caused by misinterpretation of FCR by draftsman Sargent & Lundy Drawing H-1538 will be revised prior to 821008 OIEBEKER, J Commonwealth Edison Co 82/10/19 Region 3, Office of Director 2pp 15797 110 24% Fiche 50-373,82/10/19, 8910260115

- --8210260321 LER 82-106/03L-0 on 820920, during performance of LOS-PC-QI, valve 1833-F019 did not close Caused by foreign mat1 blocking valve open Outboard isolation valve 1833-F020 closed Blockage removed prior to work initiation HIETALA, J Commonwealth Edison Co 82/10/19 Region 3, Office of Director 2pp 15799 336 24X Fiche 50-373, 82/10/19, 22/10/317
- T Hearing transcripts on non-antitiust matters
- B21021050B Forwards Commission determination statement releasing B20622 transcript of discussion of full power GL Pp 1-66 CMILKS J Office of the Secretary of the Commission B2/10/0'; Public Document Branch 2pp 15784 204 24% Fiche 50-373.82/10/05, 8210210508
- DOCKET 50-374 LASALLE COUNTY STATION, UNIT 2
- A Application/construction stage documents & correspondence
- #21001000B Responds to FOIA request for 19 categories of documents re nuclear reactor events & safety problems Forwards documents listed in App A FELTON, J H Division of Rules and Records #2/06/28 UDELL, R A Critical Mass Energy Project | 15pp | 15727 005 | 24X Fiche 50-000, #2/06/28, #21001000B
- --8008050265 Discusses addit required info to better define patential for cracking in reactor vessel notices
 NOONAN, V.S. Assistant Director for Materials & Qualifications
 Engineering 80/05/05 TEDESCO.R.L. Assistant Director for
 Licensing 2pp 15727 176 24X Fishe 50-000.82/06/28.8210018088
- 820B040341 Forwards INEL draft technical evaluation root based on util response to 801222 generic itr. "Control of Heavy Loads " Conference cail to resolve open items planned in approx 4 wks W/o enci SCHWENGER.A Licensing Branch 2 82/07/02 DECGEORGE, L C Commonwealth Edison Co 2pp 14978 002 24% Fiche 50-373,82/07/02,8208040341
- 8210040221 Forwards Revision 10 to "Mark II Design Assessment Rept" containing confirmatory assessment of containment design adequacy for pool dynamic loads developed in conjunction w/ long-term program described in NURCO-0808 BCHRIEDER, C.W. Commonwealth Edison Co. 82/09/24 BCHWENCER, A. Licensing Branch 2 2pp. 15987 179 24X Fiche 50-373,82/09/24,8310040221
- --8210040223 "Mark II Design Assessment Rept." Revision 10 * Commonwealth Edison Co 82/09/30 82pp 15587 181 247 Fiche 50-373.82/09/24.8210040221
- 9210050097 Forwards evaluation of draft BMR owners group rept re alternative design mods of automatic depressurization sys (ADB) logic Incorporation of manual ADS inhibit switch w/timer recommended SCHMRDERR.C W Commonwealth Edison Co B2/09/30 SCHWENCER.A Licensing Branch 2 30pp 15604 353 24X Fiche 50-373,82/09/30,8210050097
- 8210130241 Responds to NRC 820706 request for add1 info re high onergy line breaks on postulated monsafety power buses, nonsafety control sys or homsafety sensors, including instrument line failures

 8CHRDEDER: C W Commonwealth Edison Co 82/10/04 SCHWENCER: A
 Licensing Branch 2 lipp 15674 151 24X Fiche 50~373:82/10/04,
 8210130241
- 8210130233 informs that EMD MI 9644 mod re diesel generator prelube oil pump mod is superior to NRC proposed fix k meets functional requirements of License Condition 2 C 21 b Prelube would degrade reliability of diesel generators SCHROEDER, C W Commonwealth Edison Co 82/10/06 SCHHENCER, A Licensing Branch 2 6pp 15675 220 24X Fichs 50-373,82/10/06,8210130233
- 8210260526 Forwards Revision 3 of Chapter 9 of "Offsite Dose Calculation Manual" QULDEN.JC Commonwealth Edison Cp 82/10/06 CASE.E 0 Offics of Nuclear Reactor Regulation, Director 2pp 15805-137 24X Fiche 50-000.82/10/06

- B210260542 Revision 3 of Chapter 9 of 'Offsite Dose Calculation Manual" * Commonwealth Edison Co 82/09/30 83pp 15805 139 24X Fiche 50-000 82/10/06.8210260526
- 6210260151 Forwards supplemental response to EG&O draft technical evaluation rept of util 820622 ltr re NUREG-0612. "Control or Heavy Loads at Nuclear Power Plants '
 SMARTZ.E D Commonwealth Edison Co 62/10/19 EISENHUT, D 0
 Division of Licensing 17pp 15803 300 24X Fiche 50~373, 82/10/19, 6210260151
- F Security medical emergency & fire protection plans
- 5.0%.90125 Releases public vorsion of revised generating station emergency plan corporate command ctr emergency plan implementing procedure FELTON JM Division of Rules and Records 82/09/16 Document Management Branch to 15544 122 24% Fiche 90-000,82/09/16.
 - 8207270187 Forwards public version of Revision 4 to generating station emergency plan corporate command c41 Emergency Plan Implementing Procedure EDF-3 'Environ/Emergency Coordinator "Receipt form encl PAJCH/MI J E Commonwealth Edison to 82/09/01 DENTON, H R NRC No Bealled Affiliation Given 1p 15564 123 24X Fische 50-000 86/09 to 82/09/0125
 - 8207270.25 Public version of Revision 4 to generating station emergency plan corporate command Ctr Emergency Plan Implementing Procedure EOF 3. "Environ/Emergency Coordinator"
 PAJUMSMI JE (commonwealth Edison Co 82/08/31 lipp 15554 17: 24/ Firms 50-000, 07/07/16/8209270175
- 6.10130.476 Advises that installation of offsite dose calculation sysprogram fully operational tracking model & operational A model will be delayed until 821231 to complete prime computer installation SHARTZ E D. Commonwealth Edison Co. 82/10/06 DENION, R.R. Offsice W. Nuclear Reactor Regulation. Director 2pp 15682 098 247 1106 50 000 62/10/06 82/10/1376
- C.10270047 Releases public version or revisions to Guad Cities. Zion & Greaden emergency plan annexes & revised generating station emergency plan telephone directory (LTON / H Division or Rules and Records 82/10/08 Document Management Branch 1p 1587/313 24% Fiche 50-000.82/10/08. U210290407
 - MAIO270060 Forwards public version or Revision 3 to Quad Cities & Zion emergency plan annoies Revision 2 to Dresden emergency plan annoi Revision 0 to Nyron emergency plan annoi & revised generating station emergency plan telephone directory MUCRE R D. Commonwealth Edison Co. 82/07/30 DENTON, H R. NRC No Detailed Affiliation Given 5pp. 15877-314 24X
 Fiche 50 000 82/10/08 8/10290047
 - 82102900BB Public version of revised generating station emergency plan telephone directory GALLE D P Commonwealth Edison Co 82/08/12 43pp 15878 RIB 24X Fiche 50-000.62/10/08.8210290047
- 92)0220358 Provides info re organisation & performance of depts responsible for radiation protection activities, per 820702 commitment Training coordinator assigned in Apr 1982 to improve health physics training programs TRAMMITR Commonwealth Edison Co 82/10/14 DENTONIHR Office or Nuclear Reactor Regulation, Director 9pp 15776-287 24X Fiche 50-000,82/10/14,6210220358
- G Adjudicatory correspondence
- 6210040366 Responds to appeal re denial of FOIA request for four affidavits concerning allegations of improper const practices at facility Forwards requested info Page 4 of E Opeve affidavit withheld (ref FOIA Elemption 7) DIRCKS.W J Office of the Executive Director for Operations 82/08/24 STEPTOE.P P Isham Lincoln & Beale 2pp 15597 303 24 (Ficke 50-374.82/08/24.6210040366
- --8210040375 Forwards four affidavits no safety problems at facility Proprietary info deleted from two affidavits DEVINE, T Institute for Policy Bitudias 82/05/11 FORTUNA, R Director's Office. Office of Inspection and Enforcement ip 1597-315 24X Fiche 50-374, 82/08/24, 8210040366

- --B207140491 Afridavit re results of sloppy concrete pours, holes & honeycombs in concrete Accumulated debris not disposed of prior to pour & too much concrete poured at one time Worker health not main concern of supervisors
 SMARTZ,DW Affillation Unknown B2/06/24 10pp 15597 316 24X Fiche 50-374, B2/06/24, B210040366
- --8207140494 Affidavit re safety-related const flaws in installation of pipes & supports flipes & hanger supports not placed as specified GREVE.E Affiliation Unknown 92/04/22 App 15597 326 24X Fiche 50-374,82/08/24,8210040366
- --8207149497 Affidavit re damage to fire protection equipment such as sprinklers throughout plant during const Concerns raised over core drillings of concrete reinforcement bars in containment walls & pedestal Hangers not as specified # Affiliation Unknown 82/04/21 6pp 19597 332 24% Fiche 50-374,82/09/24,8210040366
- --8207140500 Affidavit re sloppy workmanship leading to const damage Const crews once drilled through reinforcement bars, containment wall & reactor vessel pedestal around 694 foot elevation of Unit 1 # Affiliation Unknown 82/04/21 3pp 15597 338 24X Fiche 50-374,82/08/24,8210040366
- 8210260501 Advises of State of IL intent to file comments on concrete element design margin summary Comments will be incorporated into IOCFR2 206 show cause request GOODIC, J S Illinois, State of 82/10/15 DENTON.H R Office of Nuclear Reactor Regulation, Director 1p 15806 209 24X Fiche 50-374, 82/10/15, 8210260501
- G inspection reports. IE Bulletins & correspondence
- E210190589 Forwards 1E Mgt Meeting Repts 50-373/82-44 & 50-374/82-12 on 820830 & 0913 No noncompliance noted LITEL, No. 5 Division of Engineering & Technical Programs 82/09/29 REED. C. Commonwealth Edison Co. 2pp 15739 287 24X Fiche 50-373, 82/09/29, 8210190589
- 8210170601 [E Mgt Heuting Repts 50-373/82-44 & 50-374/82-12 on 820830 & 0713 No noncompliance noted Major areas discussed voids found in wall at 710 5-ft elevation on Column Line 16 JACKIW: I N . LIFINSKI.R Division of Engineering & Technical Programs 82/07/20 16pp 15739 289 24X Fiche 50-373,82/07/29,8210170589
- 8208190233 IE Info Notice 80-35, Suppl 1, "Leaking & Dislodged I-125 Implant Seeds " Svc list encl COBBL 1 Division of Fuel Facilities, Materials & Safeguards 82/10/06 Consolidated Edison Co of New York 66pp 15761 250 24% Fiche 50-000.82/10/06.8208190233
- 8210250105 Forwards IE Insp Repts 50-373/82-41 & 50-374/82-09 on 820802-31 & notice of violation STREETER, J F Division of Project & Resident Programs 82/10/07 REED.C Commonwealth Edison Co 2pp 15787 152 24X Fiche 50-373, 82/10/07, 8210250105
- --8210250109 Notice of violation from insp on 820802-31 8TREETER, J F Division of Project & Resident Programs 82/10/07 1p 15787 154 24% Fiche 50-373,82/10/07,8210250105
- --8210250116 IE Insp Repts 50-373/82-41 & 50-374/82-09 on 820802-31 Noncompliance noted unsupervised traines performed reactivity manipulations GULDEMOND. H O . WRIGHT. O . MADISGN. A Division of Project & Resident Programs 82/10/04 9pp 15787-155 24X Fiche 50-373.82/10/707-8210250105
- 8208190238 IE Bulletin 82-03, "Stress Corrosion Cracking in Thick-Wall, Large-Diameter: Stainless Steel, Recirculation Sys Piping at BMR Plants "Svc list encl DEYGUND, R C Director's Office, Office of Inspection and Enforcement 82/10/14 Consolidated Edison Co of New York 115pp 15810 125 24X Fiche 50-000.82/10/14,8208190238
- 8 Reportable occurrences, LERs & related correspondence
- 82:0190606 Revised Final Deficiency Rept 82-10 re RCIC underground piping Replacement piping work complete except for tie to Unit 1 RCIC sys inside bldg which requires 6-day outage Work will be completed during first available outage SCHROEDER, C W Commonwealth Edison Co B2/10/00 KEPPLER, J G Region 3, Office of Director 1p 15739 353 24X Fiche 50-373, 82/10/08, 82/0170606

- DOCKET 50-382 WATERFORD GENERATING STATION, UNIT 3

 A Application/construction stage documents & correspondence
- 8209220135 Forwards pump & valve inservice test plan for approval Requests relief from ASME Code Section XI per 10CFR50 55a MAURIN.L V Louisiana Power & Light Co 82/09/13 NOVAK.T H Assistant Director for Licensing 4pp 14938 001 24X Fiche 50-382.82/09/13,8209220135
- --820922013? Response to provisions of 10CFR50 55a(g) inservice testing plan for Class 1,2 & 3 pumps & valves.Revision 0 to Louisiana Power & Light Co 82/08/16 2fipp 14938 005 24X Fiche 50-382.82/09/13 8209220135
- 6210180255 Forwards description of open items found as result of review of 820625 submittal re-purge valve operability Schedule for response requested YERRIGAN.J.D. Licensing Branch J. 62709723 MAURIN.L.V. Louisians Power & Light Co. 4pp. 15746-239 24X Fiche 50-382.82709723.
- 8210040110 Requests test exception to delete stuck control rod physics test Test has potential for placing reactor in unsafe contiguration MAURINLL V Louisiana Power & Light Co. B2/09/27 NOVAK, T N Assistant Director for Licensing 3pp 15580 347 24X Fiche 50-382, 82/09/27, 8210040110
- 8210040191 Summarizes 820903 site meeting re pending revision to FSAR, Chapter 14 MAURIN.L V Louisiana Power & Light Co 82/09/27 NGVAK, T M Assistant Director for Licensing 2pp 15583 187 24X Fiche 50-382,82/09/27,8210040191
- 8210260532 Notifies of acceptance of Revision A of Torrey Pines Technology QA program plan EISEEHUUT.D O Division of Licensing 82/09/28 MCLENDON, O D Louisiana Power & Light Co 2pp 15830 191 24X Fiche 50-382.88/09/28.8210260532
- 8210210317 Forwards portions of Franklin Research Ctr technical evalvation rept "Control of Heavy Loads" to ANSI 8td Nt4 4-1978 to assist in preparing response on special lifting devices, per 820921 conference call commitment KERRIGAN.J D Licensing Branch 3 82/09/29 MAURIN.L V Louisiana Power & Light Co. 5pp 15782 082 24X Fiche 50-362.82/09/29, 8210210317
- 8210260285 Notification of 821003-05 meeting w/util in Taft.LA to audit facility training program
 BLACK.5 Licensing Branch 3 82/09/29 KERRICAN.J Licensing
 Branch 3 3pp 15830 153 24% Fiche 50-382.82/09/29.8210260285
- 8210150347 Forwards Revision B to "Independent Design Review of Waterford Steam Electric Station Unit 3 Emergency Feedwater Sys." program plan MCLENDON: 0 D Louisiana Power & Light Co 82/10/04 NOVAK, T M Assistant Director for Licensing 2pp 15704 282 24X Fiche 50-382, 82/10/04, 8210150347
- --82101503\$3 Revision B to "Independent Design Review of Waterford Steam Electric Station Unit 3 Emergency Feedwater Sys," program plan * Torrey Pines Technology 82/09/13 18pp 15704 284 24X Fiche 50-382,82/10/04,8210150347
- 8210250355 Forwards response to 820513 Human Factors Engineering audit of facility control room Revised rept will be issued 821104 Util purchasing full scope control room simulator to study recommended changes MAURINL V Louisiana Power & Light Co 82/10/20 NQVAK.T M Assistant Director for Licensing 9pp 15790 036 24X Fiche 50-382, 62/10/20, 8210250355
- F Security, medical, emergency & fire protection plans
- 8210040168 Forwards suggested dates & schedule for conducting amergency preparedness drills, exercise for score & appraisal for facility HAURIN-L V Louisiana Power & Light Co 82/09/24 NOVAK, Y M Division of Licensing 2pp 15582 315 24X Fiche 30-382,82/09/24,8210040168
- B210010370 Forwards summary of five qualification tests. ANI acceptance itrs & excepts from five qualification test repts Repts include "Fire Qualification Test on Silicone Foam Floor Penetration Seals"

 MAURIN.L V Louisiane Power & Light Co B2/09/28 NOVAK, T M Assistant Director for Licensing 161pp 15589 001 24X

 Fiche 50-382, 82/09/28 8210010370

- 8210260362 Forwards revised tert of racility info safety brochure Revision improves readability & reflects comments received from NRC & FEMA Tert will be incorporated into printer proof by 821102 per ABLB requirement Comments requested by 821103 MAURIN.L V Louisiana Power & Light Co 82/10/22 NOVAK.T M Division of Licensing 20pp 15803 158 24% Fische 90-382,82/10/22,82/10/24,82/10/24
- G Adjudicatory correspondence
- 8210010435 Certifies sec on 820924 of applicant response to comments of parties on emergency public info blockure Sec list encl RIDGNAY, D A Louisiana Power & Light Co 82/09/27 2pp 15570 203 24X Fiche 50-382.82/09/27, 8210010435
- 8210040057 Memorializes 820928 telcon between ASLB, NRC & Joint Intervenors deferring 820927 telcon to set hearing date until Joint Intervenors pleadings on emergency into brochure tiled

 TURN, S.E. Hearing Branch 1 82/09/29 HOLFE, S.J., JORDAN, H.H., FOREMAN, H. Atomic Safety and Licensing Board Panci 2pp 15981-952 24X Fiche 50-382, 82/09/29, 8210040059
- B210050346 Motion to dismiss license application for failure to comply w/discovery Intervenors unable to prepare adequately for defense of interests against impact of facility on lives & livelihoods GROESCH.O.L. Joint Intervenors-Waterford B2/09/29 Atomic Safety and Licensing Board Panel 2pp 15609 013 24x Fiche 50-382,02/09/29,8210050366
- -8210050372 Request for production & copy of certain documents
 Documents should be delivered within 15 days in order to
 avoid prejudicing intervenors in subsequent proceedings
 GROESCH O. L. Joint Intervenors Naterford 82707/27 Louisima
 Power & Light Co. 2pp. 15609 015 24X Fiche 50-382.827077.79.
- -8210050378 Metion to disallow introduction of second evacuation brochure, grant judgment on first brochure & allow new evidence & testimony to be presented on synergism & evacuation contentions Cortificate of Svc encl GROESCH, O. L. Joint Intervenors-Naterford B2/09/29 Atomic Safety and Licensing Board Panel (Ipp. 15609-01/ 24X Fiche 50-382,82/09/29,8210050366)
- \$210040061 Advises that MRC does not oppose Joint Intervenois Legiert for cross-examination of NRC & FEMA employees or RM9901 afridavits Cross-examination must relate to scope of dilect testimony which may be introduced by IRC &/or FEMA TURK S E Hearing Dranch 1 B2/09/30 WOLFE, 5 / JORDAN, W H . FOREMAN H Atomic Safety and ticensing Board Panel 2pp 15381 250 24% Fiche 50-382.82/09/70, 8210040061
- 8210040188 Response opposing Joint Intervenors G20729 mutton re uti) emergency info brochure & reopened hearings Ruling un adequacy of Uti) emergency info brochure should be deferred Certificate of Svc encl

 TURK.S E Hearing Branch 1 82/10/04 Atomic Safety and Licensing Board Panel 1 1pp 15613 227 24X Fiche 50-362.612/10/0.8210060188
- 6210070124 Respanse opposing Joint Intervenors 820727 motion to reoper Requests not Founded in fact or law & fly in face of any sense of administrative discipling & procedural regularity Some requests defy logic Certificate of Svc encl (RNRCHILL, B W. Louisiana Power & Light Co. (RURCHILL, B W. Louisiana Power & Light Co. (RURCHILL, B W. Atomic Safety and Licensing Board Panel 13pp 15627-046 24X fichs 50-382,82/10/04
- 8210070197 Memorialites 821001 telcon w/NRC, util, Joint Intervenors & ASLB NRC & applicant to file responses to Joint Intervenors motions by 821006 Svc list enc!
 RIDGWAY, D.A. Shaw, Pittman, Potts & Trowbridge RIDGWAY, D.A.
 Louisians Power & Light Co. 82/10/04 WDLFE, S.J. Atomic Cafety an Licensing Board Panel 5pp 13634 269 24X Fiche 50-382, 82/10/04, 8210070197
- 8210080070 Objections to Joint Intervenors 820927 request for production of documents 5 opposition to motion to dismiss application for failure to make discovery NRC regulations for discovery not followed W/Certificate of Svc TURK.8 E Hearing Branch i 82/10/06 Joint Intervenors-Waterford 14pp 15643 016 24X Fiche 50-382,82/10/06 8210080070
- 8210080086 Erratum to applicant 821004 response to Joint Intervenors motion to reopen record Certificate of Bvc encl CHURCHILL, B W. Louisiana Power & Light Co. CHURCHILL, B W. Shaw, Pittman, Potts & Trowbridge 82/10/06 Atomic Safety and Licensing Board Panel 3pp 15640 219 24X Fiche 50-362,82/10/06,8210080086

1.4

H

- 8210080770 Response apposing Joint Intervenors 820929 motion to dismiss for failure to make discovery to objections to request for production of documents Discovery requests prohibited by Commission rules Churchill. B W Louisiana Power & Light Co CHURCHILL, B W Shaw, Pittnan, Poits J. Trombridge 82/10/06 Atomic Safety and Licensing Board Panel 13pp 15640 223 24X Fiche 50-382, 82/10/06, U2100800990
- 8210210372 Hemorialises 821013 conforence call w/Joint Intervenors to procedures for appealing ASLB actions Svc list encl RIDGWAY.D A Shaw. Pittnam. Potts & Troubridge RIDGWAY.D A Louisiana Power & Light Co 82/10/18 WOLFE.S J Atomic Safety and Licensing Board Panel App 1576J 164 24X Fiche 50-382,82/10/18,0210210372
- 6.10210404 Henorandum & order denying Joint Intervenors 820929 motion to dismiss for failure to make discovery & granting portion of motion requesting production > copying of documents WOLFE/S J Atomic Safety and Licensing Board Panel 82/10/18 Joint Intervenors-Waterford 9pp 15765 135 24X Fiche 50-382 82/10/18.8210210404
- 8210210412 Menorandum * order granting portion of util 820923 motion, allowing util initially proposed public info brochure to be withdrawn * reopening record to receive evidence on adequacy of util revised brochure WOLFF, S.J. Atomic Safety and Licensing Board Panel 82/10/18 Louisiana Power & Light Co. 11pp. 15765-088 24x Fiche 50-382,82/10/18.8210210412
- n210210152 Forwards JH Benton 2 AL Lookabough affidavit re emergency into brochure Artidavit identical to 820901 affidavit but includes lookabaugh signature
 TURK S £ Hearing Branch I 82/10/19 WOLFE, S J , JORDAN, W H , FOREMAN, H Atomic Sarety and Licensing Board Panol 3pp
 15766-077 24x Fichs 50-382.82/10/19.82102(0)52
- -8210210159 Arfidavit of JW Denton t AL Lookabaugh re emergency info brockure Util has revised brockure incorporating FEMA comments Guidance criteria on ed info on radiation met BENTON J W . LOOKABAUGH A L NRC - No Detailed Affiliation Given BENTOM, J W . Federal Emergency Management Agency 82/09/30 9pp 19746 080 24% Firhe 50-382 82/10/19.8210210152
- 8210210466 Order admitting three exhibits into evidence to be cited in upcoming partial initial decision on Unrosolved Bafety Issues A 45 re abutdown DHR & A-46 re seismic qualitication of equipment WOLFELS Of Atomic Solety and Licensing Doard Panel 82/10/19 2pp 15/63 047 247 Fiche 50 382 82/10/19 8210210466
- 6210220477 Advises that time for Commission to act to review ALAB-690 expired Commission declined review Decision became final agency action on 821018 UHLU-S J. Office of the Secretary of the Commission 82/10/21 Office of the Executive Legal Director 1p 15779 129 24X Fiche 50-782.02/10/21.0210220473
- 8210250288 Informs of util pending application for SNM license Util requested license be effective as of 830131 until plant OL issued No ASLB action necessary TURK, S.E. Hearing Branch 1 82/10/22 FOREMAN, H., WDLFE, S.J., JORDAN, M. H. Atomic Sefety and Licensing Board Panel 1p 15791 L64 24x Fiche 50-382, 82/10/22,8210250288
- 8210260423 Advises that author 621018 ltr memorializing 821013 telcon should have included FCMA representative Cassidy as participant Svc list encl RIDGNAY.D A Shaw. Pittman, Potts & Trowbridge RIDGNAY,D A Louisiana Power & Light Co 82/10/22 WOLFE,S J Atomic Safety and Licensing Board Panel 2pp 15806 050 24% Fiche 50-382,82/10/22,6210260423
- 82:0280387 Provides list of correspondence from applicant to NRC & FEMA since record closed on 820512 Some ltrs & svc list encl Related correspondence CHVRCHILL, B W Shaw, Fittman, Potts & Trowbridge CHVRCHILL, B W Louisiana Power & Light Co 82/10/25 GROEBCH, G Affiliation Unknown 8pp 15845 169 24X Fishe 50-382,82/10/25,8210280387

H General correspondence

8210210167 Requests copying svcs for encl documents Record reppend to admit into evidence BZ0827 ltr & appended affidavit.util 820910 response & 82099 attachment W/o encls WCLFE.8 J. Atomic Safety and Licensing Board Panel 82/10/19 Alderson Reporting 1p 15766 074 24X Fiche 50-382,82/10/19,8210210167

- K Utility Final Safety Analysis Report (FSAR) & amends
- 8210270190 Forwards Amend 29 to FSAR.addressing organization & training program
 MAURIN.L V Louisiana Power & Light Co 82/10/20 Office of Nuclear Reactor Regulation. Director 3pp 15827 269 24X
 Fiche 50-382.822/10/20.8210270190
- --8210270193 Amend 29 to FSAR Twenty-five aperture cards available in PDR + Leuisiana Power & Light Co 82/10/31 308pp 15827 274 24X Fiche 50-382,82/10/20.8210270190
- M Antitrust correspondence
- 8210270327 Forwards notice of finding of no significant antitrust changes & time for filing request for le-evaluation TOALSTON.A Antitrust & Economic analysis Branch (Utility Finance) 82/10/14 COMBS.T Docketing & Bervices Branch ip 15836 359 24X Fiche 50-382.82/10/14.8210270327
- --82(0270332 Notice of issuance & availability of notice of finding of no significant antitrust changes & time for filing request for re-evaluation TOALSTON, A Antitrust & Economic analysis Branch (Utility Finance) 82/10/12 3pp 15836 360 24X Fiche 50-382/82/10/14. 8210270327
- O Inspection reports. IE Bulletins & correspondence
- 8210120058 Forwards IE Insp Rept 50-382/82-12 on 820503-07 Np noncompliance noted MADSEN, G L Division of Resident, Reactor Project & Engineering Programs 82/09/24 MAURIN, L V Louisiana Power & Light Co 2pp 15453 110 24X Fiche 50-382,82/09/24,8210120058
- --8210120073 IE Insp Rept 50-382/82-12 on 820503-07 No noncompliance noted Major areas inspected chemistry/radiochemistry program including organization, staffing, qualifications, training, facilities, equipment & lab instrument calibr NICHOLAS. J D. MURANY. B Division of Resident, Reactor Project & Engineering Programs 82/09/01 46pp 15653 112 24x Fiche 50-382,82/09/24,8210120058
- 8210190431 Forwards IE Insp Rept 50-382/82-18 on 820816-20 & notice of violation MADSEN, 0 L Division of Resident, Reactor Project & Engineering Programs 82/09/30 MAURIN, L V Louisiana Power & Light Co 2p; 15741 154 24X fichs 50-382,82/09/30,8210190431
- --82(0190437 Notice of violation from insp on 820816-20 + Division of Resident, Reactor Project & Engineering Programs 82(09/30 ip 15741 156 24X Fiche 50-382,82/09/30,82(019043)
- --8210190452 IE Insp Rept 50-382/82-18 on 820816-20 Noncompliance noted failure to foliow procedures/instructions for control of weld insp/documentation of safety-related structural steel platforms

 JOHNSON, C. E., ROBERDS, J., CROSSMAN, N. A. Division of Resident, Reactor Project & Engineering Programs 82/09/21 9pp 15741 157 24% Fische 50-382, 82/09/30, 8210190431
- 8208190233 IE Info Notice 80-35, Suppl 1, "Leaking & Dielodged I-125 Implant Geeds " Svc list encl COBp.L I Division of Fuel Facilities, Materials & Gafeguards 82/10/06 Consolidated Edison Co of New York 66pp 15761 250 24X fiche 50-000,82/10/06.8208190233
- 8208190238 IE Bulletin 82-03. "Stress Corrosion Cracking in Thick-Wall, Large-Diameter, Stainless Steel, Recirculation Sys Piping at BMR Plants " Svc list encl DEYQUNO.R C Director's Office, Office of Inspection and Enforcement 82/10/14 Consolidated Edison Co of New York 115pp 15810 125 24X Fiche 50-000, 82/10/14, 8208190238
- S Reportable occurrences, LERs & related correspondence
- 8210040078 Interim Significant Const Deficiency Rept 62 re insp & acceptance of undersized field welds in 1/2-inch stainless steel sampling schedule 160 paping Initially reported on 820820 Mercury Co will build up welds by 821282 MAURIN. V Louisiana Power & Light Co 82/09/20 CDLLING, J T Region 4, Office of Director 3pp 15581 267, 24X Fichs 50-382,82/09/20,8210040078.

- 8210130174 Interim deficiency rept re possible failure of GE Type MFA relays Initially reported on 820513 Corrective action not completed Final rept will not be submitted until 830430 MAURIN.L V Louisiana Power & Light Co 82/09/30 COLLINS. J T Region 4. Office of Director ip 15673 045 24X Fiche 50-382.82/09/30, 8210130174
- G210130245 Second interim dericiency rept re Significant Const
 Deficiency 43 on main/emergency feedwater sys Corrective
 action not completed Final rept will be submitted by
 B21222
 MANRINL V Louisiana Power & Light Co B2/09/30 COLLINS. J T
 Region 4. Office of Director 1p 15678 101 24X
 Fiche 50-382.82/09/30,6210130245
- 6210130564 Second interim deficiency rept on Significant Const Deficiency 40 re design application of break flanges at elevated temps Corrective action described in 820326 rept not completed Neit rept to be submitted by 830117 MAURIN, L V Louisiana Power & Light Co 82/09/30 CDLLINS, J T Region 4, Office of Director ip 15683 300 24X Fiche 50-382,82/09/30,8210130564
- 9210130243 Second interim deficiency rept re reactor containment bldg liner plate nuclear coating failure Corrective action not yet completed Final rept to be submitted by 930223 MAURIM, L. V. Louisiana Power & Light Co. 82/10/01 COLLINS, J. T. Region 4, Office of Director ip 15678 100 24X Fiche 50-382:82/10/01/8210130243
- 8210130551 Fourth interim Significant Const Deficiency Rept 33 rechilled water pipe supports Corrective action not yet complete Final rept expected by 830311 MAURIN, L. V. Louisiana Power J. Light Co. 82/10/01 CULLINS, J. T. Region 4, Office of Director ip 15684 013 24X Fiche 50-382.82/10/01.8210130551
- 8210190542 Interim deficiency rept re Potential Reportable Deficiency 86 on disparity in UHS tornado case test results Initially reported on 820830 Equipment not significantly impacted at 104 F Deficiency not reportable per 10GFR50 55(e) MAURIN,L V Louisiana Power & Light Co 82/10/06 MADSEN.O L Division of Resident, Reactor Project & Engineering Programs 3pp 15751 330 24% Fiche 50-382.82/10/06.8210190542
- 8210190345 First interim deficiency rept re Significant Const Deficiency 63, "Procurement of Spare/Replacement Parts " Further info detailing investigation & evaluating questionable purchase orders will be provided by 830418 MAURIN. L V Louisiana Power & Light Co 82/10/08 COLLINS, J T Region 4. Office of Director 3pp 13742 095 24X Fiche 50-382,82/10/08,8210;70345
- 8210250217 Third interim deficiency rept re inadequate clearance between process piping sys & bor type pipe supports & restraints Nineteen hangers remain to be reworked Final rept will be transmitted by 830708 MAURIN.L V Louisiana Power & Light Co 82/10/15 COLLINS. J T Region 4, Office of Director ip 15768 337 24X Fiche 50-282, 82/10/15, 8210250217
- 8210250242 Interim Significant Const Deficiency Rept 32 re failure to perform stress analysis for welded pipe support attachments prior to fabrication Initially reported on 810810 Eleven hangers need reworking Final rept will be sent by 830624 MAURIN.L V Louisiana Power & Light Co 82/10/15 COLLINS. J T Region 4, Office of Director 1p 15788 338 24x Fiche 50-382, 82/10/15, 8210250242

- DOCKET 50-387 SUSGUEHANNA STEAM ELECTRIC STATION, UNIT 1
- € 188C Safety Evaluation Report (SER), supple & correspondence
- 8210040052 Responds to SER, Suppl 3, Section 3 11 5(1) relaging by implementation of surveillance by maint program Procedures written by schedules will be completed by 821005 CURTIS, N. W. Pennsylvania Power & Light to 82/09/24 SCHWENCER, A Licensing Branch 2 3pp 15581 308 24% Fiche 50 387, 82/09/24, 8210040032
- 921013034) Updates 820924 response to SER Suppl J. Section J 11 5(1) re surveillance & maint program, per License Condition C(IE)(a) Schedules complete for components requiring surveillance/ replacement during first yr operation CURTIS.N W Pennsylvania Power & Light Co B2/10/06 SCHWEN(FR A Licensing Branch 2 lp 15679 137 24X Fiche 50-387, 82/10/06 8210130341
- F Security, medical, emergency % fire protection plans
- \$210010417 Forwards description of actions to be taken to correct desictencies in physical security plansper \$20901-02 discussions Revised plans forthcoming Encl withheld (ref 100FR73 21)
 CURTISM W Pennsylvania Power & Light Co 82/09/16 SCHWENCER, Licensing Branch 2 ip 15572 1/5 24X Fiche 50-387.82/09/16.
- 8210210234 Notification of 821005 meeting w/util in Allentown.PA to discuss station blackout test plan PERCHAR L Licensing Branch 1 82/09/2/ YOUNGBLOOD, B J Licensing Branch 1 3pp 15774 333 24X Fiche 50-387,82/09/2/,8210210234
- 8210190158 Releases public version of emergency plan implementing procedure FELTON.J M Division of Rules and Records 82/09/28 Document Management Branch 1p 15758 020 24% Fithe 50-387,82/09/28,8210190158
- --8210190166 Forwards public version of Revision O to Emergency Plan Implementing Procedure EP-IP-048. "Estimation of Core Damage During Emergency "Receipt form encl 4 Pennsylvania Power & Light Co 82/09/17 NRC No Detailed Affiliation Oliven Ip 15758 021 24% Fiche 50-387,82/09/28.8210190158
- --8210190173 Public version of Revision O to Emergency Plan Implementing Procedure EP-IP-048. "Estimation of Core Damage During Emergency " Revision 6 to procedure manual table of contents enc!

 * Pennsylvania Power & Light Co 82/09/17 25pp (5758 023 24% Fichs 50-387, 62/09/28, 8210190158
- 8210060199 Advises that emergency operations facility & technical support ctr is operational Status of emergency response computer sys provided in 820916 Ltr CURTIS,N W Pennsylvania Power & Light Co 82/10/01 SCHWENCER, A Licensing Branch 2 1p 15614 015 24X Fithe 50-387, 82/10/01, 8210060199
- 8210130430 Responds to inquiry re supplemental interim findings on adequacy of offsite emergency preparedness for facility State & local emergency plans adequate Conditions should be imposed to assure completion of corrective actions KRIMM.R W Federal Emergency Management Agency 62/10/04 CRIMES.B K Division of Emergency Preparedness ip 15681 192 24% Fiche 50-087-82/10/04.8210130430
- 8210290201 Forwards 1E Insp Rept 50-387/82-30 on 820712-15 No noncompliance noted MARTIN.TT Division of Engineering & Technical Programs 82/10/08 KENYON.B D Pennsylvania Power & Light Co 2pp 15854 015 24X Fiche, 50-387, 82/10/08, 8210290201
- --8210290207 IE Insp Rept 50-387/82-30 on 820712-16 No noncompliance noted Major areas inspected security sys power supply access control.lighting assessment aids detection aids & communications Details withheld (ref 100FR73 21) DUNLAP.J M., QDDY.A T. Region 1. Office of Director 82/10/04 ip 15854 017 24X Fiche 50-387,82/10/08,8210290201
- 8210250256 Forwards application for Amend 11 to License NPF-14 & proposed Tech Spec changes Amend deletes Fire Zone 1-6A in access area from Tech Specs CURTIS.N W Pennsylvania Power & Light Co 82/10/19 8CHWENCER.A Licensing Branch 2 lp 15791 153 24X Fiche 50-387.82/10/19.8210250256

- --8210250264 Application for Amend 11 to License NPF-14, deleting File Zone 1-64 from Tech Spec 3 7 6 2 re sprinkler sys CURTIS:N W Pennsylvania Power & Light Co 82/10/17 1p 15791 154 244 Fiche 50 387.82/10/19.8210250256
- --8210250276 Proposed Tech Spec changes re spray & sprinkler systallowing for continuous fire watch w/backup fire suppression equipment
 - equipment

 * Pennsylvania Power % Light Co 62/10/19 1p 15791 155 24X

 Fiche 50-387, 82/10/19, 8210250256
- 8210270230 Application for Amend 13 to License NPF-14, revising License Condition 2 D to reflect Changes J.K.L & M. revision to Chapter 11 & security training & qualification plan including Revision 1 & Change A Class II amend fee enc? KENYON, D D Pennsylvania Power & Light Co 82/10/25 SCHWENCER, A Licensing Granch 2 2pp 15853 181 24X Fiche 50-387, 82/10/25, 8210270230
- 8210290318 Advices that mod to fire resistant wrap matt on cable trays in Fire Zone 1-20 remote shutdown panel completed per util 820831 commitment Mod satisfies License Condition C(7)
 - Bayusi commisment non-sacraties citaise Condition (17)
 requirements
 CURTIS,N W Pennsylvania Paugr & Light Co 82/10/25 SCHWENCER, A
 Licensing Branch 2 1p 15853 100 24% Fiche 50-387, 82/10/25,
 82/10270318

) Adjudicatory correspondence

R10280258 Order directing util to inform ASLB, by 821103, of how util will inclement change of leak rate monitoring sys per hearing testimony NRC to inform ASLB, by 821110, of related lech Specs & relationship to NURCO-0313. Revision i TOMPKINS, B A Atomic Seroty and Licensing Appeal Panel 82/10/26 Pennsylvania Power & Light Co. 3pp. 15837-024 24X Fiche 50-387, 82/10/26, 8210280258

General correspondence

- 210220351 Advises that 821006 telegram opposing facility will be sent to all parties GLLTNSKY.V Commissioners 82/10/20 DALTON,C Affiliation Unknown ip 15779 127 24X Fiche 50-387.82/10/20,8210220351
- -8210220357 Opposes granting facility OL since no suitable evacuation plan exists
- DALTON, C Affiliation Unknown 82/10/04 GILINSKY, V Commissioners 1p (5779/128 24X Fiche 50-387, 82/10/20, 8210220351

Insurance & indemnity information

- '10220102 Forwards Endorsements 15.16 & 17 to NELIA Policy NF-262 CURTIS.N W Pennsylvania Power & Light Co 62/10/16 SCHWENGER Licensing Branch 2 5pp 15778 172 24X Fiche 50-387,62/10/16, 6210220102 SCHWENGER, A
- 10220175 Forwards Endorsements 1-4 to MAELU Policy MF-107 CURTIS.N W Pennsylvania Power & tight Co 62/10/18 SCHWENCER.A Licensing Branch 2 1p 15778 001 24X Fiche 50-387, 82/10/18, 8210/20175
- Operating license stage documents & correspondence
- 10210417 Forwards action plan for investigation of small pipe program concerns per 870730 mesting commitment (EENYUN: 9 D Pennsylvania Power & Light Co 82/08/04 MARTIN, T T Division of Engineering & Technical Programs 12pp 15768 074 24X (ichs 50-387,82/08/04,8210210417
- IOOA0391 Forwards rept of outlined actions & conclusions resulting from util investigation & Commission concerns re small pipe reograms per 82081; 18:25 & 27 meetings IERYON, B D Pennsylvania Power & Light Co 82/09/10 MARTIN, T T livision of Engineering & Technical Programs 120pp 15615 195 48 Fiche 50-387.82/09/10,8210040391
- 0180274 Summary of 820909 meeting w/util. Teledyne Engineering Svcs TEB), Bechtel & Nutech re conclusion of TES final rept ssued on review of feedwater sys inside containment List
- attandess encl
 RSH.R L Licensing Branch i 82/09/24 Licensin
 15746 336 24X Fiche 50-387.82/09/24.8210180274 Licensing Branch 1 ERSH, R L
- 0190153 Summary of 820909 meeting w/util & Stannard & Co re onfiguration of gas pipeline near plant site ERCH.R L. Licensing Branch 1 82/09/24 Licensing Branch 1 pp 15761 246 24% Ficho 50-387.82/09/24.8210190153

- 8210210303 Notification of 820929 senior mgt meeting w/util in Bethesda.MD to discuss plant status PERCH.R L. Licensing Branch 2 82/09/27 YOUNDBLOOD,B J Licensing Branch 1 3pp 15774 357 24X Fiche 50-387,82/09/27.
- 8210050325 Discusses offects of change in dissel generator start time from 10-s to 25-s on LOCA analysis in FSAR Chapter 6.3 Large recirculation discharge break peak clad temp not affected by delayed start time CURTISIN W. Pennsylvania Power & Light Co. 82/09/29 SCHMENCER, A Licensing Branch 2. 3pp. 15608 212 24X Fiche 50-387,82/09/29. 8210050325
- 8210050370 Provides interim justification for operability of feedwater sys check valves Calculations & ASME/ANSI stds provide adequate assurance that guillotine break of feedwater piping would not occur as result of operational transient CURTIS.N W Pennsylvania Power & Light Co 82/09/29 SCHWENCER.A Licensing Branch 2 2pp 15609 046 24X Fiche 50-387.82/09/29, 8210050370
- 8210210244 Requests written response addressing specific & general 210210249 Requests whiteen response addressing specific & issues noted in Teledyne final rept on independent design review of plant feedwater sys inside containment NDVAK.T if Assistant Director for Licensing 82/09/30 Pennsylvania Power & Light Co 2pp 15774 331 24X Fiche 50-387,82/09/30,8210210244 82/09/30 CURTIS N H
- 8210210288 Advises that util revised process control program containing methodology & parameters for solid:fication of radwasts acceptable Program meets Tech Epec 6 13 1 requirement YOUNGBLOUD, B J Licensing Branch 1 82/09/30 CURTIS.N W Pennsylvania Power & Light Co 2pp 15774 345 24X Fiche 50-387,82/09/30,8210210288
- 8210130122 Advises that final rest on automatic degressurization sus scheduled for completion in Oct Option 4 of BWR owners group will be implemented Detailed design info will not be group will be implemented petalled besign into will not be generated until NRC approval is received CURTIS.N W Pennsylvania Power & Light Co 82/10/01 BCHWENCER Licensing Branch 2 3pp 15673 001 24X Fiche 50-387,82/10/01, 0210/30122
- 8210260241 Forwards rept of systematic assessment of licensee performance & related correspondence (14YNES: R C Region 1, Office of Director 82/10/01 KAUFMAN. J T Pennsylvania Power Co 3pp 15803-056 24X Fiche 50-387,82/10/01. 8210260241
- ~-0210260247 Systematic assessment of licensee performance for Mor 1981-Feb 1982 Overall performance acceptable * Region 1, Office of Director 82/06/01 31pp 15803 059 24x Fiche 50-387,82/10/01.8210260241
- --8210260257 Advises of completion of systematic assessment of licenses performance & notifies of 820617 site meeting to discuss assessment STAROSTECKI, R Division of Project & Resident Programs KAUFMAN, J. T. Peansylvania Power & Light Co 2pp 158 24X Fiche 50-387,82/10/01,0210260241 15903 090
- --8210260270 Responds to 820604 systematic assessment of licensed performance Items discussed include licensed operators, health physics & chemistry staffs, operating procedures, punch list status & open items
 CURTIS,N W Pennsqlvania Power & Light Go 82/07/02
 STAROSTECKI,R Division of Project & Resident Programs 9pp 19803 072 24X Fiche 50-387, 82/10/01.8210260241
- 8210080083 Forwards responses to Phase 2 finding & observations in final rept of Teledyne independent design review Program results re as-built reconciliation process will be available 82:101 CURTIS,N W Pennsylvania Power & Light Co 82/10/04 SCHWENCER.A Licensing Branch 2 Bpp 15640 211 24X Fiche 50-387,82/10/04. 8210080083
- 8210270115 Forwards Amond 3 to License NPF-14, safety evaluation & notice of issuance & availability Amend changes Tech Spacs re essential svc water pump timer settings & dissail surveillance equipment
 YOUNDELOOD, B J Licensing Branch 1 82/10/04 CURTIS,N W
 Pennsylvania Power & Light Co 2pp 15866 345 24X
 Fiche 50-387, 82/10/04, 82/0270115
- --8210270128 Amend 3 to License NPF-14, changing Tech Specs re essential syc water pump timer settings & diesel surveillance requirement YOUNDBLOOD, B J Licensing Branch 1 82/10/04 7pp 15864 347 24X Fiche 50-387,82/10/04.8210290115

- --B210270130 Safety evaluation supporting Amend 3 to License NPF-14

 Office of Nuclear Reactor Regulation, Director 82/10/04 2pp
 15956 354 24X Fiche 50-387,82/10/04,8210290115
- --8210270336 Notice of issuance & availability of Amend 3 to Licensi NPF-14 KANE.N F Licensing Branch & 82/10/04 2pp (5866-356-24X Fiche 50-387,82/10/04,8210270115
- 8210250010 Staff requirements memo summarizing 820930 discussion & possible vote on full power OL Decision deferred pending investigation review CHILF-5 J Office of the Secretary of the Commission 82/10/05 Office of the Secretary of the Commission 1p 15808 180 24X Fiche 50-387.82/10/05.8210250010
- 8210080142 Forwards application for Amend 9 to License NPF-14 adding into to minimite equipment damage due to high drywell temp KENYON. B D Pennsylvania Power & Light Co 82/10/06 SCHMENLER. A Licensing Branch 2 2pp 15640 131 24X Fiche 50-387, 82/10/06. 8210080142
- --8210080146 Application for Amend 9 to License NPF-14, adding info to minimize equipment damage due to high drywell temp KENYON, B D Pennsylvania Power & Light Co 82/10/06 tp 13640 133 24X Fiche 50-387, 82/10/06; 8210080142
- --8210080151 Marked-up proposed Tech Specs re minimi;ing equipment damage due to high drywell temp 4 Pennsylvania Pawer & Light Co 82/10/06 5pp 15640 134 24X Fiche 50-587,82/10/06.8210080142
- 5210190297 Forwards plan for expanded reconciliation sampling program to show adequacy of engineering judgments made in large pipe design process Final rept will be available 821112 Requests NRC allow operation up to 357 power CURTIS:N W Pennsylvania Pawer & Light Co 82/10/14 GCHWENGER, A Licensing Branch 2 App 15742 168 24X Fiche 50-387.82/10/14, 8210190297
- 8210250256 Forwards application for Amend 11 to License NPF-14 & proposed Tech Spec changes Amend deletes Fire Zone 1-6A in access area from Tech Specs CURTIS,N W Pennsylvania Power & Light Co 82/10/19 BCHWENCER,A Licensing Branch 2 ip 1579| 153 24X Fiche 50-387,82/t0/19,8210250256
- --8210250264 Application for Amend II to License NPF-14, deleting file Zone 1-6A from Tech Spec 3 7 6 2 re sprinkler sys CURTIS,N W Pennsylvania Power & Light Co 82/10/19 ip 13791 154 24X Fiche 50-387, 82/10/19, 8210250256
- ~-8210250276 Proposed Tech Spec changes re spray & sprintler sys.allowing for continuous fire watch w/backup fire suppression equipment

 * Pennsylvania Power & Light Co 82/10/19 ip 15791 155 24X Fiche 80-387.82/10/19.8210250256
- 8210250367 Forwards application for Amend 10 to License NPF-14, changing Tech Spec Table 3 8 4 1-1 to include more conservative Type 2 molded case circuit breakers & to add previously omitted Type 3 molded case circuit breakers CURTIGN W Pennsylvania Power & Light Co 82/10/19 SCHWENCER, A Licensing Branch 2 2pp 15790 179 24X Fiche 50-387, 82/10/19, 8210250367

- 8210260366 Forwards application for Amend 12 to Lictuse NPF-14, changing Tech Specs 4 if 2.7 i.4 if 2.7 2.6 Page 374 8-18 re radioactive effluents, main condenser & electrical power sys CURTIS.N W. Pennsylvania Power & Light Co. 62/10/22 SCHWENTER.A Licensing Branch 2 ip 15804 239 24X fiche 50-387,83/10/22,8210260366
- --8210260379 Application for Amend 1. to License NPf 14, changing fech Specs 4 11 2 7 1.4 11 2 7 2 5 Page 7/4 8-18 rp indicactive effluents, main condense; 7 electrical power sys CURTIS, N W pennsylvania Power / Light Co
- 8210290230 Application for Amend 13 to License MPF-14, revising litense Condition 2 D to reflect Changes J K t & M. revision to Chapter 11 & security training & qualification plan including Revision 1 & Crange & Class II amend fee encl KENYON, B D Pennsylvania Power & Light Co. B2/10/25 \$CHMINER, & Licensing Branch 2 2pp 15050 101 74% Fichu 50-307, 02/10/25, 8210290230
- Q Inspection reports. IE Bulletins & correspondence
- B210260241 Forwards rept or systematic assessment of licenses performance & related correspondence HAVNES, R.C. Region t. Office of Director 102/10/01 MAUFMAN. / J. Pennsylvania Power Co. 3pp. 15803-056. 24X fiche 50 187-02/10/01 821026024
- --g210260247 Systematic assessment of licensee performance for Mail 1981-Feb 1982 Overall performance acceptable PRegion 1, Office or Director 82/04/01 31pp 15803 059 29 Fiche 50-387, 82/10/01.8210260241
- --8210260257 Advises of completion of systematic assessment of license, performance & notifies of 820617 site meeting to discuss assessment STAROSTECKI, R. Division of Project & Rosident Programs 82/06/04 KAUFMAN, J.T. Pennsylvania Power * Light to Pap 1580, 020 244 Fiche 50-387, 82/10/01, 82(026024)
- --8210260270 Responds to 820604 systematic assessment of liconnec performance Items discussed include licensed operators, health physics & chemistry staffs, operating procedures, punch list status & open items CURTIS.N W Pennsylvania Power & Light to BY/0//02 SYAROSTECKI.R Division of Project & Resident Programs 9pp 15803 092 24X Fichs 50-387, 82/10/01.01210240241
- 8208190233 IE lnfo Notice 80 35. Suppl 1. "Loaking & Dielndged I-la". Implant Seeds " Svc list encl COBD.L. I Division of Fuel Facilities. Materials & Safoguards 82/10/06 Consolidated Edison Co of New York & App 15761 2"8 24% Fiche 50-000.82/10/06.820819023
- B210290201 Forwards IE (nsp Rept 50-3B7/B2-30 on B20712-19 No noncompliance noted MARTIN T T Division of Engineering & Technical Programs G2/10/08 KENYON, B D Pennsylvania Power & Light Co 2pp 15854 015 24X Fiche 50-387, B2/10/08, B210290201
- --B210290207 IE Insp Rept 50-387/82-30 on 820712-14 No moncompliance noted Major areas inspected security say power supply access control.lighting assessment aids, detection aids & communications Details withheld (ref 1007R73 R1) DUNLAP, J M , CODY, A T Region 1, Office of Director 82/10/06 by 15854 017 24% Fichs 50-387,82/10/08,8210290201
- 820B190238 IE Bulletin 82-03, "Stress Corrosion Cracking in Thick-Wall, Large-Diameter, Stainless Stoel, Recirculation Bys Piping at BHR Plants " Bur list enc."
 DEYDUNG, R C Director's Office, Office of Inspection and Enforcement 82/10/14 Consolidated Edison Co of New York 115pp 15810 125 24X Fiche 80-000, 82/10/14, 820B190238
- B Reportable occurrences, LERs & related correspondence
- 8210010177 Forwards LER 82-014/03L-0 KEISER: H W Pennsylvania Power & Light Co 82/09/22 HAYNES.R C Region 1. Office of Director 1p 15567 285 24X Fiche 50-387: 82/09/22, 8210010177

- --8210010180 LER 82-014/03L-0 on 820824, prior to initial criticality, unit taken from Operational Condition 5 to 4 w/o shutdown cooling mode of RHR in operation, as required by Tech Spec Initial startup procedure superseded by normal startup procedure white the procedure with the procedure of Newson 1.0 Office of Director 1p 15567 286 24X Fiche 50-387,82/09/22,8210010177
- 8210010228 LER 82-016/01P on 820918, turbine bidg vent monitor systemble gas nonitor declared out of svc Grab sampling once per 8-h initiated Mechanical vacuum pump in svc until 820920 contrary to Tech Specs Cause not stated PEISER.H W Pennsylvania Power & Light Co 82/09/22 HAYNES.R C Region 1, Office of Director ip 15568 261 24% Fiche 50-387.82/09/22.8210010228
- 8210010393 Forwards LER 82-015/03L-0 VEIGER:H W Pennsylvania Pougr & Light Co 82/09/22 HAYNES:R C Region I, Office of Director ip 15572 264 24X Fiche 50-387,82/09/22:8210010393
- --8210010402 LER 82-015/03L-0 on 820824, from start of initial fuel load until 820825, spray pond level & temp not monitored Caused by ontaxion of Tech Spec 4 7 1 3 requirements from procedures Procedure rewritten

 KUCZYMISKI L A Pennsylvania Power & Light Co 82/09/22 Region
 1. Office of Director 1p 15572 265 24X Fiche 50-387, 82/09/22, 8210010393
- B210040086 Forwards LER 92-017/03L-0

 KEISER.H W Pennsylvania Power % Light Co 82/07/24 HAYNES,R (
 Region 1, Office of Director 1p 15581 015 24X

 Fiche 50-387,82/07/24,8210040086
- --8210040088 LER 82-017/03L-0 on 820826, sprinkler sys for fire zone 1-5A was out of syc Detector reset initiated on Fire protection panel in control room but required reset of priorities (RSP) not performed RSP initiated KUCZYKISKI.L A Pennsylvania Power & Light Co 82/07/24 Region 1. Office of Director 1p 15581 016 24X Fiche 50-387, 82/09/24, 8210040086
- 8210040118 Forwards LER 82-012/01T-0 KEISER:H W Pennsylvania Power & Light Co 82/09/24 HAYNES:R & Region 1: Office of Director 1p 19581 193 24X Fiche 50-387:82/09/24:8210040110
- --8210040122 LER 82-012/01T-0 on 820910 potential existed for overload of Class IE electrical sys due to concurrent loading of emergency syc water pumps & either RHR or core sprey pumps during intermediate LOCA Caused by inadequate evaluation CISEMHULE F Pennsylvania Power & Light Co 82/09/24 Region I. Office of Director 2pp 15581 194 24X Fiche 30-387, 82/09/24.8210040110
- 8210130352 Forwards LER 82-020/03L-0 KEISER: H W Pennsylvania Power & Light Co 82/10/01 HAYNES: R C Region 1: Office of Director | p 15679 129 RAX Fiche 30-387: 82/10/01: 8210130352
- --8210130361 LER 82-020/03L-0 on 820903, after both RHR sys trains removed from syc, pressure & temp were not recorded Caused by operator misjudgment Operators instructed to log & follow all action statements
 MITCHELL, D O Pennsylvania Power & Light Co 82/10/01 Region
 1. Office of Director ip 15679 126 24% Fiche 50-387,82/10/01, 8210130352
- --B210130371 LER B2-018/03L-0 on B20702. w/mode switch in refuel, three out of four source range monitors were inoperable Caused by inadvertent stressing of cables during undervessel work Procedure revised to reduce cable wear HITCHELL.D O Pennsylvania Power & Light Co B2/10/01 Region 1, Office of Director 1p 15682 114 24X Fiche 50-387,82/10/01, B20130363
- 8210130377 Forwards LER 82-019/017-0 KEISER:H W Pennsylvania Power & Light Co 82/10/01 HAYNES:R C Region 1. Office of Director 1p 15681 006 24X Fichs 50-387: 82/10/01:8210130377
- --8210130387 LER 82-019/01T-0 on 820920, during power ascension testing, tustine bidg vent monitor sys became inoperable Gaused by failure to remove mechanical vacuum pump from svc Pump stopped & steam jet air ejectors placed in svc HITCHELL, D. Q. Pennsylvania Power & Light Co. 82/10/01 Region 1. Office of Director ip 15681 007 24X Fiche. 50-387.82/10/01, 8210130377

- 8210130405 PND-I-B2-064 on B21006, anchor for 6-inch RHR sys line found to have weld one-third specified length Failure of support would overstress containment penetration authorization to exceed 5% power postponed MCCABE.E C , KEIMIO Region 1. Office of Director 82/10/07 ip 15680 260 24% Fich# 50-387.82/10/07.8210130405
- 8210210440 Forwards LER 82-021/03L-0 KEIBER: H W Pennsylvania Power & Light Co 82/10/08 HAYNEB, R C Region 1, Dffice of Director ip 13763 045 24X Fiche 50-387, 82/10/08, 8210210440
- --B210210446 LER B2-021/03L on B20910, while performing surveillance of rod worth minimizer, selection error indicating light did not operate properly Caused by one 28-volt conductor being pulled loose from light assembly due to stress MITCHELL, D O Pennsylvania Power & Light Co B2/10/08 Region 1, Office of Director 19 15763 046 24X Fiche 50-387,82/10/08,8210210440
- B210210285 Forwards LER 82-019/03L-0 KEISER: H W Pennsylvania Power & Light Co 82/10/11 HAVNES: R C Region 1. Office of Director 1p 15765 086 24x Fiche 50-387: 82/10/11, 8210210285
- --8210210293 LER 82-019/03L-0 on 820912.during startup testing, Operational Condition 2 entered prior to completion of required daily surveillances Caused by incorrect identification of condition Event will be reviewed MITCHELL, D C Pennsylvania Power & Light Co 82/10/11 Region 1. Office of Director 1p 15765 087 24X Fiche 50-387,82/10/11,8210210285
- 8210210433 Forwards reissued LER 82-016/017-1 KEISER: H W Pennsylvania Power & Light Co 82/10/11 HAYNES: R C Region 1. Office of Director 1p 15763 015 24X Fiche 50-387, 82/10/11, 8210210433
- --B210210436 Reissued LER 82-016/01T-1 on 820920, methanical vacuum pump left in svc after ventilation monitoring sys noble gas monitor became inoperable on 820918 Caused by operator not noting all parts of applicable action statements HITCHELL.D O Pennsylvania Power & Light Co 82/10/11 Region 1. Office of Director 2pp 15763 016 24% Fiche 50-387. 82/10/11.8210210433
- 8210210020 Final deficiency rept re impropor field mounting of Agastat 7000/E7000 relays Initially reported on 820702 Corner mounted screws & relays will be reworked by 821026 Also reported per Part 21 CURTIS,N W Pennsylvania Power & Light Co 82/10/12 HAYNES,R C. Region 1. Office of Director 4pp 15766 017 24x Fiche 90-387,82/10/12.8210210020
- 8210210137 Final deficiency rept re pump motor start times for emergency svc water.core spray & RHR sys Initially reported on 820910 Low pressure vessel interiock deleted from RHR & core spray pump start Also reported per Part 21 CURTIS,N W Pennsylvania Power & Light Co 82/10/12 HAYNES,R C Region 1, Defice of Director. 4pp 15766 103 24X Fiche 50-387,82/10/12,8210210137
- 8210250347 LER 82-026/01P-0 confirms 821013 telcon re failure to complete graunding of reactor protection sys cabling prior to fuel loading as required by License NPF-14 KEISER, H W Pennsylvania Power & Light Co 82/10/14 HAYNES, R C Region 1. Office of Director p 15790 047 24X Fiche 50-387, 82/10/14, 8210250347
- 8210250357 LER 82-028/01P-0 confirms 821013 telcon re inability to comply w/action statement Chlorine detectors inoperable Action statement requires one control room emergency putside air supply sys in recirculation mode KEIGER.H W Pennsylvania Power & Light Co 82/10/14 HAYNES,R.C Region 1. Office of Director. 1p 15791 015 24X Fiche 50-387.82/10/14.8210250357.
- 8210250369 Forwards LER 82-022/03L-0 KEIGER, H W. Pennsylvania Power & Light Co 82/10/14 HAYNEB, R. C Region 1. Office of Director 1p 15790 137 24X Fiche 30-387, 82/10/14, 8210250369
- --8210250377 LER 82-022/03L-0 on 820916, while cleaning control rod drive (CRD) suction strainers (CRD pumps tripped Caused by low suction pressure due to pressure fluctuations from cycling condensate reject valve Suction trip logic modified MITCHELL.D Ο Pennsylvania Power & Light Co 82/10/14 Region 1. Defice of Director 1p 15790 138 24X Fiche 50-387, 82/10/14, 8210230369

- 8210250381 Forwards LER 82-023/03L-0 VEISER: N W Pennsylvania Power & Light Co 82/10/14 HAYNES: R C Region 1. Office of Director Ep 15790 134 24X Fiche 50-387: 82/10/14:8210250381
- --B210250385 LER 82 023/03L-O on B20915 during startup testing of steam relief valve acoustic monitoring systhmee monitors failed to operate correctly Event was instal catibr of monitors using steam Monitors adjusted in steated by placed in svc MITCHELL.D O Pennsylvania Power & Light Co B2/10/14 Region 1. Orfice or Director ip 15790 135 24X Fiche 50-387. B2/10/14. 62:0250381
- 8/210240539 LER 82-024/01P-0 on 821015.potential for unanalyzed accident resulting from single failure of spray pond bypass valve reported Redundancy provided by automatic transfer to B loop on failure of A loop pumps to start KEISER.H W Pennsylvania Power & Light Co 82/10/18 HAYNES.R (Region 1. Office of Director 1p 15805 136 24X Fiche 50-387,82/10/18.8210240509
- ### SECONTION OF THE STREET OF THE STREET OF S
- ~-5210280219 LER 82-027/03L-0 on 820920.two drywell/suppression chamber vacuum breakers gave false position indications during stroking Caused by loose couplings connecting limit switch to vacuum relief valve shaft Set screw replaced MITCHELL.D G Pennsylvania Power & Light Co 82/10/17 Region 1. Drice of Director 19 15837 005 24X Fiche 50-387, 82/10/17, 9210280215
- T Hearing transcripts on non-antitrust matters
- 8210130113 Unoffical transcript of 820730 public meeting in Washington, DC re-briefing on full power GL amend Pp 1-97 Supporting documentation encl * Commissioners 82/09/30 1589p 15696-083 24X Fiche 50-387, 82/09/30, 8210130113
- (Onsite Storage of Low Level Waste
- \$210270411 Notification of contract execution Mod 3 to "Environ Assessment of Low Level Waste Storage at PA Power & Light Co. Susquehanna Steam Electric Station " Contractor Science Applications. Inc FLEENOR.C M Administrative Contracts Branch NRC-02-B1-064 B2/09/20 DAVIS.J , LOYSEN,P Office of Nuclear Material Safety & Safeguards. Director 1p 15833 277 24X Fiche 50-387. 82/09/30. 8210270411
- --8210270413 Mod 3. extending period of performance to 830131, revising billing instruction info & substituting Manual Chapter 3202, to "Environ Assessment of Lou Level Haste Storage at PA Power & Light Co. Susquehanna Steam Electric Station "ARCHER.C D Science Applications, Inc. HADAN, T.F. Technical Assistance Contracts Branch NRC-02-81-064 82/09/30 2pg 15833 278 24X Fiche 50-387, 82/09/30,821027041
- DOCKET 50-388 SUGQUEHANNA STEAM ELECTRIC STATION, UNIT 2

 A Application/construction stage documents & correspondence
- 8210210417 Forwards action plan for investigation of small pipe program concerns per 820730 meeting commitment KENYON, B D Pennsylvania Power & Light Co 82/08/04 MARTIN. T T Division of Engineering & Technical Programs 12pp 15765 074 2AX Fiche 50-387, 82/08/04, 8210210417
- 8210060391 Forwards rept of outlined actions & conclusions resulting from util investigation & Commission concerns re small pipe programper 820811; 18,25 & 27 meetings

 KENYON, B D Pennsulvania Power & Light Co 82/09/10 MARTIN, T T Division of Engineering & Technical Programs 120pp 15615 195 24% Fiche 50-387, 82/09/10, 8210060391
- 8210260241 Forwards rept of systematic assessment of licenses performance & related correspondence HAYNES, R C Region i. Office of Director 82/10/01 KAUFMAN, J T Pennsylvania Power Co 3pp 15803 056 24X Fiche 50-387, 82/10/01, 8210260241
- --8210260247 Systematic assessment of licensee performance for Mar 1981-Feb 1982 Overall performance acceptable. * Region I, Office of Director 82/06/01 Sipp 15803 059 24X Fiche 50-387,82/10/01.8210260241

- --8210260257 Advises of completion of systematic assessment of license, performance A notifies of 820617 site meeting to discuss assessment
 STAROSTECKI,R Division of Project * Resident Programs 8e/04/04
 KAUPHANIJT Pennsylvania Puwer & Light Co 2pp | 15803 (99) 244 Fiche 50-387,82710701 8210260241
- -8210260270 Responds to 820604 systematic assessment of licensee performance [tems discussed include licensed operators, health physics "chemistry staffs operating procedures punch list status & open items

 CURTISH W Ponnsylvania Power / Light (a 82/0//02 STAROSTECK! R Division of Project & Resident Programs Vpp 15803 092 24x Fichs 50 387.82/10/01.8210260241
- F Security, medical emergency of fire protection plans
- 02:10010417 Forwards description of actions to be taken to correct dericinences in physical security plan per 820701 (2) discussions Revised plan forthcoming Ench withheld (ref 100F873 2) CURTISH W Pennsylvania Power Stight Co. 0.709716 SCHMINGIN Licensing Branch 2 lp. 15572-175 24% Fithe 50 JG7 62/09/16, 8210010417
- 62:10190158 Releases public version of emergency plan implementing procedure FELTON. J M Division of Rules and Records U2/09/20 Document Management Branch ip 15/58 020 24x Ficho 50 JU7.82/09/20, 6210190158
 - 8210190166 Forwards public version of Revision 0 to Emergency Plan Implementing Procedure [P-1P-046, "Estimation of tore Darage During Emergency "Receipt form encl # Pennsylvania Power 'Light Co 62/09/17 NRC No Detailed Affiliation Given to 15758-021 24x Fiche 50-387,62/097/18, 8210190158
- 8210190173 Public version of Revision O to Emergency Plan Implementari Procedure EP-1P-048, "Estimation of Core Damage During Emergency "Revision o to procedure manual table of contents encl 4 Pennsylvania Power & Light Co 62/09/17 25pp 15/58 0.1 24X Fiche 50-387.82/09/28.0210190158
- 8210130430 Responds to inquiry re supplemental interim findings on adequacy of offsite emergency preparedness for facility State & local emergency plans adequate Conditions should be imposed to assure completion of corrective actions KRIMM.R W Federal Emergency Management Agency G2/10/04 GRIMES.B K Division of Linergency Preparedness ip 15681 172 244 Fiche 50-387/82/10/04 G210130430
- G Adjudicatory correspondence
- 8210280278 Order directing util to inform ASLB, by 821103, of how util will implement change of leak rate monitoring sys per hearing testimony NRC to inform ASLB, by 821110, of related Tech Specs & relationship to NURFG-0313, Revision 1 TOMEKINS, B A Atomic Safety and Licensing Appeal Panel 82/10/26 Peinsylvania Power & Light Co. 3pp. 15837-024 24% Fiche 50-387, 82/10/26, 8210280258
- H General correspondence
- 8210220351 Advises that 821006 telegram opposing facility will be sent to all parties GILINSKY, V Commissioners 82/10/20 DALTON, C Affiliation Unknown ip 15779 127 24% fiche 50-387,82/10/20,8210220351
- --8210220357 Opposes granting facility OL since no suitable evacuation plan exists DALTON.C Affiliation Unknown 82/10/06 GILINBKY.V Commissioners ip 15779 128 24X Fiche 50-387,82/10/20, 8210220351
- Q Inspection reports, IE Bulletins & correspondence
- 8210260241 Forwards rept of systematic assessment of licensee performance & related correspondence MAYNES, RC Region I. Office of Director 82/10/01 KAUFMAN.J T Pennsylvania Power Co 3pp 19803 056 24X Fiche 50-387,82/10/01
- ---8210260247 Bystematic assessment of licensee performance for Mar 1981-Feb 1982 Overall performance acceptable 4 Region 1. Office of Director 82/06/01 31pp 15803 059 24 Fiche 50-387,82/10/01.8210260241

- --8210260257 Advises of completion of systematic assessment of licensee performance & notifies of 820617 site meeting to discuss assessment STAROSTECKI,R Division of Project & Resident Programs 82/06/04 KAUFHAN, J.T. Pennsylvania Power & Light Co. 2pp. 15803 090 224 Fiche 50-287, 82/10/01,8210260241
- --B210260270 Responds to B20604 systematic assessment of licensee performance Items discussed include licensed operators, health physics & chemistry staffs, operating procedures, punch list status & open items CURTIS.N W Pennsylvania Power & Light Co B2/07/02 STAROBTECKI.R Division of Project & Resident Programs 9pp 15803 092 244 Fiche 50-387, B2/10/01.B210260241
- \$20B190233 IE Info Notice BO-35, Suppl 1, "Leaking & Dislodged 1-125 Implant Seads " Syc list enc] COBB.L I Plyision of Fuel Facilities, Materials & Safaguards 82/10/06 Consolidated Edison Co of New York 66pp 19761 200 244 Fiche 50-000,82/10/06.8208190233
- 8208190238 IE Bulletin 82-03, "Stress Corrosion Cracking in Thick-Wall, Large-Diameter, Stainless Steel, Recirculation Sys
 Piping at BUR Plants " Svc list encl
 DEYGUNO, R C Director's Office, Office of Inspection and
 Enforcement 82/10/14 Consolidated Edison Co of New York
 115pp 15810 125 24X Fiche 50-000, 82/10/14, 8208190238
- S Reportable occurrences. LERs & related correspondence
- 8210010268 Interim deficiency rept re inadequate clearance in Pacific Scientific shock suppressors & ITT Grinnell pipe clamps
 Initially reported on 820820 Final rept will be submitted by 830201 Also reported per Part 21
 CURTIS.N W Pennsylvania Power & Light Co 82/09/23 HAYNES, R C Region 1, Office of Director 4pp 15573 110 24X
 Fiche 50-388,82/09/23,8210010268
- 3210210020 Final deficiency rept re improper field mounting of Agastat 7000/E7000 relays Initially reported on B20702 Corner mounted screws & relays will be reworked by 821026 Also reported per Part 21 CURTIGN W Pennsylvania Power & Light Co 82/10/12 HAYNES,R C Region 1, Office of Director 4pp 15766 017 24x Fiche 50-387,82/10/12,8210210020
-)210210137 Final deficiency jept re pump motor start times for emergency svc water.core spray & RHR sys Instially reported on 820710 Low pressure vessel interlock deleted from RHR & core spray pump start Also reported per Part 21 CURTISIN W Pennsylvania Power & Light Co 82/10/12 HAYNES.R (*Region I, Office of Director App 15766 103 24X Fiche 50-387,82/10/12.8210210137
 - Onsite Storage of Low Level Waste
- 210270411 Notification of contract execution, Mod 3 to "Environ Assessment of Low Level Waste Storage at PA Power & Light Co. Busquehanna Steam Electric Station " Contractor Science Applications, Inc FLEEHOR, C M Administrative Contracts Branch NRC-02-81-064 82/09/30 DAVIS, J. LOYSEN.P Office of Nuclear Material Safety & Safeguards, Director ip 18833 277 24% Fiche 50-387,82/09/30, 8210270411
- -8210270413 Mod 3, extending period of performance to 830131, revising billing instruction info & substituting Manual Chapter 3202, to "Environ Assessment of Low Level Naste Storage at PA Power & Light Co. Susquehama Steam Electric Station" ARCHER, C D Science Applications, Inc HAGAN T F Technical Assistance Contracts Branch NRC-02-81-044 82/09/30 2pp 15833 278 24X Fiche 50-387, 82/09/30, 8210270411
- CKET 80-389 BT LUCIE PLANT, UNIT 2
 Application/construction stage documents & correspondence
- 1019001A Forwards background info for meeting to discuss engineering verification program & measures used to assure program independence W/o encla
 NERSES, V Licansing Branch 3 82/09/09 DENTON. H R Office of Nuclear Reactor Regulation, Director EIBENHUT, D Q Division of Licansing VOLLMER.R H Division of Engineering 2pp 15760 316 24% Fiche 50-389,82/09/09.8210190014
- 10080340 Discusses NRC understanding of core load schedule List of licensing actions not yet resolved to NRC satisfaction encl. 40VAN,T H Assistant Director for Licensing 82/09/10 UHRIG,R E Torida Power & Light Co Spp 15663 323 24X Tiche 50-389,82/09/10,8210080340

- 8210010017 Forwards response to rindings identified in 820831-0901 audit of electrical area UHRICR RE Florida Power & Light Co 82/09/24 EISENHUT, D G Division of Licensing 3pp 13565-144 24X Fiche 50-389, 82/09/24, 82/00
- 8210040334 Forwards minutes of 820723 meeting w/util & C-E task Force managers in Windsor,CT re engineering verification program BL008ETT.T H Ebasco Services, Inc. (subs. of Enserch Corp.) 82/097/27 E186NUT D G Division of Licensing 3pp. 15584-170 24X Fiche 50-389,82/09/29 8210040334
- 8210210028 Authorizes use of ASME Cade Case N-316 for application in const of components Use of code case should be documented in FSAR KERRIOAN. J D Licensing Branch 3 82/09/29 UHRIG.R E Florida Power & Light Co 2pp 15/82 201 24% Fiche 50-389.82/09/29, 8210210028
- 82(02)025) Notification of 821000 meeting w/util in Bethesda, MD to discuss procedure for leak testing pressure isolation valves Meeting agenda ent! NERSES, V Licensing Branch 3 82/09/29 KERRIGAN, J Licensing Branch 3 4pp 15774 327 24X Fiche 50-389,82/09/29,8210210251
- B210050416 Forwards Suppl 1 to "Near-Term OL Summary Human Engineering Rept on St Lucie Unit 2 Control Room" UHRIO,R E Florida Power & Light Co 82/77/30 EISENHUT.D G Division of Licensing 1p 19607 125 24x Fiche 50-389.82/09/30. B210050416
- --8210050419 Suppl 1 to "Near-Term OL Summary Human Engineering Rept on St Lucie Unit 2 Control Room" 4 Florida Power & Light Co 82/09/07 179pp (5607 126 24X Fiche 50-389, 82/09/30,8210050416
- 8210060276 Forwards training program on Loose parts monitoring syswhich property qualities plant personnel to operate sys Submittal completes action to satisfy NRC request UARIOR E Florida Power & Light Co 82/09/30 EISENBUT.D 0 Division of Licensing 2pp 15621 170 24% Fiche 50-389.82/09/70, 8210060274
- 8210060288 Informs that requirements stated in Generic Ltr 82-12 restaff working hours adequately enforced by incorporation in administrative procedures Amend to Tech Specs unnecessary at present time
 UHRIO.R E Florida Power & Light Co 82/09/30 EISENHUT, D G
 Division of Licensing lp 15619 212 24X Fiche 50-339, 82/09/30.
 8210060288
- 82:00:80268 Trip rept of caseload forecast panel 820608-10 site visit to assess const progress Meeting agenda & attendance list encl NERSES, V Licensing Branch 3 82/10/01 Licensing Branch 3 8pp 15746 328 24X Fiche 30~389,82/10/01,8210180268
- 8210210591 Forwards final NRR input for plant Cycle 3 systematic assessment of licenses performance evaluation Contributors listed NERGES.V Licensing Branch 3 82/10/01 EIBENHUT, D 0 Division of Licensing 6pp 19784 318 24X Fiche 50-389,82/10/01,8210210591
- B210130289 Forwards util responses to NRC concerns to inadequate core cooling instrumentation, per 820914 telcon w/NRC Qualification testing of heated junction thermocouple sys scheduled for completion by 821015 UHRIG.R E Florida Power & Light Co 82/10/05 EIBENHUT, D Q Division of Licensing 4pp 15678 306 24X Fiche 50-389,82/10/05,82(0130289
- 8210270339 Forwards status of control room design review Requests addition to progress wimplementing corrections for human engineering discrepancies & control room man-machine operations

 KERRIOAN.J D Licensing Branch 3 82/10/07 UHRIG, R E Florida

 Power & Light Co 7pp 15851 342 24X Fiche 50-389,82/10/07,8210270339
- 8210130301 Forwards list of engineering & constitems that are not expected to be completed at core load & justification for aperation prior to completion of items

 UHRIG.R E Florida Pawer & Light Co B2/10/08 EIBENHUT, D Q

 Division of Licensing 19pp 15678 184 24X Fiche 50-089, 82/10/08, 8210103031
- 8210190348 Forwards addl info re oneste ac power sys bus tie interlocks UHRIO.R E Florida Power & Light Co 82/10/12 EISENHUT.D 0 Division of Licensing 2pp 15737 243 24X Fiche 50-389.82/10/12, 8210190248

DOCKETED HEIVIS

- 8210250313 Informs that all generic itrs through 82-14 applicable to facility have been reviewed & required responses submitted UHRIG.R E Florida Power & Light Co 62/10/20 EISENHUT.D 0 Division of Licensing 1p 15790 063 24% Fiche 50-389.82/10/20, 8210250313
- 8210260114 Forwards minutes of 821006-07 meeting w/util.Ebasco & C-k task force managers re engineering verification program 8LOBOETT: T H Ebasco Services. Inc (subs of Enserch Corp.) 82/10/20 EISENHUT. 09 Division of Licensing 4pp 15799 112 24% Fiche 50-389,82/10/20,8210260114
- 6210280254 Forwards proprietary "Final Assessment of St Lucie 2 Fuel Structural Integrify Under Faulted Conditions." CEN-187(1)-P. Revision 1-P 8 "St Lucie 2 Fuel & CEA Design Summary Evaluation Rept," CEN-222(1)-P. Repts withheld UHRIO.R E. Florida Fower & Light Co. 82/10/26 EISENHUT.D 0 Division of Licensing 7pp 15845-316 24X Fiche 50-387,82/10/26,8210280254
- E NRC Bafety Evaluation Report (GER), supple & correspondence
- 8210180263 Notification of 821005 meeting w/util & C-E in Windsor,Cl to discuss review of closeout of SER Section 4.2, "Fuel Sys Design," open itsms WERSES,V Licensing Branch 3. 82/09/28 KERRIGAN,J D. Licensing Branch 3. 3pp 15746-325 24X Fiche 50-389,82/09/28,8210180263
- 8210180237 Requests add1 info re fuel analysis in order to complete review of SER confirmatory (saue MERRIGAN-J D Licensing Branch 3 82/10/01 UHRIO.R E Florida Power & Light Co 2pp 15746 258 24X Fiche 50-389,82/10/01,8210180237
- 8210120257 Forwards Alden Research Lab, "Performance Evaluation of Containment Sump at Full-Scale, St Lucie Nuclear Power Station 2" Submittal completes commitment to provide BER confirmatory info on vortex testing UHRIO,R E Florida Power & Light Co 82/10/06 EISENHUT,D 0 Division of Licensing 19 15678 051 24X Fiche 50-389,82/10/06,8210130257
- --821013D287 "Performance Evaluation of Containment Sump at Full-Scale, Bt Lucie Nuclear Power Station 2 " DUROIN,W H Alden Research Laboratory 106-82/M7KF 82/09/30 41pp 15678,052 24X Fiche 50-389.82/10/06.8210130257
- 8210280067 Forwards proprietary "Response to NRC Questions on Implementation of Bt Lucie Unit 2 Rod Bow 4 Orid Specing Fenalties" to resolve action items identified in SER (NUREG-0843). Hithheld (ref IOCFA2. 790). UHRIO, R E Florida Fower & Light Co 82/10/25 EISENHUT, D 0. Division of Licensing App 15837 241 24X Fiche 50-389.82/10/29, 2310080047
- F Security, medical, emergency & fire protection plans
- 9210010185 Forwards IE Insp Repts 50-338/82-28 & 50-389/82-37 on 820809-13. No noncompliance noted.

 DANCE, H C. Division of Project & Resident Programs 82/09/08. UMR 10. R. O Florida Power & Light Co. 2pp 15565 326 24X Fichs. 50-335, 82/09/08.9210010155

- 8210190056 Forwards request for addl into re 10CFR50.App R Sections III 0 % III L info required to complete review of fire protection of safe shutdown capability KERRIGAN.J D Licensing Branch 3 82/09/29 UHRIG.R E Florida Power & Light Co 3pp 15761 046 24% Fiche 50-389.82/09/29, 8210190056
- B21013034B Forwards response to Question 410 52 re fire protection requirements
 UHRIO, R E Florida Power & Light Co B2/10/07 EISENHUT, D G
 Division of Licensing 2pp 15682 036 24% Fiche 50-389,82/10/07,8210130348
- 8210260376 Ack receipt of 821013 ltr informing NNC of steps taken to correct violations noted in IE Sareguards Insp Rept 50-335/82-30 LENIS, R.C. Division of Project J. Resident Programs 82/10/22 UNRIG. R.E. Florida Power & Light Co. Ip. 15806 IJB 244 Fiche 50-335, 82/10/22, 8210260376
- --8210260510 Forwards IE Safeguards Insp Repts 50-335/82-30 & 50-389/82-41 on 820816-20 & notice of violation Notice of violation & rept defails withheld (ref 1007R73 21) LEMIS,R C Division of Project & Resident Programs 82/09/13 UMRIO,R E Florida Power & Light Co 2pp 15806-140 24x Fiche 50-335, 82/10/22, 8210260376
- --8210260515 IC Bafeguards Insp Repts 335/82-30 &50-369/82-41 on 820816-20 Moncompliance noted failure to comply w/security plan re vehicle control, alarms & compensatory action Details withheld (ref 10CFR/3 21) gODDE, R Region 2. Office of Director 82/09/10 2pp 18806 142 24 Fiche 50-335, 82/10/22,8210260376

M Antitrust correspondence

- B210120416 Notification of contract execution, Mod 2 to "Economic Assistance for St Lucia 2 Antitrost Proceeding ([1] "Contractor JM Kuhiman MCLEAREN.T Technical Assistance Contracts Branch FIN B-7543 B2/10/05 DENTON-H R Office of Nuclear Reactor Regulation, Director ip 13689 222 24X Fiche 50-389: B2/10/05. B210120416
- --82(0)20423 Mod 2, deabligating funds, to "Economic Assistance for St Lucie 2 Antitrust Proceeding (11) "
 KUHLHANJM Kulhman, JM HAGAN, TF Technical Assistance Contracts Dranch FIN B-7343 82/10/05 ip 15487 223 24x Fiche 50-389,82/10/05,8210120416
- O Inspection reports. IE Bulletins & correspondence
- 9210010213 Forwards IE Insp Rept 50-389/82-40 on 920817-20 No nancompliance noted DANCE.H C Division of Project & Resident Programs 82/08/31 UHR10.R E Florida Power & Light Co 2pp 15568 043 24X Fiche 50-389,82/08/31,8210010213
- ---8210010216 IE Insp Rept 50-369/82-40 on 820817-20 No noncompliance noted Hajor areas inspected instrumentation cable & termination work & work activities, cable & termination GC records & followop on licenses identified items (MERRIMEATHER, N. CONLON, T.E. Division of Engineering & Technical Programs 82/08/27 3pp 15568 045 24X Fiche 50-389,82/08/31,8210010213
- 8210010155 Forwards IE Insp Repts 50-335/82-28 & 50-389/82-37 on 820809-13 No noncompliance noted DANCE, H C Division of Project & Resident Programs 82/09/08 UHRIO.R.E. Florida Power & Light Co 2pp 15565-326 24X Fichs 50-335, 82/09/08,8210010155
- --8210010157 IE Insp Repte 50-335/82-28 & 50-389/82-37 on 820809-13 % noncompliance noted Major areas inspected follows on sentrepency preparadness appraisal & serciae findings HUFFMAN-6, N., JENKINB, O. R. Division of Emergency Preparadness & Operational Support 82/09/02 188p 15565 328 24X Fichs. 80-338, 82/09/08, 8210010155

- 8210120655 Forwards draft input to systematic assessment of licenses performance for review & comments Comments should be submitted by 820910.for consideration in final rept W/o
- ancl I dicensing Branch 3 82/09/09 EISENHUT, D 0 Division of Licensing HATTSON, R L Division of Systems Integration (past Bi1005) THOMAS, H Division of Human Factors Safety ip 18572 334 24X Fichs 50-389, 82/09/09, 8210120
- 9210010301 Forwards IE Insp Rept 50-389/82-41 on 820824-27 No noncompliance noted DANCE,H C Division of Project & Resident Programs 82/09/10, UHRIO,R E Florida Power & Light Co 2pp 15568 310 24X Fiche 50-389,82/07/10.8210010301
- -8210010305 IE Insp Rept 50-389/82-41 on 820824-27 No noncompliance noted Major areas inspected safety-related pipe support & restraint sys & seismic analysis for as-built safety-related piping sys
 YORK, J W. BLAKE, J J Division of Engineering & Technical Programs 82/09/08 5pp 15568 312 24X Fiche 50-389,82/09/10,8210010301
- 210150345 Forwards IE Insp Repts 50-335/82-31 & 50-389/82-38 on 820830-0903 No noncompliance noted DANCE, H C Division of Project & Resident Programs 82/09/22 UHR10, R E Florida Power & Light Co 1p 15704 322 24X Fiche. 50-335, 82/09/22, 8210150345
- -B210150398 IE Insp Repts 50-335/82-31 & 50-389/82-38 on B20830-0903 No noncompliance noted Major areas inspected redinactive liquid & gaseous effluent releases, reactor coolant chemistry & radioactive transportation activities WRAY.J R. BARR.K P. Division of Engineering & Technical Programs 82/09/17 10pp 15704 323 24X Fiche 50-335.82/09/22, B210150345.
- '10150262 Forwards IE Insp Rept 50-389/82-42 on 820830-0903 No noncompliance noted DANGE, N C Division of Project & Resident Programs 82/09/27 UNR30, R E, Florida Power & Light Co 2pp 15703 261 24X Fiche 50-389-82/09/27,8210150262
- 8210150269 IE Insp Rept 50-389/82-42 on 820830-0903 No noncompliance noted Major areas inspected preoperational test procedure review, test witnessing & test procedure verification & plant tour TAYLOR,P.A. JAPE.F. Division of Engineering & Technical Programs 82/09/23 4pp. 15703 263 24X Fiche.50-389,82/09/27,8210150262
- 10210591 Forwards final NRR input for plant Cycle 3 systematic assessment of licensee performance evaluation, Contributors listed VERBER.V Licensing Branch 3 82/10/01, EISENHUT, D Q Division of licensing App 15784 318. 24% Fiche 50-389, 82/10/01, 8210210591
- 00190293 IE Info Notice 80-98, Suppl 1, "Leaking & Dislodged I-125 mplant Seeds." Svc list encl
 1088, L I. Division of Fuel Facilities, Materials & Gafeguards
 12/10/06 Consolidated Edison Co of New York 66pp 15761 250,
 14X Ficha: 50-000, 82/10/06, 8208190293
- 8190238 IE Bulletin 82-03, "Stress Corrosion Cracking in Thick-"alirLarge-Diameter; Stainless Steel, Recirculation Bys iping at BMR Plants " Svc list end! EYQUNO, R C. Director's Office, Office of Inspection and nforcement 82/10/14 Consolidated Edison Co of New York 15pp. 15810 125, 24X Fiche 50-000, 82/10/14, 8208190238.
- 0220280 Ack receipt of 820930 ltr informing NRC of steps taken to errect violations noted in IE Insp Repts 50-335/82-11 & D-395/82-34
 ANCE, H G. Division of Project & Resident Programs 82/10/15
 -RIO, R E. Florida Power & Light Co. ip, 15775 084
 24X
 iche. 50-335, 82/10/15, 8210220280.
- 210220291 Forwards IE Insp Repts 50-335/82-11 & 50-389/82-34 on 820711-0810 & notice of violation.
 DANCE, H.C. Division of Project & Resident Programs 82/09/01 UHRIG, R.E. Florida Power & Light Co. 2pp 15775 087, 24% Fiche 50-335,82/10/15,8210220280
- '10220303 IE Insp Repts 50-335/82-11 & 50-389/82-34 on 820711-0810 Noncompliance noted on 820805, Equipment Clearance Order L-8-30 incorrectly identified suction & discharge drain valves V-2317 & V-2327 for charging pump A. ELROD, 8 A , 8188, H.E., JULIAN, C A Division of Project & Resident Programs. 82/08/31. 10pp. 15775:090 24X Fiche: 50-335, 82/10/15, 8210220280.

- 8210260376 Ack receipt of 821013 ltr informing NRC of steps taken to correct violations noted in IE Safeguards Insp Rept 30-335/82-30
 LEWIS, R C Division of Project & Resident Programs 82/10/22
 UHRIG, R E Florida Power & Light Co ip 15806 138 24X
 Fiche, 50-333, 82/10/22, 8210260376
- ~-8210260510 Forwards JE Safeguards Insp Repts 50-335/82-30 & 50-389/82-41 on 820816-20 & notice of violation Natice of violation & rept details withheld (ref 10CFR72 21) LEWIS.R C Division of Project & Resident Programs 82/09/13 UNRIG.R E Florida Power & Light Co 2pp 15806 140 24X Fische 50-335,82/10/22.8210260376
- ~-8210260515 IE Safeguards Insp Rept 50~335/82~30 & 50~389/82~41 on 820816~20 Nancompliance noted failure to comply w/security plan re vehicle control alarms & compensatory action Details withheld (ref 10CFR73 21) GOODE, R . STANSBERRY, W . MCGUIRE, D R . Region 2, Office of Director 82/09/10 2pp 15806 142 24X Fiche 50~335.82/10/22, 8210260376
- R Periodic operating reports & related correspondence
- 8210040072 Forwards joint Ebasco & C-E task force program weekly status summary for 820920-25
 BLODOETT, TH Ebasco Services, Inc. (subs. of Enserch Corp.)
 82/09/24 EISENHUT.D 9 Division of Licensing App. 15581 272
 24X Fiche 50-389, 82/09/24, 8210040072
- 8210060371 Forwards const/startup progress rept for Aug 1982 Target fuel load date of 821028 still valid URRIO.R E Florida Power & Light Co 82/10/01 EIGENHUT.D G Division of Licensing 2pp 15618 328 24X Fichs 50-389.82/10/01, 8210060371
- 8210150431 Forwards weekly status summary of joint Ebasco & C-E verification program for 821004-08
 BLODGETT.T H Ebasco Services. Inc (subs of Enserch Corp.)
 B2/10/08 EISENHUT.D O Division of Licensing 4pp 15704 015
 24X Fiche 50-389, 82/10/08, 8210150431
- 8210260466 Forwards joint Ebasco & C-E task force engineering verification program weekly status summary for 821011-15 BLODGETT: TH Ebasco Services. Inc. (subs. of Enserch Corp.) 82/10/15 EISENHUT: D. D. Division of Licensing 4pp. 15807-225 24X Fiche 50-389,82/10/15,8210260466
- 8210250317 Forwards const/startup monthly progress rept for Sept 1982 UHRIO:R E Florida Power & Light Co 82/10/19 EISENHUT, D 0 Division of Licensing 2pp 15790 292 24X Fiche 50-389, 92/10/19, 8210250317
- 8 Reportable occurrences, LERs & related correspondence
- 8210060236 Final deficiency rept re undersize fillet walds Initially reported on 820831 Insp program revised & all undersized flange & socket fitting walds will be repaired QC breakdown not responsible for event UHRIO.R E Florida Power & Light Co 82/09/30 O'REILLY, J P Region 2, Office of Director 3pp 15619 357 24X Fiche 50-389, 82/09/30.8210060236
- 8210130070 Final deficiency rept re incorrect shaft bearings on diesel generator motors 2A1 & 2A2 Initially reported on 820826 Shaft bearings replaced w/self-aligning bearings. Not reportable per 10CFR80 55s.but reportable per Part 21 UHRIO.R E Florida Power & Light Co 82/10/01 0'REILLY, J P Region 2, Office of Director. 2pp 18673 119 24% Fiche 50-389.82/10/01.8210130090
- B210130536 Interim deficiency rept re fan belts on diesel generators 2A & 2B Initially reported on B20210 Final rept will be submitted by 821300 UHRIG.R E Florida Power & Light Co B2/10/01 O'REILLY, J P. Region 2. Office of Director ip 15682 193, 24X Fiche, 50-389, 82/10/01,8210130536
- 8210220167 Interim deficiency rept re failure of reactor shutdown cooling bypass valves to respond to command signals Initially reported on 820400 Util still reviewing problem Final rept will be submitted by 821030.

 UMRIO.R E Florida Fower & Light Co. 82/10/04. O'REILLY, J. P. Region 2, Office of Director ip 15776 362. 24X Fichs 50-389, 82/10/06,8210220167

DOCKET 50-390 WATTS BAR NUCLEAR PLANT. UNIT 1

- A Applacation/construction stage documents & correspondence
- 210010038 Responds to FOIA request for 19 categories of documents renuclear reactor events & safety problems Forwards documents listed in App A FELTON.J H Division of Rules and Records 82/06/28 UDELL.R A Critical Mass Energy Project (5pp 15727 005 24x Fishe 50-000, 82/06/28, 8210010008
- -8008050265 Discusses add1 required info to better define potential for cracking in reactor vessel notites
 NOONAN.V S Assistant Director for Materials & Qualifications
 Engineering 80/05/05 TEDESCO.R L Assistant Director for
 Licensing 2pp 15727 176 24X Fiche 50-000,82/06/28,8210010008
- 210180331 Forwards evaluation of Apr 1982 site audit of safety-related electric & mechanical equipment Resolution of specific concerns in single submittal requested AUDVAK.T H. Assistant Director for Licensing 82/09/23 PARRIS.H & Tennessee Valley Authority 39pp 15746 282 24X Fiche 50-370, 82/09/23, 8210180331
- 10190084 Summary of 820917 meeting w/util & Black & Veatch in Bethesda/MD re applicant plans to perform independent design verification of auxiliary feedwater sys Attendance list & vieugraphs encl KENYDN.T J Operating Reactors Branch 4 82/10/01 Operating Reactors_Tranch 4 13pp 15761 102 24X Fiche 50-390,82/10/01
- :1028020B Forwards revised FSAR Section 17 2.consisting of Table 17 2-1.listing cratical structures.sys & components Info will be included in Amend 48 to FSAR MILLS.L M Tennessee Valley Authority 82/10/25 ADENSAM.E Licensing Braich 4 14pp 15839 293 24X Fiche 50-390,82/10/25,821028020B

NRC Safety Evaluation Report (SER), suppls & correspondence

- 10050405 SAFETY EVALUATION REPORT RELATED TO THE OPERATION OF THE WATTS BAR NUCLEAR PLANT, UNITS: AND 2 Docket Nos 50-390 And 50-391 (Fornessee Valley Authority) # Office of Nuclear Reactor Regulation, Director NUREG-0847 801 82/09/30 29pp Available at NRC 44 50 15625 299 24X Fiche 50-390.82/09/30.8210050405
- Security, medical, emergency & fire protection plans
- 10220225 Requests NRC perform preliminary review of util program for watchtower power block security concept Meetings suggested for 82102-03 as part of review Agenda entil HLLS.L M Tennessee Valley Authority 82/10/18 EISENHUT, D 0 3/10/20225
- 10260174 Forwards revised security plan.including updated table of contents & revised Page A-5 Revision withheld (ref 10CFR73 21) fillS.L H Tennessee Valley Authority 82/10/20 ADENSAM.E .lcensing Branch 4 ip 15799 048 24X Fiche 50-390, 82/10/20,
- O260189 Confirms that evacuation time estimate study reviewed by oth local & TN state authorities Population density & listribution info provided by TN Dept of Civil Defense based in 1980 census
 ILLLS.L. K. Tennessee Valley Authority 82/10/20 ADENSAM, E. 0. icensing Branch 4 2pp 15799 030 24% Fichs 50-000,82/10/20, 50189

- Q Inspection reports, IE Bulletins & correspondence
- B210080015 Add1 response to FOIA request for 19 categories of infoir nuclear reactor events b safety problems Forwards documents listed in App A Documents in App B completely withheld (ref FOIA Exemption 5) FELTON.J M Division of Rules and Records B2/0//12 UDFil.N A Critical Mass Energy Project 9pp 15665 027 24X Fiche 50-000,82/07/12,8210080015
- --8210080167 Systematic assessment of licensee performance onto a 14 racility evaluation for Aug 1979--041 1980
 4 MRC No Detailed Affaliation Given 80/07/31 App 15868 101 24X Fiche 50-000,82/07/12,8210080015
- 8210220223 Submits add1 into to 820324 response to 1E Insp Rept 50-390/82-03 Revision of FSAR Table 14 2-1 & Chapter 9 will not be complete until 821015 MILLS.L M Tennessee Valley Authority 82/08/11 O'REILLY, J P Region 2, Office of Director [p 15776 210 24X Fiche 50-390, 82/08/11, 8210220223
- 5210010452 Forwards IE Insp Repts 50-390/82-31 & 50-391/82-28 on 620024-27 No noncompliance noted VERRELLI.D M Division of Project & Resident Programs 82/09/09 PARRIS.N G Tennessee Valley Authority 2pp 15572 305 24X Fiche 50-390, 82/09/09, 8210010452
- --8210010462 IE Insp Repts 50-370/82 II & 50-371/02 -20 on H20024-27 No noncompliance noted Major areas inspected instrumentation, installation & nonconforming lepts & conceptual design requirements HUNT.N D. CONLON.T E. Division of Engineering & Technical Programs 62/09/07 App. 155/2 JOT. 24X Fiche 50.390.62/09/09 8210010432
- 8210150304 Forwards IE Insp Repts 50-390/82-32 & 50-391/82-29 on 820824-27 No noncompliance noted VERRELLI, D M Division of Project & Resident Programs 82/09/10 PARRISH 6 Tennessee Valley Authority 2pp 1570/295 24x Fiche 50-390, 82/09/10, 82101503004
- --B210150315 IE Insp Repts 50-370/82-32 & 50-391/82-29 on 8208-4 & 27 No noncompliance noted Major areas inspected engineering design work MCFARLAND, C.R. DLEDAGE, A.O., UPRIGHT, C.H. DIVISION of Finajori & Resident Programs 82/09/10 Spp 15707 297 24X Fichs 50-390,82/09/10,8210180304
- 8210150323 Forwards IE Insp Repts 50-390/02-30 & 50-391/82-27 on 820721-0820 No noncompliance noted VERRELLI, D M Division of Project & Resident Programs 02/04/16 PARRISH 0 Tennessee Valley Authority 2pp 15/21 270 24X Fiche 50-390, 82/09/16, 8210150323
- --B210150331 IE Insp Repts 50-390/82-30 & 50 391/8R-27 on 820721-0820 k noncompliance noted Major areas inspected literases action on previous insp findings & review of periodic & special repts HEATHERLY, T. L., QUICK, D. R. Division of Project & Resident Programs 82/09/16 5pp 15721 272 24X Fiche 50-390,82/09/16,8210150323
- 8210010333 Act receipt of 820826 itr informing NRC of steps taken to correct violations noted in IC lnsp Repts 50-390/01-03 & 50-391/81-03 Williams of Project & Resident Programs 62/09/17 PARRIS, H 0 Tennessee Valley Authority 1p 15568 238 24X Fiche 50-390, 82/09/17,8210010333
- --B210010341 Suppls response to NRC 020414 ltr re violations noted in IE Insp Repts 50-370/BI-03 & 90-371/BI-03 Corrective actions leak integrity of body bonnet joint verified prior to startup & component tolerance will be confirmed MILLS.L.H. Tennessee Vallem Authority. 82/00/24 Department.

1.

j.

١,

- 3210220315 Forwards IE Insp Repts 50-390/82-34 & 50-391/82-31 on 820914-17 No noncompliance noted VERRELLI D M Division of Project & Resident Programs 82/09/30 PARRIS, N G Tennesses Volley Authority 2pp 15776 038 24X Fiche 50-390,82/09/30,8210220315
- -82[0220323 IE Insp Repts 50-390/82-34 & 50-391/82-31 on 820914-17 No noncompliance noted Major areas inspected instrumentation cable / termination.observation of work.work activities, review of quality records & licensee identified items RUFF, A B , CONLON, T E Division of Engineering & Technical Programs 82/09/29 3pp 15776 040 24X Fiche 50-390.82/09/30, 8210220315
- F10150207 Ack receipt or 820825 Itr informing NRC of steps taken to correct violations noted in IE Insp. Repts 50-390/82-18 & 50-391/82-15 Add info requested by 820923 talcon VERRELLI.D M Division of Project & Resident Programs 82/10/04 PARRIS.H C Tennessee Valley Authority ip 15706 083 24X Fiche 50-390, 82/10/04, 8210150209
- 8210150230 Responds to NRC 820707 ltr re violations noted in IF Insp Repts 50-390/82-18 & 50 391/82-15 Corrective actions personnel instructed in application of EP 1 26 to limited QA sys MILLS.L M Tennessee Valley Authority 62/09/24 O'REILLY, J P Region 2. Office of Director 4pp 15706 084 24X Fiche 50-390.82/10/04.8210150209
- 8210150241 Responds to NRC 020702 ltr re violations noted in IE linsp Repts 50-390/82-10 & 50 391/82-15 Corrective actions program to instruct all personnel in all procedures affecting design work implemented MICLS.L M Tennessee Valley Authority 82/08/25 0'REILLY.J P Region 2. Office of Director 3pp 15706 088 24X Fiche 50-390,82/10/04-82/0150209
- 62[0] 50251 Responds to NRC #20707 Prime violations noted in IE Insp. Repts 50-390/82-18 & 50-391/82-15 Corrective actions EP 1 28. "Control of Documents Affecting Guality," will require independent verification of procurement specs. MILLS, E. M. Tennossee Valley Authority 82/08/20 0'REILLY, J.P. Region 2. Office of Director 3pp 15706-091 24% Fiche 50-390.82/10/04.8510150209
- 82:0150260 Discusses IE Insp Repts 50-370/82-18 & 50-391/82-15 on (#20421-0520 & forwards corrected App A (notice of rolation)
 LEMIS.R C Division of Project & Resident Programs 82/07/07
 PARTIS.H 0 Tennessee Valley Authority 2pp 15706-094 24X
 Fiche 50-390.82/10/04 82/0150209
- 710150268 Corrected notice of violation from insp on 820421-0820 Noncompliance noted nonconforming condition rept not initiated for recignized diesel generator tube oil deficiencies ◆ Region 2, Office of Director 82/07/07 2pp 15706 096 24x Fiche 50-390.82/10/04-8210150209
- 210150278 Forwards IE Insp. Repts 50-390/82-18 & 90-391/82-15 on 820421-0520 & notice of violation
 LEWIS.R C Division of Project & Resident Programs 82/06/08 PARKIG.H G Tennessee Valley Authority 2pp 15706 098 24X Fiche 50-390.82/10/04.8210150209
- 210150206 Notice of violation from insp on 820421-0520 * Region 2 Office of Director 82/05/08 2pp 15706 100 24: Fichs 50-0390,82/10/04.82/0150209
- 210150303 IE Insp Repts 50-990/82-18 t 50-991/82-15 on 820421-0520 Moncompliance noted failure to design for environ effects. Follow corrective action procedures & conduct adequate addits MCDDNALD, J A . HEATHERLY, T L . QUICK, D R Division of Project & Resident Programs 82/06/08 App 15706 102 24X Fiche 50-390,82/10/04,8210150209
- 8190233 IE Info Notice 80-35. Suppl 1: "Leaking t Disladged I-125 pplant Seeds " Svc list encl

 DB.L I Division of Fuel Facilities. Materials & Safeguards

 2/10/06 Consolidated Edison Co of New York 66pp 15761 250

 4% Fiche 50-000.82/10/06.8208190233
-)150349 Forwards Pages 5 & 6 to 1E Insp Repts 50-390/82-32 & D-391/82-29 inadvertently omitted from 820910 transmittal IRRCLLI,D M Division of Project & Resident Programs 82/10/07 NRIS.H G Tennessee Valley Authority 2pp 15704,318, 24% Iche 50-390,82/10/07.8210150349
- 10150355 Pages 5 & 6 to IE Insp Repts 50-390/82-32 & 50-391/82-29 inadvertently omitted from B20910 transmittal * Region 2. Office of Director 82/10/07 2pp 15704 320 24X Fichs 50-390, 82/10/07, 8210150349

- 8208190238 IE Bulletin 82-03, "Stress Corrosion Cracking in Thick-Wall-Large-Diameter, Stainless Steel, Recirculation Bys
 Piping at BWR Plants " Svc list encl
 DEYCUNG, R Director's Office, Office of Inspection and
 Enforcement 82/10/14 Consolidated Edison Co of New York
 115pp 15810 125 24X Fiche 50-000, 82/10/14, 8208190238
- 8210220459 Ack receipt of 820715 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-390/81-26 & 50-391/81-24 VERRELLI.D M Division of Project & Resident Programs 82/10/18 PARRIS.H O Tennessee Valley Authority ip 15779 133 24X Fiche 50-390.82/10/18.8210220459
- 8210220466 Advises that corrective actions per violations noted in IE insp Repts 50-390/81-26 & 50-391/81-24 will be completed by 821103 MILLS.L M Tennessee Valley Authority 82/09/15 G'REILLY, J P Region 2. Office of Director 1p 15779 134 24X Fiche 50-390,82/10/18.8210220459
- 8210220472 Ack receipt of 820924 ltr informing NRC of steps taken to correct violations noted in IE Insp Ropts 50-390/82-18 & 50-391/82-15 VERRELLI, D M Division of Project & Resident Programs 82/10/18 PARRIS, N O Tennesse Valley Auchority 1p 15779 102 24X Fiche 50-390,82/10/18.821022047
- S Reportable occurrences, LERs & related correspondence
- 8210080168 Sixth interim deficiency rept re qualification of epoxy grout for safety-related applications Initially reported on 820827 Support mods or add1 supports recommended Drawing revisions an progress Completion expected by mid-May 1783 MILLS.L M Tennesses Valley Authority 82/09/23 0'REILLY, J P Region 2. Office of Director 3pg 15640 154 24X Fiche 50-390.82/09/23.8210080168
- 8210090316 First interim deficiency rept re incorrect insulation weights used in piping analysis initially reported on 820829 QA document being prepared to substantiate insulation data Naxt rept will be submitted by 830429 MILLS.L.M. Tennesses Valley Authority 82/09/24 D'REILLY, J.P. Region 2, Office of Director 2pp 15610 281 24X Fiche 50-390,82/09/24,8210050316
- 8210080247 Third & final deficiency repts re resolution of unanticipated vibratory loading concerns initially reported on 811228 Program developed to insure piping sys operate within design parameters Next rept provided by 821217 MICLS, L. M. Tennessee Valley Authority 82/09/24 0 (REILLY, J. P. Region 2, Office of Director 2pp 15638, 104 24% Fiche 50-000, 82/09/24, 8210080247
- 0210050062 First interim deficiency rept re failure to consider seismic & inertial loadings on ladders Initially reported on 620826 Ladder, platform or walkway found deficient will be modified or stiffened Next rept expected by 630124 MILLS.L M Tennessee Valley Authority 62/09/27 0'REJLLY.J P Region 2. Office of Director 2pp 15603 236 24X Fiche 50-390.62/09/27.6210050042
- 8210050099 Second interim deficiency rept re potential for setpoint program for everpressure mitigating sys to exceed IOCFR50, App 0 requirements Initially reported on 820521 Util procuring solenoid-actuated valves Next rept by 830331 MILLS,L M Tennessee Valley Authority 82/09/27 O'REILLY, J P Region 2. Office of Director 2pp 15603 242 24X Fiche 50-390, 82/09/27, 8210050099
- 8210050114 Add1 info to final deficiency rept re suismic supports for auxiliary feedwater control valves initially reported on 800624 Corrective actions on Unit 1 completed 820831 Unit 2 valves unil be installed during normal const schedula MILLS.L M Tennessee Valley Authority 82/09/27 O'REILLY, J P Region 2. Office of Director in 15603 256 24% Fiche 50-390,82/09/27,8210050114
- 8210050293 First interim deficiency rept re six sheared motor pinion yeys in Limitorque Model SB-0-25 motor operators Initially reported on 820830 Valves w/motor operators being tabulated. Next rept will be submitted by 821122 MILLS.L M Tennessee Valley Authority 82/09/28 0'REILLY, J P Region 2, Office of Director 2pp 15609 070 24X Fiche 50-000.82/09/28,8210050293
- 8210030158 Second interim rept re-undocumented minor mode to structural & miscellaneous steel Initially reported on B20510 Approx 95% of 250 features had preliminary inst/punchiist completed Next rept to be submitted by B30228 MILLS.L M Tennesses Valley Authority. B2/09/29 O'REILLY, J P Region 2. Office of Director 2pp 15605:154 24% Fiche 50-390.82/09/29,8210050158

- 8210050280 First interim deficiency rept re solid-state protection systest procedures Initially reported on 820831 Util reviewing Westinghouse proposal for Interim procedural change which would provide for failure detection Next rept by 821210 HILLS.L M Tennessee Valley Authority 62/09/29 0'REILLY.J P Region 2. Office of Director 29p 15621 164 24X Fiche 50-390, 82/09/29, 8210060280
- 8210060205 Fourth interim deficiency rept re inadequate loading criteria for structural steel & supports Initially reported on 811117 General notes revised to clarify drawings field mapping of platform steel continuing Next rept by 830310 MILLS.L M Tennessee Valley Authority 82/09/30 0'REJLLY, J P Region 2. Defice of Director 2pp J5614 041 24X Fiche 50-390,82/09/30,8210060205
- 8210060279 First interim deficiency rept re selection of undersized sway struts Initially reported on 820901 Selection methods & adequacy of Sergen-Paterson struts under evaluation Next rept expected by 830225 MILLS.L M Tennessee Valley Authority 82/09/30 O'REILLY, J P Region 2, Office of Director 2pp 15621 166 24X Fiche 50-390, 82/09/30, 8210060279
- 8210080255 First intersm deficiency rept re inadequate QA program for masonry block work [initially reported on 820902 Const personnel investigating & replying to audit Next rept due on 821214
 MILLS.L M Tennessee Valley Authority 82/10/01 O'REILLY, J P Region 2, Office of Director 2pp 15638 116 24X
 Ficks 50-390, 82/10/01.8210080255
- 8210080280 First interim deficiency rept re interpretation of radiograph test film on welded pipe by Swepco Tube Corp Initially reported on 820901 Evaluation continuing Next rept will be submitted on 830217 MILLS.L M. Tennessee Valley Authority 82/10/01 0'REILLY.J P. Region 2. Office of Director 2pp 15638 201 24% Fiche 50-390, 82/10/01.8210080280
- 8210080291 First interim deficiency rept re failure to terminate cables iPSI11. IPSI12. IPMI850. IPMI852, IPMI857. IPSI52 & IPSI53 Initially reported on 820901 Cables terminated & personnel retrained Next rept will be submitted by 821123 MILLS.L M Tennessee Valley Authority 82/10/01 O'REILLY. J P Region 2. Office of Director 2pp 15638 308 24X Fische 50-390. 82/10/01.8210080291
- 8210080160 First interim deficiency rept re corrusion in high pressure fire protection sys Initially reported on 820903 Corrosion analysis in progress to determine patential deficiences in safety-related areas Next rept expected by 830831 MILLSIL M Tennessee Valley Authority 82/10/04 0'REILLY, J P Region 2. Office of Director 2pp 15640 142 24x Fiche 50-000.82/10/04.8210080160
- 8210080310 First interim deficiency rept rellack of piping sys analysis tracking Initially reported on 820902 Util investigating corrective actions to ensure engineering change notices are not closed out until work is completed HILLS.L.M. Tennesses Valley Authority 82/10/04 D'REILLY, J.P. Region 2. Office of Director 2 pp. 15638 042 24% Fiche 50~390, 82/10/04, 8210080310
- 8210130247 Sixth interim deficiency rept re differential settlement of rock supported structures initially reported on 810707 Individual safety-related components at interfaces of structures being evaluated. Next rept by 830304 MILLS.L. H. Tennesser Valley Authority 82710705 D'REILLY, J.P. Region 2. Office of Director ip 15676 009. 24X Fiche 50-390, 82107093,8210730247
- 8210130384 Suppl to final deficiency rept re essential raw cooling water seismic support Initially reported on 810506 Completion of Bergen-Patterson review expected by 821101 Also reportable per Part 21 MILLS, L. M. Tennessee Valley Authority 82/10/05 O'REILLY, J. P. Region 2, Office of Oirector ip 15681:003 24X Fiche 50-390, 82/10/05.8210130384
- 82:0130560 Second interim deficiency rept re frequency criteria for piping supports. Initially reported on 820713 Investigation continuing Nast rept expected by 82:1220.

 MILLS.L.M. Tennesses Valley Authority 82:10/05 0'REILLY, J.P. Region 2. Office of Director. ip 15683-299 249

 Fiche 50-390 82:10/05 20:10

- 521022009B First interim deficiency rept re qualification of process piping w/instrument lines attached Initially reported on 820090 Affected piping being reanalysed to account for effect on instrument line piping Next rept by 830429 MILLS.L H Tennessee Valley Authority 82/10/08 0'REILLY, J.P. Region 2. Office of Director 2pp 15777 362 24X Fiche 50-390.82/10/08.8210220098
- 8210190307 Final deficienty rept re failure to meet pipe support luq criteria initially reported on 820607 Lug parameter limit discrepancy corrected MILLS.L M Tennessee Valley Authority 82/10/12 O'REILLY, J.P. Region 2, Office of Director 2pp 15742 155 24X Fiche 50-390.82/10/12.8210170307
- 8210290328 Second interim deficiency rept re use of honconservative calculational method to evaluate General Const Spec 0-32 spacing violations Initially reported on 820528 Next rept will be sent by 830528 MHLLS.L H Tennessee Valley Authority 82/10/12 O'REILLY, J P Region 2, Office of Director 2pp 15853 044 24X Fich 50-000.82/10/12.8210290328
- 9210190357 First Interim Deficiency Rept 50-390/82-100 re as-built & as-analyzed configuration discrepancies Initially reported on 820910 Response to 1E Bulletin 79-14 will be carried out in two phases insp & review of findings Next rept by 830325 MILLS.C.M. Tennessee Valley Authority 82/10/13 O'REILLY.J.P. Region 2. Office of Director 2pp 15742 102 24X Fiche 50-390.82/10/13.8210190357
- 8210290236 Third interim deficiency rept re-patentially overstressed embedded plates Instially reported on 820412 Investigation continuing & const activities deferred until sufficient infogathered to determine completion of project HILLS.L M Tennessee Valley Authority 82/10/14 O'REILLY.J P Region 2. Office of Director 2pp 15853-229 24X Fiche 50-000.82/10/14.8210270236
- 8210290052 Second interim deficiency rept re use of incorrect response spectra in Gilbert/Commonwealth piping analysis Initially reported on 820426 Reanalysis continuing Next rept expected by 820422 Also reportable per Part 21 MILLS, L.H. Tennessee Valley Authority 82/01/15 O'REILLY, J.P. Region 2, Office of Director ip 15853 324 24X Fiche 50-390-82/10/15, 8210290052
- 9210290178 Sixth interim deficiency rept re rerouting of high pressura fire protection piping initially reported on 810130 Three areas may contain worst case condition No deficiencies identified in two areas Nest rept provided by 821210 MILLS-L H Tennessee Valley Authority 82/10/15 O'REILLY, J P Region 2. Office of Director 1p 15853 311 24X Fichs 50-390,82/10/15,8210290178
- 8210260320 First interim deficiency rept re addition of locking devices to handwheel operated valves Initially reported on 820916 Const activities deferred Analyses of locking devices continuing Next rept will be sent by 820310 MILLS, L.M. Tennessee Valley Authority 82/10/18 0'REILLY, J.P. Region 2. Office of Director 2pp [5602 359 24X Fiche 50-000.82/10/18.8210260330
- 8210260451 Fourth interim deficiency rept re failure to include documented piping insulation insps in GC program Initially reported on 811009 Const Specs N3C-881 & N3C-912 revised to provide scope of insp requirements Next rept by 830425 MILLS, L.H. Tennessee Valley Authority 82/10/18 0'REILLY, J.P. Region 2, Office of Director 2pp 15807 104 24X Fiche 50-390,82/10/18,8210260451
- 8210260186 Second interim deficiency rept re underdesign of essential raw cooling water intake pumping station doors & hatches Initially reported on 820407 Flathead screws added to door frame for reinforcement Next rept expected by 830331 MILLS.L.M. Tennesses Valley Authority 82/10/19 0'REILLY, J.P. Region 2. Office of Director 2pp 15799 034 24X Fiche 50-390, 82/10/19, 8210260186
- 8210260370 Eighth interim deficiency rept re improper classification of essential raw cooling water sys piping & components initially reported on Bi03242 investigation ongoing Next rept will be submitted by B30427 MILLS.L H Tennessee Valley Authority 82/10/17 D'REILLY.J P Region 2. Office of Director ip 15803 104 24X Fichs 30-390.82/10/19.8210260390
- 8210260100 Second interim deficiency rept re lack of seismic analysis on auxiliary bldg platform Initially reported on 820426 Documentation for all attachments to suspect platforms being investigated Next rept expected by 830217 MILLS,L.M. Tennessee Valley Authority 82/10/20. O'REILLY, J P Region 2. Office of Director 2pp 13799 122. 24X Fiche 50-390, 82/10/20. 8210260100

026040B Second interim deficiency rept re potentially deficient alve yoke holddown nut Initially reported on 820601 Util waiting Westinghouse resolution for NSSS valves Also eportable per Part 21

waiting Hestinghouse resolution for Mada valves Kisu eportable per Part 21 MLLS.L M Tennessee Valley Authority 82/10/20 O'REILLY. J P egibn 2 Office of Director 2pp 15803 109 24X iche 50-390.82/10/20.8210260408

0290266 Fourth interim deficiency rept re failure of Limitorque of or operators during valve closure initially reported on 20126 Westinghouse, Limitorque & util investigating problem sit rept expected on 830128 Part 21 considered applicable ILLS.L.M. Tennessee Valley Authority 82/10/21 0'REILLY, J.P. 2140 2. Office of Director ip 15854 046 24X 1che 50-390, 82/10/21, 8210290266

1290274 Final rept for Deficiencies B & E & seventh interim rupt for ificiencies A & D re control of procurement activities initially reported on 810316 Final corrective actions noted it rept expected by 830428 LLS.L M Tennessee Valley Authority 82/10/21 O'REILLY, J P gion 2, Office of Director 4pp 15853 143 24% che 50-000.82/10/21.8210270274

ET 50-391 WATTS BAR NUCLEAR PLANT, UNIT 2

pplication/construction stage documents & correspondence

DIOCOOR Responds to FDIA request for 19 categories of documents reclear reactor events & safety problems Forwards documents sted in App A TOW, J M Division of Rules and Records 82/06/28 UDELL, R A itical Mass Energy Project 15pp 15727 005 24X he 50-000.82/06/28.8210010008

18050265 Discusses add! required info to better define potential for racking in reactor vessel noziles (CONAN, V S Assistant Director for Materials & Gualifications ngineering 80/05/05 TEDESCO.R L Assistant Director for icensing 2pp 15727 176 24X Fiche 50-000.82/06/28.8210010008

90084 Summary of 820917 meeting w/util & Black & Veatch in hesda. MD re applicant plans to perform independent design iffication of auxiliary reedwater sys Attendance list & wgraphs encl
YEN.T J Operating Reactors Branch 4 82/10/01 Operating ctors Branch 4 13pp 1576/102 24X Fiche 50~390,82/10/01.

3020B Forwards revised FSAR Section 17 2.consisting of Table 2-1, listing critical structures, sys & components Info to the included in Amend 48 to FSAR .S.L M Tennessee Valley Authority 82/10/25 ADENSAM.E. Insing Branch 4 14pp 15839 293 24X Fiche 50-390,82/10/25, X28020B

: Bafety Evaluation Report (SER), supple & correspondence

10405 SAFETY EVALUATION REPORT RELATED TO THE OPERATION OF THE S BAR NUCLEAR PLANT, UNITS 1 AND 2 Docket Nos 50-390 And 191 (Tennessee Valley Authority)
191 (Tennessee Valley Authority)
1916 of Nuclear Reactor Regulation, Director NUREO-0847 801 9/30 29pp Available at NRC \$4 50 15625 299 24X e 50-390, 82/09/30, 8210050405

urity, medical, emergency & fire protection plans

0225 Requests NRC perform preliminary review of util program for htower power black security concept Meetings suggested B21102-03 as part of review Agenda enc. St. M Tennessee Valley Authority 82/10/18 EISENHUT, D 9 sion of Licensing 2pp 15776 226 24X Fiche 50-390,82/10/18, 220225

)174 Forwards revised security plan.including updated table of ints & revised Page A-5 Revision withheld (ref R73 21)
3.L M Tennessee Valley Authority 82/10/20 ADENSAM.E sking Branch 4 1p 15797 048 24X Fiche 50~390, 82/10/20, 760174

PiB9 Confirms that evacuation time estimate study reviewed by local & TN state authorities Population density & flution info provided by TN Dept of Civil Defense based 180 census

LL M Tennessee Valley Authority 82/10/20 ADENSAM.E Q sing Branch 4 2pp 15799 030 24% Fiche 50-000, 82/10/20.

- O Advisory Committee on Reactor Safeguards reports & correspondence
- 8208290018 Summarizes 268th ACRS meeting on 820812-14 in Washington.DC re full power OLs for Grand Culf I & Watts Bar I & II, systematic evaluation & integrated reliability assessment of Olnna & tontrol room habitability
 SHEWMON.P ACRS Advisory Committee on Reactor Safeguards
 82/08/06 PALLADINO.N J Commissioners 3pp 15649 233 24X
 Fiche 50-000.82/08/26.8208270018
- Q Inspection reports, IE Bulletins & correspondence
- 8210080015 Addl response to FOIA request for 19 categories of info re nuclear reactor events & safety problems Forwards documents listed in App A Documents in App B completely withheld (ref FOIA Exemption 5)
 FELTON.J M Division of Rules and Records 82/07/12 UDELL.R A Critical Mass Energy Project 9pp 15665 027 24X
 Fiche 50-000.82/07/12.8210080015
- --82100B0167 Systematic assessment of licensee performance notes refacility evaluation for Aug 1979-Jul 1980
 + NRC No Detailed Affiliation Given 80/07/31 App 18648 101 24% Fiche 50-000, 82/07/12,82100B0015
- 8210010452 Forwards IE Insp Repts 50-390/82-31 & 50-391/82-28 on 820824-27 No noncompliance noted VERRELLI:D M Division of Project & Resident Programs 82/09/09 PARRISH W Tennessee Valley Authority 2pp 15572 305 24X Fiche 50-390.82/09/09.8210010452
- --8210010462 IE Insp Repts 50-390/82-31 & 50-391/82-28 on 820824-27
 No noncompliance noted Major areas inspected instrumentation, anstallation & nonconforming repts & conceptual design requirements
 MUNT-M D . CONLON-T E Division of Engineering & Technical Programs 82/09/07 4sp 15572 307 24X Fiche 50-390/82/09/08210010452
- 8210150304 Forwards IE Insp Repts 50-390/82-32 & 50-391/82-29 on 820824-27 No noncompliance noted VERRELLII D M Division of Project & Resident Programs 82/09/10 PARRIS. H & Tennessee Valley Authority 2pp 15707 295 24% Fiche 50-390, 82/09/10,8210150304
- --8210150315 IE Insp Repts 50-390/82-32 & 50-391/82-29 on 820824-27 noncompliance noted Major areas inspected engineering design work MCFARLAND, C.R. DEBBAGE, A.O., UPRIGHT, C.M. Division of Project Resident Programs 82/09/10 5pp 15707 297 24X Fichs 50-390.82/09/10,8210150304
- B210160323 Forwards 1E Insp Repts 50-390/82-30 & 50-391/82-27 on 620721-0820 No noncompliance noted VERRELLI, D M Division of Project & Resident Programs 62/09/16 PARRISH 0 Tennessee Valley Authority 2pp 15721 270 24X Fichs 50-390, 82/09/16, 8210150323
- --82j0150331 IE Insp Repts 50-390/82-30 & 50-391/82-27 on 820721-08E noncompliance noted Major areas inspected licensee action on previous insp findings & review of periodic & special repts HEATHERLY, T L , QUICK, D R Division of Project & Resident Programs 82/09/16 5pp 15721 272 24X Fichs 50-390,82/09/18210150323
- 82:00:0333 Ack receipt of 820826 itr informing NRC of steps taken to carrect violations noted in IE Insp Repts 50-390/81-03 t 50-391/81-03.

 VERRELLI.D M Division of Project & Resident Programs 82/09/17 PARRIS N 0 Tennessee Valley Authority 1p 15568 298 24X Fiche 50-390, 82/09/17.82:00:10333
- --8210010341 Supple response to NRC 820414 1tr re violations noted in IE Insp Repts 50-370/81-03 & 50-391/81-03 Corrective actions: leak integrity of body bonnet joint verified prior to startup & component tolerance will be confirmed HILLS, L. M. Tenneszee Valley Authority 82/08/26 O'REILLY, J. F. Region 2. Office of Director 3pp 15568-237 24X Fiche 50-370,82/09/17,8210010333
- 8210150026 Forwards Page 4 of IE Insp Repts 50-390/82-32 & 50-391/82 on 820824-27, omitted from 820910 submittal due to administrative oversight M/o and 10 out to administrative oversight M/o and VERRELLIO M. Division of Project & Resident Programs 82/09/28, PARIS, H O Tennessee Valley Authority 2pp 13696 337 24X Fiche, 50-390, 82/09/28, 8210150026
- 8210050344 Forwards response to Questions 0121 20 & 0121 22 per 920: request for info re preservice inep program MILLS.L.M Tennesses Valley Authority. 82/09/29. ADENBAN.E Lifensing Branch 4 4pp. 15610 121 24X Fiche 50-390,82/09/29. 8210050344.

- --8210220323 IE Insp Repts 50-390/82-34 & 50-391/82-3i on 820914-17 No noncompliance noted Major areas inspected instrumentation cable & termination observation of work, work activities, review of quality records & licensee identified items RUFF.A B , CONLON.T E Division of Engineering & Technical Programs 82/09/29 3pp 15776 040 24X Fichs 50-390.82/09/30,8210220315
- 8210150207 Ack receipt of 820825 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-390/82-18 & 50-391/82-15 Add info requested by 820923 telcon VERRELLI.D M Division of Project & Resident Programs 82/10/04 PARRIS.H Q Tennessee Valley Authority ip 19705 083 24X Fichs 50-390, 82/10/04, 8210150209.
- --82:0150230 Responds to NRC 820707 ltr re violations noted in IE Insp Repts 50-370/82-18 & 50-391/82-15 Corrective actions personnel instructed in application of EP 1 26 to limited OA 348 MILLS.L M Tennessee Valley Authority 82/09/24 O'REILLY.J P Region 2. Office of Director 4pp 15706 084 24X Fiche 50-390, 82/10/04,8210150209
- --B210150241 Responds to NRC B20702 itr re-violations noted in IE Insp Repts 50-370/8R-18 & 50-371/82-15 Corrective actions program to instruct all personnel in all procedures affecting design work implemented HILLS.L.M. Tennessee Valley Authority 82/08/25 O'REILLY.J.P. Region 2. Office of Director 3pp 15706-088 24X Fishs 50-370, 82/10/04,8210150209.
- --B21015025: Responds to NRC 820707 ltr re violations noted in TE Insp Repts 50-390/B2-18 & 50-391/B2-15 Corrective actions EP i 28. "Control of Documents Affecting Quality," will require independent verification of procurement apecs HILLB.L M Tennessee Valley Authority 82/08/20 (J'REILLY, J P Region 2. Office of Director 3pp 15706 091 24X Fiche 50-390.82/10/04.8210150209
- --8210150240 Discusses IE Insp Repts 50-390/82-18 & 50-391/82-15 on 820421-0520 & forwards corrected App A (notice of violation)

 LEMIS.R C Division of Project & Resident Programs 82/07/07 PARRIS.H Q Tennessee Valley Authority 2pp 15706 094 24X Fishe 50-390,82/10/04.8210150209
- --8210190268 Corrected notice of violation from insp on 820421-0520 Noncompliance noted nonconforming condition rept not initiated for recognized diesel generator tube oil deficiencies

 * Region 2, Office of Director. 82/07/07 2pg 15704 096 24x Fishe 50-390, 82/10/04, 8210150209
- --8210150278 Forwards IE Insp Repts 50-370/82-18 & 50-391/82-15 on 820421-0520 & notice of violation LEWIS:R C Division of Praject & Resident Programs 82/06/08 PARRIS:H O Tennesce Valley Authority 2pp 15706 098 24X Fiche 50-370,82/10/04,8210150207
- --8210150286 Notice of violation from insp on 820421-0520. * Region 2, Office of Director 82/06/08 2pp 15706 100 24 fiche 50-390.822/10/04.8210150209
- --8210150303 1E this Repts 50-390/82-18 & 50-391/82-15 on 820421-0520 Noncompliance noted failure to design for environ effects, follow corrective action procedures & conduct adequate audits
 MCDGMALD.J A , HEATHERLY, T L , GUICK, D R Division of Project & Resident Programs 92/06/08 6pp 15706 102 24X

70/82-32 & mittal ms 82/10/07 4 318 24X

50-391/82-29 .5704:320 24x

- 8208190238 IE Suiletin 82-03, "Stress Corrosion Cracking in Thick-Wall-Large-Diameter: Stainless Steel. Recirculation Sys Pring at BWR Plants" Syc ist encl DEYOUNG: R C Director's Office of Inspection and Enforcement 82/10/14 Consolidated Edison Co of New York 115pp [5810 125 24% Fitchs 50-000, 82/10/14-8208190228
- 8210220459 Ack receipt of 820915 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-390/81-26 & 50-391/81-24
 VERRELLI.D M Division of Project & Resident Programs 82/10/10 PARRIS.H 0 Tennessee Valley Authority in 15779 133 24X
 Fiche 50-390, 82/10/18, 8210220459
- --8210220466 Advises that corrective actions per violations noted in 12 Insp Repts 50-390/81-26 & 50-391/81-24 will be completed by 82103 HILLS.L M Tennessee Valley Authority 82/09/15 O'REILLY, JP Region 2. Office of Director ip 15779 134 24x Fiche 50-390.82/10/18.8210220459
- 8210220472 Act receipt of 820924 ltr informing NRC of steps taken to correct violations noted in 1E lnsp Repts 50-390/82-18 & SO-391/82-15 VERRELLI,D M Division of Project & Resident Programs 82/10/16 PARRISIN G Tennessee Valley Authority ip 15779 102 24X Fiche 50-390,8210/16.8210220472
- S Reportable occurrences, LERs & related correspondence
- 8210080168 Sixth interim deficiency tept re qualification of epoxy grout for safety-related applications Initially reported on 820827 Support mods or addisupports recommended Drawing revisions in progress Completion expected by mid-May 1983 MILLS.L H Tennessee Vailey Authority 08/07/23 0'REILLY, J P Region 2. Office of Director 3pp 15440 154 24x Fithe 50-370.82/07/23.8210080160
- 8210050316 First intersm deficiency rept to incorrect insulation weights used in piping analysis initially reported on 820825 OA document being prepared to substantiate insulation data Next rept will be submitted by 830423 HILLS.L M Tennessee Valley Authority 82/07/24 D'REILLY, J P Region 2. Office of Director 2pp 15610 201 24x Fiche 50-370,82/07/24,8210050316
- G2100B0247 Third & final deficiency repts re resolution of unanticipated vibratory loading concerns Initially reported on G1122B Frogram developed to insure piping sys operate within design paramoters Noit rept provided by 921217 HILLS: A Tennessee Valley Authority B2/07/24 O'REILLY, Jp Region 2, Office of Director Spp 1563B 104 24X Fiche 50-000; B2/07/24, G210000247
- 82100500A2 First interim deficiency rept re failure to consider seisajo & inertial loadings on ladders Initially reported on 820824 Ladder platform or walkway found deficient will be modified or stiffened Next rept expected by 830124 MILLS: L M Tennessee Valley Authority 82/09/27 0'RCILLY: J P Region 2. Office of Director 2pp 15603 236 24x Fiche 50-390:82/09/27:8210030062
- 8210030114 Addl info to final deficiency rept re seismic supports for auxiliary feedwater control valves initially reported on 800424 Corrective actions on Unit 1 completed 820831 Unit 2 valves will be installed during normal const achequie MILLS, L M Tennosses Valley Authority 82/09/27 0/REILLY, J P Region 2, Office of Director ip 13603 256 24x Fiche 50-390,82/09/27,8210050114
- 8210050293 First interim deficiency rept re six sheated motor pinion keys in Limitorque Model 80-0-25 motor operators Initially reported on 820830 Valves w/motor operators being tabulated Naxt rept will be submitted by 821122 MILLB:L M Tennessee Valley Authority 82/07/28 O'REILLY, J P Region 2. Office of Director 2pp 13609 070 24X Fithe 30-000, 82/09/28; 8210050293
- 8210090188 Second interim rept re undocumented minor mode to structural & miscellaneous stael Initially reported on 820510 Approx 95% of 250 features had preliminary inse/punchlist completed Next rept to be submitted by 830228 MILLB.L M Tennesses Vallay Authority. 82/09/29 G'REILLY.JP Region 2. Office of Director. 2pp 15605 154 24X Fichs 50-390.82/09/29.8210030158
- 8210060280 First interim deficiency rept re solid-state protection type test procedures Initially reported on 820831 Util reviewing Mestinghouse proposal for interim procedural change which would provide for failure detection Next rept by 821210 MFLLSH. M Tennessee Valley Authority 82/09/29 Q'REILLY, J P Region 2, Office of Director 2pp 15621 164 24X Fichet 50-370, 82/09/29, 8210060280

- 8210060205 Fourth interim deficiency rept re inadequate loading criteria for structural steel 5 supports Initially reported on 81117 General noise revised to clarify drawings Field mapping of platform steel continuing Next rept by 830310 MILLSIL M Tennessee Valley Authority 82/09/30 O'REILLY, J P Region 2. Dffice of Director 2pp 15614 041 24X Fiche 50 390.82/09/30,8210060205
- 8210060279 First interim deficiency rept re selection of undersized sway struts Initially reported on 820901 Selection methods & adequacy of Bergen-Paterson struts under evaluation Next rept expected by 830225 MILLS L M Tennessee Valley Authority 82/09/30 O'REILLY, J P Pegion 2. Office of Director 2pp 15621 166 24X Fiche 50 390.82/09/30,8210060279
- 0210080255 First interim deficiency rept re inadequate QA program for masonry block work initially reported on 820902 Const personnel investigating & replying to audit Noxt rept due on 821214
 MILLS.L M Tennessoe Valley Authority 82/10/01 D'REILLY, J P
 Region 2. Office of Director 2pp 15630 116 24x
 Fichs 50-390.82/10/01.8210080255
- 8210080280 First interim deficiency rapt re interpretation of radiograph test film on welded pipe by Swepco Tube Corp Initially reported on 820901 cyaluation continuing Next repf will be submitted on 830219 RfLS.L M Tennessos Valley Authority 82/10/01 O'REILLY, J. P. Pegion 2. Office of Directur 2pp 15638 201 24X Fiche 50-390.82/10/01,8210080280
- 6.10080291 First interim deficiency rept re failure to terminate cables iPSiII. IPSI[2. IPM1850. IPM1852, IPM1857, IPB182 & IPB183 initially reported on 820901 Cables terminated & personnel retrained Next rept will be submitted by 821123 MILGS.L M Tennessee Valley Authority 82/10/01 0'REILLY, J.P. Region 2 Office of Director 2pp 1563H 308 24% Fiche 50-390, 82/10/01, 8210080291
- 8210080160 First interim deficiency rept re corresion in high pressure tire protection sys Initially reported on 820903 Corresion analysis in progress to determine potential deficiencies in safety-related areas Next rept expected by 830531 MILLS-L M Tennessee Valley Authority 82/10/04 0'REILLY, J P Region 2. Office of Director 2pp 15640 142 24X Fiche 50-000, 82/10/04, 8210080160
- 8210080310 First interim deficiency rept re lack of piping sys analysis tracking Initially reported on 820902 Util investigating corrective actions to ensure engineering change notices are not closed out until work is completed MILLS-L M Tennessee Valley Authority 82/10/04 O'REILLY, J.P. Region 2. Office of Director 2pp 15638-042 24X Fiche 50 390.82/10/04.821080310
- 32:0130247 Sixth interim deficiency rept re differential settlement of rock supported structures Initially reported on 810707 individual safety-related components at interfaces of structures being evaluated Next tept by 823504 MILLS, L. M. Tennesses Valley Authority 82/10/05 O'REILLY, J.P. Region 2. Office of Director 1p 15676 009 24% Fische 50-390, 82/10/05, 8210130247
- 1210130560 Second interim deficiency rept re frequency criteria for piping supports Initially reported on 820713 Investigation continuing Next rept expected by 821220 HILLS, L.M. Tennessee Valley Authority 82/10/05 O'REILLY, J.P. Region 2, Office of Director ip 15683 299 24X Fiche 50-390, 82/10/05, 8210130360
- 210130379 Third interim deficiency rept re incorrect pipe support design by EDS Initially reported on Billip Util requested EDS to be more thorough in review of isometric models & analysis results Also reportable per Part 21 MILLS.L. M. Tennessee Valley Authority B2/10/06 O'REILLY, J.P. Region 2, Office of Director 2pp 15682:096 24X Fiche 50-390, 82/10/06, 8210130379
- 210220098 First interim deficiency rept re qualification of process piging w/instrument lines etterhed Initially reported on 820909 Affected piging being reamslyzed to account for sefect on instrument line piging Next rept by 830429 MILLS.L.M. Tennessee Valley Authority 62/10/08 O'REILLY, J.P. Region 2. Office of Director 2pp 15777, 362 24X Fiche 50-390, 82/10/08, 8210220098
- '10190307 Final deficiency rept re failure to meet pipe support lug criteria Initially reported on 820607 Lug perameter limit discrepancy corrected HILLB.L.M. Tennessee Valley Authority 82/10/12 0'REILLY, J.P. Region 2, Office of Director 2pp 15742 155 24X Fiche 50-390, 82/10/12, 8210190307

- 8210290328 Second interim deficiency rept re use of nonconservative calculational method to evaluate General Const Spec 0-32 spacing violetions initially reported on 820528 Next rept will be sent by 830528 MILLS.L M Tennessee Valley Authority 82/10/12 D'REILLY.J P Region 2. Office of Director 2pp 15853 064 24X Fiche 50-000.82/10/12.8210290328
- 8210270049 Supplemental final deficiency rept re defective 6 9 kV 0E circuit breaker Instally reported on 811218 Repaired breaker not reinstalled by 821001 due to revised delivery date Breaker to be in place by 821201 MILLS.L M Tennessee Valley Authority 82/10/14 0'REILLY.J P Region 2. Office of Director ip 15853 335 24X Fiche 50-391, 82/10/14, 8210270049
- 8210290236 Third interim deficiency rept re potentially overstressed embedded plates Initially reported on 820412 Investigation continuing & const activities deferred until sufficient info gathered to determine completion of project MILLS.L M Tennessee Valley Authority 82/10/14 Q'REJLLY, J P Region 2. Office of Director 2pp 15853 229 24X Fiche 50-000,82/10/14,8210270236
- 8210270052 Second interim deficiency rept re use of incorrect response spectra in 0/1bert/Commonwealth piping enalysis Initially reported on 820426 Reanalysis continuing Neit rept expected by 820422 Also reportable per Part 21 MILLGIL M Tennessee Valley Authority 82/01/15 0'REJLLY, J P Region 2: Office of Director ip 13853 334 24X Fiche 50-370, 82/10/15. 8210279052
- 8210270178 Sixth interim deficiency rept re revolting of high pressure fire protection piping Initially reported on 810130 Three areas may contain worst case condition No deficiencies identified in two areas Next rept provided by 821210 MILLS.L M Tennessee Valley Authority 82/10/15 0/REILLY.J P Region 2. Office of Director ip 15853 311 24X Fiche 50-390,82/10/15.8210270178
- 8210260320 First interim deficiency mept re addition of locking devices to handwheel operated valves Initially reported on 820916 Const activities deferred Analyses of locking devices continuing Next mept will be sent by 820310 MILLS.L.M. Tennessee Valley Authority 82/10/18 0'REILLY, J.P. Region 2. Office of Director 2pp 15802 339 24X Fiche 50-000, 82/10/18, 8210260320
- 8210260451 Fourth interim deficiency rept ro failure to include documented piping insulation insps in GC program Initially reported on 811009 Const Specs N30-881 & N3C-912 revised to provide scope of insp requirements Next rept by 830425 MILLS.L M Tennessee Valley Authority 82/10/18 D'REILLY, J P Region 2. Office of Director 2pp 15807 104 24X Fiche 50-390, 82/10/18 8210260451
- 8210260186 Second interim deficiency rept re underdesign of essential raw cooling water intake pumping station doors & hatches Initially reported on B20407 Flathead screws added to door frame for reinforcement Next rept expected by 830301 MILLS.L M Tennessee Valley Authority 82/10/19 O'REILLY, J P Region 2. Office of Director 2pp 13797 034 24X Fiche 50-390, 82/10/19, 8210260186
- 8210260390 Eighth interim deficiency rept re improper classification of essential raw cooling water sys piping & components initially reported on 810324 investigation ongoing Next rept will be submitted by 830427 MILLSLL M Tennessee Valley Authority 82/10/19 O'REILLY, J P Region 2, Office of Director ip 15803 104 24X Fiche 50-390, 82/10/19, 8210260390
- 82102&0100 Becond interim deficiency rept re lack of seismic analysis on auxiliary bidg platform initially reported on 82042&
 Documentation for all attachments to suspect platforms being investigated Next rept expected by 830217
 MILLS, L. M. Tennesses Valley Authority 82/10/20 O'REILLY, J. P. Region 2. Office of Director 2pp 15799, 122 24X
 Fiche 50-390, 82/10/20, 8210240100
- 82102&0408 Second interim deficiency rept re potentially deficient valve yoke holddown not Initially reported on 820601 Util awaiting Hextinghouse resolution for NSSS valves Also reportable per Part 21 MILLS, L M Tennessee Valley Authority 82/10/20 0'REILLY, J P Region 2. Office of Director 2pp 15803 109, 24% Fiche 50-370,82/10/20,8210260408
- 8210290266 Fourth interim deficiency rept re feilure of Limitorque motor operators during valve closure initially reported on 820126. Mestinghouse. Limitorque & util investigating problem Next rept expected on 830128 Part 21 considered applicable MILLG.L.M. Tennessee Valley Authority 82/10/21 O'REILLY, J.P. Region 2. Office of Director in 15854 046 24X Fiche 50-390.82/10/21,8210290266

- 8210290274 Final rept for Deficiencies B & E & seventh interim rept for Deficiencies A & D re control of procurement activities initially reported on 810316 Final corrective actions noted Next rept spected by 830428 MILLS.L M Tennessee Valley Authority 82/10/21 O'REILLY, J F Region 2. Office of Director 4pp 15853 (43 24X Fiche 50-000, 82/10/21, 8210290274
- DOCKET SO-395 VIROIL C SUMMER NUCLEAR STATION, UNIT 1

 A Application/construction stage documents & correspondence
- 8210010008 Responds to FOIA request for 19 categories of documents re nuclear reactor events 2 safety problems Forwards documents Listed to App A FELTON, J M Division of Rules and Records 82/06/28 UDELL, R A Critical Mass Energy Project 15pp 15727 005 24X Fichs 30-000.82/06/28,8210010008
- --800B050265 Discusses add1 required info to better define potential for gracking in reactor vessel noirles
 NDONAN,V S Assistant Director for Materials & Qualifications Engineering 80/05/05 TEDESCO,R L Assistant Director for Licensing 2pp 13727 176 24X Fichs 50-000.82/06/28,8210010008
- € NRC Safety Evaluation Report (SER), suppls & correspondence
- B210050175 Supple B20723 & 0024 ltrs re documentation to illustrate that pressurizer safety valve position indication sys is sessmically qualified, per SER. Suppl 4 Info completes responses needed to resolve Licensing Condition 8 & 23C DIXON.O H South Carolina Electric & Gas Go B2/09/29 DENTON.H f Office of Nuclear Reactor Regulation, Director 7pp 15404 117 24X Fiche 50-395,82/09/29,8210050175
- F Security, medical, emergency & fire protection plans
- 8210050324 Documents steps taken to fulfill commitments made in Section 8 I 2 of radiation emergency plan re emergency drills & ejercises Relief from requirement to hold another full-scale ejercise prior to full power operation requested DIYON.D W South Carolina Electric & Gas Co 82/09/23 DENTUN.H R Office of Nuclear Reactor Regulation. Director 6pp 15508 215 24X Fiche 50-395.82/09/23.8210050324
- 8210060242 Notifies that full scale emergency drill will not be conducted until Mar 1983 due to unavailability of FEMA personnel.per 820923 commitment DIYON.O W South Carolina Electric & Gas Co 82/09/29 DENTON.H F Office of Nuclear Reactor Regulation, Director 1p 19619 321 24X Fichs 50-495.82/09/29, 8210060242
- 9210060248 Ack receipt of 820927 ltr informing NRC of steps taken to correct violations noted in IE Safeguards Insp Rept 50-995/82-45

 LEWIS.R C Division of Project & Resident Programs 82/10/06
 DIXON, G W South Carolina Electric & Oas Co ip 15638 098 24X
 Fichs 30-395/82/10/06/8210080248
- --8210080250 Responds to NRC 820831 ltr re violations noted in IE Safeguards Insp Rept 50-395/82-45 Corrective actions withheld (raf 10CFR73 21) DIXON.O N South Carolina Electric & Qas Co 82/09/29 O'REILLY, JF Region 2. Office of Director 2pp 15638 099 24 Fiche 50-395,82/10/04.8210080248
- --8210080254 Forwards IE Safeguards Insp Rept 30-395/82-45 on 820806 & notice of violation Notice of violation withheld (ref 100FR73 21)

 LEMIS.R C Division of Project & Resident Programs 82/08/31 DIXON, OW South Carolina Electric & Gas Co 2pp 19638, 101 24% Fiche 50-395, 82/10/26, 8210080248

- 8210250312 Confirmatory action ltr re 821007 discussions at site concerning volumerability of security computer sys noted during 821004-08 insp Enc) withheld (ref 10CFR73 2) KEPPLER, J.G. Region 3. Office of Director 82/10/18 DDLAN, J.C. American Electric Power Service Corp. DDLAN, J.E. Indiana & Michigan Electric Co. 2pp. 15790 189 24x Fiche 50-395.82/10/18.8210250182
- B210260172 Provides current completion schedule for installation of fire barriers & detectors Fire barriers will be installed by B21115 & fire detectors by end of first quarter 1983 D1/QN.O W South Carolina Electric & Gas Co B2/10/21 BENION H & Office of Nuclear Reactor Regulation. Director 1p 15799 049 24X Fiche 50-395.82/10/21.8210260172
- 8210260157 Application to amend License NPF-12 in response to General Ltr 82-17, changing Tech Specs re emergency plan implementing procedures audits
 DIXDN.O W South Carolina Electric & Oas Co 82/10/22 DENIGN.H H
 Office of Nuclear Reactor Regulation Director 1p 15797 OOB 24/ Fiche 50-395-82/10/22.8210260159
- Q Adjudicatory correspondence
- 9210150458 Second suppl to motion to reopen record for reconsideration of motion for stay, allowed per ASLB 820924 memorandum % order Bids for stay met CM Anderson engineering rept recontainment cadwelds encl BURSEY, Buesey, B 82/10/07 Atomic Safety and Licensing Board Panel 23pp 15705 006 24% Fiche 50 375,82/10/07,8210150458
- 8210150217 Memorandum confirming ruling at B21008 telcon denying intervenar B21007 motion for recansideration of ASLB denial of motion to stay implementation of initial decision authorizing issuence of full-term CL GROSSHAN.H Atomic Safety and Licensing Board Panel 82/10/1. 3pp 15705 280 24X fishe 50-395.82/10/12.8210150217
- 8210250229 Memorandum & order denying B Dursey motion to reopen record on cadwelding Intervenor Pailed to sustain burden of demonstrating eristence of genuine issue of safety significance NRC investigation rept to be placed in LPDR GROSSHAN, H. Atomic Safety and Licensing Board Panel 82/10/22 BURSEY, B. Bursey, B. 5pp. 15789 331 24X Fiche 50-395,82/10/22,8210250229
- H General correspondence
- 8210210443 Expresses concern w/allegations of compromised const. QL stds for cadwelds & inadequacy of response to allegations Hearings should be reopened to examine & refute allegations before granting further facility licenses BASS. J. Affiliation Unknown 82/10/12 OROBBMAN. H. Atomic Safet and Licensing Board Panel 3pp 15763 073 24X Fiche 50-375. 82/10/12. 8210210443
- P Operating license stage documents & correspondence
- 8210080307 Summary of 820915 meeting w/util & Dames & Moore in Bethesda MD re confirmatory seismic analysis program Licensee must provide program & Schedule for resolving License Condition 25 & ACRB commitment KANE-W F Licensing Branch 1 82/09/24 Licensing Branch 1 6pp 13663 332 24X Fische 50-395,82/09/24,8210080307
- 82:0050210 Advises that Westinghouse performed stress evaluation of main reactor coolant loop apping withermal sleeves removed Noziles qualified to withstand all applicable design transients
 DIXON, 0 W South Caroline Electric & Pas Co 82/09/29 DENTON: R Office of Nuclear Reactor Regulation, Director 3pp 15611 260 24X Fiche 30-395,82/09/29,8210050210
- 8210080276 Requests resolution of provision to remove & reinstall USC SMA-I per 820924 ltr re confirmatory program for pad test CLARK, NE , WHORTON, R B South Carolina Electric & Gas Co 52/10/01 JACKBON, R NRC No Detailed Affiliation Olven 2pp 15638 300 24% Fiche 50-395,82/10/01,8210080276
- 8210120248 Forwards proprietary & honproprietary versions of "Interia Power Operation Evaluation Rept " Proprietary version withheld (ref 10CFR2 790) DIXON.O H Bouth Carolina Electric & Qas Co. 82/10/04 DENTON.H Office of Nuclear Reactor Regulation, Director 9pp 15656 055 24X Fiche. 50-395, 82/10/04 8210120248

- --8210120250 Nonproprietary version of "Interim Power Operation Fuel Labor Rent
 - Evaluation Rept # 4 Heatinghouse Electric Corp # 19709/30 15pp 15656 064 24X Ficks 50-395,82/10/04.8210120248
- 82(0)80156 Application to amend License NPF-12, changing Tech Specs to thermal design flow fire detection instruments &
 - thermal design flow.Fire detection instruments a overpressure protection sys
 DixQR,O W South Carolina Electric & Qas Co 82/10/08 DENTON.H R
 Office of Nuclear Reactor Regulation, Director 3pp 15719 170
 24% Fiche 50-395, 82/10/08, 02:0180156
- 8210180162 Proposed Toch Spec changes re thermal design flow, fire detection instruments? averpressure protection sys
 South Carolina Electric & Gas Co 82/10/08 54pp 15719 173 24x Fiche 50-395,82/10/08,8210180156
- t.'10190352 Forwards Technical Rept B2-1, "Seismic Activity Near VC Surmer Nuclear Station Jan-Mar 1982" & "Geological Studies in Area of Induced Seismicity at Monticello Reservoir, BC, " fourth technical rept
- DICON, O W South Carolina Electric & Gas Co 82/10/12 DENTUN, H R Office of Nuclear Reactor Regulation, Director ip 15735 009 24% Fiche 50-195 82/10/12,8910190352
- --8210190444 "Seismic Activity Near VC Summer Nuclear Station. Jan-Mar 1982: Technical Rept 82-1 TALWANI F South Carolina, Univ of 82-1 82/03/31 17pp 15735 030 24x Fiche 50-395.82/10/12,8210190352
 - 8210197457 "Geologic Studies in Area of Induced Seismicity at Monticella Resorvoir, SC." fourth technical rept Thirteen oversize figures enci Aperture cards are available in PDR SECOR D T. PITCHER, D M., PECK L S. South Carolina Electric & Gas Co. 82/06/40 153pp 15735-048 24X Fiche 50-395, 82/10/12, 82/10/0352
- 0210190505 Forwards cover iti inadvertently omitted from 021004 vubmittal of interim power operation evaluation rept plCON.O W. South Carolina Flectric & Gas Co. 02/10/12 DENTON.H N Office of Nuclear Realtor Regulation. Director ip 15735 310 24% Fische 50-195 02/10/12 02(0190505)
- -02-1017050B Forwards affidavit requesting interim power operation evaluation rept be withheld (ref 10CFR2 790) WIESEMANN,R A Westinghouse Clectric Corp 82/09/30 DENION.H R Office of Nuclear Reactor Regulation, Director 8pp 157.35 311 24x Fiche 50-395.82/10/12,0210190505
- 8210190553 Responds to Generic Ltr 82-16 re NUREQ-0737 Tech Specs All TMT items discussed in Encl 1 of generic Iti implemented DICOM, O W South Carolina Flectric D Gas Co 82/10/12 DENION, H R Orfice of Nuclear Resutor Regulation, Director 1p 15735 013 24x Fiche 50-395,82/10/12 8210190557
- 8210190492 Forwards "Independent Design Verification Turbine Driven Portion Emergency Feedwater Sys." final rept DUht DP.P. Stone & Webster Engineering Corp. 02/10/15 DENTON.H R Office of Nuclear Reactor Regulation. Director ip 16030-245 24X Fiche 90-399, 82/10/15,8210190492
- i3210190500 "Independent Seismic Design Verification Turbine Driven Portion Emergency Feedwater Sys." final rept One oversize drawing enci Aperture card is available in PDR # Stone & Webster Engineering Corp 82/10/15 105pp 16030 246 24X Fiche 50-395.82/10/15,8210190492
- 62[0]905[3 Forwards response to questions rp DG O'Brien, Inc Qualification Rept ER-307 for triaxial plugs for containment penetrations Cable failure not result of plug design or configuration since plug passed test when encl in conduit DI/QN/D W South Carolina Electric & Oas Co 82/10/15 DENTON, H R Office of Nuclear Reactor Regulation. Director 15pp 15737 224 24/ Fiche 50-395,82/10/15,8210190513
- 6210250330 Application for amend to License NPF-12, providing acceptable tolerances to be used in procurement of sample gases used for callet of associated instruments & permitting entry into Mode 2 on 821020

 DI (OH, D W South Carolina Electric & Gas Co 82/10/19 DENTON, H R Office of Nuclear Reactor Regulation, Director 1p (5790 004 24% Fiche 50-395,82/10/19 8210250330
- --8210250339 Proposed Tech Specs providing acceptable tolerances to be used in procurement of sample gases used for callbr of associated instruments & permitting entry into Mode 2 on 621020
 - # South Carolina Electric & Gas Co 82/10/19 4pp 15790 005 24X Fiche 50-395,82/10/19,8210250330

- B2(0260140 Request for temporary relief from Tech Spec requirements re containment hydrogen monitors in order to allow entry into Mode 2 under action statement for initial criticality Relief will prohibit delay of initial criticality DIXON.O W South Carolina Electric & Gas Co B2/10/20 DENTON.H R Office of Nuclear Reactor Regulation, Director ip £5797 091 24X Fiche 50-395.82/10/20.8210260140
- 8210260159 Application to amend License NPF-12 in response to Generic Ltr 82*17, changing Tech Specs re emergency plan implementing procedures audits DIXGN.O W South Carolina Electric & Qas Co 82/10/22 DENTON, H R Office of Nuclear Reactor Regulation, Director ip 15799 OOB 24% Fiche 50-395, 82/10/22, 8210260159
- --8210260166 Proposed Tech Spec changes re frequency of emergency plan

 * (mplementing procedures audits

 + South Carolina Etectric & Oas Co | 82/10/22 | 1p | 15799 009

 24X Fiche 50-395,82/10/22,8210260159
- Q Inspection reports, IE Bulletins & correspondence
- 8210010167 Revises 810707 % 1116 responses to IE Bulletin 81-02.
 "Failure of Oate Type Valves to Close Against Differential
 Pressure "Valve 81308 in Table I to 811116 ltm not modified
 since valve net functional requirements as configured
 DIXON.D W South Carolina Electric & Gas Co 82/09/08
 O'REILLY.J P. Region 2. Office of Director 2pp 15567 277 24X
 Fiche 50-395,82/09/08,8210010167
- B2(0010466 Forwards IE Insp Rept 50-395/82-41 on B20701-0B13 No nancompliance noted DANCE.H C Division of Project & Resident Programs 82/09/0B DI(ON,D W South Carolina Electric & Oas Co 2pp 15572 153 24x Fiche 50-395,82/09/08.8210010466
- --8210010469 IE Insp Rept 50-395/82-41 on 820701-0813 No noncompliance noted Major areas inspected plant tour, open item review.

 TMI action plan (tem review & surveillance test procedures performence SKOLDS.) L., BROWNLEE, V.L. Division of Project & Resident Programs 82/09/08 (1pp 15572 155 24X Fiche 50-395,82/09/08,8210010466
- 8210010467 Forwards IE Insp Rept 50-395/82-47 on 820806-07,12 & 13 No noncompliance noted DANCE,H C Division of Project & Resident Programs 82/09/09 BLKON,D W South Carolina Electric & Gas Co 2pp 15572,165 24X Fiche 50-395,82/09/09,8210010467
- --8210010472 IE Insp Rept 50-395/82-47 on B20806-07.12 & 13 No nancompliance noted Major areas (nspected initial fuel loading BURNETT, P T , JAPE, F Division of Engineering & Technical Programs 82/09/02 Gpp 15572 169 24X Fiche 50-395,82/09/09,9210010467
- 8208190233 IE Info Notice 80-35, Suppl 1, "Leaking & Dislodged I-125 Implant Beeds " Svc list encl COBB.L 1 Division of Fuel Facilities, Materials & Safeguards 82/10/06 Consolidated Edison Co of New York 66pp 15761 250 24/
- 8210080248 Ack receipt of B20929 itr informing NRC of steps taken to correct violations noted in IE Safeguards Insp Rept 50-395/82-45.

 LEHIS.R C Division of Project & Resident Programs 82/10/06 DIXON, O W Bouth Carolina Electric & Gas Co ip 15638 098 24X Fiche 50-395, 82/10/06.8210080248
- --8210080250 Responds to NRC 820831 ltr reviolations noted in IE Bareguards Insp. Rept 50-395/82-45 Corrective actions withheld (ref 100FR73 21)
 DIXON.O W South Carolina Electric & Gas Co 82/07/29
 O'REILLY, J. P. Rejon 2, Office of Director 2pp 15638 099 24X
 Fiche 50-395,82/10/06.8210080248
- --8210080254 Forwards IE Safeguards Insp Rept 50-395/82-45 on 820806 & notice of violatian Notice of violation withheld (ref 10CFR73 21)

 LEWIS.R C. Division of Project & Resident Programs 82/08/31

 DIXON.O W Bouth Carolina Electric & Gas Co 2pp 15638 101.

 24X Fichs 50-395.82/10/06.8210080248
- --8210080259 IE Safeguards Inap Rept 50-395/82-45 on 820806 Noncompliance noted failura to control designated vehicles Details withheld (ref 10CRF3 21) SKOLDS, J L., HCOUIRE, D R. Division of Engineering & Technical Programs. 82/08/26 ip 15638 IOS 24X Fiche 50-395,82/10/06,8210080248

p

- 8208190238 IE Bulletin 82-03, "Stress Corrosion Cracking in Thick-Wall, Large-Diameter, Stainless Steel, Recirculation Sys Piping at BWR Plants "Svc list encl DEYGUNG, R C Director's Office, Office of Inspection and Entorcement 82/10/14 Consolidated Edison Co of New York 115pp 15810 125 24X Fiche 50-000, 82/10/14,8208190238
- 9210250312 Confirmatory action ltr re 821007 discussions at site concerning vulnerability of security computer sys noted during 821004-09 insp Encl withheld (ref 10CFR73 21) KEPPLER, J G Region 3, Office of Director 82/10/18 DDLAN, J E American Electric Power Service Corp DOLAN, J E Indiana & Michigan Electric Co 2pp 15790 189 24% Fiche 50-395,82/10/18,8210250312
- S Reportable occurrences. LERs & related correspondence
- 9210010348 Final significant deficiency rept re-penetration gap requirements of safety-related piping sys Initially reported on 920726 Mods to piping penetrations for insulation &/or sealing handled through field change request program DIXON, O W South Carolina Electric & Gas Co 82/09/22 O'REILLY, J P. Region 2. Office of Director 2pp 15573 103 24% Fiche 50-395, 82/09/22 8210010348
- 8210220340 Forwards LER 82-005/03L-0 Detailed event analysis encl DIXON O W South Carolina Electric & Gas Co 82/10/15 O'REILLY, J P Region 2, Office of Director 3pp 15776 261 24X Fiche 50-375, 82/10/15, 8210220340
- --8210220346 LER 82-005/03L-0 on 820916, five whole detectors at 400-ft & 412-ft elevations of control bldg disabled, rendering preaction sprinkler sys automatic actuation capability inoperable Caused by need to perform welding in 400-ft area KOON. A R South Carolina Electric & Gas Co 82/10/15 Region 2, Office of Director 1p 15776 264 24X Fiche 50-395, 82/10/15, 82/10220340
- 8210220438 Forwards LER 82-004/03L-0 Detailed event analysis encl DIXON:0 W South Carolina Electric & Gas Co 82/10/15 O'REILLY, J P. Region 2. Office of Director 4pp 15778 258 24X Fiche 50-395, 82/10/15, 82/0220438
- --8210220443 LER 82-004/03L-0 on 820915, test signal generated causing B train RHR header isolation valve to shut & isolate suction Pump manually tripped Surveillance test procedure revised to line up alternate RHR train w/valve locked out FIELDS, C South Carolina Electric & Cas Co 82/10/15 Region 2, Office of Director 1p 15778 262 24X Fiche 50-395,82/10/15,821020438
- 8210270284 Forwards LER 82-006/03L-0 Detailed event analysis enci DIXON, D W South Carolina Electric & Gas Co 82/10/21 O'REILLY, J P. Region 2. Office of Director 3pp 15853 136 24X Fichs 50-395,82/10/21,8210290284
- --8210290286 LER 82-006/03L-0 on 820922, several high range monitors failed high Caused by moisture accumulation in detector preamp connections Plant completed initial fuel load but was not critical. Honitors replaced except RM-G198 FIELDS, C South Carolina Electric & Gas Co 82/10/21 Region 2. Dffice of Director ip 15853 139 24X Fiche 50-395.82/10/21, 8210290284
- 9210290335 Forwards LER 92-007/03L-0 Detailed event analysis enci DIXON:0 W South Carolina Electric & Cas Co 82/10/21 LY.J P. Region 2. Office of Director 4pp 15853 035 24X 50-395, 82/10/21, 8210290335

- DOCKET 50-397 WPPSS NUCLEAR PROJECT, UNIT 2
- A Application/construction stage documents & correspondence
- 8210070141 Forwards "WA Nuclear Project 2 Environ Equipment Qualification Rept for Safety-Related Equipment," Vols 1.2 & 3. in response to NRC 800221 ltr Rept will be incorporated into FSAR amond 80UCHEY, 6 D Washington Public Power Supply System 82/09/186HWENCER.A Licensing Branch 2 lp 15630 360 24% Fiche 50-397.82/09/15.8210070141
- --8210070144 "WA Nuclear Project 2 Environ Equipment Qualification Rept For Safety-Related Equipment." Vols 1,2 & 3 * Hashington Public Power Supply System 82/09/30 590pp 15532 019 24X Fiche 50-397. 82/09/15.8210070141
- 8210130188 Advises that manual block valve CAS-VX-82e will be utilized as containment isolation valve in lieu of relocating check valve on air line to inside containment Change will be incorporated in future FSAR amend 80UCHEY, 0 D Hashington Public Power Supply System 82/09/20 SCHMENCER, A Licensing Branch 2 3pp 15474 114 24X Fichs 50-397, 82/09/20, 8210130188
- B210060223 Forwards corrections & clarifications to Amend 23 to F5AR Section 8 3 re onsite power sys Next F8AR amend will be revised to include encl corrections BOUCHEY, G D Hashington Public Power Supply System 82/09/22 SCHHENCER, A Licensing Branch 2 68pp 15620 117 24X F(che 50-397.82/09/22,8210060223
- 8210080068 Forwards NRC position paper closing out Licensing Review Group [I channel box deflection issue SCHNENCER, A Licensing Branch 2 82/09/22 FERGUSON, R L Hashington Public Power Supply System Spp 15647 355 24X Fiche 50-297, 82/09/22, 8210080068
- 8210050348 Forwards final response to 820708 concerns re adequacy of design margins of Mark II containment sys Issues raised by QE do not represent significant safety concerns for facility
 80UCHEV.0 D Hashington Public Power Supply System 82/07/24
 BCHHENCER, A Licensing Branch 2 10pp 15610 104 24X
 Fiche 50-397.82/09/24.8210050348
- 8210270227 Notification of 821006 meeting w/util in Bethesda.MB to discuss cable segaration criteria concerns AULUCK.R Licensing Branch 2 82/09/27 BCHWENCER.A Licensing Branch 2 3pp 15876 326 24X Fiche 50-377.82/09/27,8210290227
- 8210040255 Forwards add1 info re organizational changes in preparation for ACRE 821004 meeting Formal revisions to FSAR & operational QA program description will be submitted upon completion
 BOUCHEV.O D Washington Public Power Supply System B2/09/28
 BCHWENCER.A Licensing Dranch 2 ip 15575 009 24X
 Fiche 50-397.82/09/28.8210040255
- 8210190764 Forwards update to pump & valve inservice test program plan, per util 820708 ltr M/21 oversize drawings Aperture cards are available in PDR BOUCHEV, 0 D Washington Public Power Bupply System 82/10/07 SCHWENCER, A Licensing Branch 2 lp 15799 161 24X Fiche 50-397, 82/10/07, 8210190764
- --8210260113 Revision | to "Pump & Valve Inservice Test Program Plan"
 HDYLE.T. RENBERGER.D., MARTIN.J. Washington Public Power Supply
 System 82/08/28 157pp 15779 162 24% Fiche 50-397.82/10/07.
- 8210290446 Staff requirements memo re 821007 affirmation/discussion & vote on extension of const completion dates for MPPSS, purging of classified mat! in ALAB-453 & emergency preparedness & risks associated w/fuel loading CHILK:8 J Office of the Secretary of the Commission 82/10/08 Office of the Secretary of the Commission 82/10/08 Fiche 50-000, 82/10/08, 8210270446
- B210210327 Confirms B21005 telcon re use of ABME Code Case N-310-1, "Certification of Bolting Matta Section III, Div 1, Class 1, 2, 3, MC & GS " Util will implement code case as agreed B0UCHEY, 0 D Washington Public Power Supply System B2/10/11 BCHMENGER, A. Licensing Branch 2 2pp 15764 216 24X Fiche 50-397, 82/10/11, 8210210327
- 8210270072 Notification of 821110 meeting w/util in Bethesda.ND to discuss adequacy of GA program in light of recent deficiencies disclosed at several plants AVLUGER Licensing Branch 2 82/10/19 SCHWENCER.A Licensing Branch 2 3pp 15836 293. 24X Fichs 50-397.82/10/19.8210270072

- G210260442 Requests representation at Mar 1983 environ site visit & at 830502 question & answer period LEWIS.M D Hashington. State of 82/10/20 WHEELER, L NRC No Detailed Affiliation Given 1p 15806 153 24X Fiche 50-397, 82/10/20, 8210260442
- E NRC Safety Evaluation Report (SER), supple % correspondence
- 6210060319 Commits to implementing mod of control logic on pressure interlocks of low pressure ECCS injection valves by fuel load Commitment dependent on timely equipment delivery Info closes SER Outstanding Issue 1 7(8)
 800CHEY, & D. Washington Public Power Supply System 82/09/28
 SCHWENCER, A. Licensing Branch 2 2pp 15619 013 24X
 Fiche 50-397, 82/09/28, 8210060319
- 6710050124 Requests revision to Suppl 2 of BER.NUREG-0892, Sections 4 2 3 2(7): 4 2 3 3(1) 6 4 2 3 3(3) to indicate resolution of cladding rupture concern & to reflect that PCT margin is not required BBUCHEY 6 D. Mashington Public Power Supply System 82/09/30 SCHMENCER.A. Licensing Branch 2 1p 15405 041 24X Fichs 50~397.82/09/30,8210050124
- 8210050156 Forwards marked-up correct Table 1 2 of SER (NUREO-0892) recomparison of facility principal design features to similar facilities.per ACRS Subcommittee on NNP-2 meeting BOUCHEY. O D Washington Public Power Supply System 82/07/30 SCHMENCER. A Licensing Branch 2 3pp 15605 156 24X Fiche 50-397. 82/09/30.8210050156
- 6.10190574 Forwards supplemental response to NUREG-0612, "Control of Heavy Loads." Revision 1 to close out SER Outstanding Issue 30 SOUCHEY, 6 D Washington Public Power Supply System 82/10/04 SCHUENGER, A Licensing Granch 2 22pp 15736 005 24X Fiche 50-397, 82/10/04,8210190576
 - 22[0]90582 "Reactor Vessel Head Removal & Replacement "

 * Washington Public Power Supply System 61/12/17 16pp
 15726-030 24% Fiche 50-397,82/10/04/8210190976
- UP10190586 "HPCS Pump Removal Overhaul & Reinstallation "

 Nashington Public Power Supply System 81/07/23 19pp
 15735 046 24% Fiche 50-397,82/10/04.8210190576
- EL10216049 Forwards recommondations on proposed plant operating procedure changes, equipment mods & discussion of design basis ashfall Advance warning alrangements in Section II A rolfill commitment per supplemental SER Section 2 5 1 3 1 BOUCHEY, O D Washington Public Power Supply System 82/10/04 SCHMENCER, A Licensing Branch 2 4pp 15765 345 24X Fiche 50-397. 82/10/04.8210210049
- 6210210148 Informs that hydrostatic test of diesel engine auxiliary piping to 125% of design pressure performed in response to supplemental SER Item 9 5 4 1,0pen Item 15 & FSAR Question 040 084 Exemption requested for intake 5 exhaust lines SUUCHEV. © D. Hashington Public Power Supply System 62/10/04 SCHMENCER, A. Licensing Branch 2 3pp 15766 087 24X fishe 50-397, 82/10/04,8210210148
- 8210210276 Advises that Section 14 2 14 3 17 will be amended to remove any lef to containment hot pipe penetration testing SER Outstanding Issue 21 (NUREG-0892) closed w/o need for acceptance criteria Diagrams re penetration assembly encl SDUCHEY. O D Washington Public Power Supply System 82/10/04 SCHNENCER. A Licensing Branch 2 6pp 15766 124 24X Fichs 30-397. 82/10/04.8210210276
- F Security, modical, emergency & fire protection plans
- 82:0060445 Forwards "One-Hour ASTM Ell9 Fira Simulation Facility Fire Tests Mater Hose Stream Impact Tests & Electrical Circuitry Continuity Tests on Nuclear Facility Class IE Cable Trays & Conduit Test "Rept withheld (ref 10CFR2 790) UDUCHEY. 0 Washington Public Power Supply System 82/09/20 SCHHENCER, A Licensing Branch 2 3pp 15615 001 24X Fiche 50-397, 82/09/20,8210060445
- 8210130194 Submits add1 info to suppliest rept date in util 820802 b 0920 ltrs to NRC re Thermo-Leg 330-1, subliming coating envelope sys (ITL Rept 82-5-359A) for fire protection of cable raceway sys discussed in App R BOUCHEY, O D Washington Public Power Supply System 82/10/04 SCHWENCER, A Licensing Branch 2 4pp 15674 I41 24X Fiche 50-397. 82/10/04.8210130194

- 8210210049 Forwards recommendations on proposed plant operating procedure changes, equipment mods & discussion of design basis ashfall Advance warning arrangements in Section 11 A rulfill commitment per supplemental SER Section 2 5 i 3 i 30UCHEV.0 D Washington Public Power Supply System 82/10/04 SCHWERGER.A Licensing Branch 2 App 15765 345 24X Fichs 50-397, 82/10/04,8210210049
- 8210190708 Forwards Test Rept 82-5-3558, "Three-Hour Fire Endurance Tests on Thermo-Lag 330-1 Subliming Coating Envelope Sys for WPPSS Nuclear Projects" (No encl BUUCHEY, 6 D Washington Public Power Supply System 62/10/05 SCHMENGER, A Licensing Branch 2 3pp 19736 151 24X Fiche 50-397, 82/10/05, 8210190708
- 8210130575 Notifies of meeting w/Yakima Indian Nation tentatively acheduled on 821022 to discuss emergency plan coordination. In response to NRC 820914 request BOUCHEY.0 D Hashington Public Power Supply System 62/10/06 SCHWENCER.A Licensing Dranch 2 ip 15679 108 24X Fiche 50-397, 82/10/06.0210130575
- G Adjudicatory correspondence
- 8210130336 Order CLI-82-27, referring Coalition for Safe Power petitions for hearing to ASLB ABLD chairman should appoint ASLB to determine whether 10CFR 714 requirements met & to conduct required hearing Wiseparate views of Commissioner 011insky CHILK, S.J. Office of the Secretary of the Commission 82/10/08 21pp 15681 350 24x Fiche 50-397, 82/10/08,8210130336
- 8210200056 Notice of ASLB constitution H Grossman, chairman & EE Hill & LW Little, members
 COTTER.B P Atomic Safety and Licensing Board Panel 82/10/14
 2pp 15755 027 24X Fiche 50~397, 82/10/14,8210200056
- 0210180147 Lists changes to be made in Commission 821008 Order. CLI-82-29 STUCKY.S W Docketing & Services Branch 82/10/15 Office of the Executive Legal Director Ip 15719 266 24X Fiche 50-397, 82/10/15.8210180147
- 8210290315 Notice of ASLB reconstitution H Grossman, chairman & OD Bright & J Harbour, members LAZO,R M Atomic Safety and Licensing Board Panel 82/10/25 2pp 15853 078 24X Fiche 50-397, 82/10/25, 8210290315
- K Utility Final Safety Analysis Report (FBAR) & amends
- 8210080075 Forwards Amend 26 to FBAR BDUCHEY.0 D Washington Public Power Supply System 82/09/28 SCHWENCER.A Licensing Branch 2 2pp 13640 338 24x Fiche 30-377.82/09/28.8210080095
- --8210080100 Amend 25 to FSAR

 + Washington Public Power Supply System 82/07/31, 757pp
 15640 339 24X Fiche 50-397, 82/09/28, 8210080095
- 8210210045 Forwards transmittal 1tr % Certificate of 8vc for Amend 26 to FBAR 4/0 transmittal 1tr 8DUCKEY, 0 D Washington Public Power Supply System 82/10/05 8CHWENCER, A Licensing Branch 2 2pp 15765 352 24X Fiche 50-397, 82/10/05, 8210210045
- Q Inspection reports: IE Bulletins & correspondence
- 8210080195 Forwards revised corrective actions to NRC notice of violations 79-10/01.79-10/03.80-09/07 & 80-08/22 noted in IE Insp Rept 50-0397/81-22 All future liquid penetrant exams will be performed by Bechtel approved subcontractor MATLOCK.R O Washington Public Power Supply System 82/04/16 ENGELKEN.R H Region 5, Office of Director 3pp 15640 190 24X Fichs.50-397,82/04/16.8210080195.
- B210190646 Provides additinfo re preservice insperogram plan for scram discharge sys per B20812 telcon Boundary diagram for control rod drive sys enci BOUCHEY, O D Washington Public Power Supply System B2/09/22 SCHWENCER, A Licensing Branch 2 3pp 19739 101 24x Fiche 50-397.82/09/22:8210190646
- 8210190364 Forwards IE Insp Rept 50-397/82-18 on 820816-31 No noncompliance noted STERNGERO,D M Division of Resident, Reactor Project & Engineering Programs 82/09/28 MATLOCK,R Q Washington Public Power Supply System 2pp 15741.166 24X Fiche 50-397.82/09/28,8210190366

- --8210190368 IE Insa Rept 50-397/82-18 on 820816-31 No noncompliance noted Major areas inspected reactor pressure vessel hydrotest-mechanical contractor records review program & corrective activities & work reverification program TOTH.A D. DDDDS, R T. Division of Resident. Reactor Project & Engineering Programs 82/09/27 14pp 15741 168 24x Fiche 50-397,82/09/28,8210190366
- 8210190562 Forwards IE Insp Rept 50-397/82-22 on 820830-0903 No noncompliance noted STERNBERG.D M Division of Resident, Reactor Project & Engineering Programs 82/09/28 MATLOCK.R G Washington Public Power Supply System 2pp 15736 126 24% Fiche 50-397.82/09/28.8210190562
- --8210190569 IE Insp Rept 50-397/82-22 on 820830-0903 No noncompliance noted Major areas inspected facility organization, preoperational testing operational GA program & independent insp WILLETT, D J. DDDDS. R Division of Resident, Reactor Project & Engineering Programs 82/09/27 Spp 15736 130 24% Fichs 50-397,82/09/28,8210190562
- 82i0190665 Forwards IE Insp Rept 50-397/82-17 on 820726-30,0809-13 & 0830-0903 Mo noncompliance noted STERNBERG, D M Division of Resident, Reactor Project & Engineering Programs 82/10/01 MATLOCK, R G Hashington Public Power Supply System 2pp 19737 256 24X Fiche 50-397.82/10/01.8210190665
- --8210190678 IE insp Rept 50-397/82-17 on 820726-30.0809-13 & 0830-0903 No noncompliance noted Major areas inspected electrical installation, safety-related plying & employee concerns ELIN, J O , D'ANGELO, A J , DODDS, R T Division of Resident, Reartor Project & Engineering Programs 82/09/30 9pp 15737 258 24% Fiche 50-397, 82/10/01, 8210190645
- 8210070297 Ack receipt of 820831 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-397/82-14
 STERNBERG, D M Division of Resident, Reactor Project & Engineering Programs 82/10/04 MAZUR, D W Washington Public Power Supply System 1p 15634 236 24x Fiche 50-397. 82/10/04.8210070299
- --8210070302 Responds to NRC 820802 ltr re violations noted in It Insp Rept 50-397/82-14 Corrective actions Dechtel procedures reviewed to ensure that AE approvals obtained & GC Admanistrative Instruction 15 issued MATLOCK, R O Washington Public Power Supply System 82/08/31 STERNBERO, D M Division of Resident, Reactor Project & Engineering Programs 6pp 15634 239 24X Fiche 50-397,82/10/04,8210070299
- 8208190233 iE Info Notice 80-35. Suppl i, "Leaking & Dislodged 1-125 Implant Seeds " Syc list encl COBB.L I Division of Fuel Facilities, Materials & Safeguards 82/10/06 Consolidated Edison Co of New York 6App 15761 250 24% Fiche 50-000,82/10/06.8208190233
- 8210280241 Forwards IE Insp Repts 50-377/82-20 & 30-13720/82-01 on 820831-0903 & notice of violation 800K.H E Division of Radiological Safety & Safeguards Program 82/10/12 MATLOCK.R O Mashington Public Power Supply System 2pp 15837 325 24X Fiche 50-397,82/10/12,8210280241
- --B210280244 Notice of violation from insp on B20831-0903 WENSLAWSKI, F.A. Division of Radiological Bafety & Safeguards Frogram B2/10/12 1p 15837 327 24X Fiche: 50~397, B2/10/12, 8210280241
- --8210280248 IE insp Repts 50-397/82-20 & 30-13720/82-01 on 820831~0903 Noncompliance noted receipt of radioactive matl not authorized by License 46-17948-01 YUHAB: 0 P , WENSLAMSKI.F A , BOOK.H E Division of Radiological Safety & Safeguerds Program 82/10/08 IIpp (5837-328 24X Fichs 50-397,82/10/12-8210280241

- 8210080304 Interim deficiency rept re improper installation of concrete expansion anchors to unacceptable concrete to grout work.

 Initially reported on 820403 Corrective actions continuing.

 Next rept will be submitted on 821218.

 MATLOCK.R G. Washington Public Power Supply System. 82/09/28.

 ENGELKEM.R H. Region 5. Office of Director. Opp. 15638-325-241.

 Fische 50-397,82/09/28,8210080304
- 82(0130217 Final deficiency rept re high resistance cable grounding of 4 16 kV diesel generators Initially reported on 820506 Manufacturers advised that equipment can operate for indefinite period w/line-to-ground fault w/o damage MATLOCK R 0 Washington Public Power Supply System 82/09/20 ENGELMEN, R H Region 5, Office of Director 3pp 15675 240 21% Fiche 50-397, 82/09/28, 8210130217
- 8210080275 Final deficiency rept re 4 16 kV broakers DG 1-7 % DG 2 6 k interim deficiency rept re emergency diesel generators DG-1 & DG-2 airstart circuits Initially reported on 820070 % 0709; respectively Nazt rept will be submitted by 821220 MATLOCK.R G Washington Public Power Supply System 82/09/30 ENCELKBUR H Region 5. Office of Director 3pp 15638-302 2K Fiche 50-397,82/09/30,8210080275
- DOCKET 50-400 SHEARON HARRIS NUCLEAR POWER PLANT, UNIT I
- A Application/construction stage documents & currespondence
- B210130053 Summary of 820816-19 meeting w/utiliEbasco & Westinghouse re design review of instrumentation & control sus for racilities Followup meeting scheduled for 820914-16 in New York City.NY LICITRALE A Licensing Branch 3 82/09/08 Licensing Branch 7 Spp 15696 272 24% Fiche 50-400.82/09/08.8210130053
- 8210010051 Ack receipt of 820823 itr requesting temporary relief from commitments re-training of shift technical advisors Program approved & request forwarded to NRR for evaluation O'RRILLY. J P Region 2, Office of Director 82/09/20 JONES, J A Carolina Power & Light to 1p 15565 322 24X
 Fiche 50-000:82/09/20.8210010051
- 8210270324 Requests add1 info re instrumentation & control sys Info should be in form of response to IE Bulletin 79-21 re level measurement errors due to environ temp effects on level instrument ref legs Requests submittal date within 2 w/s KERRIOAN J D Licensing Branch 3 82/09/23 JONES, J A Carolina Power & Light Co 2pp 15836 357 24% Fiche 50-400.82/09/23, 8210270324
- 8210210035 Forwards request for add1 info on FSAR Section 440-0.
 "Reactor Sqs "
 KERRIOAN.J Licensing Branch 3 82/09/29 JONES, J A Carolina
 Power & Light Co 9pp 15773 262 24X Fiche 50-400.82/09/29.
 8210210035
- 8210210258 Notification of 821012 meeting w/util & Ebasco in Bethrsda. MB to discuss review of RCPB matls
 KADAMBIN P Licensing franch 3 82/09/29 KERRIGAN J Licensing a
 Branch 3 3pp 15774 324 24% Fiche 50-400.82/09/29.8210210258
- 8210210320 Summary of 820914-16 meetings w/util.Westinghouse & Ebasco at Ebasco of the design review of instrumentation & control sys Attendance list encl. LICITRA.E A Licensing Branch 3 82/09/29 Licensing Branch 3 4pp 15782 087 24% Fiche 50-400.82/09/29, 8210210320
- 8210050106 Forwards 21 responses to Reactor Bys Dranch (440 Series) questions discussed at Reactor Bys Dranch safety review meeting held on 820921 Remaining 17 Items will be addressed in near future MCDUFFIE, M A Carolina Power & Light Co 82/09/30 DENTON, H R Office of Nuclear Reactor Regulation, Director 27pp 15603 261 24X Fiche 30~400,82/09/30,8210050106
- 8210050125 Forwards responses to Instrumentation & Control Bys Brench 820730 questions re FSAR, confirming info discussed during 820816-19 & 0914-16 meetings MCDUFFIE.M A Carolina Power & Light Co 82/09/30 DENTIN, H.R. Office of Nuclear Reactor Regulation, Director 95pp 19604 282 24X Fiche 50-400, 62/09/30, 82(0950125
- 8210210312 Summary of 820921 meeting w/applicant,Westinghouse,Ebasco t EGMO at site re Reactor Sys Branch 820424 questions concerning FBAR Attendance list encl KADAMBINP Licensing Branch 3 82/10/01 Licensing Branch 3 4pp 19782 078 24X Fiche 50~400,82/10/01,8210210312

- 8210150305 Advises that commercial operation date for Unit 1 changed from Fall 1985 to Spring 1986 No funds to be allocated in 1983 for const work on Unit 2 Most of requested rate hike disallowed W/Certificate of Svc Related correspondence FLYNN, 8 F Carolina Power & Light Co 82/10/06 KELLEY, J L. URIGHT. 0., CARPENTER, J H. Atomic Safesty and Licensing Board Panel 4pp 15701 336 24X Fiche 50-400, 82/10/06, 8210150305
- 8210150647 Notification of canceled 821012 meeting w/util & Ebasco in Bethesda.MD to perform review of RCPB matl KADAHBI,N P Licensing Branch 3 82/10/08 KERRIGAN,J Licensing Branch 3 3pp 15715 305 24X Fiche 50-400,82/10/08.8210150647
- 8210190512 Submits const completion achedule. Unit 1 scheduled for operation in Spring 1936, resulting in 6-month delay in fuel load Schedule for Unit 2 completion due Dec 1982 Present licensing review schedule should be maintained MCDUFFIE.M A Carolina Power & Light Co 82/10/14 DENTON, H R Office of Nuclear Reactor Regulation, Director ip 15735, 309 24X Fiche: 50-400, 82/10/14, 8210190512
- B210260462 Bubmits formal clarification of responses to safety review questions from Containment Bys Branch (480 Beries)
 MCDUFFIE,M A Carolina Power & Light Co B2/10/20 DENTON,H R
 Diffice of Nuclear Reactor Regulation, Director 7pp 15806 052
 24X Fiche 50-400,82/10/20,8210260462
- --8210260481 Informs that Topical Rept AAF-TR-7101, "Design t Testing of Fan Cooler-Filter Bys for Nuclear Applications," acceptable Partial "Equipment Gualification Data Packages" encl TEDEGO.R L. Atonic Energy Commission, Deputy Director for Yechnical Review (Pre-1975) 72/11/10 FIBH.J F American Air Filter Co. 54pp 15806-061 24X Fiche 50-400.82/10/20, 82/10/20462

Utility Environmental Report (ER), amende & correspondence

- 210200032 Forwards responses to environ rept review Questions 240 3.
 291, 13 & 291 i5.comparing environ impact on Buckhorn Creek
 of operation of one unit w/o Cape Fear River Makeup Bys
 MCDUFFIE:M A Caroline Power & Light Co 82/10/15 DENTON:H R
 Office of Nuclear Reactor Regulation. Director 21pp 15797 308
 24X Fichs 50-400:82/10/15:82:0200032
- 210200084 Forwards Amend 4 to environ rept.8ummary of changes encl MCBMFFIE.H A Carolina Power & Light Co 82/10/15 DENTON.H R Office of Nuclear Reactor Regulation. Director 2pp 15783 212 24X Fiche 50-400,62/10/15.8210200084
- -8210200086 Amend 4 to environ rept. Aperture cards available in PDR w Caroline Power & Light Co. 82/10/15 277pp 15783 214 24) Fiche 30-400,82/10/15,821020084.
- 210280054 Forwards affidavit re distribution of Amend 4 to environ rept.

 ZIMMERHAN, 8 R Carolina Power & Light Co. 82/10/25 RISENHUT, D. Q Division of Licensing. 5pp 15837, 256 24X Fiche: 50-400, 82/10/25, 8210280054.
- NRC Draft/Final Environmental Statements, suppls & correspondence
- 10210212 Notifies of schedule change for DEB Reservoir reanalysis has lead to delay in receipt of hydrological info. Statement will be issued by 821217.

 NOVAK, T. M. Assistant Director for Licensing 82/10/12 UTLEY, E Caroline Power & Light Co 2pp 15774'336 24X
 Fiche 50-400, 82/10/12, 8210210212

Security, medical, emergency & fire protection plans

- 10010037 Forwards request for addi info.based on review of 820826 industrial security plans safeguards contingency plan & security personnal training & qualification plan Encluithheld (ref 100FR2 790)

 KERRIGAN, J. D. Licensing Branch 3 82/09/20 JONES, J. A. Carolina Power & Light Co. 2pp 15585 315 24X Fiche, 50-400, 82/09/20, 3210010037.
- 10010349 Ack receipt of 820902 ltr informing NRC of steps taken to orrect violation noted in IE Insp Repts 50-400/82-24 & ...
 30-401/82-24 Response insufficient to determine if orrective action adequate
 EMIB:R G. Division of Project & Resident Programs 82/09/22
 (NRES.J.A. Carolina Power & Light Co 2pp 15569 213 24X iche-50-400,82/09/22.8210010349

- --8210010397 IE Insp Repts 50-400/82-24 & 50-401/82-24 on 820620-0720 Noncompliance noted failure to identify & correct nanconforming conditions on two field welds on Class IE electrical cable tray supports MACHELL, O F , BURGER, C W Division of Project & Resident Programs 82/08/03 9pp 15569 220 24X Fiche 50-400,82/09/22,8210010349
- G. Adjudicatory correspondence
- B210120103 Add1 response to FDIA request for nine categories of records generated by present NRC Commissioners, primarily Chairman Palladino & Commissioner Roberts & White House Forwards App B documents
 FELTON, J. M. Division of Rules and Records B2/07/12 UDELL, R. A. Critical Mass Energy Project 3pp 15670 117 24X
 Fiche 50-000, 82/07/12, 8210120103
- --B210120123 Forwards memorandum & order re Council of NC objection to util request for exemption to perform certain site preparation work Memorandum addresses exemption question & sets out history of Commission regulation. Bectlon 50 12 ROBERTS. T M Commissioners 81/12/09 PALLADINO, N . OILINSKY, V , BRADFORD, J Commissioners ip 15570 124 24X Fiche 50-000,82/07/12,8210120103
- --8210120132 Memorandum & order re Council of NC objection to util request for exemption per revised NEPA regulation to perform certain site preparation work NEPA does not bar preliminary work 8ite preparation work properly authorized BENDER, P. C. Atomic Energy Commission, 74/06/11 Atomic Energy Commission, 74/06/12 Atomic Energy Revision Bpp. 15690 125 24X Fiche 50-000,82/07/12,
- 82:00:0328 Supplemental statement re validity of psychological stress contentions Late filing criteria not applicable If contentions not admitted, encl arguments should be considered amends to original contentions READ, D.F. Chapel Hill Anti-Nuclear Group Effort 82/09/17 Atomic Safety and Licensing Board Panel 14pp 15569 174 24X Fiche.50-400, 82/09/17, 8210010328
- 8210010337 Suppl to Chapel Hill Anti-Nuclear Group Effort/Environ Law Project 820713 renewed & reformed motion to postpone proceedings originally submitted on 820316 Suppl based on new info Certificate of Svc encl.
 READ, D.F. Chapel Hill Anti-Nuclear Group Effort 82/09/24 Atomic Safety and Licensing Board Panel 7pp 15569 166 24X Fiche 50-400, 82/09/24,8210010337
- B210130192 Requests clarification of docket numbers for Harris & Perry plants Hixup may be causing prejudice to intervenors since documents go to incorrect LPDR HIATT.B.L. Ohio Citizens for Responsible Energy 82/10/04 Docketing & Bervices Branch. 1p 15707.260. 24X Fiche 50-000.82/10/04.8210150192
- 8210150305 Advises that commercial operation date for Unit 1 charged from Fall 1985 to Spring 1986. No funds to be allocated in 1983 for comet work on Unit 2 Most of requested rate hike disellowed H/Certificate of Syc Related correspondence FLYNN, S F Carolina Power & Light Co. 82/10/06 KELLEY, J. L., BRIGHT, O D. CARPENTER, J. H. Atomic Safety and Licensing Board Panel 4pp. 15701.336. 24X Fiche 50-400.82/10/06.8210150305
- 8210150340 Objections to ASLS 820922 prehearing conference memorandum & order Certificate of Svc encl.
 READ, D F Chapel Hill Anti-Nuclear Group Effort 82/10/08
 Atomic Safety and Licensing Spard Panel 7pp 15705-357 24X
 Fiche, 50-400, 82/10/08, 8210150340
- 8210200053 Responds to ASLB BR0922 order ruling on contention & svc of documents, Ruling an Contention IVc & an mation re svc of documents should be reconsidered Arrangements for svc unacceptable since parties unrelated, W/Certificate of Bvc. WILSONR D. Wilson R. 82/10/14. 5pp. 15753.088 24X Fiche 50-400.82/10/14.8210200053
- 8210210348 Response to ABLE 820922 memorandum & order Objects to portion of order dealing w/svc of documents & comments on security plan & structure of discovery process Notice of appearance & Certificate of 8vc encl RUNKLE, J D Conservation Council of North Carolina RUNKLE, J, D Affiliation Unknown. 82/10/14 App. 15744 204 24X Fiche 50-400, 82/10/14, 8210210348
- 8210200009 Forwards objections to & requests for clarification of ASLB 820722 memorandum & order & response to Chapel Hill Anti-Nuclear Group Effort supplemental statement repsychological stress contentions Certificate of 8vc encl BAXTER, T A Shaw, Pittman, Potts & Trowbridge. BAXTER, T A Carolina Power & Light Co. 82/10/15 KELLEY, J L, BRIGHT, O D. CARPENTER, J A. Atomic Safety and Cicensing Soard Panel, App 15755:001 24X Fiche: 50-400, 82/10/15, 8210200009

DOCKETED ITEMS

- --8210200013 Response opposing Chapel Hill Anti-Nuclear Group Effort 820927 supplemental statement re psychological stress contentions ASLB obligated to follow Commission policy statement on psychological stress issues BAYER, TA Carolina Power 2 Light Co BAXIER, TA Shaw, Pittnan, Potts & Troubridge 82/10/15 Atomic Safety and Licensing Board Panel 5pp 15755 005 24% Fiche 50-400, 82/10/15,8210200009
- --B210200021 Gb jections to & requests for clarification of ASLB 820922 memorandum & order Addl info re util plans on proposed Cape Fear River intake facility provided Ruling on & Eddleman Contention 132 should be clarified to specify bases O'NEILL.J H Carolina Power & Light Co O'NEILL.J H Shaw, Pitchan, Potts & Troubridge 82/10/15 Atomic Safety and Licensing Board Panel 17pp 15755 010 24x Fiche 50-400,82/10/15.8210200009
- B210210308 Notice of appearance in proceeding Certificate of Svc entl CREENBLATT.D Eddleman N GREENBLATT.D Greenblatt. D 82/10/15 Atomic Safety and Licensing Board Panel 3pp 15764 241 24X Fiche 30-400.82/10/15,8210210308
- 8210210376 Objections to ASLB 820922 memorandum & order reflecting decisions made at prehearing conference Objects to rulings on eve of util documents contentions & cancelation of Unit 2 Certificate of Svc encl EDDLEMAN, N Eddleman, N 82/10/15 14pp 15763 150 24X Fiche 50~400,82/10/15,8210210376
- 8210210419 Response to ASLB 820922 memorandum & order re use of security plan experts as witnesses CREENBLATT. D Eddleman, W PAYNE, M T Kudzu Alliance RUNKLE, J Chapel Hill Anti-Nuclear Group Effort 82/10/15 App 15763 076 24X Fiche 50-400,82/10/15,8210210419
- 8210200062 Forwards consolidated list of admitted & deferred contentions per ASLB 820722 order Agreement should be reached on wording b numeration to facilitate hearings & avoid misunderstandings W/o enc!

 BARTH.C A Hearing Branch 1 82/10/18 RUNKLE.J Conservation Council of North Caroline EDDLEMAN.W Eddleman. W READ.D F Chapel Hill Anti-Nuclear Group Effort 1p 18756 (52 24X Fiche 50-400.82/10/18.8210200062
- 82/0250068 Complains about svc of documents & LPDR copy machine EDDLEMAN, W EddJeman, W 82/J0/19 KELLEY, J L , CARPENTER, J H , BRIGHT, O O Atomic Safety and Licensing Board Fanel 2pp 15787-045 24X Fichs 50-400.82/10/19.8210250068
- H General correspondence
- 82[0010028 Requests NRC direct all official correspondence to EE Utley.
 util vice-president, due to 820930 retirement of JA Jone
 JONES, J A Carolina Power & Light Co 82/09/27 DENTON, H R
 Office of Nuclear Reactor Regulation, Director 1p 15565 314 24X
 Fiche 50-000, 82/09/27, 82[0010028
- 8210130323 Requests changes to distribution list for NUREC-0020, "Licensed Operating Reactors - Status Summary Rept" ZIMMERMAN, 8 R Carolina Power & Light Co 82/10/11 BEGBE, M R ADP Systems Development Branch 2pp 15683 361 24X Fiche 50-000, 82/10/11, 8210130323
- Q Inspection reports. IE Bulletins & correspondence
- 8210010086 Forwards IE Insp Repts 50-400/82-29 & 50-401/82-29 on 820830-0902 No noncompliance noted VERRELLI, D M Division of Project & Resident Programs 82/09/13 JONES, J A Carolina Power & Light Co 2pp 15565 260 24x Fichs 50-400,82/09/13,8210010086

- 8210010349 Ack receipt of 820902 ltr informing NRC of steps taken to correct violation noted in IE Insp Repto 50 400/82-24 ½ 50-401/82-24 Response insufficient to determine if corrective action adequate LEWIS.R C Division of Project & Resident Programs 82/09/22 JUNES.J A Carolina Power & Light Co 2pp 15569 213 24X Fiche 50-400.82/09/22.8210010349
- -8210010360 Responds to NRC 820804 ltr re violation noted in IE ling Repts 50-400/82-24 & 50-401/82-24 Corrective actions Hanger ED 2622 & Item 1426-10 reinspected & repaired New inspector under training in 60 welding required to pass written inspector PARSONS.R M Carolina Power & Light Co 82/09/02 Q'REILLY. J PRegion 2. Office of Director 2pp 15569 215 24X Fiche 50-404,82/09/22. 8210010349
- --8210010368 Forwards IE Insp Repts 50-400/82-24 % 50-401/82-24 un 820620-0720 % notice of violation LEMIS.R C Division of Project & Resident Programs 82/08/04 JONES. J A Carolina Power & Light Co 2pp 15569 217 24X Fiche 50-400, 82/09/22, 8210010349
- -82100103/3 Notice of violation from insp on B20620-0720
 * Division of Project & Resident Programs 82/08/04 ip
 15569 219 24% Fiche 50-400, 82/09/22, 8210010349
- --8210010397 IE Insp Repts 50-400/82-24 & 50-401/82-24 on 820620-0720 Nancompliance noted failure to identify & correct ponconforming conditions on two field welds on Class IE electrical cable tray supports

 MACWELL, 0 F , BURGER, C M Division of Project & Resident Programs 82/08/03 9pp 19569 220 24X Fiche 50-400. 62/07/22.821001037
- B210220160 Forwards IE Insp Repts 50-400/82-30 \$ 50-401/82-30 on 820820-0910 No noncompliance noted VERRELLI,D K Division of Project \$ Resident Programs 62/10/04 JONES, J A Carplina Power & Light Co 2pp 15778 072 24x Fiche 50-400,82/10/04,8210220160
- --8210220163 IE Imap Repts 50-400/82-30 & 50-401/82-30 on 820820-0910 in noncompliance noted Major areas inspected followup on previously (dentified items, concrete, piping & personnel training MAXWELL, 0 F , BURGER, C W Division of Project & Resident Progress 82/09/30 6pp 157/0 074 24X Fiche 50-400.82/10/04.8210220160
- 8208140233 IE Info Notice 80-35, Suppl !, "Leaking & Dislodged [-12th implant Seeds " Svc list enc! CDB.L ! Division of Fuel Facilities, Materials & Bafeguards 82/10/06 Consolidated Edison Co of New York 46pp 15761 2th0 24X Fiche 50-000.82/10/06.8208190233
- 8210220127 Ack receipt of 820923 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50~400/82-26 & 50-401/82-26 LEHIS.R C Division of Project & Resident Programs 82/10/12 UTLEY.E E Carolina Power & Light Co ip 15778 122 24X Fiche 50-400, 82/10/12, 8210220127
- --8210220132 Responds to NRC 820830 ltr re violations noted in () Insy Rept 50-400/82-26 Corrective actions refresher training course conducted for rebar inspectors PARSONS,R H Carolina Power & Light Co 82/09/23 d'REILLY, J P Region 2, Office of Director 2pp 15778 123 24X Fiche 50-400, 62/10/12, 8210220127
- --8210220137 Forwards IE Insp Repts 50-400/82-26 & 50-401/82-26 on 820802-06 & notice of violation LEWIS.R C Division of Project & Resident Programs 82/08/30 JONES.J A Garolina Power & Light Co 2pp 15778 125 24% Fiche 50-400,82/10/12,8210220127
- ~~8210220141 Notice of violation from insp on 620802-04 * Division of Project & Resident Programs 82/08/30 ip 15778 127 24X Fiche 50-400, 82/10/12,8210220127
- --B210220145 IE Insp Repts 50-400/82-26 & 50-401/82-26 on 820802-06 Noncompliance noted failure to analyze cut rebars for acceptability MRIGHT.R W . DEBBAGE.A G . UPRIGHT.C M Division of Engineering & Technical Programs 82/08/25 13pp 15778 128 24X Fiche 50-400,82/30/12,8210220127
- 8208190238 IE Bulletin 82-03, "Stress Corrosion Cracking in Thick-Wall.Large-Diameter, Stainless Eteel, Recirculation Sys Piping at BMR Plants " Svc list encl DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/10/14 Consolidated Edison Co of New York 115pp 15910 125, 24% Fiche 50-000,82/10/14.8208170238

- S Reportable occurrences (ERs & related correspondence
- #210180141 Part 21 rept re seismic pipe hangers previously accepted by GC weld inspector Iritially reported on 820913 Mangers will be reinspected reworked. Correctly documented Final rept expected by 830701 CHIANGI,N J. Carolina Power & Light Co. 82/09/13. 0'REILLY,J' Region 2. Office of Director. 4pp. 19719-226. 24% Fiche 50-400. 82/09/13.8210180141
- 6210]60193 Part 21 rept re faulty pipe support shop welds Initially resorted on 620613 Insp critoria being reviewed Deficient supports refurned to Bergen-Paterson for insp Next rept will be completed by 830701 CHIANGI,N J. Carolina Power & Light Co. 62/09/13 O'REILLY,J P. Region 2, Office of Director 4pp 15719 1t4 24X Fiche 50-400,82/09/13,8210180193
- E210080180 Deficiency reptite use of ASTM-A307 nuts & bolts for bolted connection in lieu of required ASTM-A325 nuts & bolts Initially reported on 820903 Ebasco Sycs currently evaluating problem All bolts replaced/leinspected PARSONS.R M Carolina Power * Light Co 82/09/30 O'REILLY.J P Region 2, Office of Director ip 15640 169 24X Fiche 50-400.82/09/30 8210080180
- 6210080283 Interim deficiency tept re sheared pinion keys on Limitarque valve motor operators Initially reported on 820903
 Restinghouse discussing problem w/Limitorque Final rept will be submitted by 830401 Also reported per Part 21
 PARSONS.R M Carolina Power / Light Cu 82/10/01 0/REILLY.J P
 Region 2, Office of Director 3pp 15630 320 24x
 Fiche 50-400.82/10/01.8216080283
- F210130557 Addendum 2 to B20319 deficiency rept re inadequately welded atude on embedded strip plates Addendum provides info re shipment of embeds (fupe [] strip plates & crane rail plates) & any associated problems PARSON.R M Carolina Power & Light Co 82/10/05 D'RFILLY, J P Region 2, Office of Director Spp 15893 113 24; Fiche 50-400, 82/10/05, 8210130567
- b210220484 Interim deficiency iept re defective governor drive coupling in emergency diesel engine-generator sets from Iransamerica Detaval Instrally reported on 820909 (oupling will be replaced Also reportable per Part 21 PARSINS.R M Carolina Power / Light Co B2/10/07 D'REILLY.J P Region 2. Office of Director App 15779 079 24X Fiche 50-400.82/10/07.6210270484
- 8210220075 Interim deficiency rept ie dosign error in solid state protection sys Initially reported on 820909 Mestinghouse centinuing to review design & has revised tost procedures to verify contact classifications reported per Part 21 PARSONS.R M. Caralina Power / Light Co. 82/10/08 G'REILLY, J.P. Regian 2. Office of Director. App. 15778 185 24X Fiche 50-400. 82/10/08 621-82/0075
- 8210220412 Final deficiency rept re grout concrete interface failure on equipment pad trame initially reported on 820909 Embed frame renoved Concrete cuib chipped completely but & curb ... rame replaced PARSONS.R M Carolina Power & Light Co 82/10/08 O'REJULY, J P Region 2. Ofrice of Director 4pp 15778 358 244 Fiche 50-400.82/10/08.8210220412
- GE10270260 Interim deficiency rept re gaps botween mating surfacus of connections between structural steel members which also had A490 bolts w/A325 nuts Initially reported on 820618 Ebasco Svcs. Inc evaluating problem PARBONS.R M Carolina Power & Light Co 82/10/13 O'REILLY, J PRegion 2, Office of Director 1p 15893 196 24X Fiche 50-400.82/10/13.8210270260
- 9210290258 Interim deficiency rept re grease between mating surfaces of structural connection designed as friction connection Initially reported on 820915 Ebasco Svcs. Inc currently evaluating problem Results expected by 830415 PARSONS:R M Carolina Power & Light Co 82/10/14 O'REILLY, J P Region 2. Office of Director 1p 15853 197 24X Fiche 50-400, 82/10/14, 8210290258
- 8210260398 Final deficiency rept re use of ASTM A307 bolts in lieu of A325 bolts specified in containment recirculating summ i cover structural steel initially reported on 820903 Yield stress would not be exceeded Matter not reportable PARBONSIR M Carolina Power & Light Co 82/10/15 D'REILLY, J P Region 2, Office of Director ip 15806 135 24X Fiche 50-400,82/10/15,8210260378

- DOCKET 50-401 BHEARON HARRIS NUCLEAR POWER PLANT, UNIT 2

 A Application/construction stage documents & correspondence
- 8210130053 Summary of 820916-19 meeting w/util/Ebasco & Westinghouse re design review of instrumentation & control sys for facilities Followup meeting scheduled for 820914-16 in New York City, NY LICITRALE A Licensing Branch 3 82/09/08 Licensing Branch 3 5pp 15696 272 24K Fishe 50-400, 82/09/08, 8210130053
- 8210010051 Ack receipt of 820823 itr requesting temporary relief from commitments re training of shift tochnical advisors Program approved & request forwarded to NRR for evaluation D'REILLY, J. P. Region 2, Office of Director 82/09/20 JONES, J. A. Carolina Power & Light Co. ip. 15565-322 24X Fiche 50-000, 82/09/20, 8210010051
- 8210270324 Requests add1 info re instrumentation & control sys Info should be in form of response to IE Bulletin 79-21 re level measurement errors due to environ temp effects on level instrument ref legs Requests submittel date within 2 wis KERRIGAN-J D Licensing Branch 3 82/09/23 JONES.J A Carolina Power & Light Co. 2pp 15836-357 24x Fiche 50-400.82/09/23, 8210270324
- 8210210035 Forwards request for add1 info on FSAR Section 440-0, "Reactor Bys "

 KERRIGAN, J Licensing Branch 3 82/09/29 JONES, J A Carolina Power & Light Co 9pp 15773 262 24K Fiche 50-400,82/09/29, 8210210035
- 8210210258 Notification of 921012 meeting w/util & Ebasco in Bethesda. MD to discuss review of RCPB makis KADAMBI,N P Licensing Branch 3 92/09/29 KERRIGAN,J Licensing Branch 3 3pp 15774 324 24% Fiche 50-400,82/09/29.8210210258
- B210210320 Summary of 820914-16 meetings w/util.Westinghouse & Ebasco at Ebasco ofc re design review of instrumentation & control sys Attendance list encl
 LICITRALE A Licensing Branch 3 82/07/27 Licensing Branch & 4pp 15782 087 24X Fiche 50-400.B2/07/29.8210210320
- 8210050106 Forwards 21 responses to Reactor Sys Branch (440 Series) questions discussed at Reactor Sys Branch safety review meeting held on 820921 Remaining 17 items will be addressed in near future MCDUFFIE,M A Carolina Power & Light Co 82/09/30 DENTON,H R Office of Nuclear Reactor Regulation. Director 27pp 15403 261 24% Fiche 50-400,82/09/30.8210050106
- 6210050125 Forwards responses to Instrumentation & Control Sys Branch 820730 questions re FBAR.confirming info discussed during 820916-19 & 0914-16 meetings MCDUFFIE.M A Carolina Power & Light Co 82/09/30 DENYON, H R Office of Nuclear Reactor Regulation. Director 56pp 15604 282 24% Fiche 50-400,82/09/30,8210050125
- 6210210312 Summary of 820921 meeting b/applicant, Westinghou E020 at site re Reactor Sys Branch 620426 questions concerning FBAR Attendance list encl
 KADAMBIN P Licensing Branch 3 B2/10/01
 App 15782 078 244 Fish 50-404 27444

- --B2102604B1 Informs that Topical Rept AAF-TR-7101. "Design & Testing of Fan Cooler-Filter Sys for Nuclear Applications." acceptable Partial "Equipment Qualification Data Packages" encl TEDESCO.R. Atomic Energy Commission. Deputy Director for Technical Review (Fre-1975) 72/11/10 FISH.J.F. American All Filter Co. 54pp 15806-061 24% Fiche 50-400.82/10/20. 82/10/20462
- C Utility Environmental Report (ER), amends & correspondence
- 8210200032 Forwards responses to environ rept review Questions 240 3, 291 13 5 291 15, comparing environ impact on Buckhorn Creek of operation of one unit u/o Cape Fear River Makeup Sys MCDUFFIE, M A Carolina Power & Light Co 62/10/15 DENTON, H R Diffice of Muclear Reactor Regulation, Director 21pp 15757 308 24X Fiche 50~400, 82/10/15.8210200032
- 5210200084 Forwards Amend 4 to environ rept Summary of changes encl MCDUFFLE, M.A. Carolina Power & Light Co. 62/10/15 DENTON, H.R. Office of Nuclear Reactor Regulation. Director 2pp. 15753 212 24X Fiche 50-400, 82/10/15
- --8210200086 Amend 4 to environ rept Aperture cards available in PDR * Carolina Power % Light Co 82/10/15 279pp 15753 214 24X Fiche 50-400,82/10/15,8210200084
- 8210280054 Forwards affidavit re distribution of Amend 4 to environ rept ZIMMERHAN, S.R. Carolina Power & Light Co. 82/10/25 EISENHUT, D.G. Division of Licensing 5pp 15837 256 24X Fiche 50-400, 82/10/25, 8210280054
- D NRC Draft/Final Environmental Statements, supply & correspondence
- 8210210212 Notifies of schedule change for DES Reservoir reanalysis has lead to delay in receipt of hydrological info Statement will be issued by 821217
 NOVAK.T M Assistant Director for Licensing 82/10/12 UTLEY.E E Carolina Power & Light Co 2pp (5774 336 24X Fiche 50~400.82/10/12.82/0210212
- F Security, medical, emergency & fire protection plans
- 8210010037 Forwards request for addl info.based on review of 820626 industrial security plantsafeguards contingency plant & security personnel training & qualification plan Encl withheld (ref 10CFR2 790) KERR[OAH, J D Licensing Branch 3 82/09/20 JONES, J A Carolina Power & Light Co 2pp 15565 315 24X Fiche 50~400,82/09/20,8210010937
- 8210010349 Ack receipt of 820902 ltr informing NRC of steps taken to correct violation noted in IE Insp Repts 50-400/82-24 & 50-401/82-24 Response insufficient to determine if corrective action adequate LEMIS.R C Division of Project & Resident Programs 82/09/22 JONES.J A Carolina Power & Leght Ca 2pp 15569 213 24X Fiche 50-400.82/09/22.8210010349
- --8210010397 IE Insp Repts 50-400/82-24 & 50-401/82-24 on 820620-0720 Noncompliance noted failure to identify & correct nonconforming conditions on two field welds on Class IE electrical cable tray supports MACHELL. G F Division of Project & Resident Programs 82/08/03 9pp 15569 220 24% Fiche 50-400.82/09/22,8210010349
- G Adjudicatory correspondence
- 8210120103 Add1 response to FOIA request for nine categories of records gamerated by present NRC Commissioners, primarily Chairman Palladino & Commissioner Roberts & White House Forwards App B documents FELTON.J M Division of Rules and Records 82/07/12 UDELL.R A Critical Mass Energy Project 3pp 15690 117 24X Fiche 50-000.82/07/12.8210120103
- --8210120123 Forwards memorandum & order re Council of NC objection to util request for exemption to perform certain site preparation work Memorandum addresses exemption question & sets out history of Commission regulation. Section 50 12 ROBERTS-T M Commissioners 81/12/07 PALLADINO, N Commissioners 1p 15490 124 24X Fiche 50-000.82/07/12, 8210120103
- --B2(0120132 Memorandum & order re Council of NC objection to util request for exemption per revised NEPA regulation to perform certain site preparation work NEPA does not bar preliminary work Site preparation work property authorized BENDER.P C Atomic Energy Commission 74/06/11 Atomic Energy Commission 9pp. 15670 125 24X Fiche, 50-000, B2/07/12, 82/0120103

- 8210010328 Supplemental statement re validity of psychological stress contentions. Late filing criteria not applicable if contentions not admitted, encl arguments should be considered amends to original contentions.

 READ, D F Chapel Hill Anti-Nuclear Group Effort 82/09/17

 Atomic Safety and Licensing Board Panel 14pp 15569 174 24X

 Fiche 50-400, 82/09/17, 9210010328
- 6210010337 Suppl to Chapel Hill Anti-Nuclear Group Effort/Environ law Project 620713 renewed & reformed motion to postpone proceedings, originally submitted on 820316 Suppl based on new info Certificate of Svc enci READ, D.F. Chapel Hill Anti-Nuclear Group Effort 82/09/24 Atomic Safety and Licensing Board Panel 7pp 15569 166 24x Fiche 50-400, 82/09/24, 8210010337
- 8210150192 Requests clarification of docket numbers for Harris & Peirq plants Mixup may be causing prejudice to intervenors since documents go to incorrect LPDR HIATT, 8 L Ohio Citizens for Responsible Energy 82/10/04 Docketing & Services Branch 1p 15707 260 24X Fiche 50-000,82/10/04,8210150192
- 8210150305 Advises that commercial operation date for Unit 1 changed from Fall 1985 to Spring 1986 No funds to be allocated in 1983 for const work on Unit 2 Most of requested rate hike disallowed W/Certificate of Svc Related correspondence FLYNN.5 F Carolina Power / Light Co 82/10/06 KELLEY.J L, BRIGHT, O 0, CARPENTER,J H Atomic Safety and Licensing Board Parel App 15701 336 24X Fiche 50-400.82/10/06.8210150305
- 8210150340 Objections to ASLB 820922 prehearing conference memorandum 3 order Certificate of Svc enci READ, D.F. Chapel Hill Anti-Nuclear Oroup Effort 82/10/08 Atomic Safety and Licensing Board Panel 7pp 15705-357 24y Fiche 50-400, 82/10/08, 8210150340
- B210200033 Responds to ASLB 820922 older ruling on contention & five of documents Ruling on Contention IVC % on motion re-sec of documents should be reconsidered Arrangements for sec unacceptable since parties unrelated W/Certificate of Sec WILSON, R.D. Wilson, R. 82/10/14 5pp. 19753 088 24% Fiche 50-400, 82/10/14,8210200053
- 82102(0348 Response to ASLB 820922 memorandum & order Objects to portion of order dealing w/svc of documents & comments on security plan & structure of discovery process Notice of appearance & Certificate of Svc and RUNKLE, J D Conservation Council of Noith Carolina RUNKLE, J D Arfilsation Unknown 82/10/14 6pp 15764 204 24X Fiche 50-400,82/10/14,8210210348
- 8210200007 Forwards objections to & requests for clarification of ASLB 820922 memorandum & order & response to Chapol Hill Anti-Nuclear Oroup Effort supplemental statement repsychological stress contentions Certificate of Svc encl BAXTER.T A Shaw, Pittman, Patts & Troubridge BAXTER.T A Carolina Power & Light Co 82/10/15 KELLEY.J L, BRIGHT, O CAMPENTER.J H Atomic Safety and Licensing Board Panel 4pp 15755 001 24X Fighe 50-400,82/10/15.8210200009
- --8210200013 Response opposing Chapel Hill Anti-Nuclear Group Effort B20927 supplemental statement re psychological stress contentions ASLD obligated to follow Commission policy statement on psychological stress issues BAXTER.T A Carolina Power & Light Co BAXTER.T A Shaw. Pittman. Potts & Troubridge B2/10/15 Atomic Safety and Licensing Board Panet Spp 15755 005 24X Fiche 50-400. B2/10/15.8210200009
- --8210200021 Objections to \$ requests for clarification of ASLB 820922 memorandum \$ order Addl info re util plans on proposed Cape Fear River intake facility provided Ruling on H Eddleman Contention 192 should be clarified to specify bases O'NEILL, J H Carolina Power & Light Co O'NEILL, J H Shaw. Pittman, Potts & Trowbridge 82/10/15 Atomic Safety and Licensing Board Panel 17pp 15755 010 24X Fiche 50-400,82/10/15,8210200009
- 82102103000 Notice of appearance in proceeding Certificate of Svc entl OREENDLATT.D Eddiemen W OREENBLATT,D Greenblatt, D 82/10/15 Atomic Safety and Licensing Board Panel 3pp 15764 241 24X Fiche 30-400. 82/10/13.8210210308
- 9210210376 Objections to ASLB 920922 memorandum & order reflecting decisions made at prehearing conference Objects to rulings on svc of util documents; contentions & cancelation of Unit 2 Certificate of Svc encl EDDLEMAN, M. Eddlemen, M. B2/10/15 14pp 15763 ISO 24X Fiche 50-400, 92/10/15, 8210210376

- 62:0210419 Response to ASLB 820922 memorandum % order re use of security plan experts as withesses GREENBLATT D Eddleman W PAYNE, M T Kudzu Alliance RUNKLE, J Chapel Hill Anti-Morlear Group Effort 82/10/15 4pp 15763 076 24% Fiche 50-400.82/10/15.8210210419
- 6210700062 Forwards consolidated list or admitted & deferred contentions per ASLB 820922 order Agreement should be reached on wording 5 numeration to facilitate heatings & avoid misunderstandings N/o encl SARTH, C A Heating Branch 1 82/10/18 RUNKLE, J Conservation Council or North Carulina EDDLEMAN, W Eddleman, W READ, D F Chapel Hill Anti-Nuclear Group Effort ip 15756 152 24X Fiche 50-400, 82/10/18, 8210200062
- 6210250048 Complains about sic of documents & LPDR copy machine EDDLEMAN.N Eddleman, V 82/10/19 KELLEY.J L CARPENTER, J H , BRIGHT, C U Abomic Safety and Licensing Board Panel 2pp 15787 045 24x Fishe 50-400,82/10/19.8210250048

H General correspondence

- 6210010028 Requests NRC direct all official correspondence to EE Utley, util vice-president, due to 820930 retirement of JA Jone JCFE, J A Carolina Power & Light Co 82709/27 DENTON, H R Office of Nuclear Reactor Regulation Director (p. 15565-314 24X Fiche 50-000, 82709/27, 6210010028
- 5210130323 Requests changes to distribution list for NUREG-0020. Licensed Operating Reactors Status Summary Rept "ZIMERMAN.5 R Caralina Power Light Co 82/10/11 BEEBE, M R APP Systems Development Branch 2pp 15683 341 24X Fiche 50-000, 82/10/11, 8210130323
- q Inspection reports, IE Dulletins & correspondence
- 5210010086 Forwards IE Insp Repts 50-400/82-27 % 50-401/82-29 on 620830-0702 No noncompliance noted VERRELLI.D M Division of Project & Resident Programs 82/09/13 JDF-25.J A Carolina Power & Light Co 2pp 15565 260 24X Fiche 50-400.82/09/13.8210010086
- -8210010071 IE Insp Repts 50-400/82-27 b 50-401/82-27 on B20830-0702 Nu noncompliance noted Major areas inspected const progress, safety-related piping. RCPB piping steel structures & reactor vessel internals KLEINSDROEL N P. BLAYE J. J. Fivision of Engineering & Technical Programs 82/07/10 10pp 15565-262 24X Fiche 50-400.82/07/13, 6210010086
- F210010102 Forwards IE Investigation Repts 50~400/82-23 & 50~401/82 23 on 820604-23 No noncompliance noted CREILLY, JP Region 2. Orice of Director 82/09/13 JONES, J A Carolina Power & Light Co. 2pp 15566-041 24X Fiche 50~400, 82/09/13, 8210010102
- --3210010111 IE Investigation Repts 50-400/82-23 & 50-401/82-23 on G20606-23 No noncompliance noted Major areas investigated allegations re forging of GC inspector initials on weld data rept VGRSE, J Y , URYC.B , ALDERSON, C E Region 2, Office of Director 82/09/09 3pp 15566-043 24x Fiche 50-400,82/09/13,8210010102
- E210010349 Ack receipt of 820902 ltr informing NRC of steps taken to currect violation noted in IE this Repts 50-400/82-24 & 50-401/82-24 Response insufficient to determine if corrective action adequate
 LEMIS.R C Division of Project & Resident Programs 82/09/22
 JONES.J A Carolina Power & Light (a 2pp 15569 213 24X Fiche 50-400, 82/09/22, 8210010349
- -8210010360 Responds to IRC 820804 ltr re violation noted in IE Innp Repts 50-400/82-24 & 50-401/82-24 Corrective actions Hanger ED 2622 & Item 1436-10 reinspected & repaired New inspector under training in GC welding required to pass written insp PARSONS,R M Carolina Power & Light Co 82/09/02 D'REILLY, J P Region 2, Office of Director 2pp 15569 215 24X Fiche 50-400,82/09/22,8210010349
- --8210010368 Forwards IE Insp Repts 50-400/82-24 & 50-401/82-24 on 820620-0720 & notice of violation LEWIB.R C Division of Project & Resident Programs 82/08/04 JONES, J A Carolina Power & Light Co 2pp 15569 217 24X Fiche 50-400,82/09/22,8210010349
- --8210010397 IE Insp Repts 50-400/82-24 & 50-401/82-24 on 820620-0720 Noncompilance noted failure to identify & correct nonconforming conditions on two field welds on Class IE electrical cable tray supports MACNELL, 0 F , BURGER.C W Division of Project & Resident Programs 82/08/03 7pp 15569 220 24% Fiche 50-400,82/09/22.8210010349

- 8210220160 Forwards IE Insp Repte 50-400/82-30 & 50-401/82-30 on 820820-0910 No noncompliance noted VERRELLI, D M Division of Project & Resident Programs 82/10/04 JONES, J A Carolina Power & Light Co 2pp 15778 072 24X Fiche 50-400, 82/10/04.8210220160
- --8210220163 IE Insp Repts 50-400/82-30 & 50-401/82-30 on 820820-0710 No noncompliance noted Major areas inspected followup on previously identified litems, concrete, piping & personnel training MAXHELL, OF, BURGER, C. W. Division of Project & Resident Programs 82/07/30 6pp 15778 074 24X Fiche 50-400.82/10/04,8210220160
- 820B190233 IE Info Notice 80-35, Suppl 1, "Leaking & Dislodged [-125 Implant Seeds " Svc list encl COBB.L I Division of Fuel Facilities, Materials & Safeguards 82/10/06 Consolidated Edison Co of New York 66pp 15761 250 24< Fichs 50-000-82/10/06-8208190233
- 8210220127 Ack receipt of 820923 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-400/82-24 & 50-401/82-26 LEMIS.R C Division of Project & Resident Programs 82/10/12 UTLEY.E E Carolina Power & Light Co Ip 15778 122 24X Fiche 50-400. B2/10/12,82/10220127
- ~~8210220137 Forwards IE Insp Repts 50-400/82-26 & 50-401/82-26 on 820802-06 & notice of violation LEMIS.R C Division of Project & Resident Programs 82/08/30 JONES, J A Carolina Power & Light Co 2pp 15778 125 24X Fichs 50-400,82/10/12,8210220127
- --B210220145 IE Insp Repts 50~400/B2-26 & 30~401/B2-26 on 820802-06 Noncompliance noted farlure to analyze cut rebars for acceptability WRIOHT.R W , pEBBAGE, A Q , UPRIGHT.C M Division of Engineering & Technical Programs 82/08/25 13pp 15778 128 24X Fiche 50-400,82/10/12.8210220127
- G20819D238 IE Builetin 82-03. "Stress Corrosion Cracking in Thick-Wall-Large-Diameter: Stainless Steel, Recirculation Sys Piping at DUR Plants "Svc list encl DEYGUNO; R C Director's Diffice. Office of Inspection and Enforcement 82/10/14 Consolidated Edison Co of New York 115pp 15810 125 24X Fiche 50-000.82/10/14.8208190238
- S Reportable occurrences. LERs & related correspondence
- B210180193 Part 21 rept re faulty pipe support shop welds Initially reported on 820813 Insp criteria being reviewed Deficient supports returned to Bergen-Paterson for insp Next rept will be completed by 830701 CHIANOI,N J Carolina Power & Light Co 82/09/13 O'REILLY,J P Region 2. Office of Director 4pp 15719 [14 24X Fichs 50-400, 82/09/13, 8210180193
- 8210080180 Deficiency rept re use of ASTM-A307 huts & bolts for bolted connection in lieu of required ASTM-A325 huts & bolts Initially reported on 920903 Ebasco Svcs currently evaluating problem All bolts replaced/reinspected PARSONS;R N Carolina Power & Light Co 82/09/30 D'REILLY, J P Region 2. Office of Director 1p 15640 169 24X Fiche 50-400, 82/09/30, 82(0080180
- 8210080283 Interim deficiency rept re sheared pinion keys on Limitorque valve motor operators Initially reported on 820703 Westinghouse discussing problem w/Limitorque Final rept will be submitted by 830401 Also reported per Part 21 PARSONS,R M Caroline Power & Light Co 82/10/01 O'REILLY, J P Region 2, Office of Director 3pp 15638 320 24% Fiche 50-400. 82/10/01,8210080283
- 8210130567 Addendum 2 to 820319 deficiency rept re inadequately welded studs on embedded strip plates Addendum provides info re shipment of embeds (Type II strip plates & crane rail plates) & any associated problems
 PARSON,R M Carolina Power & Light Co 82/10/05 O'REILLY, J P
 Region 2, Office of Director 5pp. 15683 113 24X
 Fiche 50-400, 82/10/05, 8210130567
- 8210220484 Interim deficiency rept re defective governor drive coupling in swergency diesel engine-generator sets from Transamerica Delaval Initially reported on 820909 Coupling will be replaced Also reportable per Part 21 PARSONS.R N Carolina Power & Light Co 82/10/07 O'REILLY, J P Region 2. Office of Director 4pp 15779 079 24X Fiche 50-400, 82/10/07, 8210220484

- 6210220075 Interim deficiency rept re design error in solid state protection sys Initially reported on B20909 Westinghouse continuing to review design & has revised test procedures to verify contact closure Also reported per Part 21 PARSONS.R M Carolina Power & Light Co 82/10/08 D'REILLY.J P Region 2. Orfice of Director 4pp 15778 185 24% Fiche 50-400, 82/10/08.8210220075
- G210220412 Final deficiency rept re grout concrete interface failure on equipment pad France Initially reported on 820909 Embed frame removed Concrete curb chipped completely out // curb // riame replaced PARSONS.R M Carolina Power & Light Co 82/10/08 G'REILLY, J P Region 2, Office of Director 4pp 15778 358 24x Fiche 50-400,02/10/08,0210-220412
- 618290260 Interim deficiency rept to gaps between mating surfaces or connections between structural steel members which also had A490 bolts w/A325 nuts initially reported on 820618 Ebasic Sycs (no evaluating problem PARSONS,R M. Carolina Power / Light Co. 82/10/13 0/REJLLY,J P. Region 2. Office of Director 1p 15853 176 24x Fiche 50-400, 82/10/13 6210290260
- 8210290258 Interim dericiency rept re grease between mating surfaces of structural connection designed as friction connection Initially reported on 820915 Ebasco Svos, Inc currently evaluating problem Results espected by 830415 PARSONS.R H Carolina Power & Light Co 82/10/14 D'REILLY, J PRegion 2, Office of Director 1p 19853 197 24X Fiche 50-400, 82/10/14, 8210290258
- 8210260398 Final deficiency regt re use of ABTM A307 bolts in lieu of A325 bol's specified in containment recirculating sump I cover structural steel Initially reported on 820903 Yield stress would not be exceeded Matter not reportable PARSONS,R M Caroline Power & Light Co 82/10/15 O'REILLY, J P Pegion 2, Office of Director ip 15806 135 24X Fiche 50-400,82/10/15,8210260398

DOCKET 50-402 SHEARON HARRIS NUCLEAR POWER PLANT, UNIT 3

- 0 Adjudicatory correspondence
- GIIO120103 Add1 response to FD]A request for nine categories of records generated by present RRC Commissioners, primarily Chairman Palladino & Commissioner Roberts & White House Forwards App B documents
 FELTON J M Division of Rules and Records 82/07/12 UDBLL, R A Critical Mass Energy Project 3pp (5690 117 24X Fiche 50-000 82/07/12 BZ(0120103
- --8210120123 Forwards memorandum *> order re Council of NC objection to util request for exemption to perform certain site preparation work Memorandum addresses exemption question & sets out history of Commission regulation. Section 50 12 ROBERTS, IT M Commissioners 81/12/07 PALLADINO. M Commissioners 1p 15/90 124 24% Fiche 50-000, 82/07/(2, 82/07/07/07)
- --B210(20132 Memorandum & order re Council of NC objection to util request for exemption per revised NEPA regulation to perform certain site preparation work NEPA does not bar preliminary work Site preparation work properly authorized BENDER.P C Atomic Energy Commission 74/06/11 Atomic Energy Commission 74/06/11 Atomic Energy Commission 68pp 15590 125 24X Fiche 50-000, B2/07/12, B210120103

DARKET 50-403 SHEARON HARRIS NUCLEAR POWER PLANT, UNIT 4

request for name categories of records sioners, primarily Chairman " "lite House Forwards

> rds 82/07/12 UDELLIR A 390 [17 24X

> > NC abjection to

€.

DOCKET 50-404 NORTH ANNA POWER STATION, UNIT 3

A Application/construction stage documents & correspondence

- 6210070016 Forwards request for addl info re 820708 application for (pertension of Unit 3 Info needed to assess environ impact of allowing CP for Unit 4 to expire ADENSAM, E G Licensing Branch 4 82/09/22 FERGUSON, J H Virginia Electric & Power Co 3pp 15646 301 24% Fiche 50-404,82/09/22,8210070016
- B210040277 Advises of plans for const of new 230 kV transmission line to connect North Anna power station to Louisa substation NO Tech Spec or ETS change required LEASBURG, R H Virginia Electric & Power Co. 82/09/27 DENTON, H R Diffice or Nuclear Reactor Regulation. Director CLARK, R A Operating Reactors Brainh 3 2pp 15591 204 24X Fiche 50-338, 82/09/27, 8210040277
- --8210040325 Advises that proposed 230 kV transmission line between North
 Anna & Louisa need not be evaluated in amend to environ rept
 for North Anna 1 & 2 Line is not part of North Anna
 utilization facility
 RAGONE, S. Virginia Electric & Power Co. 74/01/02 MULLER, D.R.
 Atomic Energy Commission 2pp. 15591 329 24X
 Fiche 50-338, 82/09/27, 8210040277
- 8210180418 Advises that RL Tedesco no longer employed by NRC T Novil is Assistant Director for Licensing ADENSAM.E O Licensing Branch 4 82/10/01 FERQUEON, J H Virginia Electric & Power Co 2pp 15745 288 24X Fiche 50-404,82/10/01.
- O Inspection reports, IE Bulletins & correspondence
- 8210010380 Forwards IE 1nsp Rept 50-404/82-10 on 820830-0902 No noncompliance noted DAMCE/H C Division of Project & Resident Programs 82/09/13 LEASBURG/R H Virginia Flettric & Power Co 2pp 15573 081 24X Fichs 50-404/82/09/13/8210010380
- --8210010384 IE Insp Rept 50-404/82-10 on 920830-0702 No noncompliante noted Major areas inspected storage, preventive maint, measuring & test equipment calibr & followup on licensee identified items

 MERFIKEATHER, N. CONLON, T E Division of Engineering & Technical Programs 82/07/07 4pp 15573 083 24X Fiche 50-404,02/07/13, 8210010390

DOCKET 50-405 NORTH ANNA POWER STATION, UNIT 4

- A Application/construction stage documents & correspondence
- 9210070016 Forwards request for add1 info re 820708 application for CP stemsion of Unit 3 Info needed to assess environ impact of allowing CP for Unit 4 to expire ADENSAM. E 0 Licensing Branch 4 82/09/22 FERGUSON. J H Virginia Electric & Power Co 3pp 19646 301 24X Fichs 50-404.82/09/22.8210070016
- 8210040277 Advises of plans for const of new 230 kV transmission line to connect North Anna power station to Louisa substation No Tech Spec or ETS change required LEASBURG.R H Virginia Electric & Power Co B2/09/27 DENFIN
- --8210040325 Advises that proposed 230 kV transmission line between Merit Anna & Louisa need not be evaluated in amend to environ rept for North Anna i & 2 Line is not part of North Anna utilization facility RAGONE: 8 Virginia Electric & Power Co 74/01/02 MULLER, D X Atomic Energy Commission 2pp 15591 329 24X Fiche 80-038, 82/09/27, 8210040277

1

DECKET 50-409 LA CROSSE BOILING WATER REACTOR

- F Security, medical, emergency & fire protection plans
- 62:10040184 Forwards [E Investigation Rept 50-409/82-09 on 620615-17 No noncompliance noted HIMO J A Division of Emergency Preparedness & Operational Support 62/09/09 LINDER:F W Dairyland Power Cooperative 2pp 15582 001 24x Fiche 50-409,82/09/09,8210040184
- -8210040185 IE Investigation Rept 50-409/82-09 on 820615-17 No noncompliance noted Major areas inspected procedures & records & personnel interviews re health physics technicians listed in 820308 emergency plan, Revision 1 PHILLIP, G. A., PAGLIARO, J. A., WARNICK, R. F. Region 3, Office of Director 82/09/02 27pp 15582 003 24X Fiche 50-409, 82/09/09, 8210040184
- 62(6040152 Forwards response to 820510 request for add1 info re rewrite or Section 8 of fire protection rule 10CFR50 48 Revised procedures re complete loss of electrical power temergency reactor cooldown from outside control room enci LINDER.F Dairyland Power Cooperative 82/09/28 CRUTCHFIELD.D Dperating Reactors Branch 5 70pp 15582 353 24X Fiche 50-409,82/09/28,8210040152
- 821D:30365 Forwards info re containment leak testing, per NRC 820824 request info withheld (ref 10CFR73 21)
 LINDER: F. Dairyland Power Cooperative 82/09/28 CRUTCHFIELD.D Operating Reactors Branch 5 1p 19630 246 24%
 Fishe 50-407.82/09/28.8210130365
- talio150497 Forwards IE Insp Rept 50-409/82-12 on 820701-0831 No noncompliance noted STREETER, JF Division of Emergency Preparedness & Operational Support 82/09/28 LINDER, FW Dairyland Power Cooperative 2p. 15721 280 24% Ficho 50-409.82/09/28, 8210150497
- --B210150502 IE Insp Rept 50-409/82-12 on 820701-0831 No noncompliance noted Hajor areas inspected operational safety verification, menthly maint k surveillance observation, LER fullowup & fire protection/provention annual insp granCil.MW Division of Emergency Preparedness & Operational Support WALKER, RD Region 3. Office of Director 82/09/21/pp 15721 282 24x Fiche 50-409/02/09/28.8210150497
- 92(2050339 Provides status of technical support ctr & emergency operations facility Basic technical support ctr & emergency operations facility established & used in emergency erercises
 L1/DFR.F Dairyland Powel Cooperative 92/09/29 EISENHUT, D @ Division of Licensing App (5610 114 24X Fiche 50-409,82/09/29.
- 8210280045 Releases public version of rovised emergency plan & revised emergency plan implementing procedures FELTON.JH Division of Rules and Records 82/10/08 Document Management Branch 1p 15861 347 24X Fiche 50-409.82/10/08.
- -8210280048 Forwards public version of Revision 3 to emergency plan & revised implementing procedures including Procedures EPP-2 re organization & operations during emergencies & EPP-14 re emergency plan training LINDER.F Dairyland Power Copperative 82/09/27 CRUTCHFIELD.D Operating Reactors Branch 5 ip 15841 348 24X Fiche 50-409,82/10/08.8210280045
- -8210280051 Forwards public version of Revision 3 to emergency plan & revised emergency plan implementing procedures.including Procedures EPP-2 re organization & operations during emergencies & EPP-14 re emergency plan training LINDER.F Dairyland Power Cooperative 82/09/15 KEPPLER.J G Region 3. Office of Director 2pp 15861 347 24X Fiche 50-409.82/10/08.8210280045
- --8210280053 Public version of Revision 3 to emergency plan * Dairyland Power Cooperative 82/09/03 26pp 15861 351 24X Fiche 50-409,82/10/08,8210280045
- --B210280055 Public version of revised emergency plan implementing procedures including Procedures EPP-2 re organization & operations during emergencies & EPP-14 re emergency plan training LINDER.F Dairyland Power Cooperative 82/09/03 114pp 15862 015 24% Fiche 50-409, 82/10/08.8210280045

- 8210220176 Responds to NRC 820915 Itr re IE Emergency Preparadness Insp Rept 50-409/82-1t on 820803 Corrective actions Tech Spec change to emergency operating facility data acquisition sys will be installed & operating during Oct 1982 LINDER: F Dairyland Power Cooperative 82/10/11 HIND. J A Division of Emergency Preparadness & Operational Support 9pp 18777 295 24X Fiche 50-409, 82/10/11, 8210220176
- 8210250349 Forwards revisions to physical security, contingency & training & qualification plans Revisions withheld (ref 10CFR73 21)

 LINDER: F Dairyland Power Cooperative 82/10/20 CRUTCHFIELD, D Operating Reactors Branch 5 2pp 15790 045 24x

 Fishe 50-409, 82/10/20, 8210250349
- 8210260371 Requests that R Walker be added to Encl 1 of 820715 ltr to provide for unescorted access to vital & protected areas KEPPLER, J O Region 3, Office of Director 82/10/20 LINDER, F W Dairyland Power Cooperative 1p 15803 106 24X Fiche 50-409, 82/10/20, 8210260371
- 8210270127 Forwards IE Safeguards Insp Rept 50~407/82-16 on 820920-24 & notice of violation Details & notice of violation withhold (ref 100FR73 21)
 MILLER, J. R. Division of Engineering & Technical Programs 82/10/26
 LINDER, F. W. Dairgland Power Cooperative 2pp 15852 355 24X
 Fiche 50~407, 62/10/26.8210270127
- --8210290137 IE Safeguards Insp Rept 50-409/82-16 on 820720-24
 Noncompliance noted security equipment not alarm equipped & not tested properly Details withheld (ref LOCFR73 21)
 PIRTLE-0 L . OREED.J R Region 3. Office of Director 82/10/20
 2pp 15653 357 24X Fiche 50-409.82/10/26.8210290129
- J Insurance & indemnity information
- 8210220009 Responds to NRC 820812 questions re util request for exemption from requirements of 10CFR50 54(w) concerning property insurance
 LIMDER.F. Dairyland Power Cooperative 82/09/13 SALTZMAN. J
 Assistant Director for State & Licensee Relations 5pp 15778 214
 24X Fiche 50-409,82/09/13,8210220009
- P Operating license stage documents & correspondence
- 8210010389 Forwards revised Page 36g to Fech Specs.per 820915 proposed amend to License DPR-45 LINDER.F Dairyland Power Cooperative 82/09/23 CRUTCHFIELD.D Operating Reactors Branch 5 1p 15574 291 24X Fiche 50-409.82/09/23.8210010389
- --B210010394 Revised proposed Page 34g to Tech Specs re radioactive gaseous effluent monitoring instrumentation

 † Dairyland Power Cooperative 82/09/23 ip 15574 292 24X Fiche 50-409,82/09/23,8210010389
- 8210040067 Forwards safety evaluation of util 820305 to 0926 assessments of SEP Topic XV-1, "Decrease in Feedwater Temp, Increase in Feedwater Temp, Increase in Feedwater Flow to Increase in Steam Flow " Evaluation will be basic input to integrated safety assessment Topic complete CRUTCHFICLD.D Operating Reactors Branch 5 82/09/29 LINDER, F Dairyland Power Cooperative 15pp 15581 220 24X Fiche 50-409, 82/09/29, 8210040067
- 8210050045 Informs that preliminary review of submittal re TMI Action Item II K 3 17, "Rept on Outages of ECCS" completed Add1 info required to complete review requested within 30 days of receipt of Itr GRUTCHFIELD, D. Operating Reactors Branch 5 82/09/29 LINDER, F. Dairyland Power Cooperative 2pp 15603 229 24X Fiche 30-409, 82/09/29, 8210050045
- --9210050068 "ECCS Repts (F-47), TMI Action Plan Requirements, Dairyland Fower Cooperative; LACBUR, " request for addl info USBURY, F M., DVERBECK, G J Franklin Institute/Franklin Research Center NRC-03-BI-(30 RAI-C5506-196 82/08/25 CHOW, E NRC-No Detailed Affiliation Given Spp 15603 231 24X Fichs 50-409, 82/09/29, 8210030065
- 8210050067 Application to amend License DPR-45, revising Tech Specs re safety valves installed on RCS. LINDER: F Deiryland Fower Cooperative 82/07/29 CRUTCHFIELD, D Operating Reactors Branch 5 5pp 15603 196. 24X Fiche 50-407. 82/09/29, 8210050067
- --8210050070 Proposed Tech Specs re sefety valves installed on RCS * Dairyland Power Cooperative 82/09/29 26pp 15600 201 24x Fiche 50-409,82/09/29.8210050067

- B210130326 Comments on proposed scope of Phase III of SEP as reflected in individual topic definitions appended to 820907 Itr Staff encouraged to develop & implement means to incorporate positive attributes of Phase III in Licensee/NRC interface KACICH-R M SEP Dumers Group 82/10/07 ETSENHUT, D © Division of Licensing 7pp 15682 179 24X Fiche 50-000,82/10/07,8210130326
- 8210180183 Provides guidance & clarification for response to NUREG-0737. Item IT B 3 "Post-Accident Sampling Sys," per 820830 request for additinfo CRUTCHFIELD.D Operating Reactors Branch 5 82/10/07 LINDER.F Dairyland Power Cooperative Spp 15718 179 24X Fiche 50-409.82/10/07.8210180183
- 8210220272 Forwards final topic evaluation for sys aspects of safe shutdown requirements for SEP Topics V-10 B.V-11 B & VII-3, "RHR Reliability." "RHR Interlock Requirements," & "Sys Required for Safe Shutdown," respectively CRUTCHFIELD. D. Operating Reactors Branch 5 82/10/07 LINDEK, F. Dairyland Power Cooperative 53pp 15775 140 24X Fiche 50-407, 82/10/07, 8210220272
- 8210150203 Forwards completed Table Loriginally submitted w/NRC 82082/ evaluation of SEP Topic VI-4, "Containment Isolation Sys." Containment mode made since 1964 comply w/DRM--NSIC-5 LINDER: Dairyland Power Copperative 82/10/08 CRUTCHFIELD.D Operating Reactors Branch 5 Jpp 15701 320 24x Fichs 50-407:82/10/08.8210150203
- 8210150375 Forwards safety evaluation re GEP Topic XV-9, "Startup of Inactive Loap or Recirculation Loap at Incorrect Temp" Plant in conformance w/SRP Sections 15 4 4 8 15 4 5 requirements & analysis acceptable CRUTCHFIELD. D. Operating Reactors Branch 5 82/10/12 LINDER, F. Dairyland Power Cooperative 7pp 15715 (66 24X Fiche 50-409, 82/10/12, 8210150375
- B210190446 Provides unresolved safety issue status in response to 820606 request LINDER:F Dairyland Power Cooperative 82/10/13 LAINAS.0 C Assistant Director for Safety Assessment 7pp 15740 162 24X Fiche 50-409. 82/10/13.8210190446
- 8210200015 Forwards evaluation of SEP Topic VI-1. "Drganic Matls & Post-Accident Chamistry" Design meets licensing criteria for topic based on consideration of unique noncirculating ECCB design.
 CRUTCHFIELD. D Operating Reactors Branch 5 82/10/14 LINDER:F Dairyland Power Cooperative App 15757 334 24X Fichs 50-407.82/10/14.8210200015
- 8210200025 Forwards evaluation of SEP Topic XV-16. "Radiological Consequences of Failure of Small Lines Carrying Primary Coolant Dutside Containment LACBUR " Facility meets current licensing criteria for topic CRUTCHFIELD D Operating Reactors Branch 5 82/10/14 LINDER.F Dairyland Power Cooperative Spp 15755 028 24X Fiche' 50-407, 82/10/14, 8210200025
- 8210200031 Forwards evaluation of SEP Topic XV-20. "Radiological Consequences of Fuel Damaging Accidents " Evaluation will be included in integrated safety assessment Thyroid dose at exclusion area boundary within 10CFR100 requirements CRUTCHFIELD.D Operating Reactors Branch 5 62/10/14 LINDER.F Dairyland Power Cooperative Spp 15757 329 24X Fiche 50-409-82/10/14-8210200031
- 8210200038 Forwards evaluation of SEP Topic XV-19, "LDCA Resulting From Spectrum of Piping Breaks Within RCPB (Radiological) LACBER " Util mests current licensing criteria for topic CRUTCHFIELD, D. Operating Reactors Brench 5 82/10/14, LINDER, F Dairyland Pouer Cooperative 5pp 15757 299 24X Fiche 50-407-82/10/14-8210200038
- 8210220449 Forwards safety evaluation & supporting technical rept for licensee BIEROS proposed electrical sys design mods & Tech Spec changes re degraded grid voltage protection Proposed changes acceptable SEP Topic VIII-I A complete.
 CRUTCHFIELD.D Operating Reactors Branch 5 82/10/14 LINDER, F Dainyland Power Cooperative 7pp 15778 339 24X
 Fichs 50-409, 82/10/14.8210220449
- 8210200016 Forwards evaluation of SEP Topic II-2 C re atmospheric transport & diffusion characteristics for accident analysis. Section V X/Q values appropriate for estimating exposures & should be used in all but steam line break calculations CRUTCHFIELD. Operating Reactors Branch 5 82/10/15 LINDER, F Dairyland Power Cooperative 4pp 15752 357 24X Fiche 50-409, 82/10/15, 8210200016

į

H

- 8210210246 Advises NUREG-0737. [tem II K 3 27. "Common Ref Level," complete since util committed to eliminate potential operator confusion when changing water level instrumentation by integrating Items II K 3 27 & I D 1 CRUTCHFIELD. D Operating Reactors Branch 5 82/10/15 LINDER. Fiche 50-409. 82/10/15. 8210210246
- 8210260319 Advises that TMI Items II D 3 % II F i 2. "Reactor Versel Liquid" % "Stack Effluent Sampling Sys." respectively, were completed on 820927 prior to refueling outage TMI Item III D 3 4 unil be completed by 830101 LINDER.F Dairyland Power Cooperative 82/10/20 EISCNHUI, D C Division of Licensing 1p 15805 227 24X Fiche 50-409, 82/10/20 8310260319
- 8210290307 Submits summary of review of SEP Topic III-3 A re effects of design basis flood on containment & turbine bldg structures Response satisfies NRC requirement for addI flooding effects into LINDER:F Dairyland Power Cooperative 82/10/22 CRUTCHFIELD, p Operating Reactors Branch 5 3pp 15853 167 24x Fiche 50-409, 82/10/22, 8210290307
- B210290151 Forwards summary of outages of manual depressurization systeming 1976-1980 per NRC 820929 request re TMI Action Item 11 K 3 17 Bys performed adequately during reporting period Sys used for testing only LINDER: F Dairyland Power Cooperative 82/10/25 CRUTCHFIELD, D Operating Reactors Branch 5 2pp 15853 151 24X Fiche 50-409, 82/10/25, 8210290151
- 8210280289 Forwards evaluation of SEP Topic IX-1, "Fuel Storage," based on 820226 safety assessment rept & 820831 addl info Fuel storage facilities acceptable Evaluation will be basic input to integrated safety assessment CRUTCHFIELD. D. Operating Reactors Branch 5 82/10/26 LINDER.) Dairyland Power Cooperative 7pp 15837 033 24X Fishe 50-409, 82/10/26, 8210280289
- Q Inspection reports, IE Bulletins & correspondence
- 8210040184 Forwards IE Investigation Rept 50-409/82-09 on 820615 17 No noncompliance noted HINO.J A Division of Emergency Preparedness & Operational Support 82/09/09 LINDER.F W Dairyland Power Cooperative 2pp 13582 001 24% Fiche 50-409.82/09/09.8210040184
- --8210040185 IE Investigation Rept 50-409/82-09 on 820615-17 No noncompliance noted Major areas inspected procedures & records & personnel interviews re health physics technicians listed in 820308 emergency plan. Revision i PHILLIP, 0 A , PAGLIARO, J A , MARNICK, R Region 3, Office of Birector 82/09/02 27pp 13582 003 24X Fiche 50-409.82/09/03, 8210040184
- 8210130400 Forwards IC Insp Rept 50-409/82-14 on 820809-13 & notice of violation KEPPLER, J O Region 3, Office of Director 82/09/24 LINDER, F H Dairyland Power Cooperative 2pp 15682 072 24X Fiche 50-409, 82/09/24, 8210130400
- --9210130403 Notice of violation from insp on 820809~13 KEPPLER, J O Region 3, Office of Director 82/09/24 15682 074 24X Fiche 50-409, 82/09/24, 82;0130400
- --B210130408 IE Insp Rept 50-409/B2-14 on B20809-13 Noncompliance noted radiation levels in excess of DOT regulations, failure to meet burial sites acceptance criteria & uncontrolled release of radioactive liquide
 PAUL-R A Division of Engineering & Technical Programs
 OREOER-L R Region 3, Office of Director 82/09/20 Bpp
 15682-076 24X Fiche 50-409, 82/09/24, 8210130400
- --B210130416 Discusses apparent violation of 10CFR47 by util re radustry shipment containing radioactive low-specific activity on 820730 Readings from util & Chem Nuclear Sys, Inc instruments show apparent discrepancy SHAFER: PW Dairyland Power Cooperative 82/08/17 GREGER, L R Division of Project & Resident Programs 12pp 15682 084 24X Fiche 50-409,82/09/24,8210130400
- 8210150497 Forwards IE Insp Rept 50-409/82-12 on 820701-0831 No noncompliance noted BTREETER, J. F. Division of Emergency Preparedness & Operational Support 82/09/28 LINDER, F.W. Dairyland Power Cooperative 2pp 15721 280 24X Fiche 50-409.82/09/28,8210150497

- --8210150502 IE Insp Rept 50-409/82-12 on 820701-0831 No noncompliance Plotsubus Le Insp Rept 30-40704722 on 20/01-0031 No noncompi northig maint & surveillance observation, LER followup & fire protection/prevention annual insp BRANCH M W Division of Emergency Preparedness & Operational ort HALKER.R D Region 3. Office of Director 82/09/21 15721 282 24% Fiche 50-409.82/09/28,8210150499
- 8208190233 IE Info Notice 80-35, Suppl 1, "Leaking & Dislodged I-125 Implant Seeds " See list encl
 Implant Seeds " See list encl
 COBB.L I Division of Fuel Facilities, Materials & Gafeguards
 82/10/06 Consolidated Edison Co of New York 66pp 15761 250
 24X Fiche 50-000, 82/10/06,8208190233
- 6210130211 Confirms conversation between J Taylor & R Halker rescheduling mgt meetings for 821019 at facility to discuss systematic assessment of licenses performance Second meeting uill fallow to discuss regulatory improvement program SPESSARD, R L Division of Project & Resident Programs 82/10/0 LINDER, F W Dairyland Power Cooperative ip 15674 116 24X Fische 50-409, 82/10/07, 8210130211 82/10/07
- 8210220176 Responds to NRC 820915 ltr re IE Emergency Preparedness Insp. Rept 50-409/82-11 on 820803 Corrective actions Tech Spec change to emergency operating facility data acquisition syswill be installed & operating during Oct 1982 LINDER: F Dairyland Power Cooperative 82/10/11 HIND. J A Division of Emergency Preparedness & Operational Support 9pp 15777 275 24X Fiche 50-409.82/10/11.8210220176
- 8210190638 Ack receipt of 820910 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 30-409/82-07 SPEBSARD, R L Division of Project & Resident Programs 82/10/13 LINDER, F W Dairyland Power Cooperative 1p 15740 049 24X Fiche, 50-409, 82/10/13, 8210190638
- --8210190404 Responds to NRC 820812 ltr re violations noted in IE Insp. Rept 50-409/82-07 Corrective actions Tech Spec limits for primary systactivity & chemistry entered onto water chemical a radiochemical analyses rept. LINDER. F. Dairyland Power Cooperative 82/09/10 KEPPLER. J. G. Region 3. Office of Director 3pp. 15740 050 24X Fiche 50-409.82/10/13.8210190638
- 6208190238 IE Bulletin 82-03. "Stress Corrosion Cracking in Thick-Wall, Large-Diameter, Stainless Steel, Recirculation Sys Piping at BMR Plants " Svc list encl DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/10/14 Consolidated Edison Co of New York 115pp 15810 125 24X Fiche 50-000.82/10/14.8208190238
- 8210190433 Confirms J Taylor & R Walker conversation re scheduling of two mpt meetings Meetings will be held 821105 at LaCrosse, NI, to discuss systematic assessment of licensee performance & regulatory improvement program EPEBBARD, R L Division of Project & Resident Programs 82/10/15 LINDER, F W Dairyland of Project & Resident Programs 82/10/15 Fiche 50-409, 82/10/15,8210190433
- 82(02)0336 Forwards evaluation of SEP Topic III-3 C, "Inservice Insp of Water Control Structures," based on licensee 820129 safety assessment Insp program does not conform w/intent of Reg Guide 1 127 & should be modified CRUTCHFIELD.D Operating Reactors Branch 5 82/10/15 LINDER,F Dairyland Power Cooperative 9pp 15765 054 24X Fiche 50-409, 82/10/15, 8210210336
- 8210250106 Confirms conversation between J Taylor & R Walker re-rescheduling two mgt meetings Meetings will be held 821109 to discuss systematic assessment of licenses performance & regulatory improvement program SPEBSARD, R L Division of Project & Resident Programs 82/10/1 LINDER, W Dairyland Power Cooperative ip 15787-079-24X Fiche 50-409, 82/10/18, 8210250106 82/10/18.
- 8210290127 Forwards IE Bafeguards Insp Rept 50-409/82-16 on 820920-24 & notice of violation Details & notice of violation withheld (ref 10CFR73 21)
 HILLER.J.R Division of Engineering & Technical Programs 82/10/26
 LINDER.F W Dairyland Power Cooperative 2pp 15853.355. 24X
 Fichs.50-409.82/10/26.8210270129
- --8210270137 IE Bafeguards Insp Rept 50-409/82-16 on 820920-24 Noncompliance noted security equipment not alarm equipped & not tested property Details withheld (ref 10CFR73, 21) PIRTLE,0 L , OREED,J R Ragion 3, Office of Director 82/1 2pp 13853-357. 24X Fiche, 50-409,82/10/26,8210290129 82/10/20

- S Reportable occurrences, LERs & related correspondence
- 8210050353 PNO-111-82-091A on 820926, plant returned to svc following cloududd PND-111-82-091A on 820926, plant returned to svc i removal of blockage in emergency high pressure core spray ays lines Blockage caused by allt entering sys through interconnection w/svc water sys Silt removed WALKER, R. JORDAN, M. Region 3, Office of Director 82/05 15608 255 24X Fichs 50-409.82/09/27.8210050353 82/09/29 10
- 8210190448 Forwards LER 82-017/03L-0 Detailed event analysis submitted LINDER, F. Dairyland Power Cooperative 82/10/11 KEPPLER, J. G. Region 3. Office of Director 2pp 15740 170 24X Fiche 50-409, 82/10/11, 8210170448
- --8210190454 LER 82-017/03L-0 on B20926, during Mode A, high pressure svc water containment isolation valve closed Caused by air leak due to losse fitting on valve operator air supply line Air supply line fitting tightened 5 valva reopened OGDDMAN, L 8 Dairyland Power Cooperative 82/10/11 Region 3, Office of Director ip 15740 172 24X Fiche 50-409, 82/10/11, 8210190448
- DOCKET 50-410 NINE MILE POINT NUCLEAR STATION, UNIT 2 H Ceneral correspondence
- 8210210322 Requests changes to NRC correspondence distribution list TB Conner replaces LM Trasten & CD Hobelman JW Keib should be added to list MANGAN, C V Niegara Mahawk Power Corp 82/09/10 DIRCKS, W J Uffice of the Elecutive Director for Operations ip 15764 222 24X Fichs 50-410, 82/09/10.8210210322
- Q Inspection reports. IE Bulletins & correspondence
- 8210040170 Advises that util response to IE Bulletin 80~14 will be submitted by 830131 instead of 820730 MAKNO 8 F Niagara Mohauk Power Corp 82/07/23 HAYNES, R C Region 1. Office of Director 1p 15582 314 24X Fiche 50~410,82/09/23,8210040170
- 8208190233 IE Info Notice 80-35, Suppl 1. "Leaking & Dislodged 1-125 Implant Seeds " Svc list encl COBB.L I Division of Fuel Facilities, Materials & Safeguards 82/10/06 Consolidated Edison Co of New York & App 15761 250 24X Fiche 80-000,82/10/06.8208190233 15761 250
- 8210270415 Notification of 821020 enforcement conference in Region 1 ofc w/wtil to discuss GA insp
 BAUNACK, W NRC No Detailed Affiliation Given 82/10/13
 DIRKS, W J Office of the Executive Director for Operations
 STELLO, V Regional Operations & Generic Requirements DEYOUNG, R C
 Director's Office, Office of Inspection and Enforcement ip
 15833 283 24X Fiche 50-410,82/10/13,8210270415
- 8208190238 IE Bull-tin 82-03, "Stress Corresion Cracking in Thick-208190238 1E Bulletin 82-03, "Stress Corrosion Cracking in Thick Mall.Large-Diameter, Bainless Steel, Recirculation Sys Piping at BWR Plants " Svc list encl DEYOUNO.R C Director's Office. Office of Inspection and Enforcement 82/10/14 Consolidated Edison Co of New York 115pp 13810 125 24X Fiche 50-000.82/10/14.8208190238
- S Reportable occurrences, LERs & related correspondence
- 8210040071 Final deficiency rept re control bldg termination cabinet ecourous, ranes sericiency rept to control bldg termination cabins support sills Initially reported on 820615 Welded stude to be replaced by drilled-through anchor bolts tied directly to base concrete Work will be completed by 820930 MANNO,S F Niegare Mohawk Power Corp 82/09/23 STARQSTECKIR Division of Project & Resident Programs 2pp 15581 276 24X Fiche: 50-410, 82/09/23, 8210040071
- 8210040190 Final deficiency rept re Rosemount Model 1152 transmitters AUGUSTATE THAT deficiency pept Te Rosemount model 1102 transulative Codes At D Transmitters do not use A or D amplifier boards. Deficiency per 10CFRSO 55e not valid Reportable per Part 21 by GE MANNO.8 F Niegara Mohawk Power Corp 82/09/23 STAROSTE Division of Project & Resident Programs 2pp 15583 189 Fiche 30-410.82/09/23.8210040190 STAROSTECK I. R
- 8210150129 Interim deficiency rept re ASME III Class 1 joints welded w/ASME Class 2 k 3 welding procedures Contrary to 820831 itm, deficiency deamed reportable per 10CFR50 55(e) MANNO. S. F. Niagara Mohawk Power Corp. 82/10/06 STAROSTECKI, R. Division of Project & Resident Programs 1p 15497 069 24X Fiche 50-410, 82/10/06, 8210150129

- 8210250378 Interim deficiency rept re insufficient environ &/or seismic qualification documentation of listed control room equipment Initially reported on 820921 Final rept will be submitted by 821231 MARNO, 9 F Magara Mohauk Power Corp 82/10/15 STAROSTECK[,R Division of Project & Resident Programs 2pp 15790 139 24X Fiche 50-410, 82/10/15, 8210250378
- DICKET 50-412 BEAVER VALLEY POWER STATION, UNIT 2
- A Application/construction stage documents & correspondence
- 6210120031 Summary of 820831 meeting w/util in Bethesda.MD recontents of CL application "to introduce project mpt personnel Applicant requested deferral of FSAR Chapter 18 until finalization of NUREG-0800 DOCLITICE t Licensing Branch 1 82/09/10 Licensing Branch 1 3pp 15689 197 24x Fiche 50-412.82/09/10.8210120031
- Q Inspection reports. IE Bulletins & correspondence
- 8210050211 Forwards [E Insp Rept 50-412/82-10 on 820809-13 No noncompliance noted MARTIN.T 7 Division of Engineering & Technical Programs 82/09/17 WOOLEVER.E J Duquesne (ight Co 2pp 15615 089 24X Fiche 50-412.82.909/17.821006021)
- --B210060215 IE Insp Rept 50-412/B2-10 on B20809-13 No noncompliance noted Hajor areas inspected records re reactor pressure vessel storage & maint at site vessel lift & transportation 5 final rigging & installation VARELA,A A., DURR,J P. Region 1 Office of Director 82/09/11 6pp 15515 071 24X Fiche 50-412-82/09/17, 8210060211
- 6208190203 IE Info Notice 80-35. Suppl 1. "Leaking & Distodged I-125 Implant Seeds " Svc list encl COBB.L I Division of Evel Facilities. Materials & Bafeguards 82/10/06 Consolidated Edison Co of New York 66pp 15761 256 24% Fiche 50-000.82/10/06.8208190233
- 52/8190238 IE Bulletin 92-03, "Stress Corrosion Cracking in Thick-Wall, Large-Diameter: Stainless Steel, Recirculation Sys Piping at BWR Plants" Svc list entl DEYGUNG.R C Director's Office. Office of Inspection and Enforcement 82/10/14 Consolidated Edison Co of New York 115pp 15819 125 24X Fisch 50-000.82/10/14.8208190238
- S Reportable occurrences, LERs & related correspondence
- 8210070155 Final Significant Deficiency Rept 82-05 re misapplication of torquing equipment on emergency diesel generators shaft spider assemblies Retorquing of all fasteners to vendors specified value of 5.000 ft lb has been performed MDDLEVER.E J Duquesne Light Co 82/09/24 HAYNES.R C Region 1, Office or Director 2pp 15627 069 24X Fiche 50-412,82/09/24,8210070155
- 6210070233 Interim deficiency rept re Westinghouse solid state protection sys Initially reported on 820830 Vendor reviewing on-line test circuitry design Next rept will be submitted by 830520 MOCLEYER, E. J. Duquesne Light Co. 82/09/29 HAYNFS, R. C. Region 1 Office of Director. 3pp. 15634 303 24X Fiche 50-412,82/09/29,8210070233
- 8210260143 Interim Significant Deficiency Rept 82-06 re sheared pinion keys in Linitorque notor operators supplied by Hestinghouse Initially reported on 820901 Keys replaced Westinghouse will provide data for completing corrective action WOLLEVER.E J Duquesne Light Co 82/10/07 HAYNES.R Region 1, 0Ffice of Director 4pp 15797 085 24X Fiche 50-412,82/10/07,8210260143
- 6210260135 Interim Significant Deficiency Rept 62-02 re possible inaccuracy in two RCS wide-range pressure transmitters initially reported on 820512 New Mestinghouse info being evaluated Next rept expected by 830328 WOLEVER.E J Duquesne Light Co 92/10/18 HAYNES, R Region 1. Office of Director dop 15799 079 24% Fiche 50-412,82/10/18,8210260135

1

11

- DOCKET 50-413 CATAWBA NUCLEAR STATION, UNIT 1
- A Application/construction stage documents & correspondence
- 821001000B Responds to FOIA request for 19 categories of documents rancilear reactor events & safety problems Forwards documents listed in App A FELYON, J M Division of Rules and Records B2/06/28 UDELL, R A Critical Mass Energy Project 15pp 15727 005 24X Fichs 50-000, 82/06/28, 8210010008
- --BOOSOSOZOS Discusses add1 required info to better define potential far cracking in reactor vessel noticles NDONAN.V S Assistant Director for Materials & Qualifications Engineering 80/05/05 TEDESCO,R L Assistant Director for Licensing 2pp 15727 176 24X Fiche 50~000.82/06/28.8210010008
- 8210050264 Forwards summary of 820406-07 meeting in Bethesda, HD & 820419-22 meeting in Charlotte, NC w/Mechanical Engineering Branch, Hestinghouse & BNML relitems in NRC 820129 itr W/sight oversize drawings Aperture cards are in PDR TUCKER. H B Dute Power Co 82/09/27 DENTON, H R Office of Nuclear Reactor Regulation, Director ADENSAM, E Q Licensing Dranch 4 343pp 15606 060 24% Fiche 50-413, 82/09/27, 8210050264
- 8210070092 Forwards minutes of meeting held during wk of 820419
 w/Westinghouse & Mechanical Engineering Branch.discussing
 resolution of FSAR Item 109 re fuel damping values Minutes
 withheld (ref 10CFR2 790)
 TUCKER.H B Dute Power Go 82/09/28 DENTON, H R Office of
 Nuclear Reactor Regulation, Director ADENSAM, E G Licensing Branch
 4 2pp 15628 079 24X Fiche 50-413,82/09/28,8210070092
- 82100503H4 Forwards revised FSAR pages reflecting organizational changes & changes to Chapter i3 Changes will be included in Revision 7 to FSAR
 TUCKER.H B Duke Power Co 82/09/29 DENTON,H R Office of Nuclear Reactor Regulation, Director ADENSAM,E C Licensing Branch 4 28pp 15408 281 24X Fiche 50-413,82/09/29,8210050384
- G2:019007| Notification of 82:006 meeting w/util in Charlotte, NC to discuss matls design General Design Criterion 51 JADBOUR, K N Licensing Branch 4 82/09/29 ADENSAM, E & Licensing Branch 4 3pp 16761 095 24X Fiche 50~413, 82/09/29, 82:019607
- 82(0050130 Provides fifth Quarterly update of projected const completion date Plant 90% complete as of 820718 Fuel load scheduled for Oct 1984 TUCKER:N B Duke Power Co 82/09/30 DENTON, H R Office of Nuclear Reactor Regulation. Director ADENBAM, E Q Licensing Branck 4 2pp 15605 045 24X Fiche 30-413, 82/09/30, 8210050130
- 8210060311 Informs that review of plant operations relative to void formation in vessel head during transients completed Assessment of facility procedures in training program per Generic Ltr 81-21 encl TUCKER: H B Duke Power Co 82/09/30 DENTON: H R Office of Nuclear Reactor Regulation, Director ADENBAM. E O Licensing Branch 4 App 15617 190 24X Fiche 30-413,82/09/30,8210060311
- 8210130094 Application for Amend 2B to CPPR-116 & CPPR-117, consisting of Revision 6 to FBAR & Revision 1 to license application TUCKER-H B Duke Power Co 82/10/12 DENTON-H R Office of Nuclear Reactor Regulation. Director ADENSAM, E O Licensing Branch 4 22pp 13699 001 24X Fiche 50-413:82/10/12,8210130094
- 8210220026 Summary of 820907-09 site visit & meetings w/util re Instrumentation & Control Sys Branch concerns & open items Responses to open items will be provided by end of Oct 1982 Summary & status of concerns & open items encl JABBBUR, K N Licensing Branch 4 82/10/15 Licensing Branch 4 9pp 15786 292 24X Fiche 50-413.82/10/15.8210220026
- 8210260201 Revises NO Parker 820701 ltr re schedule for submission of info meeded to resolve concerns identified in DO Eisenhut 801222 ltr & NUREO-0612 Info requested in Bections 2 2 & 2 4 of Encl 2 to be submitted by 821124 TUCKER: H B Dute Pawer Co 82/10/21 DENTON, H R Office of Nuclear Resolven Regulation, Director ADENBAM, E O Licensing Branck 4 lp. 15804 271 24X Fiche 50-413,82/10/21.8210260201
- D NRC Draft/Final Environmental Statements, supple & correspondence
- BB10040322 Comments on historic & archeologic impacts, water qualityentrainment; thermal discharge & post-operational monitoring discussions in DES DLANCHARD, B Interior, Dept of B2/09/30 ADENBAM, E Q Licensing Branch 4 3pp 15586 175 24X Fiche 50-413, B2/09/30, B210040322

1

- 32(0130117 Advises that DES is rated LO-1 Normal operation of facility will not have significant impact on environ No addl info
- MODRE, S. N. Environmental Protection Agency 82/10/06 JUBBOUR. K. N. Division of Licensing 2pp 15673 007 24X Fiche 50~413,82/10/06,82/10/3017
- 1210130487 Forwards comments on DES (NUREG-0921) re operation of
- Tacilities LOCHSTET,W A Pennsylvania State Univ 82/10/06 Division of Licensing 7pp 15682 140 24X Fiche 50-413,82/10/06,8210130487
- 210130506 Comments on DES List of water users in downstream order, to 10130506 Comments on URS List or Water Users in downstream order to be contained in FES, encl TURNER, L.E. South Carolina, State of 82/10/07 JABBOUR, K.N. Division of Licensing 3pp. 15682-253 24X Fiche 50-413,82/10/07, 8210130504
- 210250102 Forwards comments on DES,per 10CFR51
 TUCKER,H B Dute Power Co 82/10/07 DENTON,H R Office of
 Nuclear Reactor Regulation, Director EISENHUT,D Ø Licensing
 Branch 4 14pp 15791 191 24% Fishe 50-413.82/10/07.8210250102
- 21018010A Advises that review of DES for facility has been completed Clearance valid for 1 UT CROHER.D L South Carolina, State of 62/10/00 C Nuclear Reactor Regulation, Director 1p 15719 316 Fiche 50-413,82/10/06,8210180104 Office of
- 210180169 Comments on DES (NUREG-0921) & public health & safety impacts of proposed plant operation
 VILLFORTH, J C Food & Drug Administration 82/10/12 JABBDUR, K N
 Division of Licensing 2pp 15719 166 24X Fiche 50-413,82/10/12.
 82/10/80169
- 10260150 Requests encl comments on DES be transmitted to appropriate FIGURE 13 Hequests enc. comments on DEB be transmitted to ap NRC ofc DES summary of cost/benefit in Table & I deficent RILEY.J L Carolina Environmental Study Oroup 82/10/22 JABBOUR.K N Division of Licensing 3pp 15797 015 24X Fiche 50-413, 82/10/22.8210260180
- NRC Safety Evaluation Report (SER), supply & correspondence
- 10280045 Forwards responses to none (tems in EG Adensam 820409 ltr reauxiliary feedwater system draft 8ER.Section 7 1 3 1
 TUCKER.H B Dute Power Co 82/10/19 DENTON.H R Office of
 Nuclear Reactor Regulation, Director ADENSAM,E G Licensing Branch
 4 9pp 15837 263 24X Fiche 50-413,82/10/19.8210280065
- Security, medical, emergency & fire protection plans
- 09170053 Forwards Revision 3 to security plan Revision withheld (ref 09170033 Forwards (1970) 100 PR 1970 100 PR 201 PR 1970 100 PR 201 PR 1970 100 PR 201 PR 1970 100 PR 1970 PR 1970 100 PR 1970 PR 1970 100 PR 1970 PR 1970 100 PR 1
- 10:906:1 Responds to 8:0723 request for schedule for installation of public notification sys at facilities Final design of sys & schedule for installation not finalized Info submittal anticipated by 8:120:1

 TUCKER H B Duke Power Co 82/10/08 DENTON, H R Office of Nuclear Reactor Regulation, Director ADENBAH, E O Licensing Branch 1, NENTON,F Federal Emergency Management Agency 2pp, 15737 22:1

 24X Fiche 50-413,82/10/08.8210190411
- Adjudicatory correspondence
- 0050202 Response opposing Palmetto Alliance & Carolina Environ Study Proup 820922 supplemental petitions to intervene (CQARRY, JM. Duke Power Co. MCQARRY, JM. Debavoise & Liberman 82/10/04 Atomic Safety and Licensing Board Panel 71pp 5602 279 24X Fiche 50-413,82/10/04,8210050202
- 121005020B Response to Charlotte-Mecklenberg Environ Coalition 820919 revised Contention 4 Contention acceptable Notice of appearance & Certificate of Svc encl MCOARRY, J M Duke Power Co MCOARRY, J M Debevoise & Liberman 82/10/04 Atomic Bafety and Licensing Board Panel 4pp. 15602 350 24% Fiche 50-413.82/10/04.8210050202
- 0060991 Btatement of position on DES contentions Objects to all almetto Alliance/Carolina Environ Study Group contentions xcept Contention 4 as specified Certificate of Svc encl. OHNBON. 9 E Hearing Branch 4 B2/10/04 Atomic Safety and icensing Board Panel 26pp 15613 264. 24X Fiche, 50-413, 82/10/04, 210060191.

- 8210080081 Motion to compel util to respond to Palmetto Alliance 820703 second set of interrogatories & requests to produce Certificate of Syc end. OUTLD:R Palmetto Atliance GUILD:R Guild:R 82/10/0/ Atomic Safety and Licensing Board Panel 5pp 15640 199 Fiche 50-413:82/10/04:8210080081
- 8210180182 Order extending time until 821112 for Commission to act to elulabilaz Under extending time until 821112 for Commission (review ALAB-687 CHILK.S J Office of the Secretary of the Commission 82. Commissioners (p. 15719 td4 24X Fiche 50-413.82/10/14: 82(0180182 B2/10/14
- 8210200071 Provides response to ASLB questions at 821007-08 second special prehearing conference Questions relate to risks from McGuire facility & scope of evacuation costs listed in DES Table 5 ti JOHNSON, GE Hearing Branch 4 82/10/18 KELLEY, J. L., FOSTER, R. F., CALLIHAN, D. Atomic Safety and Licensing Board Panel 2pp 15757-192 24X Fiche 50-413,82/10/18,8210200071
- 6210210187 Motion for order to protect NRC from answering Palmetto Alliance Interrogatories 1 % 36 on Contention 8 % Interrogatory 1 on Contention 27 Requests are for large amount of matt w/a regard to relevance UDHN90N.0 E Hearing Branch 4 82/10/19 Atomic Safety and Licensing Board Panel 3pp 15765 159 24% Fiche 50-413.82/10/19,8210210187
- --8210210197 Responses to second set of interrogetories & requests to produce re Palmetto Alliance Contentions 8 & 27 Prof qualifications, NNREG/CR-2644 & Certificate of Svc encl JOHNSON, G E Hearing Branch 4 82/10/19 Palmetto Alliance 134pp 15765 162 24X Fiche 50-413,82/10/19,8210210187
- 8210250125 Responses to Palmetto Alliance 820927 third set of interrogatories & requests to produce Related CARR: A V Duke Power Co 82/10/17 Palmetto 15787 243 24X Fiche 50-413, 82/10/17, 8210250125 Palmetto Alliance 62pp
- 8210250282 Motion for protective order relieving applicants from rivesousce notion for protective order relieving applicants from requirement to respond to Palmetto Alliance 820927 third set of interrogatories & requests to produce Certificate of Svc encl Related correspondence CARR, A V Dute Power Co. 82/10/19 Atomic Safety and Licensing Board Panel 4pp 18791 098 24X Fiche 50-413,82/10/19.8210250282
- \$210250370 Forwards EIA re spent fuel storage of Oconee spent fuel at McOurre Unit 1 spent fuel pool, dtd Dec 1978 Copies also sent to intervenors W/o enct
 JOHNSON,O E Hearing Branch 4 82/10/21 KELLEY,J L : FOSTER,R F .
 CALLIHAN, D Atomic Safety and Licensing Board Panel 1p
 15790 188 24X Fiche 50-413,82/10/21.8210230370
- 8210260415 Answer apposing Palmetto Alliance 821004 motion to compal 21U200419 Answer apposing Palmetto Alliance 821004 motion to compe) answers to interrogatories ASLB should issue order denying motion as lacking merit Motion devoid of supporting arguments Certificate of Svc enc!

 CARR, A V Duke Power Co 82/10/22 Atomic Safety and Licensing Board Panel 20pp 15806 HIS 24X Fiche 50-413.82/10/22. B2102A0415
- 8210270002 Answers ASLB question re Palmetto Alliance/Carolina Environ Study Oroup Contention 10 DEG totaled risks to public of accidents from each unit JOHNSON, 0 E Hearing Branch 4 B2/10/25 KELLEY, J L , FOSTER, R F , CALLIMAN, D Atomic Safety and Licensing Board Panel 1p 15817 011 24X Fiche 50-413, 82/10/25, 82/10270002
- 8210270010 Advises that NRC does not intend to file response to Palmetto Alliance 821004 motion to compel discovery from applicants NRC responded to requests on 821017
 JUINBON.0 E Hearing Branch 4 82/10/25 KELLEY, J L , FOSTER.R F , CALLIHAR, D Atomic Safety and Licensing Board Panel ip 1822 340 24% Fiche 30-413,82/10/25,8210270010
- H General correspondence
- 8210130046 Responds to 820912 ltr request that NRC continue to send copies of correspondence to util on McGuira Since McGuira proceedings complete & documents in LPDR request denied.

 ADENBAME 0 Licensing Branch 4 B2/09/28 RILEY. J L Carolina Environmental Study Group ip 15696 284 24X Fiche 50-000.82/09/28.8210130046

- V Utility Final Safety Analysis Report (FSAR) & amends
- G2ID150094 Application for Amend 28 to CPPR-116 & CPPR-117, consisting or Revision 6 to FSAR & Revision 1 to license application TUCKER.H B Dute Power Co 82/10/12 DENTON,H R Office of Nuclear Reactor Regulation, Director ADENSAM,E © Licensing Branch 4 22pp 15699 001 24x Fiche 50-413,82/10/12,8210150094
- --8210150101 Revision 6 to FSAR 4 Duke Pouer Co 82/10/12 761pp 15699 023 24X Fiche 50-413,82/10/12-8210150094
- Q Inspection reports, IE Bulletins & correspondence
- 6210080015 Add1 response to FOIA request for 19 categories of info re nuclear reactor events % safety problems Forwards documents listed in App A Documents in App B completely withheld (ref FOIA Exemption 5)
 FELTON-J M Division of Rules and Records 82/07/12 UDELL.R A Critical Mass Energy Project 9pp 15665 027 24X
 Fiche 50-000, 82/07/12.8210080015
- 8210080156 Systematic assessment of licensee performance notes re racillty evaluation for Sept 1979-Aug 1980 * NRC - No Detailed Affiliation Given 80/08/31 5pp 15668 057 24x Fiche 50-000, 82/07/12.8210080015
- 5210010106 Farwards 1E Insp Repts 50-413/82-22 & 50-414/82-20 on 820824-27 No noncompliance noted DANCE.HC Division of Project & Resident Programs 82/09/13 TUCKER.HR Duke Power Co 2pp 15567 194 24X Fiche 50-413,82/09/13,8210010106
- --8210010110 IE insp Repts 50-413/82-22 & 50-414/82-20 on 820824-27 No noncompliance noted Major areas inspected independent insp effortireview of quality records for containment structures & supports & insertice review of program CCLEY.J L. BLAKE.J J Division of Engineering & Technical Programs 82/09/09 10pp 15567 196 24X Fiche 50-413,82/09/13,8210010106
- B210010131 Ack receipt of B20907 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-413/82-18 & 50-414/82-16 & EHIS.R C Division of Project & Resident Programs 82/09/22 TUCKER.H B Duke Power Co ip 15565 351 24X Fiche 50-413.82/09/22.8210010131
- --8210010134 Responds to NRC 820809 ltr re violations noted in IE Insp. Repts 50-413/82-18 & 50-414/82-16 Corrective actions matts personnel training uill be completed by 820915 & paint storage Darshouse will be upgraded by 821015 TUCKER-H B Duke Power Co 82/09/07 O'REILLY, J.P. Region 2, 04fice of Director 4pp 15565 352 24% Fichs 50-413,82/09/22,8210010134
- --8210010138 Forwards IE Insp Repts 50-413/82-18 & 50-414/82-16 on 820712-16 & notice of violation LEMIS.R C Division of Project & Resident Programs 82/08/09 TUCKER.H B Duke Power Co 2pp 19565 256 24X Fiche 50-413, 82/09/22, 8210010131
- --8210010141 Notice of violation from insp on 820712-16 * Division of Project & Resident Programs 82/08/09 2pp 15565 358 24% Fiche 50-4(3,82/09/22,8210010131

- --8210220471 IE Insp Repts 50-413/82-24 & 50-414/82-22 on 820826-0910 N noncompliance noted Major areas inspected review of nonconforming items & followup of IE circulars VANDOORN. D K., BRYANT, J C. Division of Project & Resident Programs 82/09/28 3pp 15779 IIB 24X Fiche 50-413,82/09/29,8210220467
- 8208190233 IE Info Notice 80-35, Suppl 1, "Leaking & Dislodged 1-126 Implant Seeds " Svc list onc! COBB.L I Division of Fuel Facilities, Materials & Bafeguards 82/10/06 Consolidated Edison Co of New York 64pp 1576/250 244 Fiche 50-000, 82/10/06, 8208190233
- 8210220134 Ack receipt of 1E Insp Repts 50-413/82-22 \$ 50-414/82 20 H_a proprietory info TUCKER, H 0 Duke Power Co B2/10/08 G'REILLY, J P Region 2, Orfice of Director 1p 15778 114 24X Fiche 50-413.82/10/08, 8210220134
- 0208170238 IE Bulletin 82-03. "Stress Corrosion Cracting in Thick-Wall, Large-Diameter, Stainless Steel, Recirculation Sys Piping at BMR Plants " Svc list end! DEYQUMO, R C Director's Office, Office of Inspection and Enforcement 82/10/14 Consolidated Edison Co of New Yorl 118pp 15810 125 24X Fiche 50-000.82/10/14.8208190238
- S Reportable occurrences, LERs & related correspondence
- 8210080208 Significant Deficiency Rept SD 413-414/82-18 re radiographic exams not performed on flux core wailding filter matt ordered to SFA 5 20 Initially reported on 820703 Vendor committed to radiograph all matts Action to be completed by 830301 UCKER.H B Duke Power Co 82/10/01 0/REILLY, J.P. Region 2, Office of Director 3pp 15640 086 24X Fiche 50-413,82/10/01.
- 8210270119 Significant Deficiency Rept SD 413/82-17 re linear indications identified on Kerntest valve body 90-551 on 820819 Initially reported on 820909 Valve returned to manufacturer Final rept will be submitted by 821108 TUCKER.H B Duke Power Co 82/10/08 O'REILLY, J.P. Region 2, Office of Director 2pp 15854 024 24% Fiche 50-413,82/10/00,8210290119
- 8210290354 Significant Deficiency Rept SD 413-414/82-20 re inappropriate governor drive matl coupling supplied for diesel generator Initially reported on 820708 Manufacturer recommends replacement w/neoprene matl TUCKER.H II Duke Power Co 82/10/08 O'REILLY.J P Region 2, Office of Director 3pp 15853 040 24X Fiche 50-413,82/10/08.
- 8210290250 Significant Deficiency Rept 413-414/B2-11 re-potential failure to activate safeguards sys due to possible failure of switch contacts shunting proving lamp Revision to solid state protection sys will be made by Westinghouse TUCKERSH B Duke Power Co. 82/10/20 GRELLLY. J.P. Region 2. Orfice of Director 3pp 15854 096 24X Fiche 50-413.82/10/20.
- T Hearing transcripts on non-antitrust matters
- 8210130207 Transcript of 821007 prehearing conference in Charlotte, KC Pp 380-567 * Atomic Safety and Licensing Board Panel 82/10/07 188pp 19673 272 24X Fiche 50-413.82/10/07.8210130207
- 8210130238 Transcript of 821008 prehearing conference in Charlotte, NC Pp 548-455

 * Atomic Safety and Licensing Board Panel 82/10/08, 88pp 15675 124 24X Fiche 50-413, 82/10/08, 8210130238
- V Operator Examinations

Ł

8210260065 Bummary of 820909 meeting w/util in Cornelius, NC re cold license exam scheduls HILBON, B. A. Division of Engineering & Technical Programs JABBOUR, K. N. Licensing Branch 4 82/10/01 Division of Engineering & Technical Programs 21pp 15810 340 24X Fiche 50-413, 82710/01.8210260065

- DOCKET 50-414 CATAMBA NUCLEAR STATION, UNIT 2

 A Application/construction stage documents & correspondence
- 8210010008 Responds to FDIA request for 19 categories of documents re nuclear reactor events & safety problems Forwards documents listed in App A FELTON, J M Division of Rules and Records 82/06/28 UDELL.R A Critical Mass Energy Praject 15pp 15727 005 24X Fiche 50-000.82/06/28,8210010008
- --8008090265 Discusses addi required info to better define potential for cracking in reactor vessel noizles
 NOUNAN,V S Assistant Director for Materials & Qualifications
 Engineering 80/05/05 TEDESCO.R L Assistant Director for
 Licensing 2pp 15727 176 24X Fiche 50-000,82/06/28,8210010000
- 8210050264 Forwards summary of 820406-07 meeting in Bethesda, MD & 820419-22 meeting in Charlotte, NC w/Mechanical Engineering Branch, Westinghouse & BNML relitoms in NRC 820129 ltr W/eight oversize drawings Aperture cards are in PDR 7UCKER, H B Duke Power Co. 82/09/27 DENTON, H R. Office of Nuclear Reactor Regulation. Director. ADENSAM, E. Q. Licensing Branch 4 343pp 15606-060 24% Fiche 50-413, 82/09/27, 8210050264
- 8210070092 Forwards minutes of meeting held during wk of 820419 u/Mestinghouse & Mechanical Engineering Branch discussing resolution of FSAR Item 109 re fuel damping values Minutes withheld (ref 10CFR2 790) TUCKER: H B Duke Power Co 82/09/28 DENION: H R Office of Nuclear Reactor Regulation, Director ADENBAM: E Q Licensing Branch 2pp 15628 079 24% Fiche 50-413.82/09/28,8210070092
- 8210050384 Forwards revised FSAR pages reflecting organizational changes to changes to Chapter 13 Changes will be included in Revision 7 to FSAR
 TUCKER.H B Duke Power Co 82/09/29 DENTON.H R Office of Nuclear Reactor Regulation, Director ADENSAM.E G Licensing Branch 4 28pp 13408 281 24X Fiche 50-413.82/09/29.8210050384
- B2:0198071 Notification of 82:006 meeting w/util in Charlotte,NC to discuss matts design General Design Criterion 5! JABBOUR,K N Licensing Branch 4 B2/09/29 ADENSAM,E Q Licensing Branch 4 3pp 15761 095 24% Fiche 50-413,82/09/29,82:0190071
- BR10060311 Informs that review of plant operations relative to void formation in vessel head during transients completed Assessment of facility procedures in training program per Ceneric Ltr BI-21 and TUCKER: H 5 Duke Power Co BR209730 DENTON: H R Office of Nuclear Reactor Regulation. Director ADENSAM: E Q Liceneing Branch 4 App 15619 170 24X Fiche 50-413.82/09/30.82/0060311
- 9210150094 Application for Amend 28 to CPPR-116 & CPPR-117, consisting of Revision A to FBAR & Revision I to license application FUCKER. H B Duke Power Ca B2/10/12 DENTON. H R Office of Nuclear Reactor Regulation. Director 22pp 15699 001 24X Fiche 50-413, 82/10/12, 8210150094
- 8210220026 Summary of B20907-09 site visit & meetings w/util re Instrumentation & Control Sys Branch concerns & open items Responses to open items will be provided by end of Oct 1982 Summery & status of concerns & open items encl JABBOUR.K N Licensing Branch 4 82/10/15 Licensing Branch 4 9pp 15786 292 24X Fiche 50-413.82/10/15.8210220026
- 8210260201 Revises WD Parker 820701 ltr re schedule for submission of info needed to resolve concerns identified in D0 Eisenhut 801222 ltr & NUREO-0612 Info requested in Sections 2 2 & 2 4 of Encl 2 to be submitted by 821124

 TUCKER: H B Duke Power Co 82/10/21 DENTON: H R Office of Nuctear Reactor Regulation, Director ADENSAM.E Q Licensing Branch 4 1p 15804 271 24X Fiche 50-413,82/10/21.8210260201
- D NRC Draft/Final Environmental Statements, suppls & correspondence
- 8210040322 Comments on historic & archeologic impacts, water quality, entrainment thermal discharge & post-operational monitoring discussions in DES BLANCHARD, B Interior, Dept of 82/09/30 ADENBAM, E Q Licensing Branch 4 3pp 15586 195 24X Fiche 50-413, 82/09/30, 8210040322
- B210130117 Advises that DEB is rated LO-1.Normal operation of facility will not have significant impact on environ No addl info needed MOCRE.8 N. Environmental Protection Agency B2/10/06 JUBBOUR.K N Division of Licensing 2pp 15673 007 24X Fiche 50-413.82/10/06.8210130117

- 8210130487 Forwards comments on DES (NUREC-0921) re operation of facilities LOCHSTET.W A Pennsylvania State Univ 82/10/06 Division of Licensing 7pp 19682 140 24% Fiche 50-413,82/10/06,821013048/
- 8210130506 Comments on DES List of water users in downstream order, to be concluded in FES, enci TURNER, L.C. South Carolina, State of 82/10/07 JABBOUR, K.N. Division of Licensing 3pp 15682 253 24X Fiche 50-413,82/10/07, 8210130506
- 8210250102 Forwards comments on DEG.per LOCFR51 TUCKER,H B Duke Power Co B2/10/07 DENTON,H R Office of Nuclear Reactor Regulation, Director E19ENRUT.D Q Licensing Branch 4 14pp 1579 171 24X Fiche 50-413,82/10/07,8210250102
- 8210180106 Advises that review of DES for facility has been completed Clearance valid for 1 yr CROMER.D.L. South Carolina, State of 82/10/08 Office of Nuclear Reactor Regulation, Director &p 15719 318 24X Fiche 30-413,82/10/08,8210180106
- 8210180169 Comments on DES (NUREG-0921) & public health & safety impacts of proposed plant operation VILLEGATH, JC Food & Drug Administration 82/10/12 JABBOUR, K & Division of Licensing 2pp (5719 166 24% Fiche 50-413,02/10/12, P210180169
- 8210260150 Requests encl comments on DES be transmitted to appropriate NRC ofc DES summary of cost/benefit in Table 6 1 deficient RILEY, J L Carolina Environmental Study Group 82/10/22 JABBOUR, K N Division of Licensing 3pp 15/99 015 24X Fiche 50-413, 82/10/22,8210260150
- E NRC Safety Evaluation Report (SER), suppls & correspondence
- 8210280065 Forwards responses to nine items in EQ Adenson 820609 1tr re auxiliary feedwater sys.per draft SER. Section 7 1 3 i TUCKER. H B Duke Power Co 82/10/19 DENTON, H R Office of Nuclear Reactor Regulation, Director ADENSAM, E Q Licensing Branch 4 9pp 13837 263 24X Fiche 50-413,82/10/19.8210280365
- F Security, medical, emergency & fire protection plans
- B209170053 Forwards Revision 3 to security plan Revision withheld (ref 10CFR73 21) TUCKER, H B Duke Power Co 82/08/18 DENTON, H R Office of Nuclear Reactor Regulation, Director ADENSAM, E G Licensing Branch 4 2pp 14910 095 24% Fiche 50-413, 82/08/18, 8209170053
- 6210190611 Responds to 810723 request for schedule for installation of public notification sys at facilities Final design of sys & schedule for installation not finalized Info submittal anticipated by 821201
 TUCKER.H B Duke Power Co 82/10/08 DENTON.H R Office of Nuclear Reactor Regulation. Director ADENSAM, E Q Licensing Branch 4 NEWTON.F Federal Emergency Management Agency 2pp 19737 221 24X Fiche 50-413.82/10/08.9210190611
- Q Adjudicatory correspondence
- 8210050202 Response opposing Palmetto Alliance & Carolina Envi Group 820922 supplemental petitions to intervene MCGARRY, J M Duke Power Co MCGARRY, J M Debevoise 82/10/04 Atomic Safety and Licensing Board Panel 15602 279 24X Fiche 50-413,82/10/04.8210050202
- --8210050208 Response to Charlotte-Mecklenberg Environ (
 revised Contention 4 Contention acceptable Notice of
 appearance & Certificate of Svc enc;
 MCOARRY, J M Duke Power Co MCOARRY, J M Debevoi:
 82/10/04 Atomic Sefety and Licensing Board Panel
 1502 350 24% Fiche 50-413, 82/10/04,8210050202
- 8210060191 Statement of position on DES contentions Objet Palmetto Alliance/Carolina Environ Study Group contentions as specified Certificate of Svoter JUHNSON: Q E Hearing Branch 4 82/10/04 Atomic E Licensing Board Panel 26pp 15613 264 24X Fiche t 8210060191
- 8210080081 Motion to compel util to respond to Palmetto 820703 second set of interrogatories & requests to pro Certificate of Byc encl QUILD,R: Palmetto Alliance QUILD,R Quild, R. 82/ Atomic Befety and Licensing Board Panel 5pp 15640 Fiche, 50-413, 82/10/04,8210080081

JUUILLED HEITIU

- 8210180182 Order extending time until 821112 for Commission to act to review ALAB-687 CHILKS J Office of the Secretary of the Commission 82/10/14 Commissioners ip 15719 134 24% Fiche 50-413.82/10/14 R210180182
- 6210200071 Provides response to ASLB questions at 821007-08 second special prehearing conference Questions relate to risks from McGuire facility & scope of evacuation costs listed in DES Table 5 II JOHNSON, GE Hearing Branch 4 82/10/18 KELLEY, J L , FOSTER, R F , CALLIHAN, D Atomic Safety and Licensing Board Panel 2pp 15757 192 24x Fiche 50-413,82/10/18.8210200071
- 8210210187 Motion for order to protect NRC from answering Palmetto Alliance Interrogatories (\$ 36 on Contention 8 & Interrogatory 1 on Contention 27 Requests are for large amount of nat) u/o regard to relevance
 JOHNSON O E Hearing Branch 4 82/10/19 Atomic Safety and Licensing Board Panet | 3pp | 15765 159 | 24X Fiche 50-413.82/10/19, 8210210187
- --B21021019/ Responses to second set of interrogatorses & requests to produce re Palmetto Alliance Contentions 8 & 27 Prof qualifications, NUREG/CR-2644 & Certificate of Svc enct JUH/SOUNG E Hearing Branch 4 B2/10/19 Palmetto Alliance 134pp 15765 162 24% Fiche 50-413,82/10/19,8210210187
- 8210250125 Pesponses to Palmetto Alliance 820927 third set of interrogatories & requests to produce Related correspondence CARR.A V Duke Power Co 82/10/19 Palmetto Alliance 62pp 15787 243 24x Fiche 50-443.82/10/19,8210250
- 8210250282 Motion for protective order relieving applicants from requirement to respond to Palmetto Alljance 820927 third set of interrogalories ? requests to produce Certificate of Svc encl Related correspondence CARR.A V Duke Power Co 82/10/19 Atomic Safety and Licensing Board Panel 4pp 15791 078 24X Fiche 50-413.82/10/19.8210250282
- 8210250370 Forwards EIA re spent fuel storage of Oconee spent fuel at McGuire Unit [spent fuel pool, dtd Dec 1978 Copies also sent to intervenors W/o encl JOHNSOV.G E Hearing Branch 4 82/10/21 KELLEY.J L , FOSTER.R F , CALLIHAN.D Atomic Safety and Licensing Board Panel ip 15790 188 24X Fiche 50-413.82/10/21.8210250370
- 8210260415 Answer opposing Palmetto Alliance 821004 motion to compel answers to interrogatories ASLB should issue order denying motion as lacting merit Motion devaid of supporting arguments Certificate of Svc encl CARR.A V Duke Power Co 02/10/22 Atomic Safety and Licensing Board Panel 20pp 15806 115 24x Fiche 50-413,82/10/22.
- 8210270002 Answers ASLB question re Palmetto Alliance/Carolina Environ Study Group Contention II DES totaled risks to gublic of accidents from each unit JONNSON. 0 E Hearing Branch 4 62/10/25 KELLEY. J. C. FOBTER, R. F. CALLIMAN. D. Atomic Safety and Licensing Board Panel 1p 15817 011 24% Fiche 50-413.62/10/25, 8210270002
- 8210270010 Advises that NRC does not intend to file response to Palmetto Atliance 821004 motion to compel discovery from applicants NRC responded to requests on 821019

 JOHNSON, G E Hearing Branch 4 82/10/25 KELLEY, J L , FOSTER, R F , CALLIHAN, D Atomic Safety and Licensing Board Panel 1p

 15822 340 24% Fiche 50-413,82/10/25,8210270010

at NRC continue to send e Since McGuire equest denied B RILEY.J L Carolina 24X

- K Utility Final Safety Analysis Report (FBAR) & amends
- 8210150094 Application for Amend 28 to CPPR-116 & CPPR-117, consisting of Revision 6 to FBAR & Revision 1 to license application TUCKER, H B Dute Power Co B2/10/12 DENTON.H R Office of Nuclear Reactor Regulation, Director ADENBAM, E 0 Licensing Branch 4 22pp 15699 001 24% Fiche 50-413,82/10/12,8210150094
- --8210150101 Revision 6 to FSAR • Duke Fower Co 82/10/12 761pp 15699 023 24X Fiche 50-413,82/10/12.8210150094

- Q Inspection reports. IE Bulletins & correspondence
- 8210080015 Addl response to FOIA request for 19 categories of info to nuclear reactor events & safety problems Forwards documents listed in App A Documents in App B completely withheld (ref FOIA Exemption 5)
 FELTON.J M Division of Rules and Records 82/07/12 UDELL.R A Critical Mass Energy Project 7pp 15665 027 24X
 Fiche 50-000, 82/07/12, 8210080015
- --8210080156 Systematic assessment of licenses performance notes re facility evaluation for Sept 1979-Aug 1980 • NRC - No Detailed Affiliation Given 80/08/31 Spp 15668 057 24X Fiche 50-000, 82/07/12.8210080015
- 8210010106 Forwards IE Insp Repts 50-413/82-22 & 50-414/82-20 on 820824-27 No noncompliance noted DANCE: H C Division of Project & Resident Programs 82/09/13 TUCKER: H R Duke Power Co 2pp 15567 194 24X Fiche 50-413, 82/09/13, 8210010106
- --8210010110 IE Insp Repts 50-413/82-22 & 50-414/82-20 on 620824-27 h; noncompliance noted Major areas inspected independent inspecffort-review of quality records for containment structures & supports & inservice review of program COLEY.J L. BLAKE.J J Division of Engineering & Technical Programs 62/09/09 (Opp 15567 196 24X Fiche 50-413,82/09/13 8210010106
- 9210010131 Ack receipt of 920907 ltr informing NRC of steps taken to correct visualitions noted in (E Insp Repts 50-413/82-16 & 50-414/82-16 LEMES, R C Division of Project & Resident Programs B2/09/22 TUCKER, H B Duke Power Co 1p 15565 351 24X Fiche 50-413, 82/09/22, 8210010131
- --8210010134 Responds to NRC 820809 ltr re violations noted in It Insp. Repts 50-413/82-18 & 50-414/82-14 Corrective actions matis personnel training will be completed by 820915 & paint storage warehouse will be upgraded by 821015 TUCKER.H II Duke Power Co 82/09/07 O'REILLY.J P Region 2. Office of Director 4pp 15565 332 24X Fiche 50-413.82/09/22.
- --821001013B Forwards IE Insp Repts 50-413/82-18 & 50-414/82-16 on 820712-16 & notice of violation LEWIS.R C Division of Project & Resident Programs 82/08/09 TUCKER:H D Duke Power Co 2pp 15565 356 24X Fiche 50-413.82/09/22.8210010131
- --8210010141 Notice of violation from insp on 820712-16

 * Division of Project & Resident Programs 82/08/09
 15565 358 244 Fiche 50-413,82/09/22,9210010131
- --8210010143 IE Insp Repts 50-413/82-18 & 50-414/82-16 on 820712-16 Noncompliance noted failure to initiate nonconforming team item repts re coatings storage temps & failure to conduct civil work activities surveillances WRIGHT, R W , DEBBAGE, A C , UPRIGHT, C M Division of Engineering & Technical Programs 82/08/06 11pp 15565 360 24% Fiche 50-413,82/09/22,8210010131
- 8210150069 Ack receipt of IE Insp Repts 50-413/82-20 & 50-414/82-18
 No proprietary info
 TUCKER.H B Duke Pawer Co 82/09/24 O'REILLY, J P Region 2,
 Office of Director 1p 15696 348 24X Fiche 50-413.82/09/24,
 8210150068
- 8210220467 Forwards IE Insp Repts 50-413/82-24 & 50-414/82-22 on 820826-0910 No noncompliance noted DANCE, H C. Division of Project & Resident Programs 82/09/29 TUCKER, H B Date Power Co 2pp 15779 116 24X Fiche 50-413, 82/09/29, 8210220467
- --8210220471 IE Insp Repts 50-413/82-24 & 50-414/82-22 on 820826-0916 to noncompliance noted Major areas inspected review of honcomforming items & followup of IE circulars VANDOORN. D K . BRYANT. J C Division of Project & Resident Programs B2/09/28 3pp 15779 ii8 24X Fiche 50-413.82/09/29.8210220467
- 8208190233 IE Info Notice 80-35, Buppl 1, "Leaking & Dislodged 1-125 Implent Seeds " Svc list encl. COBB.L 1. Division of Fuel Facilities, Materials & Bafeguards 82/10/06 Consolidated Edison Co of New York 66pp 15761 250 24X Fiche 50-000 82/10/06,8208190233
- 8210220134 Ack receipt of IE Insp Repts 50-413/82-22 & 50-414/82-20 % proprietary info TUCKER.H B Duke Power Co 82/10/08 O'REILLY, J P Region 2. Office of Director ip 15778 114 24X Fiche, 50-413,82/10/09, 82/10/20134

- 8208190238 IE Bulletin 82-03. "Stress Corrosion Cracking in Thick-Wall, Large-Diameter, Stainless Steel, Recirculation Sys Piping at BWR Plants " Svc list encl
 BEYQUNO.R C Director's Office. Office of Inspection and
 Enforcement 82/10/14 Consolidated Edison Co of New
 115pp 15810 125 24% Ficha 50-000.82/10/14,8208190238 Consolidated Edison Co of New York
- 5 Reportable occurrences, LERs & related correspondence
- 8210080208 Significant Deficiency Rept SD 413-414/82-18 re radiographic exams not performed on flux core welding filler math ordered to SFA 5 20 Initially reported on 820903 Vendor committed to TUCKER, H B Duke Power Co 82/10/01 D'REILLY, J P Region 2, Office of Director 3pp 15440 086 24X Fiche 50-413,82/10/01.
- 8210290354 Significant Deficiency Rept SD 413-414/82-20 re inappropriate governor drive matt coupling supplied for diesal generator Initially reported on 820708 Manufacturer recommends replacement w/neoprene matl TUCKER, H B Duke Power Co 82/10/08 D'REILLY, J P Region 2, Office of Director 3pp 15853 040 24X Fiche 90-413,82/10/08,
- 8210290250 Significant Deficiency Rept 413-414/82-11 re potential failure to activate safeguards sys due to possible failure of switch contacts, shunting proving lamp Revision to solid state protection sys will be made by Westinghouse TUCKER. H D Duke Power Co 92/10/20 O'REILLY, J P Region P. Office of Director 3pp 15854 096 24% Fiche 50-413,82/10/20. 8210270250
- T Hearing transcripts on non-antitrust matters
- 8210130207 Transcript of 821007 prehearing conference in Charlotte NC Pp 380-567 * Atomic Safety and Licensing Board Panel 82/ 15673 272 24X Fiche 50-413,82/10/07,8210130207 82/10/07 188no
- 8210130238 Transcript of 821008 proboaring conference in Charlotte. NC Pp 568-655

 * Atomic Bafety and Licensing Board Panel 82/1
 15675 126 24X Fiche 50-413,82/10/08.8210130238 82/10/08 68pp
- V Operator Examinations
- 8210260065 Bummary of 820909 meeting w/ctil in Cornelius.NC re cold license exam schedule MULSON, B A Division of Engineering & Technical Programs
 JABBOUR, K N Licensing Branch 4 82/10/01 Division of
 Engineering & Technical Programs 21pp 15810 340 24X
 Fiche 50-413, 82/10/01,8210260065
- DOCKET 50-416 GRAND QULF NUCLEAR STATION, UNIT 1 E NRC Safety Evaluation Report (SER), supple & correspondence
- 8210190566 Advises of completion of thermocouple qualification testing per SER Buppl 3 Thermocouples considered qualified for seimic & hydrodynamic loads including variable pool swell final test rept will be reviewed upon receipt DALELL F Mississippl Power & Light Co 82/10/14 DENTON:H R Office of Nuclear Reactor Regulation. Director 2pp 19736 133 24X Fiche 50-416.82/10/14,8210190566
- 8210200064 Forwards comments & status of util review of DL & SER Info provided to assist in generation of fourth suppl to SER & full power OL DALE.L F Mississippi Power & Light Co 82/10/14 DENTON,H R Office of Nuclear Reactor Regulation, Director 54pp 15756 153 24X Fiche: 50-416,82/10/14,8210200064
- 82i0200005 Forwards outline of in situ test for HPCS standby svc water pump flow induced vibration Test will be performed prior to startup following first refueling outage Commitment to conduct test resolves BER Suppl 2. Section 3 io concerns DALG/L F Mississippi Power & Light Co 82/10/18 DENYON, H R Office of Nuclear Reactor Regulation, Director 7p 15754 341 24X Fiche. 50-416.82/10/18.8210200005
- 8210200030 Forwards evaluation of valve disc pin overstressing, addressing concerns & closing supplemental SER 2, Section 22 2 (Issue II E 4.2). "Purge Valve Operability"

 DALGL F Mississippi Power & Light Co 82/10/18 DENTON, H R Office of Nuclear Reactor Regulation, Director 7pp 15757 19/24X Fichs 30-416/82/10/18, 8210200030

- 8210200073 Forwards info re monitoring trend analysis program per commitment to summarize vibration monitoring analysis program for deep draft pump reliability per SER Section program for deep draft young 100 (13)

 DALE, L. F. Hississippi Power & Light Co. 82/10/18 DENTON, H.R.

 Office of Nuclear Reactor Regulation, Director 2pp. 15754 13:

 24X Fiche 50-416, 82/10/18, 8210200073
- 8210220425 Forwards addl info is qualification of hydraulic control units affected by variable pool swell loads Test response spectra-required response spectra companisons should be sufficient to close concern in SER Suppl 3, Section 3 10 DALE, t. F. Mississippi Power & Light Co. 82/10/19 DE DALE, L. F. Mississippi Pawer & Light Co. B2/10 Office of Nuclear Reactor Regulation. Director 24X Fiche 50-416, 82/10/19, 8210220425 DENTON H R 7pp 15779 15J
- F Security, medical, emergency & fire protection alans
- 82(0150013 Responds to nuncompliance re emergency accountablility noted in IE Insp Rept 50-414/82-27 Interpretion of "onsite" questionable Other utils make same distinction of site poundary being same as protected area

 DALE, L.F. Mississippi Power & Light Co. 82/07/19 0'REILLY.J ()
 Region 2. Office of Director 2pp. 15698 346 24X
 Fiche 50-446.82/07/19, 8210150013
- 8210070040 Releases public version of corrections to emergency action level table FELTON.J M Division of Rules and Records 82/09/17 Docum Management Branch 1p 15646 341 24% Fiche 50-416.82/09/17. 8210070040
- --8210D70044 Forwards public version of corrections to Table 4-1 ro emergency action levels in response to NRC questions on Revision 6 to emergency plan Encl changes will be incorporated into plan by 821031 DALE.L F Mississippi Power & Light Co 82/09/09 DENTON.H R Office of Nuclear Reactor Regulation. Director 2pp 15646 345 24X Fiche 50-416,82/09/17.8210070040
- --8210070048 Public version of corrected Table 4-1 re emergency action levels Initial & final notification forms encl
 4 Mississippi Pawer & Light Co 82/09/09 App 15646 345 P4X
 Fiche 50-416.82/09/17.8210070040
- 8210010234 Forwards Revision 5 to physical security plan Revision withheld (ref 10CFR2 790)

 MCGAUGHY, J.P. Hississippi Power & Light Co. 82/07/22 DENTCH. II R

 Diffice of Nuclear Reactor Regulation, Director 2pp. 15574 060

 24X Fiche 50-416, 82/09/22, 8210010234
- 6210010023 Requests delay in implementation of emergency response facility Facility will be structurally complete by 621001 commitment date, but several important sys will not yet be installed Schedule should be developed between NRC b util DALE, L. F. Mississippi Pawer & Light Co. 82/09/29 DENTON. H R DALE.L F Mississippi Pawer & Light Co dezov Dffice of Nuclear Reactor Regulation. Director 24% Fiche 50-416,82/09/29,8210010023 Эрр
- O Adjudicatory correspondence
- 8210040115 Order granting State of I time to respond to ASLB 820631 or applicant arguments due 921011 No uill be granted LAURENSON J A Atomic Safety and Louisiana, State of 3pp 1598 8210040115
- 8210150462 Brief supporting State of participate as interested state Gountimely petition Certificate of S LINDSEY, I D Louisiana, State of LINDSEY, I D. Louisiana, State of E Licensing Board Panel Sipp 157 8210150462
- 8210210393 Memorandum & order denuar 210210393 Memorandum & order denuir intervention ASLB unable to consic in proceeding Commission retained to grant full power OL LAURENSON.J A , BRIGHT.O Q , HARDC Board Panel 82/10/20 Louisia 24X Fichs 50-416,82/10/20,82102105

- D Advisory Committee on Reactor Safeguards reports & correspondence
- 8208290018 Summaries 268th ACRS meeting on 820812-14 in Washington.DC refull power QLs for Grand Gulf I & Watts Bar I & II. systematic evaluation & integrated reliability assessment of Ginna & control room habitability SHEMMON P ACRS Advisory Committee on Reactor Safeguards 82/08/06 PALLADING.N J Commissioners 3pp 15649 233 24X Fiche 50-000.82/08/26.820829018
- E2(02703B0 Summary of ACRS Grand Gulf Subcommittee 820B11 meeting in Washington.DC re DL review * ACRS - Advisory Committee on Reactor Safeguards 82/09/09 ACRS - Advisory Committee on Reactor Safeguards 16pp 15834 302 24/
- P Operating license stage documents & correspondence
- 8210130024 Forwards Amend 3 to License NPF-13, safety evaluation & notice of issuance & availability Amend grants add) one-time Tech Spec exceptions for Phase I operations & changes to Tech Specs re valves & stroke times EISEMMUT.D G Division of Licensing 82/09/20 MCGAUGHY, J P Missispip Power & Light Co 3pp 15492 312 24X Fiche 50-414, 82/09/20.8210130024
- --8210130029 Amend 3 to License NPF-13 granting addl one-time Tech Specezoceptions for Phase I operation & changes to Tech Specs re valves & stroke times
 EISENHUT.D G Division of Licensing 82/09/20 16pp 15692 315
 24X Fiche 50-416.82/09/20.8210130024
- --8210130038 Safety evaluation supporting Amend 3 to License NPF-13 4 Office of Nuclear Reactor Regulation. Director 82/09/16 3pp 15572 326 24% Fiche 50-416.82/09/20.8210130024
- --8210130043 Notice of issuance % availability of Amend 3 to Licensu NPF-13 SCHWENCER.A Licensing Branch 2 82/09/20 3pp 15692 329 249 Fiche 50-416.82/09/20.8210130024
- 8210220032 Advises that postponement of associated startup test acceptable Recirculation flow control test under cold plant conditions should be deleted SCHWENCER. A Licensing Branch 2 82/09/28 MCGAUGHY, J P Mississippi Power & Light Co 2pp 15786 283 24% Fiche 50-416, 82/09/28, 8210220032
- 8210040053 Advises of delay in response to Humphrey concerns recontainment issues pending 821001 conference discussion w/GE on local encreachments.Action Plans 1-4 Commitment based on 820729 telcon w/Containment Sys Branch DALE.L F Mississippi Pawer & Light Co 82/09/30 DENTON.H R Director Nuclear Reactor Regulation, Director 1p 15581 307 24X Fiche 50-416.82/09/30.8210040053
- B210040264 Discusses independent design review per License Condition 2 C(43) Design verification program to provide addiasurance that design & constactivities meet 10CR30, App B requirements will be performed by Cygna Energy Svcs DALE, L.F. Mississippi Power & Light Co. B2/09/30 DENION, H.R. Office of Nuclear Reactor Regulation, Director 2pp 15595 001, 24% Fiche 50-416.82/09/30, 8210040264
- 8210040353 Forwards responses to 820826 request for add1 info re Items 1-8,including current status & submittal schedule for outstanding items IF Plunkett prof qualifications enc! DALELC F Mississippi Power & Light Co 82/09/30 DENTON,H R Office of Nuclear Reactor Regulation, Director 8pp 15593 348 24% Fiche 50-416.82/09/30,8210040353
- 8210060295 Responds to request for add1 info re HPC8 svc water pump Add1 testing or mod not required Suggests meeting w/Equipment Qualification Branch to discuss evaluation results on 821008 in Bethesda, MD DALE, L.F. Mississippi Power & Light Co. 82/10/04 DENTON, H.R. Office of Nuclear Reactor Regulation, Director 4pp. 15619 305 24% Fiche 50-416,82/10/04,8210060295
- 8210260264 Advises that util will reissus plant emergency operating procedures in accordance w/INPO writer guide & Revision 2 of BWR owners group emergency planning guidelines Revised procedures to be submitted by 821027

 PALEL F Mississippi Power & Light Co 82/10/12 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 15803 031 24X Fiche 50-446.82/10/12.8210260264

- B210190921 Provides info in response to Human Factors Engineering Branch 820913 informal request ro meeting human performance environ conditions in plant remote shutdown panel area DALE, L. F. Mississippi Power & Light Co. B2/10/14 DENTON, H. R. Office of Nuclear Reactor Regulation. Director 2pp 1975; 236 24X Fiche 50-416, B2/10/14, B210190521
- 8210210217 Bubmits add1 info re design & testing of automatic depressurfication sys air sys.including response to NUREG-0737. Item II K 3 28. air sys testing & air sys makeup provisions Revision to FSAR Subsection 18 i 30 i2 encl DALEIL F Mississippi Power & Light Co 82/10/18 DENION, H R Office of Nuclear Reactor Regulation. Director 3pp 15766 340 24X Fichs 50-416, 82/10/18, 8210210217
- B210260412 Requests that License Condition 2 C (44)(i)(a) be revised to require submittal re automatic depressurization sys logic mods by 821215 Previous submittal date of 821027 erroneously requested due to revised BWR owners group schedule DALELL F Mississippi Power & Light Co 82/10/21 DENTON, H & Office of Nuclear Reactor Regulation, Director 2pp 15803 10/24X Fishe 50-416,82/10/21,8210260412
- 8210270277 Forwards add1 info re containment design, in response to J Humphrey questions Status rept per util 820715 ltr & GE proprietery info encl Proprietary info withheld Affidavit & 11 oversize drawings encl Aperture cards are in PDR DALE.L F Mississippi Power & Light Co 82/10/22 DENTON.H R Office of Nuclear Reaction Regulation. Director 82pp 15852-199 24% Fiche 50-416.82/10/22.8210270277
- 8210280135 Provides addl responses to NRC concerns re adequacy of onsite communication sys in areas exhibiting high ambient noise levels, use of 2-way radio sys & work stations requiring communications w/control room or shutdown panel DALE.L F Mississippi Power & Light Co 82/10/26 DENION.H R Office of Nuclear Reactor Regulation, Director 3pp 15837 130 24X Fiche 50-416, 82/10/26, 8210280135
- B210290102 Outlines commitments made during B21025 telcon re design k testing of automatic depressorization air sys Integrated leak test on sys will be performed every 18 months Justification for interim operation listed DALELL F Mississippi Power & Light Co B2/10/26 DENTON.H R Office of Nuclear Reactor Regulation. Director 2pp 15854 001 24X Fiche 50-416.82/10/26,8210290102
- Q Inspection reports, IE Bulletins & correspondence
- 8210130013 Responds to noncompliance re emergency accountability noted in IE Insp Rept 50-416/82-27 Interpretion of "onsite" questionable Other utils make same distinction of site boundary being same as protected area DM.E.L F Mississippi Power & Light Co 82/07/19 O'REILLY, J Region 2. Office of Director 2pp 15698 346 24% Fiche 50-416.82/07/19.8210150013
- 6210010442 Forwards IE losp Regts 50-416/82-61 & 50-417/82-13 on 820817-20 No noncompliance noted VERRELLI, D.M. Division of Project & Resident Programs 82/09/03 STAMPLEY, N.L. Mississippi Power & Light Co. 2pp 15570 175 24X Fiche 50-416,82/09/03.8210010442
- --B210010447 IE Insp Repts 50-416/82-61 & 50-417/82-13 on 820817-20 % noncompliance noted Major areas inspected const deficiency repts for Unit 1 & observation of safety-related piping work activities at Unit 2
 BLAKE.J. J. Division of Engineering & Technical Programs 62/09/02 4pp 15570 177 24X Fiche 50-416, B2/09/03, 8210010442
- 8210010148 Forwards IE Insp Rept 50-416/82-63 on 820815-18 No noncompliance noted VERRELLI, D M Division of Project & Resident Programs 82/09/07 STAMPLEY, N L Mississippi Power & Light Co 2pp 15570 334 241 Fiche 50-416, 82/09/07, 8210010148
- --82:00:10:15) IE Insp Rept 50-416/82-63 on 8208:15-18 No nencompliance noted Major areas inspected open vessel criticality & associated tests
 BURNETT-P T , VOOT-LOWELL, R , JAPE, F Division of Engineering & Technical Programs 82/09/03 4pp, 15570 356, 24X
 Fiche 50-416,82/09/07,8210010148

- 150005 Ack receipt of 820831,0907 & 20 ltrs informing NRC of steps ten to correct violations noted in IE Insp Rept 414/82-55
- o Division of Project & Resident Programs 82/09/24 L Mississing: Power & Light Co ip 15696-314 AMPLEY N L MPLEY, N L Mississippi Power & Light Co ip he 50-416, 82/09/24, 8210150005
- O1500i1 Suppls 820831 response to NRC 820730 ltr re violations noted n IE Insp Rept 50-416/82-55 Corrective actions Anubar nstallations will be identified as temporary alterations & laced under temporary alteration program (COAUGHY, J P Mississippi Power & Light Co 82/09/20 PREILLY, J P Region 2. Office of Director 2pp 15696 315 24% iche 50-416,62/09/24,8210150005
- 0150019 Supple 820831 response to NRC 820730 ltr re violations noted Olsgoly Supple B2041 response to NRC B20730 for reviole n IE Insp Rept 50-416/82-55 Corrective actions plant dministrative procedure will be revised to clarify emporary alteration program & delete use of chit log sys COAUGHY, J.P. Mississippi Power & Light Ca. B2/09/07 (REILLY, J.P. Region 2) Office of Director. 3pp. 15696 iche 50-416,82/09/24,8210150005
- 15696 317 24X
- DISO024 Responds to NRC B20730 ltr re violations noted in IC Insp ept 50-416/82-55 Corrective actions IOCFR50 59 evaluations erformed for temporary alterations & temporary alteration rocedure revised
- "REILLY, J P Mississippi Power & Light Co 82/08/31
 "REILLY, J P Region 2, Office of Director 2pp 15/11che 50-416.82/09/24.8210150005 15676 320
-)150027 Forwards IE Insp Rept 50-416/82-55 on 820616-0716 & notice
- 7 violation THIS.R C. Division of Project & Resident Programs 82/07/30 TAMPLEY.N L. Mississippi Power & Light Co. 2pp. 15446-322 Che 50-416,82/09/24.8210150005
- #150028 Notice of violation from insp on #20616-0716 Division of Project & Resident Programs #22/07/30 #676:324 24X Fiche 50-416, #2/07/24, #210150005 200
- 150002 IE Insp Rept 50-416/82-55 on 820616-0716 Noncompliance ted failure to perform safety evaluation for temporary terations to facility & failure to follow written
- , SCOTT.D E , CHABE.J W Division of Project & Resident 82/07/30 8pp 15696 326 24X Fiche 50-416.82/09/24. 0grams 10150005
- 0384 Ack receipt of 820907 ltr informing NRC of steps taken to ect violations noted in IE Insp Rept 50-416/82-55
 5.R G Division of Project & Resident Programs 82/09/24
 PLEV.N L Mississippi Power & Light Co ip 15704 048 24X s 50-416.82/09/24.8210150384
- 0233 IE Info Notice 80-35, Suppl 1, "Loaking & Distodged 1-125 ant Seeds " Syc list encl L I Division of Fuel Facilities, Materials & Safeguards 2004 Consolidated Edison Co of New York 66pp 1576 Tiche 50-000, 82/10/06.820819023
- 1238 IE Bulletin 82-03, "Stress Corrosion Cracking in Thick-Large-Diameter Stainless Steel Rocirculation Sys 1g at BMR Plants "Syc list encl NO.R C Director's Office, Office of Inspection and coment 82/10/14 Consolidated Edison Co of New York 15810 125 24X Fiche 80-000.82/10/14.8208190238
- 132 Forwards responses to Instrumentation & Control Bys Branch 4 questions re util evaluation of IE Info Notice 79-22. ification of Control Bys" & control sys failures Info C review available in NREO-0831
 L.F. Mississippi Power & Light Co 82/10/25 DENTON, H R e of Nuclear Reactor Regulation, Director 10pp 15837 120 ichs.50-416,82/10/25.8210280132
- odic operating reports & related correspondence
- 104 Forwards monthly operating rept for Bept 1782 OHY, J. F. Mississippi Power & Light Co. 82/10/14 DEYOUND, R C ctor's Office, Office of Inspection and Enforcement 2pp 309 24X Fiche 30-416,82/10/14,8210180104
- 30109 Monthly operating rept for Sept 1982 HARDBON, J.D. Mississippi Power & Light Co. it 19 311. 24X Fiche, 50-416, 82/10/14, 8210180104 82/10/15. 8pp

- S Reportable occurrences. LERs & related correspondence
- 821001800B Responds to FOIA request for 19 categories of documents re cludiouds Responds to 101A request for 17 categories of documents in the responsibilities of accuments listed in App A FELTON, J M Division of Rules and Records 82/06/28 UDE Critical Mass Energy Project 15pp 15727 005 24 Critical Mass Energy Project 1: Fiche 50-000, 82/04/28, 8210010008
- --8204210289 Forwards deficiency rept re failure of control rod drive hydraulic sys scram pilot valves Problems w/va'tage of reactor protection sys power supplies adequately addressed CHIRAMAL, M Director's Office 82/03/31 MICHELSON, C Director's Office 2pp &&Olf 190 24% Fiche 50-000.82/06/20.8210010008
- 8210080015 Add1 response to FOIA request for 19 categories of info is nuclear reactor events & safety problems Forwards documents listed in App A Documents in App B completely withheld (rof FOIA Exemption 5)
 FELTON, J M Division or Rules and Records 82/07/12 UDELLAR A Critical Mass Energy Project 9pp 15665 027 24X
 Fiche 50-000, 82/07/12, 8210080015
- --B2061101B6 Forwards review b evaluation of BWR scram pilot valve failures due to low voltage Aug 1981 event at facility reviewed Applicability of event to operating BWRs described HICHELSON. C Director's Office B2/06/01 DENTON. HR Offic Nuclear Reactor Regulation. Director DEVOUND. R C Director' Office, Office of Insection and Enforcement Spp 15666 137 24X Fiche 50-000.82/07/12.8210080015 DENTON.H R Office of WG.R C Director's Spp 15666 137
- 8210010243 Forwards LER 82-055/03L-0 MCGAUGHY, J P Mississippi Power & Light Co B2/09/27 D'REILLY, J P Region 2: Office of Director Ip 15548 284 Fiche 50-415. 82/09/27. 8210010243
- --8210010248 LER 82-055/03L-0 during 820829-0908, discharge basin flow trip channel inoperable Caused by approved alteration of trig circuitry to discharge glycol-contaminated water w/o normal dilution Trip circuitry restored after discharge SPARKS 0 L. Mississippi Power & Light Co. 82/09/27 Region d. Office of Director. 2pp. 15568-287, 24x Fiche 50-416.82/09/2/. 8210010243
- 8210050193 Forwards LER 82-047/03L-0 STAMPLEY, N L Hississippi Power & Light Co O'REILLY, J P Region 2, Office of Director Fiche 50-416, 82/09/28, 8210050193 82/09/28 15609 253 1 p
- ~-8210050203 LER 82-047/03L-0 on 820830, reactor vessel & head flange temps not monitored consistently Caused by mechanical group personnel failing to adhere to procedure Procedure under revision

 SPARKS. G.L. Mississippi Power & Light Co. 82/09/28 Region 2

 Office of Director 2pp. 15609-254 24X Fiche 50-416.82/09/20.

 8210050193 Region 2,
- 8210060201 Forwards LER 82-062/03L-0 MCOAUQHY, J.P. Mississippi Power & Light Co O'REILLY, J.P. Region 2, Office of Director Fiche 50-416, 82/09/29, 8210060201 82/09/29 10 15614 016

- 8210080120 Forwards LER 82-071/03L-0 MCGAUDHV.JP Hississippi Power & Light Co 82/10/04 O'REILLY JP Region 2. Office of Director 1p 15640 127 247 Fichs 50-416.82/10/09.8210080120
- 8210080127 LER 82-071/03L-0 on 820903, smoke detectors in fire zones 2-4 alarmed w/no fire of fumes present On 820929, detectors alarmed egain No cause stated Detectors cleaned BrRD-R Mississippi Power & Light Co 82/10/04 Region 2, Dfrice of Director Ip 15640 128 24X Fiche 50-416.82/10/04, 82/10/060120
- 8210080277 Forwards LER 82-069/03L-0 MCGAUGHY. J P Mississippi Power / Light Co 92/10/04 O'REILLY. J P. Region 2. Office of Director 1p 15638 298 24X Fiche 50-416.82710704.8210080277
- -8210089281 LER 82 069/03L-0 on 820703, supervisory alarm for fire door separating RHR A piping room & east passageway alarmed & would not clear Caused by out-of-adjustment door microsustich Switch adjusted & tested to assure operability ALBERT. J h Mississippi Power & Light Co 82/10/04 Region 2, Office of Director 1p 15638 299 24X Fiche 50-416.82/10/04, 8210080277
- 8210080282 Forwards LER 82-063/031-0 MCFAUGHY, J P Mississippi Power & Light Co 82/10/04 O'REILLY, J P Region 2, Office of Director 1p 15638 199 24X Fiche 50-416 82/10/04.8210080282
- -8210080287 LER 82-063/03L-0 on 820902, various fire rated cable penetrations discovered not smalled in several field termination cabinets located in control room Penetrations removed to allow cable retouting MALKER.K L Kississippi Power & Light Co 82/10/04 Region 2. Ortice or Lirector Ip 15638 200 24X Fiche 50-416,82/10/04. 8210080282
- 021008018a Forwards LER 82-0/0/031-0 MCGAUCHY-J P Mississippi Pawer & Light Co 62/10/05 O REILLY, J P Region 2: Orfice of Director 1p 13640 177 247 Fithe 50-416, 82/10/05, 8210080186
- -8210080192 LER 82-070/03L-0 on 820907.13 & 16.smoke detector P65 tone 2-01 sensed smoke in standby svt water pumphouse Caused by smoke blown from nearby burn pit liber wind changed directions, alarm cleared Detector cleaned DIFFEREMI.P M Mississippi Power & Light Co 82/10/05 Region 2. Orfice of Director ip 15640 178 24X Fiche 50-416.82/10/05, 8210080186
- 82:0080284 Forwards LER 82-066/03L-0 MCGAUGH1,J P Mississippi Power & Light Co G'REILLY,J P Region 2: Office of Director 1p 15638 318 24x Fiche 50-416,82/10/05,8210080284
- -8210080289 LER 82-046/03L-0 on 820909, smake detector ione covering hallway area elevation 93-ft auxiliary blide & HPCS pump room alarmed & would not clear Caused by dust accumulation on ionitation smake detectors Detectors cleaned 8YRO,R Mississippi Power & Light Co 82/10/05 Region 2, Office of Director ip 15538 319 24X Fiche 50-4146.82/10/05, 8210080284
- 6210080295 Forwards LER 82-045/03L-0 MCANUGHY.JP Mississippi Power & Light Co 82/10/05 O'REILLY.JP Region 2. Office of Director #p 15638 323 24x 50-416.62/10/05.6210080295

- 8210220158 Forwards LER 82-064/03L-0 MCGAUGNY. J P Mississippi Fower & Light Co 82/10/08 O'REILLY. J P Region 2. Office of Director 1p 15778 080 24x Fiche 50-416.82/10/08.8210220158
- --8210220162 LER 82-064/03L-0 on 820914, two independent chlorine detection sys inoperable Caused by chlorine gas detector failing due to clogging of internal flow paths Detector cleaned repaired & returned to svc SPARKS, 9 L. Mississippi Power & Light Co. 82/10/08 Region 2, Office of Director 2pp 15779 081 24X Fiche 50-416,82/10/08,8210220158
- 82:0220181 Forwards LER 82-068/03L-0 MCGAUGHY, J.P. Mississippi Fower & Light Co. 82/10/08 O'REILLY, J.P. Region 2. Office of Director 1p. 15776 254 24x Fichs 90-416, 82/10/08, 8210220181
- --B210220191 LER 82-068/03L-0 on 820909, reactor pressure vessel flamge head flange temp not monitored periodically per Toch Speca Caused by operator error Required parameters verifying acceptable value read & recorded SPARKS.G L Mississippi Power & Light Co Q2/10/08 Region &, Office of Director 2pp 15776 255 24X Fiche 50-416, 82/10/04. 82/10220181
- 8210220259 Forwards LER 067/0%L-0 MCGAUGHY, J P Mississippi Power & Light Co 62/10/08 O'REILLY, J P Region 2, Office of Director 1p 15775 130 24x Fiche 50-416, 82/10/08, 8210220259
- --8210220262 LER 82-067/03L-0 on 820910, smoke detectors in zone covery; auxiliary bidg corridor area alarmod & would not reset Caused by accumulation of dust on contration smoke detector combined which sensitivity setting Detector cleaned PACE.D L Mississippi Power & Light Co 82/10/08 Region J. Office of Director ip 15775 (39 24x Fiche 50-416,82/10/08, 821022039
- ~-B210220462 LER B2-073/03L-0 on B20909, smoke detectors alarmed w/no fer present Caused by paint fumes resulting from maint painting activities in area Bmoke detectors cleaned BYRD, R Miesissippi Power & Light Co B2/10/08 Region 2, Office of Director in 15779 126 24X Fiche 50-416, 82/10/00, B210220458
- @210220045 Forwards LER @2~077/03L-0 MCGAUGHY, J.P. Hississippi Power & Light Co. @2/10/11 @'REILLY, J.P. Region 2. Diffice of Director ip 15778 195 24K Fiche 50-414, @2/10/11, @210220065
- ~~8210220067 LER 82-079/03L-0 on 820910, discovered temp monitoring of specific safety-related areas not conducted every 12-h Data recorded once every 24-h from 820824-0911 Caused by inadvertent emission from aperating log procedure HHITE, A J Mississippi Power & Light Co 82/10/11 Region al. Office of Director ip 15778 196 24X Fiche 50-416, 82/10/11, 8210220065
- 8210190417 Forwards LER 82-077/01T-0 MCGAUGHY, J P Mississippi Power & Light Co 82/10/12 O'REILLY, J P Region 2, Office of Director 1p 15741 014 24# Fishe 50-416, 82/10/13, 82/0190417
- --8210190424 LER 82-077/01T-0 on 920930, two penetrations found not sealst from auxiliary bldg to control bldg Penetrations for electrical conduit not sealed during const Penetration sealed DIFFERENT, P M Mississippi Power & Light Co 82/10/13 Region 2, Office of Director 2pp 15741 015 24x Fiche 30-416. 82/10/13,8210190417
- 8210190561 Forwards LER B2-075/99X-0 MCGAUGHY, JP Mississippi Power & Light Co 82/10/13 O'REILLY, JP Region 2. Office of Director 1p 15735 020 24x Fichs. 50-416. 82/10/13. 8210190561.
- --B210190567 LER 82-075/79X-0 on B20915, steam tunnel fire door 1A200 discovered open w/no fire watch stationed during preparation for non-nuclear heatup Caused by need for tunnel maint Hourly fire watch established Door closed following maint CHENAULT. W H Mississippi Power & Light Co. B2/10/13 Region 2. Office of Director ip 15735, 021 24X Fiche 50-416.82/10/13 B210190561

- 9210220131 Forwards LER 92-080/011-0 MC0AU0HY, J P Mississippi Power & Light Co #2/10/18 U'REILLY, J P Region 2, Office of Director 1p 15778 115 24X Fichs 50-416.82/10/18.8210220131
- --8210220190 LER B2-080/017-0 on 821004, during cold chutdown insp on Div 2 standby dissel generator, capscrew to rear trankcase cover of engine block found deflective Caused by fatigue during engine operation Capscrews replaced CHENAVLT, W.H. Mississippi Power & Light Co. 82/10/18 Region 2, Office of Director 2pp. 15778 116 24X Fiche 50-416, 82/10/18, 82/10/20131
- 6210220269 Forwards LER 82-086/03L-0 MCOAUGHY, J P Msssissippi Power & Light Co 82/10/18 O'REILLY, J P Region 2, Office of Director 1p 15776 200 24X Fiche 50-416, 82/10/18, 8210220269
- --8210220274 LER 82-086/03L-0 on 820916, fire detection Zone 2-6 trouble light alarmed & would not clear Caused by improperly seated smoke detector allowing open circuit Detector reseated, tested & returned to svc

 BYRD, R Mississippi Power & Light Co 82/10/18 Region 2, Office of Director ip 15776 201 24X Fiche 50-416, 82/10/18, 82/202649
- 8210220278 Forwards LER 82-083/03L-0 MCGAUGHY.J P Mississippi Power & Light Co 82/10/18 O'REILLY.J P Region 2. Office of Director ip 15775 047 24X Fiche 50-416.82/10/18.8210270278
- ~-8210220282 LER 82-083/03L-0 on 820918, during cold shutdown, nine fire barrier penetrations were broken in auxiliary & control bldgs Caused by add1 electrical conduit being routed due to implementation of Design Change 82-0594
 ALBERT. J M Hississippi Power & Light Co 82/10/18 Region 2, Office of Director ip 15775 048 24X Fiche 50-414, 82/10/18, 8210220278
- 8210220284 Forwards LER 82-081/03L-0 MCGAUGHY, J P Mississippi Power & Light Co 82/10/18 O'REILLY, J P Region 2, Office of Director 1p 15775 045 24X Fichs 50-416, 82/10/18, 8210220284
- --8210220289 LER 82-081/03L-0 on 920916, containment ventilation menitoring sys effluent flowrate monitor failed to give proper indication Passibly caused by clugged flow sensor Haint work order issued to remove, inspect & clean sensor CHENAULT, H Mississippi Power & Light Co 82/10/18 Region 2, Office of Director 1p 19775 046 24X Fiche 50-416,82/10/18,82/202884
- 8210220428 Forwards LER 82-085/03L-0 MCGAUCHY.J P Mississippi Power & Light Co 82/10/18 O'REILLY.J P Region 2, Office of Director 1p 15779 162 24X Fiche 50-416.82/10/18.0210220428
- --B210220431 LER 82-085/03L-0 on 820916, three secondary containment panetrations opened for cable routing per planned maint activity Fire match established Penetrations sealed BYRD, R Mississippi Power & Light Co 82/10/18 Region 2, Office of Director Ip 19779 163 24X Fiche 50-416,82/10/18, B21020428
- 8210260445 Interim Deficiency Rept 3 re corroded terminal boards on pressure flow & level transmitters initially reported on 820421 Corroded transmitters being analyzed by independent lab Final rept will be sent by 821215 MC9A00Hy.JP Mississippi Power & Light Co 82/10/18 O'REILLY.JP Region 2. Office of Director 2pp 15805 248 24X Fichs 50-416, 82/10/18, 8210260445
- 8210260513 Final deficiency rept to extensive internal corrosion of Dikkers safety relief valve actuators Initially reported on 820521 Actuators cleaned referbished tested & returned to original design condition Also reported per Part 21 MCGAUGHY, JP Mississipgi Power & Light Co 82/10/18 O'REILLY, JP Region 2, Office of Director 5pp 15805 128 24X Fichs 50-416, 82/10/19, 8210260513
- 8210290050 Forwards LER 82~074/03L~0 MCGAUCHY.J P. Mississippi Power & Light Co 82/10/23 O'REILLY.J P. Region 2. Office of Director 1p 15894 020 24X Fichs 50~416, 82/10/23, 8210270050
- --8210290055 LER 82-074/03L-0 on 820923 review revealed only one ECCB operational during 820722 fuel load Caused by personnel & procedural error resulting in operators not being fully aware of ECCB status Equipment problems corrected BYRD.R W Mississippi Power & Light Co 82/10/23 Region 2, Diffice of Director 3pp 15854 021 24X Fiche 50-416,82/10/23,8210290050.

- 8210290124 Forwards LER 82-076/031-0 MCGAVGHY, J P Mississippi Power & Light Co 82/10/23 O'REILLY, J P Region C. Office of Pirector 1p 15854 018 24) Fichs 50-416, 82/10/23, 8210290124
- --8210590135 LER 82-079/03L-0 on 820923, smoke detectors in Zones 2-06. 2-07.2-17 & 2-20 of auriliary bldg alarmed & would not clear No smoke or fire present Alarms deactivated Caused by dust accumulation Detectors cleaned ALBERT. J M Mississippi Power & Light Co 82/10/23 Region C. Office of Director ip 15854-019 24X Fiche 50-416.82/10/23 8210290124
- 8210290340 Forwards LER 82-088/03L-0 MCGAUDHY, J P Hississippi Power & Light Co 82/10/23 O'REILLY, J P Region 2, Office of Director to 15853 03t 24x Fiche 50-416, 82/10/23, 8210290340
- --8210270345 LER 82-088/03L-0 on 820923 discovered that Survey lance Procedure 06-EL-1831-M-1002 allowed for bench test of drywell equipment drain sump pump running timers but did but specify in-says testing Procedure revised BYRD.R Mississippi Power * Light Co 82/10/23 Region & Office of Director 2pp 15853 032 24X Fiche 50-416.82/10/23, R210290340
- 8210290073 Forwards LER 82-082/03L-0 MCGAUCHY, J P Mississippi Power & Light CJ 82/10/25 O'REILLY, J P Region 2, Office of Director 1P 15853 147 24x Fiche 50-416, 82/10/25, 8210290073
- --8210290081 LER 82-082/03L-0 on 820925. Channels CtD of control room vent radiation monitors were outside required Tech Spec tolerences Caused by monitors being out of callbr Channels recallbr CHENAULT, W H. Mississippi Power & Light Co. 82/10/25 Requin 2, Office of Director ip 15853 148 24X Fiche 50-416, 82/10/25, 8210290073
- B210290311 Forwards LER 82-089/03L-0 MCGAUGHY, J P Mississippi Power & Light Co 82/10/25 O'REILLY, J P Region 2, Office of Director 1p 15853 110 24X Fichs 50-416, 82/10/25,821029031
- --B210270332 LER 82-087/03L-0 on 820725 LPCS failed Surveillance lest OA-OP-1621-M-0001 due to failure of LPCS min flow valve (E21-F011) Caused by tailure of valve to cycle Motor replaced, tested & sys returned to svc on 820730 MHITE.A J Mississippi Power & Light Co 82/10/25 Region 1, Office of Director 1p 15853 111 24X Fishe 50-416.82/10/25, 8210290311
- 8210290348 Forwards LER 82-090/99X-0 MCGAUCHY, J P Mississippi Power & Light Co 82/10/25 O'REILLY, J P Region 2. Office of Director 1p 15853 024 24X Fiche 50-416, 82/10/25, 8210290348
- --B210270351 LER B2-090/97X-O on B20720, five penetration room fire door alarm doors found inoperable, voiding ability to monitor door position Cause unknown Hourly fire watch established Alarms retested & returned to aperability ALBERT, J M Mississippi Power & Light Co B2/10/25 Region 2, Office of Director 1p 15853 025 24X Fiche 50-416.82/10/25, 8210270348
- DOCKET 50-417 GRAND GULF NUCLEAR STATION, UNIT 2
- A Application/construction stage documents & correspondence
- 8210040053 Advises of delay in response to Humphrey concerns recontainment issues pending 821001 conference discussion w/GE on local encroachments. Action Plans 1-4 Commitment based on 820929 telcon w/Containment Sys Branch DALE, L.F. Mississippi Power & Light Co. 82/09/30 DENTON, H.R. Office of Nuclear Reactor Regulation, Director ig 15581 307 2: Fiche 50-416,82/09/30,8210040053
- 8210040353 Forwards responses to 820824 request for add1 info re
 Items i-8.including current status & submittal schedule
 for outstanding items TF Plunkett prof qualifications
 enc!
 DALE, L F Mississippi Power & Light Co 82/09/30 DENTON, H R
 Office of Nuclear Reactor Regulation, Director 8pp 15593 348
 24X Fiche 50-416,82/09/30.8210040353
- 8210060295 Responds to request for add1 info re HPCS svc water pump Add1 testing or mod not required Suggests meeting w/Equipment Qualification Branch to discuss evaluation results on 821008 in Bethesda.MD DALE, L.F. Mississippi Power & Light Co. 82/10/04 DENTON, H. R. Office of Nuclear Reactor Regulation, Director 4pp. 15619 305 24X Fiche, 50-416, 82/10/04, 8210040295

- 62(0210217 Submits addi into the design & testing of autometic depressuritation systain systicctuding response to NUREO-0737. Item II & 3 28. Air systesting & air sys makeup provisions Revision to FSAR Subsection 18 1 30 12 encl DALE.L F. Mississippi Power & Light Co. 62/19/18 DENTON, H. R. Office of fluctear Reactor Regulation, Director 3pp. 15766-346-24X Fiche 50-416.82/19/18.8210210217
- 8210270277 Forwards additinform containment design, in response to J Numphrey questions Status rept per usil 820715 ltr & OE proprietary info withheld Affidavit & II oversize drawings encl Aperture cards are in PPR DALEL F Mississippi Power & Light Co 82/10/22 DENTON, H & Office of Nuclear Reactor Regulation, Director 82pp 15852 198 24% Fiche 50-416,82/10/22,8210270277
- 8210280135 Provides add1 responses to NRC concerns re adequate of onsite communication says in areas exhibiting high ambient noise levels, use of 2-way radip says & work stations requiring communications w/control roam or shutdown panel DALE, L. F. Mississippi Power & Light Co. 82/10/26 DENION, H. R. Office of Nuclear Reactor Regulation, Director ... 3pp. 15837 130 24% Fiche 30-416, 82/10/26, 82/10280135
- B210290102 Outlines commitments made during B21025 teleon re design & testing of automatic depressuritation air sys Integrated leak test on sys will be performed every 18 months Justification for interim operation listed DALE, L. F. Mississippi Power & Light Co. B2/10/26 DEN7ON; H. R. Office of Nuclear Reactor Regulation, Director 2pp. 15854 Onl. 24X Fiche 50-416,82/10/26 8210290102
- E NRC Safety Evaluation Report (SER), suppls & correspondence
- 6210190366 Advises of completion of the smorouple qualification testing per SER Suppl 3 Thermocouples considered qualified for seismic & hydrodynamic loads including variable pool swell Final test rept will be reviewed upon receipt DALE.L F Mississippi Power & Light Co. 82/10/14 DENTON.H R Office of Nuclear Reactor Regulation, Director 2pp 15736 Li33 24X Fichs 50-416.82/10/14,8210190566
- 8210200025 Forwards outline of in situ test for HPCS standby svc water pump flow induced vibration Test will be performed prior to startup following first refueling outage Commitment to conduct test resolves SER Suppl 2:Bection 3 10 concerns DALE.L.F. Hississippl Pawer & Light Co. 82/10/18 DENTON, H.R. Office of Nuclear Reactor Regulation. Director 7p 15754 341 1/4% Fiche 50-416, 82/10/18, 8210200005
- BRIO200030 Forwards evaluation of valve disc pin overstressing, addressing concerns & closing supplemental BER 2.8ection 22 2 (issue II E 4 2), "Purge Valve Operability " DALE.L. F. Mississippl Power & Light Co. BR/10/18 DENTON, H. R. Office of Nuclear Reactor Regulation, Director 7pp \$5757 194 24X Fichs 50-416.62/10/18.8210200030
- 8210200073 Forwards info re monitoring trend analysis program per commitment to symmetrie vibration monitoring analysis program for deep draft pump reliability per BFR Section 1 10 (13) DALELL F Mississippi Power & Light Co. 02/10/18 DENTON, H R Office of Nuclear Reactor Regulation. Director 2pp 15794 133 24X Fiche 30-416.62/10/18.0210200073
- 6210220425 Forwards add3 info ne qualification of hydraulic control units affected by variable pool swell loads Test response spectra-required response spectra comparisons should be sufficient to close concern in SER Suppl 3, Section 3 IO DALE-L F Mississipps Power & Light Co 82/10/19 DENTON-H R Office of Nuclear Reactor Regulation, Director 7pp (8779-193) 24X Fiche 50-416-82/10/19,82/0220425
- F Sycurity: medical, emergency & fire protection plans

- --B210070044 Forwards public version of corrections to Table 4-) re emergency action levels.in response to NRC questions on Revision 6 to emergency plan Encl changes will be incorporated into plan by 821031 DALE, L. F. Mississippi Power & Light Co. B2/07/09 DENTON, H. R. Offsice of Nuclear Reactor Regulation, Director 2pp. 15646-343 24X Fiche 50-416, 82/09/17, 8210070040
- --8210070048 Public version of corrected Table 4-1 re emergency actics levels Initial & Final notification forms encl # Hississippi Power & Light Co 82/09/09 app 15646 145 41 Fiche 50-416,82/09/17.8210070040
- 8210010234 Forwards Revision 5 to physical security plan Revision withheld (ref 10CFR2 790) MCGAUGHY, J.P. Mississippi Power & Light Co. 82/09/22 DENTOW, H. R. Office of Nuclear Reactor Regulation, Director 2pp. 15574 060 244 Fichs 50-416.82/09/22.8210010234

G Adjudicatory correspondence

- 8210040115 Order granting State of LA 820921 motion for extension of time to respond to ASLS 820831 order LA response to NRC & applicant arguments due 821011 No further extension of time will be granted LAURENSON, J A Atomic Safety and Licensing Board Panel 02/09/in Louisiana, State of 3pp 15581 186 24X Fiche 50-416, 82/09/3
- B210150462 Brief supporting State of LA Jul 1982 petition to participate as interested state Good cause shown for untimely petition Certificate of Svc enci LinoSEY, I D Louisiana, State of B2/10/11 Atomic Bafety and Licensing Board Panel Sipp 15703 073 24X Fiche 50-416,82/10/1; B2101508A2
- 8210210393 Memorandum & order denying State of LA 820726 getition for intervention ASLB unable to consider challenges to Table 8-3 im proceeding Commission retained jurisdiction over decision to great full power OL LAURENBON, J A , BRIGHT 0 O . HARBOUR, J Atomic Safety and Licensing Board Panel 82/10/20 Louisians, State of 17pp 15763 184 24% Fiche 50-416/82/10/20.8210710393
- Q Inspection reports, IE Bulletins & correspondence
- 8210150013 Responds to noncompliance re emergency accountablifity noted in IE Insp Rept 50-416/82-27 Interpretion of "onsite" questionable Other utils make same distinction of sits boundary being same as protected area DALE-L.F. Mississippi flower & Light Co 82/07/19 O'REILLY, J.P. Region 2, Office of Director 2pp 15698 346 24X Fiche 50-416, 82/07/19, 8210150013
- 8210010442 Forwards IE Insp Repts 50-416/82-61 & 50-417/82-13 on 820817-20 No honcompliance noted VERRELLI, D M Division of Project 3 Resident Programs 82/09/03 8TAMPLEY, N L Miss(seight Programs 62/09/03 FTAMPLEY, N L Miss(seight Programs 62
- --8210010447 IE Insp Repts 50-416/82-61 & 50-417/82-13 on 820817-20 % noncompliance noted Major areas inspected const deficiency repts for Unit 1 & observation of safety-related piping worl activities at Unit 2 BLAME, J J Division of Engineering & Technical Programs 82/09/02 4pp 15570 177 24X Fiche 50-416, 82/09/03, 8210010447
- 8208190233 IE Info Notice 80-35, Suppl 1, "Leaking & Dislodged I-125 Implant Baads " Svc list ancl. COB3.L I. Division of Fuel Facilities, Materials & Bafeguards BZ/10/06 Consolidated Edison Co of New York. 66pp. 13761 255 24X Fichs 50-000,82/10/06,8208190233
- 8208190R38 IE Bulletin 82-03, "Stress Corrosion Cracking in Thick-Wall, Large-Diameter, Stainless Steel, Recirculation Sys Piping at SWR Plants " Syc list entl DEYOUND, R. C Director's Office, Office of Inspection and Enforcement. 82/10/14 Consolidated Edison Co of New York 115pp 15810, 125 24X Fiche 50-000, 82/10/14, 8208190238
- 8210280132 Forwards responses to Instrumentation & Control Bys Branch 820714 questions re util evaluation of IE Info Notics 79-22. "Qualification of Control Sys Failures Info re NRC review available in NNREO-0831 DALE: L. F. Mississippi Power & Light Co. 82/10/25 DENTON.H 8 Office of Nuclear Reactor Regulation. Director 10pp 15837 130 24% Fiche: 80-416,82/10/25,8210280132

- S Reportable occurrences, LERs & related correspondence
- B2100B0223 Interim deficiency rept re unqualified Bettis air actuators on Henry Pratt valves Initially reported on B11029 Scope eipanded to include other actuators Subj not reportable per IDCR950 55(e) Final rept expected by 830331 MCGAUGHY, J.P. Mississipp, Pawer & Light Co. 82/10/01 G*REILLY, J.P. Region 2. Office of Director. 4pp. 19638-049 24X Fiche 50-416,82/10/01,8210080223
- 82(0270193 Final Deficiency Rept PRD-82/36 re cadwell rebar splice testing Instially reported on 820920 Spec Change Notice j issued requiring splice testing of each bar size All splices reviewed MCGAUGHY. J P Mississipp Fower & Light Co 82/10/20 O'REILLY, J P Region 2. Office of Director 5pp 15854 004 24X Fiche 50-417.82/10/20.8210270193
- BOCKET 50-423 MILLSTONE NUCLEAR POWER STATION. UNIT 3
- A Application/construction stage documents & correspondence
- 9210090105 Informs that bolt matl discussed in util 920817 ltr miq & tasted to matl spec requirements of SA-540. Grade 823, Class 2. in response to D Sellers request for addl info Expeditious approval of ASHE Code Case N-310-1 requested COUNSEL.41 9 Northeast Nuclear Energy Co (subs of Northeast Utilities) 82/09/28 GRANT. J Licensing Branch 1 ip 15440 274 24X Fishe 50-423, 82/09/28, 8210080105
- 3210130331 Discusses revision of administrative procedures to incorporate revised working hour guidelines & provisions for authorizing deviations per 820208 & 0615 requests.TMI Item 1 A 1 3, "Shift Manning" & Generic Ltr 82-12 CDUNSIL.W O Northeast Nuclear Energy Co (subs of Northeast Utslities) CAONETTALJ P Connecticut Vankee Atomic Power Co CAONETTALJ P Northeast Utslites 82/10/01 EISENHUT.D G Division of Licensing 3pp 18679 127 24X Fiche 50-000.82/10/01, 8210130331
- I Inspection reports, IE Bulletins & correspondence
- 208190233 1E Info Notice 80-35, Suppl 1, "Leaking & Dislodged 1-126 Implant Seeds " Svc list encl COUBL I Division of Fuel Facilities, Materials & Safeguards 92/10/06 Consolidated Edison Co of New York 66pp 15761 256 244 Fiche 50-000.82/10/06.8208190233 5
- 210210241 Forwards IE Insp Rept 50-423/82-11 on 820802-31 & 0701-10 & notice of violation STAROSTECKI, R Division of Project & Resident Programs 82/10/04 COUNSIL-W O Northeast Nuclear Energy Co (subs of Northeast Utilities) 2pp 15766 247 24x Fiche 50-423,82/10/06,8210210241
- -8210210248 Notice of violation from lnsp on 820802-31 & 0901-10 * Region i, Office of Director 82/10/06 ip 15766 249 24) Fiche 50-423, 82/10/06, 0210210241
- -8210210261 IE Insp Rept 50-423/82-11 on 820802-31 & 0901-10

 Noncompliance noted failure to follow design specs when storing electrical cables & follow requirements of document control procedure for use of const drawings

 MATTIA-J C. ELBASSER, T Division of Project & Resident Programs 82/10/04 9pp 15746 250 24X Fiche 50-423,82/10/06.8210230241
- 208190238 IE Bulletin 82-03, "Stress Corrosion Cracking in Thick-Wall, Large-Diameter, Stainless Steel, Recirculation Sys Piping at BMR Plants " Svc list encl DEYGUNG, R C Director's Office, Office of Inspection and Enforcement B2/10/14 Consolidated Edison Co of New York 115pp 15810 125 24X Fiche 50-000, 82/10/14, 8208190238
- Reportable occurrences, LERs & related correspondence
- '10210340 Interim deficiency rept re failure of pinion gear shear keys in Limitorque Model 880 (SD-25) Initially reported on 820804. Util currently awaiting info from vendor Next rept sipected by 821115 (SDW-881L. W O Northeast Nuclear Energy Co (subs of Northeast Utilities) GOUNSIL. W O Northeast Utilities 82/10/06 HAYNES, R C Region 1. Office of Director 1p 15764 310 24X Fichs 30-423, 82/10/06. 8210210340
- 10170555 Final deficiency rept re design & const of metal shavings in containment recirculation pump motor initially reported on B20331 Event mot considered reportable significant deficiency per 100FR50 556 CGUNSIL, W G Northeast Nuclear Energy Co (subs of Northeast Utilities) CGUNSIL, W G Northeast Utilities B2/10/08 HAYMES, R C Region 1, Office of Director 2pp 15734 124 24X Fichs S0-423, B2/10/08, B210190555

- 8210250329 Interim deficiency rept re cracking of control rod guide tube support pins. Initially reported on 800405 Westinghouse evaluating problem Next rept will be provided by 821116.

 CGUNSIL, W.G., OPEKA, J.F. Northeast Nuclear Energy Co. (subs. nf. Northeast Utilities). 0PEKA, J.F. Northeast Utilities. 82/10/12 HAYNESR C. Region 1, Orfice of Director. 1p. 15790-328. 24%. Fiche 50-423, 82/10/12, 8210250329
- 8210250290 Final deficiency rept re-missing Westinghouse design thermal sleeves in 2-inch chemical & vol control sys (SD-24) Initially reported on 820712 Affected thermal sleeves will be eliminated COUNSIL & G. OPEKA.J F. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). OPEKA.J F. Northeast Utilities 62/10/13 HAYKES.R C. Region I. Office of Director 2pp. 15791 160 204X Fiche 50-423,82/10/13.8210250290
- DOCKET 50-424 ALVIN W VOCTCE NUCLEAR PLANT, UNIT 1
- A Application/construction stage documents ♦ correspondence
- 8210080312 Summary of 820831 meeting w/util in Betheeda.ND re requirements of Reg Guide 1 88. "Collection.Storage & Maint of Nuclear Power Plant 9A Records "Applicant concerned that tornado criteria not uell defined GRANTIJ M Licensing Branch 1 82/09/17 Licensing Branch 1 3pp 15643 338 24X Fiche 50-424.82/09/17,8210090312
- 8210120341 Forwards request for addl info re QA controls for field change notices Response due by 821020 YOUNOBLOOD & J. Licensing Branch 1 82/09/20 DUTTUN, D.E. Charqi. Pauer Co. App. 15691-053 24X Fiche 50-424.82/09/20.8210120341
- 8210080314 Summary of 820714 meeting w/utils & Bechtel Civil & Minerals. Inc in Bethesda. MD re Millett Fault Study Final rept will be submitted by mid-Oct ORANT, JM Licensing Branch 1 82/07/23 Licensing Branch 5pp 15663
- 8210070168 Informs that FSAR will be submitted by 830701 instead of 830901 Environ rept. security plan t antitrust info scheduled for 830901 DUTTON.D Georgia Power Co 82/10/01 EISENNUT.D G Division of Licensing 1p 15627 008 24X Fiche 50-424.82/10/01.8210070168
- 8210150362 Forwards "Studies of Postulated Militett Fault," Vols 1 & i', in response to USOS Open File Rept B2-156, which postulates existence of fault near facility Postulated Fault not capable
 DUTION.D Georgia Power Co
 Licensing 2pp 15711 011 24X Fiche 50-424,82/10/15,82101503042
- --8210150373 "Studies of Postulated Millett Fault." Vols (& 2 Thirty oversize figures encl Aporture cards are available in PDR * Bechtel Corp 82/10/31 809pp 15711 013 24X Fiche 50-424,82/10/15.8210150342
- 8210270246 Responds to NRC 820920 request for add1 info re controls for field change notices Field change notice program will not result in marginally acceptable design DUTTON.D E Georgia Power Co 82/10/15 EISENKUT,D G Division of Licensing 13pp 15829 238 24X Fiche 50~424.82/10/15,8210270246
- Q Inspection reports, IE Bulletins & correspondence
- 8210010182 Forwards IE Insp Repts 50-424/82-21 & 50-425/82-21 on 820817-20 No noncompliance noted DANCE-H C Division of Project & Resident Programs 82/09/09 KELLYR J Georgia Power Co 2pp 15567 306 24X Fiche 50-424,82/09/09,8210010182
- --8210010187 IE Insp Repts 50-424/82-21 & 50-425/82-21 on 820817-20 No noncompliance noted Major areas inspected licensee action on previous insp items, storage & preventive maint of electrical & instrumentation equipment & IE circular followup RUFF.A B , CONLONITE Division of Engineering & Technical Programs 82/09/08 4pp 15567 308 24X Fiche 50-424,82/09/09,8210010182
- 8210150096 Forwards IE Insp Repts 50-424/82-19 & 50-425/82-19 on 820711-0810 No noncompliance noted DANCE.H C Division of Project & Resident Programs 82/09/15 KELLY.R J Georgia Power Co 2pp 15701 185 24X Fichs 50-424.82/09/15.8210150096

- --8210150103 IE Insp Repts 50-424/82-19 t 50-425/82-19 on 820711-0810 No noncorpliance noted Major areas inspected primary containment fabrication.equipment handling & protection. structural steel installation / steam generator mod SAUNDERS.W F BROWNLEE.V L Division of Project & Resident Programs 82/09/09 5pp 15701 187 24x Fiche 50-424-82/09/15, 8210150096
- 8210220155 Forwards IE Insp Repts 50-424/82-22 & 50-425/82-22 on 820311-0710 No noncompliance noted DANCE H C Division of Project / Resident Programs 82/09/29 KELLY:R J Georgia Power Co 2pp 15778 083 24x Fiche 50-424, 82/09/29, 8210220155
- --8210220159 IE Insp Repts 50-424/82-22 % 50-425/82-22 on 820811-0910 No noncompliance noted Major areas inspected primary containment fabrication, rabar welding, concrete placement & steam generator mode SANDERS, W.F. BROKKLEE, V.L. Division of Project % Resident Programs 82/09/29 5pp 15778-085 249 Fiche 50-424,82/09/29, 8210220155
- 8208190337 IE Info Notice 80-35, Suppl 1, "Leaking & Dislodged 1-125 Implant Seeds " Svc list enc) COSR L I Division of Evel Facilities. Materials & Safeguards 82/10/06 Consolidated Edison Co of New York 66pp 19761 ab0 244 Fiche 50-000.62/10/06.8208190233
- SENBI90238 IE Bulletin 82-03. 'Stress Corroston Cracking in Thick-Walli Laige-Diameter. Stainless Steel, Recirculation Sys Piping a' BPR Plants "Syc list encl LEYQUNG, R C Director's Office, Office of Inspection and Enforcement 82/10/14 Consolidate Edison Co of New York 115pp 15810 125 24X Fiche 50-000, 82/10/14, 8208190238
- 8210(202)4 Ack receipt of 820928 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-424/82-20 % 50-425/82 20 DANCE, H C Division of Project & Resident Programs 82/10/15 FECHE VIOLATION POWER CO. 1p 15774 339 244 FICHE 50-424,82/10/15 82:0220204
- E210220211 Forwards IE Insp Repts 80-424/82-20 % 50-425/82-20 on B20809-13 % notice of violation DANCE, IC Division of Project & Resident Programs 82/08/27 KELLY, R. J. Georgia Poues Co. 2pp. 15776-342 24X Fiche 50-424/82/10/15 E210220204
- --8210220215 Notice or Fiolation from inspired 820809-13 4 Region 2, Giffice or Director 87/09/27 2pp 15776 344 (4x Fiche 50-424 827/07/35.8/10220204
- S. Reportable occurrences. LERs & related correspondence
- 8210220078 Interim deficiency rept re control cable length/sizing Initially reported on 820922 Deficiency determined reportable under 100FR80 55(e) Final rept expected by 821022 FOSTER, D. G. Georgia Pawer Co. 82/10/08 D'REILLY, J. P. Region 2: 00ffice of Director ip 15778 184 24X Fiche 50-424, 82/10/08, 2014/200748
- 8210190621 PND-II-82-112 area media interest occurred following licenses 821015 issuance of news release re geological survey rept stating that no active santhquake fault exists in vicinity of const site CLARK.K N GILLILAND J T Region 2 Office of Director 82/10/15 2pp 15737 217 247 Fiche 50-424.82/10/15.8210190621

- DOCKET 50-425 ALVIN W VOGTLE NUCLEAR PLANT, UNIT 2
- A Application/construction stage documents & correspondence
- 8210080312 Summary of 820831 meeting w/util in Bethosda, MD re requirements of Reg Guide 1 BB, "Collection, Storage & Maint or Nurlear Power Plant OA Records " Applicant concerned that tornado criteria not well defined GRANT, J.M. Licensing Branch 1 82/09/17 Licensing Branch I 3pp 15663 338 24X Fiche 50-424,82/09/17,8210080312
- 8210120341 Forwards request for add1 info re QA controls for field change notices Response due by 821020 YQUNOBLOOD.B J Licensing Branch 1 82/09/20 DUTTON,D E Georgia Power Co App 15641 053 24X Fiche 50-424.82/09/20.8210120341
- 8210080314 Summary of 820914 meeting w/utils & Bechtel Civil & Minerals, Inc. in Bethesda, MD ra Millett Fault Study Final rept will be submitted by mid-Dct ORANT, JM Licensing Branch 1 82/09/23 Licensing Branch 1 5pp 15663 353 24X Fiche 50-424,82/09/23,8210080314
- 8219070168 Informs that FSAR will be submitted by 830701 instead of 830901 Environ rept.security plan & antitrust info scheduled for 830901 OUTION.D Georgia Power Co 82/10/01 EISENHUT, D G Division of Licensing 1p 15627 008 24X Fiche 50-424.82/10/01.8210070168
- E210150362 Forwards "Studies of Postulated Millett Fault," Vols 1 & 2, in response to USGS Open File Rept 62-156.which postulates eristence of fault near facility Postulated fault not capable DUTTON D Georgia Power Co 82/10/15 EISENHUT.D 0 Division of Licensing 2pp 1571: Oil 24% Fithe 50-424, 82/10/15, 8210150363
- --8210150373 "Studies of Postulated Millett Fault." Vols 1 & 2 Thirty oversize figures enc? Aperture cards are available in PDR * Bechtel Corp 82/10/31 809pp 15711 013 24X Fiche 50-424,82/10/15,8210150362
- 8210270246 Responds to NRC 820920 request for add1 info re controls for tield change notices Field change notice program will not result in marginally acceptable design DUTTON,D E Opergia Power Co 82/10/15 EISENHUT,D O Division of Licensing 13pp 15829 238 24% Fiche 50-424,82/10/15,8210270246
- ù inspection reports. IE Bulletins & correspondence
- E210010182 Forwards IC Insp Repts 50-424/82-21 & 50-425/82-21 on 820817-20 No noncompliance noted DANCE.H C Division of Project & Resident Programs 82/09/09 KELLY.R J Georgia Pawer Co 2pp 15567 306 24X Fichs 50-424, 82/09/09,8210010182
- --8210010187 IE Insp Repts 50-424/82-21 & 30-425/82-21 on 820817-20 No noncompliance noted Major areas inspected licensee action on previous insp items, storage & preventive maint of electrical & instrumentation equipment & IE circular followup RUFF.A B . CONLON.T E Division of Engineering & Technical Programs 82/09/08 4pp 15567 308 24X Fiche 50-424,82/09/09,8210010182
- 8210150096 Forwards IE Insp Repts 50-424/82-19 & 50-425/82-19 on 820711-0810 No noncompliance noted DANCE:N C Division of Project & Resident Programs 82/09/15 KELLY.R J Georgia Power Co 2pp 15701 185 24X Fiche 30-424.82/09/15.8210150096
- --8210150103 IE Inep Repts 50-424/82-19 & 50-425/82-19 on 820711-0810 % noncompliance noted Major areas inspected primary containment featrication, equipment handling & protection, structural steel installation & steam generator mod SAUNDERS. W F . BROWNLES, V L Division of Project & Resident Programs 82/09/09 5pp 15701 187 24X Fiche 50-424,82/09/15,8210150096
- 8210220155 Forwards IE imap Repts 50-424/82-22 & 50-425/82-22 on 820811-0910 No noncompliance noted DANCE.H C Division of Project & Resident Programs 82/09/29 KELLY,R J Georgia Power Co 2pp 15778-083 24X Fiche 50-424.82709/29.8210220155
- --B210220159 IE Insp Repts 50-424/82-22 t 50-425/82-22 on 820811-0910 % noncompliance noted Major preas inspected primary contestment fabrication, rebar welding, concrete placement & steam generator mods SANDERS, N. F., BROWNLEE, V. L. Division of Project & Resident Programs 82/09/29 Spp 15778 085 24X Fiche 50-424,82/09/29,8210220155

OB190233 IE Info Notice 80-35, Suppl 1, "Leaking & Dislodged 1-125 Implant Seeds " Svc list encl
Implant Seeds " Svc list encl
COBB. I Division of Fuel Facilities, Materials & Safeguards 82/10/06 Consolidated Edison Co of New York 66pp 15761 250 244 Fight 50-000, 82/10/06, 8208190233

108190238 IE Bulletin 82-03, "Stress Corrosion Cracking in Thick-Wall.Large-Diameter.Stainless Steel.Recirculation Sys
Piping at BMR Plants " Svc list onc!
DEYOUNG.R C Director's Office. Office of Inspection and
Enforcement 82/10/14 Consultdated Edison Co of New York
115pp 15810 125 24X Fiche 50-000.82/10/14.8208190238

10220204 Ack receipt of 820928 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-424/82-20 % 50-425/82-20

DAMCE, H C Division of Project & Resident Programs MELLY, R J Georgia Power Co ip 15776 339 24x Fiche 50-424, 82/10/15, 8210220204

B21022020B Responds to NRC 820827 lir re violations noted in IE Inep Repts 50-424/88-20 t 50-425/82-20 Corrective actions contractor Procedure X-IB revised to address transition between different wall thicknesses FOSTER.D Cleargia Power Co. 82/09/28 DANCE, IC C. Region 2, FOSTER, D. G. Georgia Power Co. B2/09/28 DANCE, H.C. Region 2, Office of Director 2pp 15776 340 24X Fiche 50-424,82/10/15, 5210220204

3210220211 Forwards IE Insp Repts 50-424/82-20 & 50-425/82-20 un B20807-13 & notice of violation
DANGE, H C Division of Project & Resident Programs
KELLY, R J Georgia Power Co 2pp 15776 342 24X
Fiche S0-424,82/10/15:8210220204 82/08/27

3210220213 Notice of violation from this on 820809-13 • Region 2, Office or Director 82/08/27 2pp 15776 344 44X Fiche 50-424, 62/10/15, 8210220204

1210220218 IE Inso Reats 50-424/82-20 & 50-425/82-20 on 820809-13 Noncompliance noted visual insp procedure inadequate for piping butt welds & failure to follow procedure for removal of arc strikes COLEY, J L BLAKE, J 82/08/26 App 15 J. Division of Engineering & Technical Programs 15776-346 - 24X Fiche 50-424,82/10/15,8210220204

Reportable occurrences: LERs & related correspondence

0220078 Interim deficiency rept re control cable length/sixing nitially reported on 620922 Deficiency determined eportable under IOCFR50 55(e) Final rept expected by OSTER, D O E1922 (STER.) O Georgia Power Co 82/10/08 O'REILLY, J P Region frice of Director ip 15778 184 24% Fiche 50-424,82/10/08, Retion 2. 210220078

019062: PNO-11-82-112 area media interest occurred following icensee 621015 issuance of news release re geological urvey rept stating that no active earthquake fault exists n vicinity of const site LARK.K II. GILLILAND.J T Region 2, Office of Director 82/10/15 pp 15737 217 24X Fiche 50-424.82/10/15.8210190421

E TIMU 'NOITATE RAWOR VIRUE BEE-CE TAR Reportable occurrences, LERs & related correspondence

D290267 Part 21 deficiency rept re potential galling problem between tem & bunnet of 1 25-inch & larger A105 carbon steel & 182-F22 valyes supplied Feb 1981-Aug 1982 Valves should be riviced & stem &/or bornet replaced **ABELLE.1.**D Conval, Inc. B2/10/11 HAYNES.R C Region 1, Office Director 17pp 15854 232 24K Fiche 50-000.82/10/11. Director

LET 50-435 SURRY POWER STATION, UNIT 4 teportable occurrences. LERs & related correspondence

#290267 Part 21 deficiency rept re potential galling problem between em & bunnet of 1 25-inch \$ larger A105 carbon steel & 82-F22 valves supplied Feb 1981-Aug 1982 Valves should be rviced & stem \$/or bonnet replaced ABELLE, L D Conval, Inc 82/10/11 HAYNES, R C Region 1, Office Director 17pp 19854 232 24X Fiche 50-000,82/10/11, 10280247

DOCKET STN-50-437 FLOATING NUCLEAR PLANT

G Adjudicatory correspondence

6210150404 Order extending time until 821022 for Commission to art to review ALAB-666 & ALAB-689 CHILK.S J. Office of the Secretary of the Cummission 82/10/12 Commissioners Ip 19704-024 24X Fiche 50-437.82/10/12.

8210260460 Order extending time until B21112 for Commission to act to review ALAB-686 & ALAB-689 CHILK.S J. Office of the Secretary of the Commission 82/10/22 Commissionurs to 15007 224 24x Fische 50-437.82/10/22.

Q Inspection reports, IE Bulletins * correspondence

8208170233 IE Info Notice 80-35. Suppl 1. "Leaking & Dislodged I 12% Implant Seeds " Svc list encl CDBAL I Division of Fuel Facilities, Materials & Safeguards B2/10/06 Consolidated Edison Co of New York dapp 15741 24/ 24/ Fichs 50-000/82/10/06/8208190233

8208190238 IE Bulletin 82-03, "Stress Corrosion Cracking in Thick-Wall, Large-Diamefer, Stainless Steel, Recirculation Sys Piping at BWR Plants " Svc list encl DEYGUNG.R C Director's Office, Office of Inspection and Enforcement 82/10/14 Consolidated Edison Cu of New York 115pp 15810 125 24X Fiche 50-000, 82/10/14, 8208190238

DOCKET 50-438 BELLEFONTE NUCLEAR PLANT, UNIT 1 A Application/construction stage documents & correspondence

6210280013 Responds to FOIA request for all internal non-public documents.nemos. evafuation repts & other matl dealing w/ nuclear plant operations Forwards documents listed in App A FELTON. J M Division of Rules and Records 92/09/17 NCINNI News & Observer Spp 15860 065 24% Fichs 50-000.82/09/17. 8210280013

--8210280100 Notifies that on 820224.C Alderson advised that rept sunt re possible willful violation of reporting requirements & falsification of GA & quard qualification records at facilities
RESNER.H E Office of Inspector & Auditor 82/03/01 Office
Inspector & Auditor Ip 15861 039 24% Fiche 50-000,82/09/1/,8210280013 Office of

8210070348 Forwards responses to NRC B20903 questions on facilities, "Bellefonte Site," "Rept on Old Bellefonte Historical Site in Northern AL" & "Archaeological Survey of Scottsboid - Lim Rock 161 kV Transmission Line & Fort Payne "
MILLS.L M Tennessee Valley Authority 82/10/04 ADENSAM.E
Licensing Branch 4 32pp 15664 001 24X Fiche 50-438,82/10/04,8210070348

--8210070355 "Bellefente Site " FUTATO,E M Alabama, Univ of, I JA 300 77/ 1564 032 24X Fiche 50-438, 62/10/04/8210070348 1 JA 300 77/09/30 2ABna

--8210070358 HO--- -- --- ---- ----- -----NANCE C R 15664

~~8210

- n Inspection reports. IE Bulletins & correspondence
- \$10220180 Forwards IE Insp Repts 50-438/82-17 % 50 439/82-17 on BED607-10 & notice of violation LONG, F. L. Division of Project & Resident Programs 82/06/28 PARRIS, H. G. Tennessee Valley Authority 2pp 15776 246 24X Fiche 50-438 82/06/28, 8210220180
- 8210220183 Notice of violation from insp on 820607-10 9 Division of Project 5, Resident Programs 82/06/28 15776 248 244 Fiche 50-438,82/06/28 8210220180
- --B210220189 (E Insp Repts 50-438/82-17 % 50-439/82-17 on 820607-10 Mencompliance noted space heaters not energized on diesel generator IRT-EMB-0016-8 / discrepancies between cable bend radil ? vertical cable tray fittings identified MONITH D : MERRIMENTHER.N . COMLON 7 E Division of Engineering & Technical Programs 62/06/25 5pp 15776 249 24% Fiche 50-438.82/06/28.8210220180
- 8210010037 Advises of upcoming constrinsprto be conducted during 820920-1001 & 1011-85 Areas to be inspected fisted on encl Preinsprvisif to be held on 820830 to obtain preliminary inco
 LEMS, R.C. Division of Project & Resident Programs 82/08/31
 PARRISH G. Tennessee Valley Authority 3pp 15545 163 24%
 Fiche 50-438,82/08/31,8210010037
- 6210010421 Ack receipt of 820907 ltr informing NRC of steps taken to carrect violations noted in IE Insp Repts 50-438/82-12 & 50-439/82-12 WERRELLI.D M Division of Project & Resident Programs 62/09/17 PARRIS.M G Tennessee Valley Authority ip 15569-351 24X Fiche 50-438-82/09/17.6210010421
- --B210010427 Forwards revised response to NRC 820521 ltr re violations noted in IE Insp Repts 50-436/82-12 Corrective actions 9A program 2 procedure to require GC insp before fitup of piping components revised MILLS-L M Tennessee Valley Authority 62/09/67 O'REILLY-JP Region 2 Office of Director Jpp 15569 352 24X Fiche 50 438-82/09/17-8210010421
- 8210150149 Forwards IF insp Repts 50-438/82-27 & 50-439/82-27 on 820830-0903 No moncumpliance noted VERRELLID M Division of Project & Resident Programs 82/09/21 PARPIS, N G Tennéssee Valley Authority 2pp 15697 282 247 Fichs 50-438,82/09/21/8210150149
- 8210150164 IC Insp Repts 50-439/82-27 & 50-439/82-27 on 820830-0903 No nencompliance noted Major areas inspected structural concrete * licensee action on previously identified items HARRIS.J R CONLON I E Division of Engineering & Technical Programs 82/09/17 4pp i5697 284 24X Fiche 50-438,82/09/21,8210150149
- SCICOIO191 Ack receipt of B20913 ltr informing NRC of steps taken to correct violations noted in IE lnsp Repts 50-438/82-18 & 50-438/82-18 M Division of Project & Resident Programs 82/09/22 (ARRIS.H 0 Tennessee Valley Authority 1p 15568 078 24% fiche 50-438.82/09/22.8210010191
- -8210010197 Respands to NRC 820726 ltr reviolations noted in IL Insp Repts 50-438/82-18 % 50-439/82-16 Corrective actions QC Investigation ropts initiated for each discrepant item KAMMER.D B Tennessee Valley Authority 82/09/13 to REILLY, J P Region 2, Office of Director 3pp 15568 079 24X Fiche 50-438.82/09/22,8210010191
- --8210060200 Forwards IE Insp Repts 50-438/82-18 & 50-439/82-18 on 820608-11 & notice of violation M/o notice of violation VERRELLID M Division of Project & Resident Programs 82/07/26 PARRIS-M O Tennessee Valley Authority 2pp 15568 082 24X Fiche 50-438.82/09/22.8210010191
- 8210150171 Ack receipt of 820707 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-438/82-22 & 50-439/82-22 LEHIS.R C Division of Project & Resident Programs 82/09/23 PARRIS.H C Tennessee Valley Authority 1p 15707 184 24X Fiche 50-438.82/09/23-6310150171

- --8210150181 Responds to NRC 820812 Itr reviolations noted in [E [nsp Repts 50-438/82-22 & 50-439/82-22 Corrective actions hold placed on further installation of shielded power cable in cable tray sys Investigation continuing MILLS.L M Tennessee Valley Authority 82/09/09 O'REILLY.JP Region 2, Office of Director 2pp 15707 185 24% Fiche 50-438, 82/09/23, 8210150171
- --8210150189 Forwards IE Insp.Repts 50-438/82-22 & 50-439/82-22 on 820713-16 & notice of violation LENIG.R C Division of Project & Resident Programs 82/08/12 PARRIS.H G Tennessee Valley Authority 2pp 15707 187 24x Fiche 50-438, 82/09/23, 8210150175
- --8210150195 Notice of violation from insp on 820713-16 • Division of Project & Resident Programs 82/08/12 tp 15707 189 24X Fiche 50-438,82/09/23,821015017(
- --8210150207 IE Insp Repts 50-408/82-22 & 50-409/82-22 on 820713-14 Noncompliance noted discrepancies between cable bend radii & vertical cable tray fittings OIBBONS.TS. CONLON.TE Division of Engineering & Technical Programs 82/08/11 3pp 15707-190 24X Fiche 50-428.82/09/20, 8210150171
- 8208190233 IE Info Notice 80-35. Suppl 1. "Leaking & Dislodged 1-12b Implant Seeds " Svc list encl CDB8.L I Division of Fuel Facilities, Materials & Safeguards 82/10/06 Consolidated Edison Co of New York 66pp 15761 2b0 244 Fiche 50-000.82/10/06.8208190233
- 8210220387 Ack receipt of 820210 itr re violations noted (n IE Supplemental Investigation Repts 50-439/81-26 & 50-439/81-26 on 820707-08 Violation against provisions of Energy Reorganization Act withdrawn O'REILLY, J.P. Region 2, Office of Director 62/10/12 PARRIS, R. Tennessee Valley Authority 2pp 15780 259 24X Fichs 50-438, 82/10/12, 9210220387
- --8210220406 IE Supplemental Investigation Repts 50-438/81-26 & 50-439/81-26 on 820707-08 No noncompliance noted Major areas investigated response to Section 210 of Energy Reorganization Act of 1974 UPYC, 8 MURPHY, D D ALDERSON. C E Region 2. Office of Director 82/09/21 3pp 15780 261 24X Fichs 50-438 82/10/12,82102203H7
- --8210220422 Responds to NRC 820111 ltr re violations noted in IE Investigation Repts 50-438/81-26 2.50-439/81-26 Denies that employee terminated in violation of Energy Reorganization Act 8C procedure revised correcting second violation MILLS,L H Tennessee Valley Authority 82/02/10 0 REILLY,J P Region 2, Office of Director 5pp 13780 244 24X Fiche 50-438.82/10/12.8210220387
- --D210220432 Forwards four exhibits inadvertantly omitted from 820111 ltr transmitting IE Investigation Repts 50-438/81-26 & 50-439/81-26 & ALDERSON.C E Region 2: Atlanta. Office of the Director (81/03/01) 82/01/19 PARRIS.N C Tennessee Valley Authority 6pp 15780 269 24X Fiche 50-438, 82/10/12, 8210220387
- --8210220446 IE Investigation Repts 50-438/81-26 & 50-439/81-26 on 810831-1001 Noncompliance noted employee discharged in violation of Energy Reorganization Act of 1974 & OC not performed in accordance w/Procedure GAP-17 1 VORSE, J Y , ALDERSON C E Region 2, Atlanta, Office of the Director (81/03/01) 81/12/08 24pp 15780 275 24X Fiche 50-438,82/10/12,8210220387
- 6208170238 IE Bulletin 82-03. "Stress Corrosion Cracking in Thick-Wall:Large-Diameter: Stainless Step!, Recirculation Sys Piping at BMR Plants " Svc list encl
 DEYOUNO.R C Director's Office, Office of Inspection and
 Enforcement 82/10/14 Consolidated Edison Co of New York
 115pp 19810 125 24X Fiche 50-000, 82/10/14, 8208170238
- 8210220237 Ack receipt of 820812 & 0924 ltrs informing NRC of steps taken to correct violations noted in IE Insp Repts 50-438/82-22 & 50-439/82-22 LEMIS.R C Division of Project & Resident Programs 82/10/15 PARRIS.H C Tennessee Valley Authority, 1p 15776 206 24X Fiche 50-438.82/10/15.8210220237
- --B210220271 Responds to NRC 820812 ltr re violations noted in IE Insp.
 Repts 50-438/82-22 & 50-437/82-22 Revises 820909 ltr re
 date full compliance expected Compliance will be achieved by
 821220
 MILLS, L. M. Tennesse Valley Authority 82/09/24 D'REILLY, J.P.
 Region 2. Office of Director 2pp 15776 207 24X
 Fiche 50-438, 82/10/15, 8210220237

- S Reportable occurrences, LERs & related correspondence
- \$210010011 Third Interim Deficiency Repts 50-438/81-77 & 50-439/81-76 re allowable stresses for pipe support design Initially reported on 81:207 Deficiency details being evaluated Next rept by 82:1217 MILLS.L M Tennessee Valley Authority 82/09/20 O'REILLY, J.P. Region 2. Office of Director 2pp 15565 148 24X Fiche 50-438.82/09/20,82:0010011
- 821C080222 Second interim deficiency rept re B&W design of RCS supports 5 restraints Initially reported on 820618 Welds & shear bars at interface points potentially undersized Investigation continuing Next rept espected by 821220 MILLS.L H Tennessee Valley Authority 82/09/24 0/REILLY, J P Region 2. Office of Director 2pp 15638 081 24X Fiche 50-438.82/09/24,8210080222
- 6210080247 Third & final deficiency repts re resolution of unanticipated vibratory loading concerns Initially reported on 311228 Program developed to insure piping sys operate within design parameters Next rept provided by 821217 MILLS.L M Tennessee Valley Authority 82/09/24 0'RESILLY, J.P. Region 2. Office of Director 3pp 15638 104 24X Fiche 50-000.82/09/24.8210080247
- 82:10080272 Seventh interim deficiency rept re imprecise specs in util procurement document resulting in improper seismic qualification of B&H equipment in local instrument panels initially reported on 80:125 Util awaiting B&H input MILLS, L M Tennessee Valley Authority 82/09/24 O'REILLY, J P Region 2. Office of Director 2pp 15638 306 24X Fiche 50-438.82/09/24,8210080292
- 3219050115 Fifth interim deficiency rept re failure of boits & nuts to meet ASTM requirements Initially reported on 810924 Engineering interpretation/recommendation awaited Also reported per Part 21 Mext rept expected by 830110 MILLS, LM Tennessee Valley Authority 82/09/27 O'REILLY, J.P. Region 2, Office of Director 2pp 15601 349 24X Fiche 50-438,82/09/27.8210050115
- 3210050117 Supplemental deficiency rept re Lambda power module failures initially reported on 801218 Addl discrepancies identified w/power supplies Corrective action will be completed by 830301 Also reported per Part 21 MILLS.L.B. Tennessee Valley Authority 82/09/27 O'REILLY.J.P. Region 2. Office of Director ip 15601 351 24X Fiche 50-438.82/09/27.8210050119
- 210050074 Fourth interim deficiency rept re seismically unqualified auxiliary bldg fuel handling zone ventilation fans Initially reported on 810506 Contract awarded to provide qualified coils in fans Next rept by 830222 MILLS.L M Tennessee Valley Authority 82/09/28 O'REILLY.J P Region 2. Uffice of Director 2pp 15604 234 24X Fiche 50-438.82/09/28.8210050074
- 210050249 Fanal deficiency rept recuse of insoluble give for purge dams in stainless attel piping initially reported on 820322 Give residue left in piping sign will not cause safety problems Give will dissolve MILLSLL M Tennessee Valley Authority 82/09/28 O'REILLY. J P Region 2. Office of Director 5pp 15607 076 24X Fiche 50-438,8210050247
- Ji0050273 First interin deficiency rept re six sheared motor ginion teys in Linitorque Model \$8:0-25 motor operators Initially reported on £20830 Valves w/motor operators being tabulated Neit ropt will be submitted by 82:122 MILLS.L H Tennessed Valley Authority 62/09/28 O'REILLY, J P Region 2. Office of Director 2pp 15409 070 24X Fiche 50-000, 82/09/28, 82:10050293
- '10050407 First interim deficiency rept re design problems w/steam generators Initially reported on 820830 BM proposed preliminary design change to inject warm feedwater into header Next rept by 821127 Also reportable per Part 21 MILLS.L H Tennessee Valley Authority 82/09/28 O'REILLY. J P Region 2. Office of Director 1p 15603 004 24X Fache 50-438, 82/09/28,8210050407
- '10060274 Seventh interim deficiency rept re discrepancies in IfT Grinnel weld depositions initially reported on 800905 ITT Grinnel revision of affected hanger detail sheets near completion Also reported per Part 21 Next rept by 830315 MILLS.L M Tennessee Valley Authority 82/09/29 D'REILLY, J P Region 2, Office of Director 2pp 15621 178 24X Fiche 50-438, 82/09/29, 8210060274

- 8210080307 Third interim deficiency rept to defective weldalots on NAVCO spool pieces installed in DHR sys & makeup & purification sys iping Initially reported on 820224 Next rept due on 830208 Also reported per Part 21 MILLS.L M Tennessee Valley Authority 82/10/01 D'REILLY.J P Region 2, Office of Director 2pp 15638 119 24X Fiche 50-438 82/10/01, 8210080307
- 8210080140 First interim deficiency rept to corrosion in high pressure fire protection sys Initially reported on 820703 Corrosion analysis in progress to determine potential deficiencies in safety-related areas Next rept expected by 830831 MILLS.L M Tennessee Valley Authority 82/10/04 0'REILLY.J P Region 2, Office of Director 2pp 15640 142 24X Fiche 50-000.82/10/04.8210080160
- 8210080278 Fourth interim deficiency rept re Viking flow control valves in fire protection sys initially reported on 811124 Engineering Change Notice 1584 initiated implementing affected drawing revisions Also reportable per Part 21 MILLS.L N Tennessee Valtey Authority 82/10/04 0'REILLY, J P Region 2. Office of Director 2pp 15608 296 24X Fiche 50-438,82/10/04,8210080278
- 8210130407 Fourth interim deficiency mept nonconservative FSAR analysis for loss of normal feedwater event Initially reported on 810316 ASME code limits will be exceeded fullowing loss of feedwater Also reported per Part 21 MILLS.L M Tennesses Valley Authority 82/10/05 O'REILLY.JP Region 2. Office of Director 2pp 15681 008 24X Fiche 50-438.82/10/05,8210130407
- 8210220071 Final deficiency rept re attachment of pipe supports to 6-inch strip plates Initially reported on Bi1231 Field mods for unacceptable supports scheduled for completion by 831001 MILLS.L H Tennessee Valley Authority 82/10/07 O'REILLY.JP Region 2, Office of Director 2pp 15770 189 24X Fiche 50-438.82/10/07,8210220071
- 8210220350 First interim deficiency rept re diesel generator bldg coble tray support welds made as fillet welds instead of grove welds Initially reported on 820708 Supports being reworked Process spec revised Next rept to be submitted by 830124 MILLS.t. M. Tennessee Valley Authority 82/10/08 O'REILLY, J.P. Region 2. Office of Director 2pp 15776 279 24X Fiche 50-438,82/10/08,8210220350
- 8210190528 Final deficiency rept re overpressurization of makeup & gurification piping & valves Initially reported on 620928 Valves visually examined for signs of distress & site personnel retrained re hydrostatic sys test procedures MILLS.L.M. Tennessee Valley Authority 82/10/12 O'REJLLY, J.P. Region 2, Office of Director 3pp 15751 314 24X Fiche 50-438.82/10/12,8210190528
- 8210270328 Second interim deficiency rept re use of nonconservative calculational method to evaluate General Const Spec G-32 spacing violations initially reported on 820528 Next rept will be sent by 830328 MILLS.L M Tennessee Valley Authority 82/J0/12 O'REILLY.J P Region 2. Office of Director 2ps 19853 064 24X Fiche 50-000.82/10/12.82/0270328

- 8210200322 First interin deficiency rept re generic deficiencies in solid state control sys % basic control room switch modules supplied by Consolidated Controls Corp Initially reported on 820916 Next rept by 830519 Also reported per Part 21 MILLS:L M Tennessee Valley Authority 82/10/18 0'REILLY, J P Region 2. Office of Director 2pp 15799 342 24X Fiche 50-438.82/10/18 8210260322
- B2:10260251 Final deficiency rept re-work releases allowing const to cut reinforcing steel to install anchor bolts for pipe supports [initially reported on 820727 Personnel instructed to review sessign drawings more carefully [MILLS.L.M. Tennesses Valley Authority 82/10/19 0'REILLY, J.P. Region 2 Office of Director 2pp 15799-350 24X Fiche 50-438.82/10/19.8210260251
- FC10260105 Third interim deficiency rept re governor lube oil confer Initially reported on 820308 Supplier has provided drawing procedure to reforate cooler below governor Vendor working to identify cause Also reportable per Part 21 MILLS.L M. Tennessee Valley Authority 82/10/20 D'REILLY, J.P. Region 2. Office of Director 2pp 15799 120 24X Fiche 50-438.82/10/20,8210/260105
- 6210260107 Second interim deficiency rept re failed valve control unit Initially reported on 820727 Vendor has not responded w/recommended disposition Nert rept will contain addition re vendor reply Also reportable per Part 21 MILS L H Tennessee Valley Authority 82/10/20 D'REI(LY, J P Region 2 Office of Director 2pp 15799 117 24X Fiche 50-438,82/10/20,8210260107
- 2210290274 Final rept for Deficiencies B & E & seventh interim rept for Dericiencies A & D re control of procurement activities Initially reported on 810316 Final corrective actions noted Next rept expected by 030428 MILLS.L H Tennesses Valley Authority 82/10/21 0'REILLY, J P Region 2. Office of Director 4pp 15853 143 24X Fiche 50-000 82/10/21.8210270274
- 6210290248 Revised final deficiency rept re structural tubing exceeding AWS allowables Initially reported on BIOBL3 Design drawings which dictate configuration of 86 cable tray supports altered to ensure seismic qualification MILLS, L. H. Tennessee Valley Authority 82/10/22 0'REILLY, J.P. Region 2, Office of Director 3pp 15853 122 24X
- DOCKET 50-439 BELLEFONTE NUCLEAR PLANT, UNIT 2
- A Application/construction stage documents & correspondence
- FZ10Z80013 Responds to FQIA request for all internal.non-public documents.memos.evaluation repts & other matl dealing w/ nuclear plant operations forwards documents listed in App A FELTON.J M Division of Rules and Records 82/09/17 MCINNIS.D Memos & Observer 5pp 15860 065 24X Fishe 50-000.82/09/17.
- --B210280100 Notifies that on 620224.C Alderson advised that rept sent re
 possible willful violation of reporting requirements &
 ralsification of GA & guard qualification records at
 facilities
 RESNER.M.E. Office of Inspector & Auditor B2/03/D1 Office of
 Inspector & Auditor ip 15861 039 24% Fiche 50-000.82/09/1/,
 B210280013
- 5210070348 Forwards responses to NRC 820903 questions on facilities, "Bellefonte Site," "Rept on Old Bellefonte Historical Site in Northern AL" & "Archaeological Survey of Scottsboro Lim Rock idi kV Transmission Line % Fort Payne "MILLS.L M Tennessee Valley Authority 82/10/04 ADENSAM.E Licensing Branch 4 32pp 15664 001 24X Fiche 50-438,82/10/04, 8210070348

- F Security, medical, emergency & fire protection plans
- 8210260189 Confirms that evacuation time estimate study reviewed by both local & TN state authorities Population density & distribution (afo provided by TN Dept of Civil Defense based on 1980 census MILLE, LM Tennessee Valley Authority 82/10/20 ADENSAM, F. G. Licensing Branch 4 2pp 15799 030 24X Fiche 50-000, 82/10/FC.
- O Inspection reports, IE Bulletins & correspondence
- 8210220180 Forwards IE Insp Repts 50-438/82-17 & 50 439/82-17 on 820607-10 & notice of violation LONG, FL Division of Project & Resident Programs 82/06/28 PARRIS.H 0 Tennessee Valley Authority 2pp 157/6 246 2/4x Fiche 50-438,82/06/28,8210220180
- --8210220189 IE Insp Repts 50-438/82-17 to 50-439/82-17 on 82080/-10 Moncompliance noted space heaters not energised on diesel generator IRT-EMB-0010-0 & discrepancies between cable bend radio & vertical cable tray fittings identified HUNT, M D . MERRIMEATHER. N . CONLON. T E Division of Engineering & Technical Programs 82/06/25 Spp 15776 249 24x Fiche 50-438, 82/06/25 890020180
- 8210010039 Advises of upcoming const inspite be conducted during 820720-1001 & 1011-15 Areas to be inspected listed on encl Preinspivist to be held on 820830 to obtain preliminary into LENIS.R C Division of Project & Resident Programs 82/08/31 PARRIS.H 0 Tennesses Valley Authority 3pp 15065 163 24X Fiche 50-438,82/08/31,82(0010039
- B210010421 Ack receipt of B20707 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 90-438/82-12 & 50-439/82-12 VERRELLI, D M Division of Project & Resident Programs 02/09/1/PARTS,N G Tennessee Valley Authority ip 18569 391 24x Fiche 50-438,82/09/17.8210010421
- 8210150149 Forwards IC Insp Repts 50-438/82-27 & 50 439/82-27 on 820830-0903 No noncompliance noted VerreLLI.D M Division of Project & Resident Programs 82/09/21 PARRIS.H Q Tennessee Valley Authority. 2pp 19697 202 24x Fiche 50-438,82/09/21.8210150149
- --8210150164 IE Insp Repts 50-498/82 27 & 50-439/82-27 on 890810 0903 h; noncompliance noted Major areas inspected structural concrete & licensee action on previously identified teems HARRIS, J R. CONLON, T E Division of Engineering & Technical Programs 82/09/17 4pp 15697 284 24X Ciche 50-438.82/09/21.
- 6210010191 Ack receipt of 620913 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-438/82-10 to 50-439/82-10 to ExerctLI.D M Division of Project to Resident Programs 62/09/22 PARRIS.H 0 Tennessee Valley Authority ip 18360 078 24x Ficks 50-438, 82/09/22, 8210010191
- --8210010197 Responds to NRC 820726 ltr re violations noted in IE Insp.
 Repts 50-438/82-18 & 50-439/82-16 Corrective actions 8C
 investigation repts initiated for each discrepant item
 KAMMER, D. S. Tennessee Valley Authority 82/09/13 0/REJLLY, J.P.
 Region 2, Office of Director 3pp 15568 079 24X
 Fiche 50-438,82/09/22,8210010191
- --8210010200 Forwards IE Insp Repts 50-438/82-18 & 50-439/82-18 on 820608-11 & notice of violation M/o notice of violation VERRELLI, D M Division of Project & Resident Programs 92/07/26 PARRIS, H O Tennessee Valley Authority 2pp 15568-082 24x Fiche 50-438,82/09/22,8210010171
- ---8210010203 IE Insp Repts 50-438/82-18 t 50-439/82-18 on 820600-11 Noncompliance noted failure to follow procedure for hanger insps YORK, J W , ECONDMOB, N Division of Engineering & Technical Programs 82/07/23 App 15568 084, 24X Fiche 50-438.82/09/22.
- 82(015017) Ack receipt of 820707 ltr informing NRC of steps talen to correct violations noted in IE Insp Repts 50-436/82-22 to 50-439/82-22 to EMIS.R C Division of Project & Resident Programs 82/09/23 PARRIS.H C Tennesses Valley Authority 1p. 15707 184, 24x Fichs 50-438, 82/09/23, 82(015017)

- --0210150181 Responds to NRC 020812 ltr re violations noted in TE Insp Repts 50-438/02-22 & 50-439/02-22 Corrective actions hold placed on further installation of shielded power cable in cable tray sys Investigation continuing MILLS.L.M Tennessee Valley Authority 02/09/09 O'REILLY, J.P. Region 2. Office of Director 2pp 15707 185 24X Fiche 50-438, 82/09/23.8210150171
- --9210150189 Forwards IE Insp Repts 50-438/82-22 & 50-439/82-22 on 820713-16 & notice of violation LEMIS.R C Division of Project & Resident Programs 82/08/12 PARRIS.H O Tennessee Valley Authority 2pp 15707 187 24) Fiche 50-438,82/09/23-8210150171
- --8210150195 Notice of violation from insp on 820713-14 • Division of Project & Resident Programs 82/08/12 ip 15707 189 24X Fiche 50-438.82/09/23.8210150171
- --8210150207 IE Insp Repts 50-438/82-22 & 50-439/82-22 on 820713-16 Noncompliance noted discrepancies between cable bend radii & vertical cable tray fittings OIBBONS.T S , CONLON.T E Division of Engineering & Technical Programs 82/08/11 3pp 15707 190 24X Fichs 50-438-82/09/23, 8210150171
- 8208190233 IE Info Notice 80-35, Suppl 1, "Leaking & Dislodged I-125 Implant Seeds " Svc list encl COBB.t I Pivision of Fuel Facilities, Materials & Safeguards 82/10/06 Consolidated Edison Co of New York 66pp 15761 250 24% Fiche 50-000,82/10/06,8208190233
- 8210220387 Ack receipt of 820210 ltr re violations noted in IE Supplemental Investigation Repts 50-438/81-26 & 50-439/81-26 on 820707-08 Violation against provisions of Energy Reorganization Act withdrawn O'REILLY, J P Region 2. Office of Director 82/10/12 PARRIS, H & Tennessee Valley Authority 2pp 15780 259 24X Fiche 50-438, 82/10/12.8210220387
- --821022040& IE Supplemental Investigation Repts 50-438/BI-2& & 50-439/BI-2& on 820707-08 No noncompliance noted Major area investigated response to Section 210 of Energy Reorganization Act of 1974
 URYC.B., MURPHY.D.D. ALDERSON.C.E. Region 2. Office of Director 82/09/21 3pp 15780 261 24X Fiche 50-438.82/10/12.8210220387
- --8210220422 Responds to NRC 820111 ltr re violations noted in IE. Investigation Repts 50-438/81-26 & 50-439/81-26 Denies that employee terminated in violation of Energy Reorganization Act 8C procedure revised correcting second violation HILLS/L M Tennessee Valley Authority, 82/02/10 0'REILLY, J P. Region 2. Office of Director 5pp 15780 264 24X Fiche 50-438, 82/10/12, 8210220387
- --B210220432 Forwards four exhibits inedvertantly omitted from 820111 ltr transmitting IE Investigation Repts 50-438/81-26 & 50-439/81-26 & ALDERSON.C E Region 2. Atlanta. Office of the Director (81/03/01) 82/01/19 PARRIS, H O Tennessee Valley Authority opp 15780 269 24% Fiche 50-438,82/10/12,8210220387
- --8210220446 IE Investigation Repts 50-438/81-26 & 50-439/81-26 on 810831+1001. Noncompliance noted employes discharged in violation of Energy Reorganization Act of 1974 & GC not performed in accordance w/Procedure QAP-17 1 VORSE. J Y , ALDERSON, C E. Region 2, Atlanta: Office of the Director (61/03/01) 81/12/08 24pp 13780 275 24X Fiche 50-438,82/10/12,8210220387
- 8208190238 IE Bulletin 82-03, "Stress Corrosion Cracking in Thick-Hall, Large-Diameter: Stainless Steel: Recirculation Sys Piping at BMR Plants "Svc list encl DEYQUNO.R C Director's Office of Inspection and Enforcement 82/10/14 Consolidated Edison Co of New York (15pp. 15810-125 24X Fiche 50-000.82/10/14.8208190238
- 8210220237 Ack receipt of 820812 & 0924 ltrs informing NRC of steps taken to correct violations noted in IE Insp Repts 50-438/82-22 & 50-439/82-22 LEMIS,R C Division of Project & Resident Programs 82/10/15 PARRIS,H O Tennessee Valley Authority ip. 15776 204 24X Fiche 50-438,82/10/15.8210220337
- --B210220271 Responds to NRC B20B12 ltr re violations noted in IE Insp Repts 50-438/82-22 t 50-439/82-22 Revises B20707 ltr re date full compliance expected. Compliance will be achieved by B21220 MILLS.L M. Tennessee Valley Authority B2/09/24 O'REILLY.J P Region 2. Office of Director 2pp 15776 207. 24X Fiche 50-438.82/10/15.8210220237

- S Reportable occurrences. LERs & related correspondence
- 8210080222 Second interim deficiency rept re IMM design of RCS supports to restraints Instially reported on 820618 Welds & shear bars at interface points potentially undersized investigation continuing Next rept supected by 821220 MILLS-L M Tennessee Valley Authority 82/07/24 O'REILLY-J P Region 2, Office of Director 2pp 15638 081 24X Fiche 50-428.82/09/24,8210080222
- 8210080247 Third & final deficiency repts re resolution of unanticipated vibratory loading concerns initially reported on 811228 Program developed to insure piping sys operate within design parameters Next rept provided by 821217 MILLSIL M Tennessee Valley Authority 82/09/24 O'REILLY, J P Region 2, Office of Director 3pp 15638 104 24X Fiche 50-000,82/09/24,8210080247
- 8210080272 Seventh interim deficiency rept re imprecise specs in utiliprocurement document resulting in improper 4eismic qualification of BSW equipment in local instrument panels instially reported on 801/25 Util awaiting BSW input MILLS.L.M. Tennesse Valley Authority 82/07/24 0'REILLY.J.P. Region 2, Office of Director 2pp 15638 306 24% Fiche 50-438,82/07/24,8210880292
- 8210030115 Fifth interin deficiency mept re failure of bolts & nots to meet ASTM requirements Initially reported on 810724 Engineering interpretation/recommendation awaited Also reported per Part 21 Next rept expected by 830110 MILLS, L. M. Tennessee Valley Authority 82/09/27 O'REILLY, J.P. Region 2, Office of Director 2pp 15601 349 24X Fiche 50-438, 62/09/27, 8210050115
- 8210050319 Supplemental deficiency rept re Lambda power module failures Initially reported on 801218 Addl discrepancies identified w/power supplies Corrective action will be completed by 830301 Also reported per Part 21 MILLS.L M Tennesses Valley Authority #22/09/27 D'REILLY, J P Region 2. Office of Director ip 15601 351 24X Fiche 50-438,82/09/27,8210050119
- 8210030074 Fourth interim deficiency rept re seismically unqualified auxiliary bldg fuel handling ione ventilation fans initially reported on 810306 Contract awarded to provide qualified coils in fans Next rept by 630222
 MILLS.L.M. Tennessee Valley Authority 82/07/28 D'REILLY, J.P. Region 2. Dffice of Director 2pp 15604 234 24X
 Fiche 50-438,82/07/28,8210050074
- 8210050249 Final deficiency rept re use of insoluble glue for purge dams in stainless steel piping Instially reported on 820322 Glue residue left in piping sys will not cause safety problems Glue will dissolve HILLS, L M Tennessee Valley Authority 82/09/28 O'REILLY, J P Region 2. Office of Director 5pp 15609 076 24X Fiche 80-438.82/09/28.8210050249

ししくいにっこし こにころり

- 8210080140 First interim defictency rept re corrosion in high pressure sire protection sys Initially reported on 820903 Corrosion analysis in progress to determine potential deficiencies in safety-related areas Next rept expected by 830531 MILLSIL M Tennessee Valley Authority 82/10/04 0/REILLY J P Pegion 2, Office of Director 2pp 15440 142 24X Fiche 50-000, 82/10/04, 8210080160
- 8210080278 Fourth interim deficiency rept to Viking flow control valves in time protection sys Initially reported on 811124 Engineering Change Natice (504 initiated implementing affected drawing revisions Alsa reportable per Part 21 MILLS.L M Tennessee Valley Authority 82/10/04 0'REILLY.J P Region 2. Office of Director 2pp 15638 296 24X Fiche 50-438, 82/10/04, 82(0080278)
- 62:0130407 Fourth interim dericiency rept nonconservative FSAR analysis for loss of normal feedwater event initially reported on 810316 ASME code limits will be exceeded following loss of feedwater Alsa reported per Part 21 MILLS.L M. Tennessee Valley Authority 82/10/05 0'REILLY.J P. Region 2. Office of Director 2pp 15681 008 24% Fiche 50-438,82/10/05.8210130407
- 8210220071 Final deficiency rept re attachment of pipe supports to whinch strip plates Initially reported on 811231 Field mods for unacceptable supports scheduled for completion by 831001 FILLS. A Tennesser Valley Authority 82/10/07 O'REILLY. J P Region 2. Office of Director 2pp 15778 189 24% Fiche 50-438.82/10/07.8210220071
- 8210220350 First interim deficiency rept re diesel generator bldg cable tray support welds made as fillet welds instead of grove welds. Initially reported on 820708 Supports being reworked Process spec revised Next rept to be submitted by 830124 MILLS.L. H. Tennessee Valley Authority 82/10/08 0'REILLY. J.P. Region 2, Office of Director 2pp 15776 273 24X Fiche 50-438 82/10/08.8210220350
- 8210290328 Second interim deficiency rept re use of montonservative calculational method to evaluate General Const Spec G-32 spacing violations Initially reported on 820528 Next rept will be sent by 830528 MILLS, L.M. Tennesses Valley Authority 82/10/12 D'REILLY, J. P. Region 2. Diffice of Director 2pp 15853 064 24X Fiche 50-000, 82/10/12.8210290328
- 52.10270059 Sixth interim deficiency ropt re piping potential safety concern Initially reported on 801121 8kM analyses completed sicept for in-core piping Next rept by 630523 Also reported per Part 21 MILLS.L.M. Tennessee Valley Authority 82/10/14 O'REILLY, J.P. Region 2, Office of Director 2pp 15854 024 24X Fishe 50-438, 62/10/14, 8210290059
- 8210290236 Third interim deficiency rept re-potentially overstressed embedded plates initially reported on 820412 investigation continuing & const activities deferred until sufficient infogathered to determine completion of project MILLS.L M Tennessee Valley Authority 82/10/14 O'REJLLY, J.P. Region 2. Office of Director 2pp 15853 229 24X Fiche 50-000,82/10/14.8210290236
- 9210270324 Third interin deficiency rept re Bresser safety valve. Model 31709NAs suffering unacceptable internal damage during steam test Initially reported on 610707 EPRI & 0&M repts evaluated Also reportable per Part 21 MILLS.L M Tennessee Valley Authority 62/10/14 O/REILLY, J P Region 2. Office of Director 2pp 15853 101 24% Fiche 50-438, 82/10/14,8210270324
- 8210250320 First interim deficiency rept re addition of lacking devices to handwheel operated values Initially reported on 820916 Const activities deferred Analyses of locking devices continuing Next rept will be sent by 820910 MILLS.L M Tennessee Valley Authority 82/10/18 O'REILLY, J.P. Region 2. Office of Director 2pp (5802-359-24X) Fiche 50-000.02/10/18.8210260320
- 8210260322 First interim deficiency rept re generic deficiencies in solid state control sys & basic control room switch modules supplied by Consolidated Controls Corp Initially reported on 820916 Next rept by 830517 Also reported per Part 21 MILLS, L. H. Tennessee Valley Authority 82/10/18 0'REILLY, J.P. Region 2. Office of Director 2pp 15799 342 24X Fiche 50-438.82/10/18.8210260322
- 8210260251 Final deficiency rept rework releases allowing const to cut reinforcing steel to install anchor builts for pipe supports. Initially reported on 820727 Personnel instructed to review design drawings more carefully MILLS.L.M. Tennessee Valley Authority 82/10/19 O'REILLY, J.P. Region 2, Office of Director app 15799 350 24X Fiche 50-438.82/10/19.8210260251

- 8210260105 Third interim deficiency rept re governor lube oil cooler Initially reported on 820308 Supplier has provided drawing by procedure to relocate cooler below governor Vendor working to identify cause Also reportable per Part 2! MILLS.L. H. Tennessee Valley Authority 82/10/20 0'REILLY, J. P. Region 2. Office of Director 2pp 15797 120 24X Fiche 50-438, 82/10/20.8210260105
- 6210290274 Final rept for Deficiencies B & E & seventh interim rept for Deficiencies A & D re control of procurement activities. Initially reported on 810316 Final corrective actions noted Nert rept expected by 830428
 MILLS.C. M Tennessee Valley Authority 62/10/21 D'REJLLY, J.P. Region 2. Office of Director 4pp 15853 143 24X
 Fiche 50-000, 82/10/21, 8210270274
- 8210270248 Revised final deficiency ropt re structural tubing entering AMS allowables Initially reported on BIOBIS Design drawings which dictate configuration of 86 cable tray supports altered to ensure seismic qualification MILLS: L. K. Tennessee Valley Authority 82/10/22 0'REILLY, J. P. Region 2. Office of Director 3pp 15853 122 24X Fiche 50-438, 82/10/22, 8210270248
- DOCKET 50-440 PERRY NUCLEAR POWER PLANT, UNIT 1

 A Application/construction stage documents & correspondence
- 8210130010 Requests submittal of addl fee for 820721 application for extension of const completion dates
 DIGOS.R Literase Fee Management Branch 82/09/27 DAVIDSOM.D R
 Cleveland Electric Illuminating Co 1p 15492 332 24X
 Fiche 50-440. 82/09/27, 8210130010
- 8210130179 Advises that response to NRC 820906 ltr re degraded core hydrogen control will be provided by 821201 DAVIDSON.D R Cleveland Electric Illuminating Co. 82/09/29 SCHHERGER,A Licensing Dranch 2 ip 13673 019 24X Fiche 50-440,82/09/29,8210130179
- 8210190326 Forwards slide presentation from 820813 meeting re-safety relief hydrodynamic loads Position similar to criteria outlined in NURES-0763 Encls withheld (ref 100FR2 790) DAVIDSON, D. R. Cleveland Electric Illuminating Co. 82/10/08 SCHWENCER, A. Licensing Branch 2 2pp 15742 059 24X Fiche 50-440,82/10/08,8210170326
- 6210260419 Forwards NEDE-22203, "Reactor Internals Vibration Predictions." dtd Aug 1982 Rept contains proprietary infore internals vibration program & peak amplitude predictions per engineering analysis Rept withheld (ref 105F82 790) DAVIDSON, D.R. Cleveland Electric Illuminating Co. 62/10/08 SCHMENGER, A. Licensing Branch 2 ip 15806 114 24X Fiche 50-440,82/10/08.8210260419
- 8210190619 Confirms 821006 telcon re preoperational testing program
 Util not required to continue sending preliminary
 preoperational test procedures Current status of procedures
 & implementation will be forwarded monthly
 LITLE:W 8 Division of Engineering & Technical Programs 89/10/15
 HICKS,0 R Cleveland Electric Illuminating Co (p 15737 223)
 24% Fiche 50-440.82/10/15.8210190619
- 8210210077 Forwards proprietary util 821008 ltr & attachments resisting relief valve hydrodynamic loads, inadvertently omitted from original submittal Nonproprietary info to be provided by 82105
 0AVIDSON, D.R. Cleveland Electric Illuminating Go. 82/10/15
 SCHWENCER.A. Licensing Branch 2 ip 15762 235 24X
 Fiche 50-440, 82/10/15,8210210079
- 8210270073 Notification of 821109 meeting w/util,C-E & OAJ in Bitheld MD to discuss pool dynamic load criteria application to plant specific design STEFANO. J Licensing Branch 2 82/10/19 SCHWENCER.A Licensing Branch 2 3pp 15836 296 24X Fiche 50-440.82/10/19.8210270073
- D NRC Draft/Final Environmental Statements, suppls & correspondence
- 8210260235 Comments on FES for facility Applicant aware of effluent limits No add1 adverse environ impacts within EPA field of expertise anticipated BACKLEY. B T Environmental Protection Agency 82/10/19 SCHHENGER. A Licensing Branch 2, 1p 15799 354 24X Fiche 50-440.82/10/19.8210260235,

RRC Safety Evaluation Report (SER), supply & correspondence

2:0150230 Forwards response to SER Confirmmatory Issue 16 re beltline weld matts Info review response to Questions 123 1,123 2 & 123 3 & should resolve issue of matt surveillance capsules DAYIDSON, D R Cleveland Electric Illuminating Co 82/09/22 SCHMENCER.A Licensing Branch 2 42pp 15706 010 24X Fiche 50-440,82/09/22,8210150233

210130173 Advises that responses to NRC 820708 itr re SCR Outstanding Issue 21 concerning reanalysis of transients & accidents & development of emergency operating procedures will be provided by 821027
DAVIDSON.D R Cleveland Electric Illuminating Co 82/09/28
SCHWENCER, A Licensing Branch 2 tp 15673 044 24χ
Fiche 90-440, β2/09/28,8210130173

210190333 Responds to SER Confirmatory Items 32 & 45 re accident monitoring instrumentation & location of plant area radiation monitoring instrumentation Items also address THI Items II F 1 3. II F 1 4. II F 1 5 & II F 1 6
DAVIDSON, D.R. Cleveland Electric Illuminating Co. 82/10/14
SCHHENCER, A. Licensing Branch 2 3pp 15742 120 24X
Fiche 50-440. 82/10/14.8210190333

210170883 Forwards response to SER Confirmatory Issues 28,30 & 33 re instrumentation & control Three dversize drawings encl Aparture cards are available in PDR DAVIDSON, D.R. Cleveland Electric Illuminating Co. 82/10/14 SCHMENCER.A. Licensing Brench 2 &pp. 15791 013 24X Fiche 50-440, 82/10/14.8210170683

Security, medical, emergency & fire protection plans

'O7180055 FOIA request for all documents since 1979 re drug or alcohol abuse by persons at facilities SANICKI,S G News-Herald Milloughby, OH B2/08/30 FELTON, J M Division of Rules and Records ip 1975B 359 24X Fiche 50-440, 62/08/30, 820/180055

10170179 Responds to FOIA request for all documents since 1979 redrug or alcohol abuse by persons at facilities Forwards documents identified during 820713 telcon FELTON. J M Division of Rules and Records, 82/09/15 SAHICKI, 8 G Rews-Herald Willoughby, 0H 1p 15758 360 24X Fiche 50-440, 82/09/15, 8210170199

8210170204 Provides info re drug & alcohol abuse, fire support deficiencies, theft & forced entry observed at facilities Author name delated * Affiliation Unknown 82/09/15 NRC - No Detailed Affiliation Oiven 2pp 18758 361 24X Fiche 50-440,82/09/15,8210190199

8210190209 Ack receipt of itr expressing concerns re security administration at facility NRC does not impose security requirements on licensee prior to onsite receipt of reactor fuel Contacting util suggested info partially deleted PHILLIP, 0 A Region 3, Chicago, Office of the Director (81/03/01) 81/07/16 Affiliation Unknown ip 15758 363 24% Fiche 50-440,82/09/15,8210190199

i0(90011 Notification of 821006 meeting w/util in Dethesda.MD to discuss responses to NRC questions re emergency plan & status of plan finalization STEFANO.J Licensing Branch 2 82/09/23 SCHWENCER, A Licensin Branch 2 3pp 15760 318 24X Fiche 50-440.82/09/23,8210190011

10260572 Releases public version of revised emergency plan FELTON.J M Division of Rules and Records 82/10/08 Document Management Branch 1p 15832 026 24X Fiche 50-440,82/10/08. 8210260572

B210260575 Forwards public version of Revision O to emergency plan DAVIDBON, D. R. Commonwealth Edison Co. B2/09/22 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 15832 027 24X Ficha 50-440, 82/10/08, B210260572

3210240579 Public version of Revision O to emergency plan
+ Commonwe with Edison Co 82/09/22 29/pp 15832 029 24X
Fiche 50-440, 82/10/08.821024057

Adjudicatory correspondence

10070075 Forwards responses to interrogatories from Sunflower Alliance requiring FEMA reply (RIMM, R W Federal Emergency Management Agency 82/09/09 RIMES, B K Division of Emergency Preparedness 35pp 15428 127 24X Fiche 50~440.82/09/09.8210070075

8210010335 Reply to applicant 820921 motion to amend ASLB 820916 memorandum & order re-scheduling Moving filing date of testimony will prejudice intervenors Applicant suggestion to delay hearing until 800222 should be granted HIATT.S.L. Ohio Citizens for Responsible Energy 82/09/27 Atomic Safety and Liconsing Board Panel 1p 15569 163 24X Fiche 50-440, 82/09/27, 8210010335

8210010366 Seventh set of interrogatories Certificate of Svc enci Related correspondence HIATT,6 L Dhio Citizens for Responsible Energy 82/09/27 Office of the Executive Legal Director 8pp 15573 095 24X Fische 50-440,82/09/27,8210010366

8210010377 Reply opposing applicant 820913 motion to rescind ASLD B10804 procedural order requiring intervenors to respond to NRC & applicant answers to late filed contentions Certificate of Svc encl HIATT, 6 L Ohio Citizens for Responsible Energy 82/09/27 Atomic Safety and Licensing Board Panel 5pp 15573 054 24X Fiche 50-440,82/09/27,8210010377

8210010386 Requests article from Nuclear News noted in ASLB 820916 memorandum & order by provided to all parties since magazine unavailable in public & univ libraries HIATT & L. Ohio Citizens for Responsible Enorgy 82/09/27 BLOCH, P. B. KLINE, J. R. SHON, F. J. Atomic Safety and Licensing Board Panel 1p 15569 212 24X Fiche 50-440,82/09/27,8210010386

8210010416 Sixth set of interrogatories Certificate of Svt entl Related correspondence HIATT'S t. Dhio Citizens for Responsible Energy 82/09/27 Cleveland Electric Illuminating Co tOpp 15372 173 24x Fiche 50~440.82/09/27.8210010416

82:00:10250 Response apposing applicant motion to revise procedures for late filed contentions No prejudice demonstrated Proof of Svc encl HILT.D D Sunflower Alliance HILT.D D Hilt, D D 82/09/28 Atomic Safety and Licensing Board Panel 2pp 15568 262 24X Fichs 50~440,02/09/28,82:100:10250

8210010323 Motion for 5-day extension to file motion to compel discovery against NRC Addl time necessary due to other business & personal illness Fronf of Bruc encl WILT-D D Sunftower Alliance WILT-D D Wilt, D D 82/09/28 Atomic Safety and Licensing Board Panel Ip 15569 192 24X Fiche 50-440,82/09/28,8210010223

BRIGO10345 Answer to fourth set of interrogatories Certificate of Svc encl MILLMORE, R. L. Cleveland Electric [lluminating Co. WILLMORE, R. L. Shaw, Pittman, Potts & Trowbridge 82/09/28 Ohio Citizens for Responsible Energy 17pp 15574 001 24% Fiche 50-440,82/09/28, 8210010345

8210010457 Forwards RF Zucker & RA Pender original affidavits to be substituted for photocopies in applicant 820728 answer to OH Citizens for Responsible Energy fourth set of interrogatories Related correspondence WILLMORE.R L Shaw, Pittman, Potts & Trowbridge WILLMORE.R L Cleveland Electric Illuminating Co 82/09/29 Docketing & Services Branch 3pp 15572 311 24X Fiche 50-440,82/09/29,8210060457

8210040019 Notice of withdrawal of appearance in proceeding LEWIS, S. H. Hearing Branch 2 82/09/29 3pp 15581 262 24X Fiche 50-440,82/09/29,8210040019

B210040019 Certifies svc of NRC response to Sunflower Alliance motion seeying admission of late contention on shift rotation & GE Johnson notice of appearance on B20930 JOHNSON, 0 E Hearing Dranch 4 82/09/30 2pp 15581 348 24X Fiche 50-440, 82/09/30, 8210040015

8210040017 Response opposing Sunflower Alliance 820910 motion seeking admission of late contention on shift rotation Contention beyond Commission regulatory requirements, lacks basis & nexus & is untimely JOHNBON, 9 E Hearing Branch 4 82/09/30 Atomic Sefety and Licensing Board Panel 8pp 15581 297 24X Fiche 50-440,82/09/30,8210040017

B210040023 Notice of appearance in proceeding JOHN5DN, G E Hearing Branch 4 B2/09/30 1p 15581 256 24X Fichs. 50-440, B2/09/30, B210040023

8210050173 Third set of interrogatories re Issue 3 & requests for production of documents Proof of Svc enci Related correspondence WILT.D D Sunflower Alliance WILT.D D Wilt, D D 82/09/30 NRC - No Detailed Affiliation Olven 7pp 15604 138 24X Fiches 50-440.82/09/30,8210050173

- 8210050228 Fourth request for production of documents re Contention L. counted routh request for production of documents re Coni Issue 1 on energency evacuation planning Proof of Svc encl Related correspondence WICTO D Sunflower Alliance HILT.DD Wilt. DD 02/C Office of the Elecutive Director for Operations 2pp 150 24/ Fiche 50-440, 92/09/30, 82/0050228 HILT. D.D. Wilt. D.D. 02/07/30
 - 15610 351
- 8210050242 Requests extension of discovery time on Contention 1 lessee not ready for hearing as final emergency plans not yet in place Plans must be reviewed prior to hearing Proof of Svc WILT.D.D. Sunflower Alliance WiLT.D.D. Wilt, D.D. 82/0 Atomic Safety and Licensing Board Panel 2pp 15610 334 Fiche 50-440, 82/09/30, 8210050242 82/09/30
- 5210050252 Third set of interrogatories w/requests for production of property intra set of interrogatories wirequest for production focuments re Issue 3 on adequacy of applicant QA program Froof of Svc encl Related correspondence WILT.D D Wilt.D D 82/09/30 (Eeveland Electric Illuminating Co 12pp 15610 274 24X Fiche 50-440, 82/09/30, 8210050252
- 8210050255 Third set of interrogatories & request for production of documents re Issues 1,3 & 11 on offsite emergency evacuation plans OA & local economic benefits respectively Certificate of Syc encl WILLPORE R L Cleveland Electric Illuminating Co WILLMORE, R L Shaw, Pittman, Potts & Trowbridge 82/09/30 Sunflower Atliance 12pp 15609 199 24x Firne 50-440.82/09/30.8210050255
- 6210050374 Response in opposition to Sunflower Alliance. Inc 820910 motion to compel applicant answer to second set of interrogatories Applicants will respond shortly Certificate of Sic encl
 Silbero, JE Cleveland Electric Illuminating Co Silbero, JE
 Thombsides 82/09/30 Atomic Safety and Shaw, Pattman, Potts & Troubridge 82/09/30 Atomic Safety and Licensing Board Panel 20pp 15608 256 24X Fiche 50-440,88/09/30, 8210050374
- 8210050207 Seventh set of interrogatories directed to applicant & eighth set of interrogatories directed to MRC.pursuant to ASLB 810728 Memorandum & Order, LOP-81-24 Certificate of Svc entl Related correspondence HIATLS L. Dhio Citizens for Responsible Energy 82/09/30 Cleveland Electric Bliuminating Co. 5pp. 10614-157 24X Fiche 50-440, 82/09/30, 8210060207
- 82100500A9 Response supporting applicant 820913 mation to revise procedures for late filed contentions Allowing intervenors to raise new matter in reply constitutes amend to contentions Certificate of 80c sect CUTCHIN.J M Hearing Dranch 4 82/10/04 Atomic Safety and Licensing Poard Panel 8pp 19603 f88 24% Fiche 50-440.82/10/04, 8210050069
- 8210150192 Requests clarification of doctet numbers for Harris & Petry plants Mixup may be causing prejudice to intervenars since documents go to incorrect LPDR HIAIT.S L Ohio Citizens for Responsible Energy 82/10/04 Docteting & Services Branch ip 15707 260 24% Fishe 50-000.82/10/04,9210150192
- 8210040303 Response opposing CH Citizens for Responsible Energy 820920 motion to compet discovery of NRC 5 util ASLB chairman comments did not allow intervenors to breaden contention or scope of discovery CUTCHIN. J M Hearing Branch 4 82/10/05 Atomic Safety and Licensing Board Panel Sep 15617 017 24X Fiche 50-440,82/10/05, 8210060303

- 8210150161 Confirms B21005 teleon re time for filing util response to OH Citizens for Responsible Energy motion to compel answers to Sunflower second set of interrogatories Answer to be filed by 821012 Svc list encl Related correspondence SILBERG, J E Shaw, Pittman, Potts & Troubridge SILBERG, J E Cleveland Electric Illuminating Co 82/10/06 HIATT, B Ohio citizens for Responsible Energy 2pp 15697 067 24% Fiche 50-440,82/10/06,8210150161
- 8210120337 Hemorandum & order denying Sunflower Alliance, Inc 820930 request for extension of time for discovery on Issue I Info has been made available BUDCH.P B Atomic Safety and Licensing Board Panel 82/10/08 Sunflower Alliance IP 15652 183 24X Fiche 50~440,82/10/08,8210120337
- 8210130327 Memorandum & order denging OH Citizens for Responsible Energy 820907 motion to sever proceedings No reason provided for ASLB to reconsider 810909 ruling on identical motion by Synflower Alliance OLOCH, P B Atomic Safety and Licensing Board Panel 82/10/00 Ohio Citizens for Responsible Energy ip 15478 283 24X Fiche 50-440, 82/10/08, 8210130329
- 8210130333 Memorandum & order admitting Contention 12 re inadequals consideration of economic consequences of accidents Preponderance of considerations favors admission of contention
 BLOCKLP B , KLINE, J R , SHON, F J Atomic Safety and Licensing Braid
 Panel B2/10/08 Ohio Citizens for Responsible Energy 3pp
 15682 059 24X Fiche 50-440.82/10/08.8210130333
- 8210150228 Confirms conversations w/OH Citizens for Responsible Energy 2:0150228 Confirms conversations w/OH Citizens for Responsible Energy

 **X Judge Black re extension of time for util to respond to
 OH Citizens for Responsible Energy 820920 motion to compel
 discovery on NRC & util Response due 821018 M/svc list
 SILBERG.J E Shaw, Pittman. Potts & Troubridge SILBERG.J E
 Cleveland Electric Jiluminating Co 82/10/08 BLOCH.P B ,
 KLINE.J R , SHON.F J Atomic 84fety and Licensing Board Panel 4);
 15706 008 24% Fiche 50-440.82/10/08.8210150228
- 8210150467 Answer to sixth set of interrogatories Certificate of Bur enci WILLMORE.R L. Glevelend Electric Illuminating Co. WILLMORE.R L. Shaw, Pittman, Potts & Trowbridge 82/10/12 Ohio Citizens for Responsible Energy 10pp 15703 050 24% Fiche 50-440.82/10/12.
- 8210180211 Reply opposing NRC & applicant responses to OH Citizens for Responsible Energy motion for leave to file Contentions 21-26 Good cause specificity & basis requirements met ZI-Zo vdou couser specificity & deals requirements mee Centificate of Svc encl HIATT, 8 L Ohio Citizens for Responsible Energy 82/10/12 Atomic Bafety and Licensing Board Panel 14pp 15718 110 24X Fiche 50-440 82/10/12, 8210180211
- 8210150175 Advises that documents requested by Sunflower Alliance fourth request directed to Executive Director for Operations available in PDR evel-sock in Fun CUICHIN, J M Hearing Branch 4 82/10/13 WLLT, D D Wilt, D P WILT, D D Sunflower Alliance ip 15707 183 24X Fiche 50-440, 82/10/13, 8210150175
- 210130275 Advises that NRC will not voluntarily respond to any discovery requests in Sunflower Alliance third set of interrogatories & requests for documents except Request 17 Remainder of discovery broader than Issue 3 CUICHIN.J M Hearing Branch 4 82/10/13 HILT.D D Willt.D D Sunflower Alliance 3pp 15705-001 24X Fiche 50-440, 82/10/13, 8210150275 8210150275 Advises that NRC will not voluntarily respond to any
- 8210180155 Advises of correction to util response to Interrogatory 68 of OH Citizens for Responsible Energy sixth sat of interrogatories Conclusion of response remains unchanged Interrogatories Conclusion of response remains unitarily Related correspondence WILLMORE, R. L. Bhaw, Pittman, Potts & Trombridge WILLMORE, R. L. Cleveland Electric Illuminating Co. 82/10/14 HIATT, B. Ohio Citizens for Responsible Energy. Ip. 15719 269 24X Fiche 50-440. 82/10/14, 8210180155
- 8210190377 Answers to 820907 Fifth set of interrogatories Prof qualifications & Gentificate of Svt encl JOHNSON O E Operations & Administrative Division 82/10/15 Ohio Cititens for Responsible Energy 15pp 19740 300 24% Fichs 50-440-82/10/15,8210190377
- 8210190475 Answer opposing Sunflower Alliance SR09RS motion to extentime to file motion to compel discovery against NRC No besis for unlimited request provided Certificate of Svc encl CUTCHIN-J M Hearing Branch 4 82/10/15 Atomic Safety and Licensing Board Panel, 4pp 15740 241 24x Fiche 50-440-82/10/15 0010190475

- 8210210351 Dbjects to issuance of ASLB 821008 memorandum & order re request to extend discovery on Issue 1 Order issued ASLB should request responses from all parties on expedited schedule W/Certificate of 8vc Related correspondence HIATT.S L Dhio Citizens for Responsible Energy 82/10/15 BLOCH.P B . KLINE,J R . SHON,F J Atomic Safety and Licensing Bourd Panel 1p 15764 010 24X Fiche 50-440, 82/10/15, 8210210351
- --8210210358 Seventh discovery progress rept.pursuant to ASLB 810909 memorandum & order.LBP-81-35 Interrogatories submitted to applicant & NRC re Issues 4.5.6.7.8 & 9 Discovery re Issue 9 forthcoming HIATT.S L Dio Citizens for Responsible Energy 82/10/15 2pp 15764 011 24X Fiche 50-440, 82/10/15.8210210351
- --0210210366 Motion to extend discovery on Issue 9 to 821101 to permit review of documents referenced in applicant responses to 820830 interragatories & followed discovery Certificate of 8vc encl Related correspondence
 HIATT.S.L. Onto Citizens for Responsible Energy 82/10/15
 Atomic Bafety and Licensing Board Panel 3pp 15764 013 24X
 Fiche 50-440,82/10/15,821021035
- 8210210284 Answer opposing DH Citizens for Responsible Energy 820920 motion to compel discovery on NRC & util Interrogatories not relevant to & beyond scope of Issue & Certificate of Svc encl Related correspondence
 STLBERG. J E Gleveland Electric Illuminating Co GILBERG. J E Shaw, Pittman, Potts & Trombridge 82/10/18 Atomic Safety and Licensing Board Panel 36pp 15765 099 24X Fiche 50~440, 82/10/18, 0210210264
- 3210210333 Amended answer to Interrogatory 13 of Sunflower Alliance second set of interrogatories Certificate of Svc encl Related correspondence SILBERO, J E Cleveland Electric Illuminating Co SILBERO, J E Shaw, Pittman, Potts & Trowbridge 82/10/19 Sunflower Alliance Spp 15763 177 24% Fiche 50-440.82/10/18.621020353
- 3210220481 Requests attachment to NRC 780203 Itr to GE be provided to allow progress on Issue 4 Document needed before intervenor can decide if updates to interrogatories necessary Related correspondence HIATLE L. Ohio Citizens for Responsible Energy 82/10/18 SILDERO, J. Shaw, Pittman, Potts & Trowbridge BILDERO, J. Clevelam Electric Illuminating Co. ip. 15779-078 24X Fiche 50-440, 82/10/18-8210220481
- 3210210476 Memorandum & order denying Sunflower Alliance 820910 motion to compel applicant to answer second set of interrogatories If util agrees to stipulation on potassium iodide subcontention, Interrogatory 36 need not be answered BLOCH, P II * KLINE, J R . SHON.F J Atomic 8afety and Licensing Board Panel 82/10/19 Cleveland Electric Illuminating Co 6pp 15762 265 24X Fiche 30-440,82/10/19.8210210476
- 1210220309 Seventh discovery progress rept Certificate of Evc encl HILLMORE.R L Cleveland Electric Illuminating Co WILLMORE.R L Shaw, Pittman, Potts & Troubridge 82/10/19 4pp 15776 049 24) Fiche 50-440, 82/10/19, 8210220309
- 1210220396 Hotion for leave to file answer to OH Citizens for Responsible Energy (OGRE) 821012 reply to util & NRC answers to DCRE motion for leave to file Contentions 21-26 WILLMORE, R L Cleveland Electric Filuminating Co WILLMORE, R L Shaw, Pittman, Potts & Troubridge 82/10/19 Atomic Safety and Licensing Board Panel 2pp 15777 312 24X Fiche 50-440,82/10/19,8210220396
- -8210220405 Answer to CH Citizens for Responsible Energy 821012 reply to NRC & applicant response to Citizens motion to file Contentions 21 through 26 Citizens did not meet burden of proof for admission of new contentions WCertificate of Svc WILLHORE.R L. Cleveland Electric Illuminating Co WILLMORE.R L. Shaw. Pittman. Potts & Trowbridge 82/10/19 Atomic Bafety and Licensing Board Panel 15pp 15777 314 24X Fiche 50-440, 82/10/19, 8210220396
- 1210250331 Reply brief supporting motion to submit addition to submit addition food cause for late filing demonstrated Applicant shift rotation plans may not be incorporating circadian principles WILT, D.D. Bunflower Alliance, WILT, D.D. Wilt, D.D. B2/10/19 Atomic Safety and Licensing Board Fanel 3pp 15790.325 24X Fiche, 50-440, 82/10/17, 8210250331

- 8210250299 Answer to OH Citizens for Responsible Energy 821015 motion to extend discovery on Issue 9 repolymer degradation No justification exists for extending discovery cutoff date Certificate of Svc encl SILBERG, J E Cleveland Electric Illuminating Co SILBERG, J E Shaw, Pittman, Potts & Troubridge 82/10/20 Atomic Safety and Licensing Board Panel Spp 15790 195 24X Fiche 50-440,82/10/20,82(0250299
- 8210250322 Supplemental answers to Sunflower Alliance. Inc second set of interrogatories Certificate of Svc encl
 SILBERO. J. E. Cleveland Electric Illuminating Co. SILBERG. J. E. Shaw. Pittman, Potts & Trowbridge 82/10/20
- 8210250365 Advises that NRC will not voluntarily respond to CH Citizentor Responsible Energy seventh set of interrogatories except for interrogatories listed Requests irrelevant & will not lead to discovery of admissible evidence CUTCHIN.J M Hearing Branch 4 82/10/22 HIATT.5 L Chio Citizentor Responsible Energy 2pp 15790 175 24X Fiche 50-440.82/10/2/, 8210250365
- 8210260033 Answers to 820830 fourth set of documents Certificate of Svi enc! MRIOHT, N.A. Hearing Branch 2 82/10/22 Ohio Citizens for Responsible Energy 12pp 15799 124 24X Fiche 50-440, 82/10/소스. 8210240033
- 821028021A Responds to 821018 ltr resvo of documents to parties Telcons could expedite matters in future Svo list encl Related correspondence SILBERO, J.E. Shaw, Pittman, Potts & Trombridge 82/10/22 MIATT, B.L. Ohio Citizens for Responsible Energy 7pp 1583/356 24X Fiche 30-440,82/10/22-8210280216
- 8210280231 Update to response to Interrogatory 4-2 of OH Citizens for Responsible Energy 820928 fourth set of interrogatories Related correspondence WILLMORE.R L. Bhaw. Pittman. Potts & Trowbridge WILLMORE.R L. Cleveland Electric Illuminating Co. 82/10/22 HIATT.S. Ohio. Citizens for Responsible Energy Ip. 15837-081 24X Fiche 80-440.82/10/22,8210280231
- 8210260383 Answers to listed interrogatories of 820727 seventh set of interrogatories NRC will not voluntarily answer remaining interrogatories Certificate of Svc encl CUTCHIN.J M. Hearing Branch 4 82/10/25 Ohio Citizens for Responsible Energy Tipp 15803 348 24X Fiche 50-440,82/10/25,
- 8210260395 Discovery rept for previous two months per ASLB 810909 memorandum & order CUTCHIN, J M Hearing Branck 4 82/10/25 BLOCK, P D . SHON, F J . KLINE, J R Atomic Safety and Licensing Board Panel ip 15803 34J 24X Fiche 50-440,82/10/25,8210260395
- 8210280246 Forwards RB Coffey original affidavit to be included in applicant 821020 supplemental answers to Sunflower Alliance second set of interrogatories Related correspondence HILLMORE.R L. Shaw. Pittman. Potts & Troubridge WILLMORE.R L. Cleveland Electric Illuminating Co 82/10/25 Docketing & Bervices Branch 2pp 15837 094 24X Fiche 50-440.82/10/25. 8210280246
- B210290287 Requests encl RF Zucker & RV Tanney original affidavits he substituted for photocopies in applicant 821019 answers to OH Citizens for Responsible Energy seventh set of interrogatories will MORE, R L. Shaw, Pittman, Potts & Trowbridge WILLMORE, R L. Cieveland Electric Illuminating Co 82/10/26 Docketing & Bervices Branch 3pp 15854 069 24X Fichs 50-440,82/10/26,82/10/2087.
- 8210280346 Answer apposing OH Citizens for Responsible Energy 821015 motion to extend time for discovery on Issue 9 No Justification for extension provided Certificate of 8vc encl CUTCHIN, J M Hearing Branch 4 82/10/27 Atomic Safety and Licensing Board Panel, 5pp 15838-301 24X Fiche 50-440.82/10/27, 8210280346
- K Utility Final Bafety Analysis Report (FSAR) & amonds
- 8210040146 Forwards Amend 9 to FBAR Certificate of Svc encl. DAVIDSON D R Cleveland Electric Illuminating Co 82/09/20 DENTON H R Office of Nuclear Reactor Regulation, Director 3pp 15584:251 24X Fiche. 50-440,82/09/20/8210040146
- --8210040130 Amend 9 to FBAR 4 Cleveland Ejectric Illuminating Co 82/09/30 573pp 15884 254. 24% Fiche 50-440,82/09/30.8210040144

H Antitrust correspondence

- 6210120268 Confirms 821007 telcon & forwards NRC 820809 ltr to City of Cleveland, Div of Light & Power 820708 % 10 responses VOGLER.B H Hearing Branch 2 82/10/08 LAMSDALE.J Squire, Sanders % Denpsey ip 15652 318 24X Fiche 50-440.82/10/08.82/10/068.82/10/068
- u Inspection reports. IE Bulletins & correspondence
- 8210060305 Forwards 1E insp Repts 50-440/82-11 & 50-441/82-10 on 820931-0902 No noncompliance naked LITTLE.U 5 Division of Engineering & Technical Programs 82/09/22 DAVIDSON: D R Cleveland Electric Illuminating Co 2pp 15619 195 24X Fiche 50-440 82/09/22.8210040305
- --8210060308 IE Insp Repts 50-440/82-11 & 50-441/82-10 on 820831-0902 Nu noncompliance noted Major areas inspected preservice inspected of the surfactivities, previous inspected preservice inspected of the surfactivities, previous inspected program in IE Gulletin 80-08 activities, previous inspected program in IR Region 3. Office of Director 82/09/14 Spp 15419 197 24% Fiche 50-440.62/09/22.8210060305
- 8210190763 Forwards IE Investigation Repts 50-440/81-19 & 50-441/81-19 on 611027-820319 & notice of violation PEPPLER, J G Region 3. Office of Director 82/09/27 DAVIDSON, D R Cleveland Electric Illuminating Co 3pp 15736 318 24% Fische 50-440, 82/09/27, 8210190763
- --8210190771 Notice of violation from investigation on 011027-820319 KEPPLER.J O Region 3. Office of Director 92/09/24 9pp 15736 321 24% Fiche 50-440, 82/09/27, 8210190763
- --8210190787 IE Investigation Repts 50-440/81-19 % 50-441/81-19 on 811027-820319 Noncompliance noted Gould Inc Drawings E-35-51-758 E231 & E233 inadequately reviewed & instructions not incorporated into cable pulling procedures WEIL.C H. NAIDU.K P. BRAWND.C D. Region 3. Office of Director 82/09/22 95pp 15736 330 24X Fiche 50-440.82/09/27,8210170/63
- 8208[902]3 IE Info Notice 80-35, Suppl 1, "Leaking & Dislodged 1-12"; Implant Seeds " Svc list enc! COBB.L I Division of Fue) Facilities, Materials & Safeguards 82/19/06 Consolidated Edison Co of New York 66pp 15761 250 24% Fiche 50-000 82/10/06,8208190233
- 820B190238 IE Builetin 82-03, "Stress Corrosion Cracking in Thick-Wall, Large-Diameter, Stainless Steel, Recurculation Sys Piping at BUR Plants " Svc list ent! DEYOUNGER C Director's Office of Inspection and Enforcement 82/10/14 Consolidated Ediston Co of New York 115pp 15810 125 24x Fiche 50-000.82/10/14.8208190238
- 8210260333 Ack receipt of 821008 ltr informing NRC of steps taken to correct violations noted in IE insp Repts 50-440/82-09 h 50-441/82-09 h 100 NRELIUS.C E Division of Project b Resident Programs 82/10/21 DAVIDSON, D R Cleveland Electric Illuminating Co ip 15803 191 24x Fiche 50-440.82/10/21.8210260333
- --9210260337 Responds to NRC 820910 ltr reviolations noted in IE Insp Repts 50-440/62-09 & 50-441/62-08 Corrective actions Kaiser Engineer Procedure GAP-22 revised to require annual evaluation Detailed hardware insp performed 820728 DAVIDSON D R Cleveland Electric Illuminating Co 82/10/08 NORELIUS.C E Division of Project & Resident Programs 6pp 15803 192 24X Fiche 50-440, 82/10/21.8210260333
- S Reportable occurrences. LERs & related correspondence
- 8210050132 Final deficiency rept to nonconforming Transamerica Dalava) standby diesel generator ASNE Section III.Class 3.piping welds initially reported on 820329 Weld insp & required repair/rework will be completed by 830401 DAVID50M, D.R. Cleveland Electric Illuminating Co. 82/09/24 KEPPLER.J. G. Region 3. Office of Director 2pp. 15605-047 24X Fiche 50-440.82/09/24.8210050132
- 8210130364 Third interial deficiency rept re rejection of previously accepted containment vessel radiographs Initially reparted on 820405 All potentially rejectable radiographs submitted to Hartford Steam Boiler Insp Co for review DAVIDSON.D R Cleveland Electric Illuminating Co 82/09/30 KEPFLER.J O Region 3, Office of Director 2pp 15681 169 24X Fiche 50-440.82/09/30.8210130364

- DUCKET 50-441 PERRY NUCLEAR POWER PLANT, UNIT 2
- A Applacation/construction stage documents & correspondence
- B210130010 Requests submittal of add1 fee for B20721 application for extension of const completion dates DIGGS.R License Fee Management Branch B2/09/27 DAVIDSON, D.R. Cleveland Electric Illuminating Co ip 15692 332 24% Fiche 50-440.82/09/27.8210130010
- B210130179 Advises that response to NRC B20906 ltr re degraded cure hydrogen control will be provided by B21201 DAVIDSON, D R Cleveland Electric Illuminating Co 82/09/29 SCHMENCER.A Licensing Branch 2 lp 15673 019 24X Fiche 50-440, 82/09/29, 8210130179
- B210190326 Forwards slide presentation from B20813 meeting re-safety relief hydrodynamic loads Position similar to criteria outlined in NURGE-0763 Encls withheld (ref 100CR2 790) DAYIDSON, D.R. Cleveland Electric Illuminating Co. 82/10/08 SCHWENCER.A. Licensing Branch 2 2pp 15742-059 24x Fiche 50-440.82/10/08.8210190326
- 8210260419 Forwards NEDE-22203, "Reactor Internals Vibration Predictions," dtd Aug 1982 Rept contains proprietary infore internals vibration program & peak amplitude predictions per engineering analysis Rept withheld (ref 10CFR2 790) DAVIDSON, D.R. Cleveland Electric Illuminating Co. 82/10/08 SCHWENCER.A. Licensing Branch 2 ip 15806 114 24X Fichs 50-440, 82/10/08, 6210260419
- 6210190619 Confirms 821006 telcon repreoperational testing program Util not required to continue sending proliminary preoperational test procedures Current status of procedures & implementation will be forwarded monthly LITTLE.W S Division of Engineering & Technical Programs (12/10/13 HICKES OR Cleveland Electric Illuminating Co Ip 1971/ 2012 244 Fiche 50-440.82/10/15.8210190619
- B210210079 Forwards proprietary util B2100B ltr & attachments re sate; relief valve hydrodynamic loads; madvertently omitted from original submittal Nonproprietary info to be provided by B2105 DAVIDSON, D.R. Cleveland Clectric Illuminating Co. 82/10/13 BCHHENGER, A. Licensing Branch 2 lp. 15762 233 24X Fiche 50-440, B2/10/15, B210210079
- B210270073 Notification of B21109 meeting w/util.C-E & OAI in Bethess, MD to discuss pool dynamic load criteria application to plant specific design STEFANO,J Licensing Branch 2 B2/10/19 SCHWENCER, A licensing Branch 2 3pp 15836 276 24X Fiche 50-440,82/10/19,82102709/3
- D NRC Draft/Final Environmental Statements, supply & correspondence
- 8210260235 Comments on FES for facility Applicant aware of offluint limits No add1 adverse environ impacts within EPA field of expertise anticipated BACKLEY.B T Environmental Protection Agency 82/10/19 SCHWENCER.A Licensing Branch R ip 15/79/354 24X Fiche 50-440.82/10/19.8210260235
- E NRC Safety Evaluation Report (SER), supple & correspondence
- 8210150233 Forwards response to SER Confirmnatory Issue 16 re belting weld mails info revises response to Questions 123 (.123 2 % 123 3 % should resolve issue of mail surveillance capsules DAVIDSON.D R Cleveland Electric Illuminating Co 82/09/22 SCHMENCER-A Licensing Dranch 2 42pp 15706 010 24X Fiche 50-440, 82/09/22,8210150233
- 8210130173 Advises that responses to NRC B20908 ltr re SER Butstandirg
 Issue 21 concerning reanalysis of transients & accidents &
 development of emergency operating procedures will be
 provided by B21029
 DAVIDBON.D R Cieveland Electric Illuminating Co B2/09/20
 SCHMERCER,A Licensing Branch 2 lp 19673 044 24X
 Fiche 50-440, 82/09/28, 8210130173
- 8210190333 Responds to SER Confirmatory Items 32 & 45 re accident monitoring instrumentation & location of plant area radiation monitoring instrumentation Items also address TNI Items II F 1 3, II F 1 4, II F 1 5 & II F 1 4
 DAVIDBON, D R. Cleveland Electric Illuminating Co B2/10/14
 BCHEROER, A Licensing Branch 2 3pp 15742 120 24X
 Fiche 50-440, 82/10/14, 8210190333

- S210190683 Forwards response to SER Confirmatory Issues 28,30 & 43 re instrumentation & control Three oversite drawings encl Aperture cards are available in PDR DAVIDSON, D.R. Cleveland Electric Illuminating Co. 82/10/14 SCHWENCER, A. Licensing Branch 2 6pp 15751 013 24X Fiche 50-440,82/10/14,0210190683
- F Security, medical, emergency & fire protection plans
- 8207180055 FOIA request for all documents since 1979 to drug or alcohol abuse by persons at facilities SAMICKI,8 O News-Herald Willoughby, OH 82/08/30 FELTON, J M Division of Rules and Records 1p 15758 359 24X Fiche 50-440,82/08/30,8207180055
- D210170179 Responds to FDIA request for all documents since 1979 redrug or alcohol abuse by persons at facilities Forwards documents identified during 820713 telcon FELTON.J K Division of Rules and Records 82/09/15 SAWICKI, S G Rews-Herald Willoughby, OH 1p 15758 360 24X Fiche 50-440,82/09/15,8210170179
- --8210190204 Provides info re drug & alcohol abuse, fire support deficiencies, theft & forced entry observed at facilities Author name deleted # Affiliation Unknown 82/09/15 NRC No Detailed Affiliation Given 2pp 15758 361 24X Fiche 50-440, 82/09/15, 8210190199
- --8210190209 Ack receipt of Itr expressing concerns re security administration at facility NRC does not impose security requirements on licensee prior to onsite receipt of leactor fuel Contacting util suggested Info partially deleted PHILLIPIO A Region 3. Chicago, Office of the Director (81/03/01) 81/07/16 Affiliation Unknown ip 15758 363 24X Fiche 50-440,82/09/15,8210190199
- 8210190011 Notification of 821006 meeting w/util in Bethesda.MD to discuss responses to NRC questions re umorgency plan & status of plan finalization STEFANGIJ Licensing Branch 2 82/09/23 SCHWENCER.A Licensing Branch 2 3pp 15760 318 24X Fiche 50-440,82/09/23,8210190011
- 8210240572 Releases public version of revised emergency plan FCLTON, J.H. Division of Rules and Records 82/10/08 Document Management Branch Ip 15832 026 24X Fiche 50-440,82/10/08, 8210260572
- ---8210260975 Forwards public version of Revision O to emergency plan PAVIDBOND R Commonwealth Edison Co 82/09/22 DENTON H R Office of Nuclear Reactor Regulation, Director 2pp 19832 02/ 24X Fiche 50-440,82/10/08.8210260572
- --B210260579 Public version of Revision O to emergency plan 4 Commonwealth Edison Co B2/09/22 291pp 15832 029 24X Fiche 50-440,82/10/08,8210260572

G Adjudicatory correspondence

- 6210070075 Forwards responses to interrogatories from Sunflower Alliance requiring FEMA reply KRIMM.R W Federal Emergency Management Agency 82/09/09 GRIMES.B K Division of Emergency Preparedness 35pp 15628 12/ 24X Fiche 50-440, 82/09/09, 8210070075
- 8210010335 Reply to applicant 820721 motion to amend ASLB 820716 memorandum & order rescheduling Moving filing date of testimony will prejudice intervenors Applicant suggestion to delay hearing until 830222 should be granted HIATT-S L. Ohio Citizens for Responsible Energy 82/09/27 Atomic Safety and Licensing Board Panel 1p 18869 163 24% Fiche 50-440.82/09/27.8210010335
- 8210010366 Beventh set of interrogatories Cartificate of Svc encl Related correspondence HIATT, S.L. Ohio Citizens for Responsible Energy 82/09/27 Office of the Executive Legal Director. Spp 15573 075 24X Fiche 50-440,82/09/27,8210010366
- 8210010377 Reply opposing applicant 820913 motion to rescind ASLB BIO804 procedurel order requiring intervenors to respond to MRC & applicant ensuors to late filed contentions. Certificate of Byc and HATT, S.L. Ohio Citizens for Responsible Energy 82/09/27 Atomic Befety and Licensing Board Panel, 5pp 15573 054, 24X Fiche 50-440, 82/09/27, 8210010377

- 8210010386 Requests article from Nuclear News noted in ASLB 820916 memorandum & order be provided to all parties since magazine unavailable in public & univ libraries HIATTIS L Ohio Cititens for Responsible Energy 82/09/27 BLOCH P B . KLINE, J R . SHON. F J Atomic Safety and Licensing Bound Panel 1p 15569 212 24% Fiche 50-440.82/09/2/.8210010386
- B210010416 Sixth set of interrogatories Certificate of Svc encl Heluted correspondence HIATT,S L. Dhio Citizens for Responsible Energy 82/09/27 Cleveland Electric Illuminating Co 10pp 15572 173 24X Fiche 50-440,82/09/27,8210010416
- 8210010250 Response opposing applicant motion to revise procedures for late filed contentions No prejudice demonstrated Proof of Syc encl WILT.D D Sunflower Alliance WILT.D D Wilt. D D 82/09/28 Atomic Safety and Licensing Board Panel 2pp 15568 262 247 Fiche 50-440.82/09/28.8210010250
- 8210010323 Motion for 5-day extension to file motion to compel discovery against NRC Additime necessary due to other business & personal lilness Proof of Svc enci HILT, D D Sunflower Alliance HILT, D D Wilt, D D 82/09/34 Atomic Safety and Licensing Doard Panel 1p 15569 192 24X Fichw 50-440,82/09/28,8210010323
- 8210010345 Answer to fourth set of interrogatories Certificate of Svc encl WILLMORE,R L. Cleveland Electric Illuminating Co. WILLMORE,R I Shaw, Pittman, Potts & Trowbridge 82/09/28 Ohio Citizens for Responsible Energy 17pp 15574 001 24X Fichs 50-440,82/09/28 8210010345
- 9210010457 Forwards RF Zucker & RA Pender original affidavits to be substituted for photocopies in applicant 820928 answer to OH Citizens for Responsible Energy fourth set of interrogatories Related correspondence HILLMORE.R L. Shaw. Pittman. Potts & Troubridge WILLMORE.R L. Cleveland Electric Illuminating Co 82/09/29 Docketing & Services Branch 3pp 15572 311 24X Fiche 50-440.82/09/29. 8210010457
- 8210040019 Notice of withdrawal of appearance in proceeding LEWIS.S H Hearing Branch 2 82/09/29 3pp 15581 262 24% Fiche 50-440.82/09/29.8210040019
- 8210040015 Certifies svc of NRC response to Sunflower Alliance motion seeking admission of late contention on shift rotation & GE Johnson hotice of appearance on 820930 JOHNSON, GE Hearing Branch 4 82/09/30 2pp 15581 348 249 Fiche 50-440,82/09/30,8210040015
- 8210040017 Response opposing Sunflower Alliance 820910 motion seeking admission of late contention on shift rotation Contention beyond Commission regulatory requirements, lacks basis b nervs & is untimely

 JOHNSON.0 E Hearing Branch 4 82/09/30 Atomic Safety and
 Licensing Board Panel 8pp 15581 297 24X Fiche 50-440,82/09/3D, 8210040017
- 8210040023 Notice of appearance in proceeding JOHNSON.O E Hearing Branch 4 82/09/30 1p 15581 256 Fiche 50-440.82/09/30.8210040023
- B210050173 Third set of interrogatories re Issue 3 & requests production of documents Proof of Svc encl Related correspondence WILT.D D Sunflower Alliance WILT.D D Wilt. D D 82/0 NRC No Detailed Affiliation Civen 7pp 15604 138 24X Fiche 3D-440.82/09/30.8210050173
- 8210050228 Fourth request for production of documents re Cont Issue 1 on emergency evacuation planning Proof of Svc encl Related correspondence HILT.D D Sunflower Alliance HILT.D D Hilt. D D 82/0 Office of the Executive Director for Operations 2pp 156 24X Fiche 80-440.82/09/30.8210050228
- B210050242 Requests extension of discovery time on Contention not ready for hearing as fitnal emergency plans not yet in place Plans must be reviewed prior to hearing Proof of Svc encl Related correspondence
 WILT, D D Sunflower Alliance WILT, D D Wilt, D D B2/0°
 Atomic Bafety and Licensing Board Panel 2pp 15610 334
 Fiche, 30-440, B2/07/30, B210050242
- 8210050252 Third set of interrogatories w/requests for product documents re Issue 3 on adequaty of applicant GA program Proof of Svc encl Related correspondence WILT, D. D. Sunflower Alliance WILT, D. D. Wilt, D. D. 82/05 Cleveland Electric Illuminating Co. 12pp. 15610-274 24X Fiche: 50-440, 82/09/30, 8210050252

- 0210050255 Third set of interrogatories & request for production of documents re Issues 1.3 % [I on offsite emergency evacuation plans.04.7 local economic benefits.respectively Certificate of Svc encl MILLMORE.R L. Cleveland Electric III)uminating Co. WILLMORE.R t. Shaw, Pittman, Potts & Trowbridge 02/09/30 Sunflower Alliance 12pp 15609.199 24% Fiche 50-440.82/09/30 6210050255
- 8210G50374 Response in opposition to Sulflower Alliance, Inc. 820910 motion to compel applicant answer to second set of interrogatories Applicants will respond shortly Certificate or Svc encl
 SILBERG.J E Cleveland Electric Illuminating Co. SILBERG.J E. Shaw, Pittman, Potts & Trowbridge 82/09/30 Atomic Safety and Licensing Board Panel. 20pp. 15608-256. 24x Fiche 50-440.8P/09/30.8210050374
- 8210040207 Seventh set of interrogatories directed to applicant % eighth set of interrogatories directed to NRC.pursuant to ASLB 810728 Hemorandum / Order, LBP 81-24 Certificate of Svc encl Related correspondence
 MIGATUS L Ohio Citizens for Responsible Energy 82/09/30
 Cleveland Electric [1]uninating Co 5pp 15614-15/ 24x
 Fiche 50-440, 82/09/30,8210060207
- 8210050069 Response supporting applicant 820913 motion to levise procedures for late filed contentions Allowing intervenors to raise new matter in reply constitutes amend to contentions Certificate of Svc encl CVFCMIN.J M Hearing Branch 4 82/10/04 Atomic Safety and Licensing Board Panel 8pp 15603 188 24% Fiche 50-440.82/10/04.
- 8210150192 Requests clarification of docket numbers for Harris & Peiry plants Mirry may be causing prejudice to intervenors since documents go to incorrect LPDR HighTis L. Ohio Citizens for Responsible Energy 82/10/04 Docketing & Services Branch 1p 24X Fiche 50-000.82/10/04. 0204151992
- 8210040303 Response opposing OH Citizens for Responsible Energy 820020 motion to compel discovery of NRC A util ASIB chairman comments did not allow intervenors to broaden contention or scope of discovery CUTCHINI M Hearing Branch 4 82/10/05 Atomic Sarety and Licensing Board Panel App 15619 017 24% Fiche 50-440,82/10/05, 01:00/07079
- --6210060321 Response to applicant 820921 motion to amend schedule net earth in ASLS 820916 order NRC does not abject to extending period between filing of testimony & commencement of hearing Certificate of Six encl CyfCHIN.J H. Hearing Branch 4 82/10/05 Atomic Safety and Licensing Board Panel Spp. 15619 023 24X Fiche 50-440. RP/10/05 82/06060303
- 6210070405 Answer opposing Sunflower Alliance 820430 application to lift 820930 discovery cutoff date for Issue 1 Intervenor has had over 1 1.2 yes to file discovery No good cause shown Certificate of Svc encl Related correspondence WILLHORE, R. L. Cleveland Electric Illuminating Co. WILLHORE, R. L. Shaw, Pittman, Fotts & Troubridge 62/10/05 Atomic Safety and Licensing Board Panel. Spp. 15633 307—24X Fiche 50-440-82/10/05, 6210070405
- 8210070137 Memorandum & order denying util 920913 motion to revise procedures for late-filed contentions If intervenor introduces new math in reply, applicants will be allowed to respond BLOCK-P B KLINE, J R SHON, F J Atomic Safety and Licensing Board Panel 82/10/06 Cleveland Electric Illuminating Co 4pp 19427 OLA 244 Ficher 50-440. B2/10/06. 82/10/2012

- 8210130327 Memorandum & order denying OH Citizens for Responsible Energy 820707 motion to sever proceedings No reason provided for ASLB to reconsider 810707 ruling on identical motion by Sunflower Alliance
 BLOCH.P.B. Atomic Safety and Licensing Board Panel 82/10/08
 Ohio Citizens for Responsible Energy 1p 15678 283 24X
 Fichs 50-440, 82/10/08.8210130327
- 8210130333 Memorandum & order admitting Contention 12 re inndequale consideration of economic consequences of accidents Preponderance of considerations favors admission of contention BLOCH-P B , KLINE, J R , SHON, F J Atomic Safety and Licensing Donte Panel 82/10/08 Onto Citizens for Responsible Energy 5pp 15682 059 24X Fiche 50-440,82/10/08.8210130333
- 6210150228 Confirms conversations w/OH Citizens for Responsible Energy & Judge Block re extension of time for util to respond to OH Citizens for Responsible Energy 620720 motion to compel discovery on NRC & wtil Response due 821018 W/svc list Studeno, JE Shau, Pittman, Patts & Troubridge SILBERG, J (Cleveland Electric Illuminating Co 82/10/08 BLOCH, P D, KLINE, J R, SHON, F J Atomic Bafety and Licensing Board Panel 3, 15706 008 24% Fiche 50-440, 82/10/08, 8210/150228
- 8210150467 Answer to sixth set of interrogatories Centificate of but entl
 entl
 MICLMORE, R L. Cleveland Electric Illuminating Co. WillMORE, R t
 Shaw, Pittman, Potts & Trowbridge 82/10/12 Ohio Citiions fur
 Responsible Energy 10pp 15703 050 24% Fiche 50~440.62/10/12
 8210150467
- 8210180211 Reply opposing NRC & applicant responses to OH Citizens for Responsible Energy motion for leave to file Contentions 21-26 Good cause, specificity & basis requirements met Certificate of Svc encl HATTIS L Ohio Citizens for Responsible Energy 82/10/12 Atomic Safety and Licensing Board Panel 14pp 15718 110 .71% Fiche 50-440, 82/10/12, 8210180211
- 8210150175 Advises that documents requested by Bunflower Alliance fourth request directed to Executive Director for Operationa available in PDR GUICHIN.J M Hearing Branch 4 82/10/13 WILT.D D Wilt. Bit HILT.D D Sunftower Alliance ip 15707 183 24X Fiche 50-440.82/10/13.8210150175
- 8210150275 Advises that NRC will not voluntarily respond to any discovery requests in Sunflower Alliance third set of interrogatories & requests for documents, except Request 19 Remainder of discovery broader than Issue 3 CUTCHIN.J M Hearing Branch 4 82/10/13 WILT.D D Wilt. U.E. WILT.D D Sunflower Alliance Spp 15705 001 24% Fiche 50-440.82/10/13.8210150275
- 8210180155 Advises of correction to util response to Interrogatory of OH Citizens for Responsible Energy sixth set of interrogatories Conclusion of response remains unchanged Related correspondence WILLMORE, R. I. Shaw, Pittman, Potts & Trowbridge WILLMORE, R. I. Cleveland Electric Illuminating Co. 82/10/14 HIATT, 8 Ohio Citizens for Responsible Energy ip 15719-269 24X Fiche 50-440,82/10/14,8210180185.
- 8210190377 Answers to B20907 fifth set of interrogatories Prof qualifications & Cartificate of Svc encl JOHNSON, O E Operations & Administrative Division 82/10/15 Ohio Citizens for Responsible Energy 15pp 15740 300 44X Fiche 50-440, 82/10/15, 8210190377
- 8210190475 Answer opposing Sunflower Alliance 820928 motion to est time to file motion to compel discovery against NRC No basis for unlimited request provided Cortificate of Svc encl CUICHIN.J H Hearing Branch 4 82/10/15 Atomic Safety and Licensing Board Panel 4pp 15740 241 24X Fiche 50-440,02/10 8210190475,
- B2[021035] Objects to issuance of ABLB 821008 memorandum & order request to extend discovery on Jasue I Order issued ASLB should request responses from all parties on expedited schedule W/Certificate of Svc Related correspondence HARTIS L Ohio Citizens for Responsible Energy 82/10/15 BLOCH, P B . KLINE, J R . 6HON, F J . Adomic Bafety and Licensing Panel ip 15764 010 24% Fiche, 50-440, 82/10/15, 821021035]
- --8210210358 Seventh discovery progress rept, pursuant to ASLS BLOY memorandum & order, LBP-81-35 Interrogatories submitted to applicant & NRC re Issues 4,5,47.8 & 9 Discovery re Issue 9 forthcoming HATTS L Ohio Citizens for Responsible Energy 82/10/15 15764 011 24X Fichs 30-440,82/10/15,8210210351

- --8210210364 Motion to extend discovery on Issue 9 to 821101 to permit review of documents referenced in applicant responses to 820830 interrogatories & followup discovery Certificate of Svc encl Related correspondence HIAFT.S L Ohio Citizens for Responsible Energy 82/10/15 Atomic Safety and Licensing Board Panel 3pp 15764 013 24X Fiche 50-440,82/10/15.8210210351
- 8210210284 Answer opposing OH Citizens for Responsible Energy 820920 motion to compel discovery on NRC & util Interrogatories not relevant to & beyond scope of Issue & Certificate of Svc encl Related correspondence
 SILBERG. J E Cleveland Electric Filuminating Co SiLBERG. J E Shaw, Pittman, Potts & Trowbridge 82/10/18 Atomic Safety and Licensing Board Panel 36pp 15765 099 24X Fiche 30-440,82/10/18,8210210284
- 8210210353 Amended answer to Interrogatory 13 of Sunflower Alliance second set of interrogatories Certificate of Svc encl Related correspondence SILBERO. J E Cleveland Ejectric Illuminating Co SILBERO. J E Shaw. Pittman. Potts & Trowbridge 82/10/18 Sunflower Alliance Spp 15763 177 24X Fiche 50-440.82/10/18.8210210353
- 8210220481 Requests attachment to IRC 780203 ltr to GE be provided to allow progress on Issue 4 Document needed before intervenor can decide if updates to interregalories necessary Related correspondence
 HIATT.S L. Ohio Citizens for Responsible Energy 82/10/18
 SILBERG J. Shaw, Pittman, Potts & Trowbridge SILBERG, J. Cleveland
 Electric Illuminating Co. 1p. 15779-078-24X Fiche 50-440, 82/10/18,8210220481
- 8210210476 Memorandum & order denying Bunflower Alliance 820910 motion to compel applicant to answer second set of interrogatories if util agrees to stipulation on potoassium indide subcontention. Interrogatory 36 need not be answered BLOCH F B . KLINE, J R . SHON.F J Atomic Safety and Licensing Bourd Panel 82/10/19 Cleveland Electric Illuminating Co App 15762 R65 24X Fiche 50-440,82/10/19.8210210476
- B210220305 Answer to 820930 seventh set of interrogatories Certificate of Svc encl HILLMORF.R L Cleveland Electric Illuminating Co WILLMORF.R L Shaw, Pittman, Potts & Trowbridge 82/10/19 Ohio Citizens for Responsible Energy 13pp 15776 053 24X Fiche 50-440,82/10/19, 8210220305
- 82[0220309 Seventh discovery progress rept Certificate of Svc enti-MILLMORE,R L Cleveland Electric Illuminating Co WILLMORE,R L Shau, Pittman, Potts & Trowbridge 82/10/19 4pp 15776-049 ,P Fiche 50-440,82/10/19,8210/220309
- 8210220376 Motion for leave to file answer to OH Citizens for Responsible Energy (OCRE) 821012 reply to util & NRC answers to OCRE motion for leave to file Contentions 21-26 MILLMORE.R L Cleveland Electric Illuminating Co MILLMORE,R L Shaw Pittman, Potts & Trowbridge 82/10/19 Atomic Safety and Licensing Board Panel 2pp 13777 312 24X Fiche 50-440,82/10/19,8210220374
- --B210220405 Answer to OH Citizens for Responsible Energy 821012 reply to NRC & applicant response to Citizens motion to file Contentions 21 through 26 Citizens did not meet burden of proof for admission of new contentions W/Certificate of Svc WILLMORE, R. Cleveland Electric Illuminating Co. WILLMORE, R. t. Shaw, Pittman, Potts & Trowbridge 82/10/19 Atomic Safety and Licensing Board Panel 155p 1577 314 24X Fiche 50-440,82/10/19.8210220396
- B210250331 Reply brief supporting motion to submit addl contention Oned cause for late filing demonstrated Applicant shift rotation plans may not be incorporating circadian principles HILT, D.D. Sunflower Alliance. WILT, D.D. Wilt, D.D. B2/10/19 Atomic Safety and Licensing Board Fanel 3pp 15790 325 24X Fichs 50-440, 82/10/19, 8210250331
- 8210250299 Answer to OH Citizens for Responsible Energy 821015 motion to extend discovery on Issue 9 repolymer degradation No justification exists for extending discovery cutoff date Certificate of Svc encl SILDEROLDE. Claveland Electric Illuminating Co SILBEROLDE Shaw. Pithman, Patts & Troubridge 82/10/20 Atomic Safety and Licensing Board Panel 5pp 18790 [95 24X Fithe 50-440.82/10/20, BD10280299
- 8210250322 Supplemental ensures to Sunflower Alliance. Inc second set of interrogetories Certificate of Svc enc!
 SILBERG. J E Claveland Electric Illuminating Co SILBERG. J E Shaw, Pittman, Potts & Troubridge 82/10/20 Sunflower Alliance 17pp 15790 226 24% Fiche. 50-440. 82/10/20, 8210250322

- 8210250365 Advises that NRC will not voluntarily respond to DM Cittien for Responsible Energy seventh set of interrogatories except for interrogatories listed Requests irrelevant & will not lead to discovery of admissible evidence CUTCHIN.J M Hearing Branch 4 82/10/22 HIATT S.L. Ohio Citzzen for Responsible Energy 2pp 15790 175 24% Fiche 50-440.82/10/22, 8210250365
- 8210260033 Answers to 820830 fourth set of documents Contificate of two enci MRIGHT, N.A. Hearing Branch 2 82/10/22 Chio Citizens for Responsible Energy 12pp 15799-124 24X Fiche 50-440, 82/10/22,
- 8210280216 Responds to 821018 ltr to svc of documents to parties Telcoms could expedite matters in future Svc list encl Related correspondence
 SILDERO, J E Shaw, Pittman, Potts 3 Trombridge 82/10/22
 HIATT, S L Ghio Citizens for Responsible Energy 9pp 15837 J35 24X Fiche 50-440,82/10/22,8210280216
- 8210280231 Update to response to Interrogatory 4 2 of GH Citizen, for Responsible Energy 820928 fourth set of interrogatories Related correspondence
 WILLMORE.R L Shaw, Pittmen, Putts 4 Troubridge WillMORE.R I
 Cleveland Electric Illuminating Co 82/10/22 HIATT.S Ohio
 Citizens for Responsible Energy ip 15837 081 24x
 Fiche 50-440, 82/10/22, 8210280231
- 0210260383 Answers to listed interrogatories of 020927 seventh set of interrogatories NRC will not voluntarily answer remaining interrogatories Certificate of Svc encl CUTCHIN.J M Hearing Dranch 4 82/10/25 Ohio Citizens for Responsible Energy (1pp 15803 348 24X Fiche 50-440,02/10/25,0260303)
- 8210260395 Discovery rept for previous two months per ASLB B10907 memorandum & order CUTCHIN.J M Rearing Branch 4 82/10/25 DLCKH.P B SHON.I J KLINE.J R Atomic Safety and Licensing Board Panel (p. 1580J J); 24X Fiche 50-440.82/10/25.8210260395
- 8210280246 Forwards RB Coffey original affidavit to be included in applicant 821020 supplemental answers to Sunflower Alliance second set of interrogatories Related correspondence WILLMORE, R L. Shaw, Pittman, Potts 1 Trowbridge WILLMORE, R t. Cleveland Electric Illuminating Co. 82/10/25 Docksting & Services Branch 2pp. 15837-054 24X Fiche 50-440,82/10/25, 8210280246
- 8210290287 Requests encl RF Zucker & RV Tanney original affidavits he substituted for photocopies in applicant 821019 answers to OH Citizens for Responsible Energy seventh set of interrugatories
 HILLHORE: RL Show: Pittman, Polts & Trowbridge WillMORE: Rt Cleveland Electric Illuminating Co 82/10/26 Docksting & Services Branch 3pp 15854 069 247 Fiche 50-440,82/10/26.8210290287
- 8210280346 Answer opposing OH Citizens for Responsible Energy 821016 motion to extend time for discovery on Issue 9 No justification for extension provided Certificate of Svc encl
 CUTCHINUM Hearing Branch 4 82/10/27 Atomic Safety
 Licensing Board 7 9210280346

- 4 Inspection reports IE Bulletins & correspondence
- 5210060305 Forwards IE Insp Repts 50 440/82-11 % 50-441/82-10 on 820931-0902 No noncompliance noted LITTLE.N S Division of Engineering & Technical Programs 82/09/2, DAVIDSON, D R Cleveland Electric Illuminating Co 2pp 15619 195 24% Fiche 50-440.82/04/22/8210060305
- 82:0060308 IE Insp Repts 50-440/82-11 % 50-441/82-10 on 820831-0902 Nu noncompliance noted Major areas inspected preservice insp procedures 7 work activities, previous insp findings & IE Bulletin 80 08 activities MARD.k D. DANIELSON.D M. Region 3 Office of Director 82/09/14 5pp 15619 197 244 Finhe 50-440 82/09/22.8210060305
- 8210170763 Forwards If Investigation Repts 50-440/81-17 A 50-441/01 by on 811027-820319 & notice of violation MEPPLER J & Region 3. Office or Director 82.09/27 DAVIDSON.D R Clevelard Electric Illuminating CG 7pp 15736-318 24X Fichs 50-440 82/09/27 6210190765
- --8210190771 Nutice of violation from investigation on 811027-820319 AEPPLER, J. G. Region 3. Office of Director 82:09/24. 9pp 15735-321. 247 Fiche 50-440-82/09/27.8210190763.
- -821017076" IE investigation Repts 50-440/81-19 & 50-441/81-19 on 811027-820019 Nonconpliance noted Gould Inc Drawings E-33-51 998 E231 > 6311 > 6311
- 보208190233 IE Info Notice Bu 35, buppl 1, Leaking * Dislodged I-1/b Implant Seeds " Svo list enr! CDBC, I Division of Evel Facilities, Materials % Safeguards EZ/10/06 Consolidated Edison Co of New York obsp 15/61 년년 교사 Fiche 50-000 원간 10/06 8208190233
- 9208190236 IE Builetin 82-03 Stress Carrosson Cracking in Thick-Wall Large-Otal eter Statifies Steel Recirculation Sys Piping at BNR Plants "Svt list encl EPYOUNG R C Director's Office, Office of Inspection and Froncement EPY10-14 Consolidated Edison Co. of New York 115pp 15616 125 24: Fiche 50 000-82/10/14.8208(90238
- E210240333 Act receipt of 6.1008 itr informing NRC of steps taken to correct violations noted in IE like Repts 50 440/62-09 & 90-441/62-08 MCRELIUS, C.E. Division of Project? Resident Programs DAVIDSON D.R. Cleveland (letter [1104]) Cleveland (letter [
- -8210260337 Responds to NRC 820710 lti te violations noted in IE (htp. Repts 50-440/82-09 % 50-441,82-38 Corrective actions Maiser Engineer Procedure QAP 22 revised to require annual evaluation Detailed hardware inspiperformed 920728 PAVID50N.D R Claveland Electric (Illuminating Co. 82/10/08 STREL 105,000 F. Division of Project (New York 1987) Programs 6pp 15803 192 24X Fiche 50-440,92/10/21,9210260333
- 5 Reportable occurrences. LFRs & related correspondence
- 5210050132 Final deficiency rept to nonconforming Transamerica Belavat standby diesel generafor ACME Section III. Class 3.fiping welds Initially reported on 820327 Weld insp & required repair/rework will be completed by 830401 DAVIDSON-D R Cleveland Electric Illuminating Co 82/09/24 EFFLER.J G Region 3. Office of Director 2pp 15605 047 249 Fiche 50 440.82/09.24.82(0050132
- 8210130364 Third interin deficiency rept re rejection of previously accepted containment vessel rediographs Initially reported on 820405 All potentially rejectable radiographs submitted to Hartford Steam Boiler Insp Co for review DAVIDSON. D R Cleveland Electric Illuminating Co 82/09/30 KEPFLER. J G Region 3. Office of Director 2pp [568] 169 24X Fiche 50-440, 82/09/30, 8210130364
- 1 THU NOITATE READOUR NOCLEAR STATION. UNIT 1
- A Application/construction stage documents & correspondence
- 8210120617 Notification of 820924 meeting w/applicant in Seabrook.NH to inspect onsite radiological monitoring sys as part of GL sarety review MHEELER.LL Licensing Branch 3 82/09/17 KERRIGAN.J D Licensing Branch 3 3pp 15672 235 24X Fiche 50-443.82/09/17, 8210120617

- 8210070160 Forwards draft results of analysis of associated circuits addressing question raised at 820910 meeting Once concurrence received response will be issued as amend to FSAR, closing out Open Item 26
 BAXTER: F Yankee Atomic Electric Co 82/09/20 SRINIVASAN. H Power Systems Branch 12pp 15645 049 24% Fiche 50-443,82/09/20 8210070160
- 0210180378 Requests assignment of reviewers for Bechtel work packages all three packages should be ready for NRR review by 021004
 Task Interface Agreement TIA 02-55 w/Region 4 encl
 KERRICAN.J D Licensing Branch 3 02/09/20 LEAR.G Mydrologic &
 Geotechnical Engineering Branch BOSNAK.R Mechanical Engineering
 Branch SCHAUER,F Structural Engineering Branch 2pp 15/45 JC.
 24X Fiche 50-443.82/09/20.0210180378
- 8210010465 Forwards "Response to NRC Generic Request for Add) Info He NUREG-0612, Control of Heavy Loads " DEVINCENTIS. J Yankee Atomic Electric Co DEVINCENTIS. J Public Service Co of New Hampshire 92/09/24 KERRIGAN. J D Licentin. Branch 3 1p 15572 017 24X Fiche 50-443, 82/09/24, 8210010445
- --8210010470 "Response to NRC Generic Request for Addl Infa Re LUREG-0612. Control of Heavy Loads " * Public Service Co of New Hampshire 82/09/30 ±34pp 15572 018 24X Fichs 50-443, 82/09/24,8210010465
- 8210040112 Forwards response to NRC generic request for add] info re NUREQ-0612. "Control of Heavy Loads" W/a encl DEVINCENTIS.J Yankee Atomic Electric Co DEVINCENTIS.J Public Bervice Co of New Hampshire 82/09/24 KERRIGAN.J B Litemaine Dranch 3 ip 13581 143 24X Fiche 50-443.82/09/24.8210040112
- 8210040193 Forwards responses to Hydrologic & Geotechnical Engineering Branch 820727 Series 240 requests for addl info.Guestions 240 38,240 39 & 240 41 Response to Guestion 240 40 rorthcoming DEVINCENTIS, J. Yankee Atomic Electric Co. DEVINCENTIS, J. Public
- DEVINCENTIS, J Yankee Atomic Electric Co DEVINCENTI9, J Public Service Co of New Hampshire 82/09/30 KERRIGAN, J D Liconsina Branch 3 14pp 15583 168 24X Fiche 50-443,82/09/30,(2210048)71
- 8210050199 Responds to Mechanical Engineering Branch 820618 request for add1 info Response includes "Prying Effect on Concrete Expansion Anchor Bolts Due to Pipe Support Base Plate Flexibility" Draft responses submitted 820728 DEVINCENTIS. J Public Service Co of New Hampshire 82074730 KERRIGAN, J S licenting Branch 3 3p 15609 085 24X Fiche 50-443,82/09/30,8210050149
- --8210050206 "Prying Effect on Concrete Expansion Anchor Bolts Due to Pipe Support Base Plate Flexibility " OALUNIC, B. MCKENNA, H. RIGAMONTI. G. United Engineers & Constructors, Inc. (subs. of Raytheon Co.) 79/07/20 @Bpp 15609 088 24X Fiche 50-443, 82/09/30,8210050199
- 8210050393 Requests add1 info re analysis proving any challenges in Class IE circuits from associated circuits do not prevent sare shutdown of plant info re NUREG-0737, Item II E 4 2. Position 6 on containment isolation valves required KERRIOAN, J. Licensing Branch 2 82/10/01 TALLMAN, W.C. Public Service Co. of New Hampshire 9pp 15608 324 24X Fiche 50-443, 82/10/01. 8210050393
- 8210070105 Forwards revised response to Question 440 136 re Reactorist ;
 Branch B20727 request for add1 info concerning steam generator tube rupture
 DEVINCENTIS.J Yankse Atomic Electric Co DEVINCENTIS.J Public Service Co of New Hampshire 82/10/05 KERRIGAN, J B Lizensing Branch 3 4pp 15628 074 24X Fichs 50-440.02/10/05.0210070105
- 6210130436 Forwards revised responses to Mechanical Engineering Dract 820301 & 05 Requests for Add1 Info 210 3-210 69, originally submitted in util 820421.30 & 0510 ltrs, per 020511-13 meeting Responses will be incorporated into FSAR Amend 47 DEVINCENTIS.J Yankee Atomic Electric Co DEVINCENTIB.J Public Service Co of New Hampshire 82/10/06 KERRIGAN.J B Licensin; Branch 3 124pp 15681 193 24X Fiche 50-443,82/10/06,8210130436
- 82:0:505:10 Forwards revised FBAR Section 6.2.2 providing justification for excluding inert cover gas on sedium hydroxide storage tank Info will be incorporated in Amend 48 to OL application
 DEVINCENTIS.J Yankee Atomic Electric Co DEVINCENTIS.J Public Service Co of New Hampshire 82/10/07 KERRIGAN.J Licensing Branch 3 4pp 15714 189 24X Fiche 50-443.82/10/07.8210150510
- 8210180001 Forwards notes from 820914 & 15 Instrumentation & Controls
 Sys Branch review meetings.per NRC 820216 & 0323 requests
 Notes also include items discussed at 820323-25,0512 & 13 &
 0715 & 16 meetings & NUREG-0737 action items
 DEVINCENTIS.J Yankes Atomic Electric Co DEVINCENTIS.J Public
 Service Co of New Hampshire 82/10/14 KERRIGAN.J Licensing
 Branch 3 95pp 15720 031 24X Fiche 50-443,82/10/14,8210180001

1 .

j,

Table sales

12

```
gouse/ Requests advanced notification of scheduled NRC meeting:
clittes to enable ample time for Atty General Ofc to
range for staff attendance
NDER.E T New Hampshire, State of 82/10/18 WHEELER.L L
gensing Granch 3 ip 15790 069 24X Fiche 50-443,82/10/18,
10250307
250307 Requests advanced notification of scheduled NRC meetings re
```

270006 Forwards request for info re unsite audit for seismic & namic qualification review & pump & valve operability mpletion of encl forms requested within 3 wks Specific terof audit to be untually agreed to by NRC & applicant RRIGAN, J D Licensing Branch 3 82/10/21 TALLMAN, W C Public Price C o of New Hampshire 25pp 15816 348 24X C Public C be 50-443, 82/10/21, 8210270006

280119 Forwards response to Power Sys Branch & Equipment glification Branch 821001 Request for Addl Info 430 149 re glysis on associated circuits.per 820910 & 1020-21

alysis on aspociated circuits, per B20410 & 1020-21 etings w/NRC VINCENTIS, J Yankee Atomic Electric Ca DEVINCENTIS, J Public rvice Co of New Hanpshire B2/10/26 HIRAQLIA,F J Licensing anch 3 10pp 19837 136 24X Fiche 50-443,82/10/26,8210280119

RC Draft/Final Environmental Statements, suppls & correspondence

120029 Forwards comments from State of NH to be included in NRC

person recognize comments from State of NH to be included in NRC 0730 itr refacilities DEG Myo encl 1800-1814 TALLMAN, W.C. Public RAGLIA, F.J. Licensing Branch 3 82/08/24 TALLMAN, W.C. Public rylice Co. of New Hampshire ip 15489 196 24X che 50-443, 82/08/24, 8210120029

ecurity, medical, emergency & fire protection plans

120128 Summary of 820720 meeting w/utils & United Engineers & ieures commany or seures meeting wrottle & United Engineers & metructors in Bethesda.MD re associated circuits agentation outline & details of preliminary review & alysis of associated circuits FSAR change encl DX.J Power Systems Branch 82/09/24 SRINIVASAN.M Power Stems Branch 100pp 15692 050 24X Fiche 50-443,82/09/24,10120128

djudicatory correspondence

D60194 Forwards Seacoast Anti-Pollution League objection to & tion for reconsideration of ASLD 820913 order & motion to

ring objections to ASLAD
CKUS.R A Backus.R A BACKUS.R A Seacoast Anti-Pollution
ague 82/09/30 HQYT,H F. LUEBKE.E A. HARBOUR.J Atomic Bafety
d Licensing Board Panel 2pp 15614 220 24X
che 50-443,82/09/30.0210060194

10060206 Objection to 5 motion for reconsideration of ASLB 820913 order & motion to certify objections to ASLAB Contention 8 uppl 4 should be admitted BACKUS, R A Seacoast Anti-Pollution League BACKUS, R A Suckus, R A 8/09/30 Atomic Safety and Licensing Board Panel /pp 13614 222 24X Fiche 50-443,82/09/30.8210060194

10060214 Affidavit of P Brown Hearings underway before appropriate state agencies re New England Clectric Transmission Corp & New England Power Pool applications for const of transmission lines
BROWN.P Seacoast Anti-Pollution League 82/09/30 8pp
19614 287 24X Fiche 50-443,82/09/30.8210060194

O50262 Grder allowing parties to file reply to New England alition on Nuclear Pollution objections & motion & State NH motion for reconsideration of ASLB 820913 memorandum & der Reply due by 821019 YT.H F Atomic Bafety and Licensing Board Panel 82/10/01 2pp 610 284 24X Fiche 50-443,82/10/01,8210050262

200026 First set of interrogatories & request for documents on intentions 1 A 2.I B 1.I B 2 & I C RDAN.W 5 , CURRAN.D New England Coalition on Nuclear Pollution RDAN.W 5 Harmon & Weiss B2/10/13 Public Service Co of New mpshire 14pp 15755 033 24X Fiche 50-443,82/10/13,8210200026

0510200036

10200042 First set of interrogatories & request for documents on Contentions II B 1, II B 3, II B 4 & II B.5
UARDAN W B , CURRAN, D New England Coalition on Nuclear Pollution
UCRBAN, W S Harmon & Weiss 82/10/13 Public Service Co of
New Hampshire Bpp 15755 059. 24% Fiche 50-443,82/10/13.
82/10200226

--0210200049 First set of interrogatories & request for documents on Contentions II 8 1.[[8 3.II B 4 & I] D 5 Certificate of JORDAN, H.S., CURRAN, D. New England Coalition on Nuclear Pollution JORDAN, H.S., CURRAN, D. New England Coalition on Nuclear Pollution JORDAN, H.S., Harmon & Weiss 82/10/13 Office of the Executive Legal Director 9pp 15755 067 24X Fiche 50-443, 82/10/13, 8210200026

8210270153 Response opposing New England Coalition on Nuclear Power objections to prehearing conference memorandum & order & motion to certify objections to ASLAB Issues in objections already considered Certificate of Svc encl GAD.R K Public Service Co of New Hampshire GAD.R K Rope-& Gray 82/10/26 Atomic Safety and Licensing Board Panel Supplisser 327 24X Fiche 50-443.82/10/26,82(0270153)

8210270166 Response opposing State of RM objection 5 motion for reconsideration of ASLB 820913 order No errors committed in ruling on RM contentions ASLB should not certify rulings since certification not requested Certificate of Svc end GAD.R K Public Service Co of New Hampshire CAD.R K Popc. * Gray 82/10/26 Atomic Safety and Licensing Doard Panel Public Service Co of New Hampshire CAD.R K Popc. * Gray 82/10/26 Atomic Safety and Licensing Doard Panel Public Service So-443,82/10/26,8210270166

H General correspondence

B210120270 Requests that DR Lewis be added to svc list TAYLOR, J. Atomic Safety and Licensing Board Panel B2/10/08 Public Service Co. of New Hampshire ip 15652 317 24X Fiche 50-443, 82/10/08.8210120270

G. Inspection reports. IE Bulletins & correspondence

8210070372 Forwards IC Insp Repts 50-443/82-09 t 50-444/82-09 on 820824-27 No nancompliance noted MARTIN.T T Division of Engineering t Technical Programs 82/09/22 TALLMAN.W C Public Service Co of New Hampshire 2pp 156.33 331 24X Fiche 50-443,82/09/22,8210070372

--8210070400 1E Insp Repts 50-443/82-07 & 50-444/82 09 on 820824 27 No noncompliance noted Major areas inspected procedures & work activities re-concrete const of reactor containment bldg done, structural welding within containment bldg & QA review VARELAYA A . DURR.J P. Region 1. Office of Director 82/09/20 7pp 15633 333 24% Fiche 50-443,82/09/22-8210070322

8208290124 FDIA request for IE Insp Rept 50-443/82-06 % 10CFR50 BACHAND,D Affiliation Unknown B2/09/28 CARR,J NRC - No Detailed Affiliation Given 1p Fiche 50-443,82/09/28,8208290124

8210190035 Responds to FOIA request for IE Insp Rept 50-443/82-06 A 10CFR50 Forwards documents W/o encl FELTON J K Division of Rules and Records 82/10/04 BACHAND. D Affiliation Unknown ip 15758 392 24X Fache 50-443, 82/10/04. A210190035

8208190233 IE Info Notice 80-35. Suppl 1, "Leaking & Dislodged I-12", Implant Beeds "Byo list end: COBBL I Division of Fuel Facilities, Materials % Safeguards 82/10/06 Consolidated Edison Co of New York 65pp 15761 250 24X Fiche 50-000,82/10/06.8208190233

8208190238 IE Bulletin 82-03, "Stress Corrosion Cracking in Thick-SUBTIVISED IN BUTTER BE-03, "Stress Corresion Cracking in Thic)
Wall.Large-Diameter, Stainless Steel, Recirculation Sys
Piping at BWR Plants " Svc list enc!
DEYOUNG, R C Director's Office, Office of Inspection and
Enforcement 82/10/14 Consolidated Edison Co of New York
Li5pp 15810 125 24X Fiche 50-000, 82/10/14,8208190238

S Reportable occurrences, LERs & related correspondence

82i0190126 Corrected version of final deficiency rept re misapplication of torquing equipment by Beloit Power Sys Instially reported on 820820 Corrective procedure provided by vendor will preclude potential problems
DEVINCENTIS, J. Yankee Atomic Electric Co. DEVINCENTIS, J. Public Service Co. of New Hampshire 82/09/20 STAROBTECKI, R. Division of Project & Resident Programs 2pp [5742 132 24X]
Ficher 50-443, 82/09/20, 8210190126

82(0190136 Corrected version of final deficiency rept re Robertshaw Controls thermostatic valves Initially reported on 820820 Corrective actions described by vendor will preclude potential problems

DEVINCENTIS, J Yankee Atomic Electric Co DEVINCENTIS, J Public Service Co of New Hampshire 82/09/20 STAROSTECKI: R Division of Project & Resident Projeams 3pp 15742 227 24X

Fiche 50-443,82/09/20,8210190136

- 8210190363 Final deficiency rept re cracked welds in containment annular skeel end connections Initially reported on 820910 Metallurgical investigation performed welding & installation procedure revised & cracked connections replaced DEVINCENTIS. J. Venkee Atonic Electric Co. DEVINCENTIS. J. Public Service Co. of New Manpshire. 82/10/12 STAROSTECKI.R. Division of Project & Resident Programs. 3pp. 15740-321 24x Fiche 50-443,82/10/12,8210170363
- 5210260330 Interim defictency rept re sheared pinion keys in Limitorque Model SB-0-25 mator operators Initially reported on 620902 Caused by use of inappropriate key matl Limitorque & Westinghouse continuing investigation DEVINCENTIS J Yankee Atomic Electric Co DEVINCENTIS J Public Service Co of New Manphilie B2:10718 STARGSTECKI, R Division userice to Resident Programs 2pp 15802 340 24% Fiche 50-443, 82/10718, 8210260330
- 5210260149 Interim deficiency rept re power surges in solid state protection sys which may disable protection circuit initially reported on 820805 item reportable based on 820806 kestinghouse itr Final rept elepected by 820115 DEVINCENTIS. J Yankee Atomic Electric Co DEVINCENTIS. J Public Service Co of New Hampshire 82/10/19 STARDSTECKI R Division of Project & Resident Programs ip 15799 018 24% Fiche 50-443, 82/10/19, 8210260149
- PULKET 50-444 SEABROOF NUCLEAR STATION. UNIT 2
- A Application/construction stage documents & correspondence
- E210120617 Nativication of 820924 meeting w/applicant in Seabrook,NH to inspect onsite radiological monitoring sys as part of OL sarety review.

 HRELERIU L Licensing Branch 3 82/09/17 KERRIGAN J D
 Licensing Branch 3 3pp 19672 235 24X Fiche 50-443,82/09/17,8210120617
- B210070160 Forwards drart results of analysis of associated circuits addressing question raised at 820910 meeting Once concurrence received, response will be issued as amend to FSAR, closing out Open Item 26 GAXTER: F Yankee Atomic Electric Co 82/09/20 SRINIVASAN, M Power Systems Branch 12pp 15645 049 24% Fiche 50-443, 82/09/20, 8210070160
- 8210180378 Requests assignment of reviewers for Bechtel work packages
 All three packages should be roady for NRR review by 821004
 Task Interface Agreement TIA 82-55 w/Region 4 enc!
 PERRIGAN, J D. Licensing Branch 3 82/09/20 LEAR, O. Hydrologic &
 Geotechnical Engineering Branch 308NAM, R. Mechanical Engineering
 Branch SCHAUER, F. Structural Engineering Branch 2pp 15/45 300
 24X Fiche 50-443, 82/09/20, 8210180378
- 8210010455 Forwards "Response to NRC Generic Request for Addl Info He NUMBO-0612-Control of Heavy Loads" DEVINCENTIS.J Yantes Atomic Electric Co DEVINCENTIS,J Public Service Co of New Hampshire 82/09/24 HERRIGAN.J B Licensing Branch 3 Lp 15572 017 24X Fiche 50-443.82/09/24.8210010445
- --8210010470 "Response to NRC Generic Request for Addi Info Re NUREG-0612, Control or Heavy Loads " + Public Servica Co of New Hampshire 82/09/30 134pp 15572 018 24X Fiche 50-443, 82/09/24,8210010465
- E210040112 Forwards response to NRC generic request for add) info re NAREO-DE12. "Control of Heavy Loads " W/o encl DEVINCENTIS. J Value Atomic Electric Co DEVINCENTIS. J Public Service Co of New Hampshire B2/09/24 KERRIDAN. J B Licensing Branch 3 [p 15581 143 24X Fiche 50-443.82/09/24.8210040112
- E210040193 Forwards responses to Hydrologic & Grotechnical Engineering Branch 820727 Series 240 requests for addl info, Questions 240 38, 240 39 & 240 41 Response to Ovestion 240 40 forthcoming DEVINCENTIS. J. Yankee Atomic Electric Co. DEVINCENTIS. J. Public Service Co. of New Hampshire B2/09/30 KERRIGAN. J B. Licensing Branch 3 14pp 15583 168 24X Fishe 50-443.82/09/30.8210040193
- 6210050199 Responds to Mechanical Engineering Branch 820618 request for addition Response includes "Prying Effect on Concrete Espansion Anchor Bolts Due to Pipe Support Base Plate Flexibility" Draft responses submitted 820728 DEVINCENTIS, J Public Service Co. of New Hampshire 82/09/30 RERRIGAN. J B. Licensing Branch 3 3p. 13609 085 24X Fiche 50-443.82/09/30,8210050199
- --8210050206 "Proging Effect on Concrete Expansion Anchor Golts Due to Pipe Support Base Plate Flexibility " GALUNIC.B., MCXENNA.M., RIGAMONTI.O United Engineers & Constructors, Inc. (subs. of Raytheon Co.) 79/07/20 88pp 15607 088 24X Fache 50-443, 82/09/30, 8210050199

- 8210050393 Requests add1 info re analysis proving any challenges so Class IE circuits from associated circuits do not prevent safe shutdown of plant Info re NUREG-0737. Item II E 4 2, Position A on containment isolation valves required KERRIGAN, J Licensing Branch 3 82/10/01 TALLMAN, N C Public Service Co of New Hampshire 9pp 15608 324 24x Fiche 50-443, 82/10/01, 8210050393
- 8210070105 Forwards revised response to Guestion 440 136 to Reacter's, Branch 820727 request for add1 info concerning steam generator tube rupture DEVINCENTIS.J Yankee Atomic Electric Co DEVINCENTIS.J Public Service Co of New Hampshire 82/10/05 KERRIGAN.J B Lichnits Branch 3 4pp 15628 074 24X Fiche 50-443.82/10/05 0210070105
- 8210130436 Forwards revised responses to Mechanical Engineering Bra-1 820301 & 05 Requests for Addl Info 210 3-210 69, originally submitted in util 820421.30 & 0510 ltrs.per 820511-13 meeting Responses will be incorporated into FSAR Amend 4/ DEVINCENTIS-J Yankee Atomic Electric Co DEVINCENTIS-J Public Service Co of New Hampshire 82/10/006 RERIIGAN J D Licensing Granch 3 126pp 15681 193 24X Fiche 50-443, 82/10/06x 82101.041s
- 82]0150510 Forwards revised FSAR Section & 2 2 providing justificality for excluding inert cover gas on sodium hydraxide storage tank info will be incorporated in Amend 48 to OL application
 DEVINCENTIS. J Yanker Atomic Electric Go DEVINCENTIS. J Public Service Co of New Hampshire 82/10/07 KERRIGAN. J Licensing Branch 3 4pp 15714 189 24X Fiche 50-443.82/10/07.82(0)30518
- 8210180001 Forwards notes from 820914 & 15 instrumentation & Controls Sys Branch review meetings, per NRC 820216 & 0323 requests Notes also include items discussed at 820323-25,0512 & 13 & 0715 & 14 meetings & NURES-0737 action items
 DEVINCENTIS. J Yankee Atomic Electric Co DEVINCENTIS, J Publis Service Co of New Hampshire 82/10/14 & MERRIGAN. J Licensing Branch 3 93pp 15720 031 24X Fichs 50-443,82/10/14.8210180031
- 8210250307 Requests advanced notification of scheduled NRC meetings to facilities to enable ample time for Atty General Ofc to arrange for staff attendance
 KINDER.E T New Hampshire, State of 82/10/18 WHEELER, ()
 Licensing Dranch 3 1p 15790 069 24X Fiche 50~443, 82/10/10.
- 8210270006 Forwards request for info re onsite audit for setamic to dynamic qualification review & pump & valve operability Completion of encil forms requested within 3 was Specific date of audit to be mutually agreed to by NRC & applicant KERRIGAN, J D Licensing Branch 3 82/10/21 TALLMAN, H C Publis Service Co of New Hampshire 25pp 15816 348 24% Fiche 50~443,82/10/21,8210270006
- 8210280117 Forwards response to Power Sys Branch & Equipment Qualification Branch 821001 Request for Add 1 Info 430 149 rs analysis on associated circuits, per 820910 & 1020-21 meetings w/NRC BEVINCENTIB. J Yankee Atomic Electric Co DEVINCENTIB. J Public Service Co of New Hampshire 82/10/26 MIRAGLIA,F J licensing Branch 3 10pp 15837 136 24X Fiche 50-443.82/10/26.621021021031
- D NRC Draft/Final Environmental Statements, supply & correspondence
- 8210120029 Forwards comments from State of NH to be included in FML 820730 Itm re facilities DES W/o encl MIRAOLIA:F J Licensing Branch 3 82/08/24 TALLMAN, W C Fublic Service Co of New Hampshire Ip 13689 196 24X Fiche 50-443, 82/08/24, 8210120029
- F Securaty, medical, emergency & fire protection plans
- 821012012B Summary of 82072O meeting w/utils & United Engineers & Constructors in Bethesda.MD re associated circuits Presentation outline & details of preliminary review & analysis of associated circuits FRAR change encl MNOX-J Power Systems Branch 82/09/24 SRINIVASAN.H Power Systems Branch 82/09/24 SRINIVASAN.H Power Systems Branch 100pp 15692 050 24X Fiche 50-443.82/09/24.8210120128
- G Adjudicatory correspondence
- 8210060194 Forwards Seacoast Anti-Pollution Leagus objection to k motion for reconsideration of ASLB 820713 order & motion to certify objections to ASLAB BACKUS, R A Backus, A HOYT, H F, LUEBKE, E A, HARBOUR, J Atomic Bafett and Licensing Board Panel 2pp 15614 220 24X Ficks 50-443, 82/09/30, 8210060174

- --8210060206 Objection to & motion for reconsideration of ASLB 820913 order & motion to certify objections to ASLAB Contention Suppl 4 should be admirted BACKUS, R A Seacoast Anti-Pollution League BACKUS, R A Bockus, R A 82/07/30 Atomic Safety and Licensing Board Panel 7ρρ 15614 222 24X Fiche 50-443, 82/09/30.8210060194
- --B210060214 Affidavit of P Brown Hearings underway before appropriate state agencies re New England Electric Transmission Corp. Lifew England Power Poul applications for const of transmission lines
 BROWN.P Seacoast Anti-Pollution League 82/09/30 Bpp
 [5514 227 24% Fiche 50-443, 82/09/30.8210060194
- 0210050262 Order allowing parties to file reply to New England Coalition on Nuclear Pollution objections & motion & State of NH motion for reconsideration of ASLB 820913 memorandum & order Reply due by 821019 HOYL-H F Atomic Safety and Licensing Board Panel 82/10/01 2pp 15610 284 24% Fiche 50-443,82/10/01.8210050262
- 8210200026 First set of interrogatories & request for documents on Contentions I A 2, I B 1, I B 2 & I C
 JORDAN, M 9 CURRAN, D New England Coalition on Nuclear Pollution
 JORDAN, M 5 Harmon & Weiss B2/10/13 Public Service Co of New Hampshire 14pp 15755 039 24X Fiche 50-443,82/10/13,8210200026
- --8210200035 First set of interrogatories & request for documents on Contentions I A 2.I B 1.I B 2 & I C
 JORDAN, W S , CURRAND New England Coalition on Nuclear Pollution
 JORDAN, W S Harnon & Weiss B2/10/13 Office of the Executive
 Legal Director 12pp 15755 047 24X Fiche 50-443, 82/10/13.
 8210200026
- --8210200042 First set of interrogatories & request for documents on Contentions II B 1.II B 3.II B 4 & II B 5
 JORDAM, W S , CURRAN, D Now England Coalition on Nuclear Pollution
 JORDAN, W S Harmon & Weiss 62/10/13 Public Service Co of
 New Hampshire 8pp 15755 059 24X Fiche 50-443,82/10/13,
 8210200026
- --8210200049 First set of interrogatories & request for documents on Contentions II B 1, II B 3.II B 4 & II B 5 Certificate of Svc ench

 JORDAN, N S , CURRAN, D New England Coalition on Nuclear Pollution

 JORDAN, N S Harmon & Weiss 82/10/13 Office of the Executive
 Legal Director 9pp 15755 067 24X Fiche 50-443, 82/10/13, 9210200026
- 8210270153 Response opposing New England Coalition on Nuclear Power objections to prehearing conference memorandum & order & motion to certify objections to ASLAB Leaves in objections already considered Certificate of Svc encl
 GAD.R K Public Service Co of New Hampshire GAD.R K Roper & Gray 82/10/26 Atomic Safety and Licensing Board Panel 63pp 15829 327 24X Fichs 50-443,82/10/26,8210270153
- B210270166 Response opposing State of NH objection & motion for reconsideration of ASLB 820913 order No errors committed in ruling on NH contentions ASLB should not certify rulings since certification not requested Certificate of Svc encl OAD, R K Public Bervice Co of New Hampshire OAD, R K Ropeu & Gray 82/10/26 Atomic 8afety and Licensing Board Panel P2pp 15830 117 24X Fiche 50-443,82/10/26,8210270166
- H General correspondence
- 8210120270 Requests that DR Lewis be added to svc list TAYLOR.J Atomic Safety and Licensing Board Panel 82/10/08 Public Service Co of Naw Hampshire ip 15652 317 24X Fiche 50-443, 82/10/08.8210120270
- G inspection reports, IE Bulletins & correspondence
- 8210070392 Forwards IE Insp Repts 50-443/82-09 & 50-444/82-09 on 820824-27 No noncompliance noted MARTIN.T T Division of Engineering & Technical Programs 82/09/22 TALLMAN.H C Public Service Co of New Hampshire 2pp 15433 331 24x Fichs 50-443.82/09/22.8210070392
- --8210070400 IE Insp Repts 50-443/82-09 & 50-444/82-09 on 820824-2/ No noncompliance noted Major areas inspected procedures & work activities re concrete const of reactor containment bidg dome.structural welding within containment bidg & GA review VARELA, A A . DURR J P Region I. Office of Director 82/09/20 7pp 15633 333 24% Fiche:50-440-82/09/22.8210070392
- 820BI90233 IE Info Notice 80-35, Suppl 1, "Leaking & Dislodged I-125 Implant Seeds." Svc list encl. COBB.L. I. Division of Fuel Facilities, Materials & Safeguards 82/10/06 Comsulidated Edison Co of New York 66pp 15761 250 24X Fiche 50-000, 82/10/06, 820BI90233

- 8208190238 IE Bulletin 82-03, "Stress Corresion Cracking in Thick-Wall, Large-Diameter, Stainless Steel, Recirculation Sys Piping at BMR Plants " Svc list enc)
 DEYOUNG, R C Director's Office. Office of Inspection and Enforcement 82/10/14 Consolidated Edison Co of New York
 115pp 15810 125 24X Fiche 50-000, 82/10/14,8208190228
- S Reportable occurrences. LERs & related correspondence
- 6210190126 Corrected version of final deficiency rept re misapplication of torquing equipment by Beloit Power Sys Initially reported on 820820 Corrective erocedure provided by vendor will preclude potential problems
 DEVINCENTIS, J. Yantee Atomic Etectric Co. DEVINCENTIS, J. Public Service Co. of New Hampshire. 82/09/20. STARDSTECKI. R. Division of Project & Resident Programs. 2pp. 15742 132. 24X
 Fiche 50-443, 82/09/20, 8210190126
- 8210190136 Corrected version of final deficiency rept re Robertshaw Controls thermostatic valves initially reported on 820820 Corrective actions described by vendor will preclude potential problems
 DEVINCENTIS.J Yankee Atomic Electric Co DEVINCENTIS.J Public Service Co of New Hampshire 82/09/20 STARDSTECKI.R Division of Project & Resident Programs 3pp 15742 227 24X
 Fiche 50-443.82/09/20.82(0190136
- 8210190363 Final deficiency rept re cracked welds in containment annular steel end connections Initially reported on 820910 Metallurgical investigation performed welding & installation procedure revised & cracked connections replaced DEVINCENTIS, J. Yankee Atomic Electric Co. DEVINCENTIS, J. Public Service Co. of New Hampshire 82/10/12 STARDSTECKI.R Division of Project & Resident Programs 3pp 15740 321 24X Fiche 50-443, 82/10/12, 8210190363
- 8210260:30 Interim deficiency rept re sheared pinion keys in Limitorque Model 5B-0-25 motor operators Initially reported on 820702 Caused by use of inappropriate key mati Limitorque 5 Westinghouse continuing investigation DEVINCENTIS, J Yankee Atomic Electric Co DEVINCENTIS, J Public Service Co of New Hampshire 82/10/18 STAROSTECKI.R Division of Project & Resident Programs 2pp 15802 340 24X Fiche 50-443, 82/10/18, 8210260330
- 0210260149 Interim deficiency rept re power surges in solid state protection sys which may disable protection circuit initially reported on 020005 Item reportable based on 020006 Westinghouse Itr Final rept expected by 030115
 DEVINCENTIS.J Yankes Atomic Electric Co. DEVINCENTIS.J Public Service Co. of New Hampshire 02/10/19 STARGSTECKI, R Division of Project & Resident Programs 1p 15799 018 24X
 Fiche 50-443, 02/10/19, 0210260149
- DOCKET 50-445 COMANCHE PEAK STEAM ELECTRIC STA JUNIT 1
- A Application/construction stage documents & correspondence
- 8210220513 Notification of 820913 meeting w/util in Bethesda, MD to discuss procedures generation package CLIFFORD, J W Procedures & Yest Review Branch 82/08/27 ZIEMANN, D L Procedures & Test Review Branch 2pp 15786 089 24X Fiche 50-445, 82/08/27, 8210220513
- #210210025 Summary of #20625 meeting w/util & Gibbs & Hill in Bethesda, MD re equipment qualification BURWELL.8 B Licensing Branch 1 #82/09/30 Licensing Branch 1 17pp 15782 180 24% Fichs 50-445.#82/09/30.#8210210025
- F Security, medical, emergency & fire protection plans
- 8210040020 Releases public version of applicant motions & affidavits & State of TX emergency mgt plan FELTON.J H Division of Rules and Records 92/09/21 Document Hanagement Branch ip 15577 293 24X Fich = 50-445.82/09/21. 8210040020
- --8210040042 Public version of State of TX emergency mgt plan.including Hood County, Somervell County & City of Olen Rose, TX emergency operations plans CLEMENTS, W D. ADAMS, J B. LANSFORD, R A. Teras, State of 82/09/24 801pp 15878 269 24X Fiche 50-445,82/09/21, 8210040020
- 8210070109 Forwards "Evaluation of Hood & Bommervell Counties & State of TX Radiological Emergency Plans for Comanche Peak Steam Electric Station " Offsite protection adequate Joint exercise planned for early 1983 THOMAS.L M Federal Emergency Management Agency 82/09/29 DIRCKS.W Office of the Executive Director for Operations ip 15628 165 24X Fiche 30-445.82/09/29,8210070109

- --8210070112 "Evaluation of Hood & Sommervell Counties & State of FX Radiological Emergency Plans for Comanche Peak Steam Electric Station "
 - Federal Emergency Management Agency 82/09/29 57pp 15628 166 24X Fiche 50-445.82/09/29.8210070109
- 6210130576 Forwards response to license condition on physical security program approval & pages to FSAR security plan Response & plan withheld (ref 10CFR2 790 % 10CFR3 21) GARY,R J Teras Utilities Generating Co 82/10/08 YDUNOBLOOD, U J Licensing Branch 1 1p 15679 060 24X Fiche 50-445,82/10/08, 62/6100576
- 6210180006 Forwards Amend 35 to FSAR consisting of Revision 5 to emergency plan CARN.R J Telas Utilities Generating Co 82/10/12 DENTON.H R Difice of Nuclear Reactor Regulation. Director 2pp 15720 126 24X Fich 50-445, 82/10/12, 8210180006
- --821018000B Amend 35 to FSAR consisting of Revision 5 to emergency plan JONES,R A Teras Utilities Generating Co 82/10/12 199pp 15720 128 24X Fiche 50-445, 82/10/12, 8210180006
- B210280259 Forwards FEMA interim finding on plant offsite emergency preparedness, consisting of FEMA memo to NRC & attachments ROTHSCHILO,M V Hearing Branch I 82/10/27 MILLER.H E. COLF.R., MCCOLLON.K A Atomic Safety and Licensing Board Panel 59pp 15838 147 24X Fiche 50-445 82/10/27,8210280259
- G Adjudicatory correspondence
- G210040020 Releases public version of applicant motions % affidavits & State of TX emergency mgt plan FELTON, JM Division of Rivies and Records B2/09/21 Document Management Branch Ip 13577 293 24X Ficho 50-445.82/09/21, 8210040020
- B210040024 Public version of applicant motion for summary disposition of intervenor Citizens Assoc for Sound Energy Contention 22 re emergency planning SANFORD, J C Teras Utilities Generating Co SANFORD, J C Debevoise & Liberman 82/08/23 Atomic Safety and Licens) nq Board Panel 16pp 15577 294 24X Fishe 50-445.82/09/21, 8230400020
- ~-8210040030 Public version of affidavit of RA Jones re intervenor Citizens Assoc for Sound Energy Contention 22 concerning energency planning JONES.R A Texas Utilities Generating Co 82/08/20 iipp 15577 315 24X Fiche 50-445,82/09/21.8210040020
- --B210049033 Public version of BT Lancaster affidavit re intervenor Citizens Assoc for Sound Energy Contention 22 concerning emergency plan exercises & drills LANCASTER.B T Texas Utilities Generating Co B2/08/20 7pp 15577
- --9210040037 Public version of affidavit of RE Linnemann re intervenor Citizens Assoc For Sound Energy Contention 22 conterning sycs of medical personnel for radiation emergencies U/resumes, notice of appearance & Certificate of Syc LINMEMANN.R E Texas Utilities Generating Co LINNEMANN.R E Radiation Management Corp 82/08/20 21pp 15577 333 24X Fiche 50-445.82/09/21.8210040020
- --8210040042 Public version of State of TX emergency mgt plan.including Mood County.Scmervell County & City of Glen Rose, TX emergency operations plans CLEMENTS.W D . ADAMS.J B . LANSFORD.R A Texas, State of 82705/24 801pp 15578 269 24X Fiche 50-445.82/09/21. 8210040020
- B2t0040089 Order denying NRC B20824 request for reconsideration of ASIM B20804 order to show cause re NRC failure to disclose identity of informants Ltr-designated individuals B K must be identified HILLERINE Atomic Safety and Licensing Board Panel B2/09/30 Office of the Erecutive Legal Director 14pp 1558f 001 24X Fiche 50-445, B2/09/30, B210040089

- 8210130299 Brief on status of record re findings needed for doctation, per ASLB 820922 memorandum & order ABLB should close record on all issues.order prompt submittal of proposed findings & issue decision Certificate of Svc enci REYNOLDS.N S . HORIN.W A Teras Utilities Generating Co REYNOLDS.N S . Debevoise & Liberman B2/10/08 35pp 19678 205 24V Fiche 50-445.82/10/08.8210130299
- 82(01501B3 Forwards exceptions to ASLB 820730 order denying reconsideration filed per 10CFR2 762(a) Motion seeking stay of effectiveness of order to be filed on 821012 M/o enc! TURK, S E. Hearing Branch 1 82/10/08 SHOEMAKER, C J. Atomic Safety and Licensing Appeal Panel 2pp 15707 178 24x Fiche 50-445, 82/10/08, 8210150183
- 8210150366 Exceptions to ASLB B20930 order denying reconsideration of ASLB B20804 order to show cause why sanctions should not be imposed on NRC for failure to disclose informants Certificate of Svc encl TURK, S E Hearing Branch 1 82/10/08 Atomic Safety and Licensing Appeal Panel 7pp 15704 307 24X Fiche 50-445.82/10-8210150366
- 82(0)50224 Response to ASLB 820922 memorandum & order for briefs on necessary documents & info to close evidentiary record Certificate of Svc enci ELLIS.J Citizens Association for Sound Energy 82/10/09 6(Ipp 19705 286 24X Fishe 50-445,82/10/09.8210150224
- 8210130292 Responds to ASLB 820922 memorandum & order re record stat ASLB should close record on Contention 22 & Contention 5 w/sxception of portions on issues of Board Notification 82-90 & Walsh/Doyle allegations M/Cortificate of Svc ROTMSCHILD.H U . MIZUND.0 B Hearing Branch 1 82/10/11 .3 ipp 15678 102 24X Fiche 50-445.82/10/11.6210130292
- S210150124 Application for stay of effectiveness of ASLB 620730 Ordinating reconsideration ruling that NRC did not show good cause for failure to comply w/orders to disclose informants 3 ordering disclosure Certificate of Svc encl
 TURK 5 E Hearing Branch 1 82/10/12 Atomic Safety and Licensing Appeal Panel 13pp 15698 001 24X Fiche 50-449, 62/10/12,8210150124
- 8210250104 Response to ASLB directive re Citizens Assoc for finund Energy exhibits Requests listed documents from Assoc Exhibits 190A-447 be accepted into evidence Certificate of Svc encl Related correspondence ELLIG.J Citizens Association for Sound Energy 82/10/10 5/19: 15792 089 24% Fiche 50-445.82/10/10.8210250104
- 9210280355 Hotion for reconsideration of ASLB ruling re attachments
 J Doule deposition/testimony Clean copies of drawings will
 be provided, but intervenor should be allowed to ref
 documents Certificate of Svc encl Related correspondence
 ELLIB. J Citizens Association for Sound Energy 82/10/23 At
 Safety and Licensing Board Panel 8pp 15839 001 24X
 Fiche. 50-445, 82/10/23, 8210280355
- 8210280259 Forwards FEMA interim finding on plant offsite emergenty greparedness consisting of FEMA memo to NRC & attachments ROTHSCHILD, M U Hearing Branch i 82/10/27 MILLER, M E. CUlf, MCCOLLON, K A Atomic Safety and Licensing Board Panel. 59pp i5838.147 24X Fiche 50-445,82/10/27,8210280259
- K Utility Final Safety Analysis Report (FBAR) & amends
- 8210180006 Forwards Amend 35 to FBAR consisting of Revision 5 to emergency plan GARY, R J Texas Utilities Generating Co 82/10/12 DENTON, H & Office of Nuclear Reactor Regulation, Director 2pp 13720 1c/A 24X Fiche 50-445
- --8210180008 Amend 35 to FSAR consisting of Revision 5 to smergency JONEB.R A Texas Utilities Generating Co 82/10/12 199pp 15720 128 24X Fiche 50-445, 82/10/12, 8210180006
- Q Inspection reports. IE Bulletins & correspondence
- 8210070364 Forwards IE Insp Rept 50-445/82-20 on 820801-31 No noncompliance noted MADSEN.O L. Division of Resident, Reactor Project & Engineering Programs 82/09/22 OARY, R. J. Texas Utilities Generating Co 15634 040 24X Fiche 50-445, 82/09/22, 8210070364

- --B210070369 IE Insp Rept 50-445/82-20 on B20801-31 No moncompliance noted Major areas inspected preoperation test review procedure: plant tour & status KELLEY. D.L., WESTERMAN. T.F. Division of Resident. Reactor Project & Engineering Programs B2/09/17 Spp 15634 042 24X Fiche 50-445.82/09/22:8210070364
- 6210190816 Forwards IE insp Rept 50-445/82-14 on 820803-20 No noncompliance noted MADSEM, G.L. Division of Resident, Reactor Project & Engineering Programs 82/09/27 GARY, R.J. Texas Utilities Generating Co 2, 15736 139 24X Fiche 50-445,82/09/29,8210190816
- --8210190820 lE Insp Rept 50-445/82-14 on 820803-20 No noncompliance noted Major areas inspected pipe whip restraints & licensee method of QC insp of skewed welds
 STEMART,R C . TAYLOR.R O . WESTERMAN,T F Division of Resident, Reactor Project & Engineering Programs 82/09/28 8pp 15736 141 24X Fiche 50-445,82/09/29,8210190816
- 6210190772 Forwards IE Insp Repts 50-445/82-18 & 50-445/82-09 on 820907-10 No noncomplance noted MADBEN, G. L. Division of Resident, Reactor Project & Engineering Programs 62/10/01 OARY, R. J. Texas Utilities Generating Co. 2pj 15737 128 24X Fiche 50-445,82/10/01,8210190772
- --8210190776 IE Insp Repts 50-445/82-18 & 50-446/82-09 on 820907-10 No noncompliance noted Major areas inspected const activities, including site tour, observation of welding, eram of safety-related piping & welding on main control panels QILBERT. D. TOMLINSON, D.P., MESTERMAN, T.F. Division of Resident, Reactor Project & Engineering Programs 82/09/29 ip 15737 130 24X Fiche 50-445,82/10/01,8210190772
- 8208190233 IE Info Notice 80-35, Suppl 1, "Leaking & Dislodged 1-125 Implant Seeds " Svc list encl CDBB.L I Division of Fuel Factities, Materials & Safeguards 82/10/06 Consolidated Edison Co of New York 66pp 15761 250 24X Fiche 50-000,82/10/06,8208190233
- 8208190238 IE Bulletin 92-03, "Stress Corrosion Cracking in Thick-Wall, Large-Diameter, Stainless Steel, Recirculation SysPiping at BWR Plants " Svc list encl DEYOUNG, R C Director's Office, Office of Inspection and Enforcement B2/10/14 Consolidated Edison Co of New York 115pp 15010 125 24% Fiche 50-000, 82/10/14, 8208190238
- S Reportable occurrences. LERs & related correspondence
- 8210040318 Interim deficiency rept re conduit supports Initially reported on 820823 Evaluation continuing Completion anticipated by 821082 DARY.R J Texas Utilities Generating Co. 82/09/20 HADSEN, O. L. Division of Resident, Reactor Project & Engineering Programs 1:15386-167 248 Fiche 50-445:82/09/20:8210040318
- 8210260375 Deficiency rept re overtorquing of safety-relief valves Initially reported on 820910 Evaluation in progress & will be completed by 821130 OARV.R J Texas Utilities Generating Co 82/10/06 MADSEN.G L Division of Resident. Reactor Project & Engineering Programs ip 15803 3642 24X Picho 50-445.82/10/06.8210260375
- 821025033B Interim deficiency rept re defective Limitorque pinion keye Initially reported on 82081B Matter not reportable per 10CFR50 55(e) based on investigation GARY,R J Texas Utilities Generating Co 82/10/12 MADBEN, & L Division of Resident, Reactor Project & Engineering Programs Ip 15790 331 24X Fichs 90-445,82/10/12,821025033B
- 8210250346 Interim deficiency mept re linear indications identified in diesel generator auxiliary skid Initially reported on 820709 Evaluation continuing Next mept expected by 821217 GARY.R J Texas Utilities Generating Co 82/10/14 MADSEN, 0 L Division of Resident, Reactor Project & Engineering Programs lp 15790 336 24X Fiche 50-445,82/10/14,8210250346.
- DOCKET 50-446 COMANCHE PEAK STEAM ELECTRIC STA JUNIT 2
- A Application/construction stage documents & correspondence
- S2102205i3 Notification of 8209i3 meeting w/util in Bethesda,MD to discuss procedures generation package CLIFFORD,J W Procedures & Test Review Branch 82/08/27 ZIEMANN,D L Procedures & Test Review Branch 2pp 15786 089 24X Fiche. 30-445, 82/08/27, 82102205i3
- 8210210025 Bummary of B20625 meeting w/util & Gibbs & Hill in Bethesda, MD re equipment qualification, BURMELL: B B. Licensing Brench i 82/09/30 Licensing Branch i 17pp 15782 180 24X Fiche. 30-445, 82/09/30, 8210210025.

- F Security, medical, emergency & fire protection plans
- 8210040020 Releases public version of applicant motions & affidavits & State of TX emergency mgt plan
 FELTON. II Division of Rules and Records 82/07/21 Document Management Branch (p. 15577-293 24X Fiche 50-445,82/09/21,8210040020
- --B210040042 Public version of State of TX emergency mgt plan, ancluding Hood County, Somervell County & City of Glen Rose, TX emergency operations plans CLEMENTS, W D , ADAMS, J B , LANSFORD, R A Texas, State of B2/05/24 801pp 15578 269 24X Fiche 50-445, 82/09/21, 8210040020
- B210070109 Forwards "Evaluation of Hood & Sommervell Counties & State of TX Radiological Emergency Plans for Comanche Peak Steam Electric Station "Offiste protection adequate Joint exercise planned for early 1983 THOMAS, L M Federal Emergency Management Agency 82/09/29 DIRCKS, W Office of the Executive Director for Operations 1p 15628 165 24% Fiche 50-445,82/09/29,8210070109
- --8210070112 "Evaluation of Hood & Summervell Counties & State of IX Radiological Emergency Plans for Comanche Peak Stram Electric Station "
 * Federal Emergency Management Agency 82/09/29 57pp 15628 166 24X Fiche 50-445,82/09/29,8210070109
- B210130576 Forwards response to license condition on physical security program approval & pages to FSAR security plan Response & plan withheld (ref 10CFR2 790 & 10CFR73 21)

 QARY,R J Teras Utilities Generating Co B2/10/08 YOUNGBLOOD, II J
 Licensing Branch 1 1p 15679 060 24X Fiche 50-445, 82/10/08.
- B210180006 Forwards Amend 35 to FSAR consisting of Revision 5 to smergency plan GARY, R J Teras Utilities Generating Co 82/10/12 DENTON, N R Office of Nuclear Reactor Regulation, Director 2pp 19720 126 24X Fiche 50-445,82/10/12,8210180006
- --8210180008 Amend 35 to FSAR consisting of Revision 5 to emergency plan JONES.R A Teras Utilities Generating Co 82/10/12 199pp 15720 128 24X Fiche 50-445, 62/10/12/8210180006
- 8210280259 Forwards FEMA interim Pinding on plant offsite emergency preparedness, consisting of FEMA memo to NRG & attachments ROTHSCHILD, M U Hearing Danach 1 82/10/27 MILLER, M E Atumic Safety and Licensing Board Panel 59pp 15838 147 24X Fiche 50-445, 82/10/27, 8210280259
- G Adjudicatory correspondence
- 8210040020 Releases public version of applicant motions & affidavity & State of TX emergency mgt plan FELTON.J H Division of Rules and Records 82/09/21 Document Management Branch 1p 15577 293 24X Fiche 50-445.82/09/21. 8210040020
- --8210040024 Public version of applicant motion for summary disposition of intervenor Citizens Assoc for Sound Energy Contention 22 re-emergency planning SANFORD, J C Texas Utilities Generating Co SANFORD, J C Debevoise & Liberman 82/08/23 Atomic Safety and Licensing Board Panel 16pp 15577 294 24X Fiche 50-445,82/09/21,8210040020
- --B2(0040026 Public version of statement of matl facts not genuinely at issue re emergency planning
 * Texas Utilities Generating Co B2/08/23 Atomic Befety and
 Licensing Board Panel Spp 15577 310 24X Fiche 50-445,
 82/09/21
- --8210040030 Public version of affidavit of RA Jones re intervenor Citizens Assoc for Bound Energy Contention 22 concerning emergency planning JONES.R A Texas Utilities Generating Co. 82/08/20 Hpp 15577:315 24X Fiche 50-445,82/09/21.8210040020
- ---B210040033 Public version of BT Lancaster affidavit re intervenor Citizens Assoc for Sound Energy Contention 22 concerning emergency plan exercises & drills LANCASTER.B T Texas Utilities Generating Co B2/08/20 7pp 15577 326 24X Fiche: 50-445, B2/09/21, B210040020

- --8210040037 Public version of affidavit of RE Linnemann re intervenor Citizens Assoc for Sound Energy Contention 22 concerning syes of nedical personnel for radiation emergencies W/resumes, notice or appearance & Certificate of Syc Linnemann, R E Teras Utilities Cenerating Co. Linnemann, R E Radiation Management Corp. 82/08/20. 21pp. 15577-333. 24X Fiche 50-445,82/09/21.8210040020
- 8210040089 Order denying NRC 820824 request for reconsideration of ASLN 820804 order to show cause to NRC failure to disclose identity of informants Ltr-designated individuals 8 K must be identified MILLER.M E Atomic Safety and Licensing Board Panel 82/09/30 Bifice of the Elecutive Legal Director 14pp 15581 001 24X Fichs 50-445, 82/09/30, 8210040089
- 8210130299 Brief on status of record re findings needed for detision, per ASLB 820722 memorandum & order ASLB should close record on all issues.order prompt submittel of proposed findings & issue decision Certificate of Sve enci RENOLDS.N S . HORIN.W A Teras Utilities Generating Co RENOLDS.N S . Debevoise & Liberman 82/10/08 35pp 15678 205 24% Fiche 50-445.82/10/08.8210130299
- 8210150183 Forwards exceptions to ASLB 820930 order denying reconsideration, filled per 10CFR2 782(a) Hotion seeking stay or effectiveness of order to be filed on 821012 M/o encl TURK, S.E. Hearing Branch J. 82/10/08 SHGEMAKER, C.J. Atomic Sarety and Licensing Appeal Panel 2pp 15707 178 24X Fiche 50-445, 82/10/08,8210150183
- 8210150346 Exceptions to ASLB 820930 order denying reconsideration of ASLB 820804 order to show cause why sanctions should not be imposed on NRC for failure to disclose informants Certificate of Svc encl TURK, S.E. Hearing Branch 1 82/10/08 Atomic Safety and Licensing Appeal Panel 7pp 15704-307 24X Fiche 50-445,82/10/08, 8210150366
- 6210150224 Response to ASLB 820922 memorandum & order for briefs on necessary documents & info to close evidentiary record Certificate of Svc enc! ELLIS.J Citizens Association for Sound Energy 82/10/09 60pp 15705 286 24X Fiche 50-445.82/10/09.8210150224
- 8210130272 Responds to ASLB 820922 memorandum & order re record status ASLB should close record on Contention 22 & Contention 5 w/exception of portions on issues of Board Notification 92-90 & Walsh/Doyle allegations W/Certificate of Svc ROTHSCHILD.M V. HIZUND.G S Hearing Branch 1 82/10/11 33pp 15478 102 24x Fiche 50-445,82/10/11.8210130292
- B210150124 Application for stay of effectiveness of ASLB 820930 order denying reconsideration ruling that NRC did not show good cause for failure to comply w/orders to disclose informants b ordering disclosure Certificate of Svc encl
 TURK, S E Hearing Branch 1 82/10/12 Atomic Safety and Licensing Appeal Panel 13pp 15498 Out 24% Fiche 50-445, 82/10/12,8210150124
- 8210150464 Notice of ASLAB constitution AS Rosenthal, chairman & (R Johnson & TS Moore, members SHOEHAKER, C J Atomic Safety and Licensing Appeal Panel 82/10/12 to 15703 105 24X Fiche 50-445.82/10/12.8210150464
 - SLB directive re Citizens Assoc for Sound

 "isted documents from Assoc
 ted into evidence Gertificate of
 fence
 ion for Sound Energy 82/10/18 55pp
- Judyle deposition/testimony Clean copies of drawings will be provided but intervenor should be allowed to ref documents Certificate of Svc encl Related correspondence ELLIS, J Citizens Association for Sound Energy 82/10/23 Atomic Safety and Licensing Board Panel 8pp 15837 001 24x Fiche 50-445,82/10/23,8210280355
- 8210280259 Forwards FEMA interim finding on plant offsite emergency preparedness, consisting of FEMA memo to NRC & attachments ROTHSCHILD:N U Hearing Branch 1 82/10/27 MILLER:N E. COLE:N. ACCOLLON;K A. Atomic Safety and Licensing Board Panel 39pp 15838 147 24% Fiche 50-445.82/10/27.8210280259
- K Utality Final Bafety Analysis Report (FSAR) & amends

1

8210180006 Forwards Amend 35 to FBAR consisting of Revision 5 to emergency plan CARY.R J Texas Utilities Generating Co 82/10/12 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 15720 126, 24X Fichs 50-445, 82/10/12, 82/0180006

- --8210180008 Amend 35 to FSAR consisting of Revision 5 to energer() JONES, R A Terms Utilities Generating Co 82/10/12 [v/pp 15/720 128 24% Fiche 50-445, 82/10/12, 82/10/8000)
- O inspection reports. IE Bulletins & correspondence
- --B210190776 IE Insp Repts 50-445/B2-18 & 50-446/B2-09 on U.V.O/ 12), noncompliance noted Major areas inspected const activities including site tour observation of welding, exam of safety-related piping & welding on main control panels of LBERTI. D . TOMLINSON. D P . WESTERMAN, T F Division of Resider Reactor Project & Engineering Programs B2/09/29 ip 15/J? to 24% Fithe 50-445/B2/10/01/8210190772
- 8208190233 IE Info Notice 80-35, Suppl 1, "Leaking & Divided 1-177 Implant Seeds " Svc list encl COBB.L I Division of Fuel Facilities, Materials & Hafegueres 82/10/06 Consolidated Edison Co. of New York 6559 15/64 24X Fiche 50-000.82/10/06.8208170233
- 8208170238 IE Bulistin 82-03, "Stress Corrosion Cracking in this?"
 Wall, Large-Diameter, Stainless Steel, Recirculation flys
 Piping at BWR Plants " Svx list encl
 DEYDUNG, R C Director's Office, Office of Inspection and
 Enforcement 82/10/14 Consolidated Edison Co of the Yor)
 115pp 15810 125 24X Fichs 50-000. 82/10/14, 0208170218
- S Reportable occurrences. LERs & rotated correspondence
- 82100403)B Interim deficiency rept re-conduit supports initially reported on 820823 Evaluation continuing Completion anticipated by 821022
 GARY.R J Texas Utilities Cenerating Co. 82/09/20 (MADIAN. U. Division of Resident. Reactor Project & Engineering Program 15586-167 24x Fiche 50-445,82/09/20,8210040318
- 8210240375 Deficiency rept re overtorquing of safety-relief valves Initially reported on 820910 Evaluation in progress & ufit be completed by 821130 OARY:R J Texas Utilities Generating Co 82/10/06 HABUIN. G I Division of Resident. Reactor Project & Engineering Programs I 15803 362 24X Fichs 50-445, 82/10/06. 8210240375
- 82(0250338 Interim deficiency rept re defective Limitarque piniam keys Initially reported on 820818 Matter not reportable per 10CFR80 55(e) based on investigation GARY/R J Texas Utilities Generating Co 82/10/12 MABLE 6 to Division of Resident, Reactor Project & Engineering Programs 1:15790 331 24X Fichs 50-445,82/10/12,8210250338
- 8210250346 Interim deficiency rept re linear indications identified in diesel generator auxiliary skid initially reported on 820709 Evaluation continuing Next rept expected by 821217 CARY.R J Texas Utilities Generating Co 82/10/14 MADNEN Q L Division of Resident, Reactor Project & Engineering Programs 15770 336 24% Fichs 50-445.82/10/14.8210250346

DOCKET STN-50-447 GESSAR-238

- A Application/construction stage documents & correspondence
- B207;20147 Forwards NEDO-2147;-01, "Analytical Hodel for Estimations Drag Forces on Rigid Submerged Structures Caused by LOCA & Safety Relief Valve Ramshead Air Discharges, Suppl for Y-Quencher Air Discharges "BUCHHOLZ,R H General Electric Co 80/06/18 PARR, O D Licenta-Oranch 3 Jp 13808:001 24X Fishe 50-447,80/06/18,8207120147
- --8207120283 "Analytical Model for Estimating Drag Forces of Rigid Submerged Structures Caused by LOCA & Safety Relief Valve Remehead Air Discharges, Suppl for X-Quencher Air Discharges " LASHER, L E , TOWNSEND.H E . ROSERS.A E General Electric Co NEDD-21471-01 501 79/10/31 lipp 13808 002 24X Fiche 50-447.80/06/18.8207120147
- 8210040380 Notification of 820923 meeting w/OE in Bethesda,MD for Technical Update Meeting 4 on 0688AR-II probabilistic risk assessment LYNCH.M D. Licensing Branch 2 82/09/17 THOMAS,C O Standard Listion & Special Projects Branch 4pp 15597 207 28x Fiche 50-447,822/09/17,8210040380.

- 9210050398 Forwards Amend 7 to application for final design acceptance review of OESBAR-238 correcting typographical errors & clarifying discrepancies in portions of Chapters 1.3.4,6 & 15
 VILLAR Oeneral Electric Co. 82/09/23 EISENHUT.D.9 Division of Cicensing 1p 15777 001 24X Fiche 50-447.82/09/23,8210050398
- --8210050408 Amend to application for final design acceptance review of OESSAR-238, correcting typographical errors & clarifying discrepancies in portions of Chapters 1, 3, 4,6 & 15 VILLA, R. Oeneral Electric Co. 82/07/23 4pp 15777 002 24X Fiche 50-447,82/09/23,8210050398
- --8210220174 Amend 7 to GESSAR II * General Electric Co 82/09/23 259pp 15777 006 24X Fiche 50-447,82/09/23,8210050398
- 8210050328 Submits GE understanding of major agreements & ground rules re NRC review of GESBAR II. in response to NRC request at 820915 meeting Concurrence requested SHERHOOD. 9 General Electric Co 82/10/01 EISENHUT. D G Division of Licensing 2pp 15610 252 24X Fiche 50-447.82/10/01.8210050328
- 8210220468 Notification of 821015 meeting w/util to discuss inclusion of external events in probabilistic risk assessment review LYNCH, M.D. Licensing Branch 2 82/10/07 THUMAS, C. Standardization & Special Projects Branch 3pp 15786 204 24X Fiche 50-447, 82/10/07, 8210220468
- 8210220463 Notification of 821015 meeting w/util to discuss major issues identified in probabilistic risk assessment & impact on review schedule LYNCH M D Licensing Branch 2 82/10/08 THOMAS.C Standardization & Special Projects Branch 3pp 19786 207 24X Fiche 50-447.82/10/08.0210220463
- 021027004A Forwards Amend 8 to OE8SAR II.responding to NRC 811203 acceptance review ltr re geotechnical, radiation sources & failure mode & effects analysis & committing applicant to address NRC acceptance criteria SHERNOOD.0 Q General Electric Co 82/10/18 EISENHUT.D 0 Division of Licensing 2pp 15814 001 24X Fiche 50-447.82/10/18.8210270046
- --8210270081 Amend 8 to 238 GEBBAR II application for review responding to NRC 811231 questions re geotechnical radiation sources & failure mode & effects analysis & committing applicant to address NRC acceptance critaria VILLA:R General Electric Co 82/10/18 345pp 15816 003 24% Fiche 50-447.82/10/18.8210270046
- K Utility Final Bafety Analysis Report (FSAR) & amends
- 8210050398 Forwards Amend 7 to application for final design acceptance review of OESBAR-238, correcting typographical errors & clarifying discrepancies in portions of Chapters 1, 3, 4, 4, 5, 15
 VILLAR General Electric Co. 82/09/23 EIBENHUT.D 0 Division of Cicensing ip 15777 001 24X Fiche 50-447.82/09/23.8210050398
- --02:0220174 Amend 7 to QEBBAR II # General Electric Co 62/07/23 259pp 15777 006 24X Fiche 30-447,62/09/23:8210050378
- DOCKET STN-50-454 BYRON STATION, UNIT 1
- A Application/construction stage documents & correspondence
- 8210010271 Forwards five oversized P&IDs referred to in util 820909 ltr to NRC re waterhapmer prevention. Aperture cards are available in PDR TRAMM.TR Commonwealth Edison Co 82/09/22 DENTON, HR Office of Nuclear Reactor Regulation, Director 2pp 15573 122 24X Fiche 50-000, 82/09/22, 8210010271
- 8210080313 Bummary of 820908 & 0? meetings w/utils, Sargent & Lundy,
 Aerojet Energy Conversion Co & Rockford League of Women
 Voters in Chicago.IL & at plant site re vol reduction sys
 Questions re Topical Rept AECC-2-P encl
 KIPER.K L Licensing Branch I 82/09/23 Licensing Branch I
 I2pp 15663 341 24X Fiche 50-454.82/09/23,8210080313
- 8210050123 Submits final quarterly rept re const completion date Unit i const & testing schedule still keyed to fuel loading on 830831 DELGEORGE: L. O Commonwealth Edison Co. 82/09/27 DENTON, H R Office of Nuclear Reactor Regulation, Director. ip 15605 170 24X Fiche: 50-454, 82/09/27, 8210050123

- 8210280429 Forwards addit question re vol control sys, in response to applicant answer to NRC Guestion G321 43 Response requested within 30 days
 YDUNOBLOOD, B J Licensing Branch 1 82/10/04 DELCEGREE, LO Commonwealth Edison Co. 3pp. 15860 042 24X Fishe 50-000, 82/10/04 8210280429
- 8210260526 Forwards Revision 3 of Chapter 9 of "Offsite Dose Calculation Manual" GOLDEN, J C Commonwealth Edison Co 82/10/06 CASE, E G Offsice of Nuclear Reactor Regulation, Director 2pp 15805 137 24x Fiche 50-000, 82/10/06.8210260526
- --8210260542 Revision 3 of Chapter 9 of "Offsite Dose Calculation Manual " • Commonwealth Edison Co 82/09/30 83pp 15805 139 24x Fiche 50-000,82/10/06-8210260526
- 8210280420 Forwards request for add1 info re venting of high points in RCS.method of depressurization to cold shutdown & depressurization following steam generator tube rupture events Response requested within 30 days YOUNOBLOOD, B J Licensing Branch | 82/10/07 DELGEORGE, L O Commonwealth Edison Co | 4pp | 15060 009 | 24x Fiche 50-000,82/10/07,8210280420
- E NRC Safety Evaluation Report (SER), supple & correspondence
- 92:0010202 Submits add1 info re reactor coolant pump locked rotor by shaft break transients at facilities Info closes Confirmatory Issue 34 of Buron SER TRAMM. TR Commonwealth Edison Co. 82/09/22 DENTON, HR Office of Nuclear Reactor Regulation, Director 4pp 15568 073 24X Fiche 50-000, 82/09/22, 82:0010202
- 8210250108 Forwards revised FSAR info re protection against possible turbine missiles Revisions to turbine missile analysis rept encl Info closes out SER Outstanding Item 2

 TRAMM.T R Commonwealth Edison Co 82/10/19 DENTON.H R Office of Nuclear Reactor Regulation. Director 15pp 15789 296 24X Fiche 50-000.82/10/19.8210250108
- F Security, medical, emergency & fire protection plans
- B210270363 Forwards list of deviations from Chemical Engineering Branch Technical Position 7.5 i re fire protection program Deviations listed include lighting & communication & hydrogen line routing Justification of deviations requested YOUNOBLOOD, B. J. Licensing Branch 1 82/10/05 DELGEORGE. L. C. Commonuealth Edison Co. 7pp. 15865-240 24X Fiche 50-000 B2/10/05, B210270363
- 82[0]:30376 Advises that installation of offsite dose calculation syprogram fully operational tracking model & operational A model will be delayed until 82[23] to complete prime computer installation SWARTZ, E.D. Commonwealth Edison Co. 82/10/06 DENTON, M.R. Defice of Nuclear Reactor Regulation, Director 2pp 15682 098 24X Fiche 90-000, 82/10/06, 8210130376
- 8210130370 Forwards Revision 7 to modified amended security plan Revision withheld (ref 10CFR2 790 & 10CFR73 21) DELOEOROE, L D Commonwealth Edison Co 82/10/08 DENTON, H R Office of Nuclear Reactor Regulation, Director 1p 15680 323 24X Fiche 50-454,82/10/08,8210130370
- 8210290047 Releases public version of revisions to Guad Cities, Zion & Dreaden emergency plan annexes & revised generating station emergency plan telephone directory FELTON. J M Division of Rules and Records 82/10/08 Document Management Branch 1p | 15877 313 24X Fiche 50-000, 82/10/08, 8210290047
- --B210290060 Forwards public version of Revision 3 to Guad Cities & Zion emergency plan annexes. Revision 2 to Dresden emergency plan annex. Revision 0 to Byron emergency plan annex & revised generating station emergency plan telephone directory MOORE. R D Commonwealth Edison Co B2/07/30 DENTON, H R NRC No Detailed Affiliation Given 5pp 15877 314 24X Fiche 50-000, 82/10/08, 8210290047
- --8210290077 Public version of Revision 3 to Guad Cities & Zion emergency plan annexes.Revision 2 to Dresden emergency plan annex & Revision 0 to Syron emergency plan annex & Revision 0 to Syron emergency plan annex + Commonwealth Edison Co 82/06/30 325pp 15877 319 24X Fiche 50-000,82/10/08,8210290047
- --8210290088 Public version of revised generating station emergency plan telephone directory QALLE,D P Commonwealth Edison Co 82/08/12 43pp 15878 218 24% Fiche. 50-000, 82/10/08, 8210290047

8210220358 Provides info re organization & performance of depts responsible for radiation protection activities, per 820702 cornstment Training coordinator assigned in Apr 1982 to improve health physics training programs TRAMM, T.R. Commonwealth Edison Co. 82/10/14 DENTON, H.R. Office or Nuclear Reactor Regulation, Director 9pp 15776-287 24% Fiche 50-000, 82/10/14 8210220358

G Adjudicatory correspondence

- 6210050391 Motion for clarification of portions of ASLB 620910 merorandum to order ruling on notions for summary disposition of certain contentions Certificate of Svc encl Related correspondence
 BIELAWSKI.A P Commonwealth Edison Co BIELAWSKI.A P Isham,
 Lincoln & Beale 82/09/28 Atomic Safety and Licensing Board Panel 6pp 15608 225 24% Fiche 50-454,82/09/28,8210050391
- 8°1COa0182 Confirms 820928 telcon.in which NRC withdrew Interrogatories 77-1 & 77-2 based on withdrawn Contention 70 Answers to remaining interrogatories due by 821015 RAMSCHIRJ Hearing Branch 4 82/10/04 ROSE B Cherry, M //Cherry Flynn & Kanter ROSE B League of Homen Voters of Roctford IL 1p 15614 120 24x Fiche 50-454,82/10/04,8210040182
- R210070127 Motion for leave to file answers to util amended second round of interrogatories E day lake RDSE.3 League of Momen Voters of Rociford.IL ROSE,B Cherry, M / Cherry Flynn & Kanter 82/10/05 Atomic Safety and Licensing Board Panel 2pp 15627 084 24X Fiche 50-454,82/10/05,8210070127
- -8210070129 Answers to amended second round of interrogatories Certificate of Svc encl ROSE. B League of Homen Voters of Rockford, IL ROSE, B Cherry, M M /Cherry, Flynn, t Kanter 82/10/05 Commonwealth Ediron Co 344pp 15627 086 24X Fiche 50-454,82/10/05,8210070127
- 8210130373 Response opposing Dekalo Area Alliance for Responsible Energy/Sinnissippi Alliance for Environ 820933 motion to reconsider summary disposition of Contention 1 on GA/GC New info would not change decision W/Certificate of Svc MILLER.M I Commonwealth Edison Co MILLER.M I Isham, Lincoln & Deale 92/10/08 Abomic Safety and Licensing Board Panel IJpp 15480 247 24X Fiche 50-454.82/10/08.8210130373
- to 10130095 Response supporting applicant 820928 motion for clarification of portion of ASLB 820910 memorandum % order denging NRC % applicant motions for summary disposition. Litigable issues should be delineated Wcertificate of Svc GDLDERO, S.C. Hearing Branch 4 82/10/12 Atomic Safety and Licensing Board Panel. Spp. 15673-110 24% Fiche 50-454.82/10/13.8210130095
- 8210150087 Response opposing Details Area Alliance for Responsible Energy/Sinnissippi Alliance for Environ 820923 motion for reconsideration of summary disposition of Contention 1(h) Introduction of new facts not allowed W/Certificate of Syc GOLOBERG, S. C. Hearing Branch 4 62/10/12 Atomic Safety and Licensing Board Panel 14pp 15701 200 24x Fiche 50-454,82/10/12,8210150067
- 5210150383 Memorandum & order ruling on applicant disclosure obligations Applicant 820827 motion requesting mod of ASLB 820726 memorandum & order denied Relevant or new info must orided, per Commission precedents

 7 Atomic Safety and Licensing Board Panel 92/10/12 Edison Co 7op 15704 058 24X Fiche 50-454.

- --8210180145 Affidavit of LA Bowen Util does not intend to install 15 sensors on feedwater bypass sys piping Existence of constant feedwater flow procludes water hammer event similar to event at Krsko
 BONEN, L.A. Commonwealth Edison Co. 82/10/05 34pp 19719 14-24X Fiche 50-454,82/10/14,8210180142
- 8210180166 Confirming order canceling 821014 prehearing conference of Rockford, IL Discovery progress discussed during 821014 tation
 MARGULIES, M. B. Atomic Safety and Licensing Board Panel 82/10/15
 1p 15719 168 24% Fiche 50-454, 82/10/15, 8210180166
- B210180170 Order granting Rockford League of Women Votors motion & leave to file instanter answers to util amended second round of interrogatories 1 day late MARCULIESIA B Atomic Safety and Licensing Board Panel 82/10/14
- 8210210274 Answers to first set of interrogatories, pursuant to AH & 821020 memorandum & order Verification & Proof of Syc encl Related correspondence
 JOHNSON, B. League of Homen Voters of Rockford, IL 12/40/15
 Defice of the Executive Legal Director 48pp 15766 170 142
 Fiche 50-454, 82/10/15, 82102/0274

Fiche 50-454, 82/10/15, 8210180170

- 92(0210278 Reply to amended first request for production of dort*:-li Proof of Svc encl Related correspondence ROSE.8 League of Homen Voters of Rockford, IL ROSE.8 (Agray M. /Cherry, Flynn & Kanter 92/10/15 Office of the Liecutis, Legal Director 3pp 15745 150 24X Fiche 50~454, 82/10/19, 8210210278
- 8210210384 First interrogatories & request for documents proof of 5, encl Related correspondence
 ROSE,B League of Women Voters of Rockford, IL RO56, D Cherry **
 M /Cherry, Flynn & Kanter 82/10/15 Commonwealth Edison 6, 22pp 15764 016 24% Fiche 50-454,82/10/15,8210210104
- 6210210346 Motion for leave to file reply to new matters related by applicant & NRC in response to Alliance motion to reconsider disposition of Contention I re GA & GC CASSELLD W Dekalb Area Alliance for Responsible Inergy CASSELLD W Similarippi Alliance for the Environment (4Alt) 62/10/18 Atomic Safety and Licensing Board Panel 10 19764 210 24X Fichs 50-454,82/10/18.8210210346
- --8210210347 Reply to new matters raised by applicant & NR(in resp.*.. to Alliance motion to reconsider summary disposition of Contention i re GA & GC Disposition should be donted since issues of matl fact exist Certaficate of Svc ancl CASSEL, D W DeKalb Area Alliance for Responsible Energy CASSEL, D W Sinnissippi alliance for the Environment (GAL): 82/10/18 Atomic Safety and Licensing Doard Panel 5pp 15764 211 24X Fiche 50-454, 82/10/18, 8210210,146
- 8210250071 Corrects two typographical errors & minor misstatement is Rockford League of Momen Voters answers to NRC amended first set of Interrogatories ROSE, B. ROSE, B. Cherry, M. M. /Cherry, Flynn & Kanter (19/10/20) Docketing & Services Branch ip 15787-047 24X Fiche 50-454: 82/10/20, 8210250071
- 8210260380 Forwards author 821022 ltr to NRC transmitting first est sinterrogationies ROSE,8 Cherry, M M /Cherry, Flynn & Kanter ROSE,8 (sague of Women Voters of Rockford, IL 82/10/22 MARGULIES, H D Atomic Safety and Licensing Board Panel 1p 15804 205 24X Fiche 50-454, 82/10/22, 8210260380
- --8210260384 Forwards proposed interrogatories & motion for production of documents
 ROSE, B. Cherry, M. M. /Cherry, Flynn & Kanter ROSE, B. League at ,
 Homen Voters of Rockford, IL. 82/10/22 ODLDBERO, B. C. Hearing
 Branch 4 ip 18804 206 24X Fiche 50-454,82/10/22,82102803891
- --8210260392 Proposed first set of interrogatories Proposed Mollon froproduction of documents by NRC & Proof of Svc encl

 * League of Momen Vaters of Rockford/IL 82/10/22 Office of
 the Executive Legal Director 26pp 15804 207 24X
 Fiche 50-454,82/10/22,8210260380
- B210290305 Answers to NRC amended first set of interrogatories Certificate of Svc enci ROEE, B League of Women Voters of Rockford, IL B2/10/25 Office of the Executive Legal Director 15pp 15855 021 24X Fiche 50-454, 82/10/25, 8210290305

- 8210270293 Forwards original B Johnson verification for Rockford League of Momen Voters answers to NRC amended first set of interrogatories on Contentions 39 & 109 Related correspondence ROSE, B Cherry, M /Cherry, Flynn & Kanter ROSE, B League of Women Voters of Rockford, IL 82/10/26 Docketing & Services Branch 2pp 15854 075 24X Fiche 50-454, 82/10/26, 8210290293
- 8210280347 Response opposing Dekalb Area Alliance for Responsible Energy/Sinnissippi Alliance for Environ 821018 motion for leave to submit reply to NRC & util responses to intervenor 820923 motion for reconsideration W/Certificates of Svc GOLDBERG, S.C. Hearing Branch 4 82/10/27 Atomic Safety and Licensing Board Panel 5pp 15838 351 24% Fiche 50-454,82/10/27, 8210280347
- B210290105 Ack receipt of Rockford League of Women Voters proposed interrogatories to NRC & motion For production of documents NRC will shortly advise League of which interrogatories will be answered ODLDBERG, S C Hearing Branch 4 82/10/28 ROSE, B Cherry, M M /Cherry, Flynn & Kanter ROSE, B League of Women Voters of Rockford, IL 1p 15854 003 24X Fiche 50-454,82/10/28,8210290105

H General correspondence

- 82:0070176 Responds to 820929 ltr requesting NUREQ-0782 & OMNI-20 NUREO can be ordered from NRC Div of Technical Info & Decument Control BMI rept available from NTIS OOLDOERG-8 C Hearing Branch 4 82/10/06 VON ZELLEN,8 Northern Illinois Univ 1p 15634 262 24X Fiche 50-454,82/10/06,8210070176
- % Utility Final Safety Analysis Report (FSAR) & amends
- 8210040060 Forwards affidavit stating that distribution of FBAR Amend 39 has been made in accordance w/Encl 1 of NRC 781020 ltr TRAHM, T R Commonwealth Edison Co 82/09/23 DENTON, H R Office or Nuclear Reactor Regulation, Director 2pp 15583 191 24X Fiche 50-000, 82/09/23,8210040040

M Antitrust correspondence

- 8210070180 Forwards, for review & comment, draft DL antitrust review finding of no significant change W/o encl VOLER, B H Hearing Branch 2 82/10/06 CUTLER, M Justice, Dept of 1p 15634 277 24X Fiche 50-454, 82/10/06, 8210070180
- O Inspection reports, IE Bulletins & correspondence
- 8208190233 IE Info Notice 80-35, Buppl 1, "Leaking & Dislodged J-125 Implant Seeds " Syr list encl COSD.L I Division of Fuel Facilities, Materials & Safeguards 82/60/06 Consolidated Edison Co of New York 66pp 15761 200 24X Fiche 50-000,82/10/04,8208190233
- 8208190238 IE Bulletin 82-03, "Stress Corrosion Cracking in Thick-Wall, Large-Diameter, Stainless Steel, Recirculation Sys Fiping at BMR Plants " Svc list enc) PEYOUNO.R C Director's Defice. Office of Inspection and Enforcement 82/10/14 Consolidated Edison Co of New York 115pp 15810 128 24% Fiche 50-000, 82/10/14, 8208190238
- 82102603B7 Confirms 8210R6 meeting at Region 3 oft to discuss util response to IE Insp Repts 50-454/82-05 & 50-459/82-04 SPESSARD, R L Division of Project & Resident Programs 62/10/17 REED. C Commonwealth Edison Co ip 15803 105 24X Fiche 50-434, 82/10/17, 82102603B7
- B210260307 Ack receipt of B21014 ltr informing NRC of steps taken to correct violations noted in 1E Insp Rept 50-454/82-14 NRRELIUS C E Division of Engineering & Technical Programs B2/10/22 REED, C Commonwealth Edison Co ip 15797 321 24X Fiche 50-454/82/10/22/8210260307
- --821026030B Responds to NRC 820913 ltr re violations noted in IE Insp Rept 50-494/82-14 Corrective actions piping contractor initiated revision to 8IP 4 000 to include mod to hardware removal/alteration rept form DELOEDROE.L O Commonwealth Edison Co 82/10/14 KEPPLER.J G Region J. Office of Director 6pp 15799 322 24X Fiche 80-454,82/10/22.8210260307

- DOCKET STN-50-455 BYRON STATION, UNIT 2
- A Application/construction stage documents & correspondence
- 8210010271 Forwards five oversized P&IDs referred to in util 820909 let to NRC re-waterhammer prevention Aperture cards are available in PDR
 IRANN.I R Commonwealth Edison Co. 82/09/22 DENYDN.H.R. Ulfication Nuclear Reactor Regulation, Director 2pp 15573 122 247 Fiche 50-000.82/09/28210010271
- 8210080313 Summary of 820908 & 09 meetings w/utils, Sargent & Lundy.
 Aerojet Energy Conversion Co & Rockford League of Women
 Voters in Chicago, IL & at plant site re vol reduction sys
 Guestions re Topical Rep* AECC-2-P encl
 KIPER, K L Licensing Branch 1 82/09/23 Licensing Branch 1
 12pp 15663 341 24X Fiche 50-454.82/09/23,8210080313
- 8210280429 Forwards add1 question re vol control sys, an response to applicant answer to NRC Question Q321 43 Response requested within 30 days YOUNOBLOOD, B. J. Licensing Branch 1 82/10/04 DELGEORGE, L. D. Commonwealth Edison Co. 3pp. 15860 042 24% Fiche 50-000, B2/10/04, B310290409
- 8210260526 Forwards Revision 3 of Chapter 9 of "Offsite Dose Calculation Manuel" GOLDEN, J C Commonwealth Edison Co 82/10/06 CASE, E G Office of Nuclear Reactor Regulation, Director 2pp 15805 137 24X Fiche 50-000, 82/10/06, 8210260526
- --B210260542 Revision 3 of Chapter 9 of "Offsite Dose Calculation Hanual"

 * Commonwealth Edison Co 82/09/30 83pp 15805 139 249 Fiche 50-000, 82/10/06, 8210260526
- 8210280420 Forwards request for add1 info re venting of high points in RCS, method of depressurization to cold shutdown 2 depressurization following steam generator tube rupture events Response requested within 30 days YDUNGBLOOD, B J Licensing Branch # 82/10/07 DELOEGROE, L G Commonwealth Edsson Co 4pp 15860 007 24X Fiche 50-000, 82/10/07.
- E NRC Safety Evaluation Report (SER). suppls & correspondence
- B210010202 Submits add1 info re reactor coolant pump locked rotor & shaft break transients at facilities Info closes
 Confirmatory Issue 34 of Byron SER
 TRAMM.T R Commonwealth Edison Co 82/09/22 DENTON.H R Office of Nuclear Reactor Regulation, Director 4pp 1556B 073 24X
 Fiche 50-000, 82/09/22, 8210010202
- 8210250108 Forwards revised FBAR info re protection against possible turbine missiles Revisions to turbine missile analysis rept encl Info closes out SER Outstanding Item 2 TRAMM.T R Commonwealth Edison Co 82/10/19 DENTON.H R Office of Nuclear Reactor Regulation, Director 15pp 15789 296 24X Fiche 50-000.82/10/19.8210250108
- F Security, medical, emergency & fire protection plans

DOCKEIED HEIMO

- --8210290060 Forwards public version of Revision 3 to Quad Cities & Zinn emergency plan anneres. Revision 2 to Dresden emergency plan anner. Revision O to Byron emergency plan anner & revised generating station of surron emergency plan anner & revised generating station generating the defence of the surrounding MODRE, R D Commonwealth Edison Co. 82/07/20 DENTON, H R NRC - Roy Detailed Affiliation Given Spp. 15877 314 24% Fiche 50-000, 82/10/08, 8210270047
- --8210290077 Public version of Revision 3 to Quad Cities & Zion emergency plan annerss. Revision 2 to Dresden emergency plan anner 4 Relision O to Dyron emergency plan anner 4 Componwealth Edison Co. 82/06/30 325pp 15877 319 & Fishs 50-000.82/10/08.8210290047 325pp 15877 319 24X
- --8210290088 Public version of revised generating station emergency plan GALLE, D P Commonwealth Edison Co 82/08/12 43pp 15878 218 24% Fichs 50-000,82/10/08.8210290047
- 8210220358 Provides info re organization & performance of depts responsible for radiation protection activities, per 820702 commitment Training coordinator assigned in Apr 1982 to improve health physics training programs TRAHM, T.R. Commonwealth Edison Co. 82/10/14 DENTON, H.R. Cof Nuclear Reactor Regulation, Director 9pp 15776-287 24 DENTON, H R DFF Office Fiche 50-000 82/10/14,821022035B

G Adjudicatory correspondence

- 8210050371 Motion for clarification of portions of ASLB 820910 memorandum & order ruling on motions for summary disposition of certain contentions Certificate of SVc encl Related of certain convenients.

 correspondence
 BIELAWSKI,A P Commonwealth Edison Co BIELAWSKI,A P Isham,
 Lincoln & Deale 62/09/28 Atomic Safety and Licensing Board
 Panel 6pp 13608 225 24X Fishe 50-454,82/09/28,8210050391
- 8210050182 Confirms 820928 telcon.in which NRC withdrew Interrogatories 77-1 & 77-2 based on withdrawn Contention 70 Answers to remaining interrogatories due by 821015
 RAKSGN.R J Hearing Branch 4 82/10/04 RGSE.B Cherry. M
 M /Cherry, Flynn & Kanter RGSE.B League of Women Voters of
 Rociford.R. 1p 15614 L20 24X Fiche 50-454,82/10/04,8210060182
- 8210070127 Motion for leave to file answers to util amended second round of interrogatories 1 day late ROSE, B. League of Women Voters of Rockford, IL. ROSE, B. Cherry, M. W. Zherry, Flynn & Kanter 82/10/05 Atomic Safety and Licensing Board Panel 2pp 15627 084 24X Fiche 50-454,82/10/05,8210070127
- --8210070129 Answers to amended second round of interrogatories Certificate of Svc encl ROSE.B League of Homen Voters of Rockford.IL ROSE.B C M M /Cherry. Flynn & Kanter 82/10/05 Commonwealth Ed 344pp 15627 086 24% Fiche 50-454.82/10/05.8210070127 Commonwealth Edison Co
- 8210130373 Response opposing Datalb Area Alliance for Responsible 210130373 Response opposing Detail Area Alitance for Responsible Energy/Sinnissippi Alliance for Environ 820923 motion to reconsider summary disposition of Contention 1 on GA/GC New Info would not change decision W/Certificate of Syc MILLER.M I Commonwealth Edison Co MILLER.M I Isham, Linculn & Beale 82/10/08 Atomic Safety and Licensing Goard Panel 13pp 15680 247 24X Fiche 50-454,82/10/08,8210130373
- 8210130095 Response supporting applicant 820928 motion for clarification of portion of ASLB 820910 memorandum & order denying NRC & applicant motions for summary disposition Litigable issues should be defineated Wicertificate of Syc GDLDBERG.S C Hearing Branch 4 82/10/12 Atomic Safety and Licensing Board Panel Spp 15673 110 24X Fichs 50-454,82/10/12,8210130095
- 8210150087 Response opposing Dekalb Area Alliance for Responsible Enerou/Sinnissippi Alliance for Environ 820923 motion for ition of summary disposition of Contention 1(h) new facts not allowed H/Certificate of Syc marine Response 4 Defect Atomic Safety and Atomic Bafety and 'X Fiche 50-454,82/10/12,

- 8210150190 Confirms 821012 & 13 telcons Ref to specific answers to ctil interrogatories may be suitable response to NRC interrogatories General ref unresponsive NRC does not object Interrogatories General ret Universional ve NNL odes not object to extension to answer listed interrogatories RAMSON.R J Hearing Branch 4 82/10/13 ROBE.B Cherry, M M /Cherry, Flynn & Kanter ROSE.B League of Women Voters of Rockford,IL ip 15707 261 24% Fiche 50-454,82/10/13,8210170170
- 9210180151 Forwards original verification of Rockford League of Women Voters answers to util amended second round of ROSE.B Cherry, M M /Cherry, Flynn & Kanter 82/.
 Docketing & Services Dranch 2pp 15719 267 24x 82/10/13 Fiche 50-454, 82/10/13, 8210180151
- 8210180142 Forwards LA Bowen 821005 affidavit per ASLB 821012 memorandum % order ruling on disclosure obligation Info provided re DeKalb Area Alliance for Responsible Energy/ Sinnisippi Alliance for Energy Contention 9a GALLO.J (sham, Lincoln & Beale GALLO.J Commonwealth Edison Ca 82/10/14 MARGULIES M B . CALLIHAN.A D Atomic Safety and Licensin, Board Panel COLE.R F Atomic Safety and Licensing Appeal Panel 2pp 15719 230 24X Fiche 50-454.82/10/14.8210180142
- -B210180144 Affidavit of LA Bowen Util does not intend to initial! terp sensors on Feedwater bypass sys piping Existence of constant feedwater flow precludes water hammer event similar to event at Krsko 24X Fiche 50-454,82/10/14.8210/80142
- 9210180166 Confirming order canceling 821014 prehearing conference is Rockford, IL Discovery progress discussed during 821014 telcon telcon MARGULIES,M 8 Atomic Safety and Licensing Board Panel 82/10/15 Ip 13719 168 24X Fiche 50-454,82/10/15,8210180166
- 8210180170 Order granting Rockford League of Homen Voters motion for leave to file instanter answers to util amended second round of interrogatories I day late MARQULIES. M D. Atomic Safety and Licensing Board Panel D2/10/15 League of Homen Voters of Rockford, IL. ip 13719 165 24x
- 8210210274 Answers to first set of interrogatories, pursuant to ALP 821020 memorandum & order Verification & Proof of Svc encl Related correspond under verification & Proof of Svc encl Related correspondence JOHNSON, D. League of Women Voters of Rockford, IL 62/10/13 Office of the Executive Legal Director 48pp 15766-130 24r Fiche 50-454, 82/10/15, 8210210274

Fiche 50-454, 82/10/15, 8210180170

- 8210210278 Reply to amended first request for production of documents Proof of Svc encl Related correspondence

 ROSE, B League of Women Voters of Rockford IL ROSE, D Cherry. H

 M /Cherry, Flynn & Kanter 82/10/15 Dffice of the Elecutive

 Legal Director 3pp 15765 150 24X Fiche 50-454,82/10/15. 8210210278
- 8210210384 First interrogatories & request for documents Proof of ber encl Related correspondence MOSE, B League of Women Voters of Rockford, IL ROSE, B Charry, M M /Cherry, Flynn & Kanter 82/10/15 Commonwealth Edison Co 22pp 15764 016 24x Fiche 50-454,82/10/15,8210210384
- 8210210346 Motion for leave to file reply to new matters raised by applicant & NRC in response to Alliance motion to reconsider disposition of Contention I re GA & GC CASSEL, D W Defails Area Alliance for Responsible Energy CASSELL, D W Elinissippi Alliance for the Environment (BAFE) 82/10/18 Admic Safety and Licensing Board Panel | p 15764 210. 24X Fiche 50-454,82/10/18,8210210346
- --8210210347 Reply to new matters raised by applicant & NRC in response to Alliance motion to reconsider summary disposition of Contention i re OA & OC Disposition should be denied since Contention I re us & ut Disposition should be denise since issues of mabl fact wrist Certificate of Byc encl
 CASSEL.D W Dekalb Area Alliance for Responsible Energy
 CASSEL.D W Sinnissippi Alliance for the Environment (BAFE)
 B2/10/18
 Atomic Safety and Licensing Board Panel 5pp
 15764 211 24X Fiche 50-454, 82/10/18, 8210210346

1 ;

11

- 8210250071 Corrects two typographical errors & minor misstatement in Rockford League of Homen Voters answers to NRC amended first set of interropatories ROSE, B. ROBE, B. Cherry, M. M. /Cherry, Flynn & Kanter 02/10/20 Docteting & Services Branch ip 15787 047 24X Fiche 50-454,82/10/20,8210250071
- 8210260380 Forwards author 821022 ltr to NRC transmitting first set of ROSE, 8 Cherry, M M /Cherry, Flynn & Kanter ROSE, Momen Voters of Rockford, IL 82/10/22 MARGVLIES, M Safety and Licensing Soard Panel 1p 15804; 205 2 Fiche 50-454, 82/10/22, 8210260380 ROSE, D. Leasue of n B Atonic 24X

- --8210260384 Forwards proposed interrogatories & motion for production of documents ROSE,B Cherry, M M /Cherry, Flynn & Kanter ROSE,B League n Homen Vaters of Rockford,IL 82/10/22 GOLDBERG,S C Hearing Branch 4 ip 19804 206 24% Fishe 50-454,82/10/22,8210240300 ROSE.B League of ERG.S C Hearing
- --B210260392 Proposed first set of interrogatories Proposed motion for production of documents by NRC & Proof of Svc encl 4 League of Momen Voters of Rockford IL B2/10/22 Office of the Executive Legal Director 26pp 13804 207 24x Fiche 50-454, 82/10/22, 8210260380
- 3210270216 Notice of ASLB reconstitution IW Smith, chairman & AD Callihan & RF Cole, members LAZO,R M Atomic Safety and Licensing Board Panel 02/10/25 2pp 15823 006 24% Fiche 50-454,82/10/25,8210270216
- B210290305 Answers to NRC amended first set of interrogatories 210290305 Answers to NIK amended first set of interro Certificate of 30c enti RDSE.B. League of Komen Voters of Rockford, IL B2/ of the Executive Legal Director | 15pp | 15855 021 Fiche 50-454 82/10/25.8210290305 Office
- 8210290293 Forwards original B Johnson verification for Rockford League of Women Voters answert to NRC amended first set of interrogatories on Contentions 39 & 109 Related carrespondence carrespondence ROSE, B. Cherry, M. M. /Cherry, Flynn & Kanter ROSE, B. League Homen Voters of Rockfold, IL. 82/10/26 Docketing & Services Branch 2pp 15854 075 24X Fiche 50-454.82/10/26,8210290293 League of
- B210200347 Response opposing Dekalb Area Alliance for Responsible Energy/Sinsissippi Alliance for Environ 821018 motion for leave to a submit reply to NRC & util responses to intervenor 820923 motion for reconsideration W/Certificates of Svc GOLDBERG.S C Hearing Branch 4 82/10/27 Atomic Safety and Licensing Board Panel Spp 15838 351 24X Fiche 50-454,82/10/2/,8210280347
- 8)210290105 Atk receipt of Rockford League of Women Voters proposed interrogatories to NRC & motion for production of documents NRC will shortly advise League of which interrogatories will be answered be answered COLDBERO.S C Hearing Branch 4 82/10/28 ROSE.B Cherry. N M /Cherry, Flynn & Manter ROBE.B League of Women Voters of Rockford, IL Ip 15854 003 24% Fiche 30-454.82/10/28.82102901()5
- H General correspondence
- \$210070174 Responds to \$20929 ltr requesting NUREQ-0782 & OMNI-20 NUMERO can be ordered from NRC Div of Technical Info & Dacument Control BMI rept available from NIB
 Occument Control BMI rept available from NIB
 OCLDBERG, B C Hearing Branch 4 82/10/06 VON ZELLEN, B
 Illinois Univ 19 18634 262 24X Fiche 50-454, 82/10/06. Northern 821007017A
- K Utility Final Bafety Analysis Report (FSAR) & amends
- \$210040060 Forwards affidavit stating that distribution of FSAR Amend 37 has been made in accordance w/Encl 1 of NRC 781020 ltr TRAMM.T R Commonwealth Edison Co 62/09/23 DENTON.H R Office of Nuclear Reactor Regulation, Director 2pp 15583 191 24X Fiche 50-000 62/09/23 8210040060
- II Antitrust correspondence
- 8210070180 Forwards, for review & comment, draft OL antitrust review VOOLER, B H Hearing Branch 2 82/10/06 CUTLER, M Justice, Dept of Ip 15634 297 24X Fiche 50-454,82/10/06. B210070180
- @ Inspection reports, IE Bulletins & correspondence
- 8208190233 IE Info Notice 80-35, Suppl 1, "Leaking & Dislodged 1-125 Implant Seeds " Svc list encl. COBB.L. I Division of Fuel Facilities, Materials & Safeguards 82/10/04 Consolidated Edison Co of New York 46pp 15761 250 24X Fiche 50-000,82/10/06,8208190233
- 8208170238 IE Bulletin 82-03, "Stress Corrosion Cracking in Thick-Wall:Large-Diameter, Stainless Steel, Recirculation Sys Piping at BHR Plants " Syc list encl DEYOUND, R C Director's Office, Office of Inspection and Enforcement 82/10/14 Consolidated Edison Co of New York 115pp 15810 125 24k Fiche 50-000, 82/10/14,8208170238

- 8210260387 Confirms 821026 Meeting at Region 3 ofc to discuss util response to IE Insp Repts 50-454/82-05 & 50-455/82-04 SPESSARD,R L. Division of Project & Resident Programs 82/10/19 REED, C. Commonwealth Edison Co. 1p 15803 105 24X 82/10/19 REED,C Commonwealth Edison Co 1p 15803 105 Fiche 50-454, 82/10/19, 8210260387
- DOCKET STN-50-456 BRAIDWOOD STATION. UNIT 1
- A Application/construction stage documents & correspondence
- 8210010202 Submits additinfore reactor coolant pump locked rotor & shart break transients at facilities Info closes
 Confirmatory Issue 34 of Byron SER
 TRAMM T R Commonwealth Edison Co 82/09/22 DENTON H R NF+11 TRAMM, T R Commonwealth Edison (of Nuclear Reactor Regulation, Di Fiche 50-000, 02/09/22, 0210010202 82/09/22 DENTON H R DE DEFICE Director
- 8210010271 Forwards five oversized P&IDs referred to in util 82040* 2100102/1 Forwards five oversized P&IDs referred to 1 ltr to NRC re waterhammer prevention Aperture cerds are available in PDR
 TRAMM, TR Commonwealth Edison Co 82/09/22 DENI of Nuclear Reactor Regulation. Director 2pp 155; Fiche 50-000, 82/09/22, 8210010271 DENTON, R. R. Office 15573 122
- 8210050073 Application for amend to CPPR-132 & CPPR-133, revising completion dates to 870430 & 860430, respectively DELGEORGE, D. Commonwealth Edison Co. 82/09/30 DENION, H.R. Office of Nuclear Reactor Regulation, Director 2pp. 15603 1624% Fiche 50-456.82/09/30.8210050073 5bb 12903 1111
- --8210050077 EIA supporting request for extension of dates for completion of const of units extending Unit 1 to 870430 & Unit 2 to 880430 Commonwealth Edison Co 82/09/30 2pp 15603 183 24X Fiche 50-454, 82/07/30, 8210050073
- 15860 042 24X Fiche 50-000, 82/10/04,
- 8210260526 Forwards Revision 3 of Chapter 9 of "Offsite Dose Calculation Manual GOLDENIJC Commonwealth Edison Co 82/10/06 CASE, Nuclear Reactor Regulation, Director 2pp 15805 137 Fiche 50-000, 82/10/06, 8210240526 CASE, E 0 Office of 24X
- --8210260542 Revision 3 of Chapter 9 of "Offsite Dose Calculation Manual ' Commonwealth Edison Co 82/09/30 83pp 15805 139 24X Fich # 50-000, 82/10/04, 8210260526
- 8210280420 Forwards request for add) info re venting of high points in RCB, method of depressurization to cold shutdown δ ACCIMENTAGE OF DEPRESSION 13 TION TO COIS SHUTCHEM & depression following steam generator tube repture events Response requested within 30 days YOUNOBLOOD, B J. Licensing Branch 1 82/10/07 DELGEORGE, L O Commonwealth Edison Co. 4pp. 15860 009 24% Fishe 50-000, 82. 24X Fiche 50-000, 82/10/U/, 8210280420
- E NRC Safety Evaluation Report (SER), suppls & correspondence
- 821025010B Forwards revised FSAR info re protection against possible turbine missiles Revisions to turbine missile analysis rept encl Info closes out SER Dutstanding Item 2 TRAMM, TR Commonwealth Edison Co 82/10/19 DENTON, HR Office of Nuclear Reactor Regulation, Director 15pp 15789 296 24X fiche 50-000, 82/10/19, 8210250108 Office
- F Security, medical, emergency & fire protection plans
- 8210290363 Forwards list of deviations from Chemical Engineering Branch Technical Position 9 5 1 re fire protection program Deviations listed include lighting & communication & hydrogen line routing Justification of deviations requested YOUNGBLOOD, B J Licensing Branch ! 82/10/05 DELGEDROE, L C Commonwealth Edison Co 7pp 15865 240 24X Fiche 50-000, 82/10/05, 8210270363
- 8210130376 Advises that installation of offsite dose calculation mys program fully operational tracking model to perational A-model will be delayed until 821231 to complete prime computer installation SMARTZ.E D. Commonwealth Edison Co. 82/10/06 DENTON, H.R. Of of Nuclear Reactor Regulation, Director 2pp. 15682,098 24X Fiche 50-000,82/10/06,8210130376 Office

6210220358 Provides info re organization & performance of depts responsible for radiation protection activities.per 820702 commitment Training coordinator assigned in Apr 1982 to improve health physics training programs TRAMM.T R Commonwealth Edison Co 82/10/14 DENTON.H R Office of Nuclear Reactor Regulation, Director 9pp 15776-287 24X Fiche 50-000.82/10/14.8210220358

G Adjudicatory correspondence

- 8210050259 Order directing all parties to file complete status repts w/ASLB Repts should contain present status of application, documents filed by NRC or util const plans & future projections & basis for scheduling projections MILLER, ME Atomic Safety and Licensing Board Panel 82/10/01 Commonwealth Edison Co | Ip | 15610 290 | 24X Fiche 50-456.82/10/01.
- 8210250211 Status rept on plants in response to ASLB 821001 order
 Unit 1 scheduled for fuel load on 850430 & Unit 2 on 860430
 Dates uill be confirmed or revised in Jan 1983 Certificate
 of Svc encl
 MILLERIM J Commonwealth Edison Co MELLERIM J Isham, Lincoln &
 Beale 82/10/19 5pp 15788 242 24X Fiche 50-456,82/10/19,
 82(02502)1
- 8210220453 Response to ALSB 821001 order to file status rept on plant Schedule for issuance of NRC documents & considerations to be used in developing prehearing & hearing schedule listed Notice of appearance & Certificate of Svc encl HASSELL, D.F. Hearing Branch 1 82/10/20 13pp 15778-325 24x Fiche 50-456,82/10/20,8210220453

K Utility Final Safety Analysis Report (FSAR) & amends

- 6210040040 Forwards affidavit stating that distribution of FSAR Amend 39 has been made in accordance w/Encl 1 of NRC 781020 ltr TRAMM.T R Commonwealth Edison Co 82/09/23 DENTON, H R Dffire of Nuclear Reactor Regulation, Director 2pp 15583 191 24X Fiche 50-000.82/09/23, 8210040040
- O Inspection reports, IE Bulletins & correspondence
- 8210040230 Ack receipt of 820817 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-456/82-01 & 50-457/82-01 Denies request to withdraw Violation I Concurs that Violation 2 does not constitute noncompliance NRECIUS, C E Division of Engineering & Technical Programs 82/09/27 REED, C Commonwealth Edison Co 2pp 15586 114 24X Fichs 50-456. 82/09/27, 8210040230
- ---8210040246 Responds to NRC 820707 itr re violations noted in 1E Insp Repts 50-456/82-01 & 50-487/82-01 Disputes Violations 1 & 2 Post-tensioning sequence adequately controlled Corrective action re Comstock nonconformance repts taken DELGEORGE, L. D. Commonwealth Edison Co. 82/08/17 KEPPLER, J. G. Region 3, Office of Director 9pp. 15586 116 24X Fishe 50-496, 82/09/27, 8210040230
- 9208190233 IE Info Notice 80-35, Suppl 1, "Leaking & Dislodged I-125 Implent Sweds " Svc list encl CDBB.L I Division of Fuel Facilities, Materials & Safeguards 82/10/06 Consolidated Edison Co of New York 66pp 15761 250 24% Fiche 50-000,82/10/06.8208190233
- 8208190238 IE Bulletin 82-03, "Stress Corrosion Cracking in Thick-Wall-Large-Diameter. Stainless Steel. Recirculation Sys Piping at BWR Plants " Svc list encl DEYDUNG.R C Director's Office, Office of Inspection and Enforcement 82/10/14 Consolidated Edison Co of New York 115pp 15810 125 24X Fiche 50-000, 82/10/14,8208170238

's & related correspondence

re breakdown of QA procedures
ifety-related mechanical
'02 All affected
rent Procedure QCP-B22
E2/10/08 KEPPLER.J O Region
'1 24X Fiche 50-455,62/10/08,

069 sufety-

egion 0/13. DOCKET STN-50-457 BRAIDWOOD STATION, UNIT 2

- A Application/construction stage documents & correspondence
- 5210010202 Submits addl info re reactor coolant pump locked rotor k shaft break transients at facilities Info closes Confirmatory Issue 34 of Buron SER TRAMM.TR Commonwealth Edison Co 82/09/22 DENTON.HR Office of Nuclear Reactor Regulation. Director 4pp 15568 073 241 Fiche 50-000.82/09/22.8210010202
- 8210010271 Forwards five oversized P&IDs referred to in util D2090/ 1; to NRC re waterhammer prevention Aperture cards are available in PDR TRAMM.T R Commonwealth Edison Co 82/09/22 DENTON.H R 0/fire of Nuclear Reactor Regulation, Director 2pp 15573 122 24x Piche 50-000, 82/09/22, 8210010271
- 8210050073 Application for amend to CPPR-132 & CPPR-133, revising completion dates to 870430 & 880430, respectively DELGEDROE, L.O. Commonwealth Edison Co. 82/07/30 DENTON, H.R. Office of Nuclear Reactor Regulation, Director 2pp (USO) 184 24X Fiche 50-456.82/09/30,8210050073
- ---8210050077 EIA supporting request for extension of dates for cumplets of const of units extending Unit 1 to 870430 & Unit 2 to 880430

 4 Commonwealth Edison Co 82/09/30 2pp 15603 183 24x
 Fiche 50-456,82/09/30.8210050073
- 8210280429 Forwards addit question re vol control sys.in response to applicant answer to NRC Question Q321 43 Response requested within 30 days YOUNOBLODD. B J Licensing Branch 1 82/10/04 DELQEGRGE, L C Commonwealth Edison Co 3pp 15860 042 24X Fiche 50-000.82/10/04
- 8210260526 Forwards Revision 3 of Chapter 9 of "Offsito Dose Calculation Manual" GGLDEN.J C Commonwealth Edison Co 82/10/06 CASE,C Q (Iffice & Nuclear Reactor Regulation, Director 2pp 15805 137 24x Fiche 50-000.82/10/06.8210260526
- ~-8210260542 Revision 3 of Chapter 7 of "Offsite Dose Calculation Manual" • Commonwealth Edison Co 82/09/30 83pp 15805 139 24F Fiche 50-000,82/10/06.8210260526
- 8210280420 Forwards request for add1 info re venting of high points is a RCS, method of depressurization to cold shutdown & depressurization following steam generator tube rupture avents Response requested within 30 days YOUNOBLOOD, B J Licensing Branch I BZ/10/07 DELOCORGUL D Commonwealth Edison Co. 4pp 15860 009 24X Fiche 50-000.82/10/0/8210280420
- E NRC Bafety Evaluation Report (SER), supple & correspondence
- 8210250108 Forwards revised FSAR info re protection against postible turbine missiles Revisions to turbine missile analysis rept enc! Info closes out ESR Outstanding Item 2
 TRANH.T R Commonwealth Edison Co 82/10/19 DENTEN.ICR Office of Nuclear Reactor Regulation, Director 15pp 15787 276 AZX Fiche 50-000.82/10/19.8210250108
- F Security, medical, emergency & fire protection plans
- 6210290363 Forwards list of deviations from Chemical Engineering Branch Technical Position 9.5 i re-fire protection program Deviations listed include lighting & communication & hydrogen line routing Justification of deviations requested YOUNCBLOOD, B. J. Licensing Branch i B2/10/05 DELGEORGE, L. O. Commonwealth Edison Co. 7pp. 15865-240 24X Fiche 50-000, 82/10/05 R210290363
- B210130376 Advises that installation of offsite dose calculation squ program fully operational tracking model & operational A-model will be delayed until 821231 to complete prime computer installation SWARTZ, E.D. Commonwealth Edison Co. B2/10/06 DENTON, N.R. Office of Nuclear Reactor Regulation, Director 2pp 15682 698 24% Fiche 50-000, 82/10/06.8210130376
- 8210220338 Provides info re organization & performance of depts responsible for radiation protection activities, per 820702 commitment Training coordinator assigned in Apr 1982 to improve health physics training programs
 TRAMM, TR Commonwealth Edison Co 82/10/14 DENTON, HR Office of Nuclear Reactor Regulation, Director 9pp 15776 287 248
 Fiche 50-000, 82/10/14, 8210220358

DOCKETED ITEMS

Adjudicatory correspondence

- \$210050259 Order directing all parties to file complete status repts WASLB Repts should contain present status of application, documents filed by NRC or util, const plans & future projections & basis for scheduling projections

 MILLER, M E Atomic Safety and Licensing Board Panel 82/10/01

 Commonwealth Edison Co ip 15610 290 24X Fiche 50-456,82/10/01, 82(0050259
- 8210250211 Status rept on plants in response to ASLB 821001 order. Unit 1 scheduled for fuel load on 850430 & Unit 2 on 860430 Dates will be confirmed or revised in Jan 1983 Certificate of Svc encl Hitter, N J Commonwealth Edison Co MILLER, N J Isham, Lincoln 8 Beals 82/10/19 5pp 15788 242 24X Fiche 50-456, 82/10/19, 82(0250211
- ₽210220453 Response to ALSB 821001 order to file status rept on plant Schedule for issuance of NRC documents & considerations to be used in developing prehearing & hearing schedule listed Notice of appearance & Certificate of Svc encl MASSELL.D F Hearing Branch i 82/10/20 13pp 15778 325 24y Fiche 50-456.82/10/20.8210820833
- M. Utility Final Safety Analysis Report (FSAR) & amends
- B210040060 Forwards affidavit stating that distribution of FSAR Amend 39 has been made in accordance w/Encl 1 of NRC 781020 ltr RAMMIT R Commonwealth Edison Co 82/09/23 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 24X Fichs 50-000,82/09/23,8210040060
- O Inspection reports, IE Bulletins & correspondence
- 8210040230 Ack receipt of 820817 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-456/82-01 & 50-457/82-01 Denies request to withdraw Violation I Concurs that Violation 3 does not constitute noncompliance NORELIUS, C E Division of Engineering & Technical Programs 82/09/27 REED, C Commonwealth Edison Co 2pp 15586 114 24X Fichs 50-456/82/09/27.8210040230
- --9210040246 Responds to NRC 820707 ltr re violations noted in IE. Insp. Repts 50-456/82-01 & 50-457/82-01 Disputes Violations 1 & 2 Post-tensioning sequence adequately controlled Corrective action re Comstock nonconformance repts taken DELOGOROG. L. O. Commonwealth Edison Co. 82/08/17 KEPPLER, J. O. Region 3, Office of Director 7pp 15586 116 24X Fiche 50-456,82/09/27,8210040230
- 8208190233 IE Info Notice 80-35, Suppl 1, "Leaking & Dislodged I-125-Implant Seeds " Svc list encl GOBB, L I Division of Fuel Facilities, Materials & Safeguards 82/10/06 Consolidated Edison Co of New York 66pp 15761 250 24% Fiche 50-000,82/10/06,8208190233
- B208190238 IE Bulletin B2-03, "Stress Corresion Cracking in Thick-Wall, Large-Diameter: Stainless Steel, Recirculation Sys Piping at BWR Plants " Svc list encl DEYOUNG.R C Director's Office, Office of Inspection and Enforcement B2/10/14 Consolidated Edison Co of New York 11599 15810 125 24X Fiche 50-000.82/10/14/8208190238
- S. Reportable occurrences. LERs & related correspondence
- \$210040249 Deficiency Rept 82-06 re containment post-tensioning bushing thread failure Initially reported on 820820 Caused by undersize major thread diameter of bushing Thread measurements will be verified before stressing TRAMM.T R Commonwealth Edison Co 82/09/23 KEPPLER.J 0 Region 3. Office of Director 2pp 15581 358 24% Fiche 50-457.82/09/23, 8210040249
- E210190297 Interim deficiency rept re breakdown of QA procedures concerning control of erection of safety-related mechanical equipment Initially reported on 820902 All affected equipment will be rechecked using current Procedure GCP-B22 TRAMM.TR Commonwealth Edison Co 92/10/08 KEPPLER.J 0 Region 3. Office of Director 7pp 15742 161 24X Fiche 50-456.82/10/08.8210190299
- B210190662 Interim deficiency rept re untimely reinsp of 3,069 safety-related pipe hanger welds Initially reported on 820908 Contractor will inspect hanger supports installed before June 1981 prior to fuel load TRAMM.T R Commonwealth Edison Co 82/10/13 KEPPLER, J O Region 3, Office of Director 2pp 15739 092 24X Fiche 50-456,82/10/13,8210190662

- DOCKET 50-458 RIVER BEND STATION, UNIT 1
- K Utality Final Safety Analysis Report (FSAR) & amends
- 8210040215 Forwards Amend 6 to FSAR.consisting of "Failure Modes & Effects Analysis " Certificate of Svc encl CAHILL.W J Oulf States Utilities Co 82/09/27 EISENHUT, D G Division of Licensing 4pp 15587 263 24X Fiche 50-458,82/09/27,8210040215
- --8210040220 Amend 6 to FSAR # Gulf States Utilities Co 82/09/30 480pp 15587 267 e/4\lambda Fiche 50-458.82/09/27.8210040215
- Q Inspection reports. IE Bulletins & correspondence
- --9210050399 IE Insp Rept 50-458/82-10 on 820823-27 No nuncompliance noted Major areas inspected previous insp findings, site tour, observation of work & review of records for welding & nondestructive eram of safety-related piping OILBERT, L D . CROSSMAN, W A . HUNNICUTT, D M Division of Resident, Reactor Project & Engineering Programs 62/09/1/4 4pp 15603 010 24X Fiche 50-458, 82/09/20, 8210050387
- 8208190233 IE Info Notice 80-35, Suppl 1, "Leaking % Dislodged ! L.", Implant Seeds " Svc list encl COBB.L ! Division of Fuel Facilities, Materials & Safeguards 82/10/06 Consolidated Edison Co of New York 66pp 15761 2°,0 24X Fiche 50-000, 82/10/06, 8208190233
- 8208190238 IE Bulletin 82-03. "Stress Corrosion Cracking in Thick-Wall, Large-Diameter, Stainless Steel, Recirculation Sys Piping at BMR Plants" Svc list encl DEYGUNO, R C Director's Office, Office of Inspection and Enforcement 82/10/14 Consolidated Edison Co of New York 115pp 15810 125 24X Fiche 50-000.82/10/14.8208170238
- S Reportable occurrences. LERs & related correspondence
- B210050201 Interim Deficiency Rept DR-71 re QA program inconsistencies in mfg of personnel air locks Initially reported on 820827 Investigation not yet complete Next rept expected by 830115 BOOKER, J E Quif States Utilities Co 82/09/27 COLLINS, J T Region 4. Office of Director ip 15609 294 24X Fiche 50-450, 82/09/27, 8210050201
- 8210050350 Interim deficiency rept re defective math used in coupling drive element of Transamerica Delaval standby diesel/ generators Initially reported on 820827 Final rept will be provided by 821027 Also reported per Part 21 800KER. J E Gulf States Utilities Co 82/09/27 COLLING. J T Region 4, Office of Director in 15608 254 24X Fiche 50-458, 82/09/27, 8210050350
- 8210050219 Final deficiency rept re indications found on shop radiographs of containment penetration bellows Initially reported on 820603 Investigation determined no reportable deficiency exists

 BOOKER, J E Guif States Utilities Co 82/09/29 COLLING, J T Region 4, Office of Director 1p 15611 245 24X

 Fiche 50-458,82/09/29,8210050219
- 8210050317 Interim deficiency rept re improper installation (torquing) & insp of drilled-in expansion-type anchors Initially reported on 820830 Investigation continuing Final status rept will be provided by 821115
 BOOKER, J E Quif States Utilities Co 82/09/29 COLLING, J T Region 4, Office of Director ip 15601 357 24X
 Fiche 50-458,82/09/29,8210050317.
- 8210130516 Interim deficiency rept re unsatisfactory insp performed by former field QC inspector initially reported on 820327 Re-evaluation of insp continuing Next rept to be provided by 821027 DODKER, J E Quif States Utilities Co 82/09/30 COLLING, J T Region 4. Office of Director ip 15683 107 24X Fiche 50-458, 82/09/30, 8210130316
- 8210130182 Interim Deficiency Rept 73 re improperly installed spring nuts in GE supplied power generation control complex termination cabinets Initially reported on 820902 Investigation continuing Next rept expected by 830121 BODKER, J E Gulf States Utilities Co 82/10/05 COLLINS, J T Region 4, Office of Director ip 19673 012 24X Fiche 50-458, 82/10/05, 8210130182

- 8210190518 Final deficiency rept re weld surface imperfections in Graver shop weld for containment personnel airlock Instably reported on 820702 Imperfections do not affect safe plant operation Deficiency not reportable per 10CFR0S0 55e BOOKER. J E Gulf States Utilities Co 82/10/06 COLLINS. J T Region 4. Office of Director 19 15751 243 24X Fiche 50-458, 82/10/06, 8210190518
- 8210190367 Interin Deficiency Rept DR-65 re cracking & spalling of surface concrete around penetrations Initially reported on 820806 Investigation continuing Next rept will be provided by 821203

 BGGVER, J E Gulf States Utilities Co 82/10/07 COLLINS, J F Region 4. Office of Director ip 15742 101 24X
 Fiche 50-458, 82/10/07, 8210190367
- 8210190529 Interim Deficiency Rept FR~74 re incorrect installation of I/4-inch drilled in expansion type enchor bolts used to support emergency lighting battery unit Initially reported on 920830 Investigation incomplete Final rept due by 830128 800KER, J E Gulf States Utilities Co 92/10/08 COLLING, J I Region 4. Office of Director tp 15740 034 24X Fichs 50-458, 82/10/08, 82/10/06, 82/10/06
- 8:1020003/ Interim Deficiency Rept DR-37 re insufficient beam end gapt between drywell 8 primary shield walls initially reported on 820302 Deficiency determined reportable per 10CFR50-55(e) Next rept expected by 821108 BCCMER J E Out States Utilities Co 82/10/08 COLLINS. J T Region 4 Office of Director (p. 15756-326) 24X Fiche 50-458.82/10/08.921020037
- U210250118 Final Deficiency Rept DR-63 ie use of improper stud mail in valve fabrication Initially reported on 820629 Studs being replaced w/special mail Condition not reportable per 10CRR50 55:e) BOOKER.J E Gulf States Utilities Co 82/10/12 COLLINS.J F Region 4. Office of Director 1p 15787 018 24% Fishe 50-458 82/10/128210250118
- B210260272 Final Deficiency Rept DR-46 re improperly retained rod end bushings that may disengage from Bergen Paterson shubber & sway strut assemblies I nitually reported on B20426 Generic part number changed on B7 drawings for riser clamps BCOMER. J E Gulf States Utilities Co B2/10/14 COLLINS. J (Region J E Gulf States Utilities Co B2/10/14 COLLINS. J Fiche 50~458. §2/10/14. @210260292
- 6210260286 Interim Deliciency Rept DR-75 re error found in GHOSH computer program used in reactor blig hydrodynamic analysis initially reported on 920721 Investigation to determine significance of error continuing Next rept by 830114 BOCKER, J E Quif States Utilities Co 92/10/15 COLLINS, J / Region 4, Office of Director 1p 15803 217 24% Fichs 50-458, 82/10/15, 8910260286
- COCKET 50-459 RIVER BEND STATEON, UNII 2
- A Utility Final Safety Analysis Report (FSAR) & amends
- 8210040215 Forwards Amend & to FSAR consisting of "Failure Modes & Effects Analysis " Certificate of Byc encl CAMILLA U Gulf States Utilities Co 82/09/27 EISEMHUT.D (Division of Licensing App 15587 263 24% Fiche 50-458 82/09/27, 8210040215
- --8210040220 Amend & to FSAR
 # Gulf States Utilities Co 82/09/30 480pp 15587 267 24X
 Fiche 50-438.82/09/27.8210040215
- G Inspection reports. IE Bulletins & correspondence

- DOCKET 50-460 MPPSS NUCLEAR PROJECT, UNIT 1

 A Application/construction stage documents & correspondence
- B210220511 Forwards WPPSS 820825 & 0909 & CPC B20812 ltrs re B&H owners group 820720 meeting w/NRC re resolution of NUREG-0737. Item II K 3 30 on small break LOCA methods Appropriate action should be taken ADENSAMIE 0 Licensing Branch 4 B2/10/04 SHERON, B H Reacter Systems Branch 1p 15786 091 24X Fiche 50-000, B2/10/09
- 8210270446 Staff requirements memo re 821007 affirmation/discussion a vote on extension of const completion dates for WPPSS, purging of classified math in ALAB-653 & emergency preparedness & risks associated w/fuel loading CHILK, S. J. Diffice of the Secretary of the Commission 82/10/69 Uffice of the Secretary of the Commission 92/10/69 Uffice of the Secretary of the Commission 92/10/69.8210270446
- G Adjudicatory correspondence
- S210040016 Response to Coalition for Safe Power 820710 request for hearing by petition to intervene Current petition does not satisfy requirements Contention must be submitted Winotice or appearance & Certificate of Svc YOUNG, M A Hearing Branch 4 82/09/30 About Safety and Licensing Board Panel 12pp 15581 316 24% Fichs 50-460.02/6/11 821000016
- 8210130336 Order CL1-82~29, referring Coalition for Safe Power petiti, for hearing to ASLB ASLB chairman should appoint ASLB to determine whether 10CFR2 714 requirements met & to conduct required hearing 4/separate views of Commissioner Ollinsiy CHILK, 8 J Office of the Secretary of the Commission 6/10/40 21pp 15681 350 24% Fiche 50-397, 82/10/08, 8210130336
- 8210150480 Memorandum & order granting Coalition for Safe Power les i to amend petition to intervene per order, within 15 days after svc Util complete answer to original & amended petition due within 10 days after amended petition served SMITH, I W. Atomic Safety and Licensing Board Panel B2/10/1; Coalition for Safe Power Tap 15702 001 24x Fiche 50-460,82/10/13,8210150480
- B210200056 Notice of ASLB constitution H Grossman.chairman & Et (111) & LW Little.members COTTER.B P Atomit Safety and Licensing Board Panel 192/10/14 2pp 15755 027 24% Fiche 50-377.82/10/14.8210200056
- 9210270181 Notice of ASLB reconstitution H Grossman, chairman f. (1)

 Oright & J Harbour, members
 LAZOR M Atomic Safety and Licensing Board Panel 82/10/25 (15629 315 24X Fichs 50-460,82/10/25,821027018)
- 8210270315 Natice of ASLB reconstitution H Grossman, chairman & GB Bright & J Harbour, members LAZO, R M Atomic Bafety and Licensing Board Panel BR/10/47 .19 15853 078 24X Fiche 50-397, 82/10/25, 8210290315
- Q Inspection reports, IC Bulletins & correspondence
- 8210070378 Ack receipt of 820909 ltr informing NRC of steps taken to correct violations noted in insp on 820501-28
 STERNBERG, D M Division of Resident, Reactor Project & Engineering Programs 82/10/04 ROOT, R W Washington Public Power Supply System 1p 15634 017 24X Fiche 50-460,82/10/04.82(10070378)
- ~-8210070387 Responds to NRC 820624 ltr re violations noisd in H. 1937.
 820801-28 Corrective actions subcontractor procedures for
 installation of electrical penetration assemblies submitted
 & approved by engineer
 ROOTER W. Washington Public Power Supply System 82/09/09
 BISHOPET W. Division of Resident. Reactor Project & Engineering
 Programs 4pp 15634 018 24X Fiche 50-460.82/10/04.82100/03/3
- 8208190233 IE Info Notice 80-35, Suppl (, "Leaking & Disloded 1 12 Implant Seeds " Svc list encl COBB.L I Division of Fuel Facilities, Materials & Safeguard 82/10/06 Consolidated Edison Co of New York 66pp 15761 244 Fich

- B210130415 Ack receipt of 820909 & 30 ltrs informing NRC of steps taken to correct violations hoted in IE imsp on 820401-30
 STERNBERG,D M Division of Resident, Reactor Project & Engineering Progrems 82/10/06 R00TrR W Washington Public Power Supply System ip 15681 319 24X Fiche 50~460.82/10/06.8210130415
- --8210130425 Updates response to NRC 820608 ltr re violations noted in IE insp on 820401-30 Corrective actions local grinding to expose weld root performed on four welds Cause of undersized welds due to improperly prepared weld bevels RCOT.R W. Hashington Public Power Supply System 82/09/30 STERNBERG,D M. DIVISION of Resident, Reactor Project & Engineering Programs Spp 15681 320 24% Fiche 50-460,82/10/06,82101J0415
- --B210130432 Responds to NRC B2040B itr re violations noted in it into on B20401-30 Corrective actions local grinding conducted to expose weld root & base metal surfaces Partial penetration butt weld undersized RCOT.R W Washington Public Power Supply System 82/09/09 BISHOP, T W Division of Resident, Reactor Project & Engineering Programs 7pp 15681 325 24X Fiche 50-440,82/10/06,82/0130415
- 3208190238 IE Builetin 02-03, "Stress Corrosion Cracking in Thick-Hall.Large-Diameter.Stainless Steel, Recirculation Sys-Piping at 8WR Plants "Syc list encl DEYGUNO, R C Director's Office. Office of Inspection and Enforcement 82/10/14 Consolidated Edison Co of New York 115pp 15810 125 24% Fiche 50-000,82/10/14,8208190238
- 3210280185 Ack receipt or 821012 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-460/82-08 STERNSERG, D M Division of Resident, Reactor Project & Engineering Programs 82/10/22 ROOT, R Washington Public Power Supply Bystem 1p 15837 006 24X Fiche 50-460, 82/10/22, 8210280185
- --B210280190 Responds to NRC 820607 itr re violations noted in it imp Rept 50-460/82-08 Corrective actions const package sys initiated to track work operations in field & craft personnel instructed to perform work per package sys RQOT.R W Hashington Public Power Supply System 62/10/12 STERNBERG.D M Division of Resident, Reactor Project & Engineering Programs 4pp 15837 007 24x Fiche 50-460.82/10/22,8210280185
- 3210280286 Ack receipt of 821012 itr informing NRC of steps taken to correct violations noted in IE lnsp Rept 50-460/82-07 STERNBERG, D M Division of Resident, Reactor Project & Engineering Programs 82/10/22 ROOT, R W Washington Public Power Supply System 1p 15845 194 24X Fiche 50-460, 82/10/22, 8210280286
- --8210280297 Responds to NRC B20B04 ltr re violations noted in II Insp
 Rept 50-460/B2-07 Corrective actions GCRFI sys deleted &
 insp repts will be written when question as to validity/
 accuracy of requirements of item occurs
 ROOT, R W Washington Public Power Bupply Bystem 62/10/12
 STERNDERO, D M Division of Resident, Reactor Project & Engineering
 Programs 3pp 15845 175 24K Fiche 50-460,62/10/22,62102B0286
- S Reportable occurrences, LERs & related correspondence
- 8210070338 Interim deficiency rept re emergency diesel generator governor lube oil cooler Initially reported on 820126 Lube oil cooler will be moved to elevation below oil level per Transamerica Belaval instructions & drawings ROOT.R W Washington Public Power Supply System 82/09/15 STERNBERGO, D M Division of Resident. Reactor Project & Engineering Programs 2pp 15634 071 24X Fiche 50-440,82/09/15,82(0070338)
- 8210070297 Interim deficiency rept re unsuitability of isoprene mathused in governor drive coupling elements Initially reported on 820819 Field change notice issued to implement changeout of element math to neoprene Also reported per Part 21 ROOTAR W Mashington Public Power Supply System 82/09/20 STERNBERO, D M Division of Resident, Reactor Project & Engineering Programs 2pp 15634 178 24X Fiche 50-460.82/09/20.8210070897
- 82:00703:1 Interim deficiency rept re use of lumped mass loads in performance of pipe stress analysis Initially reported on 820305 Paremetric studies may resolve trivial mass changes interim status repts will be provided on semiannual basis ROOTAR H Washington Public Power Supply System 82/09/20 STERNBERG.D H Division of Resident, Reactor Project & Engineering Programs Spp. 15634 145 24X Fiche 50-460.82/09/20.8210070311

- DOCKET 50-461 CLINTON POWER STATION. UNIT 1
- A Application/construction stage documents & correspondence
- B209290072 Forwards 581 oversize electrical, instrumentation & control drawings, identified in Table (7-1 of FSAR Aperture cards are available in PDR WULLER, 0 E Illinois Power Co B2/09/20 YHOMAS, C O Standardization & Special Projects Dranch ip 15540 196 24x Fiche 50-461, B2/09/20, B209290072
- B210050460 Requests add1 info re 820722 submittal on meteorological measurements sys.data acquisition & assessment scheme for emergency plan & B1016 submittal on hydrogen ignition sys Schedule for responding to questions requested within 2 wks THOMAS, C O Standardization & Special Projects Granch 92/09/2./ MULLER.G [11inois Power Co 7pp 15626 250 24X Fiche 50-461, 92/09/22, 6210050460
- 8210040104 Responds to 820326 request for add1 info re hydrodynamic water hammer analysis of control rod drive Sys WULLER.0 E []Ilnois Power Co 62/09/24 THOMAS.C D Standardization & Special Projects Branch 3pp 15580 35! 44% Fiche 50-461, 82/09/24, 8210040104
- 8210040070 Disapproves 820920 request for concurrence re partial lift of Stop Work Order Old re electrical conduit installation Matrix of commitments & completion status for each item required SPESSARD, R L Division of Project & Resident Programs 82/09/27 OERSTNER, W C Illinois Power Co 2pp 15581 278 24X Fiche 50-461,82/09/27,8210040070
- B210130490 Advises that response to Questions 810 57.810 58 & 810 59 of NRC 820922 litrine degraded core hydrogen control & emergency plan dose assessment reporting sys will be provided via FEAR amend by 821130 HULLER.O E Illinois Power Co 82/10/08 THOMAS.C O Standardization & Special Projects Branch ip 15682 169 249 Fiche 50-461.82/10/08.8210130490
- 8210130325 Provides quarterly update re const schedule Fuel loading & commercial operation projected for Jan & Aug 1984, respectively KOCH.L J Illinois Power Co 82/10/11 DENTON.H R Office of Nuclear Reactor Regulation, Director 1p 15678 281 24X Fiche 50-461(82/10/11.8210130325
- 8210150357 Provides schedule for submitting additinfo for NRC review of hydrogen ignition sys in response to NRC 820922 questions re degraded core hydrogen control & omergency plan dose assessment rept sys Questions will be addressed by 830101 MULER, G. E. Illinois Power Co. 82/10/11 THOMAS, C. O. Standardization & Special Projects Branch ip 15704 317 290X Fiche 50-461,82/10/11,8210150357
- 8210280340 Responds to 820902 questions re ECCS NRC review of util lafe on Humphrey concerns will be reported in SER suppl No further concern over Kuo Sheng incident warranted re Contention 10 portions of ACRS transcript entl GODDARD R J Hearing Branch 3 82/10/15 WILLMAN.F L 1111NO State of 24pp 15038 327 24X Fithe 50-461.82/10/15.82102803
- 8210260204 Confirms 821006 discussion w/util & LL! Iimited resumption of work, per 820901 confirmat lift Concurrence assumes that listed changes will implemented prior to conducting nondestruct: KEPFLER, J Q Region 3, Office of Directo 1111nois Power Co 821026---
- 8210280213 Provides initial response to 820901 confirmatory action itre course of action in progress to assure that facility will be constructed in accordance w/FSAR Viewgraph of facility project update and!
 HALLID P Illinois Power Co 82/10/20 KEPPLER, J G Region 2, Office of Director 43pp 15838 258 24X Fiche 50-461,82/10/20,8210280213
- 8210280089 Forwards operability analyses to demonstrate capability of containment vent/purge butterfly isolation valves to function as designed info resolves TML Action Item II E 4 2(6) & SER Outstanding Issue 10a MULER.0 E Illinois Power Co 82/10/22 THOMAS.C O Standardization & Special Projects Dranch 369pp 15843 088 24X Fiche 50-461.82/10/22.8210280089

- E NRC Bafety Evaluation Report (SER), suppls & correspondence
- 8210050278 Requests incorporation of Licensing Review Group II program re channel box deflection concern into future suppl to SER, superseding SER Section 4 2 3 13 info
 WULLER. O E Illinois Power Co. 82/09/28 THOMAS, C 0

WULLER O E | Illinois Power Co | 82709728 | THUMAS C U Standardisation & Special Projects Branch | 2pp | 15611 187 | 24X Fiche 50-461, 82709728, 8210050278

- 8210050289 Confirms commitment to revise emergency operating procedures to address common vessel ref level for fuel zone level meter Info should close out SER Confirmatory Item 39 WULLER, O E Illinois Pouer Co 82/09/28 THOMAS, C O Standardization & Special Projects Branch Ip 15609 084 24X Fiche 50-461, 82/09/28, 8210050289
- 821005028; Forwards Sargent & Lundy analysis of feedwater check valves Analysis indicates that feedwater check valve will withstand worst case loadings w/o losing pressure boundary integrity info should close out SER issue
 HULLER. G E Illinois Power Co 82/09/30 THOMAS. C O
 Standardization & Special Projects Branch 7pp 15609 179 24X
 Fiche 50-461, 82/09/30, 8210050281
- 8210280089 Forwards operability analyses to demonstrate capability of containment vent/purge butterfly isolation valves to function as designed Info resolves FMI Action Item II E 4 2(6) & SER Clutstanding Issue IOA HULLER. G E Illinois Power Co 82/IO/22 THOMAS, C O Standardization & Special Projects Branch 369pp 15843 088 24X Fiche 30-461, 82/10/22, 8210280089
- F Security, medical, emergency & fire protection plans
- 8210050460 Requests add1 info re 820722 submittal on meteorological measurements sys.data acquisition & assessment scheme for emergency plan & 816016 submittal on hydrogen ignition sys Schedule for responding to questions requested within 2 wks THOMASIC O Standardization & Special Projects Branch 82/09/22 HULLER.O Illinois Power Co 7pp 15626 250 24% Fiche 50-461,82/09/22,8210050460
- 8210130470 Forwards Revision 4 to physical security plan Revision withheld (ref 10CFR2 790) KCCH.t. J 111nois Fawer Co 82/09/30 DENTON, H R Office of Nuclear Reactor Regulation, Director 19 15682 160 24X Fiche 50-461, 82/09/30, 8210130470
- 8210130490 Advises that response to Questions 810 57,810 58 & 810 57 of NRC 820922 ltr re degraded core hydrogen control & emergency plan dose assessment reporting sys will be provided via FSAR amend by 821130 HULLER.O E Illinois Power Co 82/10/08 THOMAS.C O Standardization & Special Projects Branch ip 15682,169 24X Fiche 50-461, 82/10/08,8210130490
- 8210150357 Provides schedule for submitting add1 info for NRC review of hydrogen ignition sys, in response to NRC 820922 questions re degraded come hydrogen control & emergency plan dose assessment rept sys questions will be addressed by 830101 HULLER, O E Illinois Power Co 82/10/11 THOMAS, C O 8tandardization & Special Projects Branch ip 15704 317 24X Fiche 50-461, 82/10/11, 8210150357

.

- Q Inspection reports: IE Bulletins & correspondence
- B210130547 Forwards IE Investigation Rept 50~461/82-02 on 820105 03.0 KEPPLER, J G Region 3, Office of Director 82/08/04 DERSTALA, H I Illinois Power Co 2pp 15683 307 24X Fichs 50-461, 62/08/04, 8210130547
- --8210130557 IE Investigation Rept 50-461/82-02 on 820105-0303 Flyor violations noted in GA program for safety-related electrical work QC personnel not granted sufficient freedom to perform duties PHILLIP.0 A , FOSTER, J E . LOVE, R S Region 3, Office of Direct 82/06/09 53pp 15683 309 24X Fiche 50-461,82/08/04,8210130547
- 8210040270 Confirms 820924 verbal approval re limited work resumption 820927 per confirmatory action its Scope of work limited to insp of remedial work associated w/nonsafety-related seismic electrical trays in Seismic Category I bligs NORELIUS, C.E. Division of Engineering & Technical Programs 82/09/28 OERBTNER, W.C. Illinois Power Co. ip 15594 360 C4T Fiche 50-461.82/09/28,8210040270
- 8210070336 EN-82-032 on 821006, notice of violation & proposed imposition of civil penalty to be issued to licensee Action based on numerous violations in electrical area & licensee failure to exercise control over contractor FLACK, E., AXELRAD, J. Director's Office, Office of Inspection and Enforcement 82/10/04 ip 15634-084 24X Fiche 50-461, 82/10/04 8210070336
- 8210130451 Discusses IE insp on 820105-0303 \$ forwards notice of violation t notice of proposed imposition of civil penalty KEPPLER.J Q Region 3. Office of Director 82/10/05 GERTMR NC 1 Illinois Power Co 2pp 15681 332 24X Fiche 50-461.82/10/05. 8210130451
- --B210130459 Notice of violation & notice of proposed imposition of 1, penalty in amount of \$40,000 Noncompliance noted failure to exercise adequate oversight & control of principal contractor for assuring execution of QA program KEPPLER, J G Region 3, Office of Director B2/10/05 13pp 15691 334 24X Fiche 50-441, 82/10/05, 8210130451
- 8208190203 IE Info Notice 80-35, Suppl 1, "Leaking & Distodged 1-135 Implant Seeds" Svc list encl COBBL I Division of Foel Facilities, Materials & Safeguards 82/10/06 Consolidated Edison Co of New York 66pp 15761 2'0 24X Fich 50-000, 82/10/06, 8208190233
- 8210(3018) Forwards revised Pages 3,11,12 & 14 to 820223 "Clinton Power Station Preservice Insp Program "
 MULLER: 0 E Illinois Power Co 82/10/06 THOMAS. C 0
 Standardization & Special Projects Branch ip 15673 013 241
 Fiche. 50-461: 82/10/06.8210(3018)
- --8210130184 Revised Pages 3,11,12 & j4 to "Clinton Power Stateon Preservice Insp Program" * Illinois Power Co 82/10/06 Spp 13673 014 24% Fiche 50-461,82/10/06,8210130181
- 8210130240 Submits confirmatory action ltr per 820930 meeting No further work will be allowed until completion of NRC approval af overines program plan SPESBARD.R L. Division of Project & Resident Programs 82/L0/05 GERSTNER.H C. Illinois Power Co. 2pp 15675 124 24x Fiche 50-461.82/10/06.8210130240
- 8210250224 Forwards IE Insp Rept 50-461/82-08 on 820601-0731 No noncompliance moted KNQP: R C Division of Project & Resident Programs 82/10/06 OERBYNER: M. C Illinois Power Co 2pp 15788 349 24% Fiche 50-461. 82/10/06.82102590224
- --8210250232 IE Insp Rept 50-461/82-08 on 820601-0731 No nencompliance noted Major areas inspected const activities, including mail laydown & storage areas, pipe & structural welding, program control & numerous stop work recovery activities LIVERMORE.H H . HAYES.D W Division of Project & Resident Programs 82/09/30 App 15788 351 24X Fiche 50-461.82/10/ug 8210250224.
- E210280170 Forwards IE Mgt Meeting Rept 50-461/82-17 on 820930 Mg noncompliance noted KEPPLER.J.O Region 3. Defice of Director 82/10/13 GERSTNER W: Illinois Power Co 2pp 15845 048 24X Fiche 50-461.82/10/13 8210280170

- --8210280174 IE /lgt Meeting Rept 50-46//82-17 on 820730 No noncompliance noted Major areas discussed status of stop work recovery & overinsp programs, master mgt plan & recommendations from audit Related viewgraphs enc!

 KEPPLER, J C , MAYES, D W Division of Project & Resident Programs PNOP, R C Division of Project & Resident Programs 82/10/13 42pp 15845 050 24% fishe 50-461.82/10/13,8210280170
- --8210280174 [E Mgt Meeting Rept 50-461/82-17 on 820930 No noncompliance noted Major areas discussed status of stop work recovery & overinsp programs, master mgt plan & recommendations from audit Related viewgraphs enci

 KEPPLER, J G Region 3. Office of Director SPESSARD, R L

 Division of Project & Resident Programs 82/10/13 42pp
 15845 050 24% Fiche 50-461, 82/10/13, 8210280170
- 82-08190236 IE Bulletin 82-03, "Stress Corrosion Cracking in Thick-Hallitaige-Diameter Stainless Steel.Recirculation Sys Piping at BWR Plants "Syc list entl DEYOUNG, R C Director's Office. Office of Inspection and Enforcement 82/10/14 Consolidated Edison Co of New York 115pp 15810 125 24X Fiche 50-000.82/10/14.8208190238
- 82:10280050 Forwards full payment for 82:1005 notice of proposed imposition of civil penalties re-violations noted in IE Investigation Rept 50-461/82-02 GERSTNER.W C 111:nois Power Co 82/10/21 Director's Office, Orfice of Inspection and Enforcement 4pp 15837-252 24X Fiche 50-461, 82/10/21, 82:10280050
- 5 Reportable occurrences, LERs & related correspondence
- 5210190350 Interim Deficiency Rept 82-08 re lack of distribution control for instrument data sheet Initially reported on 820902 Condition could result in errors in documentation & instrument requirements Document control tightened HALL, D.P. Illinois Power Co. 62/10/01 KEPPLER, J.Q. Region 3, Office of Director 4pp. 19742-091 24X Fiche 50-461,82/10/01, 8/10190350
- 82:0190354 Final Deficiency Rept 82-06 ie loss of structural steel inspreyed and Initially reported on 820625 Measures taken to document destroyed drawings brevise 8C requirements GERSTNER.W C Illinois Power Co 82/10/01 KEPPLER.J O Region), Office or Director 3pp 15742 104 24X Fiche 50-461.82/10/01.82/10/90554
- 0210190416 Interim Deficiency Rept 82-09 re small bore/instrumentation piping support dosign calculations Initially reported on 820902 Review of all calculations to determine extent of errors underway Next rept due in 90 days HALLill P Illinois Power Co 82/10/01 KEPPLER. J 0 Region 3. Office of Director 3pp 15740 353 24X Fiche 50-461,82/10/01,62:0190416
- G210190633 PNO-111-B2-108 on G21005.util announced hiring of 5&W Engineering to augment const mgt plogram & assess site const organization Majority of safety-related work stopped since June 1982, tending upgrading of GA program LIVERUMRE.H · HAVES.D . KNUP.R Region 3. Office of Director D2/10/06 Ip 15737 359 24X Fiche 50-461.62/10/06.8210190633
- 8210280160 Interim Part 21 Ropt 82-07 re breakdown in const 9A program insp & corrective action procedures Initially reported on 820708 Stop work action issued until investigation complete Results expected in 90 days MALL D P Illinois Power Co 62/10/19 KEPPLER, J O Region 3, Office of Director 5pp 19837 210 24X Fiche 50-461,82/10/19,82/10/20160
- DOCKET 50-462 CLINTON POWER STATION. UNIT 2

 3 Inspection reports, IE Bulletins & correspondence
- 8208190233 IE Info Notice 80-35, Suppl 1, "Leaking & Dislodged 1-125 implant Seeds " Svc list encl COBB.L I Division of Fuel Facilities, Materials & Safeguards 82/10/06 Consolidated Edison Co of New York 46pp 15761 250 24% Fiche 50-000.82/10/06.8208190233
- 8208190238 IE Bulletin 82-03, "Stress Corresion Cracking in Thick-Hall-Large-Diameter: Stainless Steel, Recirculation Sys Piping at BWR Plants " Syc list encl BEYQUNG, R C Director's Office, Office of Inspection and Enforcement B2/10/14 Consolidated Edison Co of New York 115pp 13810 125 24X Fiche 50-000, 82/10/14, 8208190238

- DOCKET 50-466 ALLENS CREEK NUCLEAR STATION, UNIT 1
- G Adjudicatory correspondence
- B210070120 Motion for termination of proceedings Util decided to cance) plant Certificate of Svc encl
 NENMAN.J R Houston Lighting & Power Co NEWMAN.J R
 Lowenstein.Neuman.Reis.Azelrad & Toll 82/10/06 Atomic Safety
 and Licensing Board Panel 3pp 15627 061 24x
 Fiche 50-466.82/10/06.8210070120
- 8210070147 Withdrawal of application for CP NEHMAN, J R Houston Lighting & Power Co NEHMAN, J R Lowenstein, Newman, Reis, Azelrad & Toll 82/10/06 1p 15627 075 244 Fiche 50-466, 82/10/26, 82/10/20147
- 8210190390 Response to util 821006 motion for termination of proceeding NRC does not object to motion Certificate of Syc encl
 BLACK,R L Hearing Branch 3 82/10/15 Atomic Safety and Licensing Board Panel 3pp 15740 348 24X Fiche 50-466,82/10/15, 001010/0000
- Q Inspection reports, IE Bulletins & correspondence
- 8208170233 IE Info Notice 80-35, Suppl 1, "Leaking & Dislodged I-12', Implant Seeds " Svc list ent! COBB.L I Division of Free! Facilities, Materials & Safeguards 62/10/06 Consolidated Edison Co of New York 66pp 15761 250 244 Fiche 50-000, 82/10/06. 8208170233
- 820B19023B IE Bulletin 82-03, "Stress Corrosion Cracking in Thick-Wall, Large-Diameter, Stainless Steel, Recirculation Sys
 Piping at BWR Plants "Svc list encl
 DEYOUNG, R C Director's Office, Office of Inspection and
 Enforcement 82/10/14 Consolidated Edison Co of New York
 115pp 15810 125 24X Fiche 50-000, 82/10/14, 8208190238

DOCKET STN-50-470 CESSAR SYSTEM BO

- B Utility Preliminary Safety Analysis Report, amends
- B210280202 Withdraws App C to CESSAR-F supporting operation of Sys 80 NBSB at reduced power level w/two pumps from NRC review Partial loop operation not required for issuance of final design approval SCHERER.A E Combustion Engineering, Inc 82/10/25 THOMAS.C Standardization & Special Projects Branch 1p 15837 049 24X Fiche 50-470.82/10/25.8210280202
- E NRC Safety Evaluation Report (SER), suppls & correspondence
- 8210150306 Forwards proprietary & nonproprietary "Statistical Combination of Uncertainties.Part II" & "Statistical Combination of Uncertainties.Part III," re SER Confirmatory Item 7 Proprietary versions withheld (ref 10CFR2 790) SCHERER:A E Combustion Engineering Inc 82/10/08 EISENHUT.D & Division of Licensing App 13715 173 24X Fiche 50-470.82/10/08, 8210150306
- --8210150313 "Statistical Combination of Uncertainties, Part II, Uncertainty Analysis of Limiting Safety Sys Settings for C-E Sys 80 NSBS " * Combustion Engineering, Inc 82/09/30 50pp 15715 175 Fiche 50-470, 82/10/08, 8210150304

VE DOURETED IT AIM

- --B210220253 "Comparison of Finite Element & Lumped Mass Seismic Analysis Hethods for Selected SNUPPS Bldgs: "Revision 1 + Standardized Nuclear Unit Fower Plant System 82/06/18 24pp 15775 327 24X Fiche 50-000, 82/10/18,8210220252
- B210260274 Submits plant-specific rept re NUREO-0737. Item [I D 1. "Relief 2 Safety Valve Testing " Acceptable operability of SNUPPS safety valves demonstrated Evaluation of safety & relief valve discharge piping % support espected by B21231 PETRICK.X A Standardized Nuclear Unit Power Plant System 82/10/20 DEMITON.H Office of Nuclear Reactor Regulation, Director 3pp 15803 026 24X Fiche 50-000.82/10/20.8210260274
- E NRC Safety Evaluation Report (SER), supply & correspondence
- 8210040373 Forwards Suppl 1 to SER (NUREG-0891) W/o encl YOUNGBLOOD B J Licensing Branch 1 82/07/07 KOESTER G L Kansar Gas & Electric Co 3pp 15597 200 24X Fiche 50-482,82/09/07, 8210040373
- F Security, medical, emergency & fire protection plans
- B210210272 Notification of 821019 meeting w/utils & SNUPPS organization in Bethesda, MD to discuss matters re fire protection for alternate shutdown panel EDISON, G E , HOPKINS. J B Licensing Branch 1 B2/09/27 YOUNGBLOOD, B J Licensing Branch [4pp 15774 341 24X Fiche 30-000, B2/09/27, 8210210272
- G Adjudicatory correspondence
- 8210200050 Notice of ASLB reconstitution JA Laurenson.chairman & GC Anderson & HC Parton.members COTTER.B P Atomic Safety and Licensing Board Panel 82/10/14 2pp 15757 224 24X Fiche 50-482.82/10/14.8210200050
- H General correspondence
- 8210120197 Informs of mgt organization changes FSAR will be revised to reflect changes.

 KOESTER: & L. Kansas Gas & Electric Co. 82/10/06 DENTON,H R. Office of Nuclear Reactor Regulation. Director. 3pp. 15651 232 24/ Fiche 50-482.82/10/06.8210120197
- K Utility Final Gafety Analysis Report (FSAR) & amends
- 8210080260 Forwards Revision 10 to FSAR, including FSAR changes transmitted by 820706,13 & 0827 ltrs
 PETRICK, N A Standardized Nuclear Unit Power Plant System
 92/09/30 DENTON,H R Office of Nuclear Reactor Regulation,
 Director 2pp 15638 333 24X Fiche 50-000,82/09/30,8210080260
- --8210080266 Revision IO to FSAR
 4 Standardised Nuclear Unit Power Plant System 82/09/30 40%pp
 15638 335 24X Fiche 50-000.82/09/30.8210080260
- Q Inspection reports, IE Bulletins & correspondence
- B210190596 Forwards IE Insp Rept 50-482/82-11 on B20701-0B31 No noncompliance noted SEIDLE.W C Division of Resident, Reactor Project & Engineering Programs B2/09/22 KOESTER, C L Kansas Cas & Electric Co 2pp 15739-339 24X Fiche 50-482/82/09/22-8210190596
- ~~B210190608 IE Insp Rept 50~482/82-11 on B20701-0B31 No noncompliance noted. Major areas inspected followup on previous insp findings: records review for post-tensioning sys installation & raceways & power cable installation activities VANDEL.7 E . NORTON.J F . HUNNICUIT.D M Division of Resident. Reactor Project & Englisheering Programs B2/09/20 12pp 15739 341 24X Fiche 50~482,82/09/22,8210190596
- 8208170233 IE Info Notice 80-35. Suppl i: "Leaking & Dislodged I-125 Implant Seeds " Syc list encl CDBB.L I Division of Fuel Facilities, Materials & Safeguards 82/10/06 Consolidated Edison Co of New York 66pp 15761 250 24X Fiche 50-000,82/10/06,8208170233
- 920B19023B IE Bulletin 92-03. "Stress Corrosion Gracking in Thick-Wall, Large-Diameter, Stainless Steel, Recirculation Sys Piping at BWR Plants " Svc list encl DEYGUNO, R. C Director's Office, Office of Inspection and Enforcement 82/10/14 Consolidated Edison Co of New York 115pp 15810 125 24X Fiche 50-000, 82/10/14,820819023B

- 8210280225 Advises that IE Insp Rept 50-482/81-18 has been canceled Rept will not be issued SEIDLE, W.C. Division of Resident, Reactor Project & Engineering Programs 82/10/25 KDESTER.O.L. Kansas Gas & Electric Co. 1p 15837
- 5 Reportable occurrences, LERs & related correspondence
- 8210040364 Interim deficiency rept re-potential defect in diesel generator thermostatic valve units AE awaiting receipt of additectnical info from vendor to finalize rework plan Rept on status of insp by 830120 Also reported per Part 21 KOESTER.G.L. Kansas Gas & Electric Co. 82/07/23 SEIDLE, W.C. Division of Resident, Reactor Project & Engineering Program | Ip 15589-027 24X Fiche 50-482,82/09/23,8210040364
- DOCKET STN-50-483 CALLAWAY PLANT, UNIT 1
- A Application/construction stage documents & correspondence
- B210040370 Informs that util proposed exception to Reg Ouide (146 sc qualifications of GA audit personnel unacceptable Util should provide clear commitment to Reg Guide (146 by B21005 YOUNOBLOOD, B J Licensing Branch (02/09/03 SCHNEI(,D F Unica Electric Co 3pp 15597 197 24X Fiche 50-403,82/09/07,62/094017)
- 8210210309 Notification of 821020 meeting w/utils & SNUPPS in Oaithersburg, MD to discuss electrical power sys E0150N.0 E. HOPKINS.J B. Licensing Branch (82/09/27 YOUNOBLOOD, B. J. Licensing Branch (4pp. 15782 074 24X Fiche 50-000, 82/09/27, 8210210309
- 8210050299 Responds to 820903 ltr re commitments to Reg Guide | 144, pe Revision 2 of FSAR site addendum Commitment will be revised, w/o stated clarification, in next revision to FSAR addendum SCHNELL, D.F. Union Electric Co. 82/09/28 YOUNGBLOOD, B.J. Licensing Branch 1 4pp 15609 072 24X Fiche 50-483,82/09/,49, 8210050299
- 8210220252 Forwards Revision 1 to "Comparison of Finite Element J. Lumped Mass Seismic Analysis Methods for Bolected SNUPPG Bldgs " PETRICK.N A Standardized Nuclear Unit Power Plant System
- PETRICK: N A Standardized Nuclear Unit Power Plant System 82/10/18 DENTON HR Office of Nuclear Reactor Regulation, Director Ip 15775-326 24X Fiche 30-0000-02/10/16.021022022
- --8210220293 "Comparison of Finite Element & Lumped Mass Seismic Analymethods for Selected SNUPPB Bldgs: Revision 1
 4 Standardized Nuclear Unit Power Plant System 82/06/18 44pt
 15775 327 24% Fiche 50-000, 82/10/18, 821022029
- G210260274 Submits plant-specific rept re NUREG-0737, Item II D I.
 "Relief & Safety Valve Testing " Acceptable operability of
 SNUPPS safety valves demonstrated Evaluation of safety &
 relief valve discharge piping & support expected by D21231
 PETRICK:N A Standardized Nuclear Unit Power Plant System
 B2/10/20 DENTON.H Office of Nuclear Reactor Regulation. Directo.
 3pp 15803 026 24X Fiche 50-000.82/10/20.8210260274
- F Security, medical, emergency & fire protection plans
- 8210070152 Advises that no radiological emergency response plan of std operating procedure has been developed or accepted by Montgomery or Oasconade Counties, MO, as reported in RW Krimm 820817 memo REED, J O Affiliation Unknown 82/09/23 ORIMES, B Division of REED, J O Affiliation Unknown 82/09/23 ORIMES, B Division of Emergency Preparedness KRIMM, R W Federal Emergency Hanagement Agency Gpp. 15627 071 24X Fiche 50-483,82/09/23,82100/0152
- 8210210272 Notification of 821017 meeting w/utils & SNUPPS organisation in BethesdaiMD to discuss matters re fire protection for alternate shutdown panel EDISON.0 E. HOPKINS.J B. Licensing Branch 1 82/09/27 YOUNGBLOOD, B. J. Licensing Branch 1 4pp 15774 341 24X Fiche 50-000.82/09/27.8210210272
- Q Adjudicatory correspondence
- B210060197 Fine) particularization of J Reed amended Contentions 1. is a 3 Certificate of Svc encl REED. J G Reed, J G 82/10/01. Atomic Safety and Licensing boar Panel 42pp 15614 176 24X Fiche 50-483,82/10/01,8210060197

DOCKETED ITEMS

- BIIO120202 Forwards revised schedule stipulated at B2090B prehearing conference reflecting 2-wk extension for discovery of undisputed contentions Original interrogatories no longer appropriate Svc list encl Related correspondence

 DATER.T A Shaw Pittman, Potts & Trowbridge BAXTER,T A Union Electric Co B2/10/06 GLFASON.J P. BRIGHT,O D., KLINE,J R Atomic Safety and Licensing Board Panel 4pp 15652 293 24X Fiche 50-483, 82,10/06, 8210120262
- 02102103c5 Objections to JG Reed 821001 particularization of Contentions II & IZ Contention II seeks greater specificity re energency planning for re-entry & recovery than specificity its displayment of Svc encions Certificate of Svc encions Certificate of Svc encions Troubridge 02/10/18 Atoms Cafety and Licensing Board Panel 24pp 19763 216 24% Fiche 50-483.82/10/18.8210210365
- Falluatull40 Forwards revised interrogatories & requests of JO Reed for production of documents Responses due 8211(3 & objections due 621027, per stipulated schedule Requests replace util 2007)5 interrogatories & requests Certificate of Syct enci BA/TER, T.A. Shaw, Pittmen, Potts & Troubridge BAYTER, T.A. Union Electric Co. 82/10/20. REED, J.C. Reed, J.G. 4pp. 15788-308-24) Fiche 50-483, 82/10/20. 8210250248
- -6210250253 Revised interrogatories? requests for production of documents BAXTER.T A Union Electric Co BAXTER.T A Shaw, Pittman, Potts 7 Froubtidge 82/10/20 REED.J G Reed. J G 25pp 15788 312 24x Fiche 50-483.62/10/20.8210250248
- EZICZ70159 Response to J Reed 821001 final particularization of amended Contentions 1,2 * 3 Objects to admission of Contentions 7 11,12 * 14 % portions of 3,19 % 15 Certificate of Sic encl
 PERLISER G Hearing Branch 3 82/10/25 Atomic Safety and Licensing Board Panel 16pp 15830 028 24X Fiche 50-483.82/10/25, 8210270159
- . Utility Final Safety Analysis Report (FSAR) & amends
- E21003026U Forwards Revision to to FSAR, including FSAR changes transmitted by B20706.13 & 0827 ltrs
 PETRICK.N A Standardized Nuclear Unit Power Plant System 82/09700 DENTION.H R Office of Nuclear Reactor Regulation, Director 2pp 15630 333 24X Fiche 50-000.82709/30.8210080260
- 8210080266 Revision 10 to FSAR + Standardized Nuclear Unit Power Plant System 82/09/30 409pp 15638 375 24; Fiche 50-000.82/09/30.8210080260
- a inspection reports. IC Bulletins & correspondence
- B210130514 Forwards IE Insp Rept 50-483/B2-10 on B20801-31 & notice of violation SPESSARD, R L. Division of Project & Resident Programs 62/09/16 SCINELL, D F. Union Clectric Co. 2pp. 15682 241 24X Fiche 50-483, 62/09/16, 8210130514
- 8210130523 Notice of violation from insp on 820801-31 SPESSARD, R. L. Division of Project & Resident Programs 82/09/16 2pp 15682 243 244 Fiche 50-483.82/09/16.8210130514
- --8210133529 IE Insp Rept 50-483/82-10 on 820801-31 Noncompliance noted failure to follow cable installation procedures & failure to identify nonconforming electrical penetrations NEISLER.J H , KONKLIN.J E Division of Project & Resident Programs 82/09/16 7pp 15682 245 24% Fiche 50-483,82/09/16,8210130514
- 8210130484 Ack receipt of 820923 itr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-483/82-06 SPESSARD, R L Division of Project & Resident Programs 82/10/05 SCHNELLD F Union Electric Co ip 15684 194 24X Fiche 50-483,82/10/05,8210130484
- --8210130555 Responds to NRC 820825 ltr re violations noted in IE Insp.
 Rept 50-483/82-06 Corrective actions review of all completed work assistanments for non-one non-scheduled raceway within Selsmic II/I boundaries in process
 SCHNELL.D F Union Electric Co. 82/09/23 SPESSARD, R L. Division of Project & Resident Programs 2pp 15684 197 24X
 Fiche 50-483,82/10/05.8210130484
- 8208190233 IE Info Notice 80-35, Suppl 1, "Leaking & Dislodged I-125 implant Seeds " Svc list encl COBB.L I Division of Fuel Facilities, Materials & Safeguards 82/10/06 Consolidated Edison Co of New York & Spp 15761 250 24% Fiche 50-000, 82/10/06, 8208190233

- 8208190238 IE Bulletin B2-03, "Stress Corrosion Cracking in Thick-Wall-Large-Diameter.Stainless Steel.Recirculation SysPiping at BMR Plants" Svc list encl
 DEYOUNO,R C Director's Office. Office of Inspection and
 Enforcement B2/10/14 Consolidated Edison Co of New York
 115pp 15810 125 24% Fiche 50-000.82/10/14.8208190238
- S Reportable occurrences, LERs & related correspondence
- 8207180037 FOIA request for insp % enforcement records re accidents of F Lawson & H Dillon at facility. Union Electric Co CP & other NRC safety manuals or matls 160E. V H 1goe, V M 82708/12 KEPPLER, J Q Region 3, Office of Director 1p 15626 243 24X Fiche 50-483, 82/08/12, 8207180037
- 8210050512 Responds to FOIA request for insp & enforcement records ro accidents of F Lawson & H Dillon at facility. Union Electric CP & other NRC safety matls or manuals Forwards two documents Renaining records available in PDR FELTON, J H Division of Rules and Records 82/09/21 IQCE, M V Igor, V M 2pp 15626 244 24X Fiche 50-000, 82/09/21, 821005051,2
- --8210050518 Region 3 daily rept for 780807 • Region 3. Chicago. Office of the Director 78/08/07 1p 15626 246 24X Fiche 50-000, 82/09/21,8210050512
- -6210050522 PNO-111-78-062 on 780804, two workers seriously injured whin hit by support girder for polar crane rail QSNA notified SCHWEIBINZ, E.R., HAYES, D.W., HEISHMAN, R.F., Region G. Chicago, Office of the Director 78/08/04 ip 15626-247 24% Fiche 50-000,82/09/21,8210050512

DOCKET STN-50-485 STERLING POWER NUCLEAR PROJECT, UNIT 1

- @ Inspection reports. IE Bulletins & correspondence
- 8208190233 IE Info Notice 80-35. Suppl 1. "Leaking & Dislodged I-125 Implant Seeds " Svc list encl COBB.L J Division of Fuel Facilities. Materials & Safeguards 82/10/06 Consolidated Edison Co of New York 66pp 15761 250 24% Fiche 50-000.82/10/06.8208190233
- 8208190238 IE Bulletin 82-03, "Stress Corrosion Cracking in Thick-Wall, Large-Diameter, Stainless Steel, Recirculation Sys Piping at BWR Plants " Sve list encl BEYBUNG, R C Director's Office. Office of Inspection and Enforcement 82/10/14 Consolidated Edison Co of New York 115pp 15810 125 24X Fiche 50-000, 82/10/14, 8208190238

DOCKET STN-50-488 PERKINS NUCLEAR STATION, UNIT 1

- Q Inspection reports. IE Bulletins & correspondence
- 8208190233 IE Info Notice 80-35. Suppl i. "Leaking & Distodged 1-18b Implant Seeds " Svc list enci COBB.L I Division of Fuel Facilities, Materials & Safeguards 82/10/06 Consolidated Edison Co of New York 66pp 15761 256 24/
- 8208190238 IE Bulletin 82-03, "Btress Corrosion Cracking in Thick-Wall, Large-Diameter, Stainless Steel, Recirculation Sys Piping at BWR Plants " Syc list encl DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/10/14 Consolidated Edison Ca of New York 1155p 15810 125 24X Fichs 50-000, 82/10/14-8208170238
- DOCKET STN-50-489 PERKINB NUCLEAR STATION, UNIT 2

 O Inspection reports, IE Bulletins & correspondence
- 8208190233 IE info Notice 80-35. Suppl i. "Leaking & Dislodged I-125 Implant Seeds " Svc list encl COBB.L I Division of Fuel Facilities. Materials & Safeguards 82/10/06 Consolidated Edison Co of New York 66pp 15761 250 24X Fiche 50-000.82/10/06.8208190233
- 8208190238 IE Bulletin 82-03, "Stress Corrosion Cracting in Thick-Wall, Large-Diameter, Stainless Strei, Recérculation Sys Piping at BWR Plants "Svc list and DEVOUNG, R C Director's Office, Office of Inspection and Enforcement 92/10/14 Consolidated Edison Co of New York 115pp 15810 125 24X Fiche 50-000, 82/10/14, 8208190238

DOCKET STN-50-490 PERKINS NUCLEAR STATION, UNIT 3

- Q Inspection reports, IE Bulletins & correspondence
- 8208(90233 lE Info Nutice 80-35, Suppl 1, "Leaking & Dislodged 1-125, Implant Seeds " Svc list enc! COBB.L I Division of Fuel Facilities, Materials & Safeguards 82/10/04 Consolidated Edison Co of New York 66pp 1576) 256
- UBSIC. I DIVISION OF FUEL PACIFITIES, NEVERTIALS & Safeguards
 B2/10/06 Consolidated Edison Co of New York 66pp 1576) 250
 24X Fiche 50-000, B2/10/06, B208190233

 B208190238 IE Bulletin B2-03, "Stress Corrosion Cracking in Thick—
 Hall, Large-Diameter, Stainless Steel, Recirculation Sys
- 8208190238 IE Builetin 82-03. "Stress Corrosion Cracking in Thick-Mall:Large-Diameter, Stainless Steel, Recirculation Sys Piping at BWR Plants " Svc list encl DEYDONG.R C Director's Office, Office of Inspection and Enforcement 82/10/14 Consolidated Edison Co of New York 115pp 15810 125 24X Fiche 50-000, 62/10/14,8208190238
- DOCKET STN-50-491 CHEROKEE NUCLEAR STATION, UNIT 1
- O Inspection reports, 1E Bulletins & correspondence
- 8208190233 IE Info Notice 80-35, Suppl 1, "Leaking & Dislodged I-12"; Implant Seeds " Svc list encl CORDLL I Division of Fuel Facilities, Materials & Safeguards 82/10/06 Consolidated Edison Co of New York 66pp 15761 250 24% Fiche 50-000,82/10/06,8208190233
- 820B190238 JE Bulletin 82-03, "Stress Corrosion Cracking in Thick-Hall-Large-Diameter, Stainless Steel Recirculation Sys Piging at BMR Plants" Svc Isst encl DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/10/14 Consolidated Edison Co of New York 115pp 15810 125 24X Fichs 50-000,82/10/14,8208190238
- OGCKET STN-50-492 CHEROKEE NUCLEAR STATION, UNIT 2

 G Inspection reports: IE Gulletins & correspondence
- G208190233 IE Info Notice 80~35, Suppl 1, "Leaking & Dislodged I-12h implant Seeds " Svc list encl COBp.L I Division of Fuel Facilities, Materials & Safeguards G2/10/06 Consolidated Edison Co of New York 66pp 15761 250 24
- 8208190238 IE Bulletin 82-03, "Stress Corrosion Cracking in Thick-Wall, Large-Diameter, Stainless Steel, Recirculation SysPiping at BUR Plants "Svc list encl
 DEYOUND, R.C. Director's Office, Office of Inspection and Enforcement 82/10/14 Consolidated Edison Co. of New York
 11500 15810 125 24% Fisch 50-000, 82/10/14, 8208190238
- DOCKET STN-50-493 CHEROKEE MUCLEAR STATION, UNIT 3
- G Inspection reports. IE Bulletins & correspondence
- 8208190233 lE Info Notice 80-35, Suppl 1, "Leaking & Dislodged I-125 Implant Seeds " Svc list encl COBB, L I Division of Fuel Faculities, Materials & Safeguards 82/10/06 Consolidated Edison Co of New York 66pp 15761 250 24X Fiche 50-000,82/10/06,8208190233
- 8208190238 IE Builetin 82-03. "Stress Corresion Cracking in Thick-Wall, Large-Diameter, Stainless Steel, Recirculation Sys Piping at BWR Plants " Svc list encl DEYGUNG.R C Director's Office. Office of Inspection and Enforcement 62/10/14 Cansolidated Edison Co of New York 115pp 15810 125 23K Fiche 50-000.82/10/14,8208190238
- DOCKET STN-50-498 SOUTH TEXAS PROJECT. UNIT 1
- A Application/construction stage documents & correspondence
- 8210250358 Requests latest revision to Form NRC-3, "Notice to Employees," per amend of 10CFR19, 20, 40, 50, 60, 70, 72 & 150 to provide employee protection against discrimination as consequence of reporting info to NRC OPREA, 0 W Houston Lighting & Power Co. 82/08/09 COLLINS, J T Region 4, Office of Director 2pp. 15790 341 24X Fiche 50-498, 82/08/09, 8210250358
- 8210250263 Bubmits updated schedulas for const activities to be restarted during remainder of 1982, per util 820514 ltr W/ two oversite charts Aperture cards are evaliable in PDR CPREA.0 W Houston Lighting & Power Co 82/08/30 COLLINS.J T. Region 4. Defice of Director. Bpp. 15791:027, 24X Fiche 50-498,82/08/30.8210250263

- B210040422 Forwards Task Interface Agreement 82-44, complete with plan for Quadret Rept re Brown & Root design of project MAR input needs to be generated during Sept 1982, in order for Region 4 to issue final rept in Oct 1982. In order for Region 4 to issue final rept in Oct 1982. Hull MAR () All RROULIA-F J Licensing Branch 3 82/08/31 Hull MAR () Evaluation Branch PARR () D Ausiliary Systems Branch BERLINGER (Core Performance Branch 2pp 1997/2)/ Fiche 50-498,82/08/31,8210040422
- 9210250259 Advises that add) safety-related const utility to be restarted in 1982 has been identified since util (1200) if the Updated schedule for const activities to be restarted due for 1982 enc). Whose eversize chart Aperture card as an PPN OPREA.O W. Houston Lighting & Power Co. B2/UY/2() (44) for J1 Region 4, Office of Director. Ppp. 15791-019 24x. Fiche 50-498.82/09/20.0210250259
- B210200075 Forwards info requested at B20722 meeting hospital 1' geotechnical info on essential cooling water pipelines soil profiles, boundaries of four low density barifit areas a contaminated barifit of the contaminated barifit of the contaminated barifit of the cooling a fower for 63/10/12 to ASSISTANT Director for Licensing B4pp 157% 11 '41 Fiche 50-498.82/10/12.8210200075
- 8210200052 Forwards responses to Questions 24t 1 through 441 A 174 to expedite geotechnical review Info will be incorporated into FBAR amend QULDBERG, J.H. Houston Lighting & Power Co. 112/10/111 146*A5*** Assistant Director for Licensing 77pp 19791 0111 /41 Fichs 50-498.02/10/18.0210200032
- 8210220237 Forwards Revision 0 to "Control Room Dusign Mevice For Plan"
 GULDBERO, J H. Houston Lighting S. Power Co. (12/10/41) N.C.A.J. N.C.J. N.C.A.J. N.C.J. N.C.A.J. N.C.J. N.C.A.J. N.C.J. N.C
- --B210220241 Revision O to "Control Room Design Review Program Plant Houston Lighting & Power Co B2/10/11 129pp 15/75 144 Fiche 50-490, B2/10/20, B210220239
- 9 Adjudicatory correspondence
- 8210050241 Proposed opinion, findings of fact, conclusions of law & in form of partial initial decision Certificate of the Prof. GUILGREZ, J. M. Hearing Branch 3. 92/10/04. 21/pp. 15/u/ 705. Fiche 50-476, 92/10/04. 8210050241
- 8210180172 Memorandum & Order LBP-82-91 granting Citizens Conserval About Nuclear Power motion to adopt Citizens for Equitable Utils contentions re Contention 4 & denying motion re Contentions 3-8 American Bridge contentions of dismissed BECHNOFFER C Atomic Safety and Licensing Board Panel Caffell Citizens Concerned About Nuclear Power, Inc 17pp 13719 444 J. Fiche 50-490,82/10/15,8210180172
- B210210363 Forwards applicant reply to Citizens Concerned Abaul Mar Power Inc & MRC proposed findings of fact & conclusions of Law NEWMAN J R Lowenstein, Newman, Reis, Axelrad & Toll PRIMAN J R Houston Lighting & Power Co 82/10/18 BCCHMETER.C . 1A제로 J € HILLE E Atomic Bafety and Licensing Board Panel 19 1354 2. 24X Fishe 50-498, 82/10/18, 8210210363
- --B21021036B Reply to Citizens Concerned About Nuclear Paver Inc & w proposed findings of fact & conclusions of law Certificate of Byc enci # Houston Lighting & Power Co # Lowensteam Newman. Ret& Alsin. & Toll B2/10/18 Atomic Bafety and Licensing Sears Pares, 9700 15763 241 248 Tiche 50-498.82/10/16.0320/2107867
- G Inspection reports: IE Bulletine & correspondence
- 8210080015 Add1 response to FOIA request for 19 categoriss of the 31 nuclear reactor events & safety problems forwards documents listed in App A Documents in App B completely withheld fast FOIA Exemption 5)
 FELTON, J. H. Division of Rules and Records 82/07/12 UD&LL. R A Critical Mass Energy Project 9pp 13665 027 24%
 Fiche 50-000, 82/07/12, 8210080015
- --B2100B0163 Bystematic Assessment of licensee performance motter; facility evaluation for Aug 1979-Jul 1980 * NRC - No Detailed Affiliation Given B0/07/31 13;p 13668 079 24X Fiche 50-000, B2/07/12, B2100B0015
- 8210190413 Forwards IE Insp Repts 50-498/82-14 & 50-499/82-14 em 820823-27 No noncompliance noted.

 MADBEN, O. Division of Resident, Reactor Project & Engineering Programs 82/97/28 OPREA, O.W. Houston Lighting & Pewer Co 25 15741 001 24% Fichs 50-498,82/09/28,8210190413

DOCKETED HEMS

- -8210190419 IE Insp Repts 50-498/82-14 & 50-499/82-14 on 820823-27 No noncompliance noted Major areas inspected GA program re noncompliance nowe major area inspected da program redesign, engineering procurement & const CROSSMAN.W A. HILL.W H. BOARDMAN.J R. Division of Resident, Reactor Project & Engineering Programs 82/09/24 [Ipp 1574] OO3 24% Fiche 50-498,82/09/28,8210190413
- 6208190233 IE Info Notice 80-35, Suppl 1, "Leaking & Disloged I-125 Implant Seeds "Svc list encl COBOL C Division of Fuel Facilities, Materials & Safeguards 82/10/06 Consolidated Edison Co of New York 66pp 19761 250 24x Fiche 50-000.82/10/06.8208190233
- 6208190238 IE Bulletin 82-03. 'Stress Corrosian Cracking in Thick-Mall.Carge-Diameter, Stainless Steel, Recirculation Sys Mall.Carge-Diameter, Stainless Steel, Recirculation Sys Piping at BWR Plants "Svc list encl DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/10/14 Consolidated Edison Co of New York LISpp 15810 [25 24X Fiche 50-000,82/10/14,8208]90238
- 6210220122 Ack receipt of 820909 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-498/82-02 MADSEM 6 L Division of Resident, Reactor Project & Engineering Programs 82/f0/14 0/9REA.G W Houston Lighting & Power Co ip 15777 332 24X Fiche 50-498/82/10/14/8210220122
- --8210220125 Responds to NRC 820811 ltr re violations noted in IC Insp Repts 50-498/82-02 & 50-499/82-02 Corrective actions deficiency reporting procedures revised & employees retrained

 CPREA, G W Houston Lighting & Power Co 82/09/07 COLLINS, J T
 Region 4, Office of Director 4pp 15777 333 24X

 Fiche 50-498,82/10/14.8210220122
- S Apportable occurrences. LERs & related correspondence
- 日210250112 Supplemental deficiency rept re beam to column connection design in containment bldg.per NRC inequest Info expected by B21217 Crown & Root.inc reanalysis received in Aug & Submitted to Becktel for review

 OPAEA, O V Houston Lighting J. Power Co 82/08/19 CDLLINS, J T

 Region 4. Office of Director Rpp 15787 022 24X

 Fiche 50-498. 62/08/19.8210250112
- 6210050329 Final deficiency rept re possible exceeding of design pressure loading of isolation valve cubicle auxiliary feeduater pump compartment walls in event of feedwater bypais line break Initially reported on B20901

 OPREA, O W Houston Lighting & Power Co B2/09/29 COLLINS, J T

 Region 4, Office of Director App 15610 254 24X

 Fiche 50-498, B2/09/29, B210050329
- 3210250249 Fifth interim defictency rept re vendor fabricated structural steel Initially reported on 810108 Bechtel will assure that surveillance insp of 100% of all welded mott was or will be performed prior to shipment Noxt rept by 830809 OPREA. O W Houston Lighting & Power Co B2/10/15 COLLII Region 4. Office of Director 3pp 15788 339 24x Fiche 50-498.82/(0/15.8210250249 15 COLLINS: J 1 24x
- 8210260452 Final deficiency ropt re NVAC design Instially reported on 010908 Chillers added to existing auxiliary bldg chillers, mixing boxes deleted make-up air balanced & electrical penetration exhaust sys down-graded

 GPREA. O W Houston Lighting & Power Co 82/10/20 (
 Region 4. Office of Director 14pp 18807 106 24x
 Fiche 50-498.82/10/20.8210260452 COLLINS, J. T.
- DOCKET STN-50-499 BOUTH TEXAS PROJECT, UNIT 2
- A Application/construction stage documents & correspondence
- &2:0250358 Requests latest revision to Form NRC-3, "Notice to Electronal Requests latest revision to Form NRC-3, "Notice to Employees," per amend of lOCFR19, 30, 40, 50, 60, 70, 72 & 150 to provide employee protection against discrimination as cansequence of reporting info to NRC OPREA, G W Houston Lighting & Power Co 82/08/09 COLLINS, J T Region 4. Office of Director 2pp 15790 341 24X Fichs 50-498.82/08/09,8210250358
- 8210250263 Gubmits updated schedules for const activities to be restarted during remainder of 1982,per util 820514 ltr H/tuo oversite charts Aperture cards are available in PDR OFREA.O W Houston Lighting & Power Co 82/08/30 COLLINS, J T Region 4, Office of Director 8pp 15791 027 24X Fiche 50-498,82/08/30,8210250263

- 8210040422 Forwards Task Interface Agreement 82-44, complete w/review plan for Quadrez Rept re Brown & Root design of project NRR input needs to be generated during Sept 1982, in order for Region 4 to issue final rept in Oct 1982 MIRAGLIA,F J Licensing Branch 3 82/09/31 HULMAN,L G Accident Evaluation Branch FARR,O D Auxiliary Systems Branch BERLINGER,C Core Performance Branch 2pp 15597 237 24X Fiche 50-498,82/08/31,8210040422
- 8210250259 Advises that addl safety-related const activity to be restarted in 1982 has been identified since util 820830 ltr Updated schedule for const activities to be restarted during 1982 encl Wione oversize chart Aperture card is in PDR OPREA.0 W Houston Lighting & Power Co 82/07/20 COLLINS, J Region 4, Office of Director 9pp 15791 019 24X Fiche 50-498.82/09/20,8210250239 COLLINS, J T
- 8210200075 Forwards info requested at 820722 meeting Submittal includes geotechnical info on essential cooling water pipelinas soil profiles boundaries of four low density backfill areas & contaminated backfill GOLDBERG. J H Houston Lighting & Power Co 82/10/12 NOVAK.T M Assistant Director for Licensing 84pp (5756 231 Fiche 50-498,82/10/12,8210200075 24X
- 8210200052 Forwards responses to Questions 241 1 through 241 6, in order to expedite geotechnical review Info will be incorporated NOUAK.T M
- 8210220239 Forwards Revision O to "Control Room Design Review Program Plan "
 GOLDBERG, J H Houston Lighting & Power Co B2/10/20
 Assistant Director for Licensing 3pp 15775 193 24X
 Fiche 50-498.82/10/20.8210220239 NOVAK, I' M
- -8210220241 Revision O to "Control Room Design Review Program Plan + Houston Lighting & Power Co 82/10/11 129pp 15775 196 24x Fiche 50-498.82/10/20.8210220239
- G Adjudicatory correspondence
- 8210090241 Proposed opinion, findings of fact, conclusions of law & order in form of partial initial decision Certificate of Svc encl OUTIERREZ, J M Hearing Branch 3 82/10/04 217pp 15607 306 24X Fiche 50-498, 82/10/04, 8210050241
- 8210180172 Memorandum & Order LBP-B2-91 granting Citizens Concerned About Nuclear Power motion to adopt Citizens for Equitable Utils contentions re Contention 4 & denying motion re Contentions 5-B American Dridge contentions dismissed BECH-IOEFER, C Atomic Safety and Licensing Board Panel 82/10/15 Citizens Concerned About Nuclear Power, Inc 17pp 15719 148 EFiche 50-498,82/10/15,8210180172
- 8210210363 Forwards applicant reply to Citizens Concerned About Nuclear Power, Inc & NRC proposed findings of fact & conclusions of NEWMAN, J.R. Lowenstein, Newman, Reis, Axelrad & Toll NEWMAN, J.R. Howston Lighting & Power Co. 82/10/18 BECHMBEFER, C., LAMB, J.G., HILL, E.E. Atomic Safety and Licensing Board Panel 1p 15763 240 24% Fiche 50-498, 82/10/18, 8210210363
- --8210210368 Reply to Citizens Concerned About Nuclear Power, Inc & NRC proposed findings of fact & conclusions of law Cortificate of Bay encl
 - of Byc encl * House & Power Co * Lowenstein, Newman, Rmis, Ax toll 82/10/18 Atomic Safety and Licensing Board Pane? 79pp 18763 241 24X Fithe 50-49B, 82/10/18, 8210210363
- Q Inspection reports, IE Bulletins & correspondence
- 8210080015 Add1 response to FDIA request for 19 categori nuclear reactor events & safety problems Forwards docu-listed in App A Documents in App B completely withheld FOIA Exemption 5) FELTON, J M Division of Rules and Records, 82/07/1; Critical Mass Energy Project 9pp 15665 027 24X Fiche 50-000,82/07/12,8210080015
- --B210080163 Systematic assessment of licensee performan facility evaluation for Aug 1979-Jul 1980 + NRC No Detailed Affiliation Given 80/07/31. 12668 079 24X Fiche 50-000, 82/07/12, B210080015
- 8210190413 Forwards IE Insp Repts 50-498/82-14 & 50-499/1 200323-27. No noncompliance noted MADBEN. 0 L. Division of Resident, Reactor Project & El Programs 82/09/28. OPREA. 0 M. Houston Lighting & P. 15741 Ool. 24% Fiche 50-498,82/09/28.8210190413

- --B210190419 IE Insp Repts 50-498/82-14 & 50-499/82-14 on 820823-2/ No noncompliance noted Major areas inspected GA program re design, engineering procurement & const CROSSMAN,W A . HILL,W K . BDARDMAN,J R Division of Resident, Reactor Project & Engineering Programs 82/09/24 11pp 15741 003 24% Fiche 50-498,82/09/28,8210190413
- 8208190233 IE Info Notice 80-35, Suppl i, "Leaking & Dislodged I-125 Implant Seeds" Svc list encl COBB.L 1 Division of Fuel Facilities, Materials & Safeguards 82/10/04 Consolidated Edison Co of New York 6App 15741 250 24% Fiche 50-000.82/10/04. 8208190233
- 8208190238 IE Bulletin 82-03. "Stress Corrosion Cracking in Thick-Mall.Large-Diameter, Stainless Steel, Recirculation Syspiping at BWR Plants "Svr list encl DEYOUNG, R C Director's Office. Office of Inspection and Enforcement 82/10/14 Consolidated Edison Ca of New York 115pp 15910 125 24X Fiche 50-000.82/10/14.8208190238
- 8210220122 Ack receipt of 820909 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-498/82-02 MADSEN. O L Division of Resident, Reactor Project & Engineering Programs 82/10/14 QPREA. O M. Houston Lighting & Power Co ip 15777 332 24% Fiche 50-498,82/10/14,8210220122
- ~-8210220125 Responds to NRC 820811 ltr re violations noted in IE Insp Repts 50-478/82-02 & 50-499/82-02 Corrective actions defitiency reporting procedures revised & employees retrained DREA: G W Houston Lighting & Power Co 82/09/09 Chilling, J r Region A. Office of Director 4pp 15777 333 24X Fiche 50-498, 82/10/14, 8210220122
- S Reportable occurrences, LERs & related correspondence
- 8210250112 Supplemental deficiency rept to beam to column connection design in containment bldg.per NRC request Info expected by 821217 Broom & Root.Inc reamalysis received in Aug & submitted to Bechtel for review OPREA.0 U Houston Lighting & Power Co 82/08/19 COLLINS.J T Region 4. Dffice of Director 2pp 15787 022 24% Fiche 50-498.82/08/19.8210250112
- B210050327 Final deficiency rept re possible exceeding of design pressure loading of isolation valve cubicle auxiliary feedwater pump compartment walls in event of feedwater bypass line break initially reported on B20901 OPREA:0 W Houston Lighting & Power Co B2/09/29 CGLLINS, J T Region 4, Office of Director 4pp 15610 254 24X Fiche 50-498, 82/09/27, 8210050329
- 6210250249 Fifth interim deficiency rept re vendor fabricated structural steel initially reported on Bioloß Bechtel will assure that surveillance insp of 100% of all welded mati was or will be performed prior to shipment Next rept by 830509 OPREA:0 W Houston Lighting & Power Co 82/10/15 COLLINS, J T Region 4. Office of Director 3pp 15788.339 24% Fiche 50-496.82/10/15.8210250249
- 8210260452 Final deficiency rept re HVAC design Initially reported on B10508. Chillers added to existing auxiliary bidg chillers, mixing boxes deleted, make-up air balanced & electrical penetration exhaust sys down-graded OPREA: OW Howston Lighting & Power Co 82/10/20 COLLING, J T Region 4. Defice of Director 14pp 15807 106 24X Fiche 50-498, 82/10/20, 8210260452
- DOCKET STN-50-508 WPPSS NUCLEAR PROJECT, UNIT 3
- A Application/construction stage documents & correspondence
- 8210180214 Summary of B20831-0902 caseload forecast panel site visit w/util in Satsop. WA re info to use as input to OL review scheduling progress & projected fuel load date. WHEELERL Litensing Branch 3 82/09/17 Licensing Branch 3 2pp 15746 113 24% Fichs 50-508,82/09/17,8210180214
- --8209210550 Notification of 820831 & 0701-02 meetings w/util in Satsop, WA to review const progress in order to obtain info for use as input to OL review scheduling process Related matl encl WHEELER, L. Licensing Branch 3 82/08/20. MIRAGLIA: F. Licensing Branch 3 103pp. 14746:117 24X Fichs. 50-508.82/09/17.
- S210120197 Advises that fuel load date scheduled for Dec 1985, per NRC request Schedules do not preclude achieving fuel load 6 months earlier. Planning details provided basis for discussions w/NRC Caseload Forecast Panel on 820831-0902.
 BOUCHEY, O.D. Washington Public Power Bupply System 82/10/01 EISENHUT, D. Q. Division of Licensing 1p. 15651 229 24X Fiche 50-508, 82/10/01, 8210120197

- 8210280416 Approves use of ASME Code Case N-249-2, in response to 820921 request Scope of approval limited to use of code case for strap & rivet matis in ITT-Grinnel Figures 215 for stiff clamps
 KERRIOAN, J D Licensing Branch 3 82/10/08 FERGUSON.R L
 Hashington Public Power Supply System 2pp 15859 358 24x
 Fiche \$0-508.82/10/08.8210280416
- 8210270012 Forwards responses to FSAR questions transmitted w/NRi B20820 Itr Responses to questions re environ rept will be sant under separate rover BOUCHEY, G.D. Washington Public Power Supply System 82/10/2, KERRIGAN, J.D. Licensing Dranch 3 300pp 15815 001 24x Fiche 50-508, 82/10/22, 8210270012
- H General correspondence
- 8210010020 Advises that EPA (Region X) deleted from distribution ii I for FSAR & general info amends EPA informed util that FSAR, esergency preparedness plan. Fire protection plan & general info not required DOUCHEY, G D Washington Public Power Supply System 82/07/22 EISENHUT, D O Division of Licensing 2pp 15565 150 -4X Fiche 50-508. 82/09/22, 8210010020
- K Utility Final Bafety Analysis Report (FSAR) & amends
- B210120194 Forwards Amend 1 to FBAR.updating design description to correcting typographical errors
 BOUCHEY.G D Washington Public Power Supply System (92/10/06 KERRIOAN.J D Licensing Branch J Jpp 15657 137 24X
- --8210120200 Amend 1 to FSAR

 # Washington Public Power Supply System 82/10/31 216/pp
 15657 140 24X Fiche 50-508.82/10/06.8210120194
- G [napaction reports, IE Bulletins & correspondence
- 8210060155 Forwards IE Insp Repts 50-508/82-17 & 50 509/04 0/ on 820801-31 & notice of violation STERNBERG, D M Division of Resident, Reactor Project & Inginering Programs 82/09/24 LEDDICK, R S Washington Public Power tupple System 2pp 15614 056 24X Fiche 50-508.82/09/24.02100/017
- --8210060197 Notice of violation from insp on 820801-j1 BODDS.R T Division of Resident, Reactor Project & Engineering Programs 82/09/24 ip 15614 058 24% Fichs 50 508,82/0//
- --B210060163 IE Insp Repts 50-508/B2-17 & 50-509/B2-D7 on II/Q[0] > Noncompliance noted on B20B10, nonsafety-related Q decling attached to containment bldg safety-related structural steel at 395-ft level using nonqualified procedure ALBERT, W G , DDDBS, R T Division of Resident, Reactor Project Engineering Programs B2/09/22 9pp 15614 Q59 24x Fiche 50-508,82/09/24,8210060155
- 8210070158 Ack receipt of 820528 itr informing NRC of steps talen to correct violations noted in IE Insp Repts 50-508/82-06 & 50-509/82-03 STERNBERO.D M Division of Resident, Reactor Project & Inginterious Programs 82/10/04 LEDDICK, R S Washington Public Power (west) System 1p 15627 064 24X Fiche 50-508, 82/10/04, 82100/0158
- --8210070161 Responds to NRC 820426 ltr re-violations noted in if 1 in Repts 50-508/82-06 & 50-509/82-03 Corrective actions the shutdown cooling MXs placed in care & makint program to insure monthly monitoring of maint on nitrogen purge LEDDICK, R S Washington Public Power Supply System 92/05/mill BISHOP, T W Division of Resident, Reactor Programs 4pp 15627 065 24X Fiche 50-508,82/10/04,0210070118
- 8208190233 IE Info Notice 80-35, Suppl 1, "Leaking & Bislodged I lea Implent Seeds " Svc list encl COBB.L. I Division of Fuel Facilities, Materials & Bafaguaria 82/10/06 Consolidated Edison Co of New York Jupp 13761 pto 24X Fiche 50-000/82/10/06/8208190233
- 8208170238 JE Bulletin 82-03, "Stress Corrosion Cracking in Thick Walls Earge-Diameter, Stainless Steel, Recirculation Sysping at BWR Plants" Svc list encl DEYGUNG, R C Director's Office, Office of Inspection and Enforcement 82/10/14 Consolidated Edison Co of New York 115pp 15810 125 24X Fiche 50-000, 82/10/14, 9208190238

- DOCKET STN-50-509 WPPSS NUCLEAR PROJECT, UNIT 5
- a inspection reports. IE Bulletins & correspondence
- 6210060155 Forwards IE Insp Repts 50-508/82-17 % 50-509/82-07 on 820801-31 & notice of violation STERNBERG, D M DIVISION of Resident. Reactor Project & Engineering Programs 82/09/24 LEDDICK, R S Washington Public Power Supply System 2pp 15614 Q56 24% Fiche S0-508.82/09/24.8210060155
- -8210040163 IC Insp Repts 50-508/82-17 b 50-509/82-07 on 820801-31 Noncompliance noted on 820810.nonsafety-related G decting attached to containment bldg safety-related structural steel at 395-ft level using nonqualified procedure M.BRRT.W G DODDS.R T Division of Resident. Reactor Project & Engineering Programs 82/09/22 9pp 15614 059 24X Fichs 50-508,82/09/24,8210060155
- 6210070158 Ack receipt of BP052B Iti informing NRC of steps taken to correct violations noted in IE Insp Repts 50-508/82-03 & 50-508/82-03 M Division of Resident, Reactor Project & Engineering Programs 82/10/04 LEDDICK,R & Washington Public Power Supply System Ip 13627 064 24X Fishe 50-508,82/10/04,8210070158
- -02100/0161 Responds to NRC 820426 ltr re violations noted in IE Insp
 Repts 90-500/82-06 & 50-507/82-03 Corrective actions
 two shutdown cooling HXs placed in care & maint program to
 insure monthly monitoring of maint on nitrogen purge
 LLDBICK.R S Nashington Public Power Supply System 82/05/28
 BISHBP,T W Division of Resident, Reactor Project & Engineering
 Programs 4pp 15627-065 24X Fishe 50-508,82/10/04,8210070198
- DURKET 50-511 WPPGS HULLEAR PROJECT, UNIT 4
- d Inspection reports. IE Bulletins & correspondence
- 62100707/B Ack receipt of 820909 Itr informing NRC of steps taken to correct violations noted in Insp on 820501-28

 5FFRNECRG D M Division of Resident, Reactor Project & Engineering Programs 02/10/04 R00T,R W Washington Public Power Supply System 1p 15434 017 24% Fiche 50-440.82/10/04.8210070378
- 8210070397 Responds to NRC 820624 lfr re violations noted in 1E insp on 82001-20 Corrective actions subcontractor procedures for initallation of electrical penetration assemblies submitted & approved by engineer RODT, R W Washington Public Power Supply System 82/09/09 BIGHOP, T W Division of Resident, Reactor Project & Engineering Programs 4pp 15634 016 24% Fiche 90-460,82/10/04,8210070378
- (2)0130415 Ack receipt of 820707 & 30 ltrs informing NRC of steps taken to correct violations noted in IC insp on 820401-30
 STERNBERG, D M Division of Resident, Reactor Project & Engineering Programs 02/10/06 ROOT, R Washington Public Power Bupply System 1p 15601 319 24X Fiche 50-440, 62/10/06, 6210130415
- --8210130425 Updates response to NRC 820608 ltr re violations noted in 16 insp on 820401-30 Corrective actions local grinding to expose weld root performed on four wolds Cause of undersized welds due to impraperly prepared weld bevels ROOT, R W Rashington Public Power Supply System 82/07/30 SIERNBERG,D M Division of Resident, Reactor Project & Engineering Programs 5pp 15681 320 24% Fichs 50-460,82/10/06,8210130415
- 8710130432 Responds to NRC 820608 ltr re violations noted in IE inspon 820401-30 Corrective actions local grinding conducted to spose weld root & base metal surfaces Partial penetration butt weld undersized RDDI.R H Hashington Public Power Supply System 82/09/09 BIBHOP,T W Division of Resident. Reactor Project & Engineering Programs 7pp 15681 325 24X Fiche 50-440,82/10/06.8210130415
- S Asportable occurrences, LERs & related correspondence
- B21007033B Interim deficiency rept re emergency dissel generator governor lube oil cooler initially reported on B20126 Lube oil cooler will be moved to elevation below oil level per Transamerica Delaval instructions & drawings R00F.R W Washington Public Power Supply System 82/09/15 SYERNDERO, D M Division of Resident, Reactor Project & Engineering Programs 2pp 15634 071 24X Fiche, 50-460, B2/09/15, 821007033B
- 8210070297 Interim deficiency rept re unsuitability of isoprene math used in governor drive coupling elements Initially reported on B20819 Field change notice issued to implement hangeout of element math to neoprene Also reported per Part 21 ROOTLR W. Washington Public Power Supply System 82/09/20 STERNBERG. D. M. Division of Resident, Reactor Project & Engineering Programs 28p 15634 178 24X Fiche 50-460,82/09/20,8210070297

- 8210070311 Interim deficiency rept re use of lumped mass loads in performance of pipe stress analysis Initially reported on 820305 Parametric studies may resolve trivial mass changes Interim status repts will be provided on semiannual basis RDOT, R W Washington Public Power Supply System 82/09/20 STERNBERO, D M Division of Resident, Reactor Project & Engineering Programs 3pp 15634 145 24% Fichs 50-460, 82/09/20, 8210070311
- DOCKET 50-514 PEBBLE SPRINGS NUCLEAR PLANT, UNIT 1
- G Adjudicatory correspondence
- 8210150476 Hemorandum & order directing applicants to rept details of status of applications for CPs to ASLB within 30 days of svc of order SMITH.I W Atomic Safety and Licensing Board Panel B2/10/13 Portland General Electric Co ip 15703 047 24x Fichs 50-514,82/10/13,8210150476
- G Inspection reports, IE Bulletins & correspondence
- 8208190233 IE lnfo Notice 80-35, Suppl 1, "Leaking & Dislodged I-125 Implant Seeds " Svc list encl COBB.L I Division of Fuel Facilities, Materials & Safeguards 82/10/06 Consolidated Edison Co of New York 66pp 15761 250 24X Fiche 50-000,82/10/06,8208190233
- 8208190238 IE Bulletin 82-03, "Stress Corrosion Cracking in Thick-Wall, Large-Diameter, Stainless Steel, Recirculation Sys Piping at BMR Plants " Syc list and DEYOUNG, R C Director's Office, Office of Inspection and Enforcement B2/10/14 Consolidated Edison Co of New York 115pp 15810 125 24X Fiche 50-000, 82/10/14, 8208190238
- DOCKET 50-515 PEBBLE SPRINGS NUCLEAR PLANT. UNIT 2
- G Adjudicatory correspondence
- 8210150476 Memorandum & order directing applicants to rept details of status of applications for CPs to ASLB within 30 days of svc of order SMITH, I W Atomic Sefety and Licensing Board Panel 82/10/13 Portland Omneral Electric Co 1p 15703 047 24X Fiche 30-514,82/10/13,8210150476
- Q Inspection reports, IE Bulletins & correspondence
- 8208190233 IE Info Notice 80-35, Suppl 1. "Leating & Dislodged I-125 Implant Beeds " Svc list encl CDBb, L 1 Division of Fuel Facilities, Materials & Safeguards 82/10/06 Consolidated Edison Co of New York 66pp 15761 250 24X Fichs 50-000, 82/10/06. 8208190233
- 820B19023B IE Bulletin 82-03. "Stress Corrosion Cracking in Thick-Wall, Large-Diameter: Stainless Steel, Recirculation Sys Piping at BWR Plants " Svc list encl DEYGUNO, R C Director's Office. Office of Inspection and Enforcement 82/10/14 Consolidated Edison Co of New York 115pp 15810:125 24X Fiche 50-000, 82/10/14, 8208190238
- DOCKET STN-50-510 HARTSVILLE NUCLEAR PLANT, UNIT 1
- A Application/construction stage documents & correspondence

- 8210010411 Ack receipt of 820913 ltr informing NRC of steps taken to correct violations noted in 1E Insp Repts 50-518/82 08 & 50-520/82-08 WERRELLI.D M Division of Project & Resident Programs 82/09/22 PARRIS.H O Tennessee Valley Authority 1p 15572 181 24X Fiche 50-518.82/09/22.8210010411
- --B21001042D Forwards response to NRC B20B12 ltr re violations noted in IE Insp Repts 50-518/B2-0B & 50-520/B2-0B Corrective actions GC investigation rept written to prevent use of protective coatings & FVC conduit covered & stored KAMMER.D S Tennessee Valley Authority 82/09/13 O'REILLY, J P Region 2. Office of Director 3pp 15372 192 24X Fiche 50-51B, B2/09/22, B210010411
- --8210010426 Forwards IE Insp Repts 50-518/82-08 & 50-520/82-08 on 820720-29 & notice of violation VERRELLI.D M Division of Project & Resident Programs 82/08/12 PARRIS.H G Tennessee Valley Authority 2pp 15572 185 24X Fichs 50-518 82/09/22/8210010411
- --8210010431 Notice of violation from insp on 820720-23 4 Division of Project & Resident Programs 82/08/12 ip 15572 187 24X Fiche 50-518,82/09/22,8210010411
- --8210010433 IE Insp Repts 50-518/82-08 & 50-520/82-08 on 820720-23
 Noncompliance noted failure to follow procedures on storage
 & preventive maint of safety-related matis
 MERRIMEATHER.N. CONLOW.T E Division of Engineering & Technical
 Programs 82/08/11 5pp 15572 188 24X Fiche 50-518.82/09/22,
 8210010411
- 8208190233 IE Info Notice 80-35, Suppl 1, "Leaking & Dislodged I-125 Implant Seeds " Svc list enci CD83.L I Division of Fuel Facilities, Materials & Safeguards 82/10/06 Consolidated Edison Co of New York 66pp 15761 250 24% Fiche 50-000, 82/10/06.8208190233
- 8208190238 IE Bulletin 82-03, "Stress Corrosion Cracking in Thick-Wall, Large-Diameter, Stainless Steel, Recirculation Sys Piping at BMR Plants "Syc list encl DEYOUNG, R C Director's Office Office of Inspection and Enforcement 82/10/14 Consolidated Edison Co of New York 115pp 15810 125 24X Fiche 50-000, 82/10/14,8208190238
- S Reportable occurrences. LERs & related correspondence
- 8210080247 Third & final deficiency repts to resolution of unanticipated vibratory loading concerns Initially reported on Bil228 Program developed to insure piping sys operate within design parameters Next rept provided by 821217 MILLS.L H Tennessee Valley Authority 82/09/24 O'REILLY.J P Region 2. Office of Director 3pp 15638 104 24X Fiche 50-000.82/09/24,8210080247
- 8210050293 First interim deficiency rept re six sheared motor pinion keys in Limitorque Model 88-0-25 motor operators Initially reported on 820830 Valves w/motor operators being tabulated Next rept will be submitted by 821122 MILLS,L M Tennessee Valley Authority 82/09/28 0'REILLY, J P Region 2, Defice of Director 2pp 15609 070 24X Fiche 50-000, 82/09/28, 8210050293
- 8210270328 Second interim deficiency rept re use of nonconservative calculational method to evaluate General Const Spec 0-32 spacing violations Initially reported on 820528 Next rept will be sent by 830528 MILLS, L M Tennessee Valley Authority 82/10/12 0'REILLY, J P Region 2. Office of Director 2pp 15853 064 24X C'-he-50-000, 82/10/12, 8210270328

- 8210260320 First interim deficiency rept re addition of locking deals to handwheel operated valves Initially reported on 820916 Const activities deferred Analyses of locking devices continuing Neit rept will be sent by 820310 MILLS.L H Tennessee Valley Authority 82/10/18 0'REILLY.J# Region 2. Office of Director 2pp 15802 359 24X Fichs 50-000.82/10/18.8210260320
- 8210290274 Final rept for Deficiencies B & E & seventh interim repli Deficiencies A & D re control of procurement activities Initially reported on 810316 Final corrective actions noted Next rept expected by 830428 MILLS, L M Tennessee Valley Authority 82/10/21 O'REILLY, J! Region 2, Office of Director 4pp 15853 143 24% Fiche 50-000, 82/10/21, 8210290274
- DOCKET 51N-50-519 HARTSVILLE NUCLEAR PLANT, UNIT 2

 A Application/construction stage documents & correspondence
- 8210040430 Informs of decision to refund fees remitted w/BDI(X)1 application to delete certain requirements from primary water quality monitoring Fees should not be charged in cases where licensee has effective NPDES permit MILLER, H. O. License Fee Management Branch B2/09/21 PANHILL, H. C. Tennessee Valley Authority ip 15597 263 24X Fiche 50-000, B2/09/21, B210040430
- Q Inspection reports. IE Bulletins & correspondence
- 8210150318 Forwards IE Insp Repts 50-518/82-11,50-519/82-1(), 50-520/82-11 & 50-521/82-09 on 820816-18,25 & 0910 No noncompliance noted VERRELLI,D M Division of Project & Resident Programs 6)2/09/_{NV} PARRIS,H 0 Tennesse Valley Authority 2pp 15705 25%, 24x Fiche 50-516,82/09/20,8210150318
- --8210150334 IE Insp Repts 50-518/82-11.50-519/82-10.50 520/82 (1 % 50-521/82-09 on 820816-16.25 % 0910 No noncompliance inited Major areas inspected open items. Independent insp effort (A-1 & A-2) & site deferral preparation (A-1 & A-2) SCHAPKER.J F. CANTRELL.F.S Division of Project & Resident Programs 92/09/20 4pp 15705 258 24X Fithe 50-516,82/8//...08210150318
- 6208190233 IE Info Notice 80-35, Suppl 1, "Leaking & Distinged 1 pp Implant Seeds " Svc list encl COBD.L I Division of Fuel Facilities, Materials & Safeguards 62/10/06 Consolidated Edison Co of New York 66pp 13/Al PCO 24% Fiche 50-000.82/10/06.8208190233
- 8208190238 IE Bulletin 82-03, "Stress Corrosion Cracking in Thick Wall, Large-Diameter, Scainless Steel, Recirculation Sys Piping at BMR Plants " Syc list enc! DEYQUNO, R C Director's Office, Office of Inspection and Enforcement 82/10/14 Consolidated Edison Co of New Yort 115pp, 15810 125 24X Fiche 50-000, 82/10/14, 8208170238
- S Reportable occurrences. LERs & related correspondence
- 8210270187 Interim deficiency rept re deferral of const activities Initially reported on 820623 Commitments made in rept. audit findings & response to violations deferred until restart of design & const MILLS, L M Tennesses Valley Authority 82/10/14 0'REJLLY, J P Region 2, Office of Director 1p 15853 312 24% Fiche 50-000, 82/10/14, 8210270187
- DOCKET STN-50-520 HARTSVILLE NUCLEAR PLANT, UNIT 3
- A Application/construction stage documents & correspondence
- 8210040430 Informs of decision to refund fees remitted w/B01031 application to delete certain requirements from primary water quality monitoring Fees should not be charged in cases where license has effective NPDES permit HILLER.W O License Fee Management Branch 82/09/21 PARRITH L Tennessee Velley Authority 1p 15597 263 24X Fiche, 50-000, 82/09/21, 8210040430
- Q Inspection reports, IE Bulletins & correspondence
- 9210150318 Forwards IE Insp Repts 50-518/82-11,50-519/82-10,50-520/82-11 & 50-521/82-07 on 820816-18,25 & 0910 No noncompliance noted VERRELLI,D M Division of Project & Resident Programs 82/09/20 PARRIS,H G Tennessee Valley Authority 2pp 15705 256 24X Fiche 50-518,82/09/20,8210150318

DOCKETED ITEMS

- --8210150334 IE Insp Repts 50-518/82-11.50-519/82-10.50-520/82-11 & 50-521/82-09 on \$20816-18.25 & 0910 No noncompliance noted Major areas inspected open items; independent insp effort (A-1 & A-2) & site deferral preparation (A-1 & A-2) SCHAPKER.J F. CANTRELL.F S Division of Project & Resident Programs \$2/09/20 App 15705 258 24X Fiche \$0-518.82/09/20, 8210150318
- 6210010431 Ack receipt of 820713 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-518/82-08 & 50-520/82-08 VERRELLI, D M Division of Project & Resident Programs 82/09/22 PARRIS.H G Tennessee Valley Authority Ip 15572 181 24X Fiche 50-518.822/09/22.8210010411
- --B210010420 Forwards response to NRC 820812 1tr re violations noted in IE (nsp Repts 50-518/R2-08 & 50-520/82-08 Corrective actions QC investigation rept written to prevent use of protective coatings & PVC conduit covered & stored MAMMER, D S Tennessee Valley Authority 82/09/13 0'REILLY, J P Region 2, Office of Director 3pp 15572 182 24X Fiche 50-516,82/09/22,821001041i
- --8210010426 Forwards JC Insp Repts 50-518/82-08 & 50-520/82-08 on 820720-23 & notice of violation VCRRELLI, D M Division of Project & Resident Programs 82/08/12 PARRIS, H G Tennessee Valley Authority 2pp 15572 185 24X Fiche 50-518 82/09/22 821001041
- --8210010431 Notice of violation from insp on 920720-23 4 Division of Project & Resident Programs 82/08/12 ip 15572 187 24X Fiche 50-518,82/09/22,8210010411
- --B210010433 IC Insp Repts 50-518/82-08 & 50-520/82-08 on 820720-23 Noncompliance noted failure to follow procedures on storage 1 preventive maint of safety-related matls MERRIMEATHER, N. CONLON. T. E. Division of Engineering & Technical Programs 82/08/11 5pp 15572 188 24% Fiche 50-518,82/09/22, 8210010411
- 820B190233 IE Info Notice 80-35. Suppl 1. "Leaking & Dislodged I 125 Implant Seeds " Svc list encl COB9.L I Division of Fuel Facilities. Materials & Safeguards 82/10/06 Consolidated Edison Co of New York 66pp 15761 250 24x Fiche 50-000.82/10/06.820B190233
- 0208190238 IE Bulletin 82-03, "Stress Corrosion Cracking in Thick-Hall.Large-Diameter Stainless Steel Recirculation Sys Piping at DWR Plants" Syr list encl DEYDUNG.R C Director's Office. Office of Inspection and Entercement 82/10/14 Consolidated Edison Co of New York 115pp 15810 125 24% Tiche 50-000.02/10/14, 8208190238
- 5 Reportable occurrences, LERs & related correspondence
- 9210080247 Third b final deficiency repts re resolution of unanticipated vibratory loading concerns Initially reported on 811228 Program developed to insure piping sys operate within design parameters Next rept provided by 821217 MILLS.L M Tennessee Valley Authority 82/09/24 D'REILLY, J PRegion 2. Office of Director 3pp 15638 104 24X Fiche 50-000, 82/09/24, 8210080247
- 2210050293 First interim deficiency rept to six sheared motor pinion keys in Limitorque Model SG-0-25 motor operators initially reported on 820830 Valves w/motor operators being tabulated Next rept will be submitted by 821122 MILLS.L M Tennessee Valley Authority 82/09/28 0'REILLY, J P Region 2. Office of Director 2pp 15609 070 24X Fiche 50-000-82/09/28,8210050293
- 6210290328 Second interim deficiency rept re use of nonconservative calculational method to evaluate General Const Spec 0-32 spacing violations initially reported on 820528 Next rept will be sent by 830528 MILLG.L M Tennessee Valley Authority 82/10/12 O'REILLY, J P Region 2. Office of Director 2pp 15853 064 24X Fiche 50-000, 62/10/12, 9210290328
- 8210290187 Interim deficiency rept re deferral of const activities Initially reported on 820623 Commitments made in rept, audit findings & response to violations deferred until restart of design & const HJLL8, L M Tennessee Valley Authority 82/10/14 O'REILLY, J P Region 2, Office of Director ip 15853 312 24X Fiche 50-000,82/10/14,8210290187

- 8210290236 Third interim deficiency rept re potentially overstressed embedded plates Initially reported on 820412 Investigation continuing & const activities deferred until sufficient infogathered to determine completion of project MILLS.L M Tennessee Valley Authority 82/10/14 D'REILLY, J P Region 2. Office of Director 2pp 15853 227 24X Fiche 50-000, 82/10/14, 8210290236
- 8210260320 First interim deficiency rept re addition of locking devices to handwheel operated valves Initially reported on 820916 Const activities deferred Analyses of locking devices continuing Next rept will be sent by 820310 MILLSIL M Tennessee Valley Authority 82/10/18 O'REILLY, J P Region 2, Office of Director 2pp 15802 359 24X Fiche 50-000, 82/10/18, 8210260320
- 8210290274 Final rept for Deficiencies 8 & E & seventh interim rept for Deficiencies A & D re control of procurement activities Initially reported on 810316 Final corrective actions noted Next rept expected by 830428 MILLS.L M Tennessee Valley Authority 82/10/21 D'REILLY.J P Region 2, Office of Director 4pp 15853 143 24X Fiche 50-000, 82/10/21, 8210290274
- DOCKET BIN-50-521 HARTSVILLE NUCLEAR PLANT, UNIT 4

 A Application/construction stage documents & correspondence
- B210040430 Informs of decision to refund fees remitted w/B01031 application to delete certain requirements from primary water quality monitoring fees should not be charged in cases where licensee has effective NPDES permit MILLER.W O License Fee Management Branch B2/09/21 PARRIS.H O Tennessee Valley Authority 19 15597 263 24X Fiche 50-518, B2/09/21, B210040430
- G Inspection reports. IE Bulletins & correspondence
- 8210150318 Forwards IE Insp Repts 50-518/82-11.50-519/82-10, 50-520/82-11 & 50-521/82-09 on 820816-18.25 & 0910 No noncompliance noted VERRELLI.D M Division of Project & Resident Programs 82/09/20 PARRIS, H 0 Tennessee Valley Authority 2pp 24X Fiche 30-518.82/09/20.8210150318
- --8210150334 IR Insp Repts 50-518/82-11, 50-519/82-10, 50-520/82-11 & 50-521/82-09 on 820816-18, 15 & 0910 No noncompliance noted Major areas inspected open items, independent insp effort (A-1 & A-2) & site deferral preparation (A-1 & A-2) & Site
- 8208190233 IE Info Notice 80-35, Suppl i, "Leaking & Dislodged I-12b Implant Seeds " Svc list encl COBB.L I Division of Fuel Facilities, Materials & Safeguards 82/10/06 Consolidated Edison Co of New York AApp 15761 280 24X Fiche 50-000,82/10/06,8208190233
- 820Bi9023B IE Duiletin 82-03, "Stress Corrosion Cracking in Thick-Wall Large-Diameter, Stainless Steel Rectrculation Sys Plping at BNR Plants "Svc list encl DEYOUNG.R C Director's Office. Office of Inspection and Enrortement 82/10/14 Consolidated Edison Co of New York 115pp 15810 125. 24% Fiche 50-000, 82/10/14,820819023B
- S Reportable occurrences. LERs & related correspondence
- 8210290)87 Interim deficiency rept re deferral of const activities Initially reported on 820623 Commitments made in rept, audit findings & response to violations deferred until restart of design & const MILLS.L M Tennessee Valley Authority 82/10/14 0'REILLY.JP Region 2, Office of Director by 15853 312, 24% Fiche 50-000, 82/10/14.8210290187
- DOCKET 50-522 BRAGIT NUCLEAR POWER PROJECT, UNIT 1
- A Application/construction stage documents & correspondence
- 8210270158 Summary of 820721 meeting w/applicants in Bethesda.MD reprogram to investigate May Junction monocline MDON.C W Licensing Branch 4. 82/10/05 Licensing Branch 4 4pp 15876 224. 24% Fishe 50-522.82/10/05.8210270158

- 8 Utility Preliminary Safety Analysis Report, amends
- B210210337 Forwards Amend 27 to PSAR
 MYERS,R V Puget Sound Power & Light Co 82/10/08 Dffice of
 Nuclear Reactor Regulation, Director 3pp 85764 311 24X
 Fiche 50-922,82/10/08.8210210337
- --8210210339 Amend 27 to PSAR 4 Puget Sound Power & Light Co 82/10/08 101pp 15764 314 24X Fiche 50-522,82/10/08.8210210337
- 8210260430 Forwards Affidavit of Svc certifying distribution of PSAR Amend 27 to listed persons on 821020 THOMSEN.FT Perkins. Cois. Stone. Clisen & Williams 82/10/22 Office of Nuclear Reactor Regulation. Director 3pp 15804
- C Utility Environmental Report (ER), amends & correspondence
- G210070189 Forwards Amend 7 to application for site certification/environ rept Amend revises info re need-for-power, alternative energy sources, socioeconomics & exclusion area boundary Verrification & distribution list encl MYERS, R V Puget Sound Power & Light Co 82/09/16 Office of Nuclear Reactor Regulation, Director opp 15634 348 24% Fiche 50-522.02/09/16.8210070189
- --8210070193 Amend 7 to application for site certification/environ rept * Puget Sound Power & Light Co 82/09/16 250pp 15634 354 24x Fiche 50-522,82/09/16.8210070189
- 8210010382 Forwards Affidavit of Svc for Amend 6 to application for site certification/environ regt THOMSEM.F T. Perkins. Cole. Stone, Olsen & Williams 82/09/27 Office of Nuclear Reactor Regulation, Director 3pp 15574 293 24X Fiche 50-522, 82/09/27, 8210010382
- 8210130190 Forwards Affidavit of Svc for Amend 7 to application for site certification/environ rept
 THOMSEN,F T Perkins, Coie, Stone, Oisen & Williams 82/10/07
 Office of Nuclear Reactor Regulation, Director 3pp 15674 104
 24X Fiche 50-522,82/10/07.8210130190
- G Adjudicatory correspondence
- 8210050389 Responds to util 820917 first set of interrogatories Certifficate of Syx encl Related correspondence BELL,N Coalition for Safe Power 82/09/28 Puget Sound Power & Light Co 4pp 15608 231 24X Fiche 50-522, 82/09/28, 8210050389
- 8210050169 Supplement to petition to intervene, consisting of contentions & bases for contentions HOVIS, J B Yakima Indian Nation HOVIS, J B Hovis, R L 82/09/29 Atomic Safety and Licensing Board Panel 62pp 15605 052 24X Fiche 50-522,82/09/29,8210050169
 - 10050171 Applicant response to Coalition for Bafe Power 820910 first set of interrogatories Certificate of Svc encl. Related correspondence
 THOMSEN.F T Puget Sound Power & Light Co THOMSEN.F T Perkins, Coie: Stone: Olsen & Hillians 82/09/29, Coalition for Safe Power 34pp 15604 145 24x Fiche 50~522,82/09/29,8210050171
 - of interrogatories Certificate of Svc

Federation THATCHER, T.L. Oregon T.L. Thatcher, T.L. 82/10/04, p. 15643 268 24X

> bal Fish Commission Indom & order Ise appeal in

THOMSEN, FT Puget Sound Power & Light Co
Coie, Stans, Olsen & Williams 92/10/06
Licensing Appeal Panel 3pp 15680 320
24X Fich: 50-522, 82/10/06,
92/0/30367

::0::30498 Response to 820917 first set of interrogatories THOMSEN.F.T Puget Saund Pauer & Light Co THOMSEN.F.T Perkins. Coie. Stone. Olsen & Williams 82/10/06 Natural Resources Defense Council. 8pp 15683 689 24X Fiche 50-522, 82/10/06.

130120271 Notice of appearance in proceeding Certificate of Svc encl DEMEY, L S Hearing Branch 3 82/10/08 3pp 15652 314 24X Fiche 50~522, 82/10/08, 8210120271

- 8210120288 Brief supporting Columbia River Inter-Tribat Fish Commission 820923 appeal of ASLB 820908 memorandum & order denging Columbia petition to intervene Columbia has met injury in fact test Certificate of Svc encl DEWEY.L S Hearing Branch 3 82/10/08 Atomic Safety and Licensing Appeal Panel 20pp 15653 058 24X Fiche 50-522, 82/10/08, 82/10/20288
- 8210200045 Response to Vakima Indian Nation 820930 suppl to pelilian t intervene containing list of contentions Objects to Contentions 4-10 Certificate of Svc encl THOMSEN, F I pertison to the contention of the content of the conte
- 8210190373 Notice of withdrawal of appearance in proceeding Certifical of Svc encl
 BLACK.R L. Hearing Branch 3 82/10/15 3pp 1574t 2tt 24x
 Fiche 30-522.82/10/15,8210190373
- 821020005B Response to B20910 first set of production requests
 Certificate of Svc encl Related correspondence
 FRANTZ,S P Puget Sound Power & Light Co FRANTZ,S P
 Lowenstein Newman-Resis.Asetrad & Toll B2/10/15 Coelition for
 Safe Power 82pp 15750 093 24X Fiche 50-522,82/10/15,8210.0000
- 8210220427 Response to Yakima Indian Nation 820930 supplies petition to intervene, setting forth contentions Contentions L. 2, 3 to 6 should be admitted & consolidated w/similar contentions Certificate of Svc encl
 DEWEYL B Hearing Branch 3 82/10/20 Atomic Safety and Licensing Board Panel 2(pp. 15780-190-24X Fiche 50-522,03/10/8210220427
- H General correspondence
- 8210220434 Requests all parties be informed of Natl Hildlife federat & DR Environ Council correct address THATCHER, T.L. National Wildlife Federation 82/10/19 illege the Secretary of the Commission 1p 15778 269 24X Fiche 50-522, 82/10/19, 8210220434
- Q Inspection reports, IE Bulletins & correspondence
- 8208190233 IE Info Notice 80-35, Suppl i, "Leaking & Dislodged t La Implant Seeds " Syc list enc!
 COBB.L I Division of Fuel Facilities, Materials & Enfeguards 827/10706 Consolidated Edison Co of New York 66pp 19761 J 24X Fiche 50-000.82/10/06,8208190233
- 8208190238 IE Bulletin 82-03, "Stress Corrosion Cracking in Thick Wall, Large-Diameter, Stainless Steel, Recirculation Sys Piping at BHR Plants " Svc list encl BEYOUND, R C Director's Office, Office of Inspection and Enforcement 82/10/14 Consolidated Edison Co of New York 115pp 15810 125 24X Fichs 50-000.82/10/14; 82001902/38
- DOCKET 50-523 SKAGIT NUCLEAR POWER PROJECT, UNIT 2

 A Application/construction stage documents & correspondence
- 921029013B Summary of B20921 meeting w/applicants in Bethesds.HD r. progrem to investigate May Junction monocline HBON-C W Licensing Branch 4 B2/10/05 Licensing Branch 4 4pp 13876 224 24X Fishe 50~522.82/10/05,82(029013B
- B Otility Preliminary Safety Analysis Report, amends
- 8210210337 Forwards Amend 27 to PBAR

 MYERG.R V Puget Sound Power & Light Co 82/10/08 Office &
 Nuclear Reactor Regulation, Director 3pp 15764 311 24x
 Fiche 50-522,82/10/08,8210210337
- ~-8210210339 Amend 27 to PSAR 4 Puget Sound Power & Light Co 82/10/08 101pp 15764 [J]4 24X Fiche: 50-522, 82/10/08, 8210210337
- 8210260430 Forwards Affidavit of Svc certifying distribution of P:
 Amend 27 to listed persons on 821020
 THUMSEN,F T Perkins: Coie, Stone: Olsen & Williams 82/10/22
 Office of Nuclear Reactor Regulation, Director 3pp 13806 Op
 24X Piche. 50-522, 82/10/22, 8210260430

- Utility Environmental Report (ER), amenda & correspondence
- 10070189 Forwards Amend 7 to application for site certification/environ rept Amend revises info re need-for-power, alternative energy sources, socioeconomics & exclusion area boundary Verification & distribution list encl MYERS, R V Puget Sound Power & Light Co 82/09/16 Office of Nuclear Reactor Regulation, Director &pp 15634-348 24X Fichs 50-522,82/09/16,8210070189
- -8210070193 Amend 7 to application for site certification/physron rept 4 Puget Sound Power % Light Co 82/09/16 250pp 15634 354 24% Fiche 50-522,82/09/16,8210070189
- 2100103B2 Forwards Affidavit of Svc for Amend 6 to application for site certification/environ rept 1HOMSENIF T Perkins, Coie, Stone, Olsen & Williams 82/09/27 Orrice of Nuclear Reactor Regulation, Director 3pp 15574 293 24/ Fiche 50-522,82/09/27,8210010382
- 3210130190 Forwards Affidavit of Svt for Amend 7 to application for site certification/environ rept
 THOMESH F T Perkins, Coie, Stone, Olsen & Williams 82/10/07
 Office of Nuclear Reactor Regulation, Director 3pp 15474 104
 24x Fiche 50-522,82/10/07.8210130190
- s Adjudicatory correspondence
- 8210050389 Responds to util 820917 first set of interiogetories Certificate of Svc encl Related correspondence BELL,N Coalition for Safe Power 82/09/28 Puget Sound Power & Light Co 4pp 15608 23t 24% Fiche 50-522,82/09/28,8210050389
- 6210050169 Supplement to petition to intervene consisting of contentions & bases for contentions MOVIS.J B Hovis. R L 82/09/29 Atomic Safety and Lirensing Board Panel 62pp 15605 052 24X Fiche 50-522.82/09/29.8210050169
- GZ10050171 Applicant response to Coalition for Safe Power B20910 first set of interrogatories Certificate of Eve entl Related correspondence
 THOMSEN,F T Puget Sound Power & Light Co. THOMSEN,F T Perking, Coie, Stone, Olsen & Hilliams 02/09/29 Coalition for Safe Power 34pp 15604 145 247 Fiche 50-522. B2/09/29, B210050171
- 8210080073 Response to first set of interrogatorius Certificate of Sve encl HATCHER, T.L. National Wildlife Federation THATCHER, T.L. Oregon Environmental Council THATCHER, T.L. Thatcher, T.L. 82/10/04 Pupet Sound Power & Light Co. 9pp. 15443 P68 24X Fiche 50-522, 82/10/04, 8210080073
- 9210130367 Response to Columbia River Inter-Tilbal Fish Commission 820723 notice of appeal of ASLB 820703 memorandum & order denying intervention Applicants will not oppose appeal in order to maintain schedule for proceeding HollsErlif T Puget Sound Power & Light Co THOMSEN, F T Perkins, Cale. Stone. Olsen & Williams 82/10/06 Atomic Safety and Licensing Appeal Panel 3pp 15680 320 24X Fiche 50-522,82/10/06. 82:0130367
- S210130498 Response to B20917 first set of interrogatories
 IHONSEN.F T Puget Sound Power & Light Co THOMSEN.F T Perkins,
 Core. Stone. Olsen & Williams B2710706 Natural Resources
 Defense Council Bop 15683 089 24X Fiche 50-522, 82/10/06,
 67:10130498
- 6210120271 Notice of appearance in proceeding Certificate of Svc encl DEUZY,L S Hearing Branch 3 62/10/08 3pp 15652 314 24X Fiche 50-522,62/10/08,6210120271
- \$210120288 Brief supporting Columbia River Inter-Tribal Fish Commission 820923 appeal of ASLB 820908 memorandum & order denying Columbia petition to intervene Columbia has met injury in fact test Certificate of Svc enc.

 DENEY.L 8 Hearing Branch 3 82/10/08 Atomic Safety and Licensing Appeal Panel 20pp 15653 058 24% Fiche 50-522, 82/10/08, 8210120288
- 8210200045 Response to Yakima Indian Nation B20930 suppl to petition to intervene, containing list of contentions Objects to Contentions 4-10 Centificate of Svc encil THOMSEN, FT Puget Sound Power & Light Co THOMSEN, FT Perkins, Cois, Stone, Clien & Williams B2/10/14 Atomic Bafety and Litensing Board Panel 15pp 15756 026 24X Fiche 50-522, 82/10/14, B210200045

- 8210190373 Notice of withdrawal of appearance in proceeding Certificate of Svc encl BLACK,R L. Hearing Branch 3 82/10/15 3pp 15741 211 24X Fiche 50~522.82/10/15.8210190373
- 8210200058 Response to 820910 first set of production requests
 Certificate of Svc encl Related correspondence
 FRANTZ.S P Puget Sound Power & Light Co FRANTZ.S P
 Lowenstein Newman, Reis, Axelrad & Toll 82/10/15 Coalition for
 Safe Power 82pp 15753 093 24X Fichs 50-522, 82/10/15, 8210200058
- 8210220429 Response to Yakima Indian Nation 820930 supplits petition to intervene, setting forth contentions Contentions 1.2,3 & 6 should be admitted & consolidated w/similar contentions Certificate of Svc anci DEMEY.L S Hearing Branch 3 82/10/20 Atomic Safety and Licensing Board Panel 21pp 15780 190 24X Fichs 50-522.82/10/20, 8210220429
- H General correspondence
- B210220434 Requests all parties be informed of Natl Wildlife Federation & OR Environ Council correct address
 THATCHER.T L National Wildlife Federation 82/10/19 Office of the Secretary of the Commission 1p 15778 269 24X
 Fiche 50-522, 82/10/19, 8210220434
- O Inspection reports. IE Bulletins & correspondence
- 8208190233 IE Info Notice 80-35, Suppl 1, "Leaking & Dislodged I-125 Implant Seeds " Syc list encl COBUL 1 Division of Fuel Facilities, Materials & Safeguards 82/10/06 Consolidated Edison Co of New York 66pp 15761 250 24% Fiche 50-000,82/10/06,8208170233,
- 8208190238 IE Bulletin 82-03. "Stress Corrosion Cracking in Thick-Wall, Large-Diameter, Stainiess Steel, Recirculation Sys Piping at DWR Plants " Syc list encl DEYOUNG.R C Director's Office. Office of Inspection and Enforcement 82/10/14 Consolidated Edison Co of New York 115pp 15810 125 24X Fiche 50-000, 82/10/14, 8208190238
- DOCKET STN-50-528 PALO VERDE NUCLEAR STATION, UNIT 1

 A Application/construction stage documents & correspondence
- 8210180308 Notifies that commitment re accuracy of calibr stds per Amend 9 Page 17 2-56 not acceptable Justification should be provided or 2nd & 3rd paragraphs should be revised MIRADLIA.F J Licensing Branch 3 82/09/17 VAN BRUNT.E E Ariona Public Service Co 2pp. 15746 355 24X Fiche 50-528,82/09/17,82101803DB
- --B209210413 Discusses branch position on Amend 9 to FBAR re revised commitment regarding accuracy of calibr side Justification must be provided or commitment must be revised in order to be acceptable
 HAASB, W.P. Quality Assurance Branch 82/08/31 MIRAGLIA, F. J. Licensing Branch 3 2pp 15746 357 24X Fiche 50-528, 82/09/17, 8210180308
- 8210120025 Discusses organizational arrangement for technical support of facility operation Updated arrangement should be provided by 821115
 KERRIQANJD Licensing Branch 3 82/09/23 VAN BRUNT, E E Ariona Public Service Co 2pp 15489.187 24X
 Fithe 50-528,82/09/23.8210120025
- 8210180243 Forwards draft final nonradiological protection plan Comments requested KERRIGAN,J D Licensing Branch 3 82/09/23 VAN DRUNT,E E Florida Power & Light Co 2pp 15746 243, 24X Ficha 50-528,82/09/23,8210180243
- --8210180248 Draft final nonradiological environ protection plan 4 Licensing Branch 3 82/09/23 13pp 15746 245 24X Fiche 50-528,82/09/23,8210180243
- 8210210026 Forwards request for add1 info to complete review of "Probabilistic Risk Assessment of Tornado Missile Damage to Station UMS." Bethtal Staty 13-NS-10B KERRIGAN.J D Licensing Branch 3 82/09/29. VAN BRUNT, E Ariona Public Bervice Co 4pp 15782 197 24X Fiche, 50-528, 82/09/29, 8210210026
- 8210060245 Forwards Revision i to "Pump & Valve Inservice Testing Program,Palo Verde Nuclear Generating Station " VAN BRUNT,E C Arisona Public Service Co 82/10/01 NDVAK, T DIVISION of Licensing 2pp. 15620 243 24% Fiche 50-528,82/10/01. 8210060245

- --B210060247 "Pump & Valve Inservice Testing Program, Palo Verde Nuclear Generating Station," Revision 1 * Aniiona Public Service Co 82/08/17 179pp 15620 245 24X Fiche 50-528, 82/10/01-2210060245
- 8210150143 Forwards application to amend CPPR-141.CPPR-142 & CPPR-143, extending const completion date for Unit 1 to 830831 VAN BRUNT, E Ariona Public Service Co 81/10/12 Office of Nuclear Reactor Regulation. Director 3pp 15706 351 24X Fiche \$0-528.82/10/12.6210150163
- --8210150176 Application to amend GPPR-141.CPPR-142 & CPPR-143, extending const completion date for Unit 1 to 830831 VAN DRUNT.E E Arizona Public Service Co 82/10/12 7pp 15704 354 24X Fiche 50-528.82/10/12.8210150163
- B210190717 Requests NRC review results of PWR design analyses to approve renoval of pipe whip restraints Meeting W/NRC to discuss request & facilitate exchange of info & questions suggested VAN BRUNE, E.E. Arizona Public Service Co. 82/10/14 NOVAK, T.M. Assistant Director for Licensing 2pp 15738 211 24X Fiche 30-528, 62/10/14, 8210190717
- B210190463 Forwards responses to Auxiliary Sys Branch 820929 request for add1 info re probabilistic risk assessment of tornado missile danage to UHS VAN BRUNT, E E Arizona Public Service Co 82/10/15 NOVAK, T H Assistant Director for Licensing 9pp 15740 289 24X Fiche 50-528, 82/10/15, 8210190463
- 8210280057 Advises that util will provide comments on draft environ protection plan by 821129 VAN BRUNTLE E Arizona Public Service Co. 82/10/21 NOVAK, I M Assistant Director for Licensing 1p 15837 261 24X Fiche 50-528.82/10/21.8210280057
- B210280139 Advises that util will respond by 821129 to NRC 920929 ltr re schedule for resolution of remaining outstanding to onfirmatory issues VAN BROWN, E.E. Ariona Public Service Co. 82/10/21 OVAK, T.H. Assistant Director for Licensing (p. 15837 133, 24X Fiche 50-528.82/10/21.8210280139
- 8210280199 Forwards Proof of Svc for 821012 application to amend CPPR-141.CPPR-142 & CPPR-143
 VAN BRUNT, E E Arizona Public Service Co 82/10/21 Office of Nuclear Reactor Regulation, Director 3pp 15837 001 24X
 Fiche 50-528
- 8210270211 Forwards proposed amended pages to FBAR Section 6 2 & providing Type C testing of valves associated w/Containment Penetrations 44,67 & 77 using air Affidaylt encl
 VAN BRUNT. E E Arizona Public Service Co 82/10/22 NOVAK, T H Assistant Director for Licensing 17pp 15829 318 24X
 Fiche 50-528,82/10/22,821027021
- E NRC Safety Evaluation Report (SER). suppls & correspondence
- 8210210500 Forwards SER. Suppl 3 to OL application W/o encl KERRIGAN.J D Licensing Branch 3 82/09/23 VAN BRUNT.E E Artiona Public Service Co Jpp 15782 263 24x Fiche 50-528. 82/09/23. 8210210300

ETY EVALUATION REPORT RELATED TO THE OPERATION OF PALO R GENERATING STATION. UNITS 1.2. AND 3 Docket "Q--520, And 50-530 (Arisma Public Service")

Regulation, Director NUREO-0857 803 44 75 | 15636 268 | 24X

> 'n 13 1 2 3 concerning I be

> > 0/04 NOVAK, T H 50-528, 82/10/04,

OCTUROUS, TITUTES OF SESSION MODE SECOPPOPARED INTO listed drawings to provide two devices in series for adequate primary & backup protection of circuits Mode close SER confirmatory item discussed in Section B 4.3 VAN BRUNTLE & Arizona Public Service Co. 82/10/25 NOVAK, T M. Assistant Director for Licensing. 2pp. 15838-356 24X Fiche 50-528,82/10/25,8210280274

- @ Adjudicatory correspondence
- 8210130417 Notice of corrections to Joint Applicants reply to PL Hourihan proposed findings of fact & conclusions of law BISCHOFF, CA Joint Applicants-Palo Verde BISCHOFF, CA Bischoff CA 82/10/05 2pp 15680 224 24X Fiche 50-528,82/10/05,
- ---B210130486 Corrected pages to Joint Applicants reply to PL Hourshin proposed findings of fact & conclusions of law Certificate of Svc encl
 * Joint Applicants-Palo Verde B2/10/05 15pp 15680 226 .4tc
 Fiche 50-528, 82/10/05, 8210130417
- 8210150247 Forwards Suppl 3 to SER W/o encl DEMEY.L S Hearing Branch 3 82/10/13 LAZO,R M . COLE.R C . CALLIHAN, D Atomic Safety and Licensing Board Panel ip 15704 357 24x Fiche 50-528,82/10/13,8210130247
- 8210150497 Memorandum of law supporting Weat Valley Agricultural Protection Council. Inc petition to intervene Substantial new info only recently discovered Certificate of Svc encl BERLIN.K Affiliation Unknown BERLIN.K Affiliation Unknown 82/10/13 Atomic Safety and Licensing Board Panel 24pp 15712 209 24x Fiche 50-528,82/10/13.8210150499
- --B210150512 Petition of West Valley Agricultural Protection Council; is to intervene, request for preparation of supplemental or revised EIA & request for reopening record Certificate of Svc encl
 BERLIN,K Affiliation Unknown BERLIN,K Affiliation Unknown
 82/10/13 Atomic Safety and Licensing Board Panel 300pp
 15713 233 24X Fiche 50-528,82/10/13,8210150499
- 8210150474 Notices of appearance in proceeding Certificate of Svi Birth BERLIN,K., DERWIN,E F., LASOTA, J. Affiliation Unknown 82/10/14 4pp 15703 043 24X Fiche 50-528,82/10/14,8210150474
- B210270171 Motion for 2-wk extension of time to answer West Valley
 Agricultural Protection Council. Inc B21013 petition to
 intervene Complete petition not received Certificate of Svc
 encl
 B18CHOFF, C.A. Jaint Applicants-Paio Verde B18CHOFF, C.A. Bischute
 C.A. B2/10/22 Atomic Safety and Licensing Board Panel hpp
 15822 349 24x Fichs 30-528.68/10/22, 8210270171
- 8210290297 Response of Mest Valley Agricultural Protection County to Joint Applicants 821022 motion for extension of time to answer Council patition to intervene Tenday extension should be granted Cartificate of Svc encl
 BERLIN.K Affiliation Unknown 82/10/26 Atomic Safety and Licensing Board Panel Opp 15853 160 24X Fiche 50-528,02/10/26,82102/0297
- 8210280262 Brder granting Joint Applicants 821022 motion for extension of time to answer West Valley Agricultural Protection Council, Inc 821014 petition to intervene Joint Applicants have 2 wks after syc of complete petition to file answer LAZO,R M Atomic Safety and Licensing Roard Panel 82/10/27 Joint Applicants-Palo Verde 2pp 15837 310 24X Fichs 50-528, 82/10/27, 8210280262

M Antitrust correspondence

- 9210040292 Forwards page inadvertently omitted from first response to requirements contained in Reg Quide 7 3
 VAN BRUNYI.E E Arizona Public Service Co 82/09/28 Office of Nuclear Reactor Regulation, Director 2pp 15587 138 24X
 Ficha 50-528.82/09/28.8210040292
- --B210040305 Forwards Bait River Project Agricultural Improvement & Fe District & AZ Public Svc Co revised responses to requirements contained in Reg Quide 9 3 Corrected copy VAN BRUNTIE E Arizone Public Bervice Co 82/05/10 Office of Nuclear Reactor Regulation Director 9pp 15587, 140 24X Fiche 30-928, B2/09/28, B210040292
- G Inspection reports, IE Bulletins & correspondence
- 9210080155 Responds to NRC 811119 ltr re violations noted in 1E Inap Rept 50-528/81-12 on 810817-21 Corrective actions procedure for piping sys final inap, WPP/QCI No 2023, deleted & included in other procedures VAN SRUNTLE E Arisona Public Service Co 82/06/16 BleHoP.T W Division of Resident, Reactor Project & Engineering Programs Spp 15640-137, 24x Fiche 50-528,82/06/16,8210080155

1

ji j

- 210060341 Forwards IE Insp Rept 50-528/82-23 on 820823-0917 No noncompliance noted STERIBERG,D M Division of Resident, Reactor Project & Engineering Programs 82/09/23 ANDOGNINI.G C Arizona Public Service Co 2pp 15619 046 24x Fiche 50-528.82/09/23.8210060341
- -8210060345 [E Insp Rept 50:528/82-23 on B20823-0917 No noncompliance noted Major areas inspected startup testing, document control, maint, startup do % sys releases & organization FIGRELLI.G., JUHNSTON.G., YOUNG.T. Division of Resident, Reactur Project & Engineering Programs 82/09/22 Spp 15619 04B 44% Fiche 50-528,82/09/23,8210060341
- 8210060413 Forwards Relief Request 8 for exemption from preservice exam requirements, supplementing 820406 relief requests VAN BRUNT.E E Arizona Public Service Co 82/10/01 NOVAK.T N Assistant Director for Licensing 3pp 15615 007 24X Fiche 50-528,82/10/01,8210060413
- 8210070210 Provides corrected supplemental response to [E Bulletin B]-02. "Failure of Gate Type Valves to Close Against Differential Pressure" No Westinghouse Flectro Motor Div gate valves used in plant design Twenty-five manhours used VAN BRUNT, E E Arizona Public Service Co 82/10/01 ENGELKEN, R H Region 5. Office of Director 2pp 15634 264 24X Fiche 50-528,82/10/01,8210070210
- 6300170233 IE Info Notice 80-35. Suppl 1. "Leaking & Dislodged 1-125 Implant Seeds " Svc list encl COBB L I Division of Fuel Facilities. Materials & Safeguards 82/10/06 Consolidated Edison Co of New York 66pp 15761 250 24% Fiche 50-000.82/10/06.8208190233
- 9210130443 Commits to performing guide tube surveillance insp on representative bundles or first reload per NUREO-0852, Section 4 2 3 i VAN BRUNT.E E Arizona Public Service Co 82/10/06 NOVAK. 1 Assistant Director for Licensing 2pp 15682 013 24X Fiche 50-528.82/10/06.8210130443
- 6210220374 Corrected cupy of commitment to perform guide type wear surveillance insp described in NUREG-0852 Section 4 2 3 1, per NUREG-0857 Section 4 2 5 requirement Commitment will be incorporated into neit FSAR amend VAN BRUNT, E E Artiona Public Service Co 82/10/06 NDVAK, [Assistant Director for Licensing 2pp 15777 203 24X Fiche 50-528,82/10/06,8210270374
- 8210250351 Forwards 1E Insp Repts 50-528/82-25,50-529/82-09 & 50-530/82-10 on 820830-0903 % notice of violation STERNBERG, D M Division of Resident, Feactor Project & Engineering Programs 82/10/08 VAN BRUNT, F E Aritona Public Service Co 2pp 15790 026 24X Fiche 50-528-82/10/08,8210250351
- --8210250361 Notice of violation from insp on 820830-0903 YOUNG T Division of Resident, Reactor Project & Engineering Programs 82/10/08 2pp 15790 028 24X Fiche 50-528.82/10/08, 8210250351
- --8210250375 IE Insp Repts 50-528/82 25.50-529/82-09 & 50-530/82-10 en 820830-0903 Noncompliance noted 29 inches of wold metal found missing from control room panels & defective instrument repts not prepared £CKHARDJ.J H. HERNANDEZ.O., YOUND.T Division of Resident. Resetter Project & Engineering Programs 82/10/07 App 15790 030 24X Fiche 50-528 82/10/08/8210250351
- 8210280368 Forwards IE Insp Repts 30-528/82-26, 50-529/82-10 & 50-530/82-11 ph 920713-0703 No noncompliance noted STERNBERO, D M Division of Resident, Reactor Project & Engineering Programs 82/10/13 VAN BRUNT, E Arizona Public Service Co 2pp 15845 155 24X Fiche 50-528, 82/10/13, 8210280368
- --B2102B0372 IE Insp Repts 50-528/82-26.50-529/92-10 & 50-530/82-11 on 820713 0903 No honcompliance noted Major areas inspected const activities associated dygrouting of temporary underground piping & tontainment post-tensioning VORDERGRUEGGEN, YOUNG.T Division of Resident, Reactor Project & Engineering Programs 82/10/07 12pp 15845 157 24X Fiche 50-528,82/10/13.8210280368
- 8208190238 IE Bulletin 82-03. "Stress Corresion Cracking in Thick-Wall-Large-Diameter, Steinless Steel, Recirculation Sys Piping at BRR Plants " Svc list encl DEYOUNG, R C Director's Office. Office of Inspection and Enforcement 82/10/14 Consolidated Edison Co of New York 15pp 15810 125 24X Fichs 50-000,82/10/14,8208190238

R Pariodic operating reports & related correspondence

- B210120264 Forwards biweekly status rept of independent QA evaluation of Palo Verde Nuclear Generating Stations Units 1,2 & 3 for period 820911-24
 SIMON, WA Torrey Pines Technology B2/10/04 TURLEY, K.L. Arijuna Public Service Co. 15pp. 15652-27B. 24X Fiche 50-528, 82/10/04.
 B210120264
- 8210220198 Forwards "Independent QA Evaluation of Palo Verde Nuclear Cenerating Stations Units 1.2 & 3." Blueckly Status Rept 7 for period ending 821008 SIMON, WA Torrey Pines Technology 82/10/18 TURLEY, K.L. Arizon. Public Service Co. 1p. 15776 211 24X Fiche 50-528,82/10/18,8210220198
- --B210220244 "Independent GA Evaluation of Palo Verde Nuclear Generating Stations Units 1.2 & 3." Biweekly Status Rept 7 for period ending B2100B 4 Torrey Pines Technology B2/10/18 14pp 15776 212 24X Fiche 50-528.82/10/18
- S Reportable occurrences, LERs & related correspondence
- 8210070321 Final deficiency rept re mounting failures of C-E supplied valve position indicating suitches Initially reported on 820325 Nonconformance Rept SE-0487/0542 dispositioned to rework broken brackets Not reportable per 10CFR50 55(e) VAN BRUNT.E E Arizona Public Service Co 82/07/07 STERNBERG.D M Division of Resident, Reactor Project & Engineering Programs App 15634 117 24X Fiche 50-528,82/09/09,8210070321
- 8210070213 Interim Deficiency Rept DER 82-44 re ITT-Barton pressure transmitters failing to meet required overpressure range initially reported on 820824 C-E issuing purchase order suppl to obtain correct transmitters Next rept by 821118 VAN BRUNT.E E Arizona Public Service Co 82/09/15 STERNBERG,D M Division of Resident, Reactor Project & Engineering Programs 3pp 15634 258 24% Fiche 50-528,82/09/15,8210070213
- 8210070227 Requests add1 time to submit Final Deficiency Rept DER 82-9 re thermowells in diesel generator Jube oil sys by Cooper Energy not procured to ABME code Initially reported on 820316 info should be finalized by 821116 VAN BRUNTLE E Arizona Public Service Co 82/09/15 STERNBERG, D M Division of Resident, Reactor Project & Engineering Programs 2pp 19634 281 24X Fiche 50~528,82/09/15,8210070229
- B210070320 Final deficiency rept re weld procedure not prequalified by Ametek-Strain for reactor hot leg pipe stops Initially reported on 820514 Review of documentation revealed no further deviations Item not reportable per 10CFR90 55(e) VAN BRUNT.E E Arizona Public Service Co 82/09/15 STERNBERO,D M Division of Resident, Reactor Project & Engineering Programs Spp 15424 114 24X Fiche 50-528.82/09/15.8210070320
- 8210070337 Interim Deficiency Rept DER 82-45 re unqualified motor operators installed w/C-E/Borg-Harner safety injection sys valves Initially reported on 820826 Motor operators returned to mfg for mod Next rept expected by 821117 VAN BRUNTLE E Arizona Public Service Co 82/07/15 STERNBERG, D a) Division of Resident, Reactor Project & Engineering Programs Upp 13634 068 24X Fiche 50-928,82/09/15,8210070339
- B210070374 Final Deficiency Rept DER 82-18 re Westinghouse pump motors Initially reported on 820423 Motors found w/deteriorating epoxy coatings & metal particles in lube oil C-E determined incident not reportable per 10CFR50 35s VAN DRUNTIC E Arizone Public Service Co 82/09/16 STERNBERG, D M Division of Resident, Reactor Project & Engineering Programs 5pp 15634 022 24X Fiche 50-528,82/09/16.8210070374
- 8210070394 Final deficiency rept re steam generators loose internal nuts & couplings Nonconformance repts will be dispositioned to repair defects to conform w/C-E drawing requirements Unit 2 & 3 will be inspected for similar defects VAN BRUNT.E E Arizona Public Service Co BZ/09/21 STERNBERG, D M Division of Resident, Reactor Project & Engineering Programs App 15624 055 24% Fiche 50-528,82/09/21,8210070354
- 8210330187 Interim deficiency rept re Dragon Valva Co instrument line check valves saited open by welding heat Initially reported on 820701 Corrective action plan under review Next rept will be provided by 821205
 VAN BRUNT, E. Arizona Public Service Co 82/09/30 STERNBERG, D. M. Division of Resident, Reactor Project & Engineering Programs 3pp 13674 131 24X Fiche, 50-528, 82/09/30, 8210130187

- B210250100 Interim Deficiency Rept DER 82-50 re potential damage of flexible conduit couplings between auxiliary & control bldgs during selsmic event Initially reported on 820910 Dechtel establishing min acceptance criteria Final rept by 821230 VAN BRUNTLE E Arizona Public Service Co B2/10/08 STERNBERG, D M Division of Resident, Reactor Project & Engineering Programs Jpp 15787 111, 284 Fiche 50-528,88710/08.8210250100
- 8210250305 Final Deficiency Rept DER 82-47 re steam generator 2 pipe support welded to sway struts instead of attached by approved braciets Initially reported on 820905 Deam attachments replaced wisway strut roar end brackets VAN BRURT, E.E. Artiona Public Service Co. 82/10/08 STERNBERG, D. 13 Division of Resident, Reactor Project & Engineering Programs 3pp 15790-074 24X Fiche 50-528.82/10/08.8210250305
- 8210250326 Interim Deficiency Rept DER 82-51 re Pullman-Kellogg pipe lining failure in essential cooling water sys Initially reported on 820910 Condition under evaluation Final rept expected by 821202 VAN BRUNTLE Arisona Public Service Co 82/10/08 STERNBERG, D N Division of Resident, Reactor Project & Engineering Programs Spp 15790-322 24X Fichs 50-526,82/10/08,8210250326
- 9210260275 Final Deficiency Rept DFR 02-19 re Class IF GE motor control ctr burned out due to damage during testing Noncomformance SE-0567 dispositioned to replace damaged components Test procedures revised providing spec warning re damage VAN BRUNT, E. E. Artiona Public Bervice Co. 82/10/14 STERNBERO, D. M. Division of Resident. Reactor Project & Engineering Programs 4pp. 15003 222 24% Fische 50-528.82/10/14.8210260275

BOCKET STN-50-529 PALO VERDE MICLEAR STATION, UNIT 2

A Application/construction stage documents & correspondence

- 8210100308 Notifies that commitment re accuracy of calibr stds per Amend 9 Page 17 2-86 not acceptable Justification should be provided or 2nd & 3rd paragraphs should be revised MIRAOLIA.F J Licensing Branch 3 62/09/17 VAN BRUNT.E E Afiona Public Service Co 2pp 15746 395 24X Fiche 50-528, 82/09/17, 8210180308
- ~-B209210413 Discusses branch position on Amend 9 to FBAR re-revised commitment regarding accuracy of calibr stds Justification must be provided or commitment must be revised in order to be acceptable HAABB, N.P. Quality Assurance Branch B2/0B/31 MIRAGLIA, F.J. Licensing Branch 3 2pp 15746-357 24X Fiche 50-528,82/09/17,8210180308
- 8210120025 Discusses organisational arrangement for technical support of facility operation Updated arrangement should be provided by 821115

 MERRIGAN. J B. Licensing Branch 3 82/09/23 VAN BRUNT, E Aritona Public Bervice Co. 2pp. 15689 187 24X

 Fiche 50-528,82/09/23,8210120025
- 8210[80243 Forwards draft final nonradiological protection plan Comments requested KERRIGAN, J D Licensing Branch 3 82/09/23 VAN BRUNT, E E Florida Power & Light Co 2pp 15746 243 24X Fiche. 50-528, 82/09/23, 8210180243
- --B210180248 Draft final horradicingical environ protection plan * Licensing Branch 3, 82/09/23 13pp 15746 245 24X Fiche 50-528,82/09/23,8210180243

or addlines to complete review of one of Tornado Missile Damage to NE-108 3 62/09/29. VAN DRUNT, E E 15762 197 24X

- 8210060245 Forwards Revision i to "Pump & Valve Inservice Testing Program.Palo Verde Nuclear Generating Station " VAN BRUNT,E E Artrona Public Bervice Ca 82/10/01 NOVAK,T Division of Licensing 2pp 15620 243 24X Fiche 50-528.82/10/01.
- --8210060247 "Pump & Valve Inservice Testing Program, Pelo Verde Nuclear Generation Station " Bautain | 15620 245 248

~142 & CPPR-143, Office of 51 24X

- --B210150176 Application to amend CPPR-141, CPPR-142 & CPPR-143, eiterdict const completion date for Unit 1 to 830831 VAN BRUNT,E E Artiona Public Service Co 82/10/12 7pp 15706 354 24X Fiche 50-528,82/10/12.8210150163
- 8210190717 Requests NRC review results of PWR design analyses to approve removal of pipe whip restraints Meeting w/NRC to discuss request & facilitate exchange of info & questions suggested VAN BRUNT, E.E. Arisona Public Service Co. 82/10/14 NOVAK, 1 M Assistant Director for Licensing 2pp 15738 211 24% Fiche 50-528, 82/10/14, 8210190717
- 8210190463 Forwards responses to Auxiliary Sys Branch 820929 request for addi info re probabilistic risk assessment of tornado missile damage to UHS VAN BRUNT-E E Artiona Public Service Co 82/10/15 NOVAK, I il Assistant Director for Licensing 9pp 15740 289 24x Fiche 50-528, 82/10/15, 8210190463
- 8210280057 Advises that util will provide comments on draft environ protection plan by 821129 VAN BRUNT,E E Artiona Public Service Co 82/10/21 NDVAK,7 M Assistant Director for Licensing ip 15837 261 24X Fiche 50-528.82/10/21.8210280057
- 8210280199 Forwards Proof of Svc for 821012 application to amend CPPR-141.CPPR-142 & CPPR-143

 VAN SRUNT, E E Aritona Public Service Co 82/10/21 Office of Nuclear Reactor Regulation, Director 3pp 15837 001 24X

 Fiche 50-528.82/10/21.8210280199
- 8210270211 Forwards proposed amended pages to FSAR Section 6 2 6. providing Type C testing of valves associated w/Containment Penetrations 44,67 & 77 using air Affidavit encl VAN BRUNT, E E Arizona Public Service Co 82/10/22 NOVAH, (): Assistant Director for Licensing 17pp 15829 318 24x Fiche 50-528,82/10/22,82/02702(1
- E NRC Safety Evaluation Report (SER), supply & correspondence
- 8210210500 Forwards SER, Suppl G re OL application W/o encl KERRIGAN, J D Licensing Branch G 82/09/23 VAN BRUNT, E E Arizona Public Service Co Gpp 15782 263 24X Fiche 50-528, 82/09/23, 8210210500
- 8210060006 SAFETY EVALUATION REPORT RELATED TO THE OPERATION OF PALG VERDE NUCLEAR GENERATING STATION UNITS 1.2, AND 3 bocket Nos 50~528.50~529. And 50~530 (Aprilona Public Service Company.et al) # Office of Nuclear Reactor Regulation, Director NUREO-085/ \$07 82/09/30 38pp Available at NRC \$4.75 15636 268 24X Fiche 50~528,82/09/30,8210060006
- 8210190315 Advises that position re SER. Section 13 1 2 3 concerning operations superintendent not filled Resume will be forwarded to NRC when position is occupied VAN BRUNT. E E Arizona Public Service Co 82/10/04 NOVAK, T H Division of Licensing 2pp 15742 146 24% Fiche 50-528.82/10/18210190315
- 8210280274 Informs of design mods incorporated into listed drawings provide two devices in series for adequate primary & backup protection of circuits Mods close SER confirmatory item discussed in Section 8 4 3 VAN BRUNT.E E. Arizona Public Service Co 82/10/25 NOVAK.T H Assistant Director for Licensing 2pp 15838 356 24X Fichs 50-588.88/10/25.8210280274
- Q Adjudicatory correspondence
- 8210130417 Notice of corrections to Joint Applicants reply to Pt. Houriban proposed findings of fact & conclusions of law BISCHOFF.C A Joint Applicants-Palo Verde BISCHOFF.C A Bitz C A 82/10/05, 2pp 15680 224 24% Fiche 50-528,82/10/05,82/10/30417
- --B210130486 Corrected pages to Joint Applicants reply to PL Hours proposed findings of fact & conclusions of law Certificate of Byc encl 4 Joint Applicants-Palo Verde 82/10/05 15pp 15480 22& Fichs. 50-528, 82/10/05, 8210130417

- 5210150247 forwards Suppl 3 to SER W/o encl DENEYLL S Hearing Branch 3 92/10/13 LAZO,R M . COLE.R F . CALLIHAN D Atomic Safety and Licensing Board Panel lp 15704 337 24% Fische 50-528,82/10/13.8210150247
- B210150499 Memorandum of law supporting West Valley Agricultural Protection Council, Inc petition to intervene Substantial new info only recently discovered Certificate of Svc encl 3ERLIN.K Affiliation Unknown BERLIN.K Affiliation Unknown B2710713 Atomic Safety and Licensing Doard Panel 24pp 15713 209 24% Fishe 50-528, 82710713, 8210150499
- -2210150512 Petition of West Valley Agricultural Protection Council, Inc to intervene, request for preparation of supplemental or revised EIA & request for reopening record (ertificate of Svt encl

BERLINA Affiliation Unknown BE

- 8210150474 Notices of appearance in proceeding Certificate of Byc enci BERLIN: K , GERWIN: E F , LASGTA: J Affiliation Unknown B2/10/14 4pp 15703 043 24X Fiche 50~528:82/10/14:8210150474
- 5210270171 Motion for 2-wk extension of time to answer West Valley Agricultural Protection Council, Inc 821013 petition to intervene Complete petition not received Certificate of Sycencl BISCHOFF.C.A. Inint Applicants Pale Verde BISCHOFF.C.A. Risk BISCHOFF.C.A

BISCHOFF, C A Joint Applicants Pala Verdo BISCHOFF, C A Bischoff, C A 62/10/22 Atomic Safety and Licensing Board Panel 5pp 15822 349 24x Fiche 50-528.82/10/22.8210270171

- 8210290277 Response of West Valley Agricultural Protection Council to Joint Applicants 821022 motion for extension of time to answer Council petition to intervene Ten-day extension should be granted Certificate of Svc encl BERLINIX Affiliation Unknown 82/10/26 Atomic Safety and Econsing Board Panel App 19853 160 24X Fiche 50-528.82/10/26.8210270297
- 8210280262 Order granting Joint Applicants 021022 motion for extension of time to answer Nest Valley Agricultural Protection Council. Inc 021014 petition to intervene Joint Applicants have 2 uts after syc of complete petition to file answer LAZO.R H Atomic Safety and Licensing Noard Panel 02/10/27 Joint Applicants/Palo Verde 2pp 19837 010 24X Fiche 50-528, 82/10/27, 8210280262

M Antitrust correspondence

- 8210040292 Forwards page inadvertently omitted from first response to requirements contained in Reg Quide 7 3
 VAN BRUNTLE E Arizona Public Service Co 82/09/28 Office of Nuclear Reactor Regulation, Director 2pp 15597 138 24X
 Fishe 50-528, 62/09/28, 6210040292
- --8210040305 Forwards Salt River Project Agricultura) Improvement & Power Bistrict & AZ Public Svc Co revised responses to requirements contained in Reg Guide 9 3 Corrected copy VAN BRUNTLE E Arizona Public Bervice Co 82/08/10 DFFice ut Nuclear Reactor Regulation. Director 9pp 15587 140 24X Fiche 50-528.82/09/28.8210040292
- O inspection reports: 18 Bulletins & correspondence
- 621007021Q Provides corrected supplemental response to IE Bulletin B1-02: "Failure of Gate Type Valves to Close Against Differential Pressure" No Westinghouse Electro Motor Divgate valves used in plant design Tuenty-five manhours used VAN BRUNT.E E Arizona Public Service Co 82/10/01 ENGELKEN.R H Region 5. Office of Director 2pp 15634 264 24X Fiche 50-528,82/10/01.8210070210
- 8208190233 IR Info Notice 80-35, Suppl i, "Leaking & Dislodged I-125 Inplant Seeds " Svc list encl COB9.L I Division of Fuel Facilities, Materials & Safeguards 62/10/06 Consolidated Edison Co of New York 66pp 15761 250 24/
- 9210250351 Forwards IE Insp Repts 50-528/82-25,50-529/82-09 & 50-530/82-10 on 820830-0903 & notice of violation STERNQERO, DM Division of Resident, Reactor Project & Engineering Programs 82/10/08 VAN BRUNT, E E Artzona Public Service Co 2pp 15790 026 24X Fiche 50-528,82/10/08,8210250351
- --8210250361 Notice of violation from insp on 920830-0903 YOUNG.T Division of Resident, Reactor Project & Engineering Programs, 82/10/08 2pp 15790 028 24X Fiche 50-528,82/10/08, 8210250351

- --8210250375 IE Insp Repts 50-528/82-25.50-529/82-09 & 50-530/82-10 on 820830-0903 Noncompliance noted 27 inches of weld metal found missing from control room panels & defective instrument repts not prepared ECKMARDT.J H. HERNANDEZ.G. YOUNG.T Division of Resident. Reactor Project & Engineering Programs 82/10/07 App 15790 030 24X Fiche 50-528, 82/10/08, 8210250351
- 8210280368 Forwards IE Insp Repts 50-528/82-24.50-529/82-10 & 50-520/82-11 on 820713-0903 No noncompliance noted STERNBERG. D M Division of Resident. Reactor Project & Engineering Programs, 82/10/13 vAn BRUNT. E Arizona Public Service Co 2pp 13845 155 24% Fiche 50-528.82/10/13.8210280368
- --8210280372 IE Insp Repts 50-528/82-26,50-529/82-10 & 50-530/82-11 on 820713-0903 No noncompliance noted hajor areas inspected const activities associated w/grouting of temporary underground piping & containment post-tensioning VORDERBRUEGGEN, YOUNG, T Division of Resident, Reactor Project & Engineering Programs 82/10/07 12pp 15845 157 24X Fiche 50-528,82/10/13,8210280368
- B20B190238 IE Bulletin B2-03, "Stress Corrosion Cracking in Thick-Wall, Large-Diameter, Stainless Steel, Recirculation Sys Piping at BWR Flants " Svc list encl
 DEYOUND, R C Director's Office, Office of Inspection and Enforcement B2/10/14 Consolidated Edison Co of New York
 115pp 15B10 125 24X Fiche 50-000,82/10/14,8208190238
- A Periodic operating reports & related correspondence
- 8210120264 Forwards biweekly status rept of independent QA evaluation of Palo Verde Nuclear Opnerating Stations Units 1.2 & 3 for period 820711-24
 61MON-W A Torrey Pines Technology 82/10/04 TURLEY. K.L. Arizona Public Bervice Co. 15pp. 15652-278 24X Fiche 50-528,82/10/04. 8210120264
- 8210220198 Forwards "Independent OA Evaluation of Palo Verde Nuclear Generating Stations Units 1,2 & 3," Biweekly Status Rept 7 for period ending 821008 SIMOUNH A Torrey Pines Technology 82/10/18 TURLEY, K L Arizon, Public Service Co 1p 15776 2[1 24X Fiche 50-528, 82/10/18, 8210220198
- --8210220244 "Independent OA Evaluation of Palo Vorda Nuclear Generating Stations Units 1.2 & 3." Biweekly Status Rept 7 for period ending 821008 # Torrey Pines Technology 82/30/18 14pp 15776 212 24X Fiche 50-528.82/10/18
- S Reportable occurrences, LERs & related correspondence
- 8210070391 Interim Deficiency Rept DER 82-43 re improperly crimped termination lugs on Comstp main control penels Initially reported on 820813 Extensive investigation & evaluation underway Final rept expected by 821212

 VAN BRUNT.E E Arizona Public Strvice Co 82/09/09 STERNBERO, D M Division of Resident, Reactor Project & Engineering Programs Spp 15663 343 24x Fiche 50-529, 82/09/09, 8210070391
- 8210070229 Requests add1 time to submit Final Deficiency Rept DER 8P-9 re thermowells in diesel generator lube oil sys by Gooper Energy not procured to ASME code Initially reported on 820316 info should be finalized by 821116 VAN BRUNT.E E Arizona Public Service Co 82/07/15 STERNBERO, D M Division of Resident, Reactor Project & Engineering Programs 2pp 15634 281 24X Fiths 50-528.82/09/15,82/0070229
- 8210070320 Final deficiency rept re weld procedure not prequalified by Ametek-Straia for reactor hot leg pipe stops Initially reported on 820514 Review of documentation revealed no further deviations I tem not reportable per 10CFRSO 55(a) VAN BRUNT, E E Arizone Public Service Co 82/09/15 STERNBERG, D M Division of Resident, Reactor Project & Engineering Programs 3pp 15634 114 24X Fiche 50-526,82/09/15,8210070320
- 8210070339 Interim Deficiency Rept DER 82-45 re unqualified motor operators installed w/C-E/Borg-Marner safety injection system valves initially reported on 820826 Motor operators returned to mfg for mod Next rept expected by 821117

 VAN BRUNT,E E Anizona Public Service Co 82/09/15, 8YERNBERG,I) N Division of Resident, Reactor Project & Engineering Programs Spp 15634 068 24X Fiche 50-528,82/09/15,8210070339
- 8210130495 Finel deficiency rept re low pressure safety injection & containment spray pump casing hold-down boilts under-torqued Condition determined not regortable per 10CFRSO 55(e) VAN BRUNT, E E Arizona Public Service Co 82/09/29 STERNBERG, D M Division of Resident, Reactor Project & Engineering Programs. 4pp 154882 145 24X Fiche 50-529,82/09/29.8210130495

- 8210130544 Revised interim deficiency rept re Pullman pipe for main feedwater lines w/multiple linear indications or laminations Final rept will be submitted by 821123 VAN DRUNT,E E Arizona Public Service Co. 82/09/30 STERNBERG,D M Division of Resident, Reactor Project & Engineering Programs App 15692 283 24X Fiche 50-529,82/09/30,8210130544
- DOCKET STN-50-530 PALO VERDE NUCLEAR STATION, UNIT 3
- A Application/construction stage documents & correspondence
- 8210180308 Notifies that commitment re accuracy of calibr stds per Amend 9 Page 17 2-56 not acceptable Justification should be provided or 2nd & 3rd paragraphs should be revised MIRAGLIA.F J Licensing Branch 3 82/09/17 VAN BRUNT, E E Artiona Public Service Co 2pp 15746 355 24X Fiche 50-528.82/09/17.8210180308
- 8210120025 Discusses organizational arrangement for technical support of facility operation Updated arrangement should be provided by 821115
 KERRIGAN.J D Licensing Branch 3 82/09/23 VAN BRUNT.E E Arizona Public Service Co 2pp 19689 187 24X
 Fiche 50-528,82/09/23.8210120025
- 8210190243 Forwards draft final nonradiological protection plan Comments requested KERRIGAN,J D Licensing Branch 3 82/09/23 VAN BRUNT,E E Florida Power & Light Co 2pp 15746 243 24X Fiche 50-528,82/09/23,8210180243
- --8210180248 Draft final nurradiological environ protection plan + Licensing Branch 3 B2/09/23 13pp 15746 245 24X Fich: 50-528, 82/09/23, 8210180243
- 8210210026 Forwards request for addl info to complete review of "Probabilistic Rist Assessment of Tornado Missile Damage to Statson UHS." Bechtel Study 13-NS-108
 KERRIGAN, J D Licensing Branch 3 82/09/29 VAN BRUNT, E E Abizona Public Service Co 4pp 15782 197 24X
 Fiche 50-528.82/09/29,8210210026
- 8210060245 Forwards Revision 1 to "Pump & Valve Inservice Testing Program, Palo Verde Nuclear Generating Station" VAN BRUNT, E E Artiona Public Service Co 82/10/01 NOVAK, T Division of Licensing 2pp 15620 243 24X Fiche 50-528, 82/10/01. 8210060245
- --B210060247 "Pump & Valve Inservice Testing Program,Palo Verde Nuclear Generating Station." Revision 1 Anisona Public Service Co B2/08/17 179pp 15620 245 24X Fiche 50-526,82/10/01.8210060245

- 8210280057 Advises that util will provide comments on draft environ protection plan by 821129
 VAN SRUNTIE E Arizona Public Service Co 82/10/21 NOVAK. FM Assistant Director for Licensing Jp 15837 261 24X Fiche 50-528. 82/10/21. 8210280057
- 8210280139 Advises that util will respond by 821129 to NRC 820929 ltreschedule for resolution of remaining outstanding to confirmatory issues

 VAN BRUNT, E Arizona Public Service Co 82/10/21 DVAK, FH Assistant Director for Licensing 1p 15837 133 24X

 Ficha 90-528, 82/10/21,8210280139
- 0210280199 Forwards Proof of Svc for 821012 application to amend CPPR-141, CPPR-142 & CPPR-143 VAN BRUNT, E. E. Arizona Public Service Co. 82/10/21 Office of Nuclear Reactor Regulation, Director 3pp. 15837 001 24X Fiche 50-528, 82/10/21, 8210280199
- 8210270211 Forwards proposed amended pages to FSAR Section 6 2 L. providing Type C testing of valves associated w/Containment Penetrations 44.47 & 77 using air Affidavit encl
 VAN BRUNT, E E Arizona Public Service Co 82/10/22 NOVAK, 7 M
 Assistant Director for Licensing 17pp 15829 318 24X
 Fiche 50-528, 82/10/22, 8210270211
- E NRC Safety Evaluation Report (SER). suppls & correspondence
- 8210210500 Forwards SER, Suppl 3 to OL application W/o ent] KERRIOAN, J D Licensing Branch 3 82/09/23 VAN BRUNT, E E Arizona Public Service Co 3pp 15782 263 24X Fiche 50-528. 82/09/23, 8210210500
- E210060006 SAFETY EVALUATION REPORT RELATED TO THE OPERATION OF PAID VERDE NUCLEAR GENERATING STATION, UNITS 1.2. AND 3 Docket Nos \$0-528,50-529, And 50-530 (Arizona Public Service Company, et al.)

 # Office of Nuclear Reactor Regulation, Director NUREO-0857 501 82/09/30 38pp Available at NRC 44 75 15636 268 24X Fiche 50-528,82/09/30,8210060006
- 8210190315 Advises that position re SER, Section 13 1 2 3 concerning operations superintendent not filled Resume will be forwarded to NRC when position is occupied VAN BRUNT.E E Arizona Public Service Co 82/10/04 NOVAK, I II Division of Licensing 2pp 19742 144 24X Fiche 50~526, 62/10/04, 8210190315
- B210280274 Informs of design mods incorporated into listed drawings to provide two devices in series for adequate primary & backup protection of circuits Mods close SER confirmatory item discussed in Section 8 4 3

 VAN BRUNT, E.E. Ariiona Public Service Co. B2/10/25 NOVAK, T.H. Assistant Director for Licensing 2pp. 15838-356 24X

 Fichs 50-528, 82/10/25, 8210280274
- G Adjudicatory correspondence
- 8210130417 Notice of corrections to Joint Applicants reply to PI Hourikan proposed findings of fact & conclusions of law BISCHOFF, CA Joint Applicants-Palo Verde BISCHOFF, CA Bischeff, CA 82/10/05 2pp 15680 224 24X Fiche 50-528,82/10/05, 8210130417
- --8210130486 Corrected pages to Joint Applicants reply to Pt Houriban proposed findings of fact & conclusions of law Certificate of Svc entl
 4 Joint Applicants-Palo Verde 82/10/05 15pp 15680 226 .4;
 Fichm 50-528,82/10/05,8210130417
- B210150247 Forwards Suppl 3 to SER W/o encl DENEY, L 8 Hearing Branch 3 82/10/13 LAZO, R M , COLE, R F , CALLIHAN, D Atomic Safety and Licensing Board Panel Ip 15704 357 24X Fiche 50-528.82/10/13,8210150247
- 8210150499 Memorandum of law supporting West Valley Agricultural Protection Council, Inc petition to intervene Bubstantial new info only recently discovered Certificate of Svc encl BERLIN, K Affiliation Unknown, BERLIN, K Affiliation Unknown 82/10/13 Atomic Safety and Licensing Board Panel 24pp 15713 209 24X Fiche 50-528,82/10/13,8210150499
- --8210150512 Petition of West Valley Agricultural Protection Council,:
 to intervene, request for preparation of supplemental or
 revised EIA & request for reopening record Certificate of
 Svc encl
 BERLIN.K Affiliation Unknown BERLIN.K Affiliation Unknown
 B2/10/13 Atomic Safety and Licensing Board Panel 300pp
 15713 233 24X Fiche 50-528, 82/10/13.8210150499

DOCKETED ITEMS

- G210150474 Notices of appearance in proceeding Certificate of Svc Bicl BERLIN.K., GERMIN.E F., LASOTA, J. Affiliation Unknown B2/10/14 App. 15703 043 24X Fiche 50-528.82/10/14.8210150474
- 8210270171 Motion for 2-wk extension of time to answer West Valley Agricultural Protection Council, Inc 821013 petition to intervene Complete potition not received Certificate of Svc encl BISCHOFF, C. A. Joint Applicants-Palo Verde BISCHOFF, C. A. 82/10/22 Atomic Safety and Licensing Board Panel Spp 15822 347 24X Fichs 50-528 82/10/22.82102/0171
- 9210290297 Response of Nest Valley Agricultural Protection Council to Join' Applicants 821022 motion for extension of time to answer Council petition to intervene Tenday extension should be granted Certificate of Svc encl BERLIN. Affiliation Unknown 82/10/26 Atomic Safety and Licensing Board Panel 6pp 15853 160 24X Fiche 50-528,82/10/26,6210290297
- 8210280262 Order granting Joint Applicants 821022 motion for extension or time to answer West Valley Agricultural Protection Council Inc 821014 petition to intervene Joint Applicants have 2 wts after svr of complete petition to file answer LAZOR M Atomic Safety and Licensing Board Panel 82/10/27 Joint Applicants-Palo Verde 2pp 15837 310 24X Fiche 50-528.82/10/27.8210280262

M Antitrust correspondence

- 8210040292 Forwards page inadvertently omitted from first response to requirements contained in Reg Ouide 9 3
 VAN BRONTLE E Arizona Public Service Co 82/09/28 Office of Nuclear Reactor Regulation, Director 2pp 15587 138 24X
 Fiche 50-528.82/09/28.8210040292
- --8210040305 Forwards Salt Rive: Project Agricultural Improvement & Power District & AZ Public Svc Co revised responses to requirements contained in Reg Guide 9 3 Corrected copy VAN BRUNT, E E Aricona Public Service Co 82/05/10 Office of Huclear Reactor Regulation, Director 7pp 1558/ 140 24X Fiche 50-528,82/07/28,8210040292
- @ Inspection reports, IE Bulletins & correspondence
- \$210070210 Provides corrected supplemental response to 1E Bulletin BI-02. "Failure of Gate Type Valves to Close Against Differential Pressure" No Westinghouse Electro Motor Div gate valves used in plant design Twenty-five manhours used VAN BRUNT, E Arizona Public Service Co 82/10/01 ENGELKEN, R II Region 5, Office of Director 2pp 13634 264 24X Fiche 50~528, 82/10/01; \$2210070210
- 8208190233 IE Info Notice BO-35, Suppl I, "Leaking & Dislodged I-12% Implant Seeds ' Svc list enc! C088, I Division of Fuel Facilities, Materials & Safeguards 82/10/06 Consolidated Edison Co of New York 66pp 15761 2hD 244 Fichs 50-000 82/10/06.0208190233
- 8210250351 Forwards IE Insp Repts 50-528/82-25.50-529/82-09 & 50-530/82-10 on 820830-0903 & notice of violation SERN/BERG. D M Division of Resident, Reactor Project & Engineering Programs 82/10/08 VAN SRUNT, E C Artiona Public Service Co 2pp 15790 026 24X Fiche 50-528.82/10/08.8810250351
- --B210250375 IE Insp Repts 50-528/82-25,50-529/82-09 % 50-530/82-10 un 820830-0903 Moncampliance noted 29 inches of weld metal found missing from control room panels & defective instrument repts not prepared ECKHARDT.J H , HERNANDEZ, C , YOUNG T Division of Resident, Reactor Project & Engineering Programs 82/10/07 6pp 15790 030 24X Fiche 50-526,82/10/08-8210250351
- 8210280368 Forwards IE Insp Repts 50-528/82-26.50-529/82-10 & 50-530/82-(1 on 820713-0903 No noncompliance noted STERNBERO,D M Division of Resident, Reactor Project & Engineering Programs 82/10/13 VAN DRUNT,E E Arizona Public Service Co 2pp 15845 155 24X Fiche 50-528-82/10/13-8210280348
- --8210280372 IE Insp Repts 50-528/82-26.50-527/82-10 & 50-530/82-11 en 820713-0903 No noncompliance noted Mayor areas inspected constactivities associated wygrouting of temporary underground piping & containment post-tensioning VORDERBRUEGGEN, YOUNG.T Division of Resident. Reactor Project & Engineering Programs 82/10/07 12pp 15848 137 24X Fiche 50-528.82/10/13.8210280368

- 820819023B IE Bulletin 82-03, "Stress Corrosion Cracking in Thick-Wall, Large-Diameter, Stainless Steel, Recirculation Sys Piping at BNR Plants " Svc list enct DEYOUNO, R C Director's Office, Office of Inspection and Enforcement 82/10/14 Consolidated Edison Co of New York 11500 15810 125 24X Fiche 50-000, 82/10/14.820819023B
- R Periodic Operating reports & related correspondence
- 8210120264 Forwards biweekly status rept of independent QA evaluation of Palo Verde Nuclear Generating Stations Units 1.2 & 3 for period 820711-24
 SIMON.W A Torrey Pines Technology 82/10/04 TURLEY, K L. Arizon: Public Service Co 15pp 15652 278 24X Fiche 50-528.82/10/04, 8210120264
- 8210220198 Forwards "Independent GA Evaluation of Palo Verde Nuclear Generating Stations Units 1.2 & 3," Biweekly Status Rept 7 for period ending 821008 SIMON, WA Torrey Pines Technology 82/10/18 TURLEY, K.L. Arizona Public Service Co. ip 15776-211 24X Fiche 50-528,82/10/18.
- --B210220244 "Independent BA Evaluation of Palo Verde Nuclear Generating Stations Units 1.2 & J." Biweekly Status Rept 7 for period ending 821008 * Torrey Pines Technology 82/10/18 14pp 15776 212 24X Fichs 30-528, 82/10/18, 8210220198
- S Reportable occurrences, LERs & related correspondence
- 8210070219 Interim Defictency Rept DER 82-44 re ITE-Gould load ctrs w/improperly crimped ampere termination lugs Initially reported on 820813 Bechtel pursuing matter w/Gould Brown Boveri to determine disposition Next rept by 821207 VAN BRUNT, E E Ariona Public Service Co 82/09/09 BIERNBERG, D M Division of Resident, Reactor Project & Engineering Programs 2pp 15637 163 24X Fiche 50-530,82/09/09,8210070219
- 8010070227 Requests add1 time to submit Final Deficiency Rept DER 82~9 re thermowells in diosel generator Tube oil sys by Cooper Energy not procured to ASME code Instituting reported on 820316 Info should be finalized by 821116 VAN BRUNT, E. E. Arizona Public Service Co. 82/09/15 STERNBERG, D. M. Division of Resident. Reactor Project & Engineering Programs . 2pp 15634 281 24X Fiche 50-528.82/09/15.8210070229
- 8210070320 Final deficiency rept he weld procedure not prequalified by Ametek-Straza for reactor hot leg pipe stops initially reported on 820514 Review of documentation revealed no further deviations Item not reportable per IOCFR50 55(e) VAN BRUNI, E.E. Aritona Public Service Co. 82/09/15 STERNBERG, D.N. Division of Resident. Reactor Project & Engineering Programs 3pp 15634 114 24X Fiche 50-528,82/09/15.8210070320
- 8210070339 Interim Deficiency Rept DER 82-45 re unqualified motor operators installed w/C-E/Borg-Warner safety injection systyles Initially reported on 820826 Motor operators returned to mfg for mod Next rept expected by 821117

 VAN BRUNT, E E Arizona Public Service Co 82/09/15 STERNBERO, D M Division of Resident, Reactor Project & Engineering Programs 3pp 15634 068 24X Fiche 50-528,82/09/15,8210070339
- 8210130444 Final Deficiency Rept DER Bi-55 re const svc water line leak under ewiliary bidg Initially reported on 820105 Foundation of auxiliary bidg not adversely affected Ali temporary air, water & gas lines near Category I bidgs taken out of svc VAN BRUNT.E E Aritona Public Service Co. 82/07/29 STERNBERG.D M Division of Resident, Reactor Project & Engineering Programs App 15682 015 24X Fiche 50-530.82/07/29.8210130446
- B210130491 Interim deficiency rept to Pullman 24-inch pipe spools winternal surface indications violating min wall thickness Initially reported on 820831, Bechtol Engineering investigating cause Final rept will be submitted by 821119 VAN DRUNT, E. E. Arizona Public Service Co. 82/09/30 STERNBERG, D. M. Division of Resident, Reactor Project & Engineering Programs. App. 15682 115 24X Fiche 50-530,82/09/30,8210130491
- B210130544 Revised interim deficiency rept to Pullman pipe for main feedwater lines w/multiple linear indications or laminations Final rept will be submitted by B21123 VAN ORUNT, E E Ariona Public Service Co 82/09/30 STERNBERO.D M Division of Resident, Reactor Project & Engineering Programs 4pp 15482,283 24% Fiche 50-529.82/09/30.8210130544

DOCKET 50-537 CLINCH RIVER BREEDER REACTOR

- A Application/construction stage documents & correspondence
- 8210120103 Addl response to FDIA request for nine categories of records generated by present HRC Commissioners, primarily Chairman Palladino & Commissioner Roberts & White House Forwards App B documents

 FELYON, J H Division of Rules and Records 82/07/12 UDELL, R A Critical Mass Energy Project 3pp 15690 117 24x

 Fiche 50-000, 82/07/12, 8210120103
- --8210120140 Agrees w/recommendation that Commission adopt modified DUF schedule circulated at 811216 meeting Forwards changes to schedule for Commission review of Section 50 12 request for CRBR ROBERTS.T M Commissioners 81/12/21 PALLADING.N , GILINSKY.V , BRADFORD.J Commissioners 2pp 15690 133 24X Fiche 50-000,82/07/12.8210120103
- --8210120143 Db jects to action outlined in Commissioner Gilinsky 8±12.21 memo rs CRBR licensing exemption RDBERTS.T M Commissioners 81/12/22 PALLADINO.N GILINSKY.V . BRADFORD.J Commissioners 2pp 15690 135 24X Fiche 50-000,82/07/12.8210120103
- 8210070029 Partial response to FDIA request for documents re CRBR E15 & all comments, evaluations & documents from BNML re EIS Forwards documents listed in App A FELTON, J M Division of Rules and Records 82/07/16 WEISS, E R Harmon & Weiss 8pp 15648 004 24X Fiche 50-537, 82/07/16, 8210070029
- --B210070039 Forward: updated schedule for CRER environ review HURT, D. NRC No Detailed Affiliation Given 82/04/29 MULLEN.8. GASKIN, C. JUNES, B. NRC No Detailed Affiliation Given 2pp 15448 014 24% Fiche 50-537,82/07/16,8210070029
- --8210070070 Discusses lead ofc responsibilities for CRBR fuel cycle environ review Dverall schedule should be established for NMSS for inclusion utexecutive operating plan DAVIS,J G NRC No Detailed Affiliation Given 82/02/12 CUMNINGHAM, R E NRC NO Detailed Affiliation Given 2pp 15648 028 24X Fiche 50-537,82/07/16.8210070029
- --B210070071 Advises that continued delay of DBE environ input will result in schedule compression for CRBR fuel cycle environ review DAVIS-J O Office of Nuclear Material Safety & Safeguards, Director B2/02/12 DENTON, H R Office of Nuclear Reactor Regulation, Director 10 1548 030 24X Fiche 50-537, 82/07/14, 8210070029
- --B210070084 Requests contentions for CRBR licensing which have implications in areas of fuel cycle, safeguards & waste mgt discussed during B10906 meeting LONENBERO, H Office of Nuclear Material Safety & Safeguards, Director B1/10/09 CHECK.P S Clinch River Breeder Reactor Program Office 3pp 15648 033 24X Fiche 50-537, 82/07/16, 8210070029
- --8210070089 Ack receipt of 811020 memb re CP review schedule Severe problems in meeting deadlines anticipated due to time constraints & personnel limits LUMENBERO. H Office of Nuclear Material Safety & Safeguards, Director Bi/10/23 CHECK.P S Clinch River Breeder Reactor Program Office Zpp 15548 036 24X Fiche 50-537.82/07/16.8210070029

review of CP application activities, in response to inte schedule dates impossible ""structure of internat

> led Affiliation Given 81/11/02 filiation Given 2pp 15648 03B 2027

- --82[0070103 Advises that R Browning will be contact for Div of Waste Mgt & T Johnson & R Boyle will provide technical review for low level & high level waste matters re CRBR fuel cycle review MARTIN. J B NRC No Detailed Affiliation Given 82/02/10 CUMNINGHAM. R NRC No Detailed Affiliation Given Ip 15448 047 24X Fiche 50-537. 82/07/16. 8210070029
- --82(0070118 Provides info re resources allocated to CRBR as of 8.ºu/3|
 in response to 8205t1 request
 BROWN.R S Program Support Branch 82/05/12 WINNINGHAM, J
 Resource Analysis Branch ip 13648 052 24X
 Fiche 50-537, 82/07/16. 8210070029
- ---8210070151 Provides guidance to standardize resumes of starf membe consultants who may participate in environ review hearings

 J Dee educational & prof qualifications encl

 LOMENBERO.H Office of Nuclear Material Safety &
 Safeguards. Director 82/03/26 BROWNING.R E Division of Hart

 Management DUBE.R J Division of Safeguards MACRDINALD.(1

 Transportation Branch 2pp 15648 194 24% Fiche 50-537.
 82/07/16.82/10070029
- --8210070157 Discusses resource utilization for CRDR fuel cycle invireview Projected expenditures for remainder of FY82 provided LOHENDERO.H Office of Nuclear Material Safety & Safeguards.Director 82/07/02 DAVIS.J & Office of Nuclear Material Safety & Safeguards.Director 2pp 15648 198 24X Fiche 50-537,82/07/16.8210070029
- --8210070163 Provides highlights for wk ending 820618 re CRBR fun) i environ review Minor corrections to FES update submitted to CRBR program ofc LONEMBERG. H. Office of Nuclear Material Safety & Safeguards. Director 82/06/24 DAVIS, J. G. Office of Nuclear Material Safety & Safeguards, Director Ip 15648 200 24X Fiche 50-537, 82/07/16, 8210070029
- --8210070179 Provides highlight items for CRBR fuel cycle environ it for uk ending 820604 Discovery items requiring input received on 820604 CURNINGHAM.R E Division of Fuel Cycle & Material Safety 82706/09 DAVIS, J G Office of Nuclear Material Safety & Safeguards, Director 1p 15448 232 24X Fiche 50-537.82/07/1/8210070029
- --B210070182 Provides highlight items to CROR fuel cycle environ reafor uk ending 820521 Callection & resolution of NRC comments scheduled for 820601
 CUMNINOHAM.R E Diffice of Nuclear Material Safety & Bareguards, Director 82/05/27 DAVIG.J C Diffice of Nuclear Material Safety & Saf
- --8210070222 Provides highlight items re CRBR fuel cycle environ rul for uk ending 820423 Final version of GRIGEN 2 Code received from ORNL LONENBERG, H. Office of Nuclear Material Safety & Safeguards, Director 82/04/29 CUNNINDHAM, R. Office of Nuclear Material Safety & Safeguards, Director 1, 15648 248 248 Fiche 50-537, 82/07/16,8210070029
- --8210070225 Submits schedule for CRDR fuel cycle environ review LGNENBERG.H Office of Nuclear Material Safety & Safeguards.Director 82/04/27 ROUSE,L C Advanced Fuel & typel Licensing Branch MACDONALD.C E Transportation Branch DUBE.R J Division of Safeguards 2pp 18448 250 24X Fiche 50-537,82/07/16,8210070027
- --B210070251 Forwards revised ORIGEN 2 outputs for CRBR LOWENBERO.H Office of Nuclear Material Bafety & Safeguards. Director 82/04/23 ROUSE,L C Advanced Fuel & Up Fuel Licensing Branch MACDINALD.C E Transportation Branch PAGE.R G Uranium Fuel Licensing Branch 1p 15648 252 JAX Fichs 50-537, 82/07/16, 8210070029
- --8210070253 Forwards revised ORIGEN 2 output for CRDR Averaging procedures altered for agreement between flows & physical mass
 CROFF,A G Gas Ridge National Laboratory B2/04/20 LOHENBLR
 Office of Nuclear Material Safety & Safeguards, Director 13\$4
 13648 253 24% Fiche 30-337.82/07/16.8210070029
- --8210070256 Forwards backup calculations for Table D 4, CRBR fuel c suppl Related info entl HILL.O F Battelle Memorial Institute, Pacific Northwest Laboratory 82/06/09 LOMENBERG, H Office of Nuclear Materia Bafety & Bafeguards. Director 8dpp 15648 266 24X Fiche 50-537, 82/07/16/ 8210070029

- --B210070259 Provides highlights to CROR fuel cycle environ review for ut ending 820416 Revised ORIGEN 2 Code prepared by ORNL LONENDERG, H. Office or Nuclear Material Safety. Safequards, Director 82/04/22 DAVIS-J G Office of Nucleur Material Safety 5 Safequards, Director ip 15648-352 24X Fiche 50-537, 82/07/16.8210070029
- --8210370266 Clarifies responsibility for dose assessment calculation for CRSR activities LONENBERG H Office of Nuclear Material Safety & Sareguards, Director 82/09/12 CONNEL F J Radiological Assessment Branch MILLS.N A Human Factors Engineering Branch ROUSE L C Advanced Fuel & Spont Fuel Licensing Branch Lp L5549 087 24/ Fiche 50-537.02/07/16.8210070029
- --Eclog70273 Provides clarification of DQE Amend XIII submittals per 820323 telcon Full Pu ' II throughputs used as basis for radioactive release valuations for conservative estimation of erfluents

 ig fNDERG. H. Office of fuctor Material Safety *
 Sarejuards.Darketor 82/03/25 ROUSE.L. C. Advanced Fuel & Spint Fuel Licinsing Branch (MCDONALD.C E. Transportation Branch DICE, R. J. Davision of Safeguards | p. 15649 009 24X
 Fiche 50-537, 82/07/16, 8210070029
- -TIO070276 Notification of 820414-15 meeting w/BNML in Bethosda, ND to discuss contract under FIN 8-2477 Discussion will include preliminarly source term data 3 initial ORIGEN 2 data LOWENGERG H Office or Nucleor Material Safety 7. Saregoards, Director FIN 8-2177 82/03/23 ROUSE, L.C. Advanced Fuel 'Spent Fuel Litensing Branch MACDONALD, C.E. Transportation Branch DUBF, J. Division of Sareguards ip 15649-090 24X Fiche 50-937.82/07/16 8210070029
- --PJ10070JM2 Advises that proposal submitted by BNWL meets objectives of statement of work for review & assessment of CRDR environ impact towerHERG. H. Office or Nuclear Material Safety & Safeguards Director FIN 0-2477 82/03/19 GRESHAM, J. Division of Fuel Cycle & Naterial Safety by 15449 092 24X Fiche 50-537,82/07/(4,82)0070029
- -8210070285 Provides quidance for designation or specialists for environ review proceeding List of experts followed by individual statement of qualitirations must be propared (DUEFORREGIE OFFICE OF Nuclear Material Safety & Sareguards Director 82/03/19 BROWNING.R & Division of Watte Management DURF.R J Division of Safeguards MACDONALD.C & Transportation Branch Ppp 15647-073 24X Fiche 50-537, 82-07/16 B2100700-79
- --8210070.93 Submits schedule of meetings w/technical assistance contractor & DDC or LHBR environ review LONEMBERG.H Diffice or Nuclear Material Safety % Safeguards Director 82702723 ROUSELL C Advanced Fuel & Spint Fuel Licensing Branch MACDONALD.C C Transportation Branch DUSE.R J Division of Sareguards 1p 15649 100 24X Fich 50-537,82707716.8210070029
- --2/10070278 Confirms 62072, meeting w/DUF to review 620219 draft input to CRRR fuel cycle review LOIEMBERG.H. Office of Nuclear Material Safety & Sareguards. Director 62/02/23 ROUGE.L. C. Advanced Fuel & Spirit Fuel Licensing Branch MACDONALD.C E. Transportation Branch BUBE.R.J. Division of Safeguards 1p 15649 101 24% Fiche 50-537.82/07/16.8210070029
- ~-B210070701 Provides broad assessment of CRBR fuel cycle environ effects Amena XII fairly represents 50-yr dose commitments from fuel fabrication & reprocessing ROUSE:1. C. Advanced Fuel & Spent Fuel Licensing Branch B2/02/06 LOMENGERG. N. Office of Nuclear Material Safety & Safeguards, Director 1p 15449 102 24X Fiche 50-537,82/07/16. B210070027
- --8210070306 Provides results of review of DDE draft Amend XIII to CRIM fuel cycle environ review Addi info needed re data used as basis for DDE determination of environ impact AYER, J E MRC No Detailed Affiliation Given 82/02/20 LOMENBERG, M NRC No Detailed Affiliation Given 2pp 15449 103 24X Fiche 50-537, BZ/07/16, BZ10070029
- --8210070310 Forwards resumes of JE Ayer & AT Clark for CRBR fuel cycli environ review ROJSEL C Advanced Fuel & Spent Fuel Licensing Branch 82/03/31 LOMENBERG. H Office of Nuclear Material Safety & Safeguards. Director Spp 15649 105 24X Fiche 50-537.82/07/16. 8210070029
- 6207110033 FOIA request for documents by Science Applications. Inc for CRPR project including FES: site suitability rept & SER WEISS: ER Harmon & Weiss 82/07/26 FELTON. JM Division of RVIs and Records 1p 15597 264 24X Fiche 50-537.82/07/26.820710033

- 8208270699 Summary of 820723 meeting w/util,DDE & Project Mgt Corp in Bethesda.MD re review of CRBR probabilistic risk assessment in areas of success criteria for shutdown heat removal sys, logic & event trees & fault trees
 STARK.R M Clinch River Breeder Reactor Program Office 82/08/13
 Clinch River Breeder Reactor Program Office 4pp 14683 045 749
 Fiche 50~537,82/08/13,8208270699
- B210040343 Responds to FOIA request for all documents re work performed by Science Applications, Inc for CRBR project Forwards documents listed in App A FELTON, J M Division of Rules and Records B2/08/20 WEISS, E R Harmon & UB195 2pp 15597 265 24X Fiche 50-537, B2/08/20, B210040343
- --8210040346 Forwards draft itr repts for CRDR Tasks 1-A, 1-D & probabilistic risk assessment review plan Comments requested JOHNSON, B Science Applications, Inc. NRC-03-82-076 82/05/26 SILVER, H NRC No Detailed Affiliation Given 4pp (5597 26/24X Fiche 50-537, 82/08/20, 8210040343
- --8210040349 Advises that answers to NRDC interrogatories for CRBR review will be completed per 820609 tetron Plan & schedule submitted vDHNSDN, B Science Applications, Inc. NRC-03-82-096 82/04/10 SILVER, H. VRC No Detailed Affiliation Given 2pp 15597 271 244 Fiche 50-537, 82/08/20, 8210040343
- --8210040350 Confirms action item re risk reduction per 820607 telcon Info re diversity of CRBR heat transport sys encl LINER, RT Science Applications, Inc. NRC-03-82-096 82/04/ii IRC - No Detailed Affiliation Given 2pp 15397 273 24X Fiche 50-537,82/08/20,8210040343
- --8210040351 Forwards comments on applicant 820618 proposed probabilistic risk assessment plan Items addressed include content, resource allocation & phenomenological tasks JOHNSON, B. Science Applications. Inc. NRC-03-82-096 82/07/07 SPANO, A. NRC No Detailed Affiliation Given 3pp 15597 375 24% Fiche 50-537, 82/08/20, 8210040343
- --8210040355 Forwards questions for applicant re frequency of simultaneous loss of three main cooling loops, discussed during 820715 meeting times. Inc. NRC-03-82-096 (RC-03-82-096) SWIFT. J. NRC No Detailed Affiliation Given Rul 15597 278 24X Fichs 50-537.82/08/20.8210040343
- 8210060442 Responds to FDIA request for input to Chapter 7 & App J of FES & suppl to CRBR Documents listed in App A available in PDR App D documents completely withheld advice & aprilons (ref FDIA Exemption 5) FELTON.J H Division of Rules and Records 82/08/24 WEISS.L R Harmon & Weiss App 15636 040 24% Fiche 50-537.82/08/24.
- --B210060451 Forwards list of transients within 10 miles of CROR per 820217 request FERREIL.C NRC No Detailed Affiliation Given 62/02/17 THADAMI,M NRC No Detailed Affiliation Given 3pp 15636 12/24X Fiche 50-537.82/08/24.8210060442
- --B210060453 Submits representative meteorological data for input 111th CRAC computer code for CRBR site SPICKLER. I Accident Evaluation Branch G2/04/13 PASEDAG, W Accident Evaluation Branch 19 15636 130 24X Fiche 50-537, B2/08/24, B210060442
- --8210060455 Forwards site description of CRBR per 820513 request FERRELL.C NRC No Detailed Affiliation Given 82/05/13 THADAMI,M NRC No Detailed Affiliation Oiven 19pp 15436 134 24X Fiche 50-837, 82/08/24,8210060442
- --B203190016 Forwards draft statement of work for technical assistance contract re-probabilistic assessment & reliability program for comment by 820305 Detailed breakdown of FV82,FV83 & FV84 time required for wach subtask forthcoming THADARI, A Reliability & Risk Assessment Branch 82/03/03 SPEI8,T NRC No Detailed Affiliation Given 13pp 15636 152 24X Fiche 50-537,62/09/24,6210060442
- B2101501B6 Forwards response to NRC 820407.0514 & 0609 ltrs re request for add1 info Responses to Questions C5 421 26.43.51 & 53 & C8 760 162.164 & 176 will be incorporated into future FBAR amend LONGENECKER, J. Energy, Dept of, Clinch River Breeder Reactor Plant 82/08/24 CHECK, P. S. Clinch River Breeder Reactor Program Office 39pp 15707 195 24X Fiche 50-537.82/08/24.8210150186

- 9208290086 FOLA request for rept to EPA. "Pu & Human Tissues re Smoking. Age. Residence Near Rocky Flats & Eastern CO " JOHNSON, C Affiliation Unknown 82/09/01 Office of Administration Ip 15636-207 24X Fiche 50-537.82/09/01, 8208290886
- 82100&0454 Summary of 820915 meeting w/applicants in Bethesda.MD re review of thermal margin beyond design basis & seismic margin beyond design basis issues BECKER,R A Clinch River Breeder Reactor Program Office 82/09/20 Clinch River Breeder Reactor Program Office 4pp 15636-221-241 Fiche 50-537,82709/20.8210060634
- 8210050477 Comments on CRBR probabilistic risk assessment program plan submitted in 820621 ltr Plan responsive to NUREG-0718, Item III B 8 requirements Dotails encl CHECK.P S Clinch River Breeder Reactor Program Office 82/09/2.J LONGENECKER.J Energy. Dept of. Clinch River Breeder Reactor Plant App 13626 257 24X Fiche 30-537.82/09/23.8210050477
- 8210120445 Notification of 821004-08 meetings w/DDE.Project Mgt (urp & TVA in Bethesda.MD to discuss direct heat Temoval sys STARK.R M Clinch River Breeder Reactor Program Office 82/09/2/CHECK.P S Clinch River Dreeder Reactor Program Office 3pp 15671 183 24% Fiche 50-537,92/09/27-8210120445
- B210040251 Confirms that microfiche containing CACECO input/output for extreme todium-concrete penetration case & explanatory info has been delivered to CRBR program of LONGENECKER. J Energy. Dept of 82/09/28 CHECK.P S Clinich River Breeder Reactor Program Office ip 15581-357 24X Fiche 50~537,82/09/28.8210040251
- 8210040304 Forwards TN Historical Commission 820708 ltr to TVA concurring that archelogical & historical field survey is not warranted prior to transmission line tower const LONGENECKER. J Energy Dept of. Clinch River Breeder Reactor Plant 82/09/28 CHECK. P 8 Clinch River Breeder Reactor Program Office 2pp 15587 149 24X Fiche 30-537.82/09/28,8210040304
- 8210130069 Notification of 821005 meeting w/BDE.Project Hgt Corp & IVA in Bethesda.MD to discuss working structural & seismic review STARK.R H Clinch River Breeder Reactor Program Office 82/09/28

STARK, R M Clinck River Breeder Reactor Program Office 82/09/26 CHECK, P S Clinck River Breeder Reactor Program Office 3pp 15696 264 24X Fiche 50-537,82/09/28,8210130059

- B210040167 Forwards 1tr rept in support of CRBR thermal margins beyond design base instrumentation development per DDE 820514 submittal re future info for review of CRBR LONGENECKER. J. Emergy, Dept of, Clinch River Breeder Reactor Plant B2/09/29 CHECK.P S. Clinch River Breeder Reactor Program Office 11pp 15582 034 24X Fiche 50-537, B2/09/29, B210040167
- 8210060426 Responds to FDIA request for rept to EPA, "Pu & Human Tissues re Smoking, Age. Residence Near Rocky Flats & Eastern CO" & related documents No info available Forwards request to EFA for response FELTON. J M Davision of Rules and Records \$2,09/29 JOHNSON.C J Affiliation Unknown ip 19636 208 24% Fiche 50-537,82/09/29,8210060426
- 8210060217 Forwards responses to Questions CS 421 27.30.31.34 & 58 to ESF. Instrumentation & control drawings for safety-related sys & adequacy of reactor vessel level gauges per 820409 request Responses will be incorporated in future PSAR amend LONGENECKER.J Energy. Dept of: Clinch River Breeder Reactor Plant 82/10/04 CHECK.P.S Clinch River Breeder Reactor Program Office.

- B210130311 Summarizes B20928 meeting w/NRC to CRBR leak detection sqr for primary coolant boundary Test results encl LONGEMECKER. J Energy, Dept of B2/10/07 CHECK.PS (linch River Breeder Reactor Program Dffice ip 15678 135 24X Fishe 50-537, B2/10/07. B210130311
- --8210130315 "Liquid Metal to Gas Leak Detection Instruments" HATLIN.E. WITHERSPOON, J. JOHNSON, J. L. Rockwell International Corp. 82/10/07 15pp 15678 136 24% Fiche 50-597, 88/10/47, 9210130311
- 8210220023 Notification of 821019 meeting w/DDC, Project Mgt (*nrp & IV. in Rethesda, MD to review control room design STARK, R M Clinch River Breeder Reactor Program Office 12/10/17 CHECK, P S Clinch River Breeder Reactor Program Office 13pp 15786 306 24X Fiche 50-537, 82/10/14, 8210220023
- 8210210022 Forwards summary of 820717 ASME Code comparison working meeting w/CRBR project of class. Westinghouse & William of 1774 ASME Code for design of containment vessel LONGENECKER. J Energy, Dept of 82/10/15 CHECK, P 5 (1104 h River Deceder Reactor Proglam Office 14pp 15765.15)8 ,4xx Fiche 50-537,82/10/15,8210210022
- B210210273 Forwards summary of CRUR/NRC hypothetical core distuplinated accident energetics B20921 meeting replenum fission gas compaction, role of structures in energetic termination to fuel removal & energetic potential LONGENECKER J Energy, Dept of B2/19/15 CHECK,P & Cliub River Breeder Reactor Program Office Slpp 15766-17H Max Fiche 50-537, B2/10/15, B210210273
- B210260302 Forwards add1 info resulting from Mechanical Engineering Branch 820908-09 meetings & response to Items 17,19,32,4,68 Responses to Items 3,4,34,49,51 & 54 will be provided by 821025 LONGENECKER, J. Energy. Dept or 82/10/20 CHCCK Pl. (1)11h River Breeder Reactor Program Office 6pp 16072 297 ,4% Fichs 50-937,82/10/20,9210260302
- 82)0260168 Summarizes 821019 control room philosophy exchange merting Viewgraphs encl LONGCNECKER, J Energy, Dopt of 82/10/21 CHECK.P () (11112). River Breeder Reactor Program Office 38pp 15004 276, 24x Fiche 50-537.82/10/21.8210260168
- 8210260401 Forwards summary of Decay Heat Removal Theimal Hydiaulsva B21020 meeting w/NRC re-resolution of items concerning CRRR project LONGENECKER J Energy, Dept of B2/10/21 CHCCK, I is (11377 h River Dreeder Reactor Program Office Spp 13805 Pd.) 144 Fitch 50-537,82/10/21.8210260401
- 8210280496 Notification of B21028-27 meetings w/util.DOL & Prinje to Corp in DethesdorMD to discuss matls & mechanical issues, including test before break & leak detection STARK.R M Clinch River Breeder Reactor Program Office (DECK.P S Clinch River Breeder Reactor Program Office (July 1986) 052 24% Fiche 50-537.82/10/22,8210280493
- B. Utility Preliminary Safety Analysis Report, amends
- 8209300353 Forwards Amend 71 to PSAR Amend includes responses to requests for add1 inforrevisions to Chapter 7, "Instrumentation & Controls," Sections ITE & 171 & other updates & revisions Certificate of Svc encl LONGENECKER, J Energy, Dept of, Clinch River Oreeder Reactor #101 & 82/09/30 CHECK, P & Clinch River Breeder Reactor #101 & 4pp 15560 197 24X Fiche 50-537,82/09/30,8209300353
- ---8209300355 Amend 71 to PBAR

 + Clinch River Dreader Reactor Program Office 82/07/,KO 5a.'s

 | 1550 201 24X Fichs 50-537,82/09/30.8209300353
- 8210130246 Forwards Certificate of Svc confirming distribution of to PSAR LONGENECKER. J Energy, Dept of B2/10/07 DENTON, H R 188186 Nuclear Reactor Regulation, Director 2pp 15676 010 24x Fich 30-537, B2/10/07, B210130246
- C Utility Environmental Report (ER), amends & correspondence
- 8210070029 Partial response to FOIA request for documents re CREM at all comments, evaluations & documents from BNWL re EIB Forwards documents listed in App A FELTON. J M Division of Rules and Records 82/07/16 WEIGN. E WHarmon & Weiss 8pp. 15648 004 24X Fichs 50-537.82/07/16.

- -8210070128 Forwards drart Amend XIII to CRDR environ rept, consisting of rinor editorial changes
 LONEUBERG H Ortice of Nuclear Haterial Safety & Safeguards, Director 82/02/24 ROUSE, L C Advanced Fuel & Spunt fuel Licensing Branch MACDOMALD C E Transportation Branch MUSER & Division of Sareguerds 48pp 15648 136 24X
 Fiche 50-537,82/07/16,82100/0029
- --B210070131 Forwards add1 input to Amend XIII to CRBR environ rept to sociaeconomic impact N/o encl LONEMBERG. H. Office of Nuclear Material Safety & Sareguards. Director 82,04/26 ROUSEL C., MACDONALD, C.E., DUBE R. J. NRC No Detailed Afriliation Given 2pp 15648 184 247 Fichs 50-537. R2/07/16 8210070029
- --8210070134 Requests review of DGE revised environ rept. Section 5 / 1 re
 fuel cycle Revision includes detailed explanation of method
 used to calculate doses from transportation M/o encis
 LONENDERG: H Dffice or Nuclear Hateria! Safety &
 Safeguards: Director 82/03/15 ROUSE: L C Advanced Fuel & Spont
 Fuel Licensing Branch MACDDNALD: C E Transportation Branch
 DJGE: R J Division of Safeguards 2pp 15648 186 24X
 Fiche 50-537,82/07/16,8210070029
 - e210070138 Dutines revised Amend XIII to fuel cycle environ rept
 Updated version contains supplemental safeguards info.
 estimated costs % modified Kr-85 disposal scheme
 LOKENDERGO: Office or Nuclear Material Safety %
 Sareguards Director 82/03/23 Advanced Fuel & Spent Fuel
 Licensing Branch MACDUNALD: C E
 LyBE.R J Division of Safeguards
 Ficha 50-53/ 82/07/16 8210070029
- --B210070142 Requests review of Amend XIV.containing revised environ ript Section 5.7) re fuel cycle W/o encl LONEMBERG.H Office of Nuclear Material Safety & Sareguards. Directol 82/05/04 ROUSC.L C Advanced Fuel & Spirit Fuel Licensing Branch MACDONALD.C E Transportation Branch DUBE.R J Division of Sareguards ip 15648 190 24X Fiche 50-537 82/07/16.8210070029
- 6210070146 Requests review of Amend XIV.including Section 3 8 % 5 / j
 to environ rept Comments affecting final versions of Apps
 D & E Y Sections 7 2.7 J.5 7 2 6 % 5 7 2 7 should be
 transmitted by G2Voto
 LOWENDERG, H Office or Nuclear Material Safety &
 Safeguards Director 82/06/09 CLARK, A T. AYER. J. LONG, J NRC
 No Defelled Afficiation Olven ip 15448 191 24X
 Fiche 50-537 82/07/16.8210070029
- --6210070170 Advises that DCE has been notified of omissions, errors & inconsistencies found in Amend XIV to environ rept lokeMBERG.H Office of Nuclear Material Bafety & Safeguards, Director 82/06/16 CHFCK,P S Clinch River Breader Reactor Program Office 2pp 15648 227 24X Fiche 50-537 82/07/16.8210070029
- --B2]00701/4 Provides highlight items to CRBR fuel cycle environ review for uk ending 820611 Amend XIV to environ rept under review LOKENBERG H Office or Nuclear Material Safety & Safeguards.Director 82/06/16 DAVIS, J O Office of Nuclear Material Safety \$ Safeguards.Director 1p 18648 234 24X Fiche 50-537 82/07/16/8210070029
- --E210070198 Discusses status & changes to Amend XIV to environ rept, per 820514 telcon w/DDE Rept will be modified to cover protection for rail shipments
 LOWENBERG.H Office or Nuclear Material Safety & Sareguards. Director 82/05/14 ROUSE.L.C Advanced Fuel & Spint Fuel Licensing Branch MACDONALD.C E Transportation Branch PAGE.R C Uranium Fuel Licensing Branch 2pp 19648 238 P4X Fiche 50-537,82/07/16.8210070029
- --8210070200 Forwards socioeconomic impact portion of environ rept for inclusion u/Amend XIV LOWENBERG.H Office of Nuclear Material Safety & Safeguards. Director 82/05/07 ROUGE.L C Advanced Fuel & Spint Fuel Licensing Branch MACDONALD.C E Transportation Branch PAGE.R J Uranium Fuel Licensing Branch 3pp 15648 240 24X Fichs 50-537, 82/07/16, 8210070029
- --B210070206 Advises that DOE failed to meet schedule of milestone for safeguards info & revised CRBR environ rept New target date scheduled for 820511
 LDNENBERG.H Division of Fuel Cycle & Material Safety 82/05/05
 DAVIS.J C Office of Nuclear Material Safety & Safeguards. Director 1p 15648 246 24X Fiche 50-537,82/07/14. 8210070029

- ~~821007026D Forwards revision to Amend XIII to environ rept, provided by DDE on 820415
 LOWENBERG.H Office of Nuclear Material Safety & Sareguards. Director 82/04/20 ROUSE.L C Advanced Fuel & Spirit Fuel Licensing Branch MACDONALD.C E Transportation Branch DUBE.R J Division of Safeguards 86pp 15648 393 24X Fiche 50-537, 82/07/16, 8210070027
- ~-8210070262 Provides highlights of CRBR fuel cycle environ review for wk ending 820413 DDE plans to submit draft Amend XIII to environ rept during wk of 820419 COMENDERG.H Office of Nuclear Material Safety & Safeguards, Director 82/04/13 DAVIS, J Q Office of Nuclear Material Safety & Safeguards, Director 82/04/13 DAVIS, J Q Office of Nuclear Material Safety & Safeguards, Director 2pp 15649 077 24X Fiche 50-537, 82/07/16, 8210070029
- --B210070280 Discusses radiological dose assessment for licensing of CRBR DDE will submit environ rept on fuel cycle used to fabricate, reprocess, transport \$ safeguard fuel LOMENBERG, H Office of Nuclear Material Safety & Safeguards, Director 82/03/19 CONGEL, F J Radiological Assessment Branch 1p 15649 091 24X Fiche 50-537, 82/07/16, 8210070029
- --8210070291 Forwards corrected pages to Amend XIII package of CRBR environ rept
 LOMENBERG.H Office of Nuclear Material Safety &
 Safeguards. Director 82/03/16 ROUSE.L C Advanced Fuel & Bpent
 Fuel Licensing Branch MACDDNALD.C E Transportation Branch
 BUBE.R J Division of Safeguards 5pp 15649 095 244
 Fiche 5D-537.82/07/16.8210070029
- D NRC Draft/Final Environmental Statements, supple & correspondence
- 8210070029 Partial response to FOIA request for documents re CRBR EIS & all comments, evaluations & documents from BNWL re EIS
 Forwards documents listed in App A
 FELTON.J M Division of Rules and Records 82/07/16 WEISB.E R
 Harmon & Weiss Bpp 15648 004 24X Fiche 50-537,82/07/16.
- --8210070037 Provides info re revision to GRDR fuel cyclo environ revists schedule FES contributions due 820614 Review responsibilities identified EVANB, I. J. NRC No Detailed Affiliation Given 82/03/23 MCCORKLE, G., SHERR, T., ERICKBON, B. NRC No Detailed Affiliation Given 2pp 15648 012 24% Fishe 50-537, 82/07/16, 8210070029
- --8210070043 Discusses plans for 820408-09 meeting w/BNWL in Silver Spring, MD to discuss CRBR environ review Draft updates of EIS sections on transportation & fuel fabrication will be provided HURT, D. NRC No Detailed Affiliation Given 82/03/22 DUBF, II NRC No Detailed Affiliation Given 1p 15648 Q16 24X Fiche 50-537, 82/07/16, 8210070029
- --B210070047 Discusses plans for B20512 & 13 meeting w/DNML re draft update of safeguards portion of EIS HURT.D NRC No Detailed Affiliation Given B2/04/21 GASKIN.C : MULEN.S : BAKER.P NRC No Detailed Affiliation Given Ip 15448 017 R4X Fiche 50-537.82/07/14.8210070029
- --B210070050 Advises that DNWL contractors will be available on B20407-QU to discuss CRBR environ review Transportation section of EIP will be reviewed on B20407 HURT, D NRC No Detailed Affiliation Given B2/03/31 D NRC No Detailed Affiliation Given 1p 15648 OIB 24X Fiche 50-537.82/07/16.8210070029

- --8210070067 Advises that work task sheet uill serve for basis of plan supporting environ review effort Safeguards portion of DOE environ rept should be reviewed to determine if sufficient info has been included for confirmatory review BURNETT, R F Division of Safeguards 82/02/17 LOWENDERO, H Office of Nuclear Material Safety & Safeguards, Director 2pp 15648 026 24X Fiche 50-537,82/07/16.8210070029
- --8210070084 Requests that BNML handle all safeguards-related arras of EIS & interrogatory updates except those concerning threats by clandestine fission explosives in response to 820303 memor MCCORKLE. G NRC No Detailed Affiliation Given 82/03/04 EVANS, B WRC No Detailed Affiliation Given 19 15648 032 24% Fiche 50-537,82/07/16.8210070029
- --B210070101 Advises that 820305 deadline for draft suppl to EIS cannot be net due to delay in receipt of info from DDE LONENDERG. H. Office of Nuclear Material Safety & Bafeguards, Director 82/01/13 CHECK. P. Clinch River Breeder Reactor Program Office 2pg 15648 043 24X Fiche 50-537.82/07/16,8210070029
- --8210070119 Forwards safeguards portion of FEB update.including Section 7 3 & App E LOWENBERG.H Office of Nuclear Material Safety & Safeguards, Director 82/06/09 CHECK.P S Clinch River Breeder Reactor Program Office 20p 15648 093 24X Fiche 50-537.82/07/16.8210070029
- --B210070123 Forwards updated responses to comments on 1976 DES.

 NUREQ-0137 re safeguards & fuel cycle info re radwaste
 shipments disposal site & licensed burial site included
 LOWENBERG H Office of Nuclear Material Safety &
 Bafeguards Director 82/06/15 LEECH.P Clinch River Breedor
 Reactor Program Office 15pp 15648 073 24X
 Fiche 50-537.82/07/16.8210070029
- --8210070126 Forwards update to FES, including App D, "Environ Effects of CRBR Fuel Cycle & Transportation of Radioactive Matls" & Section 5 7 2 7, "Fuel Cycle Impacts "
 LOHENBERG: H Office of Nuclear Material Safety & Safeguards. Director 82/06/19 CHECK: P S Clinch River Breeder Reactor Program Office 50pp 15648 088 24X
 Fiche 50-537, 82/07/16, 8210070029
- --8210070163 Provides highlights for wk ending 820618 re CRBR fuel cycle environ review Minor corrections to FES update submitted to CRBR program ofc LOWENBERG. N Office of Nuclear Material Safety & Safeguards. Director 82/06/24 DAVIS.J 0 Office of Nuclear Material Safety & Safeguards. Director 19 15448 200 24X Fiche 50-537, 82/07/16, 8210070029
- --8210070166 Forwards replacement pages for fuel cycle portion of CRIM FES update Pages correct minor errors LOMENDERG, H Office of Nuclear Material Safety & Safeguards, Director 82/06/21 CMECK.P S Clinch River Breader Reactor Program Office 28pp 15648 201 24X Fiche 50-537, 82/07/16, 8210070029
- --8210070186 Provides highlight items re CRBR fuel cycle environ review for wk ending 820514 Draft fuel cycle portion of EIS in progress.
 LONENBERO.H Office of Nuclear Material Safety & Safeguards, Director 82/05/20 DAVIS.J 0 Office of Nuclear Material Safety & Bafeguards. Director ip 15648 235 24% Fiche 50-537,82/07/16.8210070029

- --8210070223 Notifies that BNWL will be available to review (HBH | 1 on 820512 LOWENBERG.H Office of Nuclear Material Safety & Safeguards, Director 82/04/26 ROUSE, L C Advanced Fuel 1 * ; , * 1 Fuel Licensing Branch MACDONALD.C E Transportation Branch PAGE, R G Uranium Fuel Licensing Branch to 1564H 247 44 Fishe 50-537, 82/07/16, 8210070029
- --B210070313 Submits responses to Contention 6. Interrogatories 15 4/1/61.62.63 & 64 on CROR hearing re ETS update

 AYER, J E , CLARK, A T Advanced Fuel b Spent Fuel ficensing Bid
 B2/06/09 LOWENDERG, H Office of Nuclear Naterial Indiety |

 Safeguards, Director 4pp 15649 i10 24X Fithe 50 517 H; Just P

 8210070029
- --B210070315 Discusses potential need for add1 funding for (1404-11), update project (RELSON, I Battello Memorial Institute, Pacific Northwest Laboratory 82/06/24 LCMENDERO.H Office of Nuclear Material Safety & Safeguards, Director 2pp 15649 114 24X Fiche 30-537, 82/07/16/8210070029
- --B210070318 "CRBR EIS Update," monthly progress rept for Hisy I'm., NELSON, I C Battelle Hemorial Institute, Pacific Northwest Laboratory B2/06/17 LONENBERG, H Office of Northwest (al Safety & Safegwards, Director Jpp 15649 116 24x Fiche 50-507, 82/07/16-8210070029
- --8210070923 Forwards final draft submittal of CRBR EIS update professor 5 7 2 6.5 7 2 7.7 2 5 7 3 M/o encl
 NELSON-I C Battelle Memorial Institute, Pacific Northwest
 Laboratory 92/05/21 (OMENBERG.N Office of Nortean Material
 Safety & Safeguards Director 1p 15649 119 ,48
 Fiche 50-537,82/07/16.8210070029
- ~-8210070327 Confirms changes to final CRBR EIS draft update per untelcon w/MRC sefeguards staff
 NELSCH, I Battelle Hemorial Institute, Pacific Northwest
 Laboratory 82/05/18 LOMENBERG. H Office of Number Material
 Sarety & Safeguards, Director ip 15649 120 24X
 Fiche 50-537, 82/07/16 8210070029
- --8210070332 "CRAR EIS Update," monthly progress rept for Apr 1'd, NELSON, I C Dattelle Memorial Institute, Pacific Northwest Laboratory 82/05/17 LOWENBERG, H Office of Northwest Patent & Safety & Safeguards, Director | 3pp | 15649 121 | 194x | Fiche 50-537, 82/07/16, 8210070029
- --8210070335 Forwards second draft of CRDR EIS undate, including 'et 5 7 2 6. "Transportation of Radioactive Math," Section 5 8 2 7 "Fuel Cycle Impacts" & Section 7 3. "Safequent de Considerations " W/o encl NELSON. I C Battolle Memorial Institute. Pacific Noi University Barety & 82/05/07 LOWENBERG.H Office of Notice. If steel & Early & Safeguards, Director ip 15649 124 24x Fiche 50-537.82/07/16.8210070029
- --8210070347 "CRBR EIS Update," monthly progres rept for Has 14cr NELSON, I C Battelle Memorial Institute, Pacific Northwest Laboratory 82/04/12 LOMENBERG, H Office of Noticer Pales 14 Safety & Safeguards, Director 3pp 15449 125 44x Fiche 50-537, 82/07/16, 8210070029
- --B210070465 Forwards back-up notes & refs for fuel cycle part) opdate Related info encl
 NELBON. I Battelle Memorial Institute, Pacific Northwest
 Laboratory 82/06/24 LOMENBERO, H Office of Nuclear Maleria
 Safety & Safeguards, Director 57pp 15649 128 24X
 Fiche 50-537, 82/07/16, 8210070029
- 8207110034 FDIA request for input to Chapter 7 & App J of \$10. h . . to GRBR
 MEISS, E R Harmon & Weiss 82/07/26 FELTON, J H 101218100 . . . Rules and Records ip 15636 039 24X Fiche 50-537. 102/07/42 8227110034
- B210060442 Responds to FOIA request for input to Chapter / h Asp | FES & suppl to CRIR Documents listed in App A available in PDR App B documents completely withheld advice & opinions (ref FOIA Exemption 3)
 FELTON, J H Division of Rules and Records B2/08/24 Williamon & Weiss App 15636 040 24X Fiche 50-537.88/04/-4
 B210060442
- --B201150176 Forwards Accident Evaluation Branch input to 11% ###
 for Pacifity Section 7 requires suppl to address NRC @PODMES
 atatement of interim policy Info presented in Sections V 2 4
 11 7 requires no update
 KREGER W E Assistant Director for Radiation Protection
 B1/12/18 CHECK, P S Clinch River Breeder Reactor Program
 Bpp 15636 044 24% Fichs 50-537, 82/08/24, 8210060444

- --8206080467 Forwards Accident Evaluation Branch input to final environ statement update re Class 9 accidents MDUSTBHAR W Assistant Director for Radiation Protection 82/05/28 CHECK.F 5 Clinch River Breeder Reactor Program Office 9pp 15636 049 24% Fiche 50-537,82/08/24,8210060442
- --E207140138 Forwards Accident Evaluation Branch revised evaluation of four classes of come disruptive accident included as App J to proposed FES addendum.per B Morris verbal request Calculated risks of accidents not different from LUR risks HOUSTON, R W Assistant Director for Radiation Protection 82/07/01 CHECK.P S Clinck Riser Breeder Reactor Program Uffice 42pp 15636 058 24% Fiche 50-537,82/08/24,8210060442
- --8210060447 Draft input to Class 9 accident analysis for CRBR FFB RAMBLE,E Science Applications, Inc 82/06/30 NRC - No Detailed Affiliation Given 20pp 15636 100 24X Fiche 50-537,82/08/24,8210060442
- --8202240446 Forwards population data input for DES Section 5 9 4 1 2 for yr 2010, per request REGAY, W H Siting Analysis Branch 82/02/10 HULMAN, C Accident Evaluation Branch 3pp 15636 124 24X Fiche 50-537, 82/08/24, 8210040442
- -- P201150087 Provides description of aspects of liquid pathway for update of accident analysis section of FES suppl Liquid pathway consequences small due to absence of large water stores LEAR. O Hydrologic & Ocotechnical Engineering Branch B1/12/22 HOUSTON.R W Accident Evaluation Branch 2pp 15636 132 24X Fiche 50-537, B2/08/24, B210060442
- --8203050073 Confirms tentative schedule for roview of CRBR program probabilistic risk assessment study to be included in FEB suppl MULMAN, L. G. Accident Evaluation Branch 82/02/17 THADANI, A Reliability & Risk Assessment Dranch Ip 15636 165 24X Fiche 50-537 82/08/24.8210060442
- --B21006045B Forwards comments on draft matl for FES update per 820501 request Section 7 2 should include brief discussion on U herafluoride Related info encl CHECK, PS Clinch River Breedo: Reactor Program Office 82/05/20 LOMENBERG.H IRC No Detailed Affiliation Given 14pp 15636 166 24X Fiche 50-597, 82/08/24, 8210060442
- --8204290408 Forwards marked up Table 7 2 of FES Revisions reflect differences in current site atmospheric dispersion values from reg guide values used for original FES calculations HOUSTON,R W Assistant Director for Radiation Protection 82/04/07 CHECK.P 5 Clinch River Breeder Reactor Program Uffice 2pp 15636 189 24x fiche 50-597.82/08/24,8210060442
- --8203220512 Advises that schedule for review of probabilistic risk assessment proposed in 820217 memo no longer applicable input to review will be provided upon request FULHAMIL Q Accident Evaluation Branch 82/03/09 THADANIA Reliability & Risk Assessment Branch 1p 15636 192 24X Fiche 50-537.82/08/24.8210060442
- E210080053 Ack receipt of 870908 ltr commenting on draft suppl to lts Comments will be considered in FES CHECK,PS Clinch River Breeder Reactor Program Office 82/09/23 CHGNO-L R Affiliation Unknown Ip 15669 319 24X Fiche 50-537.82/09/23.8210080053
- --6210080055 Comments on draft suppl to FEG re decommissioning of CHUR CHONG.L R Affiliation Unknown 82/09/08 NRC ~ No Detailed Affiliation Given 2pp 15669 320 24X Fiche 50-537,82/09/23, 8210080053
- F Security, medical, emergency & fire protection plans
- 8210070027 Partial response to FDIA request for documents re CRBR E15 & all comments, evaluations & documents from BNWL re EIS
 Forwards documents listed in App A
 FELTON, J M Division of Ruies and Records 82/07/16 WEISS.E. R
 Harmon & Weiss Spp 15648 004 24% Fiche 50-537, 82/07/16.
 8210070027
- --8210070047 Discusses plans for 820512 & 13 meeting w/BNWL re draft update of safeguards portion of E16 HURT/D NRC - No Detailed Affiliation Olven 82/04/21 OASXIN.C: MULLEN,S. BAKER,P NRC - No Detailed Affiliation Given 1p 15448 017 24X Fiche 50-537.82/07/14.8210070029
- --8210070064 Provides update of EIS review Document requires updated mation reactor safeguards Interrogatories may be issued to clarify or constrain issues

 EVANS.L J NRC No Detailed Affiliation Given 82/03/01

 MCCORKLE.G NRC No Detailed Affiliation Given 2pp 15648 024

 24X Fiche 50-537,82/07/16.8210070029

- --8210070067 Advises that work task sheet will serve for basis of plan supporting environ review effort Safeguards portion of DBE environ rept should be reviewed to determine if sufficient into has been included for confirmatory review BURNETT.R F Division of Bafeguards 82/02/17 LOWENBERO.H Office of Nuclear Haterial Safety & Safeguards, Director 2pp 15648 026 24% Fiche 50-537, 82/07/16,8210070029
- --8210070084 Requests that BNML handle all safeguards-related areas of ETS & interrogatory Updates except those concerning threats & clandestine fission explosives, in response to 820303 memo HCCORKLE, 0 NRC - NO Detailed Affiliation Given 82/03/04 EVANS, B NRC - NO Detailed Affiliation Given 1p 15448 032 24X Fiche 50-537,82/07/16,8210070029
- --8210070086 Requests contentions for CRBR licensing which have implications in areas of fuel cycle safeguards & waste mgt discussed during 810906 meeting LQMENBERG.H Office of Nuclear Material Safety & Safeguards. Director 81/10/09 CHECK.P 5 Clinch River Broads) Reactor Program Office 3pp 15648 033 24X Fichs 50-537, 82/07/16, 8210070029
- --8210070119 Forwards safeguards portion of FES update.including Section 7 3 & App E LCHENDERO, H Office of Nuclear Material Safety & Safeguards.Director 82/06/09 CHECK.P S Clinch River Breeder Reactor Program Office 20pp 15648 053 24X Fiche 50-537,82/07/16.8210070029
- --8210070123 Forwards updated responses to comments on 1976 DES, NUREQ-0139 re safeguards & fuel cycle Info re radwaste shipments, disposal site & licensed burial site included LOMENBERO.H Office of Nuclear Material Safety & Safeguards, Director 82/06/15 LEECH, P Clinch River Breeder Reactor Program Office (19p. 15648-073 24X Fiche 50-537,82/07/16,8210070029
- --8210070138 Outlines revised Amend XIII to fuel cycle environ ropt Updated version contains supplemental safeguards info, estimated costs & modified Kr-85 disposal scheme LOMENBERO, H. Office of Nuclear Material Safety & Gafeguards, Director 82/03/23 Advanced Fuel & Spent Fuel Licensing Branch MACDONALD, C.E. Transportation Brench DUBE, R.J. Division of Safeguards 2pp 15648 188 24K Fiche 50-537,82/07/16,8210070029
- --B210070148 Forwards updated list of staff members & contractor personnel who may be called to testify on fuel cycle or safeguards (ssues at CRUR hearings LOWENSERG,H Office of Nuclear Material Bafety & Safeguards, Director 82/05/06 TREBY, S & Office of the Executive Legal Director 2p 19648 192 24X Fiche 50-537, 82/07/16, 8210070029
- ~-82:0070154 Submits list of staff members & Contractors who may provide testimony on GRBR fuel cycle safeguards LUMENBERG.H Defrice of Nuclear Material Safety & Safeguards. Director 82/03/16 JONES.B NRC ~ No Detailed Affiliation Civen 2pp 15648 196 24X Fiche 50-537,82/07/16. 8210070029
- --8210070204 Advises that DDE failed to meet schedule of milestone for safeguards info & revised CRBR environ rept New target date scheduled for 82051(LOMENDERO, H. Division of Fuel Cycle & Material Safety 82/05/05 DAVIS. J. O. Office of Nuclear Material Safety & 8afeguards: Director | p. 15648 244 244 Fiche 50-537, 82/07/16, 8210070029
- --8210070264 Forwards add) info re add1 safeguards cost info for CKBR fuel cycle environ review
 LCHENBERG.H Office of Nuclear Material Safety &
 Safeguards.Director 82/03/26 ROUSE.L C Advanced Fuel & Sprnt
 Fuel Licensing Branch MACDINALD.C E Transportation Branch
 DUBE.R J Division of Safeguards ip 15649 079 24%
 Fiche 50-537,82/07/16.8210070029
- --8210070269 Provides weekly rept on CRBR fuel cycle environ review activities for whending 820380 DDE submitted supplemental inforce fraft Amend XIII concerning request for safeguards costs

 LOHENBERO, H. Office of Nuclear Material Bafety & Safeguards, Director 82/03/31 CUNNINGHAM.R. Division of Fuel Cycle & Material Safety in 15649 088 24X Fiche 30-537, 82/07/16.8210070029

- Q Adjudicatory correspondence
- 8210120103 Addi response to FDIA request for nine categories of records generated by present NRC Commissioners, primarily Chairman Palladino & Commissioner Roberts & White House Forwards App B documents
 FELTON, J M Division of Rules and Records 82/07/12 UDELL.R A Critical Mass Energy Project 3pp 15690 117 24X
 Fiche 50-000.92/07/12.8210520103
- --8210120123 Forwards memorandum & order re Council of NC objection to util request for exemption to perform certain site preparation work Memorandum addresses exemption question & sets out history of Commission regulation. Section 50 12 ROBERTS, TM Commissioners B1/12/09 PALLADINO,N, OILLINSKY,V, BRADFORD, J Commissioners Ip 15690 124 24X Fiche 50-000, 82/07/12, 8210120103
- 8208270094 FDIA request for CRAC & CRAC 2 analyses for facilities CURRAN.D Harmon & Weiss 82/09/10 Office of Administration 1p 15686 239 24X Fiche 50-000,82/09/10,8208290094
- 8210010064 Motion for summary disposition of NRDC & Sierre Club Contentions 6 & 7a(1) No factual issues requiring adjudication exist & dismissal of contentions warranted as matter of law Mati facts as to which there is no issue encl JONES, B W . SUANSON, D T Hearing Branch 1 82/09/29 Atomic Safety and Licensing Board Panei 12pp 15565 274 24X Fiche 50-537,82/09/27,8210010064
- --8210010079 Affidavit of K Lowenberg on Contentions 6(a) & (b) Concern that fuel cycle analysis be CROR-specific fully addressed by environ rept & draft FES suppl Analysis will be detailed in final FES suppl Prof qualifications encl LOMENBERO, H. Office of Nuclear Material Safety & Safeguards, Director 82/09/29 App 15565 286 24X Fiche 50-537, 82/09/29, 8210010064
- --8210010082 Affidavit of P Leech on Contention 7(a)(1) Concern re CRBR achieving objectives of LMFBR program impact statement & suppl superseded by timing changes given in suppl Prof qualifications & Certificate of Svc encl LEECH, P Clinch River Breeder Reactor Program Office 82/09/28 5pp 15565 290 24X Fiche 50-537,82/09/29,8210010064
- 8210050184 Corrected notification of pending litigation.including omitted sentence from 820924 notice Certificate of Svc encl EDOAR.O L Project Management Corp BERGHOLZ.W E Energy. Dept of EDOAR.O L Edgar.O L 82/09/29 24pp 15604 001 24X Fiche 80-537.82/09/29.8210050184
- B210050582 Responds to FOIA request for CRAC & CRAC 2 analyses for facilities No analyses exist for Shoreham Nuclear Plant Analyses for CRDR furnished under FOIA 82-344 FELTON, J M Division of Rules and Records B2/09/29 CURRAN, D Harmon & Wells 19 15626 240 24% Fiche 50-000,82/09/29, B210050582
- B210060183 Answers to twenty-seventh set of interrogatories Certificate of Svc encl SWANSON, D T. JONES.B W. MIZUNO.0 S Hearing Branch i 82/10/01 Natural Resources Defense Council 176pp 15613 001 24X Fiche 50-537.82/10/01
- B210060185 Slith set of interrogatories Certificate of Svc encl EDGAR, O. L. Project Management Corp BEROHOLZ, W. E. Energy, Dept of EDGAR, O. L. Edgar, O. L. 82/10/04 Natural Resources Defense Council 14pp 15613 198 24X Fiche 50-537, 82/10/04, 8210060185
- 82:10040195 Proposed findings of fact on Contentions 1,2 & 3 re site suitability FINAMORE, B A , TOUSLEY, D R Natural Resources Defense Council TOUSLEY, D R 6:erra Club 82/10/04 77pp 156:3 293 24X Fiche 50-537, 82/10/04, 8210040195
- 8210060200 Second set of admissions & seventh set of interrogatories, per ASLB 820831 scheduling order Certificate of Bvc encl EDQAR.O L. Project Management Corp BERGHOLZ,W E Energy, Dept of ED0AR.G L. Edgar. G L. 82/10/04 Natural Resources Dofense Council App 15614 170 24X Fiche 50-537.82/10/04.8210060200
- 8210070192 informs that time provided for Commission to act to review ALAB-688 expired Commission declined review Decision became final agency action on B21004 CHILK. B. J. Office of the Secretary of the Commission B2/10/05. Office of the Executive Legal Director ip 15637,155 24X Fiche:50-537,82/10/05,8210070192

- 8210120302 Confirms 821005-06 discussions listing NRC personnel to be deposed on various contentions on 821012-13 FINAMORE, B A Natural Resources Defense Council 82/10/0/ SMANSON. D Hearing Branch 1 3pp 15653 03B 24X Fiche 50-537, 82/10/07, 8210120302
- 8210120327 Withdrawal of 821004 proposed findings of fact on Contentions 1.2 & 3 re site suitability Intervenors failed to note ASLB 820831 withdrawal of request for filing proposed findings Certificate of Svc encl FIXAMORE.B A . WEISS.E R Natural Resources Defense Council WEISS.E R Sierra Club 82/10/07 5pp 15653 028 24X Fiche 50-537.82/10/07.8210120327
- 8210130435 Notice of pending litigation Certificate of Svc enri EDGAR.G L Project Management Corp BERCHOLZ, W E Energy, Dipt of 82/10/07 7pp 13681 171 24% Fiche 50-537, 82/10/07, 8210130435
- B210130268 Confirms 821007 discussion listing addi NRC personnel to be available for deposition re Contentions 5(a) & 7(b) on 821013 FINAMORE, B A. Natural Resources Defense Council * Finamore D.A. 82/10/08 JONES, B. Hearing Branch 1 2pp 15678 240 24x Fiche 50-537, B2/10/08, B210130268
- 8210130343 Answer supporting NRC 820929 motion for summery disposition of intervenor Contentions 6(a) & (b) & 7(a)(1) No genuine issue of mat1 fact exists Certificate of Svc encl Related correspondence

 BERCHOLZ,NE Energy, Dept of EDGAR,O L Project Management Corp 82/10/12 Atomic Safety and Licensing Board Panel Upp 19682 038 24X Fiche 50-537.82/10/12,8210130343
- 8210200080 Confirms 821005 & 06 telcons NRDC will have no witnesses for LWA-1 hearings other than TB Cochnan NRC considers failure to update discovery to be affirmative statement that previous responses still correct SMANSON.D T Hearing Branch I 02/10/15 FINAMORE.B A Natural Resources Defense Council 3pp 15753 001 24X Fiche 50-537.82/10/15.8210200080
- 8210200047 Answer to 820917 third request for production of documents Certificate of 8vc encl SMANSON D T Hearing Dranch | 82/10/18 Natural Responses Defense Council App 15755 08B 24X Fiche 30-537.02/10/10. 8210200047
- 8210200092 Supplemental responses to discovery requests Prof qualifications & Certificate of Svc encl HIBBITTS.H W Joint Applicants-Clinch River Broeder Renttor 82/10/18 Natural Resources Defense Council 27pp 15/72 16, 24% Fiche 50-537, 82/10/18, 8210200082
- 8210210357 Response to 821004 sixth set of interrogatories Helatud correspondence
 FINAMORE, BA. WEISS, ER Natural Resources Defense Council
 WEISS, ER Sierra Club 82/10/18 Atomic Safety and licensina
 Board Panel 26pp 15763 346 24X Fiche 50-537,82/10/10.
 8210210357
- 8210210453 Response to applicant 821004 seventh set of interregaturate & second set of admissions Related correspondence FINAMORE, B.A. MEISS-E R. Natural Resources Defense Council FINAMORE, B.A. Beierra Club 82/10/18 Joint Applicants Clanch River Dreeder Reactor 8pp 15763-065-24X Fiche 90-51/, 82/10/16/19/19/8210210453
- B210210232 Answer to NRC motion for summary disposition of MADC/'.iv.ra Club contentions Motion should be granted for Contentions 6(a) & 6(b)(2) & denied for Contentions 6.6(b)(1).(3) & (4) & 7(a)(1) No matl facts at issue Related correspondence TOUBLEY.D R, FINAMORE.B A Natural Resources Defense Council FINAMORE.B A Sierra Club B2/10/19 Atomic Gafety and Liverity. Board Panel 17pp 15766 264 24X Fiche 50-537.82/10/19.
- --B210210240 Affidavit of TB Cockman re environ analyses for fuel tyct timing objective Prof qualifications & Certificate of five encl Related correspondence COCHRAN.T B Natural Resources Defense Council 62/10/19 1504 281 24X Fiche 50-537.82/10/19.8210210232

i i

8210220268 Motion for qualification of TB Cochran as expert interrogator, allowing Cochran to cross-examine on Contentions 1,2,3,4,5(b),6,7(a),7(b),8 & 11,excluding Contentions 1(b),3(a) & 11(a) FIRAMORE,8 A , TOUSLEY,D R Natural Resources Defense Cauncil TOUSLEY,D R Bierra Club B2/10/20 5pp 15775 051 34X Fiche 50-537,82/10/20,8210220268

- -- P2)0220276 Arfidavit of ER Weiss UCS scientist R Pollard allowed to act ejvecuera erriadys, ur en weiss und scientist et Pollard as expert witness for UCS b as cross-examiner of other uitnesses during TMI restart hearing
 - uitnesses during into restant hearing NEISS.ER Matural Resources Defense Council WEISS.ER Unit of Conterned Scientists MEISS.E R Harmon & Weiss 82/10/20 2pp 15775 056 24% Fiche 50-537.82/10/20.8210220268
 - 8210220279 Affidavit of TB Cochran listing qualifications to be CONSIDER A TITLE OF THE CONTROL OF T
- -8210220203 Arfidavit of TB Cochian clarifying testimony at 820826-2/ hearings Shock wase production not required for nuclear explosion to occur COCHRAN T B Natural Resources Defense Council 15775 063 24% Fiche 50-537, 82/10/20 8210220268 82/10/20 Jpp
- 821022028B Request to derer cross examination of C Johnson until 821213-17 portion of LNA-1 hearings Johnson will not be in US during 821114-19 portion of hearings LEISS.E R. FINAMORE.B A. Natural Resources Defense Council NEISS.E R. Sierra Club. #2/10/20. Atomic Safety and Licensing Board Panel. 3pp. 15775-046-24X Fiche 50-537.82/10/20. 6210220268
- --8210220295 Motion to regulate conduct of cross-examination Util & NRC should cross-examing withesses first Util & NRC used cross-eramination for rehabilitation Certificate of Svc enci TOUSLEY, D.R., FINAMDRE, B.A. Naturel Resources Defense Counc) 1 TOUSLEY, D.R. Sierra Club 82/10/20 Atomic Safety and Licensing Board Panel 7pp 15775 069 24X Fiche 50-537. 52/10/20, 82/102068
- 6210250393 Forwards NRC signed % notarrized affidavits re answers to NADO & Sierra Club 821001 twenty-seventh set of Interrogatories

 LMM/SON, D T Hearing Branch 1 82/10/20 FINAMORG, B , WEISS, F R
 Natural Resources Defense Council 21pp 15790 343 24X
 Fiche 50-537, 82/10/20 8210750353
- @210260397 Supplamental response to second set of admissions & seventh set of interrogatories
 FIKAMORE B A . MEIGS.E R Natural Resources Defense Council
 FIKAMORE.B A Sierra Club B2/10/21 Joint Applicants-Clinch
 Fikamore.B reector 4pp 15803 331 24X Fiche 50-537.82/10/21, 8210260397
- -8210260404 Statement of qualification for intervenor expert withouser TB Cochran & C Johnson Prof qualifications & Certificate of Svc encl Sic enc! FINAMORE.B A., WEISb.C R. Natural Resources Defense Council FINAMORE.B A. Sierra Club. B2/10/21 Bpp. 15803 335 24X Fiche 50-537.82/10/21:8210260397
- e210270015 Forwards documents to be placed in PDR Documents respond to 210270015 Forwards documents to be placed in the becoments responsible to Sierra Club 820917 third request for production of documents & Sierra Club 27th set of interrogatories SWEEREY. If Office of the Executive Legal Director 82/10/22 SCOTT. S Document Management Branch 4pp 15818 092 24X Fiche 50 000, 82/10/22, 8210270015
- --8210270020 "Greater Commitment Needed to Solve Continuing Problems at TMI." rept to Congress
 General Accounting Office EMB-81-106 81/08/26 122pp
 15818 076 24X Fiche 50 000,82/10/22.8210270018
- --8210270023 "INEL as Site for Large LMFBR "
 * 16aho, State of 81/01/31 75pp 15818 218 24X
 Fiche 50-537,82/10/22,8210270015
- --8210270035 "AIRDOS Computer Code for Estimating Population & Individual Doses Resulting From Atmospheric Releases of Radionuclides From Nuclear Facilities " KOMER, R E Dak Ridge National Laboratory ORNL-TM-4687 /5/01/31 80pp 15819 317 24X Fiche 50-537.82/10/22,8210270015
- --8210270041 "ALLDOS Computer Program for Calculation of Radiation Doses From Airborne % Waterborne Raleases" STRENDE.D L. NAPIER.D A., PELOGUIN,R A. Battelle Memorial Institute, Pacific Northwest Laboratory PNL-3524 80/10/31 152pp 15820 034 24% Fiche 50-537,82/10/22,8210270015
- --8210270052 "CONCEPT 5 User Manual " FIRM -5470 79 /01 /31 HUDSON, C R Dak Ridge National Laboratory DRNL-5470 191pp 15820 186 24X Fiche 50-537,82/10/22,8210270015

- --8210270056 Advises that listed mods made to CONTAC & CONCEPT computer codes to improve usefulness & accuracy of CONCEPT code HUDBON.C R Oak Ridge National Laboratory 81/09/02 BDWERS.H 1 Oak Ridge National Laboratory 2pp 15821 017 24X Fiche 50-537.82/10/22.8210270015
- --8210270060 "Energy Economic Data Base (EEDB) Program," Phase 4 Final roughouth update
 ALLENARE United Engineers & Constructors, Inc. (subs of Raytheon Co.) UE&C-ANL-810930 81/09/30 421pp 15821 019
 24X Fiche 50-537,82/10/22.8210270015
- --8210270044 Computer runs for 400 MW, 800 MW & 1,200 MW PWRs 4 NRC No Detailed Affiliation Given 82/04/03 24pp 15822 080 24X Fiche 50-537, 82/10/22,8210270015
- -8210270068 Provides info re verification of reasonableness of applicant cost estimates for CRBR Applicant cost estimate may be low due to low escalation rate & inadequate contingency allowance for design & regulatory evolution BOHERS.H I Dak Hidge National Laboratory FIN B-0741 82/06/15 TDALSTON.A Antitrust & Economic analysis Branch (Utility Finance) 7pp (5822-079 24X Fiche 50-537.82/10/22,8210270015
- --B210270069 Computer printout for 1.000-yr dose ECKERMAN, K F NRC No Detailed Affiliation Given 75. 28pp 15822 104 24% Fiche 50-537,82/10/22,8210270015
- 82(026035) Corrected Page 4 to applicant 821018 supplemental responses to NRDC & Sierra Club discovery requests Certificate of Svc enct EDOAR.O L Project Hanagement Corp 82/10/25 Natural Res Defense Council 5pp 15799 358 24X Fiche 50-537,82/10/25.
- 8210270178 Order ruling on NRC 820929 motion for summary disposition
- 110270178 Order ruling on NRC B20927 motion for summary disposition Contentions 6(a) & 6(b)(2) dismissed, but Contention 7(a)(1) retained Portions of Contentions 6(b)(3) & 6(b)(4) deleted LINENDERGER, G., MILLER, M.E. Atomic Safety and Licensing Board Panel 82/10/26 Office of the Executive Legal Director 10pp 15820 025 24x Fiche 50-537, 82/10/26, 82(0270178
- a Inspection reports. IE Bulletins & correspondence
- 8208190233 IE Info Notice 80-35, Suppl 1, "Leaking & Dislodged 1-125 COBB.L I Division of Fuel Facilities, Materials & Safeguards 82/10/06 Consolidated Edison Co of New York 64pp 1376 82/10/06 Consolidated Edison Co of New York 44pp 24% Fiche 50-000,82/10/06,8209190233
- 8208190238 IE Bulletin 82-03, "Stress Corrosion Crecking in Thick-(MI) VOX.B IE Bulletin B2-03, "Byress corrosion cracking in Thick Mail, Large-Diameter: Stathless Steel, Recirculation Sys Piping at BWR Plants "Svc list encl DEYOUNO, R C Director's Office. Office of Inspection and Enforcement 82/10/14 Consolidated Edison Co of New York 115pp 15810 125 24% Fiche 50-000, 82/10/14, 8208170238
- T Hearing transcripts on non-antitrust matters
- 8210040257 Transcript of ACRS CRBR Working Group on Sys Integration 820930 meeting (n Washington, DC Pp 1-242 Viewgraphs enc) # ACRS Advisory Committee on Reactor Safeguards 82/09/30 359p 15599 001 24% Fiche 50-537, 82/09/30, 8210040257
- 8210280133 Transcript of ACRS CRBR Thermal Hydraulic Working Group 821026 meeting in Washington, DC Pp 1-278 Eupporting documentation encl ** ACR8 - Advisory Committee on Reactor Safeguards 82/1456pp 15839 307 24% Fiche 50-537,82/10/26,8210280133
- 8210290184 Transcript of ACR6 Subcommittee on CRBR 821027 meeting in Washington.DC pp 1-233 Supporting documentation encl * ACR6 Advisory Committee on Reactor Safeguards 82/10/27 308pp 15855 048 24X Fiche 50-537.82/10/27.8210290184
- DOCKET STN-50-546 MARBLE HILL NUCLEAR STATION: UNIT 1
- A Application/construction stage documents & correspondence
- 8210120348 Forwards NUREG-0885, "Steam Generator Tube Experience," par telephone request W/o enci versprone request W/G enc. YOUNDBLOOD, B. J. Licensing Branch 1 B2/09/13 PILALIS, L. Public Service Co. of Indiana: Inc. 1p. 15690 300 R4X Fiche 50-546.82/09/13.8210120348

- 8210210023 Summary of 820917 meeting w/util, Bechtel & Sargent & Lundy in Bathesda, MD re SRP conformance review required by 10CFRSO 35 DODLITTLE, E. Licensing Branch 1 82/09/27 Licensing Branch 1 5pp 15782 203 24X Fiche 50-546,82/09/27,8210210023
- 8210290008 Frovides info on procedures for tendering OL application, FSAR & environ rept Two copies of FSAR should be sent directly to E080, who will perform acceptance review NRC will perform acceptance review of environ rept YOUNGBLOOD, B. J. Licensing Branch i 82/10/06 SHIELDS, S.W. Public Service Co. of Indiana. Inc. App. 15877 073 24X Fiche 50-546, 82/10/06, 8210290008
- Q Inspection reports: IE Bulletins & correspondence
- 8210080015 Add1 response to FDIA request for 19 categories of info re nuclear reactor events & safety problems Forwards documents listed in App A Documents in App B completely withheld (ref FDIA Exemption 5) FELTON.J M Division of Rules and Records 82/07/12 UDELL.R A Critical Mass Energy Project 9pp 15665 027 24X Fiche 50-000.82/07/12.8210060015
- --8210080157 Systematic assessment of licenses performance notes re facility evaluation for Jul 1979-June 1980 + NRC - No Detailed Affiliation Given 80/06/30 9pp 13668 062 24X Fiche 50-000,82/07/12.8210080015
- 8210130221 Forwards IE Insp Repts 50-546/82-15 & 50-547/82-15 on 820827-28 No moncompliance noted KNOP.R C Division of Project & Resident Programs 82/09/21 8HIELDS,8 W Public Service Co of Indiana, Inc 2pp 15674 145 24% Fiche 50-546,82/09/21,8210130221
- --9210130222 IE Insp Repts 50-546/82-15 & 50-547/82-15 on 820827-28 No noncompliance noted Major areas inspected Unit 1 reactor vessel installation activities & 10CFR21 reportable items PELKE, P R . KONKLIN. J E Division of Project & Resident Programs 82/09/20 Spp 15674 147 24X Fichs 50-546.82/09/21.8210130221
- 8208190233 [E Info Notice 80-35, Suppl 1. "Leaking & Dislodged I-125 Implant Seeds " Svc list encl CODB.L I Division of Fuel Facilities, Materials & Safeguards 82710706 Consolidate Edison Co of New York Abp 15761 250 24X Fiche 50-000.82710706.8208190233
- 8208190238 IE Bulletin 82-03, "Stress Corrosion Cracking in Thick-Wall, Large-Diameter, Stainless Steel, Recirculation 54s
 Piping at BMR Plants " Svc list encl
 DEYQUNO, R C Director's Office, Office of Inspection and
 Enforcement 82/10/14 Consolidated Edison Co of New York
 115pp 15810 125 24Y Fiche 50-000, 82/10/14, 8208170238
- S Reportable occurrences, LERs & related correspondence
- 8210250130 Interim deficiency rept re incorrect fabrication of several pieces of structured steel Initially reported on 820010 Procedures established to inspect for deficiencies & to repair remaining steel Next rept expected by 830210 SMECDS:S W Public Service Co of Indiana. Inc 82/10/15 KEPPLER:J G Region 3. Office of Director 2pp 15787 016 24X Fiche 50-546.82/10/15.8210250130
- DOCKET STN-50-547 MARBLE HILL NUCLEAR STATION, UNIX 2
- A Application/construction stage documents & correspondence
- 8210120348 Forwards NUREQ-0886, "Steam Generator Tube Experience," per telephone request W/o encl VOUNOBLOOD, B J Licensing Branch i 82/09/13 PILALIS, L Public Service Co of Indiana, Inc. 1p. 15670-300 24X Fiche 50-546, 82/09/13, 8210120348
- B210210023 Summary of 820917 meeting w/util.Bechtel & Sargent & Lundy in Bethesda,MD re SRP conformance review required by 100FR50 35 BOGLITTLE.E L Licensing Branch I, 82/09/27 Licensing Branch I 5pp 15782 203 24% Fiche 50-544,82/09/27,8210210023
- 8210270008 Provides info on procedures for tendering OL application, FSAR & environ rept Two copies of FSAR should be sent directly to EG\$0, who will perform acceptance review NRC will perform acceptance review of environ rept YGUNGBLOOD. B. J. Licensing Brench I. 82/10/06 SHIELDS, S. W. Public Bervice Co of Indiana. Inc. 6pp. 15877-073 24X Fiche 50~546, 82/10/06, 8210250008

- O Inspection reports. IE Bulletins & correspondence
- 8210080015 Add1 response to FOIA request for 19 categories of info re nuclear reactor events & safety problems Forwards documents listed in App A Documents in App B completely withheld (ref FOIA Eremption 5) FELTON.J M Division of Rules and Records 82/07/12 UDCLL.(f A Critical Mass Energy Project 9pp 15665 027 24X Fiche 50-000.82/07/12.8210080015
- --8210080159 Systematic assessment of licensee performance notes re racility evaluation for Jul 1979-June 1980 • NRC - No Detailed Affiliation Given 80/06/30 9pp 13568 062 24X Fiche 50-000.82/07/12.8210080015
- 8210130221 Forwards 1E Insp Repts 50-546/82-15 & 50-547/82-15 on 820827-28 No noncompliance noted KNOP.R C Division of Project & Resident Programs 82/09/21 SHIELDS & Weblic Service Co of Indiana, Inc. 2pp 176/4 14J 24X Fiche 50-546,82/09/21.82(013022)
- ---8210130222 IE Insp Repts 50-546/82-15 & 50-547/82-15 on 820927 .ii N noncompliance noted Major areas inspected Unit I reactor vessel installation activities & 10CFR21 reportable (tems PELKE, P.R., KONKLIN, J.E. Division of Project & Resident Programs 82/09/20 Spp 15674 147 24X Fiche 50-544, 82/09/21 (021013) 31
- 8208190233 IE Info Notice 80-35, Suppl 1, "Leaking & Dislodged | 12.7 Implant Seeds " Svc list encl COBB, L I Division of Fuel Facilities, Materials & Safeguards 82/10/06 Consolidated Edison Co of New York 66pp 15/61 224 Fiche 50-000/82/10/06/8208190233
- 820B19023B IE Duiletin 82-03, "Stress Corrosion Cracking in Thick Wall, Large-Dlameter, Stainless Steel, Recirculation Sys Pleing at BWR Plants " Svc list encl DEYDUNO,R C Director's Office, Office of Inspection and Enforcement 82/10/14 Consolidated Edison Co of New York 115pp 15810 128 24X Fichs 50-000, 82/10/14, 820B1702J9
- 5 Reportable occurrences. LERs & related correspondence
- 8210250130 Interim deficiency rept re incorrect fabrication of several pieces of structured steel Initially reported on 820610 Procedures established to inspect for deficiencies & to repair remaining steel Next rept system by 830210 SHIELDS.S W. Public Service Co. of Indiana. Inc. 82/10/15 KEPPLER.J G. Region 3. Office of Director 2pp 137817 01/6 .4x Fiche 50-546,82/10/15,8210250130
- DOCKET STN-50-553 PHIPPS BEND NUCLEAR STATION, UNIT 1
- Q Inspection reports. IE Bulletins & correspondence
- 820B190233 IE Info Notice 80-35, Suppl i, "Leaking & Disinceed 1 lar-Implant Seeds " Svc list enci COBD.L I Division of Fuel Facilities, Materials & Bafequards 82/10/06 Consolidated Edison Co of New York 66pp 19761 & C 24X Fiche 50-000.82/10/06.8208190233
- 8208190238 IE Bulletin 82-03, "Stress Corrotion Cracking in JALLE Wall, Large-Diameter, Stainless Steel, Recirculation System Piping at BUR Plants "Svc list encl DEYOUND, R C Director's Office, Office of Inspection and Enforcement 82/10/14 Consolidated Edison Co of New Yorl 115pp 13810 125 24% Fiche 50-000, 82/10/14, 8208190238
- DOCKET SYN-50-554 PHIPPS BEND NUCLEAR STATION, UNIT 2

 O Inspection reports, IE Bulletins & correspondence
- 8208190233 IE Info Notice 80-35, Suppl 1, "Leaking & Dislodged 1 최고도 Implant Beeds " Svc list enc! COBB.L I Division of Fuel Facilities, Materials & Bafeguards B2/10/06 Consplitated Edison Co of New York 66pp [5/6] 같았
- 8208190238 IE Bulletin 82-03, "Stress Corrosion Cracking an Thack-Wall, Large-Diameter, Stainless Steel, Recirculation Sys Piping at BWR Plants "Svc list encl DEYDUNG, R C Director's Office, Office of Inspection and Enforcement 82/10/14, Consolidated Edison Co of New York 113pp 13810 123 24X Fiche 50-000, 82/10/14, 8208190238

DOCKET STR-50-556 BLACK FOX STATION, UNIT 1

- A Application/construction stage documents & correspondence
- E210330595 Informs that implementation of erosion control plan will adequately stabilize soil in areas found to be eroding during site visit in May MOVAK.TH Assistant Director for Licensing B2/09/24 WEST.J I Public Service Co of Otlahoma 2pp 15692 341 24X Fiche 50-556 82/09/24.8210130595
-) Inspection reports. IE Bulletins & correspondence
- 8208190233 IE Info Notice 80-35. Suppl 1. "Leaking & Dislodged I-125 Implant Seeds " Syc list encl COSB.L I Division of Fuel Facilities, Moterials & Safeguards 82/10/06 Consolidated Edison Co of New York 66pp 15761 2h0 24
- 5208190236 IE Bulletin 82-03, "Stress Corrosion Cracking in Thick-Hall, Large-Diameter. Stainloss Steel. Recirculation Sys Piping at BMR Plants " Svc list encl REYDUNG.R C Director's Office. Office of Inspection and Enforcement 82/10/14 Consolidated Edison Co of New York 115pp 15810 125 24x Fiche 50-000.82/10/14,8208190238
- DOCKET STN-50-\$57 BLACK FOX STATION, UNIT 2
- A Application/construction stage documents & correspondence
- B210130595 Informs that implementation of erosion control plan will adequately stability soil in areas found to be eroding during site visit in May MCVAK.TH Assistant Director for Licensing 82/09/24 HESF.JB Public Service Co of Otlahoma 2pp 15692 341 24X Fiche 50-556,82/09/24,8210130595
- a Inspection reports. IF Bulletins & correspondence
- 5238190233 IE Info Notice 80-35, Suppl 1, "Leaking & Dislodged I-125 Implant Greds " Svc list encl CDBs,L I Division of Fuel Facilities. Materials & Safaguards 82/10/04 Consolidated Edison Co of New York 66pp 15761 250 247 Fiche 50-000,82/10/06,8208170233
- G2vBj90238 IE Dujletin 82-03, "Stress Corrosion Cracking in Thick-Wall, Large-Diameter, Stainless Bleel, Recirculation Sys Piging at BWR Plants "Svc list encl DEYOUNG.R C Director's Office of Enspection and Enforcement E2/10/14 Consolidated Edison Co of New York I[5pp 15810 125 24% Fiche 50-000, G2/10/14, G200170238
- GOCKET STN-50-566 YELLOW CREEK NUCLEAR PLANT, UNIT 1

 4 [Inspection reports, IE Sulletins & carrespondence
- 8208190233 IE Info Notice 80-35, Suppl 1, "Leaking & Dislodged 1-125 Implant Seeds " Svc list enc! COBB.L I Division of Fuel Facilities, Materials & Safeguards 82/10/06 Consolidated Edison Co of New York & App 15761 256 24x Fiche 50-000,82/10/06.8208190233
- 820B190236 IE Builetin 82-03, "Stress Corrosion Cracking in Thick-Hall, Large-Diameter, Steinless Steel, Recirculation Systeping at DMR Plants " Svc list encl BeyouNo.R C Director's Office. Office of Inspection and Enforcement B2/10/14 Consolutated Edison Co of New York 115pp 15810 125 24% Fiche 50-000,82/10/14,820B190238
- S Reportable occurrences, LERs & related correspondence
- 82(0080247 Third & final deficiency repts re resolution of unanticipated vibratory loading concerns Initially reported on Bil228 Program developed to insure piping sys operate within design parameters Next rept provided by 82(2)17 MILLS.L.H. Tennessee Valley Authority 82/09/24 O'REILLY, J.P. Region 2. Office of Director 3pp 15638 104 24X Fiche 50-000, 82/09/24, 8210080247
- 82(0050285 First interin deficiency rept re failure to consider skismic & inertial loadings on ladders, platforms & walkways Initially reported on 820826 Const activities deferred until decision re const completion reached HILLS.L M Tennessee Valley Authority 82/09/27 O'REILLY, J P Region 2, Office of Director 2pp 15611 176 24X Fiche 50-566.82/09/27.8210050285

- 8210050293 First interim deficiency rept re six sheared motor pinion keys in Limitorque Model SB-0-25 motor operators Initially reported on 820830 Valves w/motor operators being tabulated Next rept will be submitted by 821122 MILLS.L.M. Tennessee Valley Authority 82/09/28 O'REILLY, J.F. Region 2, Office of Director 2pp 15609 070 24X Fiche 50-000, 82/09/28, 8210050293
- 8210290328 Second interim deficiently rept re use of nonconservative calculational method to evaluate General Const Spec G-02 spacing violations (nitially reported on 820528 Next rept will be sent by 830528 MILLS.L M Tennesses Valley Authority 62/10/12 O'REILLY, J P Region 2, Office of Director 2pp 15853 064 24X Fiche 50-000-82/10/12,8210290328
- 8210290187 Interim deficiency rept re deferral of const activities Initially reported on 820623 Commitments made in rept.audit findings & response to violations deferred until restart of design & const MILLS.L M Tennessee Valley Authority 82/10/14 0'REILLY, J P Region 2, Office of Director ip 15853 312 24X Fiche 50-000.82/10/14,8210290187
- 8210290236 Third interim deficiency rept re potentially overstressed embedded plates Initially reported on 820412 Investigation continuing & const activities deferred until sufficient infogathered to determine completion of project MILLS.L M Tennessee Valley Authority 82/10/14 0'REILLY, J.P. Region 2. Office of Director 2pp 15853 227 24X Fache 50-000.82/10/14.8210290236
- 8210260320 First interim deficiency rept re addition of locking devices to handwheel operated valves Initially reported on 820916 Const activities deferred Analyses of locking devices continuing Next rept unli be sent by 820310 MILLS.4. H Tennessee Valley Authority 82/10/18 O'REILLY.JP Region 2. Office of Director 2pp 15802 359 24X Fiche 50-000.82/10/18.8210260320
- 8210270274 Final rept for Deficiencies D % E & seventh interim rept for Deficiencies A & D re control of procurement activities Initially reported on 810316 Final corrective actions noted Next rept expected by 830428 MILLS.L M Tennessee Valley Authority 82/10/21 O'REILLY, J P Reglon 2, Office of Director 4pp 15853 143 24% Fiche 50-000,82/10/21,8210270274
- DOCKET STN-50-567 YELLOW CREEK NUCLEAR PLANT, UNIT 2

 Q Inspection reports, IE Buildetins & correspondence
- 8208190233 IE lnfo Notice 80-35, Suppl 1, "Leaking & Dislodged 1-125 Implant Beeds " 8vc list enc! COBB.L ! Division of Fuel Facilities, Materials & Safeguards 82/10/06 Consolidated Edison Co of New York 64pp 15761 250 24% Facts 50-000.82/10/06.8208190233
- 8208190238 IE Bulletin 82-03. "Stress Corrosion Cracking in Thick-Wall Large-Diameter. Stainless Steel Recirculation Sys Piping at BMR Plants " Svc list encl DEYGUNQ.R C Director's Office. Office of Inspection and Enforcement 82/10/14 Consolidated Edison Co of New York 115pp 16810 125 24X Fichs 50-000.82/10/14.8208190238
- 9 Reportable occurrences, LERs & related correspondence
- 8210080247 Third & final deficiency repts re resolution of unanticipated vibratory loading concerns Initially reported on Bil228 Program developed to insure piping sys operate within design parameters Next rept provided by 821217 MILLS.L M Tennessee Valley Authority 82/09/24 O'REILLY. J'Region 2, Office of Director Spp 15638 104 24X Fiche 50-000.82/09/24.8210080247
- 8210050285 First interim deficiency rept re failure to consider & inertial loadings on ladders, platforms & walkways Initially reported on 820826 Const activities deferred until decision re canst completion reached HILLBL M Tennessee Valley Authority 82/09/27 D'REILLY, Region 2. Office of Director 2pp 15611 176 24X Fiche 50-566, 82/09/27, 8210050285
- 8210050293 First interim deficiency rept re six sheared motor pi keys in Limitorque Model 88-0-25 motor operators Initially reported on 820830 Valves w/motor operators being tabulated Next rept will be submitted by 821122 MILLS,L M Tennessee Valley Authority 82/09/28 O'REILLY, Region 2. 8ffice of Director 2pp 15409.070 24X Fiche 50-000.82/09/28.8210050293

- 8210290328 Second interam deficiency rept re use of nonconservative calculational method to svaluate General Const Spec 0-32 spacing violations Instially reported on 820528 Next rept be sent by 830528 MILLS.L M Tennesse Valley Authority 92/10/12 D'REILLY. J P Region 2. Dffice of Director 2pp 15853 064 24X Fiche 50-000, 82/10/12, 8210290328
- 8210270187 interim deficiency rept re deferral of const activities Initially reported on 820623 Commitments made in rept, audit findings & response to violations deferred until restart of design & const MFLLS.t. M. Tennessee Valley Authority 82/10/14 0'REJLLY, J.P. Region 2, Office of Director ip 15853 312 24X Fiche 50-000. 82/10/14.8210270187
- 8210290236 Third interim deficiency rept re potentially overstressed embedded plates Initially reported on 820412 Investigation continuing & const activities deferred until sufficient info gathered to determine completion of project MILLS, L.M. Tennessee Valley Authority 82/10/14 O'REILLY, J.P. Region 2, Office of Director 2pp 15853 229 24X Fiche 50-000, 82/10/14, 8210290236
- 8210260320 First interim deficiency rept to addition of locking devices to handwheel operated valves Initially reported on 820916 Const activities deferred Analyses of locking devices continuing Next rept will be sent by 820310 MILLS.L. M. Tennessee Valley Authority 82/10/18 O'REILLY. J.P. Region 2. Office of Director 2pp 19802 359 24% Fichs 50-000.82/10/18.8210260320
- 8210290274 Final rept for Deficiencies B & E & seventh interim rept for Deficiencies A & D re control of procurement activities initially reported on 810316 Final corrective actions noted Next rept expected by 830428 HILLS.L H Tennessee Valley Authority 82/10/21 O'REILLY, J P Region 2, Office of Director 4pp 15853 143 24% Fiche 50-000.82/10/21,8210290274

DOCKET STN-50-584 OIBBSAR, GIBBS & HILL

- A Application/construction stage documents & correspondence
- 8210270124 Forwards OA program, Topical Rept OIBBAR 17-A.Amend & KEDDIS,N N Gibbs & Hill. Inc. (subs of Dravo Corp.) 82/10/25 HA495,W P Quality Assurance Branch 1p 15827 115 24X Fiche 50-584,82/10/25,8210270124
- --8210270129 Amend 6 to GA program Topical Report CIBEAR 17-A * Oibbs & Mill, Inc. (subs. of Dravo Corp.) OIBSAR-17-A AO6 82/08/31 115pp 15827 116 24X Fiche. 50-584, 82/10/25, 8210270124

DOMESTIC LICENSING OF SPECIAL NUCLEAR MATERIAL

DUCKET 70-0007 ICN PHARMACEUTICALS, INC , IRVINE, CA

- B210060225 Forwards IE Insp Rept 70-0007/82-01 on 920505-0605 No noncompliance noted KINNEHAN J D Division of Engineering & Technical Programs. 82/09/30 BAIETTIAL ICN Pharmaceuticals.inc , ICN-C&R Development 2pp 15620 048
- --8210060227 IE insp Rept 70-0007/82-01 on 820505-0605 No noncompliance ' "acility decontamination surveyed & site closed out cense 37-00345-03 terminated M. KINNEMAN.J D. Division of Engineering & Technical 92/08/02 10pp 15620.030

CA

--- CAMMON O O

for

- --8210060356 IE Safeguards Insp Rept 70-0025/82-08 on 920913-16 No noncompliance noted Major areas inspected measurement control program & independent insp safeguards effort Details withheld (ref 10CFR2 790)
 NELSON, 0 B Division of Radiological Safety & Safeguards Progras 82/09/27 ip 15615 193
- DOCKET 70-0027 BABCOCK & WILCOX CO , LYNCHBURG, VA
- 8210270232 Forwards mods to B&W upgrade physical security plan made during implementation Mods withheld (ref 10CFR2 790) KELLY.J W Babcot & Wilcox Co 82/06/10 EVANS, L J Fuel Facility Safeguards Licensing Branch 2pp 15886 070
- 8210010359 Forwards IE Safeguards Insp Rept 70-0027/82-19 on 820893-2 No noncompliance noted 01B80N.AF Division of Engineering & Yechnical Programs 82/09/1 ECKERT.JP Babcock & Wilcox Co 2pp 15569 233
- --8210010361 IE Safeguards Insp Rept 70-0027/82-19 on 620623-26 No noncompliance noted Major areas inspected MC 652060 measurement control & statistics Details withheld (ref 10CFR2 790) SARADOS, J W, MCALPINE, E J Division of Engineering & Technolas Programs 82/09/10 ip 15569 235
- 8210150229 Forwards IE Insp Rept 70-0027/82-20 on 820830-0901 No noncompliance noted GIBSON, AF Division of Engineering & Technical Programs 82/69/1 ECKERT, J.P. Babcock & Wilcox Co. 2pp 15701 356
- --8210150239 IE Insp Rept 70-0027/82-20 on B20830-0901 No noncomplia:
 noted Major areas inspected review of lab GC program,
 radiochemistry procedures & records & liquid & gaseous
 sampling & accountability
 EVANS.C D. MCNTGOMERY.D M Division of Emergency Preparedness:
 Operational Support 82/09/16 4pp 15701 358
- 8210220497 Forwards page changes to radiological contingency plan to clarify procedure for notifying NRC state & locality of declared state emergency Provisions for assessing offsite radiological impact of radiological emergency also revised KELLY.J W Babcock & Wilcox Co 92/09/29 PAGE.R O Uranium Fu Licensing Branch 4pp 15786-317
- 8210210341 Forwards IE Safeguards Insp Rept 70-0027/82-25 on 820927-1001 No noncompliance noted 01BSDN.AF Division of Engineering & Technical Programs 81/10/ ECKERT,JP Babcock & Hilcox Co 2pp 15764 307
- --8210210342 IE Safeguards Insp Rept 70-0027/82-25 on 820927-1001 N: noncompliance noted Major areas inspected security plan & implementing procedures records & repts.lucks.keys & detection aids Details withheld (ref 100FR73 21) QOODE.R W , MCGUIRE.D R Division of Engineering & Technical Programs 82/10/14 ip 15746-309
- DOCKET 70-0033 TEXAS INSTRUMENTS, INC , ATTLEBORD, MA
- 8210070239 Forwards IE Insp Rept 70-0033/82-04 on 820901-03 No noncompliance noted STAROSTECKI, R Division of Project & Resident Programs 82/09/2: 0DETZ.W K Texas Instruments, Inc 2pp 15637 146
- --8210070240 IE Insp Rept 70-0033/82-04 on 820901-03 No noncompliant noted Major areas inspected review of operations, closeout surveys: environ programs & licensee/licensing meeting ROTH, J. KEIMIO, R. Division of Project & Resident Programs SHUM, E. Office of Nuclear Material Safety & Safeguards, Directon 82/09/21 App. 15537-146
- 8210290238 Forwards IE Insp Rept 70-0033/82-03 on 820831-0902 No noncompliance noted MARILNIT T Division of Engineering & Technical Programs 82/10 OUETZ.W H Texas Instruments, Inc 2pp 15853 198
- --8210290241 IE Insp Rept 70-0033/82-03 on 820831-0902 No noncomptinoted Major areas inspected licenses closeout survey reptindependent measurements in general mfg area, chemical & metallographic labs & roof exhausts
 JOHAMSEN.J. LADUN.R. KINNEMAN.J. D. Division of Engineering & Technical Programs 82/10/12 lipp. 15853 200.

- EGUVET 70-0036 COMBUSTION ENGINEERING, INC., WINDSOR, CT
- 8210210583 Provides schedule for review of license renewal application Comments & recommendations on application, notification of scheduled insp & action required to meet schedule requested CRGW.W T. Uranium Fuel Licensing Branch 82/10/01 MILLER, J. R. Division of Engineering & Technical Programs 2pp 15782-360
- 8210180316 Requests transfer of C-E fee funds from deferred revenue to ratis revenue account per review of amend to License SNM-33 MILLER.W D. License Fee Management Branch 82/10/06 MANION.W E Finantial Operations Branch ip 15746-017
- DOCKET 70-0135 BABCOCK & WILCOX CO , APOLLO, PA
- EC10130303 Ack receipt of 820728 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 70-0135/82-07 & 70-0264/82-06
 STAROSTECKIAR Division of Project & Resident Programs 82/10/06 CARLSON R V Babcock & Wilcox Co ip 15678 181
- --821013930B Responds to NRC 820901 ltr re violations noted in IE Insp Repts 70-0135/82-07 & 70-0344/82-06 Corrective actions amount of furanate drying belt encl adjusted & more effectively designed reflector installed AUSTIRM A Babook & Wilcox Co 82/09/28 STAROSTECKI, R Division of Project & Resident Programs 2pp 15478 182
- DOCKET 70-0143 NUCLEAR FUEL SERVICES. INC . ERWIN. TN
- 8210270235 Application for amend to License SNM-124 to allow use of Finishing onit for Finishing Aighly enriched U in Bldg IIO HICHELC J Nuclear Fuel Services, Inc. (subs. of Getty Gil Co.) B2704714 WIXON,W A. Division of Fuel Cycle & Material Bafety 2pp. 18078 073
- @310200571 Forwards Revision B to physical sefeguards plan incorporating personnel seatch to detect 3 g unshielded U. enriched to 90% U-235 to allow wider range of flexibility Revision withheld (ref 10CRR9 21) MICHEL: C J Nuclear fuel Services. Inc (subs of Gotty Oil Co) B2/06/01 EVANS.L J Fuel Facility Safeguards Licensing Branch Ip 15814 358
- 82(0)5006) Confirms 820721 commitment to submit groundwater nanitoring program to NMSS by 82(0)5 KANSER,U C Nuclear Fuel Services: Inc (subs of Getty Oil Cn) 82/07/27 GIBENN.A.F Division of Engineering & Technical Programs 1p 15701 244
- 8210010164 Ack receipt of IC lnsp Rept 70-0143/82-28 No proprietary into MANSER, H C Nuclear Fuel Services, Inc (subs of Getty Oil Cu) 82/08/30 (BBSON.A F Division of Engineering & Technical Programu 19 15368 090
- 92/02/20568 Forwards Page 3-2 to application for renewal of Centificate of Compliance 5492 for Model RMG-IBI-I Inadvertantly omitted from original MICHELC J Nuclear Fuel Bervices. Inc (subs of Getty Dil Co) 92/09/30 MACDONALD.C E Transportation Branch Ip 15814-355
- 8210010162 Concurs w/decision to terminate use of environ impingers in conjunction u/environ samples; based on review of 820327 results of environ impinger air measurements for Jan-Mar 1982 G1850N, A.F. Division of Engineering & Technical Programs 82/09/03 MAVSER, W.C. Nuclear Fuel Services, Inc. (subs. of Getty Oil Co.) tp. 15567-273
- 6210010364 Forwards IE Insp Rept 70-0143/62-32 on 620623-27 No noncompliance noted (Sissonia F Division of Engineering & Technical Programs 62/09/10 MANEER, N.C. Nuclear Fuel Services, Inc. (subs. of Getty Oil Co.) 2pp 15567 236
- --8210010371 (E Insp Rept 70-0143/82-32 on 820823-27 No nencompliance noted Hajor areas inspected facility operations, storage & internal control & records & repts Details withheld (ref 10CFR2 790)
 10DD-0 A / MCALPINE.E J Division of Engineering & Technical Programs 82/09/10 ip 15569 238

- 8210150197 Forwards IE Safeguards Insp Rept 70-0143/82-33 on 820806-0903 No noncompitance noted 01850N.A F Division of Engineering & Technical Programs 82/09/14 MANSER.W C Nuclear Fuel Services. Inc (subs of Getty Dil Co) 2pp 15715 273
- --82i0150204 IE Safeguards insp Rept 70-0143/82-33 on 820806-0903 No noncompliance noted Major areas inspected licensee action on previous insps.nonroutine events & facility operation Details withheld (ref 10CFR2 770)
 LEE.T D , McALPINE.E J Division of Engineering & Technical Programs 62/09/14 4pp 15715 275
- 8210040048 Ack receipt of check in payment of civil penalty proposed on 820809 Corrective action discussed in 820903 ltr will be examined during future insp.

 AXELRAD, J. A. Director's Office. Office of Inspection and Enforcement 82/09/21 MANSER, W. C. Nuclear Fuel Services. Inc. (subs. of Getty Oil Co.) 2pp. 15577 208
- 8210010052 Denies 820127 % 0507 requests that IE Insp Rept 70-0143/81-04 not be placed in PDR D'REILLY.J P Region 2. Diffice of Director 82/09/22 MANSER.W C Nuclear Fuel Services, Inc (subs of Oetty Oil Co) ip
- 8210010313 Forwards IE Safeguards Insp Rept 70-0143/82-34 on 820707-10 No noncompliance noted OIBSON.A F Division of Engineering & Tachnical Programs 82/09/22 MANSER.H C Nuclear Fuel Services, Inc (subs of Getty Oil Co) 2pp 15568 283
- --8210010317 IE Safeguards Insp Rept 70-0143/82-34 on 820907-10 No noncompliance noted Major areas impacted shipping & receiving of SNM Details withheld (ref 10cFR2 790) JONES, D. W., RICHARDS, B. L., NCALPINE, E. J. Division of Engineering & Technical Programs 82/09/22 ip 15568 285
- B210150473 Ack receipt of check for \$2,500 sent in payment of civil penalty proposed on 820809 Corrective action specified in 820903 ltr will be examined at future insp AXELRAD. J A Enforcement Staff 82/09/22 MANSER. W C Nuclear Fuel Services. Inc (subs of Oetty Oil Co) 2pp 15714 172
- --B210150477 Responds to NRC B20809 ltr re violations noted in IE Insp Rept 70-0143/82-23 Corrective actions withheld (ref 100FR2 790) Payment of civil penalty encl MANSER, H C Nuclear Fuel Services, Inc (subs of Getty Dil Co) B2/09/03 Director's Office, Office of Inspection and Enforcement 1p 15714 174
- 8210040085 Order establishing addl extensions of time Parties may submit questions to be posed in oral session by 821107 Oral session will be held between 821215-830115 CHILK, S. J. Office of the Secretary of the Commission 82/10/01 2pp 15581 037
- 8210080179 PND-II-82-10A on 821003, explosion occurred in calciner area of scrap recovery bldg.causing two to three times max airborne radioactivity release Caused by introduction of volattle math to calciner (small furnace) WRAY, J. R. , OIBSON, A. F. Region 2, Office of Director B2/10/04 2pp 15640 165

821

OCKETED HEIMS

- --8210(50376 Forwards IE Safeguards Insp Rept 70-0143/82-29 on 820802-06 & notice of violation Details & notice of violation uithheld (ref 10CFR79 21)
 GLSHINSKI, J A Davision of Engineering & Technical Programs 82/08/25 MANSER, H C Nuclear Fuel Services, Inc (subs of Getty Old Co) 2pp 15704 273
- --B2101503B0 IE Safeguards Insp Rept 70-0143/82-29 on B20802-06
 Noncompliance noted failure to review & audit safeguards
 contingency plan Details withheld (ref 10CFR73 21)
 PERNY, C D , TILLMAN. A , MCGUIRE. D R Division of Engineering &
 Technical Programs 82/08/24 2pp 15704 275
- 82(0)(30383 Motion for Commission to direct DOE to make available to NRDC, under suitable protections, classified info covered by enci FOlA requets Deadline for filing testimony should be suspended Certificate of Svc enci WEISS, E.R. Natural Resources Defense Council WEISS, E.R. Harmon & Heiss 82/10/08 Commissioners 12pp 15680-324
- 8210130281 Advises that organization will appear at hearing but will not present direct oral testimony Comments provided on Issues A.B & C
 MISDRENER.J M Oil.Chemical & Atomic Workers Intl 82/10/12
 CHILK.S J Office of the Secretary of the Commission 3pp
 15578 276
- 8210150472 Order denying NRDC 821012 motion to suspend deadline for filing testimony until NRDC FOIA requests resolved Motion would be unnecessary if NRDC had filed FOIA request on more timely basis Commissioner Ahearne separate views encl CHILK.S U Office of the Secretary of the Commission 82/10/14 Natural Resources Defense Council 3pp 15703 040
- 8210180103 Submittal of R Burnett 820930 testimony representing consolidated testimony of all NRC ofcs FDNNER.R L Regulations Division 82/10/14 2pp 15718 025
- --8210180107 Testimony of R Burnett Present safeguards program adequate to protect public health & safety License should be revoked if amend not sustained W/Certificate of Svc BURNETT.R F Division of Safeguards 82/09/20 30pp 15718 02/
- B210200001 Forwards memorandum of law re license amend process & TB Cochran testimony Testimony & Exhibit 28 withheld SCHERR, B J Natural Resources Defense Council B2/t0/15 STUCKY, B H Docketing & Services Branch (p 1575
- --8210200004 Memorandum of law on license amend process Amend unlawfully substitutes "reasonably achievable" std in place of legislatively ordained std of protection of public health & safety Certificate of Svc encl Exhibit 20 withheld HEISS.ER Natural Resources Defense Council 82/10/15 Commissioners 240pp 15755 105
- 8210200057 Response opposing NRDC motion for Commission to direct production of documents FOIA process cannot be used as substitute for discovery Commission has no authority to order production of DDC documents Certificate of Svc encl LEIKEN.L., BERGHOLZ,W E Energy, Dept of 82/10/18 Commissioners 8pp 15756-048
- 8210250060 Forwards Page 50 of written testimony filed w/Commission on 821015 LEIKEN.L Energy, Dept of 82/10/21 CHILK,S J Office of the Secretary of the Commission 1p 19787 090
- ---B210250041 Page 50 of testimony filed tr/Commission on B21015, inadvertently omitted Certificate of Svc encl ← Energy, Dept of 82/10/21 3pp 15787 091
- DOCKET 70-0223 CALIFORNIA, UNIV OF, LOS ANGELES, CA
- 9210290023 Partial response to FOIA request for documents re UCLA Lab & research reactors Forwards documents listed in App A FELTON.J M Division of Rules and Records B2/09/03 HIRSCH.D Government Accountability Project 2pp. 15864 195
- --8210290048 Discusses insp of activities authorized under License R-71 & SMM-974 on 750520 No honcompliance noted Major areas inspected control of SMM & selective exams of procedures & personnel interviews ENGELKEN,R H Region 5, San Francisco. Office of the Director 75/06/10 BROWN,H V California, Univ of, Los Angeles 1p 15864 262 24X Fichs 30-142,82/09/03,8210290023

DOCKET 70-0278 DOW CHEMICAL CO , MIDLAND, MI

- B2101B002B Responds to FOIA request for seven categolies of documents re Dow Chenical Co & incineration of low level radwaste Request for fee waiver granted Forwards listed documents FELTON.J & Division of Rules and Records 82/08/20 William Afrillation Unknown 29
- --8210180424 Provides info re use of Dow Chemical Co radiation protest, manual, per AEC 581219 ltr Requests info on licensing of irradiated U
 BEAMER, W.H. Dow Chemical Co. 58/12/24 JOHNSON, L. Atomia Eraig.
 Commission 2pp 15748 331
- DOCKET 70-0364 BABCOCK & WILCOX CO , APOLLO, PA
- B210280452 Forwards corrected Page B of Amend 17 to License (I.H 414 issued 82083) License Condition 36 C should reflect conditions contained in Amend 12 issued 810225 RGUSEL C Advanced Fuel & Spent Fuel Licensing Branch 18707's AUSTINIA A Babcock & Wilcox CO 1p 15857 011
- --8210280453 Corrected Page 8 to Amend 17 to License UNM-414.revibira License Condition 36 C ROUSE.L C Advanced Fuel & Spent Fuel Licensing Branch (12) -- 1p 15859 012
- 8210070307 Forwards IE Insp Rept 70-0364/82-05 on 82072) & notifer of violation
 MARTIN.T T Division of Engineering & Technical Programs (Ind/of 2) CARLSON/R V Babcock & Wilcol Co 2pp 15604 [2]
- --8210070312 Notice of violation from insp un 02072;

 # Division of Engineering & Technical Programs (62/07/24 ***)
- --8210070316 IE Insp Rept 70-0364/82-05 on 820723 Noncompliants initial excessive dose rate at external surface of vehicle & failure to label package correctly CLEMONS.P E. GREENMAN.E Q Division of Engineering & Technics #1 Programs 82/07/21 7pp 15634 127
- 8210130303 Ack receipt of 820928 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 70-0135/02 0/ 5 70-0364/82-06 STARDSTECKIOR Division of Project & Resident Programs 153/10/25 CARLSON, R V Babcock & Wilcox Co 1p 15678 181
- --8210130308 Responds to NRC 820701 ltr re violations noted in 14 hig Repts 70-0135/82-07 & 70-0364/82-06 Corrective actions ammonium diuranate drying belt encl adjusted & more effectively designed reflector installed AUSTIN,M A Babcock & Wilcox Co 82/09/28 STAROBITCKI, A Division of Project & Resident Programs 2pp 136/8 187
- DOCKET 70-0371 UNC NAVAL PRODUCTS: INC , UNCASVILLE, CT
- 8210040372 issues Amend 18 to License 8NM-36B, authorizing new starage shelves & new fuel handling criteria for raw fuel storage room, in response to 820510 application & 820604,0707 & OBI2 suppls
 PAGE,R 0 Uranium Fuel Licensing Branch 82/09/07 MIRK, H & United Nuclear Corp 2pp 15597 214
- --B210040397 Safety evaluation supporting Amend 18 to License "Net Art BIDINCER G H . CROWN T Uranium Fuel Licensing Branch (1974):11 2pp | 15597-216
- 8210250016 Forwards revised fundamental nuclear mail control progress W/o enci COLLOPY,T J United Nuclear Corp 82/09/07 EVANS,L J fuel Facility Safeguards Licensing Branch lp 15808 259
- 8210220168 Forwards IE Safeguards Insp Rept 70-0371/82-10 on 820616-19 No noncompliance noted MARTINIT T Division of Engineering & Technical Programs 82/10/10 AMY, 0 0 United Nuclear Corp 2pp 15778 055
- --8210220172 IE Bafeguards Insp Rept 70-0371/82-10 on 820816-19 Pd-noncompliance noted Major areas inspected security plan & implementing procedures lighting & review of open items Details withheld (ref 10CFR73 21)
 SMITH 9 C , GODY, A T. Division of Engineering & Technical Programs. 82/10/07 ip 15778 057

- 8210220177 Forwards IE Safaguards Insp Rept 70-0371/82-09 on 820809-13 No noncompliance noted MARTIM T T Division of Engineering & Yechnical Programs 82/10/14 AMY C O United Nuclear Corp 2pp 15777-304
- --8210220179 [E Safeguards Insp Rept 70-0371/82-09 on 820809-13 No noncompliance noted Major areas inspected measurement control program Details withheld (ref 10CFR2 790) ZIBULSKY.H . GODY.A T Division of Engineering & Technical Programs 82/10/07 1p 15777 306
- DOCKET 70-0398 COMMERCE, DEPT OF, WASHINGTON, DC
- 821CO50138 Ack receipt of 820917 ltr informing MRC of steps taken to correct violations noted in IE lusp Repts 70-0398/82-03 & 20-03918/82-03 MARTIN I T Division of Engineering & Technical Programs 82/09/30 PEVEV. E Commerce Dept of National Bureau of Standards 1p 1544-304
- --B210060147 Responds to NRC 820908 ltr re violations noted in IL lisp Repts 70-0398/82-03 & 30-03918/82-03 Corrective actions instructions issued re Spec /A container reuse & labeling & posting of containers for Cf-252 source PEVEY.L E Commerce.Dept of, National Bureau of Standards 82/09.17 MARTIN.T T Division of Engineering & Technical Programs 2pp 19614 305
- DOCKET 70-0416 COLORADO STATE UNIV , FT COLLING, CO
- 6210220004 IE losp findings & Licensee Ack dtd 820921 of License SAM-380 losp findings no violations observed SP1728686.0 D Region 4, Office of Director 82/09/21 13pp
- DOCKET 70-0633 PAN AMERICAN WORLD AIRWAYS, INC , PATRICK AFD, FL
- 82(00)0116 IC Insp Findings & Licensee Ack dtd U20901-02 of License EAM-575 Insp findings no nancompliance noted FRAMALIE Region 2. Office of Director 82/09/02 ip 15567 219
- COLKET 70-0687 UNION CARBIDE CORP . TUXEDO. NY
- 6510270067 Forwards integrated site wide emergency preparedness plan Agreement itrs encl BUILCKA, R C Union Carbide Corp 82/07/03 CUNNINGHAM, R E Division of Fuel Cycle & Material Safety 1p 15836 128
- --0210270070 Nuclear facility emergency plan + Union Carbide Corp 82/09/03 85pp 15836 129
- B210220260 Forwards IC Sareguards Insp Rept 70-0687/82-06 on 82090/-10 No noncompliance nuted MARTIN T T Division of Engineering & Technical Programs 82/10/13 MCGOVERN, J J Union Carbide Corp 2pp 15776 325
- --0210220264 IE Safeguards Insp Rept 70-0607/82-06 on 020707-10 No noncompliance noted Major areas inspected nuclear maticontrol & accounting, including measurement & statistical controls Details withheld (ref 100FR2 700) 210ULSKY,H , RATTA.A D , CODY.A T Division of Engineering & Technical Programs 02/10/07 ip 15776-32/
- DOCMET 70-0753 WHEATON COLLEGE, WHEATON, IL
- 6210220343 Hemorandum & order directing OE to file rept on intention to submit applications to renew OL & SNM license, within 15 days of sic of order FRYELJ H Atomic Safety and Licensing Board Panel 82/10/21 General Electric Co 3pp 19776 265 24X Fiche 50-070,82/10/21, 8210220343
- DOCKET 70-0754 GENERAL ELECTRIC CO . PLEABANTON: CA
- 8210080302 Forwards IE Insp Repts 70-0754/82-03 on 820812 & 70-0754/82-04 on 820910 & 14 Excessive Pu contamination levels found in Advanced Fuels Lab Blog 102 besement, front lab & sodium room areas in 820812 insp BODA: H E Division of Radiological Safety & Bafeguards Program 82/10/05 ROUSE, L C Advanced Fuel & Spent Fuel Licensing Branch 2pp 15638 008

- --8210080311 IE Insp Rept 70-0754/82-04 on 820910 & 14 Major areas inspected walls, floors, pipelines & fixture Pu contamination levels in Advanced Fuels Lab Bldg 102 Surfaces within guidelines for release of area for unrestricted use RIEDLINGER, B A, PANG.J F., ZURAKONSKI.P R Division of Radiological Safety & Safeguards Program 82/09/28 19pp 15408 029
- 8210190473 Forwards IE Insp Rept 70-0754/82-04 on 820910 % 14 No noncompliance noted 800K.H E Division of Radiological Safety & Safeguards Program 82/10/05 DARMITZEL, R W General Electric Co 2pp 15740 220
- 8210200087 Notice of ASLB reconstitution JH Frye, chairman & H Foreman & GA Linenberger, members
 COTTER, B P Atomic Safety and Licensing Board Panel 82/10/14
 2pp 15753 176 24% Fiche 50-070:82/10/14:8210200087
- DOCKET 70-0820 UNITED NUCLEAR CORP , WOOD RIVER JCT , RI
- B2)027021B Forwards well results Sr-90(pCi/L), Apr 1980-Mar 1982 MELGESON, K. A. United Nuclear Corp. B2/06/17 CROW. W. T. NRC - Nu Detailed Affiliation Oliven 2pp 158936 041
- 8210250012 Forwards corrected copy of fertilizer analysis performed & reported on 800718 Analysis consistent w/n ture of crushed apatite fertilizer

 #ELCESON.X A United Nuclear Corp 82/06/22 CROW.W T Uranium Fuel Licensing Branch 2pp 15808 [8]
- 8210270206 Forwards corrected copy of Controls for Environ Pollution, Inc 800718 fertilizer analysis, per 820911 request Fluoride concentration analysis consistent M/nature of crushed apatite fertilizer
- apacite refuliter HELOESON:KA United Nuclear Corp. 82/06/22 CROWWT Uranium Fuel Licensing Branch 2pp. 15836-031
- 8210200104 Forwards "Water Solubility Test Performed on Soll." used by analytical vendor HELGESON, K A United Nuclear Corp. 82/08/18 CROW, W T. NRC Nu Detailed Affiliation Given. Ip. 15747-307
- --8210200106 "Water Solubility Test Performed on Soil," for United Nuclear Corp., Nodriver Junction, RI MUELLER, J Controls for Environmental Pollution, Inc. 82/07/.
 NRC No Detailed Affiliation Given 9pp 15767 308
- 8210250014 Forwards response to NRC comments on licensee 820412 detailed soil decontamination plan Revised plan will not be presented but comments will be incorporated into plan GREGG RJ United Nuclear Corp 82/08/31 CROW.W T NRC No Detailed Affiliation Given 6pp 15808 253
- 821026010B Forwards response to NRC comments on B20412 detailed suil decontamination plan Conduit to river will be surveyed per required criteria Site characterization survey will be forwarded under separate cover GREGOR J United Nuclear Corp B2/0B/31 CRDW, W T NRC No Detailed Affiliation Given 6pp 19808 353
- 8210270213 Forwards response to NRC Comments 1-13 on 820412 "Detailed Soil Decontamination Plan" Revisions will be incorporated into final survey rept OREGO.R J United Nuclear Corp 82/08/31 CRDW.W T NRC No Detailed Affiliation Given App 15834 035
- 8210260038 Forwards site character(ration survey w/addendum re dose commitment data for Lagoon A area soil sample analyses HELCESON,K A United Nuclear Corp 82/09/02 CROW,W T NRC - No Datailed Affiliation Given ip 15809 CDJ
- --B210260041 Exposure tables for Dec 1981

 * Controls for Environmental Pollution, Inc 81/12/31 41pp.
- --8210260049 "Macadam & Soil Statistical Analysis & Evaluation of Analytical Data for Decommissioning of Woodriver Junction Facility " "Controls for Environmental Pollution, Inc 81/07/14 443pp.
- 8210270173 Provides info on & justification for two imperative actions to be taken as preventive maint re roof over main processing bldg & ofc areas & steelwork in process area GREGO,R.J. United Nuclear Corp. 82/09/07 GROW.W.T. NRC No Detailed Affiliation Given 3pp. 15835-329

1

- B210290211 Requests detailed survey rept for maint to be performed on roor & steelworks, including map showing grid sizes & locations & survey results for each grid Time should be scheduled so Region 1 can conduct survey prior to painting CROWHT Uranium Fuel Licensing Branch 82/09/28 GREGO.R J United Nuclear Corp ip 15876 287
- DOCKET 70-0824 BABCOCK & WILCOX CO . LYNCHBURG, VA
- 621022021 Responds to NRC itr re violations noted in IE Insp Rept 70-0824/82-04 Corrective actions cutting & walding permit form revised W/o encl OLSEN.A F Babcack & Nalcox Co 82/08/18 TRDUP.O L Region 2, Office of Director ip 15775 130
- B210150130 Forwards 1E Insp Rept 70-0824/82-05 on 820901-03 No noncompliance noted 01880N.A F Division of Engineering & Technical Programs 82/09/16 ENGELDER.T C Babcock & Wilcox Co 2pp 15698 318
- --8210150136 IE Insp Rept 70-0824/82-05 on 820901-03 No noncompliance noted Hajor areas inspected external & internal radiation control, contamination surveys & source lask testing XARLE-J B. METZGER, J R. BARR, K. Division of Engineering & Technical Programs 82/09/15 4pp 15698 320
- --B210010398 IE Safeguards Insp Rept 70-0894/82-06 on 820909 & 1/ No noncompliance noted Major areas inspected MC-85206 measurement control program (scrap/waste) Rept details withheld (ref 100FR2 790) CLAY, E. L. MCALPINE, E. J. Division of Engineering & Technical Programs 82/09/22 ip \$5572.291
- 8210210194 Forwards IE Safeguards Insp Repts 50-013/82-03 & 70-0824/82-10 on 820930-1001 No noncompliance noted 01880N:A F Division of Engineering & Technical Programs 82/10/11 ENGELOER. T C Babcot & Wilcot Co 2pp 15765 304 24X Fiche: \$0-013, 82/10/15, 8210210194
- --8210210205 IE Safeguards Insp Repts 50-013/82-03 & 70-0824/82-10 on 820930-1001 No noncompliance noted Major areas inspected physical protection of low enriched SNN Details withheld (ref 10CFR2 790) OCCUPE.R. MCGUIRE.D R Division of Engineering & Technical Programs 82/10/15 is 15765-306 24X Fiche 50-013,82/10/15,82/10/10/15
- DOCKET 70-1100 COMBUSTION ENGINEERING, INC . WINDBOR, CT
- 8210060365 Forwards IE Safeguards Insp Rept 70-1100/82-07 on R20824-27 No noncompliance noted MARTIKE, T. Tolyrision of Engineering & Technical Programs 82/09/28 LICHTENBERGER Combustion Engineering, Inc. 2pp 13615,188
- ---8210060370 IE Safeguards Insp Rept 70-1100/82-07 on 820824-27. No nencompliance noted Hayar areas inspected facility organization, operation & mot of matls control sys Details withheld (ref 100FR2, 790) DELCA RATTA.A. GODY.A T Division of Engineering & Technical ms. 82/09/21 19 15615.190

reipt of 8209/0 ltr informing NRC of steps taken to one noted in IE Insp Rept 70-1100/82-06.
Project & Resident Programs. 82/09/29 oring. Inc. ip 13883 100

e violations noted in IE Insp adjustable windows for chemistry labs set at

inc 82/09/10 Resident Programs 2pp.

- DOCKET 70-1113 GENERAL ELECTRIC CO , WILMINGTON, NO
- 8210220518 Advises that groundwater monitoring program will be implemented before 821101 MAKILD.C North Carolina, State of 82/09/15 CROH.W I Urina: 4 Recovery Licensing Branch 1p 15786 085
- B21G150064 Forwards IE Safeguerds Insp Rept 70-1113/82-10 on U2U/UJ-32 No noncompliance noted GIBSON, A.F. Division of Engineering & Technical Programs Bi/G9:21 LONG, J.A. General Electric Co. 2pp 15715-270
- --B210150067 IE Safeguards Insp Rept 70-1113/82-18 on 020/0/-10 to noncompliance noted Major areas inspected measurement control program & followup of previous insp findings Details withheld (ref 10CFR2 790)

 BATES, J. W. BABADDS, J. W. MCALPINE, E. J. Division of Engineering | Technical Programs 82/09/24 ip 15715-271
- 8210270425 Notification of contract execution. Mod 2 to "FIA He ut 5:4 License SNN-1097" Contractor Science Applications, Inc. FLEENOR.C M. Administrative Contracts Branch FIN 19 737 1 82/09/30 DAVIS.J., LDYSEN.P. Office of Nuclear Malerial 4-14ety 1 Safeguards, Director 1p 19803-357
- --8210270428 Mod 2, deobligating unexpended balance of contract Juria issuance of no cost settlement after termination, to 'fla re OE SNM License SNM-1097' "
 ARCHERIC D Science Applications, Inc HAGAN, I & technological Assistance Contracts Branch FIN 0-7337-1 192/09/,80 Jep
- 8210210514 Forwards draft litense conditions re effluent & program nonradiological monitoring requirements Conditions include stack monitoring of fluoride release & groundwater monitoring on nonradiological parameters CROWN T Uranium Recovery Licensing Branch 82/10/00 WAKILD (North Carolina, State of App. 15782 201
- 8210220205 Ack receipt of IE Insp Rept 70-1113/82-20 on Ba091 1 17 N proprietary info Particle Co. B2/10/12 OIBBEAN J DEV25 of Engineering & Technical Programs 1p 15/76 393
- 8210220420 Ack receipt of 820914 itr informing NRG of steps taken torrect violations noted in IC Insp. Rept. 70-1113/D2 JA.
 OLSHINSRIJ A Division of Engineering & Technical Programs
 82/10/12 LONG.J A General Electric Co ip 15780 211
- --8210220427 Responds to NRC 820820 ltr re violations noted in the Rept 70-1113/82-16 Corrective actions meetings between supervisors & radiation technicians conducted & New Survey equipment ordered VAUGHAN,C M. General Electric Co. 82/09/14 (NLGHRGM.), F.A. Division of Engineering & Technical Programs (Rpp. 15/H) 211
- --8210220430 Forwards IE Insp Rept 70-1113/82-16 on 820/26 to 8 v8 to bice of violation OLSHKINBKI, J.A. Division of Engineering & Technical Programs 82/08/20 LONG, J.A. General Electric Co. 2pp 15/80 215
- --8210220437 Notice of violation from insp on 820726 30 t CHARACT A Division of Engineering t Technical Programs 82708740
- --8210220442 IE Insp Rept 70-1113/82-16 on 820726-30 & ORB) C& Noncompliance noted contamination limits exceeded for release of mati to restricted area HOBEY, C M . BARR, K P Division of Engineering & Technical Programs 82/08/19 10pp 13780 218
- 8210220308 Ack receipt of 820930 itr informing NRC of steps tet all correct violation noted in IR Insp Rept 70-113/82-17 OFBON.A F Division of Engineering & Technical Programs B2 LGNG, J A. General Electric Co ip 15778 304
- --8210220320 Responds to NRC 820902 ltm re violation noted in RE Rept 70-1113/82-17 Corrective actions withheld (ref 10CFR2 790)
 VAUDHAN.C M General Electric Co 82/09/30 DL6HINDRI J & Division of Engineering & Technical Programs ip 157/8 35
- DOCKET 70-1143 WESTINGHOUSE ELECTRIC CORP . PITTSBURGH. PA
- 8210150433 Advises that portion of few for Amend 7 to Licence BJ will be refunded
 MILLER, M.O. License Fee Management Branch 82/10/07 MARD],
 Westinghouse Electric Corp. 1p. 15715.360.

SOCKET 70-1151 WESTINGHOUSE ELECTRIC CORP , PITTSBURGH, PA

- E216010189 Ack receipt of LE Safeguards Insp Rept 70-1151/82-16 on 820815-19 No proprietary info FOSTER, H Westinghouse Electric Corp 82/09/10 D'REILLY, J P Region 2, Office of Director ip 15567 312
- 321u270434 Amend II to License SNM-1107, authorizing disposal of matl containing trace quantities of enriched U as of 820818 PAOE, R G Uranium Recovery Licensing Branch 82/10/12 NORDI. A J Hestinghouse Electric Corp. Jp. 15833-281
- --0210270436 Safety evaluation supporting Amend 11 to License StM-110/ redisposal of trace quantities of enriched UBIDINGER, G. H., CRON, M. T. Uranium Recovery Licensing Branch 82/10/12 ip 15033 202

DOCKET 70-1201 BABCOCK & WILCOX CO . LYNCHBURG. VA

- 8210010121 Forwards IE Insp Rept 70-1201/82-13 on 820830-0901 No noncompliance noted GIBSON A F Division of Engineering % Technical Programs 82/09/10 ALTO, R A Babcock % Wilcox Co 2pp 15567 220
- 8210010127 IE Insp Rept 70~1201/82~13 on 820830~0901 No honcompliance noted Major areas inspected health physics procedures, externel & internal radiation controls instrument rajibr, contamination surveys leak testing \$ radiation work permits KAHLELJ B , BARH, K P Division of Engineering & Technical Programs 82709/10 bpp 15567 222
- B210150215 Forwards IC Insp Rept 70-1201/82-14 on B20901-02 No noncompliance noted G1858N:A F Division of Engineering & Technical Programs 62/09/1/ ALTO,R A Babcock & Hilcol Co 2pp 15721 316
- -8210150219 IE Insp Rept /o·1201/82 14 on B20901-02 No noncompliance noted Major areas inspected review of lab GC program & radiochemistry procedures & records EVANS.C D. MONTOGMER.D M. Division of Emergency Preparedness & Operational Support B2/09/15 3pp 15721 318
- a210210216 Forwards IE Safeguards Insp Rept 70-1201/82-1/ on 820929-30 No noncompliance noted G1380N.A.F. Division of Engineering & Technical Programs 82/10/15 ALTO.P.A. Babcock & Milcox Co. 2pp. 15765-301
- --8210210223 IE Safeguards Insp Rept 70 1201/82-1/ on 820929-30 Nu noncompliance noted Major areas inspected general requirements for physical protection of low enriched SW Details withheld (ref (DCFR72 21) ODDE R W MCOUIRL D R Division of Engineering & Technical Programs 84/10/15 ip 15765 303

BOSKET 70-1257 EXXON NUCLEAR CO . INC . RICHLAND, WA

- 6210220025 Advises of issuance of Amend 7 to Liconse 6NM-1227, authorizing sever discharge of process liquids & changing environ monitoring requirements PAGE.R G Uranium Fuel Licensing Branch 82/09/29 MALODY, C W Erron Nuclear Co., Inc. (subs. of Exxon Corp.) 2pp. 15786-301
- --8210220028 Safety evaluation supporting Amend 7 to License SNM-1207 deleting License Conditions 15-17 & revising Section 3 reliquid effluent & monitoring controls SIDINCER.O H . CROW.W T Uranium Fuel Licensing Branch 82/09/29 bp 15786 303
- 8210260389 Forwards IE Sakeguards Insp Rept 70-1257/82-10 on 820920-24 No honcompliance noted NORDERHAUG,L R Division of Radiological Bafely & Safeguards Program 82/10/18 NILEGII,R Exton Nuclear Co / Inc (subs of Error Corp) 2pp 15803 322
- BBIOR60402 IE Safeguards Insp Rept 70-1257/82-10 on B20920-24 No nancompliance noted fajor areas inspected followup actions for closing out notice of deviation: records & rept audits & independent insp Details withheld (ref 10CFR2 790) WIEDER, A V. NORDERHAUGL R. Division of Radiological Safety & Bafeguards Program 82/10/18 ip 15803 326

4

DOCKET 70-1510 NUCLEAR ASSURANCE CORP . ATLANTA, GA

- 8207110023 FQIA request for correspondence between Nuclear Assurance Corp & NRC re 1982 irradiated fuel shipments between Chaik River, Ontario & Savannah River, NC RESNIKOFF, M. Council on Etonomic Priorities 82/06/23 Division or Rules and Records Ip 19849 109
- 8210050430 Responds to FDIA request for correspondence between Nuclear Assurance Corp & NRC re 1982 (readlated flus) shipments between Ontario & NC Forwards App A documents App B documents withheld (ref FDIA Exemption 3) FELTON, J M Division of Rules and Records 82/08/17 RESNIKOFF, M Council on Economic Priorities 3pp 15626 172
- --820420405 Forwards decontrolled version of routs for transport of spent fuel route requested in 811113 ltr Submittal meets 10CFR73 37 requirements for shipment & is approved SHERR.T 8 Material Transfer Safeguards Licensing Branch 82/04/02 DANESE.F L Nuclear Assurante Corp 14pp 15626 207
- --8210050446 Requests revision to route from Alexandria Bay, NY to Savannah River, NC, approved by NRC on 820402 Route change necessary in Byracuse, NY DANESE, F. L. Nuclear Assurance Corp. 82/05/25 Division of Safeguards ip 15626-221
- --8210030451 Forwards "Spent Fuel Route Survey, Syracuse, NY Bypass."
 approving detour around const per 820525 request
 SHERR, T.S. Office of Nuclear Material Safety &
 Safeguards, Director 82/06/03 DANESC, F.L. Nuclear Assurance
 Corp. 1p. 15426-222
- --8210050456 "Spent Fuel Route Survey, Syracuse, NY Bypass " EMERR, 7 6 Office of Nuclear Material Safety & Safeguards, Director 82/06/30 2pp 15626 223
- 8210270423 Addit response to FOIA request for correspondence between Nuclear Assurance Corp & NRC re 1982 feel shipments Forwards documents listed in App A App 8 documents partially withheld (ref FOIA Exemption 3) FELTON, J.M. Division of Rules and Records 82/09/23 RESNIKUFF, M. Council on Economic Priorities Spp. 15849 110
- --8210270427 Confirms 820616 telcon re indefinite delay of six spent fuel shipments from AECL Chalk River facility to DOE Bavannah River facility DANEEE,FL Nuclear Assurance Corp 82/06/16 GODY, A Region 1. Office of Director 1p 15849 [13]
- --8210270429 Confirms 820816 teleon re route approval for reactor fuel shipments between AECL Chalk River facility & DOE Savannah River facility Eight shipments planned w/pussible increase to 11
 DANESE.F L Nuclear Assurance Corp 82/08/17 HILLMAN.C
 Division of Safeguards 2pp 15849 114
- --8204200408 Forwards decontrolled version of route for transport of spent fuel route requested in 811113 ltr Submittal meets 10CFR73 37 requirements for shipment & is approved Info partially withheld (ref FDIA Exemption 3) SHERR.15 Material Transfer Safeguards Licensing Branch 82/04/13 DANESE.F.L. Nuclear Assurance Corp 24pp 19849 116
- --B204220144 Advises that Bill13 request for spent fuel route meets
 10CFR73 37 requirements & is approved Data re initial
 arrangements wilaw enforcement agencies & approved route
 encl Bafeguards info withheld (ref FOIA Exemption 3)
 BHCRR: T B Haterial Transfer Safeguards Licensing Branch
 B2/04/14 DANEBE, F L Nuclear Assurance Corp 32pp 15849 130
- --8210270437 Notifies of plans for series of spent fuel shipments from AECL Chalk River facility to DOE Bavannah River facility Schedule encl DANESE,FL Nuclear Assurance Corp 82/06/03 GODY, A Region 1, Office of Director 2pp 15849 171
- --8210270438 Forwards schedule for addl spent fuel shipments
 DANESE:FL Auclear Assurance Corp 82/08/13 GDDY, A Region 1,
 Office of Director 2pp 15849.173

DOCKET 70-1621 DUQUESNE LIGHT CO , PITTERUROH, PA

8210060020 Forwards Endorsements 59 \$ 51 to NELIA Policy NF-226 & MAELU Policy MF-87, respectively BARNETT, J E Conover & Associates, Inc. Insurance, 82/09/30 DINITZ, I Antstrust & Economic analysis Branch (Utility Finance) 3pp 15615 010

DOCKET 70-1739 TRI-STATE HOYOR TRANSIT CO . JOPLIN, MQ

- 82(0150605 Forwards route overview re planned theck call frequency for shipment of strategic quantity of SNM W/o encl RUTENKROSER.E. Tri-State Motor Transit Co. (subs. of Georgia Pacific Corp.) 82/09/01 HILLMAN.C. NRC - No Detailed Affiliation Given Ip. 15716-334
- ~-B210150609 Submits review of 820901 application for matls safeguard amend HILLMAN,C R Division of Safeguards 82/09/16 MILLER,W D License Fee Management Dranch 1p 15716 335
- DOCKET 70-2116 LAWRENCE GENERAL HOSP , LAWRENCE, MA
- 8210210437 Ack receipt of 820924 itr informing NRC of steps taken to correct violations noted in IE insp Repts 30-01878/82-01 & 70-2136/82-01 Division of Engineering & Technical Programs 89/10/14 NOYES.A W Lawrence General Hosp Lawrence MA 1p 15762 296
- --8210210448 Responds to NRC 620826 ltr re violations noted in Ib Insp. Repts 30-01878/82-01 & 70-2116/82-01 Corrective actions personnel util be monitored following 1-131 therapy & elution & preparation area will be surveyed on daily basis NDVES.A M. Lawrence General Hosp Lawrence.HA 82/09/24 Region 1. Office of Director 2pp 15762 257
- DOCKET 70-2650 ST JOHN'S HERCY MEDICAL CTR . ST LOUIS, MO
- 8210250190 Discusses IE insp of Licenses 24 00794-03 & SNM-1752 on 820927 No noncompliance noted Major areas inspected radiation safety, procedures & representative records, observations, independent measurements & interviews HIEDEMAN, D.G. Division of Project & Resident Programs 82/10/13 FARRELL, J.T. St. Johns Mercy Medical Hosp. St. Louis, MO. 1p. 15787, 342
- DOCKET 70-2748 SCIOTO MEMORIAL HOSP , PORTSMOUTH, DH
- 8207070319 Ack receipt of 820621 itr informing NRC of steps taken to correct violations noted in IE insp of Licenses 34-15938-01, 34-15938-02 b EMM-1789
 SRENIAMBKI.D J Division of Engineering & Technical Programs 92/06/30 CASS.K Scioto Memorial Hosp Portsmouth, DH ip 13734 170
- --8207070324 Responds to NRC 820512 ltr revialations noted in IE insp of Licenses 34-19938-01,34-15938-02 & SNH-1788 Corrective actions implemented procedure to survey dases & sates of injections outside of hasp EMMERT.R M Scioto Memorial Hosp Portsmouth.DH 82/06/21 SRENIAMSKI.D J Division of Engineering & Technical Programs 2pp. 13734 171

DOCKET 70-2789 MISSOURI, UNIV OF. COLUMBIA, MO

- 8210080293 Discusses IE insp of Licenses 24-00513-35 & SNM-1799 on 820915 & forwards notice of violation WIEDEMAN.D Q Region 3. Office of Director 82/10/05 TOLAN.J Missouri, Univ of, Columbia 2pp 15638 311
- --8210080299 Notice of violation from insp on 820915 Noncompliance noted Padiation monitor not functional in battery mode WIEDEMAND O Region 3. Office of Director 82/09/29 ip 15438-313
- DOCKET 70-2792 LOWER BUCKS HOSP . BRISTOL, PA
- 8210080306 IE Insp Findings & Licensee Ack dtd 820916 of Licenses SNM-1800 & 37-06572-02 Insp findings no noncompliance noted * Region 1. Office of Director 82/09/16 ip 15638 123
- DOCKET 70-2873 PUERTO RICO, UNIV OF, MAYAGUEZ, PR
- 8210010231 IE Insp Findings & Licensee Ack dtd 820701 of License SNM-1836 Insp findings no violations observed BROWN,R A Region 2, Office of Director 82/09/Qs 1p. 1556B 247

- DOCKET 70-2942 HARPER-GRACE HOSPS , DETROIT, MI
- B210050204 Ack receipt of B20922 ltr informing NRC of steps taken to correct violations noted in IE insp of Licenses 21-04127-02. 21-04127-08 & SMM-1889 SRENIAMBKI.D J Region 3. Office of Director 82/10/01 (ARA) 1.5 Harper-Grace Hosps Detroit.MI ip 15409 048
- --B210050213 Responds to NRC B2090B ltr re violations noted in 11 irsy of Licenses 21-04127-06 & 21-04127-08 Corrective actions timer accuracy determination made & included in spot checks CARALIS.9 P Harper-Orace Hosps Detroit,MI B2/09/22 SRENIAMSKI.D J Ragion 3. Office of Director ip 15609 biy
- DOCKET 70-2944 DUKE POWER CO . CHARLOTTE, NO
- 8210150617 Application to renew License SM-1885, requesting litense extension to 831231
 TUCKER: H B Duke Power Co. 82/09/07 DAVIS: J O. () Office of Nicle Material Safety & Safeguards: Director CUNNINGHAM: R L. Divasion of Fuel Cycle & Material Safety | Ip 15716 099
- 8210290383 Issues Amend I to License SNM-1805, changing literise expiration date to 831231 or upon conversion of CPPH-84 to DL PAGE, R G Uranium Recovery Licensing Branch 82/10/1/ THEFT H Duke Power Co. 2pp 15845 264
- --8210290392 Reviews 820907 application for Amend 1 to license 'Am | requesting expiration date be extended to 831411 Citension should be granted KETZLAGIAN . CROMANT Uranium Retovery Licensing Branch 82/10/12 Uranium Recovery Licensing Branch 1p 15447 .'A/
- DOCKET 70-2946 LOUISIANA POWER & LIGHT CO . NEW URLLAND. IA
- 6210260003 Forwards Revision I to physical protection plan for type SNM-1886 Revision consists of changes made to plan three on agreements reached during 820624 telcon Revision withheld (ref 100FR2 790) HULLER, G E 1112nois Power Co 62/06/28 BURNLTT, R I Historia Safeguards | p 15814 251
- 8207150432 Forwards updated pages to SNM application is persumbed changes
 MAURIN.L V Louisiana Power & Light Co 82/07/2}
 Nuclear Material Safety & Safeguards, Director in 14(9) 1/2
- --8209150436 Updated pages to SNM | license application | Louisiana Power & Light Co | 82/07/23 | 10pp | 14870 | 1470 |
- --B209150438 Application to extend SNM license until Haterford in received MAURINIC V Louisians Power & Light Co 82/01/04 10814 C Nuclear Material Bafety & Safeguards Director 290 141/44 1
- DOCKET 70-2949 ARIZONA PUBLIC BERVICE CO . PHOENIX. AT
- 8210260363 Forwards Palo Verde Nuclear Generating Stateum physis a security plan Amend 2 in support of 810817 application for SNM licents Amend withheld (ref 10CFR2 770) ANDONINIO C Arizona Public Service Co D2/08/111 (1884 Nuclear Material Safety & Safeguards, Director 19 15814 148)
- DOCKET 70-2955 EDLOW INTERNATIONAL CO . WASHINGTON, DL
- B210210537 Forwards responses to B20520 request for addition of application for SNM license SRAM. A Edlow International Co B2/06/21 SERINI. B: live. Fuel Licensing Branch Bpp [5782-220]
- --8210210543 Application for license to store U hexafivoride en S% max EDLON, J Edlow International Co 82/03/11 PAGE.R Q tar Fuel Licensing Branch 34pp 15782 228
- DOCKET 70-2957 FLORIDA POWER & LIGHT CO . MIAMI, FL
- B2102B0415 Forwards License SNM-1902, Amend 7 to Indemnity Aprel B-76 & safety evaluation PAGE,R 9. Uranium Recovery Licensing Branch 日2/10/14 (吳祖 Florida Power & Light Co 2pp 15859 339

DUCKELED ITEM

- -- 8210283417 License SNM-1902 for FL Power & Light Co. authorizing PAGE, R. G. Uranium Recovery Licensing Branch 82/10/14 Jpp 15859 341
- --8210283421 Safety evaluation to review of 820319 license application t suppls for maths license Application acceptable SERINI, D.L., CROW, W.T. Uranium Recovery Licensing Branch 82/10/14 13pp 15859 344
- DOCKET 70-2948 CLEVELAND ELECTRIC ILLUMINATING CO . CLEVELAND, OH
- G3[026009 Forwards application for SM1 license for storage only of unifradiated reactor fuel % associated radioactive mat1 DAVIDSON DR Cleveland Electric Illuminating Co 82/08/30 DAVIS.J & Office of Nuclear Material Safety & Safeguards, Director
- ~-R2102A9011 Apolication for SMM license for storage only of unirradiated reactor fuel & associated radioactive mat[
 DAVIDSON D R Cleveland Electric Illuminating Co 82/08/30 15814 253

PACKAGING OF RADIOACTIVE MATERIAL FOR TRANSPORT AND TRANSPORTATION OF RADIOACTIVE MATERIAL UNDER CERTAIN CONDITIONS

DOCKET 71-0030 GENERAL ATOMIC CO

- 8210270187 Supple 820623 request for NRC consent re acquisition by GA 210270187 Supply B20823 request for INC. consent re acquisition by Technologies. Inc of licenses hold by GA Co GA Tuchnologies. Inc adopts OA OA program.lopical Rept GA-A13010A, Amend 6 AGNEUL HM GA Technologies. Inc /General Atomic Co 82/08/30 Difice of Nuclear Reactor Regulation. Director 1p 15835 27') Office of Nuclear Reactor Regulation, Director
- DOCKET 71-0481 MONROE X-RAY CO . INC.
- 0210010005 Forwards OA program for pending license, in accordance U/requirements of 1001R71
 HEAD, T C Monroe X Ray Co . Inc 82/07/09 MACDONALD, C E Transportation Brench ip 15577 221 ransportation Branch
- --8210010024 GA program for pending license in accordance w/requirements of 100FR71 • Noncoe 1-Ray Co., Inc. 82/07/09 Spp. 15577 222
- DOCKET 71-5908 MODEL DOT-6M TYPE B. BABCOCK & WILCOX CO
- 8210120331 Forwards Revision 9 to Certificate of Compliance 5908 for Model DOT-6M Type B MACDDNALD,C E Transportation Branch 82/09/13 AUSTIN.M Babtuck MACDONALD, C E Transportation
 Mileor Co 3pp 13689 279
- --B210120384 Certificate of Compliance 5708, Revision 9, for Model HACDONALD C E Transportation Branch 82/09/13 4pp 15489 PB2
- DOCKET 71-5924 MODEL GE-100, GENERAL ELECTRIC CO
- 8210150348 Submits revised certification drawings for GE Model 100.per 820716 Itr Notes consistent w/Model 700 drawings Cask weights listed on drawings should be used to correct weight on Certificate of Compliance 5926 CUMNINGHAM, O E General Electric Co 82/09/07 MACDONALD, Transportation Branch 10pp 15715 343 82/09/07 MACDONALD, C E
- DOCKET 71-5939 MODEL GE-1500, GENERAL ELECTRIC CO
- 8210270057 Forwards revised certification drawings for QE Model 1500 per 820722 itr Changes listed Three aperture cards available CUNNINGHAM G E General Electric Co 82/09/08 MACDONALD. C E Transportation Branch Spp 15836 113
- DOCKET 71-6115 MODEL RIG10-0032, ENERGY, DEPT OF
- 8210280343 Forwards Revision 1 to Certificate of Compliance 6115 for Hadel Rigion-0032 MACDONALD.C E Transportation Branch 82/09/21 BAUER.R H Energy, Dept of 1p 15859 193

- --8210280345 Certificate of Compliance 6115, Revision 1, for Model R1010-0032 MACDONALD.C E Transportation Branch 82/09/21 3pp 15859 194
- DOCKET 71-6346 MODEL FSV-1, GENERAL ATOMIC CO
- 8210250122 Requests registration as user of Model FSV-1 MATHIB.C J Boston Edison Co B2/07/22 MACDONALD.C E Transportation Brench 1p 15778 361
- 8210280322 Forwards Revision & to Certificate of Compliance 6346 for Model FSV-1 MACDONALD,C E Transportation Branch 82/10/01 MDI Technologies, Inc./General Atomic Co. 1p. 15859-046 MDWRY. W R GA
- --8210280326 Certificate of Compliance 6346, Revision 6, for Model FSV-1 MACDONALD, C.E. Transportation Branch 82/10/01 4pp 15859 04/
- 82(0150653 Notification of registration as user of Model FSV-1 in response to 820922 request
 MACDONALD,C E Transportation Branch 82/10/13 MATHIS,C J
 Boston Edison Co to 15715 308
- DOCKET 71-6947 MODEL FSV-9, GENERAL ATOMIC CO
- 8210120146 Forwards Revision 4 to Certificate of Compliance 6347 for Model FSV-3 MACDONALD.C E Transportation Branch 82/10/01 MOWRY.W R GA Technologies, Inc./Oeneral Atomic Co 2pp 15492 171
- --8210120150 Certificate of Compliance 6347 Revision 4 for Model FSV-3 MACDQNALD C & Transportation Branch 82/10/01 App 15692 173
- DOCKET 71-A574 MODEL HN-200, HITTMAN NUCLEAR & DEVELOPMENT CORP
- 8210290439 Requests registration as user of Models GE-1600, CNS-1600. CNS-6-80-2, CNS-8-120, CNS-14-195H, CNS-21-300, HN-600, HN-200 & HN-100, Series S. 1, 2 & 3 MAURIN, L Louisiana Power & Light Co 82/07/07 DAVIS, J Office of Nuclear Material Safety & Safeguards, Director ip 15863 187
- DOCKET 71-6601 MODEL CNS 8-120, CHEM-NUCLEAR BYSTEMS, INC
- 821028038B Responds to 82072/ ltr re cause of defects in cask lid bolt, of CNS-B-120 shipping cask Preliminary investigations determined defects caused during bolt mfg PDPPELL K Chem-Nuclear Systems. Inc. 82/08/25 MACDONALD, C F Transportation Branch 3pp 15859 299
- 8210270438 Requests registration as user of Models GE-1600, CNS-1600, CNS-6-80-2, CNS-8-120, CNS-14-195H, CNS-21-300, HN-600, HN-200 & FIN-100. Series 5.1.2 % 3
 MAURIN, L V Lewisiana Power & Light Co 82/09/07 DAVIS, J Q Office of Nuclear Material Safety & Safeguards.Director 15863 187
- DOCKET 71-6639 MODEL MH-16, ARMY, DEPT OF
- 8210270074 Forwards "SAR for Packaging of TRIGA & MTR Irradiated Furl Assemblies in MK-IA Spent Fuel Shipping 82/09/07 MACDONALD, C E PRICHARD RP Energy Dept of 92/09 Transportation Branch 4pp 15848 109
- --B210270079 Certificate of Compliance 4639, for Model MH-1A ROEDER,J R Energy, Dept of 82/06/18 Zpp 15848:
- --8210270085 "SAR for Packing of TRIDA & MTR Irradiated Fuel Assemblies in MH-1A Spent Fuel Shipping Cask " Fourteen oversize drawings encl Aperture cards available in PDR * Ridihalph, Eggers & Associates 82/05/31 354pp 15848 115
- DOCKET 71-6677 MODEL LP-12, ENERGY, DEPT OF
- 8210280334 Forwards Revision 3 to Certificate of Compliance 6677 for Model LP-12 MACCONALD,C E Transportation Branch, 82/09/17 BTETSON.N Energy, Dept of, 1p 15859 129

- --8210280337 Certificate of Compliance 6677 Revision 3 for Model LP-12 MACDDIALD, C & Transportation Branch 82/09/17 3pp 15859 130
- DOCKET 71~6678 MODEL LP-50, ENERGY, DEPT OF
- 821028033B Forwards Revision 3 to Certificate of Compliance 667B for Model LP-50 MACDONALD.C E Transportation Branch 82/09/17 STETSON.N Energy Dept of 1p 15859 133
- --B210280342 Certificate of Compliance 6678 Revision 3 for Model LP-50
 MACDONALD, C. E. Transportation Branch 82/09/17 3op 15859 134
- DOCKET 71-4698 MODEL NFS-4, MUCLEAR FUEL SERVICES, INC
- 8210290155 Forwards pages inadvertently omitted from 820720 responses to NRC ltr W/o encl JUNNSON.GR Nuclear Assurance Corp 82/09/02 MACDONALD,C E. Transportation Branch 1p 15876-223
- BOCKET 71-6703 HODEL RG-1: GENERAL ATOMIC CD
- --8210120192 Certificate of Compliance 6703 Revision 3, for Model 80-1 MACDONALD.C E Transportation Branch 82/10/01 3pp 15692 213
- DOCKET 71-6745 MODEL FSV-2, GENERAL ATOMIC CO
- 8210280329 Forwards Revision 3 to Certificate of Compliance 6745 for Model FBV-2 MACDONALD, C.E. Transportation Branch 82/10/01 MOWRY, W.R. GA Technologies, Inc. /General Atomic Co. ip. 15859 125
- --8210280333 Certificate of Compliance 6745, Revision 3, for Model FSV-2 HACDUNALD, C & Transportation Branch 82/10/01 3pp 15859 126
- DOCKET 71-900; MODEL IF-300, GENERAL ELECTRIC CO
- B210120138 Forwards Revision 14 to Certificate of Compliance 9001 for Model IF-300 MACDONALD, C E Transportation Branch 82/09/30 BAHSON, D M General Electric Co 2pp 15692 187
- --8210120166 Certificate of Compliance 9001.Revision 14.for Hodel IF-300 MACDDNALD, C E Transportation Branch 82/09/30 8pp 15692 189
- DOCKET 71-9010 MODEL NLI-1/2, NL INDUSTRIES, INC
- 821028044B Requests revision to maint manual covering NLI-1/2 spent fuel shipping casks to further define maint schedule JOHNSON, C.R. Nuclear Assurance Corp. 82/09/09 MACDONALD, C.E. tation Branch ip 15859 121
 - wards Revision 8 to Certificate of Compliance 9010 for ation Branch 82/09/24 JOHNSON, C R
 - · 9010 Revision 8, for Model NL1-1/2 nch R2/09/24 6pp 15690 184
- 82:0150428 Advises that licensing action for amend of Certificate of Compliance 90:10 terminated on 820828 No addl fees required HILLER, W O License Fee Management Branch 82/10/07. JCHNSON, C R Nuclear Assurance Corp Ig 15715 358
- DUCKET 71-9034 MODEL TRIGA-1, DENERAL ATOMIC CD
- B210120169 Forwards Revision 4 to Certificate of Compliance 9034 for Model TRICA-1 MACDONALD.C E Transportation Branch 82/10/01 MOHRY, H E CA Technologies, Inc /General Atomic Co 2pp 15692 197

- --E210120174 Certificate of Compliance 9034 Revision 4 for Model 18104-1 MACDONALD.C E Transportation Branch 82/10/01 3pp 15692 19/
- DOCKET 71-9037 MODEL TRIGA-2, GENERAL ATOMIC CO
- B210120339 Forwards Revision 4 to Certificate of Compliance 903) for Model TRIOA-2 MACDONALD.C E Transportation Granch B2/10/01 MOWRY,W R LA Technologies, Inc./General Atomic Co. 2pp. 15690 177
- ~-8210120340 Certificate of Compliance 9037 Revision 4 for Model 1RiCa MACDDMALD,C E Transportation Branch 82/10/01 3pp 156/0 1/y
- DOCKET 71-9044 MODEL GE-1600, GENERAL ELECTRIC CO
- 821029043B Requests registration as user of Models GE-1600,CNS-12490. CNS-6-80-2.CNS-6-120.CNS-14-195H.CNS-21-300.HN-400.HN-200 & HN-100.Series S.1,2 & 3 MAURIN.L V Louisiana Power & Light Ca 82/09/07 DAVIS.J O Dêrice of Nuclear Material Safety & Safeguards.Director Ip 15863 187
- 8210280382 Requests registration as user of Model GE-1600 BORBT,F J Public Service Co of Coloradn 82/09/08 MACDUNALD,C & Transportation Branch 2pp 15859 257
- B210150691 Notification of registration as user of Model GC-1600 Niresponse to B20908 request MACDDNALD,C E Transportation Branch B2/10/13 BDRST,! J Pub Service (a of Colorado Ip 15715 319
- DOCKET 71-9057 MODEL FPD-100, GENERAL ATOMIC CO
- 8210280311 Forwards Revision 3 to Certificate of Compliance 905/ Fu. Model FPD-100 MACDENALD, C.E. Transportation Branch 92/10/01 MOWRY, H.R. U.A. Technologies, Inc./General Atomic Co. lp. 15839-042
- --8210280316 Certificate of Compliance 7057, Rovision 3, for Hodel Fit MACDONALD, C E Transportation Branch 82/10/01 3pp 13(1):4
- DOCKET 71-9079 MODEL HN-100, SERIES 2 & 2A, HITTMAN NUCLEAR
- 8210260023 Requests registration as user of Model MN-100 Beries .' a SCOTTID J Commonwealth Edison Co 82/08/03 MACDMALD.C i Transportation Branch | 6p 15808 360
- 821029043B Requests registration as user of Models GE-1600.CNB (c.t. CNB-6-80-2: CNB-8-120: CNB-14-193H; CNB-21-300; HN-600; HR-200 & HN-100; Series S. 1, 2 & 3 MANRIN L. V. Louisiana Power & Light Co. 82/09/07 RAVIB; J. G. Office of Nuclear Material Safety & Safeguards, Director to 15863 187
- DOCKET 71-9080 MODEL 9080, HITTMAN NUCLEAR & DEVELOPMENT COMP
- 8210270438 Requests registration as user of Models GE-1600.CNN1-12.CNS-6-80-2:CNS-6-812-300.RN-14-175H.CNS-21-300.HN-600.HN-800 & HN-100.Series S. 1.2 & 3 MAURINI. V Louislana Power & Light Co 82/07/07 DAVIS.J Q Office of Nuclear Material Safety & Safeguards.Director 1p 15963 87
- DOCKET 71-9081 MODEL CN8-1600, CHEM-NUCLEAR BYBTEMS. INC
- 8210290438 Requests registration as user of Models GE-1600, CNS-14 CNS-6-80-2, CNB-6-120, CNS-14-175H, CNB-21-300, HN-600, HH-200 E HN-100, Beries 8, 1, 2 & 3 MAURIN.L V Louisiana Power & Light Co 82/09/07 DAVIB. J Q Office of Nuclear Material Safety & Bafeguards, Director 1p 15863 187
- DOCKET 71-9086 MODEL, HN-100, BERIES 1, HITTMAN NUCLEAR & DEV C
- B21027043B Requests registration as user of Models GE-1600, CNS-1 CNS-6-80-2; CNS-8-120, CNS-14-195H, CNS-21-300, HN-600, HN-200 & HN-100, Series S.1, 2 & 3 HAURIN. L. V. Louisiana Power & Light Co B2/09/07 DAVIS, J. 10ffice of Nuclear Material Bafety & Bafeguards, Director lp. 15863 187

- GOCKET 71-9689 MODEL HM-1008, HITTMAN NUCLEAR & DEVELOP CORP
- 8/10/2004 BB Requests registration as user of Models GE-1600 CNS-160b. CNS-6-80-2. CNS-8-120. CNS-14-175H. CNS-21-300. HN-600, HN-200 & HI-100, Series S. 1. 2. 3. 3. MARTIN, L. V. Louisiana Power / Light Co. 82/09/07 DAVIS, J. G. Miller of Nicelear Material Bafely & Safeguards, Director. 1p. 1986 187
- COLKET 71-9091 HODEL JOA 7 308, GULF NUCLEAR CO
- 5210570430 Requests registration as user of Models GF-1600, CNS-1600, CNS-6 BD-2, CNS-6 120, CNS-14-195H, CNS-21-300, HN-600, HN-200 & RR-100, Serios S, 1, 2 % 3 HAWRING V Light Co 82/09/07 DAVIS, J D GFICE of Nuclear Material Safety & Safeguards, Director Ly 1586 & 1847
- BOCKEF 71 9094 MODEL CN3 11 195-H, CHEM-NUCLEAR SYSTEMS, INC
- 8210/50037 Proquests registration as user of Model CHS 14-195-H HILLER.R 1 Sectemento Municipal Utility District 80/12/24 HACDENALD.C E. Transportation Branch tp 19808-352
- GICKET 71-9090 MIDEL (Nº 21 300, CHEH NUCLEAR SYSTEMS, INC.
- 8702/90478 Requests registration as user of Models GL-1600, CNS-1600, CNS-6-80 2, CNS-8-120, CNS-14 1988, CNS-21-300, EN-600, EN-200 & RAPIDO, Series S. 1, 2 ½ d RAPIDO, Series S. 1, 2 ½ d RAPIDO & Louisiana Hower & Light to Be/09/07 DAVIS, J 9 Drice of Noclear Material Safety ? Sateguards, Director 1p 15063-107
- EDUPET 74 90 M MIDEL UICE 20NC-2 & 2A, UNION CARBIDE CORP
- --Batto-BOMS-Y Curtificate of Compilance 9098, Revision S. for Hodels UCC-ACHC-2 & UCC-ACHC-2A MACDONALD-C F Transportation Branch 82/09/16 3pp 15899 201
- BOOKET 71 9111 HODEC CASE BO-2. CHEH NUCLEAR SYSTEMS, INC.
- 6210270438 Requests requirtration as used of Models OF-1600, CNS-1600, CNS-6 80 ×2 CNS (B-120, CNS-14-199H, CNS-21-300, NN-600, FR7-200 & NY-100, Geries B. L.P. / / HAURING V Louistana Power & Light Co. 82/09/07 DAVIS, J. G. Office of Nuclear Material Safety & Gafeguards, Director. 1p. 15863-187.

- DOCKET 71-9150 MODEL PAT-2, ENERGY, DEPT DF
- 8210070409 Requests relief from or nod to operational controls on air carriers New evidence provides reasonable technical & economic basis for relief PAT-2 package safe by all definitions in any onboard location CAVOLE: R E Energy, Dept of 82/08/18 MACDONALD.C & Division of Fuel Cycle & Material Safety dpp 15637 223
- --8210070410 "Operational Conditions for Pu Air Transportable Packages PAT-1 & PAT-2" 4 Eclow International Co 82/04/22 33pp 15637 233
- --B210070413 "Analysis of Crush Environ for Light Weight framsportable Accident Resistant Containers" MCCCURE, J. D. Sandia Laboratories SANDB0-0763 81/12/31 29µp 15637 272
- DOCKET 71-9151 MODEL HN-100, SERIES 3, HITTMAN NUCLEAR & DEV (GRP
- 8210290438 Requests registration as user of Models GE-1600 CMS-1800, CMS-6-80-2, CMS-8-120, CMS-14-193H, CMS-21-300, HM-600, HM-200 % HM-100 Berres 5, 1,2 & 3 MAURIN, L V Louisiana Power & Light Co 82/09/07 DAVIS, J G Office of Nuclear Haterial Safety & Mafeguards, Director 1p 19863 187
- 8210150687 Notification of registration as user of Model MN-100 Series 3 in response to 820914 request MACDONALD.C E Transportation Branch 82/10/13 MARSHALL.J R Artansas Power & Light Co ip 15715 318
- DOCKET 71-9167 MODEL TYPE B, AMERSHAM CORP
- 8210080225 Application for certificate of compliance to use Type B keg design containers for storage & shipping of up to 25 Ci Amersham mfg Am-241 & beryllium approved special form sources BAOBY: A Amersham Corp 82/08/25 MACDONALD. C NRC No Detailed Affiliation Given 2pp 15663 141
- --8210080232 Forwards payment to replace incorrect funds accidentally included in 820825 application for certificate of compliance to use Type 8 keg design containers for storage & shipping of up to 25 Ci Amerikam mfg Am-241 & beryllium BAOBY, A Amerikam Corp 82/08/26 WEISS.D License fee Management Branch 2pp 15663 142
- --82100B0237 "SAR Keg Design Containers Type B Package " • Amersham Corp 82/08/25 75pp 15463 145
- DDCKET 71-9964 MODEL LP-12-1. ENERGY, DEPT OF
- 8210120349 Forwards Revision 2 to Certificate of Compliance 9964 for Model LP-12-1 MACDONALD.C E Transportation Branch 82/09/24 STETSON, N Energy, Dept of 1p 15690 172
- --8210120352 Certificate of Compliance 9964. Revision 2. for Model LP-12-1 MACDONALD, C E Transportation Branch 82/09/24 4pp 15690 173

- COMMISSION MEETING RECORDS LOCER
- 8210050435 Unofficial transcript of 820910 public meeting w/ACRS in Eluvourso unorriciai transcript or deuriu public Rashington/DC Pp 1-52 4 Commissioners 82/09/10 55pp 15622 164
- 8210060070 Transcript of 820918 affirmation/discussion session in Washington DC Pp 1~3 * Commissioners 82/09/18 7pp 15636 257
- 8210080329 Staff requirements memo informing that Commission was briefed on ORNL rept. "Potential Precursors to Savera Core Qemage" on 820721 Wamage" on 820721 CHILK.S J Office of the Secretary of the Commission M820721A 82/07/22 DIRCKS,W J Office of the Executive Director for Operations ip 15463 292
- 8210120581 Transcript of 820918 public meeting in Washington.DC re FEMA briefing on offsite appraisals program Pp 1-63 Vieugraphs encl. Commissioners 82/09/18 87pp 15685 232
- 8210120599 Staff requirements memo re FEMA 820917 briefing on offsite appraisals program for commercial nuclear power plants FEMA should provide NRC w/info re availability of emergency plans spublic broadcasts in foreign language
 CHILK,S J Office of the Secretary of the Commission, MS2C
 82/09/24 BICKHITL Office of the Executive Director for
 Operations DIRKS,W J Office of the General Countei by MR209170
- 0210220507 Unofficial transcript of 821007 briefing by Regulatory Reform Task Force re legislative proposals in Washington, DC
 - Commissioners 82/10/07 75pp 15786 127
- 8210280402 Addi response to FOIA request for SECY-82-232 & SECY-82-202 Documents listed in App A available in PDR FELTON.J K Division of Rules and Records 82/09/30 BUCKLEG.R Affiliation Unknown 2pp 15889 101
- --8210190198 Staff requirements memo re 820701 affirmation session concerning SECY 82-202 on amend to 10CFR140 9, "Financial Fretection Requirements & Indemnity Agreements " Chjections to publication of apps as reg guides due by 820719 CHILM.8 J Office of the Secretary of the Commission MB20701 82/0706 DRCMS, W J Office of the Executive Director for Operations 2pp 15859 106
- 8210270393 Transcript of 820929 public meeting on 8ECY-82-352 rs GA in Washington, DC Pp 1-85 Marked-up SECY-82-352 encl PALLADINO, N : OILINGKY, V : AHEARNE, J : Commissioners 82/09/29 146pp 15865 268
- 8210270400 Unofficial transcript of B20730 public affirmation/ discussion & vote in Washington, DC Pp 1-3 Commissioners 82/07/30 App 15866 329
- ACRS ADVISORY COMMITTEE ON REACTOR BAFEGUARDS
- 8207180066 Forwards edited version of draft on pressurized thermal shock Wisubstantive changes proposed
 KOUTB.H Brockhaven National Laboratory KOUTB.H ACRS — Advisory
 Committee on Reactor Sefguerds 82/OS/10 IGNE,E ACRS — Advisory
 Committee on Reactor Sefguerds 82/OS/10 IGNE,E ACRS - Advisoru
- 8207180080 Comments on util group position per 820630 request ATMB issue remains unresolved because of difference between NRC estimate of ATMB risk & risk preferred by industry DAVIB.PR ACRB Advisory Committee on Reactor Safeguards. 82/08/24. BDEHNERT,P ACRB Advisory Committee on Reactor Safeguards. 82/08/24. BDEHNERT,P ACRB Advisory Committee on Reactor Bafeguards. 3pp. 13832 043.

- 8208270011 Comments on ACRS Subcommittee on Human Factors 82090/ meeting Planned research program lacks in basic generic research SALVENDY, O ACRS - Advisory Committee on Reactor Safeguards SALVENDY, O Purdue Univ 82/09/09 FISCHER, D ACRS - Advisory Committee on Reactor Safeguards 4pp 13852 034
- 8208290012 Comments on ACRB Bubcommittee on Human Factors Safety integrated program plan Approx levels of effort to areas & at major units within areas need to be clearly shown BUCK.J R Iowa, Univ of BUCK.J R ACRS ~ Advisory Committee on Reactor Safeguards 82/09/13 WARD,D ACRS ~ Advisory Committee on Reactor Safeguards 82/09/13 WARD,D
- 8208290017 Summarizes 269th ACRS meeting on 820909-11 in Washington. DC 2082/001/ 30mmariss 2076 ACRS meeting on 02/07-11 in washing proposed safety goals: radioactive math packaging for transport, testing requirements for diesel generators & integrated human factors program plan
 SHEMMON, P. ACRE. Advisory Committee on Reactor Safeguards
 SL-0278 82/09/21 PALLADINO, N. J. Commissioners. 3pp. 1 15449 236
- 8208290019 Forwards comments on util group response to NRC proposal for raducing ATHS sequences Meeting planned for 821001 MUELLER.C J Argonne National Laboratory MUELLER.C J ACRS ~ Advisory Committee on Reactor Safeguards 82/07/14 BOEHMER7.P ACRS ~ Advisory Committee on Reactor Safeguards 8pp 15852 001
- 8208290026 Dutlines two approaches for evaluating seismic margins consultants to approaches for evaluating seismic margi available to accomplish safe shutdown following earthquake of greater severity & lower liklihood than SSE Assessment of margins in terms of risk singularity recommended ZUDANS, Z Franklin Institute/Franklin Research Center ZUD/ ACRB - Advisory Committee on Reactor Safeguards 6pp 158: ZUDANS, Z 15851 356
- 8210010464 Transcript of ACRB Subcommittee on Reactor Operations 820929 meeting in Washington, DC Pp 1-268 Supporting documentation
 - ACRS Advisory Committee on Reactor Safeguards 82/09/29 370pp 15571 00B
- 8210040080 Transcript of ACRS Metal Components Working Group 820930 meeting in Washington, DC Pp 1-268 Supporting documentation # ACRB - Advisory Committee on Reactor Bafeguards B2/09/30 344pp 15583 195
- 8210050435 Unofficial transcript of 820910 public meeting w/ACRS in Washington.DC Pp 1-52 * Commissioners 82/09/10 55pp 15622 164
- B210120149 Transcript of 270th ACRS general meeting on B21007 in Washington DC Pp 1-267 Viewgraphs and s ACRB Advisory Committee on Reactor Bafeguards B2/10/07 416pp 15656-083
- 8210130157 Transcript of ACRS 270th general meeting on 821008 in Washington, DC Pp 268-399 Supplemental info encl # ACRS Advisory Committee on Reactor Safeguards 82/10/08 194pp 13697:087
- 8210210324 Ack receipt of 820914 views on BECY-82-001A, "Proposed Commission Policy Statement on Severe Accidents & Related Views on Nuclear Regulation." DIRCKS H J Office of the Executive Director for Operations 82/09/27 SHEWMON, P ACRB - Advisory Committee on Reactor Safeguards App 15774-315.
- 8210260119 Transcript of ACRS Subcommittee on ATMS 821022 meeting in Washington DC Pp 1-332 Supporting documentation encl # ACRS Advisory Committee on Reactor Safeguards. 82/10/22, 404pp. 15800:001

- 82(0270210 Transcript of ACRS Subcommittee on Extreme External Phenomena 821022 meeting in Santa Monico CA Pp 352-703 ACRS ~ Advisory Committee on Reactor Safeguards 82/10/22 350pp 15826 034
- 8210270217 Transcript of ACRS Subcommittee on Extreme External Phenomena 821021 meeting in Santa Monsca.CA Pp 1-331 * ACRS ~ Advisory Committee on Reactor Safeguards 82/10/21 394pp 15825 040
- 8210270371 Summary of ACRS Subcommittee on Reactor Radiological Effects 820720 meeting in Washington, DC re-methods for reducing radiation exposure, exposure histories at PWRS & status of RURREG-0761. "Radiation Protection Plans for Licensees"

 ACRS Advisory Committee on Reactor Sereguards 82/09/17 * ACRS - Advisory Committee on Reactor Safeguards 82/09/17
 ACRS - Advisory Committee on Reactor Safeguards 17pp 15835 006
- 6210270375 Summary of ACRS Subcommittee on Reactor Radiological Effects 2 Site Evaluation 820623 joint meeting in Washington, DC restatus of revision to 10CFR20. "Stds for Protection Against Radiation"

 ACRS Advisory Committee on Reactor Safeguards 82/08/23 ACRS Advisory Committee on Reactor Safeguards 19pp 15835 237
- 8210270378 Summary of ACRS Subcommittee on Safety Research Program 820707 meeting in Washington, DC re research program & budget for FYB4-85
- ACRS Advisory Committee on Reactor Safeguards 82/08/11
 ACRS Advisory Committee on Reactor Safeguards 19pp 15835 256
- 8210270385 Summary of ACRS Subcommittees on Reactor Radiological Effects & Site Evaluation 820609 joint meeting in Washington, DC re proposed FY84-85 research programs & budget * ACRS - Advisory Committee on Reactor Safeguards 82/08/09 ACRS - Advisory Committee on Reactor Safeguards 14pp 15833 343 budget
- 8210270404 Summary of ACRS Subcommittee on Waste Mgt 820608 meeting in Washington, DC to review "DDE Public Draft of Natl Plan in Washington, DC to review "DQ Public Draft of Natl Plan for Siting High Level Haste Repositories & Environ Assessment Review " 4 ACRB - Advisory Committee on Reactor Safeguards 82/08/09 ACRS - Advisory Committee on Reactor Safeguards 17pp 15833 251
- 8210270420 Summary of ACRS Subcommittee on Safety Research Program 820402 meeting in Washington DC re research program & budget
 - ter FY84-85 for Fideria * ACRB - Advisory Committee on Reactor Bafeguards 82/07/23 ACRS - Advisory Committee on Reactor Safeguards 20pp 15833 312
- 8210270424 Summary of ACRS Subcommittee on Human Factors 820706 meeting in Washington,DC re FY84-85 research program & budget & corments on long range research plan
 # ACRS Advisory Committee on Reactor Safeguards 82/09/13
 - ACRS Advisory Committee on Reactor Safeguards 37pp 15834 263
- 8210280044 Summary of ACRS Ad Hoc Ketal Components Subgroup 820511-12 meetings in Washington DC repressurised thermal shock
 - problem
 # ACRS Advisory Committee on Reactor Safeguards 82/07/27
 ACRS Advisory Committee on Reactor Safeguards 17pp 15862 336
- 8210280059 Transcript of ACRS Subcommittee on SEP 821026 meeting in Washington, DC Pp 1-292 Supporting documentation encl # ACRS Advisory Committee on Reactor Sefeguards 82/10/26 433pp 15841 043 453pp
- 8210290011 Transcript of ACRS Subcommittee on SEP 821027 hearing in Washington, DC Pg 293-509 Supporting documentation encl # ACRS - Advisory Committee on Reactor Safeguards 8 82/10/27 335pp 15955 354

mic Safety Margins Research Program Review ter presentation provided good involved w/correlating sarthquake assignments HAXMELL, J. C ACRS - Advisory /02/14 GRRENT, T D ACRS -ards 7pp 15877 306

> | establishment of joint proposed mads Hogestinns

MARTINEZ.FP Spain ip

- --8206060015 Requests joint program to resolve approval of mods to Westinghouse Model D-3 steam generators & followup evaluation during operating conditions MARTINEZ,F P Spain 82/05/27 PALLADINO,N J Communications MARTINEZ:F P Spain 82/05/27 PALLADINO.N J Commissioners 2pp 15624 050
- 8206200091 Responds to 820629 inquiry re discussions between NRC & LOS on requirements for site characterization of potential high level waste repositories No negotiations to relax requirements have taken place LADINO,N J Commissioners 82/07/29 MATHESON,S M Utah, Stat 4pp 19624 052 PALLADING, N J
- --8206270016 Requests verification as to occurrence of informal negotiations w/DOE to relax waste repository requirements of NATHESIN 5 M Utah, State of 82/09/29 PALLADING.N J Commissioners 2pp 15684-056
- 8206200097 Responds to 820602 itr proposing extension of current preliminary design approvals for nuclear power plant designs until reactivation under new guidelines Standardization of designs is Vital component to viable program PALLADIND,N J Commissioners 82/07/29 WALSKE, C Atomic Industrial Forum 2pp 15512 302
- --8204060013 Requests that NRC develop & implement new guidelines re preliminary design approval extensions & take action to preliminary design approval extensions & take action to extend administrative approvals that have expired until activation of new guidelines WALSKE, C. Atomic Industrial Forum 82/06/02 PALLADING, N. J. Commissioners 2pp 15512 303
- --8209270377 Discusses extension of applicability period for previous issued preliminary design approvals Resources already expended should be preserved & standardization program used effectively TMI-related safety issues must be addressed QIBBS.D.C. Atomic Industrial forum Gi/O5/28 DIRCKS.W. J Office of the Executive Director for Operations 2pp 155
- 8206270053 Forwards Science Mgt Corp/DRNt interim rept, "Fresibilit Licensing Nuclear Util Managers & Officers " Licensing requirements should not be established for managers & senior officers W/O encl PALLADINO.N J Commissioners FIN 8-0764-1 82/10/04 O'NEILL. TP House of Rep . Speaker of the House 6pp 13074::
- --8210270003 Forwards summary of selected US govt agency licensing programs & Science Mgt Corp/ORNL. "Feasibility of Licensing Nuclear Util Managers & Officers " Licensing requirements should not be established for managers & senior officers
 PALLADING, N J Commissioners FIN 8-0764-1 82/10/04
 Senate, President of the Senate 9pp 15876 335
- --8210290006 "Feasibility of Licensing Nuclear Util Managers & Off SELBYID , BARTINE D E 81/12/17
- 8206270059 Accepts invitation to serve as chairman of 1980 combin federal campaign, w/PO Norry as vice-chairman PALLADING, N J Commissioners 82/09/16 LEWIB, D Transportation, Dept of ip 15722, 251
- 82:0150659 Requests apportunity for members of public to comment following full-scale joint exercises involving licenses. state & local agencies
 AHEARNE.J F Commissioners 82/09/14 OIUFF
 Emergency Management Agency 2pp 15716 348 GIUFFRIDALL O Feder.
- 8210290423 Public version of weekly info rept for wh ending 8205 REHM, T. A Office of the Executive Director for Operations 82/09/30 49pp, 15863 190

CONTRACT NRC CONTRACTS AND MODIFICATIONS

- 8210040001 Notification of contract execution "LA Offshore Radiological License Survey," awarded to LA Dept of Natural MCNULTY:A Purchasing Section FIN 8-8703 NRC-05-82-832, 82/09/23 BLAMA.J., YACZKO.C Program Support Branch 1p.
- ---B210040002 Contract "LA Offshore Radiological License Burvey to LA Dapt of Natural Resources.

 SHONEAUX.F.P. Louisiana. Stats of SMITH.P. A Administration of Contracts Branch. IN 8-8703 NRC-05-82-252 B2/09/23

- 82;CO40003 Notification of contract execution "Maint & Operation of Local Public Document Rooms (LPDRs)," awarded to Phoenix:AZ Public Library LITTLE,H Purchasing Section NRC-10-82-497 82/09/22 FELTON,J N . BOUDER J Division of Rules and Records
- --8210040004 Contract "Maint & Operation of Local Public Document Rooms (LPDRs)," awarded to Phoenix, AZ Public Library COLLEY, J A Phoenix, AZ SMITH.P A Administrative Contracts Branch NRC-10-82-677 82/09/22 9pp 15577 253
- B210940410 Notification of contract execution. Mod 5 to "Technical Assistance in Support of NRC Reactor Licensing Actions Program 2 " Contractor Science Applications, Inc FLYRX, M Technical Assistance Contracts Branch NRC~03-B2-096 B2/09/15 EISENNUT. D 0 . SILVER, H Division of Licensing ip 15597 202
- ~-B210040412 Mod 5, incorporating award fee darned for period Mar-May 1982.to "Technical Assistance in Support of NRC Reactor Licensing Actions Program 2"
 4 Science Applications, Inc. HAGAN, T.F. Technical Assistance Contracts Branch NRC-03-82-096 82/09/15 2pp
- 8210050501 Notification of contract execution, Mod 3 to "Unsaturated eloupusus Notification or contract execution.Mod 3 to "Unsaturated Flow & Transport Through Fractured Rock re High Level Haste Repositories " Contractor Univ of AZ JACOBS: A Research Contracts Branch FIN B-7291 NRC-04-81-224 82/09/20 BATSON.W. NICHOLSON.T J Office of Nuclear Regulatory Research, Director 1p 15626 234 Office of Nuclear Regulatory
- --B21005050B Mod 3, changing reporting requirements, to "Unsaturated Flow & Transport Through Fractured Rock re High Level Waste Repositories " CARRISE Arisona, Univ of GUSTAVE,R P Research Contracts Branch FIN 8-7291 NRC-04-81-224 82/09/20 4pp 15626 235
- 8210030916 Notification of contract execution. Mod 6 to "Memphis Area Regional Seismic Network" Contractor Memphis State Univ JACOBS, A Research Contracts Branch FIN B-6276 NRC-04-78-200 62/097/3 FOREMAND. W. HURPHY. A Office of Nuclear Regulatory Research. Director ip 15626 354
- --8210050521 Ltr contract.NRC-04-78-200. "Momphis Area Regional Beismic Natuork." Mod 6. increasing amount of funds Receipt ack by TO Carperter on 820830 GUSTAVE.R.P Research Contracts Branch FIN B-6276 NRC-04-78-200 82/08/19 TRENKIN 8 Memphis State Univ. 1p
- 8210050525 Notification of contract execution.Mod 3 to "NGS Calibr Heasurement Assurance Program to Support NRC Third Pilot Study Test of Personnel Dosimetry Processors " Contractor NES NRC-01-B0-023
- CUSTAVE:R P Research Contracts Branch. FIN 8-7103 NRC-01-80-82/09/14 FOREHAND,W , DERNIB,N Office of Nuclear Regulatory Research, Director in 15626 376
- --8210050530 Mod 3 extending period of performance to 830731 at no addl cost, to "NBS Calibr Measurement Assurance Program to Support NRC Third Pilot Study Test of Personnel Dosimetry Processors "
 BREEVE, D Commerce, Dept of, National Bureau of Standards
 OUGTAVE, R P
 Research Contracts Branch. FIN P-3000
 - OUGTAVE.R P Research Contracts Branch. FIN B-7103 886-01-80-023 62/09/14. 1p 15626 357
- 8210060420 Notification of contract execution "Const & Calibr of Br-90 Irradiator for Multiple Dosimeter Irradiations, " awarded to HAGEY, H Research Contracts Branch. 82/09/20 FOREHAND, U. DENNIS W. FIN 8-8285 NRC-04-82-024 82/09/20 FOREHAND, W. DENNIB. N. Office of Nuclear Regulatory Research, Director 19 13636 243
- --8210060424 Contract: "Const & Calibr of Br-90 Irradiator for Multiple Desinater Irradiations:" awarded to Univ of MI MATTHERB: C W Michigan, Univ of MORTON, K V Research Contracts Branch FIN 8-8285 NRC-04-82-024 82/09/20. 9pp 15636:244
- 8210070017 Notification of contract execution. "Reviewing Hydrologic Investigations of Baselt Waste Isolation Project (BMJP), Project B." awarded to Golder Associates Inc MILEBLE B Technical Assistance Contracts Branch FIN B-7373-2 NRC-02-B2-045, 82/07/20. DAVIB.J., JOHNSON, R Office of Nuclear Material Bafety & Bafeguards, Director. ip 15646:304
- --B210070021 Contract: "Reviewing Hydrologic Investigations of Besalt Waste Isolation Project (BHIP), Project B. " awarded to Colder Associates, Inc. VEBTI-L J Colder Associates. MATTIA-M, J Technical Assistance Contracts Branch FIN 8-7373-2 NRC-02-82-045 82/07/20, 36pp

- 8210070153 Notification of contract execution. Mod 3 to "Fuel Cycle Analysis - Spain " Contract execution.Mod 3 to "Fuel Cycle Analysis - Spain " Contractor Nuclear Assurance Comp MCMNLTY.A Administrative Contracts Branch FIN B-7374-2 NRC-02-82-048 B2/08/13 BROWN.R S . THOMAS, B H Program Support Branch Ip 15445 004
- --B210070186 Mod 3.deobligating funds to "Fuel Cycle Analysis Spain "
 SMITH.R L Nuclear Assurance Corp REBELLO, J & Division of
 Contracts FIN 8-7374-2 NRC-02-82-048 B2/08/13 ip
- 82:0070456 Notification of contract execution "ADP Planning Assistance:" awarded to Dept of Air Force MILES.E B Technical Assistance Contracts Branch FIN B-8810 NRC-43-82-321 82:09/17 FROST.A Office of Resource Management. Director 19 13644 325
- --8210070459 Contract "ADP Planning Assistance," awarded to Dept of Air Force RUPP, W A RUPP.W A AIT Force, Dept of MATFIA. P FIN D-BBIO NRC-33-82-321 82/09/17 MATFIA.M J D 12/09/17 15pp Division of Contracts 15644 326
- 8210080004 Notification of contract execution. Mod 3 to "Resolution of Shipper-Receiver Differences" Contractor PNL MOLLETT. 8 Research Contracts Branch FIN II-8103 NRC-01~81-012-0 82/09/21 Farenanch Regulatory Research
- --8210080009 Mod 3, adding no-cost extension from B20723 to 0823 to,
 "Resolution of Shipper-Receiver Differences"

 HAVERFIELD: A J Battella Memorial Institute, Pacific Northwest
 Laboratory QUSTAVER P Research Contracts Branch FIN 8-8103
 (NRC-01-81-012-0 82/09/21 p 13669 352
- 8210080012 Notification of contract execution. Mod 4 to "Seismicity & Earthquake Hazard Research in Northern AL" Contractor Ocological Survey of AL. Univ of AL Veological durvey of ALJUNIV of AL HOLLETT, B. Research Contracts Branch FIN B-6674 NRC-04-80-220 82/09/21 DATSON,W. MURFNY,A. Office of Nuclear Regulatory Research, Director 1p 15669 353
- --8210080022 Mod 4, adding funding for equipment purchases for use under previously approved scope to: "Beismicity & Earthquake Hatard Research in Northern AL "
 MANCINI.E A Alabama, Univ of, GUSTAVE.R Research Contracts
 Branch FIN B-6674 NRC-04-80-220 82/09/21 1p 15669 354
- 8210120321 Notification of contract execution, Mod 8 to "Development & Implementation of Flow Analysis Sys Based on Synthetic Aperture Ultrasonic Imaging Technique" Contractor SHRI MOLLETT. 8 Research Contracts Branch FIN 8-3605 NRC-09-77-145 82/09/15 FOREHAND, W. MUSCARA, J Géfice of Nuclear Regulatory Research, Director ip 12642 218
- --B210120330 Mod 8, extending period of performance to 830930 & increasing funding, to "Development & implementation of Flow Analysis Based on Synthetic Aperture Ultransonic Imaging Technique, " Technique... SPRENCELL'J F Bouthwest Research Institute GUBTAVE,R Research Contracts Dranch FIN 8-3605. NRC-04-77-145 15692 219
- 8210120338 Notification of contract execution, Mod 2 to "Habash Valley 8elsmic Profile " Contractor Purdue Research Foundation WOLLETT.8 Research Gontracts Brench FIN 8-7223 NRC-04-80-224 82/07/22 BATSON.W , ZURFLEUH.E Office of Nuclear Regulatory Research, Director 1p 15691 051
- --8210120342 Mod 2.extending period of performance to 830907.to "Wabesh Valley Belsmic Profile" og GRENKORN, R. A. Purdue Research Foundation GUSTAVE.R.P. Research Gontracts Branch FIN 8-7223 NRC-04-80-224 82/09/22 Ip
- 8210120347 Notification of contract execution. "Reviewing Hydrogeologic Investigations of NV Test Site (NTS)-Project D. awarded to GeoTrans. Inc WIGGING.E Technical Assistance Contracts Branch FIN B-7377-2 NRC-02-82-047 82/09/29. DAVIS.J., VERMA, T Defice of Nuclear Material Bafety & Safeguards, Director ip 15691 061 FIN 8-7377-2
- ~-8210120350 Contract "Reviawing Hydrogeologic Investigations of NV Test Site (NTB) *Project D." awarded to GeoTrans. Inc. HERCER, J W geotrans. Inc. MATTIA: M J Division of Contracts FIN 8-7377~2 NRC-02-82-047 82/09/29, 37pp 15691, 062

RYPLITATIONS INC FLYNN, M Technical Assistance Contracts Branch FIN 8-8622 NRC-03-82-131 82/09/28 EISENHUT, D Q , BILVER, H Division of Licensing 1p 15690 340

- --B210120357 Mod 2.redefining tasks.extending delivery date of draft technical evaluation rept & increasing contract amount to.

 "Value-Impact Analysis of Recommendations re Steam Generator Tube Degradations & Rupture Events "
 FINDLEY.D E Science Applications, Inc HAGAN, T F Division of Contracts FIN 8-9622 NRC-03-82-131 82/09/28 2pp Contracts (5690 341
- 82(0)2036) Notification of contract elecution Mod 3 to "Economic Assistance in Connection w/Antitrust Hearings"

 Contractor JH Kuhlman HOLEAREN.T Technical Assistance Contracts Branch NRC-03-75-097 82/10/05 PENTON DE CONTRACTOR FIN 8-5494 NRC-03-75-097 82/10/05 DENTON.H R Office of Nuclear Reactor Regulation, Director ip 15690 247
- --8210120362 Mod 3.deobligating funds.to "Economic Assistance in Connection w/Antitrust Hearings " KUHLMAN.J H Kulhman. J M FIN B-5494 NRC-03-75-097 B2/10/05 Ip 15670 248
- 8210120363 Not: #1cation of contract execution. Mod 7 to "Study of Paleonoic Stratugraphy in New Modrid Area of MS Embayment "
 Contractor Univ of KY Research Foundation
 SILVIS.R M Research Contracts Branch FIN 8-9972 NRC-04-76-321
 82/09/20 BATSON.W STEUER.N Office of Nuclear Regulatory
 Research, Director 1p 15690 245
- --8210120364 Ltr Contract NRC-04-76-321. Mod 7. deobligating funds, to "Study of Paleozoic Stratigraphy in New Madrid Area of MS Embayment " QUSTAVE.R P Research Contracts Branch NRC-0* CARTER.R Kentucky, Univ of 1p 15690 246 NRC-04-76-321 82/06/08
- 82(0120365 Notification of contract election "Purchase of BSAM-1 Assay Neters for Region 2." awarded to IRT Corp EDGEWORTH.P J Administrative Contracts Branch NRC-29-82-721 82/09/16 STOHR.J P. MONTGOMERY.D H Division of Emergency Preparedness & Operational Support 1p 15690 222 "Purchase of BSAM-100
- --B210120366 Contract "Purchase of BSAM-100 Assay Meters for Region 2." * IRT Corp MATTIA: M J Administrative Contracts Branch NRC-29-82-72: 82/09/16 82pp 15690 223
- 82(0120391 Notification of contract execution "Reviewing Hydrogeologic Investigations of NV Test Bite (NTB)-Project C," awarded to William-Robinette & Associates, Inc Wildgins, E. Technical Assistance Contracts Branch. FIN 8-7377-2 NRC-02-82-046 82/09/30 DAVIS, J. VERMA, T. Office of Nuclear Material Safety & Safeguards, Director. Ip. 15689 242
- ---8210120401 Contract "Reviewing Hydrogeologic Investigations of NV Test Site (NTS)-project C," awarded to Williams-Robinette Associates, Inc HATTIA, N J Technical Associates, Inc HATTIA, N J Technical Assistance Contracts Branch FIN 8-7377-2 NRC-02-82-046 82/09/30 36pp 15689 243.
 - i of contract execution. "Maint & Operation of Rooms (LPDRs)." awarded to Appling
 - stive Contracts Branch NRC-10-82-714 SOUDER, J Division of Rules and Records

of Local Public Document Rooms ibrary: OA 4 Administrative Contracts

- 8210120427 Notification of grant execution, Mod 2 to "Aerospace~ lili2042/ Notification or grant execution mod 2 to "Aerospace" Electric Power Morkshog Conference on Commercial Nuclear Power " Orantee American Inst of Aeronautics & Astronautics HCDERMOIT, D Research Contracts Branch FIN 0-1005 RRC9-04-81-002 82/09/29 RIBL Office of Nuclear Regulatory Research, Director 1p 15671 159
- --8210120432 Mod 2.extending no-cost period of performance to 821231,t
 "Agrospace-Electric Power Workshop Conference on Commercial Nuclear Power | BRUCE, W R American Institute of Aeronautics & Astronautics MORTON, K V Research Contracts Branch FIN G-1005 NRCO-04-81-002 82/09/29 1p 15471 140
- 82(0120436 Notification of contract execution "Bipassaya Using Resource Tonization Spectroscopy," awarded to Atom Sciences, HAGEY, H Research Contracts Branch FIN D-8122 NRC-04-82-021 82/09/27 FOREMAND, N NEEL, R Office of Nuclear Regulatory Research, Director 1p 15671 167
- -- 8210120440 Contract "Bioassays Using Resource Ionization Branch FIN B-8122 NRC-04-82-021 82/09/27 15pp 15671 168
- 8210120454 Notification of contract execution, Mod 1 to "Reviewing Hydrologic Investigations of Basalt Waste Isolation Project (BMTP), Project B " Contractor Colder Associates, Inc. FLEENOR: C Technical Assistance Contracts Branch FIN 8-7373-2 NRC-02-82-045 82/09/22 DAVIS, J. VERMA, T R Office of Nuclear Material Safety & Bafeguards, Director ip 15671 207
- --8210120458 Mod 1 increasing funds to "Reviewing Hydrologic Investigations of Baselt Haste Isolation Project (BWIP), Project B " WEST.L J Golder Associates HAGAN, TF Technical Assists Contracts Branch FIN 8-7373-2 NRC-02-82-045 82/09/22 Technical Assistance
- 8210120467 Notification of contract execution, Mod 4 to "US Army Corp! of Engineers Geotechnical Assistance" Contractor US Army Corps of Engineers FLEENOR, C Technical Assistance Contracts Branch NRC-02-01-036-82/09/24 DAVIS, J. PRESTHOLT, P Office of Nuclear Material Bafe! & Bafeguards, Director ip 15672-001
- --8210120471 Mod 4 revising reporting requirements extending period performance to 830930 & changing project officer to "UB Army Corps of Engineers Geotachnical Assistance"

 KAVANAUGH.P. F. Army Dept of, Corps of Engineers HAGAN.T.F.

 Tachnical Assistance Contracts Branch NRC-02-81-036 B2/09/24

 3pg 13672 002
- 8210120483 Notification of grant execution "Horkshop on Strong-Orov Motion Simulation & Engineering Applications," awarded to Earthquake Engineering Research Inst MCDERMOTT, D. Research Contracts Branch FIN 0-1038 NRC-0-04-82-007 82/09/29, BATBON, H. MURPHY, A. Office of Nucle Regulatory Research, Director Ip 15672 053
- --8210120488 Orant: "Workshop on Strong-Oround Motion Simulation & Engineering Applications," awarded to Earthquake Engineering Research Inst. SCHOLL, E Earthquake Engineering Research Institute. MORTON, K V Research Contracts Branch. FIN G-103B NRC-G-04-82-007 82/09/29 2pp 15672 054,
- 8210120490 Notification of contract execution "Maint & Operation of Local Public Document Rooms (LPDRs)" awarded to Joseph Hann 82/09/27.
- --8210120494 Contract "Maint & Operation of Local Public Documents Rooms (LPDRs)" gwarded to Joseph Mann Library HEITKEMPER, B M. Two Rivers, WI BMITH.P. A Administrative Contracts Branch NRC-10-82-707. 82/09/27 9pp 13672 057
- 8210120497 Notification of contract execution. Task Order 25. "Techn Assistance to Support NRC IE Personnel in Investigations of Incidents." awarded to Parameter. Inc HOLLETT.8, Research Contracte Branch FIN 8-1302, NRC-03-82-24. B2/09/10 BLAHA.J., LAUDAN.W Director's Office Office of Inspection and Enforcement, ip 13672-072,
- --8210120508 Ltr Contract NRC-05-BQ-249, Task Order 25, "Technical Assistance to Support NRC IE Personnel in Investigations of Incidents," awarded to Parameter Inc OUBTAVER P Research Contracts Branch. FIN 8-1902 NRC-05-B2-249. 82/09/07. LOFY, R A Parameter Inc 2pp 15672, 073.

- E210120510 Notification of contract execution "Maint & Operation of Local Public Document Rooms (LPDRs)," awarded to Exeter,NH ruels Library Little, H. Administrative Contracts Granch NRC-10-82-712 82/09/30 FELTON, J.M., BOUDER, J. Division of Rules and Records Public Library 15672 081
- --82(0)20517 Contract "Maint & Operation of Local Public Document Rooms (LPDRs)," awarded to Exeter.NH Public Library GLETTUM.P Exeter.NH SHITH.P A. Administrative Contracts Branch NRC-10-82-712 82/09/30 7pp 15672 082
- 8210120534 Notification of contract execution "Maint & Operation of Local Public Document Rooms (LPDRs)," awarded to Ocean County Library, NJ LITTLE, M Administrative Contracts Dranch NRC-10-82-713 82/09/30 FELTON, R R . BOUDER, J Division of Rules and Records
- --P210120341 Contract "Maint & Operation of Local Public Document Rooms (LPDRs)," awarded to Grean County Library, NJ WDZXI, J J Grean Gounty, NJ SMITH,P A Administrative Contracts Branch NRC-10-82-719 92/09/30 7pp 15672 207
- S210120540 Notification of contract elecution. Mod 7 to "Peer Review of High Level Maste Site Suitability Criteria " Contractor TRM. INC. MCLEAREN, T Technical Assistance Contracts Branch FIN B-613/~3 MCL-02-77-143 82/09/27 DAVIR, J 9 Office of Nuclear Material Safety & Safeguards, Director ip 15672 217
- --B210120550 Hod 7, incorporating final indirect rates for FY77 & FY78, to "Peer Review of High Level Waste Site Suitability Criteria" "MCDDNNELLE J TRH. Inc HAGAN.T F Division of Contracts FIN B-6137-3 NRC-02-77-143 82/09/27 ip 15672 218
- @210120549 Notification of contract execution "Maint & Operation of ENUMERATE MODIFICATION OF CONTRACT EXECUTION "MBINT & Operation of Local Public Document Rooms (LPDRs)," awarded to San Clemente, CA Public Library LITTLE, H Administrative Contracts Branch NRC-10-82-708 82/09/30 FELTON, J H, BOUDER, J Division of Rules and Records in 15672 224
- --0210120556 Contract "Maint & Operation of Local Public Document Rooms (LPDRs)," awarded to San Clemento, CA Public Library SMITH, E M San Clemento, CA SMITH, P A Administrative Contracts Branch NRC-10-82-708 82/09/30 7pp 15472 227
- 82(0120407 Notification of contract execution "Maint & Operation of Local Public Document Rooms (LPDRs)" awarded to Kowawnee, WI Public Library
 LITTLE, M Administrative Contracts Branch NRC-10-82-694
 82/09/27 FELTON, J M , BOUDER, J Division of Rules and Records
- --82[0120613 Contract "Maint & Operation of Local Public Document Rooms (LPDRs)" awarded to Kewawnee, MI Public Library (CROSSHUESCH, B Kewawnee County, MI SMITH, P. A Administrative Contracts Branch NRC-10-82-674 82/09/27 9pp 15684 200
- 8210130008 Notification of grant execution, Mod 2 to "Study of Faulting in & Near Burface & Underground Mines of Southwestern IN "
- to a new pureles & disergroups interest branch FIN 0-1017

 HCDERHOTT, D.K. Research Contracts Branch FIN 0-1017

 HCD-C-04-81-017 82/09/22 8CMHIT, T. Office of Nuclear Regulatory

 Research, Director 1p 15692 333
- --8210130014 Hod 2, incorporating renewal proposal, extending period of performance to B30930 & increasing funding to "Study of Faulting in & Near Burface & Underground Mines of Southwestern HULHOLLAND, J Indiana Univ MORYON, K V Research Contracts Branch Fin 9-1019 NRC-9-04-81-017 82/09/22 1p 15692:334
- 8210130052 Notification of contract execution. "Expert Opinion During Meetings of NRC Advanced Reactor Subcommittee of ACRB Concerning LMFBRs." awarded to Rockwell Intl.
 TOWNBEND.B L Administrative Contracts Branch FIN 8-1557 TORREEND, B L Administrative Contracts Branch FIN 8-1557 NRC-11-82-433 82/09/23, GABKE, M. C., BOEHNERT, P. A. ACRB - Advisory Committee on Reactor Safeguards. 1p 15696 277.
- -- 8210130054 Contract "Expert Opinion During Meetings of NRC Advanced Resector Sub-committee of ACRS Concerning LMFBRs," awarded to Rockwell Intl. JOHNBON.R A Rockwell International Corp REBELLO, J E Againistrative Contracts Branch FIN 8-1557 NRC-11-82-433 82/09/23, 4pp. 18496: 278

- 8210130058 Notification of contract execution "Maint & Operation of Local Public Document Rooms (LPDRs)" awarded to Southport- Brunswick NC County Library LITTLE, M Administrative Contracts Branch NRC-10-82-702 82/09/28 FELTON, J. H., SDUDER, J. Division of Rules and Records 15692 274
- --8210130061 Contract "Meint & Operation of Local Public Document Hours (LPDRs)," awarded to Southport-Grunswick NC County Library HARPER, M T Bouthport, NC BMITH, P Administrative Contracts Branch NRC-10-82-702 82/09/28 9pp 15492 275
- 82[0130071 Notification of contract execution "Maint & Operation of Local Public Document Rooms (LPDRs)." awarded to Sometvell County Public Library on Square

 LITTLE, M Administrative Contracts Branch NRC-10-82-686
 82/09/28 FELTON, J. M. SQUDER, J. Division of Rules and Records
- ---8210130074 Contract "Haint & Operation of Local Public Document Houms (LPDRs)," awarded to Somervell County Public Library on Square
 WHITHORTH,F Somervell County,TX SMITH,PA Administrativ
 Contracts Branch NRC-10-82-486 82/09/28 900 15496 254
- 82(0130587 Notification of contract execution Task Orders 21.22.23 & 24.to "Technical Assistance to Support NRC IE Personnel in Investigations of Incidents." Awarded to Parameter.Inc HOLLETT'S Research Contracts Branch FIN 8-1302 MRC-05-82-249 82/09/02 BLAHA.J. LAVDAN.W Director's Office of Inspection and Enforcement ip 13492 338
- --BRIGIOUS92 Ltr contract executing Task Orders 21,22,23 & 24, to "Technical Assistance to Support NRC IE Personnel in Investigation of Incidents" GUSTAVE.R P Research Contracts Branch FIN B-1302 NRC-09-B2-249 B2/08/31 LOFTY.R A Parameter. Inc. 2pp
- 8210150328 Notification of contract execution, Mod 11 to "Study of Beismicity & Tectonics in New England" Contractor Boston Seleminity & Jectonica in New England "Contractor Edition College JACOBS: A Research Contracts Branch FIN A-4086 NRC-04-74 82/09/23 BATBON,H : HURPHY: A Office of Nuclear Regulatory Research, Director 1p 15715-337 NRC~04~74~238
- --8210150350 Mad ii.increasing funding, to "Study of Seismicity & Tectonics in New England" GMITH.J.R Boston State College QUSTAVE.R P Research Contracts Branch FIN A-4056 MRC-04-74-238 82/09/23 5pp 15715 338
- 8210180327 Notification of contract execution: Mod 22 to "Rayisw & Evaluation of Approx 500 Pending Operating Reactors Licensing Actions " Contractor Franklin Inst FLYNN:M Technical Assistance Contracts Branch FIN 8-6590 NRC-03-79-118 82/09/28 EISENHUT, D.G., BAJWA, B. Division of Licensing ip 15746 003
- --B210180332 Mod 22, obligating funds, to "Review & Evaluation of Approx STOCKED TO SECURITY THE STORM TO THE RESEARCH A CHARLEST TO THE RESEARCH ACTIONS TO STORM THE PROPERTY OF THE STORM THE STORM
- 8210180329 Not Reformation & Document Control | Ip 15745: Division of Technical 15745:339
- -8210180348 Contract, "Microfiche Verification & Retrofit," awarded to Lebat-Anderson:Inc LABAT:V J Lebet-Anderson, Inc HILL:D Small Business Administration, NRC-10-82-425 82/09/30 E3pp 15745
- 8210180357 Notification of contract execution Mod 9 to "Seismotectonic Study of New England & Adjacent Areas " Contractor Boston College. College.

 JACOSB: A Research Contracts Branch FIN 8-596: NRC-04-76-29:
 BATBON W , MURPHY, A Defice of Nuclear Regulatory
 Research, Director 19 15745.302

- --B210180362 Mod 9, funding FYB2 action, to "Seismatectonic Study of New England & Adjacent Areas " SMITH.J R Baston Collège QUSTAVF, R P Division of Contracts FIN B-5961 NRC-04-76-291 82/09/23 Bpp 15745 303
- 8210180365 Notification of contract execution "Maint & Operation of Local Public Document Rooms (LPDRs)," awarded to Calvert County, MD Library LITKE, M Administrative Contracts Branch NRC-10-82-704 82/09/29 FELTON, J M , SQUDER, J Division of Rules and Records in 15745 311
- --8210180371 Contract "Maint & Operation of Local Public Document Rooms (LPDRs)." awarded to Calvert County. HD Library HURREY.K C Calvert County, MD REBELLO.J E Division of Contracts NRC-10-82-704 82/09/29 9pp 15745 312
- 8210180384 Notification of contract execution,Mod 23 to, "Review & Evaluation of Approx 500 Pending Operating Reactors Licensing Actions "Contractor Franklin Inst FLYNN,M Technical Assistance Contracts Branch FIN 8-6590 NRC-03-79-118 82/09/30 EISENHUT.D, BAUHA:S Division of Licensing 1p 15745 321
- --8210180390 Mod 23, obligating funds, extending performance period to 830331 & assigning new project monager, to "Review & Evaluation of Approx 500 Pending Operating Reactors Licensing Actions"

 ZUDANG, Z Franklin Institute/Franklin Research Center MATTIA.H J Division of Contracts FIN 8-6590 NRC-03-79-118 82/09/30 3pp 15745 382
- 8210180395 Notification of contract execution "Haint & Operation of Local Public Document Rooms (LPDRs)" awarded to Lawson McGhee Public Library LITTLE, M. Administrative Contracts Branch RC-10-82-701 62/09728 FELTON, J.M., SDUDER, J. Division of Rules and Records (p. 15745-290
- --8210180401 Contract "Maint & Operation of Local Public Document Rooms (LPDRs)." awarded to Lawson McOhee Public Library BARIOLINI.R P Knosville, IN SMITH,P A Administrative Contracts Branch NRC-10-82-70L 82/09/28 9pp 15745 291
- 8210180411 Notification of contract execution. "Maint & Operation of Local Public Bocument Rooms (LPDRs)." awarded to Emporía State Univ LITTLE.M. Administrative Contracts Branch NRC-10-82-687 82/09/28 FELTON, J K. SOUDER, J Division of Rules and Records 1p 15745-325
- --8210180416 Contract "Maint & Ogeration of Local Public Document Rooms (LPDRs):" awarded to Emporia State Univ VISSER.J E Emporia State Univ SMITH.P A Division of Contracts NRC-10-82-687 82/09/28 8pp 15745 326
- 8210190001 Notification of grant execution "Chapman Conference on Fault Behavior & Earthqueke Generation Process," awarded to American Geophysical Union MCDERMGET, D.K. Research Confracts Branch FIN 0-1039 NRC-G-04-82-008 82/09/27 BATSDN.W. MURPHY, A. U. Office of Nuclear Regulatory Research. Director ip 15760 174
- --B210190002 Grant "Chapmen Conference on Fault Behavior & Earthquake
 Process," awarded to American Geophysical Union
 American Geophysical Union MURPHY, A J Research
 sch FIN 0-1039 NRC-0-04-82-008 82/09/29 2pp

- 82:019001B Notification of contract execution.Mod 7 to "Technica)
 Assistance in Bupport of Reactor Licensing Actions Program
 2 "Contractor Science Applications.Inc
 FLYNN, H Technical Assistance Contracts Branch FIN B-8609
 NRC-03-82-094 82/09/30 EISENHUT, D, SILVER, H Division of
 Licensing ip 15760 342
- B210190030 Natification of contract execution, Mod 4 to "Trchnics)
 Assistance in Support of NRC Reactor Licensing Actions
 Program 2 "Contractor Science Applications: Inc
 FLYNN,M Technical Assistance Contracts Branch FIN 8-8409
 NRC-03-82-096 82/09/28 EISEMAUT.D 0 , BILVER, H Assistant
 Director for Licensing 1p 13761 031
- --8210190037 Mod A, substituting members of performance evaluation bould a providing incremental funding to "Technical Assistance in Support of NRC Reactor Licensing Actions Program 2" . FINDLEY, D E Beience Applications, Inc. HAGAN, T F Tachnical Assistance Contracts Branch FIN B-8609 NRC-03-82-096 82/09/28 2pp 15761 032
- 8210190057 Notification of contract execution "Tornado Hindepsed Documentation," awarded to Univ of Chicago HA0EY.H Research Contracts Branch FIN 8-8108 NRC-04-82-004 82/09/22 BATSON,W. ORENIER,B. ABDEY.R Office of Nuclear Regulatory Research, Director ip 15761 049
- --8210190063 Contract "Tornado Windspeed Documentation," awarded to Univ of Chicago SIOALD S Chicago Univ of MORTON, K V Research Contracts Branch FIN 8-8108 NRC-04-82-004 82/09/82 10pp 15761 050
- B210190076 Notification of contract execution, Mod 2 to "Degraded Piping Program" Contractor BMI WOLLETT, B Research Contracts Branch FIN 8-7027 NRC-04-81-178 82/09/24 FOREMAND 8, STROSNIGER, J Office of Nuclear Regulators Research, Director 1p 18761 098
- ---B2101900B7 Mod 2.increasing funding 8 extending period of perforate to 830531.to "Degraded Piping Program" * Battelle Hamorial Institute, Columbus Laboratories OUSTAVE.R.P Research Contracts Branch NRC-04-81-176 82/09/24 3pp 15761 099
- B210190102 Notification of contract execution, Mod 1 to "Hydrological Engineering Coastal Review of Operating Factors (I) " Contractor DDD. FIELDS, J.A. Technical Assistance Contracts Branch FIN N-DOCA NRC-03-81-132, B2/09/30 VOLLMER, R.H., LEAR, G. Division of Engineering ip 13761 223
- --8210190105 Mod 1.deobligating balance of FY81 travel funds & oblighty FY82 travel funds to "Hydrological Engineering Coastal Review of Operating Factors (I) " * Army Dept of FIN B-8006 NRC-03-81-132 82/09/30 2pp 15761
- 8210190132 Notification of contract execution. Mod 9 to "Utilication of BMR & PMR Simulator Activities " Contractor TVA JACO89.A Research Contracts Branch NRC-05-76-357 82/09/23 SLAHA, J. PGX.E Program Support Branch 1p. 15761 237
- --8210190141 Mod 7, increasing funding, to "Utilization of BUA & PAR Simulator Activities." JUHNSON.R.A Tennessee Valley Authority GUBTAVE.R P Recease Contracts Branch NRC-05-76-387 B2/09/23 ip 15761 239
- B210190149 Notification of contract execution, Mod 4 to "On-Call & Scheduled Monthly Preventive Haint on ECLIPBE 8/230 Computer Sys " Contractor Computer Sys Bupport Corp EMITH.P A. Division of Contracts FIN 8-1671 NRC-1D-ND-7QA 82/04/30 DORIE:W H , JOHNBON, C Office of Administration 19 13761 244
- --8210190156 Mod 4, deobligating balance remaining, to "Dn-Call & Scarl Monthly Preventive Maint on ECLIPSE S/230 Computer Sys ROSTILE Computer Systems Support Corp SMITH.P. A Division Contracts FIN 8-1671 NRC-10-80-706 82/09/30 bp 1574121
- 82:0190162 Notification of contract execution:Mod 1 to "Partitions" Contractor. Aspects: Inc SHITH-P.A Division of Contracts. NRC-10-82-401 82/09/30 FETROH:0 Division of Facilities & Operations ip 15844 138

- ~-8210190167 Mod 1, deobligating balance remaining, to "Partitions " LED.F A Aspects, Inc BMITH,P A Division of Contracts ARC-10-82-401 82/09/30 ip 15758 048
- 821G190172 Notification of contract execution "Near Ground Turnado Mind Fields." awarded to TX Tech Univ PAGEY.H Research Contracts Branch FIN 8-8099 NRC-04-82-002 82/09/21 BATSDN.W r ABBEY.R Office of Nuclear Regulatory Research, Director Ip 15758 049
- --8210190177 Contract "Near Ground Tornado Wind Fields," awarded to TX Tech Univ JONES, J K Texas Tech Univ MORTON, K V Research Contracts Reanch B-8099 NRC-04-82-002 82/09/21 12pp 15758 050
- 8210190179 Notification of contract execution "Presentation of General & Refresher Courses in Nondestructive Exam," awarded to Rockwell Intl Corp HAGEY.H Research Contracts Branch FIN 8-1303 NRC-05-82-246 82/09/21 FOX.E Program Support Branch ip 15759 114
- --B210190182 Contract "Presentation of General & Refresher Courses in Nondestructive Exam." awarded to Rockwell Intl Corp JOHNSON, R. A. Rockwell International Corp. MORTON, K. V. Research Contracts Branch FIN B-1303 NRC-05-82-246 82/09/21 3pp 15758 115
- 6210190210 Notification of contract execution "Maint & Operation of Local Public Document Rooms (LPDRs)" awarded to Charlevoix, MI Public Library LITTLE, M Administrative Contracts Branch, NRC-10-02-699 82/09/30 FELTON, J M : SOUDER, J Division of Rules and Records 1p 13759 141
- --8210190215 Contract "Haint & Operation of Local Public Document Rooms (LPDRs)" awarded to Charlevoix MI Public Library MALLICK, HE Charlevoix MI REBELLO, JE Administrative Contracts Branch NRC-10-82-899 82/09/30 9p 15758 142
- 8210190219 Notification of contract execution "Radio Frequency Surveillance Receiver & Accessories," awarded to Micro-Tel Corp. COLEMAN, R. Administrative Contracts Branch NRC-10-82-682 B2/09/30 B8ADV, R., FINGER, R. Division of Security ip 19739 151
- --8210170223 Contract "Radio Frequency Surveillance Receiver & Accessories," awarded to Micro-Tel Corp Hicro-Tel Corp EMITH.P.A Administrative Contracts Branch NRC-10-82-682 82/09/30 21pp 13759-132
- 8210190230 Notification of contract execution, Mod 1 to "Reviewing Hydrogeologic Investigations of NV Test Site (NTS) Project D.* Contractor Geotrans. Inc H1001NB.E Technical Assistance Contracts Branch FJN A-7377-2 R8C-02-82-047 82/09/30 DAVIS.J. VERMA.T. Office of Nuclear Miterial Safety & Befeguards. Director. 1p 18758 177
- --8210190309 Mod i, correcting accounting & appropriation data, to
 *Reviewing Hydrogeologic Investigations of NV Test Site
 (MTS) Project D *

 4 Geotrans, Inc. MATTIA-H J Technical Assistance Contracts
 Branch FIN 8-7377-2 NRC-02-82-047, 82/09/30 jp 15758 J78
- 8210210036 Notification of grant execution. Mod 2 to "Development of Kethodology for Systematic Probabilistic Risk Assessment of Nuclear Power Plants." Orantse, IEEE KODERHOTT.D Research Contracts Branch FIN 0-1007 NRC-0-04-81-005 B2/08/30 BATSON. W., JOHNSON, C Office of Nuclear Regulatory Research, Director 1p. 15773, 271
- -8210210038 Hed 2.providing addI funds.to "Development of Methodology for Systematic Probabilistic Risk Assessment of Nuclear Power Plants."

 * Institute of Electrical & Electronic Engineers HORTON, K V, Research Contracts Branch FIN 0-1007. NRC-0-04-01-005 82/08/30. ip 15773 272
- 921021006: Notification of contract execution. Mod 7 to "Bealing Rock Masses " Contractor. Univ of AZ JACOBS: A research Contracts Brench FIN 8-6627 NRC-04-78-27! 82/09/20 BATSON, N. DOYLE.L. Office of Nuclear Regulatory Research, Director 1p. 15774:123.
- --8210210066 Mod 7.adding govt property, to "Seeling Rock Masses" CARR:8 E Arizona, Univ of. QUBTAVE, R P Research Contracts Branch. FlN 8-6627. NRC-04-78-271 82/09/28. 1p 15774 124

- 8210210147 Notification of contract execution, Mod 1 to "Maint & Operation of Local Public Document Rooms (LPDR) "Contractor Richland, MR Public Library LITLE, M Administrative Contracts Branch NRC-10-82-706 82/09/29 FELTON, J M , SOUDER, J Division of Rules and Records Ip 15774 299
- --8210210161 Mod [,increasing monetary value of contract, to "Maint & Operation of Local Public Document Rooms (LPDR) " Richland, MA. SMITH,P A. Administrative Contracts Branch NRC-10-82-706 82/09/29 ip 15774-300
- 82/02/01/74 Notification of grant execution "Evaluation of Denefits of Response Time In Situ Testing of Neutron Bensons Used in Nuclear Power Reactor Protection Bys " Awarded to OH State Univ Research Foundation MCDERMOTT, D. Research Contracts Branch FIN G-1044 NRC-0-04-82-011 82/09/20 HNTZE, A. Office of Nuclear Regulatory Research, Director 19 15772 361
- --8210210178 Grant "Evaluation of Benefits of Response Time In Situ Testing of Neutron Sensors Used in Nuclear Power Reactor Protection Sys" SLOAN: KW Opio State Univ MORTON: KV Research Contracts Branch FIN G-1044 NRC-0-04-82-011 82/09/20 2pp 15772 362
- 8210210438 Notification of contract execution "Facilities Occumentation & Update Project," awarded to SBA Subcontractor Bryant & Bryant EDBEMORTH.P Administrative Contracts Branch NRC-10-82-420 82/09/28 CORLEY, J H., FISHER, L. Division of Facilities & Operations ip 15773 273
- --8210210444 Contract "Facilities Documentation & Update Project,"
 awarded to SBA & Bryant & Bryant, (subcontractor)
 BRYANT,R E Bryant & Bryant AIA DENNISTON, S F Small Business
 Administration MATTIA, M J Administrative Contracts Branch
 NRC-10-82-420 82/09/28 21pp 15773 274
- 8210210502 Notification of contract execution "Maint & Operation of Local Public Document Rooms (LFDRs)," awarded to Richland, WA Public Library LITKE: Administrative Contracts Branch NRC-10-82-704 82/09/29 FELTON, J H , BOUDER, J Division of Rules and Records to 15782 273
- --8210210905 Contract "Maint & Operation of Local Public Document Rooms (LPDRs)," awarded to Richland, HA Public Library ROBERTS, D E Richland, HA: SMITH. P A Administrative Contracts Branch NRC-10-82-706 62/09/29. 9pp 15792 274
- B210210564 Notification of contract execution "Transient Prototypical Steam Generator (MB-2) Research Testing Program," awarded to Westinghouse & EPRI DAIGDEN.L. Research Contracts Branch FIN B-8252 NRG-04-82-020 82/09/30 BATSON,H , HOPENFELD.J Office of Nuclear Regulatory Research, Director 2pp 15784 283
- --B210210570 Ltr Contract NRC-04-82-020, "Transient Prototypical Steam Openerator (MB-2) Research Testing Program "Accepted by BB Rytkonen on 820929 & J Moore on 820924 HORTON, K V Research Contracts Branch FIN 8-8252 NRC-04-82-020 82/09/28 FEROUSON, K L Westinghouse Electric Corp. RYTKONEN, 8 D Electric Power Research Institute (1pp 15784, 285

- 3210260237 Notification of grant elecution "Thermal-Hydraulic Transient Behavior of Coolant in Simulated Reactor Loop," awarded to Univ of ND MCDERMOTT, D.K. Research Contracts Branch FIN 0-1043 NRC-0-04-82-013 82/09/27 YOUNG, M. Office of Nuclear Regulatory Research, Director 10 15830 145
- --8210260240 Grant "Thermal-Hydraulic Transient Dehavior of Coolant in Simulated Reactor Loop," awarded to Univ of MD CASHHAN.D C Maryland, Univ of MORTON,K V Research Contracts Branch FIN 0-1043 NRC-0-04-82-013 82/09/27 2pp 15830 144
- 8210240278 Notification of contract elecution, Mod 11 to "Technical Assistance to Support NRC IE Personnel in Investigation of Incidents" Contractor Parameter. In:
 MOLLETT, 5 Research Contracts Branch FIN 8-1013 NRC-05-80-251
 82/09/24 BLAHA, J. L. LOFY, R. A. Program Support Branch in
- --8210260280 Mod il.increasing colling & changing billing ofc & address for submission of invoices, to "Technical Assistance to Support NRC IE Personnel in Investigation of Incidents " LCFY, R A Parameter. Inc OUSTAVE, R Research Contracts Branch FIN 2-1013 NRC-05-80-251 82/09/24 ip 15830 149
- 8210260282 Notification of contract execution, Mod 4 to "Presentation of CE BUR/6 Design & Operation Courses " Contractor GE JACOBS, A Research Contracts Branch FIN B-1224 NRC-05-80-282 82/09/29 BLAHA, J. PIERCE.R Program Support Branch ip 15830 150
- --8210260284 Mod 4, changing order re-price & funding action, to "Presentation of DE BMR/6 Design & Operation Courses "AVERITIOD D General Electric Co OUSTAVE.R P Division of Contracts FIN B-1224 NRC-05-80-282 82/09/29 2pp
- B210240516 Notification of contrast execution "Maint & Operation of Local Public Document Rooms (LPDRs): "awarded to Chattanooga-Hamilton County IN Ricentennial Library LITTLE.H Administrative Contracts Branch NRC-10-82-703 B2/09/28 FELTON.J H : SCUDER.J Division of Rules and Records 19 15830 158
- --8210260520 Contract "Maint & Operation of Local Public Document Rooms (LPDRs)," awarded to Chattenooga-Hamilton County TN Bicentennial Library ARNOLD-K Chattenooga-TN EMITH-P A Administrative Contracts Branch NRC-10-82-703 82/09/28 9ps 15830 159
- 8210260525 Notification of contract elecution "Maint & Operation of Local Public Document Rooms (LPDRs)," awarded to Lacrosse WI Public Library LITLE: M. A&ministrative Contracts Branch NRC-10-82-685-82/09/20 FELTON, J. M.; SQUDER, J. Division of Rules and Records ip 15830-179
- --8210260530 Contract "Maint & Operation of Local Public Document Rooms (LPDRs)," awarded to Lacrosee MI Public Library HHITE, J H LaCrosee MI SMITH, P A Administrative Contracts Branch NRC-10-82-685 82/09/28 9cs 15830 180

- 8210270199 Natification of contract execution "Maint & Operation of Local Public Document Rooms (LPDRs)," awarded to State Library of PA BAIN.J P Administrative Contracts Branch NRC-10-82-694 B2/09/28 FELTON,J M., SDUDER,J Division of Rules and Records in 15836 001
- --8210270203 Contract "Haint & Operation of Local Public Document Rc: (LPDRs)," awarded to State Library of PA SHELKROT.E L Pennsylvania, State of MATTIA.H J Division of Contracts NRC-10-82-696 82/09/28 14pp 15836 002
- 8210270207 Notification of contract execution "Availability of Medifitreatment to Minimize Early Fatalities Post-Severe Reactor Accidents," awarded to SBA Subcontractor Andrulia Research Corp HIGGINS, E Technical Assistance Contracts Branch FIN B-R616 NRC-03-8R-128 82/09/29 MATTSON, R J , WOHL, M Division of Ugits. Integration (post 811005) Ip 18836 016
- --8210270221 Contract "Availability of Medical Treatment to Histail® Early Fatilities Post-Severe Reactor Accidents:" awarded to SBA Subcontractor Andrulis Research Corp ANDRULIS, M M. Andrulis Research Corp DENNISTON, 8 F. (mg.) 1 Business Administration FIN 8-8616 NRC-03-82-128 (2/09/29 2pp. 15836 017
- 8210270226 Notification of contract execution "Fire Protection ("FGFF4)
 Review Case Work Plant 1." awarded to Qaga-Babcock &
 Associates
 W1001NS.E Technical Assistance Contracts Branch FIN B (NO20)
 NRC-03-B2-11B 82/09/28 VOLLMER:R H Division of Engineer) ne
 NOLAN.F Chemical Engineering Branch 1p 15836 046
- --8210270230 Contract "Fire Protection Program Review Case Hurb Plans.
 i." awarded to Gage-Babcock & Associates
 COMMB H Gage-Babcock Associates, Inc MATTIA, N. J. Divisio el
 Contracts FIN 8-8020 NRC-03-82-118 82/09/20 Ripp
 15836-047
- 8210270393 Notification of contract execution, Mod 3 to "Invyron Monitoring Program w/State of NC " Contractor State of NC WGLLETT, B Research Contracts Branch FIN B-1239 NRC 05 NO 50 B2/10/12 COBB.L I, COHEN.L, V Director's Office of Inspection and Enforcement ip 15033 360
- --B210270375 Mod 3.changing name of NRC billing ofc & address for submission of invoices to "Environ Monitoring Program w/State of NC"

 * North Caralina, State of, GUSTAVE,R P. Ressarch Contracts Branch FIN 8-1237 NRC-05-80-283 82/10/12 ip 158183 855
- B210270399 Notification of contract execution, Mod 7 to "Hemphis Area Regional Beismic Network " Contractor Memphis State Univ JACOBS, A Research Contracts Branch FIN B-6276 NRC 04 7th 2277 B2/09/13 BATBON, W. HURPHY, A Office of Nuclear Reguletory Research, Director 1p. 15832 356

- --B210270419 Hod 3, deabligating unexpended balance of contract funds by issuance of no cost settlement after termination, to "Environ Assessment of Raffinate Study Disposal at Kerr-McGee Sequagah Facility, Gore, OK "
 ARCHER, C D Science Applications, Inc HAGAN, T F Technical Assistance Contracts Branch FIN B-7316 NRC-02-B1-045 B2/09/30 2p 15833 285
- 8210280206 Notification of contract execution "Use of PA Fish & Hildlife Data Base Sys in Environ Analyses for Nuclear Power Plant Lichasing," awarded to PA Game Commission HOYLE, A Administrative Contracts Branch FIN 8-8812 RSC-25-82-323 82/09/30 BASSETT, H B , JOHNSON, C Division of Data Automation & Hengement Information ip 15858 355
- --B210280235 Contract "Use of PA Fish & Wildlife Data Base Bys in Environ Analyses for Nuclear Power Plant Litensing," awarded to PA Came Commission
 SMITH, P A Pennsylvania, Etate of SITLINGER, J I Administrative Contracts Branch FIN 8-8812 NRC-25-82-323 82/09/30 5pp 13858 336
- 8210280299 Notification of contract execution. Mod 2 to "Environ Assessments & EIS for Low Level Waste Disposal Facilities" Contractor Envirosphere Co.
 FLEENOR.C M Technical Assistance Contracts Branch NRC-02-82-026-09 82/10/05 DAVIS, J. PANOBURN.G Office of Nuclear Haterial Safety & Safeguards, Director 1p 15889 036
- --8210280306 Mod 2, extending period of agreement to 830929 & incorporating administrative changes re billing, to "Environ Agreements & EIS for Low Level Waste Disposal Facilities " # Envirosphere Co HAGAN.T F Division of Contracts NRC-02-89-026-09 82/10/05 2pp 15859 037
- 8210280310 Notification of contract execution Mod 2 to "Environ Assessments & EIS for Low Level Waste Disposal Faculities " Contractor Engineering-Science, Inc FLEENDR,C M Technical Assistance Contracts Branch RRC-02-82-026-08 82/10/05 DAVIS,J , PANOBURN,O Office of Nuclear Material Bafety & Safeguards, Director ip 15859 039
- --B210280319 Mod 2, extending period of agreement to B30929 \$
 incorporating administrative changes re billing, to "Environ
 Assessment & EIS for Low Level Waste Disposal Facilities "

 Engineering Science HAQAN,T F Division of Contracte
 NRC-02-B2-026-0B 82/10/05 2pp 15859 040
- 9210280327 Notification of contract execution. Hod 2 to "Environ Assessments & EIB for Low Level Maste Disposal Pacilities" Contractor Maste Hgt Group. Inc FLEENOR, C M Technical Assistance Contracts Branch NRC-02-82-026-06 92/10/05 DAVIS, J, PANGBURN, Q Defice of Nuclear Material Safety & Bafeguards, Director ip 15859 122
- --9210280331 Mod 2. extending period of agreement to 830929 & incorporating administrative changes re billing, to "Environ Assessment & EIS for Low Level Waste Disposal Facilities " & Maste Management Group, Inc. HAOAN, T Division of Contracts NRC-02-82-026-06. 82/10/05 2pp 15859 123
- 8210280354 Notification of contract execution, Mod 2 to "Environ Assessments & EIB for Low Level Waste Disposal Facilities "Contractor Kaman Tempo FLEENOR, C M Technical Assistance Contracts Branch NRC-02-82-026-05 82/10/05. DAVIB.J. PANOBURN, G Office of Nuclear Material Safety & Safeguards, Director 1p 15859:197
- --8210280336 Mod 2, extending period of agreement to 830929 & interparating administrative changes re billing, to "Environ Assessments & EIS for Low Level Waste Disposal Facilities" 4 Kaman Tempo HAQAN.T.F Division of Contracts NRC-02-82-026-05 82/10/05, 2pp 15859 178
- 8210280370 Notification of contract execution "Monitoring Use of Equipment Purchased by NRC Under Contract NRC-04-74-187," awarded to GARD. Inc MCDERMOTT, D Research Contracts Branch NRC-04-82-023, 82/10/07 BATSON, M. MUSCARA, J Office of Nuclear Regulatory Research, Director ip 15897-228.
- --8210280374 Contract "Monitoring Use of Equipment Purchased by NRC Under Contract NRC-04-74-187: " awarded to OARD, Inc SAIGH,P A Gard, Inc MORTON,K.V Research Contracts Branch, NRC-04-82-023 82/10/07. 7pp. 15857 229
- 8210280384 Notification of contract execution, Mod 1 to "Establish Collaborative Program Between State & Commission to Provide Independent Measurements of Radioactivity in Effluents & Environ "Contractor CT Dept of Environ Protection SICVIS, R.M. Administrative Contracts Brench. NRC-05-73-011. 82/10/15 CD88.L.I., ROBE.H. Director's Office, Office of Inspection and Enforcement. 1p 13839:236

- --8210280397 Mod 1, deabligating funds, to "Establish Collaborative Program Between State & Commission to Provide Independent Measurements of Redicativity in Effluents & Environ Around Selected Commissioned Licensed Activity "
 HEUBNER, A T Connecticut, State of GUSTAVE, R P Research Contracts Granch NRC-05-73-011 82/10/15 1p 15859 237
- 8210270104 Notification of contract execution, Mod 1, to "Use of PA Fish & Wildlife Date Base Sys in Environ Analyses for Nuclear Power Plant Licensing " Contractor Commonwealth of PA HOYLE: A Administrative Contracts Branch FIN 8-8912 NRC-25-82-323 82/10/19 BASEFIT: H S , JOHNSON, C Division of Datu Automation & Management Information 1p 15864 336
- --8210270131 Mod 1, adding statement that data base training will be conducted at game commission, Harrisburg & deleting Reporting Requirement 2, to "Use of PA Fish & Wildlife Data Base Bys in Environ Analyses for Nuclear Power Plant Licensing "REBELLO,JE Pennsylvania, State of # Administrative Contrarts Branch FIN B-8812 NRC-25-62-323 82/10/18 1p 15866 337
- 8210290396 Notification of contract stecution "Safety Aspects of Industrial Radiography Course," awarded to Oamma Industries COLEMAN. R Administrative Contracts Branch NRC-05-82-251 BLAHA, J. L. HASSELBERG, R Program Support Branch 1,15866-054
- --8210290398 Contract "Bafety Aspects of Industrial Radiography Course." awarded to Camma Industries * Nuclear System SNITH.P A Administrative Contracts Branch NRC-05-82-251 82/09/28 28pp 15866 055
- 8210290420 Natification of contract execution Mod 3 to "Hydrologic Engineering Consulting Svos for Site Bafety Reviews" Contractor ifaria Engineering Co HCLEREN.T Technical Assistance Contracts Branch FIN B-1123 NRC-03-74-308 82/10/08 DENTON.H R Office of Nuclear Reactor Regulation, Director ip 15863 237
- --8210290422 Mod 3.deobligating unliquidated balance of contract funds, to "Hydrologic Engineering Consulting Sycs for Site Safety Reviews"

 4 Haria Engineering Co HAQAN, T F Division of Contracts FIN 8-1123 NRC-03-76-308 82/10/08 1p 15863 240
- FOIA FREEDOM OF INFORMATION ACT REQUESTS AND RELEASES
- 8204060002 Appeals denial of FQIA request for segregable portions of draft NUREG-OB44. "Resolution of Unresolved Safety Issues A-3,A-4 & A-5 Re Steam Generator Tube Integrity UDELLAR A Critical Mass Energy Project B2/06/04 DIRCKS,W J Office of the Executive Director for Operations 2pp 15668 333
- 8207050075 FOIA request for seven categories of documents re Dow Chemical Co & incineration of low level radwaste HILBON A K APfiliation Unknown 82/07/01 MALLETY Region 3, Office of Director ip 15748 OOL

- B207180060 FDIA request for documents to NRC shutdown plan mentioned in weekly info tept for wk ending 810828 & SECY 81-600 & SECY 81-600A
 - SECY BI-600A CONNOR.L Doc-Search Associates 82/08/31 Division of Rules and Records 1p 15758-311
- 8207180061 FOIA request for documents re pre-implementation review of MUREO-0737. Item II F 2 CONNUR.L Doc-Search Associates 82/09/01 Division of Rules and Records Ip 15669 096
- 8207180064 FOIA request for "Initial Guidance for Performance of Sys Interaction Analysis at Selected LVRs" & "Initial Guidance on Diagraph-Matrix Analysis for Sys Interaction Studies at Selected LVRs"
- Selected LURs "
 FABRIZIO, R F Boston Edison Co 92/08/30 Division of Rules and Records in 15859 117
- 8208270088 FOIA request for SECY 82-419 re use of nonplant-specific simulators for initial, replacement & requalification exams for licensed reactor operators & senior operators ARMSTRONG, K.A. Debevois & Liberman 82708/29 FELTON, J.M. Division of Rules and Records Ip 15760 177
- 820829089 FOIA request for records to disposal of radwasto & chemical medical wastes at St Albans Hosp in Queens, NY FREEDERG.L Youth News 82/09/07 Division of Rules and Records ip 15774-313
- B20B290098 FOIA request for all declassified matl on Manhattan Project CHAIXEN.J A Affiliation Unknown B2/09/10 Division of Rules and Records ip 15636 205
- 8208270105 FOIA request for info re each NRC licensee in States of PA. DE & NJ FREDLAND.D R Affiliation Unknown 82/09/15 Office of Administration 1p 15646 006
- 820827010B FOIA request for RFP RS-01E-82-251 "Safety Aspects of Industrial Radiography Course" & related info MILLIAMS, DT Affiliation Unknown 92/10/01 Division of Contracts ip 15877 071
- 8209150056 FOIA request for lists of names & addresses of all NRC Jicenses in ME.VT.MA.OH.CT & MV & appropriate ofcs in Agreement States of NH.RT.MY & MD PARKINSON.T W Interstate Nuclear Services 02/07/27 FELTON, J Division of Rules and Records ip 15843 310
- 8209150057 FOIA request for NRC Annual Rept to Congress for 1981 SCRULKE.8 Affiliation Unknown 82/09/25 FELTON.J M Division of Rules and Records ip 15758 309
- 8209290168 Respands to FDIA request for documents prepared by NRC staff & tensultants on 10CFR50. App B re GA audits of testing racilities conducted within past to yrs by NRC Related documents listed FELTON, J M Division of Rules and Records 82/08/26 PHILIPS, M H Debevoise & Liberman 2pp 15564 002
- --B209290236 Forwards QA Program Insp Rept 99900905/B2-01 on Bi1229-30 No noncompliance noted HEISHMAN R F Reactor Construction Branch 82/05/26 BBUCHEY.O D Washington Public Power Supply System 2pp 15564 060

- --B005270822 Discusses shortcomings in NUREG-0572: "Review of LERs (1973-1978) " MORER H Office of Management and Program Analysis B0/03/23 MALLER, N M Office of Management and Program Analysis 3pp (1927-098)
- --8006300104 Forwards BL Cohen 800324 ltr & study re design adequacy of refueling water storage tank Requests views FRALEY, R F ACRB Advisory Committee on Reactor Safegwards 80/04/18 DENTON, H R Office of Nuclear Reactor Regulation, Director ip 15727 104
- --8010240413 Submits evaluation of NUREG-0667. "Transient Response of Bi Designed Reactors " Recommends related studies be combined & specified Priority 2 items implemented by expanding on existing task in TMI action plan MATTBON.R Division of Safety Technology 80/08/08 DENTON, H R Office of Nuclear Reactor Regulation, Director 43pp 15/2/ 199
- --B010240496 Forwards analysis & recommendations re plants w/o seismial qualified auxiliary feedwater sys Concludes that shutdown of non-seismically qualified sys would not significantly reduce risk & proposes that more detailed study be initiated HATTBOD.R Division of Safety Technology 80/08/08 EISENRUT.D O Division of Licensing 19pp 15727 241
- --Bi03030076 Furwards revision to evaluation of automatic air header de on BHRs transmitted in B01208 memo Revision restructures analysis supporting proposed change to BHR scram discharge sys
 ERNST, HL Assistant Director for Technology Review 80/12/12
 DENTON.H R Office of Nuclear Reactor Regulation, Director 13pp 15727 307
- --8103050756 Forwards as part of NUREO-0651 review.cost benefit analyse of radiation detectors on main steam lines to provide added diagnostic capability for PWR operator during steam generator tube rupture
 LOBEL.R. VANDERNOLEN.H Safety Program Evaluation Branch
 80/12/15 BAER.R Safety Program Evaluation Branch
 10pp
 15727 322
- --BIO3DACOBB Comments on proposed change to BTS re battery sys per UCI request for review Operating plants using battery sys not covered by BTS should submit for approval equivalent surveillance program Proposed STB & BOI23O memo encl ERNST, M. Assistant Director for Technology Review GI/OI/OII SCHROEDER: F Assistant Director for Generic Projects ip
- --B103240272 Forwards summery of B10128 operating reactor events mert Next meeting scheduled B10204 LAINAB.O C Assistant Director for Bafety Assessment B1/02/(14 EIEBNHUT,D O Division of Licensing opp 13728,003
- --B103310127 Bummary of 810226 operating reactor events meeting re exwhich occurred since lest meeting Next meeting scheduled for B10311 LAINAB.Q C Assistant Director for Bafety Assessment G1/Q 1/04 E16ENHUT.D.Q Division of Licensing App. 15728 235
- --BIO4240059 Discusses reactor coolant pump seal failurs, in response 800612 memo Issue will be considered potential unresolved safety issue Potential failure during station blackout may be taken up under Task Action Plan A-44 MURLEY, T E Division of Bafety Technology, 81/03/27 EISENHUT, D O Division of Licensing 13pp 15728 336
- --Bi04290103 Discusses IE daily rept for BI0406 re alternate off mite source interlack w/emergency diesel generators at Unit i Licenses will propose mod to correct non-Class IE interlect preventing automatic operation of safety sus CHIRAMAL, M Director's Office, Bi/04/21 Director's Office, 3pp 13729 041 24X Fiche 50-000, 82/06/28, 8210010000
- ---8105110396 Forwards findings & recommendations for J Elin 810 tt 5 , re requirements of preferred or offsite power sys ASHE,F, Director's Office, 81/04/29 MICHELBON,C Director , Office 4pp 18729 070
- --Bio6100362 Comments on problem of flow blockage of cooling water by asiatic clams (ref IE Bulletin 81-03). Problem considered potentially serious common mode failure. Guidance for proposed stepwise investigation provided BAER, R L. Barety Program Evaluation Brench IEB-81-03 Biros MURLEY.T.E Division of Safety Technology 3pp 18729 166
- --Bi07070220 Discusses Ofc of Nuclear Regulatory Research comments supporting conclustons of Mar 1981 ofc rept re safely concerns associated while breaks in PMR scram sys Shortcomings of analysis listed ORNSTEINH L. Director's Office CF-356 81/06/11 MICHEL St. Director's Office 3pp 15729.205

NONDOCKETED HEIVIS

- --BL07090355 Forwards Nuclear Bafety Analysis Ctr/INPO rept, "Significant Event Evaluation & Info Network" & background info re review of steaming & preliminary evaluation program, for comment HICHRLSON, C Director's Office CF-337 81/06/22 DENTON, H R Office of Nuclear Reactor Regulation, Director 15pp 15729 222
- --B107360386 Provides info as discussed at ACRS B10507 meeting re-control sys failures that could cause or accelerate nuclear power facility accidents Comments from plant sys unit encl ASME.F Director's Office AEOD/E114 81/06/24 MICHELBON, C Director's Office 5pp 15729 251
- ~~BIOBOGOO41 Discusses priorititation of new requirements for PMR feedwater line cracks Remedial measures development should be responsibility of industry w/approval of design changes responsibility of NRR ERNST.M & Barety Program Evaluation Branch Bi/06/30 KURLEY.T & Division of Bafety Technology 26pp 15729 290
- --310B180604 Discusses review of LERs re setpoint drift occurrences for Barton Model 288 instrument Provides recommendations for KRR ASHE,F Director's Office 81/07/20 MICHELBUN,C Director's Office 2pp 13730 054
 - 3108240273 Forwards marked-up draft Commission paper re integrated operational experience reporting sys for concurrence Draft advance notice of proposed rulemaking & Congressional ltrs and MICHELSON, C. Director's Office 81/07/15 DENTON, H R Office of Nuclear Reactor Regulation, Director 14pp 15730 007
 - BIO8270056 Forwards concurrence on NUREO-0803, "Generic Bafety Evaluation re Integrity of BWR Scram Ggs Piping " Any significant changes will be provided for consideration HICHELSON, C Director's Office 81/07/30 EISENHUT, D O Division of Licensing 3pp 15730 083
 - 8109100077 Advises that review of proposed draft supplied IE Bulletin 81-02, "Failure of Gate Type Valves to Close Against Differential Pressure," yielded no substantive comments HELTENES, C. J. Director's Office IED-81-02 81/08/06 JORDAN, E. L. Division of Resident & Regional Reactor Inspection 15 18730 106
 - 6109220915 Recommends memo be prepared requesting Ofc of Nuclear Regulatory Research to initiate preparation of proposed rule thange on high priority basis for General Design Crituria 4 MURIEV, TE Division of Bafety Technology 61/09/26 VOLLHER, R H Division of Engineering 2pp 15731 031
 - -gio7240007 Comments on NUREG/CR-1459 Vol 2, "Reactor Safety Study Mathodology Application Program Ocones 3 PWR Power Plant "DENNING, R L Director's Office Si/09/15 Director's Office 2pp 45587 237
 - -8109250504 Comments on proposed IE circular re torque switch jumpers for safeguards see motors More appropriate title could be "Torque Bwitch Jumpers for Bafeguards Bec Valve Motor Control Circuits " Marked-up circular encl HICHELBON.C Director's Office BI/08/28 JORDAN.E L Birector's Office App 15730:142
 - -9110010072 Comments on J Austin 810306 note re purge & vent valve assembly operability during expected accident conditions & potential problems should valve closure be delayed BROWNE J Director's Office 4pp 15730 273
 - --Bijoi90928 Discusses Bi0625 memo re approach to sys interactions in LRs No comments were developed which would need to be assimilated into interim guidance Author ofc will offer assistance w/use of sequence coding & search procedure HICHELBON,C Director's Office. Bi/09/02 MURLEY.T E Division of Bafety Technology ip 15730 202
 - -- Rii0190933 Forwards background statement & discussion of process & policies established for Ofc of Analysis & Evaluation of Operational Data repts. Future repts sent for peer review will be complete & include conclusions & recommendations HICHELSON, C Director's Office 81/09/02. DAVIB.J 0 Office of Nuclear Material Safety & Bafeguards, Director. 3pp 15730 199
 - --Bil0220004 Forwards summary of activities re FWR primary sys voids.
 Initiated by Ofc for Analysis & Evaluation of Operational
 Data
 BIRCKB.W J Office of the Executive Director for Operations
 Bi/09/30 PALLADINO.N Commissioners 2pp 15730; 290.

- --Bii1030201 Responds to inquiry into status of BWR scram discharge volgips break safety concerns NUREO-0803 contains guidance for resolving outstanding issues on plant by plant basis RUBIN,S O Director's Office 81/10/02 LEWIS,M I Affiliation Unknown ip 15730 336
- --BillO60130 Forwards draft proposed rule & reg guide re new LER sys.for review Comments should indicate whether improved sys will meet needs for operational safety data MICHELSON.C Director's Office Bi/10/06 DERNTON, H.R. Office of Nuclear Reactor Regulation, Director 24pp 19730 337
- --Biili6030B Responds to Bi082B memo re draft rept, "Compressed Air & Backup Nitrogen Sys in Nuclear Power Plants" Forwards comments re areas where addl work is suggested prior to final publication
 HELTEMEB,C J Director's Office Bi/10/07 ERNST,M L Assistant Director for Tachnology Review 3pp 15730 361
- --BiiiiBOOOi Recommends comprehensive assessment of plant operating conditions to determine specific predetermined time related sequences of occurrence to emergency buses SRP should be revised re design features
 ABHE, F Director's Office Bi/LO/16 MICHELSON, C Director's Office 4pp 15731 049 24X Fiche 50-000.82706/28.82100100008
- --8(112407)2 Requests Div of Sys Integration review SER section on leak rate & leak rate detection criteria Conclusions should be limited to subj plants but general comments would be appreciated HURLEY.T E Division of Safety Technology 81/10/07 HATTBON.R J Division of Systems Integration (post 811005) Opp
- ---Bii2020725 Comments on draft CRNL Bi0930 rept, "Evaluation of Events Involving Byc Water Sys in Nuclear Power Plants," per Bii020 request Several recommendations made w/o sufficient justification to ment serious consideration HICHELSON, C Director's Office Bi/11/10 MINNERS, H Safety Program Evaluation Branch Ip 15731 117
- --Bil2030585 Provides info re better means of coordinating & reducing duplication in acreening LERs & evaluation efforts Supporting info encl ERNBT.M L Division of Safety Technology 81/11/09 HELTEMES.C J Director's Office 8pp 15731 107
- --Bil2i00374 Forwards summary of NRR.NMBB & IE actions resulting from Ofc of Analysis of Evaluation & Operational Data activities, in response to recommendations contained in case studies & engineering evaluations

 LANNINO.W Director's Office 81/11/12 MICHELBON.C Director's Office 4pp 19731 ilb
- --Bil2210166 Recommends that proposed LER rule including existing & proposed reporting requirements & coordination plan be sent to Commission for consideration BTELLO, V Regional Operations & Generic Requirements B1/11/24 DIRCKB, W J. Office of the Executive Director for Operations 1, 18732 005
- --Bil22i0193 Requests assistance of Ofc of Nuclear Regulatory Research to complete editorial & administrative activities necessary to issue enci draft reg guide HICHELBONIC Director's Office 81/11/17 HINDOUE.R B Office of Nuclear Regulatory Research. Director ip 15731 202,
- --8201060003 Comments on NRC svaluation of MCAP-9558 & MCAP-9787, re excluding asymmetric bloudown loads in plant design based on leak-before-break acceptance criteria Safety evaluation using subj basis will require regulation changes ERNBT.H L Assistant Director for Technology Review BI/ JOHNSTON.H V Assistant Director for Materials & Qualif Engineering 2ipp, 15731 315
- --B20113D322 Provides background info re FIN B-0445, "Analy Reliebility Data From Nuclear Power Plants " Review of Billi3 in-plant data program (FIN B-0445) progress revi meeting encl DENNING:R L DITECTOR'S Office FIN B-0445 B1/12/OZ MICHELBON, C Director's Office Spp 15731:336
- --BRO1150003 Forwards Chairmen Palladino & Akearne 811110 & Commission briefing on NRC program for reactor operatio experience evaluation.
 HELTEMES: C. J. Director's Defice, 81/11/25 BERNERO, R Nuclear Regulatory Research, Director 1p. 15731 309.

14

11,

- --8201150004 Responds to BiliO5 memo re functions of Ofc for Analysis & Evaluation of Operational Data Commission briefing should cover NRC program for reactor operational experience evaluation
 PALLADINO, N J Commissioners 81/11/10 AHEARNE, J
 Commissioners ip 15731 310
- --B201150005 Suggests Commission be briefed on current & projected distribution of Ofc of Analysis & Evaluation of Operational Data resources thru FY84 AMEARIELJ Commissioners 81/11/05 PALLADING, N J Commissioners 4pp 157J1 311
- --8201190040 Forwards INPO 811110 ltr commenting on draft proposed rule to modify & codify existing LER reporting requirements Comment 1 should be considered during review of reporting requirements MICHELSON C Director's Office 81/12/11 DEYOUNG. R C Director's Office of Inspection and Enforcement 1p 15732 015
- --820119004! Comments on draft rule.10CFR50 73 re LER sys Rule would significantly reduce number of LERs filed Only significant events would be reported ZEGROGKI.E L Institute of Nuclear Power Operations B-B1-0.306 B1/11/10 MICHELSON.C Director's Office 60pp 15732 016
- --8201190296 Concurs w/procedures for developing NRC research program, in response to NRC 811112 memo Requests that all research projects collection, storage analysis or evaluation of operational safety data be sent for review & concurrence MICHELSON.C Director's Office 81/11/24 BASBETT, HS Office of Management and Program Analysis 1p 15731 246
- --B201270037 Endorses Committee to Review Generic Requirements recommendation that appropriate ofto coordinate outline of reporting requirements interrelated w/draft proposed LER rule Identifies documents he reporting requirements DIRCKS, M. J. Office of the Executive Director for Operations B1/12/08 DAVIS.J.G. Office of Nuclear Material Safety & Safeguerds, Director 2pp. 15732-003
- B20202044("Evaluation of Events Involving Svc Water Sys in Nuclear Power Plants," draft HARIED. A Clark Ridge National Laboratory FIN B-0755 B2/01/31 47pp 15732 107
- --8202030092 Forwards proposed Commission paper requesting approval of proposed rule which would modify & codify existing LER sys MICHELSON, C Director's Office 81/12/30 DIRCKS, W J Office of the Executive Director for Operations ip 15732-104
- --B203120016 Discusses repetitive failures of emergency feedwater flow value as reported in LERs due to valve operator hydraulic problems LERs encl
 IMBRO, E V Director's Office AEQD/E211 82/02/24 MICHELSON. C
 Director's Office 76pp 15732 308 24X Fiche 50-000, 82/06/78, 8210010008
- --8203160383 DRNL/NSIC-208
 "Evaluation of Events Involving Unplanned Boron Dilutions in Nuclear Power Plants"
 HAGEN.E W Clak Ridge National Laboratory FIN II-0755 82/03/31
 Office of Nuclear Reactor Regulation, Director 37pp 15733 017
- --B203170060 Requests that review be conducted on missile protection of safety-related sys at plants to assure adequate protection calculated protection rotor retaining Tings as missiles

 Director's Office AEGD/E209 B2/02/23

 Director's Office 15pp 15745 054

~50

t Removal Sys in

0755 82/03/31 101pp

> ator t

> > r i

- --B2040B0171 Forwards "Recommendations for Improving NRC Incident Response Technical Assessment Capability " Recommendations consistent w/NRC B20104 1tr re NUREO-0845 List of recommendations enci MINNERS.W Safety Program Evaluation Dranch 82/03/04 DENTON,H R Office of Nuclear Reactor Regulation. Director DEVOUND&R C Director's Office. Office of Inspection and Enforcement 3pp 15733 274
- --B2040B0260 "Recommendations for Improving NRC Incident Response Technical Assessment Capability " CONGEL.F Office of Nuclear Reactor Regulation, Director B2/02/2B 77pp 15733 297
- --8204270464 Submits engineering evaluation re-potential for air binging or degraded performance of BURR RHR sys pumps during LOCA recirculation phase Air bubble generation will not adversely affect RHR pump performance Oas release calculations onto RUBIN.S Director's Office AEOD/E218 82/03/31 NICHE(60M.C Director's Office Bpp 15745-103
- --B205070377 Advises that proposed circular, "Contamination of Air Serving Safety-Related Equipment." reviewed Followup to Ii Notice BI-3B or IE bulletin should be sent requesting info assessment of plant air supply sys ORNBTEIN.H L Director's Office AEOD/E219 82/04/01 MICHELSON.C Director's Office 2pp 15745 263
- --8210010061 Forwards review of 82W itr rept on effect of fuel rod bowing on DNBR Proposed method acceptable for licensing calculations GRIMES B K Division of Operating Reactors 79/07/25 VARGA 's A Assistant Director for Light Water Reactors 6pp 19327 O/O
- --8210010065 Notification of ACRS LER Subcommittee 800422 meeting in Mashington, DC Schedule & background info encl BATES, A ACRS Advisory Committee on Reactor Safeguards 80/04/14 MOELLER, D. MATHIS, W., CATTON, I ACRB Advisory Committee on Reactor Safeguards 3pp 15727 078
- --8210010067 Gutlines INPO & Ofc for Analysis & Evaluation of Operation Data 800311 & 20 reviews of nuclear plant operating data Related info encl
 YOUND, 9 O ACR8 Advisory Committee on Reactor Safeguards
 80/03/26 ACRS Advisory Committee on Reactor Gafeguards App 15727 081
- --B210010068 "Status Rept.Ofc for Analysis & Evaluation of Operational Data"
 MICHELSON, C Director's Office 80/03/20 10pp 15/4/ 08/
- --8210010073 Advises that ACRS 800422 meeting w/LER Subcommittee & PAPT will include discussion of status organization & planned activities of Ofc for Analysis & Evaluation of Operational Data & NRC program for collection of data MICHELBON, C Director's Office 80/03/21 BERNERO, R Probabilistic Analysis Btaff (Pre 80/117) CARTER, T F Division of Operating Reactors 2pp 15727 101
- --B210010074 Confirms telcon re 800422 presentation on INPD w/AIRD tes Bubcommittee Member requested to make presentation on status of organization & plans for Puture activities re use & evaluation of operational data from nuclear plants BATEB.A ACRE - Advisory Committee on Reactor Bafeguards B0/04/14 LAVALLEE.W Electric Power Research Institute to 15727 to3
- --8210010089 Discusses failures of HPCI & RCIC sys subsequent to //r/u& event culminating in 790627 loss of both sys BOEHNERI,P ACRS Advisory Committee on Reactor Sefsguards 79/09/04 KERR,W ACRS Advisory Committee on Reactor Sefsguards 2pp 15727 142 24X Fiche 50-000,82/04/2N, 8210010008
- --8210010119 Discusses problems w/LER data reporting & recording sys-Form is not designed for subsequent use of data for statistical analyses Draft notes onci HDELLERR, D W. Hervard Univ. 80/07/01 BATES, A L. ACRS -- Asvisa Committee on Reactor Safeguards. 8pp. 15727, 146
- --9210010161 Discusses potential problem re sequoyah reactor pressur, norzle, supplementing 800222 memo Underciad cracks found by use of ultrasonic equipment, Addl items of recent origin discussed Related info encl
 DENTON:H R Office of Nuclear Reactor Regulation, Director 80/02/28 AHEARNE.J Commissioners 9pp 15727 178 24% Fichs 50-000, 82/06/28, 8210010008

- --B210010169 Discusses evaluation of applicability of proposed new requirement of Class IE station batteries Div of Licensing should retain responsibility for further exploration of matter in course of licensing reviews

 MATTEON.R J Division of Systems Safety 80/02/28 EISENHUT, D G
 Division of Licensing 2pp 15727 187
- --B210010172 Forwards comments on NRC LER sys W/o anci BATES.A NRC - No Detailed Affiliation Given B0/07/22 MICHELSON.C Director's Office HALLER.N Office of Management and Program Analysis ip 15727 189
- --8210040368 Discusses NRC procedures for reviewing LERs, in response to request during 245th ACRS meeting on 800904-06 Reporting requirements require revision to eliminate unneeded matl BATES. A ACRS Advisory Committee on Reactor Safeguards 80/09/23 ACRS Advisory Committee on Reactor Safeguards 3pp 15727 266
- --8210040371 Responds to 800523 request re action by Dfc for Analysis & Evaluation of Operational Data on two specific LERs Ofc currently working on more significant safety areas BATES.A NRC No Detailed Affiliation Given 80/07/23 BENDER.M NRC No Detailed Affiliation Given 1p 15727 271
- --8210040379 Bubmits review of IE insps of operating PWRs related to followup actions identified in NUREG-0138 Bensitivity analyses recommended BUTLER, H B Plant Systems Branch 77/12/28 EISENHUT, D G Division of Operating Reactors 12pp 15727 285
- --B2(00403B) Netification of ACRS LER Bubcommittee 801120 meeting in Washington DC to discuss progress toward improving NRC use of operational data BATES. A NRC No Detailed Affiliation Given B0/i1/10 MATHIS.W. LAMRUSKI.S., RAY, J NRC No Detailed Affiliation Given ip 15727 304
- --B2100403B3 Notification of ACRS LER Subcommittee B01120 meeting in Hashington DC Schedule oncl BATES: A NRC - No Detailed Affiliation Given B0/11/10 HICHELSON: C Director's Office 2pp 15727 305
- --8210040376 Submits evaluation of recommendations contained in NURLG-0651. "Evaluation of Steam Generator Tube Rupture Events " Licensees should investigate other techniques to more rapidly determine damage BAER, R L Safety Program Evaluation Branch 81/02/17 MURLEY, T Division of Safety Technology 26pp 15788-007
- --B210040411 Summary of B10311 operating reactor events meeting Assignment of followup review responsibility discussed Related info encl LAINAS.0 C Assistant Director for Bafety Assessment 81/03/13 EISENHULD 0 Division of Licensing 5pp 15728 263
- --8210040416 Summary of 810318 operating reactor events meeting LAINAS.9 C. Assistant Director for Safety Assessment 81/03/24 EISENHUT.D G Division of Licensing 4pp 15728 328
- --B210040421 Summary of 810325 operating reactor events meeting LAINAS.Q C Assistant Director for Bafaty Assessment D1/03/26 EISENRUT.D Q Division of Licensing App 15728 332
- --8210050006 Forwards draft rept, "Potential for Water Hammer During Restart of RHR Pumps for BHR Nuclear Plants " HUANG,Y S Director's Office 81/03/31 MICHRLSON.C Director's Office ip 15729 008
- ~-8210050007 "Potential for Water Hammer During Restart of RHR Pumps for BIR Nuclear Plants" HUANGJ Director's Office 81/03/31 14pp 15729 009
- ~-B210050010 Forwards preliminary rept. "Initial Consideration of Potential for Water Hammer in Bteam Condensing Mode of RHR Sys Operation for BMR Nuclear Plants " HUNNOY B Director's Office. B1/03/31 MICHELSON.C Director's Office ip 15729 023.
- --8210050011 "Initial Consideration of Potential for Water Hammer in Steam Condensing Mode of RHR Bys Operation for BWR Nuclear Plants " HUAND.J Director's Office 81/03/31. 11pp 15729 024
- --8210050021 Summary of 910408 operating reactor events meeting LAHAB.0 C. Assistant Director for Safety Assessment 81/04/15 EIBENHUT.D Q. Division of Licensing 4pp 15729 035 24X Fichs 50-000-82/04/28.8210010008

- --8210050031 Speech entitled "Assessment of Operational Safety Data in NRC" presented at 810427-29 Fourth Symposium on Training of Nuclear Facility Personnel in Gatlinburg.TN MICHELSON.C., HELTEMES.C. J. Director's Office 81/04/27 24pp 15729 046
- ~-8210050035 Summary of 810422 operating reactor events meeting Related info encl LAINAS.O C Assistant Director for Safety Assessment 81/04/29 EISENHUT.D O Division of Licensing 10pp 15729 074
- ~-8210050038 "Power Reactor Events, Jan-Feb 1981," Vol 3, Number 2 MASSARD, S A Director's Office 81/05/31 14pp 15729 084
- --8210050064 Summary of 810506 operating reactor events meeting LAINAS.CC Assistant Director for Safety Assessment B1/05/1; E[SENHUT.D G Division of Licensing 9pp 13729 151
- --8210050075 Summary of 810513 operating reactor events meeting LAINAS,O C Assistant Director for Safety Assessment 81/09/40 EISENHUT.D G Assistant Director for Licensing 6pp 15729 860
- --8210050082 Forwards IE Buitetin 8t-03, "Flow Diockage of Cooling Water to Safety Sys Components by Corbicula Sp (Asiatic Clam) & Mytitus Sp (Mussel)," for issuance on 810410 SNIEZEK,J H. Division of Resident & Regional Reactor Inspertion 81/04/08 GRIER,D H. Region i, Philadelphia, Office of the Director (81/03/01) O'REILLY,J P. Region 2, Atlanta, Office of the Director (81/03/01) KEPPLER,J G. Region 3, Chicago, Office of the Director (81/03/01) XEPPLER,J G. Region 3, Chicago, Office of the Director (91/03/01) Pop. 15729 169
- --0210050007 Summary of 010520 operating reactor events meeting LAINAG.G C Assistant Director for Safety Assessment 01/05/2/ EISENHUT.D G Division of Licensing 7pp 15729 189
- --8210050093 Summary of 810403 operating reactor events meeting LAINAS, 8 C. Assistant Director for Bafety Assessment 81/06/09 EISENHUT, D. 6 Division of Licensing 7pp 15729 196 24X Ficha 50-000, 82/06/28, 8210010008
- --B210050116 Forwards comments & questions re GE response to Ofc for Amalysis & Evaluation of Operational Data safety concerns of pipe breaks in BHR scram sys, in response to D Eisenhut B10603 request MICHELBON, C Director's Office B1/06/14 Nuclear Reactor Regulation, Director 2pp 15729 203
- --B210050124 Summary of B10410 operating reactor divents meeting LAINAB.0 C Assistant Director for Safety Assessment 81/06/1/EISENHUT.D O Division of Licensing 5pp 13727 217 24X Fiche 50-000.82/06/28.8210010008
- --8210050135 Summary of 810617 operating reactor events meeting LAINAB.0 C Assistant Director for Safety Assessment 81/06/23 EISENHUT D 0 Division of Licensing 4pp 15729 246 247 Fichs 50-000.82/06/28.8210010008
- --8210050155 Forwards summary of NUREG/CR~1682, "Electrical ref Insulators in Reactor Accident Environ." Used as ref in Ofc of Nuclear Regulatory Research comments on safety concerns re pipe breaks in BHR acram sys EL-ZEFTAHY.M Director's Office 81/06/26 Director's Office 5pp. 15727 285
- --8210DS0164 Summary of 810708 operating reactor events meeting Noxt meeting scheduled on 810715
 LAINAB.0 C Assistant Director for Safety Assessment B1/0//13
 EISENBUT, D 0 Division of Licensing Bpg 15727 355 247
 Fiche 50-000,82/06/28,8210010008
- --8210050181 Discusses plans for managing NRPD8 per 810708 telcon Data & repts from data base will continue to be made available to NRC Hesting scheduled on 810721
 HILKINSON, E. P. Institute of Nuclear Power Operations 81/07/09
 DIRCKB, W. J. Office of the Executive Director for Operations Spp. 187070 019
- --82i0050i90 Summary of Bi0723 operating reactor events meeting Next meeting scheduled for Bi0B05
 LAINAB.0 C Assistant Director for Safety Assessment B1/07/29 EIBENUT, D 0 Division of Licensing Spp 15730 075 24X Fiche 50-000,82/06/28,82i0010008
- --8210050200 "Power Reactor Events. Mar-Apr 1981," Vol 3. Number 3 MASBARO, 8 A Director's Défice 81/08/31 18pp 15730 086
- --8210050209 "Operational Safety Data Review," Chapter 0515 d Director's Office. 81/08/12 8pp 15730 107

- --8210050212 Summary of 810806 operating reactor events meeting Related info encl Next meeting scheduled for 820812 LAINAS, 0 C. Assistant Director for Safety Assessment Bi/OB/10 EISENHUT, D O Division of Licensing 16pp 15730 115 24X Fiche 50-000,82/06/28,8210010008
- --8210050217 Summary of B10B19 operating reactor events meeting Status of followup review responsibility assignments encl LAINAS.0 C Assistant Director for Safety Assessment B1/0B/24 E1SENHUT.D @ Division of Licensing 5pp 19730 123 24X Ficha 50-000,82/06/28.8210010008
- --B210050403 Forwards draft rept entitled "Characteristics of LEH Reporting Sys " RYDER,C ACRS - Advisory Committee on Reactor Safeguards 81/08/31 ACRS - Advisory Committee on Reactor Safeguards ip 15730 146
- --8210050409 Draft rept entitled "Characteristics of LER Reporting Sys" RYDER, C.P. ABBOTT. C.C., MCCRELESS, T.O. ACRS -- Advisory Committee on Reactor Safeguards 81/08/28 43pp 15730 147
- --B210050424 Advises that SECY B1-494 will be discussed at B10707 subcommittee meeting on evaluation of LERs QUITTECHREIBER ACRS Advisory Committee on Reactor Safeguards B1/07/02 HATHIS W, WARD, D, MOELLER, D ACRS Advisory Committee on Reactor Safeguards 2pp 15730 203
- --B210050426 Provides presentation schedule for 810909 subcommittee meeting for evaluation of LERs QUITTSCHREIBER ACRS - Advisory Committee on Reactor Safeguards B1/09/02 MICHELSON. Birector's Office 3pp 15730 227
- --8210050434 Comments on LER Subcommittee 810909 meeting Ofc for Analysis & Evaluation of Operational Data could benefit from analytical models used in other fields & other stages of data analysis

 RYDER, C. ACRS Advisory Committee on Reactor Safeguards
 81/09/11 MATHIS-W M. ACRS Advisory Committee on Reactor Safeguards
 2pp 15730 238
- --B210050436 Discusses methods for preventing recurrence of LERs Attention should be given to mat1 suppliers & architect engineers as LER originators MOELLER, D.W. ACRS Advisory Committee on Reactor Bafaguards B1/09/06 MATHIB.W. ACRS Advisory Committee on Reactor Safeguards ip 15730 240
- --82100\$0473 Forwards draft proposed rule re integrated operational experience reporting for comment HICHELBON, C. Director's Office 81/09/IB ROSSIN, D. Affiliation Unknown 9pp 15730-251
- --B210050478 Forwards SECY-B1-505 re systematic assessment of licensee performance, first rept on licensee assessments W/o encl licensee facility ratings for operating power reactor licensees & CP holders

 MAJOR: ACRS Advisory Committee on Reactor Safeguards
 81/09/21 ACRS Advisory Committee on Reactor Safeguards ip 15700-261

naru of 810916 operating events meeting List of

ector for Safety Assessment 81/09/21 Licensing 9pp 15730 263

> Zudans comments on LER sys tee on Reactor Bafeguards Advisory Committee on Reactor

- --B210050496 Comments on LER reporting sys LER cover sheets contain mitleading into re facility in question LERs should not be grouped in packets w/o appropriate sub, heading MDELLER,D W ACRS Advisory Committee on Reactor Safeguards 81/09/19 MAJOR,R ACRS Advisory Committee on Reactor Safeguards 19 15730 278
- --8210050500 "Power Reactor Events May June 1981," Vol 3, Number 4 MASSARO, S A . RIZZO, J Birector's Office 81/10/31, 14pp 18730 319
- --B210050514 Topical rept evaluations of Revision 2 to MCAP-9558, "Mechanistic Fracture Evaluation of Reactor Coolant Pipe " & MCAP-9787, "Tensil & Toughness Properties of Primary Piping Weld Metal for Use in " * NRC No Detailed Affiliation Given 82/04/28 24pp. 15731 005

- --8210050520 Summary of 811007 operating reactor events meeting Blatus of previous assignments end LAINAS, & C Assistant Director for Safety Assessment 81/10/13 EISENHUT, D & Division of Licensing 9pp 15731 033 24x Fiche 50-000, 82/06/28, 8210010008
- --8210050533 Summary of 911021 operating reactor events meeting list of attenders, events discussed & assignments encl LAINAS, 0 C Assistant Director for Safety Assessment 91/10/27 EISENHUT, D 0 Division of Licensing opp 19731 053 24% Fiche 80-000,82/06/28.8210010008
- --8210050537 Discusses proposed rule dealing w/LER sys Features will include compatibility of sys w/100FR50 72
 MAUDRIR ACRS Advisory Committee on Reactor Sefeguards 81/11/02 MATMIES M ACRS Advisory Committee on Reactor Sefeguards 19 15731 071
- --8210050542 Forwards info re selection of LERs worthy of AD rept gtates

 MDELLER, D 9 ACRS Advisory Committee on Reactor Dafeguards
 81/10/24 MAJOR.R ACRS Advisory Committee on Reactor
 8afeguards 2pp 15731 092
- --8210060001 Summary of 811028 operating reactor events meeting itst of attendees; events discussed & review assignments encl LAINAB, O C Assistant Director for Bafety Assessment DI/11/0 J EISENHUT, D Q Division of Litensing 5pp 15731 074.
- --8210060005 Revised draft rept, "Compressed Air & Backup Nitrogen Sys Nuclear Power Plants" HAGEN,E W Clak Ridge National Laboratory. FIN 8-0755 W-7405-EN9-26 81/11/13 NRC - No Detailed Affiliation Given BOpp 15731 122
- ~~B21006000B Forwards background mat! for 81120B reactor operations subcommittee meeting on proposed rule & reg guide ro LER rulemaking
 MAJOR.R ACRS Advisory Committee on Reactor Safeguards
 B1/11/19 MATHIB.W ACRS Advisory Committee on Reactor Safeguards
 1p 15731 205
- ~-8210050009 Draft Reg Guide : XXX.Revision 3, "LER 8ys " a NRC - No Detailed Affiliation Given 81/11/16 22pp 19731 215
- --8210060026 Discusset Zudans comments re ACRS LER subcommittee through meeting Change in connectivity function of sequence coding proposed Fundamental change involved MAJDR.R ACRB Advisory Committee on Reactor Safeguards 81/11/20 MATHIB.W M ACRB Advisory Committee on Reactor Safeguards 1p 19731.237
- --8210050042 Summary of 811112 operating reactor events meeting tits (attendees, events discussed & review assignments encl
 LAINAS, G C Assistant Director for Safety Assessment BI/11/2)
 EIBENHUT, D Q Division of Licensing 6pp 18731 240
- --8210060068 Discusses 811107 itr re LERs & AD repts per 85CY 01 30M BECY 81-602 Meeting to discuss proposed LER rule scheduled for 811208. MAJOR.R. ACR8 - Advisory Committee on Reactor Safeguards 81/11/24 MOELLER, D. W ACR8 - Advisory Committee on Reactor Bafeguards. 2pp 15731 247
- --8210060079 Requests info re-notification of ACRB concerning properture change for immediate notification of significant events per BECY 81-598 MDELLER:D H. ACRS Advisory Committee on Reactor Refeguerda B1/11/07. MAJOR:R ACRS Advisory Committee on Reactor Bafeguerds ip. 18731 249
- --8210060084 "Background Reading for Discussion of Program & Methods Screening & Analysis of Operational Info at NRC," presented to IAEA Advisory Group on 811123-27. MICHELBON.C Director's Office 81/11/23 25pp 13731 284
- --8210060100 Summary of 811202 operating reactor events meeting a sate attendess events discussed & status of previous assignments entl.

 LAINAG.O C Assistant Director for Safety Assessment BI/12/O.

 EISENHUI.D O. Division of Licensing. Spp 15731 345
- --8210060363 Bummary of 811216 operating reactor events meeting that attendees, events discussed & status of massignments encl LAINAS.O C Assistant Director for Safety Assessment 81/12/20
- --8210060369 "Power Reactor Events, Jul-Aug 1981, " Vol 3, Number 5 MASSARD, 8 A., RIZZD, J. Director's Office. 82/01/31 14pp

- --B210C603B1 Discusses Zudans input re sequence coding & search sys, per 810930 memo Implementation of approach would require major revision to sys hell-femes C J Director's Office 81/10/22 MAJOR, R ACRS --Advisory Committee on Reactor Eafeguards ip 15731 239
- --8210060427 Forwards comments re potential consequences of load drop in LHRs, providing understanding & background of scope of current regulatory review for accidents EL-ZEFTANY. M Director's Diffice AEOD/E205 88/02/16 Director's Office 13pp 19732 281
- --8210060449 Responds to request for review of LERs on steam generator leats Distribution of problems from 1976 to 1981 provided RYDER.C.P ACR8 - Advisory Committee on Reactor Safeguards 82/03/05 MATHERW ACR8 - Advisory Committee on Reactor Sefeguards 3pp 15745 026
- --8210060452 Comments on "Learning Function in Nuclear Reactor Operation to Implications for Siting Policy " Analysis does not support finding that adding reactors to existing sites enhanced learning MACEVOY, J A ACRB Advisory Committee on Reactor Bafeguards 82/03/15 COTTRELL, W D Oak Ridge National Laboratory 5pp. 13475 045
- --B21007000B Responds to B20324 request for assessment of reactor coolant pump stude Ceneral rept on all mechanisms of bolting degeneration in progress Visual insp of reactor coolant sys bolts recommended HANAUER, B M Division of Safety Technology B2/04/05 ETSCHHUT, D O Division of Licensing 5pp 15745-265
- 6210040357 "Should Addi Independent Power Source Bo Required for CHR Sys "
 ATEF1.8 , LINER, R, HUOHES, A Science Applications, Inc.
 MSC-03-82-096 82/07/15 10pp 15597 280
- B210040350 Responds to FOIA request for BECY-82-728 & BECY-82-720 ruccerdinated program for steam generators Documents available in PDR FELTON, J.M. Division of Rules and Records 82/09/27 FORTING, K.C. Louenstein, Neuman, Reis, Axelrad & Toll ip 15597-291
- --8204200390 SECY-82-0728
 Responds to Chairman 820301 request for short-term actions re-performance of steam generators Comprehensive water chemistry criteria for steam generators should be implemented DIRCKS-W J Office of the Executive Director for Operations 82/04/03 2pp. 15597 292
- --8205270507 8ECY-82-072C
 Advises Commission of results of 820428 meeting w/industry re-proposed coordinated program for steam generators
 Proposal in 8ECY-82-72A re-formal structural organization such as policy group & steering committee rejected DIRCKS.M.J. Office of the Executive Director for Operations 82/05/17 3pp 15597 294
- --8205270526 Advises of legal difficulties re coordinated steam generator research program proposed in BECY-82-72A Reconsideration of program organization suggested in light of Federal Advisory Committee Act HALBCH.H 0 Office of the General Counsel 82/05/05 AHEARNE, J Commissioners, 4pp. 13597-297
- 8210240365 Responds to appeal re denial of FOIA request for four affidavits concerning allegations of improper const practices at facility Forwards requested info. Page 4 of E Grave affidavit withheld (ref FOIA Examption 7).

 DIRCKE.H J. Office of the Executive Director for Operations.
 82/09/24. BTEPTOE, P.P. Isham, Lincoln & Beale. 2pp. 15597 303.
- 8210950430 Responds to FOIA request for correspondence between Nuclear Assurance Corp & NRC re 1982 irradiated fuel shipments tetween Ontario & NC.Forwards App A documents.App B decuments withheld (ref FOIA Exemption 3).
 FRITONLUM Division of Rules and Records 82/08/17. RESNIKOFF, M Council on Economic Priorities 3pp. 15626 172
- --8201050245 Requests approval of alternate routes for planned irradiated fuel shipments from Chalk River Nuclear Labs to DDE Savanneh River facility, Date of arrival deleted, DANEGE,F,L. Nuclear Assurance Corp. 19955. 81/11/13. Division of Safeguards Upp. 15626; 201
- --8210050439 Provides add1 info re initial shipment of irradiated fuel per 811110 ltr.Shipment will arrive at destination on 811121. DAMESE:F.L. Nuclear Assurance Corp FLD/81/81/ETS. 81/11/17 Division of Emergency Prepar

- --8210050467 Advises of plans for series of spent fuel shipments from Chalk River to DDE Savennah River Plant DANESE, FL Nuclear Assurance Corp FLD/82/84/ETS 82/07/02 00DY. A Region 1. Office of Director 1p 15426 232
- --8210080471 Corrects 820702 prenotification of planned series of irradiated reactor fuel shipments from Chalk River to Savannah River Plant Port of entry is Derby Line, VT DANESE, F L Nuclear Assurance Corp FLD/82/85/ETS 82/07/07 00DY: A Region 1. Office of Director 1p 15626 233
- 8210030512 Responds to FOIA request for insp & enforcement records is accidents of F Lawson & H Dillon at facility. Union Electric CP & other NRC safety mails or nanuals Forwards two documents Remaining records available in PDR FELTON, J M Division of Rules and Records 82/09/21 1002, M V 1908. V M 299 15626 244 24% Fiche 50-000, 82/09/21, 8210050512
- --B210050518 Region 3 daily rept for 780807 * Region 3. Chicago, Office of the Director 78/08/07 1p 15626 246 247 Fiche, 50-000, 82/09/21, 8210050512
- --B210050322 PND-III-78-062 on 780804, two workers seriously injured whin hit by support girder for polar crane rail OSHA notified BCHWEIBINZ, E.R. Region 3. Chicago, Office of the Director 78/08/04 ip 15626 247 24X Fiche 30-000, 82/09/21, 8210050512
- 8210050562 Responds to FOIA request for SECY-75-588, 588A, 588B, SECY-R-74-64, SECY-81-600A & SECY-81-622A Document review in progress FELTON, J. M. Division of Rules and Records 82/09/17 CONNOR, L. Doc-Search Associates 1p 15626 242
- 8210060403 FOIA request for itrs from Ohmart Corp & TX Nuclear justifying proprietary claims re FOIA 82-A-12 COLLINS,P L. Research Counsel of Nashington 82/09/03 DIRCKS,W J Office of the Executive Director for Operations ip 15636 235
- 8210060406 Responds to FOIA request for lirs from Ohmart Corp & 1X Nuclear justifying proprietary claims re FOIA 82-A-12 Forwards documents. FELTON.J M Division of Rules and Records 82/09/22 COLLINS,P L Research Counsel of Washington ip 15636 236
- --82:00604:1 Responds to 820630 request for info re FGIA 82-263 All info contained in general license rept considered proprietary Any rept dtd earlier than Apr 1976 may be released w/o significant competitive harm HENDRICKIN 0 Texes Nuclear Div (subs of Ramsay Eng Co) 82/07/09 FELTON, J.M. Division of Rules and Records 2pp 13636 238
- --8210060415 Responds to 820630 ltr re Ohmart Corp quarterly repts listing devices distributed to general licenses Repts are always treated as confidential Disclosure would harm competitive position CODK, H L Ohmart Corp 82/07/13 FELTON, J M Division of Rules and Records, 2pp 15636 240.
- 8210060419 Responds to FOIA request for GECY-82-728 & SECY-82-72C recoordinated program for steam generators Document review in progress.
 FELTON, J M Division of Rules and Records.
 ELTON, J M Division of Rules and Records.
 Lowerstein Neuman, Reis, Azelvad & Toll ip 15636 255
- 8210060429 Forwards CJ Johnson FOIA request for rept to EPA. "Pu & Human Tissues Re Smoking, Age, Residence Near Rocky Flats & Eastern CO " Response requested, FELTON, J M Division of Rules and Records B2/09/27 OREEN. J. B Environmental Protection Agency ip 15634 209
- 8210060434 Responds to FOIA request for all declassified matl on Manhattan Project NRC has no documents subj to request FELTON, J M Division of Rules and Records 82/09/15 CHAIKEN, J A Affiliation Unknown. ip 15636. RO6
- B210060442 Responds to FOIA request for input to Chapter 7 & App J of FEB & suppl to CRER. Documents listed in App A available in PDR App B documents completely withheld advice & opinions (ref FDIA Exemption 5) FELTON, J M Division of Rules and Records, B2/08/24 WEISB, E R Harmon & Weiss 4pp. 15636 040.
- 8210070007 Responds to FDIA request for eight categories of records re steam generators & steam turbines App A documents provided in R Udell FDIA Request Bi-313, Forwards documents listed in App B FELTON, J. H. Division of Rules and Records 82/08/10. LONG, D. J. Hinthrop, Stimson, Putnam & Roberts. 9pp 15645:063 24X Fiche: 50-000, 82/08/10, 8210070007.

- --7812200285 Summariles steam generator tube leak on 780920 & 1hsp Leak rate reached 560 gpd at 5 00 AM, caused by two tubes w/cracks located w/in thickness of tube sheet & one tube w/cracks located w/in thickness of tube sheet & one tube w/cracks plug General cause plant conversion to AVT KOONAM, V S Engineering Branch (Pre 791030) 78/12/12 GRIMES, B K Assistant Director for Engineers & Projects (Pre 790625) 2pp 15645 244 24X Fiche 50~000.82/09/10,8210070007
- --7909280105 Discusses steam generator tube leak & inservice insp Steam generator caused by deep crevice cracking of three tubes within tube sheet Hot leg tube tests indicated 52 tubes w/ deep crevice cracking in eccess of 50% plugging limit NOBNAN, V S Engineering Branch (Pre 791030) 79708/17 FISEINUTL 0 G Division of Operating Reactors Jpp 15645 254 24% Fiche 50-000, 82/09/10.8210070007
- --8201210107 Advises that utils should be informed that impact of tube plugging should be evaluated for all SAR Chapter [5 events & results of evaluation submitted when requesting approval of new steam generator tube plugging limit I'OVAK.T M Assistant Director for Operating Reactors 81/12/29 Assistant Director for Operating Reactors 2pp 15445 281
- --8203190034 Forwards State of IL Pollution Control Board 820127 ltt & delineates areas of responsibility re response LARMAS, G.C. Assistant Director for Safety Assessment 92/02/09 JCHNSTON: B.V. Assistant Director for Materials & Qualifications Engineering ip 15645-124
- --82032650003 Recommends that STS limits for coolant activity & sampling requirements be incorporated into remaining operating plant Tech Specs w/other substantive change requests lodine dose problems can be avoided by limiting coolant HOUSTON.R W Assistant Director for Radiation Protection 82/03/04 NOVAK.T Assistant Director for Operating Reactors 2pp 15645 285
- --8210070135 Devil rept input re Ginna 820125 steam generator tube rupture event NRC 16th monthly status rept to Congress re TMI-1 restart enci + NRC No Detailed Affiliation Given 82/03/11 3pp 15645 128 24% Fiche 50-000 82/08/10.8210070007
- --8210070196 Distusses intervice inspiprograms for PMR steam generator tubing to monitor conditions of tubing in all PMR operating plants Licensees w/o steam generator tube surveillance program should be required to suppli Tech Specs SCHROEDER: F. Division of Technical Review (MRR-1975 only) 75/04/21 GIMBUSSDA Division of Reactor Licensing (NRR-1975 only) 3pp 15645-207
- --8210070198 Recommended Tech Specs 3 4 5 & 4 4 5 re steam generator tubing surveillance

 * Division of Technical Review (NRR-1975 only) 75/04/21 20pp 15445 210
- --8210070205 Submits summary of findings & comments Te facility steam generator tube leak incident & inspiresults contained in Annual Operating Rept 1976 Recommends that licensee be requested to submit inspirogram for next scheduled inspishAO.L C Engineering Branch (Pre 791030) 77/07/25 EISENBUT.D 0 Division of Deprating Reactors Ppp 15645 235 24X Fiche 50-000,82/08/10.8210070007
- ---8210070235 Agrees w/801028 memo suggestions All assistant directors in Dis of Licensing requested to follow same approach EISENHUT.D Q Division of Licensing 80/11/07 MARTIN.J D Division of Waste Management ip 15645-290
- 8210070029 Partial response to FOIA request for documents re CRBR CIS & all comments, evaluations & documents from BNWL re EIS Forwards documents listed in App A FELTON, J M Division of Rules and Records 82/07/16 WEISS, E R Harmon & Weiss 8pp 15648 004
- --8210070123 Forwards updated responses to comments on 1976 DES.
 NUREC-0137 re safeguards & fuel cycle Info re radwaste
 shipments, disposal site & licensed burial site included
 LOHENBERO.H Office of Nuclear Material Safety &
 Safeguards, Director CRIR 82-647 82/06/15 LEECH, P Clinch
 River Breeder Reactor Program Office 15pp 15648 073

- --B210070421 Notifies that no physical security concerns exist re expert of low enriched U to Japan under export license application KENN-1896 SHERR.T 9 Material Control & Accountability Development Branch 81/12/17 DEVINC.J B Assistant Director for Export/Import & International Safeguards 1p 15647 007
- --8210070426 Recommends that N4SS provide representative to join State
 Dept entourage to Canada on 820112-14 to exchange technical
 info on application of IAEA safeguards to on-load reactors
 tHIRES, L. NRC No Detailed Affiliation Given B2/01/07
 CHAPELL, D. NRC No Detailed Affiliation Given 19 15447 000
- --B210070428 Forwards summary of Interagency Steering Group 820106 meeting w/Ofc of Intl Programs & NMS8 re action plan activities. US program for technical assistance & resource allocation to IAEA DIRCKS, W J Office of the Executive Director for Operations 82/01/19 PALLADING, N , GILINSKY, V , BRADFORD, J Commissioners App 15647 009
- ---8210070431 Requests that summary of Interagency Steering Group D20165 meeting be forwarded to Commission No major decisions reached SHEA.J R Office of International Programs. Director 02/01/14 DIRCKG.W J Office of the Executive Director for Operations 1p 15447 014
- --8210070434 Notifies that no physical protection concerns exist reexport of highly enriched U to Japan Update on status of negotiations requested SHERR.T S Haterial Transfer Safeguards Licensing Granch G2/02/09 DEVINE, U B Assistant Director for Export/Import & International Safeguards 1p 15547 015
- --8210070436 Notifies that no physical protection concerns exist #8
 applications to export low enriched U to Japan under
 Licenses XBNM-1723,1925,1928 & 1876
 SHERR.T 8 Material Transfer Safeguards Licensing Branch
 82/02/25 PETERSON.M R Assistant Director for Export/Import &
 International Safeguards 1p 15647 016
- --8210070441 Forwards response to Bill25 & 30 ltrs re IACA safeguards & Classified info received through briefings
 PALLADING, N J Commissioners B2/03/02 OTTINGER, R L House of Rep , Energy & Commerce 12pp 15647 017
- --8210070445 Forwards Intl Bafeguards & foreign physical security review for comment & inclusion in draft Commission paper re proposed export of highly enriched U to West Gormany & Switzerland BURNETT-R F Division of Safeguards 82/03/08 GHEA-JR Officer of International Programs, Director 2pp 15647-036
- ---8210070447 Notifies that no physical protection concerns exist reapplications to export low enriched U to Japan, Inforquested re status of facility attachment to Fukushima I. Unit 4
 SHERR.T S Material Transfer Safeguards Licensing Branch 82/03/11 PETERSON.M R Assistant Director for Export/Import & International Safeguards ip 15647 038
- --8210070448 Speech entitled, "Nuclear Common Sense," presented at 020, AIF fuel cycle conference KENNEDY,R T President of US & Executive Offices 82/03/22. 13pp 15647 039
- --821007045; Forwards trip rept of 820315-26 visit to Vienna Austria to working consultants session on IAEA safeguards effectiveness assessments

 BRACH, E W Office of International Programs, Director 02/04/08

 OREEN, L Brookhaven National Laboratory 6pp 13647 052
- --8210070454 Forwards transcript of Bubcommittees on Intl Brourity & Scientific Affairs & Intl Economic Policy & Trade Committee on Foreign Affairs 820318 hearing re IAEA safeguards Edited comments requested by 820402 KAMMERER, C Office of Congressional Affairs 82/03/30 PALLADIND, N, GILINSKY, V, AHEARNE, J Commissioners & 15447 057
- ---82:0070458 Transcript of Subcommittees on Intl Security & Scientific Affairs & Intl Economic Policy & Trade & Committee on Foreign Affairs 820318 hearing in Washington, DC re IACA safeguards improvements

 4 House of Rep 82/03/18 110pp 15647 058

- --8210070464 Discusses plan established for fulfilling Ofc of Executive Director for Operations request for info re NRC efforts to improve IAEA safeguards Accuracy of info reported by states to IAEA needs major improvement WIRFS.L NRC NO Detailed Affiliation Given 82/05/04 BURNETT.8 NRC No Detailed Affiliation Given 4pp 15647 171
- --B210070467 Forwards draft IAEA guidelines for nuclear facility design, incorporating design features to facilitate implementation of intlitafaguards Comments requested by B20021
 SHERRITS Material Transfer Safeguards Licensing Branch B2703707 GRICKSON, R.A. Power Reactor Safeguards Licensing Branch EVANS-L.J. Fuel Facility Safeguards Licensing Branch COMEN.K. Office of International Programs, Director 44pp 13647 175
- -- E210070468 Forwards memo for Commission providing summary of significant NRC & Executive Branch efforts to improve IAEA rafeguards H/o encl SHEA, J R Office of International Programs, Director 82/05/21 DIRCKS, H J Office of the Executive Director for Operations 10 13647 223
- ~-6210070471 Forwards draft Commission paper re application for license to export highly enriched U to France Comments & license conditions specified in Encl 2 should be included in license BURNETY. If Division of Safeguards 82/05/25 SHEA, J R Office of International Programs, Director 3pp 15647 224
- --B210070473 Comments on DDE analysis re retransfer of spent fuel assemblies from Japan to United Kingdom & France for reprocessing Advanced notification required if fuel shipment enters US territorial waters SHERR, T & Haterial Transfer Safeguards Licensing Branch B2/06/03 INMERMAN, J V Assistant Director for Export/Import & International Safeguards 2pp 15647 227
- --8210070475 Summarizes 820607-08 meeting w/lAEA in Dethesda, MD re lAEA safeguards agreement Problems associated w/US reporting of nuclear mati info to IAEA discussed SHERR. 18 Division of Safeguards 82/06/09 DAVIS. J @ Diffice of Nuclear Material Safety & Safeguards. Director 2pp 15647 229
- --8210070478 Discusses corrective actions re reporting transactions & inventories for UB facilities selected by IAEA Bys to provide correction data to IAEA in acceptable format should be developed SHERR: IS Haterial Transfer Safeguards Licensing Branch 82/05/18 DDYLE:0 J Union Carbide Corp 2pp 15547 231
- --8210070480 Forwards intl safeguards & foreign physical security review sections for inclusion in Commission paper re retransfer of low enriched U fuel assemblies from Federal Republic of Germany to Peru SEERR, IS Haterial Transfer Safeguards Licensing Granch 82706/16 ZIMHERMAN, J V Assistant Director for Export/Impurt & International Safeguards 2pp 15647 233
- ~-8210070482 Bubmits summary of activities to support interagency efforts to strengthen IAEA safeguards during first half of CYB2 BURKETTER F Division of Safeguards 82/07/13 DAVIB, J Q Office of Nuclear Material Safety & Safeguards, Director 29pp 15647 235
- --92:0070484 Notifies that no physical protection concerns found reapplication for license to export single reload of low enrithed U to Japan
 SKERR.T 8 Material Transfer Safeguards Licensing Branch
 82/06/23 ZIMMERMAN.J V Assistant Director for Export/Import & International Bafeguards ip 13647 269
- --82100704B5 Forwards list of priorities activities for FYR3 per f Hourks
 820824 memo.
 CDHEN.K D Assistant Director for Export/Import & International
 Safeguards 82/07/13 Assistant Director for Export/Import &
 International Safeguards 3pp 15647 264
- --82:0070486 Notifies that no special physical protection or intl safeguerds concerns identified re Amend i to application to expect low enriched U to Malaysia BHERRIS Haterial Transfer Bafeguards Licensing Branch 82/06/28 ZIMMERHAN.J V Assistant Director for Export/Import & International Safeguards ip. 15647:267.
- --8210070488 Speech entitled "Nuclear Bafeguards Challenges & Realities," presented at 22nd annual meeting of Inst of Nuclear Hatls High KRATZERH B International Energy Associates: Ltd 82/09/10 27pp 15647 288

- ~~8210070489 Notification of 820908-10 consultant meeting to discuss draft guidelines for design features to facilitate intl safeguards Draft guidelines ent!

 SANDERS.K E Office of Nuclear Material Safety & Safeguards, Director 82/06/29 HOUCK, F. NRC No Detailed Affiliation Olven SHERR.T Office of Nuclear Material Safety & Safeguards, Director COHEN, K. Office of International Programs, Director 68pp 15647 297
- 8210070417 Responds to FOIA request for info re each NRC licensee in States of PA.DE & NJ Forwards three computer printouts furnishing names & addresses of licensees Info re licensee this executive officers not maintained FELTON.J M Division of Rules and Records 82/09/27 FREDLAND.D R Affiliation Unknown lp 15446 007
- --B210070423 Computer printouts listing names & addresses of NRC licensees in States of NJ,DE & PA 4 NRC No Detailed Affil(ation Oiven B2/09/24 210pp 15646 008
- 8210080010 Add1 FDIA request re minor additions & deletions to 820003 request for 19 categories of info on nuclear reactor events & safety problems
 UDELLAR A Critical Mass Energy Project 82/06/11 FELTON, J
 Division of Rules and Records 1p 15665 022
- 0210080015 Add1 response to FOIA request for 19 categories of into remoclear reactor events & safety problems Forwards documents listed in App A Documents in App B completely withheld (ref FOIA Exemption 5)
 FELTON.J M Division of Rules and Records 82/07/12 UDELL.R A Critical Mays Energy Project 9pp 15665 027 24X
 Fiche 50-000,82/07/12,8210080015
- --8011060346 Discusses licensee responses to NRC request to commit to interim position re Generic Item B-24 venting & purging containments while at full power Plants meet interim position & existing TAGS should be closed but REEVES.E A Operating Reactors Branch 1 BO/08/25 Operating Reactors Branch 1 JOpp J5668 155
- --Bi04080309 Std order for DOE work "Program for Cost Estimation for Freposed Safaty Requirements," issued to 1D Operations Ofc Statement of work encl ORENIER, BL Office of Nuclear Reactor Regulation, Director (IN A-6452-1 20-Bi-165 81/03/12 App 13665 183
- ---BI052B0476 Requests that regions confirm licensee submittal of rept for satisfactory implementation of Item 4 of IE Bulletin 79-26.

 Revision 1

 JORDAN, E. L. Division of Resident & Regional Reactor Inspection IEB-79-26 BI/05/18 GRIER, B. H. Region 1. Philadelphia, Office of the Director (BI/03/01) SEYFRIT, M. V. Region 4. Dallas. Diffice of the Director (BI/03/01) ENGELMENTH Region 5. San Francisco, Office of the Director (BI/03/01) 1p 13668 INO 24X Fiche 50-000, 82/07/12. B210080015
- --BI06220159 Supports efforts in resolving purgs valve leakage & operability issues Incorporation of leak testing position into Tech Spece should assure leakage integrity of containment BAER: R L Reactor Engineering Branch 81/06/09 DUTLER, H R Containment Systems Branch 2pp 15668, 153
- ~-8106220168 Forwards proposed [E bulletin identifying potential safety concern rs leakage of reactor bldg purge valves O'REILLY-U P. Region 2. Atlanta: Office of the Director (81/03/01) [EC-77-11 Bi/03/20 SNIEZEK, J Director's Office 5pp 18568 167
- --BiD7i7O126 Comments on proposed IE bulletin re leakage of reactor bidg purge valves issuance not marited for reasons indicated queric issues 8-20 & 8-24 provide assurance of increased surveillance testing & reduced excessive leakage SNIEZEK.J H Director's Office IEC-77-11 81/07/01 O'REILLY.J P Region 2, Atlanta, Office of the Director (Bi/03/01) 2pp 15668, 151
- --8108210025 Forwards draft suppl to IE Bulletin 81-02, "Failure of Oale Type Valves to Close Against Differential Pressure," for raview & comment JORDAN, E. L. Director's Office 81/07/23 ORIER, B.H. Region 1, Philadelphia, Office of the Director (81/03/01) D'REILLY, J.P. Region 2, Atlanta, Office of the Director (81/03/01) KEPPLER, J.Q. Region 3, Chicago, Office of the Director (81/03/01) 200 18668 181

- 1203040536 Comments on Bil21B corrections to facility assessment contained in NUREG-0B34 re hearings & discussion of systematic assessment of ficense performance Revision to NUREG inappropriate issue closed MOSELEY, N.C. Systematic Assessment of Licensee Performance Review Group B2/01/04 WESSMAN.R H. NRC No Detailed Affillation Given 1p 15668 256 24X Fiche 50-000, 82/07/12,8210060015
- 203040538 forwards performance element summary for Jul 1979-June 1980 in response to ABLB request for testimony on systematic assessment of license performance in general & facility assessment in particular MESBMAN,R H Director's Office. Office of Inspection and Enforcement 81/12/18 MOSELEY,N C Systematic Assessment of Licensee Performance Review Group 2pp 15668 254 24% Fiche 50-000,82/07/12.8210080015
- 12041204B7 Discusses problems w/water in fuel mil tank Case does not have generic implications
 TREMAN N Director's Office B2/04/06 MICHELSON.C
 Director's Office Spp 15669 036 24X Fiche 50-000.B2/07/12:
 R210AB0015
- |205190428 Forwards engineering evaluation rept. "Inadvertent Loss of Reactor Coolant Events at Sequoyah Nuclear Plant Units 1 & 2 " Rept contains recommendations which should be incorporated in ungoing Task Interface Agreement 81-15 LANNING.N D Director's Office 82/05/11 HICHELSON.C Director's Office 92/05/11 HICHELSON.C 2010080015
- 205190441 "Inadvertent Loss of Reactor Coolant Events at Bequoyah Nuclear Plant, Units 1 % 2." engineering evaluation rept LANNING, W D Director's Office | EB-80-12 02/05/31 23pp 13665 096 24X Fiche 50-000, 82/07/12.8210080015
- 205280490 Forwards diesel generator interim reliability program for operating plants & proposed Tech Specs
 MANAUER, SH Division of Safety Technology 82/05/06
 EISENHUT, D G Division of Licensing MATTSON, R J Division of Systems Integration (post 811005) THOMPSON, H L Division of Human Factors Safety 4pp 15666 031
- 205280497 "Diesel Generator Interim Reliability Program for Operating Plants " 4 Division of Safety Technology 82/05/06 22pp 15666 037
- 205280502 Proposed Tech Spets re electrical power sys 4 Division of Safety Technology 82/05/06 lipp 15666 059
- 206040401 Forwards procedures for screening operational data, particularly LERs received after 820501 Submittal replaces procedures issued by 810427 / 820315 memos MICHELSON, C Orrector's Office 82/04/23 Director's Office 15pp 15668 265
- 206070106 Operating Reactor Event Memo 82-01 re 810810 reactor scram w/water hammer event Study of Unresolved Eafety Issue A-1 shows no other water hammer events in SWR isolation condensors EISENHUT, D.Q. Division of Licensing OREM-82-002 82/05/25 VOLLMER, R.H. Division of Engineering 7pp 15645 150 24X Fiche 50-000, 82/07/12, 8210080015
- 1210080054 Forwards "Cost of Upgrading Capability to Isolate LPWR Mayn Fredwater Sys in Event of Breaks Inside Containment," final rept.in response to statement of work in TE Murley 810616 ltr re INEL technical assistance to NRR SAFFELL.B F EG&O, Inc. FIN A-6452 SAFF-155-82 82/04/14 SDLECKI,J E Energy Dept of, Idaho Operations Office ip 15665 167
 - Upgrading Capability to Isolate LPWR Main Feedwater leaks Inside Containment." final rept, per for DDE Work Order 20-81-165, "Program for Proposed Safety Requirements" A-6452 RGB-2-82 82/03/19 15µp

- ~-8210080106 Oral presentation of "New Trends in Evaluation & implementation of 8afety-Related Operating Experience "MICHELSON, C NRC No Detailed Affiliation Given 14EA-CN-39/2 2A 82/07/12, 13pp 15667 278
- ~-8210080187 Forwards draft IE bulletin on channel independence in Eita actuation sys for DNB clearance Specific items listed in Part II of app to draft NRC Manual Chapter 0213 discussed Expedited review & DMB clearance requested JURDAN.E L Director's Office 81/05/28 SCOTT.8 Document Management Branch 7pp 15668 144
- --8210080195 Forwards IE Circulars 80-15 & 81-10. Generic Lit 11 21 & 1
 Info Notice 79-13, in response to 810630 request re issuance
 of IE bulletins concerning steam voids & events at foreign
 or domestic BHR
 STELLO,V Director's Office, Office of Inspection and Inforce # 100-81-21 81/07/27 LEMIS.M I Lewis, M 20p 13660 1(1)
- --8210080197 NRC operations ctr usage chart re events at facilities * NRC - No Detailed Affiliation Oiven 82/07/12 tp 194613 C2 24X Fiche 50-000:82/07/12,8210080015
- --8210080202 Forwards questions on licensee performance rating process for use in preparing for systematic assessment of licensee performance briefing Draft responses dtd 810904 encl 4 NRC No Detailed Affiliation Given 81/08/20 paid No. Detailed Affiliation Given 18pp 18668 222
- --8210080206 Forwards SJ Chiik Bi0923 staff requirements memo re the briefing on systematic assessment of licenses performance rept Excerpts of Bi0922 briefing transcript re Commission guidance encl ALLISON.D P NRC No Detailed Affiliation Given Bi/10/01 MOSELEY.N C NRC No Detailed Affiliation Given 9pp
- --B210080207 Forwards Commission guidance for future conduct of licenses assessment process per systematic assessment of licenses performance program Commission should be advised of progress CHILK, S.J. Office of the Secretary of the Commission (inital 4) 81/10/20 DIRCKS, W.J. Office of the Executive Director for Operations 4pp 15668-250
- ---8210080213 Forwards revised description of responsibilities & For of Div of Engineering & GA
 JORDAN, E Division of Engineering & Quality Assurance in Property, SNIEZEK, J. NRC No Detailed Affiliation Given App. 176,676.
- --8210080215 Forwards revised IE organizational charts & funriquing statements for review & comment Reorganizations of 6001014 & 25 will be incorporated in NUREG-0325 BLAHAJ L. Program Support Branch 82/04/29 [.16] NHAM ; Enforcement Staff FORTUNAJR Director's Office. ()ffice of Finapection and Enforcement COBOL I Division of Fuel Facilities, Materials & Safeguards 7pp 19668 261
- --B210080216 Forwards draft IE Manual Chapter 0101 re If organis all functions Comments requested by B20624 Chapter will be included in Jul quarterly issue of changes to IE manual BRACH, B Director's Office, Office of Inspection and Information 2006/10 CODB, L. ORIMES, B. JORDAN, E NRC No Detailes Affiliation O(ven 17pp 13668 272
- --B210080217 Forwards new IE organization chart, functional statement organizational units & list of progosed personnel new organization, per NJ Palladino 1811(--tip memo Functional statements for reactor sys specialists with DEYOUNG:R C Director's Dffice, Office of Inspection and Enforcement 81/12/14 Director's Office, Office of the and Enforcement 32pp 15688 289
- 82:0080020 Responds to FOIA request for documents re preimplement review of NUREG-0737. Item III F 2 Forwards documents listed in App A FELTON. J M Division of Rules and Records 82/09/16 (1997) in Doc-Search Associates 2pp 15669 097
- ---BIOB270549 Requests add1 info through C-E owners group Fe Reat junction thermocouple reactor yessel level measurement for info should be submitted by BiO901 RUBENBTEIN.L B Assistant Director for Core & Containment Of BI/07/09 LAINAS,O C Assistant Director for flafety Asset Spp 13669,103
- --BioBi9000B Forwards LS Rubenstein 810709 memos requesting from C-E & Westinghouse owners groups re reactor vessel level measurement sys. TMI Action Plan Item II F 2 C LAINAB, Q. Assistant Director for Safety Assessment CRUICHFIELD, D Operating Reactors Branch 5 2pp 156.50 3

- -80910410478 Requests that licenses provide plant-specific submittal reinstallation of Wostinghouse reactor vessel level instrument PHILLIPS, L. E. Core Performance Branch 81/08/13 9HEA/J Operating Reactors Branch 5 2pp 65569 309
- --gj09280484 Requests that project managers transmit encl sample ltr ru Histinghouse reactor vessel level instrumentation sys for donitoring inadequate core cooling. TMI Item II F 2 3 to licensees for plants listed CRUTCHFELLD. O Georating Reactors Branch 5 81/09/16 VARGA.S A Operating Reactors Branch 1 5pp 15469 110
- --82100800(14 Advises of Commission approval re delay in implementation schedula for NURCO-0737, Item II F.2. "Add I Instrumentation for Detection of Inadequate Core Cooling "SECY-81-528A withdrawn (AINAS, O Assistant Director for Safety Assessment 82/02/10 ECBERNIUT, D. O Division of Licensing 2pp 15667-226
- 8210080038 HCAP-7870 Sizerpt from "Neutron Shielding Pads" • Hestinghouse Electric Corp 72/05/31 4pp 15669 242
- --D20B250412 Responds to B20327 memo re broken core barrel assembly thermal shield bolts at Ocomes 1 & applicability to other 3tW plants NRR review.described in encl Task Interface Agreement B1-17 dtd G11026, should be completed by B20901 tigEHNUT, D Q Division of Licensing B2/07/17 OLGHINGKI.J A Division of Engineering & Technical Programs 1p 15669 284
- 100000000 Responds to appeal re denial of FOIA request for segregable portions of draft NUREO-0844, "Resolution of Unresolved Safety Issues A-3.A-4 & A-5 Re Steam Generator Tube Integrity, "Request denied (ref FOIA Exemption 5) DINCKS.H J Office of the Executive Director for Operations 82/07/19, UDE: L.R.A. Critical Mass Energy Project 2pp 18660 331
- IOIRODIS Partial response to FOIA request for documents re St Josoph Hosp in Albuquerque.NH & 1-125 seed incident Forwards documents listed in App A FELTAN.J H Division of Rules and Records 82/08/20 DAVIES.L S Richards, Brandt, Miller & Nelson 3pp 15691 173
- Q012180362 PNA-80-039 on B01201, Btate of NM informed NRC of overexposures of patients receiving I-125 seed therapy for treatment of prostate cancer Gausedby computer dose conversion factor error Btate request hosp rept
- -8210120018 Discusses PNA-DO-039 re overexposures of patients receiving 1-129 seed therapy for prostate cancer at St Joseph Hosp. Albuquerque, NM Computer program error cited as contributing factor LUBENAU. J O NRC No Detailed Affiliation Given 80/12/02 REHM. T NRC No Detailed Affiliation Given ip 15691 178
- -BRIOIROORI Confirms BOIRRE telcon w/LW Huppert re misadministration of J-125 seeds used in prostate cancer therapy Definitive rept will be provided by BIORRE Related info anci TOPP-A A New Mexico. State of BO/12/31 KOEBEL, C St Joseph Hosp Albuquerque, NM 14pp 15671, 180
- -B210120023 Requests assistance in independent technical review of encl rept from St Joseph Hosp re misadministration of 1-125 seed implant Ltr delineating info required & article from Albuquerque Journal encl M/o enci. MDLFF, TA New Hesico. State of. 81/02/03 NUSBHAUMER.D A Assistant Director for State Agreements Programs ip 15691 192
- -8210120027 Forwards rept to 8t Joseph Hosp, Albuquarque, NM remisadministration of I-125 seed implant Event attributed to personnel error & lack of communication between computer plan davelopers & users Comments requested by 810227 NJ888AUMER, D.A. Assistant Director for State Agreements Programs 82/02/23 H109IN80THAM, L. Radiological Safety Branch. CUNNINOHAM, R. Advenced Fuel & Spent Fuel Licensing Branch 19 1949 193

- --8210120030 Advises that hosp rept re misadministration of I-125 seed implant therapy raises more questions than answers Related info encl HIOOINBOTHAM.L. Radiological Safety Branch 62/08/20 NUSSBAUMBER, D.A. Assistant Director for State Agreements Programs 11pp 15691 194
- ~-8210120055 Discusses review of hosp rept re misadministration of I-125 seed implant therapy Rept does adequate job of defining magnitude of misadministration Contributing causes unclear Related info encl
 HILLER.Y L Licensing Hanagement Branch 81/03/09
 NUSSBAUMER.D A Assistant Director for State Agreements Programs 82pp 15691 206
- --8210120057 Forwards WR Hender review of selected matls remisadministration of I-125 seeds at St Joseph Hosp Albuquerque M/vo encl NUSSBAUMER, D.A. Assistant Director for State Agreements Programs B1/03/25 H10GENBOTHAM, L. Radiological Safety Branch MILLER, V.L. Licensing Management Branch 1p 1591 289
- --8210120062 Forwards rept re investigation of St Joseph Hosp I-125 serd incident Related info enci TOPP. A A New Hexico. State of 81/31/13 NUSSBAUMER. D A Assistant Director for State Agreements Programs 12pp 15591 290
- --B210120066 Statement of St Joseph Hosp president re treatment of 18 prostate cancer patients by 1-126 seed implantation Related info encl KOEBEL.C St Joseph Hosp Albuquerque, NM 80/12/18 68pp 13691 303
- --8210120068 "Radiation Dose Evaluation of I-125 Implants at St Joseph Hosp" ANDERSON, L. Affiliation Unknown 81/08/18 30pp 15692 008
- --82(0120075 Forwards State of NM rept re investigation of incident involving overexposure of patients treated w/l-125 seeds AD rept will be included in next quarterly rept W/o encl NUSSBAUMER D A Assistant Director for State Agreements Programs B1/11/24 CUNNINDHAM, R E Advanced Fuel & Spent Fuel Licencing Branch ip 15492 040
- 8210120090 Addl response to FOIA request for 19 categories of documents Forwards "Summery of Events Discussed At Operating Reactors Events Meeting During 1981," "Most Significant Events of 1981," & "Less Significant Events of 1981" FELTON.J Division of Roles and Records 82/07/26 UDELL.R A Critical Mass Energy Project 5pp 15692 041
- 8210120112 Advises that questions re T Hoffett 810817 memo on efforts to expedite licensing of new nuclear power plants should be answered by Chairman ROBERTS, T M Commissioners 81/08/25 HALLER, N Commissioners Ip 15690
- --8205060558 Expresses concern that 780208 NRC Manual Chapter NRC-0502, NRC incident response which pradates TMI-2 accident, remains effection should; ROBERTS.T M

. .

1

1 1

1 1 -1

> Ι, .di) 9 11

1.0 li L

Чi

July 1 事

14 , 1

 I_{\parallel}

1

- -- 8210120170 Comments on SECY 82-74 re proposed rulemaking, 10CFR50 55a, "Codes & Stds "First full sentence on Page 7 of Encl 1 is misstatement of fact Requests B Dircks response ROBERTS, T M Commissioners 82/03/04 CMLK,S Office of the Secretary of the Commission ip 15690 154
- --8204010046 Comments on Commissioner Roberts statement in SECY-82-74 on 204010046 Comments on Commissioner Roberts statement in SECY-BE Page 7 of Enct I or estimated costs applicant companies incur when applying for ASME approval Statement applies only to ASME charges made to company applying for N stamp MIMIOQUE, R B Office of Nuclear Regulatory Research, Director 82/03/18 DIRCKS, N J Office of the Executive Director for Operations ip 15670 455
- --8210120176 Forwards Ofc of Nuclear Regulatory Research memo explananing concerns re proposed rulemaking. "Godes & Stds " Section of rule in question not intended to upgrade or downgrade basic quality of product DIRCKS.W J Office of the Executive Director for Operations 82/03/24 ROBERTS.T M Commissioners ip 15690-156
- --821012018) Requests that P Paris C Irwin & R Cooper experts in fracture mechanics field be invited to Commission 820504 briefing repressurized thermal shock RQBEPTS, T M Commissioners 82/04/21 PALLADING.N Commissioners 1p 15690 159
- --9210120174 Recommends approva) of SECY 81-570 proposed amend to IODERSO. App E mod to emergency preparedness regulations ZECH, Q NRC - No Detailed Affiliation Given B1/11/25 RGBERTS. T M Commissioners ip 15590 161
- --8210120202 Requests meeting during next visit to Washington.DC to discuss subj of recent ltr to NY Times ROBERTS.T M Commissioners 82/04/16 PARIS.P.C Affiliation Unknown 1p (5690 162
- 7903090181 In accordance w/790118 application.Matl/Syproduct License 21~08362-12 for Dow Corning Corp is amended to read Cs-137 sealed sources for use in Damart Model SR-1 source holders for density & level measurements

 BASSIM.N Radioisotopes Licensing Branch (Pre 790501) 79/02/15
- --8001080054 Mati/Byproduct License 21-08362-12 for Dow Corning Corp is renewed per 790622 application Amend 5 authorizes Cs-137 for source holders for density measurement COUPER.JW Licensing Management Branch 79/11/07 3pp
- ~-8006050154 Mat1/Byproduct Lirense 21-08362-07 for Dow Corning Corp 16 amended per 800227 ltr Amend 9 changes Condition 14 as described in 800227 ltr PETTIJOHN, 5 L. Region 3, Chicago, Office of the Director
- ~-8006050188 Nat1/Byproduct License 21-08362-12 for Dow Corning Corp is amended per 800229 itr Amend & changes Conditions 15 & 18 & allows use of bicensed matt by J Banderson J Leicht, D Coff & others BETTIJOHU,S L. Region 3, Chicago, Office of the Director 80/03/17 ip 15748 094
- --B006170030 Matl/Byproduct License 21-08362-08 for Dow Corning Corp. is amended in its entirety per 790109 application Amend 10 authorizes use of C-14, tritium, P-32, I-125, I-131 & B-35 for biological tracer studies in plants

 JONES, J. A. Licensing Management Branch 80/05/06 2pp
- --8008070143 Matl/Byproduct License 21-08362-12 for Dow Corning Corp is amended per 800828 ltr Amend 7 authorizes users of of licensed matl PETTINGHN, 8 L Licensing Management Branch 80/06/26 1p
- --8101270870 Hat1/Byproduct License 21-08362-12 for Dow Corning Corp is amended per 801014 ftr Amend authorizes J Sanderson, J Esicht. D Goff, A Shovan D Hingert et al to use or supervise use of licensed mat! PETTIJOHN, S L Region 3. Chicago, Office of the Director 80/11/20 ip 15748 096
- --8102280195 Mat1/Byproduct License 21-08362-12 for Dow Corning Corp is amended per 801014 ltr Amend 8 changes reading of Condition 12 re users of licensed matl (corrected copy). COOPER.J W. Region 3. Chicago: Défice of the Director 81/02/02 ip 15748 097
- --8103160338 Mat1/Byproduct License 21-08362-05 for Dow Corning Corp is amended per 801014 ltr Amend 14 changes Conditions 12 & 16 re users use & possession of licensed mat1 GUINN,P.R. Licensing Management Branch 81/02/11 ip

- --8103160316 Mat1/Byproduct License 21-08362-13 for Dow Corning Coff #6 amended per B01022 itr Amend 3 changes Condition 12 & 14 re users, possession & use of licensed mat1 GUINN,P R Licensing Management Branch 81/02/17 1p 15748 107
- --8104170703 Mat1/Byproduct License 21-08362-05 for Dow Corning corp #1
 amended per Amend 14 changes reading of Conditions 12 & 16
 re use of licensed mat1 (corrected topy)
 GUINN,P R Licensing Management Branch 81/03/23 1p
- --8210180030 Mati/Byproduct License 21-08362-01 for Dow Corning Coff-authorizing possession & use of 10 Cl tritium.100 mCl C-14 k 100 mCl Cl-3d in any form for lab chemical research BRINKMAN,R E Atomic Energy Commission 62/04/26 lp 1574B QQ4
- -8210180032 Amend 1 to Metl/Byproduct License 21-08362-01.adding 100 nci 8-35 in any form for lab chemical research.per 63031 application BRINKMAN, R E Atomic Energy Commission 63/03/20 1p 15748 005
- --B210180034 Amend 2 to Mat1/Byproduct License 21-08362-01, priending expiration date to 660430, per 640127 application BRINKMAN, R E Atomic Energy Commission 64/02/24 jp 15748 006
- ~-B2[0]G0036 Amend 3 to Matl/Dyproduct License 21-08362-0), increasing max amount of C-14 in any form per 640507 application BRINKHAN, R E Atomic Energy Commission 64/06/04 [p 15748 007
- --8210180038 Amend 4 to Hatl/Dyproduct License 21-08362-01.changing 10180000 Amend a to metropproduct Literias allocade unicaea literase in entirety per 660000 application Amend authoritas possession of tritium.C-14 & CI-26 in any form for lab chemical research & activation analysis
 BRINKHAN, R E Atomic Energy Commission 66/03/21 4pp 15748 008
- --B210180040 Amend 5 to Mat1/Byproduct Lizense 21-08362-01, thanging expiration date to 730430, per 680321 application BRINKMAN, R E Atomic Energy Commission 68/04/03 jp 15748 010
- --B210180041 Amend 6 to Mat1/Byproduct License 21-08362-01.changing expiration date to 780430 & amending Condition 12 re users of byproduct mati,per 730201 itr BRINKMANA E Atomic Energy Commission, Directorate of License 73/02/14 1p 15748 011
- --0210180042 Amend 7 to Mati/Byproduct License 21-08362 Ol. changen. Condition 14 re possession & use of byproduct mati described in Items 6.7 & 8.per 740529 ltr Atomic Energy Commission, Directorate of Licensing 74/104 1574B 012
- --8210180043 Amend B to Matl/Byproduct License 21~08362 01.thangar Conditions 12 & 14 we possession & use of byproduct matl, per 790304 application # Licensing Management Branch 78/06/24 in 18840 des Licensing Management Branch 75/06/26 ip 15/40 QLA
- --8210180046 Amend 9 to Mati/Byproduct License 21-08362 Oi.chemgar license in entirety per 780328 application Amend authorises possession of tritium. C-14.01-36.8-35 & any byproduct satt w/Atomic Numbers 3-83 inclusive: in any form COMBS.F C Radioisotopes Licensing Branch (Pre 790501) 70 // 2pp 15748 014
- --B2101B0049 Mati/Byproduct License 21-0B362-05 for Dow Corning & authorizing possession of Br-90 sealed sources as check sources in Victoreen remote area monitoring sys HOWELL, D.B. Atomic Energy Commission 66/09/02 2pp 1574
- -8210180051 Amend i to Hatl/Byproduct License 21-08362-03-add no BNL MK-I strip sources, per 660907 & 22 ltrs CHURCHILL. B H Atomic Energy Commission 66/09/27 lp 15748 018
- --B210180054 Amend 2 to Mati/Byproduct License 21-08362-05.re=1 Subitams 6.B.7.8 & B. B to authorize possession of 25.000 7.8 CG-60 8N. Ma-1 strip sources, per telegram received 64121/2 CHRCHILL, B.W. Atomic Energy Commission 66/12/29 1p 13748, 019
- ~8210180097 Amend 3 to Metl/Byproduct License 21-08362-05.chem.s license in entirety. Amend authorizes Co-60 BNL MK-L strip sources for use in hot cell for irradiation of matis & Br.~ec called sources se check sources in monitoring sys CHURCHILL B W Atomic Energy Commission 67/01/30 Upp

- --2210)80058 Amend 4 to Nati/Byproduct License 21-08362-05, deleting Condition 16,per 670405 ltr CMRCHILL,B W Atomic Energy Commission 67/04/27 lp 15749 029
- ~-P210180061 Amend 5 to Matl/Byproduct License 21-08362-05, changing Substems 7 A & B A to read 35,000 Ci sealed sources (BNL MK-1 strip sources or Neutron Products Inc Catalog IP1-12CC5 clad wire) per 710609,0709 & 0820 ltrs HALARO: J C Atomic Energy Commission 71/08/30 ip 15748 024
- --8210180064 Amend & to Mat1/Byproduct License 21-08362-05, changing license in entirety per 711227 application Amend authorizes Co-60 smaled sources for use in hot cell for irradiation of aatls & Sr-90 smaled sources as check sources FERORIES OF Atomic Energy Commission 72/01/25 3pp 15748 025
- --BRIO1800A6 Amend 7 to Mat1/Byproduct License 21-08362-05, changing Conditions 12 & 15 re user & possession & use of byproduct nat1.per 740327 ltr
 DAVIS.R C Atomic Energy Commission, Directorate of Licensing 74/07/23 ip 13748 028
- --8210180072 Amend 8 to Mat]/Byproduct License 21-08362-05, changing Conditions 12 % 15 re user & possession & use of byproduct ogtl.per 741[2] & 750623 ltrs
 SMUPE.N W Licensing Management Branch 75/07/22 1p
 15748 029
- --B210180075 Amend 7 to Mat1/Byproduct License 21-08362-05.changing Condition 12 re user of lirensed mat1.per 750818 ltr CDLLIRS.D M Licensing Management Branch 75/10/09 lp 15748 030
- --821018007G Amend iQ to Matl/Byproduct License 21-08362-05, changing Candition i2 re user of licensed matl.per 761112 application BASSIN. N Radioisotopes Licensing Branch (Pre 790501) 77/01/17 ip 15748 031
- -- £210180080 Amend il to Matl/Nyproduct License 2i-08342-05, changing license in entirety per 761222 application Amend authorizes Co-60 sealed sources for use in hot cell for irradiation of eatls & Sr-90 sealed sources as check sources ASSIM, N Radioisotopes Licensing Branch (Pre 790501) 77/05/06 3pp 15748 032
- -- \$210180081 Amend 12 to Matl/Byproduct License 21-08362-05, changing Condition is repossession & use of licensed matl.per 771212 application BASHN.N Radioisotopes Licensing Branch (Pre 770501) 78/02/13 is 15748 035
- --8210180085 Amend 13 to Matl/Byproduct License 21-08362-05, adding Co-60 issled sources for use in Tracerlab Model DC-1 dosimeter calibrators for dosimeter calibrator 780307 application COMBS,F C Radioisotopes Licensing Branch (Pre 790501) 78/04/20 19 15748 036
- --8210180089 Amend 15 to Mati/Buproduct License 21-08362-05, changing license in entirety per 811228 application Amend authorities Sr-90 & Co-60 sealed sources as check sources in Victoreen area monitoring sys & as dosimater calibrators GUNN, P.R. Licensing Management Branch 82/04/19 3pp 15748 039
- --8210180092 Corrected Amend 15 to Matl/Byproduct License 21-08362-05, changing license in entirety per 811228 application Amend authorizes Br-90 & Co-60 sealed sources as check sources in Victorien area monitoring sys & as dosimeter calibrators GUINN.P R Licensing Management Branch 82/05/04 3pp 13748 042
- --82i0180076 Matl/Byproduct License 21-08362-07 for Dow Corning Curpauthorizing tritium as foils in F & M Model 2-2837 datector cell for use w/gas chromatography unit for sample analysis BRINKMAN,R, E Atomic Energy Commission 67/10/12 2pp. 13748 045
- --8210180098 Amend 1 to Metl/Byproduct License 21-08342-07, changing Condition 12 re user of byproduct metl.per 681224 ltr. + Atomic Energy Commission 69/01/10 ip 15748 047
- --B210180102 Amend 2 to Mati/Byproduct License 21-08362-07, changing license in entirety per 691113 ltr Amend authorizes tritium as foils in F & H Model 2-2837 detector cell for use w/gas chromatography unit for sample analysis.
 BRINKMAN, R E Atomic Energy Commission. 69/11/21. 2pp 13748 0ap

- ---8210180105 Amend 3 to Mat1/Byproduct License 21-08362-07, changing Condition 14 re possession & use of byproduct matliper 700312 ltr
 BRIMMAN R £ Atomic Energy Commission 70/03/23 lp
 18788 050
- --B2101B010B Amend 4 to Matl/Ryproduct License 21-0B362-07, changing expiration date to 771031 & amending Condition 12 re user of byproduct matt, per 720912 application
 BRINKHAN.R E Atomic Energy Commission 72/10/12 1p
 15748 051
- --8210180111 Amend 5 to Matl/Byproduct License 21-08362-07, changing Condition 14 re possession & use of byproduct matl, per 740529 ltr
 - # Atomic Energy Commission, Directorate of Licensing 74/06/20 ip 15748 052
- --8210180115 Amend 7 to Matl/Byproduct License 21-08362-07, changing Conditions (2 & 14 re user & possession & use of licensed matl, per 761222 application

 Radio(sotopes Licensing Branch (Pre 790301) 77/03/04 ip 15748 054
- --B210180116 Amend 8 to Matl/Dyproduct License 21-08362-07.changing license in entirety per 770928 application Amend authorizes tritium as US Radium Lab Model 508-1 foils in Hewlett-Packard Model 2-2837 detector cell JONES, J A. Radioisotopes Licensing Branch (Pre 790501) 78/04/10 2pp 15748 055
- --8210180118 Mat1/Byproduct License 21-08342-08 for Dow Corning Corp. authorizing C-14, tritium & P-32 in any form for use in biological tracer studies on animals & microorganisms BUCHANAN.C R Atomic Energy Commission 69/01/09 2pp 13748 038
- --8210180121 Amend 1 to Mat1/Byproduct License 21-09362-08, changing license in entirety per 681113 ltr Amend authorizes C-14, tritium & P-32 in any form for use in biological tracer studies on animals & microorganisms
 BRINKHAN, R C. Atomic Energy Commission 69/11/21 ip 15748 060
- --8210180125 Amend 2 to Metl/Byproduct License 21-08362-08, changing Condition 13 re possession & use of byproduct matl.per 700312 itr
 BRINKMAN.R E Atomic Energy Commission 70/03/20 ip 15748 O&1
- --8210180127 Amend 3 to Matl/Dyproduct License 21-08362-08, adding I-125 & I-131 in any form for use in biological tracer studies on animals, plants & microgramisms, per 720814 ltr
 DRINKMAN.R E Atomic Energy Commission 72/09/25 ip
 15748 062
- --82i0180132 Amend 5 to Mat1/Byproduct License 21-08362-08, adding 8-35 in any form for use in biological tracer studies on animals, plants & microorganisms, per 740306 ltr # Atomic Energy Commission, Directorate of Licensing 74/03/20 in
- --8210180135 Amend 5 to Matl/Byproduct License 21-08362-08, changing Condition 13 re possession & use of byproduct matl.per 740329 ltr * Atomic Emergy Commission, Directorate of Licensing 74/06/20 fp 15748 065
- --8210180137 Amend 7 to Matl/Byproduct License 21-08362-08, changing Condition 13 re-possession & use of licensed matl.per 761203 application.

 # Radjoisotopes Licensing Branch (Pre 790501). 77/01/10 | Ip
- --B210180140 Amend B to Matl/Byproduct License 21-08362-08, changing Conditions 12 & 13 re user & posession & use of licensed matl.per 761227 application RASBIN.N Radioisotopes Licensing Branch (Pre 790501) 77/03/02 lp 15748 067.

- --B210180145 Amend 9 to Matl/Byproduct License 21-08362-08, changing Subitems 8 A & B 8 to read 150 mCi & 50 mCi, respectively & amending Condition 13 re possession & use of licensed matl.per 780403 ltr HRIOHT, E G Radioisotopes Licensing Branch (Pre 790501) 78/08/10 1p 19748 068
- --8210180150 Matl/Byproduct License 21~08362-07 for Dow Corning Corp. authorizing Ni-63 as foils in detector cells (Mewlett-Packard 2-6195) for use in gas chromatography unit for sample analysis
 BRINMAN, R & Atomic Energy Commission 69/03/14 3pp 15248 071
- --8210180152 Amend 1 to Matl/Byproduct License 21-08362-09, adding tritium as titanium tritide foils in detector cells for use in gas chromatograph for chemical analysis, per 700707 application

 URINMAN, R E Atomic Energy Commission 70/07/22 ip 15748 074
- --8210180157 Amend 2 to Matl/Byproduct License 21-08362~09, adding Ni-63 as foils in detector cells (Hewlett-Packard 18713A) for use in Hewlett-Packard gas chromatography unit for sample analysis.per 730327 ltr
 BRINKMAN.R E Atomic Energy Commission 73/05/02 1p
- --8210180159 Amend 3 to Matl/Opproduct Literar 21-08362-09; changing expiration date to 790331 & amending Condition 12 re user of byproduct matliper 740227 application + Atomic Energy Commission. Directorate of Licensing 74/04/01 ip 15748-076
- --8210180164 Amend 4 to Mati/Dyproduct License 21-08362-09, changing Condition 14 re passession 5 use of byproduct matiliper 740527 ltr

 * Atomic Energy Commission, Directorate of Licensing 74/08/20 in 15748 077
- ~~8210180168 Amend 5 to Matl/Byproduct License 21-08362-09, changing license in entirety per 790228 application Amend authorizes Ni-63 % tritium as foil source for use in gas chromtography units for sample analysis CODPER.J W Licensing Hanagement Branch 79/03/14 4pp 19748 078
- ~-8210180171 Matl/Buproduct License R1-08362-12 for Dow Corning Corp. authorizing Cs-137 sealed source for use in Dhmart Model RD-4 density gauge * Atomic Energy Commission. Directorate of Licensing 74/07/16 3pp 15748 082
- --B210180173 Amend i to Matl/Byproduct License 21-08362-12, adding Cs-137 sealed source for use in source holder for measurement of pipe fluid density, per 750729 itr e Radioisotopes Licensing Branch (Fre 790501) 74/05/28 2pp 19748 009
- --82[0]80176 Amend 2 to Matl/Byproduct License 21-08062-12.changing Conditions 12.14 D.15 & 16 re user of licensed math, performance of tests for leakage/contamination & maint, repair & radiation survey.per 761223 ltr
 BELLIJ M Radioisotopes Licensing Branch (Pre 790501) 77/07/29 2pp 46383 153
- --8210180178 Amend 3 to Mat1/Buproduct License 21-08362-12, changing Bubitems B & C of Items 6.7 & B & adding Cs-137 sealed sources for use in source holders for measurement of pips density & level.per 770729 & 1206 ltms Radioisotopes Licensing Branch (Pre 770301) 37712/20 ip. 15748 039
- ---8210180194 Matl/Byproduct License 21-08362-13 for Dow Corning Corp. authorizing Co-60 sealed sources for use in two irradiation reaction vessels for irradiation of matls to produce

1 (Pre 790501) 77/03/22 3pp

- --B210180213 Amend 4 to Mati/Byproduct License 21-08362-13, changing Items 6.7.8 & 9 to read Co-60 sealed sources for use in three irradiation reaction vessels for irradiation of matls to produce chemical synthesis.per B1031 itr OUINN:P R Licensing Management Branch 81/04/21 tp 15748 108
- --8210180215 Responds to AEC 611220 ltr re violations noted in Insp of License 21-00265-01 on 610309-10 Corrective actions amend to license requested to permit use of two addl Co-60 sealed sources & tags fastened to each source holder BEAMER. H H Dow Chemical Co 40569 62/01/02 PRICE. E Atamic Energy Commission 2pp 15748 109
- --8210180219 Corrects 610109 ltr requesting increase in quantity of Cs-137 on License 2i-00265-01 Limit of Cs-137 smaled sources requested to be increased to 6,000 mCi [wo smaled sources containing 1,500 mCi each of Cs-137 will be ordered BEAMER.H H Dow Chemical Co 31801 61/01/12 RDGERS.L R Atomic Energy Commission 1p 15748 111
- --8210180222 Requests that limit of Cs-137 sealed sources on License 21-00265-01 be increased to 3:000 mCi Bealed source containing 1,500 mCi Cs-137 will be installed as part of liquid level controller instrument BEAMER.W R Dow Chemical Co 3:807 6:/01/09 ROVERB.L R Atomic Energy Commission ip 15748 112
- --8210180229 Inquires about possibility of amending License 2(-00085-) to increase 1 Ci per yr limit for disposal of tritiated water into effluent sewage stream KEAMER.W H Dow Chemical Co 58/12/24 BOHYER.J E Atomic Energy Commission ip 15748 ii3
- --9210180234 Describes relationship of Bechtel Corp to Dow Chemical C (DCC) as agent in purchase of four radioactive Cs-137 sources, per AEC 580616 request Bources will be in physical potsession of DCC before & after installation BEAMER.W H Dow Chemical Co 58/06/24 BONYER.J E Atomic Energy Commission 1p 15748 114
- --8210180239 Application for renewal of Matl/Byproduct Licentes 21-00265-06, 21-00265-02, 21-00265-04, 21-00265-07, SNM-1253, STB-527 & R-108 authorizing any byproduct matl between Atomic Numbers 3 & 83. tritium, Pc-210 & Am-241 HOYLE: H R Dow Chemical Co 38652 73/06/25 2pp
- --B2101B0247 Forwards application for renewal of Matl/Bygroduct Lice 21-00265-06 List of plant locations including three plants not authorized under current license & description of hyproduct matl used in lower animals encl W/o application HOYLE,H R Dow Chemical Co 38652 73/06/18 CUNNINGHAM.R & Atomic Energy Commission 3pp 15748 117
- --8210180251 Forwards application for renewal of Matl/Byproduct L.(c) 21-00265-01 & 21-00265-02 Sample of isotope data card & revisions to radiation protection manual encl BEAMER, W H Dow Chemical Co. 28079 & 60/07/21 MASON, J R. Atomic Energy Commission 5pp 15748 120
- --8210180257 Application for renewal of Matl/Byproduct Licenses 21-00265-01 & 21-00265-02 authorizing use of Elements 3 through 83 in any form & tritium sealed source for R&D Sealed source inventory enci BEAMER.W H Dow Chemical Co. 28079 60/07/21 5pp 13748 |
- --B2101B0260 Ack receipt of 600113 Amend B to Matl/Byproduct Licent 21-00265-01 adding authorization for use of Pm-147 sources at Bay City plant. Day Chemical Co will possess beta ray instrument ordered by Bechtel BEAMER. W H. Dow Chemical Co. 60/01/29 BRINKMAN. R.E. Atomic Energy Commission ip 15748:130
- --8210180262 Application for math/byproduct license authorizing E1 i to 84 inclusive in any form for use in chemical & agricultural RED. tracer problems & as sealed sources in instruments. Std for control of radiation hazards encl BEAMER. H H Dow Chemical Co 56/04/03 20pp 15748-131
- ~-8210180266 Forwards application for renewal of Matl/Byproduct & 11-00265-06
 BEAMER, W. H. Dow Chemical Co 66/06/10 Atomic Energy
 Commission. 1p 15748 151
- --8210180270 Amend ii to Matl/Byproduct License 21-00265-03, chang Condition ii re user of byproduct matl & adding Condition ID to require compliance w/10CFR20, Chapter i, "Stds for Protection Against Radiation," per 590105 ltr + Atomic Energy Commission 59/01/29 ip. 15748 155

- -- 8210180275 Mat1/Byproduct License 21-00265-03 for Dow Chemical Co. inibuzzo nestroughouses cicense al-uozao-ou for nom Chemica authorizing Co-60 as aluminum clad slugs in stainless steel rods per Dow Chemical Drawing NDI-3492 for use in gamma irradiator to initiate chemical reactions Atomic Energy Commission 57/09/10 10
- --82:0180277 Mat1/Byproduct License 21-00265-02 for Dow Chemical Co. elusious/, nati/ouprisous alternse el-ousod-us for Dow Chemic authorizing Co-60 as cylindrical sealed source & aluminum clad siugs in copper rods per 560706 ltr for use in radiation chemistry studies - Atosic Energy Commission 56/09/21 2pp 15748 157
- --8210180282 Amend 1 to Matl/Byproduct License 21-00265-02, adding Co-60 sealed sources for use in high level radiation chemistry research per 370115 application 57/02/25 1p 15748 159
- --82|0180284 Amend 2 to Matl/Byproduct License 21-00265-02, changing Conditions 11 & 12 re user of byproduct matl & compliance w/10CFR20.Chapter 1, "Btds for Protection Against Radiation" respectively, per 590105 ltr KASON, J R Atomic Energy Commission 59/01/29 tp 15748 160
- --B230180287 Amend 3 to Mat1/Byproduct License 21-00265-02, changing license in entirety per 610711 application Amend authorizes Co-60 as BNL cylindrical source & aluminum clad cobalt sluge for use in irradiator & hot cell for experimental studies MASON, J.R. Atomic Energy Commission 61/07/19 2pp 15748 161
- -- P2[0180270 Amend 4 to Mat1/Byproduct License 21-00265-02, changing license in entirety per 620531 itr Amend authorizes Co-50 as cylindrical source in aluminum & as aluminum clad slugs in stainless steel for use in irradiator & hot cell EELL.J M Atomic Energy Commission 62/07/24 2pp 15748 163
- --B210180295 Amend 5 to Matl/Dyproduct License 21-00265-02, changing license in entirety per 620925 ltr Amend authorizes Co-60 as tylindrical source in aluminum & as aluminum clad slugs in stainless steel for use in irradiation & hot cell BELL.J M Atomic Energy Commission 62/11/09 3pp 15748 16 Эрр 15740 165
- --8210180278 Amend & to Matl/Byproduct License 21-00265-02, changing Conditions 13 & 14 re possession & use of byproduct matl & written instructions concerning operating procedures for cobalt radiation sources & facilities, per 621219 1tr BELL-J H Atomic Energy Commission 63/01/28 1p 15748 168
- --B210180301 Amend 7 to Hatl/Byproduct License R1-00265-02, adding Condition 19 authorizing disposal of 100 mCi Co-60 by autial, per 621219 ltr
 BELL-J H Abomic Energy Commission 63/02/28 lp 15748 id 15748 169
- --8210180304 Amend B to Mat1/Buproduct License 21-00265-02, adding 330 Ci Co-60 as BNL cylindrical source in aluminum for use in a praduator device & revising Subitems 98 & Conditions 13 & 14 rs gossession of byproduct mathper 630418 & 0317 ltrs BUCHANAH.C R Atomic Energy Commission 63/06/23 2pp 15748 170
- --8210180307 Amend 9 to Matl/Dyproduct License 21-00265-02, deleting Bubitems C of Items 6.7.8 & 9 & Condition 18, per 660125 ltr HOHELL,D B. Atomic Energy Commission. 66/02/17 ip 15748 172
- --8210180310 Amend 10 to Matl/Byproduct License 21-00265-02, extending application date to 710930 deleting Subitems 6A, 7A, 8A & 9A & revising Subitems 78, per 660705 application 904ELL.D.B Atomic Energy Commission. 66/09/01 ip 1574B, 173
 - 2:0180312 Amend 11 to Mat1/Byproduct License 21-00265-02, adding Condition 20 to permit transfer of byproduct mat1 to new irradiation facility per 641017 1tr CHURCHILL B W. Atomic Energy Commission 66/11/02. Ip 1574B 174
 - 210180315 Amend 12 to Mat1/Byproduct License 21-00265-02, changing Literse in entirety Amend authorizes Co-60 as aluminum clad slugs in stainless steel & as cylindrical source in aluaique for use in hot cell & irradiation device CERRCHILL B. W. Atomic Energy Commission 67/01/25 Spp 15748 175
 - 9210180318 Amend 13 to Mat1/Byproduct License 21-00265-02, revising Bulitems 6 A:7 A & 8.A to read 15,000 Ci Cu-60 as aluminum clad slugs in stainless steel & edding Ca-137 as doubly entapsulated stainless steel sources/per 670126 ltr.
 CKMRCHILL:8 W Atomic Energy Commission 67/02/15 ip. 13748 178

- --8210180319 Amend 14 to Mati/Byproduct License 21-00265-02, deleting Condition 17.per 670313 ltr BUCHANAN.C R Atomic Energy Commission 67/03/30 1574B 179
- --8210180324 Amend 15 to Matl/Byproduct License 21-00245-02.revising Bubitam 9 A to authorize use of byproduct matl in hot cell or radiation reactor for irradiation of various matls, per 690415 ltr
 BUCHANAN C R Atomic Energy Commission 69/04/23 to 15748 180
- --BR10180326 Amend 16 to Hatl/Buproduct License 21-00265-02, revising Condition 12 authorizing HR Hoyle to use %/or supervise use of byproduct matl.per 700615 ltr MALARD, J C Atomic Energy Commission 70/07/06 ip 15748 181
- ---9210180328 Amend 17 to Matl/Byproduct License 21-00265-02, changing license in entirety per 710726 application Amend authorizes Co-60 as aluminum clad slugs in stainless steel & Ca-137 as doubly encapsulated stainless steel sources MALARO, J.C. Atomic Energy Commission 71/08/16 3pp 15748 182
- --8210180333 Amend 18 to Matl/Buproduct License 21-00265-02. revising Condition 16 re possession & use of byproduct matl.per HENDRIE. O H Atomic Energy Commission 71/12/21 1p 15748 J&S
- --B210180335 Amend 17 to Mat1/Byproduct License 21-00265-02, revising Condition 16 re-possession & use of licensed matl.per 760315 ltr
 BASSIN N Radioisotopes Licensing Branch (Pre 770501) 76/05/17 ip 15748 186
- --8210180337 Amend 20 to Matl/Byproduct License 21-00265-02, revising Condition 16 re possession & use of licensed matl.per 760909 ltr DASSIN N Radioisotopes Licensing Branch (Fre 790501) 76/J1/24 lp 15748 187
- -- B210180340 Ameng 2 to Mat1/Byproduct License 21-00265-04. changing license in antirety per 651210 application Amend authorizes Co-60 sealed sources for use in industrial rediography by open-air handling techniques
 MILLER, W.O. Atomic Energy Commission 65/12/29 2pp 15748 188
- --8210180341 Amend 13 to Mati/Byproduct License 21-00265-04, adding Co-60 sealed source for use in Tech Ops Model 525 exposure device for industrial radiography & adding Conditions 14. C. 15 & 14. per 660729 ltr
 HILLER: W.O. Atomic Energy Commission 66/09/27 2pp 15748 190
- --B210180343 Amend 4 to Matl/Byproduct License 21-00265-04, changing license in entirety per 681227 application Amend authorizes Co-60 sealed sources for use in Tech Ope Model 525 exposure devices for industrial radiography
 MALARO.J C Atomic Energy Commission 69/01/17 4pp 1974B 192
- --8210180344 Amend 5 to Matl/Byproduct License 21-00265-04, changing Item 9, A & Condition 16 re possession & use of byproduct matl BASSIN, N Atomic Energy Commission 72/05/19 1p 15748 196
- --8210180346 Amend & to Matl/Byproduct License 21-00265-04, changing license in antiraty per 731227 application Amend authorizes Co-60 sealed sources for use in Tech Ops Model 525 exposure devices & Model 416 source changers REBNER, E.P. Licensing Management B Licensing Management Branch 75/09/10 2 15748 197

- --8210180353 Requests ducuments indicating disposal of all licensed math possessed under License 21-00265-04, per 770707 telcon in response to licensee 770627 request for termination of license Note of 770707 telcon end J
- --8210180354 Requests termination of Matl/Byproduct License 21-00265-04 Five Co-60 source used for industrial radiography disposed of via Nuclear Engineering Co at Sheffield, IL N(LLIAMS, P. R. Dow Chemical Co. 88359 77/06/27 Radioisotopes Licensing Branch (Pre 790501) ip 15748 205
- --82(0180358 Requests termination of Matl/Byproduct License 21-00265-04 Industrial radiographic source (2 3 C) Co-60) shipped to Shaffield, IL by Nuclear Engineering Co for disposal Shipping record encl
 THOMAS, B R Dow Chemical Co 89463 77/08/25 JONES, J
 Radiolisotopes Licensing Branch (Pre 790501) 2pp 15748 206
- --8210180360 Matl/Byproduct License 21-00265-06 for Dow Chemical Co. authorizing any byproduct nat1 between Atomic Numbers 3 & 83 anclusive w/listed exceptions in any form for use in R&D lab tracer studies # Atomic Energy Commission 64/08/14 3pp 15748 208
- --8210180363 Amend 1 to Matl/Byproduct License 21-00265-06, increasing max amount of Kr-85 from 10 Ci to 25 Ci & revising Condition in re use of instruments, devices & gauges containing scaled sources, per 650414 ltr
 BRINKMAN, R E Atomic Energy Commission 65/04/28 ip
- --8210180366 Amend 2 to Matl/Byproduct License 21-00265-06, adding Po-210 as static eliminators & revising Condition 11 re use of instruments devices b gauges containing sealed sources, per 650728 ltr
 4 Atomic Energy Commission 65/09/18 ip 15748 212
- --8210180367 Amend 3 to Mati/Byproduct ticense 21-00265-06, adding Po-230 in any form for use in R8D, per 651006 ltr 4 Atomic Energy Commission 69/10/29 ip 13748 213
- --8210180370 Amend 4 to Mat1/Byproduct License 21-09265-06, revising Condition 11 re use of instruments, devices & gauges containing sealed sources.per 660214 ltr BUCHANAN.C R Atomic Energy Commission 66/02/24 lp 15748 214
- --9210180372 Amend 5 to Hat1/Byproduct License 21-00265-06, changing licente in entirety per 660610 ltr Amend authorizes any byproduct mat1 between Atomic Numbers 3 & 83 inclusive, tritium 2-Po-210 in any form for use in R&D BRINKMAN,R E Atomic Energy Commission 66/06/29 App 15748 215
- --8210180373 Amend & to Matl/Byproduct License 21-00265-06, revising Condition 16 re possession & use of byproduct matl.per &60722 ltr
 BRINKMAN.R E Atomic Energy Commission 66/08/08 ip 15748 219
- --8210189374 Amend 7 to Matl/Ryproduct License 21-00265-06, adding Am-241 & 80-239 in any form for use in analytical chemistry tracer experiments, per 661216 ltr 4 Atomic Energy Commission 67/01/03 ip 15748 220
- --8210180375 Amend 8 to Matl/Qyproduct License 21-00265-06, adding Po-210 sealed source for use in storage & testing of instruments & revising Condition 16 re possession & use of byproduct matl, per 670525 telegram
 BUCHANANIC R Atomic Energy Commission 67/06/01 ip
 15748 221
- --8210180376 Amend 9 to Mati/Byproduct License 21-00265-06, changing Subitem 8 F to read 10 Ci.per telegram received 670608 * Atomic Energy Commission 67/06/15 ip 13748-222
- --8210180377 Amend 10 to Matl/Byproduct License 21-00265-06, changing license in entirety per 680627 application Amend authorizes any byproduct matl between Atomic Numbers 3 & 83 inclusive. 4 tritium, Po-210, Am-241 & Pu-237 in any form BRINMAN.R E Atomic Energy Commission, 68/07/16 4pp 15748 223
- --8210180379 Amend 11 to Matl/Byproduct License 21-00265-06, changing Subitem 8 8 to read 60 Ci.per 681223 ltr * Atomic Energy Commission 69/01/10 ip 15748, 227

- --8210180380 Amend 12 to Matl/Byproduct License 21-00265-06, changing Subitem 8 A to limit redionalide to 1 Ci except for Kr-85, Cs-137, Co-60, Sr-90 & C-14, per 700115 ltr BRINKMAN, R E Atomic Energy Commission 70/01/26 1p 15748 228
- --8210180381 Amend 13 to Matl/Byproduct License 21-00265-06.changing Condition 12 re user of byproduct matl.per 700615 ltr * Atomic Energy Commission, 70/06/25 tp 15748 229
- --8210180383 Amend 14 to Matl/Byproduct License 21-00265-06, changing Condition 10 re use of byproduct matl.per telegram received 710325
 BRINKMAN.R E Atomic Energy Commission 71/03/25 ip 15748 230
- --8210180386 Amend 15 to Matl/Byproduct License 21-00265-06, adding Am-E4 sealed sources for use in development, standardization & testing of instruments, devices & gauges, per 710807 ltr BRINKMAN,R E Atomic Energy Commission 71/08/20 ip 15748 231
- --8210180387 Amend 16 to Hatl/Byproduct License 21-00265-06, changing Subitem 8 0 to read il Ci.per 711118 itr BRINKMAN.R E Atomic Energy Commission 71/11/30 ip 15748 232
- --8210180391 Amend 17 to Matl/Byproduct License 21-00265-06, changing Substem 8 Q to read 15 Ci.per 720107 ltr
 BRINXMAN.R E Atomic Energy Commission 72/01/19 1p 15748 233
- ~~B210180394 Amend 18 to Matl/Byproduct License 21~00265-06, changing Subitem 9 0 re use of licensed matl, per 720509 ltr
 BRINKMAN.R E Atomic Energy Commission 72/05/24 1p
- --B210180397 Amend 19 to Matl/Byproduct License 21-00265-06, changing Subitem 8 0 to read 25 Cipper 720721 1tr
 BRINKMAN, R E Atomic Energy Commission 72/08/03 1p
- --B210180399 Amend 20 to Matl/Byproduct License 21-00265-06, changing Subitem 8 A to limit radionuclide to 1 Ci w/exceptions of Kr-85, Ce-137, Co-60, Sr-90 & C-14 & deleting Bubitems A C.7 E. 8 E & 9 E. per 730222 ltr
 BRINKMAN.R E Atomic Energy Commission, Directorate of Licensing 73/03/08 lp 15748 236
- --8210180402 Amend 21 to Hetl/Byproduct License 21-00265-04, changing Subitem 8 0 to read 40 Ciper 730301 ltr
 BRINKHAN,R E Atomic Energy Commission, Directorate of Licensin; 73/03/27 ip 15748 237
- ~-8210180406 Amend 22 to Matl/Byproduct License 21~00265~06, changing license in entirety per 730625 application Amend authorites any byproduct matl between Atomic Numbers 3 & 83. tritium. Po-210 & Am-241 in any form & Po-210 & Am-241 sealed source BRINKMAN.R & Atomic Energy Commission. Directorate of Licensin 73/07/31 App 15748 238
- ~-8210180409 Amend 23 to Hatl/Byproduct License 21-00269-0A.ch.anging Subitom B B to read 100 Ci.per telegram received 730706 BRINKNAN.R E Atomic Energy Commission. Directorate of Licensir 73/09/26 ip 15748-242
- --B2101B0410 Amend 24 to Mat1/Byproduct License 21-00265-06, changing Subitem B F to read 75 Ciper 740401 ltr

 * Atomic Energy Commission, Directorate of Licensing 74/04/1; ip 15748 243
- --8210180413 Amend 25 to Matl/Byproduct License 21-00265-06, changing Conditions 10 & 16 re possession & use of byproduct matl, per 740829 telegram

 * Atomic Energy Commission, Directorate of Licensing 74/09/0
 - * Atomic Energy Commission, Directorate of Licensing 74/09; to 15748 244
- --B2101B0417 Amend 26 to Matl/Byproduct License 21-00265-06, adding sealed sources for use in process control instrumente & Eberline Model 1000 calibrator.per 750103 ltr
 BELLJ M Licensing Management Branch 75/03/20 ip 15-46
- --8210180421 Amend 27 to Matl/Buproduct License 21-00265-06.rsvia Bubitems 8. A.B F.9 A.P 8 & 9 C re amount of radionuclide & use of licensed matl.per 750407 ltr # Licensing Management Branch 75/07/11 1p 15748 246

- --8210(80422 Amend 28 to Matl/Byproduct License 21-00265-06, revising Subiters 9 A.B & C re use of licensed matl, per 750714 application BASSIN.N Licensing Management Branch 75/09/04 1p 1574B 247
- -8210180425 Amend 3D to Matl/Byproduct License 21-00265-06, revising Candition 10 re use of Fe-55 & Am-241 sealed sources.per 760706 application a Radioisotopes Licensing Branch (Pre 790501) 76/08/26 1p 13748 249
- -8210(80426 Amend 31 to Matl/Byproduct License 21-00265-06, revising Confitions 10 & 16 re passession & use of licensed matl.per 780909,17 & 1019 ltrs BASSIN.N Radioisotopes Licensing Branch (Pra 790901) 76/11/30 to 10748 250
- --8210180427 Forwards up-to-date list of radiation detection instruments, par item 15 of 660403 application for renewal of Matl/
 Byproduct License 21-00265-06
 BEAHER, H Down Chemical Co 66/07/22 DRINKMAN, R E Atomic Energy Commission, 2pp 15748 333
- --8210180428 Revised "Radiation Protection Manual" a Dou Chemical Co 73/01/31 159pp 15748 337
- --B210180429 Amend 32 to Mati/Byproduct License 21-00265-06, changing Subitem 8 A to limit radionuclide to 1 Ci w/exceptions of Kr-85.Cs-137.Co-60, Br-90, C-14.mixed fission products & Ni-63 & revising Condition 16.per 761102 ltr BASSIN.N Radioisotopes Licensing Branch (Pre 790501) 77/04/11 ip 15748 251
- --B210180430 Application for amend to Matl/Byproduct License 21-00265-06. (creating dosing of rats & mice to 1,500 uCi C-14 or tritium per animal & 10,000 uCi per animal for monkeys ferwards revised "Radiation Protection Manual" LANGER R. F. Dow Chemical Co 2344 77/07/07 URIGHT, E. Radioisotopes Licensing Branch (Pre 790501) ip 15748 334
- -- @210180431 Advises that use of polonium/beryllium neutron source for testing instruments under Mati/Byproduct License 21-00265-04 will cease after reactor OL becomes effective, per licensee 670511 & 16 ltrs.

 BEAUCER, W H Dow Chemical Co 67/05/25 HADDICAN, W Atomic Entry Commission Ip 15748 335
- -- 5210190432 Amend 33 to Matl/Byproduct License 21-00265-06, changing Condition 11 re use of licensed matl.per 770404 ltr = Radioisotopes Licensing Branch (Pre 790501) 77/04/25 ip 15748 252
- --8210180433 Amend 34 to Mati/Byproduct License 21-00265-06, changing Suitems 7 A.B & C & Conditions 10 A & C & 16 re possession byte of licensed mati, deleting Condition 10 F & adding toadtion 17.per 770601, 21 & 30 applications WildHT.E 0 Radioisotopes Licensing Branch (Pre 790501) 77/07/27. 2pp 1574B 253
- --8210180434 Application for renewal of Matl/Byproduct License 21-00265-06, authorizing any hyproduct matle w/Atomic Numbers 1-83, Po-210 & Am-241 in any form for use in R&D LAWER, R R Dow Chemical Co 95118 78/06/14 ADPP 15748 260
- --8210180435 Corrected Amend 39 to Matl/Byproduct License 21-00269-06, changing Condition 17 re possession & use of licensed matl & seling Condition 18 re disposal of licensed matl, per 801029 ltr.

 MALLET, B 8. Licensing Management Branch 81/07/31 1p 19740 Dc9
- -- 200180436 Corrected Amend 37 to Mati/Byproduct License 21-00245-06, changing Condition 17 re passession & use of licensed mati & effing Condition 18 re disposel of licensed mati, per 801027 ltr MALETT, B 8 Licensing Management Branch 81/07/03 ip
- #210199067 Add1 response to FOIA request for tape recordings of interviews w/F Oitz on 810225 & O604 Forwards amitted transcript pages. W/o encl. FRITOM JH Division of Rules and Records 82/10/04 HICKEY, J. P. Stew, Fittman, Potts & Trombridge, ip 19798 333

- 8210190079 Partial response to FOIA request for documents re NRC shotdown plan mentioned in weekly info rept for wk ending 810831 & SECY 81-600 & SECY 81-600A Forwards draft Manuel Chapter 1302 FELTON-JM Division of Rules and Records 82/10/01 CONNOR.L Doc-Search Associates 1p 15758 312
- --8210050573 Forwards draft Manual Chapter 1302, "Shutdown Plan Contingency Plan for Periods of Lapsed Appropriations," for review & comment BARRY, L N Office of Resource Management, Director 82/09/03 NRC No Detailed Affiliation Given 37pp 15758 313
- 8210190094 Responds to FOIA request for NRC Annual Rept to Congress for 1981 Forwards document W/o enci FELTON, J H Division of Rules and Records 82/10/06 SCHULKE, S Affiliation Uningum tp 15758 310
- 82(0190112 Partial response to FDIA request for five categories of documents re SEP Forwards documents listed in App A App B lists documents available in PDR FELTON. J H Division of Rules and Records 82/10/06 GALLO. J Isham, Lincoln & Beale 3pp 15758 191
- --8210190115 Responds to request for advice on applicability of general design criteria & 100FR100, App A to older licensed facilities Stds of general design criteria must be used for assessing safety of all facilities
 SCINTO, J. Hearings Division 82/03/10 LAINAS.Q. Assistant
 Officetor for Safety Assessment 4pp 15758 196
- -- 6210190121 Discusses legal questions concerning re-review program
 Backfitting recommendations premature, pending re-review for
 particular case
 SCINTO. J F. Hearings Division 76/09/03 QDLLER. K.R. Division
 of Operating Reactors 3pp 15758 200
- --8210190124 Responds to 500116 request for legal opinion reapplicability of siting requirements of 10CFR100 to
 operating plants App A elements should be used in seismic
 adequacy judgments for all reactors
 SCINTO, J.F. Hearings Division 62/10/06 VOLLMER.R. Division of
 Engineering 2pp 15758 203
- --B002080095 Requests consultation re operating reactors legal obligation to fulfill code requirements re selemic & geologic considerations of proposed sites VOLLNER,R H Assistant Director for Systems & Projects 80/01/16 CHRISTENDURY,E Hearings Division 2pp 15758 205
- 8210190144 Responds to FOIA request for SECY 82-232 re use of nonplant-specific simulators for initial replacement & requalification exams for licensed reactor operators & senior operators FELTON. J K Division of Rules and Records 82/09/30 ARMSTRONG, K A Debevoise & Liberman 2pp 15760 178
- ~-8206180042 SECY-82-232

 Recommende requirements of simulator licensing exam be continued for power reactors w/plant-apecific simulator Oral exam per 10CFR55.23 should be administered where facility has no plant-specific simulator DIRCKS.H J Dffice of the Exacutive Director for Operations 82/06/07 14pp 16002 236
- --8210190152 Advices that Commission has approved reconting to the specific HOYLE.

 DIRCKE
 15760
- 8210190189 Responds to J Hickey FOIA request for names & plant locations of all US facilities licensed to possess 100,000 or more G1 Co-bO FELTON, J H Division of Rules and Records . 82/09/08 BUFFALD, V Cobe Laboratories
- --BR10190191 "Co-60 Irradiations w/Possession Limits of 100,000 Ci or Orester " # NRC - No Dateiled Affiliation Given 82/09/08 2pp 13758,337.
- 821021007: Responds to FOIA request for retords re disposal of radwaste & chemical & medical wastes at St Albans Hosp in Gueens, NY NRC has no documents subj to request FELTON, J M, Division of Rules and Records. 82/09/30 FREEDBERG, L. Youth News ip. 15774-314.

- 8210270083 Add1 response to FOIA request for eight categories of LERs Forwards documents listed in App A App B documents withheld (ref FOIA Exemption 5) FELTON, J M Division of Rules and Records 82/09/20 ARNOLD, J Miaml Herald 4pp 15836 221
- --8204300098 SECY-82-142
 Requests approval of draft Rept to Congress on AD
 (NUREG-0090) for Oct-Dec 1981
 DIRCKS.W J Office of the Executive Director for Operations
 82/04/02 40pp 15836 225
- --B208020047 Responds to B20603 memo re proposed AD incident involving pressure transients during shutdown does not constitute AD Finding based upon analysis showing integrity of pressure vessel not impaired & fatigue life not affected MINOGUE.R B Office of Nuclear Regulatory Research. Director B2/06/22 MICHELSOR.C Director's Office Jpp 15836 282
- 8210280019 Responds to 750619 memo re QA Program Insp Rept 99700084/ 75-01 Info in rept does not establish reasonable basis for determining violation of criminal statutes Referral to DOJ inappropriate MCTIERNAN-T J Office of Inspector & Auditor 75/10/01 DAVIS, J G Office of Inspection & Enforcement, Office of the Director App 15860 070
- --8210280110 ORNL/NSIC-it2 DRFT

 "Pressure Vessel Thermal Shock at US SWRs Events & Precursors.1963 to Mid~1981." draft interim rept Related info encl
 PHUNG.D L. Gak Ridge National Laboratory FIN 8-0435 82/05/19
 Office of Nuclear Regulatory Research. Director 218pp
 19861 082
- --8210280321 "Extremity Doses & Compliance w/Monitoring Regulations at Nuclear Power Plant"

 NUCOINS, T. North Carolina, Univ. of 62/06/30 11pp 15861 300
- B210280396 Responds to FOIA request for "Initial Quidance for Performance of Sys Interaction Analysis at Belected LHRs" & "Initial Quidance on Diagraph-Matrix Analysis for Sys Interaction "Forwards repts W/o enci FELTON.J M Division of Rules and Records 82/09/14 FAORIZIO.R F Boston Fdison Co 1p 15859 118
- 8210280402 Add) response to FDIA request for SECY-82-232 & SECY-82-202 Documents listed in App A available in PDR FELTON.J K Division of Rules and Records 82/09/30 DUCKLES.R Affiliation Unknown 2pp 15859 101
- --8210280406 Commissioner Absarms Affirmation response sheet re SECY-82-202, amend to 10CFR140, "Financial Protection Requirements & Indomnity Agreements " Comments encl AHEARNE, J. NRC - No Detailed Affiliation Given 82/06/16 3pp 1989 103
- --8210190198 Staff requirements memo re 820701 affirmation session concerning SECY 82-202 on amend to 10CFR140 9, "Financial Protection Requirements & Indemnity Agreements "Objections to publication of apps as reg guides due by 820719 CHILK, B J Office of the Secretary of the Commission M820701 82/07/06 DIRCKS, W J Office of the Executive Director for Operations 2pp 15859 106
- 82[0290020 Responds to FOIA request for RFP R8-01E-82-25; "Gafety Aspects of Industrial Radiography Course" & related info Forwards document M/o encl FELTON. J M Division of Rules and Records 82/10/01 WILLIAMS, D T Affiliation Unknown 1p 15877 072
- 8210290027 "Annex i, Cost Benefit Analysis of Proposed Rule 73 47 of 10CFR73" List of commentors encl
 * NRC No Detailed Affiliation Given 82/09/03 57pp 15864 197
- --8210290032 Discusses impact of proposed safeguards upgrade rule on nonpower reactors Paper requesting exclusion of nonpower reactors from rule will be initiated MILLER.J R Standardization & Special Projects Branch 82/09/03 SYELLO, V Division of Operating Reactors 4pp 15864 255
- --8210290053 "Licensees-SNM of Moderate Strategic Bignificance (Category II)"

 ** NRC No Detailed Affiliation Given 78/12/05 3pp
 15864 267
- --8210290058 "Category II Nonpower Reactor Licenses Holdings as of Jan 1979 "
 4 NRC - No Detailed Affiliation Given 82/09/03 2pp 15864 270

- --8210290061 Responds to Commission request for rept on safeguards self-protection criterion impact of safeguards upgrade rule on 23 affected nonpower reactors would be severe Financial expense would force many reactors out of operation DENTON, H.R. Office of Nuclear Reactor Regulation, Director 79706/20 HENDRIE, J. GILINSKY, V. KENNEDY, P. Commissioners 5pp. 15845-045
- --8210290065 Comments on new Commission paper re upgrade rule Nonpower reactors should be exempt from rule Legal backup needed in event of public meeting HILLER, JR Assistant Director for Reactor Safeguards 77/06/28 BURNETT,R Division of Safeguards 2pp 15865 070
- --8210270D67 "Dose Rate Due to Irradiated Fuel "

 NRC Na Detailed Affiliation Given 81/04/14 Spp
 15865 088
- B210270085 Responds to FOIA request for lists of names & addresses of all NRC licensees in ME.VT.MA.DH.CT & WV & appropriate ofcs in Agreement States of NH.RI.NY & MD Forwards requested lists FELTON, J M Division of Rules and Records 82/10/15 PARKINSON, T W Interstate Nuclear Services 1p 15863 311
- --8210270070 Lists of active licenses for States of MA,VT,ME,CT,OH & W. & Agreement States as of 820710
 4 NRC No Detailed Affiliation Given 82/10/07 240pp 15863 312

GEN TEC 18 GENERIC TECHNICAL ISSUES

- 8205060002 Appeals denial of FOIA request for segregable portions of draft NUREO-0844, "Resolution of Unresolved Safety Issues A-3,A-4 & A-5 Re Steam Cenerator Tube Integrity UDELL,R A Critical Mass Energy Project 82/06/04 DIRCKS,W J Office of the Executive Director for Operations 29p 15668 333
- 8207180056 Forwards edited version of draft on pressurized thermal shock w/substantive changes proposed KOUTS, H Brookhaven National Laboratory KOUTS, H ACRS Advisor Committee on Reactor Safeguards 82/08/10 IONE, E ACRS Advisor Committee on Reactor Safeguards 22pp 15852 012
- 8209280424 Discusses status of pressurized thermal shock short term recommendations ACRS Horking Ordup on Metal Components meeting scheduled for 820930 to continue discussion Forwards draft "NRC Staff Evaluation of Pressurized Thermal Shock "DIRCKS,H J Office of the Executive Director for Operations 82/09/20 PALLADIND,N GILINSKY,V , AHEARNE,U F Commissioners 2pp 13670 033
- --8210120335 "NRC Staff Evaluation of Pressurized Thermal Shock." drg rept Apps encl • Office of the Executive Director for Operations 82/09/13 393pp 13670 035
- 8210010286 Concurs that NUREO-0744, "Resolution of Reactor Vessel Matls Toughness Eafety Issue," need not be reviewed by CROR STELLO, V. Regional Operations & Generic Requirements B2/09/30 DENTON, H.R. Office of Nuclear Reactor Regulation, Director, 1p 15573 881
- 8210080015 Add1 response to FOIA request for 19 categories of info r nuclear reactor events & safety problems. Forwards documents listed in App A Documents in App B completely withheld (ref FOIA Exemption 5) FELTON, J M Division of Rules and Records 82/07/12 UDELL, H A Critical Mass Energy Project 9pp 15665 027 24X Fiche 50-000. 82/07/12. 8210080015
- --B011060346 Discusses licensee pesponses to NRC request to commit interim position re Generic Item B-24 venting & purging containments while at full power Plants meet interim position & existing TACs should be closed out REEVES:E A Operating Reactors Branch 1, 80/08/25, Operating Reactors Branch 1, 100/08/25, Reactors Branch 1, 10pp 15668 155
- ---B106220159 Supports efforts in resolving purge valve leakage & operability issues Incorporation of leak testing position into Tech Specs should assure leakage integrity of containment BAER.R.L. Reactor Engineering Branch. B1/06/09 BUTLER, W. & Containment Systems Branch. 2pp 1566B 153

- --8107170126 Comments on proposed IE bulietin re leakage of reactor bldg
 purge valves Issuance not merited for reasons indicated
 Generic issues B-20 & B-24 provide assurance of increased
 surveillance testing & reduced excessive leakage
 SNIEZEK, J H Director's Office IEC-77-11 81/07/01
 O'REILLY, J P Region 2, Atlanta, Office of the Director
 (81/03/01) 2pp 15668 151
- --B21Q0B0057 "Cost of Upgrading Capability to Isolate LPWR Main Feedwater Sys in Event of Breaks Inside Containment," final rept. per statement of work for DOE Work Order 20-81-165, "Program for Cost Estimation for Proposed Safety Requirements" BEARDEN, R O EQ&G, Inc FIN A-6452 RGB-2-82 B2/03/17 15pp 15555 169
- --BIO5220157 Supports efforts in resolving purge valve leakage & operability issues incorporation of leak testing position into Tech Specs should assure leakage integrity of containment BAER, R L Reactor Engineering Branch 81/06/07 BUTLER, W R Cantainment Systems Branch 2pp 15668 153
- --8107170126 Comments on proposed IE bulletin re leakage of reactor bldg purse valves issuance not merited for reasons indicated Generic Issues 8-20 & 8-24 provide assurance of increased torve()lance testing & reduced excessive leakage SNIEZEKJ H Director's Office IEC-77-11 81/07/01 O'REILLY, J.P. Region 2, Atlanta, Office of the Director (81/03/01) 2pp 15668 151
- 8210080021 Summary of 253rd ACRB meeting on 810507 re control sys failures that could cause or exacerbate nuclear power plant accidents per Task Action Plan A-47
 ASME.F. Reactor Operations Analysis Branch AEDD/E114 81/06/24
 NICHELBON.C Director's Office 23pp 15669 073
- EZIO08005B Responds to appeal re denial of FDIA request for segregable portions of draft NUREG-0844, "Resolution of Unresolved Safety Issues A-3.A-4 & A-5 Re Steam Generator Tube Integrity "Request denied (ref FDIA Exemption 5) DIRCKS.RJ Office of the Executive Director for Operations 82/07/19 UDELL, R A Critical Mass Energy Project 2pp [5569 331
- 621008015B Forwards "Potential for Hater Hammer During Restart of RHR Pumps for BHR Nuclear Plants " HUANNY 8 Director's Office, AEGD/C105 01/03/31 MICHELEDN.C Director's Office 1p 15663 255
 - 2210380165 "Potential for Water Hammer During Restart of RHR Pumps for BLR Nuclear Plants" HAMO,J Director's Office AEOD/E105 81/03/31 14pp 13663-236
 - (10080169 Forwards "Initial Consideration of Potential for Water Kawarr in Steam Condensing Mode of RHR Sys Operation for SWR Plants " HAUMOY B Director's Office AEOD/E106 81/03/31 MICHELSON. C Director's Office ip 15663 271
 - -0210080172 "initial Consideration of Potential for Water Hammer in Size Condensing Mode of RHR Sys Operation for SHR Nuclear Flants" HJAHO.J Director's Office AEOD/E106 B1/03/31 11pp 15663 272
 - 210080294 Forwards "Review of Emergency Response Outdelines Re Fissurized Thermal Shock " KINSLEY.O D Westinghouse Operating Plants Owners Group STRISSLEY,O D Alabama Power Co 00-72 82/06/22 DENTON.H R Offics of Nuclear Reactor Regulation, Director 1p. 15638 208
 - --8210080297 "Review of Emergency Response Quidelines Re Pressurized Tiermal Shock " + Nestinghouse Electric Corp 82/04/30 84pp 19638 209
 - P210150552 NUREO/CR-2791
 NETHEODOLOGY FOR EVALUATION OF INSULATION DEBRIS EFFECTB
 Continuent Emergency Sump Performance, Unresolved Safety
 Issu A-43
 WEEKELJ, KOLBE, R Sandia Laboratories FIN A-1276 SAND-82-7067
 R2/97-30. Division of Safety Technology 27ipp Available at
 NC 48 00 15725.005
 - 8210180002 Requests attendance at CROR Heeting 29 on 821028 in Retained and to discuss cost/benefit info for alternatives for resolving pressurized thermal shock issue SELLO.V. Committee to Review Generic Requirements 82/10/14 EISBNI,D 9. Division of Licensing JARDAN.E L. Division of Endingering & Quality Assurance. CUNNINGHAMR E. Diffice of Nuclear Naterial 8sfety & Bafeguards, Director. 1p 15718.024

- 8210250156 Notification of CRGR 821110 25th meeting in Bothesda, MD to discuss proposed revision to 100FR20 on stds for protection against radiation, proposed amend to 100FR50 re radiation protection programs & Unresolved Safety Issue A~43 STELLO.V Regional Operations & Generic Requirements 82/10/22 EISENHUT.D G Office of Nuclear Reactor Regulation, Director URBAN, E L Director's Office, Office of Inspection and Enforcement Cunntropham, R Office of Nuclear Material Safety & Safeguards, Director ip 15788 288
- 8210280044 Summary of ACRS Ad Hoc Metal Components Subgroup 820511-12 meetings in Washington.DC repressurized thermal shock problem * ACRS - Advisory Committee on Reactor Safeguards 82/07/27 ACRS - Advisory Committee on Reactor Safeguards 19pp 15862 336
- 8210290118 Forwards, for info, draft rept & apps on pressurized thermal shock Completed rept will form basis of Commission decision due 821030 W/o encl
 LAINAS, C C Assistant Director for Operating Reactors 82/09/28 ROCHINO.L Babcock & Hilcox Operating Plants Duners Group ROCHINO.L General Public Utilities GPU Service Corp 2pp 15886 358
- 8210290450 Forwards, for info.draft rept & apps on pressurfied thermal shock Completed rept will form basis of Commission paper due 821030 W/o enci
 LAINAS O C Assistant Director for Operating Reactors 82/09/20
 HIGGINS,P Atomic Industrial Forum 2pp 15863 181
- 8210290453 Forwards, for info,draft rept & apps on pressurized thermal shock Completed rept will form basis of Commission paper due 821030 M/a encl LAINAS, 0 C Assistant Director for Operating Reactors 82/09/28 BASKIN, K C-E Operating Plants Owners Group 2pp 15863 185
- O210290458 Forwards, for info.draft rept & apps on pressurized thermal shock Completed rept will form basis of Commission paper due 921030 H/o enc!

 LARMAS.O C Assistant Director for Operating Reactors 82/09/28
 KINOSLEY.O Wastinghouse Operating Plants Duners Group KINOSLEY.O Alabama Power Co 2pp 15863 163

INSPECTION AND ENFORCEMENT

- 8208190233 lE Info Notice 80-35, Suppl 1. "Leaking & Dislodged I-125 implent Beeds" Svc list encl COBB.L I Division of Fuel Facilities, Materials & Safeguards 82/10/06 Consolidated Edison Co of New York 66pp 15761 250 24X Fiche 50-000.62/10/06.8208190233
- 8200170238 IE Bulletin 82-03, "Attress Corrosion Cracking in Thick-Hall-Large-Diameter.Stainless Steel.Recirculation Bys Piping at BMR Plants "Svc list encl DEVOUND, R C Director's Office. Office of Inspection and Enforcement 82/10/14 Consolidated Edison Co of New York 115pp 13810 125 24X Fiche 50-000.82/10/14.8208170238
- 821004013D PNO-III-82-102 on 820926, lead container marked radioactive math found on Cleveland. Oli street Hipe survey showed container to be free of radioactive container to the free of radioactive containing Container reportedly mislabeled to discourage theft from auto LASUM. 8 R. BRENIAHSKI. D. J. Region 3. Office of Director 82/09 ip 15581 212
- 8210050224 PNO-11-92-105 on 920925,100 mCi Cs-137 mins logging source discovered missing Search of mins premises datected slightly elevated radiation level in one area of coal car POTTER, J. OIBBON, A Region 2: Office of Director B2/09/30 App 15611.024
- 8210030314 PNO-III-82-104 on 820903:40 42 mCi Ir-172 seeds removed from patient on 820605 determined to be missing Search continuing w/assistance of two NRC inspectors MATSON, E R : BRENIAMBKI,D J Region 3, Office of Director 82/09/29 2ep 15602 360
- 8210070265 PNO-TMI-82-020 on 821005, game poacher apprehended on util property & turned over to state police & Game Commission No vital areas threatened Security increased Licensee will issue press release.

 WIEBE, J. Region 1, Office of Director. 82/10/06 ip.

- 92(0150496 EN-82-026A on 820722, order to show cause & order suspending license effective immediately issued to Hidstate Testing Lab Action based on licensee apparent abandonment of radiographic facility & licensed mati RROCKETIT . AXELRAD.J Director's Diffice . Diffice of Inspection and Enforcement 82/10/14 2pp 15714 168
- B210150507 PND-|II-02-109 on 821007, US Army infinity aiming collimator containing IO Ci gaseous tritium distovered missing Theft suspected State of IL. local police & defense contract administration notified DBERO.C T. HIEDEMAN, D. G. Region 3, Office of Director B2/10/12 ip 15713 208
- B210190673 PNO-111-82-110 on B21011. Troiler soil density & moisture gauge u/Ct-137 & Am-241 scaled sources reported stolen from const site in Ashland. HI Significant inadvertent eiposure unlifely since warming labels attached OBERG. C T . MIEDEMAN. D Q Region 3. Diffice of Director 82/10/13 19 18737 283
- 8210250055 FND-V-82-043 on 821016 unusual event declared when grass fire started in 500 kV switchward On 821017, three 500 kV circuits tripped resulting in loss of all offsite power Second unusual event declared STERNBERG, D M Region 5. Office of Director 82/10/16 ip 15/87 100
- 8210260471 PNO~III-82-113 on 820917.Victoreen Model 848-8 calibrator containing 112 mCi of Cs-137 shipped w/o proper warning labels or shipping papers Calibrator discovered in storage on 820924 & read 12 millbren/hour Caused by personnel error SREMIANSKI,D J. MILLER,J R Region 3, Office of Director 82/10/19 1p 15807 229
- 8210260493 PND-1-82-067 on 821022, kinetic expansion conducted on eight rows of tubes in B once-through steam generator Expansion involves controlled detonation within tube Some media attention expected CONTE.R Region 1, Office of Director 82/10/22 ip 19806-232
- 8210280072 EN-82-030A on 821026, decision re 820827 order to show cause & order modifying License 41-19870-01 issued Since licensee took adequate corrective actions on violations. License will not be revoked Order to modify (icense further Forthcoming FLACK, E., AXELRAD.) Director's Office, Office of Inspection and Enforcement 62/10/26 to 15837 146
- 8210280073 EN-82-031A order issued rescinding \$20903 order to show cause & order temporarily suspending license of Orion Chemical Co Licensee \$20924 response describing corrective actions acceptable AXELRAD. J Director's Office, Office of Inspection and Enforcement \$2/10/24 ip 15837 to4
- 1086 PHRI TO INCUMENT ROOM MISCELLANGUIS

- 0210070476 Forwards findings & recommendations re 810115 memo on requiraments offsite power sys design criteria ASHE,F Director's Offsice AEGD/E110 81/04/29 MICHELSON,C Director's Offsice 4pp 15637 358
- 8210070481 Recommends actions to be taken to lower rate of occurrences of inoperability of instrumentation due to extreme cold weather Suppl to IE Bulletin 79-24 directing changes to Tech Specs should be issued HICHELSON,C Director's Office AEOD/E112 B1/06/15 DENTON.H R Office of Nuclear Reactor Regulation, Director STELLO,V Director's Office of Inspection and Enforcement Spp 13644 353
- 8210080057 Summarizes findings of LER review to determine patterns of setpoint drift occurrences for Darton Model 288 instrument for 1975-80 Changes to procedures for BHRs w/o analog safety sensor sys recommended ASHE,F Director's Office AEOD/Ei18 81/07/20 MICHELSON,C Director's Office 2pp 15669 324
- B210120073 Compares reactor coolant pump events contained in LERs, NRRDs, RECON & plant records Search indicates little confidence can be placed in single reporting tys, but such sys should be developed BROWN, E. J. Director's Office AEOD/E003 BQ/06/19 MICHELBOW, C. Director's Office 11pp 19689 172
- 8210120370 Discusses IE Builetin 80-21, "Integrity of Polymer Coating for Surfaces Inside Containment " Coating developed by Con-Chem, Inc could fail when subjected to DBA conditions, releasing debris through sump screen MICHELSGN.C Director's Office AEOD/E011 80/08/29 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 15690-170
- 8210120372 "Burvey of Valve Operator-Related Events Occurring During 1978.1979 & 1980 "
 BROWN,E J. ASHE,F S Director's Office AEOD/C203 82/05/31
 SBpp
- 8210130545 Forwards abstract & summary cover sheet for paper re testing of 1/4-inch expansion anchors in repaired concrets Review requested for consideration of paper as candidate for presentation at Aug 1983 SHMRT-7 conference TOGNI.C S Public Service Co of Indiana. Inc 82/10/07 WILLIAMS.M Office of Nuclear Reactor Regulation. Director 3pp 15682 287
- 8210150090 Forwards statement of consideration of biomedical wasts disposal published in FR when NRC adopted 100FR20 304 Adoption of regulation does not pose unreasonable radiological risk to public health & safety H/a encl DURNS-8 0 Regional Operations & Enforcement Division 82/10/07 SCHEUERMANN-X KS Processing Co . Inc 1p 15701 197
- 8210260554 Forwards Engineering Planning & Mgt, Inc analysis of NAC sponsored fire tests evaluating 20-fit separation criteria. NOTLEY:D P Electrical Engineering Branch 82/09/29 KNIOISTON. O W Research & Standards Coordination Branch 67pp 15830 193
- 8210280431 Submits NRC findings re Phibro-Salomon, Inc application for proposed import of 300,000 tons U from Australia, South Africa & other countries Proposal conforms w/std provisions MODRE, R N Office of International Programs, Director 92/09/26. Office of International Programs, Director 19 15860-053

NUREO REPORTS AND RELATED CORRESPONDENCE

- 8206060002 Appeals denial of FOIA request for segregable portions of draft NURGO-0844, "Resolution of Unresolved Bafety Issues A-3.A-4 & A-3 Re Steam Generator Tube Integrity UDELLIR A Critical Mass Energy Project B2705/04 DIRCKB, H J. Office of the Executive Director for Operations 2pp 15668 333
- B207180061 FOIA request for documents re-pre-implementation review of NUREO-0737. Item II F 2.
 CONNOR.1. Doc-Bearch Associates B2/09/01 Division of Flules + Records. 1p 15669 096
- 8207290410 NUREG/CR-2229 VO2
 BUR LARGE BREAK BIMULATION TESTS-BUR BLOWDOWN/EMERGENCY CORE
 COOLING PRODRAM Volume 2-Appendices I-N
 LEF,L S. General Electric Co FIN 8-3014 GEAP-24962~2, \$2707/
 Division of Accident Evaluation 552pp, Available at NTIB
 #13 00 14126 OOL

- 8:33290017 Summarizes 269th ACRS meeting on 820909-11 in Washington, DC to proposed safety goals radjoactive math packaging for transport testing requirements for diesel generators & integrated human factors program plan SECMONN P ACRS Advisory Committee on Reactor Safeguards SL-0278 82/09/21 PALLADINO, N J Commissioners 3pp 15449 236
- B2092B0307 NUREG/BR-0024 NORKING BAFELY IN DAMMA RADIOGRAPHY A TRAINING MANUAL FOR NUMBERIAL RADIOGRAPHERS NCOURE, B A . PEABODY, C A Office of Nuclear Regulatory Research, Director B2/09/30 168pp
- E210010308 Responds to FOIA request for 19 categories of documents re nuclear reactor events & safety problems Forwards documents listed in App A FELTON-J H Division of Rules and Records, 82/06/28 UDELL-R A Critical Mass Energy Project 15pp 19727 005 24% Fiche 50-000-82/06/28,8210010008
- --8210040379 Submits review of IE insps of operating PWRs related to followup actions identified in NUREO-0138 Bensitivity analyses recommended SULER: H B Plant Bystems Branch 77/12/RB EJSEN-JUT, D O Division of Operating Reactors 12pp 15727 285
- -- P21004039& Submits evaluation of recommendations contained in NURLG-0651. "Evaluation of Steam Generator Tube Rupture Events" Licensess should investigate other techniques to more rapidly determine damage ARR.R.L. Safety Program Evaluation Branch 81/02/17 MURLEY.T Civision of Bafety Technology 26pp 15728 007
- --Sig040413 Submits evaluation of NUREO-0667, "Transient Response of BtW Designed Reactors" Recommends related studies be combined to specified Priority 2 items implemented by expanding an existing task in TMI action plan MATSON. 8 Division of Bafety Technology 80/08/08 DENTON, H R Office of Nuclear Reactor Regulation. Director 43pp 15727 199
- --Biit03020i Responds to inquiry into status of BHR scram discharge vol pipe breal safety concerns NUREO-0803 contains guidance for resolving outstanding issues on plant by plant basis RUBIN-5 D Director's Office 81/10/02 LEWIS, M I Application Uninoun ip 15730-336
- --8108270056 Forwards concurrence on NUREG-0803, "Generic Bafety Evaluation re Integrity of BMR Scram Bys Piping " Any significant changes will be provided for consideration MICHELSON, C Director's Office 81/07/30 EISENHUT, D 9 Division of Licensing 3sp 19730 OB3
- -811030201 Responds to inquiry into status of DWR scram discharge volsign breat safety concerns NUREG-0803 contains guidance for resolving outstanding issues on plant by plant basis RUBINS D Director's Office 81/10/02 LEWIS, M I, Affiliation Uninown ip 19730 336
- -8105110376 Forwards findings to recommendations for J Elin 810115 memo re-requirements of preferred or offsite power sys ASHE, F Director's Office 81/04/29 MICHELSION: C Director's Office 4pp 19729-070
- -8109240007 Comments on NUREO/CR-1659 Vol 2: "Reactor Safety Study Methodology Application Program Oconee 3 PWR Power Plant "
 DEWINDER L. Director's Office 81/09/15 Director's Office 3p 55597 237
- E210010223 Comments on proposed rule IOCFR50 re mandatory property insynance for decontentination of nuclear reactors & MAREO-0891; "Nuclear Property Insurance Status & Outlook " Ogestes rule "MAREO-1891; "Nuclear Property Insurance Status & Outlook " Ogestes rule "MAREO-1891; Power & Light Co 47FR27371 041 82/09/24 Office of the Secretary of the Commission ip 15568 019
- 8210010286 Concurs that NUREO-0744, "Resolution of Reactor Vessel Nats Toughness Safety Issue," need not be reviewed by CARR STELLO, V Regional Operations & Generic Requirements 82/09/30 EXTOR: HR Defice of Nuclear Reactor Regulation, Director ip 13573 181

- 8210010307 Package of three comments opposing proposed rule (OCFR50 re mandatory property insurance for documentamination of nuclear reactors
 OLEGICER, C. H. Wisconsin Public Service Corp. WITHERS, B. D. Pacific Qas & Electric Co. KELLY, A. B. American Nuclear Insurers
 47FR27371 82/09/28 CHILK, S. J. Office of the Secretary of the Commission 19pp 15549 289
- 8210010381 Package of four comments on proposed rule 10CFR50, "Mandatory Property Insurance for Decontamination of Nuclear Reactors" Supports rule MYATT-JM Louisiana Power & Light Co DELLSY.H H Commonwealth Edison Co ROBERTSON, CO Houston Lighting & Power Co 47FR97371 82/09/24 Decitating & Services Branch 22pp 15573 059
- 8210040311 Forwards Revision 4 to SCP-01-A. "RADCAL Gamma Thermometers as Local Power Measuring Devices for Use in Cores of PMRs."
 per NUREO-0370
 MARING. P Scandpower, Inc 82/09/29 BERNARD, Η Standardization & Special Projects Dranch 1ρ 15586 198
- 82:0050360 NUREG/CR-2792
 AN ASSESSMENT OF RESIDUAL HEAT REMOVAL AND CONTAINMENT SPRAY
 PUMP PERFORMANCE UNDER AIR AND DEGRIS INCESTING CONDITIONS
 KAMATH.P S , TANTILLO.T J , SWIFT.W L Creare, Inc I'IN A-1837
 B2/09/30 Division of Bafety Technology 110pp Available at
 NRC \$5 50 15625-010
- 8210050368 NUREO/CR-2905
 RAMAN BCATTERING TEMPERATURE MEASUREMENTS FOR WATER VAPOR
 IN NON-EQUILIBRIUM DISPERSED THO-PHASE FLOU
 AMASTASIA.C M. NETI.S. SMITH.W.R. Lehigh Univ. FIN B-6794
 B2/09/30 Division of Accident Evaluation 204pp Available at
 NRC \$7.00 15624-061
- B21005038B NUREG/CR-2761

 RESULTS OF VORTEX SUPPRESSOR TESTS, SINGLE QUILET SUMP TESTS,
 AND MISCELLANEOUS SENSITIVITY TESTS

 FARMANARIMAN. H Alden Research Laboratory * Sandia Laboratories
 FIN A-1237 SAND82-7065 82/07/30 Office of Nuclear Reactor
 Regulation, Director 115pp Available at NRC \$6.50 15625 170
- 8210050397 NUREO/CR-2606
 ANALYSES OF 1/15 SCALE CREARE DYPASS TRANSIENT EXPERIMENTS
 KMETYK-L N . DUXTON-L D . COLE, R K Sandia Casoratories FIN
 A-1115 SANDS-1932 92/09/30 Division of Systems Integration
 (post Bi1005) 6ipp Available at NRC \$9 00 15625 329
- BRIO050412 NUREO/CR-2920
 BEHAVIOR OF REINFORCED CONCRETE SLABS SUBJECTED TO COMBINED PUNCHINO SHEAR AND BIAVIAL TENSION
 JAU-W C . WHITE.R N . OERCELV.P Gornell Univ 82/09/30
 Division of Engineering Technology 100pp Available at NRC 45 50 15624 266
- 0210050416 NUREO/CR-2754
 CRITICAL REVIEW OF SYDDES ON ATMOSPHENIC DISPERSION IN
 COASTAL REGIONS
 SHEARER, D.L.: KALEEL, R.J. TRC Environmental Consultants, Inc. *
 Battelle Hemorial Institute, Pacific Northwest Laboratory FIN
 B-2304 PNL-4292 02/07/30 Division of Health, Siting &
 Environment 39pp Available at NRC \$4.75 13625 237
- B210050428 NUREO/CR-2897
 GALCULATIONS OF HYDROGEN DETONATIONS IN NUCLEAR CONTAINMENTS
 BY RANDOM CHOICE HETHOD
 DELICHATBIOS, M., GENADRY, M.D., FARDIS, M.N. Massachusetts Instituts
 of Technology FIN B-7085 82/09/200 Division of Engineering
 Technology 215pp Available at NRC 97 50 15612 117
- 8210030431 NUREC-0858
 COMPARISON BETHER FIELD DATA AND ULTIMATE HEAT BINK COOLING POND AND BPHAY POND MODELS
 CODELL, R 8 Division of Engineering 82/09/30 67pp Available at MRC \$5 00 15626 108
- 8210060004 NUREO/CR-1349 ROI
 PROCEDURES EVALUATION CHECKLIST FOR MAINTENANCE, TEST AND
 CALISMATION PROCEDURES USED IN NUCLEAR POWER PLANTS
 BRUNE, R. L. HEINSTEIN, M. HPT. Inc. & Bandia Laboratorias FIN
 B-3098 BANDBO-7034 82/09/30 Division of Reactor Programs
 25pp Available at NRC 43 50 15636,308
- 82100&0417 NUREO/CR~22&0 ERR
 Errate, Changing Report Number Of NUREO/CR-22&0 To
 NUREO/CR~2&20 To. AN ANALYBIB OF PROPOSED INLET FLOW BLOCKAGE
 EXPERIMENTS USING MAYU-46
 4 EGG. Inc E00-2181 82/06/30 Office of Nuclear Regulatory
 Research, Director 1p 15636 242

- 8210070007 Responds to FOIA request for eight categories of records re steam generators & steam turbines App A documents provided in R_Udell FOIA Request 81-313 Forwards documents listed in FELTON, J M Division of Rules and Records 82/08/10 LONG, D J Hinthrap, Stimson, Putnam & Rabberts 9pp 15445 063 24X Fiche 50-000, 82/08/10, 8210070007 FELTON. . M
- --B203260003 Recommends that STS limits for coolant activity & sampling requirements be incorporated into remaining operating plant Tech Specs wisther substantive change requests lodine dose problems can be avoided by limiting coolant HOUSTON.R W Assistant Director for Radiation Protection 82/03/04 NOVAK.T Assistant Director for Operating Reactors 2pp 15645 285
- 8210070029 Partial response to FOIA request for documents re CRBR EIS & all comments, evaluations & documents from BNML re EIS Forwards documents listed in App A FELTON, JM Division of Rules and Records 82/07/16 WEISS.E R Harmon & Weiss 8pp 15648 004
- --8210070123 Forwards updated responses to comments on 1976 DES.
 NUREG-0137 re safequards & fuel cycle (nfo re radwaste shipments, disposal site & licensed burnal site included LOMENBERG.H Office of Nuclear Material Bafety & Safeguards, Director CRBR 82-69 82/06/15 LEECH, P Clinch River Breeder Reactor Program Office 15pp 15648 073
- 6210080015 Add1 response to FDIA request for 19 categories of info re nuclear reactor events & safety problems Forwards documents listed in App A Documents in App B completely withheld (ref FOLKER IN MP A DECUMENTS IN APP B completely withheld (ref FOLK Exemption 5) FELTON J H Division of Rules and Records 82/07/12 UDELL R A Critical Mass Energy Project 9pp 19665 027 24X Fishe 50-000. 82/07/12.8210080015
- ~-82100B0057 "Cost of Upgrading Capability to Isolate LPWR Main Feedwater Bys in Event of Breaks Inside Containment," final rept.per statement of work for DUE Mork Drder 20-81-165. "Program for Cost Estimation for Proposed Safety Reguirements." DEARDEN.R G EG&G. Inc FIN A-6452 ROB-2-82 B2/03/19 15pp
- --8210080215 Forwards revised IE organizational charts & functional statements for review & comment Reorganizations of 820104 & 25 will be incorporated in NUREO-0325 BLAHA-J L. Program Support Branch 82/04/29 LIEBERMAN.J Enforcement Staff FORTUNA,R Director's Office. Office of Inspection and Enforcement COBB. L. I. Division of Fuel Facilities. Materials & Bafeguards 7pp 15668 261
- --8203040536 Comments on Elizia corrections to facility assessment contained in NUREQ-0834 re hearings & discussion of systematic assessment of license performance Revision to NUREQ imagepropriate lisue closed Group B2/01/04 WESBMAN.R H NRC - No Detailed Affiliation Group 1p 15668 256 24X Fiche 50-000:82/07/12.8210080015
- ---B203040538 Forwards performance element summary for Jul 1979-June 1980 in response to ABLB request for testimony on systematic assessment of license performance in general & facility assessment in particular MESSMAN.R H Director's Office. Office of Inspection and Enforcement 01/12/18 MUSELEY, N C Systematic Assessment of Licensee Performance Review Group 2pp 15669 254 24% Fiche 50-000,82/07/12.8210080015
- 8210080020 Responds to FOIA request for documents re preimplementation of NUREG-0737, Item III F 2 Forwards documents listed

and Records 82/09/16 CONNOR.L

intation

10

able

- 8210120092 NUREO/CR-2873 VO2
 NUCLEAR FUEL CYCLE RISK ASSESSMENT DESCRIPTIONS DF
 REPRESENTATIVE NON-REACTOR FACILITIES Sections 15-19
 SCHNEIDER, K J. BICKFORD, W E. DALING, P M. Battelle Memorial
 Institute, Pacific Northwest Laboratory FIN B-2402 PNL-4306,
 B2/09/30 Division of Risk Analysis 361pp Available at NRC 15687 328 \$9 00
- 8210120102 NUREO/CR-2873 V01

 NUCLEAR FUEL CYCLE RISK ASSESSMENT DESCRIPTIONS OF REPRESENTATIVE NON-REACTOR FACILITIES Sections 1-14
 SCHNEIDER, K J. BICKFORD, W E. DALINO, P M Battelle Memorial Institute. Packfic Northwest Laboratory PIN B-2402 PNL-4304, B2/09/30 Division of Risk Analysis 376pp Available at NRC 99 50 15686 313
- 8210120115 NUREG-0748 VO2 NDB OPERATING REACTORS LICENSING ACTIONS SUMMARY Data As DR August 31.1982 (Grange Book)

 * Hanagement Information Branch 82/09/30 355pp 15685 JlV
- B210120119 NUREQ-0580 VI1 NO9
 REQULATORY LICENSING STATUS SUMMARY REPORT Data As Of
 September 15, 1982 (Blue Book) Management Information Branch 82/09/30 63pp 15689 004
- 8210120125 NUREQ/CR-2820 PROJUCTION OF SHIPPER-RECEIVER DIFFERENCES
 JOHNSTON, J W. BROWNS, R J. STEWART, K B. Battelle Memorial
 Institute, Pacific Northwest Laboratory FIN B-BIO3 82/09/(1)
 Division of Facility Operations 117pp Available at NRC 47 47 30
- 8210130391 Comments on proposed rule 10CFR50 re mandatory property insurance for decontamination of nuclear reactors (NUREO-0891) Imposition of blanket coverage requirement poses restrictive economic hardship on smaller plants TAYLORJU Dairyland Power Cooperative 47FR27371 042 02/09 Office of the Secretary of the Commission 2pp 15681 001 02/09/23
- 8210130539 Forwards util comments on proposed rule 10CFR30 re mandator property insurance for decontamination of nuclear reactors (NUREG-0891) FLYNN B F Carolina Power & Light Co 47FR27371 044 92/09/29 WOOD, R S Office of State Programs, Director Ip 15682 26:1
- --8210130950 Comments on proposed rule 10CFR50 re mandatory property insurance for decontamination of nuclear reactors (NUREO-0891) Present requirements re property insurance adequate to assure sufficient funds for decontamination BARHAM.C D. Carolina Power & Light Co. 47FR27371 044 122/6922 CHIK.S J. Office of the Secretary of the Commission 102p 02/12/22/20
- 8210130554 Comments on proposed rule 10CFRSO re-mandatory property insurance for decontamination of nuclear reactors (NUREO-0891) MITTLER L Public Service Electric & Cas Co of New Jersey 47FR27371 043 82/09/24 CHILK: 8 J Docketing & Services Stable 4pp 15684 Ool
- 8210190547 NUREG-0750 V15 NO5 NVCLEAR REGULATORY COMMISSION ISBUANCES May 1982, * Division of Technical Information & Document Control 1827() D.F. \$1 275pp. 15722 Oct
- 8210150548 NUREG/CR-2404
 ANALYZING SAFEQUARDS ALARMS AND RESPONSE DECISIONS
 AL-AYATER A JUDDE R MCCORDER K Laurence Livermore Labour & Est
 FIN A-0115 UCRL-53034, 82/09/30. Division of Facility
 Operations 115pp Available at NRC, \$5 00 15726 13.3
- 8210190549 NUREO/CR-2831
 A TEBT OF THE CONTROLLABLE UNIT APPROACH (CUA) CONCEPT IN A LOW-ENGICHMENT URANIUM FUEL-FABRICATOR FACILITY
 FOSTER: K W Hound Laboratory/Monsanto FIN A-1075 NLM 24
 82/10/31 Safeguards Branch 108pp 15724 061 NLH 2457
- 8210150550 NUREO/CR-2889 A TECHNICAL TEST DESCRIPTION OF THE NRC LONG-TERM WHOLE ROD AND CRUD PERFORMANCE TEST AND CRUD PERTURNANCE IGGI EINZINGER,R E., FIBH,R L. Hanford Engineering Development Laboratory. FIN B-2435 HEDL/TME B2-32. B2/09/30 Division Engineering Technology. 77pp Available at NRC #5 00 15 Pub
- 8210150552 NUREG/CR-2791 HOTSOSSE MERGYCK-#/7/ KETHOBOLOGY FOR EVALUATION OF INSULATION DEBRIS EFFECTS Containment Emergency Sump Performance, Unresolved Safety

Elicitotti (NREO/CP-0030 %7903104 ON UNBATURATED FLOM AND TRANSPORT MODELING %7903104 ON UNBATURATED FLOM AND TRANSPORT MODELING ARNOLDE M. OKE.4 U. NELSON.R W. Battelle Memorial Institute. ARNOLDE M. OKE.4 U. NELSON.R W. Battelle Memorial Institute. Partitic Northwest Laboratory FIN B-2220 PNL-8A-10325 \$2/09/30 Pivision of Waste Management 337pp Available at NRC \$7.00 15735 156

R210150555 INREO/CR-2885
MCCUANISH AND CORRELATION OF DROPLET ENTRAINMENT AND
MCCUANISH AND CORRELATION OF DROPLET ENTRAINMENT AND
MCCP0517100 IN ANNULAR THO-PHABE FLOW
MFACUAL: ISHII, H Argonne National Laboratory FIN A-2026
MFACUAL: ISHII, H ARGONNE NATIONAL FIN A-2026
MFACUAL: ISHII, H ARGONNE

C150537 MUREO/CR-2859
CALUATION OF AIRCRAFT CRASH HAZARDS FOR NUCLEAR POWER
CALUATION
CALUATION OF AIRCRAFT CRASH HAZARDS FOR NUCLEAR POWER
CALUATION
CALUATION OF AIRCRAFT CRASH HAZARDS FOR NUCLEAR POWER
CALUATION OF AIRCRAFT CRASH POWER
CALUATION OF AIRCRAFT CRAS

.3150360 NUREO/CR-0169 V20
LOFT EXPERIMENTAL HEASUREMENTS UNCERTAINTY ANALYSES VOLUME
17 FLUD VELOCITY HEASUREMENT USING PULSED NEUTRON
ACTIVATION
LASSANIO D , TAYLOR, D J EG&G, Inc FIN A-6043 EGG-2037 VRO
LASSANIO D DIVision of Accident Evaluation 32pp 15747 296

PIDISOSA MAREO/CR-2874 VOI
HICH-TEMPERATURE GAS-CODLED REACTOR BAFETY STUDIES FOR THE
DIVISION OF ACCIDENT EVALUATION Quarterly Progress Report,
DIVISION OF ACCIDENT EVALUATION QUARTERly Progress Report,
DIVISION OF ACCIDENT STATEMENT OF ACCIDENT
FIN B-0122 GRAL/7M-B44G/VI B2/09/30 DIVISION OF ACCIDENT
FYAIVATION 19PP 15716 113

EZIOLXSE7 NUREO/CR-2163

DISFERSED FILM FLOW BOILING OF HIGH PRESSURE WATER IN A ROD

PINDE

HERRIB O C MARLINE C B : YODER O L Cak Ridge National Laboratory

FIM B-0125 ORNL/TM-7864 82/09/30 Division of Accident

Evaluation 88pp 15716 246

E00150589 NAREO/CR-2719
ENUATION OF INSERVICE INSPECTIONS OF GREASED PRESTRESSING
ENCOME
ENCO

EIGINOTI MUREO/CR-2730
MIROSEN BURN SURVIVAL PRELIMINARY THERMAL MODEL AND TEST
FESUS
RCALCCHUR R. RAZZEL, A. C., KEMPKA, S. N. Sandia Laboratories FIN
A-1270 SAND62-1180 82/07/30 Division of Accident Evaluation
319 15716

EIG5074 NUREO/CR-2098
IKIMFORCED CONCRETE CONTAINMENT BAFETY UNDER HYDROGEN
EMUSSON LOADING
FAUGUSH N , NACAR, A , DELICHATSIUS, M
Inchalogy FIN B-7095 B2/09/30 Division of Engineering
Inchalogy 222pp Available at NRC \$7 50 15722 252

Litip577 NUREO/CR-2000 VOI NB LICOSEE EVENT REPORT (LER) COMPILATION For Month Of Right 1982 • GI Ridge Netional Laboratory FIN B-1583 ORNL/NSIC-200 21/9/30 Director's Office 180pp 15723, 113

EMMYR2 MREGICE-2922
(GPRISON OF OUICE PREDICTIONS WITH RESULTS OF SELECTED
RECOI ARROSOL BEHAVIOR EXPERIMENTS
(ANN.H., SCHWMACHER, P. H., OIESEKE, J. A., Battelle Memorial
Inditute, Columbus Laboratories FIN A-4063, BMI-R099
(Office of Nuclear Regulatory Research, Director 37pp 15726-324

Engro10 Responds to 820805 ltr re unresolved issues from 820615 ltr is indisquate requirements developed per TM1 Item I.D i satisfies of responsibility for human factors within NRC & chiefs of operator integrity addressed COMEN.H 8 Office of Nuclear Reactor Regulation, Director 8209116 BHEEHY, E. J. Affiliation Unknown 27ep 15758 207.

-E0/10008 Informs that response to 820615 ltr incomplete in areas of John factor evaluation of ADs & ability of operator to act attacked.

SERMY, E.J. Affiliation Unknown 82/08/05 PALLADING, N.J. (Seafssioners, 8pp. 15758-294

8210210014 NUREG/CR-2923
MSPEC USER'S MANUAL
JURDAN, H. BCHUMACHER, P. M. OIESEKE, J. A. Batteile Memorial
Institute, Columbus Laboratories FIN A-4063 BMI-2100 B2/09/30
Office of Nuclear Regulatory Research, Director 53pp Available
at NRC \$4.75 15784 324

B210210024 NUREG-0940 VOI NO1-2
ENFORCEMENT ACTIONS SIGNIFICANT ACTIONS RESULVED Quarterly
Progress Report, January-June 1982
Director's Office of Inspection and Enforcement
B2/09/30 250pp Available at NRC 87 50 15781 187

8210210037 NUREO/CR-2673
EVALUATION OF THERMAL DEVICES FOR DETECTING IN-VESSEL
COOLANT LEVELS IN PURS
HARDY, J E , DAVIS, C E , TURNAGE, K O Dak Ridge National Laboratory
FIN N-0401 ORNL/TM-6306 82/09/30 Division of Accident
Evaluation 73pp 15773 295

8210210039 NUREG/CR-2609
THERMAL-HYDRAULIC TEST FACILITY BUNDLE 3 IN-CORE
INSTRUMENTATION AND OPERATING HISTORY
DITLL J Gat Ridge National Laboratory FIN D-0125 ORNL/NUMFG 75
82/09/30 Division of Accident Evaluation 104pp 15774 906

8210210046 NUREG/CR-2914
CORRELATION OF LIGHTE BEDS FOR FAULT IDENTIFICATION IN THE
HIBSISSIPPI EMBAYMENT AREA OF HESTERN KENTUCKY
COBS.J C. WILLIAMS.D A Kentucky. State of FIN 8-5972 82/09/30
Division of Nealth. Biting & Environment 36pp Available at
NRC \$4.50 15786-012

82t0210051 NUREO/CR-2909
PALEOZOIC GEOLOGY OF THE NEW MADRID AREA
SCHWALD, FIR Illinois, State of # Illinois, Univ of,
Urbana-Champaign FIN 0-6251 B2/09/30 Division of Health,
Siting & Environment 69pp Available at NRC 45 OD 15785 IB:

9210210054 NUREO/CR-2444 V01
PHR FLECHT SEASET 21-ROD DUNDLE FLOW BLOCKAGE TASK DATA
AND ANALYSIS REPORT.NRC/EPRI/MESTINGHOUSE REPORT NO 11
LOFTUS.H J. HOCHREITER.L E. LEE.N Westinghouse Electric Corp
FIN B-6204 EPRI NP-2014 82/09/30 Division of Accident
Evaluation 550pp 15793 001

8210210329 Forwards proposed proprietary Revision S to Topical Rapt EDR-1(P)-A. "Ederers Nuclear Safety-Related Extra-Safety & Monitoring (X-SAM) Cranes "Rapt withheld (ref 100FR2 770) CLARK: C H Ederer. Inc. 82/10/08 THOMAS.C Standardization & Special Projects Branch 2pp 19765 296

8210220047 Proposes to submit by end of CY82, evaluation of AGRE 820818 recommendations recontrol room habitability & NRC plans for implementing design improvements
BIRGKS.H U Defice of the Elecutive Director for Operations
82/09/17 SHELHOM, P B AGRS - Advisory Committee on Reactor
82/09/17 SHELHOM, P B AGRS - Advisory Committee on Reactor

--8210220048 Comments on ACRS 820818 itr re-control room habitability Response should address burden of new requirements on licenses, limited NRC budget & overall contribution to total risk addobtine. F. Technical Support Branch 82/08/24 MATTSON. R J Division of Systems Integration (post 811005) 3pp 1878A 222

- 8210220154 NUREC/CR-2444 VO2
 PHR FLECHT SEASET 21-ROD BUNDLE FLOW BLDCKAGE TASK DATA AND
 ANALYSIS REPORT, NRC/EPRI/WESTINGHOUSE REPORT NO 11
 LOFTUS, M J. HOCHRELITER, L E, LEE, M Westinghouse Electric Corp
 EPRI NR-2014 B2/09/30 Division of Accident Evaluation YUSpi
 Available at NRC 115 00 15796 128
- 8210220353 Comments on proposed rule 10CFR50 re mandatory property inturance for decontamination of huclear reactors (NUREC-0871) Insurance problems should remain responsibility of utils 5 NRC should not impose mandates OLKON.O W South Carolina Electric & Qas Co 47FR27371 046 82/10/11 CHILK.S J Office of the Secretary of the Commission 2pp 15776 271
- 8210250030 Forwards NUREO/CR-2927, "Nuclear Power Plant Electrical Cable Damageability Esperiments" Patential problem recable failures at temps less than min temps required for LOCA atmosphere should be brought to attetion of ASLB NOTLEY, DP Electrical Engineering Branch 82/09/30 KNIGHTON, CW Research & Standards Coordination Branch 1p 15808 271
- --8210250033 Forwards NUREO/CR-292/, "Nuclear Power Plant Electrical Cable Damageability Esperiments" LUKENS, L. t. Sandia Laboratories 82/09/20 NOTLEY, D.P. Electrical Engineering Branch 41pp 15808 272
- \$210260206 NUREG/CR-2710
 MASS FLOW MEASUREMENTS UNDER PWR REFLOOD CONDITIONS (N A DOWNCOMER AND AT A CORE BARREL VENT VALVE LOCATION
 HARDY, J E Gat Ridge National Laboratory FIN 8-0413
 ORNL/TH-8331 82/09/30 Division of Accident Evaluation 46pp
 15831 001
- 8210260211 NUREG/CR-2877
 INVESTIGATION OF CABLE DETERIORATION IN THE CONTAINMENT
 BUILDING OF THE SAVANNAM RIVER NUCLEAR REACTOR
 GILLEN, X T. CLOUCH, R W. JONEG, L H. Sandia Laboratories FIN
 A-1051 SANDEI-2613 82/09/30 Division of Engineering
 Technology 42pp 15831 048
- 8210260215 "TMI Action Plan Tracking Sys." 820630 issue KNO,M Office of Resource Management. Director 82/06/30 is9pp i5831 227
- 8204300098 BECY-82-142
 Requests approval of draft Rept to Congress on AD
 (NUREO-0090) for Oct-Dec 1981
 DIRCKS, W J Office of the Executive Director for Operations
 62/04/02 40pp (563o 225
- 8210270106 Forwards request for QMB review & supporting statement re NUREO-0906. "Outdance for implementation of SRP Rule:" per 10CRSO 34(g) amend NURRY:P G Office of Administration 82/10/20 SCURRY.N Office or Management & Budget ip 15832 320
- 8210270322 SECY-82-407
 Advises of issues remaining from 820108 meeting reinstrumentation for detection of inadequate core cooling in FWRs Requests action on update recommendations for implementation of NUREO-0737. Item II F 2
 DIRCKS: M J Office of the Elecutive Director for Operations 82/10/07 12pp 15851 323
- 8210270331 NUREQ-0267 R01
 PRINCIPLES AND PRACTICES FOR KEEPING OCCUPATIONAL RADIATION
 EXPOSURES AT MEDICAL INSTITUTIONS AS LOW AS REASONABLY
 ACHIEVABLE
 BRODSKY, A Division of Facility Operations 82/10/31 90pp
 Available at NRC #5 50 15648 022
- 8210270338 NUREO/ER-2759
 A PARAMETRIC STUDY OF CONTAINMENT SMERGENCY SUMP
 PERFORMANCE RESULTS OF VERTICAL DUTLET SUMP TESTS
 KREIN, M S , WESTER, M J , STROM, P. O Gandis Laboratories FIN
 A-1276 SAND82-7062 82/10/31 Division of Engineering
 Tachnology 113pp Available at MRC \$5.50 15847.271
- 8210270371 Summary of ACRS Subcommittee on Seactor Radiological Effects
 820720 meeting in Washington.OC re methods for reducing
 radiation exposures exposure histories at PMRs & status of
 NUREO-0761. "Radiation Protection Plans for Licensees"
 * ACRS Advisory Committee on Reactor Safeguards. 82/09/17
 ACRS Advisory Committee on Reactor Safeguards 17pp 15835 006

- ORG CORRESPONDENCE WITH OTHER ORGANIZATIONS
- 8208190233 IE Info Notice 80-35, Suppl 1, "Leaking & Dislodged 1-125 Implant Seeds " Svc list entl COBB.L I Division of Fuel Facilities, Materials & Safeguards 82/10/06 Consolidated Edison Co of New York 66pp 15761 1250 24X Fiche 50-000.82/10/06.8208190233
- B208190238 IE Bulistin B2-03, "Stress Corrosion Cracking in Thick-Wall.Large-Diameter.Stainless Steel, Recirculation Sys Piping at BHR Plants " Svr list entl DEYOUNO.R C Director's Office, Office of Inspection and Enforcement 82/10/14 Consolidated Edison Co pe New York 115pp 15810 [25 24% Fiche 50-000, 82/10/14,8208190238
- 8104080309 Std order for DDE work "Program for Cost Estimation for Proposed Safety Requirements." issued to ID Operations Dfc Statement of work end GRENIER. B L Office of Nuclear Reactor Regulation. Director J.J. A-6452-1 20-81-163 81/03/12 6pp 15465 183
- ~-8210080054 Forwards "Cost of Upgrading Capability to Isolate (PHR Main Feedwater Sys in Event of Breaks Inside Containment," final rept in response to statement of work in TE Murley 810616 liter re INEL technical assistance to NRR SAFFELL, B F EQ&G, Inc FIN A-6452 SAFF-155-82 82/04/14 SOLECKI, J E Energy, Dept of, Idaho Operations Office 1p 19565 167
- 8210120378 Forwards request for OMB review & supporting statement reporting & recordkeeping requirements of 10CFR73 concerning physical protection of plants & matis NORRY.P G Office of Administration 82/10/08 SCURRY,N Office of Management & Budget ip 15692 223
- 8210120388 Forwards request for QMB review & supporting statement refinal amend to 10CFR71 12 concerning general license for shipment in packages approved for use by another person NORRY, 9 O Office of Administration 82/10/06 BCURRY, N Office of Management & Budget ip. 19692 242
- 8210120402 Responds to approval request for info collection re-10CR150 Request approved through 850630 under OMB Number 3150-0032, per Paperwark Reduction Act. SCURRY. N Office of Management & Budget OMB 3150-0032 (12/07/12 SCOTT.8 Document Management Branch 2pp 15672 250
- B210120404 Responds to approval request for info collection ry domps1; itemsing of source math.10CFR40 Request approved through 830930 under GMB Number 3130-0020, per Paperbork Reduction Act
 SCURRY, N Office of Management & Budget OMB 3150-0020 IN'/UY/.1 SCOTT, B Document Management Branch Zpp 15652 252
- 8210120981 Transcript of 820918 public meeting in Washington. BC re-FEMA briefing on offsite appraisals program Pp 1-63 Visugraphs encl 4 Commissioners 82/09/18 87pp 15685 232
- 8210120599 Staff requirements memo re FEMA 820917 briefing on offeate appraisals program for commercial nuclear power plants FLMA should provide NRC w/info re availability of emergency plans & public broadcasts in foreign language CHILK.8 J Office of the Secretary of the Commission HD2091/F 82/09/24. BICKHIT.L Office of the Executive Director for Operations DIRKS.W J Office of the General Counsel Ip 15672 349
- 8210150236 Forwards 10CFR2 206.10CFR2 202.supplementary mail accompanying issuance of original rule in 1974,1977 amend to FR notice re 10CFR2 206 procedures
 BURNB. B Regional Operations & Enforcement Division 82/09/14,
 OREENER, K Federal Emergency Management Agency Upp. 15706 (19.2)
- B210220072 Informs that proposed rule on radiological protection activities coordination plan will be reviewed within next few months for congruence w/NRC/INPO umbralla memorandum of agreement re plant evaluations
 DIRCKS.H. J. Defice of the Executive Director for Operations
 82/09/20 WILKINSON.E P Institute of Nuclear Power Operationa
 2pp 15786-245.
- ~-BROBO10019 Informs of acceptability of encl draft App 3. "Coording Plan for NRC/INPO Radiological Protection Activities." 10 NRC/INPO unbrella memorandum of agreement re plant evaluations
 HILKINBON M.P. Institute of Nuclear Power Operations. B2: DIRCKB: N.J. Office of the Executive Director for Operations.

NUNDUCKETED ITEINS

- 1210280531 Forwards requests for OMB review & supporting statement re groposed revisions to 100FR30,40 & 70 specifying licensee responsibility for nuclear matis & procedures for termination of specific licenses WGPRY-P O Office of Administration 82/10/22 SCURRY-N Office of Administration 82/10/22 SCURRY-N Office of Hangement & Budget 1p 15814 333
- E210260544 Forwards request for OMB review & Congressional infocallection request re economic & worker safety aspects of problem concerning steam generator tube integrity (generic lit) MCRR.P Q Office of Administration 82/10/22 SCURRY.N Office of Management & Budget ip 15814-325
- SISO270106 Forwards request for DMB review & supporting statement re NARC-0906. "Guidance for Implementation of SRP Rule." per ICCFR50 34(9) amend MCRNY.P 0 Office of Administration B2/10/20 SCURRY.N Office of Management & Dudget ip 15832 320
- E210270116 Responds to approval request for info collection re
 1007R35 27 concerning records of teletherapy inaps &
 1007R35 27 concerning records of teletherapy inaps &
 1007R35 27 concerning records Calobara State Concerning Request approved through C30300 under CMB Number
 1100-0010, per Paperwork Reduction Act
 1100-0010, per Pa
- E210270119 Responds to approval request for info collection re Mark 1 containment program Request approved through 851031 under Cr3 Hubber 3150-0091 per Paperwork Reduction Act States, N. Office of Management & Budget DMD 3150-0091 82/10/09 5015.8 Document Management Branch 2pp 15832 344
- 5210270301 Forwards comments on Aug 1982 draft FEMA planning guidance for preparation of federal radiological emergency response jansiper 820920 memo NRC needs to continue to work w/ΓΕΜΑ in defining role as cognizant federal agency (ΕΝΙΟΝ-18 R Office of Nuclear Reactor Regulation, Director 82/10/15 DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 6pp 19836 330
- --B2102703D4 Requests comments on planning guidance for preparation of Jeffral radiological response plan by 821015 Results of review will be provided for consideration & comment DEVOUND, R C Director's Office, Office of Inspection and Enforcement 82/09/20 DENTON-NR Office of Nuclear Reactor Regulation, Director MAYNES, R C Region 1, Office of Director GYREILLY, J P Region 2, Office of Director ip 15836-336
 - 1:0290450 Forwards, for info, draft rept & apps on pressurized thermal that Completed rept will form basis of Commission paper (se 221030 H/o encl LAIMSSO C Assistant Director for Operating Reactors 02/09/28 pt02185.P Atomic Industrial Forum 2pp 13863 181

PROPOSED RULE

- 1:27149060 Transcript of 820615 public meeting re-certification of tidiographers (Region 5) in Oakland, CA Pp 1-99 Exhibits and
- 1 Commissioners 82/06/15 121pp. 13847.206
- E2:0010185 Comments on proposed rule 10CFRSO re fitness for duty Rule should be altered to require that any individual substantially injured by licensee application of rule be afforded adequate opportunity to rebut info HACKHONIA F Affiliation Unknown 47FR339BO 024. 82/09/24 Detecting & Services Branch 13pp 1556B 030
- 220010190 Consents on proposed rule 10CFR50 re fitness for duty of notiser pouer plant personnel Opposes rule CCMODT-D H Affiliation Unknown 47FR33980 025 82/09/2/ Colliting & Services Brench 1p 15568 020
- kil0010218 Comments on proposed rule 10CFR50 re fitness for duty of nuclear power plant personnel Opposes rule 5111K-JE American Nuclear Society 47FR33980 026 82/09/27 bottsting & Services Branch 2pp 15568 028.
- RIO010223 Comments on proposed rule IOCFR50 re mandatory property Invience for decontamination of nuclear reactors & NREG-0891, "Nuclear Property Insurance Status & Gutlook " Speces rule. TORKE B Mississippi Power & Light Co. 47FR27371 041, 82/09/24 Office of the Secretary of the Commission Ip 15568 019

- 8210010226 Pactage of two comments opposing proposed rule 10CFR90 rumandatory property insurance for decontamination of nuclear reactors
 SANDERS.H L Alabama Power Co GUODMAN.L Affiliation Unknown
 47FR27371 82707/27 CHILK.S J Office of the Secretary of the
 Commission 7pp 15568 021
- B210010230 Package of three comments on proposed rule 10CFR50 rollicensed operator staffing at nuclear power units COUNSIL.W 0 Connecticity Yanke Atomic Power Co COUNSIL.W 0 Northeast Nuclear Energy Co (subs of Northeast Otilities) COUNSIL.W 0 Northeast Otilities 2 COUNSIL.W 0 Northeast Otilities 3 Harvices Branch 13pp 15580 248
- 8210010232 Package of three comments opposing proposed rule 100FR50 rulicensed operator staffing at nuclear power units GIESLER.C W Misconsin Public Service Corp SMITH.JE American Nuclear Society SMITH.JE Duke Power Co 47FR38135 02/09/29 Docketing & Services Oranch Lipp 15574 062
- 9210010273 Comments on proposed rule 10CFR50 re licensed operator staffing at nuclear power units Requirement to have two senior reactor operators on shift should be reconsidered to implementation date delayed for 1 yr HOUGHTON, T C MKC. Inc. 47FR38135 008 82/09/27 CHILK, 8 J Office of the Secretary of the Commission 14pp 15569 197
- --8207050005 Informs that vendor has been working closely woutcle for NHC in developing personnel requirements for operators of nuclear power plants NRC should issue regulations or guidance & not dictate means of meeting requirements KNUTH.DF HMC, Inc. 82/07/13 PALLADIND,N Commissionors 7pp 15569 202
- 8210010302 Comments on proposed rule 10CFR50 re mandatory property insurance for decontamination of nuclear reactors Supports rule
 SPENCER.N D Texas Utilities Generating Co. 47FR27371 035
 82/09/22 Office of the Secretary of the Commission 2pp 15549 308
- 8210010307 Package of three comments opposing proposed rule 1001850 re mandatory property insurance for decontamination of nuclear feactors
 OIESLER.C W. Misconsin Public Service Corp. WITHERS, D.D. Pacific
 Cas & Electric Co. KELLY.A B. American Nuclear Insurers
 47FR27371 82/09/28 Chilly, S.J. Office of the Secretary of the Commission 19pp. 15968-289
- 82:0010310 Comments on proposed rule 100FR50 re staffing at nuclear power plants Opposes rule
 LENIS.N I Lewis. M 47FR38135 006 82/09/10 Office of the Bacretary of the Commission 1p 19568 264
- 8210010322 Comments on proposed rule 100FR50 relicensed operator staffing at nuclear power units Comment period should be extended a months during which time NRC should introduce addl evidence to justify proposed rule
 POPEOID J Washington Legal Foundation 47FR38135 007 82/07/2/Docketing & Bervices Branch 5pp 15574 035
- 8210010374 Package of two comments opposing proposed rule 100fR90.
 "Mandatory Property Insurance for Decontamination of Nuclear
 Reactors "
 PARKYN, J D Affiliation Unknown SOUCY, A R Yanker Atomic Electric
 Co 47F827371 82/09/24 Docketing & Services Branch 5pp
 15573 090
- 82100103Bi Package of four comments on proposed rule 10CFR50,
 "Mandatory Property Insurance for Decontamination of Nuclear
 Reactors "Supports rule
 WYATT-J M Louistana Power & Light Co DELLSY-H K Commonwealth
 Edison Co. R
- 8210120147 Responds to 820830 ltr expressing concern re final version of 100FR61. "Licensing Requirements for Land Disposal of Radwaste." De minimis issue for managing low level radwaste will be addressed within next few yra MARTIN. J. B. Division of Waste danagement 82/09/21 HARRIS.B J. Health Physics Society 2pp 15692 177
- 8210120173 Forwards minutes of 820729 briefing on 100F860 W/o enci BELL:M J High Level Weste Technical Development Branch 82708/31 BOHLINOERL H Louisiana, State of LIEBOLD:W C Affiliation Unknown CAHIL:P C Environmental Protection Agency App 15492:205

- 8210130270 Package of three comments supporting proposed rule 10CFR50, "Applicability of License Conditions & Tech Specs in Emergency"

 CLAYTON.F L Atabama Power Co HULLER, O. E. Illinois Power Co PARKYN, J. D. Afrillation Unknown 47FR35976 82/10/04 CHILK, S. J. Ortice of the Secretary of the Commission 5pp 15677 004
- 8210130277 Package of two comments opposing proposed rule 10CFRSO rulthoss for duty of personnel w/unescorted access to protected areas
 O'TODLE.J D Consolidated Edison Co of New York POPEO.D J
 Washington Legal Foundation 47FR33780 82/10/05 CHILKIS J
 Office of the Secretary of the Commission 11pp 15678 355
- 62(0130282 Package of three comments on proposed rule 10CFR50 refitness for duty of personnel w/unescorted access to protected areas

 JENS.II H Detroit Edison Co GIESLER, C W Wisconsin Public Service Corp KEARREY, J J Edison Electric Institute 47FR33980

 62/10/04 CHILK, S J Office of the Secretary of the Commission 14pp 15678-264
- 821013033: Comments on proposed rule (OCFRSO re mandatory property insurance for decontamination of nuclear reactors (NUMEG-0891) Imposition of blanket coverage requirement poses restrictive economic hardship on smaller plants [AYLOR.J H Dairqland Power Cooperative 47FR27371 042 82/09/23 Office of the Secretary of the Commission 2pp 15681 001
- 82:0130391 Comments on proposed rule 10CFR50 refitness for duty of personnel w/unescorted access to protected area Existing program adequate Transferring authority to federal level will not improve effort LUNDVALLIAE Baltimore Gas & Electric Co 47FR33980 027 82/09/30 CHILK, S J Office or the Secretary of the Commission 2pp 15581 004
- 8210130376 Comments on proposed rule 10CFR50 re fitness for duty of pursonnel D/unescorted access to protected areas Great latitude for implementation would provide better end product than rule that defies compliance Opposes rule ANDOONINI.9 C Ariiona Public Service Co 47FR39880 028 82/09/2/Docketing & Services Oranch 4pp 15681 021
- 8210130399 Package of 10 comments opposing proposed rule 10CFR50 refitness for duty of personnel w/onescorted access to protected areas KNUTM.D F KMC, Inc. UHRIG.R E Florida Power & Light Co. COUNSIL.W G. Hortheast Utilities 47FR33980 82/10/04 CHILK.S.J. Office of the Secretary of the Commission 33pp 1568 128
- 8210130402 Comments on proposed rule 10CFR50, "Licensed Operator Staffing at Nuclear Power Units "Requirement to have senior reactor operator domiciled to control room would not controlbute to overall plant safety DELGCORGE, LO Commonwealth Edison Co 47FR39135 Q17 82/09/27 Doctoting & Services Branch 1p 15692 G64
- 8210130433 Comments on proposed rule 10CFR50 "Licensed Operator Staffing at Nuclear Power Units" Need for proposed rule has not been adequately established HELFRICH: R = Yantee Atomic Electric Co 47FR38135 021 82/09/27 Docketing & Services Branch 4pp 15682 055
- 8210130521 Package of two comments on proposed rule 1QCFRSO, "Lacensed Operator Staffing at Nuclear Power Plants"

 NILLB.L.M Tennessee Valley Authority VANDEWALLE.D.J Consumers Power Co. 47FR38155 82/10/04 Docketing & Services Granch 60s. 15682 355
 - ents on proposed rule 10CFRSO, "Applicability of License" each Specs in Emergency " Supports rule efense, Dept of, Defense Nuclear Agency 47FR35996 006 ach 500 15683 001

- 8210130554 Comments on progosed rule IOCFR50 re mandatory property insurance for decontamination of nuclear reactors (NUREG-0891) MITTL.R L Public Service Electric & Gas Co of New Jersey 47FR27371 043 82/09/24 CHILK.S J Docketing & Services Branch App 15684 001
- 8210130584 Comments on proposed rule 10CFR50. "Licensed Operator Staffing at Nuclear Power Units" Min staffing table should be modified to indicate two-operator requirement for two-units.one-control room plant FAY.C W. Wisconsin Electric Power Co. 47FR38135 018 82/09/27 CRILK.S J. Diffice of the Secretary of the Commission 2pp 15679 088
- 8210130594 Comments on proposed rule 10CFR50, "Licensed Operator Staffing at Nuclear Power Units" Due to difficulties in obtaining qualified personnel effective date for rule should be extended to 840101

 THORPE.J R Oeneral Public Utilities OPU Service Corp 47FR30135
 016 82/09/20 CHILK, S J Office of the Secretary of the Commission ip 15679 116
- 8210130599 Package of two comments opposing proposed rule 10CFR50
 "Licensed Operator Staffing at Nuclear Power Units"
 TUCKER.H B Duke Power Co MATTIMOE, J J Sacramento Municipal
 Utility District 47 FR38135 82/09/30 Docteting & Services
 Branch Spp 15479 050
- 8210220226 Comments on proposed rule 10CFR34 providing third party certification of radiographers Measure would be excellent step in direction of safety
 LOW.R.L. Associated Technologies, Inc. 47FR19152 090 82/05/11
 JDNES.J.A. Office of the Secretary of the Commission 1p. 19776 209
- B210220246 Comments re proposed rule 10CFR34 providing for third party radiographic certification Opposes rule THOMPSON, V J Vester J Thompson, Jr., Inc. 47FR19152 081 B2/05/21 GODWIN, A V Alabama, State of ip 15776 199
- B210220256 Comments on proposed rule 10CFR34 providing for certification of radiographers Supports rule SACKETIMH A Affiliation Unknown 47FR19152 087 82/04/00 JONES J A Diffice of Nuclear Regulatory Research, Director 3pp
- B210220285 Package of two comments opposing proposed rule 100FR50 rule fitness for duty COLLING.R M Dechtel Corp FLYNN.S F Carolina Power & Light Co 47FR33980 B2/10/07 Docketing & Services Branch Spp 19775 076
- B210220301 Comments on proposed rule 10CFR50 allowing waiver of Tech Specs during emergency situation if necessary to protect health & safety of public Supports rule WITHERS:B D Portland General Electric Co 47FR35974 011 B2/10/05 Docketing & Services Branch 1p 15776 104
- B210220306 Comments on proposed rule 10CFRSO re applicability of license conditions & Tech Specs in emergency Applauds rule for providing leeway to protect health & safety of public Deplores need for rule which should be self-evident 0000MANLS Affiliation Unknown 47FR35996 010 82/10/07 Docketing & Services Branch 2pp 15776 179
- 6210220316 Package of five comments on proposed rule 10CFR34 providing for third party radiographic certification MANILTON.J F Oklahoma Batel Castings Co MODES, M C Universal Technical Testing Laboratories. Inc MCINNIS.E L Jacksonville Shippards, Inc 47FR19152 82/10/08 JONES, J A Office of Nuclear Regulatory Research, Director 17pp 15776 128
- B210220321 Package of two comments on proposed rule 10CFR34 providing for certification of radiographers
 HICKLICH,R M Rockwell International Corp BRADLEY,F J New York,
 State of 47FR19152 B2/10/08 JONES,J A Office of Nuclear
 Regulatory Research, Director 7pp 15776 170
- 8210220326 Package of two comments on proposed rule 10CFR50 re licensed operator staffing at nuclear power plants
 HITTLER L Public Service Electric & Qas Co of New Jersey PRATT.C M Power Authority of the State of New York 47FR38135 82/10/07 CHILK.S.J Office of the Secretary of the Commission 2pp 15776 045
- 8210220333 Comments on proposed rule 10CFR50 re licensed operator staffing Rule lacks true applicability to criteria of YMI lassons learned & ignores complexity range of different facilities & human factor issue of size of control room PARKYN, J D. Adfiliation Unknown 47FR38135 025 82/09/26 Docketing & Services Branch 2pp 15776 181

- 2210220334 Package of three comments on proposed rule 10CFR50 re
- 210:20334 Package of three comments on proposed rule 10CFR50 re litress for outy of parsonnel w/unescorted access to tratected areas scientsOut O Houston Lighting & Power Co DALE, L.F. Mississippi forer & Light Co VANDEMALLE, D.J. Consumers Power Co 47FR33980 Forer & Light Co VANDEMALLE, D.J. Consumers Power Co 47FR33980 52:10706 CHILLES J. Office of the Secretary of the Commission 15776 152
- E210220337 Comments on proposed rule 10CFR50 re licensed operator haffing Shared control room w/identical layout & controls for each unit of multi-unit stations proposed LAVIDSOND R. Clevaland Electric Illuminating Co. 47FR3B135 0: 22/07/25 Docketing & Services Branch ip 15776 028 47FR3B135 022
- #210220342 Forwards comments on proposed rule 10CFR94 M/o encl FAULICK,L R Pipe Fabrication Institute 47FR19152 084 8 CONES.J A Office of Nuclear Regulatory Research, Director 82/09/09 15776 151
- \$210220348 Comments on proposed rule IOCFR90 re fitness for duty of personnel u/unescorted access to protected areas Proposed Tile should be coordinated w/ANSI/ANS 3 3 screening rate shows requirements requirements EPADBURY.R B Stone & Wabster Engineering Corp 47FR339BC e2/10/04 Docketing & Services Branch 3pp 15776 268 47FR33980 045
- E215220353 Comments on proposed rule 10CFR50 re mandatory property invitants for decontamination of nuclear reactors (NAFCO-0891) Insurance problems should remain responsibility of wills NRC should not impose mandates (NRC Should not impose mandates (NRC Should not impose mandates (NRC Should Na South Carolina Electric & Oas Co 47FR27971 0946 (E2/10/11 CHILK-S J Office of the Secretary of the Commission of the Same of the Same of the Same of the Commission of the Same of the
- 1210220359 Comments on proposed rule 10CFR50 re fitness for duty of second Divinescorted access to protected areas Most practical approach would be issuance of general policy stateback rather than rule

 AREMBURO.D W. Public Service Co. of Colorado. 47FR33990 056

 E210704 CHIEKS J. Office of the Secretary of the Commission
- E210220366 Comments on proposed rule 10CFR50 re fitness for duty of personnel divinescorted access to protected areas Rule not receivary CURISH H pennsylvania Power & Light Co 47FR33980 037 E210/07 MOVLELU C Office of the Secretary of the Commission 255 15779 199
- E210220312 Package of four comments on proposed rule 10CFR50 re fitness for luty of parsonnel w/unescorted access to protected
- army of H Yankee Atomic Electric Co THORPE, J R General Public EXAMPS, D H Yankee Atomic Electric Co THORPE, J Roseral Public Littlics GPU Service Corp GARY, R J Taxas Utilities Generaling Co 47F833980 B2/10/12 Docketing & Services Branch 13pp Congral Public Litties
- EXIOMOGIA Comments on proposed rule IOCFRSO re fitness for duty of strong! w/unescorted access to protected areas Opposes Virginia Electric & Power Co 47FR93980 06: Docketing & Bervices Branch 2pp 19779 182 LEASOURO.R H 47FR33980 0A3
- EJI0220376 Comments on proposed rule 10CFR50 re fitness for duty of streamel w/unescarted access to protected areas Current espers practiced throughout industry adequate w/o use of the think 5100cf tests and the configuration of the configu
- 21022379 Comments on proposed rule 10CFR60 re technical criteria is teologic repositories for high level radwaste Overly restrictive & specific performance side not necessary WHILIMGALL MAMERICAN NOTION OF STATES OF THE PROPOSED BY A STATES OF THE PROPOSED OF THE PROPOS
- E20020303 Package of three comments on proposed rule 10CFR50 rediffuses for duty of personnel w/unescorted access to intertité areas

 EDMODS.N S Debevoise & Liberman DELOEUROE.L O Commonwealth

 Fisher Co MAIER. J E Rochester Oas & Electric Corp. 47FR33780

 82/10/05 CHILK.S. J Office of the Secretary of the Commission 2740 13779 351
- 20222095 Package of three comments on proposed rule 10CFR50 re filmss for duty of personnel w/unescorted access to statected areas FINITESSES AREAS

 MINIMAD, PY FIORIDE POWER CORP CRANE, PA Pacific Cas & £lectric

 Co MICHEL, C.J. Nuclear Fuel Services, Inc. (suba of Getty Dil

 Co) 47FR33980 82/10/07 CHILK, B.J. Office of the Secretary of

 Ni Consisting 1Gpp 15778 248

- 8210820403 Package of two comments on proposed rule 10CFR50 reapplicability of license conditions & Tech Specs in emerdentu embrgenty KOESTER:O L Kansas Cas & Electric Co FUENTE.E S Mississippi State of 47F835996 82/10/13 Docketing & Gervices Branch 2pp 15779 164
- B210220409 Petition for exemption from schedular requirements of proposed rule 10CFR50 re hydrogen control
 NTLEV,E EC Carolina Power & Light Go 49FR65466 B2/10/11
 CHILK,S J Office of the Secretary of the Commission 4pp
- 8210290234 Package of four temments supporting proposed rule 10C/R50 re applicability of license conditions & Tech Specs in emergency situations a LeBoeuf, Lamb, Leiby & MacRae GIEGLER, C W Wisconsin Public Service Corp FISHER, C R GA Technologies. Inc /General Atomic Co 47FR39796 82/10/21 CHILK, S J Office of the Secretary of the Commission App 15033 267
- 8210290237 Comments on proposed rule 100FR50 re applicability of license conditions & Tech Specs in emergency situations Rule vague & unquantified BRADDURY, R & Stone & Webster Engineering Corp. 47FR35996 026 62/10/18 Docteting & Services Branch 2pp. 15853 179 47CR35896 026
- 8210290239 Package of two comments opposing proposed rule 10CFR50 refitness for duty of personnel w/onescorted access to protected areas SHIELDS:S W Public Service Co of Indiana. Inc MUSCLE, D Northern States Power Co 47FR33980 82/10/18 CHILLS J Office of the Secretary of the Commission 11pp (5853-239
- 6210270240 Package of six comments supporting proposed rule 1007R#0 rule applicability of license conditions & Tech Space (nemergency situations ZUMMO.J. LORIO,P. Utility Workers Union of America MARSHALL, J. R. Arkansas Power & Light Co. 47FR35976 82/10/18 CHILK, S.J. Office of the Secretary of the Commission 13pp. 15053 182
- 8210290242 Comments on proposed rule 10CFR50 re fitness for duty of personnel U/unescorted access to protected areas Utils elready have related programs SZALAY.R Atomic Industrial Forum 47FRDD 986 Docketing & Bervices Dranch 2pp 15853 265 47FR33980 070 82/10/22
- 8218290244 Comments on proposed rule 10CFR50 re applicability of license conditions & Tech Specs in energency estructions Opposes rule EDOLEMAN, W. Affiliation Unknown 4/FR35996 021 82/10/14 Office of the Secretary of the Commission Spp. 15853 254
- 8210290245 Package of two comments supporting proposed rule 1007850 re applicability of license conditions & Tech Space in amergency situations
 DIXON, Q W. South Carolina Electric & Qas Co. DELOCORDE, L. D. Commonwealth Edison Co. 47FR35976 82/10/19 CHILL, B J. Diffice the Secretary of the Commission. Spp. 15854 086 Diffics of
- 8210240249 Comments on proposed rule tOCFR50, "Licensed Operator Staffing at Nuclear Rower Units " Rule underestimates difficulty involved in relecting training & licensing NUSCLE, D. Northern States Power Co. 47FR3G13 Docketing & Services Branch 2pp. 15854-099
- 8210290253 Comments on proposed rule 10CFR50, "Licensed Operator Staffing at Nuclear Power Units " Dpposes rule SZALAY,8 Atomic Industrial Forum 47FR89135 027 82/10/22 Docketing & Services Branch 1p 15854 090
- 8210290255 Comments on proposed rule 10CFR50 re reduction in vol of Tech Specs for nuclear power reactors Supports rule HONEY, J American Nuclear Insurers 47FB13369 031 82/10/14 Docketing & Services Dranch 6pp 15853 114
- 8210290259 Comments on proposed rule 10CFR50 re applicability of license conditions & Tech Specs in emergency situations BAUBER, N A Lowenstein, Newman, Reis, Azelrad & Toll 47FR95994 014 82/10/15 Bocksting & Services Branch 2pp 15859'126
- 8210290263 Package of two comments supporting proposed rule 10CFR50 reapplicability of license conditions & Tech Specs in emergency situations
 EDWARDS. D W Yankee Atomic Electric Co BOOKER. J E Gulf States
 Utilities Co 47FR35996 82/10/20 Doctoting & Services Branch
 3pp 15854 091

8210270265 Comments on proposed rule 10CFR50 relactions that depart from license conditions or Tech Specs in emergency Supports

MILLS.L M Tennessee Valley Authority 47FR35996 031 8: Drfice of the Secretary of the Commission 19 15854 045

8210290249 Package of two comments opposing proposed rule 10CFR50 re

fishess for duty of personnel w/unescorted access to protected areas
NUBINAK,R A Long Island Lighting Co SANDY,W Affiliation
Unknown 47FRJ3980 82/10/21 Docketing & Services Branch
15854 078

8210290273 Package of two comments opposing proposed rule 10CFR50 re fitness for duty of personnel w/unescorted access to protected areas

DIXON.O M South Carolina Electric & Gas Co GUCHA-L T Georgia Power Co 47FR339BO 82/10/19 CHILK,9 J Office of the Secretary of the Commission 5pp 15854 054

PRM PETITION FOR RULEMAKING

6210130257 Comments on petition for rulemaking PRM-50-33 re reduction in frequency of emergency planning evertises Supports petition & concept of blennial evertises Supports HOPMODO.C A Drange County, CA 47FR24252 035 82/0 of the Secretary of the Commission ip 15475 336 82/09/30

8210130280 Comments on petition for rulemaking FRM-50-32 re protection against affects of electromagnetic pulse Petition should be CACHETTA, J.P. Atomic Industrial Forum 47FR27371 021 82/10/04 Docketing & Services Branch 29p 15678 350

82:0220294 Comments on petition for rulemaking PRM-50-328 re electromagnetic pulse in nuclear power plants Requests that IGCFR50 be amended to require provision for design features for protection against attacks & destructive acts MARSHALL.W H Mapleton Intervenors ISSUANCES OM 82/08/5 Office of the Secretary of the Commission 2pp 15776 066

8210220386 Comments on petition for rulemaking PRM-50-33 re emergency preparedness Supports concept of reducing frequency of emergency exercise involving state & local govt GUCKA-L T Georgia Power Co 47FR2925 036 82/10/04 Docketing & Services Branch 1p 15779 170 Docksting

PROJECTS - PREDOCKET LICENSING

8210120360 Forwards comments on "Topical SAR for Castor Cask Type ISFSI eivizouou rorwaros comments on "Topical SAR for Castor Cast Type ISI (Dry Storage) " Tests & analysis results do not address site parameters Only generic design info applicable ROUSELL C Advanced Fuel & Spent Fuel Licensing Branch 82/09/29 ROLLINS, J D Gesellschaft für Nukleur-Bervice mbH 47pp 15690-249

8210250356 Comments on 820921 proposed order concerning preservation of documents Util should not be allowed to terminate proceeding Parties should provide list of files designated "central files " Certificate of Svc encl MCDIARMID.R C Northern California Pawer Agency, California, State of, BLAIR.B S Anaheim, CA BLAIR.B S Riverside, CA ISSUANCES A 82/10/21 [Opp 15790 141]

9210270175 Notice of ASLB reconstitution VA Laurenson, chairman LAID,R M Atomic Safety and Licensing Board Panel ISBUANCE 62/10/25 ip 15922 354 ISSHANCES A

MONCOMPLIANCE REPORTS AND RELATED CORRESPONDENCE

itrol rod guide tube lants,

214 60/03/14

+ tube support pins ratina

11 EIBENHUT, D

82(0)20236 Part 21 rept to emergency standby diesel generator set Defect exists in one power piston installed in Cylinder Location 7L in engine 7168 Piston will be replaced by Apr 1983.prior to startup STOLBALF B Cooper Energy Services PT21 82-498-000 82/09/30 Director's Office, Office of Inspection and Enforcement 1p 15652 124

B210130447 Part 21 rept re sheared pinion keys in Limitorque Model SB-0-25 motor operators Sheared keys apparently resulted from use of inappropriate matls Utils advised to watch for indications of failed pinion keys RAME, E.P. Westinghouse Electric Corp. NS-EPR-2637 B2/09/29 DEYOUNG, R.C. Director's Office, Office of Inspection and Enforcement 2pp 15482 028

8210250132 Part 21 rept re preliminary exam of EPRI safety & relief valve test program indicating that Dresser safety valves could chatter, reducing capability to relieve pressure Listed plants should determine ring settings
TAYLOR.J H Babcock & Milcor Co PT21 82-718-000 82/10/15 DEYOUNG.R C Director's Office, Office of Inspection and Enforcement 3pp 15787 013

QUALITY ASSURANCE INSPECTIONS QA999

820929016B Responds to FOIA request for documents prepared by NRC staff & consultants on 10CFR50.App B re GA audits of testing facilities conducted within past 10 yrs by NRC Related Division of Rules and Records 82/08/26 PHILIPS.H N Liberman 2pp 15564 002 FELTON, J H Division Debevoise & Liberman

--8207290236 Forwards GA Program Insp Rept 79900705/82-01 on 811227-30 No noncompliance noted
HEISHMAN.R F Reactor Construction Branch 82/05/26 HEISHMAN.R F Reactor Construction Branch 82/05/26 BOUCHEY, G D Washington Public Power Supply System 2pp 15564 060

--8209290240 GA Program insp Rept 99900905/82-01 on 811229-30 No noncompliance noted Major areas inspected test set-up of Weldmuller terminal block post-LOCA test program.post-test insp test specimens & test plan AGEE.JR. BENNETT.AB Reactor Construction Branch CRAFT.C M Sandia Laboratories 82/09/18 3pp 15564-062

B21004014B Ack receipt of 820827 ltr informing NRC of steps taken to correct nonconformance noted in GA Program Insp Rept 99900043/82-01 POTAPOVS, U Division of Vendor & Technical Programs 82/09/27 MOYER, D J Pacific Pumps Div 1p 15582 350

--8210040155 Responds to NRC ltr re nonconformance noted in GA Program
Insp Rept 99900063/82-01 Corrective actions visual insp
procedure added providing approved written procedure after
mfg operations, welding & cleaning
MOYER, D J Pacific Pumps Div 82/08/27 POTAPDV8, U Division o
Vendor & Technical Programs 2pp 15582,351

8210040171 Ack receipt of 820908 ltr informing NRC of steps taken to correct nonconformance noted in GA Program Insp Rept 99900503/82-02

POTAPOVS, U Division of Vendor & Technical Programs 82/09/27 HENDRICKSON, T Burns & Ros Co ip 15582 305

---8210040173 Responds to NRC 820806 itr re nonconformance noted in GA Program lnsp Rept 99900503/82-02 Corrective actions special audit will be performed to verify that each corporate operation manual it up-to-date
HENDRICKSON.T. Burns & Ros Co 82/09/08, POTAPOVS,U Division
of Vendor & Technical Programs Spp 15582 306

8210040192 Ack receipt of 820823 ltr informing NRC of steps taken to correct nonconformance noted in OA Program Insp Rept 99900404/82-01 999000404782201 PDTAPOUS, U Division of Vendor & Technical Programs S2/ SLEMBER,R J Heatinghouse Electric Corp. 1p 15583 184, 82/09/27

--B210040196 Responds to NRC 820811 ltr rs nonconformance noted in 0 Program Insp Rept 97900404/82-01. Corrective actions, GA program revised in 1981 to require that purchase order or purchase order change se issued to vendor RLEMBER: R J. Nestinghouse Electric Corp PI&DA-82-2115 82/08/23 POTAPOVS.U Division of Vendor & Technical Programs 2pp 15583 185

8210040333 Ack receipt of 820904 & 15 ltrs informing NRC of steps to correct nonconformance noted in GA Program Inap Rept 999007(2/82-0)
POTAPOVE,U Division of Vendor & Technical Programs, 82/09/27.
CAPRA,L A Systems Control, Inc. ip. 15586:180

- --221GQ40335 Revises B20904 response to NRC B20804 ltr re nonconformance nated in QA Program Insp Rept 99900712/B2-01 Corrective actions QA manual will be revised & new procedure developed to address control of brawings CAPRA. A Systems Control Inc B2/09/15 PATAPOVS, U Division of Vendor & Technical Programs 2pp 15586 181
- --2210040340 Responds to NRC 820806 ltr re nonconformance noted in GA Program Insp Rept 99900712/82-01 Corrective actions GA example will be revised procedures followed in transmitting frautings instructions developed for control of drawings CAPRAL A Systems Control. Inc 82/09/04 POTAPOVS. U Division of Vendor & Technical Programs Rpp 15386 183
- F110050188 Act receipt of 820630 ltr informing NRC of steps taken to cereet nonconformance noted in GA Program Insp Rept \$4900513/82-01 F074P0051/B2-01 Bivision of Vendor & Technical Programs 82/10/01 BALEY.F C Yeledyne Engineering Services ip 15611 189
- --P2(035019) Responds to NRC B20611 ltr re-nonconformance noted in OA Program Insp Rept 9990313/B2-01 Corrective actions dual storage of records design activities re-containment torus agrodynamic analyses provided in accordance w/OA manual B2/LEV.F C. Teledyne Engineering Services A773-B2/O1, B2/O6/30 P014F09, U pivision of Vendor & Technical Programs 7pp 15611 190
- E210050193 Ack receipt of B20910 ltr informing NRC of steps taken to tareet monconformance noted in GA Program Insp Rept 99500033/82-01 POLEPUS. Division of Vendor & Technical Programs 82/10/01 PUPPEL.H D Westinghouse Electric Corp 1p 15609 173
- 8240030284 Act receipt of 820128 & 811006 ltrs informing NRC of steps taten to correct nonconformance noted in GA Program Insp Fell 99700334/81-02. Two nonconformances, Itams C & D. closed with require no further action SOTAPOVS.U Division of Vendor & Technical Programs 82/10/01 MATERIS.C Transamerica Delayal. Inc ip 19611 163
- --9210030287 Act reteipt of 820128 & 811006 ltrs informing NRC of steps titen to correct nonconformance noted in QA Program Insp Rest 99900314/81-02 Questions re validity of honconformance. It is to be never on qualification of motors unacceptable sports095. U Division of Vondor & Technical Programs 82/05/06 MATHEMB.C Transamerica Delaval, Inc. 200 15611 164
- --8210050290 Responds to NRC B20114 ltr re nonconformance noted in GA Program Insp Rept 97900334/81-02 Requests reconsideration of monconformance Items C & D Motor name plate & motor test rest indicate motors are environmentally qualified.

 BOYER, RE Transamerica Delaval, Inc B2/01/28 POTAPDVB, U Vendor Inspection Branch 2pp 15611 166
- --B210050292 Ack receipt of 811004 ltr re nunconformance noted in QA fregram insp Rept 99900334/81-02 Addl info required in order to consider request for re-evaluation priprov8.U Vendor Inspection Branch 88/01/14 MATHEWS. C Transmerica Delaval: Inc. 2pp 15611 148.
- -- 2210030275 Responds to NRC 810718 ltr re-nonconformance noted in GA Frogram line Rapt 79700334/81-02 Corrective actions drawings showing installation of oil plug revised. Requests reconsideration of Items B.C. k.D. 20168, R.E. Transamerica Delaval, Inc. 81/10/06 POTAPOVB. U. Vandor Inspection Branch App. 15611-170
- \$210120222 Forwards OA Program Insp Rept 99900522/82-02 on 820712-15 to noncompliance noted FOTAPDUS-U Division of Vendor & Technical Programs 82/09/15 STATION C D Bechtel Corp Spp 15452 130
- -- 8210120233 GA Program Insp Rept 99900522/82-02 on 820712-15 No noncompliance noted, Major areas inspected: procedures & representative records re hydrodynamic load analysis, interviews w/personnel & observations by inspectors, COSTELLO, J. R., HALE, C. J. Division of Vendor & Technical Programs 82/09/08 11pp 15632 133.
- 8210120280 Ack receipt of 820525 ltr informing NRC of steps taken to terret nonconformance noted in GA Program Insp Rapt 9760302/81-02.
 FORMOUS U Division of Vendor & Tachnical Programs 82/10/06
 FRIEDMAN N.A Western Piping & Engineering Co., Inc. Ip. 18413-032

- --8210120285 Forwards ASME Ltr indicating status of inquiry re nonconformance noted in GA Program Insp Rept 99900302/81-02 HAYTACK,R K Western Piping & Engineering Co , Inc 82/08/23 POTAPOVS,U Division of Vendor & Technical Programs 2pp 15553-053
- --8210120293 Responds to NRC 820504 ltr re nancanformance noted in UA Program Insp Rept 99900302/81-02 Categorically denies allegations of nonconformance re design of component supports
 FRIEDMAN. K.A. Western Piping & Engineering Co., Inc. 82/05/25 POTAPOVS. U. Division of Vendor & Technical Programs 3pp 19553-055
- 6210120301 Ack receipt of 620623 & 0901 itrs informing NRC of steps taken to correct nonconformance noted in QA Program (nsp Rept 97900400/79-04 POTAPOVS.U Division of Vendor & Technical Programs 62/10/05 GUILBERT.D & Babcock & Hilcox Co ip 15653 Q41
- --B210120304 Responds to NRC 620811 ltr re nanconformance noted in UA Program Insp Rept 99900400/79-04 Corrective actions input ref for old calculations winew effectivities varified OUTLBERT, D E Babook & Milcor Co 82/09/01 POTAPRUS, U Division of Vendor & Technical Programs 2pg 15653 042
- --8210120309 Ack receipt of 820623 lir informing NRC of steps taken to correct nonconformance noted in OA Program Insp Rept 99900400/79-04 Requests verification of input lef for revised calculations POTAPOVS.U Division of Vendor & Technical Programs B2/08/11 GUILBERT.D E Dabcock & Hiled: Co lp 15459 044
- --8210120313 Forwards rept re nonconformance noted in GA Program Insp 99900400/79-04 Corrective actions treatment of new & revised calculations defined for source ref pilot program QUILDERT.D E Babcock & Wilcox Co B2/06/23 POTAPOVS U Division of Vendor & Technical Programs 8pp 15653 045
- 8210(2031) Forwards GA Program Insp Rept 99900780/82-01 on 820712-16 & notice of violation & Honconformance POTAPOVS, U Division of Vendor & Technical Programs 82/09/15 STEVENSON, J G Magnetrol International Inc 2pp 15652-059
- --8210120312 Notice of violation from insp on 820712-16
 # Division of Vendor & Technical Programs 82/09/15 ip
 15652.061
- ~~82;0120317 Notice of nonconformance from these on B2D712~16 # 5191ston of Vendor & Technical Programs 62/09/15 Ip #3632:062.
- --BR10120319 QA Program Insp Rept 99900780/B2-01 on 820712-16
 Noncompliance noted Part 21 procedures not adopted for
 evaluating defects pertaining to Class IE items & IEEE Std
 OA program not astablished for mfg of Class IE items
 PARKERIL D , BARKERI Division of Vendor & Technical Programs
 82/08/30 Spp. 15652 063
- 8210150513 Ack reseipt of 820713 & 0914 line re nonconformances noted in GA Program Insp Rept 9990289/82-01 POTAFOVS.V Division of Vendor & Technical Programs 82/10/08 DUBROWA L Borg-Warner Corp 1p 15714 212
- ~-8210150517 Responds to NRC 820831 ltr re nonconformances noted in QA Program Insp Rept 99900289/82-01 Corrective actions systematic check of drawings made No evidence of similar error found MILINAZZOP, L. Barg-Werner Corp. 0~82~084/PLM 82/09/14 PQTAPOVB, U. Division of Vendor & Technical Programs 3pp 15714 213
- --8210150521 Act receipt of 820713 ltr re honconformances of Program Thep Rept 99700289/82-01 Response unacceptable. Required design incomplete Revised response expected within 25 days of ltr receipt POTAPOVS.U Division of Vendor & Technical Programs PUSROW.A L Sorg-Warner Corp Ip 15714 216
- --82(0150526 Responds to NRC ltr re nonconformances noted Insp Rept 99900289/82-01 Corrective actions disagress; revealed nonconformance Byetematic check of remaining drawings found no similar error HILINAZZO,P L. Borg-Herner Corp Q-82-043/PLM 82/0 PDTAPDV8JU. Division of Vendor & Technical Programs 15714-217.

- 6210150502 Ack receipt or 811120, 820111 & 0720 ltrs in response to GA Program insp Rept 99900759/81-01 Efforts to account for 10 missing or unaccounted for defective springs & 8 remaining governors w/defective springs continuing POTAPOVS, U Division of Vendor & Technical Programs 82/10/08 SUNDSTEDITJ & Moodward Governor Co 1p 15713 149
- --B2j0150536 Forwards ltr sent to customers re exemption from 10CFR21 6 posting regulations, per NRC 820506 ltr & in response to GA Program Insp Rept 97900759/81-01 List of customers encl ZWEG.A Hoodward Governor to 82/07/23 POTAPOVS, U Division of Vendor & Technical Programs 4pp 15713 150
- --8210150540 Ack receipt of Bili23 & 820111 ltms in response to GA Program into Rept 97900759/81-01 lnfo re corrective action measures required within 25 days PDTAPQUS.U Division of Vendor & Technical Programs 82/05/06 SUNDSTEDT.J E Woodward Governor Co ip 15713 156
- --8210190544 Supplemental response to violations noted in QA Program Insp Rept 97900759/01-01 Corrective actions second Complete investigation results search conducted to verify original results Ltrs to customers encl VEITCH, J L Woodward Opvernor Co 82/01/11 POTAPOVS, U Vendor Inspection Branch 51pp 15713 157
- 8210170369 Ack receipt of 820730 ltr informing NRC of steps taken to correct nonconformances noted in QA Program Insp Rept 97900769/82-02 POTAPOVS.U Division of Vendor & Technical Programs 82/10/14 HESS.L R Pacific Air Products Co tp 15741 133
- --B210190372 Responds to NRC B20823 ltr re nonconformances noted in GA Program Insp Rept 99900767/82-02 Corrective actions calibr date labels on micrometers talipers & Porta-Lab replaced & GC insp implemented to inspect/replace labels Audits enci HCSS.L R. CONLON.E T Pacific Air Products Co 82/09/30 POTAPDVS.U Division of Vendor & Technical Programs 20pp 15741 174
- 8210190725 Forwards QA Program Insp Rept 99900902/82-06 on 820525-26, 0603-05 & 29-0701 No noncompliance noted POTAPOVS.U Division of Vendor & Technical Programs 82/10/01 SMITH.E W Hyle Laboratories 3pp 15737 114
- --8210170761 QA Program insp Rept 99900902/82-06 on 820325-26,0603-05 & 29-0701 No noncompliance noted Najor areas inspected first 24-h of LOCA/HELB environ qualification tests for Foxboro N-E 10 & Rosemount 1193 Series D pressure transmitters PHILLIPS H S. JCHNSON A R Division of Vendor & Technical Programs 82/09/20 11pp 15737 117
- 8210190756 Forwards OA Program Insp Rept 99900907/82-02 on 820621-22 No noncompliance noted POTAPOUS.V Division of Vendor & Technical Programs 82/09/27 EDELSTEIN.A National Testing Systems Jpp 15737 105
- --8210190766 QA Program Insp Rept 97900907/82-02 on 820621-22 No noncompliance noted Major areas inspected followup insp of allegations made against employee & initial testing of Dorg Warner modulating electrohydraulic valve operator AGEL J R. PHILLIES, H. S. Region 4. Office of Director 82/09/23 App 18737 (OB
- 8210220407 Responds to 820803 itr re Woodward Obvernor Co failure to adopt appropriate procedures, per 10CFR21 21(a) & failure to post procedures, per 10CFR21 & Dedication of governors falls on procuring party, per 10CFR21 & Programs 92/10/05 HORIARTY, J Colt Industries, Inc. 1p. 15778 297
- ~-8210220417 Discusses Woodward Covernor Co failure to comply w/10CFR21 6 posting requirement No further action will be taken unless advised by NRC MCREARTY.J M Colt Industries Inc 82/08/03 PDTAPDVB,U Division of Vendor & Technical Programs 3pp 13778 298
- 8210250121 Ack receipt of 820923 ltr informing NRC of steps taken to correct nonconformance noted GA Program Insp Rept 999000005/82-01 POTAPOVS,V Division of Vendor & Technical Programs 82/10/20 JACOBILM N Westinghouse Electric Corp 1p 15787 038
- ---8210250128 Responds to NRC 820902 ltr be nonconformance noted in GA Program Insp Rept 97900005/82-01 Corrective actions OC instruction revised to include instruction to area supervisors & procedure placed in assigned book RUSSO, H L Wastinghouse Electric Corp 82/09/23 PDTAPOVS, U Division of Vendor & Technical Programs 3pp 15787 039

- 8210250135 Ack receipt of 820924 ltr informing NRC of steps taken to correct nonconformance noted in GA Program Insp Rept 9900294/82-01
 POTAPOVS.U Division of Vendor & Technical Programs 82/10/20
 HOGUER.D.L. Westinghouse Electric Corp. 1p. 15787-007
- --8210250141 Responds to NRC 820817 ltr re nonconformance noted in QA Program Insp Rept 99900294/82-01 Corrective actions ltr sent to district sales afcs requesting copy of customer purchase order for any nuclear safety-related orders MCKEEVER:R F Westinghouse Electric Corp 82/09/24 POTAPOVS, U Division of Vendor & Technical Programs 3pp 15787 008
- 8210260126 Forwards GA Program Insp Rept 99900400/82-03 on 820817-18 & notice of nonconformance
 PDTAPDV8.U Division of Vendor & Technical Programs 82/10/05
 GUILBERT, D G Babcock & Milcox Co 2pp 15799 057
- ~-8210260127 Notice of nonconformance from insp on 820817-18 * Division of Vendor & Technical Programs 82/10/05 2pp 15797 059
- --8210260131 QA Program Insp Rept 99700400/82-03 on 820817-18
 Noncompliance noted error identified in hybrid computer
 program POWER TRAIN not processed per Procedure NPG-0903-13
 HALE.C J Division of Vendor & Technical Programs 82/09/27
 700 15799 061
- 8210269494 Forwards QA Program Insp Rept 99900003/82-02 on 820824-27 & notice of nonconformance POTAPGUS,U Division of Vendor & Technical Programs 82/10/12 LONG, J A General Electric Co 2pp 15805 116
- ~-8210260496 Notice of nonconformance from insp on 820824-27 • Division of Vendor & Technical Programs 82/10/12 2pp
- --8210260558 QA Program insp Rept 9990003/82-02 on 820824-27
 Noncompliance noted all purchase order requirements not
 verified purchased bulk chemicals not always examined upon
 delivery & hardness tester not calibr every 3 months
 MCNEILL-W M , BARNESI Division of Vendor & Technical Programs
 82/10/05 Bpp 15805 120
- RECOD REGULATORY GUIDES
- B210060009 Draft Reg Quide 1 XXX, Revision 3, "LER Sys"

 NRC No Detailed Affiliation Given B1/11/16 22pg 15731 215
- 8210050017 Forwards proposed response to Ballot N13 on proposed AHB1 Std N721.per draft Reg Guide OP 713-4, "Internal Dosimetry Stds for Tritium." for concurrence COOL.W Occupational Health Standards Brench 79/03/16 DRODSKY.A NRC - No Detailed Affiliation Olven 4pp 15612 332
- ---8210050020 Forwards "Quidelines for Bioassay Requirements for Tritium" to assist in development of licensing program, per draft Reg Quide OP 713-4

 ALEXANDER, R. & Occupational Health Standards Branch, (after 74)072-4

 see SSDH) 77/10/27 SINGER, B Radioisotopes Licensing Branch (Pre 790301) ip 15612-335
- --8210050026 Concurs w/NMSS position on proposed ANBI Btd, N721, "Internal Dosimetry Btds for Tritium," per draft Reg Guide GP 713-4 Considerable empirical data available to develop reg guide similar to branch position used by NMSS BRODSKY, A NRC No Detailed Affiliation Oliven 79/01/31 COOL, W Occupational Health Standards Branch 2pp 15612 344
- --8210050030 Forwards Environ Evaluation Branch comments on proposed ANG Std N721, "Internal Dosinstry Stds for Tritium" per draft Reg Ouide OP 713-4 Std suitable for implementation as reg guide DENTON-H R Office of Nuclear Reactor Regulation, Director 79/01/29 HIMDOUE/R Office of Standards Development, Director App 13612:346
- --8210050034 Comments on proposed ANSI Std N721, "Internal Dosimetry Std for Tritium," per draft Reg Guide OF 713-4 Document unacceptable as reg guide in present form because prof background required for comprehension CUNNINGHAH.R E Division of Fuel Cycle & Material Bafety 79/01/23 OGLER,K Division of Biting, Health & Bafeguards Standards Spp 13612 350

- --22ICO50039 Recommends affirmative ballot re proposed ANSI Std N721,
 Internal Dosimetry Stds for Tritium," per draft Reg Guide
 CP 713-4
 AFSEMAULY,F J Division of Safeguards, Fuel Cycle & Environmental
 Researth 79/01/18 GOLLER,K R Division of Siting, Health &
 Safeguards Standards ip 13612 353
- --E210050042 Requests technical review of encl proposed ANSI Std N721, *Internal Dosimetry Stds for Tritium" per draft Reg Guide OP 713-4 Recommendations for action on Ltr Ballot N13 requested by 77017 H/o encl GCLER.K R Division of Siting, Health & Safeguards Standards 78/12/27 DAVIS.J G Office of Inspection & Enforcement, Office of the Director DENTON.H R Office of Nuclear Reactor Regulation, Director DIRCKS.W J Office of Nuclear Material Safety & Safeguards. Director 2pp 15612 354
- EliQuOl12 Reg Guide 2 B.Revision 2, "Preparation of Environ Repts for U Nilss" • Office of Nuclear Regulatory Research, Director 82/10/31 49pp 15763 318
- Elicabolio Forwards proprietary & nonproprietary responses to Revision i to Res Ouide 1 92. "Combining Model Responses & Spatial Corponents in Seismic Response Analysis" to assist in fuel assistly analysis response withheld (ref 100FR2 790) ALEEF Prestinghouse Electric Corp NS-EPR-2658 82/09/17 EERINGER, C. NEYER, R.O. Core Performance Branch 2pp 15803 045
- -- \$210240351 Submits application for withholding proprietary response to Revision I to Reg Ouide 1 72, "Combining Model Responses & Systial Components in Seismic Response Analysis " Affidavit & nosproprietary response encl NIESEMANNR A Westinghouse Electric Corp AW-82-55 82/09/17 SERJEMER, C H Core Performance Branch 7pp 15803 047
- 62.0793247 Comments on draft Reg Guide QP 722-4, "Qualification for Patiation Safety Officer in Large-Scale Non-Fuel-Cycle Reference of Small hosp will be at disadvantage of 4 years adopted ALENJJ St Lukes Hosp Milwaukee, WI 82/09/28 BELL, J M NRC No Detaited Affiliation Oliven 2pp 15834 088

11200251 Comments on draft Reg Guide OP 722-4, "Qualification for Patistion Safety Officer in Large-Scale Non-Fuel-Cycle Prefaram " Guide should be more specific representate requiring expertise CCOM.S R Forbes Health Sys , East Suburban Health Center XI. 1916 PA 82/10/15 Docketing & Services Branch Ip 1553 125

RESEARCH AND TECHNICAL ASSISTANCE REPORTS

© 050504 "Quick Look Rept on Test of Intermediate Vessel V-8A-Tearing Blavier of Lou Upper-Sheif Matl"

(BY-MIR H , BOLT, B E , MERKLE, J O Oak Ridge National Laboratory

FIN B-0157 ORNL-/1887-4 82/08/25 Division of Engineering

Technology 20pp 19426 334

5:10:60425 "Quarterly Mgt Rept ORNL Programs for NRC Ofc of Nuclear Segistory Research." third quarter ICTIS.A L., BAYLOR.V B., HOMAN.F.J. Oak Ridge National Laboratory 82/39/01 Office of Nuclear Regulatory Research. Director 72pg 1555-308

- KINNO49 "SSC Development, Validation & Application, " & "Owneric Blant of Plant Modeling," monthly highlights for Aug 1982 9977.3 0 Brockhaven National Laboratory FIN A-3015 82/09/08 UMISA Y Sever Accident Assessment Branch 8pp 15637-348
- K 06032 "Actual Emission/Flaw Relationships for Inservice Mailtoning of Nuclear Pressure Vessels," monthly progress 11th for Nuclear Pressure Vessels," monthly progress 12th Flaw 11th Progress 12th Physics Actual Progress 12th Physics Progress 12th Progress 12th Physics Physics Progress 12th Physics Progress 12th Physics Physics Progress 12th Physics Physics
 - N2018 "Reactor Expert Sys for Diagnosis & Treatment of Nuclear Inter Accidents," presented to Natl Conference on Hifs(sal Intelligence, 820818-20 BDN: R E040, Inc. E00-M-09782 82/08/20 Office of Nuclear Quistory Research
 - 0130124 "Multimethods Approach to Bafety Parameter Display Valuation" Awth W . BLACKMAN, H B . QERTMAN, D I EQ&G. Inc EQG-M-11782 R019703 MRC ~ No Detailed Affiliation Given 7pp 15672 235

- E210120367 "Source Terms of Radionuclides in Shallow Land Burial Sites "PIETRZAK.R F , DAYAL.R Brookhaven National Laboratory BNL-NUREG-31834 82/10/05 NRC - No Detailed Affiliation Given 9pp 15690 213
- 8210120368 "Approximate Tolerance Intervals, Based on Max Likelihood Extimates " ATMOOD.C L EO&G. Inc EGG-M-11482 82/10/05 NRC - No Detailed Affiliation Given 22pp 15690 191
- 8210120390 "Stress Corrosion Cracking of PMR Steam Generator Tubing," monthly highlights for Aug 1982
 VAN RCOYEN, D. Broothaven National Laboratory FIN A-3208
 82/09/17 TABOADA, A. Office of Nuclear Regulatory Research, Director 5pp 15691 103
- 8210120397 "Safety Parameter Display Sys Progress Statement "
 MEYERJO R EQGO, Inc. HARMON,D.L. Combustion Engineering, Inc.
 LONG,A B Electric Power Research Institute EGO-M-04382
 B2/10/05 NRC No Detailed Affiliation Given IDpp. 15691 124
- 8210120400 "LWR Debris from Severe In-Pile Transient Tests " HODBINS.R R. COOK.B A. MASON.R E. EOKG. Inc. 82/10/05 NRC -No Detailed Application Given Sep. 15549: 137
- 82(0120420 "Investigation of Accident Induced Flow & Matl Transport in Nuclear Facilities," progress rept for Aug 1982 MARTIN,R A., OREGORY,H S. Los Alamos Scientific Laboratory FIN A-7029 G-6-507 (R673) 62(09/28 BERNSTEIN,S Transportation & Materials Risk Branch 6pp 15671 161
- S210120430 "Polynomial Regression for Tektroniz 4052 Computer" BHATIA:P E026, Inc FIN A-6043 E00-L071-9373 82/09/30 LANDRY:R P Experimental Programs Branch 92pp 156/71 067
- 8210120453 "Rept of Foreign Travel of AP Malinauskas to England. Austria & Cermany." foreign trip rept MALIMAUSKAS.A Oak Ridge National Laboratory FIN B-0127 GRNL/FTR-1365 82/07/09 MINDGUER B Office of Nuclear Regulatory Research, Director 2pp 15671 187
- 8210120455 "Stress Corrosion Cracking Calvanic Corrosion & Selectave Leaching Test Requirements for TiCode-12 High Level Waste Containers: " draft rept SIGKIND. B Brookhaven National Laboratory FIN A-3167 BNL-MUREO-31755 82/09/31 Office of Nuclear Material Safety & Safeguards Director 43pp 15671 210
- 8210120459 "Cravice Corrosion Data Requirements for TiCode-12 High Layel Maste Containers," draft rept LEE,B B Brookhayen National Laboratory FIN A-3164 BNL-NUREO-31775 82/08/31 Office of Nuclear Material Safety & Safeguards, Director 25pp 15671 253
- 82;0120460 "Hechanical Failure Mode Data Requirements for TiCode-12 High Level Maste Container Sys." draft rept SOD.P. BREWSTER.C. SCHWEITZER.D.O. Brookhaven National Laboratory FIN A-3164 BNL-NUREO-31774 82/08/31 Dffice of Nuclear Material Safety & Safeguards.Director 1700 15671 279
- 8210120463 "Statistical Margin to DNB Safety Analys LOFT" ATKINBON,S A EQ&O. Inc 82/10/05 Office of Research, Dire '-- '000' '44/-' ''
- 82101204co win...... Embrittlement Test Requirements for TiCode-12 High Level Waste Containers, daeft rept.
 JAIN.H Broothaven National Laboratory FIN A-3167
 BNL-NVREQ-31754 82/08/31 Office of Nuclear Material Safety & Safeguards, Director 34pp 15671,310
- 8210120630 "HTOR Bafety Program," monthly highlights for Aug 1982 SABTRE, C Brookhaven National Laboratory FIN A-3016 82/09/14 FOULDB, Q Diffice of Nuclear Regulatory Research, Director 4pp 18672, 360.
- 8210520649 "Thermal-Hydraulic LMFBR & LWS Safety Experiments."
 nonthly highlights for Aug 1982
 OINSBERG, T., GREENE, G.A. Broothaven National Laboratory FIN
 A-3024 82/08/31 CURTIS, R.T. Severe Accident Assessment Branch
 400. 15684 237
- 8210120453 "Rept of Foreign Travel of TS Kress to Neeting of CSNI Oroup of Experts on Nuclear Aerosols in Paris, France re Aerosol Release & Transport Program, "Foreign trip rept. KRESS.T S. Oak Ridge National Laboratory FIN 3-0121 ORNL/FTR-1371 82/09/15 BILBERG!M Division of Accident Evaluation Bpp 15672 279

- E210120654 "TRAC-BD1 Turbine Model for Code Development & Improvements" informal technical rept QILES:M M E0&G, Inc. FIN A-6052 EGG-CDD-6029 82/09/30 ODAR:F Office of Nuclear Regulatory Research. Director 47pp 15472 287
- 8210120657 "Advanced Display Concepts in Nuclear Control Rooms"
 CLARKIM T , BANKSIN W : BLACKHANIH S E060. Inc 82/10/05
 Office of Nuclear Regulatory Research. Director 11pp 15672 335
- 8210150409 Speech entitled. "Swaling Criteria & Assessment of Semiscale Mod-3 Scaling for Small Break Loss-of-Coolant Transfects." presented at NRC/ANS 820914-15 meeting on Basic Thermal Hydraulic Mechanisms in LWR Analysis in Bethesda, MD LARSON, T K , ANDERSON, J L , SHIMECK, D J E0&G, Inc EGG-M-21082 82/09/15 47pp 15716 001
- 8210150412 Speech entitled, "Power Burst Facility Severe Fuel Damage Test Program," presented at 820728-1001 Intl Topical Meeting on Irradiation Technology MCCARDELL.R K. MACDONALD.R & EG&G. Inc EGG-M-06682 82/10/01 19pp 15716 049
- 82(0150415 Speech entitled, "Manitoring PMR Reactor Vessel Liquid Level w/BPND Buring LOCAs:" presented at ANG 820722-24 meeting on Advances in Rejictor Physics & Core Thermal Hydraulics ADANS, J P EG&O, Inc EGG-N-14082 82/09/24 15pg 15716 068
- B2[015042] "Natural Circulation in Experimental Facility Scaled from PWR" LOUMIS G G EG&G, Inc SDDA.K Japan Atomic Energy Research Inst B2/10/12 NRC - No Detailed Affiliation Given App 15714 084
- 8210150611 "Dest Estimate Prediction for LOFT Experiment Series L6-8C," interim rept CONDIE.K Q EG&G. Inc FIN A-6048 EGQ-LOFT-5982 82/08/31 MCPHERSON.G D Integral Systems Section 48pp 15717 017
- 8210150625 "LOFT Experiment Operating Spec.LOFT Anticipated Transient Series L6 Nuclear Experiment L6-6," Interim rept Document Revision Requests L-4953 & L-4954 encl SILVERHAN.8 EQ&O. Inc FIN A-6048 EQ&-LQFT-5733 92/07/21 MCPHERSON, Q D Office of Nuclear Regulatory Research. Director 63pp 15717 114
- 82:0150631 "Eram of Health Effects Associated W/Unit Radionuclide Releases to Surface Environ " HELTON: J Arizona State Univ « Sandia Laboratories FIN A-1165 SANDG2-8855 B1/12/31 Division of Waste Management 85pp
- 8210180497 "ORNL Programs for Ofc of Nuclear Regulatory Research," Jul 1982 monthly highlights LOTTS,A L , BAYLOR,V B , HOMAN,F J Dak Ridge National Laboratory 82/09/25 Office of Nuclear Regulatory Research, Director 96pp 15746 019
- 8210200102 "Fiber Optic Void Fraction Heasurement Sys for Steam Generator in LOFT" SNYDERS C EGMG, Inc FIN A-6043 EGG-tOFT-5997 82/09/30 LANDRY R Division of Accident Evaluation 20pp 15767 283
- 8210270421 "Accident Aerosol Characterization," quarterly rept for Jul-Sept 1982 OMCZARSKI, P C Battelle Memorial Institute, Pacific Northwest Laboratory F(N 8-2287 82/10/13 BEANSTEIN,8 Transportation & Materials Risk Branch 18pp 15833 332
 - "Preliminary Two-Phase Instrumentation Evaluations" status
 - 3 R E0&0, Inc. FIN A-6376 E00-ID-6040 82/09/30 N Instrumentation & Control Branch 23pp 15859 013

or Aug 1982," interim rept PG-LOFT-4039 82/09/30 72pp 15892 299 8210270377 "Network Flow & Transport/Distributed Valocity Methods, Self-Teaching Curriculum" FINLEY,N C Sandia Laboratories LONGSINE,D E Disewood Corp CAMPBELL,J E INTERA Environmental Consultants,Inc FIN A-1158 SANDB1-0

REVIEW GRP NRC RESEARCH REVIEW GROUPS

- 8210010286 Concurs that NUREO-0744. "Resolution of Reactor Vesse)
 Matis Toughness Safety Issue," need not be reviewed by
 CRCR
 STELLD.V Regional Operations & Generic Requirements 82/09/30
 DENTON.H R Office of Nuclear Reactor Regulation, Director 1p
 15373 181
- 8210040314 Summary of CROR Meeting 19 on 820915 re cost/benefit study of design requirements for inadequate core cooling instrumentation & open technical issues from CROR Meeting 11 on 820324
 STELLO.V Regional Operations & Generic Requirements 82/09/22
 DIRCKS.W J Office of the Executive Director for Operations opp
- 6210080109 Notification of 821008 CRGR Meeting 22 in Bethesda, MD to consider proposed bulletin re stress corrosion cracking as Category I requirement under provision of III-D of CRGR charter Attendance should be limited to senior staff STELLO, V Regional Operations & Generic Requirements B2/10/07 EISENHUT, D G Division of Licensing JORDAN, E L Director's Office, Office of Inspection and Enforcement CUNNINGHAM, R Office of Nuclear Material Safety & Safeguards, Director ip 15640 021
- 8210120049 Forwards response to 820819 memo re standby shutdown racilities Postulated SBE could cause failure of condenser circulating sys Util seismic criteria permits auxiliary syc water sys backup
 DENTON: HR Office of Nuclear Reactor Regulation, Director
 82/09/23 STELLO, V Regional Operations & Generic Requirements
 4pg 15689 207
- --8210120053 Requests briefing re standby shutdown facility design requirement changes, focusing on integration of NRC bacifit efforts Briefing requested at 820708 CRQR meeting STELLO.V Regional Operations & Generic Requirements 82/08/19 DENTON-H R Office of Nuclear Reactor Regulation, Director 2pg 15889 218
- 9210120216 Forwards summary rept of CROR activaties for 920929-1001 SCHWINK,W Regional Operations & Generic Requirements 92/10/00 Regional Operations & Generic Requirements 6pp 19692 144
- 8210120326 Forwards 820713 ltr documenting 820623 meeting between Licensing Review Group 1 & NRR BDYD,R 8 KMC. Inc 82/10/06 THOMAS.C 0 Standardization & Special Projects Branch 19. 15652 333
- --8210120331 Forwards summary of 820623 meeting w/Licensing Review Ordup 1 Tech Spec Group & NRR in Bethesda. MD STS issues, proposed mode & justification encl BOYD, R S KMC, Inc. 82/07/13 TEDESCO, R & Assistant Director for Licensing 52pp 15652 334
- 8210150138 Summary of CRGR Meeting 20 on 820921 re proposed resolution of reactor coolant pump trip issue & BWR pipe cracking issue
 STELLO, V Committee to Review Generic Requirements 82/10/05
 DIRCKS, W J Office of the Executive Director for Operations App
- 8210180002 Requests attendance at CRGR Meeting 23 on 821028 in Sethesda, MD to discuss cost/benefit info for alternatives for resolving pressurited thermal shock issue STELLO, V Committee to Review Generic Requirements 82/10/14 EISENHUT, D Q Division of Licensing JORDAN, EL Division of Engineering & Quality Assurance CUNNINGHAM, R E Office of Nuclear Material Bafety & Bafeguards, Director ip 15718 024
- 8210190006 Notifies of CRGR Meeting 20 on 820921 to discuss proposed resolution of reactor coolant pump trip issue & proposed bulletin to address BMR pipe cracking STELLO, V. Regional Operations & Generic Requirements 82/09/20 EISENHUT, D. O. Office of Nuclear Reactor Regulation, Director, UCRDAN, E. L. Director's Office, Office of Inspection and Enforcement MAUSSHARDT, D. R. Office of Nuclear Material Safety & Safeguards, Director 50pp 15760:240

- ELIPOOP2 Designates R Purple as NRR co-chair of Safety/Safeguards fined Committee Comprehensive re-evaluation of safety/Safeguards program should consider human factors elegants SENDM.H R Office of Nuclear Reactor Regulation, Director 22.77/30 DAVIS.J 9 Office of Nuclear Material Safety & Safeguards Director 4pp 15761 115
- -Rill190075 Responds to encl Commission 820816 memo & forwards draft
 Safety/Safequards Review Committee charter, describing
 17050846 committee responsibilities
 8.67ETT.R F Division of Safeguards 82/07/14 STELLO, V

proposed committee responsibilities

EMMITIRE Division of Safeguards 82/07/14 BIELLO,V

EMMITIRE Division of Safeguards 82/07/14 BIELLO,V

Figuonal Operations & General Requirements DENTON, H R Office of

Nuclear Reactor Regulation, Director MINDOUC, R Office of

Nuclear Regulatory Research, Director 2pp 15761 119

- 11:10:118 Responds to 820805 itr rs unresolved issues from 820415 itr rs inadequate requirements developed per TMI Item I D I suspension of responsibility for human factors within NRC & crept of operator integrity addressed (EATOM.H.C. Office of Nuclear Reactor Regulation, Director 82:29/16 SHEEHY.E. J. Affiliation Unknown 29pp 15758 207
- Siturcal Forwards long-range CROR agenda for Oct 1982-Sept 1983 Mods for signal items not reflecting current status should be arranded to H Schwink by 831101 Listed info for new items for consideration of 820616 CROR charter requested STELLOV Committee to Review Generic Requirements 82/10/18 EDMITA MINDOUELR B NRC No Detailed Affiliation Given CRUNHAR Office of Nuclear Reactor Regulation, Director 12pp 17740 013
- at 2350131 Notifies of CROR meeting on 821103 in Bethesda, HD Requests at firstors limit attendance to senior staff needed to adjess agends items STELO.Y Regional Operations & Generic Requirements 82/10/20 (TEOMILD O Division of Licensing 29p 15787 114
- E. 250155 Notification of CRGR 821110 25th meeting in Bethesde, MD to district proposed revision to 10CFR20 on stds for protection against radiation, proposed amend to 10CFR20 or eradiation programs & Unresolved Safety Issue A-42 ftt.0.9 Regional Operations & Generic Requirements 82/10/22 ftt.0.9 Office of Nuclear Reactor Regulation, Director SCHANE t. Birector's Office Office of Inspection and Enforcement DANINHAME RE Office of Nuclear Material Safety & Safetyards, Director ip 15788 288
- E.M70199 Summary of CRGR 22nd meeting on 821008 re proposed IR Littin. "Stress Corrosion Cracking in Thick-Wall Large Illates Stainless Steel Recirculation Sys Piping at BWR Flists t reactor coolant pump criteria for PWRs "RLD.V Regional Operations & Generic Requirements IEB-79-05C EVIC/20 DIRCKS: U. Office of the Executive Director for Circulation opp 15822 357.
- E::::003HB Comments on summary of CROR Meeting 21 on 821006 re proposed princing criteria for vessel ref temp NDT Figure provides Ingitylinal crack extension frequencies for mean surface start than computed mean plus 2 sigma SIMTO. F NRC No Detailed Affiliation Given 82/10/26 ELLOV Regional Operations & Generic Requirements 1p 1937-043
 - SiD:805i Summary of CROR Meeting 21 on 821006 in Bethesda, MD List of attackes encl sELID. Regional Operations & Generic Requirements 82/10/20 MKGS.W J Office of the Executive Director for Operations App 1869 044

EY POSITION PAPERS BEFORE THE COMMISSION

2320435 SECY-82-186
hitlist Commission of current status of makeup nozzle
hitlist Commission BAM plants Problem under evaluation
hideatri have established task group to oversee followup
sitiss Group will meet w/NRC in early May 1982
18(35) U Office of the Executive Director for Operations
82(65)01 6pp 15597.082.

F420812 SECY-82-267
Graiders postgoning work on comprehensive fire protection than far nuclear power plants. Recommends Commission redirect staff is prepare comprehensive fire protection rule for new return power plants by June 1984.

ALKEN J. Office of the Executive Director for Operations R/M/21 App 15636 033.

8210040360 Responds to FDIA request for SECY-82-728 & SECY-82-720 re coordinated program for steam generators Documents available in PDR FELTON.J M Division of Rules and Records 82/09/27 FORTING, K C Lowenstein, Newman, Reis, Azelrad & Toll 1p 15597 291

--8204200390 SECY-82-072B
Responds to Chairman 620301 request for short-term actions re performance of steam generators Comprehensive water chemistry criteria for steam generators should be implemented
DIRCKS.W J Dffice of the Elecutive Director for Operations 62/04/03 2pp 15597 292

--8205270507 SECY-82-072C
Advises Commission of results of 820428 meeting w/sndustry re-proposed coordinated program for steam generators Proposal in SECY-82-72A re-formal structural organization such as policy group & steering committee rejected DIRCKS, W J Office of the Executive Director for Operations 82/03/17 3pp 15597 294

82:0190144 Responds to FOIA request for SECY 82-232 re use of nonplant-specific simulators for initial replacement & requalification exams for licensed reactor operators & senior operators
FELTON.J M Division of Rules and Records 62/09/30 ARMSTRONG,K A Debevoise & Liberman 2pp 15760 178

--8206180042 SECY-82-232
Recommends requirements of simulator licensing exam be continued for power reactors w/plant-specific simulator Oral exam per 10CFR55 23 should be administered where facility has no plant-specific simulator DIRCKB.W J Office of the Executive Director for Operations 82/06/07 14pp 16002 236

9210220534 SECY-82-399
Informs Commission of status of "Nuclear Standardization Act of 1982" & proposed plan for 1983 legislative proposals TOURTELLOTTE, J. Regulatory Reform Task Force 82/09/30 28pp 15784 049

8210270083 Add1 response to FOIA request for eight categories of LERs Forwards documents listed in App A App B documents withheld (ref FOIA Exemption 5) FELTON.J M Division of Rules and Records 82/09/20 ARNOLD.J Miami Nerald 4pp 15836 221

--8204300098 GECY-82-142
Requests approval of draft Rept to Congress on AD
(MUREO-0090) for Det-Dec 1981
DIRCKS,W J Office of the Elecutive Director for Operations
82/04/02 40pp 15836 225

8210270322 SECY-82-407
Advises of issues remaining from 820108 meeting reinstrumentation for detaction of inadequate core cooling in PHRs Requests action on update recommendations for implementation of NUREO-0737. Item [I F 2] DIRCKB.H J. Office of the Executive Director for Operations 82/10/07 12pp 15851 323

B210290393 Transcript of B20929 public meeting on SECY-B2-352 re QA in Washington. DC. Pp 1-85 Marked-up SECY-B2-352 encl PALLADING.N., OILINSKY.V. AHEARNE.J Commissioners B2/09/29 146pp 15865 268

STATE PROD STATE PROGRAMS

8210010016 Comments on state actions outlined in 820617 & 09 ltrs re NRC recommendations on State of KY radiation control program Program adequate to protect public health & safety NRC should be kept informed of staff augmentation O'REILLY.J P Region 2: Office of Director 82/08/13 BTUHOD.W G Kentucky, State of 2pp. 13565 160

B21001004B Forwards rept of NRC 1982 review of State of TN radiation control program for agreement matts Program adequate to protect public health & safety Physicists should receive specific radiation safety control training.

HODDRUFF.R.L. Region 2: Office of Director. B2/09/13
FOWINKLE.E W Tennesses, State of 106pp 15565 010

821001010D Responds to 820609 ltr re NRC review of State of KY radiation control program NRC comments re review of selected licensee files encl Licensing comments minor. Rept not yet completed.

MODRUFF, R L Region 2, Office of Director. 82/08/13 HUGHES, D Kentucky, State of 12pp 15555.243

- 8210010154 Forwards rept & evaluation of State of MS radiation control program for 800426-810911 Program adequate to protect public health & safety MDDRMFF,R L Region 2, Office of Director 82/09/08 COSB,A B Mississippi, State of 72pp 15568 140
- 82(0010358 Forwards "Rept & Evaluation of GA Radiation Control Program for Period Juli 15,1980 to Nov 25,1981." twelfth regulatory review program MODRMFF,R L. Region 2, Office of Director 82/09/10 LEDBETTER.J G. Georgia, State of 1p 15574 160
- --8210010363 "Rept & Evaluation of GA Radiation Control Program for Period Jul 15,1980 to Nov 25,1981," twelfth regulatory review program + NRC -- No Detailed Affiliation Given 82/09/10 129pp 15574 161
- 8210120015 Partial response to FOIA request for documents re St Joseph Hosp in Albuquerque, NM & I-125 seed incident Forwards documents listed in App A FELTON, JM Division of Rules and Records 82/08/20 DAVIES, L S Richards, Grandt, Miller & Nelson 3pp 15691 173
- --8012180362 PNA-80-037 on 801201. State of NM informed NRC of oversiposures of patients receiving 1-125 seed therapy for treatment of prostate cancer Causedby computer dose conversion factor error State request hosp rept LUBENAU. J O Office of State Programs. Director 80/12/02 ip 15591 176
- --8210120023 Requests assistance in independent technical review of encirent from St Joseph Hosp re misadministration of [-125 seed implant Ltr delineabing info required & article from Albuquerque Journal enct M/o encl HOLFF.T A New Mexico. State of 81/02/03 NUSSHAUMER.D A Assistant Director for State Agreements Programs ip 15691 192
- --B210120027 Forwards rept to St Joseph Hosp, Albuquerque, NH remisadministration of I-125 seed implant Event attributed to personnel error & lack of communication between computer plan developers & users Comments requested by 810227 NUSSBAUMER, D. A. Assistant Director for State Agreements Programs B2/02/23 MIOGINBOTHAM, L. Radiological Bafety Branch CUNNINGHAM, R. E. Advanced Fuel & Spent Fuel Licensing Branch Jp 15591 193
- --8210120057 Forwards WR Hendee review of selected matls remisadministration of I-125 seeds at St Joseph Hosp.
 Albuquerque W/O encil
 NUSSBAUMER, D. A. Assistant Director for State Agreements Programs
 81/03/25 HIQGENBUTHAM, L. Radiological Safety Branch
 RILLER, V. L. Licensing Management Branch ip 15591 289
- --8210120075 Forwards State of NM rept re investigation of incident involving overexposure of patients treated w/I-125 seeds AD rept will be included in next quarterly rept W/o encl NUSSBAUMER. D. A. Assistant Director for State Agreements Programs 81/Ji/24 CUNNINGHAM. R. E. Advanced Fuel & Spont Fuel Licensing Branch ip 19692-040
- 82/0130152 Discusses insp of Western Industrial X-Ray at Hunters Point Naval Shipyard on 820922 Two violations of DDT regulations, 49CFR[72, re placarding of transportation vehicle observed State of CA consideration of enforcement action requested BOOK, H & Division of Radiological Safety & Safeguards Program 82/10/08 HONEY, D California, State of 2pp 15673 080
- 8210190530 Forwards results of insp of Model Ce-30 gauge mfg by Industrial Gauging & Control CAMPBELL, M A Region 1. Office of Director 82/10/12 CORCORAH, R G Maryland, State of 1p 15751 250
- --8210190533 Responds to 820806 request for insp of general licenses cility to obtain info re C-Frame type gauge mfg by dustrial Gauging & Control ENIAMBKI, D J Region 3. Office of Director 82/09/20
- 8210270393 Notification of contract execution, Mod 3 to "Environ Monitoring Program w/State of NC " Contractor State of NC WOLLETT'S Research Contracts Branch Fin 8-1239 NRC-03-80-1222

- --8210270395 Mod 3, changing name of NRC billing ofc & address for submission of invoices to "Environ Monitoring Program W/State of NC " « North Carolina, State of GUSTAVE, R P Research Contracts Branch FIN 8-1239 NRC-05-80-283 82/10/12 ip 15833 361
- 8210280386 Notification of contract execution. Mod 1 to "Establish Collaborative Program Between State & Commission to Provide Independent Measurements of Radioactivity in Effluents & Environ "Contractor CT Dept of Environ Protection SILVIS.R M Administrative Contracts Branch NRC-05-73-011 82/10/15 COBB.L I , ROSE, H Director's Office of Inspection and Enforcement ip 15859 236
- ---BR102B0397 Mod 1.deobligating funds, to "Establish Collaborative Program Between State & Commission to Provide Independent Massvements of Radioactivity in Effluents & Environ Around Selected Commissioned Licensed Activities " HEUDNER:A T Connecticut, State of OUSTAVE, R P Contracts Branch NRC-05-73-011 82/10/15 1p 15859 237
- 8210290085 Responds to FDIA request for lists of names & addresses of all NRC licensess in ME.VT.MA.DH.CT & HV & appropriate ofcs in Agreement States of NH.RI.NY & MD Forwards requested lists
 FELTON, J M Division of Rules and Records 82/10/15
 PARKINSON, T W Interstate Nuclear Services 1p 15863 311
- --B210290090 Lists of active licenses for States of MA.VT.ME.CT.OH & WV & Agreement States as of 820910 & NRC No Detailed Affiliation Given B2/10/07 240pp 15863 312
- TOPREP VENDOR REPORTS AND RELATED CORRESPONDENCE
- 8207070009 Forwards response to NRC B20923 questions on BAW-10143P, "Statistical Core Design Applied to Bebcock 205 Core," including proprietary response to Question 20 & microfiche records of computer runs associated w/listed questions TAYLOR, J H Babcock & Wilcor CO 82/08/25 BEROGREN, J B Standardization & Special Projects Dranch 23pp 14754 037
- 82:00:0008 Responds to FOIA request for 19 categories of documents re nuclear reactor events & safety problems Forwards documents listed in App A FELTON, J H Division of Rules and Records 82/06/28 UDELL,R A Critical Mass Energy Project 15pp 15727 005 24X Ficha 50-000,82/06/28,8210010008
- --8210050514 Topical rept evaluations of Revision 2 to WCAP-9558, "Mechanistic Fracture Evaluation of Reactor Coolant Pipe " & WCAP-9787, "Tensil & Toughness Properties of Primary Piping Weld Metal for Use in " + NRC No Detailed Affiliation Given 82/06/28 26pp 15731:005
- B210010217 Forwards "Mark I Dwners Group Response to Humphrey Containment Concerns," per 820715 request SHERHIODD, O General Electric Co MFN 138-82 82/09/24 EIBENHUT, D O Division of Licensing 2pp 15567 351
- ~-8210010224 NSEO-88-0982

 "Mark I Owners Group Response to Humphrey Containment
 Concerns "
 BILLIO,P F , ROGERS,A E General Electric Co T23-00452
 82/09/30 28pg 19547 353
- 8210010351 Forwards proprietary NEDE-22232, "Shutdown of Reactor Power w/Boron Injection" Rept withheld GRAVES, C C Reactor Systems Branch 82/09/16 DIAMOND, D Brookhaven National Laboratory, ip 15573,124
- 8210040229 Forwards XN-NF-507(P), "Exxon Nuclear Co Betpoint Methodology for C-E Reactors - Statistical Setpoint Methodology, Suppl 1 " Rept withheld (ref 10CFR2 790) BMSLEY.O F Exan Nuclear Co , Inc (subs of Exxon Corp) GFO 077 82 82/09/29 THOMAB,C O Standardization & Special Projects Branch 4pp 15595 358
- 8210040275 Forwards complaint & amended complaint re law suit filed by ML Williams per BF Williams death allegedly caused by radiation exposure during employment from 1958 to Oct 1980 HARWARD, J. E. American Nuclear Insurers, 82/09/13 GALTZMAN, J. Assistant Director for State & Licensee Relations 14pp 15587 135
- 8210040311 Forwards Revision 4 to SCP-D1-A, "RADCAL Gamma Thermometers as Local Power Measuring Devices for Use in Cores of PWRs."

 per NUREO-0390

 MARINO.J.P. Beandpower.inc 82/09/29, BERNARD.H Standardization ;

 & Special Projects Branch ip 15586-198.

- --22:CO40319 SCP-01-A R04

 Revision 4 to "RADCAL Gamma Thermometers as Local Fuel
 Power Heasuring Devices for Use in Cores of PHRs "
 Power Heasuring 182/02/28 291pp 15586 200
- FILC:40323 Forwards nonproprietary & proprietary versions of Suppl 3 to Figical Rapt CEN-185, "Heated Junction Thermocouple Phase III Task Rept "Proprietary version withheld Itel 10CFP2 7901

 REALINAY P C-E Operating Plants Owners Group DABKINAK P Starkers of the California Edison Co 82/09/30 BERNARD, H Starkers Lational Edison Co 82/09/30 SERNARD, H Starkers of Special Projects Branch 7pp 15611 304
- EIDH0394 Forwards request for addl info re NNI-BI-6(P), "Waste Silvelfication & Packaging Sys "
 THEMAS.C.O. Standardization & Special Projects Branch 82/09/08
 ESSEMAN, R. Newport News Industrial Corp (subs of Newport News Stipbuilding) 8pp 15597 218
- -:10350053 Requests meeting w/NRC to present status of BWR owners group interest program on pipe cracking Most favorable date is E21015 Proposed agenda encl.

 AARELLEE BWR Duners Group HARWELL, EF Tennessee Valley Libertly 82/09/29 VOLLMER, R H Division of Engineering 3pp 1503.185
- ELECTION Forwards revised organization chart for Div of Nuclear Power as described in TVA-TR75-1A. "GA Program Description for Issign. Censt & Operation of TVA Nuclear Plants "
 HILLS, L. H. Tennesses Valley Authority 82/09/29 HAABS, W.P. Telity Assurance Branch ip 19605-199
- t. NAO152 Forwards Steam Generator owners group comments on draft steam generator generic requirements discussed during 620729 resting STANDT, A D Steam Generator Owners Group SCHMIDT, A D Florida Fiver & Light Co 62/09/30 EISENHUT, D G Division of Licensing Rep 15603 244
- 1:0:50255 Forwards proprietary & nonproprietary versions of AECC-2-NP 1F 'Refueste Vol Reduction Sys.Amend I," in response to NRC 9:110 & 820428 requests for add1 info Proprietary version withing inef 10cFR2 7901 (ACLIA, R. Aerojet Energy Conversion Co (subs of General Tire & 1.11tr Co) 8:00 2891 RG RR 82/10/01 THOMAB.C Standardization 6 Special Projects Branch [p 15615 109
- -- C210050257 Affidavit of SP Ferreira requesting withholding of AECC-2-P, fladuste Vol Reduction Sys, " from public disclosure tref IOCFR2.790), FEREIRA B P Aerojet Energy Conversion Co (subs of General Yire FRubber Co) 82/09/29 App 15615 111
- -:210050259 AECC-2-NP AOI
 h.sproprietary version "Radwaste Vol Reduction Sys-Amend 1 "
 Aerojet Energy Conversion Co (subs of General Tire & Rubber
 to 8 82/10/01 72pp 15415 115
- EIMAGN46 Forwards BAM-10153P, "Extended-Burnup Evaluation, "Rept will truled to support util customer OL applications for fuel lattle everage burnups up to 45,000 mMd/mtU Rept withheld in FIGURE 790).

 TAMORJ H Babcock & Wilcox Co 82/09/30. BERGOREN, J. B Stanfardication & Special Projects Branch Spp 15615 100
- EIMORONA Advises that proprietary WCAP-9863(P), "Rod Bank Worth Faster Nachts Utilizing Bank Exchange," contains info of incern to NRC Resolution of concern needed to proceed white NRC viewpoint withheld FURANCE Standardization & Special Projects Branch 82/09/06 6AMEEP Nestinghouse Electric Corp. ip 15628 081
- 20060038 MCAP-7870 Intrif from "Neutron Shielding Pads " : destinghouse Electric Corp. 72/05/31 4pp 15669 242

- 8210080138 Forwards "Potential for Water Hammer During Restart of RHR Pumps for BMR Nuclear Plants " HUANO.Y 8 Director's Office AEOD/E105 81/03/31 MICHELSON.C Director's Office ip 15663 295
- --8210080165 "Potential for Water Hammer During Restart of RHR Pumps for BHR Nuclear Plants " HUANO.J Director's Office AEOD/E105 81/03/31 14pp 13563 256
- 8210080169 Forwards "Initial Consideration of Potential for Hater Hammer in Steam Condensing Mode of RHR Sys Operation for BUR Plants " HUANO, Y S Director's Office AEOD/E106 81/03/31 MICHELBON. C Director's Office 1p 15663 271
- --8210080172 "Initial Consideration of Potential for Hater Hammer in Steam Condensing Mode of RHR Sys Operation for BWR Nuclear Plants " HUANG.J Director's Office AEOD/E106 81/03/31 11pp 13648 272
- 82:0080229 Forwards proprietary response to EGMO questions/comments re seismic aspects of equipment qualification program & "Beismic Analysis of Safety Injectson Motors for Byron Nuclear Stations 1 & 2 & Draidwood Nuclear Stations 1 & 2 " RAHE, E P Westinghouse Electric Corp NB-EPR-2667 82/10/05 ROSZTOCZY, Z Equipment Qualification Branch 1p 15438 007
- 8210080262 Forwards slide presentation w/summary of 820917 meeting in Bathasda, MD re Intergranutar Stress Corrosion Cracking Progress Rept 8 Encl withheld (ref 100FR2 790) ORIDLEY, R L General Electric Co MFN-141-82 82/09/30 JBHNSTON, W V Assistant Director for Materials & Gualifications Engineering 6pp 15638 COI
- 9210080269 Recommends OE &/or affected BWR licensees be requested to submit & commit to sthedule for replacement of all hold down beams W/improved design Potential for water hammer type loads on jet gump integrity should be evaluated MICHELSON,C Director's Office AEOD/EOO2 80/05/23 DENTON,H R DFfice of Nuclear Reactor Regulation, Director 4pp 15667-270
- B2100B0294 Forwards "Review of Emergency Response Guidelines Re Pressurized Thermal Shock" KINOBLEY.O D Hestinghouse Operating Plants Owners Group KINOBLEY.O D Alabama Power Co 00-72 B2/06/22 DENTON.H R Office of Nuclear Reactor Regulation, Director ip 15639 208
- --B210080297 "Review of Emergency Response Guidelines Re Pressurised Thermal Bhock " # Hestinghouse Electric Corp 82/06/30 86pp 15638 209
- 8210150173 Forwards nonproprietary "Combined Seismac-LOCA Mechanical Evaluation for Exam Nuclear 15x15 Reload Fuel for Hestinghouse PMRs" OHBLEY, O.F. Exam Nuclear Co., inc. (subs. of Exam Corp.) OFO 082 82 82/10/08 THOMAS, C.O. Standardization & Special Projects Branch ip 15706 361
- --B210150182 XN-NF-76-47(NP)(A)
 Nonproprietary "Combined Seismic-LGCA Mechanical Evaluation
 for Exxon Nuclear 15x15 Reload Fuel for Westinghouse PWRs "
 # Exxon Nuclear Co . Inc (subs of Exxon Corp) 82/10/04
 176pp 15707 001
- 8210150416 Forwards proprietary responses to NRC 820708 request for add1 info, Questions 1-5 re NEDE-23785-1(P). "GESTR-LOCA & SAFER Models for Evaluation of LOCA" Responses withheld (ref 10CFR2 790)

 GUJRK-J F General Electric Co MFN-144-82 82/10/07 THOMAS, C O Standarfization & Special Projects Branch 19 19715 283
- 8210150445 Summarite: 820802 meeting w/NRC re planned dynamic testing of BHR 4/5 HPCI turbins Mods to original HPCI seismic qualification test extremely conservative Viewgraphs and QUIRK, JF General Electric Co MFN-146-82 82/10/07 JCHNSTON W. V Assistant Director for Materials & Qualifications Engineering Epp. 15703 156
- 8210150461 Forwards slide presentation used at 820929 meeting w/NRC to discuss QE environ qualification program as defined in NEDE-24026-P Info withheld QUIRK, J F. Quareal Electric Co MFN-145-B2 82/10/07 JOHNSTON-W V Division of Engineering 2pp 15715-279
- 8210150511 Forwards XN-NF-80-19(P), "Exxon Nuclear Methodology for BMR4 Application of ENC Methodology to BMR Reloads," Vol 4 Rept withheld (ref 100FR2 790) CHANDLER, J C. Exxon Nuclear Co., Inc. (subs. of Exxon Corp.) JCC.098,82 82/10/13 THOMAS, C.D. Standardization & Special Projects Branch Ip. 15715.162

- 6210150656 Notification of 821005 branch meeting in Bethesda.MD to discuss STS for rod position indication TAM.P S Operating Reactors Branch I 82/09/28 VARGA.S A Operating Reactors Branch I fp 15715-310
- 8210150681 Discusses review of Licensing Topical Rept XN-NF-77-57
 "Exton Nuclear Power Distribution Control for PMR Phase II"
 Rept acceptable for referencing in Westinghouse-designed
 reactor reload license applications
 THOMAS, C. G. Standardization & Special Projects Branch 82/09/24
 OMSLEY, O. F. Exxon Nuclear Co., Inc. (subs. of Exxon Corp.) 2pp
- B210180023 Forwards request for additinfo needed to review Topical Rept CENPD-266(P), "ROCS & DIT Computer Code for Nuclear Design " THOMAS.C O Standardization & Special Projects Grench B2/09/15 SCHERER,A E Combustion Engineering, Inc. 4pp 15721 265
- B210180050 Forwards NEDE-24602, "Mark I Containment Program Cumulative Distribution Functions for Typical Dynamic Responses of Mark I Torus & Attached Piping Sys." per NRC 820909 request Pept withheld Preference Co. PFN-147-82 B2/10/07 VASSALLO, D.B. Gereating Reactors Branch 2 9pp 15720 016
- B210190607 Submits add1 info per B21014 discussion w/G Laines re review of Dresser safety valve performance observed in EPRI safety trailef valve test program Valves consistently achieved rated steam flow RAHELE P Westinghouse Electric Corp NS-EPR-2669 B2/10/15 EISENNUT.D 0 Division of Licensing 3pp 15739 334
- 8210190755 Forwards comments on NRC proposed steam generator requirements distributed at 820727 meeting w/NRC & industry representatives in Dethesda.MD MILLS.L M Tennessee Valley Authority 82/10/13 DENTON.H R Office of Nuclear Reactor Regulation, Director 4pp 15737 100
- B210190810 Forwards proprietary slide presentation entitled. "GE BWR Fuel Performance" from NRC/GE 820708 meeting in San Jose, CA Slides not properly labeled proprietary Slides withheld (ref 10CFR2 790) CHARNLEY. J General Electric Co JSC-017-B2 82/10/12 BERLINER, C H Core Performance Branch 1p 15736-317
- 8210200113 Notification of 821015 meeting w/BMR owners group & EPR1 in BethesdarMD to discuss status of research on pipe cracking in BMRs & questions raised at 820927 meeting w/BWR licensees CLARK,D Operating Reactors Branch 2 82/10/13 VASSALLO,D B Operating Reactors Branch 2 3pp 15767 320
- 8210210329 Forwards proposed proprietary Revision 3 to Topical Rept ERR-1(P)-A. "Ederers Nuclear Safety-Related Extra-Safety & Monitoring (X-SAM) Cranes "Rept withheld (ref 10CFR2 790) CLARK,C W Ederer. Inc 82/10/08 THOMAS.C Standardization & Special Projects Branch 2pp 15765 294
- G210220152 Notifies of organization re restructuring within Water Reactor Div effective 920927 & forwards clarification of GA program plan GA plan in WCAP-83/0 is accurate description of GA program controls GAUTET Westinghouse Electric Corp. NS-EPR-2666 82/10/14 Quality Assurance Branch 13pp 15778 093

- 8210260072 Notification of 820930 meeting w/8&W in Bethesda, MD to discuss status of work re generic accident source term considerations
 HOUSTON.R W Assistant Director for Radiation Protection 82/09/21
 DENTON.H R, CASE, E, MINOGUE, R NRC No Detailed Affiliation Olven ip 15808-359
- 8210260305 Requests review of Instrumentation & Control Sys Branch proposed requirement for addl reactor trip breaker circuit tests in near-term Westinghouse plants TVA recommended procedures represent potential threat to safety RAME, E P Westinghouse Electric Corp NS-EPR-2640 82/10/18 SPESS T Division of Systems Integration (post 811005) 2pp 15805 231
- --8206300370 Ack receipt of 820427 ltr providing position on testing of shunt trip circuits of reactor trip breakers in Westinghouse plants Instrumentation & Control Sys Branch does not concur w/vendor position Evaluation encl ROSA,F Instrumentation & Control Systems Branch 82/06/18 RAME,E P Westinghouse Electric Corp App 15805 233
- 8210260340 Forwards proprietary & nonpreprietary responses to Revision i to Reg Quide 1 92. "Combining Model Responses & Bpatial Components in Seismic Response Analysis" to assist in fuel assembly analysis Response withheld (ref 10CFR2 790) RAHE, E P Westinghouse Electric Corp NS-EPR-2658 82/09/17 BERLINGER, C. MEYER, R. O. Core Performance Branch 2pp 15803 045
- --82i0260351 Submits application for withholding proprietary response to Revision i to Reg Ouide 1 92, "Combining Model Responses & Spatial Components in Seismic Response Analysis" Affidavit & nonproprietary response enci
- 9210270092 Forwards proprietary "Exxon Nuclear Power Distribution Control for PWRs - Phase II." Suppl 2 & Addendem 1 to Suppl 2 Encl withheld (ref 100FR2 790) UMSLEY. 6 F Exxon Nuclear Co., Inc. (subs of Exxon Corp.) 0FO 087 82 82/10/21 THOMAS. CO. Standardization & Special Projects Branch 1p 15829 317
- 8210270164 Forwards nonproprietary & proprietary "Generic Mechanical Design for Exxon Nuclear Jet Pump BWR Reload Fuel," per NRC 820826 request Proprietary rept withheld (ref 100FR2 790) CHANDLER, J C Exxon Nuclear Co., Inc. (subs. of Exxon Corp.) JCC 094 82 82/09/29 THOMAS, C O Standardization & Special Projects Branch ip 15824 236
- --8210270169 XN-NF-81-21(NP)(A)

 Nonproprietary "Generic Mechanical Design for Exxon Nuclear

 Jet Pump BHR Reload Fuel "

 # Exxon Nuclear Co. Inc (subs of Exxon Corp.) 82/09/22

 113pp 13824 238
- 9210270214 Forwards proprietary revision to "RODEX2 Fuel Rod Thermal—
 Mechanical Response Evaluation Model " Revision modifies
 RODEX2 code based on benchmarking of model to enlarge data
 base Rept withheld (ref 10CFR2, 790)
 CMSLEY, 9 F Exxon Nuclear Co., Inc. (subs. of Exxon Corp.)
 QFO 088 B2 82/10/22 THOMAS, C O Standardization & Special
 Projects Branch 1p 15822 347
- 8210280433 Forwards review of Nestinghouse safety parameter display sys, in response to 820506 request Verification & validation program generally acceptable Outstanding concerns must be resolved before review completion CRUTCHFIELD, D Operating Reactors Branch 5 LS05-82-10-005 82/10/05 RAHE, E P Westinghouse Electric Corp 7pp 15860 056.
- 8210290118 Forwards for info draft rept & apps on pressurized thermal shock Completed rept will form basis of Commission decision due 821030 W/o encl
 LAINAS G C Assistant Director for Operating Reactors 82/09/28 ROCHINO, L Babcock & Wilcox Operating Plants Owners Group ROCHINO, L General Public Utilities GPU Service Corp 2pp 15866 398
- 8210290141 Forwards GA Topical Rept, Amend 7
 FISHER, C R OA Technologies, Inc / Oeneral Atomic Co LRB 69. CRF; 82/10/17 HAASS, W P. Guality Assurance Branch ip 15854 310.
- --8210290144 GA-A13010A A07 Amend 7 to GA program + GA Technologies, Inc /General Atomic Co. GA-LTR-11 82/10/31 71pp 15854 311.

E210270288 Confirms 821020 telcon re new fatigue curve (Figure 2-11b) aided to NFOE-24011-P-A-4 Curve illustrates stress/cycle relationships used in fatigue evaluations & serves as basis for fatigue analysis of approved PBx8R fuel design HARRAEY, J S General Electric Co HFN-154-B2 B2/10/25 ERGGREN, J S NRC - No Detailed Affiliation Given 1p 15854 07/

10270453 Forwards for info draft rapt & apps on pressurized thermal shock Completed rept will form basis of Commission paper due

231030 H/o entl LAINAS.G C Assistant Director for Operating Reactors 82/09/28 PASKIN K C-E Operating Plants Owners Group 2pp 15863 185

1029045B Forwards, for info, draft rept & apps on pressurized thermol shock Completed rept will form basis of Commission paper (u. 821030 H/s enc.)

for Bettod Wid and 1 AlNAS,G C Assistant Director for Operating Reactors 82/09/28 HINGSLEY,D Westinghouse Operating Plants Owners Group KINGSLEY,O Alabama Power Co 2pp 15863 183

STE HOT NUCLEAR WASTE MANAGEMENT

iO120131 Summary of 820903 meeting w/DDE.BNL & DuPont re environ issetiant & draft finding of no significant impact re use if borosilicate glass in defense waste processing facility istandence list encl
SEL.H J High Level Waste Licensing Management Branch 82/09/1

|0120138 Requests copies of papers presented at Bozeman Montain |testing of Rocky Mountain Section of Geological Boc of |intrica,deaking w/geologic aspects of Basalt Waste Isolation

MIGHT R J High Level Waste Technical Development Branch 12/08/31 SOUINES, D Energy, Dept of 1p 15692 169

,0120147 Responds to 820830 ltr expressing concern re final version ,0120147 Responds to HAUSSU itt expressing Loncern re final pf 100FR61, "Licensing Requirements for Land Disposal of ladvaste " De minimis issue for managing low level radwaste unlike addressed within nest few yrs (ARTIN.) B Division of Waste Management 82/07/21 HARRI Halth Physics Society 2pp 15672 177 82/07/21 HARRIS, 5 J

|0120173 Forwards minutes of 820729 briefing on 10CFR40 W/o encl |ELL,N J High Level Waste Technical Development Branch 82/08/31 |OME,NOSER.L H Louisiana State of LIEBOLDW C Affiliation |Intreval CAMIL,P C Environmental Protection Agency 4pp 5692 205

.0120179 Notification of 820709 meeting w/Basalt Waste Isolation reject coordinators in Silver Spring MD for site issue malysis treatment & systematic review & comparison of site

House
RIGHT, R J High Level Waste Technical Development Branch
12/08/31 BELLIM J. BOYLE, R., COCK, R High Level Waste Licensing
1magement Branch 2pp 15692 209

10120322 Forwards draft DOE/NWTS-33(3), "NWTS Program Criteria for [O]2022 Forwards draft DDC/RRID-33131 THEID Program Criteria for sind Geologic Disposal of Nuclear Wastes Repository Parformance & Development Criteria "Comments on repository Issign features requested by 821006 W/o enci 30mEnR High Level Waste Licensing Management Branch 82/09/21 RECKES. J T High Level Waste Technical Development Branch 1p

|0120324 Forwards draft DOE/NHTS-33(3), "NWTS Program Criteria for the declogic Disposal of Nuclear Wastes Repository Perforance & Development Criteria " Comments on GA stds requisted by 82(00.6 W/o and! ONLERR High Level Waste Licensing Management Branch 100.8 F High Level Waste Licensing Management Branch 10 15690 351. 82/09/21

0120385 Forwards "Corrosion of Cast Iron & Low Carbon Steel Nuclear Ists Containers in Basalt Repository " Draft rept will be stud as NUREO Repository " Draft rept will be stud as NUREO Rept Waste Technical Development Branch 12/09/20 SQUIREB.D Energy, Dept of ip 15690-353

1210120329 "Corrosion of Cast Iron & Low Carbon Steel Nuclear Waste Containers in Basalt Repository," draft rept MALLE E NRC - Nu Detailed Affiliation Given 62/08/26 44pp 15590 354

012035; Firmards second "Draft Technical Position on Radionuclide jec & Bolobility Determinations " USIUS.P B High Level Waste Technical Development Branch 2709/30 MILLER,H J High Level Waste Technical Development ranch ip 15690 301

--8210120353 "Draft Technical Position on Radionuclide Spec & Salubility Determinations "BROOKS, D. CORRADO, J. NRC - No Detailed Affiliation Given 82/08/30 28pp 15690 302

6210120355 Trip rept of 820507 internal dosimetry symposium in Harrisburg.PA FEHRINGER.D J High Level Waste Licensing Management Branch 82/09/10 KNAPP,R High Level Waste Licensing Management Branch

8210120356 Trip rept of 820830-0703 visit to Denver, CQ & Los Alamos, NM to attend fourth annual DDE low level waste mgt program participants info meeting HAHKINS, EF, STARMER, R J Low Level Waste Licensing Branch 62/09/21 6CARANO, R A Low Level Waste Licensing Branch 4pp 15690 347

8210120358 Proposes lead responsibilities for Basalt Waste Isolation Project
WRIGHT:R J High Level Waste Technical Development Branch
B2709/22
High Level Waste Technical Development Branch

8210120359 Requests list of documents referenced in BCR for Basult Naste Isolation Project HRIGHT.R J Stigh Level Waste Technical Development Branch 82/09/21 BDYLE.R , CODK.R , OREEVES, J Division of Waste Management 3pp 15690 275

89:10120375 Requests review & comments on encl DDE/NWT6-33(3), "NWT6 Program Criteria for Mined Geologic Disposal of Nuclear Hastes Repository Performance & Davelopment Criteria " W/o enti BELL.N J High Level Waste Licensing Management Branch B: ARBENAULT.F Division of Health, Biting & Environment ip 82/09/21

S2(0)20379 forwards preliminary geological hydrological & geotechnical evaluation of Coke Oven Site, Montrose County, CO Meeting planned for early Sept to discuss comments

JACONI, W Colorado State of B2/08/20 SMITH, R D Low Level Waste Licensing Branch ip 15699/330

--821012038& Preliminary geological, hydrological & geotechnical evaluation of Coke Site, Mentruse County, Ca ROSASCO, PV , HEATH, R A Fox Consulting Engineers & Geologists 82/07/31 147pp 15889 331

821012044B Forwards draft DOE/NWTS-33(3), "NWTS Program Criteria for AIDIZUMAN FORWARDS GRAFT DUB/KNIS-SIGN, "NATH PROGRAM Criteria Mined Geologic Disposal of Nuclear Hastes Repository Performance & Development Criteria " Radiological safety & dosimetry comments requested by 82:006 H/o encl BOYLE.R R High Level Waste Licensing Management Branch 62/ KNAPP.M R High Level Waste Licensing Management Branch 1p 82/09/21

8210120854 Comments on Jul 1982 monthly rept for Edgemont cleanup action program No changes to costs or final delivery of contracted products authorized FLORY, CA Uranium Recovery Licensing Branch FIN D~2217 B2/09/14 HOGMAN, N A Battelle Memorial Institute, Pacific Northwest Laboratory 2pp 15684 216

8210120374 Forwards comments on draft remedial action concept paper for U mill tailings site.

BCARAND,R A Low Level Waste Licensing Branch
CAMPBELL,R H Energy, Dept of 3pp 15685 2 82/09/20. 15695 229

8210220037 Forwards NRC comments on final draft remedial action concept paper for Durango. OD inactive U mil) tailings site Comments can be sessily resolved.

8CARÁMORA A Upanium Recovery Licensing Branch 82/09/09 CAMPRELL.R H Energy, Dept of Spp 15786-278

8210250025 UHTRA-DOE/ALO-34 DRF Draft "Remedial Action Concept Paper for U Hill Tailings Site at Shiprock.NM "

* Navajo Nation CAMPBELL.R.H Energy, Dept of 20482
82/08/31 27pp 15778 316

8210240084 Forwards "Certificate of Mater Analysis, May 1982" CAIN, J Cotter Corp 20591 82/05/09 HAZLE, A J Cotor, of. 2pp. 15814 153.

| _}

--8210260091 "Certificate of Water Analysis.May 1982 " Five oversize Histings encl Aperture cards available in PDR
MCDDMELL, J. CURREY, M. HERRERA, D. Cotter Corp. 05-82 82/07/12
5pp 15864 155

CEORTLIC EXPORT AND IMPORT LICENSES

- 8210040382 Ltr of assurance re export of 330 32 kg U-235.contained in 11,590 kg U, to Japan SHIRAKAWA.T Japan 82/09/02 GRIFFIN.J A Energy, Dept of 1p 15597 211
- 8210040395 Ltr of assurance re export of 268 kg U-235, contained in 10,936 kg U, to Japan SHIRAKAYA, T Japan 82/09/02 GRIFFIN, J A Energy, Dept of 1p 15597 212
- 8210040387 Ltr of assurance re export of 340 28 kg U-235, contained in 10,470 kg U.to Japan SHIRAKAWA.T Japan 82/09/02 GRIFFIN.J A Energy, Bept of ip 15597 213
- 8210040403 Executive Branch position re Mitsubishi Intl Corp application to export 575 kg U-235 contained in 29.698 kg U, to Japan Ltr of assurance enci License should be granted DEVINELJ B. State. Dept of Dureau of Oceans & Internati Environ Scientific Affairs 82/09/10 SNEAJ R Office of International Programs, Director 2pp 15597 230
- 8201060245 Requests approval of alternate routes for planned irradiated Oldower Requests approve to a literate routes for plan fuel shipments from Chalk River Nuclear Labs to DDE Savannah River facility Date of arrival deleted DANESE.F L Nuclear Assurance Corp 19955 81/11/13 of Safeguards 3pp 15026 201
- ~-8210050467 Advises of plans for series of spent fuel shipments from Chalk River to DOE Savannah River Plant DANESE,F t. Nuclear Assurance Corp FLD/02/B4/ET6 82/07/02 GDDY, A Region t. Office of Director Ip 15626 232
- --821005047(Corrects 820702 prenotification of planned series of irradiated reactor fuel shipments from Chalk River to Savannah River Plant Port of entry is Derby Line, VI DANESE, F. L. Nuclear Assurance Corp. FLD/82/86/ETS 82/07/07 GODY, A. Region 1, Office of Director. 1p. 15626-233
- 8210060007 Amend 5 to GE export license changing licensee & consignee addresses & adding 3 addl consignees PETERSON M R Assistant Director for Export/Import & International Safeguards ODM-073-02 02/08/31 ip 15636-267
- 8210060471 Ltr of assurance re-application to export 319 20 kg U-235. contained in 11.200 kg U-to Japan SHIRAKAMA.T Japan 82/09/02 GRIFFIN.J A Energy. Dept of ip 15636 219
- 8210070411 Add1 response to FOIA request for documents re IAEA nuclear mat1 safeguards program Forwards documents listed in App A FELTON.J M Division of Rules and Records 82/09/10 OREENBERO.E V Tuttle & Taylor 3pp 15647
- --8210070486 Notifies that no special physical protection or intl safeguards concerns identified re Amend I to application to export low enriched U to Malaysia SHERR.I S Material Transfer Safeguards Licensing Branch 82/06/28 ZIMMERMAN.J V Assistant Director for Export/Import & tonal Safeguards ip 15647 267

urity concerns exist we enriched U

-h

D- -1

- --8210070421 Notifies that no physical security concerns erist re eipart of low enriched U to Japan under export license application XSNM-1896
 - SHERR.TS Material Control & Accountability Development Dranch 81/12/17 DEVINE.JB Assistant Director for Export/Import & International Safeguards ip 15647 007
- --8210070436 Notifies that no physical protection concerns erist re applications to export low enriched U to Japan under Licenses XBNM-1923, 1928, 1928 & 1896 SHERR. T.S. Material Transfer Safeguards Licensing Branch 82/02/25 PETERSON, M.R. Assistant Director for Export/Import & International Safeguards 1p 13647-016
- --B210070434 Notifies that no physical protection concerns exist re export of highly enriched U to Japan Update on status of negotiations requested SHERR.T S Haterial Transfer Safeguards Licensing Branch B2/02/09 D2VINE.J B Assistant Director for Export/Import & International Safeguards 1p 15647-015
- --8210070436 Notifies that no physical protection concerns exist re applications to export low enriched U to Japan under Licenses XSNM-1923, 1925, 1928 & 1896 SHERR.T S Material Transfer Safeguards Licensing Dranch 82/02/25 PETERSON.M R Assistant Director for Export/Import & International Safeguards 1p 15647 016
- --8210070471 Forwards draft Commission paper re application for license to export highly enriched U to Franco Comments & license conditions specified in Encl 2 should be included in BURNETT, RF Division of Safeguards 82/05/25 BHEA, J. R. Office of International Programs, Director 3pp 15647 224
- --8210070436 Notifies that no physical protection concerns erast re applications to export low enriched U to Japan under Licenses XSNK-1923,1925,1928 & 1896 GHERR. T S Makerial Transfer Safeguards Licensing Branch 82/02/25 PETER80N,M R Assistant Director for Export/Import & International Safeguards 1p 15647 016
- --B210070447 Notifies that no physical protection concerns exist re applications to export low enriched U to Japan Info requested re status of facility attachment to Fukushima I. Unit 4
 SHERR.T S Material Transfer Safeguards Licensing Branch
 82/03/11 PETERBON,M R Assistant Director for Export/laport &
 International Safeguards ip 15647 038
- ---8210070484 Notifies that no physical protection concerns found reapplication for license to export single reload of low application to literature of application for Expan
 SHERR.T S Material Transfer Safeguards Licensing Branch
 S2/06/23 ZIMMERMAN.J V Assistant Director for Export/Import &
 International Safeguards ip 19647 263
- 8210070493 License for Transnuclear, Inc. to import 17,000 kg U, enriched to 1 04 U-235, as U hexafluoride, from France ZIMMERIAN. J V Assistant Director for Export/Import & International Safeguards 82/09/24 ip 15637 336
- 8210070439 License for Exxon Nuclear Co. Inc to import 93.020 kg U. enriched to 4 3% U-235 contained in fuel rods or assemblies. from Taiwan from laiwan ZimmERRAN.J V Assistant Director for Export/Import & International Safeguards 82/09/26 ip 13637-344
- 8210070443 License for Phibro-Balamon, Inc to import 500,000 tg U, including normal U & U enriched to 5 0% U-235, in any form except U contained in irradiation fuels, from any country ZIMMERMAN, J V Assistant Director for Export/Import & International Safeguards 82/09/26 1p 15637 347
- 8210070452 Application for license to import 21.702 kg U.containing 418 49 kg U-235 & 21.346 kg U.containing 544 232 kg U-235. From West Germany
 HANNETT, B A Transnuclear, Inc TNF 41B. 82/09/28 HOORE, N
 Office of International Programs, Director 2pp 15637 356
- 8210080003 Forwards application for license to export 500,000 Cs tritium gas to United Kingdom SHANIA Ediom International Co. 82/09/10 HEMBY.E Assistant Director for Export/Import & International Bafeguards 1p 15668 353.
- --B2100B0005 Application for license to export 500,000 Ci tritium pau to United Kingdom SHAMA A Ediow International Co BRD-1(82) 82/09/10 | p 15668 354

NONDOCKETED ITEMS

- E210080033 Forwards application for license to export 400 ig caselterite enriched to 0 4% to United Kingdom VAN RIPER,0 0 AMAX. Inc B2/09/09 HEMBY,E NRC - No Detailed Affiliation Olven ip 15669 001
- -\$210080035 Application for license to expart 400 kg cassiterite, enriched to 0 4% to United Kingdom DISTLER.H F AMAX, Inc SN-EXP 82/09/10 1p 15669 002
- 210080037 Forwards application for license to export 86 861 m(.)
 Cf-252 as cermet wire to France
 HANKEITLE A Transnuclear, Inc 82/09/08 MODRE,N Office of
 International Programs, Director 1p 15669 003
- -8210080040 Application for license to export 86 861 mCi Cf-252 as cerast wire to France HANNETT, 8 A Transnuclear, Inc (TNP 414) 82/09/08 ip 18449 004
- --B210080042 Advises that CEA will fabricate Cf-252 & send entire source to Institut Quatave Roussy de Villejuif, in response to questions on 820708 application for license to export 86 861 mCi Cf-252 as cermet wire to France HARRETIS A Transnuclear, Inc 82/09/15 HEMBY, E Director's Office, Office of Inspection and Enforcement 2pp 18669 005
- 3210090055 Corrected license for Edlow Intl Co to import 30,000 kg U.enriched to 3 5% U-235. from France IJMSCHAN. V Assistant Director for Export/Import & International Safeguards 82/09/15 ip 15663 330
- ©210080071 Application for license to import 5,000,000 kg U.containing 250,000 kg U-235 SMANA Edlow International Co 82/09/17 Assistant Director for Easert/laport & International Badeguards ip 15669 363
- B210080108 Application for license to import 21.000 kg U.containing 210 bg U-235.from the Netherlands
 WARETT, D.A. Transnuclear, Inc. 82/09/20 MODRE, N. Office of International Programs. Director 2pp 19669-360
- 6210080113 Application to amend export license, submitting addl info reinterediate consignees HJLSDN,8 D General Electric Co BDW-083-82 82/09/07 MRIGHT,8 L NRC No Detailed Affiliation Given 1p 15669 362
- 8210080(19 Executive Branch position re Carpanter Technology Corpapplication to export Zircalog tubing to Norway License should be granted DEVINE.J B State, Dept of, Bureau of Oceans & Internati Environ & Scientific Affairs B2/09/17 SHEA.J R Office of International Propress, Director 2pp 13663 283
- 8210080126 Executive Branch position re KMS Fusion, Inc application to export 300 Ci tritium in hollow glass pellets to United Xingdon License should be granted DEVINE. J B State, Dept of, Bureau of Oceans & Internati Environ & Scientific Affairs, 82/09/10, SHEA. J R Office of International Programs, Director ip 15463 315
- 8210880130 Application for license to import 27,280 kg U.containing 872 % kg U-235, from West Germany HAPRETT, B A Transnuclear, Inc 82/09/13 HODRE, N Office of International Programs. Director 3pp 15663,243
- 8210080133 Application for license to import 27,000 kg U.containing 32 kg U-235, from the Netherlands MAMETIB A Transnuclear, Inc 82/07/20, MOORE, N Office of International Programs, Director 2pp. 15663 246
- 8210080135 Application to emend export license eubmitting addl info re interestiate consignees NILSON B D. General Electric Co BDW-O83-82 B2/09/07 WRIGHT: B L NRC - No Detailed Affiliation Given. Ip 15663:248
- 8210099138 License for Mitsui & Co (USA), Inc to export 33,000 lb Itralog-4 tube shells to Japan IlmeRMAN, J V Assistant Director for Export/Import & International Staguerds 136261, 82/07/20, ip. 15663,249.
- 8210080143 License for Westinghouse to export 15 kg depleted U oxide in fire of sintered pellets to Canada INMERHAN, J V. Assistant Director for Export/Import & International Steguerds ILB-194 82/09/22 1p 15663.250

- 8210080149 License for Hestinghouse to export 1.808 microgram Cf-252, contained in eight cermet sealed sources & 480 mg Np-237, contained in 24 radiation surveillance capsules, to South Korea
 ZIMMERMAN, J V Assistant Director for Export/Import & International Safeguards ILS-187 82/09/22 2pp 15663 251
- 8210080153 License for Wastinghouse to export three ionalation chambers & three gamma chambers to West Germany ZIMMERHAN.J V Assistant Director for Export/Import & International Safeguards ZE 10478 82/09/22 1p 15663 253
- 8210080157 License for Exxon Nuclear Co.Inc to export fuel rod hardware & cage assemblies to France ZIMMERMAN.J V Assistant Director for Export/Import & International Safeguards 82/09/22 ip 15663 254
- 82:0080162 Amend 1 to Transnuclear, Inc export license, increasing quantity of U-235 from 91 434 kg. contained in 98 kg U, to 94 513 kg. contained in 101 3 kg U
 ITMMERIAN.J V Assistant Director for Export/Import & International Bafeguards 81-269/01 82/09/21 1p 15663 270
- 8210080319 Forwards application for license to export four Zircaloy-4 alloy fuel channels to Republic of China WOZNIAK, D.R. Carpenter Technology Corp. 2-909-028 82/09/09 HEMBY, E. Assistant Director for Export/Import & International Bafeguards ip. 15663 358
- --8210080320 Application for license to export four Zircaloy-4 alloy fuel channels to Republic of China * Carpenter Technology Corp 82/09/09 2pp 15663 359
- 8210080321 Forwards application to export 15 kg depleted U oxide to Canada HERSCHIM H Westinghouse Electric Corp. ILS-174 82/07/15 ZIMMERMAN, J V Assistant Director for Export/Import & International Safeguards 1p 15563 361
- --B2100B0323 Application for license to export 15 kg depleted U nxide, in form of sintered pellets, to Canada
 HERBCH, M H Westinghouse Electric Corp B2/09/15 lp 15663 362
- 8210080324 Application for license to export 12 guide thimble tubes to Japan * C. Itoh & Co (America), Inc. M-004 82/09/15 in 15563 288
- 8210080327 Forwards application for license to export 9,500 kg
 individual rare earth compounds or mixtures & concentrates
 to various countries
 BARNUME C Molycorp. Inc 82/09/16 HEMBY.E Assistant Director
 for Export/Import & International Safeguards 2pp 15463 289
- --B2100B0331 Application for license to export 9.500 kg individual rare earth compounds or mixtures & concentrates to various countries Elements consist primarily of cerium, lanthonum, needynium & praseodymium,
 WARHOL.W N Holycorp, Inc B2/09/16 1p 15663 29:
- 8210080334 License for Luigi Serra. Inc. to export 16,400 springs to Italy
 ZIMMERHAN, J V Assistant Director for Export/Import & International Bafeguards 828-536 82/07/22 ip 13663 329
- 8210080339 Application for license to export 4,050 ft rinconium Grade II seamless tubing to Canada TUPPER.K F. Cabot Corp 1-6930(01-28043 82/09/15 ip 15AA3:328
- 82:0080343 License for Ediaw Intl Co to export 0 01 micro; 0 17 microgram Pu-239 to Philippines ZIMMERHAN.J V Assistant Director for Export/Import & Bafeguards PMC-1 82/09/20 2pp 13663 321
- 82i0080345 Advises of issuance of license to Mastinghouse kg depleted U to Canada w/o 18-day waiting period since matl to be shipped on 820924

 ZIMMERMAN, J V Assistant Director for Export/Import & Bafaguards 82/09/22 Assistant Director for Export International Bafaguards. 1p 13663 320
- 8210080349 Requests Executive Branch position re Intl Co application for license to export 500,000 Ci bulk tritium gas to United Kingdom ZIMMERMAN, J. V Assistant Director for Export/Import & Bafeguards 82/0722 STOIBER, C R. State, Dept of Da & Internati Environ & Scientific Affairs ip 15663

- 9210120117 License for KMS Fusion, Inc to export 300 C1 tritium, contained in microshell hollow glass pellets, to United Kingdom ZIMMERMAN, J V Assistant Director for Export/Import & International Safeguards KMSF-882-RO 82/09/22 Ip 15689 157
- 8210120503 Application for Eicense to Import 26 kg low enriched U digitde pellets from Japan CROSBLE.K L IRT Corp 82/10/01 MODRE.N NRC - No Detailed Affiliation Given ip 85672 075
- 9210120511 Forwards application for export license for minor nuclear export Ltr of assurance required W/o encl
 ZIMMERMAN, J V Assistant Director for Export/Import 9 International Safeguards 92/09/30 GRIFFIN. J A Energy. Dept of 1p 156/72 091
- 8210120519 License for Transnuclear. Inc to import 31.000 kg U.enriched to 1 10% U-235 as U hoxafluoride. from France ZIMMERMAN. J V Assistant Director for Export/Import & International Safeguards 82/09/24 1p 15672 095
- 6210130049 License for Transnuctear.Inc to export 1 464 kg U-235, contained in 3 223 kg U & 1 264 kg U-235, contained in 6 327 kg U.to Japan ZIMMERMAN,S R Assistant Director for Export/Import & International Safeguards (NUK 405)82-097 82/09/28 2pp 15594 361
- 8210130055 License for Pechiney Ugine Kuhlmann Development, Inc to export 6 547 kg U-235.contained in 7 018 kg U.to Greece ZIMMERMAN, J V Assistant Director for Export/Import & International Safeguards 7/2/82 82/09/24 2pp 15674 275
- 8210130059 License for Mitsu; & Co (USA). Inc to export 237 lb Zircaloy-2 barrier tube shells to Japan ZiMMERMAN.J V Assistant Director for Export/Import & International Safeguards 136249 82/09/26 2pp 15694 358
- 8210130062 License for Isotope Products Labs to export 0 0125 mg Cm-244 to Gatar ZIMHERMAN.JV Assistant Director for Export/Import & International Safeguards H/O 9888 82/09/24 1p 15694 357
- 8210130066 License for Carpenter Technology Corp to export 24 piecer of Zircaloy tubing to Norway ZimmERMAN.J V Assistant Director for Export/import & International Safeguards CARTECH-SPD 150 82/09/24 ip 15696 267
- 8210130070 Amend 6 to GE export license extending expiration date to BB0101.changing intermediate consigners & increasing quantity of matl for export to 3.055 kg U-235.contained in 126.535 kg U, to Italy ZIMMERHANLJ V Assistant Director for Export/Import & International Safeguards BDH-074-82 82/09/24 lp 15696 263
- 6210130072 Application for license to export equivalent of 5 kg deuterium to Malaysia * Sigma Chemical Co D-97 B2/09/23 ip 13696.252
 - uplication for license to export 2 mg Cf-252.contained in orce.Model GEN-CF123, doubly encapsulated, to

- 8210220517 Application for license to export 7 94 kg thorium, contained in 10 kg Thorium fluoride in granular form, to Lichtenstein (Buitzerland)
 COLTON.E Cerac, Inc. 82/09/24 jp. 15786-084
- 8210260083 License for Instrumentation Research Technology Corp to import 26 kg U.enriched to 4% U-235, as U dxide pollets from Japan ZIMMERNAN, J V Office of International Programs, Director 82/10/01 ip 15814 324
- 8210260529 Notifies that Westinghouse 821007 application to export cable assemblies to Belgium has been approved w/o 15-day watting period Equipment ready for immediate shipment ZIHMERMAN.J V Assistant Director for Export/Import & International Safeguards 82/10/14 Assistant Director for Export/Import & International Safeguards 1p 15830 178
- 8210260541 Not; fies that Westinghouse 821107 application to export one compensated conization chamber to Belgium has been approved w/o normal 15-day waiting period Equipment ready for immediate shipment
 ZIMMERHAN, J V Assistant Director for Export/Import & International Safeguards 82/10/14 Assistant Director for Export/Import & International Safeguards 82/10/14 Assistant Director for Export/Import & International Safeguards 1p 15830 355
- 8210260570 Application to amend export license extending expiration date to B51231

 HILSON.B D General Electric Co BDN-089-82 82/10/05 HEMBY, F O Office of International Programs. Director ip 15814 357
- 8210260573 License for Sigma Chemical Co to export 5 0 kg deuterium oxide to Malaysia ZIMMERHAN.J V Assistant Director for Export/Import & International Safeguards D-97 82/10/13 ip 13814 359
- 9210260574 Amend 1 to GE export license.extending expiration date to 851231
 ZIMMERMAN.J V Assistant Director for Export/Import & International Safeguards BDM-089-82 82/10/14 ip 15814 360
- 8210260578 Amend 3 to GE Co. Inc export license, extending expiration date to 891231 & changing end use statement ZIMMERMAN.J V Assistant Director for Export/Import & International Safeguards KKL-8DW 81008 82/10/13 ip 15830 141
- 8210260580 Amend 1 to CE export license, extending expiration date to 841231
 ZIMMERMAN, J V Assistant Director for Export/Import & International Safeguards BDM-79201 82/10/13 ip 15830 142
- 8210270001 Amend 1 to Sandvik Special Metals Corp export license, increasing quantity of matl from 12,800 to 20,000 lb & increasing value of export ZIMMERMAN.J V Assistant Director for Export/Import & International Safeguards 82/10/13 lp 15836 078
- 8210270003 Amend 1 to 0A Co export license, extending expiration date to 85101 TIMMERMAN.J V Assistant Director for Export/Import & International Safeguards IEL-4015 82/10/13 ip 15836 079
- 8210270005 Amend 6 to Transnuclear, Inc export license, extending expiration date to 880301
 ZIMMERMAN, J V Assistant Director for Export/Import & International Safeguards RBU-33180-120/0 82/10/13 1p 15836 080
- 8210270007 Application for Amend 1 to export license, increasing value of equipment to be shipped to Japan TBUKUDA.T Mitsul & Co (U S A). Inc (Subs of Mitsul & Co .Ltd) 82/10/12 WRIGHT.D L Office of International Programs. Director ip 15836.081
- 8210270011 Application for license to export 24,860 lb Zircaloy tres to Dermany
 AERNI, B L Teledyne Wah Chang Albany 2326(JFM) B2/10/OB 1p
 15836 082
- 8210270014 Application for license to export compensated ionization chamber, Model ML23084, to Japan POCHAL W F Westinghouse Electric Corp ZE 60252 82/10/06 1
- 8210270017 Application for license to export compensated ionization chamber, Model WL23774, to Belgium POCHAL, W F Westinghouse Electric Corp ZE20561 82/10/07 ip

- 8210270021 Application for license to export 12 6 kg U as metal to Canada SHAM, A Edlow International Co AECL-1(82) 82/10/13 in (5936 OBS
- 2210270076 Application for license to export 4.850 16 Zircaloy trex to West Germany AERNI.B L Teledyne Wah Chang Albany 2420 (JFM) 82/10/14 ip 15836 299
- 8210270094 Application to amend export license, changing quantity to be exported to 50 g U-235, contained in 500 g U & 500 g Th-232 MARCHAL.J European Communities. Commission of 62/09/27 GRIFFIN.J A Energy, Dept of 1p 15836 218
- 8210270103 Advises that proposed import of 26 kg U, enriched to 4% U-235 constitutes no undue risk to public health, sefety or environ environ MCORE.R N Office of International Programs, Director 82/10/04 Office of International Programs, Director 1p 15836-220
- 1p
- 821027010B Advises that license to import 26 kg U dioxide pellets, enriched to 4%, from Japan issued w/o 15-day waiting period ince matl urgently needed for testing 27MvERHAN.J V Assistant Director for Export/Import & International Safeguards 82/10/04 Assistant Director for Export/Import & International Bafeguards 1p 15832 340
- 8210270114 Advises that proposed import of 27.280 kg Usenriched to 3.27 U-235, constitutes no undue risk to public health, safety or enviran MOORE, R M. Office of International Programs, Director 82. Office of International Programs, Director 1p. 15832-341
- 8210270122 Advises that license to import 27.280 kg low enriched U in fare of U hexafluoride from Wost Germany Issued prior to espiration of 30-day period stated in FR ZIMMERHAN. J V Assistant Director for Export/Import & International Bafeguards 82/10/05 Assistant Director for Export/Import & International Bafeguards ip 15832 347
- 82(0270127 Advises that license to export 23B lb Zircaloy-2 barrier tube shells to Japan issued w/o 15-day waiting period since tubing ready for immediate shipment & organity required by CULTOMET INPERIAN. J V Assistant Director for Export/Import & Internationa)
 Safejuards 82/09/26 Assistant Director for Export/Import &
 International Safeguards ip 1592-346
- \$210270147 Application for license to import 19.500 kg U.enriched to 0.85% U-235 from France HWMETT.B A Trensnuclear, Inc 02/09/30 MODRE.N Office of International Programs. Director 2pp 15834-342
- e.ve.outry rorwards application for export license for minor nuclear siport Ltr of assurance required IIMERMAN, J V Assistant Director for Export/Import & International Safaguards 82/10/05 GRIFFIN, J A Energy, Dept of 1p 15834-344 8210270149 Forwards application for export license for minor nuclear
- --8210270152 Application to amend import license, increasing amount of U from 10 to 15 kg OLBEH.R N National Nuclear Corp. 82/09/29 WRIGHT, B L Assistant Director for Export/Import & International Safeguards 19 15834.345.
- 8210270156 Forwards application for export license for minor nuclear esport Ltr of assurance required W/o encl IIMERMAN, J V Assistant Director for Export/Import & International Safeguards 82/10/06 GRIFFIN, J A Energy, Dept. of ip 13036 077
- 8210270158 Ltr of assurance re export of SNM to Switzerland FFSCH.C Switzerland 82/09/28 GRIFFIN.J A Energy, Dept of 15934,346
- 8210270163 Application to amend export license, increasing quantity to hi laported from 12:800 to 20:000 ib.
 MENIER.L. Bandvit Special Metals Corp. B2/10/04 HEMBY.E NRC No Ostalled Affiliation Olven ip 15834 349
- 82;027016B Requests exemption from 30-day FR notice requirement for import bicense Hatl must be exported immediately HMSETT.B A Transnuclear, Inc. TNF-415 82/09/23, MODRE, N Office of International Programs, Director. 1p 18834 350

- 8210270194 Application for license to export 5 kg deuterium bride liquid over 2-yr period to Malaysia

 Sigma Chemical Co D-98 82/09/30 ip 15835 348
- 8210270201 Amend 3 to GA Co export license extending expiration date to 851001 & increasing quantity of matl authorized for export to 50 g U-235 contained in 500 g U & 500 g Fh-232 to West vermany ZIMMERMAN.J V Assistant Director for Export/Import & Internationa) Safeguards IEL-954 92/10/06 ip 15836-033
- 8210270233 License for Transnuclear. Inc to export 86 861 mC: Cf-252.es cerment wire, to France ZIMMERMAN, J V Assistant Director for Export/Import & Internationa) Safeguards (TNP-414) 82/10/05 ip 15836-072
- 8210270238 License for Carpenter Technology Corp to export four Zircalog-4 aligy fuel channels to Taxwan ZiMMERHAN.J V Assistant Director for Export/Import & International Bafeguards CARIECH 2-909-0 82/10/05 ip 15836 075
- B210270243 Informs that Amend 5 to License XSNM-1686 may be issued Nu mati changed circumstances since issuance of License XSIM-1840
 MODRE,R N Assistant Director for Export/Import & International
 Safeguards 82/10/06 Assistant Director for Export/Import &
 International Safeguards 1p 15826-076 X5/IM-1840
- 8210270281 Application for license to export 10 kg thorium oxide powder to Italy COLTON.E Cerac, Inc 82/10/06 HEMBY, E NRC No Detailed Affiliation Given tp 15836 304
- 8210270282 Amend 1 to Hitsul Air Intl. Inc export license, increasing value of equipment for export to Japan ZIMMERMAN, J V Assistant Director for Esport/Import & International Safeguards 82/10/14 1p 15836 305
- 8210270283 Application to amend export license.extending expiration WILSON D D General Electric Co BDH-088-82 82/10/05 ip
- 8210270284 License for Westinghouse to export one compensated ionization chamber. Model ML23774. to Belgium ZIMMERMAN.J V Assistant Director for Esport/Import & International Safeguards ZE-20541 82/10/14 ip 15836-307
- 8210270285 License for Westinghouse to export one triax cable assembly. Model WL-24058 & one coax cable assembly Model WL-24060 to Relgium Relgium ZIMMERNAN, J V Assistant Director for Export/Import & International Safeguards ZE-20547 82/10/14 1p 15836 308
- 8210270286 License for Natl Nuclear Corp to export 2 0 milligrams CF-252,contained in one neutron source, to United Kingdom ZIMMERNAN.J V Assistant Director for Export/Import & International Befguerds BNFL-0-578 82/10/14 ip 18836 300
- B210270287 License for CERAC, Inc. to export 7 54 kg thorium, contained in 10 kg thorium fluoride, to Sultierland ZIHMERHAN, J. V. Assistant Director for Export/Import & International Bafaguards TLX-6725 B2/10/13 2pp 15836
- 8210270290 Litense for Molycorp. Ir to Australia, Austria, Belgium, C Greece, Ireland, Italy, Japan, Lus Norway, Sweden, United Kingdom ZIMMERMAN, J V Assistant Di Safeguards 82/10/08
- B210270313 Requests Executive ... application for license to export small amounts of thorium contained in rare earth products W/o encl
 ZIMMERHAN, J V Assistant Director for Export/Import & International Safeguerds 82/10/13 STDIBER, C R State, Dept of, Bureau of Oceans & Internati, Environ & Scientific Affairs 2pp 15836 339
- 8210270391 Application for license to export 4,850 lb Zircaloy trex to West Germany AERNI,B L Teledyne Hah Chang Albany. 2419 (TFM) B2/10/14 ip AERNI, B L 15833 362
- 8210270431 License for AMAX.Inc to export 180 kg natural U.contained in 35 metric tons tin concentrate & 180 kg natural thorium, to United Kingdom
 21MHERHAN.J V Assistant Director for Export/Import & Internationa ZIMMERHAN, J V Assistant Director for Export/Import & International Bafeguards SN-EXP 82/10/05 tp 15833 250

- 8210270446 License for Cabot Corp to export 4.050 ft :irconium Grade 1) seamless tubing of various outside diameters & lengths to Assistant Director for Export/Import & International 1-6930 82/10/05 1p 15833 280
- 8210270448 Forwards application for license to export 11,279 kg U. enriched to 3 95% U-225.to Japan HATTORI.H Mitsul & Ca (U S A).Inc (Subs of Mitsul & Co .Ltd) 82/09/27 Assistant Director for Export/Import & International Sareguards 1p (5832-361
- --8210270452 Application for license to export 11,279 kg U, enriched to 3 950 U-235 to Japan HOMDEN,T Missui & Co. (U S A), Inc. (Subs. of Milsui & Co.) Ltd.) MBN-2F1-R2-(8) 82/09/27 lp. (5832-362
- 8210280030 Application for license to export 0 0000125 mg Cm-244 Isotope Products Laboratories 4/0 9975 82/09/20 JAMRISKA, D 15863 003
- ADIOPHOORS Application for license to export 355 Zircaloy-4 guide thinble tubes to Japan BANGERTER,D M. Sandvik Special Metals Corp. SSM-2927 82/09/27 1p. 15862 362
- 6210280035 License for GA Co to export (1 kg U-235, contained in 55 4 kg Ut of Bangladesh
 ZIM ERMAN, J V Assistant Director for Export/Import & International
 Safeguards IEL 1163 82/10/05 2pp 15863 001
- 8210280038 License for Transnuclear, Inc to import 27,280 kg U.enriched to 3 24 U-235, from Hest Germany
 ZIMMERMAN, J V Assistant Director for Export/Import & International
 Sarequards 82/10/05 1p 15862 361
- 8210280040 License for C Itah & Co. Ltd to export 12 guide thimble tubes ZIMMERMAN, J V Assistant Director for Export/Import & International Satequards M-004 82/10/05 15842 340 10
- 6210280043 Application for license to export 2,490 Zircaloy-4 guide 9095-E682-WSS
- 8210280052 Application for license to export 2,002 mC: Cf-252 as cornet wire to France HANNETT,D A Transnuclear, Inc. (TNP 421) 82/10/04 2pp 15862 355
- 8210280056 Forwards applications for licenses to export 15 038 kg U. enriched to 93 3% U-235 to Denmark & 2.002 mCs CF-292, as cermet wire Application for U-235 only encl HANNETY:B A Transnuclear, Inc 82/10/04 MOORE,N Office of HANNETT, B.A. Transnuclear, Inc. 82/10/04 MOORE International Programs, Director 1p. 15862 (20
 - Application for lacense to export 15 038 kg U.enriched to 5, to Denmark End use statement encl 1 Transnuctear, Inc NUK-420 8 82/10/04 3pp

- 8210280062 Application to amend export license extending expiration date 3 yrs MCMRY.W R GA Technologies, Inc /General Atomic Co IEL-40:5 82/09/30 ZIMMERMAN.J Assistant Director for Export/Import & International Safeguards 1p 15862 233
- 8210280064 Application to amend export license increasing quantity to 15 g U-25, contained in 330 g U
 MARCHALJ European Communities, Commission of
 GRIFFIN, J A Energy, Dept of 1p 15862 234
- 8210280088 Application to amend export license, increasing quantity to 10 g U-235, contained in 220 g total U HARCHAL, J European Communities, Commission of GRIFFIN, J A Energy, Dapt of 1p 15842 235
- 8210280403 Application for license to export 5 kg deuterium oxide to India nois Sigma Chemical Co D-100 82/10/12 App 15859 319
- 8210280409 Amend 1 to Westinghouse export license, increasing quantity of matl authorized for export to 10 g U-235, contained 220 U, to Belgium . V Assistant Director for Export/Import & International ILS-150 82/10/05 ip 15859 331 Safeguards
- 8210280414 Amend 5 to Transnuclear, Inc export license, increasing 210220419 Ameno o to framenuclear inc export itsense increasing quantity of met authorized for export to 6.738 665 kg
 U-235, contained in fel.131 620 kg U.to Switzerland
 ZIMMERHAN.J V Assistant Director for Export/Import & International Safeguards RBU 331 80-1207 82/10/12 Ip 15859 357
- 8210280418 Amend 1 to Westinghouse export license, increasing quantity of matl authorized for export to 10 g U-235, contained in 220 g U, to France V Assistant Director for Export/Import & International ILS-150 82/10/06 ip 19889 360 ZIMMERMAN, J V

Safequards

- 8210280422 Amend I to Westinghouse export license increasing quantity of matl authorized for export to 15 g U-235 contained in 330 g U to United Kingdom Zimmerran, V Assistant Director for Export/Import & International
 - ZIMMERHAN.J V Assistant Director for Export/Import & International Safeguards 1L6-150 82/10/06 ip 15860 013
- 8210280435 Ltr of assurance re application to export 1 464 kg U-235, contained in 3 223 kg U & 1 264 kg U-235, contained in 6 329 kg U, to Japan SHIRAKAMA, T Japan 82/07/16 GRIFFIN, J A Energy, Dept of 1p 15860 063
- 8210290367 Requests assistance in expediting issuance of export license AddI valves must be shipped to reactor site ARNDT, G E Borg-Warner Corp CGA/82/454 82/10/13 HEMBY. C Assistant Director for Export/Import & International Safeguards 15865 247
- -- 8210270372 Application for license to export carbon & stainless steel valves, various globes, gates & supporting drawings & data to ARNOT, G E Borg-Warner Corp A-55127 82/10/13 1p 15865 248

The subject category column in this index gives the docket number and the symbol for the category of information within that docket; for example, 50-320 P. The docket subject categories are defined in Appendix A.

Subject categories for nondocketed items are also entered in this column by symbol; for example, ACRS. These categories are defined in Appendix B and listed in the Contents.

An asterisk following the accession number in this index indicates that the document is an enclosure to another document. To obtain the accession number of the principal document under which the enclosure is listed, refer to the index entitled "Cross Reference of Enclosures to Principal Documents."

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AU THOR	ACCESSION NUMBER	SUBJECT CATEGORY
AAPODT, M M AAMODT, M M RAMODT, M M AARON, U A ABEOTT, E C	8210050172 8210210359 8210260400 8210130162* 8210050409*	50-287 0 50-289 0 50-289 0 50-296 8 FOIA	ALLAN, J M ALLEN, J J ALLEN, R E ALLISON, D P AMAKO, V	821022041 i 8210290247 8210270060* 8210080206* 821026040 9	50-271 G REGOD 50-537 G FOIA 50-322 H	ATKINSON, S.A. ATWOOD, C.L. AULUCK, R. AULUCK, R. AUSTIN, O	8210120463 8210120368 8210270072 8210270227 8210270227	RES RES 50-397 A 50-397 A 50-295 R
ABELSON, H ABELSON, H ABBIANCE, D L ACHERHAN, H C AIMERHAN, H C	8210180311 8210270167 8210010361 8210150597 8210210254	50-352 A 50-352 A PR 40-8743 40-6459	AMES, K ANASTASIA, C M ANDERGON, J L ANDERGON, L L ANDERSON, M T	8210270041* 8210090368 8210150407 8210120068* 8210130566*	50-285 F NUREO RES FOIA 50-306 Q	AUSTIN, M A AUTERINO, L AUTIO, H A AUTIO, H A AUTIO, H A	8210130308* 8210180091* 8210130218 8210130230 8210130519	70-135 50-286 R 50-29 6 50-29 9
B U.EMAIA P L.EMAIA R B.MOOJGA D B.MABNAIA D B.MABNAIA	8210040042* 8210150415 8210130528 8210070016 8210130046	50-445	ANDERSON, P ANDERSON, P ANDERSON, R ANDERSON, T M ANDERSON, T M	8210040125 8210250120 8210210037 8005070094 8005070099*	50-266 0 50-266 0 Nureo P121 P121	AUTIG, H A AUTIG, H A AUTIG, H A AUTIG, H A AUTIG, H A	8210260106 8210260109 8210260165 8210260428 8210280085	50-29 8 50-27 8 50-27 8 50-29 8
O BAMABIETA ADEMBAME O ADEMBAME O ADEMBAME O ADEMBAME O	8210180254 8210180247 8210180418 8210190110 8210220511	50-369 F 50-329 A 50-404 A 50-327 P 50-329 A	ANDOGNIRI, O C ANDOGNIRI, O C ANDRULIB, M H ANO, W P APPEL, R R	0210130394 021020563 0210270221* 0210150170* 0210150170*	PR 70-2949 Contract 50-324 o 40-8781	AVERITT.D D AXELRAD.J AXELRAD.J AXELRAD.J AXELRAD.J	8210260284* 8210010170 8210070336 8210150267 8210170285	CONTRACT 50-325 Q 50-461 Q 50-271 Q 50-269 Q
Acensamie o Adlerir u Adlerir u Aernii u l Acenii u l	8210280407 8210040218 8210210378 8210270011 8210270074	50-369 P 50-289 Q 50-289 O XPORTLIC XPORTLIC	APPELIR R APPLEGATE, T W ARAGON, J J ARCHERIC D ARCHERIC D	8210260412 8209270271* 8210150571 8210270413* 8210270419*	40-8728 50-358 H NUREO 50-387 X CONTRACT	AXELRAD, J AXELRAD, J AXELRAD, J AXELRAD, J AXELRAD, J	8210150368 8210150496 8210260072 8210260073 8210280163	50-315 0 16E 16E 14E 50-312 P
Acani, B l A,Arwal, R A,ee, J r Agee, J r Agew, H H	B210270391 B206230020* B209290240* B210190766* B2102701B7	XPORTLIC 50-245 P FOIA QA999 71-30	ARCHER, C D ARCHITZEL, R E ARCHITZEL, R E ARMSTRONG, K A ARNOT, Q E	8210270428# 8210150235# 8210170714# 8208270088 8210270367	70-1113 50-317 q 50-317 q FOIA XPORTLIC	AXELRAD, J AXELRAD, J A AXELRAD, J A AXELRAD, J A AXELRAD, J A	8210280221 8210048047 8210048048 8210130577 8210150473	50-272 Q 50-321 Q 70-143 50-344 Q 70-143
AHEARNE, J AHEARNE, J AHEARNE, J AHEARNE, J F AHRENS, P	8201150005* 8210280404* 8210290393 8210180459 8210040190	FOIA FOIA 10CFR COMMISSION 50-307 Q	ARNOLD, G E ARNOLD, E M ARNOLD, K ARNOLD, M L ARNOLD, R G	8210270372* 8210180553 8210260520* 8210270370 8210060342	XPORTLIC NUREG CONTRACT 40-8153 50-287 P	AXELRAD, J A AXELBON, W AXELBON, W L AXELBON, W L AXELBON, W L	8210190232 8210080251 6210040185* 6210040354* 8210080204*	ao-sov õ
L-Geng, P #101#Off, B #101MOff, B #2-A(AT, R ALBERT, J H	8210280227 8210150206* 8210150206* 8210150548 821008028[*	50-309 0 50-322 T 50-322 T NUREG 50-416 8	ARNOLDIR C ARNOLDIR C ARBENAULTIF J ABHBAUGHIC E ABHBAUGHIC E	8210130279 8210290204 8210050039* 8210290043* 8210290051*	50-320 P 50-289 P REGGD 50-142 F 50-142 F	AKELSON, W L AKELSON, W L AYER, J E AYER, J E DACHAND, D	8210150495*	
ALEERT, J H ALBERT, J K ALBERT, J K ALBERT, N O ALBRIGHT, R H	8210220282* 8210270135* 8210270351* 8210040143* 8210010137*	50-416 8 50-416 8 50-416 8 50-508 0 50-324 0	ASHE, F ASHE, F ASHE, F ASHE, F ASHE, F	8105110396* 8107160386* 8103180604* 8111180001* 8111270314*	FOIA FOIA FOIA 50-338 8 50-295 8	BACHMANN R O BACHMANN R O BACHMANN R O BACKLEY, B T BACKUB, R A		
Alden, II h Alden, II h Alderson, C e Alderson, C e Alderson, C e	8210150282 8210220174* 8210010111* 8210220406* 8210220432*	50-277 P 50-277 R 50-400 Q 50-438 Q 50-438 Q	ARHE, F ASHE, F ASHE, F ASHE, F ASHE, F	8210050023* 8210070429 8210070432 8210070474 8210070476	50-278 8 50-275 8 MISC 50-278 8 HISC	BACKUS, R A BACKUS, R A BACKUS, R A BACON, J L BAER, R L		
ALDERSON, C E ALEMANDER, R E ALLAN, J H ALLAN, J H ALLAN, J H	8210220446* 8210050020* 8210170580 8210210136 8210220182	50-438 Q RECOD 50-244 Q 50-307 Q 50-219 Q	AGHE.F ASHE.F SHE.F STEFI.B ATEFI.D	8210080021 8210080059 8210120372 8210040355* 8210040357*	GEN TEC 18 HISC HISC 30-537 A FOIA	DAER,R L BAER,R L BAER,R L BAER,R L BAGBY,L A		

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT	AUTHOR	ACCESSION NUMBER	GUBJECT CATEGD?,
BAGBY, L A GATLEY, F C BAIR G G BAIR, G G GAISDEN, L	8210080232* 8210050191* 8210250093* 8210250175* 8210210564	71-9167 94999 50-344 S 50~344 B CONTRACT	Bass In. N Bass In. N Bass In. N Bass In. N Bass In. N	8210180344* 8210180347* 8210180349* 8210180351* 8210180352*	FOIA FOIA FOIA FOIA FOIA	BEAMER, W H BEAMER, W H DEAMER, W H DEAMER, W H DEAMER, W H	8210180257* 8210180260* 8210180262* 8210180266* 8210180424*	FOIA FOIA FOIA FOIA 70-278
EAISOEN.L Bamer, C E Bamer, C E Bamer, C E Bamer, C E	8210210576 8210220516 8210250006 8210250034 8210260017	CONTRACT 40-8481 40-8481 40-8481 40-8481	BASSIN.N BASSIN.N BASSIN.K BASSO.L F BASSO.L F	8210180422* 8210180425* 8210180429* 8210250095* 8210250160*	F01A F01A F01A 50-318 S 50-317 S	BEAMER, W H BEAMER, W H BEARDEN, R G BEARDEN, R O BECHHOEFER, C	821018042/* 8210180431* 8210080057* 8210080064* 8210060229	FOIA FOIA FOIA 50-317 P 50-329 G
EAZER,C E BAKER,C E CAKER,C E BALL,B J BALLARD,R L	8210260022 8210270209 8210270435 8210150564 8111240071*	40-8481 40-8481 40-8481 NUREG 50-266 P	BASTIAN.B E DATES.A BATES.A DATES.A BATES.A	8210070358* 8210010065* 8210010076* 8210010172* 8210040368*	50-438 A FOIA FOIA FOIA FOIA	BECHMOEFER, C BECHMOEFER, C BECHMOEFER, C BECHMOEFER, C BECHMOEFER, C	8210130304 8210130421 8210180172 8210210270 8210220322	50-329 ¢ 50-329 ¢ 50-490 ¢ 50-329 ¢ 50-329 ¢
BALLARD R L BANGART, R BANGERTER, D H BANGERTER, D H BANGERTER, D H	8202120129* 7912280014* 8210280032 8210280043 8210120124	50-266 P 50-324 P XPORTLIC XPORTLIC RES	BATES.A BATES.A BATES.A BATES.J W BAUER.E G	8210040371 # 8210040381 # 8210040383 # 8210150067 # 8210200063 #	FOIA FOIA FOIA 70-1113 50-277 P	BECK.G P BECKER,R A BECKHAM.J T BECKHAM.J T BECKHAM.J T	8210130476 8210040454 8210010022* 8210060231 8210060275	50-151 S 50-537 A 50-321 Q 50-346 P 50-366 P
Banks.W W Barber G Barham.C D Barnes.C Barnes.I	8210120657 8210150285 8210130550* 8208870097 8210120319*	RES 50-269 Q PR 50-148 H GA999	BAUER.E G BAUER.T L BAUM.S L BAUM.S L BAUMACK.W	8210220007* 8210050174 8210250245 8210250245 8210270415	50-27B P 50-192 P 50-247 G 50-247 G 50-410 G	T CHAMANDE BECKMAN, J T BEILMAN, T P BELANGER, J L BELANT, J L	8210120047 8210150329 8210040205* 8210050110* 8210040162*	50-366 P 50-321 P 50-315 S 50-305 G 50-305 S
GARNES, I BARNETT, J E BARNUM, E C BARON, J S BARON, J S	8210260558	GA999 70-1621 XPORTLIC 50-322 T 50-322 T	BAUNACK, W H BAUSER, M A BAYTER, F BAXTER, T A BAXTER, T A	8210290173* 8210290259 8210070160 8210120262 8210120262	50-244 Q PR 50-443 A 50-483 Q 50-483 G	BELISLE, O A BELISLE, O A BELL, J M BELL, J M BELL, J M	8210150052* 8210150256* 8210160176* 8210160270* 8210160275*	50-324 G 50-327 G FOIA FOIA FOIA
BARON.J S RAROM.J S BARP.K CARR.K BARP.K P	8210150290 + 8210150290 + 8210150136 + 8210220341 + 8210010122 +	50-322 T 50-322 T 70-824 50-160 G 50-83 O	BAKTER, T A BAKTER, T A BAKTER, T A BAKTER, T A BAKTER, T A	8210200009 8210200009 8210200013* 8210200013*	50-400 Q 50-400 G 50-400 G 50-400 G 50-483 G	BELL.J M BELL.J M BELL.J M BELL.M J BELL.M J	8210180298* 8210180301* 8210180417* 8210120131 8210120173	FOIA FOIA FOIA WASTE HOT PR
DARR,K P BARR,K P BARR K P BARR K P BARR,X P	8210010127* 8210010137* 8210150086* 8210150358* 8210220356*	70-1201 50-324 0 50-348 0 50-335 0 50-280 0	BACTER.T A BACTER.T A BACTER.T A GACTER.T A GACTER.T A	8210210365 8210250248 8210250248 8210250253* 8210250253*	50-483	BELL.M J BELL.N BELLAMY.R BELLAMY.R BELLMAN.T P	8210120375 8210050389 8210050537 8210070245 8210170757#	HASTE HQT 50-522 Q 50-320 P 50-289 S 50-315 S
DARR,K P BARR,K P BARRETT,D J CARRETT,L	8210220401	50-259 Q 70-1113 50-327 Q 50-245 P 50-247 P	BAKTER,T A BAKTER,T A BAYLOR,V B BAYLOR,V B BAYNARD,P Y	8210280360 8210280360 8210060425 8210180407 8210060198	50-289 G 50-289 G RES RES 50-302 P	BEMIB.P R BENDER,M BENDER,P C BENNECHE,P E BENNETT,A B	8210010436* 8210040374* 8210120132* 8210080237 8209270240*	50-369 Q 50-320 S 50-400 Q 50-62 P
GARRETT, L H BARRETT, L H BARRETT, L H BARRETT, L H BARRETT, L H	8009100100 8009100104 8210070043 8210070150 8210190012	50-247 P 50-247 P 50-320 R 50-320 R 50-320 R	CAYNARD, P Y BAYNARD, P Y BAYNARD, P Y BAYNARD, P Y BAYNARD, P Y	8210060263 8210150216 8210150681 8210150691 8210210421	50-302 P 50-302 P 50-302 P 50-302 P 50-302 P	BENSINGER, P B BENTON, J W BERGHOLZ, N E BERGHOLZ, N E	8210130399 8210210159* 8210210159* 8210050184 8210060185	PR 50-382 0 50-397 0 50-537 0
BARRETT, L H BARRETT, L H BARROWS, J BARRY, L W BARTH, C A	8210190052 8210190127 8210260202 8210050572* 8210200062	50-320 P 50-320 R 50-309 H FOIA 50-400 G	BAYNARD, PY BAYNARD, PY BAYNARD, PY BAYNARD, PY BAYNARD, PY	8210220207 8210220375 8210260010* 8210260310* 8210260377*	50-302 P PR 50-302 F 50-302 Q 50-302 Q	BERGHOLZ, W E BERGHOLZ, W E BERGHOLZ, W E BERGHOLZ, W E DERLIN, K	8210060200 8210130343 8210130435 8210200057 8210150474	50 537 Q 50-537 Q 50-537 Q 70-143 50-528 Q
DARTH.C A BARTINE,D E BARTLETT.J BARTOLINI.R P	8210270087 8210290006# 8210150135 8210180401# 77	50-255 G COMMISSION 50-220 B CONIRACT 50-206 P	BAYNARD, PY BAYNARD, PY BAYNARD, PY BAYNARD, PY BAYNARD, PY	8210260422 8210260436 8210260454 8210260497 8210290186	50-302 P 50-302 P 50-302 P 50-302 P 50-302 S	BERLIN, K BERLIN, K BERLIN, K BERLIN, K	8210150499 8210150499 8210150512* 8210150512* 8210290297	50-528 0 50-528 0 50-528 0 50-528 0 50-528 0
	23 23 17 32 32	TOPREP TOPREP 50-361 P 50-206 P 50-363 A	Y Q.GRANYAD Q L.JANYAB Q L.JANYAB Q L.JANYAB Q L.JANYAB	8210290312 8210040213* 8210040317 8210050079 8210050083	50-302 8 50-286 F 90-333 Q 50-286 F 50-333 F	BERNABEI, L BERNABEI, L BERNABEI, L BERNABEI, L BERNHOFT, S L	8210150449 8210150447 8210150457* 8210150457* 8210040159*	30-358 0 50-358 0 50-358 0 50-358 0 80-305 8
)4 '6 4 14 20	50-361 P 50-206 P 50-206 P 50-361 P 50-361 P	PL, JANYAB PL, JANYAB PL, JANYAB PL, JANYAB PL, JANYAB	8210040181 8210120253 8210150031 8210170411 8210170713	50-286 P 50-247 P 50-286 P 50-333 Q 50-286 H	BERNHOFT, B L BETTENHAUSEN, L BETTENHAUBEN, L BETTENHAUBEN, L BETTENHAUBEN, L	8210170356* 8210070263* 8210070330* 8210210097* 8210210162*	50-305 S 50-293 Q 50-277 Q 50-354 Q 50-272 Q
	75 19 19 12	50-206 F 50-206 P 50-206 P 50-206 P 50-395 H	P ,3MYAB B A Y. ANYAB P , ANYAB P , ANYAB P , ANYAB	8210190728 8210190738 8210200028 8210200039* 8210200074	50-284 P 50-284 F 50-333 P 50-333 P 50-333 P	BETTENHAUBEN, L BETTENHAUBEN, L BHATIA, P BIBB, H E BICKFORD, W E	8210270132* 8210270356* 8210120430 8210220303* 8210120072	50-322 Q 50-322 Q REB 50-335 Q NUREO
	15 ** 11 ** 8 * 10 * 11 *	50-289 Q FÖIA FOIA FOIA FOIA	Bayne, J P Bayne, J P Bayne, J P Bazin, J P Bazin, J P	8210210459 8210210470* 8210280070 8210180329 8210270199	50-286 P 50-286 P 50-286 P CONTRACT CONTRACT	BICKFORD, W E BICKWIT, L BICKWIT, L BIDINGER, G H BIDINGER, G H	8210120102 8210120254 8210120314 8210040397* 8210220028*	NUREO 50-289 0 50-289 0 70-371 70-1257
	0+ 7+ 0+ 5+ 7+	FOIA FOIA FOIA FOIA	BEAMER, W H BEAMER, W H BEAMER, W H BEAMER, W H BEAMER, W H	8210180215* 8210180217* 8210180222* 8210180234* 8210180251*	FOIA FOIA FOIA FOIA	BIDINGER.O H BIELAWBKI.A P BIELAWBKI.A P, BILLIG.P F BILLB.J M	8210270436* 8210030391 8210050391 8210010224* 8210060390*	70-115k 50-454 e 50-454 e TOPREP 50-317 s

\$11.;ELI,B L 8210190493* 50-295 5 BLOCH,P B 8210210349 50-155 0 BOUCHEY,O D 8210050194 50-181;ELI,B L 8210240411* 50-295 5 BLOCH,P B 821022042* 50-244 0 BOUCHEY,O D 8210050348 50-181;ELI,B L 8210310417 30-528 0 BLOCH,P B 821022042* 50-244 0 BOUCHEY,O D 8210040373 50-181;ELI,B L 8210270171 50-528 0 BLOCH,P B 8210220338 50-155 0 BOUCHEY,O D 8210040373 50-181;ELI,B L 8210270171 50-528 0 BLOCH,P B 8210220338 50-155 0 BOUCHEY,O D 8210040317 50-181;ELI,B L 8210270171 50-528 0 BLOCH,P B 8210220338 50-155 0 BOUCHEY,O D 8210040317 50-181;ELI,B L 8210270171 50-528 0 BLODETT,T H 821040072 50-389 R BOUCHEY,O D 821004045 50-181;ELI,B L 8210270132 50-329 0 BLODETT,T H 8210150431 50-389 R BOUCHEY,O D 8210080075 50-181;ELI,B L 8210270132 50-329 0 BLODETT,T H 8210150431 50-389 R BOUCHEY,O D 8210280075 50-181;ELI,B L 8210270136 50-329 0 BLODETT,T H 8210240114 50-389 R BOUCHEY,O D 8210120174 30-181;ELI,B L 8210270136 50-329 0 BLODETT,T H 8210240114 50-389 R BOUCHEY,O D 8210120174 30-181;ELI,B L 8210270136 50-329 0 BLODETT,T H 8210240114 50-389 R BOUCHEY,O D 8210120177 50-181;ELI,B L 821020045 50-329 0 BLODETT,T H 8210240114 50-389 R BOUCHEY,O D 8210120177 50-181;ELI,B L 8210200041 50-329 0 BLUBAUGH,R E 8210103022* 50-277 0 BOUCHEY,O D 8210130189 50-181;ELI,B L 8210200041 50-329 0 BLUBAUGH,R E 8210150302* 50-274 0 BOUCHEY,O D 8210130179 50-181;ELI,B L 8210200041 50-329 0 BLUBAUGH,R E 8210150302* 50-244 0 BOUCHEY,O D 8210130575 50-181;ELI,B L 8210200041 50-329 0 BLUBAUGH,R E 8210150302* 50-344 0 BOUCHEY,O D 8210130575 50-181;ELI,B L 8210200041 50-329 0 BLUBAUGH,R E 8210150302* 50-344 0 BOUCHEY,O D 8210130575 50-181;ELI,B L 8210200041 50-349 0 BOUCHEY,O D 8210130575 50-181;ELI,B L 821020044 50-206 0 BOUCHEY,O D 8210110045 50-340 BUCHEY,O D 82102100	397 F 397 A 397 K 508 K 508 A 397 F 397 F 397 F 397 E 397 E 397 E 397 E 397 E 397 E 397 A 598 A 404 G MMISSION 507 E 7507 C 7507 C
BINDER B	397 A 397 E 397 A 397 F 397 A 598 K 598 K 397 F 397 F 397 F 397 F 397 F 397 E 397 E 397 E 397 A 4454 G 454 G
SIGNAP.L L SIG	.397 K .508 A .397 A .397 F .397 E .397 E .397 E .397 E .397 E .397 E .397 A .397 B .3
SIGNOPLIC S210200054 50-329 C BLUMBERO,N S210210213* 50-244 C BOUCHEY, C D S210130575 50-314 C S210200061 50-327 C BLUMBERO,N S210210223* 50-334 C BOUCHEY, C D S210190576 50-314 C S210200061 50-327 C BUMBERO,N S210210223* 50-334 C BOUCHEY, C D S210190576 50-314 C S210190576 S0-478 C BOUCHEY, C D S210190576 S0-314 C S210200061 S0-327 C BOUCHEY, C D S210190708 S0-314 C S21020061 S0-324 C BOUCHEY, C D S210190708 S0-314 C S21020061 S0-324 C BOUCHEY, C D S210190708 S0-316 C S21020061 S0-321 S S0UCHEY, C D S210210047 S0-316 C S21020061 S0-321 S S0UCHEY, C D S210210047 S0-316 S S0UCHEY, C D S210210048 S0-316 S S0UCHEY, C D S210210148 S0-316 S S0UCHEY, C D S210210148 S0-316 S S0UCHEY, C D S210210148 S0-316 S S0UCHEY, C D S210210276 S0-316 S S0UCHEY, C D S0UCHEY, C D S210210276 S0-316 S S0UCHEY, C D S0UCHEY, C D S0-316 S S0UCHEY, C D S0UCHEY, C D S0UCHEY, C D S0-316 S S0UCHEY	397 F 397 C 397 F 397 A 397 K 397 E 397 D 454 Q MMISSION 501 P JIEW GRP JIEW GRP
Signor S	-397 K -397 E -397 E -397 E -397 A -508 A -454 G -454 G -454 G -537 G -317 F -71EW GRP -799
SISMOP, T N B210080210 50-206 Q BOLT, S E B210050504 RES BOUCHEY, O D B210210327 50- SISMOP, T N B210080212 50-206 Q BOMBERGER, C B2101800264 50-346 P BDUCHEY, O D B210270012 50- B15MOP, T N B210190250 50-361 S BDOY, H E B210060126 50-228 Q BOMEN, L A B2101801464 50- B15MOP, T N B210190478 50-341 Q BOW, H E B2100601314 50-228 Q BOWEN, L A B2102990064 COM-	-508 A -454 G -455 CON -537 O -317 F JIEW GRP JIEW GRP
Bighib'l k profit and a profit	JIEW GRP JIEW GRP
SISHOP.T H 8210280887 50-275 0 800K.H E 8210080311 > 70-754 BOWMAKER.N J 8210150423 50- 21540P.T H 8210280324 50-275 0 800K.H E 8210130152 State Prog 80YD.R S 8210120326 RCV	
ELAKAR L 8210150309* 50-322 9 BODK, H E 8210190632 50-27 0 BOYLE, R 8210120322 WAS BLAKKR L 8210150324* 50-322 9 BODK, H E 8210170636* 50-27 0 BOYLE, R R 8210120324 WAS	
ELACARI 8210150393* 50-322 9 BOOK.H E 8210280248* 50-397 9 DRADBURY.R D 8210220348 PR ELACARI 8210150402* 50-322 9 BOOK.H 9 8210190605 50-312 9 BRADBURY.R D 8210290237 PR ELACARI 8210150410* 50-322 9 BOOKER, J E 8210050201 50-458 8 BRADFORD.L 8210050217 50-458 LACARI 8210150422* 50-322 9 BOOKER, J E 8210050217 50-458 8 BRADFORD.L 8210050237 50-	-269 Q -289 G -289 H
LACAR L 8210190370 50-312 0 BOOKER, J E 8210130182 90-458 8 BRADLEY, E J 8207090201 50- LLAK, R L 8210190373 50-522 0 BOOKER, J E 8210130516 50-458 S BRADLEY, E J 8209170149 50- LLAK, R L 8210190381 50-312 0 BOOKER, J E 8210190367 90-458 S BRADLEY, E J 8210160276 50-	-348 Q -278 P -352 F -277 J -352 A
ELAYMR L 8210280291 90-322 0 BOOKER, JE 821019027 50-458 5 BRADLEY, E J 8210190377 50- ELAYM, B 8210120124 RES BOOKER, J E 8210200037 50-458 5 BRADLEY, E J 8210200046 50- ELAYMAN, H S 8210120124 RES BOOKER, J E 8210220376 PR BRADLEY, E J 8210200064 50- ELAYMAN, H S 82101202657 RES BOOKER, J E 8210220376 PR BRADLEY, E J 8210200066 50-	-352 C -277 P -277 P -278 P -278 P
ELMA,JL 8210080215* FOIA DOMER.JE 8210260292 90~458 5 BRADLEY.E J 8210260158 50- ELMR.B S 8210250356 PROJ BODKER.JE 8210270263 PR BRADLEY.F J 821020321 PR ELMR.B S 8210250356 PROJ BODG.A 8210260504 30~329 T BRANCH.H W 8210150502* 50- FLMR.B 5 8210250356 PROJ BODG.A 8210260504 50~329 T BRANCHBOURO,D 8210260081 50-	-352 A -409 G -247 G -247 G
ELAPE, EL 8210080094 50-287 0 BORDENICK, D 8210250059* 50-322 Q BRANDENBURO, B 8210290271 50- ELAPE, EL 8210080094 50-287 0 BORDENICK, DM 8210040011 50-322 0 BRAUND, C D 8210190787* 50-	-247 Q -247 Q -440 Q -254 F
SLME, E L 8210200033 50-287 9 BORDENICK, B M 8210150117 50-322 Q BRENNER, L 821010354 S.ME, E L 8210200033 50-287 0 BORDENICK, B M 8210200036 50-322 0 BRENNER, L 8210210383 1.ME, J 8210150170* 50-324 Q BORDENICK, B M 8210280209 50-322 0 BRENNER, L 8210220332 ELME, J 8210150404* 50-257 Q BORDENICK, B M 8210280209 50-322 0 BRENNER, L 8210220332 ELME, J 8210220218* 50-424 Q BORDENICK, B M 821030471* 50-155 G BRENNER, L 8210120460	
BLAKE, J 8210010091* 50-400 G BORDINE, T C 8210150505 50-155 P BLAKE, J B210010110* 50-413 G BORDINE, T C 8210250371 50-155 F BLAKE, J 8210010124* 50-267 G BORDINE, E A 8210050137 50-358 8 \$1AKE, J 8210010303* 50-389 G BORDINE, E A 8210050332 50-358 K \$1AKE, J 8210010314* 50-338 G BORDINE, E A 821005032 50-358 K	
HARLJ B210010447* 50-416 G BERGMANN,E A 8210060309 50-358 B NAME,J J B210150063* 50-324 G BERGMANN,E A 8210060358 50-358 B HAKE,J J 8210190114* 50-324 G BERGMANN,E A 8210130372 50-358 B HAKE,J J 8210190123* 50-359 G BERGMANN,E A 8210180387 50-358 K BANKHARD,B 8210040322 50-413 D BERGMANN,E A 8210150443 50-358 S	
RASIAN,L J 8210040183* 50-220 P BOROMANN.E A 8210260279 50-358 8 RAMER.H M 8210150230* 50-322 T BOROMANN.E A 8210260488 50-358 E BLAKER.H M 8210150250* 50-322 T BOROMANN.E A 8210270281* 50-358 G BLAKER.H M 8210150257* 50-322 T BOROMANN.E A 8210270285* 50-358 G BLAKER.H M 8210150257* 50-322 T BOROMANN.E A 8210270285* 50-358 G	
BLOCH,PB 8210070137 50-440 9 BORBT,FJ 8210280382 71-9044 BLOCH,PB 8210120337 50-440 9 BORBT,FJ 8210190359+ 50-346 8 BLOCH,PB 8210130329 50-440 9 BOUCHEY,OD 8210010020 50-508 H BLOCH,PB 8210200027 50-266 Q BOUCHEY,OD 8210050126 50-397 E	

AN THOR	ACCESSION REGNUN	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT	AUTHOR	ACCEB910N NUMBER	5 3 € - CATE, -
GRINAMAN, RE BRINAMAN, RE BRINAMAN, RE BRINAMAN, RE BRINAMAN RE	8210180152* 8210180157* 8210180363* 8210180372* 821018037J*	FOIA FOIA FOIA FOIA FOIA	BUCK, J R BUCK, J R BUCFLES, J BURDOIN, J F BURGER, C	8208290012 8208290012 8210040313 8210040141* 8210010204*	ACRS ACRS 50-315 J 50-275 Q 50-325 Q	CAREY, J J CAREY, J J CARLSON, J D CARR, A V CARR, A V	8210270267 8210270268* 8210280303* 8210250125 8210250282	50 334 50 324 (50-275 50 413 (
ERINAMAN, R E NA MANAN, R E SPINAMAN, R E SPINAMAN, R E SPINAMAN, R E	8210180377+ 8210180386+ 82101803834 8210180386+ 8210180387+	FOIA FOIA FOIA	BURGER, C BURGER, C BURGER, C BURGER, C BURGER, C W	8210220173* 8210220503* 8210220504* 8210010205* 8210010397*	50-324 0 50-324 0 50-261 0 50-324 0 50-400 0	CARR, A V CARR, S E CARR, S E CARRICO, J B CARRICO, J B	8210240415 8210050300: 8210210064: 8210220066 8210220092:	20 421 COV +4.1 COV, F1 7 40 811
BRIMANAR E BRIMANAR E BRIMANAR E BRIMANAR E BRIMANAR E	8210180371* 82(0180374* 8210180377* 8210180399* 8210180402*	FOIA FOIA FOIA FOIA	BURGER, C W BURGER, C W BURGER, C W BURGER, F J BURGESS, B L	8210170300 8210170657 8210220163* 8210130173* 8210170750*	50-324 S 50-324 S 50-400 G 50-271 R 50-329 O	CARTER, R E CARTER, R B CARTER, R B CARTER, B CARTER, B D	8210180014 8210130160 8210130163: 8210290321: 8210060422:	50 62 50 184 50 184 50 457 50 457
OFINAMAN, REORINAMAN REORINAMAN REORINAMAN REORINAMAN REORINAMAN ROORINAMAN RE	6210180406* 6210180409* 8210150496 6210060354* 8210050026*	FOIA FOIA 12E 50-261 F REGGD	BURKE, D J BURKE, E M BURKETT, P T BURNETT, P T BURNETT, P T	8210010245* 8210260504 8210010151* 8210010176* 8210010472*	50-280 0 50-327 T 50-416 Q 50-261 Q 50-395 Q	CARTWRIGHT, W CARTWRIGHT, W CARTWRIGHT, W CARTWRIGHT, W CARTWRIGHT, W CARTWRIGHT, W R	8207230301 8207230301+ 8210010140 8210010145+ 8210010163	59-33 (59-33 (50-378 (50-378 (50-374 (
BRODSKY, A BRONS, J C BRONS, J C BROOKS, D BROOKS, E	8210270331 8210160391 8210180088 8210120353* 8210010208*	NUREC 50-286 F 50-286 R WASTE MOT 50-348 O	BURNETT, P T BURNETT, R F BURNETT, R F BURNETT, R F BURNETT, R F	8210150143* 8210070047* 8210070445* 8210070471* 8210070482*	50-269 Q 50-537 D FOIA FOIA	CARTWRIGHT, W R	8210010739* 8510010531 8510010514* 8510010100*	10 31- 1 50 31- 1 50 31- 10 31-
GROOMS, E H GROOMS, W OROULL C H GROUMS E J BROUMS, E J	6210010432+ 8210210200+ 8210150384+ 8110010072+ 8111040084+	50-259 Q 50-271 P 50-243 Q FGIA 50-313 S	BURNETT,R F BURNETT,R F BURNETTE,R D BURNES,R A BURNES,S	8210180107* 8210190095* 8210080258* 8210190435* 8210150236	70-143 REVIEW GRP 50-267 P 50-333 Q DRG	CARTWRIGHT, W R	8210080182 8210080105 b 8210190264 8210190270 b 8210190729	50 43 1 50-03 1 50-03 1 50-03 1
BROWN, E J BROWN E J BROWN, E J BROWN, E J	6209/50106+ 6210070104 6210070111 6210120093 6210120372	50 261 P 50-313 S 50-348 S MISC MISC	BURNS.S C BURSEY.B BURSTEIN.S BURNELL,S B BUSCH.S L	8210150090 8210150458 8210050055 8210210025 82100700994	MISC 50-395 0 50-266 P 50-445 A 50-29 P	CARTWRIGHT, W R	821019033/• 8210220227 8210220234% 8210220415 8210220421%	50 3 3 1 50 3 3 1 50 3 4 1 50 3 4 1 50 3 4 1
BROWN O D BROWN O D BROWN O D BROWN O D	821070389 8210220123 8210220161 8210220464 8210280180	40-4622 40-1162 40-2259 40-4622 40-7580	BUSCH, S. L. BUSS, R. D. BUTLER, W. B. BUKTON, L. D.	B210120300* B210120425* B210130390* B210040379* B210050397	50-213 P CONTRACT 50-254 R FOIA NOREG	CARTWRIGHT, W R	8210220441 82102204501 8210240201 8210240287* 8210240290	50 34 1 1,000 1 1,000 1 1,000 1 1,000
BROWN H H GROWN H H GROWN H H BROWN H H	8210050180 8210050180 8210050189 8210050189 8210250097	50-275 0 50-275 0 50-322 0 50-322 0 50-275 P	BYRD, R BYRD, R BYRD, R BYRD, R BYRD, R	8210080127# 8210080289# 8210080298# 8210220274# 8210220431#	50-416 S 50-416 S 50-416 S 50-416 S 50-416 S	CARTWRIGHT, W R	8210260293# 8210260346 8210260360# 8210290337 8210290347#	50 3/3 5/ 13 1/5 00 11 1/5 00 11 1/5 00
BROWN R C BROWN R C BROWN R C	8210290097 8210040214* 8210010231 8210070281 8210220171*	50-275 P 50-443 Q 70-2873 40-8745 40-2259	BYRD, R BYRD, R BYRD, R W CAGNETTA, J P CAGNETTA, J P	8210220462* 8210270345* 8210270355* 8210130280 8210130331	50-416 S 50-416 S 50-416 B PRM 50-213 P	CARUSO, R CARUSO, R CARUSO, R CARUSO, R CARUSO, R	8210070085 8210070167 9210120207 8210120245 8210120272	50 29 F1 50 29 F1 50-29 F2 50-27 F2
BROWN, R C BROWNLEE, V L BROWNLEE, V L BROWNLEE, V L	6210010469+ 621001031+ 6210010327+ 6210103250+	50-537 A 50-537 A 50-321 Q 50-321 Q 50-321 Q	CAGNETTA, J P CAGNETTA, J P CAHLL, W J CAIN, C L CAIN, C L	8210130331 8210130331 8210040215 8210070374* 8210220070*	50-213 P 50-213 P 50-458 K 40-4622 40-8111	CARUSO, R CARVER, A M CASE, E O CASEY, B J CASHMAN, D C	821021012J 8210010115 8210260939 8210170720 8210260246	50 247 F 50 247 F 50 241 F 50 241 F
BROWNLEE, V L BROWNLEE, V L BROWNLEE, V L BROWNLEE, V L BROWNS, R J	6210150103+ 6210190271 6210220159+ 6210220232+ 6210120125	50-424 Q 50-302 B 50-424 Q 50-348 Q NUREO	CAIN,C L CAIN,J CALDWELL.R A CALL.V B CAMPRELL.D	8210240084 8210240084 8210240301* 8210270288* 8210170040*	40~1162 WASTE MGT 50~278 Q 50~155 P 50~315 F	CASSEL, D W CASSEL, D W CASSEL, D W CASSEL, D W CATCHPOLE, G J	8210210346 8210210345 8210210347+ 8210210347+ 8210240377	50 454 8 2 50 454 8 2 50 446 8 2 50 434 8 2 40 6745
BRUCE, W R BRUNE, R L BRUNMER, E BRUNMER, E BRUNMER, J E	8210120432* 8210060004 8210010007 8210220255 8210050246	CONTRACT NUREQ 50-220 9 50-339 9 50-329 0	CAMPBELL. J E CAMPBELL. J E CAMPBELL. M A CAMPBELL. R H CANTER. H	8210290138 8210290379 8210190530 8210250025	50-259 S RES State Prog WASTE MOT 50-312 S	CAUDLE, R E CAVANAUDH, H CAVANAUDH, H CAVANAUDH, H CHAIKEN, J A	8210070409 8210040109 8210250159 8210260180* 8208290098	71-7150 50 313 / 50 368 / 50 313 1 FOIA
DRUNNER. J E DRUNNER. J E DRUNNER. J E BRYAN, R H BRYAN, V J	8210040193 8210180212 8210220381 8210030304 8210240084	50-329 G 50-329 G 50-329 G RES 40-8452	CANTER: H L CANTRELL: F S CANTWELL: F S CANTWELL: P E CAPHTON: D L	8210060336* 8210150032* 8210150334* 8210180175* 8210210056*	50-312 Q 50-416 Q 50-518 Q 50-304 B 50-289 Q	CHAN, T L CHANDLER, J C CHANDLER, J C CHANDLER, J C CHANDLER, L J	8210060393 8210120230 6210150511 8210270164 8210040009	50-015 4 50-016 1 10PPEP 10FFEP 50-041 1
DRYANT, J C BRYANT, J C BRYANT, J C BRYANT, J C	8210280446 6210010166* 8210010436* 8210010474* 8210170447	40~8452 50~269 0 50~369 0 50~269 0 50~287 S	CAPHTON.D L CAPHTON.D L CAPHTON.D L CAPRA,L A CAPRA,L A	8210210213* 8210210296* 8210290072* 8210040335* 8210040340*	50-244 Q 50-334 Q 50-287 Q QA777 QA777	CHANDLER, L J CHANDLER, L J CHAPLIN, B D CHARNLEY, J B CHARNLEY, J 8	8210180075 8210220240 8210150289# 8210170810 8210250074#	50-361 4 50-361 1 50-320 1 10PAEP 50-260 1
BRYANT, J C BRYANT, R E BUCHANAN, C R BUCHANAN, C R BUCHANAN, C R	82 022047 * 82 0210444* 82 01801 6* 82 0180319*	50-413 0 CGNTRACT FOIA FOIA FOIA	CARALIE, O P. CAREY, J J CAREY, J J CAREY, J J CAREY, J J	8210050213* 8210010013 8210050165 8210060076 8210130561	70-2942 50-334 F 50-334 P 50-334 R 50-334 P	Charnley, J 8 Charterina, J Chabe, J, Chabe, J, W Chaudhary, 8 K	8210290288 8210070181+ 82102205031 8210150032+ 8210290210+	10PREP 50-219 1 50-324 6 50-618 1 50-052 1
BUCHANAN, C R BUCHANAN, C R BUCHANAN, C R BUCHHEIT, R D BUCHHOLZ, R H	8210180324* 8210180370* 8210180375* 8210190420* 8207120147	FOIA FOIA FOIA 50-333 Q 50-447 A	CAREY, J J CAREY, J J CAREY, J J CAREY, J J CAREY, J J	8210150018* 8210150312 8210170747 8210220184 8210240458	50-334 P 50-334 P 50-334 P 50-334 Q 50-334 F	CHECK: P 8 CHECK: P 8 CHECK: P 8 CHECK: P 8	8002140204+ 8003310179+ 8004100193+ 8010210783 8011200025	50-245 7 50-245 7 50-245 7 50-247 1

AUTHOR	NUMBER	SUBJECT CATEGORY		AUTHOR	ACCESSION NUMBER	SUBJECT		AUTHOR	ACCESSION NUMBER	EUBJECT CATEGORY
HECKLP S HECKLP S HECKLP S HECKLP S HERLU C	8203040474* F 8210050477 S 8210060458* S 8210080053	GIA 50-537 A 50-537 D 50-537 D		CHURCHILL, B W	8210080084 8210080090 8210080090 8210180051* 8210180054*	50-382 50-382 50-382 FOIA FOIA	G G	CLAYTON.F L CLAYTON.F L CLEMENTS.W B CLEMONS.P CLEMONS.P E	8210280282 8210290289 8210240042* 8210220255 8210070314*	50-364 P 50-364 S 50-445 Q 50-333 S 70-364
HEN S J MEN S J HENAULT, N H HENAULT, N H HENAULT, N H	8107270176* 8210190567* 8210220150*	50-266 0 50-266 0 50-416 5 50-416 5		CHURCHILL, B W	6210180057* 6210180058* 6210160312* 8210180313* 6210180318*	FOIA FOIA FOIA FOIA		CLEVELAND, J C CLIFFORD, J H CLINE, N E CLOUGH, R H CLOUGH, R H	8210150564 8210220513 8210150401* 8107270176* 8107270182*	NUREG 50-445 A 50-261 0 50-266 0 50-266 4
HENAULT, H H HENAULT, H H HENG, N H HIANOI, N J HEANOI, N J	B210290081* B210270208* B210180141	50-416 S 50-416 S 50-338 P 50-400 S 50-400 S		CHURCHILL, B W CHURCHILL, B W CHURCHILL, B W GHURCHILL, B W CHURCHILL, B W	8210260406 8210280253 8210280253 8210280387 8210280387	50-266 50-266 50-268 50-382 50-382	6 6 6 6 G	CLOUGH, R W CLOUGH, R W CLOUGH, R W CLOUGH, R W CLOUGH, R W	8107270185* 8107270188* 8107270191* 8107270194* 8107270198*	50-266 0 50-266 0 50-266 0 50-266 0 50-266 0
HIFK'S A HIFK'S A HIFK'S A HIFK'S A	8210040102 8210040108 8210060189	70-143 50-275 G 50-247 G 50-133 G 50-287 G		CILIMBERO,R L CILIMBERO,R L CILIMBERO,R L CILLIS,M CILLIS,M	8210040415 8210050538 8210250340 8210060131* 8210250178*	50-315 50-315 50-315 50-228 50-362	0 6 6	CLGUGH.R W CLGUGH.R W COALWELL, I N COAD.J C COOB.L I	8107270199* 8210260211 8210040231 8210210046 8208190237	50-266 Q NUREQ 50 264 J NUREG 50-3 Q
HILK'S A HILK'S A HILK'S A	8210070145 8210070183 8210070192 8210080207* 8210080329	50-275 0 50-201 0 50-537 6 FOIA 100FR		Clpolla, A J Clapp, N E Clark, A T Clark, C W Clark, D	8210150600 8210150564 8210070313* 8210210329 8210200113	40-3392 NUREO 50-537 TOPREP TOPREP	מ	COCHRAN, † B COCHRAN, † B COCHRAN, † B CODELL, R CODELL, R	6210210240* 6210220279* 6210220263* 6007280312 6210050431	50-53/ G 50-537 G 50-537 G 50-247 P NUREG
HITK'S A HITK'S A HITK'S A HITK'S A	8210120332 8210120599 8210130075 8210130087* 8210130101	50-275 0 10CFR 50-289 T 50-289 T 50-395 T		CLARK.K M CLARK.L CLARK.M T CLARK.N E CLARK.P R	8210170621 8210170334 8210120657 8210080276 8210210280	50~424 50~20 RES 50~395 50~219	5 F P	COHEN, I COHEN, K D COHN, B M COLARULLI, P F COLARULLI, P F	8210290107* 8210070485* 8210270230* 8210250272 8210250272	50-220 G FGIA CONTRACT 50-247 H 50-247 H
HILKIS J HILKIS J HILKIS J HILKIS J	8210130106# 8210130327 8210130336 8210150193 8210150404	50-395 T 50-275 G 50-397 G 50-133 G 50-437 G	•	CLARK, R A CLARK, R A CLARK, R A CLARK, R A CLARK, R A	81102700504 8207210514 8210010018 8210040044* 8210040413	50-266 50-309 50-317 50-335 50-309	ይ ይ	COLDURNIT G COLBURNIT G COLBURNIT G COLEIR X COLEIS	8110300460* 8210270274 8210279426 8210050377 8210260232	50-266 P 50-266 P 50-266 P NUREG 50-322 T
HILKES A HILKES A HILKES A HILKES A	8210130472 8210180180 8210180182 8210170178* 8210200011	70-143 50-269 50-413 FOIA 50-269	•	CLARK, R A CLARK, R A CLARK, R A CLARK, R A CLARK, R A	8210040414 8210040420# 8210040427# 8210050484 8210050504#	50-266 50-266 50-266 50-317 50-309	6 6 6	COLEMAN, J M COLEMAN, J M COLEMAN, J M COLEMAN, J M	8210260239# 8210260367 8210260367 0210260373 8210260373	50-322 T 50-338 G 50-338 G 50-338 G
HITK'S A HITK'S A HITK'S A HITK'S A	B210210422 B210210427 B210210428 B210210493 B210210508	50-327 50-267 50-267) 3 7 9 7	CLARK, R A CLARK, R A CLARK, R A CLARK, R A CLARK, R A	8210050507# 8210070012 8210070057* 8210070060* 8210070117*	50-309 50-344 50-309 50-309 50-317	P P P	COLEMAN, R COLEMAN, R COLEY, J L COLEY, J L COLEY, J L	8210170217 8210270376 82100101104 8210150114* 8210220218*	CONTRACT CONTRACT 30-413 0 50-324 0 50-424 0
+LFK'8 1 +LFK'8 1 +LFK'8 1 +LFK'8 1	8210220249 8210220416 8210220473 8210250010 8210250460	50-275 50-382 50-387	P T G P G	CLARK, R A CLARK, R A CLARK, R A CLARK, R A CLARK, R A	8210070130* 8210120134 9210130599 9210190008 8210210507	50-317 50-317 50-213 50-313 50-336	₽ የ 0 P F	COLLEY, J A COLLINS, D M COLLINS, J T COLLINS, J T COLLINS, J T	8210040004# 8210180075# 7811200399# 7905290357# 7908130654#	CONTRACT FOIA 50-325 & 50-324 P 50-261 P
AITK'S A AITK'B A AITK'B A AITK'B A	B210260468 B210270161 0210270170 B210280265 B210270446	50~289 50~329 50~320 50~289	0 0 0 0	CLARKIR A CLARKIR A CLARKIR A CLARKIR A CLARKIR A	8210220020 8210250050* 8210250267 8210260551 8210270297*	50-336 50-335 50-307 50-335 50-266	ե ե ե	COLLINS.J T COLLINS.J T COLLINS.J T COLLINS.J T	9210220030 9210280024* 9210280027* 9210280042*	8tate frog 50-324 P 50-324 P 50-261 P
HELK-S J HERANAL-M HERANAL-M HERANAL-M	8103050787* 8104270103* 8107080417* 8112010310* 8201050061*	50-327 50-366 50-302 50-336 50-324	P 8 8 8	CLARK.R A CLARK.R A CLARK.R A CLARK.R A CLARK.R A	8210270303* 8210280210 8210270038 8210270042 8210270413	50-266 50-344 50-285 50-338 50-344	P	COLLINS. H COLLINS. H COLLINS. P L COLLINS. R M		
IIRAMAL: M FIRAMAL: M FIRAMAL: M IRAMAL: M JRAMAL: M	8201170538* 8203170060* 8204210287* 8210050027*	50-346 FDIA 50-416 50-348 50-346	8 8 8	GLARK.R A GLARK.R A GLARK.R A GLARK.R A GLARK.R A	B210270416* B210270421* B210270428* B210270431* B210270441*	50-338 50-317 50-264	P P			
IRAHAL M IRAHAL M IRAHAL M IRAHAL M IRAHAL M IRAHAL M	B210070122 B210070442 B210070440 B210070470 B21008001B	50-327 50-324 50-346 50-346 50-336	8 8 8	CLARK, R. A CLARK, R O CLAUSS, J M CLAY, E L CLAYTON, F L	92102904444 92102900414 92100104604 9210010399 9210010129					
IRAMAL, M IRAMAL, M IRAMAL, M IRAMAL, M IRAMAL, M	8210080067 8210120155 8210120171 8210120369 8210220519	50-339 50-293 50-321 50-272 50-333	8 8 8	CLAYTON, F L CLAYTON, F L CLAYTON, F L CLAYTON, F L CLAYTON, F L	6210010195 6210050066 6210050087 621013027 621013052					
DNG.L A RIGSOTINOS.N RIGITAN.J N RIBITAN.J N RIBITAN.J N	8210080055# 801104056# 8210150279 8210150279 8210050311#	50-322 50-322	D 8 0 0	CLAYTON, F L CLAYTON, F L GLAYTON, F L CLAYTON, F, L CLAYTON, F, L	821015007 8210150331 821019040 8210190722 821019074					
RESTOPHER, H. RESTOPHER, H. PROHICL: S. H. PROHICL: S. H. PROHICL: S. H. ROHICL: S. H.	8210130174* 8210290057* 8210070124 8210070124 8210080084		0 0 8 8	CLAYTON, F L CLAYTON, F L CLAYTON, F L CLAYTON, F. L CLAYTON, F. L	821025007(821026041; 821026043; 821026045; 821028013;					

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUP FOI CATEGORE
COUNTRY E L CHAPER, E L OK, ER, T B CHAPER, T B OUTER T B	8210640043 8210250048 8210050197 8210050197 8210050326	50-335 P 50-335 P 50-352 C 50-352 C	CORMIER.W H CORRADO, J COSTELLO, J R COTTER, B P COTTER, B P	8210290076 8210120353* 8210120233* 8210200050 8210200056	50-142 G WASTE MGT QA979 50-482 G 50-397 G	CRANE, P A CRANE, P A CREED, J R CREED, J R CRESWELL, J S	8210260359 8210270276 8210050110+ 8210050311+ 8210120380	50-137 / 50-275 / 50-3/5 1 50-3/8 6 50-3/7 8
CONTERT B CONTERT B CONTERT B CONTERT B CONTERT B	8210050382 8210050382 8210070402 8210970402 8210260066	50-352 G 50-358 G 50-358 G 50-358 G 50-352 G	COTTER,BP COUNSIL,WO COUNSIL,WG COUNSIL,WG COUNSIL,WG	8210200087 8209300324 6210010207 8210010207 8210010207	50-70 G 50-213 P 50-213 P 50-213 P 50-213 P	CREWS, J L CREWS, J L CREWS, J L CRISCIONE, J L CROCKER, H W	8210010042 8210010285 8210190731 8210010305 8210150059+	50 205 } MISC 50 344 £ 50-335 \$ 50 322 }
COMMERT B COMMORT L COMMORT L COMMORT L COMMORT B	8210200056 8207180058 8207180050 8207180061 8210270180	50-352 G FOIA FOIA FOIA 40-8502	COUNSIL, H C COUNSIL, H C COUNSIL, H C COUNSIL, H C	8510010315 8510010315 8510010530 8510010530	PR PR PR 50-213 P 50-213 P	CROCKER, H W CROFF, A G CROMER, D L CROSBLE, % L CROSSMAN, W A	8210210142• 821007025 1• 8210180105 821012050 3 8210050399•	50-317 50-413 50-413 5 x r 0 413 4
CONTER CONTERR CORVISSERT S COOK B A COOK H L	8210150091* 8210260483 8210130399 8210120400 8210160415*	50-289 Q 50-289 S PR RES FOIA	COUNSIL.W O COUNSIL.W G COUNSIL.W G COUNSIL.W G	8210010312 8210040120 8210040120 8210050090 8210050090	50~213 P 50~245 F 50~245 F 50~336 P 50~336 P	CROSSMAN, W A CROSSMAN, W A CROUSE, R P CROUSE, R P CROUSE, R P	8210190417+ 8210190452+ 8210050295 8210050296+ 8210050304	50 448 1 50 342 1 50 345 4 50 346 1
1 00% 1 M 1 00% 1 M 1 00% 1 M 2 00% 1 M	0210120243* 8207070419 8207070422* 8210010278 8210010437	50-333 R 50-329 K 50-329 K 50-329 E 50-329 A	COUNSIL.# G COUNSIL.# G COUNSIL.# G COUNSIL.# G	8210050318 8210050118 8210050177 8210050177 8210050179	50-245 P 50-245 P 50-245 P 50-245 P 50-334 P	CROUSE, R P CROUSE, R P CROUSE, R P CROUSE, R P CROUSE, R P	8210090310 8210090313* 8210050333 8210040314 8210080280*	50 345 F 50 345 F 50 345 F 50 345 F
COC+ U U COC+ U U COC+ U U COC+ U U COC+ U U	8210050143 8210080115 8210120274 8210130005+ 8210130264	50-329 S 50-329 R 50-329 A 50-329 F 50-329 F	COUMSIL.W G COUNSIL.W G COUNSIL.W G COUNSIL.W G COUNSIL.W G	8210050179 8210050376 8210060048 8210060048 8210060094	50-336 P 50-213 Q 50-245 P 50-245 P 50-245 P	CROUSE, R P CROUSE, R P CROUSE, R P GROUSE, R P CROUSE, R P	8210180177 8210170303 8210170823 8210210458 8210220013	50-346 P 50-341 k 50-346 P 50-346 P
COUR J U COUR J U COUR J U COUR J U COUR J W	8210130266* 8210190520 8210210294 8210260121 8210260175*	50-329 K 50-329 E 50-329 A 50-329 S 50-329 O	COUNSIL. W G COUNSIL. W G COUNSIL. W G COUNSIL. W G	8210040074 8210040233 8210040233 8210040237 8210040237	50-245 P 50-245 Q 50-245 Q 50-336 P 50-336 P	CROUSE.R P CROW.W T CROW.W T CROW.W T	8210260260 8210040397* 8210210514 8210210593 8210220028*	90 345 # 70 371 70-111 70 35 70-1-37
100% 7 W 100% 7 M 100% 7 M 100% 7 M	B210280076 B210290163* B210290228 B210290229* B210290380*	50-329 S 50-329 Q 50-329 A 50-329 Q	COUNSIL. H G COUNSIL. H G COUNSIL. H G COUNSIL. H G COUNSIL, H G	B210070354* B210070356* B210080105 B210130331 B210130331	50-245 0 50-245 0 50-423 A 50-213 P 50-213 P	CROWLET CROW, W T CROW, W T CROWLET, B R	8210270436+ 8210280421+ 8210270211 8210270772+ 8210210124+	70 1851 70 1957 70 1723 70 2744 50-217 8
COOKEY, M J COOKEY, M J COOKEY, M J COOKEY, M J	8210190750* 8210050017 8210060017 8210060047 8210060074	50-329 Q REGGD 50-278 S 50-277 S 50-277 S	COUNSIL, H G	8210130331 8210130399 8210170555 8210170555 8210170663	50-213 P PR 50-423 S 50-423 S 50-213 P	CRUTCHFIELD, D CRUTCHFIELD, D CRUTCHFIELD, D CRUTCHFIELD, D CRUTCHFIELD, D	8109280484 ¥ 82100100a3 82100400a2 82100400a7 8210040099	50 213 F 50 213 F 50 407 F
T M. (3N00) L M. (3N00) L M. (3N00) L M. (3N00)	B210040083* B210040177 B210040353 B210070177 B210130226	50-277 S 50-277 S 50-277 S 50-277 G 50-278 S	COUNSIL. H G	8210210340 8210210340 8210250290 8210250290 8210250329	50-423 S 50-423 S 50-423 S 50-423 S 50-423 S	CRUICHFIELD, D GRUTCHFIELD, D GRUTCHFIELD, D GRUTCHFIELD, D GRUTCHFIELD, D	821004013+1 82100402+1 82100402+5+1 8210050059 8210050045	50 27 F 50 219 F 50 244 F 50 409 F
COCHEY, M J COCHEY, M J COCHEY, M J COCHEY, M J COCHEY, M J	8210150154 9210150179* 9210150400 8210230190 9210240112	50-277 S 50-277 S 50-277 S 50-277 R 50-277 S	COUMBIL, W G COUMBIL, W G COUMBIL, W G COUMBIL, W G	8210250329 8210260194 8210260194 8210260414 8210260414	50-423 S 50-245 P 50-245 P 50-245 P 50-245 P	CRUTCHFIELD, D CRUTCHFIELD, D CRUTCHFIELD, D CRUTCHFIELD, D CRUTCHFIELD, D	82100500/2 8210070010 8210070404 8210120276 6210130088	00 ±55 F 00 213 F 50-213 F 50 213 F
CODNEY M J COOPER, J W COOPER, J W COOPER, J W COOPER, W E	8210240329 8001080054* 8102280195* 8210180148* 8210080191	50-277 P FOIA FOIA FOIA FO-275 P	COUNSIL, H O	8210260459 8210260519 8210260519 8210260519 8210270200	50-245 P 50-245 P 50-245 P 50-245 P 50-213 P	CRUTCHFIELD, D CRUTCHFIELD, D CRUTCHFIELD, D CRUTCHFIELD, D CRUTCHFIELD, D	8210130097 8210130205 8210130375 8210180059 8210180065	50 245 F 50 213 F 50-407 F 50-237 F 50-206 F
COOPER W E COOPER, W E COOPER, W E COOPER, W E COOPER, W E	8210080193* 8210080272 8210190583 8210190584 8210250147	50-275 P 50-275 P 50-275 P 50-275 P 50-275 P	CONSIL.W G CONSIL.C CONSIL.C CONSIL.C CONSIL.C	8210270200 8210270200 8210060374 8210070275* 8210190244*	50-219 P 50-219 P 50-219 S 50-219 Q 50-261 S	CRUTCHFIELD, D GRUTCHFIELD, D CRUTCHFIELD, D GRUTCHFIELD, D CRUTCHFIELD, D	8210180070 8210180073* 8210180074 8210180077* 8210180082	50-20a # 50-20b P 50-244 P 50-244 P 50-244 P
COOPER.W E COOPER.W E COOPER.W E COOPER.W E COOPER.W E	8210250197 8210250240 8210250291 8210280211 8210280277	50~275 R 50~275 P 50~275 P 50~275 R 50~275 P	CDA.H T COX.H T COX.H T CRAFT.C M CRAIQ.J	8210220247* 8210270078* 8210270339* 8207270240* 8210150247	50-261 8 50-261 8 50-261 8 FOIA 50-271 Q	CRUTCHFIELD, D GRUTCHFIELD, D CRUTCHFIELD, D CRUTCHFIELD, D CRUTCHFIELD, D	8210180087* 8210180094* 8210180110 8210180112 8210180149	50-244 / 50-244 / 50-255 / 50-244 / 50-244 /
CODPER.W E COPELAMD.V G COPELAMD.V G COPELAMD.V G COPELAMD.V G	8210290319 8210130448 8210130448 8210130457* 8210130457*	50-275 R 50-155 G 50-155 G 50-155 G 50-155 G	CRAIO.J Crane.J Crane.P a Crane.P a Crane.P a	8210150388 8210280143 8210010198 8210010404 8210010413*	50-315 Q 50-312 P 50-133 F 50-275 P 50-275 P	CRUTCHFIELD. D GRUTCHFIELD. D CRUTCHFIELD. D CRUTCHFIELD. D CRUTCHFIELD. D	8210180153* 8210180161* 8210180183 8210180183	50-244 # 50-244 # 50-244 # 50-409 # 50-29 #
COPPER.W E CORDARG.H CORDARG.H CORDARG.H C CORDARG.H C	8210250318 8210150204* 8210150250* 8210150223* 8210150257*	50-275 P 50-322 T 50-322 T 50-322 T 50-322 T	CRANE, P A	8210050122 8210050144 8210120278 8210130272 8210130272	50-275 P 50-275 P 50-275 P 50-275 G 50-275 A	CRUTCHFIELD, D CRUTCHFIELD, D CRUTCHFIELD, D CRUTCHFIELD, D CRUTCHFIELD, D	82101706B0 8210200015 8210200016 8210200025 8210200031	50-237 # 50-409 # 50-409 # 50-409 #
CORDARD, H C CORE, H R CORLEY, H O CORLEY, H G CORMIER, H H	8210150290* 8210090303* 8210260527 8210260527 8210150456	50~322 F 50~283 8 50~327 F 50~327 F 50~142 0	Crane, p a Crane, p a Crane, p a Crane, p a Crane, p a	8210150389 8210210044* 8210220371 8210220395 8210250192	50-275 F 50-275 F 50-275 P PR 50-133 R	CRUTCHFIELD, B CRUTCHFIELD, D CRUTCHFIELD, D CRUTCHFIELD, D, CRUTCHFIELD, D	8210200038 8210200041 8210200040 8210200070 8210210224	50-409 # 50-155 # 50-219 P 50-219 # 50-213 #

AUTHOR	ACCESSION NUMBER	CATEGO	NRY	AUTHOR	ACCESSION NUMBER	SUBJE: CATEG	JRY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGOR	
#104618000 #104618000 #104618000 #1046180000	8210210246 8210210336 8210210545 8210210555* 8210210555*	50-409 50-409 50-29 50-29 50-29	P G P P	CUTCHIN.J M D'ANGELO.A J DAHLMAN.L C DALE.L F DALE.L F	8210290100 8210190678* 8210130566* 8210010023 8210040053	50-269 50-397 50-306 50-416	0 0 0 F P	DANESE, F L DANESE, F L DANESE, F L DANESE, F L DANESE, F L	8210050471* 8210270427* 8210270427* 8210270437* 8210270438*	FOIA 70-1510 70-1510 70-1510	
UTCHFIELD, D UTCHFIELD, D UTCHFIELD, D UTCHFIELD, D	8210220105 8210220233 6210220272 6210220368 8210220449	50-244 50-155 50-409 50-155 50-409	P G P P	DALE.L F DALE.L F DALE.L F DALE.L F DALE.L F	8210040264 8210040353 8210060295 8210070044* 8210150013	50-416 50-416 50-416 50-416 50-416	₽ ₽ ₽ F 0	DARIELSON, D H DAVIDSON, D R DAVIDSON, D R DAVIDSON, D R DAVIDSON, D R	8210040308* 8210040144 8210050132 8210130173 8210130177	50-440 50-440 50-440 50-440 50-440	0 K S E A
JTCHFIELD. D JTCHFIELD. D JTCHFIELD. D JTCHFIELD. D	8210250071 8210250124 8210250203 8210250213 8210250310	50-155 50-245 50-237 50-155 50-155	р Р Р	DALE, L F DALE, L F DALE, L F DALE, L F DALE, L F	8210170476 8210170521 8210170566 8210200005 8210200030	50-416 50-416 50-416 50-416 50-416	후 문 문 문	DAVIDSON.D R DAVIDSON.D R DAVIDSON.D R DAVIDSON.D R DAVIDSON.D R	8210130364 8210150233 8210170326 8210170333 8210170683	50-440 50-440 50-440 50-440 50-440	8 6 4 6
JTCHFIELD, D JTCHFIELD, D JTCHFIELD, D JTCHFIELD, D JTCHFIELD, D	8210250323 8210250327* 8210250337* 8210250363 8210260182	50-155 50-155 50-155 50-213 50-217	ե Ե	DALE, L F DALE, L F DALE, L F DALE, L F DALE, L F	8210200064 8210200073 8210210217 8210220334 8210220425	50-416 50-416 50-416 PR 50-416	E P E	DAVIDSON.D R DAVIDSON.D R DAVIDSON.D R DAVIDSON.D R DAVIDSON.D R	8210210079 8210220339 8210220372 8210240009 82102400011*	50~440 PR PR PR 70~2968 70~2968	A
, TL PFIELD, D , TC PFIELD, D , TC PFIELD, D , TC PFIELD, D , TC PFIELD, D	8210260185* 8210260191* 8210260229 8210260296 8210270004	50-219 50-219 50-206 50-237 50-219	Р Р Р	DALE, L. F DALE, L. F DALE, L. F DALE, L. F DALE, L. F	8210260264 8210260412 8210270277 8210280132 8210280135	50-416 50-416 50-416 50-416 50-416	P P Q P	DAVIDSON, D R DAVIDSON, D R DAVIDSON, D R DAVIS, C E DAVIS, F C	8210260337* 8210260419 8210260575* 8210210037 8210180066*	50-440 50-440	t V O
TCHFIELD.D TCHFIELD.D TCHFIELD.D TCHFIELD.D	8210270202 8210270265 8210270270 8210280287 8210280433	50~219 50~155 50~155 50~409 TOPREP	P P P	DALE, L F DALING, P M DALING, P M DALTON, C DALTROFF, S	8210270102 8210120092 8210120102 8210220357 # 8207090208 #	50-416 NUREG NUREG 50-387 50-278	р Н Р	DAVIS, J O DAVIS, J O DAVIS, J O DAVIS, L S	8210070070+ 8210070071+ 8210120135 8210120187 8207110026	50-537 50-537 27-47 40-2061 FULA	Á
TCHEIELD, D TCHEIELD, D TCHEIELD, D TCHEIELD, D	9210270169 9210270175# 9210270183* 9210270316 9210150348	50-206 50-206 50-206 71-5926	P P V	DALTROFF.S L DALTROFF.S L DALTROFF.S L DALTROFF.S L DALTROFF.S L	8210130296* 8210150069 8210210297 8210210330 8210280196	50-277 50-277 50-277 50-277 50-277	9 9 P P	DAVIS.PR DAVIS.PR DAVIS.PR DAVIS.PR DAVIS.PR	8210010245# 8207180080 8207180080 8207180085 8207180085	50~280 ACRS ACRS 50~352	0
ITAGHAN, O E ITAGHAN, O E ITAGHAN, R E ITAGHAN, R E ITAGHAN, R E	8210250110 8210270057 8210050034* 8210070093* 8210070179*	50-70 71-5739 REGOD 50-537 50-537	P A A	DANCE, H C DANCE, H C DANCE, H C DANCE, H C DANCE, H C	8106220165# 8210010088# 8210010106 8210010113 8210010117	50-261 50-335 50-413 50-321 50-269	P Q Q Q Q	DAVIS.R DAVIS.S H DAVIS.S H DAVIS.S H	821020316 8210170276* 8210270380* 8210280301*	PR 50-317 50-317 50-310	9 9 9 9
i]NOMAN.R E IPIDHAH.R E IAY.D IAY.D IAY.D	8210070182* 6210280434 6206270094 6210200026 6210200026	50-537 40-2041 50-322 50-443 50-443	A G G	DANCE, H C DANCE, H C DANCE, H C DANCE, H C DANCE, H C	8210010142 8210010155 8210010158 8210010162 8210010204	50-335 50-335 50-269 50-424 50-348	0 0 0 0	DAVIS, W DAYAL, R DE AGAZIO, A W DE AGAZIO, A W DEAN, V	8210210034 8210120367 821012035 8210290370 8210250465	50-259 RES 50-346 50-346	11 6 6
AN D AN D AN D AN D AN O	8210200035* 8210200035* 8210200042* 8210200047*	50-443 50-443 50-443 50-443 50-443	0 0 0	DANCE, H C DANCE, H C DANCE, H C DANCE, H C DANCE, H C	8210010213 8210010221 8210010235 8210010245* 8210010300	50-389 50-336 50-321 50-280 50-338	0 0 0 0	DEARIEN, J A DEBBAGE, A G DEBBAGE, A G DEDBAGE, A G DEGROOT, D M	8210290017 8210010143# 8210150315# 8210220145* 8210210190	RES 90-413 (50-390 (G
18' % # 18' % # 18' % # 18' % #	8210200049* 8210260091* 8210010268 8210010417 8210040052	50-443 WASTE MG 50-388 50-387 50-387	C S F E	DANCE, H C DANCE, H C DANCE, H C DANCE, H C DANCE, H C	8210010301 8210010309 8210010316 8210010380 8210010424	50-389 50-321 50-250 50-404 50-369	0 0 0	DELGEORGE.L O DELGEORGE.L O DELGEORGE.L O DELGEORGE.L O DELGEORGE.L O	82100402464 82100500564 8210050073 8210050123 82100602684	50-456 (50-373 (50-456 / 50-454 /	0 0 A A
18' 11 11 18' 11 11 18' 11 11 18' 11 11 18' 11 11	8210090325 8210090370 8210060083 8210130122	50-387 50-387 50-387 50-387 50-387	ե Է ե	DANCE, H C DANCE, H C DANCE, H C DANCE, H C DANCE, H C	8210010451 8210010466 8210010467 8210080227 8210150014	50-369 50-395 50-395 50-321 50-369	0 0 0 0	DELGEGRGE.L G DELGEGRGE.L G DELGEGRGE.L G DELGEGRGE.L G DELGEGRGE.L G	8210130370 8210130402 8210220383 8210260308+ 8210280125+	50-454 F PR PR	F Q
8, 7 H 8, 7 H 8, 7 H 8, 7 H	0210130341 0210190297 0210210020 0210210137 0210220102	50-387 50-387 50-387 50-387 50-387	2 8 8 6 8	DANCE, H C DANCE, H C DANCE, H C DANCE, H C DANCE, H C	8210150053 8210150072 8210150078* 8210150074 8210150116	50-370 50-348 50-348 50-424 50-369	0 0 0 0 0	DELGEORGE, L O DELICHATSIOG, M DELICHATSIOG, M DELLA RATTALA DELLA RATTALA	8210270245 8210050428 8210130574 8210060370* 8210210238*	PR NUREG NUREG 70-1100 50-271	
8. K L 8. K L 8. K L 8. K L 18. M L 18	8210220175 8210220364 8210250256 8210250264* 8210250367	50-387 PR 50-387 50-387 50-387	P P P	DANCE, H C DANCE, H C DANCE, H C DANCE, H C DANCE, H C	8210150131 8210150187 8210150253 8210150262 8210150345	50-269 50-338 50-269 50-389 50-335	0 0 0 0	Dellsy, H M Delong, S R Den Ison, E Den Ison, E Den Ison, E	8210010381 8210270251 8210280078 8210080080* 8210250221	PR RECCD 50-275 P 50-275 P 50-275 R	,
9. N H 8. H H 8. H H 8. H H	8210250373* 8210260270* 8210260366 8210260379* 8210270318	50-387 50-387 50-387 50-387 50-387	P Q P P	DANCE, H C DANCE, H C DANCE, H C DANCE, H C DANCE, H C	8210190683 8210220158 8210220204 8210220211# 8210220229	50-269 50-424 50-424 50-424 50-348	5 0 0 0 0	DENISON, E DENISON, E DENNING, R DENNING, R DENNISTON, S F	8210270184 8210270185* 8109240007* 8201190322* 8210210444*	50-275 P 50-275 P FOIA FOIA CONTRACT	
N' 1 H N' 1 H N' 2 H N' 3 H N' 3 H	8210050069 8210060303 8210060321# 8210150175 6210150275	50-440 50-440 50-440 50-440	0 0 0	DANCE, H C DANCE, H C DANCE, H C DANCE, H C DANCE, H C	8210220280 8210220271* 8210220328 8210220331 8210220454	50-335 50-335 50-370 50-280 50-338	Q Q Q Q	DENNISTON, 8 F DENNISTON, 8 F DENTE, T J DENTON, H R DENTON, H R	B210270221* B210270223* B210250181 B107010140* B210010149	CONTRACT CONTRACT TOPREP 50-241 P 50-275 P	
w. 7 k w. 7 k w. 7 k が. 7 k	8210190475 8210250345 8210260383 8210260395 8210260346	50-440 50-440 50-440 50-440 50-440	0 0 0	DANCE, H C DANESE, F L. DANESE, F L DANESE, F L. DANESE, F. L	8210220467 8201060245* 8210050439* 8210050446* 8210050467*	50-413 FOIA FOIA 70-1510 FOIA	Q	DENTON, H R DENTON, H R DENTON, H R DENTON, H R DENTON, H R	8210010161# 8210050030# 8210060473 8210080350 8210120049	50-327 9 REGOD 50-320 P 50-275 P REVIEW GRP	

и пися	ACLESSIO 4	SUBJE		AUTHOR	ACCESSION NUMBER	SUBJE	ORY	ROHTUA	ACCE 49 ICH	bifa Fall
CE ITG I H R	8210160683	50-244	Р	DIETZ. C R	8210010298	50-324	5			- '
TEATLE H R	6210190092	REVIEW		DIETZ, C R	8210010399		a	H O'HOXIG	8210100156	51.9
DENTC . H A	8210190118	REVIEW		DIETZ, C R	8210010473	50-321	5	DIXON'O R	8510130325	
LENTC 1 H R	82102700764		5	DIETZ. C R	8210060320	50-324	S	DI KON, O H	0210190505	1. 1
EENTC / H R	8210270331	arc		DIETZ.C R	8510080181	50-325	s	DI KON' D M	821019051J 8210190557	53.3
Lentou H R	82102900614	FOIA		DIETZ, C R	8210080220	50-325	5	- (B)(1 D H	0210190331	27.16
TF TC I H F	8210270449	50-275	G	DIETZ, C R	8210080221	50-324	5	DIYON, D N	8210220340	\$ -5,
DENTET H R	8210270451+	50-275	Ğ	DIETZ. C R	8210130477	50-325	8	M O'NDAIG	0210320313	F
LEPICH H B	82102704544	50-275	Ğ	DIETZ, C R	8210130489	50-325	5	DIXON G M	0210320478	21.7
EZUSTER R W	8210260592¢	50-201	Ğ	DIETZ, C R	8210150016*		ã	DIXON O M	0210250710	
								א סיאטאום	0210260140	2.1 ~
FEVINCENTIS, J	8210010465	50-443	A	DIETZ, C R	8210150023*		G .	N O MONTO		
CEVINJENTIS J	821c010465 8210040112	50~443 50~443	A	DIETZ, C R Dietz, C R	8210150038*		Q:	DIXON'O M	0210260157	
CEVIT CENTIS J	8210040112	50-443	A	DIETZ, C R	8210150041	50-324	5	W D NOX 14	8210260172	4 - 4
CEU III. ERTIS, J	6210043193	50-443	Ä	DIETZ, C R	8210150045# 8210150106#	50-324 50-324	Q Q	W 0 WOY10	B210290245 B21029027)	PA PA I
		50	,,	D121210 H	0510130109*	30-324	ď	DIYON, O W	02102902414	1231
SEMIN SENTIS U	E210040193	50-443	A	DIETZ, C R	8210150291	50-324	5		***************************************	14 411
CEVINCENTIS J	8210050199	50-443	A	DIETZ, C R	B210150295*	50-324	ä	DIYON'O M	0210290315	50 1
CEVINCENTIS J	8210050199	50-443	Ą	DIETZ. C R	8210190666	50-325	6	BODDS, R	0210190589#	3.5 1
CEVINCENTIS J	8210070105 8210070105	50-443	A	DIETZ, C R	8210190748	50-324	S	DODDS,RT	0210040157*	22.51
- 1.10CK 13 3	95100,0103	50-443	A	DIETZ, C R	8210190754	50-324	8	DODDS, R T	B2100A014 1*	20.24
DEVINCENTIE >	6210130436	50-443	A	DIETZ, C R	B210220492*			DODDS, R T	8510140JVP	\$2.23
DEVINCENTIS J	8210130436	50-443	Ä	DIETZ, C R	8210260254	50-324 50-325	0	DODDS, R T	COLCARA	
DEVINCENTIS O	8210150510	50-443	Ä	DIETZ, C R	8210260255	50-325	8 5	DODDB, R T	8210190556x	10 3H 32 31
CETTINLENTIS J	B210150510	50-443	Α	DIETZ. C R	8210260294	50-325	8	DUDDS, R T	0210190733	\$2.50
CENINCENTIE J	8510180991	50-443	A	DIETZ, Ç R	8210260344	50-325	š	DODDS, R T	0210190741	\$3.54
DEVINGENTIS U	55.246346.						.,	DOERFLEIN, L. Y	8210210113	23 3
DE' INCENTIS, J	8210180001 8210190126	50-443 50-443	A	DIETZ, C R	8210290079	50~324	6			
DEVINCENTIS. J	8210170126	50-443	5 5	DIETZ.C R	8210270243	50-324	8	DOMER, J A	8210190105	50.00
CEVINCENTIS, J	8210190136	50~443	S	DIETZ, C R Dietz, C R	8210290325	50-325	6	DOOLITILE, E L	8510150931	50 49
TEVINCENTIS J	8210190136	50-443	5	DIETZ, C R	8210290336	50-324	8	DORDEHON, J	0210210021	黄年 54
			-		6210290346	50-325	6	DORSEY, J A	8210010175	22.54
DEVINJENTIS, J DEVINJENTIS J	8210190363	50-443	8	DIFFERENT, P M	821006020J*	50-416	8	- INGETTO H	0510050144	5
DEVINCENTIS J	8210190363	50-443	S	DIFFERENT, P M	8210080192*	50-416	8	DORSEY, J A	0210070199	# 1- N
CEVINCENTIS, J	8210260149 8210260149	50-443	S	DIFFERENT P M	8210190424*	50-416	s	DOUGAN, J R	8210190569	
DEVINCENTIS J	6210260330	50-443 50-443	5	DIGGS, R	8210130010	50-440	Ä	DOUGHERTY, J D	8210260740	1. 1
	051050000	50-443	S	DIGGS, R M	8210040049	50-346	P	DOUGHERTY, J II	0210240155	1.4
DEVINCENTIS J	6210260330	50-443	s	DIOGS, R M				DRAKE, J H	B2102700A)	\$ 1-14
CEVINCENTIS, J	8210280119	50-443	Ā	DIGOS, R H	8210050589	50-250	P	DD 4050 D 14		1
DEVINCENTIS, J	8510580118	50-443	Ä	DIGOS, R M	8210070033 8210130050	50-566	Q	DRAPER, D M DUBRY, N E	0210040075=	F. 31
CEVINE J B CEVINE, J B	6210040403	XPORTLIC		DIGGS, R M	8210270298	50-331 50-280	P	DUDA, L E	8210200171#	\$ 4.74
CETTILE, 5 B	8210080119	XPORTLIC		DIGNAN, T O	8210130314	50-200	9	DUDA, L E	8210120045	8 8 4
CEVINE, J B	6210080126	XPORTLIC			•	50-507	w .	OVFFY, B	0210240441*	Fi ≁iĞ Bû ^m i
DEVINE, T	8210040375+	50-373	C C	DIGNAN, T O	8210130314	50-309	0		OR FORGOTAL .	
CEVINE, T	8210150457*	50-358	Č.	DITANNI, D C	8210120589	50-282	ř	DUNLAP, J H	0210040049+	20.00
CEVINE, T	8210150457*	50-358	č	DIMASCID, N J DIMASCID, N J	8210150188*	50~322	Г	DUNLAP, J M	0210290207#	
cevine, 7	6210210391	50-358	ō	DIMASCIO, N J	8210150240*	50-322	T	DUNLOP, P	8210190492	\$2.21
LEVINE, T				orimotiani o	0210150290*	20-355	T	DUINE, L. A.	821021004 \$	222.
DEVINE, T	8210210371	50~35B	0	DIRCKS, W J	8110220004*	FOIA		DUROIN, W W	6210130207+	15.11
DEVINE, T	8210210400# 8210210400#	50-358	0	DIRCKS, W J	8201150180*	50-20A	g	DURR, J P	021001011	
DEHANDEL, E P	8210210053*	50-358 50-280	Ç F	DIRCKS, W J	8201270037*	FOIA	4	DURR, J P	8210060215+ 8210070400+	4.3 (1)
DENELL S	8210120271		G	DIRCKS, W J	8203110374*	FOIA		ק ניטאחק	0510510005	10 441 50 142
DE JEV L C			•	DIRCKS, H J.	8204200390*	FOIA		DURR, J P	0210210264	42 25
DEMEY, L B	8210120288		G	DIRCKS, W J	00010000			DURR. J P	8510550500+	3 3 GO T
DEWEN, L 8	8210150247	50-528	0	DIRCKS, W J	8204300078* 8205040550*	FOIA		Distract a		
DEYOUNG, R C	8210220429 8210220429		0	DIRCKS, H J	8205270507*	FOIA		DUTTON, D DUTTON, D	02100/0140	22 44 1
Ċ	6200170238	50-3	Q	DIRCKS, W J	8205280495	FOIA SECY		DUTTON, D. E.	0210150362	\$2.60
				DIRCKE, W J	B206180042*	FOIA		DYNES R R	8210270246 821015022 ft	35 (4)
								DYNES, R R	B2101502271	\$5.35

LINGUIAL MUTHOR INDEV

	ACCESSION NUMBER	SUBJECT		AUT#0R	ACCESSION NUMBER	SUBJECT CATEGOR	y	AUTHDR	ACCESSION NUMBER	SUBJECT CATEGORY	,
AUTHOR EDLOW, J ECHARDS, D L ECHARDS, D W ECHARDS, D W ECHARDS, D W	8210210543* 8210260079 8210220372 8210290263 8210150017*	70-2955 40-3453 PR PR	o	EVANS, L J EVANS, L J EVERETT, R J EVERETT, R J EVERETT, R J	B210070058* B210070064* B210070394* B210220128* B210220171*	50-537 50-537 40-6622 40-1162 40-2259	D D	FELTON, J M	8210180028 8210190013 8210190019 8210190020 8210190035	50-321 50-322	P F A C
EICHLER, T V EINZIMGER, R E EISENHUT, D O EISENHUT, D O EISENHUT, D O	8210150557 8210150550 8007010658 8007070448 8103170719#	50-247	P P S	FABRIZIO,R F FABRIZIO,R F FALCONER, D FALCONER, D FARDIS, M N	8207180064 8210180039 8210010166* 8210010474* 8210050428	F01A 50-318 50-269 50-269 Nureg	a a a	FELTON, J M	8210190036 8210190042 8210190066 8210190067 8210190079	50-315 50-321 50-340 FOIA FOIA	F F F
EISEMHUI, D O EISEMHUT, D O EISEMHUT, D O EISEMHUT, D O	8111300367* 8204290048* 8206070106* 8208250412* 8210010212	50-270 50-245 FOIA	9 A S P	FARDIS, M N FASANO, A FASANO, A FAN, R E FAY, C U	8210150574 8210150071* 8210150232* 8210190365 8107270156	NURE0 50-287 50-287 50-188 50-266	G G R G	FELTON, J M FELTON, J M FELTON, J M FELTON, J M FELTON, J M	8210190094 8210190097 8210190112 8210190144 8210190158	FOIA 50-367 FOIA FOIA 50-387	r r
EIGENRUT, D G EIGENRUT, D G EIGENRUT, D G EIGENRUT, D G	8210010215* 8210050495* 8210060433* 8210070217* 8210070235*	50~289 50-272	P F F P	FAY.C W FAY.C W FAY.C W FAY.C W FAY.C W	8210040119 8210050005 8210050034 8210050222 8210050256	50-246 50-246 50-246 50-246 50-246	F F P Q	FELTON, J M	8210190167 821001078 9210010199 921001079 92100130	50-219 50-250 FG1A 50-440 50-275	н г г
EISENHUT, D G EISENHUT, D G EISENHUT, D G EISENHUT, D G	8210120505 8210120590* 8210130024 8210130029* 8210150519	50-278 50-414 50-414	Ե Ե Ե	FAY.C W FAY.C W FAY.C W FAY.C W FAY.C W	8210050272 8210060325 8210060333* 8210130586 8210150150	50-246 50-301 50-301 PR 50-266	F S S	FELTON, J M	8210210050 8210210071 8210210073 8210210544 8210260008	50-210 FOTA 50-267 50-317 50 302	r r r
IISEMHUT, D G IISEMHUT, D G IISEMHUT, D G IISEMHUT, D G ISEMHUT, D G	8210250148 8210260521* 8210260532 8210280021* 8210280423	50-275 50-272 50-362 50-324 50-305	P F A P F	FAY.C W FAY.C W FAY.C W FAY.C W	8210150158× 8210150430 8210150471 8210180047 8210190264	50-266 50-266 50-266 50-266 50-266	R P G P	FELTON, J M	8210240122 8210260572 8210270083 8210270132 8210270256	50-314 50-440 50-251 50-369 50-266	F S F F
ISENHUID G ISENHUID G ISENHUID T L-ZEFTAHY, M L-ZEFTAHY, M	8210280425* 8210240203 8210040122* 8207120140* 8210050155*	50-305 50-286 50-387 50-324 FOIA	r 0 8 P	FAY,C W FAY,C W FAY,C W FAY,C W	8210190519 8210250258 8210250242* 8210250344 8210250352*	50~266 50~266 50~266 50~266 50~266	P 55 55 55 55 55 55 55 55 55 55 55 55 55	FELTON, J M FELTON, J M FELTON, J M FELTON, J M	8210270423 8210270426 8210280013 8210280016 8210280033	70-1510 50-271 50-261 50-369 50-322	F P T
L-ZEFTAWY, M LASSER, T C LORED, D T LORED, D T LIN, J O	8210040427* 8210210174* 8210250277* 8210250078* 8210170478*	F01A 50-245 50-346 50-346 50-397	g 8 9	FAY.C N FAY.C U FAY.C W FAY.C W FEHRINGER.D J	8210260476 8210270259* 8210280295 8210290294 8210120355	50-266 50-266 50-266 50-266 Waste M	P F P P GT	FELTON, J M	0210260045 0210260056 0210260108 0210260117 0210260136	50 409 50-255 50-313 50-295 50-271	F F F
LLIS.J LLIS.J LLIS.T S LLIS.T S	8210150224 8210250104 8210260355 8210200003 8210200003	50-445 50-445 50-322 50-322	@ 0 0	FELTON, J M FELTON, J M FELTON, J M FELTON, J M	8210060088 8210120090 8209150434 8209210425 8209290125	50-334 FOIA 50-267 50-251 50-10	R F S F	FELTON. J M FELTON. J M FELTON. J M FELTOIL J M FELTOIL J M	0210280140 8210280361 8210280378 8210280389 8210280394	50-3 50-254 50-315 50-149 FOIA	 - - - -
LROD, 8 A LSASSER, T LSASSER, T LSASSER, T LSASSER, T C	8210220303* 8210150017* 8210210261* 8210220521 8210270174*	50-335 50-373 50-423 50-273 50-213	0 0 0	FELTON, J M FELTON, J M FELTON, J M FELTON, J M FELTON, J M	8209290148 8210010008 8210040020 8210040343 8210040360	FDIA 50-311 50-445 50-537 FDIA	6 V	FELTON. J M	8210280379 6210280402 6210280417 6210280442 6210290020	50-315 FOIA 50-275 50-275 FOIA	r F
MMERT.R M MGEL.R E MGELMEN.R H MGELKEN.R H NGELKEN.R H	8207070324* 8207070224* 8210010267 8210250372* 8210270048*	70-2748 50-276 50-342 50-275 50-142	P Q P G	FELTON, J M FELTON, J M FELTON, J M FELTON, J M FELTON, J M	8210050013 8210050430 8210050512 8210050559 8210050562	50-309 70-1510 50-483 50-335 FOIA	F 8 F	FELTON, J M FELTON, J M FELTON, J M FENSTERMACHER FERNANDEZ, W	8210290023 8210290047 8210290085 8009250234 8210190077*	50-142 50-10 FOIA 50-247 50-233	F F F F
MGLE.L. R MGLERT.B R MTHIBLE.E B MTHIBLE.E B MTHIBLE.B	8210290414 8210280272 8210150200 8210150200 8210010284*	50-338 RES 50-170 50-170 50-329	Р Н Е	FELTON, J M FELTON, J M FELTON, J M FELTON, J M FELTON, J M	8210050582 8210060414 8210060417 8210060423	50-322 FDIA FDIA 50-358 50-537	C H A	FERREIRA, B P FERRELL, C FERRELL, C FERTNER, K FICOLER, P B	8210060257# 8210060451# 8210060455# 8210040455# 8208190170# 8210010077	TOPREP 50-537 50-537 50-213 50-219	A P P
RIKSON, K T RIKSON, K T RIKSON, K T RIKSON, K T RIKST, M L	8210260232 8210260239* 8210260239* 8103030076*	50-322 50-322 50-322 50-322 FOIA	T T T	FELTON, J M	8210060429* 8210060434 8210060437 8210060442 8210070003	FD1A FDIA 50-149 50-597 50-346	H D F	FIEDLER, P D	8210070178 8210070238 8210130167 8210130357 8210130078	30-219 50-219 50-219 50-219 50-219	5 5 5 5
RUST.M L RUST.M L RUST.M L RUST.M L URY.L W	810306008B* 8108030041* 8112030565* 8201060003* 8210050007	FOIA FOIA FOIA FOIA 50-241	P	FELTON, J M FELTON, J M FELTON, J M FELTON, J M FELTON, J M	#210070007 #210070027 #210070040 #210070411 #210070417	50-244 50-537 50-416 FOIA FOIA	P D F	FIEDLER, P D FIEDLER, P D FIEDLER, P D FIEDLER, P D FIEDLER, P D	8210190398* 8210190704 8210220187* 8210250092 8210250136	50-219 50-219 50-219 50-219	0 P 0 P
384'F M 384'F M 384'F M 384'F M	8210050362 8210060013 8210190709 8210260244 8210260323	50-324 50-261 50-261 50-324 50-324	Р Р Р Р	FELTON, J M FELTON, J M FELTON, J M FELTON, J M	8210080015 8210080020 8210080029 8210080034 8210080129	50-281 FD1A 50-295 50-269 50-315	ρ	FIEDLER, P D FIEDLER, P D FIEDLER, P D FIELDS, C FIELDS, C	8210250189 8210250285 8210270254 8210220443* 8210270286*	50-219 50-219 50-219 50-395 50-395	P 8 8
JRY, L H JRY, L H JRY, L H JAIS, C A JAIS, C D	8210260405 8210260475 8210260508 8210010176* 8210010118*	50-324 50-261 50-261 50-313 50-321	Р Р С С	FELTON, J M FELTON, J M FELTON, J M FELTON, J M	6210120015 6210120103 6210120372 6210120545 6210120643	FOIA 50-3 50-331 50-231 50-261	F	FIELDS.J A FIELDS.J A FIELDS.W W FINAMORE.D FINAMORE.D A	8210290338* 8210190102 8210190720* 8210220288* 8210040195		т Р О
/ANS, C, D /ANS, C D /ANS, C D /ANS, L J /ANS, L J	8210150217* 8210150237* 8210150263* 8210070037* 8210070056*	70-1201 70-27 50-249 50-537 50-537	G D D	FELTON, J M FELTON, J M. FELTON, J M FELTON, J M FELTON, J M	6210130004 6210130105 6210150594 6210150621 6210160014	50-329 50-336 50-315 50-244 50-334	}	FINAMORE.B A FINAMORE.B A FINAMORE.B A FINAMORE.B A FINAMORE.B A	8210210232 8210130246 8210130246 8210130246	50-537 50-537 50-537 50-537	0000

ROHTUA	ACCESSION NUBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
FINAMORE.B A FINAMORE.B A FINAMORE.B A FINAMORE.B A FINAMORE.B A	8210210232	50-537 C	Frahm, R	8210130358*	50-311 S	GARCIA, P J	8210210021	40-3453
	8210210357	50-537 G	Frahm, R	8210150065*	50-311 S	GARCIA, P J	8210210525*	40-3453
	8210210357	50-537 G	Frahm, R	8210150073*	50-311 S	GARCIA, P J	8210220475	40-1162
	8210210453	50-537 G	Frahm, R	8210150118*	50-311 S	GARCIA, R	8210040255	TOPREP
	8210210453	50-537 G	Frahm, R	8210150140*	50-272 S	GARDNER, R	8210040337	50-329 S
FINAMORE, B A	8210220268 82102202863 82102202953 8210260397 8210260397	50-537 G 50-537 G 50-537 G 50-537 G 50-537 G	FRAHM, R FRAHM, R FRAHM, R FRAHM, R FRAHM, R	8210150320* 8210150339* 8210210144* 8210250957* 8210250389*	50-311	GARDNER, R N GARDNER, R N GARNER, L GARNER, L W GARNER, L W	9210050154* 9210190750* 9210010206* 9210010205* 9210010415*	50-329 Q 50-329 Q 50-325 Q 50-324 Q 50-324 Q
FIMMORE, B A FIMMORE, B A FINCKE, J R FINOLEY, D E FINDLEY, D E	8210260404+	50-537 G	Frahm, R	8210280128*	50-311 S	GARNER, L W	8210220173*	50-324 Q
	8210260404+	50-537 G	Frahm, R	8210280154*	50-311 S	GARNER, L W	8210220503*	50-324 Q
	8210280339	RES	Frahm, R	8210270218*	50-272 S	GARRITY, J H	8210010230	PR
	8210120357+	CONTRACT	Frahm, R	8210270314*	50-272 S	GARRITY, J H	8210040074	50-309 P
	8210190037*	CONTRACT	Frahm, R	8210270361*	50-272 S	GARRITY, J H	8210040077	50-309 P
FINALL A E FINLAYSON, F C FINLEY, N C FIORAVANTE, M FIORE, R A	8210210097* 8210260246* 8210290399 8210120139* 8210260352*	50-354 0 50-322 T RES 50-317 F 40-8610	FRALEY, R F FRANCIS, E FRANCIS, E FRANÇIS, L FRANTZ, S P	8006300104* 8210130607 8210270054 8210010116 8210200058	FOIA 40-299 40-2259 70-633 50-522 G	QARRITY, J H GARRITY, J H GARRITY, J H GARRITY, J H GARRITY, J H	8210040217 8210060302 8210150398 8210220203 8210220212	50-309 P 50-309 Q 50-309 P 50-309 P
FIGHER A FIGHER LI, G FISCH, C FISCHER, L FISH, R L	8210260352* 8210060345* 8210270158 8210150500* 8210150550	40-8610 50-528 0 XPORTLIC 50-263 P NUREG	Frantz, 5 P Fredland, D R Fredrickson, P Fredrickson, P Freedberg, L	8210200058 8208290105 8210010350* 8210150256* 8208290089	50-522	GARRITY, J H GARRITY, J H GARRITY, J H GARRITY, J H GARRITY, J H	8210250078 8210260144 8210260327 8210260420 8210270008	50-309 P 50-309 G 50-309 E 50-309 P
FISHER,C R	8210290141	TOPREP	FRENCH, L D	8210130531 #	50-29 8	GARRITY, J H	8210260087	50-309 F
FISHER,C R	8210290234	PR	FRENCH, L D	8210260169 #	50-29 8	GARRITY, J H	8210260141	50-309 P
FISHFR,L	82101505094	50-263 P	FRIEDMAN, K A	8210120293 *	0A979	GARRITY, J H	8210270343	50-209 S
FITZPATRICK,B	8210040145*	50-247 S	FRIEDMAN, P	8210150272 #	50-322 T	GARY, R J	8210040316	50-445 S
FLACK,E	8210070336	50-461 0	FRIEND, H B	9210190470	50-275 P	GARY, R J	8210040376	50-445 F
FLACK, E FI EENOR, C FLEENOR, C FI EENOR C FLEENOR, C	8210280072 8210120454 8210120467 8210190180 8210270416	IVE CONTRACT CONTRACT 50-320 F CONTRACT	FRIEND, H B FRIEND, H B FRYE, J H FRYE, J H FUENTE, E 5	6210270351 6210270351 6210220343 6210250223 6210250223	50~275 P 50~275 P 50~70 G 50~142 G PR	GARY,R J GARY,R J GARY,R J GARY,R J GARY,R J	8210180004 8210220372 8210250338 8210250346 8210260375	50-445 P PR 50-445 S 50-445 S
FLEENCR. C M	8210120411	27-39	FUHRMAN, G R FULFORD, P J FULLER, C FULLER, C FULLWOOD, R R	8210190730	50~317 S	GEE.G N	8210150553	Hureg
FLEENOR. C M	8210270411	50-387 X		8210210306*	50~329 A	GEFFEN.C A	8210120092	Nureg
FLEENOR. C M	8210270425	70-1113		8210050337*	50~267 S	GEFFEN.C A	8210120102	Nureg
FLEENOR. C M	8210280299	CONTRACT		8210190543*	50~267 S	GENADRY.M D	8210050428	Nureg
FLEENOR. C M	8210280310	CONTRACT		8210120092	NUREQ	GERDEMAN.F W	8210260019	40-8648
FIEENOR, C M	8210280327	CONTRACT	FULLWOOD.R R FURGAL.D T FURATO.E M GAD.R K GAD.R K	8210120104	NUREG	GERETY, H F	8210150147	50-289 J
FLEENOR, C M	8210280354	CONTRACT		8210180571	NUREG	GERGELY, P	8210050412	NVREG
FIEISHER, Z S	8210180203	50-247 G		8210070355#	50~43B A	GERNER, L F	8210280364*	50-254 F
FLEISHER, Z S	8210200019	50-247 G		8210130314	50~307 G	GERSTNER, W C	8210190354	50-461 S
FLEISHER, Z S	8210210390	50-247 G		8210130314	50~309 G	GERSTNER, W C	8210280050	50-462 Q
LEIGHER, Z G	8210210397#	50-247 G	GAD, R K	8210270153	50-443 Q	GERTMAN, D I	8210120124	RE9
LEMING, T E	8210120936	40-8771	GAD, R K	8210270153	50-443 G	GERNIN, E F	8210150474	50-528 G
LESSNER, S A	82092902254	50-10 F	GAD, R K	8210270166	50-443 Q	GIANELLI, J	8112010310*	50-336 S
FLIPPO, T A	8210190349+	50-285 G	GAD, R K	8210270166	50-443 Q	GIANELLI, J	8210070416	50-324 S
FLORY, C A	8210120554	WASTE MGT	GALLE, D P	8210270088*	50-10 F	GIANELLI, J	82100800[8	50-336 S
FLGRY, C A	8210120634	40-8452	GALLO, J	8207180052	FDIA	GIBBONS, T 8	8210150207*	50-438 G
FLYNN, B	8210120648	WASTE MGT	GALLO, J	8207180052	FDIA	GIBBS, D C	8209270379*	CDMHESSION
FLYNN, M	8210040410	CONTRACT	GALLO, J	8210010408	50-155 Q	GIBSON, A	8210050224	18E
FLYNN, M	8210120354	CONTRACT	GALLO, J	8210010408	50-155 Q	GIBSON, A F	8210010121	70-1201
FLYNN, M	8210180327	CONTRACT	GALLO, J	8210010446	50-195 Q	GIBSON, A F	8210010162	70-143
FLYNN, M	8210180384	CONTRACT	GALLO, J	8210010446	50-155	G1850N, A F	8210010313	70-143
FLYNN, M	8210190018	CONTRACT	GALLO, J	8210050232		G1850N, A F	8210010353	70-27
FLYNN, M	8210190030	CONTRACT	GALLO, J	8210050232		G1850N, A F	8210010364	70-143
FLYNN, M J	8210190005	CONTRACT	GALLO, J	8210050356		G1850N, A F	8210010388	70-824
FLYNN, S F	8210130539	PR	GALLO, J	8210050356		G1850N, A F	8210080179	70-143
FLYIN,S F	8210150305	50-400 G	GALLO, J	8210040204	50-155 0	01890N, A F	8210150064	70-1113
FLYIN,S F	8210220285	PR	GALLO, J	8210040204	50-155 0	01890N, A F	8210150130	70-824
FOGARTY,D J	8210080211*	50-206 Q	GALLO, J	8210120457*	50-155 0	01890N, A F	8210150197	70-143
FOLEY,T	8210070216*	50-286 Q	GALLO, J	8210120457*	50-155 0	01890N, A F	8210150215	70-1201
FOLEY,T	8210210307*	50-247 Q	GALLO, J	8210150300	50-155 0	01890N, A F	8210150229	70-27
FOLSOM, R D	8210220074%	40-8111	GALLO, J	8210150300	50-155 G	OIBSON, A F	8210150361	70-143
FOLSOM, R B	8210220077%	40-8111	GALLO, J	8210150470	50-155 G	OIBSON, A F	8210150403	70-143
FONNER, R L	8210180103	70-143	GALLO, J	8210150470	50-155 G	OIBSON, A F	8210210194	50-13 Q
FORD, E W	8210130319%	50-302 5	GALLO, J	8210180142	50-454 G	OIBSON, A F	8210210216	70-1201
FORD, E W	8210130530#	50-302 8	GALLO, J	8210180142	50-454 O	OIBSON, A F	8210210341	70-27
FORTUNA.R A FOSTER.D O FOSTER.D O FOSTER.H FOSTER.J E	8210280047* 8210220078 8210220208* 8210010189 8210130557*	50-324 P 50-424 B 50-424 Q 70-1151 50-461 Q	GALLO, J GALLO, J GALLO, J GALLO, J	8210180206 8210180206 8210180242 8210180242 8210200029	50-155 0 50-155 0 50-155 0 50-155 0 50-155 0	OIBSON, A F OIESEKE, J A OIESEKE, J A OIESEKER, J OIESLER. C W	8210220308 8210150592 8210210014 8210260118* 8210010179	70-1113 NUMEO NUMEO 50-373 \$ 50-305 P
FOSTER, K W FRAHM, R FRAHM, R FRAHM, R FRAHM, R	0210150547 8210070231* 8210070252* 8210070256* 8210070314*	NUREO 50-311 S 50-311 S 50-311 S 50-272 S	GALLO.J GALLO.R GALLO.R M GALLO.R M GALLO.R M	8210200029 8210070391* 8210070393* 8210150274* 8210290157*	50-155 Q 50-307 Q 50-271 Q 50-271 Q 50-27 Q	GIESLER,C W GIESLER,C W GIESLER,C W GIESLER,C W GIESLER,C W	8210010232 8210010307 8210040154 8210050263 8210060312	PR 50-305 8 50-305 V 50-305 P
FRAHM, R FRAHM, R FRAHM, R FRAHM, R FRAHM, R	8210070377* 8210070398* 8210130170* 8210130227* 8210130345*	50-311 S 50-272 S 50-311 S 50-311 S 50-311 S	GALUNIC, B GAMMILL, W P GAMMILL, W P GARCIA, E M GARCIA, P J	8210050206* 8104290774* 8201120280* 8210190636* 8210120628	50-443 A 50-324 P 50-324 P 50-27 Q 40-6659	GIEBLER, C W GIEBLER, C W GIEBLER, C W GIEBLER, C, W GIEBLER, C W	8210130581 8210130300 8210130382 8210040338	50-305 # 50-305 # PA 50-305 F 50-305 F

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGOR	Y	AUTHOR	VCCE8310N	SUBJECT CATEGOR	
ESLER, C W ESLER, C W ESLER, C W ESLER, C W LESLERT, O D	8210170353 8210170487 8210260260 8210270234 8210270144*	50-305 50-305 50-305 PR 50-369	8 P 5	GRAY, E H GRAY, E H GRAY, J R GREED, J R GREEN, H J	8210210125* 8210210264* 8210220445 8210270137* 8209300170	50-354 50-220 50-289 50-409 50-259	00000
rivekv. Cimekv. Feevit D Feevit D	6210050399* 8210190776* 6210120654 6210220351 6210220363	50-450 50-445 RES 50-367 50-275	0 0 11	ORECILIH J ORECILIH J GRECILIH J ORECILIH J GRECILIH J	8210010108 8210040219 8210040245 8210040409 8210040414	50-327 50-327 50-276 50-259 50-259	5055
LINSAY, V LINSAY, V LLEN D H LLEN D H	6210290332* 6210290393 6210040363 6210210534* 6210260211	50-209 10CFR 40-0601 40-0601 NUREQ	o	OREEN.H J OREEN.H J GREEN.H J GREEN.H J OREEN.H J	8210130157 8210130165 8210130172 8210110317 8210130429	50-296 50-259 50-259 50-32/ 50-259	ភ ន ន ន ន ន
LLILAND, J T Nedero, T Fard, e H Fard, e H Ettum, p	8210190621 8210120649 8210010076# 8210150406# 8210120517#	50–424 RE8 50–335 50–259 CONTRACT	B Q Q	GRLEILH J GREFILH J GREENLH J GREENLH J GREEN,H J	8210130442 8210130565 8210130572 8210190378 8210190712	50-327 50-259 50-328 50-327 50-327	20000
ereon j p Ereon j p Ereon j p Ereon j p Over m 9	6210090254 6210150092 6210150141 6210200069 6210170106#	50-247 50-247 50-247 50-247 50-369	0 0 0	0 H : H : 3	8210220050 8210220050 8210220081 8210240188 8210240212	50-259 50-328 50-327 50-328 50-259	00000
CYER, M S DDASD, R J DDARD, R J DDARD, R J DDARD, R J	8210270144* 8210040081 8210040083* 8210180167 8210290301	50-369 50-155 50-155 90-155 50-155	r 0 0 0	C H.M3 300 L H.M3 1300 C H.M3 1300 U H.M3 1300 L H.M3 1300	8210260349 8210260381 8210260417 8210290054 8210290062	50-240 50-259 50-260 50-259 50-259	ខេត្តខេត្ត
DARO,R J By.a T By.a T By.a T Gy.a T	8210280340 8210040049* 8210060370* 8210130449* 8210210238*	50-461 50-27 70-1100 XPORTLIC 50-271	о о	C H 1413 300 C H 1413 400 C H 1417 400 C H 1413 400	8210J90071 8210Z90231 8210Z90277 8210Z90317 8210Z90368	50-328 50-276 50-327 50-259 50-259	88888
DY.A T BY.A T DY.A T DY.A T DY.A T	8210210321× 8210220172× 8210220179× 8210220264× 8210270107×	50 309 70 371 70 371 70 697 50 220	a a	GRETHOLATT, D GREENBLATT, D GREENBLATT, D GREENBLATT, D GREENE, O A	8210210308 8210210308 8210210419 8210210419 8210120649	50-400 50-400 50-400 50-400 REU	6666
DY. A T LEBERO, J H LEBERO, J H LEBERO, J H LEBERO, B C	8210290207# 8210200092 8210200075 8210220239 8210070176	50 007 50 490 50-490 50-490 50-494	Q A A A H	GREENKORN, R. A. GREENMAN, E. GREENMAN, E. O. GREENMAN, E. O. GREENMAN, E. O.	8210120342* 821020255 8210060127* 8210070308* 8210070316*	CONTRACT 50 -030 50-017 50-276 70 -364	3 Q Q
LDBERG,8 C LDBERG,8 C LDBERG,8 C LDBERG,8 C LDEN,J C	8210130095 8210150007 8210200347 8210270105 8210260526	50 454 50 -454 50 -454 50 -454	0 0 0	GRECHMAN E O ORCUMAN C O GRELMAN E O OREGEN L R GREGER L R	0210070345# 0210210451# 0210240344# 0210040112# 0210040205#	50~219 50~272 50~322 50~295 50~266	9 9 9
LL.ST LLER.KR LLER.KR LLER.KR	8210220149 8210050042# 8210070172# 8210070185# 8210070187#	NURLO REQQD 50~269 50~266 50~266	G P P	GREGERIL R GREGERIL R GREGGER J GREGGER J GREGGER J	8210090 i80* 8210130408* 8210290014 8210260108 8210260173	50-184 50-409 70-020 70-020 70-020	a a
MALEZA ODE: R ODE: R ODE: R W ODE: R W	6210120440# 6210210204# 6210260515# 6210210223# 6210210342#	50-341 50-13 50-335 70-1201 70-27	A G	OREOGIR J GREQURY, H B GRENTER, B L GREVE, F GRIDLEY, R L	0210270213 0210120426 8104080307* 0207140494* 0210080262	70 820 RES FOIA 90-373 TOPREP	G
COMOPE, A C COMEL J 8 COMANIL COMANIL COMANIL	8210080075 6210260501 6210010226 6210010232 6210170454*	27-39 50-374 PR PR 50-109	0 8	ORINLA: B K OROBE: J OROBE: J A GROEBCH: O L	8210010061* 8210060384* 8210260467 8210060393* 8210050366	FOIA 50~373 50~254 50~315 50~382	989
Doman. L 8 Dom Tile F ULD. J P ADA. K D AESSER. K L	8210220304 8210220048* 8210260504 8210050160* 8210040116	PR NUREQ 50-029 50-034 50-004	t P B	QROESCH, O L QROESCH, O L QROESHULECH, B QROSSMAN, H QROSSMAN, H	0210050372m 0210050378m 0210120613m 0210150217 0210250229	50~392 50~392 CDNTACT 50~395 50~395	9 9
aegser.x l Legser.x l Legser.x l Legser.x l Legser.x l	8210060262 8210150405 8210180167 8210190483 8210190689	50-304 50-295 50-304 50-295 50-295	8 8 8	GROTENHUIB, H GROTENHUIB, H GUADAGNO, V GUCHA, L T GUCHA, L T	8210050546* 8210120621 8210270376* 8210050330 8210220287*	50-315 50-250 40-8824 50-321 50-321	P P
AESSER.K L AESSER.K L AESSER.K L ARTIJ H ANTIJ H	8210260219 8210260233 8210260399 8210080312 8210080314	50-304 50-275 50-275 50-424 50-424	4 8 8	QUCHA, L T QUCHA, L T QUCHA, L T QUILDERT, D E QUILDERT, D E	8210220290 8210220386 8210290273 8210120304* 8210120315*	50-366 PRM PR QA999 QA999	
uit, X B Aves, C C Aves, R H Aves, R H Aves, R H	8210050380* 8210010351 8210150122 8210270245 8210280071	50-184 PARPOT C12-00 0-213 50-213	8 8 0	GUILD.R GUILD.R GUINN.P R GUINN.P R GUINN.P R	8210080081 8210080081 8103160338* 8103160366* 8104170703*	80-413 50-413 FOIA FOIA FOIA	

SUBJECT ACCESSION. AUTHOR CATEGORY NUMBER CUINN P R FDIA B210180089* GUINN, P. R. 8210180092* FOIA GUIIIN, P R 8210180213* COLV GULDEMOND, U G 8210250116# 50-373 OULKAN, P 810727017日# 50-266 Œ GULKAN, P 8107270182* 8107270185* 50-246 50-266 0 GULKAN, P Q 8107270174* 8210070449 50-266 ā RES GUSTAVE, R 8210080022# CONTRACT GUSTAVE, R 8210240280 * CUNTRACT GUSTAVE, R 8210240559 CONTRACT GUSTAVE, R P 8210050508# CONTRACT GUSTAVE, R. P. 8210050521# CONTRACT GUSTAVE, R P 8210050525 CONTRACT GUSTAVE, R P 8210050530* CONTRACT GUSTAVE, R P 8210080009* CONTRACT GUSTAVE, R P 8210120330 # CONTRACT GUSTAVE, R P 8210120342* GUSTAVE, R P 0210120364* CONTRACT QUETAVE, R. P. 82101204224 CONTRACT GUSTAVE, R P 0210120508* CONTRACE GUSTAVE, R P 8210130572* CONTRACT GUSTAVE, R P 8210150350# CONTRACT GUSTAVE, R P 8210180365* GUSTAVE, R P 8210180419* GUSTAVE, R. P. 8210170004* 8210170087* CONTRACT GUSTAVE, R. P. 8210170141* CONTRACT GUSTAVE, R P 8210210066* CONTRACT GUSTAVE, R P 8210210584 CONTRACT Q STAVE, R P CONTRACT 8210270033* CONTRACT GUSTAVE, R P 8210270395# CONTRACT GUSTAVE, R P 8210270402* CONTRACT GUSTAUF.R P 82102/0407* CONTRACT GUSTAVE, R P 8210280397* CONTRACT 50~498 50-309 GUTTERREZ. J H 0210050241 000 GUTTERREZ. J H 82100800A9 GUTTERREZ, J H 0210150134 50-307 GUTTERREZ. J M 8210150460 50-307 Ģ HAASSIN P 8207210413* 8010070320* 50-520 50-305 A HAFTZ.A HAGAN, T.F 8210150535× 50-287 8210040412# CONTRACT MAGAN, T. F 8210120357* CONTRACT HAGAN, T F 8210120419* 8210120423* 8210120458* 27-39 50-369 CUNTRACT HAGAN, T. F. 8210120471* CONTRACT HAGAN, T F 9210120550* CONTRACT HAGAN, T. F. 82101803324 CONTRACT HAGAN, T F 8210190025# CONTRACT 82101900024 CONTRACT MAGAN, T F 8210270413= 50-307 0210270419* HAGAIL T F

LEUSONAL MOLLION INDEX

AUTHOR	ACCESSION NUMBER	CATEGOR		AUTHOR	ACCESSION NUMBER	SUBJECT	Y	AUTHOR	ACCESSION NUMBER	Sug F 1
HALL, D P	8210280213	50-461	Α	HEIDER, L H	8210130353	50-29	Р	11224.00		
HALL, E E	8210120329*	WASTE MO	}T	HE CDER, L H	8210170686	50-29	P	HIDALOD, P. A.	8107270174*	50-2*
HALLER, N M	8005270820*	FOIA		HEIDER, LH	8210220157*	50-29	à	HIETALA, J	8210260297•	50 JB
HAMAWI, J N	8210150290*	50-322	r	HEIDER, L H	8210280094	50-29	P	HIETALA, J	8210260321*	50-37
HAMILTON. J F	910550317	PR		HEINZ, E L	8210270182*	40-8577	•	HIGGINBOTHAM, L HILF, C L	8210120030± 8210250074±	FOIA 50-2-1
HAMILTON, P P	8210050214	50-244	P	HEESHMAN, R F	8209290236*	FOIA		HILL, D	9210180338+	461 701 -
HAMMER. S	8210170273*	50-243	s	HEISHMAN R F	8209290240*	FOIA		HILL, D	8210180338*	CC+TF4
HANAUER, S H	8205280470*	FOIA		HEISHMAN, R F	8210050522*	50-483	5	HILL, K L	8210040376	CENTRA
HANAUER, S H	82100700084	FOIA	_	HEITKEKPER, E M	8210120496*	CONTRACT		HILL, K L	82101301374	30 331
HANGOCK, J A	8210130310	50-302	8	HEITHER, K L	8210040423	50-309	Р	HILLIK L	621013039B+	50 JU 50 JU
HANCOCK, J A	8210130520	50-302	8	HEITNER, K L	8210070054	50-309	P	HILL.X L	82101305704	P. A.
HANCOCK, J A	8210220052	50-302	s	HETTNER, K L	8210290160	50-309	P	HILL, K L	B5105205914	10.3%
HANNETT B A	8210070452	XPORTLIC		HETTNER, K L	8210290165	50-309	P	HILLIK L	8210250300	533.
HARNETT, B A	8210080037	XPORTLIC		HELFRICH, R E	8210130433	PR		HILL, K L	8210250387	50-01
HANNETT, B A	6210080040*	XPORTLIC		HELGESON, K A	8210200104	70-820		HILL, O F	9210070254	50 311 50 317
HANNETT, B A	8210080042*	XPORTLIC		HELCESON, K A	8210250012	70-820		HILL, U H	DOLAL DOLLAR	
HANNETT, B A	8210080108	XPORTLIC		HELGESON, K A	8210260038	70-820		HILLMAN, C R	82101904194	50 (13
HANNETT, B A	8210080130	XPORTLIC		HELGESON, K A	8210270206	70-820		A C'GNIII	B210150609e	70 17/
HANNETT, R A	8510080133	XPORTLIC		HELGESON, K A	8210270218	70-820		HIND, J A	8210040184	3C 1/2
HANNETT, B A	8210270147	XPORTLIC		HELLER, J K	8210190449*	50-255	Q	A LIGHTH	8210080201 8210190652	50-31 50 311
HANNETT B A	821027016B	XPORTLIC		HELLER, R	8210010047*	50-311	5	HIND, J A	0010100000	
HANNETT, B A	82102B0052	XPORTLIC		HELLER. R	8210010123	50-311	8	HIND, J A	9210190753	50-2"
HANNETT, B A	8210280029	XPORTLIC		HELLER. R	8210010128*	50-311	ន	HIND, J A	9210250286	50-30
HANNETT, B A	6210280057*	XPORTLIC		HELLER, R	8210010150*	50-311	S	HINRICHS, O	8210260374	50 7-1
HARBOUR, J	8210010254	50~329	G	HELLER, R	8210010192*	50-272	8	HODBINS, R R	8210250149. 8210(20400	50-247 Res
HARBOUR, J	8210210393	50-416	G .	HELLER, R	8210010239*	50-311	8	HOCH, J B	B210150159*	** * 1
HARDING, M R	8210010115*	50-327	5	HELLER, R	#210010355*	50-311	Б	HOCHREITER, L E	8210210034	50-2-5
HARDING, M R	8310070551*	50-327	В	HELLER, R	8210010370*	50-272	8	HOCHREITER, L E	8210220154	ALF(S
HARDING, M R	8210130452*	50-327	8	HELLER, R	8210010412*	50-311	8	HODGDON, A P	8210040087	AUFE :
HARDING, H R	8210130579*	50-328	8	HELLER, R	8210010423*	50-311	8	HODODON, A P	8210030088	50-342 50-312
HARDING, M R	6210170386*	50~327	В	HELLER, R	8210010461*	50-311	8	HODGDON, A P	8210200040	
HARDING, H R	6510550045*	50-328	5	HELLER, R	8210070248*	50-311	8	HODGDON, A P	8210280207	10 332
HARDING, M R	8210220085*	50-327	8	HELLER, R	8210070359*	50-311	8	HODOGE, S A	8210210034	20 3,5
HARDING, IS R	8210260176*	50-328	8	HELLER, R	8210070375*	50-272	8	HOFFMAN, D P		30-151
HARDING, H R	8210290094*	50-328	s	HELLER, R	8210150066*	50-272	8	HOFFMAN, J C	9210150146 9210130280	50-25) 50-297
HARDING, H R	8210290279*	50-327	8	HELLER, R	8210150075*	50-272	В	HOLLAND, P	82101302014	
HARDY, J E	8210210037	NUREO		HELLER, R	8210150121*	50-272	8	HOLLAND, P	82102502784	50 247
HARDY, J E	8210260206	NUREG		HELLER, R	8210150155*	50-272	B	HOLLAND, P	82102302764	30-2/1
HARIED, J A	8202020441*	FOIA		HELTEKES, C J	8109100077*	FOIA		HOLMES-RAY, P	62100103276	90 51
HARIED, J A	8203250320*	FOIA		HELTERES.C J	#80E041118	FOIA		HOLT, J	8210200010	50 32L 1 50 247 1
HARHON, D. L.	8210120397	RES		HELTEMES, C J	8112210538*	50-304	8	HOMAN, F J	0010010404	
HARPER, M T	*1900E1012B	CONTRACT		HELTEKES, C J	8201150003*	FOIA		HOMAN, F J	8210060425	RES
HARRINGTON, R M	8210150564	NUREO	_	HELTEHEB, C J	8210050031*	FOIA		HONEY, J	8210180407	RES
	6204160222*	50-293	G	HELTEMES, C J	8210060381*	FOIA			8210290255	PR
HARRINGTON. W D	8210060080		p	HELTEMES, C J	8210070422			HOPKINS, J B	8210210272	50 (27 1

THOO HAT YOU HOU THOEN

AU FHOR	ACCESSION NUMBER	SUBJECT CATEGORY	_	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	, 	AUTHOR	ACCESSION NUMBER	SUBJECT	<u>,</u>
WAYG. J WAYG. J WAYG. Y WAYG. Y S WANG. Y S	8210080165* 8210080172* 8210050006* 82100500158	GEN TEC IS GEN TEC IS FOIA FOIA GEN TEC IS	5	IMBRO, E V IMBRO, E V IPPOLITO, T IPPOLITO, T A IPPOLITO, T A	B210130065 B210170009 B210070139* B206070250* B2092103B3*	50-368 50-29 50-244	8 8 9 9 P	OCHNOON, 8 D JOHNSON, 8 D JOHNSON, 8 D JOHNSON, 8 D	8210060213 8210120076 8210130146 8210180186 8210190604	50-255 50-255 50-255	8888
WANG, Y S WBACCK, W G WCHTON, R L WDEON, C R WDEON C R	82:0080169 82101904!9* 820:200662* 82:0270052* 82:0270056*	50-537 (IPPOLITO,T A IPPOLITO,T A IRBY,B J IRBY,B J IRBY,B J	8210070121* 8210080002* 8209300175* 8210130438* 8210130569*		P P S S	JOINSON. B D JOHNSON. B D JOHNSON. B D JOHNSON. B D JOHNSON. B D	8210190620 8210190639 8210220186 8210260183* 8210280107	50-255 50-255 50-255	8 9 0 F
NUSON, S D NUFFMAN, G M NUFFMAN, G M NUGGINS T NUMPS, A	8210070350# 8210010159# 8210220461# 8210280321# 8210040357#	50-335	3	IRBY, B J IRWIN, D P ISABELLE, L D ISAII, M ISLEY, T	8210270232* 6210200036 8210270267 6210150556 6210170261*	50-294 50-322 50-247 NUREQ 50-346	8 0 5 5	JOHNSON, C JOHNSON, C JOHNSON, C JOHNSON, C R JOHNSON, C R	8210280276 8208290086 8210190452* 8210280448 8210290155	50~537	ዋ ል Q
PLCHES, P G NOFILL, H D NOFILL H D NOFILL, H D NOFILL, H D	8210220056* 8210050113 8210050176 8210060228 8210070372	50-289 50-289 50-289		JABBOUR.K N JABBOUR.K N JABKOUR.K N JACK.R A JACKIN.I	8210190071 8210220026 8210260065 8210260582* 8210190694*	50-413 50-413 50-413 50-201 50-373	A V G Q	JOHNSON, D F JOHNSON, G E JOHNSON, G E JOHNSON, G E JOHNSON, G E	8210010225* 8210040121* 8210040015 8210040017 8210040023	50-304 50-440 50-440	0 9 0 0
UNICE, H D CRICE, H D UNICE, H D UNICE, H D UNICE, H D	8210080043 8210080308 8210130204 8210130210* 8210130248	50-289 (50-289 (50-289 (7 7 9 9	JACKIN, I N JACKIN, I N JACKSON, L H JACKSON, L H	8210060335* 6210170601* 6210170626* 8210010350* 8210150132*	50-10 50-373 50-295 50-324 50~324	ბ ი ი ი	JOHNSON, 0 E JOHNSON, 0 E JOHNSON, 0 E JOHNSON, 0 E	8210040191 8210170377 8210200071 8210210187 8210210197*	50-440 50-413 50-413	0 0 0
ONICE'H D CAICE'H D CAICE'H D CAICE'H D	8210130515 8210130548 6210150202 8210250097* 8210260499	50-287 (50-287 (50-219 (3 3 3 7	JACKSON.L H JACOBE.A JACOBE.A JACOBE.A JACOBE.A	8210220307* 8210120379 8210050501 8210050516 8210150328	50-321 WASTE MGT CONTRACT CONTRACT	r r	0 NOSONIOL E	8210250370 8210270002 8210270010 8210150017# 8210260232	50-413 50-413 50-293	0 0 0 T
OLMAN, E G ULMAN, E G ULMAN, E G ULIMER, M M ONVICUIT, D M	8203050073* 8203220512* 8210290405 8210190362* 8210050399*	50~537 I 50~245 I 50~331 (0 0 1 1 1	JACOBS. A JACOBS. A JACOBS. A JACOBS. A JACOBS. A	8210180357 8210180414 8210190003 8210190132 8210210041	CONTRACT 50-201 CONTRACT CONTRACT CONTRACT	P	JOHNSON, J L JOHNSON, R A JOHNSON, R A JOHNSON, R A JOHNSON, W 0	8210130315* 8210130054* 8210170141* 8210170182* 8210240474	CONTRACT CONTRACT CONTRACT	A
CHRICOLLY B W SENTENTY B W CHRICOLLY B W CHRICOLLY B W	8210170347* 8210170452* 8210170516* 8210170537* 8210170608*	50-382 50-313 50-285	3 3 3 3	JACOBS.A JACOBS.H R JACOBS.J L JACOBS.R H	6210260282 8210270399 8210260230* 6210010434* 6210120043	CONTRACT CONTRACT 50-72 40-1202 50-287	R P	O JOHORANIAC W JOTANHOL V W JOTANHOL V W JOTANHOL V W JOTANHOL	8210060345* 8210120125 8202170310* 8203110403* 8205280532*	50-520 NUREG 50-244 50-244 50-207	G P P G
ULNICUTT D M UNSTAD A A UNSTAD A A UNSTAD A A UNSTAD A A	8210170776# 8210130533* 8210150390* 8210190745* 8210250183*	50-282 9 50-282 9 50-306 9	3 3 3 3 3 3	JACOBS.R H JAFFE.D JAFFE.D H JAFFE.D H JAFFE.D H	8210270162 8210120137* 8210070104 8210070125* 8210200108	50-289 50-317 50-317 50-317 50-317	P F P P	JOHNSTON, II V JONES, B W JONES, B W JONES, C R	8205280533* 8210010064 8210040097 8210060183 8210260217	50-209 50-537 50-275 50-537 50-298	P
UNSTABLA A UNTLM D UNTLM D UNTER D UNTER, R S	8210250376* 8210010462* 8210220189* 8210170627 8210010362	50-390 50-438 50-358		JAFFE, D H JANUSKA, D JANUSKA, A Q JANUSKA, A Q	8210290412 8210120466 8210280030 8210040208* 8210150543*	50-317 RES XPORTLIC 50-331 50-10	P Q O	JONES, D. L. JORES, D. H. JORES, J. A. JONES, J. A. JONES, J. A.	8210270009* 8210010317* 8006170030* 8210010028 8210180116*	50~309 70~143 FOIA 50~261 FOIA	Q H
UNTER.R S UNTER.R S UNTER.R S UNTER.R S UNTER.R S	8210050138 8210050159 8210050211 8210050349 8210040296*	50-315 (50-316 (50-315 (3 3 3 3	Jape. F Jape. F Jape. F Jape. F Jape. F	8210010151* 8210010176* 8210010208* 8210010240* 8210010432*	50-416 50-261 50-348 50-321 50-257	0 0 0	A RESNOL JUNES, J K JUNES, J L JUNES, L H JUNES, R A	8210180353* 8210190177* 8210150084* 8210260211 8210040030*	FOIA CONTRACT 50-269 NUREO 50-445	8
UNTER.R S UNTER.R S UNTER.R S UNTER.R S UNTER.R S	8210190676 8210220393 8210220478 8210250228 8210180371*	50~315 50~315	? 3 3 5	JAPE, F JAPE, F JAPE, F JAPE, F JAPE, F	8210010459* 8210010472* 8210150062* 8210150143* 8210150269*	50-369 50-395 50-370 50-269 50-389	Q Q Q	JONES, R A JONES, 8 Z JONES, 8 Z JONES, 9 Z JONES, W C	8210180008* 8210120527 8210120628 8210210527 8209170051	50-445 40-8102 40-6659 40-6659 50-285	K F
JAT.D LAT.D UAT.D UAT.D UAT.D	8210070039* 8210070043* 8210070047* 8210070050* 8210070053*	50~537 50~537 50~537	A D D D	JAPE, F JAPE, F JAU, W C JENKINS, O R JENKINS, O R	8210220147* 8210220337* 8210050412 8210010159* 8210150021*	50-324 50-370 NUREG 50-335 50-369	Q Q Q	JONES, W C JONES, W C JONES, W C JONES, W C	8210040186 8210050247 8210050301 8210060196 8210070333#	50-285 50-285 50-285 50-285 50-285	8 8 9 0
JSEBY.D E JSEBY.D E JSEBY.D E JTTON.J W JTTON.P H	8210170296* 8210270273* 8210280267* 8210070133 8210080322	50-317 5 50-317 5	3 3 7	JENKINS, OR JENKINS, OR JENKINS, GR JENKINGS, RT JENS, WH	8210150025* 8210150401* 8210220461* 8210130558* 8210130282	50-369 50-261 50-338 50-317 PR	Q Q Q S	JONES. U C JONES. U C JONES. U C JORDAN, E JORDAN, E	0210130570 8210170736 8210200077 8210080213* 8101050528	50-285 50-285 50-285 FOIA 50-247	\$ R P
MATONIS, A MATONIS, A JOE, V M MBRD, E MBRD, E	8210190447 8210190453 8207180037 8104100203* 8107300168*	50-269 50-483 50-313	3 3 5 6 6	JOHANSEN, J JOHANSEN, J JOHANSEN, J JOHANSEN, J JOHANSEN, J JOHANSEN, J JOHANSEN, W L	8210270075# 8210260345# 8210290241# 8210010428# 8210060227#	50-289 40-8610 70-33 40-1202 70-7	Q	JORDAN, E L. JORDAN, E L. JORDAN, E L JORDAN, E L JORDAN, E L	8105040420* 8105280476* 8108210025* 8210080187* 8210180592	50-352 50-263 FOIA FOIA NUMEQ	Q Q
1880. E 1880. E 1880. E 1880. E 1980. E V	8112010310* 8210070416 8210080018 8210080028 8203120016*	50-324 50-336 50-368	3 5 8 5 8	JOHNSON, A H JOHNSON, A H JOHNSON, A R JOHNSON, B	8210010459* 8210150062* 8210220337* 8210190761* 8210040346*	50-369 50-370 50-370 98779 50-537	G G A	JORDAN, H JORDAN, M JORDAN, M JORDAN, M J JORDAN, W 8	8210210014 8210050182 8210050353 8210150538* 8210200026	NUREQ 50-263 50-409 50-10 50-443	8 0 0
1980.E V 1980.E V 1980.E V 1980.E V 1980.E V	8203290028* 8203290031* 8210060430* 8210070425 8210080017	50-293 (50-336 (50-335 (3 3 3 3	JOHNBON, B JOHNBON, B JOHNBON, B JOHNBON, B D	8210040349* 8210040351* 8210210274 8210050265 8210050302	50-537 50-537 50-454 50-255 50-255	A Q P P	JORDAN, W 8 JORDAN, W 8 JORDAN, W 8 JORDAN, W 8 JORDAN, W 8	8210200026 8210200035* 8210200035* 8210200042* 8210200042*	50-443 50-443 50-443 50-443 50-443	00000

AUTHOR	ACCESSION NUMBER	SUBJE CATEO		AUTHOR	ACCESSION NUMBER	SUBJ		AUTHOR	ACCESSION	
JORDAN,WS JORDAN,WS JORGENSEM,BL JORGENSEM,BL JUDD,BR	8210200049 8210200049 8210190449 8210190707 8210150548	50-443 50-255 50-255 NUREO	G	KEISER, H W KEISER, H W KEISER, H W KEISER, H W KEISER, H W	8210040084 8210040118 8210130352 8210130363 8210130377	50-38 50-38 50-38 50-38 50-38	7 5 7 5 7 5 7 5	KERRIGAN, J D KERRIGAN, J D KERRIGAN, J D KERRIGAN, J D KERRIGAN, J D	NUMBER 	50-387 1 50-441 1 50-387
JULIAN, C JULIAN, C JULIAN, C JULIAN, C JULIAN, C A	92100102064 92100102255 92100103464 92102203274 9210190376	50-338 50-250 50-250 50-251	0 0 8	KEISER, H W KEISER, H W KEISER, H W KEISER, H W KEISER, H W	8210210285 8210210433 8210210440 8210250347 8210250357	50~387 50~387 50~387 50~387 50~387	7 S 7 S 7 S	KERRIGAN, J D KERRIGAN, J D KERRIGAN, J D KERRIGAN, J D KERRIGAN, J D	9210210026 9210210317 9210210500 9210270006 9210270324	50-389 / 50-382 / 50-5;2 / 50-41
JULIAN, C A JUNGE, M A JUNGE, M A JUNGE, M A JUSTUS, P S KACICH, R M	8210220303* 8210040069* 8210040219* 8210130578* 8210120351	50-318 50-318 50-317 WASTE N	5 5 5 407	KEISER.H W KEISER.H W KEISER.H W KEISER.H W KEITH.H N	8210250369 8210250381 8210260509 8210280215 8210040332*	50-387 50-387 50-387 50-387 50-333	7 S 7 S 7 S	KERRIGAN, J D KERRIGAN, J D KESSLER, J KETZLACH, N KEY, W J	8210270339 8210280416 8210200019 8210270392 8210130557	50-3 ₅ 50-5 50-24 • 70-27
KACICH,R M KADAMBI,N P KADAMBI,N P KADAMBI,N P KAEFER.W B	8210130326 8210130326 8210130647 8210210258 8210210312	50-10 50-10 50-400 50-400	P A A A	KEITH,H N KELLER,H T KELLEY,D L KECLEY,J L KECLEY,J L	8210040292* 8210270208* 8210070369* 8210050267 8210060184	50-333 50-338 50-445 50-361	Р 0	KIEL, R L KINDER, E T KINGS, M KINGSLEY, O D KINGSLEY, O D	8210260561 8210250307 8210260215 8210080294 8210080294	
KAHLE, J B KAHLE, J B KAISER, G D KAISER, W T	8210010127* 8210010130* 82101501306* 8210210306* 8210170427*	50-275 70-1201 70-824 50-329 50-282	S A P	KELLY, D B KELLY, J A F KELLY, J A F KELLY, J J KELLY, J W	8210010307 8210010178* 8210260301* 8210260145 8210220497	PR 50-313 50-298 50-247 70-27	Q	MINNEMAN, J D MINNEMAN, J D MINNEMAN, J D MINNEMAN, J D MINNEMAN, J D	8210010418 8210060225 8210060227 8210260341 8210260345	40 LE 70-7 70-7 40-8±,
KALEELR J KALIVIANAKIS,N KALIVIANAKIS,N KALIVIANAKIS,N KALIVIANAKIS,N	8210050418 8210060395 8210120551* 8210130192 8210130251	NUREO 50-254 50-254 50-254 50-254	5 6 5	KELLY, J W KELMERS, A D KEMPER, J S KEMPER, J S KEMPER, J S	8210270232 8210150564 8210040224 8210040362 8210220374*	70-27 NUREG 50-352 50-352 50-352	Q A Q	MINMENNIJ D MINMENNIJ M MINNEY, W MINTMEN, L MINTMEN, L MIPER, K L	8210290241* 8210010426* 8210290304* 8210120026 8210080313	70-33 40-12
KALIVIANAKIS, N KALIVIANAKIS, N KALIVIANAKIS, N KALIVIANAKIS, N	8210130324 8210130386 8210130413 8210130466 8210130501	50-254 50-254 50-254 50-254 50-254	5 5 5 5	KEMPKA, S N KEMNEDY, D M KEMNEDY, R T KEMNEDY, R T KEMNEDY, R T	8210150571 8210130138 8210010079* 8210010105* 8210070448*	NUREG 50-255 50-366 50-366 FOIA	R S B	KIRK, C B KIRSCH, D F KIRSCH, D F KIRSCH, D F KIRSCH, D F	8210270074* 6210060124* 8210060267* 8210170250 8210170501*	50-324 50-342
KALIVIANAKIS,N KALIVIANAKIS,N KALMAN,K L KAMATN,P S KAMMER.D S	8210190658 6210250148 8210040344 8210050340 8210010135*	50-254 50-254 40-8697 NUREO 50-327	s s	KENYON, T J KENYON, B D KENYON, B D KENYON, B D	8210070216* 8210060391 8210080142 8210080146* 8210210417	50-286 50-387 50-387 50-387 50-387	Ф Р Р	KIRSCH.D F KIRSHEN,A H KISTER,H KISTER.H KISTER,H	8210280303+ 8210060244 8210010007 8210060046+ 8210070216+	50 275 50-265 50-260 50-247 50-284
KAMMER, D S	8210010197* 8210010420* 8210250236 8210250244 8210260148	50-438 50-518 50-259 50-250 50-327	Q Q F F P	KENYON, B D KENYON, B D KENYON, T J KEPPLER, J G KEPPLER, J G	8210260350 8210290230 8210190084 8011060565* 8209160503	50-387 50-387 50-390 50-254 50-295	P P A S	KISTER, H KISTER, H B KISTER, H B KISTER, H B KLEINSORGE, W P	8210210307* 8210070350* 8210210115* 8210270173*	50-247 50-220 50-233 50-246 50-420
KAMMER.D S KAMMERER.C KANE.R S KANE.N F KANE.N F	8210240228 8210070454* 8210050341 8210080309 8210270136*	50-327 F0IA 50-199 50-395 50-387	P P P	KEPPLER, J Q KEPPLER, J Q KEPPLER, J Q KEPPLER, J Q KEPPLER, J Q	8209270242 8210050105 8210050107* 8210050186 8210050194*	50-358 50-295 50-295 50-266 50-266	H Q Q	KLINE, J R KLINE, J R KLINE, J R KLINE, J R KMETYK, L N	8210050251 8210070127 8210130333 8210210476 8210250397	90-285 50-443 50-443 50-443
KAMEN, A C KANGA, B K KANGA, B K KANGA, B K	8210240232 8210040200 8210070220 9210070224 8210070345	50-322 50-320 50-320 50-320 50-320	T P R P	KEPPLER, J O KEPPLER, J O KEPPLER, J O KEPPLER, J O KEPPLER, J O	8210060253 8210080194 8210130186 8210130400 8210130403*	50-315 50-315 50-341 50-409 50-409	0 P 0 0	KNIGHT. J P KNOLL. F J KNOP. R KNOP. R C KNOP. R C	8206290655+ 8210290202 8210190637 8210130221 8210250224	NUMES 50-264 50-264 50-461 50-545
KANGA, B K KANGA, B K KANGA, B K KANGA, B K	9210130583 8210150043 8210150085 8210170570 8210200012	50-320 50-320 50-320 50-320 50-320	P P P P	KEPPLER, J G KEPPLER, J G KEPPLER, J G KEPPLER, J G KEPPLER, J G	8210130451 8210130459* 8210130547 8210150487 8210190532	50~461 50~461 50~461 50~254 50~305	9 9 9	KNOP, R C KNOX, J KNOTH, D F KNOTH, D F KOCH, L J	8210280174# 8210120128 8207050005# 8210130397 8210050183	50-461 50-461 50-443 PR
KANGA, B K KAPLAN, C KATAOKA, I KAUCHER, J E KAUCHER, J E	9210260236* 9210160138 9210150556 9209190178* 9209190290*	50-320 50-247 NURE0 50-213 50-302	G P P	KEPPLER, J G KEPPLER, J G KEPPLER, J G KEPPLER, J G KEPPLER, J G	8210190635 8210190699 8210190763 8210190771* 8210250312	50-358 50-255 50-440 50-440 50-395	Q Q Q Q	KOCH, L J KOCH, L J KOEBEL, C KOESTER, O L KOESTER, G L	8210130325 8210130470 8210120046± 8210040364 8210120199	50-461 50-461 FOIA 50-482
KAVANAUGH, P F KAY, D L KAY, J L KAY, J A	8210120471* 8210190744* 8210190346* 8210130401 8210130363	CONTRACT 50-373 50-373 50-29 50-29	6 6 0 P	KEPPLER.J Q KEPPLER.J Q KEPPLER.J Q KEPPLER.J Q KEPPLER.J G	9210250320 6210260179 6210260198 6210260204 8210260371	50-243 50-255 50-263 50-461 50-409	P P F A	KOEBTER. O L KOESTER. O L KOLBE. R KOLTAY. P KOLTAY. P	8210120777 8210220403 8210220403 8210130552 8210060046# 8210210307*	50-482 PR PR NURED 50-247
KAYANABIN C KEAHER, W H KEARNEY, J KECKEIBEN, T	8210250097* 8210180229* 8210270054 8210130282 8210130353*	FOIA 40-2259 PR	P S	KEPPLER, J Q KEPPLER, J G KEPPLER, J G KEPPLER, J, G KEPPLER, P	8210280170 8210280174* 8210280174* 8210280174* 8210270330 8210250035	50-461 50-461 50-461 50-358 40-8820	G G A	KOMOSKY, G KONG, Y H KONKLIN, J E KONKLIN, J E	8210210160* 821028020[* 8210130222* 8210130529*	50-247 50-336 50-277 50-345 50-463
KEDDIB, N N KEIMIG KEIMIG, R KEIMIG, R	8210270124 8210130405 8210290366 8210220447 8210260483	50-387 50-277 50-334	A 8 8 6	KERRIGAN, J KERRIGAN, J	8210270073* 8210050446 8210010227* 8210050373 8210130571	50-322 50-320 50-361 50-443 50-361	Q P P A	KOON, A R KORNEGAY, P C KOT, C A KOUTS, H KOUTS, H	821025080= 8210220346+ 8210150364 8210150537 8207180066	50-341 1 50-395 1 NUREQ NUREQ ACRS
KEIMIO.R R KEIMIO.R R KEISER,H W KEISER,H W KEISER,H W	8210070240* 8210290304* 8210010177 8210010228 8210010393	50-387 50-387	8 8 9	KERR IGAN, J KERR IGAN, J KERR IGAN, J KERR IGAN, J. D	8210130573* 8210210035 8210010037 8210120025	50-361 50-400 50-400 50-526 50-387	P A F A E	KOVACK, T S KRATZER, M B KRAUSE, D KREGER, H E KREGER, W, E	8207180066 8210280364* 8210070498* 8210040203* 8108270422* 8111090062*	ACRS 50-254 / FOIA 50-315 / 50-261 / 50-266 /

ROHT UA	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGOR	Υ	AU FHOR	ACCESSION NUMBER	SUBJECT CATEGORY
PEGERNE	8112020885* 8112300287*	50-324 P 50-324 P	LAINAS, O C LAINAS, O C	8210210553* 8210290118	50-346 TOPREP	P	LEASBURG R H	8210120258	50-280 P 50-280 P
PREGER. W E	8201150176*	50-537 D	LAINAS, G C	8210290450	ORG		LEASBURG.R H LEASBURG.R H	8210120265 8210120297	50-280 P
· REGER, W E	9201200656*	50-241 P	LAINAS, G C	8210290453	TOPREP		LEASOURGIR H	8210130112*	50-338 F
FEIN II S	6210270336	NUREG	LAINAS, O C	8210290458	TOPREP		LEASBURG R H	8210130427	50-280 G
FESSIT S	8210120453 8210130284	RES 50-341 F	LAIRD, R C LAMP, M S	8210040183* 8210040313*	50-220 50-316	P 8	LEASBURG R H	8210190321	50-339 P
PREUSIR E PRIEGERIR M	8210080093	50-206 P	LANCASTER, B T	8210040033*	50~445	ä	LEASBURG R H	8210200043	50-280 P 50-338 P
ARTEGER, R W	8210240214	50-206 P	LANDGRAF, L C	8210010287	50-341	ĸ	LEASBURG, R H LEASBURG, R H	8210220011 8210220170	50-280 P
PREGER R W	8210260272	50-206 P	LANDGRAF, L C	8210010289	50-341	ĸ	LEASBURG, R H	8210220178	50-280 P
satisa's A	8210070075 8210130161	50~440 0 50-289 F	LANDIS, K D	8210190376	50-251	5	LEASBURG R H	8210220200	50-33B Q
FEIRM B H	8210130320	50-2B9 F	LANDSMAN, R B LANDSMAN, R B	8210050154* 8210190750*	50-329 50-329	0	LEASBURG R H	8210220373	PR
H R PMISS	B210130430	50-387 F	LANGER, R R	8210180430*	FOIA	u	LEASBURG, R H	8210250208	50-338 F
FRINMAR K FRUS H E	8210220147*	50-324 0	LANGER, R R	0210100430*	FOIA		LEASBURG R H	8210260133	50-338 P 50-338 P
	8210290269	PR					LEASBURG, R H	8210270160	-
PUBLICAN R A	8210010402*	50-3B7 5	LARIK.O Larik.o	80 (106056) 8210060082*	50~254 50~276	8 5	LEASBURG.R H	8210270204	50-338 ₽
FUCZYNEKI, L A	8210040088#	50-387 5	LANIK, G	8210070438	50-219	S	LEASBURG, R H	8210270256	50-338 P 50-280 P
PUNCHANIU K	8210120342*	CONTRACT	LANIK, O F	8(10230085*	50-219	S	LEASBURG R H	8510580130	50-280 P 50-280 P
ALLEROMANIA J A	8210120423*	90-389 M	LANNING, H	8112100374*	FOIA	_	LEASBURG, R H LEASER, J D	821028026 <i>6</i> 8207090224*	50-280 P
	8210080352	RES	Lanning, H	8203130539*	50-272				-
FURTZ: P. H.	8210210321*	50-309 G	LANNING, H D	8012270118	50-272	6 6	LECLAIR, D E	0210170004*	CONTRACT
FUESPARRIN L L HEUREUX,R W	Q2101305/8*	50-317 S	LANYING, H D	8107160079*	50-240	s	LEDDICK, R S	#210070161*	50-508 Q RES
L V TAEHL	621018034H*	CONTRACT	LANNING, W D	*46004011B	50-313	8	LEE, B S LEE, L S	821012045 <i>9</i> 8207290410	NUREG
ACE: N J	8210240129*	50-334 F	LANNING, H B	8205030617#	50-247	s	TEE'N	8210210054	NUREG
LACEYING	8210040045	50-334 S	LANKING, H D	8205030619*	50-247	s	LEE, N	8210220154	NUREQ
LACEY, H S	B210190185	50-334 E	LANHING, H D	8205190428*	50-327	S	LEE D R	8210250083	50-267 F
LHCEY. U S	8210150199	50-334 8	LAMITTNO, H D	8205190441*	50~327	S	LEE, G R	8210270104	50-267 P
LACE VIN S	8210150201*	50-334 S	LANHING: II D	8207150106#	50-261	P	LEE. O R	82102701134	50~267 P
tacerall 8	8210190274	50-334 S	CANHING, W D	8210070104	50-313	6	LEE, T D	8210150204*	70-143
LACELLUS	B2101902B2*	50-334 S	LANNING II D	8210070490	50-260	S	LEECH, P	8210010082*	50-537 Q
LACEYIN S	8510510009	50-334 S	LANNING, IJ D	8210120120	50-334	P	LEIGH.D N	B210010440*	40-1202
LACES W S	8210210065	50-334 8	LANMING, W D	8210120182	50-295	6	LE [KEN. L	8210200057	70-143
LACETUUS	8510590193	50-334 8	CANPHER, L C	8210050383	50-322	Q	LE INEN. L	8210250040	70~143
LACEY. (1 S	8210260203	50-334 S	LANPHER, L C	8210050383	50-322	0	LEMPGES, T E	8210010165*	50-220 0
LAÇ€1.H 5	8210240470	50-334 S	LANPHER.L C	8510300039	50-322	¢	LEMPGES, T E	8210010287*	50-220 @
LACEY II 5	8210260487×	50-334 8	LAMPHER, L C	8210200076	50~322	G	LEMPGES, T E	8210040182	50-220 P
LHCEY, W S	B210200271	50-334 S	LANPHER L C	8210200076	50-322	Q	LEMPGES, T E	8210090148	50-220 F
LHCEY.W 5	8210280200	50-334 6	LANPHER, L C	821-0200083*	50-322	G	LEMPGES, T E	851009050B*	50-220 0
LACEY.II S	8210280307	50-334 s	LANPHER: L C	8210200083#	50-322	0	LEMPGES. T E	8210040284	50-220 S
LACUPLER	8210270241*	70-33	LANPHER, L C	8210200089*	50-322	Ģ.	LEMPGES, T E	8210130347	50-220 R
H H.TRABIA	BZ10250383	50-219 F	LANPHER, L C	8210200089*	50~322	G.	LEMPGES. T E	8210260184*	50-220 G
LAG I ENSKE, J S	B210040144*	50-317 8	LANSFORD R A	8210040042*	50-445	o.	LEMPGES, T E	8210280144	50-220 P
LHU LEHSKI J S	8210130465*	50-317 8	LARSON, C E	0210150255*	50-282	Q.	LENTINE, F G	8210050207	50-295 F
LAGIENSKI, J S	8210270269*	90-317 B	LARSON, C E	8210190439*	50-282	O·	LENTINE, F 0	8210050270	50-295 P
LASTEWSKI, J 5	8210270273*	50-317 8	LARSON, T X	8210150409	RES		LENTINE, F 0	8210080111	50-275 P
LAGIEWSKI, J S	8210280141#	50-318 8	LASHER, C. E	8207120253*	50-447	A	LENTINE.F 0	8210220399	50-275 P
IAI NAS. C	8108190008*	FOIA	LATORA. J	8210150474	50~528	¢	LEG, F A	8210190167#	CONTRACT
LAIFIAS G C	8011120679	50-247 P	LASSAIN, O D	8210150540	NUREG		LESSY, R P	8210050095	27-39
(Alfias, G C	B103120107#	20-321 8	LASSAHN, G D	8210280339	RES		LESSY, R P	8210190370	50-312 0
LAISIAS, G. C	B103240292*	FOIA	LASUA.S R	8210040130	18E		LEVINE, J H	8210050346	50-368 8
LA (BLAS) D C	0103310127*	FOIA	LATHAM, & B	8210150309*	50-322	0	LEWIS, D F	8210130505#	50-329 T
PATHIVE & C	B106150555*	50-302 5	LATHAM, & B	9210150337#	50-322	G C	LEWIS D F	8210130505#	50-329 T
LAINAS, G. C	8203170034*	FOIA	LATHAM S II	9210150351#	50-322	Q A	FEMTS' W D	0210260442	50-397 A
LAZIYAS, G. C	* 1 1 4 0 4 0 0 1 SB	FOIA	LATHAM, B B	8210150365#	30-322	G	LEWIS, H I		

PENSUNAL AUTHUR INDEX

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AU THOR	ACCESSION NUMBER	Staf Cater-
LEWIS.R C LEWIS.R C LEWIS.R C LEWIS.R C LEWIS.R C	8210150027# 8210150034# 8210150034 8210150040# 8210150048#	50-324 50-324 50-324	G LINNEMANN, R E G LINVILLE, J C G LIPINSKI, D R G LIPINSKI, R G LIPPOLD, W J	8210190178* 8210210115* 8210210194* 8210190601* 8210260299	50-322 T 50-333 Q 50-245 Q 50-373 Q 50-318 P	LOWENBERG, H LOWENBERG, H LOWENBERG, H LOWENBERG, H LOWENBERG, H	8210010079 8210070084 8210070089 8210070095 8210070098	* 50-537 . * 50-537 . * 50-547 * 50-547
LEWIS.R C LEWIS.R C LEWIS.R C LEWIS.R C LEWIS.R C	8210150100 8210150113* 8210150171 8210150189* 8210150225	50-324 50-438 50-438	G LITERSKI,L A G LITTLE,B H G LITTLE,M G LITTLE,M G LITTLE,M	8209290225* 8210250080* 8210040003 8210120414 8210120490	50-10 F 50-341 G CONTRACT CONTRACT CONTRACT	LOWENBERG, H LOWENBERG, H LOWENBERG, H LOWENBERG, H LOWENBERG, H	82100701014 82100701234 82100701234 82100701284	50-53", 50-53" 50-53"
LEWIS.R C LEWIS.R C LEWIS.R C LEWIS.R C LEWIS.R C	9210150237* 8210150260* 8210150278* 8210150384 6210150396	50-390 50-390 50-416	Q LITTLE, M Q LITTLE, M Q LITTLE, M Q LITTLE, M Q LITTLE, M	8210120510 8210120534 8210120549 8210120607 8210130058	CONTRACT CONTRACT CONTRACT CONTRACT CONTRACT	LOWENBERG, H LOWENBERG, H LOWENBERG, H LOWENBERG, H LOWENBERG, H	8219070131* 8210070131* 8210070139* 6210070142* 8210070146*	50-501 50-531 50-531 50-531
LEHIS,R C LEHIS,R C LEHIS,R C LEHIS,R C	8210220127 6210220137* 6210220237 6210220277 8210220272*	50-400 50-438 50-321 50-321	0 LITTLE, M 0 LITTLE, M 0 LITTLE, M 0 LITTLE, M 11TTLE, M	821 0130071 8210180345 8210180375 8210180411 8210190210	CONTRACT CONTRACT CONTRACT CONTRACT CONTRACT	LOWENBERG, H LOWENBERG, H LOWENBERG, H LOWENBERG, H LOWENBERG, H	8210070148+ 9210070151+ 8210070154+ 82100701574	50-501 53 551
LEWIS, R C LEWIS, R C LEWIS, R C LEWIS, R C	6210220276 6210220310* 6210220469 6210220495 6210220500*	50-250 50-327 50-261 50-261	1 LITTLE, M LITTLE, M LITTLE, M LITTLE, M LITTLE, W S	8210210147 8210210502 8210260516 8210260525 8210060305	CONTRACT CONTRACT CONTRACT CONTRACT 50~440 Q	LOWENDERO, H LOWENDERO, H LOWENDERO, H LOWENDERO, H LOWENDERO, H	8210070166* 8210070170* 8210070174* 8210070186* 8210070190*	
LEHIS,R C LEHIS,R C LEHIS,R C LEHIS,R C LEHIS,R C	8210260309 8210260370 8210260376 8210260510* 8210270229	50-302 (50-302 (50-335 (50-335 (50-302 (LITTLE, W S LITTLE, N S LITTLE, W S	8210040329 8210040379 8210130368 8210190589 8210190617	50-10 8 50-373 0 50-341 0 50-373 0 50-275 0	LOWENBERG, H LOWENBERG, H LOWENBERG, H LOWENBERG, H LOWENBERG, H	8210070195# 8210070200# 8210070204# 8210070206# 8210070207#	50-531 50-531 50-531 50-531 50-537
LENIS, S H LENIS, S H LEWIS, S H LIAW, C Y LICITRA, E A	8210040017 8210040021 8210040022 8205250020* 8210130053	50-440 0 50-320 0 50-367 0 50-155 F 50-400 A	LITTLE, WS	8210190619 8210190669 8210190682 8210130509 8210190633	50-440 A 50-266 Q 50-373 Q 90-331 P 50-461 S	LOWENBERG, H LOWENBERG, H LOWENBERG, H LOWENBERG, H LOWENBERG, H	8210070222+ 8210070223+ 8210070225+ 8210070251+ 8210070259+	50 537 50-537 50-537 50-537 50-537
LICITRALE A LIDEN,E A LIDEN,E A LIDENERA LIEBERMAN,E	8210210320 8210180009 8210190507 8210220275 8210150188*	50-400 A 50-272 F 50-272 P 50-272 P 50-322 T	LIVERMORE, H H LO.R LO.T	8210130557* 8210250232* 8210050537 8205250010* 8207300222*	50-461 Q 50-461 Q 50-320 P 50-155 P 50-206 P	Lowenberg, H Lowenberg, H Lowenberg, H Lowenberg, H Lowenberg, H	8210070260* 8210070262* 8210070264* 8210070264* 8210070269*	50-511 50-511 50-531 50-531 50-531
LIEBERMAN, E LIEBERMAN, E LIEBERMAN, E LIEBERMAN, E LIEBERMAN, J	8210150188* 8210150206* 8210150240* 8210150240* 8208260424	50-322 T 50-322 T 50-322 T 50-322 T 50-280 Q	LOCKE, R F LOCKE, R F LOCKE, R F	8103050756# 8210130487 8210060220 8210250192 8210250196#	FOIA 50-413 D 50-275 G 50-133 R 50-133 R	LOWENBERO, H LOWENBERO, H LOWENBERO, H LOWENBERO, H LOWENBERO, H	8210070273 8210070276 8210070280 8210070285 8210070285	50-537 50-547 50-537 50-537 50-537
LIHDU, H LIHDU, H LIHDU, H LIN, H C	8210130253* 8210130473* 821013051[* 8210250153* 8210150557	50-254 8 50-254 8 50-254 8 50-254 8 NUREO	LOFTUS, M J	6210210054 6210220154 6210260280* 8210040338 6210250264	NUREO NUREO CONTRACT 40-8502 50-219 P	LOHENDERO, H LOHENBERO, H LOYSEII, P LUBENAU, J O	82100702914 8210070293+ 8210070298+ 8210120299+ 8012180342+	50-537 53-537 50-537 50-257 FOLA
LINDEN, E A LINDER, F LINDER, F LINDER, F LINDER, F	8210270136 8210010389 8210040152 8210050067 8210050339	50-272 P 50-409 P 50-409 F 50-409 P	LONG.A B LONG.D J LONG.F J LONG.F L LONG.J #	8210120397 8207050085 8210010194* 8210220180 8210180137*	RES 50-247 P 50-324 Q 50-438 Q 50-344 S	LUBENAU, J O LUDWIG. P G LUEBKE, E A LUEIT, W LUKENB, L L	8210120018+ 8210130445+ 8210250223 8210040252+ 8210250033+	FOIA 50-Jer 50-142 50-373 NURES
LINDER, F LINDER, F LINDER, F LINDER, F	8210130365 8210150203 8210150446 8210150448 8210150454*	50-409 F 50-409 P 50-409 S 50-409 Q	LONG.R L LONGENECKER, J LONGENECKER, J LONGENECKER, J LONGENECKER, J	8210259097* 8209300353 8210040167 8210040251 8210040304	50-219 P 50-537 B 50-537 A 50-537 A 50-537 A	LUNDELL.B E LUNDVALL.A E LUNDVALL.A E LUNDVALL.A E LUNDVALL.A E	#970040059 #21070015B #E010E3015B #E00E10159	40 8781 50-317 50-317 50-317 FR
LINDER.F LINDER.F LINDER.F LINDER.F	8210220009 8210220174 8210250349 8210260319 8210280048*	50-409 J 50-409 Q 50-409 F 50-409 F	LONGENECKER, J LONGENECKER, J LONGENECKER, J LONGENECKER, J LONGENECKER, J	8210060217 8210060249 8210130246 8210130249 8210130311	50-537 A 50-537 A 50-537 B 50-537 A 50-537 A	LUNDVALL, A E LUNDVALL, A E LUNDVALL, A E LUNDVALL, A E LUTKEHAUS, T C	9210180005 8210180124 8210190803# 8210190878 8210190577	50-317 F 50-317 F 50-317 F 50-318 F 50-322 F
LINDER, F LINDER, F LINDER, F LINDER, F LINDSEY, I D	8210280051* 8210280055* 8210290151 8210290307 8210150462	50-409 F 50-409 F 50-409 P 50-409 P 50-416 G	LONGENECKER, J LONGENECKER, J LONGENECKER, J LONGENECKER, J LONGENECKER, J	8210150186 8210210022 8210210273 8210260168 8210260302	50-537 A 50-537 A 50-537 A 50-537 A 50-537 A	LYNCH, M D LYNCH, M D LYDNS, J E LYDNB, J E	8210040380 8210220463 8210220468 82022403974 8203020267*	50-447 # 50-447 # 50-447 # 50-244 #
LINEHAN, J J LINEHAN, J J LINEHAN, J J LINEHAN, J J	8210040338 8210040344 8210040348 8210040365 8210120479	40-8502 40-8697 40-8793 40-8768 40-8786	LONGENECKER, J LONGSINZ, D E LOGKABAUOH, A L LOGKABAUOH, A L LOGKABAUOH, A L LOGKIE, O O	8210260401 8210290399 8210210159* 8210210159* 8210150421	50-537 A RES 50-382 G 50-382 O RES	LYONS, J E LYONS, J E LYONS, J E LYONS, J E	8203040502* 8203100593* 8203110334* 8203110339* 8210070038*	50-244 / 50-244 / 50-244 / 50-244 /
LINEHAN, J J LINEHAN, J J LINEHAN, J J LINENBERGER, Q LINER, R	8210120591 8210120641 8210220515 8210270178 8210040355#	40-8745 40-8681 40-8714 50-537 G 50-537 A	LORENZ,R A LORIO,P LOTITO,E LOTITO,E M LOTIS,A L	8210210457* 8210210328	50-259 F PR 50-317 R 50-317 R RES	LYONS, J E LYONS, J E LYONS, J E LYONS, J E LYONS, J E	8210070068* 8210070074* 8210070076* 8210070080* 8210070083*	50-244 / 50-244 / 50-244 / 50-244 / 50-244 /
LINER,R LINER,R T LINNEMANN,R E LINNEMANN,R E LINNEMANN,R E	8210040357* 8210040350* 8210040037* 8210040037* 8210150178*	FQIA 50-537 A 50-445 Q 50-445 Q 50-322 T	LOTTS, A L LOVE, R S LOVENDALE, P C LOVENDALE, P C LOW, R L	8210130557* 8210050205* 8210050380*	RES 50-461 G 50-266 G 50-186 G PR	LYONS, J E LYONS, J E, LYONS, P J MACDONALD, C E MACDONALD, C E	8210070087* 8210070090* 8210220491 8210120146 8210120150*	50-244 F 50-244 F 40-299 71-6347 71-6347

MUTHER	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT	AUTHOR	ACCESSION NUMBER	SUBJECT
TANDER LOS E TANDERS DE CE MANDERS	8210120158 8210120146* 8210120169 8210120174* 8210120180	71-9001 71-9001 71-9034 71-9034 71-6703	MAJOR, R MAJOR, R MAJOR, R MAJOR, R MALARO, J C	8210060008* 8210060026* 8210060051* 8210180061*	FOIA FOIA FOIA 50-289 D FOIA	MARTIN, T T	8210040345 8210070277 8210070294 8210070307 8210070317	70-1100 50-293 Q 50-278 Q 70-364 50-277 Q
MACDOMALD, C E MACDOMALD, C E MACDOMALD, C E MACDOMALD, C E MACDOMALD, C E	8210120192* 8210120334 8210120336* 8210120339 8210120340*	71-6703 71-7010 71-7010 71-7037 71-7037	MALARD, J C MALARD, J C MALARD, J C MALARD J C MALINAUSHAS, A	8210180326# 8210180328# 8210180343# 8210220080# 8210120453	FOIA FOIA FOIA 40-8111 RES	MARTIN, T T	8210070341 8210070352 8210070392 8210130079 8210130178	50-217 Q 50-245 Q 50-443 Q 50-317 Q 50-309 Q
MATEORALD C E MAY BORALD, C E MAY BORALD, C E MAYBORALD, C E MAYBORALD, C E MAYBORALD C E	8210120344 8210120352* 8210120361 8210120384* 8210150653	71-9964 71-9964 71-5908 71-5908 71-6346	MALLETTIB S MALLETTIB S MALMROS.M H MALSCHIM G MANCINITE A	82(0180435# 82(0180436# 82(0190743# 8205270526# 8210080022#	FOIA FOIA 50-344 G FOIA CONTRACT	MARTIN, T T MARTIN, T T MARTIN, T T MARTIN, T T MARTIN, T T	8210130441 8210170375 8210210052 8210210069 8210210091	XPORTLIC 50-217 G 50-287 G 50-352 G 50-354 G
MACODMAND C E MACODMAND C E MACOMAND C E MACOMAND C E MACOMAND C E	8210150±02 8210150±91 82102405494 8210280311 82102803114	71-9151 71-9044 70-143 71-905/ 71-9057	MANGAN, C V	8210010413* 8210010033 8210040117 8210040276 8210050111	50-275 P 50-220 P 50-220 P 50-220 F 50-220 P	MARTIN, T T MARTIN, T T MARTIN, T T MARTIN, T T MARTIN, T T	8210210109 8210210146 8210210201 8210210221 8210210221	50-354
MACDONALD C E	821028032# 821028032# 8210280334* 8210280334* 8210280334	71~6346 71-6346 71-6745 71~6745 71~6677	MANGAN, C. V. MANGAN, C. V. MANGAN, C. V. MANNO, S. F.	8210050260 8210050354 8210130107 8210210322 8210040071	50-220 P 50-220 P 50-220 P 50-410 H 50-410 S	MARTIN, T T MARTIN, T T MARTIN, T T MARTIN, T T MARTIN, T T	8210210255 8210210313 8210210435 8210210437 8210220168	50-220 0 50-309 0 50-272 0 70-2116 70-371
MACDONALDIC E MACDONALDIC E MALEGNALDIC E MALEGNALDIC E	8210/80345* 8210280344 8210280338 8210280335*	71-6677 71-6678 71-6678 71-6115 71-6115	MANNO, 6 F MANNO, 5 F MANNO, 5 F MANNO, 5 F MANSER, N C	8210040170 8210040190 8210150129 8210250378 8210010184	50-410 9 50-410 9 50-410 5 50-410 5 70-143	MARTIN T T MARTIN T T MARTIN T T MARTIN T T MARTIN T T	8210220177 8210220240 8210220347 8210240177 8210240334	70-371 70-487 50-352 Q 50-220 Q 50-333 Q
MACBORNED C E MACEDINED C E MACEDINA D R E MACEVOY, J A MACEVITY E	951012071\ 9510090425; 8510120415; 8510580324; 8510580324	71-9098 71-9098 RES FOIA 50-170 G	MANSER.W C MANSER W C MANSER.W C MANSER.W C MARCHAL.J	8210150061 8210150371± 8210150408± 8210150477± 8210270094	70-143 70-143 70-143 70-143 xportlic	MARTIN T T MARTIN T T MARTIN T T MARTIN T T MARTIN T T	8210270048 8210270084 8210270103 8210270125 8210270201	50-209
emirenne mairenne facrenne mairenne mairenne	82(0150317 62(0150395 62(0150375 62(070439 62(070439	50-1/0 G 50-1/0 G 50-1/0 G 50-170 G 50-170 G	MARCHAL, J HARCHAL, J MARCHI, M L MARDIS, D C MARGULIES, M D	8210280064 8210280088 8210260263* 8210010049* 8210150383	XPORTLIC XPORTLIC 50-305 8 50-302 0 50-454 0	MARTIN, T T MARTIN, T T MARTIN, T T MARTIN, T T MARTINEZ, F P	8210270236 8210270275 8210270341 8210270350 8206060015#	70-37 50-272 G 50-322 G 50-321 G
MACALINA MACHENA MACHENA US MACHENA US MACHELLA F	8210280220 8210280220 82102204484 82102204488 82102204488	50-170 G 50-170 G 50-170 G 50-170 G 50-170 G	MARGULIES,M D MARGULIES,M B MARKT,D MARKT,D MARKT,D	9210180166 9210180170 9210280138* 9210280138* 9210270430*	50-454 0 50-454 0 50-271 F 50-271 F 50-271 F	A C.ODSGW B V.ODSGW B V.ODSGW C C.ODAGEGW A G.ODAGEGW	0210180284# 8210180287# 8210120400 0210050038# 8210000200#	FOIA FOIA RES FOIA FOIA
MADISONIA MADISOILA L MADEELLO L MADEELLO L MADSENIO L	8210250114# 8210150396# 8210850226 8210090387 8210070364	50-3/3 0 50-269 9 50-267 0 50-458 0 50-445 0	MARKT, D 1 MARSHALL, J R MARSHALL, J R MARSHALL, J R MARSHALL, J R	B210270430* G210070395 G210120247* G210120252* B210130212	50-271 F 50-313 F 50-313 Q 50-313 Q 50-313 S	MASSARO, 8 A MASSARO, 8 A MATERS, 8 R MATERS, 8 R MATHESON, 8 M	8210050500# 8210060367# 8210130158 8210280222 8206270016#	FDIA FDIA 50-341 A 50-341 A COMMISSION
Mageen o l Madeen, o l Padeen, o l Madeen, g l Pageen, g l	8210120030 0210190413 0210190431 0210190547 0210190772	50-382	Marshall, J R Marshall, J R Marshall, J R Marshall, J R Marshall, J R	8210130382 8210130409 8210130513 8210130002 8210130073	50-313 5 50-343 P 50-313 S 50-313 P 50-313 F	U 3.2IHTAN U 3.2IHTAN U 3.8IHTAN U 3.8IHTAN U 3.8IHTAN	8210040100 8210060023 8210070245 8210070340 8210130472	50~273 B 50~273 S 50~273 S 50~273 S 50~273 S
MADSELL G L MADSELL G L MADSELL G L MADSELL G L MADSELL G L	6210170816 6210720122 6210220130 6210220404 6210260276	50~445 0 50~498 0 50~298 0 50~267 0 50~298 0	Marshall. J R Marshall. J R Marshall. J R Marshall. J R Marshall. J R	8210190494 8210190517 8210190545 8210220114 8210250206	50-313 P 50-313 S 50-348 S 50-313 P 50-313 P	MATHIS.C J MATHIS.C J MATHIS.C J MATHIN.E	8210170235 8210250122 8210260127 8210260146 8210130315*	50-293 \$ 71-6346 50-293 8 50-293 6 50-537 A
Padjen, G L Pajer, T R Majpus, D Majnus, D Majer, J E	8210280142 9210050427# 9210280041# 9210280041# 9210280041#	50-247 Q 50-155 P 50-322 F 50-322 F 50-244 P	Marshall, J R Marshall, J R Marshall, J R Marshall, J R Marshall, J R	8210250292 8210260120 8210260192 8210260112 8210290240	50-348 8 50-368 6 50-313 P * 50-313 F PR	MATLOCK,R G MATLOCK,R G MATLOCK,R G MATLOCK,R G MATLOCK,R G	8210070302* 8210070370 8210080195 8210080275 8210080304	50-397 0 50-397 8 50-397 0 50-397 8 50-397 8
Maier. J e Maier. J e Maier. J e Maier. J e Maier. J e	82100103554 8210010444 8210040281 82100402844 8210130175	50-244 P 50-244 P 50-244 P 50-244 P 50-244 S	MARSHALL, W H MARSHALL, W H MARSHALL, W H MARSOLAIS, L D MARSTON, R R	8210070398 8210070398 8210220294 8210180190 8210150021	50-327 G 50-327 G 50-327 G 50-271 F * 50-367 G	MATLOCKIR O MATSONIE R MATTHEWS.C W MATTEAIJ C MATTEAIN J	8210130217 8210050314 8210060424# 8210210261# 8210070021#	50-397 S 1%E CONTRACT 50-423 Q CONTRACT
Maier. J e Maier. J e Maier. J e Maier. J e Maier. J e	8210130439 8210150643* 8210190591* 8210190618* 8210190637*	50-244	Mareton.r r Martin.d e Martin.j Martin.j b Martin.j b	8210220461 8210120536 8210260113 8210010460 8210070103	40-8771 * 50-397 A * 30-341 A	MATTIA:H J MATTIA:H J MATTIA:H J MATTIA:H J MATTIA:H J	8210070459* 8210120350* 8210120364* 8210120401* 8210180370*	CONTRACT CONTRACT CONTRACT
Maier. J e Maier. J e Maier. J e Maiep. J e Maier. J e	8210190647* 8210220352* 8210220360* 8210220363 8210250275	50-244 0 50-244 0 50-244 0 PR 50-244 P	MARTIN, J B MARTIN, R A MARTIN, T J MARTIN, T T MARTIN, T T	9210120147 9210120428 9210060326 9210010157 9210010332	RES * 50~354 0 50~220 0 50~213 0	MATTAM J MATTAM J MATTAM J MATTAM J MATTAM J	8210170010* 8210170185* 8210170337* 8210210444* 8210270203*	50-320 F CONTRACT CONTRACT
Maier, J e Maier, J e Major, R Major, R Major, R	8210250334 8210250217# 8210050478# 8210050473# 8210050539#	FOIA FOIA	MARTIN, T T MARTIN, T T MARTIN, T T MARTIN, T T MARTIN, T T	8210040258 8210040034 8210040079 8210040138 8210040211	50-29 0 50-317 0 70-398	MAITTAN J MAITTAN J J LIBONITTAN J LIBONITTAN J LIBONITTAN	8210270223* 8210270230* 8210010057 8210050220 8210070287*	CONTRACT 50-312 F 50-312 P

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESS ION NUMBER	St.
MATTIMGE, J J L SOMITTAM L SOMITTAM L SOMITTAM L SOMITTAM	8210070294* 8210070331* 8210130175 8210130599 8210190331	50-312 0 50-312 q 50-312 P PR 50-312 P	MCGLESKEY, K E MCGLESKEY, K E MCGLESKEY, K E MCGLESKEY, K E	8210150351* 8210150345* 8210150393* 8210150402* 8210150410*	50-322 0 50-322 0 50-322 0 50-322 0 50-322 0	MCGUIRE. D R MCGUIRE. D R MCGUIRE. D R MCGUIRE. D R MCGUIRE, M F	8210210342* 8210260265* 8210260515* 8210270239* 8210210054	70-27 50-327 50-3 5 50-3.2 NURES
L L.EDMITTAM L L.EDMITTAM L L.EDMITTAM L L.EDMITTAM L L.EDMITTAM	8210190594 8210250065 8210250094 8210250386 8210260231	50-312 P 50-312 F 50-312 P 50-312 S 50-312 P	MCCLESKEY, K E MCCLESYEY, K E MCCLUNO, C E MCCLUNO, C E	8210150422* 6210150527* 6210250059* 8210150490 6210150490	50-322	MCGUIRE, M F MCGUIRE, B A MCGURREN, H J MCGURREN, H J MCGURREN, H J	8210230154 8207280307 8210200055 8210200059 8210280353	NURES 10-55 50-245 50-247 50-247
L COMITTAM R. NOGTTAM R. NOGTTAM L. R. NOGTTAM M. R. NOGTTAM M. R. NOGTTAM	8210280228	50-312 P	MCCLUNG, C E	8210150470	50-361 G	MCINNIS, D	820/180044	50-201
	8010240413*	FOIA	MCCLURE, J D	8210070413*	71-9150	MCINNIS, E L	8210220315	PR
	8010240496*	FOIA	MCCORD, R K	8210150548	NUREO	MCINTOSH, M D	8210280020*	50-327
	8007150303	50-247 P	MCCORKLE, O	8210070084*	50-537 D	MCKEEVER, R F	8210250141*	OAP9,
	8208310034*	50-155 P	MCCRELESS, T G	8210050409*	FOIA	MCKENNA, E M	8010210036	50-3
MATTSON.R J MATTSON.R J MATUSCHECK.R J MAURA,F MAUREF.R J	8210010169* 8210070032* 8210270046 8210170674* 8210180419*	FOIA 50-289 G 40-8781 50-373 G 50-201 P	MCCULLOCH, W H MCDERMOTT, D MCDERMOTT, D MCDERMOTT, D MCDERMOTT, D	8210150571 8210120427 8210120483 8210210036 8210210174	NUREG CONTRACT CONTRACT CONTRACT CONTRACT	MCKEMNA, M MCLEAREN, T MCLEAREN, T MCLEAREN, T MCLENDON, O D	6210050206* 8210120361 8210120416 8210120540 8210150347	50-443 CONTRACT 50-347 CONTRACT 50-542
MAURIN: L V	8209150432 8209150438* 8209220135 8210010370 8210040078	70-2946 70-2946 50-382 A 50-382 F 50-382 S	MCDERMOTT, D MCDERMOTT, D K MCDERMOTT, D K MCDERMOTT, D K MCDERMOTT, D K MCDIARMID, R C	8210280370 8210130008 8210190001 8210260237 8210250356	CONTRACT CONTRACT CONTRACT CONTRACT PROJ	MGLEREN, T MCMURRAY, C M MCMURRAY, C M MCMURRAY, C M MCMURRAY, C M	8210290420 8210010395 8210010395 8210150309* 8210150324*	50-322 50-32 50-32 50-32
MAURIN.L V	8210040110	50-362 A	MCDIARMID.R C	8210250354	PROJ	MCMURRAY, C M	8210150337* 8210150351* 8210150345* 8210150393*	50-322
MAURIN.L V	8210040168	50-382 F	MCDONALD.G K	8210240493*	50-358 E	MCMURRAY, C M		50-322
MAURIN.L V	8210040191	50-382 A	MCDONALD.J A	8210150303*	50-390 G	MCMURRAY, C M		50-322
MAURIN.L V	8210130174	50-382 S	MCDDINELL.E J	8210120550*	Contract	MCMURRAY, C M		50-322
MAURIN.L V	8210130243	50-382 S	MCDOWELL.J	8210240091*	Waste Mgt	MCMURRAY, C M		50-322
MAURITIS L. V	8210130245	50-382 &	MCDUFFIE, M A	8210050106	50-400 A	MGMURRAY,C M	8210150410*	50-322
MAURIN, L. V	8210130551	50-382 S		6210050125	50-400 A	MCMURRAY,C M	8210150422*	50-322
MAURINS L. V	8210130564	50-382 &		8210190512	50-400 A	MCMURRAY,C M	8210150527*	50-322
MAURINS L. V	8210170345	50-382 S		8210200032	50-400 C	MCMURRAY,C M	8210250058	50-322
MAURINS L. V	8210170542	50-382 S		6210200084	50-400 C	MGMURRAY,C M	8210250058	50-322
MAURIN, L V	8210250217 8210250242 8210250254 8210250341 8210250355	50-382 S 50-382 S 50-382 S 50-382 S 50-382 A	MCDUFFIE, M A MCFARLAND, C R MCFAUGHY, J P MCGARRY, J M MCGARRY, J M	8210240442 8210150315* 8210080282 8210050202 8210050202	50-400 A 50-390 Q 50-416 S 50-413 Q 50-413 Q	MCMURRAY.C M MCMURRAY.C M MCMURRAY.C M MCNEILL.C A MCNEILL.C A	8210250057+ 8210270283 8210270283 8210040324 8210060285	50-322 50-322 50-322 50-333 50-333
MAURIN, L V MAURIN, L V MAURIN, L V MAXWELL, O F MA(WELL, J C	8210240362 8210270190 8210270438 8210220163* 8210270035	50-382 F 50-382 K 71-6574 50-400 Q ACRS	MCGARRY, J M MCGARRY, J P MCGAUGHY, J P MCGAUGHY, J P MCGAUGHY, J P	8210050208* 8210050208* 8210010234 8210010243 8210060201	50-413 G 50-413 G 50-414 F 50-416 S 50-416 S	MCNEILL,C A MCNEILL,C A MCNEILL,C A MCNEILL,C A	8210120240 8210150283* 8210190069 8210200018 8210260170	50-333 50-333 50-333 50-333
MAKWELL.J C	8210270035	ACRS	A C'AHORBOW	8210060224	50-416 S	MCNEILL,C A	8210260306	50-333
MAY.E L	8210130225*	50-27 &	A C'AHORBOW	8210080120	50-416 S	MCNEILL,C A	8210260338*	50-333
MAYER.L O	8210150174	50-263 &	A C'AHORBOW	8210080184	50-416 S	MCNEILL,C A	8210260378	50-333
MAYER.L O	8210150381	50-282 &	A C'AHORBOW	8210080223	50-416 S	MCNEILL,H M	8210260558*	0A979
MAYER.R L	8107270146*	50-266 0	B C'AHORBOW	8210080277	50-416 S	MCNIVEN,H D	8107270166*	50-265
MAYES, R L	8107270169*	50-266 0	MCGAUGHY, J P	8210080284	50-416 5	MCNIVEM, H D MCNULTY, A MCNULTY, A MCTIERNAN, T J MEDFORD, M D	8107270174*	50-266
MAYES, R L	8107270174*	50-266 0	MCGAUGHY, J P	8210080295	50-416 5		8210040001	Contra
MAYES, R L	8107270178*	50-266 0	MCGAUGHY, J P	8210180011*	50-416 Q		8210070153	Contra
MAYES, R L	8107270182*	50-266 0	MCGAUGHY, J P	8210150019*	50-416 Q		8210280019*	Pola
MAYES, R L	8107270185*	50-266 0	MCGAUGHY, J P	8210150024*	50-416 Q		8210260450	50-206
MAYES, R L MAYES, R L MAYES, R L MAYES, R L, MAYES, R L	8107270198* 8107270191* 8107270194* 8107270196* 8107270198*	50-244 0 50-246 0 50-244 0 50-244 0 50-244 0	PERPENDENCE OF THE PROPERTY OF	8210180104 8210190417 6210190561 8210220065 6210220131	50-416 R 50-416 S 50-416 S 50-416 S 50-416 S	MEDLOCK, R L MEHAFFEY, R F MELKONIAN, E MENCZER, W B MENDENHALL, E E	8210150644 8210040187* 8210270307 8210040005 8210060405*	40-845 50-285 50-208 50-253 50-254
MAYES.R L	8107270199*	50-246 G	MCGAUGHY, J P	8210220158	50-416 S	MENDEZ, R	8210040384*	50-3/3
MAZETIS.G R	8205050480*	50-261 P	MCGAUGHY, J P	8210220181	50-416 S	MENDONCA, M	8210170501*	50-3/1
MGALPINE.E J	8210010317*	70-143	MCGAUGHY, J P	8210220196	50-416 S	MENDONCA, M	82102803034	50-2/5
MGALPINE.E J	8210010361*	70-27	MCGAUGHY, J P	8210220259	50-416 S	MENTER, L	8210270143	XPDR1L
MGALPINE.E J	8210010371*	70-143	MCGAUGHY, J P	8210220269	50-416 S	MERCER, J W	8210120350*	CONTRA
MGALPINE, E J	8210190067*	70-824	HCGAUGHY, J P	8210220278	50-416 S	MERKLE, J O	8210050504	RES
MGALPINE, E J	8210190067*	70-1113	HCGAUGHY, J P	8210220284	50-416 S	MERR I WEATHER, N	8210010216#	50-389
MGALPINE, E J	8210150204*	70-143	HCGAUGHY, J P	8210220428	50-416 S	MERR I WEATHER, N	8210010384#	50-404
MGBREARTY, R A	8210210264*	50-220	HCGAUGHY, J P	8210220438	50-416 S	MERR I WEATHER, N	8210010433#	50-516
MGBREARTY, R A	8210290280*	50-293	HCGAUGHY, J P	8210260445	50-416 S	MERR I WEATHER, N	8210220189#	50-436
MCBRIDE,L M	8210130349*	50-247 R	MCGAUGHY, J F	8210260513	50-416 S	METZGER, J R	8210150136#	70-824
MCBRIDE,L M	8210190667*	50-247 R	MCGAUGHY, J F	8210290050	50-416 S	MEYER, O W	8210210056#	50-281
MCBRIDE,M F	8210280250	50-287 Q	MCGAUGHY, J F	8210290073	50-416 S	MEYER, J F	8008130744	50-247
MCCABE	8210060376	50-217 S	MCGAUGHY, J P	8210290124	50-416 S	MEYER, J F	8009080466	50-3
MCCABE,E C	8210130405	50-387 S	MCGAUGHY, J P	8210290193	50-417 B	MEYER, K A	8210120399#	50-331
MCCABE, E C	8210150235#	50-317	ncoaughy, J P	8210290311	50-416 S	MEYER, D R	8210120397	res
MCCABE, E C	8210170714#		McGaughy, J P	8210290340	50-416 S	MICHEL, C J	8210220395	pr
MCCABE, E C	8210270210#		McGaughy, J P	8210290348	50-416 S	MICHEL, C J	8210260568	70-14:
MCCABE, E C.	8210270366		McGrath, J R	8210120308*	50-259 0	MICHEL, C J	8210260571	70-14:
MCCANE, E C	8210150302#		McGuire, D R.	8210080228*	50-321 Q	MICHEL, C J	8210270235	70-14:
MCCARDELL, R K MCCLESKEY, K E MCCLESKEY, K E MCCLESKEY, K E MCCLESKEY, K, E,	8210150412 8210150296* 8210150309* 8210150324* 8210150337*	RES 50-322 0 50-322 0 50-322 0	MCOUIRE.D R MCOUIRE.D R MCOUIRE.D R MCOUIRE.D R MCOUIRE.D R	8210210223* 821010206* 8210210206*	50-395 Q 70-143 50-348 Q 50-13 Q 70-1201	MICHELBON, C MICHELBON, C MICHELBON, C MICHELBON, C	8009240202 8107010161* 8107090355* 8108240273* 8108270056*	50-33(50-36) FOIA FOIA FOIA

ADH) UA	ACCESSION NUMBER	SUBJECT		AUTHOR	ACCESSION NUMBER	SUBJECT CATEGOR	Υ	AUTHOR	ACCESSION NUMBER	SUDJECT	
HICHELSON C HICHELSON C HICHELSON C HICHELSON C	8109250504* 8109280036* 8110190928* 8110190933* 8111060130*	FOIA	5	MIDURA: H J MIDURA: H J MIDURA: H J MIELE: M L MILES: E B	8210270216 8210270310 8210270353 8210150178* 8210070017	50-272 50-272 50-272 50-322 CONTRACT	5 8 5 T	AILLS, L M MILLS, L M MILLS, L M MILLS, L M	8210070255 8210070348 8210080160 8210080168 8210080218	50-259 50-438 50-390 50-390 50-259	P & 8 8 8 P
HICHELSON C HICHELSON C HICHELSON C	8111191042* 8112020725* 8112210193* 8201190040* 8201190296*	FOIA FOIA FOIA	a	MILES.E B MILETI.D S MILETI.D S MILINAZZO.P L MILINAZZO.P L	8210070456 8210150223* 8210150223* 8210150517* 8210150526*	CONTRACT 50-322 50-322 0A999 0A999	Ť	MILLS.L N MILLS.L N MILLS.L N MILLS.L N MILLS.L N	82(0080219 82:0080222 82:0080247 82:0080255 82:0080278	50-257 50-438 50-390 50-390 50-438	ខ្លួន
Michereon c Michereon c Michereon c Michereon c	8201200653* 8202030072* 8202180457 8203100549* 8703300270*	FOIA HISC	s	MILLER. D S MILLER. D S MILLER. D S MILLER. D S	0210090112# 0210090236 0210090236 0210200065 0210200065	50-295 50-309 50-309 50-309 50-309	0 0 0 0	MILLS, L M MILLS, L M MILLS, L M MILLS, L M MILLS, L M	6210080280 8210080291 8210080292 8210080307 8210080310	50-390 50-390 50-438 50-438 50-390	ស ល ល ល ល
HICHEFEON C HICHEFEON C HICHEFEON C HICHEFEON C	8203310089# 8205130114# 8206040401# 8206110186# 8210010068#	50-293 FOIA	P P S	MILLER, D S MILLER, D S MILLER, J R MILLER, J R MILLER, J R	8210270303 8210270303 8101200322# 8210050052 8210050102	50-309 50-309 50-142 50-373 50-305	G G	MILLS.L M MILLS.L M MILLS.L M MILLS.L M	8210120284 8210130142 8210130150 8210130247 8210130379	50~327 50~259 50~327 50~390 50~390	P P 8 8
HICHEFEON: C HICHEFEON: C HICHEFEON: C HICHEFEON: C	47.00100130 47.00505031 47.10050118 47.0050503 46.0050503	FOIA FOIA FOIA FOIA		MILLER, J R MILLER, J R MILLER, J R MILLER, J R MILLER, J R	8210050308 8210050359 8210050365* 8210260471 8210290032*	50-371 50-186 50-186 14E FOIA	Q Q Q	MILLS, L M MILLS, L M MILLS, L M MILLS, L M MILLS, L M	8210139384 8210130407 8210130521 8210130560 8210150181*	50-390 50-438 PR 50-390 50-438	8 6
NICHELSON C MICHELSON C MICHELSON C MICHELSON C MICHELSON C	0210040432 0210070412 0210070415 0210070401 02100600054	50 -312 50 -255 MISC	6 6 6 5	HILLER, J. R. HILLER, J. R. HILLER, L. HILLER, L. K. HILLER, L. K.	8210290065* 8210290129 8210060269* 8210200014* 8210200090*	FOIA 50-409 50-206 50-311 50-272	Q Q R R	MILLS, L M MILLS, L M MILLS, L M MILLS, L M	8210150218 8210150230* 8210150231* 6210150241* 6210150231*	50-257 50-390 50-327 50-390 50-390	0 0
MECHELSON C MECHELSON C MECHELSON C MECHELSON C MECHELSON C	8210080104 8210080106* 8210080269 8210120114 8210120129	FOTA	ន ទ ៩	MILLER, M E MILLER, M E MILLER, M I MILLER, M I	9210940089 9210950259 8210270178 8210050229* 9210090229*	50-445 50-456 50-537 50-329 50-329	G G G	MILLS.L M MILLS.L M MILLS.L M	8210180117 8210170307 8210170357 8210170467 8210170528	50-327 50-370 50-370 50-438 50-438	8 6 8
MICHELEON C MICHELEON C MICHELEON C MICHITCHER M MIDURA H J	8210120370 8210130077 8210210009 8210220321 8210010045	M190 50 334 50-266 PR 50-311	9 P 5	MILLER, M I MILLER, M I MILLER, M J MILLER, M J MILLER, N E	8210130373 8210130373 8210250211 8210250211 8210120092	50-454 50-454 50-456 50-456 NUREO	0 0 0	WILLS.L H MILLS.L H MILLS.L H MILLS.L H	8210170755 8210220071 8210220078 8210220191 8210220123	TOPREP 50-438 50-390 50-257 50-390	9 6 0
MIGURA, H. J. MIEURA, H. J. MIEURA, H. J. MIEURA, H. J. MIEURA, H. J.	8210010123 8210010144 8210010191 8210010237 8210010344	50+311 50-311 50-272 50-311 50-311	ត ទ ទ ទ	MILLER, N E MILLER, V L MILLER, W O MILLER, W O	8210120102 8210250037 8210120055* 8210040429 8210040430	NUREO 71 9094 FOIA 50-275 50-518	b b	MILLS.L M MILLS.L M MILLS.L M MILLS.L M	8210220225 821022027(* 8210220350 8210220422* 8210220466*	50-390 50-438 50-438 50-438 50-370	F 0 8 0
MIDUAN, H J MICUAN, H J MIDUAN H J MIDUAN H J MICUAN H J	821081049 7 821081040 7 821081041 9 821081045 5 8210870 82 1	50 -272 50 -3(1 50 -3(1 50 -3(1 50 -3(1	6 8 8 8 8 8 8	MILLER.W O MILLER.W O MILLER.W O MILLER.W O MILLER.W O	8210040003 8210120033 8210130428 8210130432 8210130433	50-204 50-255 71-9010 40-8102 70-1143	P	MILLS, L M MILLS, L M MILLS, L M MILLS, L M	E210220474* E210250067 E210250096 E210260100 E210260105	50-327 50-260 50-257 50-390 50-438	0 6 8
H. ARCOLM U. H. ARCOLM U. H. ARCOLM U. H. ARCOLM U. H. ARCOLM	0210070243 0210070246 0210070249 0210070254 0210070305	50-311 50-311 50-311 50-311 50-372	ភព ភព ភព ភព	MILLER, W O MILLER, W O MILLER, W O MILLER, W O MILLIONUM H	8210180316 8210180340* 8210180341* 8210180389 8210070384	70-36 FOIA FOIA 50-349 50-322	ខ	HIFTER F H WIFTER F H WIFTER F H WIFTER F H	0210260107 8210260174 8210260186 8210260189 8210260251	50-438 50-390 50-390 50-390 50-	8 8 F

	NUMBER	CATEGORY		ACCESS I D NUMBER	N SUBJ. CATE		AUTHOR	ACCESSIO NUMBER	
HIMER.G C MIRAGLIA.F MIRAGLIA.F J MIRAGLIA.F J MIRAGLIA.F J MISBRENER,J M	821024024; 821008000) 821004042; 8210180308	1 50-237 2 50-498 9 50-443 8 50-528	T MOVER. D J P HROCZKA, E J A MROCZKA, E J D MROCZKA, E J A MROCZKA, E J	821004015 821001037 821001037 821007025 821007025	6 50-336 6 50-336 0 50-249	5 S	MUSOLF, D MUSOLF, D MUSOLF, D MUSOLF, D MUSOLF, D		7 50-293 7 50-763 6 50-764
MITCHELL, A D MITCHELL, D G MITCHELL, D G MITCHELL, D O MITCHELL, D O	8210210034 8210010180 8210130361 8210130371	50-259 0# 50-387 1* 50-387 1* 50-387	MRGCZKA, E J F MRGCZKA, E J S MRGCZKA, E J S MRGCZKA, E J S MRGCZKA, E J	821007030 821007036 821007036 821007036 8210130228	4 50-245 50-245 50-245	5 5 5	MUSOLF, D MUSOLF, D MUSOLF, D MUSOLF, D MUSOLF, D	821025035 821026035 821026020 821027026 821027026	50 .82 50 .62 50 263
MITCHELL, D G MITCHELL, D G MITCHELL, D G MITCHELL, D G	8210130389 8210210293 8210210436 8210210446 8210250377	50-387 50-387 50-387 50-387 50-387	S MRDCZKA.E J S MRDCZKA.E J S MRDCZKA.E J 5 MRDCZKA.E J MRDCZKA.E J	8210130226 8210190472 8210210155 8210210155 8210210425	9 50-336 50-336 50-336	0 5 5	MUSOLF, D MYERS, D CI MYERS, D CI MYERS, D CI MYERS, D CI	8210290249 8210010409 8210010417 821072017 821072050	F P4 ■ 50 724 ■ 50 724 ■ 50 724
MITCHELL, D G MITTL, R L MITTL, R L MITTL, R C MIZUNO, G S MIZUNO, G S	8210250385: 8210260219; 8210130554 8210220326 8210040183	* 50-387 s PR PR 50-537 G	HROCZKA, E J HROCZKA, E J HROCZKA, E J HROCZKA, E J	8210210425 8210220060 8210220060 8210220103 8210220103	50-336 50-336	8 9 8 8	MYERB, R V MYERB, R V NACAR, A NADIPURAM, P NAIDU, K R	8210070189 8210210317 8210180717 6210130117 8210130174	50 572 50 572 NUNIO 50 247
MODES.M C MOELLER,D W MOELLER,D W MOELLER,D W MOELLER,D W	6210130292 8210220314 8210010119> 8210040367* 8210050436*	50-366 S	MROCZKA, E J MROCZKA, E J	8210220112 8210220195 8210220195 8210260432 8210260432	50-245 50-245 50-245 50-336 50-336	55555	NAIDU, K R NAIDU, K R NANCE, G R NAPIER, B A NAPUDA, O	0210130957 021019070358 0210270358	90 481 90 483 90 433
MOELLER, D W MOELLER, D W MOK. G MONDEN, T MONTGONERY, D H	6210050496* 6210050542* 8210060079* 8210260198* 8210270452*	FOIA FOIA 50-277 P XPORTLIC	MUCHA, E MUELLER, C J MUELLER, C J MUELLER, J J MULHOLLANO, J D	82020101674 8208270017 8208270017 82102001064 82101300144	ACRS ACRS 70-820	P	NARAYANI, I V NARDI, A J NARDOCI, P B NARDOCI, P B	82102900724 02101907204 0210130420 02101301804 82102203274	50 /61 ; 50 /2 ; 50 /2 ;
MONTGOMERY, D H HONTGOMERY, D H MONTGOMERY, D H MOON, C W HOORE, D E	8210010118* 8210150219* 8210150239* 8210150263* 8210270158	70-1201 70-27 50-269 Q 50-522 A	MULLING, C D MUNTZING, L M MURDOCK, E S MURDOCK, E S MURLEY, T E	8210150567 8210220379 8210180415 8210180420* 8103090389*	NUREQ PR 40-6622 40-6622 50-247		NATHAN, B. J. NATHAN, G. J. NAVE, C. NE ILD, J. NEILL, J. M.	8210060.194* 8210110169* 8210110169* 8210190142* 8710180226*	50 4A1 f 50 42 f 50 259 g 50 240 g 50 251 f
MODRE, D E MODRE, J E MODRE, R D MODRE, R E	8210260226* 8210260265* 821020059 8210280230 821029060*	50-321 Q 50-327 Q 50-247 Q 50-247 G 50-10 F	MURLEY, T E MURLEY, T E MURLEY, T E MURPHY, A J MURPHY, G E	8104240059* 8109220915* 8111240912* 8210190002* 8210190342*	FOIA FOIA FOIA CONTRAC 50-315	T B	NEILL, J K NEISLER, J II NELSON, O II NELSON, O II	8210100224 8210109994 8210060341 8210060391 821006039	50 M2 (50 463 s 50 369 f 70 25 70 25
MOGRE, R H MOGRE, R N MOGRE, R N MOGRE, R N MOGRE, R N	8210270035 > 8005270822 + 8210270103 8210270114 8210270243	50-537 Q FOIA XPORTLIC XPORTLIC XPORTLIC	MURPHY, D D MURPHY, D E MURPHY, D E MURPHY, D E MURPHY, D W	8210220406* 8210060412* 8210260222* 8210290371* 8209140027*	50-438 50-259 50-259 50-259 50-244	0 8 5 8	NELSON, I NELSON, I NELSON, I NELSON, I C NELSON, I C	8/100/0315+ 82100/01/24- 82100/04/5+ 82100/0310+ 82100/0323+	50 517 t 50 517 t 50 517 t 50 517 t
MOORE, S N MOORE, V A MORGAN, C MORGAN, C MORGAN, C	9210280431 8210130117 8010240329 8210040235 8210060235	MISC 50-413 D 50-247 P 50-247 G 50-247 G	MURPHY, D W MURPHY, M E MURPHY, W P MURPHY, W P MURPHY, W P	8209210523* 8210170347* 8210040113 8210130189 8210130447	50~309 50~285 50~271 50~271 50~271	P Q Q R P	NELSON, I C NELSON, I C NELSON, I C NELSON, R H NELSON, R H	0210070342* 0210070347* 0210070347* 0210210010#	20 494 2 20 214 2 20 214 3 20 214 1
MORGAN, C MORGAN, C MORGAN, C MORGAN, C MORGAN, C	8210250081 8210250081 8210250216 8210250216 8210270271	50-247 0 50-247 G 50-247 G 50-247 0 50-247 G	MURPHY, W P MURPHY, W P MURRAY, B MURRAY, B MURRAY, B	8210220418* 8210270432* 8210070394* 8210120073* 821022028[*	50-271 50-271 40-6622 50-382 50-313	0 F	NELSON, R H NELBON, R L NELBON, W R NELBON, W R NERSES, V	02107802084 02107802022 02107802022 02107802004	50 NJ 5 50 NJ 5 50 NJ 6 NIMIO RES
MORGAN, W MORGAN, W MORIARTY, J M MORISI, A V MORISI, A V	8210290271 8210190412* 8210250348* 8210220417* 8210050166	50-247 G 50-247 B 50-249 S QA999 50-293 Q	MURRAY, P L MURRAY, P L MURRAY, P L MURRAY, P L MURRAY, T D	8210260457 8210260457 8210260465* 8210260465* 8210050323	50-309 50-309 50-309 50-309	0 0 0	Nerses. V Nerses. V Nerses. V Nerses, V	0210140014 0510160598 0510160593 0510160593 0510160693	50 161 4 50 761 P 50 464 E 50 464 A 50-161 A
MORISI.A V MORISI.A V MORKEN.D J MORRILL,P J	8210280330*	50-293 P 50-293 Q 50-293 P 50-213 P 50-275 Q	MURRAY, T D MURRAY, T D MURRAY, T D MURRAY, T D MURRAY, T D	8210050355 8210070006# 8210130124 8210130356 8210130404	50-346 50-346 50-346 50-346	6 F 6	NERBES.V NERSES.V NETI.B NEUMANN,M R NEUMANN,M R	6210210251 6210210591 6210030360 6210160396 621023004;	90 %7 A 90 703 3 NUMEO 40 0493
MORRIS, D G MORTON, D K MORTON, K V MORTON, K V MORTON, K V	8210120300* 8210040424* 8210120432* 8210120440*	NUREO 50-213 P CONTRACT CONTRACT CONTRACT	MURRAY, T D MURRAY, T D MURRAY, T D MURRAY, T D MURRAY, T D	8210180131 8210190254 8210190358 8210250226 8210250270	50-346 50-346 50-346 50-346	5 5 5 6	NEWMAN, J R NEWMAN, J R NEWMAN, J R NEWMAN, J R	8210070120 8210070120 8210070147 8210070147 8210210363	50 466 0 50 466 0 50 466 6 50-466 6
MORTON, K V MORTON, K V MORTON, K V MORTON, K V MORTON, K V	8210130014* 8210170063* 8210170177*	CONTRACT CONTRACT CONTRACT CONTRACT CONTRACT	MURRAY, T D MURRAY, T D MUSOLF, D MUSOLF, D MUSOLF, D	8210260283 8210280075 8210010036 8210010041*	50~346 50~346 50~263	8 9 9	NEWMAN, J R NICHOLAB, H H NICHOLAB, J B NICHOLAB, J B, NICHOLSON, N A	8210210363 8210290356# 8210120073# 8210220281#	50 499 6 50-322 0 50-382 0 50 313 4
MORTON, K. V. MORTON, K. V. MORTON, K. V. MORTON, K. V. MORTON, K. V.	8210210570# C	CONTRACT CONTRACT CONTRACT CONTRACT CONTRACT	MUSOLF, D MUSOLF, D MUSOLF, D MUSOLF, D	8210010060 8210040123 8210050319 8210040258 8210060377	50-263 50-282 50-282 50-263	• • •	NIMITZ, R L NIV, H C NIV, H C NIX, H C	6210150543# 6210070306# 6210050060 6210050060	50-10 8 50-278 0 3 50-366 5 50-366 5 50-366 5
MORTON, K V MORTON, K V MORTON, K V MOSELEY, N C MOWRY, W R	8210260240* C 8210260561* C 8210280374* C 8203040536* 5	CONTRACT CONTRACT CONTRACT CO-329 Q CPORTLIC	MUSOLF, D MUSOLF, D MUSOLF, D MUSOLF, D MUSOLF, D	8210130260 8210130261 8210130510 8210130563	50-263 F 50-263 F 50-263 F 50-263 F 50-263 F 50-304 G 50-263 F		NIX, H C NIX, H C NIX, H C NIX, H C, NIX, H C, NIX, H C NIX, H, C	8210060287 8210060317 8210080234 8210130183 8210130183 8210130220 8210130226	50-366 \$ 50-366 \$ 50-366 \$ 50-321 R 50-366 \$ 50-366 \$ 50-366 \$ 50-366 \$

AUTINOR	NUMBER C	SUBJECT ATEGORY		AUTHOR	ACCESSION NUMBER	SUBJECT	· 	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	
14 H C 14 H C 14 H C 14 H C 14 H C	8210130541 50 8210193504 50 8210190595 50 8210220219 50	0-366 S 0-366 S 0-366 S 0-321 S 0-321 S		O'REILLY, J P O'REILLY, J P O'REILLY, J P O'REILLY, J P	8210010016 8210010019 8210010025* 8210010035 8210010091	State Pro 50-321 50-321 50-257 50-261	9 0 0 P	GTT.L J OVERBECK.G J OWCZARSKI.P C GHSLEY.G F GWSLEY.G F	8210210039 8210050068* 8210270421 8210040229 8210130123	RES TOPREP	P P
14 H C 14 H C 14 H C 16 H C	8210290096 50 8210290206 90 8210290262 5	0-366 S 0-321 S 0-366 S 0-321 S 0-321 S		O REITTA' O B OLEITTA' O B OLEITTA' O B OLEITTA' O B	9210010052 8210010102 8210010112 8210010227 8210010238*	70-143 50-400 50-324 50-348 50-280	ር ው የ በ	ONSLEY, O F OWSLEY, O F OWSLEY, O F OWSLEY, O F	8210150033 8210150173 8210190502 8210270092 8210270214	TOPREP	P P
Is H G te H G te H G Is H C Is H C	8210290349 5 8210290357 5 8210290373 5	0-321 S 0-321 S 0-321 S 0-321 S 0-326 S		0.1007E'7 0.4611TA'7 0.4611TA'7 0.4611TA'7 0.4611TA'7 0.4611TA'7	8210010326 8210190020* 8210220387 8210130559* 8210010401	50-259 50-369 50-439 50-247 50-3	0 0 0 0 P	PACE, D L PACE, P PACE, P L PACE, P L PACE, P L	8210220242* 8210130542* 8210010174* 8210040212* 8210080257*	50-335 50-335 50-251	5 5 5 5 5 5
CH H A CAU V S CHAU V S CHAU V S CHAU V S	7812200285* 5 7907280105* 5 8001300616* 5	0-8355 0-266 P 0-266 P 0-266 P 0-327 P		0 100FY D 0 100FY D 0 100FY D 0 100FY D 0 100FY D	8210010409* 8210010425* 8210010443* 8210040141 8210040232	50-3 50-3 50-3 50-247 50-247	р Р 8 Т	PACE, P L PACE, P L PACE, P L PACE, P L PADMANABHAN-M	0210130462* 0210150039* 0210260117* 0210260369* 021005038	50-335 50-250	8 8 8
CHARLY S PRETITANGLE R PRETITANGLE R PRETITS & E PRETITS & E	82102603D9 7 8210260402 7 8210040230 5	0-266 0 70-1257 70-1257 50-456 0 50-461 0		0.100FY D 0.100FY D 0.100F	8210060394 8210070361 8210120253 8210130277 8210130411	50-247 50-247 50-247 PR 50-247	8 6 8	PAGE.R G PAGE.R G PAGE.R G PAGE.R G PAGE.R G	8205240010* 8210040392 8210120446 8210220025 8210270434	40-8355 70-371 70-25 70-1257 70-1151	
PELIVS. C E *ELIVS. C E *ELIVS. C E *ELIVS. C E *ELIVS. C E	8210080284 8210190360 8210190361*	50-315 0 50-346 (50-331 (50-331 (0.100TE' A D 0.100TE' A D 0.100TE' A D 0.100TE' A D	8210130455 8210190693 8210200078 8210250145 8210260332	50-247 50-247 50-247 50-247 50-247	P G S P	PAGE.R O PAGE.R G PAGE.R G PAGLIARD.J PAGLIARD.J A	8210280415 8210280417* 8210290383 8210080251 8210040185*	70-2957 70-2957 70-2944 50-155 50-409	s o
PEL 105. C E -EL 105 C F -EL 105 C E -EL 105 C F	8210240174 8210240307 8210260315	50-454 (50-155 ()))	O'TOOLE, J D DAWLEY, C B DAWLE, K E OBERO, C T OBERO, C T	8210280154* 8210070363* 8210270373 8210150507 8210190673	50-3 50-439 40-8824 12E 14E	F A	PAGL(ARO, J A PAJOWSKI, J E PAJOWSKI, J E PALLADINO, N PALLADINO, N J	8210080204* 8209290187* 8209290225* 8210290373 8201150004*	50-305 50-10 50-10 100FR FOIA	a F F
ELIUS.C F ELIUS.C F ANDEN I RHUEMI J RIS.H R	8210270276 8210220447 8210210477*	50-358 50-334 50-272) 3 9 9	DESTMANNIM J OHLDACHIR OLSENIA F OLSENIA F OLSENIR N	821008017(* 8210250192 8210040214 8210220231 8210270152*	50-358 50-133 50-13 70-824 XPORTLEO	Q R P	PALLADINO, N J PALLADINO, N J PALLADINO, N J PALLADINO, N J PALLADINO, N J	8206200086 8206200091 8206200097 8206270053 8206270059	COMMISSIO COMMISSIO COMMISSIO COMMISSIO COMMISSIO	0N 0N 0N
A1.P 0 A7.P 0 A7.P 6 B1.P 0 A7.P 0	8210120388 8210260531 8210260544	080 080 080 080 080		H J.MAHEJO A L.1XENTHEJO A L.1XENTHEJO A L.1XENTHEJO A L.1XENTHEJO	8011070227 8010240644 8010270312 8208250417* 8210150376*	50-247 50-247 50-247 50-269 70-143	ያ ያ የ	PALLADINO, N J	8207050040* 8210070441* 8210120151* 8210270003* 8210040207*	50-289 FOIA 50-244 COMMISSI 50-316	S ON E E
TH:14 9 1011, J F ARD, J A LET:4 D P LET: D P	G2 (0140612 * B2 (0140608 * G2 (0140281 * G2 (0240030 G2 (0260554	50-482	Q Q T	OLSHINSKI.JA OLSHINSKI.JA OMATE.Y OMATE.Y OMATE.Y	8210220420 8210220430* 8107270188* 8107270191* 8107270194*	70-1113 70-1113 50-266 50-266 50-266	a a a	PALMER.R A PALMER.R A PALMER.R A PALMER.R A PALMER.R A	8210040327* 8210040330* 8210040307* 8210160129* 8210170389*	50-314 50-314 50-315 50-316 50-315	8888
Ak. T Ak. T 11 Ak. T 11 Ak. T 17 Ak. E 15	8001030220 8004230784 8201210107* 8204790237* 8205130256	50-247 50-247 FOIA 50-289 50-269	P Q P P	OPEVA. J F OPEKA. J F OPEKA. J F OPEKA. J F	8210250290 8210250290 8210250329 8210250329 8210260414	50-423 50-423 50-423 50-423 50-245	ច្ច	Palmer, R A Palmer, R A Pang. J F Pangburn, G C Pangburn, G C	8210190404* 8210190978* 8210080311* 8210120144 8210120445	50-315 50-315 70-754 27-47 27-47	8 6
120. T 21 614. T 21 64. T 29 64. T 29 84. T 25	820&140329* 8210010015 8210040424 8210040426 8210050492	50-289 50-373 50-369 50-327 50-362	P P P A	OPEKA, J F OPEKA, J F OPEKA, J F OPEKA, J F OPEKA, J F	8210260414 8210260519 8210260519 8210270200 8210270200	50-245 50-245 50-245 50-213	ይ ሴ ሴ ሴ	PAPAY, L T PAPAY, L T PAPAY, L T. PAPERIELLO, C PAPERIELLO, C J	821 008021 4* 821 0190455* 821 0250227* 821 0080251 821 0040202	50-206 50-361 50-361 50-155 50-331	0 0 0 8 0
W. T FI W. T FI W. T FI W. T FI	8210070042 8210070045* 8210070051* 8210070055* 8210070061*	50-373 50-373 50-373 50-373 50-373	н н н	OPREA.Q W OPREA.Q W OPREA.Q W OPREA.G W OPREA.G W	8210050329 8216220125* 8210250112 8210250249 8210250259	50-498 50-498 50-498 50-498 50-498	S S A	PAPERIELLO, C J PAPERIELLO, C J PAPERIELLO, C J PAPERIELLO, C J PAPERIELLO, C J	8210040204* 8210040345 8210050142 8210080146 8210080174	50-331 50-262 50-254 50-358 50-305	0 P Q Q
K. T P1 K. T 91 K. T P1 K. T P1 R. T P1	8210070066* 8210070107 8210080340 8210130595 8210180331	50-373 50-329 50-389 50-556 50-390	H B A A	Orders, W Orders, O Orders, O Orders, W	8210250263 8210290358 8210260452 8210010166* 8210010474*	50-498 50-498 50-498 50-269 50-269	A S G	Paperiello, C J Paperiello, C J Paperiello, C J Paris, O H Paris, O H	8210150539 8210250297* 8210260220 8210050254 8210150092	50-10 50-346 50-155 50-247 50-247	9 9 9
8. T 11 8, T P5 6. T 15 9. A 16 117. E L	8210210212 8210210244 8210210498 8210210448* 8210150607	50-400 50-387 50-361 70-2116 40-2259	D P P	ORNSTEIN. H ORNSTEIN. H ORNSTEIN. H L ORNSTEIN. H L ORNSTEIN. H L	8107180478* 8210080026 8004020420 8010230435 8107070220*	50-289 50-289 50-302 30-302 FOIA	P P 8 8	Paris, o H Paris, o H Paris, o H Paris, o H Parker, l B	8210210349 8210220338 8210250223 8210270176 8210120319*	50-155 50-155 50-142 50-320 QA999	0000
BAUMER. D A BAUMER. D A BAUMER. D A LEN. J LEN. J LEN. J LEN. J	B210120027* B210120057* B2101200754 B210060336* B210220135	FOIA FOIA FOIA 50-312 NUREO	Q	CANSTEIN H L CANSTEIN H L CANSTEIN H L CANSTEIN H L	8108130268* 8205070377* 8210050161* 8210060460* 8210080024	50~206 FDIA 50~320 50~320 50~320	8 8 6	PARKER: W O PARKER: W O PARKINSON, T W PARKYN: J D PARKYN: J D	8210150012* 8210180079 8209150056 8210010374 8210130270	50-369 50-269 FOIA PR PR	B
0009.P ILL. J H ILL. J H ILL. J H	8210250304 8210200021* 8210200021* 8106220168*	50-237 50-346 50-400 50-400 FOIA	6 6	ORNSTEIN.H L ORNSTEIN.H L ORNSTEIN.H L ORNSTEIN.H L OSTER.J	8210080061 8210080124 8210120079 8210120406 8210060283	50-320 50-204 50-321 50-320 50-295	9 9 9 5	D LANARAS PARSONAR M PARSONAR M PARSONAR M PARSONAR M PARSONAR M	8210220333 8210130567 8210010360* 8210080160 8210080283	PR 50-400 50-400 50-400 50-400	8 9 8

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AU THÛR	ACCEP210M	SIGNELL CATE, FI
PARSONS, R M PARSONS, R M PARSONS, R M PARSONS, R M PARSONS, R M	8210220075 6210220132* 8210220412 8210220484 6210240398	50-400 S 50-400 0 50-400 S 50-400 S 50-400 S	PETTENGILL, H J PETTENGILL, H J PETTIJOHN, S L PETTIJOHN, S L PETTIJOHN, S L	8210210527 8210210530 8006050154* 8006050188* 8008070143*	40-4659 40-299 FOIA FOIA	POTAPOVS, U POTAPOVS, U POTAPOVS, U POTAPOVS, U POTAPOVS, U	8210150540# 8210170365 8210170725 8210170756 8210170756	04777 04777 04777 04777
PARSONS,R M PARSONS,R M PASTVA,M J PASTVA,M J PASTVA,M J	8210270258 8210270260 8210010303* 8210010475* 8210060327*	50-400 S 50-400 S 50-324 S 50-324 S 50-324 S	PETTY, J C PETTY, J C PETTY, J C PETTY, J C	8101270870* 8210270087* 8210270179* 8210270313* 8210270365*	F01A 50-270 S 50-267 S 50-287 S 50-269 S	POTAPOVS, U POTAPOVS, U POTAPOVS, U POTAPOVS, U POTTER, J	8210,750121 8210250135 8210260126 8210260494 8210750224	Jaka Guara Guara Guara Guara
PASTVA.M J PASTVA.M J PASTVA.M J PASTVA.M J PASTVA.J	8210080183* 8210080230* 8210130483* 8210130497* 8210150046*	50-325 S 50-324 S 50-325 S 50-325 S 50-324 S	PEVEY, L E PFAFF, S J PFEFFERLEN, H C PHILLIP, G A PHILLIP, G A	82100401474 8210220910 8210180050 8210040165* 82101305574	70-398 40-6659 TOPREP 50-409 Q 50-461 O	POITER, J P POULK, R M POULK, R M POWERS, T B POWERS, T B	8210010072 82091603114 8210190674 8210120092 8210120102	MIUT 50 725 5 NUMES NUMES
PASTVA.M J PASTVA.M J PASTVA.M J PASTVA.M J PASTVA.M J	8210150308* 8210170759* 8210170762* 8210240246* 8210240318*	50-324 S 50-324 S 50-324 S 50-325 S 50-324 S	PHILLIPS A PHILLIPS H S PHILLIPS L E PHILLIPS M P	8210190209# 8210190761* 8210190766* 8109110478* 8210150495*	50~440 F GA979 GA999 FOIA 50~254 G	PRATT.C M PREUSS.M PREVATTE,R PRICHARD.R P PROFFITT.W L	8210220324 8210190700* 8210270074 821027007*	FH 50-054 b 50-074 F 21-4637 50-3-3 F
PASTVA, M J PASTVA, M J PASTVA, M J PASTVA, M J PASTVA, W J	8210240368* 8210270079* 8210270246* 8210270331* 8210270342*	50-325 S 50-324 S 50-324 S 50-325 S 50-324 S	PHUNG, D L PIANKI, F J PIEHL, R H PIEHL, R H PIERRET, J A	8210280110* 8210130504* 8210180123* 8210190588* 8210280184*	FOIA 70-1100 50-316 S 50-315 S 40-7580	PROFFITT.W L PROFFIFT,W L PULLANI.S V PUZEY,A M PYLE.R D	82109402474 82109403154 82103703304 82101909234 8210250063	50 443 5 50 344 2 50 27 1 50 184 6 50 344 6
PASTVA,M J PATON,W D PATROU,N PATTERSON,J P PAUL,R A	8210270352* 82100800&6 8210080271* 8210040354* 8210130408*	50~325 & 50-327 & 50-220 & 50-282 & 6 50-407 & 0	PIETRIAMA F PIGOTI, D R PIGOTI, D R PIGOTI, D R PIGOTI, D R	8210120367 8210130309 8210130309 8210150454 8210150454	RES 50-361 G 50-361 G 50-361 G 50-361 G	PYLE.R B OUICK.D R OUICK.D R OUIGG.C OUIHN.M D	8210260429 821019030 1* 8210190331* 8210210235 8210150178*	50 .50 . 50 log 4 50 log 8 50 .35 - 50 .11 1
PAULICK, L R PAULSON, W PAULSON, W PAULSON, W PAULSON, W A	821020342 8210040153 8210050300 8210200023 8210150298	PR 50-206 P 50-206 P 50-206 P 50-206 P	PIGOTT, D R PIGOTT, D R PILANT, J M PILANT, J M PILANT, J M	8210150482 8210150482 8210010058 8210130318 8210320136*	50-361 G 50-361 G 50-298 F 50-298 F 50-298 G	GUINN.M D OUIRK.J F GUIRK.J F GUIRK.J F GUITTSCHREIBER	8210289074* 8210190416 8210150445 8210150461 8210050424*	50 ,13
PAULSON, H A PAVIS. G S PAVIS. G S PAHLICKI, S S PA(SON, E	0210190671 8210250095* 8210250160* 8009040493* 8210270208*	50-204 P 50-318 8 50-317 8 50-266 P 50-338 P	PILANT, J H PILANT, J M PILANT, J M PIRTLE, G L PITCHER, D M	8210220254 8210240328 8210290323 8210290137# 8210190457#	50-298 P 50-298 Q 50-298 P 50-409 Q 50-395 P	QUITTSCHREIDER RAGONE, S RAHE, E P RAHE, E P RAHE, E P	6210050426 » 6210040375 » 6210080239 6210130447 6210130535 »	FUIA 50 1/3 F 10/F37 P124 50 J14 F
PAYTON, H C PAYNE, M T PAYNE, M T PEABODY, C A PECK, L S	8210050251 8210210419 8210210419 8210210419 8209280307 8210190457*	50-266 G 50-400 G 50-400 G NUREO 50-375 P	PLIME, Q PLIME, Q PLIME, Q PLIME, Q PLISCOLL R	8210080030# 8210280120# 8210280424# 8210280445# 8210270132#	50-295 F 50-295 F 50-295 F 50-295 F 50-322 Q	RAHE, E P RAHE, E P RAHE, E P RAHE, E P RAMBLE, E	8210190507 821022015,1 8210260305 8210260340 8210260340	tursie Tursee Turset Turset Turset Turset
PEERY, W W PEERY, W W PEERY, W W PELIZZA, M B R	8210010122* 8210050084* 8210220341* 8210180356 8210130222*	50-83 0 50-348 0 50-160 0 40-8786 50-546 0	PLOSXI, T J PLUMLEE, O L PLUMLEE, K E POCALUJKA, L P POCALUJKA, L P	8210250297# 8210050239# 8210060127# 8210150290# 8210150290#	50-346 0 50-267 0 50-317 0 50-322 T 50-322 T	RAMPY, L W RANDAZZA, J B RANDAZZA, J B RANDAZZA, J B RANDAZZA, J B	9210290202 921040171 921010252 F82010128 8210130460	50 7/4 5 50 7/3 6 50 N/1 8 50 N/1 8
	9109090011* 9201300308* 210190029*	50-289 P 50-312 S 50-271 B 50-271 S	POCHAL, N F POCHAL, N F POHLE, J A POLLARD, R D POLLOCK, M S	8210270014 8210270017 8210220515 8210120274 8210040274#	XPORTLIC XPORTLIC 40-8714 50-289 Q 50-322 Q	RANKIN,W B RANY,J RATTA,A D RATZEL,A C RAUSCH,T J	82102900414 82102800474 8210202444 8210150571 8210010007	50 265 F 50 255 F 70 707 NUREG 50 277 F
			3 L	8210040361# 8210260141# 8210150281# 8210150281# 8207180077	50-322 0 50-322 0 50-322 T 50-322 T 50-3 0	RAUSCH, T J RAUSCH, T J RAUSCH, T J RAUSCH, T J RAUSCH, T J	8310080178 8210180174 8210190464 8210190565 8210190780	50 k37 5 50-10 7 50 247 6 50 247 7 50 254 3
PERLIS,R Q PERNY,C	8210270159 8210270239#	50-387 P 50-483 Q 50-302 Q	POPEC.D J POPPE.L K PORTER.F W	8207180077 8210010322 8210130277 8210280388 8210120419#	50-3 0 PR PR 71-6601 27-39	RAUSCH, T J RAUSCH, T J RAUSCH, T J RAUSCH, T J RAUSCH, T J	8210250069 8210250114 8210250155 8210250309 8210260485	50 x37 P 50 054 P 50 054 F 50 054 F 50 054 F
PERNY,C D PERSH.R L PESCHEL,J M PETERS,R F PETERSON,D A	9210150380* 8210180274 8210170675* 8210210556* 8210130145*	70-143 50-387 P 50-266 G 50-346 P 50-255 R	PORTER, M R PORTER, M R POSNER, P POTAPOVS, V POTAPOVS, V	8210040270* 8210220057* 8210200019 8210040148 8210040171	50-296 8 30-259 8 50-247 0 GA999 GA999	RAWSON, R J RAWSON, R J RAWSON, R J RAWSON, R J RAY, H B	8210060182 8210120291 8210150190 8210270090 8210050008	50-454 £ 50-257 £ 50-454 £ 50-287 ; 50-361 5
PETERSON,M R PETRICK,N A PETRICK,N A PETRICK,N A PETRONE,C D	8210040007 8210080240 8210220252 8210240274 8210070283*	XPORTLIC 50-482 K 50-482 A 50-482 A 50-293 G	POTAPOVS, V POTAPOVS, V POTAPOVS, V POTAPOVS, V POTAPOVS, V	8210040192 8210040333 8210050188 8210050195 6210050284	QA979 QA979 QA979 QA979 QA979	RAY, H B RAY, H B RAY, H B RAY, H B RAY, H B	8210050012+ 8210050016 8210050014+ 8210050024+ 8210050029+	50-341 \$ 90-341 \$ 50-341 \$ 50-341 \$
PETTENGILL, H J	8210120494 8210120514 8210120529 8210120619 8210120624*	40-8728 40-2259 40-8102 40-8781 40-8781	POTAPOVS, U POTAPOVS, U POTAPOVS, U POTAPOVS, U POTAPOVS, U	8210050287* 8210050292* 8210120222 8210120280 8210120301	QA799 QA799 QA799 QA799 QA799	RAY, H B RAY, H B RAY, H B RAY, H B RAY, H B	8210050032* 8210050037* 8210050041* 8210050044* 8210050048*	50-361 5 50-361 5 50-361 5 50-361 5
PETTENGILL, H J	8210120634 8210120644 8210210021 8210210515 8210210525#	40-8452 40-6622 40-3453 40-8084 40-3453	POTAPOVS, U POTAPOVS, U POTAPOVS, U POTAPOVS, U, POTAPOVS, U	8210120309* 8210120311 8210180513 8210180521* 8210180532	QA777 GA777 GA777 QA777 GA777	RAY, H B RAY, H B RAY, H B RAY, H B RAY, H B	8210050090* 8210050096 8210050098* 8210050101* 8210050151	50-361 S 50-361 S 50-361 S 50-361 S 50-361 S

AUIHOR	ACCESSIDN SUBJECT Number Category	AUTHOR .	ACCESSION SUBJECT Number Category	AUTHOR	ACCESSION NUMBER	TOBLEUB CATEGORY
FAT. H B FAT. H B FAT. H B FAT. H B FAT. H B	8210050234* 50-361 5 8210050261 50-361 9 8210050264 50-361 9 8210050381 50-361 9 8210050381 50-361 9	RIBEIRO, J RICCARDELLA, P RICE, D. A RICHARDS, B. L RICHARDS, S. A	8210040183* 50-220 P 6210050427* 50-155 P 6210130235* 50-29 S 8210010317* 70-143 6210290132* 50-322 0	ROOT, L D ROOT, L D ROOT, L E ROOT, R W ROOT, R W	8210240138 8210240441 8210190156* 8210070297 8210070311	50-331 P 50-331 F CONTRACT 50-440 S 50-440 S
FALH B FALH B FALH B FALH B FALH B	8210130267 50-361 5 8210130274 50-361 5 8210130278 50-361 5 8210130285 50-361 6 8210130469 50-361 5	RICHARDSON, J D RICHTER, L RICHARD, D C RIDGELY, J RIDGWAY, D A	82101801094 50-416 R 82101903554 50-346 6 8210260425 50-170 C 82101505354 50-287 P 8210010435 50-382 G	ROOT, R W ROOT, R W ROOT, R W ROOT, R W ROOT, R W	8210070338 8210070387* 8210130425* 8210130432* 8210280190*	50-460 8 50-460 0 50-460 0 50-460 0 50-460 0
FA, # B FA, # B FA, # B FA, # B	8210130478* 50-361 S 8210130485* 50-361 S 8210130493* 50-361 S 8210130497 50-361 S 8210130508* 50-361 S	PIDGWAY, D A RIDGWAY, D A RIDGWAY, D A RIDGWAY, D A RIDGWAY, D A	8210070197 50-382 0 8210070197 50-382 6 8210120267 50-266 0 8210120267 50-266 6 82102102666 50-320 0	RODT.R W ROSA.F ROSANO.R ROSASCO.P V ROSE.B	8210280297* 8206300370* 8210280221 8210120386* 8210070127	50-440 Q TOPREP 50-272 Q WASTE MGT 50-454 G
FATH B FATH B FATH B FATH B	8210170307 50-361 S 8210170317* 50-361 S 8210170323* 50-361 S 8210170328* 50-361 S 8210170328* 50-361 S	RIDGWAY, D A RIDGWAY, D A RIDGWAY, D A RIDGWAY, D A RIDGWAY, D A	8210210266 50-320 0 8210210372 50-382 0 8210210372 50-382 0 8210260423 50-382 0 8210260423 50-382 0	ROSE, B ROSE, B ROSE, B ROSE, B ROSE, B	8210070127 8210070129* 8210070129* 8210180151 8210210278	50-454 G 50-454 O 50-454 Q 50-454 G 50-454 O
621. H B 641 H D 641 H B 642 H B	8210290506* 50-206 S 8210290137 50-361 S 8210290140* 50-361 S 8210290207 50-361 S 8210290214 50-361 S	RICDLINGER.B A RIGAMONII.G RIGGLE.E I RILEY.J L RIVELLO.J	8210080311* 70-754 621005020& 50-443 A 6210070241* 50-219 S 6210260150 50-413 D 6210150206* 50-322 T	ROSE, D ROSE, B ROSE, B ROSE, B ROSE, B	8210210278 8210210384 8210210384 8210250071 8210260380	50-454 0 50-454 0 50-454 0 50-454 0 50-454 0
8A1.H B 8A1.H B 8A1.E B 8A1.H B 8A1.H B	8210250214* 50-361 5 8210250269 50-361 5 8210250273* 50-361 6 8210250280 50-206 5 8210780066 50-206 5	BISSOY Y BISSOY O BISSOY O BISSOY O	8210150223* 50-322 T 8210150250* 50-322 T 8210270269* 50-317 S 8210050500* FOIA 8210060369* FOIA	ROSE, D ROSE, D ROSE, D ROSE, D	8210290384* 8210290384* 8210260386*	50-454 G 50-454 G 50-454 G 50-454 G 50-454 G
PAL H B RALLH B RALLH B RALLH CALLAR B W ONCHIAR	8210280068* 90-206 8 6210280080 90-261 8 6210280086* 50-261 5 6210070393* 50-271 0 8210190274* 50-271 0	R1220, P G R1220, P G R1220, P G R1220, P G R0BERDS, J	8210280200+ 50-318	ROSE.B ROSS.U J ROTH.J ROTHSCHILD.M U ROTHSCHILD.M U	8210270305 8210270352 82100702404 8210130272 8210280257	50-454 Q 50-272 P 70-33 50-445 Q 50-445 Q
PAILOR J W READ O F READ O F READAL R	6210280141# 90~318 S 6210010328 90~400 6 6210010337 90~400 0 6210150340 50~400 6 6208010022 M18C	ROBERTS, D E ROBERTS, T K ROBERTS, T M ROBERTS, T M ROBERTS, T M	8210210505* CONTRACT 8205060558* FUIA 8210120112* FOIA 8210120123* 50-537 G 8210120140* 50-537 A	ROUSE, L C ROUSE, L C ROUSE, L C ROUSE, L C ROUSE, L C	8210070301* 8210070310* 8210120340 8210280452 8210280453*	50-537 A 50-537 A PRGJ 70-364 70-364
SEAVIS, JA REAVIS, JA REBELLO JE REBELLO, JE REBELLO JE	8210190952# 50-249 R 8210190791# 90-349 R 8210070154# CONTRACT 8210130054# CONTRACT 8210180371# CONTRACT	RODERTS. TH ROBERTS. TH ROBERTS. TH RODERTS. TH RODERTS. TH	8210120143# 50-537 A 8210120161# FOIA 8210120170# FOIA 8210120181# FOIA 8210120202# FOIA	roje. C a rowe. C a rozak, 8 rozak, 8 rubenstetn. L	8210070345* 8210210451* 8210040208* 8210080171* 8011240024*	50-219 Q 50-272 Q 50-331 Q 50-358 Q 50-247 S
AFBELLO, J E AEBELLO, J E AEBELLO, SKI, T AEBELLOWSKI, T AEBELLOWSKI, T	8210190215* CONTRACT 8210790131* CONTRACT 8210060046* 50-247 0 8210210307* 50-247 0 8210290194* 50-213 0	ROBERTS, T H ROBERTS, T H ROBERTSON, C Q ROBERTSON, C Q ROBINSON, D	8210150469 50-155 0 8210250332* 50-287 0 8210010381 PR 8210020334 PR 8210020334 PR	RUGENSTEIN-L S RUGENSTEIN-L S RUGENSTEIN-C S RUGIN-S RUGIN-S D	8008210627 8007030334 8108270547* 8204270464* 8111030201*	50-247 P 50-247 P FOIA FOIA
redand R T reed. C reed. J G reed. J G reed. R F	8210280149# 50-267 Q 8210060367# 50-237 Q 8210060197 50-483 Q 8210070152 50-483 F 8210250247 50-275 R	RODINSON D L. RODINSON S RODRIOUEZ, R J ROEDER, J R ROCERS, A E	8210190426* 50~275 0 820829090 50~148 H 8210190278 50~312 R 8210270077* 71~6657 8207120253* 50~447 A	RUFF, A B RUFF, A B RUFF, A B RUNKLE, J RUNKLE, J D	8210010187* 8210150194* 8210220323* 8210210419 8210210348	50-424 Q 50-338 Q 50-370 Q 50-400 Q 50-400 Q
FERDI.R F FERDY.R F RERYES.E A RERYES.E A FERVES.E A	0210200157 50-275 R 0210200272 50-275 P 001(060346* FOTA 0210040030 50-364 P 0210200410 50-348 Q	ROCERS, A E ROGERS, H R ROCERS, H R ROCERS, H R ROCERS, H R	8210010224* TOPREP 8210060221* 50-327 5 8210130452* 50-327 5 9210130579* 50-328 5 8210220062* 50-328 6	RUNKLE-J D RUPPEL H D RUSSELL-B RUSSELL-J E	8210210348 8210070459* 8210050198* 8210040064 8210220474*	50-400 Q CONTRACT 0A999 50-31B S 40-6622
regan, W H remm, T A reimann, P M revito U A	8202240446* 50-537 D 8210080032* FQIA 8210290423 COMMISSION 8210040035* 50-10 Q 8210210162* 50-272 Q	ROGERS.H R ROGERS.H R ROGERS.P ROGERS.P ROGERS.P	8210220085* 50-327 \$ 8210290279* 50-327 \$ 8210130214* 50-313 \$ 8210130388* 50-313 \$ 8210130522* 50-313 \$	RUSSELL.J E RUSSELL.J E RUSSELL.J L RUSSELL.L B RUSSELL.L B	8210250028 8210270177 8210220319* 8210040142 8210040211	40-6622 40-6622 50-160 Q 50-317 B 50-318 B
reijeroer d reije w f peile w f pepka. D a pepka. D a	B2[02601]3* 50-397 A B2[0150168 50-322 f B2[0150272* 50-322 f B2[0190385 50-322 0 B2[0280240 50-322 0	ROGERS, P ROGERS, P ROGERS, P ROGERS, R ROGERS, R F	8210190526* 50-313 8 8210190558* 50-348 9 8210250278* 50-348 8 8210240123* 50-348 8 8210010031* 50-321 0	RUSSELL.L B RUSSELL.L B RUSSELL.L B RUSSELL.L B RUSSELL.L B	8210040216 8210060385 8210060394# 8210130461 8210130543	50-318 8 50-317 8 50-317 8 50-317 8 50-317 8
RESNER, E P RESNER, M E RESNIKÖFF, M PENES, L PENES, L	8210180346* FOIA 8210280100* 50-250 P 8207110023 70-1510 8210080088 50-295 8 8210080189 50-316 8	ROGERS,R F ROGGE,J F ROHDE,J E ROHRER,D M ROHAN,T W	8210010327* 50-321 0 8210190271 50-302 8 8210260234* 50-229 8 8210190516* 50-313 0 8210130350* 50-220 R	RUSSELL.L B RUSSELL.L B RUSSELL.L B RUSSELL.L B RUSSELL.L B	8210130548 8210190290 8210250088 8210250154 8210270297	50-317 8 50-317 8 50-318 6 50-317 6 50-318 8
REVES. L REVES. L REVES. L A REVIOLDS. J R	8210190599* 50-295 0 8210280171* 80-282 0 8210190449* 50-255 0 8210280232* 50-305 0 8210050218 50-275 0	Romine. W D Romine. W D Rood. H Rood. H Rooney. V	8210190386* 50-327 8 8210260174* 50-328 8 8210180258 50-362 A 8210210184 50-361 V 8210210200* 50-271 P	RUSBELL-L B RUSBELL-L B RUSBELL-L B RUSSELL-L B RUSSELL-L B	8210270244 8210270254 8210270246 8210270272 8210270274	50-317 S 50-317 S 50-317 S 50-317 S 50-317 S
REYNOLDS: J R REYNOLDS: II S REYNOLDS: II S REYNOLDS: II S RHEE: S	8210050218 50-279 G 8210130299 50-445 G 8210130299 50-445 G 8210220383 PR 8210050233* 50-237 B	ROONEY: V L ROOT: L D ROOT: L D ROOT: L D ROOT: L D	8210210101 50-271 P 8210050307* 50-331 Q 8210130544 50-331 Q 8210150160 50-331 P 8210190664* 50-331 Q	RUSSELL, L. B RUSSELL, L. B RUSSELL, L. B RUSSELL, L. B RUSSELL, L. B	8210270274 8210270279 8210280134 8210280191 8210280191	50-317 B 50-317 B 50-318 B 50-318 B 50-318 B

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCLSSION NUMBER	SUBLECT CATEGONY
RUSSELL.L B RUSSELL,L B RUSSELL,L B RUSSELL,L B RUSSELL,L B	8210280203 8210280249 8210280263 8210280279 8210280276	50-317 S 50-317 S 50-317 S 50-318 S 50-317 S	SCHULTZ.S D SCHUMACHER.M SCHUMACHER.M C SCHUMACHER.M C SCHUMACHER.P M	6210130379 6210080171* 6210040208* 6210150543* 8210150572	PR 50-358 Q 50-331 Q 50-10 Q NUREG	Shapiro, r Shapiro, r Shapiro, r Shapiro, r Shapiro, r	8210150402* 8210150410* 8210150422* 8210150527* 8210250059*	50-322 , 50-322 ; 50-322 ; 50-322 ; 50-322 ;
RUSSELL, L B RUSSELL, L B RUSSELL, L B RUSSO, H L RUTENKROGER, E	8210150405 8210280334 8210280334 8210250128*	50-317 S 50-317 S 50-318 S QA999 70-1739	SCHUMACHER, P M SCHWALB, H R SCHWEIBINZ, E SCHWEIBINZ, E R SCHWEITZER, D G	8210210014 8210210051 8210190627 8210050522* 8210120460	NUREG NUREG 50-358 S 50-483 S RES	SHARISON, S S SHAUD, E SHAUB, T SHAU, A SHAN, A	8208270079 8210270072* 8210210236* 8210080003 8210080005*	50-322 (50-267 , 50-334 , TPDRTLIC TPORTLIC
RUZICKA, W G RYDER, C RYDER, C RYDER, C P RYDER, C P	8210270057 8210050403* 8210050434* 8210050407* 8210060447*	70-687 FOIA FOIA FOIA FOIA	SCHWENCER, A SCHWENCER, A SCHWENCER, A SCHWENCER, A SCHWENCER, A	8208040341 8210050479 8210050488 8210070218* 8210080048	50~373 P 50~352 A 50~322 A 50~266 P 50~397 A	MAWA SHAW. A SHAW. A T SHAW. J SHEA. J	8210080071 8210210537 8210270021 8210200036 8210040237	#PORTLIC 70-2755 #PORTLIC 50-322 \$ 50-245 F
SABADOS, J W SABADOS, J W SACKETT, M H SAFFELL, B F SAGENDORF, J F	8210010361* 8210150067* 8210220256 8210080054* 8210220149	70-27 70-1113 PR FQ1A NUREG	Schwencer, A Schwencer, A Schwencer, A Schwencer, A Schwink, W	8210130043* 8210190134 8210210510 8210220032 8210120216	50-414 P 50-352 A 50-322 A 50-416 P REVIEW GRP	SHEA, J SHEA, J SHEA, J SHEA, J J	6210040293 8210150362 8210250219 8210010320 8210220479	50-245 P 50-245 P 50-245 P 50-245 P
SAIGH, PA BALDHON, SN SALVENDY, O SALVENDY, O SANCIC, D	8210280374* 8210120316* 8208270011 8208270011	CONTRACT 50-259 0 ACRS ACRS 0-333 0	SCINTO, J SCINTO, J SCINTO, J F SCINTO, J F SCINTO, J F	8210050536* 8210190115* 8210190121* 8210190124* 8210280348	50-289 P FOIA FOIA FOIA REVIEW ORP	SMEA.J J SMEA.J R SMEA.J R SMEARCR.D L SMEDLOSKY,J T	8210220486 8210070431= 8210070468* 8210050418 8210210196*	50-245 P FOIA FOIA NUREO 50-245 G
SANDERS, K E SANDERS, W F SANDERS, W L SANDOUIST, G M SANDO, S P	8210070489* 8210220159* 8210010226 8210260234* 8109280175*	FOIA 50-424 0 PR 50-72 R 50-29 S	SCOTT.D E SCOTT.D J SCOTT.D J SCOTT.D J	8210150032* 8210040126 8210040188 8210050227 8210130197	50-416 Q 50-249 S 50-237 S 50-237 S 50-249 S	SHEEHY.E J SHEERAN.R E SHELKROT.E L SHELLEY.W J SHELLEY.W J	8207180088# 8210220440 8210270203# 8210220487 8210260543	Review G= 70-1100 Contract 40-8027 40-8027
SANDB, 8 P SANDUSKY, W F SANDY, W SANFORD, J C SANFORD, J C	81100500(8* 8210220149 8210290249 8210040024* 8210040024*	50-369 S NUREG PR 50-445 Q 50-445 Q	SCOTT, D J SCOTT, D J SCOTT, D J SCOTT, D J	8210150044 8210150097 8210180097 8210190403 8210190458	50-237 S 50-249 S 50-10 R 50-249 S 50-249 S	SHEFFELYM N SHEFFELYM N SHEFFELYM N SHEFFELYM N	8210240545 8210240574 8210270077 8210270088* 8210270242	40-8027 40-8027 40-2041 40-2041 40-8027
SANTELLA, A SARSTEN. G E BASTRE, C SATTERFIELD, R SAUNDERS, G A	8210150112* 8210260205 8210120630 8011210284 8210280046	50-219 S 50-324 S RES 50-247 P 40-8745	SCOTT.D J SCOTT.D J SCOTT.D J SCOTT.D J	8210250248 8210250283 8210250304 8210250328 8210260023	50-237 S 50-237 S 50-249 S 50-249 S 71-9079	SHELLEY.W J SHERON.D U SHERR.T S SHERR.T S SHERR.T S	8210270247+ 8210270095* 8204200405* 8204200408* 8204220144*	4D-8027 50-289 4 70-1510 70-1510 70-1510
SAUNDERS,W F SAW1CK1,S D SCACE,S E SCARAND,R A SCARAND,R A	8210150103* 8207180055 8210010214* 8210120574 8210220036	50-424 Q 50-440 F 50-213 P WASTE MGT 40-6714	SCOTT, D J SCURRY, N SCURRY, N SCURRY, N SCURRY, N	8210270251 8210120402 8210120404 8210270116 8210270119	50-249 S ORG ORG ORG ORG	SHERR, T S SHERR, T S SHERR, T S SHERR, T S SHERR, T S	8210050451* 8210050454* 8210070416* 8210070421* 8210070434*	70-1510 70-1510 FOIA FOIA FOIA
SCARANO,R A BCHANEN,J F SCHAPKER,J F SCHEINER,C A SCHERER,A E	8210220037 8210130566* 8210150334* 8210200019 8210150306	WASTE MOT 50-306 Q 50-518 Q 50-247 Q 50-470 E	SECOR, D T SEIDLE, W C SEIDLE, W C SEIDLE, W C SEIDLE, W C	8210170457* 8210010175 8210070326 8210120241 8210120246	50-395 P 50-313 0 50-285 Q 50-313 0 50-313 Q	SHERRIT S SHERRIT S SHERRIT S SHERRIT S SHERRIT S	8210070436+ 8210070447+ 8210070467+ 8210070473+ 8210070475+	FOIA FOIA FOIA FOIA
SCHERER, A E SCHERER, A E SCHERER, A E SCHERR, S J SCHERRER, J	8210200022 8210280202 8210270240 8210200001 8206300188*	50-36B P 50-470 B PR 70-143 50-155 Q	SEIDLE, W C SEIDLE, W C SEIDLE, W C SEIDLE, W C	8210190347 8210190497 8210190531 8210190596 8210220110	50-285 0 50-313 0 50-285 0 50-482 0 50-285 0	SHERR, T S SHERR, T S SHERR, T S SHERR, T S SHERRER, J	6210070478* 6210070480* 6210070484* 6210070486* 8208100269*	FO[A FO[A FO]A FO[A SO-29 P
SCHERRER, J SCHIFFMACHER, W SCHMIDT, A D SCHMIDT, A D SCHMIDT, A D	8207190431* 8210150168 8210050152 8210050152 8210050152	50-29 0 50-322 T TDPREP TOPREP 50-335 S	SEIDLE.W C SEIDLE.W C SEIDLE.W C	8210220270 8210220377 8210240178 8210240224 8210280225	50-313 0 50-313 0 50-313 0 50-72 R 50-482 0	SHERWOOD, O G SHERWOOD, O O SHEWMON, P SHEWMON, P	8210010217 8210050328 8210270046 8207180073* 8208290017	TOPREP 50-447 A 50-447 A NUREO ACRS
	8210060354* 8210120440* 8210150257* 8210150265* 8210150290*	50-261 F CONTRACT 90-922 T 50-922 T 50-922 T	Belan, J C Belan, J C Belby, D Bemmel. H Behmel. H	8209130461* 8209200475* 8210290006* 8210150341 8210150341	50-293 P 50-29 P COMMISSION 50-155 G 50-155 G	SHEWMON, P SHIELDS, S W SHIELDS, S W SHIELDS, S W	8208270018 8210010230 8210250130 8210270237 8210270240	50-244 : PR 50-546 : PR PR
	8210280451 8210190599* 8210120092 8210120102 8210050299	40-8697 50-295 Q ' NUREQ NUREQ 50-483 A	Semmel. H Semmel. H Semiua. P Serini. B Eestak. F	8210210381 8210210381 8210250231* 8210280421* 8210280308	50-155 G 50-155 G 50-346 S 70-2757 50-275 R	SHIFFER, J D SHIM, K SHIM, K SHIMECK, D J SHIRAKAWA, T	8210290219 8210060267* 8210190715* 8210150409 8210040382	50-275 S 50-304 S 50-295 S RES XPORTLIC
	8210130555* 8210130196* 8210120488* 8210150102* 8210180100*	50-463 0 50-254 8 CONTRACT 50-249 8 50-10 R	SHAFER, P N SHAFER, W SHAFER, W D SHAFER, W D SHAFER, W D	8210130416* 8210040337 8210050154* 8210170342* 8210170750*	50-409 0 50-329 5 50-329 Q 50-331 Q 50-329 0	SHIRAKAWA, T SHIRAKAWA, T SHIRAKAWA, T SHIRAKAWA, T SHIRLEY, S J	8210040385 8210040387 8210060471 8210280435 8210080077	XPORTLIC XPORTLIC XPORTLIC XPORTLIC 50-142 G
	8210270254* 8210040221 8210050077 8210130233 8210130241	50-249 B 50-373 P 50-373 P 50-373 P 50-373 P	SHAMLA, W A SHAD, L C SHAPIRO, R SHAPIRO, R SHAPIRO, R	8210080117 8210070205* 8210150234 8210150234 8210150309*	50-263 8 50-266 P 50-322 0 50-322 0 50-322 0	SHIVELY, C SHOEMAKER, C J SHOEMAKER, C J SHOEMAKER, C J SHOEMAKER, C J	8210270101 8210150464 8210200006 8210260433 8210260449	50-356 P 50-445 £ 50-289 ¢ 50-289 ¢ 50-289 ¢
	8210190606 8210070196* 8210130199* 8209150057 8210220369*	50-373 6 FOIA 50-244 5 FOIA 50-275 H	SHAPIRO.R SHAPIRO.R SHAPIRO.R SHAPIRO.R SHAPIRO.R	B210150324* 8210150337* 8210150351* 8210150365* 8210150393*	50-322 0 50-322 0 50-322 0 50-322 0 50-322 0	SHOEMAKER, C J SHON, F J SHON, F J SHON, F J SHON, F J	8210280269 8210050254 8210070137 8210130333 8210150092	50-269 0 50-247 0 50-440 6 50-440 6 50-247 0

	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT
#UTHOR 5-7.1F U 5-1.F U 5-1.F U 5-1.F I 5-1.F I 5-1.F I 5-1.F I	8210210349 8210210476 8210220338 8210270176 8210220128*	50-155 0 50-440 0 50-155 0 50-320 6 40-1162	SMITH. II G SMITH. P SMITH. P A SMITH. P A SMITH. P A	8210040277 8210130041* 8210040002* 8210040004* 8210120425*	50-316 S CONTRACT CONTRACT CONTRACT CONTRACT	SPESSARD, R L SPESSARD, R L SPESSARD, R L SPESSARD, R L SPESSARD, R L	0210130514 0210130523* 0210190432 0210190433 0210190540	50-483
SHORD, E M SHORD, E M SHEEL, D B SHUILE FLITHOGAREL P	8210050162 8210190746# 8210050530# 8210070240# 8210210504	50-367 0 50-285 R CONTRACT 70-33 50-329 T	SM(TH, P A SM)TH, P A SM(TH, P A SM)TH, P A SM(TH, P A	8210120496# 8210120517# 8210120541# 8210120613# 8210130074#	CONTRACT CONTRACT CONTRACT CONTRACT CONTRACT	SPESSARD, R L SPESSARD, R L SPESSARD, R L SPESSARD, R L SPESSARD, R L	8210190613 8210190638 8210190707* 8210250072 8210250075*	50-275 0 50-407 0 50-255 0 50-341 0 50-341 0
EHLME, IN A EHLMM OCH, M D STECER, U D ETESER U D ETERFEIT, D L	8210180072* 6210010225* 8210050168* 6210260125* 6210120320	FOIA 50-938 0 50-334 P 50-934 P 27-39	SM(1H, P A SM1TH, P A SM1TH, P A SM1TH, P A SM1TH, P A	8210180338* 8210180401* 8210180416* 8210190149 8210190156*	CONTRACT CONTRACT CONTRACT CONTRACT CONTRACT	SPESSARD.R L SPESSARD.R L GPESSARD.R L GPESSARD.R L SPESSARD.R L	8210230106 8210260161 8210260387 8210280122 8210280174*	50-409 0 50-305 0 50-454 0 50-373 0 50-461 0
STEGEL. B FILAT. D B FILDERG J E SELDERG. J E SELDERG. J E	8210180320 8210190013* 8210050374 8210050374 8210150161	50-298 F CONTRAC1 50-440 G 50-440 G 50-440 G	Smith P A Smith P A Smith P A Smith P A Smith P A	8210190162 8210190167* 8210190223* 8210210161* 8210210506*	CONTRACT CONTRACT CONTRACT CONTRACT CONTRACT	SPICKLER.I SPILHAUS.A F SPITIBERG.D B SPRENCEL.J F SRENIAWSKI.D J	8210040453* 8210190002* 8210220004 8210120330* 8207070319	50~537 A CONTRACT 70-416 CONTRACT 70-2748
FILBERG, JE EILBERG, JE SILBERG, JE FILBERG, JE FILBERG, JE	8210150284 8210150286 8210150286 8210210284	50-440 G 50-440 G 50-440 G 50-440 G 50-440 G	SMITH, PA SMITH, PA SMITH, PA SMITH, PA SMITH, PA	8210260520+ 8210260530+ 8210280235+ 8210270378+ 8210120578	TOARHOO TOARHOO TOARHOO TOARHOO SOIB-OA	JENNIANSKI D J SERNIANSKI D J SERNIANSKI D J JENNIANSKI D J SRENIANSKI D J	8210040130 8210050204 8210050314 8210190533* 8210260471	1&E 70-2942 1&E State Prog 1&E
SILCERG. JE SILSERG. JE CILGERG. JE TILGERG. JE TILGERG. JE	6210250324 6210250294 6210250294 6210250324	50-440 G 50-440 G 50-440 G 50-440 G 50-440 G	SMITH.R D SMITH.R D SMITH.R L SMITH.R M SMITH.S K	8210210521 8210210532 8210070156* 8210280095* 8210150377*	40-3453 40-8681 CONTRACT 50-324 P 50-243 P	STADNICK, S STAHL, D M STAHL, D M STAHLE, C STAMIRIS, B	8210130232* 8210130482 8210130482 8210210542 82102050238	50-334 S 50-329 0 50-329 0 50-327 P 50-329 0
RIERG.JE NEEPO.JE ILLERMANS ILLISAR M ILVISAR M	0210250327 0210250216 0210120363 0210120363	50-440 G 50-440 G RES CONTRACT CONTRACT	SMITH. W G SMITH: W G SMITH: W G SMITH: W G SMITH: W G	8210040073 8210040199 8210040201 8210040212 8210040321	50-315 8 50-315 8 50-314 8 50-315 P 50-314 8	STAMIRIS, D STAMPLEY, N STAMPLEY, N STAMSDERRY, W STAMSDERRY, W	8210050240 8210210370 8210050193 8210260515* 8210180007*	50-329 0 50-329 0 50-416 S 50-335 0 50-348 0
1015.8 1 07.0 A 1 07.0 A 1 07.05 G E	8210280384 8210190340* 8210120264 8210220198 8210150025*	CONTRACT 50-315 F 50-528 R 50-520 R 50-347 0	SMETH, W G SMETH, W G SMETH, W G SMETH, W G SMETH, W G	8210050300 8210180120 8210170266 8210170340 8210170380	50-315 8 50-316 8 50-315 8 50-315 8 50-315 8	STARK,R M STARK,R M STARK,R M STARK,R M STARK,R M	8208270699 8210120445 8210130069 8210220923 8210280436	50-537 A 50-537 A 50-537 A 50-537 A 50-537 A
it ineaun f p itslair.M itslair.M itslair.M itseamat r w	8210740902% 8210770140 8210070140 8210170480 8210150307#	CONTUACT 50-327 0 50-327 0 50-255 0 50-255 0	SNIEZEK, J H SMITH, W O SMITH, W O SMITH, W D	8210190572 8210190727 8210190749 8210050368 8105040512#	50-315 S 50-316 S 50-315 S NUREO 50-285 P	STARKEY, R B STARKEY, R B STARKEY, R B STARKEY, R B STARKEY, R B	B210130242 B210190240 B210220265 B210220499* B210290074	50-261 R 50-261 S 50-261 S 50-261 G 50-261 S
10x (NO. B 111, (NOER, J) > (NOER, P) > (NOER, P) > (LDS, J)	8210120455 8210280235* 8210170132* 8210120307* 8210010464*	RES CONTRACT 50-324 Q 50-321 Q 50-375 Q	SNIEZEK, J H SNIEZEK, J H SNOW, B A SNYDER, B J SNYDER, B J	8107170126* 6210050082* 6210170703 6210260535 6210270326	F01A F01A 50-244 8 50-320 P 50-320 P	STARKEY.R B STARMER.R J STARMSTECKI.R STARMSTECKI.R STARMSTECKI.R	8210270333 8210120354 8203050387 8210010274* 8210040024	50-241 8 WASTE HGT 50-317 0 50-220 0 50-247 0
FC.DS. J.L. FU.MOLT.D.J. EHICER.R.J. CHILB. II WITH.E.M.	8210080259* 8210290034* 8210040196* 8210210176* 8210120556*	50-395 Q 50-142 F QA999 CONTRACT CONTRACT	SNYDER.S C SODA.K GOLLENBERGER.D. GOLLENBERGER.D SOO.P	8210700102 8210150421 8210120494 8210120514 8210120460	RES RES 40-8728 40-2259 RES	STAROSTECKI.R STAROSTECKI.R STAROSTECKI.R STAROSTECKI.R STAROSTECKI.R	8210040150 8210040240 8210040318 8210070214 8210070239	50-273
13TH E M 11TH C C 11TH C C 11TH C C 11TH C C	0210120556* 0210040049* 0210130449* 0210220172* 0210240206	CONTRACT 50-24 G XPORTLIC 70-371 50-286 F	SORRELL,E C SOPRELL,E C SOUCY,A R SPARKS,O L SPARKS,G L	8210190016* 8210190046* 8210010374 8210010248* 8210090203*	50-321 F 50-321 F PR 50-416 S 50-416 S	STAROSTECKI, R STAROSTECKI, R STAROSTECKI, R STAROSTECKI, R STAROSTECKI, R	8210070268 8210070337 8210070357 8210070362 8210070376	50~219 0 50~220 G 50~309 G 50~333 G 50~271 G
11TH, G H 11TH, G H 12TH, G H 11TH, G H 12TH H	8210060202 8210040306 8210080063 8210150055 8210040399	50-220 0 50-27 0 50-217 P 50-322 0 50-29 P	Sparks.g L Sparks.g L Sparks.g L Specter.a Specter.b M	8210060224* 9210220162* 9210220191* 9208010014* 9210130648*	50-416 S 50-416 S 50-416 S 50-289 H 50-244 F	STARDSTECKI, R STARDSTECKI, R STARDSTECKI, R STARDSTECKI, R STARDSTECKI, R	8210130271 8210130303 8210130476 8210130556 8210150001	50-277 G 70-135 70-1100 50-247 G 50-293 G
ITH E H ITH, E H ITH, E H IETH, J A IETH, J C	8210010427 8210150476 8210150480 8210130132* 8210150601	50-289	SPEDDEN, HR SPEIS, TP SPELS, TP SPELMAN, HJ SPELMAN, HJ	8210220086* 8010280078 8011110084 8210150463 8210250315	40-8111 50-247 P 50-247 P 40-2041 40-2061	STAROSTECKI.R STAROSTECKI.R STAROSTECKI.R STAROSTECKI.R STAROSTECKI.R	8210150015 8210150076 8210150083* 8210150214 8210150221	50-334 0 50-289 0 50-289 0 90-317 0 50-289 0
1114. J C 1114. J C 1114. J E 1114. J E 1114. J E	8210180420# 9210240013 8210010218 9210010232 8210010232	40~6622 40~6622 PR PR PR	SPELMAN, H J SPENCER, D SPENCER, M D SPESSARD, R SPESSARD, R	8210250319 8210040134* 8210010302 821008088 8210080189	PR 50-275 S 50-316 S	STAROSTECKI:R STAROSTECKI:R STAROSTECKI:R STAROSTECKI:R STAROSTECKI:R	8210150246 8210150271 8210150299 8210190702* 8210190797	50-271
17H, J K 17H, J K 17H, J K 17H, J L 17H, J L	8210190500* 8210150504* 8210150507* 8210280036* 8210280039*	50~263 P 50~263 P 50~322 F	SPESSARD, R L SPESSARD, R L SPESSARD, R L SPESSARD, R L SPESSARD, R L	6210040070 8210050304 8210050336 8210060264 8210060359	90-461 A 50-331 Q 50-155 Q 50-373 Q 50-237 Q	STARDSTECKI.R STARDSTECKI.R STARDSTECKI.R STARDSTECKI.R STARDSTECKI.R	8210210100 8210210182 8210210241 8210210300 8210210464	50-333 Q 50-245 Q 50-423 Q 50-247 Q 50-272 Q
THE J R JTHE J R STREE THE H G THE H J	82101503501 82101803621 82102702271 82100604001 82101504951	CONTRACT 40-8632 50-247 8	SPESSARD, R L SPESSARD, R L SPESSARD, R L SPESSARD, R L SPESSARD, R L	8210080190 8210130164 8210130211 8210130240 8210130484	50-237	STAROSTECKI.R STAROSTECKI.R STAROSTECKI.R STAROSTECKI.R STAROSTECKI.R	8210220153 8210220344 8210260134 8210260225 8210260257*	50-29 Q 50-244 Q 50-322 Q 50-320 Q 50-387 Q

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	RDHTUA	ACCESSION NUMBER	SUBJECT CATEGORY	AU FHOR	ACCESSION NUMBER	eurgat Categai
STAROSTECKI, R STAROSTECKI, R STAROSTECKI, R STAROSTECKI, R STAROSTECKI, R	8210260483 8210290147 8210290171 8210290189 8210290208	50-287 S 50-29 0 50-244 Q 50-213 Q 50-352 Q	STOLZ.J F STOLZ.J F STOLZ.J F STOLZ.J F STOLZ.J F	8210270342 8210270372 8210270382# 8210270387# 8210270143*	50-287 P 50-346 P 50-346 P 50-346 P 50-313 P	TARMS, D N TAUBER, H TAUBER, H TAUBER, H TAUBER, H	8210270222 8210010454 8210080044 8210150322 8210180186	40-8612 50-341 a 50-341 a 50-341 a
STAROSTECKI.R STAROSTECKI.R STASEK.B STABJESKY.F M STEED.L L	8210270212 8210270300 8210250114* 8204160212 8210060076*	50-244	STOLZ, J F STOLZ, J F STOLZ, J F STONE, J C STONER, M A	8210270148* 8210270382* 8210270387* 8210040373* 8210210301*	50-313 P 50-346 P 50-346 P 50-315 Q 50-329 A	TAUSER.H TAUSER.H TAYLOR.D TAYLOR.D J TAYLOR.J	8210190696 8210220414 8210260446 * 8210150560 8210120270	50-24 6 50-24 4 50-24 5 NUFEC 50-443 •
STEELE.R L STEELE.R L STEELE.H J STEFANG.J STEFANG.J	8210250084 8210250164 8210150089* 8210190011 8210270073	50-344 5 50-344 5 50-311 5 50-440 F 50-440 A	STGVER.J R STREETER.J STREETER.J STREETER.J STREETER.J	8210040198 8210040198 8210080088 8210080189 8210260447	CONTRACT 50-237 S 50-295 S 50-316 S 50-254 S	TAYLOR, J H TAYLOR, J H TAYLOR, J H TAYLOR, J W TAYLOR, P A	8209090009 8210060346 8210250132 8210130381 8210150269•	TOPAEP TOPAEP P T21 P R 50-33+
STELLO. V STELLO. V STELLO. V STELLO. V	8210170631 8112210166* 8210010107* 8210010286 8210040314	REVIEW GRP FOIA 50-366 S REVIEW GRP REVIEW GRP	STREETER, J F STREETER, J F STREETER, J F STREETER, J F STREETER, J F	8210050253 8210050274 8210150249 8210150385 8210150497	50-346 0 50-315 0 50-282 0 50-263 0 50-409 0	TAYLOR,R G TEDESCO.R L TERC, II M TEST,R Z THADANI.A	8210170820 * 821026048: * 8210150059 * 8210270249 * 8203170016 *	50 445 1 50 409 4 50-322 8 50 213 5 50-537 1
STELLO, V STELLO, V STELLO, V STELLO, V	8210180002 8210130138 8210130138 8210080109	REVIEW ORP FOIA REVIEW ORP REVIEW ORP REVIEW ORP	STREETER, J F STREETER, J F STREETER, J F STREETER, J F STREETER, J F	8210150523 8210150530* 8210170421 8210190427* 8210190643	50-10 Q 50-10 Q 50-255 Q 50-255 Q 50-331 Q	THATCHER, T L THIES, A C	6210080073 8210060073 8210080073 6210220434 8210260331	50-522 (50-522 (50-522 « 50-527 «
STELLO, V STELLO, V STELLO, V STELLO, V	8210170004 8210250131 8210250154 8210270178 8210280031*	REVIEW GRP REVIEW GRP REVIEW GRP REVIEW GRP 50-334 P	STREETER, J F STREETER, J F STREETER, J F STREETER, J F STREETER, J F	8210250105 8210250109* 8210280164 8210280168* 8210280223	50~373 0 50~373 0 50~282 0 50~282 0 50~282 0	O L AMOHT O L AMOHT D L AMOHT O L AMOHT R B ABAMOHT	8210040400 8210080049 8210130047 8210130063 82101803584	50-246 / 50-247 / 50-266 f 50-286 f FOIA
STELLO V STEPHENSON,C J STEPTOE,P STEPTOE,P STEPTOE,P	8210280351* 8210130524* 8210050223 8210050223	REVIEW GRP 50-289 S 50-329 Q 50-329 G 50-329 G	STREETER, J F STREETER, J F STRENGE, D L STROM, P O STUCKY, S W	8210280226# 8210260229# 8210270041# 8210270338 8210180147	50-305 Q 50-305 Q 50-537 Q NUREG 50-397 Q	THOMAS, C O	8210040394 8210050460 8210050540 8210050543* 8210070074	T 0766P 50-461 1 50-182 P 50-182 P T 0786P
STEPTOE,P P STEPTOE,P P STEPTOE,P P STEPTOE,P P STEPTOE,P P	8210050215 8210080082 8210080082 8210080079 8210080079	50-327 0 50-255 0 50-255 0 50-255 0 50-255 0	STUCKY, S W SUBRAMONIAM, N SUGARMAN, R J SUGARMAN, R J SUGARMAN, R J	8210250325 8210120640# 8210010244 8210010244 8210180204	50-289 0 50-341 A 50-352 0 50-352 0 50-352 0	THOMAS, C O	8210070110 8210120475 8210120480* 8210120492* 8210120115	TOPATA 50-62 A 50-62 A 50-62 I 50-112 I
STERNBERG, D M STERNBERG, D M STERNBERG, D M STERNBERG, D M STERNBERG, D M	8210010053 8210060165 8210060330 8210060341 8210070158	50~344 Q 50~508 Q 50~312 Q 50~528 Q 50~508 Q	Sugarmanir J Sugarmanir J Sugarmanir J Sugarmanir J Sugarmanir J	8210180204 8210180208* 8210180208* 8210180217 8210180217	50-352	THOMAS, C O THOMAS, J	8210150881 821012027 8210220185 821020504 8210707027\$*	TOPAEP TOPAEP TOPAEP 50-191 50-219
STERNBERG.D H STERNBERG.D M STERNBERG.D M STERNBERG.D M STERNBERG.D M	8210070278 8210070290 8210070297 8210070319 8210070378	50-312 0 50-312 0 50-397 0 50-312 0 50-440 0	Sugarmanir J Sugarmanir J Sugarmanir J Sugarmanir J Sugarmanir J	8210180223 8210180223 8210180224 8210180224 8210180226*	50-352 0 50-352 0 50-352 0 50-352 0 50-352 0	THOMAS, L. M THOMAS, L. M THOMAS, R. D THOMAS, R. D THOMAS, R. D	8210070109 8210250170 8210080311→ 8210130130 8210260304	50-445 F 50-10 F 70-754 27-48 27-10
STEBNBERD N M	0043000045			8210180226* 8210180253 8210180253 8210190364 8210210477*	50-352 0 50-352 0 50-352 0 50-329 K 50-272 0	THOMPSON, D THOMPSON, T R THOMPSON, T R THOMPSON, Y J THOMSEN, F T	8207180041 8210070099* 8210270288* 8210220246 8210010382	FOIA 50-27 50-155 PR 50-522 (
				8210060248* 8210270334* 8210270364* 8210270381* 8210010064	50-346 B 50-321 S 50-346 B 50-346 S 50-537 G	THOMSEN.F T THOMSEN.F T THOMSEN.F T THOMSEN.F T THOMSEN.F T	8210050171 8210050171 8210130190 8210130367 8210130367	50-522 (50-522 (50-522 (50-522 (
				8210060193 8210200047 8210200080 8210250353 8207140491*	50-537	THOMSEN, F T	8210130498 8210130498 8210200045 8210200045 8210260420	50-522 F 50-522 F 50-523 F 50-523 F 50-522 F
				8210120105 8210130376 8210190443 8210190445 8210220335	50-237 P 50-10 F 50-295 P 50-237 P 50-237 P	THORNTON, P THORNTON, P THORNTON, P THORNTON, P THORNTON, P	8210050232 8210050232 8210050356 8210050356 8210150470	50-155 f 50-155 f 50-155 f 50-155 f 50-155 f
				8210260151 8210010284* 8210270015 8210070381* 3210050360	50-373 P 50-329 E 50-537 Q 50-309 Q NUREQ	THORNTON, P THORPE, A A THORPE, J R THORPE, J R THORSEN, E O	8210150470 8210260407# 8210130594 8210220372 8210220375	50-159 6 50-259 5 PR PR 50-247 6
				3210130294 3210180154 3210290242 3210290253 3210280204*	50-358 A 50-358 A PR PR 50-277 P	THULL, T S TIETZ, O	8210210430* 8210220108* 8210220116* 8210220201* 8210130423*	50-245 5 50-245 5 50-245 6 50-245 6 50-254 5
)210260223*)210190444*)210080045)210150656)210050360	50-304 S 50-395 P 50-334 F TOPREP NUREO	TILLMAN, A TIMBON, B S TIPPS, S B TIPPS, S B TIPPS, S B	8210150380* 8210210041 8210010078* 8210050084* 8210060289*	70-143 50-201 / 50-366 \$ 50-366 \$ 50-366 \$

	ACCESSION	SUBJECT CATEGURY	AV THOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
TIPES D TIPES D TIPES D TIPES D TIPES D	NUMBER 8210140324* 8210180240* 8210130185* 8210130258*	50-366 S 50-366 S 50-366 S 50-366 S 50-366 S 50-321 S	TUCKER, H B	8210010134+ 8210010282 8210010352 8210010367 8210010463*	50-413 0 50-369 0 50-269 F 50-370 0 50-269 0	UHRIG, R E	8210050416 8210050557* 8210060236 8210060276 8210060281	50-387 A 50-335 F 90-387 B 50-387 A 50-250 P
	8210130414# 8210130549# 8210190511# 821019060# 8210220222#	50-364 5 50-366 6 50-366 5 50-366 5 50-321 5	TUCKER, H B	8210040107 8210040232 8210040254 8210040273* 8210050130	50-269 P 50-269 P 50-369 K 50-369 K 50-413 A	UHRIG,RE UHRIG,RE UHRIG,RE UHRIG,RE UHRIG,RE	8210060288 8210060371 8210080264 8210130090 8210130297	50-335 P 50-387 R 50-335 G 50-387 E 50-389 E
11 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	0210290372# 0210290106# 0210290106# 02102203084	50-321 S 50-346 S 50-321 S 50-346 S 50-321 S	TUCKER, H B	8210050264 8210050384 8210060311 8210070072 8210070092	50-413 A 50-413 A 50-413 A 50-369 F 50-413 A	UHRIO, A E UHRIG, R E UHRIG, R E UHRIG, R E UHRIG, R E	8210130289 8210130301 8210130348 8210130379 8310130536	50-387 A 50-389 A 50-389 F PR 50-389 8
([FF7 5 B (FF95 5 B (FF85 5 B (FF	BE 10090309# 8010090359# 8010090375# 8010070302#	50-321 S 50-321 S 50-321 S 50-382 M	TUCKER, H B	8210080208 8210130159 8210130177 8210130262 8210130260	50-413 5 50-269 P 50-369 S 50-369 K 50-269 0	UHRIG, RE UHRIG, RE UHRIG, RE UHRIG, RE UHRIG, RE	8210150407 8210190439 8210190186* 8210190310 8210190348	50~250 P 50~250 P 50~250 F 50~335 P 50~309 A
OBJACEA OFFICE CINCED CINCED CINCED CINCED	8210150180* 8210010371* 8210130545 8210190776* 8210010257	50 -263	TUCKER, IF B TUCKER, IF B TUCKER, H B TUCKER, H B TUCKER, H B	8210130399 8210130467 8210130502 8210130599 8210150068	PR 50-369 P 50-287 P PR 50-413 0	UHRIG, R E UHRIG, R E UHRIG, R E UHRIG, R E UHRIG, R E	8210190351 8210190371 8210190440 8210190559 8210220090	50-250 0 50-335 F 50-250 F 50-250 P 50-251 P
CHEFFE BA CHEFFE BA LIVER BBA THEFFE BBA CHEFFE BBA	6 (1604009) 0.10050275 0210040192 021072031) 021072031	50-31;	TUCAFR, H B	8210150074 8210150369 8210150518 8210150617 8210180055	50-413 K 50-269 0 50-369 F 70-2944 50-269 P	UHRIG.R E Uhrig.R E Uhrig.R E Uhrig.R E Uhrig.R E	B210220167 B210220214 B210220286# B210220304# B210220451	90-387 9 50-387 0 90-335 0 50-250 0 50-335 4
CHERKY A CHORT A CHARLE A CHARLE A CHARLE A	8101 00573 8210190469 8210190505 8210190546 8210: 20117	50~155 P 50~155 P 50~255 P 50~255 P 50~155 P	TUCKER.H B TUCKER.H B TUCKER.H B TUCKER.H B TUCKER.H B TUCKER.H B	8210180040* 8210180128 8210170103* 8210170544 8210170611	30-269 P 50-370 A 50-369 F 50-269 R 50-413 F	UHRIG, RE UHRIG, RE UHRIG, RE UHRIG, RE UHRIG, RE	8210250313 8210250317 8210260391# 8210270253 8210280067	50~387 A 50~387 R 50~335 0 50~250 P 50~387 E
ENGLANT THE FAIT H THE A A THE A A TOWNER, A	######################################	50-237 5 50-10 0 FUIA 101A 50-247 6	TUCKER, H B	8210190740 8210190742 8210210131 8210210407 8210220134	50-370 F 50-389 R 50-269 P 50-269 P 50-413 Q	UHRIO, R E UHRIG, R E UHRIG, R E ULLRICH, J ULRICH, W T	8210280254 821028027 (8210270240 8210130215* 8210130272*	50-389 A 50-250 F PR 50-373 R 50-277 P
TTH A D T. 4811 3Tte. 1 T. 2167 D R H. 1647 D R H. 1811 D R	8 701903684 9210/50934 02100/6145 0/10060175 0210060199	50-397 0 54 CY 50-537 0 50-537 0 50-537 0	TUCKER, H B	0210250102 0210220318 0210220318 0210220318	50-369 0 50-369 0 50-369 5 50-269 0 50-413 D	UNTERHEYER UPRIGHT.C M UPRIGHT.C M UPRIGHT.C M UPRIGHT.C M UPRIGHT.C M	8210130076 8210010143* 8210010350* 8210150052*	XPORTLIC 50-413 0 50-324 0 50-324 0 50-324 0
COLLEGE DE RECOLLEGE DE RECOLLE	8510250488 8510550568 8510550568 8510550568	50-537 0 50-537 0 50-537 0 50-537 0 50-537 0	TUCKER, H D TUCKER, H B TUCKER, H B TUCKER, H B TUCKER, H B	8210250304 8210260201 8210270139* 8210280017* 8210280065	50-369 P 30-413 A 50-369 F 50-369 F 50-413 E	UPRIGHT,C M UPRIGHT,C M UPRIGHT,C M UPRIGHT,C M URDANIK,T	8210150256* 8210150315* 8210220145* 8210220307* 8210250175	50-327
CONTROL DAR COLLEGE DAR COLLEG	& 110 ° 50 ° 54 63 10 ° 50 ° 54 63 10 ° 50 ° 54 63 10 ° 60 ° 51 63 0 7 6 ° 62 ° 64 63 0 7 6 ° 64 64 0 7 6 ° 64	50-537 0 50-537 0 CONTRACT	Tucker, H B Tucker, H B Tucker, H B Tucker, H B Tucker, H B	8210290045 8210290083 8210290119 8210290190 8210290250	50-370 S 50-270 S 50-413 S 50-269 S 50-413 S	VALKOVIC.M M UTLEY.E E UTLEY.E F UTLEY.E H	8210010111* 8210220406* 8210220409 8210220409 8210210054	50-400 G 50-438 G PR PR NUMEG
F H, T R A M) T R A F M, T R A F M, T R	6210010x32 6210010271 6210740060 6/13040249 6210190299	50 454 E 50-454 A 50 454 K 50 457 9	TUCKER, H B TUCKER, H B TUCKER, H B TUCKER, H B TUPPER, K F TURK, B E	0210290308 6210290354 6210290359 6210060339 6210040059	50-287 S 50-413 S 50-267 S XPORTLIC 50-382 Q	VALKOVICAN M VAN BRUNTAE E VAN BRUNTAE E VAN BRUNTAE E VAN BRUNTAE E	8210220154 8210060413 8210070391 8210040292 8210040205*	NUREO 50-529 9 50-529 8 50-528 M
AMM T R ANH T R ANH T R ANH T R ANH T R	7210190562 7210220354 8210270104 8210150354 8210150429	50-456 B 50-10 F 50-454 E 50-344 P	TURK, & E TURK, B E TURK, B E TURK, B E TURK, S E	8210040061 8210040183 8210080070 8210150124 8210150183	50~382 0 50~382 0 50~382 0 50~445 0 50~445 0	VAN BRUNT, E E VAN BRUNT, E E VAN BRUNT, E E VAN BRUNT, E E VAN BRUNT, E E	8210050245 6210070210 6210070219 6210070219 6210070229	50-528 A 50-528 Q 50-528 8 50-520 8 50-528 8
AN A C CHAMIN K CHAMIN A CHAMIN K LINAN B	8203310094 8204120487 8205180693 8210270402 8210270408	* 50-311 P * 50-281 8 * 50-281 8 * CONTRACT	TURK. S E TURK. S E TURK. S E TURNAGE. K O TURNAR. L C	8210130366 8210210152 8210230288 8210210037 8210130506	50-445 0 50-382 0 50-382 0 NUREO 50-413 D	VAN DRUNT, E E VAN BRUNT, E E VAN BRUNT, E E VAN BRUNT, E E VAN BRUNT, E E	8210070320 8210070321 8210070339 8210070334 8210070374	50-520 8 50-520 8 50-520 8 50-520 8 50-520 8
IF 1746.H B IF LIAC.H B IHOLE.D C IMP PP L F PP L E	8210270408 8210150235 8210060376 8210070275 8210210477	50-275 0 50-317 0 5-50-217 6 5-50-217 6	TURNQUEST, L UBELL, R A UDELL, R A UDELL, R A UDERLTZ, R A	8210190471 8206060032 8210010006 8210080010 8210120328	FOIA FOIA FOIA	VAN BRUNT, E E VAN BRUNT, E E VAN BRUNT, E E VAN BRUNT, E E VAN BRUNT, E E	8210080155 8210130187 8210130443 8210130444 8210130491	50-528 0 50-528 8 50-528 0 50-530 9 50-530 9
ik bridge. 0 f Weridge. 0 f Waridge. 0 f Waridge. 0 f	8210210173 8210210173 821021017 821021017 821021037	3 50-320 0 3 50-320 0 9# 50-320 0 9# 50-320 0	UDERITZ.R A UDY.A C UDY.A C UHRIG.R E UHRIG.R E	8210150080 8210250372 8210280432 8209170062 8210010017	* 50-213 P * 50-247 P 50-250 F	VAN BRUNT, E E. VAN BRUNT, E E. VAN BRUNT, E E. VAN BRUNT, E E VAN BRUNT, E E	8210130495 8210130544 8210150163 8210190176 8210190918	50-528 E
Lyridge. G F Wida. T Hea. H d Wer k g Hea. H b	921021037 921027000 920917005 921001009 921001009	4 50-287 0 7 XPORTLIC 3 50-413 F 0 50-367 0	UHRIO, REUHRIO, REUHR	8210010084 8210010153 8210010272 8210010321 8210050041	14 50-335 G 1 50-250 P 14 50-250 Q	VAN BRUNT, E E VAN BRUNT, E E VAN BRUNT, E E VAN BRUNT, E E VAN BRUNT, E, E	8210190463 8210190717 8210220394 8210250100 8210250305	50-528 A 50-528 G 50-528 S

AUTHOR	ACCESSION NUMBER	CATEGOR	łY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGOR		AUTHOR	ACCESSION NUMBER	SUZJE: T CARE
VAN BRUNT, E E	8210250326	50-528	5	VEITCH, J L	8210150544*	0A999		WALKER, R	8210250467	50 2*4
VAN BRUNT, E E	8210250322	50-528	š	VERRELLI.D	8210180004	50-348	Q	WALKER, R D	8210150386	50-267
VAN BRUNT, E E	8210270211	50~528	Ā	VERRELLI, D	8210260245	50-327	D D	WALKER, R D	8210150502+	50 101
VAN BRUNT, E E	8210280057	50-528	Ä	VERRELLI, D M	8210010086	50-400	a	WALKER, R D	8210150538×	50-10
VAN BRUNT, E E	8210280139	50-528	Ä	VERRELLI, D M	8510010150	50~83	O .	WALKER, R D	0210250116.	50 373
VAN DROVILE E	0210600101	50-020	4							4.0
VAN BRUNT, E E	6210280199	50-528	A	VERRELLI, D H	8210010132	50-324	a	WALLACE, T	8210280183	50 223
VAN BRUIT. E E	8210280274	50~528	E	VERRELLI, D M	8210010148	50-416	а	WALLICK, M E	8210190215+	CONTRACT
VAN ERP. J B	8210150557	NUREG		VERRELL (D M	8210010171	50-324	a	WALSKE, C	#E10090902B	COMMISSIO
YAN RIPER. 0 G	B210080033	XPORTL (:	VERRELLI, D M	8210010173	50-261	a	WAMBACH, T V	6510150353	50 255
VAN RODYEN, D	8210120370	RES		VERRELLI, D M	8210010171	50~43B	a	WARD, E C	6210060164	50-260
				UE0=5:1. B. W	001001000-	50 400				
VAN SYGC, C	8207180051	50-219	H	VERRELLI-D (1	8210010200*	50~438	G.	WARD, E. C	9210250200	50-262
VANDEL T E	8210190608*	50-482	Q	VERRELLI, D II	8210010333	50-390	o a	NARD, K D	8210040308	50-463
VANDENBERG, D	8210130145*	50-255	R	VERRELLI. D M	8210010336	50-324	ď	WARD, W J	8010120163	50-247
VANDERMOLEN, H	8103050756*	FOIA		VERRELLI D M	0210010340*	50-324	g	WARD W J	8101140002	50-224
VANDEWALLE: D J	8210040342	50-155	P	VERRELLI, D M	8210010411	50-518	Q	WAREMBOURG	8210040114	50 247
VANDEWALLE, D J	82100503424	50-155	Q	VERRELLI, D M	8210010421	50-438	Q	WARE MBGURG, D	92091504404	5-0~247
VANDEWALLE, D J	8210050425	50-155	P	VERRELLI, D M	82100104264	50-518	Ğ.	WAREMBOURG, D	8210050331	50-267
VANDEWALLE, D J	8210030423	50-155	P	VERRELLI, D M	8210010430	50-259	ā	WAREMBOURG. D	8210130344	50-267
VANDEWALLE, D J	8510090555	50-155	F	VERRELLI, D M	8210010442	50-414	õ	WAREMBOURG, D	8210190537	50-267
VANDEWALLE, D J	6210060222	50-155	P P	VERRELLI, D M	8210010452	50-390	ā	WAREMBOURG D	8210190655	50-247
VANDEWALLE, D J	0510000534	30-122	r				-	manching one in	DE10170033	30.12
VANDEWALLE, D J	8210070013	50-155	Р	VERRELLI, D M	8210150024	50~390	Q	WAREMBOURG, D II	8210080256	50-247
VANDEWALLE, D J	8210080279	50-155	a	VERRELLI D M	8210150108	50-324	Q	WAREMBOURG, D N	8210190306	50-767
VANDEWALLE, D J	6210130334	50-255	₽	VERRELLI.D M	8210150149	50-438	a	WAREMBOURG, D W	8210510081*	50-767
VANDENALLE, D J	8210130521	PR		VERRELLI, D M	8210150162	50-324	Q	WAREMBOURG, D W	8210220359	PR
VANDEWALLE, D J	8210220334	PR		YERRELLI, D M	8210120209	50~390	Q	WARLOL, W N	8210080331*	APORTLE,
HAUSEUM LE B	55.65.65.65	50-155	g.	VERRELL I. D M	8210150288	50-324	0	WARING, J P	8210040311	TOPPER
VANDEWALLE, D J	8210240316* 8210290240	PR 90-133	u	VERRELLI, D M	8210150304	50-390	ğ	WARNICK, R	8210040337	50 327
VANDEWALLE, D J	8210270240 8210220471*	50-413	a	VERRELLI, D M	8210150318	50-518	ă	WARNICK, R	8210190627	50~358
VANDOORN, D K				VERRELL I, D M	6210150323	50~390	ā	WARNICK, R F	8210040185*	50-409
VARELA, A A	8210060215*	50-412	Q.	VERRELLI, D M	8210150349	50-390	ă	WARNICK, R F	8210050139	50-32,
VARELA, A A	8210070400*	50-443	a	VE(EDE 112 11	GE:0100=17	00 5.0	•	WARRICK, A. F	6210030134	30-321
VARELA, A. A.	8210210082*	50~352	G .	VERRELLI, D M	8210150399	50-259	Q	WARNICK, R F	8210050146*	50-007
VARGA, S A	8209170061	50-305	Ē	VERRELLI.D M	8210220139	50~324	Q .	WARNICK, R F	8210080188	50-007
VARGA, S A	8210040037#	50-364	Р	VERRELLI, D M	8510550190	50-400	Q .	WARIIICK, R F	8210130557+	50-461
VARGA, S A	B210040041*	50-364	P	VERRELLI, D M	8510250194	50-324	0	WARNICK, R F	8210150441	50-329
VARGA, S A	8210040417*	50-315	P	VERRELLI, D M	8210220312	50-160	G .	WARNICK, R F	8210190739	50-3.7
MADON O A	0010040410-	E0-015		VERRELLI.D M	0210220315	50-390	a	WARNICK, R F	82101907874	50-440
VARCA, S A	8210040419+	50~315	P	VERRELLI, D M	8210220325*	50-140	ů.		8510370140	50-329
VARGA, S A	8210040428	50-315	P	VERRELLI, D M	0210220370	90-259	Q	WARNICK, R F		
VARGA, S. A.	8210030452	50-286	P	VERRELLI, D M	8210220459	50-390	Q	WARNICK, R F	0210270154	50-327
VARGA, S A	8210050485	50-272	P P	VERRELL I. D M	8210220472	50~390	e e	WARNICK, R F	8210290377	50-327
VARGA, S.A	8210050487	50-334	P	VERNELL TID II	DE [UERO4 / E	30-340	u	WARNOCK, R	8510580085+	50-261
VARGA, S. A.	8210050534	50-286	Р	VERRELLI.D M	#210220480*	50-327	Q	WATERS, J R	8210190599+	50-295
VARGA S A	8210050541*	50-315	P	VERRELLI, D M	8210220489	50~324	ä	WATSON, M E	8210200096+	50-331
VARGA, E A	8210060431	50-272	F	VERRELLI, D M	8210220474*	50-324	Q	WEBB. W A	8210190185*	50-320
VARGA, S A	8210120557	50-315	p	VETERE, L A	8210250287	50-247	G	WEBER, C F	8210210034	50-259
VARGA, S A	8210120560×	50~315	P	VILLA, R	8210050398	50~447	A	WEDER, D A	8210280432+	50-247
			_	Altre v A. Pr	2010150157	-0 417				
VARÇA, S.A	8210120565*	50-315	6	VILLA, R	8210050408*	50-447	A	WEBER, W V	821005042/*	50-155
VARGA, E A	8210130400	50-305	P	VILLA.R	8210270051#	50-447	A	WEE, D T	8210040189#	50-237
VAROA.S A	8510130705	50-247	P	VILLFORTH, J C VINCE, S	8210180149 8210190040*	50-413	D F	WEGST, N F	8510500081	50-142
VARGA, S A	8210130403	50-272	P	VISSER. J E	8210190040#	50-315	г	WEIGLAND, C C	02102/0338	NUREG
VARGA, S A	6210130604	50 -286	F	AISDEM'A E	05:101504194	CONTRACT		WEIL.C H	8210190787#	50-410

яФнтиа	ACCESION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
#E150 E R #E150 E P #E150 E P #E150 E P #E150 E R	8210220410 8210220465 8210220465 8210260397 8210260397	50-247 G 50-287 G 50-289 G 50-537 G 50-537 G	Wiesemann, R A Wiesemann, R A Wigoins, E Wigoins E Wigoins, E	8210170508* 6210260351* 6210120347 6210120371 6210170230	50-395 P TOPREP CONTRACT CONTRACT CONTRACT	MILSON, J C MILSON, J C MILSON, J C MILSON, J C	8210060378* 8210130204 8210130208* 8210130213* 8210130216*	50-280 8 50-280 8 50-280 8 50-280 8 50-280 8
# 155 E 8 # 155 E 8	8210240397 8210260404* 8210260404* 8210260404* 8210260242	50-537 G 50-537 G 50-537 G 50-537 G 50-247 G	MIGO INTON, D WIGG INTON, D WIGG INTON, D WIGG INTON, D	8210270207 8210270226 821026061 8210270344 8210280405	CONTRACT CONTRACT 50-315 P 50-295 P 50-295 F	MITEON' 7 T MITEON' 7 T MITEON' 7 T MITEON' 7 T	8210130500 8210130507* 8210150054 8210150075 8210150139	50-280 8 50-280 8 50-280 9 50-280 8 50-280 8
WEISSLER WELLED WELLEDA WELLEDA	8210280242 8210190332 8210040084 8210040127 8210190657	50-247 0 50-341 S 50-341 S 50-341 S 50-341 S	NIZTOR, D NIZTOR, D NILCOVE, M N WILCOVE, M N WILCOVE, M N	8210210381 8210210381 8210010042 8210040018 8210040057	50-155 G 50-155 G 50-329 G 50-329 G 50-329 G	WILSON, J L WILSON, J L WILSON, J L WILSON, J L WILSON, J L	8210150359 8210150394 8210220095 8210220097* 8210220100*	50-281 5 50-280 5 50-280 5 50-280 8 50-280 8
MENDERLICH R L MENDERLICH R L MENDERLICH R L MELLES B A	621-020171 921-0260392* 921-01-0226* 921-01-30558* 921-0280247*	50-341 S 50-341 Q 50-318 S 50-317 S 50-317 S	WILCOVE, N N WILCOVE, N N WILCOVE, N N WILCOVE, N N WILCOVE, D	8210150484 8210200051 8210240344 8210240388 8210130328#	50-320 0 50-329 0 50-329 0 50-329 0 50-254 E	WILSON, J L WILSON, J L WILSON, J L WILSON, J L WILSON, J L	8210220392 8210220398* 8210220408* 8210220413* 8210220424	50-280 8 50-280 8 50-280 8 50-280 8 50-281 8
NEINCERLICH R L NEINCEALICH R L NEINCHARKE F NEINCHARMENT A NEINSCHARMENT A	0210280284 6210280313* 6210010240 6210040131* 6210190512*	50-318 S 50-317 S 50-206 S 50-228 Q 50-312 0	WILKINSON, E P WILKINSON, W P WILLETT, B J WILLIAMS, C C WILLIAMS, C C	8210050181* 8208010019* 8210190349* 8210190787* 8210060334*	FOTA DRG 50-397 Q 50-440 Q 50-373 Q	MILSON.J L WILSON.J L WILSON.J L WILSON.J L	8210220435* 8210270212 8210270215* 8210270220* 8210270224*	50-281 5 50-280 8 50-280 5 50-280 5 50-280 5
HEIN-LANER LIF A HEIM-CHIFF A HEIM-SKIFF A HEIM-SLOWERL F A HEIM-SEL A H	6210,20044A 6210,20176# 6210,200,244# 6210,200,246# 6210,210054	50-27 Q 50-362 Q 50-397 Q 50-397 Q Nureg	Williams. C C Williams. C C Williams. C C Williams. D A Williams. D T	8210940393* 8210130374* 8210130557* 8210210944 8208293108	50-315 G 50-341 G 50-461 G NUREG FOIA	WILSON, J L WILSON, J L WILSON, J L WILSON, J L WILSON, K R	9210290264 9210290270* 8210290276* 8210290282* 8210190687*	50-280 S 50-280 S 50-280 S 50-280 S 50-302 S
enjela h Periodar b Periodar h Perioda r Perioda h	6210720154 6210130126# 6203040538# 6210050221 6210050221	NUREG 50-346 S 50-329 G 50-329 G 50-329 G	A C'SWYLTIN A C'SWYLTIN A C'SWYLTIN A C'SWYLTIN	8210010164 8210060209 8210080252 8210130456 8210130552	50-335 8 50-251 8 50-250 8 50-335 8 50-335 9	WILSON, R D WILT, D D WILT, D D WILT, D D WILT, D D	8210200053 8210010250 8210010250 8210010323 8210010323	50-400 0 50-440 0 50-440 0 50-440 0
CET A E RET.A E RET.L J CETLROWN B	8210050250 8210050230 8210070021# 8210120458# 8210040355	50-327 G 50-329 G CONTRACT CONTRACT 40-8768	Williams. J W Williams. J W Williams. P R Williams. R E Williams. R E	8210240114 8210240357 8210180354# 8210120401# 8210120404#	50-250 S 50-335 S FDIA CONTRACT 40-8745	WILT.D D WILT.D D WILT.D D WILT.D D WILT.D D	8210050173 8210050173 8210050228 8210050228 8210050228	50-440 Q 50-440 Q 50-440 Q 50-440 Q 50-440 Q
ESTEROS. H B ESTERING T ESTERINGUT T ESTERINGUT T	8210170479 8210770338 8210050239# 8210070369# 8210170547	40-8786 NURFG 50-267 0 50-445 0 50-267 8	WILLMORE.R L WILLMORE.R L WILLMORE.R L WILLMORE.R L WILLMORE.R L	8210010345 8210010345 8210010457 8210010457 8210050255	50-440 0 50-440 0 50-440 0 50-440 0 50-440 0	WILT, D D	9210050242 9210050252 9210050252 9210250331 9210250331	50-440 Q 50-440 Q 50-440 Q 50-440 Q 50-440 Q
ESTERNALT F ESTERNALT F ESTERNALL F ESTERNALL I ESTERNALL I ESTERNALL I ESTERNALL I	8214194776* 8214194820* 8214284149* 8214294294 8214294294	50-445 Q 50-448 Q 50-267 Q 27-39 50-358 Q	WILLHORE, R L WILLHORE, R L WILLHORE, R L WILLMORE, R L WILLMORE, R L	8210050255 8210070405 8210070405 8210150467 8210150467	50-440	WINKS, R W WINTERHOFF, D WINTERHOFF, D WINTERHOFF, D WIRFS, L	8210010284# 8210130236# 8210250163# 8210260313# 8210070426#	50-329 E 50-373 B 50-373 B 50-373 B FOIA
ITTERMINE II J IALEIL R IALEIL R GELERAL GELERAL	8210270279 8210240127* 8210250314* 8209210550* 8210180214	50-249 8	WILLMORE, R L WILLMORE, R L WILLMORE, R L WILLMORE, R L WILLMORE, R L	6210220309 6210220305 6210220305	50-440 0 50-440 0 50-440 0 50-440 0 50-440 0	WIRFS.L WITHERS.D D WITHERS.D D WITHERS.B D WITHERS.D D	8210070454* 8210010307 8210040163 8210080253* 8210130399	FOIA PR 50-344 P 50-344 O PR
EEWERLL ATE.A J HTE.A J HTE.J W	0210120617 0210220067* 0210270332* 0210270344* 0210270340*	90-416 8 90-322 0	WILLMORE,R L WILLMORE,R L WILLMORE,R L WILLMORE,R L WILLMORE,R L	8210220309 8210220396 8210220396 8210220405* 8210220405*	50-440 Q 50-440 Q 50-440 Q 50-440 Q 50-440 Q	WITHERS.B O WITHERSPOON, J WIZNER.D G WIZNER.D O WIZNER,D O	8210220301 8210130315# 8210170277# 8210170287# 8210170415#	PR 50-537 A 50-315 B 50-315 B 50-315 B
ITE.R L ITE.R B ITENER.H L ITENER.H L ITENEY.O O	8206170006# 8210050418 8210010459# 8210220147# 8210040105#	Nureo 90~369 0 90~324 0	WILLHORE.R L WILLHORE.R L WILLHORE.R L WILLHORE.R L WILLHORE.R L	8210280231 8210280231 8210280246 8210280246 8210290287	50-440 G 50-440 G 50-440 G 50-440 G 50-440 G	WIZNER,D G MOJEMDUSKI,A V MOJNAS,E J MOLF,J F WOLF,J F	8210190795* 8210060260* 8210210142* 8210270176 8210280245	50-316 8 50-263 9 50-304 0 50-320 0 50-275 0
itney.o c itney.o c itney.o o itney.o o	8210060030> 8210070247> 8210070346> 8210130479> 8210170237	* 50-273 B * 50-273 B	WILLMORE, R E WILLSEY, W B WELLSEY, W B WILSON, A K WILSON, B A	8210270287 8210050320 8210150356 8207050075 8210260065	50-440 Q 50-277 P 50-277 R FOIA 50-413 V	WOLF.TR WOLF.TR WOLF.TR WOLF.TR WOLF.TR	8203120103* 8206220591* 8207120140* 8209150162* 8209150164	50-331 9 50-324 P 50-324 P 50-325 P 50-324 8
THEY.CO THEY.CO TIEN.JE TWORTH F RIOM 8 D	02102801314 8210280150 92102201714 8210130074 8210080276	* 50-293 B * 40-2259 * CONTRACT	MITEON'S D MITEON'S D MITEON'S D MITEON'S D	8210080113 8210080131 821026057(8210270281 8210050071	XFORTL1C	MOTETH	82101303 6 6*	50~346 A
HMATE, K R HUER, R P BE, J DEMAN, D G DEMAN, D G	8007310117 8210210034 8210070245 8210080273 8210080279	70-2789	MIT20N·7 F MIT20N·7 F MIT20N·7 F MIT20N·7 F	821005007/ 8210050076 8210050081 8210050086 8210050091				
DEMAN, D O DEMAN, D O DEMAN, D O DEMAN, D O DEMAN, A N	8210150507 8210190673 8210250190 8210260402 8210150557	[&E 70-2650 70-1257	WILSON, J L WILSON, J L WILSON, J L WILSON, J L	8210050092 8210050103 8210050109 8210060361 8210060372				

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJEC CATEGO	RY	AUTHOR	ACCESS LON NUMBER	SUB ECT CATEG P
WOLLETT, S WOLLETT, S WOLLETT, S	8210130587 8210190076 8210260278	CONTRACT	YATES,K R YODER,O L YORK,F S	8210120102 8210150567 8210010223	NUREG NUREG PR		ZIMMERMAN, J V ZIMMERMAN, J V	921013004 8400E101SB	મદાખાડા સાલ્યાલ
HOLLETT, S	8210270027 8210270373	CONTRACT	YORK, J W	8210010203 8210010305	4 50-438	0 0	Z IMMERMAN, J. V Z IMMERMAN, J. V Z IMMERMAN, J. V	6210130070 6210260043 6210260523	71 787L[{ 1809TL]: 1819TL]:
WOLLEVER.E J WOLTNER.E WOLTNER.E F	8210240143 8210290107 8210210238	• 50-220 Q • 50-271 Q	YORK, J H YOUNG, F YOUNG, G G	82100103144 82101500914 82100100674	50-287	0	ZIMHERMAN, J V ZIMMERMAN, J V ZIMMERMAN, J V	8210260541 8210260577 8210260574	aProdicit aprodicit arteglis
MODVE C	8210250019 8210250019 8210210015	40-299 40-299	YOUNG, M A	8210040016 8210280060	50-460 50-244	G G	ZIMMERMAN, J V ZIMMERMAN, J V	051059940 0510599401	AFEIRTLE APORTLE
MOOD'E C MOOD'E C	8210210015 8210260193 8210260199 8210270165	50-309 8 50-309 5 50-309 8 50-309 5	YOUNG, T YOUNG, T YOUNG, T	8210060336+ 8210060345+ 8210250138	50-528 50-312	0 0 5	ZIMMERMAN, J. V ZIMMERMAN, J. V ZIMMERMAN, J. V	02102740001 02102740003 02102740005	af (mil) af úsflít hliofit (t
HOODHEAD, C P	8210040082 8210120261	50-341 G 50-142 G	YOUNG, T YOUNG, T	82102503614 82102503754	50-528	Q Q	ZIMMERMAN, J. V. ZIMMERMAN, J. V.	8510530108 8510530053	प्रशासीय स्थापिक
WOODQUFF.R L WOODQUFF.R L WOODQUFF.R L	8210010048 8210010100 8210010154	State Prog State Prog State Prog	YOUNG, T YOUNG, Y A YOUNGBLOOD, B J	8210280372* 8210040348 8210040285*	40-8793 50-338	Q P	Z IMMERNAN, J. V Z IMMERNAN, J. V Z IMMERNAN, J. V	8210270122 8210270127 8210270147	#4*1+971 }
WOODS.H W	8210010358 8101070276s	State Prog	ADDINGBEDOD'B 1 ADDINGBEDOD'B 1	8210040307* 8210040320*	50-338 50-338	P P	ZIMMERMAN, J. V. ZIMMERMAN, J. V.	8210/70156 8210/70101	ar eath to arrest to
WOOLEVER,E J WOOLEVER.E J WOOLEVER.E J	8210070155 8210070233 8210260135	50-412 S 50-412 S 50-412 S	AONAGBEODO'B 1 AONAGBEODO'B 1 AGNAGBEODO'B 1	8210040370 8210040373 8210040377	50~483 50~482 50~341	A F A	Z HMERHAN, J. V Z HMERMAN, J. V Z HMERMAN, J. V	6210270274 6210270276 6310270276	AF O TAL DI A PONTLITO A TIMITA I
WOOLSEY,R T	8210120619 8210120624*	40-8781 40-8781	YOUNGBLOOD, B J	8210120341 8210120344 8210120348	50-424 50-358	٨	ZIMMERHAN, J. V ZIMMERHAN, J. V	821027029h	A FALLET LAC
WOZNIAK, D R WRAY, J R	8210210515 8210080319 8210070345*	40-8084 XPORTLIC 50-219 G	YOUNGBLOOD, B J YOUNGBLOOD, B J YOUNGBLOOD, B J	8210210288 8210280420 8210280429	50-546 50-387 50-454 50-454	A A	Z IMMERMAN, J. V. Z IMMERMAN, J. V. Z IMMERMAN, J. V.	8210270206 8210270207 8210270298	A PERMITALES PERMITALES REPORTALES
RAY,JR RAY,JR RAY,R	8210080179 8210150358*	70-143 50-335 Q	YOUNGBLOOD, B J	8210290115	50-546 50-387	A A	ZIMMERMAN, J V ZIMMERMAN, J V	8210270314 8210270431	KITCHAFLEC KATHAFLE
WRIGHT, E G WRIGHT, E G WRIGHT, G	8210250210 8210180145* 8210180433*	50-275 P F01A F01A	YOUNGBLOOD, B J YOUNGBLOOD, B J YUHAS, G	8210290128* 8210290363 8210010260	50-397 50-454 50-206	P F S	ZIMMERMAN, J V ZIMMERMAN, J V ZIMMERMAN, J V	0210270446 02102090 35 02102900 36	XTORILIC XI LISTLIC
WRIGHT, N A	8210250116* 8210040018 8210080062	50-373 Q 50-329 Q 50-329 Q	YUHAS, G P YUNDT, C P	8210280248* 8210190026*	50-397 50-344	Q F	ZIMMERMAN, J V ZIMMERMAN, J V	6210280040 6210290409	X6,814.15.11 X6,814.15.11
WRIGHT, R J WRIGHT, R J WRIGHT, R J	8210260033 8210120138 8210120178	50-329 G 50-440 G Waste mgt Waste mgt	YUNDTIC P YUNDTIC P ZARBIS,W A ZEBROSXIIE Ł	9210250084 8210250164 9210250074* 9201190041*	50-344 50-344 50-260 FOIA	5 8 P	7 IMMERMAN, J V 2 IMMERMAN, J V 2 IMMERMAN, J V 2 IMMERMAN, R P 7 IMMERMAN, B R	0210280414 0210280410 0210280422 02102901715 0210050315	M (ATE) M (ATE) M (ATE) M (ATE) M (ATE)
WRIGHT, R J WRIGHT, R J WRIGHT, R W WRIGHT, R W WRIGHT, R W	8210120325 8210120358 8210120359 8210010143*	WASTE MGT WASTE MGT WASTE HGT 50-413 Q	ZECH, G ZECH, G ZIBULSYY, H ZIBULSKY, H	8210120186* 8210120194* 8210220179* 8210220244*	50~3 FDIA 70~371 70~687	P	7 IMMERMANI G R 2 IMMERMANI G R 7 IMMERMANI G R	8210050349 8210120549 8210120649	50 /24 F 50 /61 F 50 /61 F #P##TUTC
WUDZKI, J J WULLER, G E	8210220145* 8210120541* 8209290072	50-400 Q CONTRACT	ZIELENBACH, W R	8510150105 8510150065	NUREG		ZIMMERMAN, S R	881013035J	30 241 W
HULLER, C E HULLER, C E HULLER, C E	8210050278 8210050281	50-461 A 50-461 A 50-461 E 50-461 E	ZIMMERMAN, J V ZIMMERHAN, J V ZIMMERMAN, J V ZIMMERMAN, J V	8210070433 8210070439 8210070443 8210080045	XPORTLIC XPORTLIC XPORTLIC XPORTLIC		ZIMMERNAN, 8 R ZIMMERMAN, 8 R ZIMMERNAN, 6 R ZIMMERNAN, 6 R ZIMMERNAN, 6 R	82101900 IO 8210190190 8210190264 8210250202	50 241 1 50 241 1 50 241 1
WULLER, G E WULLER, O E WULLER, O E WULLER, G E	8210050289 8210130181 8210130270	50-461 E 50-461 Q PR	ZIMMERMAN. J V ZIMMERMAN. J V ZIMMERMAN. J V	8210080138 8210080143 8210080149	XPORTLIC XPORTLIC		ZIMMERMAN, G R ZIMMERMAN, S R	0210280054 8210280275 8210290356	50 4co (50-324 F 50 261 F
WULLER, O E	8210130379 8210130490 8210150357	PR 50-461 A 50-461 A	ZIMMERMAN, J V ZIMMERMAN, J V	8210080153 8210080157	XPORTLIC XPORTLIC XPORTLIC		ZIRWAB, K R ZUDANS, Z ZUDANS, Z	8210150049# 8208290026 8208290026	50 217 S ACRS ACRS
WULLER.G E WULLER.G E WYATT.J H WYSOGKI.J YANDELL.L A	8210260003 8210280089 8210010381 8210150552	70-2946 50-461 A PR NUREQ	ZIMMERMAN, J V ZIMMERMAN, J V ZIMMERMAN, J V ZIMMERMAN, J V ZIMMERMAN, J V	8210080162 8210080334 8210080343 8210080345 8210080348	XPORTLIC XPORTLIC XPORTLIC XPORTLIC XPORTLIC		ZUDANB, Z ZUDANB, Z ZUDANB, Z ZUFELT, E ZUKOR, D	9210100390+ 92102/0398 9210270398 9210200024+	COMIRACI 50 341 (50-341) 50 333 4
YANICHKO.S E YARNICK, I P YARNICK, I P YATES, K R	8210170539* 8210170429* 8210260557 8210270175 8210120072	50-285 Q 50-282 P 40-8102 40-8102 NUREQ	ZIMMERMAN, J V ZIMMERMAN, J V ZIMMERMAN, J V ZIMMERMAN, J V ZIMMERMAN, J V	8210120117 8210120511 8210120517 8210120055 8210130059	XPORTLIC XPORTLIC XPORTLIC XPORTLIC XPORTLIC		ZUMMO, J ZUPKO, J M ZUPKO, J M ZURKAOWSKI, P R ZWETZIQ, O B ZWETZIQ, O B	0203090669+ B210290240 0210290245 0210080311+ 0210060141+ 0210060299+	PR 50-272 F 70-754 50-275 2 50-275 2
							ZWIEQ, A	82101505364	QA959

Q. A 82101505364 QA959

The subject category column in this index gives the docket number and the symbol for the category of information within that docket; for example, 50-320 P. The docket subject categories are defined in Appendix A.

Subject categories for nondocketed items are also entered in this column by symbol; for example, ACRS. These categories are defined in Appendix B and listed in the Contents. An asterisk following the accession number in this index indicates that the document is an enclosure to another document. To obtain the accession number of the principal document under which the enclosure is listed, refer to the Index entitled "Cross Reference of Enclosures to Principal Documents,"

AUTHUR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGOR	Y	AUTHOR AFF [L]AT] ON	ACCESSION NUMBER	SUBJECT CATEGOR	ΙΥ
AMAK, Inc ATHesearch Associates, Inc Arnodts, The	6210060033 6210060035# 6210250035 6210250557 6210050192	XPORTLIC XPORTLIC 40-8820 NUREG 50-289		Alden Research Laboratory Allied Chemical Corp American Electric Power Service Corp	8210080022* 8210050388 8210130287* 9210150500 8210070286*	CONTRACT NUREG 50-389 40-3392 50-315	
	8210210359 8210260400	50-289 50-289	G O	American Deophysical Union American Institute of Aeronautics &	8210190002* 8210120432*	CONTRACT CONTRACT	
Aerojet Energy Conversion Co. (subs. of General Tire & Rubber Co.)	8210060255 8210060257* 8210060259*	TOPREP TOPREP TOPREP		Astronautics American Nuclear Insurers	8210010307 8210040275 8210290255	PR TOPREP PR	
Air Force, Dept of Age Force, Dept of, Radiousotope Committee	8210070459* 8210270179 8210270182*	CONTRACT 40-8577 40-8577		American Nuclear Society	821001021B 8210010232 8210220379	PR PR PR	
Alebana Power Co	8510010154 8510010154	50-348 50-348	8	Amerisham Corp	8510080535* 8510580535*	71-9167 71-9167	
	8210010139* 8210010147* 8210010195	50-348 50-348 50-348	9 9 F	Anaheim, CA Andrulis Research Carp	8210080237* 8210250356 8210270221*	71-9167 PROJ CONTRACT	
	8210010125 8210010226	50-348 FR	Ŀ	Antioch College of Law	8210270223* 8210150341	CONTRACT 50-155	
	8210050066 8210050069 8210080294 8210130270	50-364 50-364 TOPREP PR	P P	Appling County, QA Argonne National Laboratory	8210210381 8210120425* 8208290019 821	50-155 CONTRACT	, G
	8210130527 8210150074*	50-364 50-348	p O	Arizona Public Service Co	€2 ′		
	8210150338 8210150344* 8210190073*	50-364 50-364 50-348	۵ ا				
	8210190073*	50-348	F				
	8210190609 8210190614* 8210190722 8210190723*	50-348 50-348 50-348 50-348	8 B R				
	8210190767 8210190773*	50-364 50-364	R R		84100.40419	50-528	ß
	8210250090 8210260418 8210260437 8210260453	50-364 50-364 50-364 50-368	5 6 8		8210070219 8210070229 8210070229 8210070229	50-530 50-528 50-528 50-528	888
	8210240453 8210260463#	50-348 50-348	9		0210070320 0210070320 0210070320	50-528 50-528 50-528	S S
	8210260470* 8210260480* 8210260490*	50-348 50-348 50-348	6 8		8210070321 8210070339	50~528 50~528	g
	8210280158 8210280158 8210280165* 8210280165* 8210280282	50-348 50-348 50-348 50-348 50-364	р р Р		8210070339 8210070339 8210070354 8210070374 8210070391	50-528 50-528 50-528 50-528 50-529	8 8 8 8
Jahares Univ of.	8210290289 8210290292* 8210070355* 8210070358*	50-364 50-364 50-438 50-438	9 8 A	•	8210080155 8210130187 8210130394 8210130443	50-528 50-528 PR 50-528	0 8
		20-450	.,				_

AUTHOR AFF IL I AYION	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR AFF ILIAT (ON	ACCESSION NUMBER	SUBJECT CATEGORY
	8210130444 8210130491 8210130495 8210130544 8210130544	50-530 S 50-530 S 50-529 S 50-529 S 50-529 S	BHR Owners Group Babcoct & Hilcox Co	8210270253 8210050053 8210250181 8210250184 * 8207070007	PR TOPREP TOPREP TOPREP TOPREP
	8210150163 8210150176* 8210150315 8210150463 8210150717	50-528 A 50-528 A 50-528 E 50-528 A 50-528 A		8210010284* 8210060346 8210120304* 8210120315* 8210130308*	50-329 E TOPREP GA999 GA999 70-135
	8210190717 8210220394 8210250100 8210250305 8210250326	50-528 A 50-528 B 50-528 S 50-528 S 50-528 S	Backus, R A	8210220231 8210220497 8210250132 8210270232 8210040194	70-824 70-27 PT21 70-27 50-443 G
	8210240275 8210240543 8210270211 8210280057 8210280057	50-528 S 70-2949 50-528 A 50-528 A 50-528 A	Baltimore Oas & Electric Co	8210040194 8210040204* 8210040204* 8210040064 8210040069*	50-443 C 50-443 C 50-443 Q 50-318 '1 50-316 S
	8210280057 8210260139 8210280139 8210280139 8210280199	50-528 A 50-528 A 50-528 A 50-528 A 50-528 A		8210040142 8210040144* 8210040211 8210040214 8210040219*	50-317 G 50-317 G 50-318 G 50-318 G
Arizona State Univ Arizona, Univ of	8210280199 8210280199 8210280274 8210150431 8210050508#	50-528 A 50-528 A 50-528 E RES CONTRACT		8210040226* 8210060395 8210060390* 8210060394* 8210070159	50-318 8 50-317 9 50-317 9 50-317 9
Arkansas Power & Light Co	8210210066# 8210040109 8210040111# 8210050346 8210070395	CONTRACT 50-313 F 50-313 P 50-368 S 50-313 F		8210130103* 8210130338 8210130338 8210130342* 8210130342*	50-317 P 50-317 P 50-317 P 50-317 P 50-317 P
	8210070395 8210120247* 8210120252* 8210130212 8210130214*	50-313 F 50-313 0 50-313 0 50-313 8 50-313 8		8210130391 8210130461 8210130465* 8210130543 8210130558*	PR 50-317 5 50-317 5 50-317 5
	8210130382 8210130388* 8210130407 8210130513 8210130522*	50-313 9 50-313 8 50-368 P 50-313 8 50-313 8		8210130548 8210130578* 8210150423 8210180005 8210180039	50-317 5 50-317 6 50-317 F 50-317 F 50-318 0
	8210150002 8210150073 8210150073 8210150474 8210190517	50-313 P 50-313 F 50-313 F 90-313 P 50-313 S		8210180124 8210190290 8210190296* 8210190730 8210190803*	50-317 P 50-317 S 50-317 S 50-317 S
	8210170526* 8210170545 8210170558* 8210220114 8210250159	50-313 B 50-368 B 50-369 9 50-313 P 50-368 P		8210190803# 8210210328 8210210328 8210210457# 8210210457#	50-317 0 50-317 P 50-317 R 50-317 R 50-317 R
	821 0250161 * 821 0250206 821 0250292 821 0250298 * 821 0240120	50-368 P 50-313 P 50-368 S 50-368 S 50-368 S		8210210546* 8210210546* 8210210551* 8210210551* 8210220378	50-317 F 50-317 F 50-317 F 50-317 F 50-318 P
	8210240123* 8210240180* 8210240192 8210270101 8210280112*	50-368 8 50-313 Q 50-313 P 50-348 P 50-313 F		8210220385* 8210250088 8210250075* 8210250154 8210250160*	50-318 P 50-318 S 50-318 S 50-317 S 50-317 S
Armed Forces Radiobiological Research Institute	6210280112* 6210280114* 6210290240 6210260425	50-313 F 50-313 F PR 50-170 G		82;0240279 82;0270237 82;027024;* 82;0270244 82;0270248*	50-318 P 50-318 S 50-318 S 50-317 S
Army,Dept of, Headquarters Materiel Development & Readiness Command	8210270227*	40-8632 40-8632		8210270252 8210270257* 8210270266	50-317 9 50-317 S 50-317 S
Army.Dept of Army.Dept of, Corps of Engineers Aspects, Inc Associated Technologies, Inc	6210190105# 8210120471# 8210190147# 8210220226	CONTRACT CONTRACT CONTRACT PR		8210270269* 8210270272 8210270273*	50-317 S 50-317 S
Atlas Minerals	8210150596 8210260079 8210260080*	40-3453 40-3453 40-3453		8210270274 8210270275* 8210270276 8210270278*	50-317 S 50-317 S 50-317 S 50-317 S
Atom Sciences, Inc. Atomic Industrial Forum	82101 20440* 82060 600 13* 82092 70379* 82101 30280 82102 70242	Contract Commission Commission PRM PR		8210270279 8210270280* 8210280134 8210280141* 8210280191	50-217 S 50-317 B 50-318 S 50-318 S 50-318 S

AUTHOR	ACCE SSIGN	SUBJEC		AUTHOR	ACCE55ION	EUD MAI	
AFF (LIATION	NUM BER 8210280194	CATEGO 50-318		AFF ILIATION	NUMBER	CATEGOR	
	8210260195* 8210260200* 8210260203 8210260205*	50-318 50-318 50-317 50-317	ា ជ ជ ជ ជ ជ		8210050166 8210060023 8210060030# 8210060085#	50-293 50-293 50-293 50-293 50-293	0 5 P P
	8210280249 8210280255* 8210280263 8210280267* 8210280279	50-317 50-317 50-317 50-317 50-318	ង ស ស ស ស ស		8210060164* 8210060180* 8210070245 8210070247* 8210070340	50-293 50-293 50-293 50-293 50-293	0 0 9 8
	0210280264* 6210280294 6210280301* 6210280305 6210280313*	50-318 50-317 50-317 50-317 50-317	ន ន ន ន ទ		8210070345* 8210130479 8210130479* 8210130479* 8210150444	50-273 PR 50-273 50-273 50-273	8 8 8
Cattelle Memorial Institute, Columbus Laboratories	8210280318 8210280332* 8210280334 8210280341* 8210180592	50-317 50-317 50-318 50-318 NUREO	9 9 9		8210190235 8210190237≯ 8210190721 8210250085 8210250122	50-293 50-293 50-293 50-293 71-6346	8 8 9
jitelle Memorial Institute, Pacific Northwesk Laboratory	8210190087* 8210190420* 8210190428* 8210210014 8209140027*	CONTRAC 50-333 50-333 NUREO 50-244	T G Q P	Boston State College	8210280129 8210280131 * 8210280146 8210280150 * 8210150350 *	50-293 50-293 50-293 50-293 CONTRACT	9 8 8 8
WILLIAMS CONTROLLY	8209210523* 8210050418 8210070254* 8210070315*	50~309 NUREQ 50~537 50~537	P A D	Brookhaven National Laboratory	9207180066 9210070449 9210120367 9210120390 8210120495	ACRS RES RES RES RES	
	8210070318* 8210070323* 8210070327* 8210070332* 6210070335*	50-537 50-537 50-537 50-537 50-537	D D D D		8210120459 8210120460 8210120466 8210120630 8210120642*	RES RES RES RES 50-341	A
	8210070347# 8210070465# 8210080009# 8210080382 8210120092	50-537 50-537 CONTRACT RES NUREG	p r	Dryant & Bryant AIA Burns & Roe Co Bursey, D	8210120649 8210220135 8210210444* 8210040173* 8210150458	RES NUREG CONTRACT GA999 50-395	G
	B210120102 B210120125 B210150553 B210220149 B210270041 w	NUREO NUREO NUREO NUREO 50-537	0	C⊣E Operating Plants Dumors Group C Itoh & Co (America), Inc Cabot Gorp California, State of	8210040323 8210080324 8210080339 8210050180 8210290097	TOPREP XPORTLIC XPORTLIC 50-275 50-275	Q P
ar Crent Uranium Co chtel Corp	6210270421 6210290041 # 6210150644 6210050246 6210060241 #	RES 50-285 40-8452 50-329 50-155	p R P	Calitornia, Univ of, Berkelay	8107270146# 8107270149# 8107270174# 8107270176# 8107270178#	50-266 50-266 50-266 50-266	G G G
	8210130805* 8210150373* 8210190470 8210190470 8210220285	50-329 50-424 50-275 50-275 PR	T A P P		8107270182* 8107270182* 8107270185* 8107270185* 8107270188*	50-266 50-266 50-266	0 0 0 0
uviordyne Paychological Corp uinger, DuPont & Associates, Inc	8210260504 8210270351 8210270351 8210130399 8210130399	50-329 50-275 50-275 PR PR	T P P		8107270191* 8107270194* 8107270196* 8107270198* 8107270199*	50-266	0 0 0 0
eridge, Fairbanks, & Diamond choff, C A	8210240347 8210240347 8210240373 8210240373 8210130417	50-338 50-338 50-338 50-338 50-528	0 0 0	California, Univ of, Los Angeles	8210150456 8210200081 8210250076 8210250073* 8210250051*	50-142 50-142 50-142	9 9 9 F
hap, i. t.	8210270171 8210070132 8210070132 8210070136 8210070136	50-528 50-329 50-329 50-329 50-329	0 6 6	Caivert County, MD Cammer & Shapfro Carolina Environmental Study Group Carolina Power & Light Co	8210180371* 8210150234 8210260150 8209140148 8209140153*	50-413 50-324	0 0 1 F
ing Computer Services, Inc. (subs. of ling Co.) -Warner Corp	8210070140 8210260561* 8210150517*	50-329 CONTRACT GA999	Q		8209160299 8209160311* 8210010028 8210010183* 8210010188*	50-325 50-241 50-324	8 8 H Q
on Callege on Edison Co	82101 50526* 82102 70372* 82102 70372* 82101 80362* 82041 60212	QA799 XPORTLIC XPORTLIC CONTRACT 50-293	o.		8210010298 8210010303* 8210010360* 8210010399* 8210010473	50-324 50-400 50-324	8 8 0 0 8
	82041 60222* 82041 60225* 82071 80064 82100 40100 82100 40105*	50-273 50-293 FOIA 50-293 50-293	6 6 8 8		8210010475# 8210050009 8210050106 8210050106 8210050125	50-261 50-400 50-400	8 4 4 4

CUMPURATE SOURCE INDEX

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT		AUTHOR AFF ILIATION	ACCESSION NUMBER	SUBJECT	
1- 1-11-1-11-11-11-11-11-11-11-11-11-11-	8210050125 8210050362 8210050362 8210050371* 8210050371*	50-400 50-324 50-324 50-324 50-324	A P P P		8210220409 8210220412 8210220412 8210220484 8210220492*	PR 50-400 50-400 50-400 50-324	5 5 7 0
	8210060013 8210060016* 8210060316 8210060320	50-261 50-261 50-324 50-324 50-324	5 5 6 6 7 8		8210220499* 8210250202 8210260244 8210260244 8210260256	50-261 50-261 50-324 50-324 50-325	6 to 6
	8210060323# 8210060323# 8210060327# 8210060349 8210080180	50-324 50-324 50-324 50-261 50-400	F F 9 P 9		8210260264* 8210260269 8210260294 8210260318* 8210260323	50-325 50-324 50-325 50-324 50-324	45 65 55
	8210080180 8210080183* 8210080220 8210080220	50-400 50-325 50-325 50-325 50-324	1) S S S S		8210260323 8210260325* 8210260325* 8210260344 8210260368*	50-324 50-324 50-324 50-325 50-325	ម ម ម ម
	8210080230* 8210080283 8210120645* 8210120647* 8210130242	50-324 50-400 50-241 50-241 50-241	8 5 F R		8210260398 8210260398 8210260403 8210260405 8210260410*	50-400 50-400 50-324 50-324 50-324	8 8 8 8
	8210130244* 8210130295 8210130295 8210130323 8210130323	50-261 50-324 50-324 50-261 50-261	л Г Н Н		8210260410* 8210260462 8210260475 8210260482* 8210260508	50-324 50-400 50-261 50-261 50-261	4 6 6
	8210130323 8210130323 8210130477 8210130483* 8210130489	50-261 50-261 50-325 50-325 50-325	11 15 15 15		8210260511* 8210280054 8210280275 8210280275 8210280278*	50-241 50-400 50-324 50-324 50-324	P C C C
	8210130497* 8210130539 8210130550* 8210130567 8210130016*	50-325 PR PR 50-400 50-324	ម ទ 0		8210280278* 8210290074 8210290078* 8210290079 8210290099*	50-324 50-261 50-261 50-324 50-324	10000
	8210150023* 8210150030 8210150038* 8210150041 8210150045*	50-324 50-324 50-324 50-324 50-324	Q Q		8210290243 8210290246* 8210290258 8210290258 8210290258	50-324 50-324 50-400 50-400 50-400	59559
	8210150046* 8210150106* 8210150198 8210150264 8210150291	50-324 50-324 50-261 50-261 50-324	9 0 P r 8		8210290325 8210290331* 8210290333 8210290336 8210290339*	50-325 50-325 50-261 50-324 50-261	9 6 6 6
		50-324 50-400 50-324 50-155 50-400	a e e e e e e e e e e e e e e e e e e e	Garpenter Technology Corp	8210270342* 8210270346 8210270352* 8210270358 8210080317	50-324 50-325 50-325 50-261 XPORTLIC	S S S
			8 8 8 8 8 8	Center for Law in the Public Interest Gerec, Inc Chapel Hill Anti-Nuclear Group Effort	8210080320* 8210050218 8210220517 8210270281 8210010328	XPORTLIC 50-275 XPORTLIC XPORTLIC 50-400	C
				Gharlevoix, MI Ghattanooga, TN	8210010337 8210150340 8210210417 8210190215* 8210240520*	50-400 50-400 50-400 CONTRACT CONTRACT	
	8210200009	50-400	<u> </u>	Chem-Nuclear Bystems: Inc Cherry, M. M./Cherry, Flynn & Kanter	8210280388 8210070127 8210070127 8210070127*	71-6601 50-454 50-454 50-454	G G
	8210200013* 8210200013* 8210200021* 8210200021* 8210200032 8210200032	50-400 50-400 50-400 50-400 50-400	0 0 0 C		8210070129* 8210180151 8210210278 8210210278 6210210384 8210210384	50-454 50-454 50-454 50-454 50-454 50-454	0 00000
	8210200084 8210200084 8210200086* 8210200086* 8210220075	50-400 50-400 50-400 50-400 50-400	C C C		8210250071 8210260380 8210260380 8210260384* 8210260384*	50-454 50-454 50-454 50-454 50-454	0 0 0
	8210220075 8210220132* 8210220265 8210220267* 8210220265	50-400 50-400 50-261 50-261 PR	8 0 9	Chicago, Univ of Christa-Maria	8210270273 8210270305 8210170063* 8210150341 9210210381	50-454 50-454 CDNTRACT 50-155 50-155	0

	AUTHOR AFF (LIATION	ACCESSION NUMBER	SUBJEC		AUTHOR AFF IL LATION	ACCESSION		
11 12 12 13 13 13 13 13		8210050137 8210050332 8210050334* 8210060271 8210060309	50~358 50-358 50-258	K K S		8210260419 8210280231 8210280246	50-44(50-44(50-44(50-44(0 A 0 A 0 G
Calculation		8210070402 8210130294 8210130297* 8210130372	50~358 50~358 50~358	Ø A	Gobe Laboratories, Inc Colorado State Univ Colorado, State ne	8210050389 6207180039 8210150223 8210120379	50-522 FOIA 50~322 WASTE	2 G
11 12 13 14 15 15 15 15 15 15 15		8210150443 8210180154 8210260279 8210260488	50-358 50-358 50-358	8	Columbia Univ Combustion Engineering, Inc	8210270307 8210040327 8210120397 8210130504	50-208 F TOPREP RES 70-110	20
Electric File	tizens Association for Sound Energy	8210290285# 8210290290* 8210290299 8210150224	50-358 50-358 50-358 50-445	() () ()		8210150313* 8210150319* 8210180133* 8210170004*	50-470 50-470 50-317 CONTRA	E E F CT
Section Sect	tisens for Nuclear Reactor Sefety, Inc	8210280355 8210150200 8210150317 8210150395	50-445 50-170 50-170	G H G	Commerce.Dept of. National Bureau of Standards	8210220440 8210280202 8210290240	70-1100 50-470 PR	O B
Section Sect	weland Electric [[]]uminating Co	8210220439 8210220448* 8210280220 8210010345	50-170 50-170 50-170 50-440	6 6 0	Commonwealth Edison Co	8210130160 8210130163* 8209290189* 8209290225*	50-184 50-184 50-10	R R F
BE10051030		8210010457 8210010457 8210040146 8210040146	50-440 50-440 50-440 50-440	0 K K		8210010009 8210010009 8210010202 8210010202	50-237 50-237 50-454 50-454	۲ ۲ ۲
6210050374 50-440 0 8210010271 30-444 A 8210010271 30-444 A 8210010271 30-444 A 8210010271 30-440 C 8210010271 30-440 A 8210010271 30-440 B 821001		8210040150* 8210050132 8210050255 8210050255	50-440 50-440 50-440 50-440	K G G		8210010202 8210010202 8210010271 8210010271	50-454 50-454 50-454 50-454	E A A
G2101 30179		8210050374 8210070405 8210130173 8210130173	50-440 50-440 50-440 50-440	6		8210010271 8210010271 8210010381 8210040040	50-454 50-454 PR 50-454	A A K
G210150228		8210130179 8210130364 8210130364 8210150161	50-440 50-440 50-440 50-440	0 0		8210040116 8210040121* 8210040126 8210040129*	50-304 50-304 50-249 50-249	8 8 8
S210190326 50-440 A		8210150228 8210150233 8210150447 8210180155	50-440 50-440 50-440 50-440	0 0		8210040134# 8210040188 8210040189# 8210040218	50-373 50-237 50-237 50-295	8 8 8
8210190683		8210190326 8210190326 8210190333 8210190333	50-440 50-440 50-440 50-440	A E		8210040221 8210040223* 8210040223* 8210040246*	50-373 50-373 50-373 50-456	ь Ь
8210220305 50-440 0 8210220305 50-440 0 8210220307 50-440 0 8210220309 50-440 0 8210220309 PR 8210220372 PR 8210220372 PR 8210220375 50-440 0 8210220375 50-440 0 8210220405* 50-440 0 8210220405* 50-440 0 8210220405* 50-440 0 8210220405* 50-440 0 8210220405* 50-440 0 8210220405* 50-440 0 8210220405* 50-440 0 8210220405* 50-440 0 8210220405* 50-440 0 8210220405* 50-440 0 8210206027 50-440 0 8210206027 50-440 0 8210206026 50-304 8 8210206027 70-2768 8210250372 50-440 0 821026007 70-2768 8210260037* 50-440 0 8210060367* 50-237 0 8210260037* 50-440 0 8210060367* 50-237 0 8210260037* 50-440 0 8210060367* 50-237 0 8210260037* 50-440 0 8210060367* 50-237 0 8210260037* 50-440 0 8210060367* 50-237 0 8210060367* 50-237 0		8210190683 8210210079 8210210284	50-440 50-440 50-440	E A Q		8210050054+	F. 1	
B210220372 PR B210220374 50-440 0 B210220374 50-440 0 B210220375 50-440 0 B210220405* 50-440 0 B210250297 50-440 0 B210250297 50-440 0 B210250322 50-440 0 B210260325 50-440 0 B210260327 50-440 0 B210260337 50-440 0		8210210353 8210220305 8210220305	50-440 50-440 50-440	0				
8210220405# \$0-440 0 8210250279 50-440 0 8210250279 50-440 0 8210250279 50-440 0 8210250279 50-440 0 8210250279 50-440 0 821026027 50-440 0 821004026# 50-304 8 821004026# 50-373 8 821004026# 50-373 8 821004026# 50-373 8 821004026# 50-373 9 8210240007 70-2948 821024001# 70-2948 821024037* 50-440 0 821004037* 50-237 9 8210240037* 50-440 0 8210040357* 50-237 9 8210240037* 50-440 0 8210040357* 50-234 8		8210220339 8210220372 8210220396	PR PR 50-440	Q				
8210250322 50-440 0 6210060283 50-295 J 8210260007 70-2968 8210060367* 50-237 0 8210260337* 50-440 0 8210060367* 50-237 0 8210260337* 50-440 0 8210060367* 50-237 0		8210220405* 8210250299 8210250299	50-440 50-440 50-440	G G		8210060262 8210060267*	50-304 50-304	8 8
		8210260009 8210260011* 8210260337*	70-2968 70-2968 50-440	a		B210060367* B210060367* B210060395	50-237 50-237 50-237 50-254	8 0 0

. ,

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJEC	RY	THOR IATION	ACCESSION NUMBER	SUBJECT	
	8210080030# 8210080031# 8210080111 8210080111	50-295 50-295 50-295 50-295 50-295	Г F F P		8210190344 8210190346# 8210190403 8210190412# 8210190443	50-373 50-373 50-249 50-249 50-295	5 G G G G
	8210080178 8210080178 8210080178 8210080178 8210080178	50-237 50-237 50-237 50-237 50-237	Q Q Q Q Q		8210190445 8210190445 8210190445 8210190445 8210190445	50-237 50-237 50-237 50-237 50-237	ը թ թ
	8210080178 8210080178 8210120105 8210120105 8210120105	50-237 50-237 50-237 50-237 50-237	ե 		8210190458 8210190462 8210190464 8210190468* 8210190471*	50-249 50-373 50-237 50-373 50-249	ន ទ ទ ទ
	8210120105 8210120551* 8210130192 8210130196* 8210130197	50-237 50-254 50-254 50-254 50-249	P F S S		8210190481* 8210190483 8210190487 8210190493* 8210190494*	50-373 50-295 50-373 50-295 50-373	56556
	8210130200 8210130201* 8210130233 8210130233	50-373 50-249 50-373 50-373 50-373	R S R P P		8210190498 8210190503* 8210190509 8210190514* 8210190522	50-373 50-373 50-373 50-373 50-373	998
	8210130234 8210130236* 8210130241 8210130241 8210130251	50-373 50-373 50-373 50-373 50-254	8 P P		8210190525* 8210190536 8210190565 8210190573* 8210190606	50-373 50-373 50-237 50-373 50-373	9 5 6 6 6
	8210130253* 8210130324 8210130328* 8210130370 8210130370	50-254 50-254 50-254 50-454 50-454	8 9 F		8210170624* 6210170624* 6210170656 6210170662 6210170667	50-275 50-275 50-254 50-456 50-275	9 9 9 9
	8210130373 8210130373 8210130374 8210130374 8210130376	50-454 50-454 50-10 50-10 50-10	E E E		8210190700* 8210190715* 8210190737 8210190744* 8210190780	50-254 50-295 50-373 50-373 50-254	00000
	8210130374 8210130374 8210130374 8210130374 8210130376	50-10 50-10 50-10 50-10	F F F		8210200002 8210200007# 8210220335 8210220356	50-373 50-373 50-247 50-237 50-10	0 0 P F
	8210130374 8210130374 8210130374 8210130374 8210130374	50-10 50-10 50-10 50-10 50-10	F F Γ		8210220358 8210220358 8210220358 8210220358 8210220358	50-10 50-10 50-10 50-10	Г Г Г Г
	8210130376 8210130386 8210130386 8210130390* 8210130390*	50-10 50-254 50-254 50-254 50-254	F R R R		8210220358 8210220383 8210220399 8210250049 8210250049	50-10 PR 50-295 50-237 50-237	F P
	8210130402 8210130413 8210130423# 8210130466 8210130473#	PR 50-254 50-254 50-254 50-254	8 8		8210250049 8210250108 8210250108 8210250108 8210250114	50-237 50-454 50-454 50-454 50-254	t E
	8210130501 8210130511# 8210150044 8210150049# 8210150097	50-254 50-254 50-237 50-237 50-249	8 8 8 8		8210250124# 8210250148 8210250152 8210250153# 8210250155	50-254 50-254 50-373 50-254 50-254	բ 8 8 1
	8210150102* 8210150405 8210150405 8210150411* 8210150411*	50-249 50-295 50-295 50-295 50-295	# # #		8210250155 8210250163* 8210250169* 8210250169* 8210250211	50-254 50-373 50-254 50-254 50-456	Р 9 Р 0
	8210180097 8210180097 8210180097 8210180100* 8210180100*	50-10 50-10 50-10 50-10 50-10	R R R R		8210250211 8210250248 8210250278* 8210250283 8210250274*	50-456 50-237 50-237 50-237 50-237	6 6 5 5 6
	8210180100# 8210180142 8210180142 8210180146* 8210180167	50-10 50-454 50-454 50-454 50-304	R Q Q Q B		8210250304 8210250309 8210250316* 8210250324 8210250324	50-249 50-254 50-249 50-247 50-247	8 G G
	82101 80175* 82101 80194 82101 90030 82101 90038* 82101 90299	50-304 50-10 50-373 50-373 50-456	9 9 8		8210250328 8210250348* 8210260023 8210260115 8210260118*	50-249 50-249 71-9079 50-373 50-373	9

AUTHOR AFF ILIATION	ACCESSION NUMBER	SUBJEC CATEGOR		Author Aff Il 1ation	ACCESSION NUMBER	6UDJEC CATEQO	אַק
	8210240151 8210240151 8210240210 8210240219	50~373 50~373 50~373 50~304 50~373	р 8 8		8210270200 8210270245 8210270249* 8210280071 8210280074*	50-213 50-213 50-213 50-213 50-213	9 9 9
	8210260223* 8210260227 8210260233 8210260238* 8210260254*	50-204 50-273 50-275 50-273 50-275	9 9 9 8	Connecticut, State of Conner & Wetterhahn	8210280397# 8210050197 8210050197 8210050326 8210050382	CONTRAC 50-352 50-352 50-352 50-352	7 0 0 0
	8210260395 8210260308* 8210260311 8210260313*	50~373 50~373 50~454 50~373 50~373	6 9 9 9	Compyer & Associates, Inc. Insurance	8210050382 8210070402 8210200066 8210270299 8210060020	50-352 50-359 50-359 50-359 70-1621	9 9 9
	8210260317 8210260321* 8210260399 8210260411* 8210260485	50-373 50-373 50-295 50-295 50-237	9 9 9	Conservation Council of North Carolina Consolidated Edison Co. of New York	821021034B 8210010401 8210010401 8210010409* 8210010409*	50-400 50-3 50-3 50-3 50-3	е Р Р
	8210260526 8210260526 8210260526 8210260526	50-10 50-10 50-10 50-10 50-10	ն 6 6 6		8210010414* 8210010414* 8210010425* 8210010438* 8210010443*	50-3 50-3 50-3 50-3	ն 6 6
	8210260526 8210260526 8210260526 8210260526 8210260526	50-10 50-10 50-10 50-10 50-10	0 0 10 10 4		8210010449# 8210040141 8210040145# 8210040232 8210060232	50-3 50-247 50-247 50-247 50-247	P 9 5 T 7
	8210260526 8210260526 8210260526 8210260526 8210260542*	50-10 50-10 50-10 50-10 50-10	ր Ե Ե		8210060396 8210060400* 8210070361 8210070366* 8210120253	50-247 50-247 50-247 50-247 50-247	8 8 8 6
	B210260542* B210260542* B210260542* B210260542* B210260542*	50-10 50-10 50-10 50-10 50-10	લ લ ૧ ૧ ૧		8210130277 8210130411 8210130419* 8210130455 8210130559*	PR 50-247 50-247 50-247 50-247	8 9 9
	8210260542* 8210260575* 8210260575* 8210260579* 8210260579*	50-10 50-440 50-440 50-440 50-440	P - - - - -		8210170693 8210280081 8210280081 8210280099 8210280148	50-247 50-247 50-247 50-247 50-247	р 0 0 8
	6210270251 6210270254* 6210260120* 6210260120* 6210260125*	50-249 50-249 50-295 50-295 50-273	G L 8 8		9210250149* 9210260332 9210280154* 9210280154* 9210280159*	50-247 50-247 50-3 50-3 50-3	۵ د د
	8210280126# 8210280126# 8210280364# 8210280364# 8210280375#	50~295 50~295 50~254 50~254 50~254	ቴ ቴ ቴ	Consolidation Coal Co Consumers Power Co	8210290271 8210040214 8207070419 8207070419 8207070422*	50-247 50-10 50-329 50-329 50-329	е К К К
	8210280375# 8210280424# 8210280424# 8210280427# 8210280427#	50-254 50-295 50-295 50-295 50-295	F F F		8207070422# 8207070428# 8207180052 8210010278	50-329 50-329 FDIA 50-329	K K E
	8210280445* 8210280445* 8210280447* 8210280447* 8210290040*	50-295 50-295 50-295 50-295 50-10	f F F F				
tech Engineering Services, Inc., ter Bystems Support Corp	8210290077* 8210290088* 8210290245 8210040178* 8210190010*	50-10 50-10 Pr 50-206 Contract	F F				
eticut Yantes Atomic Power Co	8210170156* 8207300326 8210010207 8210010207 8210010207	CONTRACT 219-06 219-06 219-06 219-06	ሁ የ የ				
	8210010312 8210010312 8210010312 8210010312	50-213 PR 50-213 50-213 50-213	Р Р Р				
	8210050376 8210130331 8210150122 8210150128* 8210190663	50-213 50-213 50-213 50-213	0 P 8 8 P				

AUTHDR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGOR		AUTHOR AFF ILIATION	ACCESSION NUMBER	SUBJECT CATEGORY	
	8210040173 8210040204 8210040213 8210040214* 8210040222	50-329 50-155 50-255 50-255 50-155	0 0 8 5 F		8210280076 8210280107 8210280276 8210290163* 8210290163*	50-327 G 50-255 F 50-255 P 50-329 G 50-329 G	1
	8210040239 8210070013 8210070013 8210070013 8210070014*	50-155 50-155 50-155 50-155 50-155	ն Ն Ե		8210270228 8210270229 8210270227# 8210270240	50-329 A 50-329 A 50-329 A 50-329 A	١.
	8210070014* 8210070018* 8210070018* 8210080082	50-155 50-155 50-155 50-255	P P G	Controls for Environmental Pollution, Inc	8210290380# 8210290380# 8210200104#	50~329 0 50~329 0 70~820	
	82100 80099	50-255	0		8210260041* 8210260049*	70-820 70-820	
	8210080115 8210080115 8210080279 8210120078 8210130005*	50-329 50-329 50-155 50-255 50-329	R R G P	Convai, Inc Cooper Energy Sprvices Cornell Univ Cotter Corp	8210290247 8210120236 8210030412 8210260086 8210260091*	50-247 E PT21 NUREO WASTE MOT WASTE MOT	;
	8210130007* 8210130138 8210130145* 8210130146 8210130156*	50-329 50-255 50-255 50-255 50-255	F R S S	Council on Economic Priorities Creare, Inc Critical Mass Energy Project	8207110023 8210050360 8206040002 8210010006 8210080010	70-1510 NUREQ FOIA FOIA FOIA	
	8210130264 6210130264 6210130265 6210130265 8210130266*	50-329 50-329 50-329 50-329 50-329	K K T T K	D'Appolonia Consulting Engineers, Inc Dairyland Power Cooperative	8210270439* 8210010389 8210010394* 8210040152 8210050067	40-8681 50-409 P 50-409 P 50-409 P	
	8210130267* 8210130267* 8210130334 8210130448 8210130457*	50-329 50-329 50-255 50-155 50-155	К Р С С		8210050070+ 8210050339 8210130365 8210130381 8210130416*	50-409 P 50-409 P 50-409 P PR 50-409 G	-
	8210130471* 8210130482 8210130474 8210130474 8210130505*	50-155 50-329 50-329 50-329 50-329	G T T T		8210150203 8210190446 8210190448 8210190454# 8210190654#	50-409 17 50-409 17 50-409 18 50-409 18	3
	8210130505# 8210130521 8210150146 8210150152# 8210150300	50-329 PR 50-255 50-255 50-155	T ឆ ឆ ទ		8210220009 8210220176 8210250349 8210260319 8210280048*	50-409 (i 50-409 (i 50-409 f 50-409 f	1
	82101 50307* 82101 50470 82101 50533 82101 80186 82101 80191*	50-155 50-155 50-155 50-253 50-255	0 0 r 5 5		8210280051* 8210280053* 8210280055* 8210290151 8210290307	50-407 F 50-407 F 50-407 F 50-407 F	-
	821018 <i>0</i> 20 <i>6</i> 821018 <i>0</i> 212 821018 <i>0</i> 242	50-155 50-329 50-155	G G	Data Design Laboratories DeKalb Area Alliance for Responsible	B210060348# 8210210346	50-209 P 50-454 0	
	82101 90344 82101 90344	50-329 50-329	K K	Energy	8210210344 8210210347*	50-454 0 50-454 0 50-454 0	1
	8210170457 8210170457 8210170520 8210170535 8210170546	50-155 50-155 50-329 50-255 50-255	6 6 8 5 C	Debevoise & Liberman	9210210347* 9208290088 9210040024* 9210050202 9210050208*	FOIA 50-445 G 50-413 G 50-413 G 50-413 G	2
	8210190604 8210190615* 8210190620 8210190628* 8210190639	50~255 50~255 50~255 50~255 50~255	88888	Debevoise & Plimpton Defense,Dept of, Defense Nuclear Apency	8210050208* 8210130279 8210220383 8210040179 8210130528	50-413 G 50-445 G PR 50-348 M	3
	8210190649* 8210200029 8210210294 8210210294 8210220117	50-259 50-155 50-329 50-329 50-155	S G A A P	Del-Aware Unlimited, Inc.	8210010244 8210010244 8210180204 8210180204	50-352 G 50-352 G 50-352 G 50-352 G	3
	8210220186 8210220334 8210220381 8210220381 8210230371	50-255 PR 50-329 50-329 50-155	P 0 0 F		8210180208* 8210180208* 8210180217 8210180217 8210180223	50-352 0 50-352 0 50-352 0 50-352 0	
	8210260121 8210260121 8210260183# 8210260175# 8210260175#	50-329 50-329 50-255 50-329 50-329	8 9 9		8210180223 8210180224 8210180224 8210180226* 8210180226*	50-352 6 50-352 6 50-352 6	3
	8210240314* 8210240504 8210240527 8210280041* 8210280043*	50-155 50-329 50-329 50-255 50-255	Q T T F	Delaware, Univ of Detroit Edison Co	8210180253 8210180253 8210150223* 8210010289	50-352 0 50-352 0 50-322 1 50-341 F	D F

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY		AUTHOR AFF IL I AT I ON	 ACCESSION NUMBER	SUBJECT	
	8210010275* 8210010297* 8210010456 8210040084 8210040127	50-341 50-341 50-341 50-341 50-341	8 8 8		8210070092 8210080208 8210120276 8210130139 8210130177	50-413 50-413 50-329 50-269 50-369	A B A P B
	8210080046 8210130158 8210130282 8210130284 8210150322	50-341 50-341 PR 50-341 50-341	A A F Q		8210130180* 8210130262 8210130262 8210130263* 8210130263*	50-349 50-349 50-349 50-349	8 K K K
	8210180188 8210170332 8210170657 8210170676 8210220414	50-341 50-341 50-341 50-341 50-341	A S S Q A		8210130270 8210130397 8210130467 8210130502 8210130597	50-269 PR 50-369 50-287 PR	0) Р Р
.and Corp Emarch Associates	8210250171 8210260382* 8210280222 8210270397 8207180058	50-341 50-341 50-341 RES FOIA	8 Q A		8210150012* 8210150068 8210150079 8210150084* 8210150094	50-369 50-413 50-269 50-269 50-413	8 8 0
y. JA arty. JB	8207180040 8207180041 8210070177 8210240348 8210240348	FOIA FOIA 50-352 50-338 50-338	G O G		8210150094 8210150101# 8210150101# 8210150369 8210150369	50-413 50-413 50-413 50-269 50-369	K G K
henatal Go	8210260355 8210260355 8210040231 8210180199* 8210180215*	50-338 50-338 50-264 50-10 FQIA	6 G G		8210130518 8210130522* 8210150522* 8210150617 8210180055	50-369 50-369 50-369 70-2944 50-269	F F
	8210180219* 8210180222* 8210180227* 8210180234* 8210180239*	FOIA FOIA FOIA FOIA			8210180055 8210180055 8210180060* 8210180060* 8210180060*	50-269 50-269 50-269 50-269 50-269	ե ե ե
	8210180247* 8210180251* 8210180257* 8210180260* 8210180262*	FOIA FOIA FOIA FOIA			8210180128 8210190103* 6210190103* 8210190108* 8210190544	50-370 50-369 50-369 50-369 50-269	A F F R
	8210180266* 8210180354* 8210180358* 8210180424* 8210180427*	FOIA FOIA FOIA 70-278 FOIA			8210170544 8210170544 8210170552* 8210170552* 8210170552*	50-269 50-269 50-269 50-269 50-269	A R R R
	8210180428* 8210180430* 8210180431* 8210180434* 8210290202	F01A F01A F01A F01A 50-264	8		6210190411 6210190411 6210190493 6210190493 6210190740	50-419 50-419 50-270 50-270 50-370	8 8 8
uer to	8209170053 8210010070 8210010070 8210010093 8210010134#	50-413 50-367 50-367 50-370 50-413	r a a a		8210190742 8210190751# 8210210131 8210210407 8210210407	50~369 50~369 50~269 50~269 50~269	R P P
	8210010232 8210010282 8210010352 8210010367 8210010463*	PR 50-349 50-269 50-370 50-249	a F G		B210210407 B210210411* B210210411* B210210411* B210220134	50-269 50-269 50-269 50-269 50-413	р Р О
	8210040107 8210040232 8210040232 8210040232 8210040245#	50-269 50-269 50-269 50-269 50-269	ն ե ե 6		8210220134 8210220202 8210220202 8210220206 8210220206	50-413 50-369 50-369 50-369 50-369	9 9
	9210040245 9210040255 9210040254 9210040254 9210040273	50-269 50-369 50-369	Р К К К		8210220319 8210220327* 8210220426 8210220426 8210220426	50-369 50-369 50-269 50-269 50-269	8 8
	8210040273 8210040279 8210040279 8210040286 8210040286	* 50-349 * 50-369 * 50-369	К К К К		8510520585 8510520585 8510520152 8510520152	50-413 50-413 50-413 50-413 50-413	000
	8210050130 8210050202 8210050208 8210050208 8210050208	50-413 50-413 # 50-413	A G G G		8210250304 8210260201 8210260331 8210260336* 8210260415	50-349 50-413 50-369 50-369 50-413	4440
	9210050264 9210050384 9210060311 9210070072 9210070072	50-413 50-413 50-369	A A F		8210270139* 8210270139* 8210270144* 8210280017* 8210280017*	50-369 50-369 50-369 50-369 50-369	++++

AUTHOR AFF ILIATION	ACCESSION NUMBER	BUBJECT CATEGOR	Υ	AUTHDR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY	
	8210280020* 8210280020* 8210280065 8210280065 8210290045	50-369 50-369 50-413 50-413 50-370	F F E E		8210250372* 8210270266* 8210270266* 8210280292 8210280323	50-213 50-155 RES RES RES	
	8210270083 8210270087* 8210270117 8210270170 8210270177*	50-270 50-270 50-413 50-269 50-269	9 9 9	ENSA, Inc Earthquake Engineering Research Institute Ebasco Bervices, Inc (subs of Enserch	8210280432* 8210290017 8210210594* 8210120488* 8210040072	RES CONTRACT CONTRACT	P H
	8210270250 8210270308 8210270313* 8210270354 8210270354	50-413 50-267 50-267 50-413 50-413	5 5 5 5 5	Corp)	8210040334 6210150431 8210190720# 8210260114 8210260466	50-389	ARPAR
Duquesne Light Co	8210290355 8210290365* 8210010013 8210040065 8210050165	50-249 50-269 50-334 50-334 50-334	8 9 F 8 P	Eddleman, W	8210210308 6210210308 8210210376 8210210374 8210210419	50-400 50-400 50-400 50-400 50-400	. 00000
	8210050148* 8210060076 8210060081* 8210060088 8210060096*	50-334 50-334 50-334 50-334 50-334	P R R R	Edelstein & Payne Ederer, Inc Edgar, G L	8210210419 8210250068 8210210419 8210210329 8210050184	50-400 50-400 50-400 TOPREP 50-537	0 0 0
	8210070155 8210070233 8210130561 8210150018* 8210150185	50-412 50-412 50-334 50-334 50-334	S 8 P Q S	Edison Electric Institute Ediow International Co	6210040185 6210040200 6210130282 8210070410* 8210080003	50-537 50-537 PR 71-9150 XPORTLIC	G
	8210150199 8210150201* 8210150208* 8210150312 8210150316*	50-334 50-334 50-334 50-334 50-334	8 8 8 P P		8210080005* 9210080071 8210210539 8210210543* 8210270021	XPDRTLIC XPORTLIC 70-2955 70-2955 XPORTLIC	
	8210190274 8210190262* 8210190747 6210210004 8210210010*	50-334 50-334 50-334 50-334 50-334	9 8 8 8	Electric Power Research Institute Emporia State Univ Energy Fuels Nuclear, Inc	8210120397 8210180416* 8210220516 8210250006 8210250008*	RES CONTRACT 40~8691 40~8681	
	8210210065 8210210072* 8210220184 8210260125* 8210260127*	50-334 50-334 50-334 50-334 50-334	9 9 F F		8210250034 8210240017 8210240018* 8210240022 8210270209	40-8681 40-8681 40-8681 40-8681	
	8210260135 8210260143 8210260163 8210260167* 8210260203	50-412 50-412 50-334 50-334 50-334	8 8 8 8	Energy, Dept of	8210270435 8210040251 8210050184 8210040185 8210040200	40-8681 50-537 50-537 50-537 50-537	A G G
	821 0240226* 821 0240458 821 0240478 821 0240487* 821 0270267	50-334 50-334 50-334 50-334 50-334	8 8 8		8210070409 8210130246 8210130249 8210130311 8210130343	71-9150 50-537 50-537 50-537 50-537	BAAQ
	821 0270268* 821 0270271* 821 0280271 821 0280280 821 0280307	50-334 50-334 50-334 50-334 50-334	e e e e e e e e e e e e e e e e e e e		8210130373 8210130435 8210170466# 8210200057 8210210022 8210210273	50-537 50-322 70-143 50-537 50-537	94 44
EQ&O, Inc	8010070320* 8205250020* 8210060417 8210070099* 8210080054*	50-305 50-155 NUREG 50-29 FOIA	ե ե		8210250025 8210250040 8210250061* 8210260168	WASTE MO 70-143 70-143 50-537 50-537	
	8210080057* 8210080064* 8210120118 8210120124 8210120300*	FOIA 50-317 RE8 REB 50-213	P	Energy, Dept of, Clinch River Breeder	8210260401 8210270074 8210270079* 8209300353	50-537 71-6639 71-6639 50-537	A
	8210120369 8210120397 8210120400	RES RES RES		Reactor Plant	8210040167 8210040304	50-537 50-537	A
	8210120430 8210120463 8210120654	RES RES RES		Engineering Decision Analysis Company,	8210040304 8210060217 8210060249 8210150186 8210070091*	50-537 50-537 50-537 50-29	AAAP
	8210120657 8210130409 8210150412 8210150413	res res res res		Inc Engineering Science	92102B0319*	CONTRACT 50~170	Н
	8210150421 8210150560	RES NUREO		Entwisle,E B. Enviro Audits Environmental Protection Agency	9210150200 8210040301* 9210130117 8210260235	50-170 50-338 50-413 50-440	PDD
,	8210150611 8210150625 8210200102	RES RES		Envirosphere Co European Communities, Commission of	8210280304* 8210270094	CONTRACT XPORTLIC	

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT		AUTHOR AFF IL LATION	ACCESSION NUMBER	SUBJECT CATEGORY
Ereter.184 Erron Nuclear Co , Inc (subs of Erron Corp)	8210280064 6210280088 8210120517* 8201200662*	XPORTLIC XPORTLIC CONTRACT 50-261 TOPREP	P		82101 70348 82101 70351 82101 70351 82101 70371 82101 70374*	50-387 A 50-250 G 50-250 G 50-335 F 50-335 F
	8210120230 8210130123 8210150033 8210150173 8210150182*	50-316 50-316 50-316 TOPREP TOPREP	P P P		8210190440 6210190440 6210190440 6210190440 6210190559	50-250 F 50-250 F 50-250 F 50-250 F 50-250 P
	8210130911 8210190902 8210260957 8210260560# 8210270092	TOPREP 50-219 40-8102 40-8102 TOPREP	Þ		8210170559 8210220070 8210220167 8210220214 8210220286*	50-250 P 50-251 P 50-389 S 50-389 Q 50-335 Q
	8210270164 8210270169* 8210270195 8210270197* 8210270214	TOPREP TOPREP 40-8102 40-8102 TOPREP			8210220304= 8210220451 8210250313 8210250317 8210260116	50-250 Q 50-335 Q 50-389 A 50-389 R 50-250 S
Finites: Metals (subs of Fanitee),Inc) Federa: Emergency Management Agency	8210280184* 8210070075 8210070109 8210070109 8210070112*	40-7580 50-440 50-445 50-445 50-445	С Г Г		8210260117* 8210260357 8210260367* 8210260391* 8210270253	50-250 S 50-335 S 50-335 S 50-335 G 50-250 P
	8210070112* 8210130161 8210130320 8210130430 8210170760*	50-445 50-289 50-289 50-387 50-254	ዩ የ የ የ		8210280067 8210280254 8210280291 8210280291 8210280293*	50-387 E 50-387 A 50-250 F 50-250 F 50-250 F
Finamore, B A Fiore & Jaskot	8210210159* 8210230170 8210210232 8210210232	50-382 50-10 50-537 50-537 40-8410	0 F 0 0	Florida Power Corp	8210280293* 6210290240 8210010049* 6210060198 6210060263	50-250 F PR 50-302 G 50-302 P 50-302 P
Flemming, Anderson, McClung & Finch Florida Power & Light Co	8210150490 8209170062 8210010017 8210010084* 8210010153*	50-361 50-250 50-389 50-335 50-335	6 F A G		B210130310 B210130319* B210130520 B210130530* B210150216	50-302 S 50-302 S 50-302 S 50-302 S 50-302 P
	8210010164 8210010174* 8210010292 8210010292 8210010321*	50-335 50-335 50-250 50-250 50-250	9 6 6		8210190677 8210190681 8210190687# 8210190691 8210210421	50-302 9 50-302 P 50-302 S 50-302 P 50-302 P
	8210050061 8210050152 8210050416 8210050417* 8210050567*	50-335 TOPREP 50-389 50-389 50-335	P A A F		8210220052 8210220036* 8210220395 8210260010*	50-302 8 50-302 8 50-302 P PR 50-302 F
	8210060209 8210060212# 8210060236 8210060276 8210060281	50-251 50-251 50-387 50-387 50-250	8 8 A P		8210260012+ 8210260310+ 8210260377+ 8210260422 8210260436	50-302 F 50-302 G 50-302 G 50-302 P 50-302 P
	8210040288 8210040288 8210040371 8210080252 8210080257*	50-335 50-335 50-389 50-250 50-250	P P R S S	Food & Drug Administration	8210260454 8210260497 8210290186 8210290312 8210120148	50-302 P 50-302 P 50-302 S 50-302 S
	8210080264 8210130090 8210130257 8210130289 8210130301	50-335 50-389 50-389 50-389 50-389	9 £ A A	Forbes Health Eys , East Suburban Health Center Monroeville,PA Fox Consulting Engineers & Geologists Franklin Institute/Franklin Research Center	85101503894 8510540521	WASTE HOT
	8210130348 8210130399 8210130454 8210130462* 8210130334	50-387 PR 50-335 50-335 50-389	F 8 8			
	8210130552 8210130562* 8210150035 8210150039* 8210150407	50-335 50-335 50-335 50-335 50-250	8 8 8 8			
	8210150407 8210150413* 8210150413* 8210150439 8210150439	50-250 50-250 50-250 50-250 50-250	թ թ թ			
	8210190186* 8210190186* 8210190194* 8210190310	50-250 50-250 50-250 50-335	F F P	Friends & Family of GA Technologies: Ir		

CONFORMIC SOURCE INDEX

ROHTUA AFF IL IATION	ACCEBBION NUMBER	SUBJECT	<u> </u>	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJEC CATEGO	
guard	82[0280062 82[0290]4] 82[0290]44* 82[0290234 82[0150490	XPORTLIC TOPREP TOPREP PR 50-361	c		8210150202 8210190398* 8210190570 8210190577* 8210190704	50-289 50-219 50-320 50-320 50-219	0 P P
Gage-Babcock Associates, Inc Galiagher, P K Galio, J Gard, Inc General Accounting Office	8210270230* 8210150490 8210060204 8210280374* 8210270020*	50-155 CONTRACT	0 0		8210200012 8210210280 8210220187* 8210220372 8210250092	50-320 50-219 50-219 PR 50-219	բ թ 0
General Electric Co.	8207090224 * 8207120147 8207120253 * 8207290410 8210010217	30-447	P A A		8210250097 * 8210250134 8210250189 8210250285 8210250383	50-219 50-219 50-219 50-219 50-219	د د د
	8210010224* 8210050328 8210050398 8210050408* 8210080113	TOPREP 50-447 50-447 50-447 XPORTLIC	A A A		8210260236* 8210260479 8210260505* 8210280124 8210280127	50-320 50-289 50-289 50-320 50-320	Q R R S
	8210080135 8210080262 8210150348 82101503416 8210150445	XPORTLIC TOPREP 71~5926 TOPREP TOPREP		Georgia Institute of Technology Georgia Power Co	8210290204 8210290234 8210290254 8210220319* 8210010022*	50-289 PR 50-219 50-160 50-321	р О О
	8210150461 8210180050 8210190785* 8210190785* 8210190810		P P		8210010094 8210010098+ 8210050080 8210050084+ 8210050330	50-366 50-366 50-366 50-364 50-321	9 8 9 8 9
	8210220174* 8210220205 8210220320* 8210220427* 8210250074*	70-1113 70-1113 70-1113	A P		821005033D 8210060231 8210060246 8210060248* 8210060275	50-321 50-366 50-366 50-366 50-366	P P 0 S P
	8210250077* 8210250078* 8210250110 8210250113* 8210250177*	50-260 50-70 50-70	የ የ የ የ		8210060278# 8210060287 8210060289# 8210060317 8210060324#	50-366 50-366 50-366 50-366 50-366	ក ទ ទ ទ
	8210250184* 8210260284* 8210260570 8210270046 8210270051*		A A		8210070168 8210080234 8210080240# 8210120047 8210120050#	50-424 50-366 50-366 50-366 50-366	۸ 9 9
	8210270057 8210270283 8210280198* 8210280201* 8210290288	50-277 TOPREP	ь Б		8210130129 8210130127 8210130132# 8210130132# 8210130183	50-321 50-321 50-321 50-321 50-366	R R R B
			ն 6 6		8210130185# 8210130220 8210130223# 8210130256 8210130258#	50-366 50-366 50-366 50-321 50-321	8888
					8210130406 8210130414* 8210130541 8210130549* 8210150329	50-366 50-366 50-366 50-366 50-321	0 8 8
					B2101 30333+ B2101 50362 B2101 50362 B2101 70016+ B2101 70016+	50-321 50-424 50-424 50-321 50-321	P A A F
					8210190017* 8210190017* 8210190046* 8210190046* 8210190051*	50-321 50-321 50-321 50-321 50-321	F F F F
					8210190504 8210190511* 8210190595 8210190602* 8210220078	50-366 50-366 50-366 50-366 50-424	ខ្លួន
					6210220208* 6210220219 6210220222* 6210220267* 6210220267*	50-424 50-321 50-321 50-321 50-321	9 9 9
					8210220290 82102202984 8210220384 8210220386 8210220388#	50-366 50-366 50-321 PRM 50-321	P P 8

AUTHOR AFF ILIATION	ACCESSION NUMBER	SUBJECT	Y	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGOR	
	8210270246 8210270246 8210270075 8210270080* 8210270076	50~424 50~424 50~366 50~366 50~321	A A S S S S		8210220268 8210220276* 8210220288* 8210220275* 8210220410	50-537 50-537 50-537 50-537 50-247	0000
	8210270106* 8210270206 8210270207* 8210270262 8210270272*	50~321 50~366 50~366 50~321 50~321	3 6 6 5 5	Harold J Spelman & Associates	8210220465 8210240397 8210240404* 8210280242 8210150463	50-287 50-537 50-537 50-247 40-2041	G G G
	8210270373 8210270324 8210270327 8210270327* 8210270334*	PR 50-321 50-321 50-321 50-321	5 9 9	Harper-Grace Hosps Detroit.HI Harvard Univ Karza Engineering Co House of Rep	8210250315 8210050213* 8210010119* 8210290422* 8210070458*	40-2051 70-2942 FOIA CONTRACT FOIA	
	8210290349 8210290357 8210290359* 8210290364* 8210290373	50-321 50-366 50-321 50-366 50-321	3 3 3 3	Housing & Urban Development.Dept of Houston Lighting & Power Co	8210270066 8210010301 8210050329 8210070120 8210070147	40-8781 FR 50-498 50-466 50-466	6 0 0
trans, Inc	8210290374 8210290375= 8210290381= 8210120350= 8210190339=	50-344 50-321 50-364 CONTRACT CONTRACT	8 8		8210200052 8210200052 8210200075 8210210343 8210210343	80-498 50-498 80-498 50-498 50-498	A A 0 0
ty Q1] Co (Petrotomics) os & Hill: Inc (subs of Dravo Corp) der Associates	8210220510 8210270124 8210270129* 8210070021* 8210120458*	40-6659 50-584 50-584 CONTRACT			8210210368* 8210210368* 8210220125* 8210220237 8210220237	50-498 50-498 50-498 50-498 50-498	0 0 0 0 0
lds Pumps. Inc	8210150326* 8210150330* 8210150335* 8210150449 8210150457*	50-341 50-341 50-341 50-358 50-358	0 0 0 0 0		8210220241* 8210220334 8210250112 8210250247 8210250259	50-498 PR 50-498 50-498 50-498	A B B
at Lates Energy Alliance inblatt, D	8210210391 8210210400* 8210190480 8210210308 8210210308	50-358 50-358 50-255 50-400 50-400	G G G	Hovis, R L	8210250263 8210250353 8210260452 8210260452 8210260169	50-498 50-498 50-498 50-498 50-522	A A 8 8 9
d. R ' States Utilities Co	8210210419 8210210419 8210080081 8210040215 8210040215	50-400 50-400 50-413 50-458 50-458	G G K K	Hunton & Williams INTERA Environmental Consultants, Inc	8210120307 8210150279 8210150296* 8210200003 8210270379	50-022 50-022 50-022 50-022 RFB	0000
	8210040220* 8210040220* 8210050201 8210050219 8210050317	50-458 50-458 50-458 50-458 50-458	8 8 8 8	IRT Corp Jdaho, State of Igoe, V M Illinois Pawer Co	8210120346* 8210120503 8210270023* 8207180037 8207270072	CONTRACT XPORTLIC 50-537 50-483 50-461	Q B A
	8210050350 8210130162 8210130516 8210190367 8210190518	50-458 50-458 50-458 50-458 50-458	8 9 9 8		8210040104 8210050183 8210050185* 8210050278 8210050281	50-461 50-461 50-461 50-461 50-461	Y K K E E
	8210190629 8210200037 8210220376 8210250118 8210260286	50-458 50-458 PR 50-458 50-458	8 8		8210130181 8210130181 8210130184* 8210130270 8210130325	50-461 50-461 50-461 PR 50-461	E G G
Inc ind Engineering Development inatory	8210260292 8210290263 8210060004 8210150550	50-45B PR NUREO NUREO	s		8210130377 8210130470 8210130490 8210150357 8210170350	PR 50-461 50-461 50-461 50-461	F A A B
in & Wains	8207110033 8207110034 8208290094 8210040195 8210040210 8210120274	50-537 50-337 50-322 50-537 50-289 50-289	A D G G		8210170354 8210170416 8210260003 8210260050 8210260089	50-461 50-461 70-2946 50-461 50-461	9 8 Q A
	8210120327 8210130383 8210200024 8210200024 8210200035*	50-537 70-143 50-443 50-443 50-443	0 0 0	Illinois, State of	8210280140 8210280213 8210210051 8210240501 8210120419*	50-461 50-461 NUREO 50-374 27-37	8
	8210200035* 8210200042* 8210200042* 8210200049* 8210200049*	50-443 50-443 50-443 50-443 50-443	G G G		8210130265 8210130265 8210130476 8210130494 8210130494	50-329 50-329 50-151 50-329 50-329	T 8 T
	8210200054 8210200061 8210210357 8210210453	50-329 50-329 50-537 50-537	G G G	Indiana & Michigan Electric Co.	8210210051 8210010362 8210040073 8210040075# 8210040179	NUREQ 50-315 50-315 50-315	F 8

AUTHOR AFF IL IATION	ACCESSION NUMBER		JECT EGURY	AUYHDA AFFILIATION	ACCEBSII NUMBER		JECT FODTY
	8210040201 8210040203* 8210040205* 8210040209* 8210040212	50-31 50-31 50-31	5 B 6 B 5 P	Interior, Dept of Interior, Dept of, Fish & Wiidlife Bervic International Energy Associates, Ltd Interstate Nuclear Bervices	821028006 82100403 821005021 821007046 820715008	22 50-4) 14 50-24 28 FDJA	1 1¢
	8210040321 8210040327* 8210040330* 8210050138 8210050138	50-31 50-31 50-31 50-31	6 B 6 B 5 P 5 P	Iowa Electric Light & Power Co	821004034 821004037 821005030 821012039 821013013	76* 90~09 17* 50~31 17* 90~.13	11 6 11 9
	8210050159 8210050159 8210050160# 8210050211	50-31 50-31 50-31 50-31 50-31	5 P 5 P 5 P		821013039 821013039 821013039 821013030	J 50-33) 8* 50-31) 9 50-33)	1 5
	8210050276* 8210050349 8210050349 8210040256* 8210040277	50~315 50~315 50~315 50~315	5 P 5 P 5 G		621013054/ 621013056/ 6210130590 6210150140	9 50-011 0* 50-(131 0 50-301	. 6
	8210040300 8210040307* 8210040313* 8210070279 8210070279	50~315 50~315 50~315 50~315	2 1 1		821 0250269 821 0250251 821 0250251 821 0200070	50-971 50-711 * 50-311	11 11 11 12
	8210070286* 8210070286* 8210080132* 8210080132* 8210080136*	50-315 50-315 50-315 50-315	1 F F		6210250304 6210250364 6210250367 6210250367	50-31; 50-31;	es es pr
6 E E	3210150604* 3210150604* 3210150616* 3210150616* 3210150616*	50-315 50-315 50-315 50-315	4 4 4 4 4	Jour, Univ of Isham, Lincoln & Beals	0210240489 0210240495 0200290012 0207100059 0210010406	90-931 40-931 4089 7014 90-198	p II
명 중 당	210180123* 210180127* 210180127* 210190246 210190277*	50-316 50-316 50-315 50-315	88868		9210010444 9210050215 9210050221 9210050221 9210050223	50-155 50-129 50-329 50-329 50-329	0 0 0 0 0 0
8: 8: 8: 8:	210190287* 210190340 210190342* 210190380	50-315 50-315 50-315 50-315	8 8 8 8	E 1	2100 50223 2100 50227* 2100 50230 2100 50230 2100 50232	50~320 50~329 50~329 50~329 50~155	00000
85 86 82 83	210190404# 210190415# 210190572 210190578#	50~315 50~315 50~315 50~315 50~315	8 8 8	ម ល	2100 50373 2100 50309 2100 50391 2100 50391	50-155 50-454 50-255 50-255 50-255	33000
92 93 93	210190676 210190676 210190685*	50-315 50-319 50-315 50-315	S R R R	री हा स	2101 90440 2101 90457# 2101 90462 2101 90900 2101 50470	50-155 50-155 50-155 50-155 50-155	00000
85 85 85	10190735# 10190749 10190757#	50-314 50-316 50-315 50-315 50-315	8 8 8 8	8: 6: 8: 8: 8:	210180142 210180206 210180242 210200029 210250211	50-454 50-155 50-155 50-155	00000
	5	50-315 50-315 30-315 50-315	6 6 6 6	Isotope Products Laboratories 82 Jacksonville Shieyards, Inc 82 Japan 82 82	10280030 10220316 10040382 10040385 10040387	XPORTLIC PA XPORTLIC XPORTLIC XPORTLIC	•
	5 5 5	50-315 50-315 50-315	F F F F	Japan Atomic Energy Research Inst 62	10040471 10280435 10180421 10200082	XPORTLIC XPORTLIC REA	o
	5 5 5	0-170 0-170 0-170	9 9 9 9	Berlint Intervence and the Berlin Ber	0130417 0130417 0130486* 0130486* 0270171	50-528 0 50-528 0 50-528 0 50-528 0	3
	56 36 06	0-170	9 9	Joint Intervenors-Waterford 821 821 KLD Associates: Inc. 821	0050218 0050272* 0050278* 0050278*	50-275 G 50-382 Q 50-382 Q 50-382 Q 50-382 T	}
	50	31A 3-219 /	P A	KMC, Inc 821 820 821	0150240* 0280041* 7050005* 0010293	50-322 f 50-322 F PR PR PR PR	

AUTHUR AFFILIATION	ACCESSION NUMBER	SUBJECT	Y	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGOR	Y
Tan Tempo near Gas & Electric Co	8210120331* 8210130399 8210280356* 8210040364 8210120199	REVIEW C PR CONTRACT 50-482 50-482	RP		8210150204* 8210150223* 8210150240* 8210150250* 8210150257*	50-322 50-322 50-322 50-322	T T T T
nsag State Univ nnæcott Copper Corp	8210130397 8210220403 8210170365 8210220074* 8210220077*	PR PR 50-188 40-8111 40-8111	R		8210150265* 8210150272* 8210150279 8210150281* 8210150290*	50-322 50-322 50-322 50-322 50-322	T 0 T T
ntucky. State of rr-HcGes Chemical Corp (subs of spr-HcGes Corp)	8210220086* 8210210046 8210260574	40-B111 NUREG 40-8027			8210150309# 8210150324# 8210150337# 8210150351#	50-322 50-322 50-322 50-322	0 0 0
r-MrGee Corp	8210260543 8210260548*	40-8027 40-8027			8210150345* 8210150393*	50-322 50-322	0
	8210260565 8210270077 8210270088* 8210270242 8210270247*	40-8027 40-2061 40-2061 40-8027 40-8027			8210150402* 8210150410* 8210150422* 8210150527*	50-322 50-322 50-322 50-322	000
T-Hicee Muclear Corp aunce County, WI tpatrick Lockhart, Hill, Christopher Phallip		40-8027 CONTRACT 50-322	G		8210200003 8210200035 8210250059* 8210250141* 8210280035*	50-322 50-322 50-322 50-322 50-322	96961
	8210050180 8210050189	50-275 50-322	G G		8210280039* 8210280041*	50-322 50-322	F
	8210200076 8210200083* 8210200089*	50-322 50-322 50-322 50-322	0 0 0	Los Alamos Scientific Laboratory	8210280285 8210290269 8210120428	50-322 PR RES	8
. N	8210290058 8210290097 8210290097 8210290283	50-322 50-275 50-322	P P	Louise County, VA Louisiene Power & Light Co	8210240347 8210240347 8210240373 8210240373 8209150432	50-338 50-338 50-338 50-338 70-2946	0000
shen. AH kville: TN	8210180401*	50-285 CONTRACT			82091 50436* 82091 50436*	70-2946 70-2946	
ru Alliance nam. J M osse, Wi st-Amderson, Inc	8210210419 8210120362* 8210120423* 8210260530* 8210180338*	50-400 CONTRACT 50-389 CONTRACT CONTRACT	г ^М		8209220135 8209220137* 8210010370 8210010381	50-362 50-362 50-362 PR	A F
ence General Hosp Lawrence, MA ence Livermore Laboratory	8210180348* 8210210448* 8205250010* 8206170006*	CONTRACT 70-2116 50-155 50-312	p p		8210010435 8210040078 8210040110 8210040148	50-382 50-382 50-382 50-382	0 8 A F
	8207300222* 8209130461* 8209200475* 8210150548 8210290113*	50-204 50-293 50-29 NUREG 50-324	թ թ		8210040191 8210070124 8210070197 8210080086 8210080090	50-382 50-382 50-382 50-382	AGGGG
euf, Lamb, Leiby & MacRae	8210010287	50-341	K a		8210130174 8210130243	50-382 50-382	8
ue of Homen Vaters of Rockford, JL	8210180160 8210280250 8210290234 8210070127 8210070127	50-287 50-287 PR 50-454 50-454	0 0 0		8210130245 8210130551 8210130564 8210150347	50-382 50-382 50-382	9 9 8
	8210070129* 8210070129* 8210210274 8210210274	50-454 50-454 50-454 50-454	G G G		8210190345 8210190542 8210210372 8210250217	50-362 50-362 50-382 50-382	8 0 8
	8210210278 8210210278 8210210384 8210210384	50-454 50-454 50-454 50-454	6 6 6		8210250242 8210250254 8210250341 8210250355 8210260362	50-382 50-382 50-382 50-382 50-382	8 8 A F
	#210240380 #210240380 #210240384* #210240384*	50-454 50-454 50-454 50-454	0 0 0		8210260423 8210270190 8210270193# 8210280387	50-362 50-362 50-362 50-362	o K K
	8210260392* 8210260392* 8210290293	50-454 50-454 50-454	9	Louisians, State of	8210290438 8210040002*	71-6574 CONTRACT	
on Steel Foundry h Univ , M	8210270305 8210270370 8210050348 8210010310	50-454 40-8153 NUREO PR	G.	Lowell, Univ of Lowerstein, Newmen, Reis, Axelrad & Toll	8210150462 8210280183 8210280186# 8210070120	50-416 50-223 50-223 50-466	RRO
ick Ecology Action Estand Lighting Co	8210270304 8210070177 8210040274# 8210040361*	50-289 50-352 50-322	0 0 0		8210070147 8210200058 8210210363 8210210363 8210210368*	50-466 50-522 50-498 50-498 50-498	0000
	8210070384 8210120307	50-322 50-322	0		8210210348* 8210270259	50-498 PR	G
	9210150148 9210150178* 9210150188*	50-322 50-322 50-322	T T T	MPR Associates, Inc. Maine Nuclear Referendum Committee	8510540505 8510010082* 8510010081*	50-219 50-219 50-309	<u>የ</u>

AUTHOR AFF ILIATION	ACCESSION NUMBER	SUBJECT	٧	AUTHOR AFFILIATION	 ACCESSION NUMBER	SUBJECT	
Maine Yankee Atomic Power Co	8210010230 8210040074 8210040077 8210040217 8210050015*	PR 50-309 50-309 50-309 50-309	Р Р Р		8210050193 8210050203* 8210060201 8210060203* 8210060224	50-416 50-416 50-416 50-416 50-416	ងទេ១១
	8210050018* 8210060171 8210060173* 8210060302 8210130252	50-309 50-309 50-309 50-309 50-309	F P ዋ Q P		8210060226# 8210060295 8210060295 8210070044# 8210070044#	50-416 50-416 50-416 50-416 50-416	9 P F F
	8210130254* 8210130283 8210130284* 8210130314 8210130340	50-309 50-309 50-309 50-309 50-309	P P G P		8210070048* 8210070048* 8210080120 8210080127* 8210080186	50-416 50-416 50-416 50-416 50-416	F S S
	8210130369* 8210150398 8210210015 8210210018* 8210220203	50-309 50-309 50-309 50-309 50-309	Բ G S G P		8210080192# 8210080223 8210080277 8210080281# 8210080282	50-416 50-416 50-416 50-416 50-416	99999
	8210220212 8210250098 8210240144 8210240193 8210240197	50-309 50-309 50-309 50-309 50-309	ዮ ወ ይ		8210080284 8210080287* 8210080289* 8210080295 8210080298*	50-416 50-416 50-416 50-416 50-416	9 9 9 9 9
	8210260200* 8210260208* 8210260327 8210260420 8210270008	50-309 50-309 50-309 50-309 50-309	8 8 8 P Q		8210150011* 8210150013 8210150019* 8210150024* 8210180104	50-416 50-416 50-416 50-416 50-416	0 0 0 8
	8210270009* 8210270145 8210270177* 8210280087 8210280161	50-307 50-307 50-307 50-307 50-307	0 8 F P		8210180109* 8210190417 8210190424* 8210190496 8210190521	50-416 50-416 50-416 50-416 50-416	8 8 9 6
Mainer State of Manhattan College Mapieton Intervenors	8210290343 8210060190 8210280227 8210080341 8210070398	50-309 50-309 50-309 50-199 50-329	8 0 0 P 0		8210170341 8210170544 8210170544 8210170547* 8210200005	50-416 50-416 50-416 50-416 50-416	
Marsh & McLennan, Inc., M & M Nuclear Consultants, Inc. Div Marshall, W M Haryland, Univ. of	8210220294 8210040313 8210070398 8210240240*	50-329 50-329 CONTRACT	9		8210200005 8210200030 8210200030 8210200044 8210200073	50-416 50-416 50-416 50-416	E E E
Massachusetts Institute of Technology Maywood, NJ McDonald Engineering Analysis Co , Inc	8210050428 8210150574 8210190334 8210260352* 8210150343* 8210150346*	NUREQ NUREQ 50-20 40-8610 50-341 50-341	F Q		8210200073 8210210217 8210210217 8210220065 8210220067*	50-416 50-416 50-416 50-416 50-416	E P 8 8
Memphis State Univ Metropolitan Edison Co	8210150352* 8210260493* 8210270402* 8210040210 8210070194	50-341 50-358 CONTRACT 50-289 50-289	Q E		8210220131 8210220150* 8210220158 8210220162* 8210220161	50-416 50-416 50-416 50-416 50-416	8 8 8
	8210080094 8210130275 8210150280 8210150289# 8210200033	50-289 50-289 50-320 50-320 50-289	0 0 8 8		8210220191* 8210220196 8210220199* 8210220259 8210220262*	50-416 50-416 50-416 50-416 50-416	9 9 8
	8210210173 8210210179# 8210210266 8210210374 8210280360	50-320 50-320 50-320 50-287 50-289	Q Q Q		8210220269 8210220274* 8210220278 8210220282* 8210220284	50-416 50-416 50-416 50-416 50-416	នៃស្ន
Miami Valley Power Project Michigan, Univ. of	8210150449 8210150457# 8210210391 8210210400# 8210060424#	50-358 50-358 50-358 50-358 CONTRACT	0 0		8210220289* 8210220334 8210220425 8210220428 8210220431*	50-416 PR 50-416 50-416 50-416	8 8 8
Micro-Tel Corp Miller,D S. Mississippi Power & Light Co.	8210190223* 8210050236 8210200045 8210290303 8210010023	CONTRACT 50~309 50~309 50~309 50~414	0 0 0 F		8210220458 8210220462* 8210260264 8210260412 8210260445	50-416 50-416 50-416 50-416 50-416	8 P P B
	82100 10223 82100 10234 82100 10243 82100 10248* 82100 40053	PR 50-416 50-416 50-416 50-416	F 8 8		8210240513 8210270277 8210280132 8210280132 8210280135	50-416 50-416 50-416 50-416 50-416	8 9 0 9
	9210040053 9210040264 8210040353 8210040353	50-416 50-416 50-416 50-416	P P P		8210280135 8210290050 8210290055* 8210290073 8210290081*	50-416 50-416 50-416 50-416 50-416	9 9 9 9

AUTHOR AFF (LIATION	ACCESSION NUMBER	SUBJECT CATEOOR		AUTHOR AFF ILTATION	ACCESSION NUMBER	SUBJECT CATEGOR	
	8210290102 8210290102 8210290124 8210290135* 8210290193	50-416 50-416 50-416 50-416 50-417	6 to 2 d	New Hampshire, State of New Mexico, State of	8210200049* 8210200049* 8210250307 8210120021* 8210120023*	50-443 50-443 50-443 FDIA FDIA	0 0 A
	8210290311 8210290332* 8210290340 8210290345* 8210290348	50-416 50-416 50-416 50-416 50-416	8 8 8 8	New York, State Univ of. Buffalo New York, State of	8210120042* 8210010277 8208290099 8210180419* 8210210041	FOIA 50-57 50-322 50-201 50-201	F A P P
ississippi, State of issouri, Blate of itsut & Co. (U.S.A.), Inc. (Subs. of	8210290351* 8210220403 8210270033* 8210130078	50-416 PR CONTRACT XPORTLIC		New York, State of, Energy Research & Development Administration New York,NY	8210220321 8210250582*	PR 50-201 50-247	a a
Mitsus & Co . Ltd)	8210130080¥	XPORTLIC		News & Observer News-Herald Willoughby, OH	8207180044 8207180055	50-241 50-440	P F
olycorp. Inc	8210270007 8210270448 8210270452* 8210080327 8210080331*	XPORTLIC XPORTLIC XPORTLIC XPORTLIC XPORTLIC		Niagara Mohaut Power Corp	8210010033 8210010145* 8210010207* 8210040071 8210040117	50-220 50-220 50-220 50-410 50-220	P G G B P
orde K-Ray Co , Inc Irgan Associates	8210010005 8210010024* 8210040235 8210250081 8210250081	71-481 71-481 50-247 50-247 50-247	G G		8210040170 8210040182 8210040183* 8210040190 8210040296	50-410 50-220 50-220 50-410 50-220	0 P P B F
	8210250216 8210250216 8210250265 8210250265 8210250272	50-247 50-247 50-247 50-247 50-247	6 6 6		8210040303* 8210050111 8210050148 8210050260 8210050354	50-220 50-220 50-220 50-220 50-220	6 6 6
rgan. Lewis & Bocklus yns Laboratory/Monsanto rray. Plumb & Murray	8210250272 8210290271 8210260581 8210150549 8210260457	50-247 50-247 50-201 NUREQ 50-309	H G G		8210040208* 8210040284 8210040271* 8210130107 8210130347	50-220 50-220 50-220 50-220 50-220	8 8 8 8
Industries, Inc 3 Corp	8210240445# 8210010434# 8210010440# 8210040354# 8210210304#	50-309 40-1202 40-1202 50-261 50-329	G F A		8210130350* 8210150127 8210150135 8210150142* 8210210322	50-220 50-410 50-220 50-220 50-410	R 8 8 8
IECH (Kuclear Technology, Inc.)	8210010440# 8210050427# 8210150377# 8210150500# 8210150504#	50-341 50-155 50-263 50-263 50-263	A P P P	North Caroline, State of	821025037B 8210240184* 8210280121 8210280144 8210220518	50-410 50-220 50-220 50-220 70-1113	8 9 9
ional Nuclear Corp ional Wildlife Federation	8210150509* 8210130076 8210270152* 8210080073 821020434	50-263 XPORTL 10 XPORTL 10 50-522 50-522		North Carolina, Univ of North Shore Committee Against Nuclear & Thermal Pollution	8210270395* 8210280321* 8210150234 8210150309*	CONTRACT FOIA 50-322 50-322	. 0
ural Resources Defense Council	8210040195	50-537	۵		8210150324*	50-322	ä
	8210120302 8210120327 8210130268 8210130383	50-537 50-537 50-537 70-143	9		8210150337* 8210150351* 8210150345* 8210150373* 8210150402*	50-322 50-322 50-322 50-322	00000
	8210200001 8210200004# 8210210232 8210210240# 8210210357	70-143 70-143 50-537 50-537 50-537	G G	Northeast Nuclear Energy Co (subs of	8210150410* 8210150422* 8210150527* 821023059*	50-322 50-322 50-322	9999
	8210210453 8210220268 8210220276* 8210220279* 8210220283*	50-537 50-537 50-537 50-537 50-537	60000	Northeast Nuclear Energy Go (subs of Northeast Utilities)	9210010207 9210010207 9210010207 9210010214# 9210010230	50-213 50-213 50-213 PR	P P
	8210220288* 8210220295* 8210260397 8210260404* 8210250025	50-537 50-537 50-537 50-537 WASTE M	9 0 0		8210010312 8210010312 8210010376	50-213 50-213 50-336	P P S
ijo Nation aska Public Power District	8210010058	50-298	F		9210010385* 9210040120 9210050090	50-336 50-245 50-336	e P
	8210130318 8210220136* 8210220254 8210260217	50-298 50-298 50-298 50-298 50-298	e a P a		8210050118 8210050177 8210050179 8210050187#	30~245 50~245 50~336 50~336	P P P
England Coalition on Nuclear	8210290323 8210290323	50-278 50-278 50-443	P		#21006004B #210060094	50-245 50-245	ь Б
Jutian	8510500032* 8510500059	50-443 50-443	0		8210040233 8210040237 8210040238# 8210070230	50-245 50-336 50-336 50-245	9 P 8
	8210200035* 8210200042* 8210200042*	50-443 50-443 50-443	0		8210070304 8210070356*	50-245 50-245	ğ

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY		AUTHOR AFF IL IATION	ACCESSION NUMBER	SUBJECT CATEGOR	ł y
	8210070360 8210080105 8210130228 8210130232* 8210130326	50-245 5 50-423 A 50-336 5 50-336 5	5 A 5 S P		6210040380* 6210040384* 6210080117 6210080184 8210080184	50~263 50~263 50~263 50~282 50~282	P 9 5 F 8
	8210130331 8210130331 8210130331 8210190472 8210190476*	50-213 F 50-336 6	P P P G G		8210130260 8210130261 8210130510 8210130533* 8210130563	50-263 50-263 50-282 50-282 50-306	F = 1 = 0
	8210190555 8210210155 8210210160* 8210210340 8210210425	50-336 5 50-336 5 50-423 6	8 8 8 8		8210130566 • 8210150174 8210150180 • 8210150255 • 8210150255 •	50-304 50-263 50-263 50-282 50-282	0 5 6 0
Northeast Utilities	8210220060 8210220064* 8210220103 8210220108* 8210220112	50-336 5 50-245 8 50-245 8	8 8 8 9		8210150364 8210150381 8210150390* 8210190289 8210190293*	50-263 50-282 50-282 50-263 50-263	P 11 22 2 1
	8210220116* 8210220195 8210220201* 8210250290 8210250329	50-245 5 50-245 5 50-423 5	8 5 5 5 5 5 5		8210190422 8210190439# 8210190439# 8210190479 8210190726	50-282 50-282 50-282 50-263 50-306	8 0 0 0
	8210260174 8210260414 8210260432 8210260441* 8210260459	50-245 F 50-336 F 50-336	P P S S P		8210190745* 8210250179 8210250183* 8210250200 8210250364	50+306 50-282 50+282 50-282 50-282	9331.0
	8210240519 8210270200 8210270200 8210010207 8210010207	50-213 50-213 50-213	р Р Р		8210250376# 8210260154 8210260154 8210260209 8210270262	50-282 50-282 50-243 50-243	B P P P P
	8210010207 8210010230 8210010312 8210010312 8210010376	PR 50-213 (50-213 (Ե	Nuclear Assurance Corp	8210270242 8210290239 8210290249 821020245* 8210050439*	50-282 PR FR FOIA FOIA	F
	82100 40120 82100 50070 82100 50118 82100 50177 82100 50179	50-336 50-245 50-245	୮ p ቦ P		8210050446* 8210050467* 8210050471* 8210070156* 8210270427*	70-1510 FOIA FOIA CONTRACT 70-1510	г
	82100 40048 82100 60094 82100 60233 82100 60237 82100 70250	50-245 50-245 50-336	P Q P 8		8210270429* 8210270437* 8210270438* 8210280448 8210290155	70-1510 70-1510 70-1510 71-9010 71-6699	
	8210070304 8210070356* 8210070360	50-245	9 Q 8	Nuclear Energy Service, Inc Nuclear Fuel Services, Inc (subs of Getty Oil Co)	8210040228# 9210010184	50-352 70-143	G
	8210130228 8210130331	50-213	8 P		8210150061 8210150371* 8210150408*	70-143 70-143 70-143	
	8210130331 8210130377 8210170555 8210210155 8210210340	PR 50-423 50-336 50-423	P S S S		8210150477* 8210220395 8210240548 8210240571 8210240581	70-143 PR 70-143 70-143 50-201	8
	8210210425 8210210430* 8210220060 8210220103 8210220195	50-245 50-336 50-245	8 8 9	Nuclear Law Genter Nuclear System Oak Rideo Mational Laboratory	8210260582* 8210270235 8207180041 8210290398* 8202020441*	50-201 70-143 FOIA CONTRACT	G T
	8210250270 8210250327 8210240174 8210240414 8210240432	50-423 50-245 50-245	8 P P		82031 60383* 82032 50320* 82100 50504 82100 60005* 82100 60425	FOIA FOIA REG FOIA REB	
Northern California Power Agency, California State of, Northern Indian Public Service Co	8210260459 8210260519 8210270200 8210250356 8210050162	50-245 50-213 PROJ	P P P		8210070253# 8210120453 8210120653 8210150564 8210150567	50-537 RES RES NUREO NUREO	۸
Northern Indians Public Service Co Northern States Power Co	8210010036 8210010041* 8210010046* 8210010060 8210040123	50-263 50-263 50-263 50-263	р Р Р	•	8210150587 82101505577 8210150577 8210210034 8210210037	NUREO NUREO RES 50-259 NUREO	r
	8210050319 8210040258 8210040260* 8210040377	50-282 50-263 50-263	P 8 8 P		8210210039 8210260206 8210270035# 8210270052#	NUREG NUREG 50-537 50-537	0

ı

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGOR		AUTHOR AFFILIATION	ACCESSION NUMBER	BUBJEC CATEGO	RY
Ccean County, NJ	8210270056# B210270068# B2102B0110# B210290006# B210120541#	50-537 50-537 FOIA COMMISSI CONTRACT	C ON	Parameter, Inc Parents Concerned About Endian Point	82102 40280 * 82102 00019 82102 00019 82102 20389 82102 20389	CONTRAC 50-247 50-247 50-247 50-247	
<u>Gf+sce</u> of Management & Budget	8210120402 8210120404 8210270116 8210270119	980 980 980 980		Pathfinder Mines Corp	8210150401 8210150407 8210150413* 8210180415	40-6622 40-2259 40-2259 40-6622	
Cyle Petroleum. Inc	8210270063 8210280046 8210280049* 8210010335 8210010335	40-8745 40-8745 40-8745 40-8745 50-440 50-440	G G		8210180420* 8210220476* 8210250028 8210260013 8210260014* 8210270054	40-6622 40-6622 40-6622 40-6622 40-6622 40-2259	
	8210010366 8210010366 8210010377 8210010377 8210010386	50-440 50-440 50-440 50-440 50-440	0 6 6 6	Pennsylvenia Power & Light Co	8210290177 8210010177 8210010180* 8210010228 8210010228	40-6622 50-387 50-387 50-387 50-388	8 8 8
	8210010384 8210010414 8210010414 8210040207 8210150192	50-440 50-440 50-440 50-440 50-400	G G G C		8210010393 8210010402* 8210010417 8210040052 8210040086	50-387 50-387 50-387 50-387 50-387	83188
	B210180211 B210210351 B210210351 B210210358* B210210358*	50-440 50-440 50-440 50-440 50-440	0 0 0		8210040088* 6210040118 6210040122* 6210050325 6210050370	50-387 50-387 50-387 50-387 50-387	9 9 9 9
Ohio State Univ Ohmant Corp	8210210366* 8210210366* 8210220481 8210210176* 8210060419*	50-440 50-440 50-440 CONTRACT FDIA	G G		8210060199 8210060391 8210080083 8210080142 8210080146*	50-387 50-387 50-387 50-387 50-387	ր թ թ
Dil.Chemical & Atomic Workers Int) Oblahoma Steel Castings Co Praba Public Power District	8210130281 8210220316 8209170051 8210040186 8210040187*	70-143 PR 50-285 50-285 50-285	ម ន		8210080151* 8210130122 8210130341 8210130352 8210130361*	50-387 50-387 50-387 50-387 50-387	ន ក ក
	8210050247 8210050301 8210050303* 8210060196 8210070333*	50-285 50-285 50-285 50-285 50-285	ក ទ ទ ក ព		8210130343 8210130371* 8210130377 8210130389* 8210170166*	50-387 50-387 50-387 50-387 50-387	ti 8 8 F
drange County, CA	8210130570 8210190736 8210190746* 8210200077 8210130259	50-285 50-285 50-285 50-285 PRM	ម ម ម		8210190166# 8210190173# 8210190173# 8210190297 8210210020	50-387 50-387 50-387 50-387 50-387	F F P 8
uregon Environmental Council Orrick, Herrington & Sutcliffe	82100 80073 82101 30309 82101 50454 82101 50454 82101 50482	50-522 50-361 50-361 50-361 50-361	G G G G		8210210020 8210210137 8210210137 8210210285 8210210293*	50-387 50-387 50-387 50-387 50-387	8 8
Pacific Air Products Co Pacific Gas & Electric Go	8210150482 8210190372* 8210010198 8210010307 8210010404	50-361 0A999 50-133 PR 50-275	e r p		8210210417 8210210433 8210210436# 8210210440 8210210446#	50-387 50-387 50-387 50-387 50-387	p 8 8 8
	8210010413* 8210050122 8210050144 8210050144 8210060220	\$0-275 \$0-275 \$0-275 \$0-275 \$0-275	0 t- t- t-		8210220102 8210220175 8210220364 8210250256 8210250264*	50-387 50-387 PR 50-387 50-387	9 P C
	8210120278 8210120283* 8210130272 8210150151 8210150159*	50-275 50-275 50-275 50-275 50-275	P C R R		8210250276# 8210250347 8210250357 8210250367 8210250369	50-387 50-387 50-387 50-387	ր 9 8
	8210150389 8210210044* 8210210048* 8210220371 8210220395	50-275 50-275 50-275 50-275 PR	ե ե ե		8210250373* 8210250377* 8210250380* 8210250381 8210250385*	50-367 50-387 50-387 50-387 50-387	8 1 8 1 8
	8210250192 8210250194* 8210260359 8210270236 8210270240*	50-133 50-133 50-133 50-275 50-275	R R P R		8210260270* 8210260350 8210260354* 8210260366 8210260379*	50-387 50-387 50-387 50-387 50-387	0 P P
Pacific Pumps Div Palmetto Alliance	8210270351 8210290219 8210290222* 8210040155* 8210080081	50-275 50-275 50-275 0A999 50-413	ខ ខ ខ		8210240385* 8210240319* 8210280219 8210280219*	\$0-387 50-387 50-387 50-387 50-387	P 8 8

AUTHOR AFF IL IATION	ACCESSION NUMBER	SUBJECT Catequry	AUTHOR AFF IL 1AT ION	ACCESSION NUMBER	SUBJECT CATEGORY
Pennsglvenia State Univ Pennsglvenia, State of	8210290318 8210130487 8210040218 8210210378 8210270203*	50-387 F 50-413 D 50-289 G 90-289 G CONTRACT	Pollution & Environmental Problems, Inc Portland Cement Association Portland General Electric Co	8210210235 8210240527 8210240163 8210080253# 8210130399	50-295 / 50-329 ; 50-344 / 50-344 (PR
Perkans, Coie, Stone, Olsen & Walliams	8210280235* 8210290131* 8210010382 8210050171 8210130190	CONTRACT CONTRACT 50-522 C 50-522 O 50-522 C		B210190024* 8210190026* 8210220301 8210250084 8210250093*	50-344 50-344 50-344 50-344
	8210130347 8210130347 8210130498 8210130498 8210200045	50-522 G 50-522 G 50-522 G 50-522 G 50-522 G	Power Authority of the State of New York	B210250164 B210250175* B210040213* B210040317 B210040324	50-344 \ 50-344 \ 50-286 (50-333 \ 50-333 \
Philadelphia Electric Go	8210260430 8207090201 8207090208* 8207090215* 8209170149	50-522 B 50-278 P 50-278 P 50-278 P 50-352 F		8210040332* 8210050079 8210050083 8210050085* 8210050085*	50-333 (50-286 (50-333 (50-333 (
	8210040224 8210040362 8210040362 8210050197 8210050197	50-352 0 50-352 A 50-352 A 50-352 G 50-352 G		8210060091 8210060145 8210060148* 8210060181 8210060235	50-286 F 50-247 F 50-247 F 50-286 P 50-247 G
	8210050320 8210050321* 8210050321* 8210050321* 8210050382	50-277 P 50-277 P 50-277 P 50-277 P 50-352 G		82100A0235 82100A0285 82100A0292* 8210120240 8210120243*	50-247 C 50-333 5 50-333 S 50-333 R 50-333 R
	8210050382 8210060017 8210060047 8210060074 8210060083*	50-352 9 50-278 9 50-277 9 50-277 9 50-277 8		8510180041* 8510180088 8510150583* 8510150553	50-247 P 50-286 P 50-333 O 50-286 R 50-286 R
	8210060177 8210060296 8210060296 8210060353 8210070177	50-277 S 50-277 J 50-277 J 50-277 S 50-277 Q		8210190069 8210190077* 8210190411 8210190435* 8210190713	50-333 S 50-333 S 50-333 Q 50-333 Q
	8210070188* 8210130226 8210130276* 8210150069 8210150126	50-277 Q 50-278 S 50-277 Q 50-277 Q 50-252 A		8210190728 8210190734* 8210190738 8210200018 8210200024*	50-286 P 50-286 P 50-286 F 50-333 R 50-333 R
	8210150126 8210150133# 8210150133# 8210150154 8210150179#	50-352 A 50-352 A 50-352 A 50-277 B 50-277 B		8210200028 8210200039* 8210200074 8210210459 8210210470*	50-333 P 50-333 P 50-333 P 50-286 P 50-286 P
	8210150282 8210150292* 8210150356 8210150356 8210150368*	50-277 P 50-277 P 50-277 R 50-277 R 50-277 R		8210210473* 8210220326 8210250081 8210250081 8210250216	50-285 P PR 50-247 Q 50-247 G 50-247 Q
	82101 50368* 82101 50397 82101 50397 82101 50400 8210200046	50-277 R 50-352 C 50-352 C 50-277 B 50-277 P		8210250216 8210250265 8210250265 8210250272 8210250272	50-247 G 50-247 G 50-247 G 50-247 H 50-247 H
	8210200044 8210200063* 8210200066 8210200066	50-277 P 50-277 P 50-277 P 50-352 Q 50-277 P		8210260170 8210260175* 8210260306 8210260338* 8210260378	50-333 S 50-333 S 50-333 S 50-333 S
	8210200068* 8210210297 8210210297 8210210330 8210210330	50-277 P 50-277 P 50-277 P 50-277 P 50-277 P	President of US > Executive Offices	8210260386* 8210280070 8210290271 8208010022 8210070448*	50-333 S 50-286 F 50-247 O MISC FOIA
	8210220006 8210220007* 8210220170 8210220170 8210220174*	50-278 P 50-278 P 50-277 R 50-277 R 50-277 R	Project Menagement Corp	8210050184 8210060185 8210060200 8210130343 8210130435	50-537 0 50-537 0 50-537 0 50-537 0 50-537 0
	8210220174* 8210220374* 8210240112 8210240158 8210240327	50-277 P 50-352 0 50-277 S 50-352 A 50-277 P	Public Interest Research Group, New York	8210260361 8210130335 8210130335 8210130337* 8210130337*	50-537 G 50-247 G 50-247 G 50-247 D 50-247 O
Phosnix, AZ Pipe Fabrication Institute Plateau Resources, Ltd.	8210280196 8210280204* 8210040004* 8210220342 8210260019	50-277 P 50-277 P CONTRACT PR 40-8698	Public Service Co, of Colorado	8210200019 8207150440* 8210040114 8210050331 8210050337*	50-247 0 50-257 F 50-257 P 50-267 9 50-267 9

AUTHOR AFF (LIATION	ACCESSION NUMBER	SUBJECT	ľΥ	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJEC CATEGO	
	8210040273 8210040282* 8210040284* 8210080254 8210130344	50-267 50-267 50-267 50-267 50-267	P P P P		8210070314 8210070351 8210070359 8210070368 8210070371	50-311	នាធានានា
	B210130347# B210190306 B210190537 B210190543# B210190655	50-267 50-267 50-267 50-267 50-267	a r s s r		8210070375 8210070377 8210070380 8210070388 8210080241	50-311 50-272	9 9 8 9
	8210190667* 8210190701 8210190706* 821021008(* 8210210089*	50-267 50-267 50-267 50-267 50-267	ւ Ե Ե		821,006,0296 821,012,0328 621,013,014 621,013,017,01 821,013,021,9	50-311 50-272 50-311 50-311 50-311	8 6 8 8 8
	8210220359 8210250083 8210270104 8210270113* 8210270118*	PR 50-267 50-267 50-267 50-267	F p p		8210130227 8210130340 8210130345 8210130351 8210130358	50-311 50-311 50-311	99999
Public Bervice Co of Indiana, Inc	8210280382 8210010230 8210130545 8210250130 8210270237	71-9044 PR MISC 50-546 PR	g		8210130554 8210150057 8210150058 8210150066 8210150066		9
Public Service Co. of Now Hampshire	8210290240 8210010465 8210010465 8210010470* 8210010470*	PR 50-443 50-443 50-443 50-443	A A A		8210150071 8210150073 8210150080 8210150088 8210150089	50-311 11E-02	8 8 8 8
	B210040112 B210040112 B210040173 B210040193 B210050199	50-443 50-443 50-443 50-443 50-443	A A A A		8210150093 8210150099 8210150109 8210150111 8210150118	50-311 50-311 50-311 50-272 50-311	8 8 8
	B210050199 B210070105 B210130434 B210150510 B2101B0001	50-443 50-443 50-443 50-443 50-443	A A A A		82101 50121 82101 50127 82101 50140 82101 50148 82101 50155	50-272	8 8 9
	82101 90126 82101 90136 82101 90136 82101 90136	50-443 50-443 50-443 50-443 50-443	s s s s		8210150311 8210150320 8210150339 821016009 8210170507		8 8 8
	8210240149 8210240930 8210270153 8210270153 8210270166	50-443 56-443 56-443 50-443 50-443	11 15 0 0		8210190507 8210190515 8210190515 821019065 8210190651		8 6 6
Public Bervice Electric & Gas Co of New Jersey	8210270164 8210280117 8210280117 8210010045	50-443 50-443 50-443 50-311	0 A A S		8210200010 8210200014 8210200085 821020080 8210210134	50-272	19 12 13 13 13 13 13 13 13 13 13 13 13 13 13
	82100 10123 82100 10128# 82100 10144 82100 10150# 82100 10181	50-311 50-311 50-311 50-311 50-272	9 9 9 9		B210210144 6210220275 6210220326 8210230053	50-272 50-272 PR 50-311	8
	82100 10172* 82100 1023/ 82100 10237* 82100 10344 82100 10355*	50-272 50-311 50-311 50-311 50-311	8 8 8 8				
	82100 10383 82100 10390* 82100 10407 82100 10412* 82100 10419	50-272 50-272 50-311 50-311 50-311	6 8 8 8				
	8210010423* 8210010455 8210010461* 8210060326* 8210070221	50-311 50-311 50-311 50-354 50-311	8 9 9 9				
	B210070231* B210070243 B210070246 B210070248* B210070249	50-311 50-311 50-311 50-311	8 8 8 8 8	Puget Bound Powi			
	8210070252* 8210070254 8210070258* 8210070305	50-311 50-311 50-311 50-272	9 9 8				

AUTHOR AFF ILIATION	ACCESSION NUMBER	SUBJECT	Y	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
	8210130367 8210130478 6210130478 8210200045 8210200058	50-522 50-522 50-522 50-522 50-522	6 0 0		8210190331 8210190594 8210190598* 8210190603* 8210250037	50-312 P 50-312 P 50-312 P 50-312 P 71-9094
Purdue Research Foundation	8210210337 8210210337 8210210339* 8210210339* 8210120342*	50-522 50-522 50-522 50-522 CONTRACT	B B B		8210250065 8210250094 8210250386 8210250390# 8210260231	50-312 F 50-312 F 50-312 S 50-312 S 50-312 P
Pordue Univ Pyle, R S	8208270011 8210250043 8210250063 8210250043 8210260429	ACRS 50-259 50-259 50-259 50-259	0 0	Safe Power for Maine San Clemente, CA Sandia Laboratories	8210280228 8210260457 8210260465# 8210120556# 8207270240#	50-312 P 50-309 G 50-309 G CONTRACT FOIA
RF Reedy, Inc	8210260429 8210260429 8210250247 8210280157 8210280272	50-259 50-259 50-275 50-275 50-275	Q Q R R R		8210050388 8210050397 8210060004 8210070413* 8210150552	NUREG NUREG NUREG 71-9150 NUREG
Radiation Management Corp Reed, J O Research Counsel of Washington Richards, Brandt, Miller & Nelson	8210040037* 8210150178* 8210060197 8210060403 8207110026	50-445 50-322 50-483 FOIA FOIA	G T G		8210150571 8210150631 8210250033* 8210260211 8210270338	NUREG RES NUREG NUREG NUREG
Richland, WA, Ridihalgh, Eggers & Associates Riverside, CA Robert L Cloud Associates, Inc	8210210161* 8210210505* 8210270085* 8210250356 8210080078	CONTRACT CONTRACT 71-6639 PROJ 50-275		Sandvik Special Metale Corp Santa Monzca.CA	8210290399 8210270143 8210280032 8210280043 8210080077	RES XPORTLIC XPORTLIC XPORTLIC 50-142 8
Rochester Oas & Electric Corp	8210080080* 8210250221 8210270184 8210270185* 8210010357	50-275 50-275 50-275 50-275 50-244	Ե Ե Ա	Scandpower, Inc Science Applications, Inc	8210040311 8210040319* 8206210571* 8210040346* 8210040349*	TOPREP TOPREP 50-266 P 50-537 A 50-537 A
	8210010365* 8210010367* 8210010444 8210040281 8210040284*	50-244 50-244 50-244 50-244 50-244	Р Р Р		8210040350* 8210040351* 8210040355* 8210040357* 8210040412*	50-537 A 50-537 A 50-537 A FDIA CONTRACT
	8210040288* 8210070030* 8210130195 8210130199* 8210130439	50-244 50-244 50-244 50-244 50-244	P 8 8 0		8210060447* 8210120357* 8210120422* 8210170025* 8210170037*	50-537 D CONTRACT CONTRACT CONTRACT CONTRACT
	8210150643* 8210150648* 8210190591* 8210190618* 8210190637*	50-244 50-244 50-244 50-244 50-244	F Q Q	Science Management Corp	8210270413* 8210270419* 8210270428* 8210270320* 8210270006*	50-397 X CONTRACT 70-1113 50-206 V COMMISSION
	8210190647* 8210190703 8210220352* 8210220360* 8210220363	50-244 50-244 50-244 50-244 PR	G G G	Scioto Memorsal Hosp Portsmouth, OH Seaccast Anti-Pollution League	8207070324* 8210060194 8210060194 8210060206* 8210060206*	70-2748 50-443 G 50-443 G 50-443 G 50-443 G
Rockland Cititens for Safe Energy	8210250275 8210250334 8210250343* 8210270217* 8210200019	50-244 50-244 50-244 50-244 50-247	P 9 8 0	Senate Sensible Maine Power	8210060214* 8210060214* 8208010016* 8210030236 8210200065	50~443 Q 50~443 Q 50~289 H 50~309 Q 50~309 Q
Rockland County, NY Rockwell International Corp	8210220375 8210130054* 8210130315* 8210170182* 8210220321	50-247 CONTRACT 50-537 CONTRACT PR	A	Shaw, Pittman, Potts & Troubridge	6210290303 8210010345 8210010457 8210050255 8210050255	50~309 G 50~440 G 50~440 G 50~440 G
Rocky Mountain Energy Co Rolf Jensen & Associates: Inc	8210180398 8210180405* 8210250043 8210190185*	40-8380 40-8380 40-9697 50-320	F		8210050374 8210050374 8210070124 8210070194	50-440 0 50-440 0 50-382 0 50-287 0
Rondout Associates Ropes & Gray	8207180077 8210130314 8210270153 8210270153 8210270166 8210270166	50-307 50-443 50-443 50-443 50-443	0 0 0		8210070197 8210070405 8210080086 8210080090 8210080094 8210120262	50-382 0 50-440 0 50-382 0 50-382 0 50-289 6 50-483 0
SEP Owners Oroup Sacramento Municipal Utility District	8210130326 8210010057 8210050220 8210070287* 8210070294*	50-10 50-312 50-312 50-312 50-312	P P Q Q		8210120267 8210130275 8210130161 8210150228 8210150467	50-266 G 50-287 G 50-440 G 50-440 G
	8210070331# 8210130175 8210130599 8210190278 8210190285#	50-312 50-312 PR 50-312 50-312	а Р R R		8210180155 8210200009 8210200007 8210200013# 8210200013*	50-440 Q 50-400 Q 50-400 Q 50-400 Q 50-400 Q

AUTHOR AFF IL IATION	ACCESSION NUMBER	SUBJECT		AUTHO AFF (LIAT		ACCESSION NUMBER	SUBJECT	
	6210200021* 6210200021* 6210200033 6210210173 6210210179*	50-400 50-400 50-289 50-320 50-320	6 6 6 6		***************************************	8210010348 8210050175 8210050210 8210050324 8210050324	50-395 50-395 50-395 50-395 50-395	8 E F
	8210210266 8210210284 8210210284 8210210353 8210210353	50-320 50-440 50-440 50-440 50-440	G G G G			821,0080290 * 621,0080276 821,0120248 621,0180156 621,0180162 *	50-375 50-375 50-375 50-375 50-375	թ թ
	8210210365 8210210372 8210210374 8210220305 8210220305	50-483 50-382 50-287 50-440 50-440	6 6 6 0			8210190352 8210190457# 8210190505 8210190513 8210190553	50-375 50-375 50-375 50-375 50-375	ն Ե Ե
	8210220307 8210220307 8210220394 8210220394 8210220405*	50-440 50-440 50-440 50-440 50-440	0 0 0 0			8210220340 8210220346* 8210220353 8210220438 8210220443*	50-375 50-375 PR 50-375 50-375	8 8 8
	8210220405* 8210250248 8210250253* 8210250279 8210250299	50-440 50-483 50-483 50-440 50-440	G G G G			8210250330 8210250339* 8210260140 8210260159 6210260166*	50-395 50-395 50-395 50-395 50-395	д Р Р
	8210250322 8210250322 8210240406 8210240423 8210280216	50-440 50-440 50-266 50-382 50-440	0 G G			8210240172 8210270245 821027027J 8210270284 8210270284*	50-395 PR PR 50-395 50-395	8 8
	8210280216 8210280231 8210280231 8210280246 8210280253	50-440 50-440 50-440 50-440 50-266	0 6 6 0	South Carolina, State		8210270335 8210270338* 8210130506 8210180106 8210170444*	50-395 50-395 50-413 50-413 50-395	8 9 9
Shoreham Opponents Coalition	8210280360 8210280387 8210290287 8210150307* 8210150324*	50-287 50-382 50-440 50-322 50-322	6 6 6 6	Southern California Ec	lison Ca	9210040177 9210040323 9210050008 9210050012* 9210050016	50-204 Toprep 50-361 50-361 50-361	9 8 8
	8210150337* 8210150351* 8210150345* 8210150393* 8210150402*	50-322 50-322 50-322 50-322 50-322	6 6 6			8210050019* 8210050024* 8210050029* 8210050032* 8210050037*	50-361 50-361 50-361 50-361 50-361	8 9 9
	B210150410* B210150422* B210150527* B210200034 B210250057*	50-322 50-322 50-322 50-322	0 0 0 0			8210050041* 8210050044* 8210050048* 8210050050* 8210050098	50-361 50-361 50-361 50-361 50-361	6 6 6
3serra Club	8210060195 8210120327 8210210232 8210210357 8210210453	50-537 50-537 50-537 50-537 50-537	G G G			8210050098* 8210050101* 8210050151 8210050234* 82100502241	50-361 50-361 60-361 50-361	0 0 0 0
	8210220248 8210220288* 8210220295* 8210240397 8210240404*	50-537 50-537 50-537 50-537 50-537	0 0 0 0					
igma Chemical Co	8210130072 8210270194 8210280403 8210250054 821025005&*	XPORTLIC XPORTLIC XPORTLIC 40-8602 40-8602	;					
inclair. M	8210270048 8210070132 8210070132 8210070136 8210070136	40~8602 50-329 50~329 50~329 50~329	0 0 0					
nnissippi Alliance for the Environment SAFE:		50-329 50-329 50-329 50-454	0					
all Business Administration	8210210346 8210210347* 8210210347* 8210180338* 8210180348* 8210210444*	50-454 50-454 50-454 CONTRAC CONTRAC	Ť					
mervell County, TX uth Caroline Electric & Gas Co	8210270221* 8210270223* 8210130074* 8210010167	CONTRAC CONTRAC CONTRAC 50-395	T T					

AUTHOR AFF ILIATION	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGGAY
	8210150482 8210150482 8210190309 8210190317* 8210190323*	50-361 C 50-361 G 50-361 S 50-361 S 50-361 S		8210150324* 8210150337* 8210150351* 8210150365* 8210150393*	50-322 G 50-322 G 50-322 G 50-322 G 50-322 G
	8210190328* 8210190455* 8210190490 8210190506* 8210190534	50-361 S 50-361 Q 50-206 S 50-206 S 50-361 P		8210130402* 8210130410* 8210130422* 8210150527* 8210200036	50-322
	8210190560 8210190560 8210190625 8210190625 8210190625	50-361 P 50-361 P 50-204 F 50-206 F 50-206 F		8210200076 8210200083* 8210200089* 8210250058 8210250059*	50-322 G 50-322 G 50-322 G 50-322 G
	8210250137 8210250140* 8210250207 8210250214 8210250218*	50-361 S 50-361 S 50-361 S 50-361 S 50-361 S		8210240232 8210240239+ 8210240242+ 8210240244+ 8210240409	50-322 T 50-322 T 50-322 T 50-322 F 50-322 H
	821 02 50227* 821 02 50269 821 02 50273* 821 02 50260 821 02 50302	50-361	Sugarman, R J	8210290283 8210010244 8210010244 8210180204 8210180204	50-322 G 50-352 G 50-352 G 50-352 G 50-352 G
	8210260214 8210260249 8210260272 8210260416 8210260424*	50-206 P 50-206 P 50-206 P 50-361 P 50-361 P		8210180208* 8210180208* 8210180217 8210180217 8210180223	50-352
	8210260435* 8210260448 8210260450 8210260472 8210260477*	50-361 P 50-206 P 50-206 P 50-206 P 50-208 P		8210180223 8210180224 8210180224 8210180226* 8210180226*	50-352 0 50-352 0 50-352 0 50-352 0 50-352 0
	8210280046 8210280080 8210280086 82102800869	50-206 B 50-206 B 50-361 B 50-361 S 50-361 A	Sunflower Alliance	8210180253 8210180253 8210010250 8210010250 8210010323	50-352
Southern California, Univ of Southport.NC Southwest Research Institute Spain	8210290069* 8210270408 8210130061* 8210120330* 8206060015*	50-361 A 50-278 0 CONTRACT CONTRACT COMMISSION		8210010323 8210050173 8210050173 8210050228 8210050228	50-440 0 50-440 0 50-440 0 50-440 0 50-440 0
Spiegel & McDiarmid St Joseph Hosp Albuquerque, NM St Lukes Hosp Milwaukee,WI Stamiris, B	8210250356 6210120066* 6210290247 8210050238 6210050238	PROJ FOIA REGOD 50-329 G 50-329 G		8210050242 8210050242 8210050252 8210050252 8210250331	50-440 0 50-440 0 50-440 0 50-440 0
Standardized Nuclear Unit Power Plant System	8210050240 8210050240 8210210370 8210080260 8210080260	50-329 G 50-329 G 50-329 G 50-482 K	Switzerland Systems Control, Inc TRC Environmental Consultants, Inc	8210270158 8210040335# 8210040340# 8210050418 8210150290#	XFORTLIC GAPPP GAPPP NUREQ 50-322 Y
	8210080240 6210080244* 8210080244* 8210080244* 6210220252	50-482 K 50-482 K 50-482 K 50-482 K 50-482 K	TRW, inc Target Research, inc Teledyne Energy Systems	8210120550* 8210270373 8210270376* 8210080123 8210080272	CONTRACT 40-8624 40-8624 50-275 P
State,Dept.of, Bureau of Oceans & Internati Environ & Scientific Affairs	8210220253* 8210260274 8210040403	50-482 A 50-482 A XPGRTLIC	Teledyne Engineering Services	8210050191* 8210080191 8210080193* 8210190583 8210190584	GA999 50-275 や 50-275 P 50-275 P 50-275 P
Steam Cenerator Owners Oroup Stearns-Roger Engineering Corp	8210080119 8210080126 8210090152 8210220316	XPORTLIC XPORTLIC TOPREP PR		B210190584 B210250167 B210250171*	50-275 P 50-275 P 50-275 P
Stevenson & Associates Stone & Webster Engineering Corp	8210150265* 8210150265*	50-213 P 50-322 T 50-322 T		\$210250197 \$210250201* \$210250210 \$210250210	50-275 R 50-275 R 50-275 P 50-275 P
	8210150270* 8210170472 8210170500* 8210220348	50-322 T 50-395 P 50-395 P PR 50-275 R		8210250240 8210250291 8210250318	50-275 P 50-275 P 50-275 P
Stone & Webster, Inc. Stoner Associates, Inc Structural Dynamics Research Corp Scient County, NY	8210250308 8210250237 8210150281* 8210210301* 8210180143*	PR 50-322 T 50-329 A 50-358 A		8210250318 8210280211 8210280212* 8210280277 8210290319	50-275 P 50-275 R 50-275 R 50-275 P 50-275 R
Suffolk County, NY	8210150309* 8210050383 8210050383	50-322 0 50-322 0 50-322 0 50-322 0	Teledyne Wah Chang Albeny Tennessee Velley Authority	8210290322* 8210270011 8210270076 8210270391 8208170297	SO-275 R XPGRTLIC XPORTLIC XPORTLIC XPORTLIC

CORPORATE SOURCE INDEX

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGOR		AUTHOR AFF ILIATION	~	ACCESSION NUMBER	SUBJECT CATEGOR	
	820917004B 8209170101 8209300170 8209300175* 8210010011	50-327 50-259 50-259 50-259 50-438	E E E E E E E E E E E E E E E E E E E			8210080219 8210080219 8210080222 8210080222 8210080222	50-259 50-259 50-259 50-438 50-438	G G S S
	B210010104* B210010104* B210010104* B210010108 B210010115*	50-259 50-259 50-259 50-327 50-327	0 0 9 9			8210080247 8210080247 8210080247 8210080247 8210080247	50-390 50-390 50-390 50-390 50-390	9 8 9 9 5
	8210010135* 8210010197* 8210010304* 8210010304* 8210010304*	50-327 50-438 50-259 50-259 50-259	Q Q Q Q			8210080247 8210080255 8210080255 8210080278 8210080278	50-390 50-390 50-390 50-438 50-438	9 9 9
	8210010341* 8210010420* 8210010427* 8210050053 8210050042	50-390 50-518 50-438 TGPREP 50-390	Q Q Q			8210080280 8210080280 8210080291 8210080291 8210080292	50-390 50-390 50-390 50-390 50-438	5 5 5 5 5
	8210050062 8210050094 8210050094 8210050099 8210050104	50-390 50-438 50-438 50-390 TOPREP	ន ន្ត			8210060292 8210080307 8210080310 8210080310 8210120284	50-438 50-438 50-390 50-390 50-327	8 8 8 9
	8210050114 8210050114 8210050115 8210050115 8210050119	50-390 50-390 50-438 50-438 50-438	ន ព ព ព ព			8210120289* 6210120269* 6210130142 6210130150 8210130150	50-327 50-327 50-259 50-327 50-327	թ Р Р
	8210050119 8210050158 8210050158 8210050216 8210050216	50-438 50-390 50-390 50-327 50-327	9 8 8 P			8210130157 8210130162* 8210130165 8210130169* 8210130172	50-296 50-296 50-259 50-259 50-259	8 9 8 8
	8210030249 8210050249 8210050268 8210050271* 8210050285	50-438 50-438 50-259 50-259 50-566	8 9 P 8			8210130176+ 8210130247 8210130247 8210130317 8210130377	50-259 50-390 50-390 50-327 50-390	8 8 8 8
	8210050293 8210050293 8210050293 8210050293 8210050293	50-390 50-390 50-390 50-390 50-390	9 8 8 8 8			8210130384 8210130407 8210130429 8210130438* 8210130442	50-370 50-438 50-259 50-259 50-327	8 8 9 9 8
	8210050316 8210050316 8210050344 8210050344 8210050407	50-370 50-370 50-370 50-370 50-438	9 8 0 0 S			8210130452* 8210130521 8210130540 8210130560 8210130865	50-327 PR 50-390 50-390 50-259	8 9 9
	8210050407 8210060205 8210060205 8210060219 8210060221*	50-438 50-390 50-390 50-327 50-327	# # # # # # # # # # # # # # # # # # #			8210130549* 8210130572 8210130579* 8210150105 8210150181*	50-259 50-328 50-328 50-259 50-438	8 6 8 0
	8210040245 8210040270* 8210040274 8210040279 8210040279	50-296 50-296 50-439 50-390 50-390	5 9 8 8			8210150218 8210150218 8210150230* 8210150230* 8210150231*	50-259 50-259 50-390 50-390	
	8210060280 8210060280 8210060301 8210060304* 8210060347	50-390 50-390 50-259 50-259 50-327	\$ 9 P P			8210150241* 8210150251* 8210180117 8210180117		
	8210060352* 8210060352* 8210060409 8210060412* 8210060414	50-327 50-327 50-259 50-259 50-259	F # 8 8 8					
	8210040422* 8210070133 8210070255 8210070253 8210070348	50-259 50-259 50-259 50-259 50-438	8 T P A					
	8210070348 8210080160 8210080160 8210080160 8210080160	50-43B 50-390 50-390 50-390 50-390	\$					
	8210080218 8210080218 8210080218 8210080218	50-390 50-390 50-259 50-259 50-259	₽ ₽					

AUTHOR AFP ILIATION	ACCESSION NUMBER	CATEGO		AUTHOR AFF ILIATION	ACCESSION NUMBER	SUBJECT CATEGOR	fΥ
	8210220225 8210220271* 8210220271* 8210220350 8210220422*	50-390 50-438 50-438 50-438 50-438	6 0 8 0		6210290236 6210290236 6210290236 6210290236 6210290236	50-390 50-390 50-390 50-390 50-390	5 5 6 5
	8210220456* 8210220474* 8210220474* 8210250067 8210250070*	50-390 50-327 50-327 50-260 50-260	G G P P		8210270248 8210270248 8210270265 8210270266 8210270266	50-390 50-438 PR 50-390 50-390	5 6 9
	8210250096 8210250096 8210250096 8210250101* 8210250101*	50-259 50-259 50-259 50-259 50-259	ր Գ Գ		8210290274 8210290274 8210290274 8210290277 8210290279*	50-328 50-328 50-328 50-327 50-327	9 8 8 8 9
	8210250101* 6210250236 8210250236 6210250236 8210250244	50-259 50-259 50-259 50-259 50-250	4 4 4 4		8210270317 8210270321* 8210270324 8210270324 8210270328	50-259 50-259 50-438 50-438 50-390	9999
	8210250244 8210250244 8210260100 8210260100 8210260105	50-250 50-250 50-390 50-390 50-438	F F W # W		8210290328 8210290328 8210290328 8210290371*	50-390 50-390 50-390 50-259 50-259	មាខាមា
	8210260105 8210260107 8210260148 8210260174 8210260174	50-438 50-438 50-327 50-370 50-370	89 4 4 4	Teton Exploration Drilling Co , Inc Texas A & H Univ Texas Nuclear Div (subs of Ramsay Eng Co)	8210280412 8210250195 8210250198* 8210060411*	40-8728 50-341 50-341 FOIA	F
	8210260186 8210260186	50-390 50-390	8	Taxas Tech Univ Taxas Utilities Generating Co	8210190177* 8210010302	CONTRACT PR	
	8210260188 8210260189 8210260189	50-328 50-390 50-390 50-390	8 F F		8210040024* 8210040024* 8210040026* 8210040026*	50-445 50-445 50-445 50-445	9 9
	6210240189 6210240194* 6210240212 8210240222*	50-390 50-390 50-328 50-259	8 8 8 8 8		8210040030# 8210040030# 8210040033* 8210040033* 8210040037#	50-445 50-445 50-445 50-445 50-445	00000
	8210260228 8210260251 8210260320 8210260320	50-327 50-438 50-390 50-390	P 8 8		8210040037* 8210040318 8210130299 8210130299 8210130576	50-445 50-445 50-445 50-445	99991
	8210590355 8510590350 8510590350 8510590350	50-390 50-390 50-390 50-390 50-438	ខ្លួនមន្ទ		8210130576 8210180006 8210180006 8210180008#	50-445 50-445 50-445 50-445 50-445	F K K K
	8210260322 8210260347 8210260353* 8210260361 6210260390	50-438 50-260 50-260 50-259 50-390			8210220372 8210250338 8210250338 8210250344 8210240375	PR 50-445 50-445 50-445 50-445	8 6 6 8
	#210260407* #210260408 #210260408 #210260417	50-259 50-390 50-390 50-260	8 8 8	Texas, State of Texas, Univ of Thatcher, T L Three Hile Island Alert	8210040042* 8210050174 8210080073 8210050176 8210050237	50-445 50-192 50-522 50-289 50-289	0 0 0 0 0
	8210260446* 8210260451 8210260451 8210280209 8210290049	042-08 078-08 078-08 078-08	9 S S A S	Toledo Edison Co	8210280234 8210050235 8210050258* 8210050304	50-287 50-346 50-346 50-346	H C P
	8210270052 8210270054 8210270057* 8210270059 8210270059	50-390 50-259 50-259 50-438 50-438	8 8		8210050310 8210050318* 8210050323 8210050327* 8210050333	50-346 50-346 50-346 50-346 50-346 50-346	4 4 4 4
	8210290062 8210290066* 8210290091 8210290094* 8210290178	50-259 50-259 50-328 50-328 50-390	8 8 8		8210050359 8210050361* 8210060314 8210070005* 8210070006*	50-346 50-346 50-346 50-346 50-346	SEOFF
	8210270187 8210270187 8210270187 8210270187 8210270187	50-518 50-518 50-518 50-518 50-518	8 8 8		8210080288* 8210130124 8210130356 8210130356 8210130366*	50-346 50-346 50-346 50-346	. 0969
	8210290231 8210290232* 8210290236 8210290236 8210290236	50-294 50-294 50-390 50-390 50-390	8 8 8 8		8210130404 8210130410* 8210180131 8210180135	50-346 50-346 50-346 50-346 50-346	8 8 8 9

AUTHOR AFF (LIATION	ACCESSION NUMBER	SUBJECT		AUTHOR AFF IL IATION	ACCESSION NUMBER	SUBJECT CATEGORY
***************************************	8210180137* 8210190254 8210190261* 8210190303 8210190358	50-346 50-346 50-346 50-341 50-346	3 3 5 5		8210240108 8210270173 8210270204 8210270213 8210270218	70-820 70-820 70-820 70-820 70-820 70-820
	0210190359# 0210190623	50-346 50-346	8 Г	Universal Technical Testing Laboratories, Inc	8210220314	PR
	8210210458 8210210554* 8210210559*	50-346 50-346 50-346	թ թ	Uranium Resources, Inc Utah, State of Utah, Univ of	8210250013 8210250013 8206270016* 8210260230*	40-8784 40-8786 COMMISSION 50-72 R
	8210250226 8210250231* 8210250270 8210250279*	50-346 50-346 50-346 50-346	9 9 9	Utility Morkers Union of America Vermont Yankee Nuclear Power Corp	8210240234 * 8210290240 8210040113 8210130189 8210130193 *	50-72 R PR 50-271 Q 50-271 R 50-271 R
, Parks, Seliger, Simonoff & itse	8210240283 8210240283 8210280075 8210280076* 8207180051	50-345 50-345 50-345 50-346 50-219	Н 8 8 6		8210150447 8210180190 8210190022 8210190029* 8210210204	50-271 P 50-271 F 50-271 B 50-271 S 50-271 S
ų Pinæs Fechnology	8210120264 8210150353* 6210220198 8210220198 8210220198	50-528 50-382 50-528 50-528 50-528	R A R R		8210210214+ 8210220416+ 8210270430+ 8210270432+ 8210280138+	50-271 B 50-271 G 50-271 F 50-271 F 50-271 F
inerica Delavat, inc	8210220244 # 8210220244 # 8210220244 # 8210050270 # 8210050275 #	50-528 50-528 50-528 GA999 GA999	A A	Vester J. Thompson, Jr., Inc Virginia Electric & Power Co	8210280143* 8210220246 8206160306* 8207230301 8207230303*	50-271 F PR 50-280 Q 50-339 S 50-339 S
uclear. Inc	8210070452 8210080037 8210080040* 8210080042* 8210080108	XPORTLIC XPORTLIC XPORTLIC XPORTLIC XPORTLIC			9208090114 8208090114 8210010103 8210010107* 6210010125	50-338 P 50-339 P 50-337 P 50-337 P 50-280 F
	8210080130 8210080133 8210270147 8210270168 8210280052	XPORTLIC XPORTLIC XPORTLIC XPORTLIC XPORTLIC			8210010125 8210010125 8210010140 8210010145* 8210010163	50-280 F 50-280 F 50-330 S 50-330 S
ite Potor Transit Co (subs of	8210280056 8210280059 8210150405	XPORTLIC XPORTLIC 70-1739			8510010533 8510010512* 8510010502 8510010178*	50-338 9 50-338 5 50-338 5 50-339 5
P	6210120496* 6210120266*	CONTRACT 50-275	P		6210010236*	50-339 B
egy. Inc (Formerly Nuclear	B210050095 B210130302	27-39 50-84	P		8210010246* 8210010247 * 8210040277	50-338 P 50-338 P 50-338 P
arbide Corp	8210130306* 8210170246 8210170256*	50-54 40-299 40-299	P		8210040277 8210040270+ 8210040297+	50~338 P 50~338 P 50~338 P
	8210220491 8210250019 8210250021* 8210270047	40-299 40-299 40-299 70-687			8210040315* 8210040325* 8210050071	50-338 P 50-338 P 50-280 S
ectric Co	8210270070* 8210050277 8210120262 8210130555* 8210210365	70-687 50-483 50-483 50-483 50-483	A 0 0		8210050074* 8210050076 8210050078* 8210050081 8210050081	50-280 S 50-280 F 50-280 S 50-280 S
Concerned Scientists	8210250248 8210250253* 8210120274 8210130335 8210130335 8210130337*	50-483 50-483 50-289 50-247 50-247 50-247	0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0		B5100#010## B5100#010## B5100#0045# B5100#00### B5100#00################################	
	8210130337* 8210220274* 8210220410 8210220465 8210280242	50-247 50-537 50-247 50-269 50-247	0 0			
irlings, Inc. (subs of UAL)	8510550319	PR				
agingers & Constructors, Inc. 18 Raythean Co.)	8210050206#	50-443	A			
iclear Corp	8210260205 8210270060# 8210200104	50-324 50-537 70-820	S C			
	8210250012 8210250014 8210250016 8210250032 8210260038	70-820 70-820 70-371 40-8781 70-820				

AUTHOR AFF IL IATION	ACCESSION NUMBER	SUBJECT CATEGOR	łY	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY	Y
	8210120297 8210120297 8210120305* 8210120305* 8210120305*	50-280 50-280 50-280 50-280	P P P P		8210270258 8210280130 8210280266 8210290264 8210290270*	50-338 50-280 50-280 50-280 50-280	Р Р В В
	8210120305* 8210120305* 8210130112* 8210130114* 8210130114*	50-280 50-280 50-338 50-338 50-338	ր բ F F	Virginia, Univ of	8210290276* 8210290282* 8210290337 8210290347* 8210060086	50-280 50-280 50-338 50-62	5 5 9 9 9
	8210130204 8210130204 8210130208* 8210130213* 8210130216*	50-280 50-280 50-280 50-280 50-280	ស	Washington Lægal Foundation Washington Public Power Supply System	8210080237 8210010322 8210130277 8210010020 8210040255	50-62 PR PR 50-508 50-397	P H A
	8210130427 8210130431* 8210130500 8210130507* 8210150054	50-280 50-280 50-280 50-280 50-280	Q G S S		8210050124 8210050154 8210050348 8210060223 8210060319	50-397 50-397 50-397 50-397 50-397	E A A C
	8210150095 8210150139 8210150359 8210150394 8210190264	50-280 50-280 50-281 50-280 50-338	5 5 5 5 5		B210040445 B210070141 B210070144* B210070161* B210070297	50-397 50-397 50-397 50-508 50-460	F A Q S
	8210190270* 8210190321 8210190329 8210190337* 8210200043	50-338 50-339 50-338 50-338 50-280	8 8 8 9		8210070297 8210070302# 8210070311 821007033B	50-460 50-397 50-460 50-460 50-460	0 8 8
	8210200043 8210200048* 8210200048* 8210200053* 8210210053*	50-280 50-280 50-280 50-280 50-280	역 역 기 기		8210070370 8210070387* 8210070387* 8210080095 8210080100*	50-397 50-460 50-460 50-397 50-397	8 9 8 8 8
	8210210055* 8210210055* 8210210058* 8210210058* 8210220011	50-280 50-280 50-280 50-280 50-238	ድ ድ ፑ ፑ		8210080195 8210080275 8210080304 8210120194 8210120197	50-397 50-397 50-397 50-508 50-508	0 6 6 8
	8210220011 8210220095 8210220095 8210220097* 8210220100*	50-338 50-280 50-280 50-280 50-280	P 8 8 8 8		8210120200* 8210130188 8210130174 8210130217 8210130425*	50-508 50-397 50-397 50-397 50-460	K A F S
	6210220170 8210220178 6210220178 6210220178 8210220178	50-280 50-280 50-280 50-280 50-280	р Р Р Р		8210130432* 8210130432* 8210130575 8210170576 8210170582*	50-460 50-460 50-397 50-397 50-397	E 0 0
	8210220200 8210220227 8210220234* 8210220373 8210220373	50-938 50-938 50-938 PR 50-280	9 9		8210190584* 8210190646 8210190708 8210190764 8210210045	50-397 50-397 50-397 50-397 50-397	K O L E
	8210220392 8210220398* 8210220408* 8210220413* 8210220413	50-280 50-280 50-280 50-280 50-339	9 9 9 9		8210210049 8210210148 8210210276 8210210327 8210260113*	50-397 50-397 50-397 50-397 50-397	C E C A
	8210220421* 8210220424 8210220435* 8210220441 8210220450*	50-339 50-281 50-281 50-339 50-339	6 8 8 8	Washington, State of Waste Mahagement Group, Inc	8210270012 8210280170* 8210280277* 8210240442 8210280331*	50-508 50-460 50-460 50-397 CONTRACT	A G Q A
	8210250208 8210250208 8210250212* 8210240133 8210240133	50-338 50-338 50-338 50-338 50-338	F F P P	West Branch Conservation Association West Chicago, IL	8210180203 8210200019 8210210390 8210210397* 8210250315	50-247 50-247 50-247 50-247 40-2061	0 0
	8210240134* 8210240134* 8210240281 8210240287* 8210240270	50-338 50-338 50-339 50-339 50-338	P 8 8 8	Westchester County, NY Westchester Peoples Action Coelition, Inc Western Geophysical Western Piping & Engineering Co., Inc	8210250287 8210200019 8209300332* 8209300336* 8210120285*	50-247 50-247 50-213 50-213 94999	ь С С
	8210260293* 8210260346 8210260360* 8210270160 8210270204	50-338 50-339 50-339 50-338 50-338	8 8 8 P	Westinghouse Electric Corp	8210120293* 8005070094 8005070099* 8210010189 8210040196*	GA999 PT21 PT21 70-1151 GA999	
	8210270212 8210270212 8210270215* 8210270220* 8210270224*	50-260 50-260 50-260 50-260 50-260	8 8 8		8210050178* 8210080038* 8210080227 8210080227* 8210080321	GA999 FOIA TOPREP TOPREP XPORTLIG	c

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT	Y	AUTHOR AFFILIATION	ACCESSION NUMBER	CATEGO	
	6210080323* 8210120250* 8210130250* 8210130420 8210130426*	XPORTL10 50-395 50-537 50-22 50-22			8210280253 8210280295 8210280295 8210280298* 8210280298*	50-266 50-266 50-266 50-266 50-266	ф Б Б
	8210130447 8210130535± 8210190429± 8210190508± 8210190607	PT21 50-344 50-282 50-395 TOPREP	թ թ	Wisconsin Public Service Corp	8210270274 8210010179 8210010186* 8210010232 8210010307	50-266 50-305 50-305 PR PR	ե ե
	8210210054 8210220152 8210220154 8210250128* 8210250141*	NUREG TOPREP NUREG GA999 GA999			8210040156 8210040159* 8210040162* 8210050263 8210060312	50-305 50-305 50-305 50-305 50-305	8 8 9
	8210260305 8210260340 8210260351* 8210270014 8210270017	TOPREP TOPREP TOPREP XPORTLIC XPORTLIC			82100 60328 82100 70108 82101 30282 82101 30300 82101 30581	50-305 50-305 PR 50-305 50-305	0t P F
ntinghouse Operating Plents Owners	8210270208* 8210270260* 8210080294	50-338 50-338 TOPREP	P P		8210170353 8210170355* 8210170356* 8210170487	50-305 50-305 50-305 50-305	6 8 8
illiams-Robinette & Associates, Inc	8210120401* 8210120604*	CONTRACT			8210240243*	50-305 50-305	8
tisan, R	8210200053 8210010250 8210010250 8210010323 8210010323	50-400 50-440 50-440 50-440 50-440	0 0 0	Wisconsin's Environmental Decade Woodward Governor Co	8210270234 8210040125 8210250120 8210150536*	PR 50-266 50-266 GA797	G
	8210050173 8210050173 8210050228 8210050228 8210050242	50-440 50-440 50-440 50-440 50-440	0000	Hyoming Mineral Corp Wyoming, State of	8210150544* 8210270180 8210270183* 8210130607 9210150597	0A999 40-8502 40-8502 40-299 40-8743	
	8210050242 8210050252 8210050252 8210250331	50-440 50-440 50-440 50-440	0 0 0		9210210254 8210260084 8210260096 8210260099* 9210280446	40-6459 40-6452 40-8781 40-8781 40-8452	
inthrop, Stimson, Putnam & Roberts isconsin Electric Power Co	82070 90085 81072 70156 82072 90257 82072 90279 82100 40119	50-247 50-266 50-266 50-266 50-266	P a k k F	Yakima Indian Nation Yale Univ,	9210280451 9210050169 9210260232 9210260239* 9210010374	40-9697 50-522 50-322 50-322 FR	e T T
	8210050005 8210050005 8210050054 8210050054 8210050055	50-266 50-266 50-266 50-266 50-266	6 6 6		8210010465 8210010465 8210040112 8210040112 8210040193	50-443 50-443 50-443 50-443 50-443	A A A A
	8210050055 8210050222 8210050221* 8210050231*	50-266 50-266 50-266 50-266	ե ե ե		8210040193 8210050199 8210050199 8210050310* 8210070105	50-443 50-443 50-443 50-29 50-443	A A G A

CORPORATE SOURCE INDEX

AUTHOR	ACCESSION	SUBJECT		AUTHOR	ACCESSION NUMBER	SUBJECT
AFFILIATION	NUMBER	CATEGOR		AFF ILIATION		CATECOR
	~-~~	~			~~~~~~	~~~~~~
	8210260165	50-29	S	8	*E01085015	50-29
	8210260169#	50-27	S			50-443
	8210260330	50-443	8	98	210280138*	50-271
	8210260428	50-29	ន			
	8210270430#	50-271	F	88	210280143*	50-271
				52	210290263	PR
	8210280085	50-29	S	Youth News 83	208290089	FOIA
	921/12/07/094	50-20	þ			

REPORT NUMBER INDEX

The subject category column in this index gives the docket number and the symbol for the category of information within that docket; for example, 50-320 P. The docket subject categories are defined in Appendix A.

Subject categories for nondocketed items are also entered in this column by symbol; for example, ACRS. These categories are defined in Appendix B and listed in the Contents. An asterisk following the accession number in this index indicates that the document is an enclosure to another document. To obtain the accession number of the principal document under which the enclosure is listed, refer to the index entitled "Cross Reference of Enclosures to Principal Documents,"

REPORT NUMBER	ACCESSION NUMBER	SUBJECT	OTHER REPORT NUMBER	REPORT NUMBER	ACCESSION NUMBER	SUBJECT CATEGOR	
1 JA 300 1000-PLN-7200 01 R00 104-92/H7KF 11410 R01 8630 1	8210070355*	50-438 A 50-219 P 50-389 E 50-358 A 50-338 P		CRBR-ARD-0119 DEY-16-0201 R01 DNS-D1-034 EDAC 175-130 02 DRF EERC 75-19	8210130250* 8210010460* 8210180199* 8210070091* 8107270198*	50-537 50-341 50-10 50-29 50-246	A A P DOE/ET 34205-33 P Q
1139 C-21 11C152 1 12-1 12-33 210050504	8210040241* 8210170668* 8210170444* 8210280178* 8210050504	50-155 P 50-213 P 50-375 P 50-277 P RES		EERC 75-21 EERC 76-16 EERC 76-8 ECC-1183-4168 ECC-EA-5307 ROI	8107270199* 8107270191* 8107270188* 8010070320* 8210280432*	50-266 50-266 50-264 50-305 50-247	0 0 0 P P TAC 12992
210060425 210070449 210080322 220120118 210120124	8210040425 8210070449 8210080322 8210120118 8210120124	RES RES RES RES	EGG-H-09782 E00-H-11782	E0G-EA-6016 E0G-EA-6017 E0G-EA-6033 E0G-EA-6091 END-81-106	8210120300# 8210070099# 8210250372# 8210270288# 8210270020#	50-213 50-27 50-213 50-155 50-537	Р Р Р
210120367 210120368 210120390 210120397 710120400	8210120367 8210120368 8210120370 8210120397 8210120400	REG REG REG REG REG	BNL-NUREO-31 B34 EGG-M-116B2 EGG-M-043B2	GA-A13010A A07 GA-A16764 GIBSAR-17-A A06 HDB/PDG-77-1 HE-146	8210290144* 8210080258* 8210270129* 8210040279* 8210150352*	TDPREP 50~267 50~584 50~369 50~341	QA-LTR-11 P UC-77 A X
10120428 10120430 10120453 10120455 10120457	8210120428 8210120430 8210120453 8210120453 8210120459	RES RES RES RES RES	Q-6-507 (R673) E00-LDFT-5937 GRNL/FTR-1365 BNL-NUREG-31755 BNL-NUREG-31775	ME-229 ME-230 ME-884 MPR-733 MPR-734	8210150343* 8210150346* 8210260493* 8210010081* 8210010085*	50-341 50-341 50-358 50-219 50-219	Q Q Е Р
10120460 10120463 10120466 10120630 10120649	8210120460 8210120463 8210120466 8210120630 8210120649	RES RES RES RES RES	BNL-NUREG-31774 BNL-NUREG-31754	NEDD-21471-01 801 NEDD-22192 NEDD-24088-1 NO4 ERR NEDD-24088-1 NO5 ERR NEDD-24146A ERR OB	8207120253# 8210190785# 8210250077# 8210250078# 8210250177#	50-447 50-254 50-260 50-260 50-254	A 79NED99R 9 82NED080 P 77NED360 P 77NED360 P 79NED273
10120653 10120654 10120657 10130409 10150412	8210120653 8210120654 8210120657 8210150409 8210150412	RES RES RES RES	DRNL/FTR-1371 E0G-CDD-6029 E0G-M-21082 E0G-M-06682	NEDD-24934 ERR RO2 NSE-50-0582 NSE0-72-0782 NSE0-88-0982 NSP-77-001 ROO	8210250184* 8210280201* 8210280204* 8210010224* 8210150500*	TOPREP 50-277 50-277 TOPREP 50-263	P DRF-F13-00023 P DRF-F13-00023 T23-00452 P 30 1777 0100
0150415 0150421 0150421 0150625 0150623	8210150415 8210150421 8210150611 8210150625 8210150631	RES RES RES RES RES	EGG-H-14082 EGG-LOFT-5982 EGG-LOFT-5733 SAND82-1855	NSP-77-003 R00 NSP-77-007 R00 NSP-77-008 NVRE0-0030 V06 N02 NVRE0-0267 R01	8210150509* 8210150504* 8210150377* 8210220142 8210270331	50-263 50-263 50-263 NUREO NUREO	P 30 1777 0102 P 30 1777 0106 P 30 1777 0026
0180407 0200102 0270421 0280292 0280323	8210180407 8210200102 8210270421 8210280272 8210280323	RES RES RES RES	E00-L0FT-5999 E00-1D-6040 E00-L0FT-6039	NUREO-0580 V11 NO9 NUREO-0749 V02 NO8 NUREO-0750 V15 NO5 NUREO-0793 NUREO-0822 DRFT	8210120119 8210120116 8210150547 8210210030 8210270345	NUREO NUREO NUREO 50-329 50-219	E p
0280039 0290017 0290399 -FRPE-282 -2-NP A01	8210280339 8210290017 8210290399 8210270208* 8210060259*	REB REB REB 50-336 F TOPREP	EGG-ID-6037 EGG-HRR-6019 BAND81-0826	NUREO-0846 NUREO-0847 801 NUREO-0857 803 NUREO-0858 NUREO-0928	8210050422 8210050405 8210060006 8210050431 8210050377	40-1941 50-390 50-528 Nureo 50-62	EE
-1743 -04261 -185-NP -216(B) -01-110 R00	8210010284* 8210120642* 8210040329* 8210180133* 8210050427*	50-329 E 50-341 / TOPREP 50-317 F 50-155 F	1	NUREG-0740 VOI NOI-2 NUREG/BR-0024 NUREG/CR-0030 NUREG/CR-0167 V20 NUREG/CR-1367 ROI	8210210024 8207280307 8210150553 8210150560 8210040004	NUREO NUREO NUREO NUREO NUREO	PNL-8A-10325 EGG-2037 Y20 8AND80-7054

REPORT NUMBER INDEX

REPORT NUMBER	AGCESSION NUMBER	SUBJECT CATEGOR!	OTHER REPORT V NUMBER	REPORT NUMBER	ACCESSION NUMBER	SUBJECT CATEGORY	OTHER REPORT NUMBER
NUREG/CR-2000 V01 NB NUREG/CR-2182 V02 NUREG/CR-2183 NUREG/CR-2227 V02	8210150577 8210210034 8210150567 8207290410	NUREQ 50-259 NUREQ NUREQ	ORNL/NSIC-200 F ORNL/NUREG/TM-4 ORNL/TM-7864 GEAP-24962-2	SAI-184-028-22 SAI-184-029-17 SAND80-0783 SCP-01-A R04	8206210571* 8210270320* 8210070413* 8210040317*		P V TTC~0079
NUREO/CR-2260 ERR	9210060417	NUREO	E00-2181	SECY-82-0728	8204200390*	FOIA	
NUREG/CR-2404 NUREG/CR-2444 VOI	8210150548 8210210054	NUREO NUREO	UCRL-53034 EPRI NP-2014	8ECY-82-072C SECY-82-142	9205270507* 9204300078*	FOIA FOIA	
NUREG/CR-2444 V02	8210220154	NUREO	EPRI NP~2014	SECY-82-186	8205280495	SECY	
NUREG/CR-2406 NUREG/CR-2609	8210050397 8210210039	NUREG NUREG	SAND81-1932 ORNL/NUREG-75	SECY-82-232 SECY-82-255	8206180042* 8206240119*	FO[A 50-251	8
NUREG/CR-2673 NUREG/CR-2710	9210210037 9210260206	NUREO NUREO	8008-M1\JKRO 1668-M1\JKRO	SECY-82-267 SECY-82-384	820A290A12 8210210503	SECY 50~289	ρ
NUREG/CR-2719	8210150569	NUREG	ORNL/1M-8278	SECY-82-399	8210220534	SECY	r
NUREO/CR-2730	8210150571	NUREO	BAN082-1150	5ECY-82-407	8210270322	SECY	
NUREG/CR-2754	8210050418	NUREO	PNL-4272	SECY-82-414	8210290214	50-275	P
NUREG/CR-2759	8210270339	NUREG	SAND82-7062	SRD-307	8205250020*		p
NUREG/CR-2761	8210050388	NUREO	SAND82-7065	T1002745 R03	8210120283*		p
NUREQ/CR-2791	8210150552	NUREG	SANDS2-7067	TER-C5257-282	8208190290*		P
NUREG/CR-2792 NUREG/CR-2820	8210050360 8210120125	NUREO NUREO		TER-C5257-294 TER-C5257-317	8209150178* 8209160459*		P TAC 12438 P
NUREG/CR-2831	8210150549	NUREG	MLH-2957	TER-C5257-318	8208170083*	50~204	P
NUREO/CR-2846	0210220135	NUREO	BNL/NUREO-51567	TER-C5257-403	8206230020*		p
NUREG/CR-2859	8210150557	NUREO	ANL-CT-81-32	TER-C5257-414	8208180082*		P
NUREQ/CR-2862	8210210041	50-201	P	TER-C5257-426	8208100269*		P
NUREG/CR-2873 V01	6510150105	NUREG	PNL-4306	TER-C5257-530	8310180059*	50~346	Р
NUREO/CR-2873 V02	8210120072	NUREO	PNL-4306	TER-C5257~542	*88100C30SB		a
NUREG/CR-2874 VOL	8210150564	NUREO	ORNL/TM-8443/V1	TER-C5257-544	8207190431*		o
NUREG/CR-2877	8210260211	NUREO	SAND81-2613	TER~C5506~151	8204030044*		P
NUREG/CR-2885 NUREG/CR-2889	8210150554 8210150550	NUREO NUREO	ANL-82-44 HEDL/THE 82-32	TER-C5506-307 TER-C5504-58	8210120640* 8202010167*		p p
			MEDELLING BE-JE				
NUREG/CR-2897 Nureg/CR-2898	8210050428 8210150574	NUREO NUREO		UCB/EERC-77/07	8107270196*		G.
NUREG/CR-2905	8210050348	NUREO		UCB/EERC-78/17 UCB/EERC-78/27 VO1	8107270194* 8107270166*		G G
NUREG/CR-2707	8210210051	NUREG		UCB/EERC-78/28 VO2	8107270169*		Q
NUREG/CR-2914	8210210046	NURED		UCB/EERC-79/12 VQ3	8107270174*		e e
NUREO/CR-2919	8210220149	NUREG	PNL-4380	UCB/EERC-79/23 VO1	8107270178*		G
NUREG/CR-2920	8210050412	NUREG	But moon	UCB/EERC-79/24 VO2	8107270182*	50-266	a
NUREO/CR-2922 NUREO/CR-2923	8210190592 8210210014	NUREO NUREO	BMI-2099 BMI-2100	UCB/EERG-79/25 VO3	8107270185#		0
NUS-4146 RO1	8210210306*	50-329	A	UCID-18689 ROI UCID-19113	8209130461* 8206170006*		P P
NUB-4154	821006 0 354*	50-261	Ę	UCID-19141 DRFT	8207300222¥		Р
DRNL-5470	0210270052*	50-537	9	UCID-19147	Ø209200475*	50-29	P
ORNL-TM-4697 ORNL/NBIC-112 DRFT	8210270035* 8210280110*	50-537 FOIA	G	UE&C-ANL-810930	8210270060*		O COO-6411-1
ORNL/NEIC-208	6203140383*	FOIA		UMTRA-DOE/ALO-34 DRF URS/JAB 8216	8210250025 8210120286*	WASTE MOT 50-275	. 20482 P
ORNL/N81C-209	8203250320*	FOIA	_	VEP-FRD-33 ERR	8210120305*		р
P 105-4-939-008 R00	8210080080*	50-275	P	WCAP-10102	8210190429*		P
PNL-3524 R543-02 V05	8210270041* 8210040178*	50-537 50-206	G UC-11	WCAP-10142	0210130535*		P
RAI-C5504-196	8210050068*	50-409	P	WCAP-7870	8210080038*	FOIA	
	751002000	40 147	,	XN-NF-76-47(NP)(A)	8210150182*	TOPREP	
				XN-NF-81-21(NP)(A)	8210270169*	TOPREP	B 600 140 22007 -
				Y1003501A40 Y1003J01A20 R01	8210250074* 8207090224*	50-240 50-278	P DRF L12-00304-1 P

Items listed as enclosures are those indicated by an asterisk following the accession number in the indexes. The second column gives the accession number of the principal document under which the enclosure is listed. Knowing the accession number of the principal document, the date issued, and the category enables locating the title listing of the enclosure.

ACCESSION NUMBER

The subject category column in this index gives the docket number and the symbol for the category of information within that docket; for example, 50-320 P. The docket subject categories are defined in Appendix A.

Subject categories for nondocketed items are also entered in this column by symbol; for example, ACRS. These categories are defined in Appendix B and listed in the Contents.

ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	CVLECO	
7811200399 7812200285	8210280013 8210070007	82/09/17 82/08/10	50-325 50-246	S
7903090181	8210180028	82/08/20	FOIA	•
7905290357	8210280013	02/09/17	50-324	P
7908130454	8210280013	82/09/17	50-261	P
7909280105	8210070007	82/08/10	50-244	P
7912280014 8001080054	8210180028 8210180028	82/09/17 82/08/20	50-324 FOIA	P
9002080095	6210190112	82/10/06	FOIA	
8002140204	821001000B	82/06/28	50-266	P
8003310179	6210010008	82/06/28	50-244	9
8004100193 8004300616	8210010008 8210070007	85/08/10	50-265 50-266	P
EC05070079	8005070094	80/03/14	PT21	-
6005270820	8510010008	85/09/58	FOLA	
8005270822	8210010008	85/06/58	FOIA	
B006050154	8210180028	82/08/20	FOIA	
80040\$0188 8004170030	8210180028 8210180028	82/08/20 82/08/20	FOIA FOIA	
B006300104	8510010008	85/09/58	FOIA	
8008050245	8210010008	82/04/28	50-327	P
8008070143	8210180028	82/08/20	FOIA	_
8009040493 8009040497	8210070007 8210070007	82/08/10	50-266 50-266	P
BO10070320	8210210395	82/09/30	50-305	P
8010210037	8210010008	82/04/28	50-327	8
8010240413	B51001000B	85/09/58	FOIA	
8010240476	8210010008	82/06/28 82/07/12	FOIA FOIA	
8011040346 8011060565	8210080015 8011060561	80/10/20	50-254	8
	-		50~254	8
801104054B 8011120479	8011060541 8210010008	82/06/28 82/06/28	50~254	S
8011240024	8210010008	85/09/58	50-247	ŝ
8012180362	8210120012	82/08/20	FOIA	
8101090294	8210010008	82/06/28	50-247	8
B101140002	8510580013	82/09/17	50-324	Р
8101200322	8210540053	82/09/03 82/08/20	50~142 FOIA	F
8101270070 8102280195	8210180028 8210180028	82/08/20	FOIA	
8103030076	8210010008	85\09\58	FOIA	
0103050756	8210010008	82/06/28	FOIA	_
0103050987	8210010008	82/06/28	50-327	þ
8103060098	8210010008 8210010008	82/04/28 82/04/28	FOIA 50~247	8
8103090389 8103120107	8210010008	85/09/58	50~321	5
8103160338	9210180028	82/08/20	FOIA	
8103160366	8210180028	92/08/20	FOIA	_
B103190719	8210010008	82/06/28	50~245	s
8103240292	8210010008 8210010008	82/06/28 82/06/28	FOIA FOIA	
8103310127	2510010000	25,40,50		

	ACCESSION	NUMBER			
	ENCLOSURE	PRINCIPAL DOCUMENT	DATE 159UED	SUBJECT	
	8104080309 8104170703 8104240059 8104290103 8104290774	8210080015 8210180028 8210010008 8210010008 8210280013	82/07/12 82/08/20 82/06/28 82/06/28 82/09/17	FOIA FOIA FOIA 50-366 50-324	8
	8105040420 8105040512 8105110396 8105280476	8210080015 8210080015 8210010008 8210080015	62/07/12 62/07/12 82/06/26 62/07/12	50-352 50-265 FOIA 50-263	O P
	8106100203	8210010008	82/06/28	50-313	P
	8106100362 8106150555 8106220157 8106220165	8210010008 8210010008 8210080015 8210080015	92/06/28 92/06/28 92/07/12 92/07/12	FOIA 50-302 FOIA 50-261	8 P
	8106220168	8210080015	82/07/12	FOIA	•
•	8107010140 8107010141 8107070220 8107090355	8210280013 8210010008 8210010008 8210010008	92/09/17 92/06/28 92/06/28 93/06/28	50-261 50-369 FOIA FOIA	P 8
	8107160079	8210010008	82/06/28	50-240	8
	8107160386 8107170126 8107270161 8107270166 8107270169	8210010008 8210080015 8107270154 8107270156 8107270156	82/05/28 82/07/12 81/07/17 81/07/17 81/07/17	FOIA FOIA 50~246 50~266 50~266	G G
	8107270174 8107270178 8107270162 8107270185 8107270188	8107270154 8107270156 8107270156 8107270156 8107270154	81/07/17 81/07/17 81/07/17 81/07/17 81/07/17	50-266 50-266 50-266 50-266 50-266	0 0
	6107270191 8107270194 8107270196 8107270198 8107270199	8107270158 8107270158 8107270158 8107270156 8107270156	81/07/17 81/07/17 81/07/17 81/07/17 81/07/17	50-266 50-266 50-266 50-266 50-266	G G G
	8107300148 8108030041	8210010008 8210010008	85/09/58 85/09/58	50-324 FOIA	8

ACCESSION	NUMBER					N NUMBER			
	PRINCIPAL	DATE	SUBJECT			PRINCIPAL	DATE	SUBJECT	
ENCLOSURE	DOCUMENT	ISSUED	CATEGOR		ENCLOSURE 	DOCUMENT	ISSUED	CATEGORY	
8109160478 8109220915	8210010008 8210010008	82/06/28 82/06/28	50-289 FOIA	P	8203160183 6203160383 8203170060	8210010008 8210010008	82/04/28 82/06/28 82/06/28	50-331 ! FOIA FOIA	5
8109240007 8109250504	8510010008 8510010008	85\09\58 85\09\58	FOIA FOIA	_	8203170016 8203190016	8210010008 8210040442 8210070007	82/08/24 82/08/10		A
Ø109280036	8210010008	82/06/28	50-312 50-29	8	8203220512	82100/000/	82/08/24		D
8109280175 6109260684	8210010008 8210080020	82/06/28 82/09/16	FOIA FOIA	a	8203220514 82032250320	8210280013 8210010008	82/09/17 82/06/28		P
8110010072 8110050018	8210010008 8210010008	82/06/28 82/06/28	50-369 FOIA	s	8203240003 8203290028	8210070007 8210080015	82/08/10 62/07/12	FOIA	p
B110170728	8210010008	82/06/28	FOLA		8203270031	8210080015	82/07/12	50-293	
8110220004 8110230085	8310010008 8310010008	82/06/28 82/06/28	FOIA 50-219	ន	8203300270 8203310089	8210010008 8210010008	82/04/28	FOIA 50-311	
8110230050 8110290050	8210070007 8210070007	82/08/10 82/08/10	50-266 50~266	P	8203310094 8204010046	8210010008 8210010008	82/06/28		P
81110300480	821001000B	85/09/58	FOIA		8204080171	8210010008	82/05/28	FOIA	
81110400B4 8111060130	821001000B	82/06/28	50-313 FOIA	8	8204080260 8204120487	821001000B 8210080015	82/06/28 82/07/12	FOIA	5
81111600062 8111160308	8210070007 8210010008	85/09/58	50-266 FGIA	þ	8204160222 8204160225	8204160212 8204160212	82/03/19 82/03/19	50-293	a Q
B111180001	8210010008	82/06/28	50-338	s	8204200390	8210040360	82/09/27	FOIA	
8111191042 8111240071	821001000B 8210070007	82/08/10	50-206 50-266	e P	8204200405 8204200408	8210050430 8210270423	82/09/17 82/09/23	70~1510 70~1510	
8111240912 8111270314	8210010008	82/06/28 82/06/28	FOIA 50-295	s	8204200438 8204200442	8210080015 8210080015	82/07/12 82/07/12	50~289 J	P P
8111300367	821001000B	82/04/28	50-206	8	8204210289	8210010008	82/04/28		s
8112010310 8112020725	8510010008 851001000B	85\0?\59 85\0?\58	50-336 F01A	s	8204220144 8204270464	8210270423 8210010008	82/04/28 82/09/23	70-1510 FOIA	
8112020852 8112020885	8510580013 8510580013	82/09/17 82/09/17	50-241 50-324	P	8204290048 8204290237	821001000B	82/06/28 82/07/12		A P
8112030585	8210010008	82/06/28	FOIA		B204290408	8210060442	82/08/24		D
B112100374 B112210166	8210010008 8210010008	85/06/58 85/06/58	FOIA		8204300098 8205030617	82102700B3 8210080015	82/09/20 82/07/12		5
81 12210193 81 12210538	8210010008 8210010008	92/06/28 92/06/28	FO1A 50-304	5	820503 <i>0</i> 61 <i>9</i> 820505 <i>0</i> 480	8210080013 8210280013	82/07/12 82/09/17		S
8112300287	8210280013	82/09/17	50-324	P S	82050&0550 82050&0558	8210120103	82/07/12	FOIA FOIA	
8201050061 8201060003	8210010008 8210010008	82/06/28 82/06/28	50-324 FOIA		8205070377	8210120103 8210010008	82/07/12 82/06/28	FOIA	
8201060249 8201120280	8210050430 8210280013	82/08/17 82/09/17	FO1A 50-324	Ρ	8205130114 8205170128	8210280015 8210280013	82/07/12 82/09/17		P
B201130322 B201150003	8210010008 8210010008	82/06/28 82/06/28	FOIA FOIA		8205180693 8205190428	82100B0015	82/07/12 82/07/12		5 5
8201150004 8201150005	821001000B	85/09/58	FOIA FOIA		8205170441 8205240906	8210080015 8205240003	82/07/12 82/05/05		s
8201150087	8210060442	82/08/24	50-537	Ď	8205240010	0205240003	82/05/05	40-8355	
8201150176 8201150180	8210060442 821001000B	82/08/24 82/06/28	50-537 50-204	5	8205250010 8205250020	8210270270 8210270270	82/10/19 82/10/19		P
8201190040 8201190041	8210010008 8000100128	82/06/28	FOIA		8205270507 8205270526	8210040360 8210040360	82/09/27 82/09/27	FOIA FOIA	
6201170296	8210010008	85/06/58	FOIA		8205280490	8210080015	82/07/12	FOIA	
8201200453	6210010008 6210010008	82/06/28 82/06/28	50-346 50-255	8 8	8205280497 8205280502	8210080015 8210080015	82/07/12 82/07/12	FOIA FOIA	_
820120065B 8201200662	8210280013	82/09/17 82/09/17	20~591 20~591	P	8205280532 8205280533	8210080015 8210080015	82/07/12 82/07/12	50-289 f	P
8201210107	8210070007	82/08/10	FOIA		9206030064	8210040062	02/09/27		P
					8204040401 8204040013	82100B0015 8206200097	82/07/12 82/07/29	FOIA COMMISSION	
					8206050015 8206070106	8210080015	82/07/19 82/07/12 82/08/10		5 P
					8206070250 8206080467	8210 <i>0</i> 70007 8210060442	92/08/24		ר ס
					8206110186 8206140327	8210080015 8210080015	82/07/12 82/07/12	50-416	g P
					02001605B 0000170006 000017005B	8208260424 8210180195	82/07/29 82/09/20	50-280	G
					6204180042	8210190144	82/09/30	FOIA	
					8204210571 8204220591	8210040414 8210280013	82/08/31 82/09/17	50-266 50-324	P P
					8206230020 8206240119	B2101503B2	82/09/30 82/09/20	50-245	P S
					8206270016	8206200091	82/07/29	COMMISSIO	
					8206290655 8206290666	8210070007 8210080015	82/08/10 82/07/12	50-289	P P
					9204300188 9204300370	8210220233 8210240305	82/10/18 82/10/12	50-155 TOPREP	Q
					8207050005	8210010293	82/09/27	PR 50-289	P
					8207050040 8207070324	8210050506 8207070317	82/09/16 82/06/30 82/06/28	70-2746	K
					8207070422 8207070428	8207070419 8207070419	95\09\58		ĸ

ACCESSION					ACCESSIO	N NUMBER			
ENCLOSURE	PRINCIPAL DOCUMENT	DATE	SUB JECT CATEGOR		ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGOR	
#207090208 #207090215 #207090224 #207120140 #207120253	8207090201 8207090201 8207090201 8210280013 8207120147	82/07/06 82/07/06 82/07/06 82/07/06 82/09/17 80/06/18	50-278 50-278 50-278 50-276 50-324 50-447	PPPA	8210010095 8210010096 8210010098 8210010099 8210010101	8210010008 8210010075 8210010094 8210010008 8210010097	92/04/28 92/04/21 92/06/28 92/06/28	50-344 50-335 50-344 50-346 50-259	S 0 5 5 0
8207140138 8207140491 8207140494 8207140497 8207140500	8210060442 6210040366 6210040366 6210040366 8210040366	82/08/24 82/08/24 82/08/24 82/08/24 82/08/24	50-537 50-373 50-373 50-373 50-373	0 0 0 0	8210010105 8210010107 821001010 8210010110 8210010111	8210010008 8210010103 82100101048 8210010106 8210010102	82/06/28 82/09/27 82/06/28 82/09/13 82/09/13	50-366 50-339 50-366 50-413 50-400	8 9 0
6207180073 6207180068 6207190431 6207230303 6207300222	8210220047 8210190118 8210120272 8207230301 8210050300	82/09/17 82/09/16 82/10/04 82/07/13 82/09/21	NUREC REVIEW C 50-29 50-339 50-206	9 9 9	9210010115 9210010118 9210010119 8210010122 9210010124	8210010108 8210010113 8210010008 8210010120 8210010117	82/09/24 82/09/07 82/06/28 82/08/31 82/09/02	50-327 50-321 F01A 50-83 50-269	9
8209010016 8208010019 8208020047 8208100269 8208110271	8210070440 8210220072 8210270083 6210120245 6210270270	82/09/14 82/09/20 82/09/20 82/09/30 82/10/19	50-289 ORG FOIA 50-29 50-155	P P	8210010126 8210010127 8210010128 8210010138 8210010135	8210010112 8210010121 8210010131 8210010131	82/09/03 82/09/10 82/09/16 82/09/22 62/09/20	50-324 70-1201 50-311 50-413 50-327	9 9 9
6208170093 6208180082 6208170178 6208170270 6208250412	8210050300 8210200041 8210130205 8210180035 8210080036	82/09/21 92/10/12 92/10/05 82/09/27 82/08/13	50-206 50-155 50-213 50-302 FOIA	P P P	6210010137 8210010138 8210010139 8210010141 8210010143	8210010132 8210010131 8210010127 8210010131 8210010131	82/09/01 82/09/22 82/09/27 82/09/22 82/09/22	50-324 50-413 50-348 50-413 50-413	9 0
H208250417 H208310034 H209130461 H209140027 H209140153	8210080036 8210280013 8210220015 8210220105 8209140148	82/09/13 82/09/17 62/10/08 82/10/18 82/09/08	50-269 50-155 50-293 50-244 50-324	5 5 5 5	8210010145 8210010147 8210010150 8210010151 8210010153	8210010140 8210010127 8210010144 8210010148 8210010142	82/09/22 82/09/27 82/09/16 82/09/07 82/09/17	50-338 50-348 50-311 50-416 50-335	5 5 6
8209150106 8209150162 8209150436 8209150438 8209150440	8210280013 8210280013 8209150432 8209150432 8209150434	82/09/17 82/09/17 82/07/23 82/07/23 82/08/25	50-261 50-325 70-2946 70-2946 50-267	P P F	8210010159 8210010161 8210010165 8210010168 8210010168	8210010195 8210010008 8210010157 8210010158 8210010163	82/09/08 82/06/28 82/09/24 82/09/02 82/09/22	50-335 50-327 50-220 50-269 50-338	9 6 8
8207160311 8207160457 8207200475 8207210383 8207210413	8209160299 8210250091 8210040132 8210080001 8210180308	82/08/31 82/09/30 82/09/27 82/09/14 82/09/17	50-325 50-155 50-29 50-237 50-528	SPPA	8210010169 8210010172 8210010174 8210010176 8210010178	8210010008 8210010008 8210010164 8210010173 8210010175	02/06/28 82/06/28 82/09/24 82/09/08 82/09/16	FD1A FD1A 50-335 50-261 50-313	S Q
8207210523 8207210527 8207210550 8207220137 8207270271	8207210514 8207210425 8210180214 8207220135 8207270242	82/09/01 82/08/20 82/09/17 82/09/13 82/09/24	50-309 50-251 50-508 50-382 50-358	P S A A H	8210010180 8210010183 8210010186 8210010188 8210010188	9210010177 8210010171 8210010179 8210010182 8210010171	82/09/22 82/09/16 82/09/27 62/09/09 82/09/16	50-397 50-324 50-305 50-424 50-324	8 9 9
D207270379 B207270189 B207270225 B207270236 B207270240	8206200097 8209290125 8209290125 8209290168 8209290168	82/07/27 82/09/16 82/09/16 82/08/26 82/08/26	COMM (SSI 50-10 50-10 FOIA FOIA	0N F F	8210010192 8210010193 8210010194 8210010199 8210010199	8210010181 8210010170 8210010171 8210010171 8210010171	82/07/16 82/07/15 82/07/16 82/07/22 82/07/16	50-272 50-325 50-324 50-438 50-324	9 9 9
9207300175 9207300332 9207300336 9207300355 9210010022	8209300170 8209300326 8209300326 8209300353 8210010019	82/09/24 82/09/22 82/09/22 82/09/30 82/09/16	50-259 50-213 50-213 50-337 50-321	5 P P B O	0020100128 2020100128 2020100128 8020100128 8020100128	8210010191 8210010191 8210010171 8210010170 8210010204	83/09/30 83/09/15 83/09/33 83/09/33	50-438 50-438 50-324 50-325 50-348	9 9 9
8210010024 8210010025 8210010029 8210010031 8210010041	8210010009 8210010019 8210010019 8210010019	82/07/07 82/09/16 82/09/16 82/09/16 82/09/24	71-481 50-321 50-321 50-321 50-263	а а а Р	9210010210 8210010214 8210010215 8210010215 8210010219	8210010207 8210010207 8210010212 8210010213 8210010207	82/09/22 82/09/22 82/07/17 82/08/31 82/09/22	50-213 50-213 50-361 50-389 50-336	P P Q
8210010046 8210010047 8210010049 8210010061 8210010065	8210010034 8210010045 8210010044 8210010008 8210010008	82/09/24 82/09/16 82/09/22 82/06/28 82/06/28	50-263 50-311 50-302 FOIA FOIA	P S Q	8210010222 8210010224 6210010225 6210010229 6210010234	8210010212 8210010217 8210010221 8210010212 8210010233	82/09/17 82/09/24 82/08/31 82/09/17 82/09/22		
8210010047 8210010068 8210010073 8210010076 8210010078	8210010008 8210010008 8210010008 8210010008 8210010075	82/04/28 82/04/28 82/04/28 82/06/28 82/09/15	FOIA FOIA FOIA FOIA 50-335	q	8210010238 8210010239 8210010240 8210010246 8210010246	8208240424 8210010237 8210010235 8208240424 8208070114			
8210010079 8210010081 8210010082 8210010083 8210010084	8210010064 8210010077 8210010064 8210010008 8210010075	82/09/29 82/09/24 82/09/29 82/06/28 82/09/[5	50-537 50-219 50-537 50-321 50-335	G P O S	8210010247 8210010248 8210010280 8210010284 8210010287	8208 090111 8210 01024; 8210 01027; 8210 01027; 8210 010275			
8210010085 8210010088 8210010089 8210010091 8210010092	8210010077 8210010075 8210010008 8210010086 8210010075	82/09/24 82/09/15 82/06/28 82/09/13 82/09/15	50~219 50-335 50~366 50-400 50-335	P 0 5 0 0	8210010274 8210010275 8210010277 8210010203 8210010303	8210010275 8210010287 821001028' 821001029! 821001027(

TO PRINCIPAL DOCUMENTS

ACCESSIO	NUMBER					IN NUMBER			
ENCLOSURE	PRINCIPAL DOCUMENT	DATE 155UED	SUBJECT CATEGOR		ENCLOSURE	PRINCIPAL DOCUMENT	DATE	SUBJECT CATEGOR	
8210010305 8210010314 8210010317 8210010321 8210010327	8210010301 8210010300 8210010313 8210010316 8210010307	82/09/10 82/09/03 82/09/22 82/09/13 82/09/10	50-389 50-338 70-143 50-250 50-321	9 9	8210040075 8210040083 8210040088 8210040015 8210040111	8210040073 8210040081 8210040086 8210040100 8210040107	82/09/22 82/10/01 82/09/24 82/09/22 82/09/29	50-315 50-155 50-387 50-293 50-313	5 5 5 P
8210010329 8210010338 8210010340 8210010341 8210010346	6210010316 8210010336 8210010336 8210010336	82/09/13 82/09/13 82/09/16 82/09/17 82/09/13	50-250 50-250 50-324 50-390 50-250	G G G	8210040121 6210040122 8210040129 8210040134 8210040139	8210040116 8210040118 8210040126 8210040131 8210040132	82/09/24 82/09/24 82/09/16 82/09/15 82/09/27	50-304 50-387 50-247 50-373 50-29	9999
8210010350 8210010355 8210010340 8210010341 8210010343	8210010336 8210010344 8210010349 8210010353 8210010358	82/09/16 82/09/16 82/09/22 82/09/10 82/09/10	50-324 50-311 50-400 70-27 State Pr	Q S O	8210040144 8210040145 8210040155 8210040155 8210040155	8210040141 8210040141 8210040146 8210040148 8210040156	82/09/24 82/09/28 82/09/30 82/09/27 82/09/24	50-317 50-247 50-440 04999 50~305	S K S
9210010365 9210010368 9210010367 9210010371 9210010373	8210010357 8210010349 8210010357 8210010364 8210010349	82/09/28 82/09/28 82/09/10 82/09/10	50-244 50-400 50-244 70-143 50-400	P G G	8210040162 8210040173 8210040173 8210040183 8210040183	8210040156 8210040171 8210040177 8210040182 8210040184	82/09/24 82/09/27 82/09/30 82/09/27 82/09/09	50-305 0A999 50-206 50-220 50-409	S P P
8210010384 8210010385 8210010390 8210010394 8210010397	8210010380 8210010376 8210010383 8210010389 8210010349	82/09/13 82/09/22 82/09/16 82/09/23 82/09/22	50-404 50-336 50-272 50-409 50-400	8 8	8210040187 8210040189 8210040194 8210040203 8210040204	8210040184 8210040188 8210040172 8210040177 6210040202	82/09/20 82/09/15 82/09/27 82/09/24 82/09/10	50-285 50-237 0A999 50-315 50-331	5 5 5 6
8210010378 8210010379 8210010402 8210010405 8210010407	8210010388 8210010391 8210010393 8210010391 8210010401	62/09/22 62/09/22 62/09/22 62/09/22	70-824 50-324 50-387 50-324 50-3	0 5 0 P	9210040205 8210040208 8210040209 8210040213 8210040213	8210040199 8210040202 8210040201 8210040206 8210040211	82/09/24 82/09/10 82/09/23 82/09/27 82/09/24	50-315 50-331 50-316 50-286 50-318	5 9 5 8
8210010410 8210010412 8210010413 8210010414 8210010415	8210010391 8210010407 8210010406 8210010401 8210010391	82/09/22 82/09/16 82/09/17 82/08/31 82/09/22	50-324 50-311 50-275 50-3 50-324	0 5 P Q	9210040220 9210040223 9210040226 9210040226 9210040245	8210040215 8210040221 8210040216 8210040224 8210040232	82/09/27 82/09/24 82/09/23 62/09/24 82/09/27	50-45B 50-373 50-31B 50-352 50-269	К Р В Р
8210010420 8210010423 8210010425 8210010426 8210010428	8210010411 8210010417 8210010401 8210010411 8210010418	82/09/22 82/09/14 82/08/31 82/09/22 82/09/23	50-518 50-311 50-3 50-518 40-1202	а Б Р	8210040246 8210040265 8210040273 8210040274 8210040279	8210040230 8210040261 8210040254 8210040258 8210040254	82/09/27 92/09/28 82/10/01 82/09/27 82/10/01	50-454 50-219 50-349 50-322 50-349	О Р К О К
8210010429 8210010431 8210010432 8210010433 8210010434	8210010421 8210010411 8210010430 8210010411 8210010418	82/09/17 82/09/22 82/09/03 82/09/22 82/09/23	50-438 50-518 50-259 50-518 40-1202	Q Q Q	8210040284 8210040285 8210040286 8210040288 8210040289	8210040281 8210040277 8210040254 8210040281 8210040277	82/09/28 82/09/27 82/10/01 82/09/28 82/09/27	50-244 50-338 50-367 50-244 50-338	P
8210010436 8210010438 8210010440 8210010443	8210010424 8210010401 8210010418 8210010401 8210010442	82/09/08 82/08/31 82/09/23 82/08/31 82/09/03	50-369 50-3 40-1202 50-3 50-416	Q P Q	8210040297 8210040301 8210040303 8210040305 8210040307	8210040277 8210040277 8210040276 8210040292 8210040277	82/09/27 82/09/27 82/10/01 82/09/28 82/09/27	50-338 50-338 50-220 50-528 50-338	P F H P
	8210010401 8210010451 8210010456	92/09/31 92/09/08 92/09/22 32/09/16	50-3 50-369 50-341 50-311 50-390	P Q A B	8210040315 8210040319 8210040320 8210040327 8210040327	8210040277 8210040311 8210040277 6210040277 6210040321	82/09/27 82/09/24 82/09/27 82/09/27 82/09/22	50-338 TOPREP 50-338 50-338 50-316	P P P Si
			50-269 50-269 50-395 50-443	G G A	8210040327 8210040330 8210040332 8210040345 8210040340	8210040323 8210040321 8210040324 8210040333 8210040333	82/09/30 82/09/22 82/09/21 82/09/27 82/09/27	TOPREP 50-316 50-333 GA999 GA999	S
				9	8210040346 8210040347 8210040350 8210040351 8210040354	8210040343 8210040343 8210040343 8210040343 8210040345	82/08/20 82/08/20 82/08/20 82/08/20 82/09/10	50-537 50-537 50-537 50-537 50-282	AAA
					8210040355 8210040357 8210040367 8210040367 8210040368	8210040343 8210040343 8210040258 8210010008 8210010008	82/08/20 82/08/20 82/09/27 82/06/28 82/06/28	50-537 FOIA 50-322 50-366 FOIA	A Q S
					8210040371 8210040374 8210040375 9210040375 8210040376	8210010008 8210010008 8210040366 8210040369 8210010008	82/06/28 82/06/28 82/08/24 82/09/24 82/06/28	FOIA 50-320 50-373 50-331 FOIA	8 0 8
					8210040381 8210040383 8210040396 8210040397 8210040411	8210010008 8210010008 8210010008 8210040392 8210010008	82/06/28 82/06/28 82/06/28 82/09/07 82/06/28	FOIA FOIA FOIA 70-371 FOIA	

ACCESSIO	N NUMBER					ON NUMBER			
ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJEC		ENCLOSURE	PRINCIPAL DOCUMENT	CATE ISSUED	SUBJEC	
8210040412 8210040416 8210040417 8210040418 8210040419	8210040410 8210010008 9210040415 8210040415 8210040415	82/09/15 82/06/28 82/09/15 82/09/15 82/09/15	CONTRACT FOIA 50-315 50-315 50-315		821005020 821005020 821005021 821005021 8210050217	8210050202 8210010008 8210010008 8210050204	82/10/04 82/06/28 82/06/28 82/10/01 82/04/28	50-413 FOIA FOIA 70-2742 FOIA	G
8210040420 8210040421 8210040425 8210040427 8210050006	8210040414 8210010008 8210040414 8210040414 8210010008	82/08/31 82/06/28 82/08/31 82/08/31	50-266 F01A 50-266 50-266 F01A	P P	8210050229 8210050231 8210050233 8210050234 8210050239	8210050222 8210050227 8210050151	82/09/16 82/09/22 82/09/22 82/09/28	50-329 50-244 50-237 50-361 50-267	6 8 8 0
8210050007 8210050010 8210050011 8210050012 8210050015	8210010008 8210010008 8210010008 8210050008 8210050013	82/06/28 82/06/28 82/06/28 82/09/24 82/09/16	FOIA FOIA FOIA 50-361 FOE-08	8 7	821005025B 8210050266 8210050276 8210050276 8210050287	8210050253 8210050261 8210050268 8210050274 8210050284	82/09/24 82/09/23 82/09/21 82/09/24 82/10/01	50-344 50-341 50-259 50-315 0000	0 8 0
6210050018 6210050019 6210050021 6210050023	8210050013 8210050014 8210050017 8210010008 8210010008	82/09/16 82/09/24 79/03/16 82/06/28 82/06/28	50-309 50-361 REGGD FOIA 50-278	FS	8210050290 8210050293 9210050295 8210050303 8210050307	8210050284 8210050284 8210050284 8210050301 8210050306	82/10/01 82/10/01 82/10/01 82/10/01 82/09/24	QA999 QA999 BA999 50-285 50-331	s o
8210050024 8210050026 8210050027 8210050029 8210050030	8210050014 8210050017 8210010008 8210050016 8210050017	82/09/24 79/03/16 82/06/28 82/09/24 79/03/16	50–361 Regod 50~348 50–361 Regod	5 5 6	6210050311 6210050313 6210050318 6210050321	8210050308 8210050310 8210050310 8210050320 8210050323	82/09/29 82/09/30 82/09/30 82/09/28 82/09/22	50-331 50-346 50-346 50-277 50-346	9 P P B
8210050031 8210050032 8210050034 8210050035 8210050037	8210010008 8210050016 8210050017 8210010008 8210050016	82/06/28 82/09/24 79/03/14 82/06/28 82/09/24	FOIA 50-361 GOOSA FOIA 50-361	s s	8210050334 8210050337 8210050342 8210050341 8210050365	8210050332 8210050331 8210050334 8210050355 8210050357	82/09/20 82/09/23 82/09/24 82/09/24 82/09/15	50-358 50-267 50-155 50-346 50-166	K 8 0 8 0
8210050038 8210050039 8210050041 8210050042 8210050044	8210010008 8210050017 8210050016 8210050017 8210050016	82/06/28 79/03/16 82/09/24 79/03/16 82/09/24	FOIA REGOD 50-36! REGOD 50-361	8	8210050371 8210050372 8210050378 8210050380 8210050390	8210050362 8210050366 8210050356 8210050359 8210050381	82/09/29 82/09/29 82/09/29 82/09/15 82/09/23	50-324 50-382 50-382 50-186 50-361	P 0 0 0 8
B21005004B B210050050 B210050056 B210050064 B210050068	8210050016 8210050016 8210050052 8210010008 8210050065	82/09/24 82/09/24 82/09/30 82/06/28 82/09/29	50-361 50-361 50-373 FDIA 50-409	93 B B B B B B B B B B B B B B B B B B B	5210050379 5210050403 5210050409 6210050409 5210050419	8210050387 8210010008 8210050398 8210010008 8210050414	85/09/30 85/09/28 85/09/28 85/09/20	50-458 FOIA 50-447 FOIA 50-389	A A
8210050070 8210050074 8210050075 8210050077 8210050078	8210050067 8210050071 8210010008 8210050073 8210050071	82/09/29 82/09/27 82/06/28 82/09/30 82/09/27	50-409 50-280 50-304 50-454 50-280	P 22 22 22	8210050424 8210050426 8210050427 8210050437 8210050436	8210010008 8210010008 8210050425 8210010008 8210010008	82/06/28 82/06/29 82/06/29 82/06/28	FOIA FOIA 50-155 FOIA FOIA	P
6210050082 6210050084 6210050085 6210050086 6210050087	8210010008 8210050080 8210050083 8210050081 8210010008	82/06/28 82/10/01 82/09/27 82/06/28	F01A 50~366 50~333 50~280 F01A	S F S	8210050439 8210050445 8210050451 8210050456 8210050467	8210050430 8210050430 8210050430 8210050430 8210050430	82/08/17 82/08/17 82/08/17 82/08/17 82/08/17	FOIA 70~1510 70-1510 70-1510 FOIA	
8210050091 8210050098 8210050098 8210050098	8210050081 8210050081 8210010008 8210050076 8210050076	82/09/27 82/09/27 82/06/28 82/09/24 82/09/24	50-280 50-280 FOIA 50-361 50-361	s s	8210050471 8210080473 8210050478 8210030481 8210050490	8210050430 8210010008 8210010008 8210010008 8210050485	82/08/17 82/06/28 82/06/28 82/06/28 82/09/20	FOIA FOIA FOIA FOIA 50-272	P
8210050107 8210050109 8210050110 8210050116	8210050105 8210050103 8210050102 8210050105 8210010008	82/07/09 82/09/24 82/09/30 82/07/09 82/06/28	50~295 50~280 50~305 50~295 FOIA	0 8 0	8210050493 8210050495 8210050496 8210050500 8210050503	821001000B 8210030491 821001000B 821001000B 8210030497	82/06/28 82/09/14 82/06/28 82/06/28		
8210050124 8210050135 8210050146 8210050154 8210050155	8210010008 8210050139 8210050139 8210050139	82/04/28 82/09/22 82/09/22 82/04/28	50-311 FOIA 50-329 50-329 FOIA	9 0	8210050505 8210050508 8210050507 8210050514 8210030518	8210050497 8210050501 8210050497 8210010008 8210050512			
8210050140 8210050141 8210050144 8210050148 8210050181	8210050157 8210010008 8210010008 8210050165 8210010008	82/09/29 82/06/28 82/06/28 82/09/29 82/06/28	50-315 50-320 F01A 50-334 F01A	Р 8	8210050520 8210050521 8210050528 8210050528 8210050530	B21001000B B210050516 B210050512 B210050506 B210050525			
8210050185 8210050187 8210050190 8210050191 8210050194	8210050183 8210050188 8210050188 8210050188	82/09/30 82/09/24 82/06/28 82/10/01 82/09/15	50-461 50-336 FOIA GA999 50-266	K P	B210050533 B210050536 B210050539 B210050541 B210050542	8210010008 8210050506 8210050538 8210050538			
8210050198 8210050200 8210050203 8210050205 8210050206	8210050195 8210010008 8210050193 8210050186 8210050199	82/10/01 82/04/28 82/09/28 82/09/15 82/09/30	0A999 F01A 50-416 50-246 50-443	5 0 A	8210050349 8210050544 8210050546 8210050548 8210050567	B210050540 B210050538 B210050538 B210050540 B210050559			

TO PRINCIPAL DOCUMENTS

ACCE8910A	(NUMBER				ACCESSI	IN NUMBER			
	PRINCIPAL	DATE	SUBJECT		77223	PRINCIPAL	pA7E	SUBJECT	г
ENCLOSURE	DOCUMENT	ISSUED	CATEGOR	Y	ENCLOSURE	DOCUMENT	ISBUED	CATEGO	
8210050573 8210060001 8210060005 8210060008 8210060009	8210190079 8210010008 8210010008 8210010008 8210010008	82/06/28 82/06/28 82/06/28 82/06/28	FOIA FOIA FOIA FOIA		8210060345 8210060348 8210060352 8210060354 8210060354	8210060341 8210060342 8210060347 8210060349 8210060351	82/07/23 82/10/01 82/10/01 82/10/04 82/09/28	50-528 50-289 50-327 50-261 70-25	0 F F
8210040014 8210040026 8210040030 8210040041 8210040042	8210060013 8210010008 8210060023 8210060024 8210010008	82/10/01 82/06/28 82/09/24 82/09/17 82/06/28	50-241 FOIA 50-293 50-247 FOIA	P S G	8210060363 8210060367 8210060367 8210060370 8210060372	8210010008 8210060359 8210010008 8210060365 8210060361	82/05/28 82/06/28 82/09/28 82/09/28	F01A 50-237 F01A 70-1100 50-280	Q S
8210060046 8210060047 8210060068 8210060077 8210060081	8210060024 8210060034 8210010008 8210010008 8210060076	82/09/17 82/09/27 82/06/28 82/06/28 82/09/23	50-247 50-29 FOIA FOIA 50-334	Q Q	8210060380 8210060381 8210060384 8210060386 8210060390	8210060377 8210010008 8210060379 8210060377 8210060385	82/09/30 82/06/28 82/09/21 82/09/30 82/09/27	50-263 FDIA 50-273 50-263 50-317	р О Р Б
8210040082 8210040083 8210040084 8210040085 8210040094	8210010008 8210040074 8210010008 8210040080 8210040088	82/06/28 82/09/24 82/06/28 82/09/30 82/09/28	50-296 50-277 FOIA 50-293 50-334	8 8	8210060373 8210060374 8210060379 8210060400 8210060403	8210060387 8210060385 8210060361 8210060376 8210060375	82/09/22 82/09/27 82/09/30 82/09/24 82/09/27	50-315 50-317 50-260 50-247 50-254	9 5 5 5
8210060100 8210060104 8210060119 8210060127	8210010008 8210040079 8210040117 8210040109 8210040079	82/06/28 82/09/17 82/09/30 82/09/16 82/09/17	FOIA 50-317 50-361 50-362 50-317	0 P 0	8210060411 8210060412 8210060413 8210060422 8210060422	8210060406 8210060409 8210060406 8210060414 8210060420	82/09/20 82/09/30 82/09/30 82/09/22	FOIA 50-259 FOIA 50-259 CONTRACT	8 2
8210060131 8210060141 8210060147 8210060148 8210060157	8210060126 8210060133 8210060138 8210060145 8210060155	82/09/15 82/09/17 82/09/30 82/09/15 82/09/24	50-228 50-275 70-398 50-247 50-508	0 0 F	8210060427 8210060429 8210060430 8210060432 8210060433	8210010008 8210040424 8210010008 8210010008 8210060431	82/06/28 82/09/29 82/06/28 82/06/28 82/09/23	F01A F01A 50-336 50-334 50-272	ទ ទ F
8210060163 8210060164 8210060173 8210060180 8210060203	8210060155 8210060150 8210060171 8210060150 8210060201	82/09/24 82/09/30 82/09/29 82/09/30 82/09/29	50~50B 50~293 50~309 50~293 50~416	0 0 P 0 B	8210040447 8210040449 8210060451 8210060452 8210060453	8210060442 8210010008 8210060442 8210010008 8210060442	82/08/24 82/06/28 82/08/24 82/06/28 82/08/24	50-537 F01A 50-537 F01A 50-537	D A A
8210060206 8210060208 8210060212 8210060214 8210060215	8210060174 8210060202 8210060207 8210060174 8210060211	82/07/30 82/07/29 82/10/01 82/07/30 82/07/17	50-443 50-220 50-251 50-443 50-412	0 8 0	, 8210060455 8210060449 8210060460 8210070005 8210070006	8210060442 8210060442 8210010008 8210070003 8210070003	82/08/24 82/08/24 82/06/28 82/09/17 82/09/17	50-537 50-537 50-320 50-346 50-346	A B F F
8210060216 8210060221 8210060226 8210060227 8210060230	8210060213 8210060219 8210060225 8210060228	82/10/01 82/09/30 82/09/30 82/09/30	50-255 50-327 50-416 70-7 50-289	8 8 8	8210070008 8210070014 8210070018 8210070021 8210070030	821001000B 8210070013 8210070013 8210070017 8210070007	82/06/28 82/09/29 82/09/29 82/07/20 82/08/10	FOIA 50-155 50-155 CONTRACT 50-244	P P
8210040238 8210040241 8210040243 8210040247 8210040248	8210060237 8210060239 8210060240 8210060245 8210060246	82/09/24 82/09/30 82/09/29 82/10/01 82/09/23	50-336 50-155 50-317 50-528 50-366	Р В В	8210070032 8210070035 8210070037 8210070038 8210070039	8210070028 8210070029 8210070007	82/09/14 82/09/14 82/07/16 82/08/10 82/07/16	50-289 50-289 50-537 50-244 50-537	G D G A
8210040252 8210040254 8210040254 8210040257 8210040259	8210060251 8210060253 8210060253 8210060255 8210060255	82/09/20 82/10/04 82/10/04 82/10/01 82/10/01	50-373 50-315 50-315 TOPREP TOPREP	0	8210070043 8210070044 8210070047 8210070047 8210070048	8210070040 8210070042 8210070029	82/07/16 82/09/17 82/09/10 82/07/16 82/09/17	50-537 50-416 50-373 50-537 50-416	D H D F
					8210070050 8210070051 8210070053 8210070055 8210070056	8210070042 8210070029	82/07/16 82/09/10 82/07/16 82/09/10 82/07/16	50~597 50~379 50~597 50~373 50~537	D H D H B
					8210070058 8210070057 8210070060 8210070061 8210070064	8210070029 8210070054 8210070054 8210070042 8210070029	82/07/16 82/09/15 82/09/15 82/09/10 82/07/16	50-537 50-309 50-309 50-373 50-537	P P H D
					821007/066 8210070067 8210070086 8210070070 8210070071	8210070029	82/07/10 82/07/16 82/08/10 82/07/16 82/07/16	50-373 50-537 50-244 50-537 50-537	H P A A
					8210070073 8210070074 8210070080 8210070083 8210070084	8210070007 8210070007 8210070007	82/08/10 82/08/10 82/08/10 82/08/10 82/07/16	50-244 50-244 50-244 50-244 50-537	P P P P
					821007008 8210070087 8210070087 8210070090 8210070091	8210070007 8210070029 8210070007	82/07/16 82/08/10 82/08/16 82/08/10 82/10/04	50-537 50-244 50-537 50-244 50-29	A P P P

ACCESSION	NUMBER				ACCESS 1	IN NUMBER			
ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGOR		ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT	
8210070093 8210070094 8210070095 8210070098 8210070099	8210070029 8210070085 8210070029 8210070029 8210070085	82/07/16 82/10/04 82/07/16 82/07/16 82/10/04	50-537 50-29 50-537 50-537 50-29	A P A A P	821070247 8210070270 8210070273 8210070273 8210070275	8210070029 8210070248 8210070029 8210070248 8210070029	82/07/16 82/09/22 82/07/16 82/09/22 82/07/16	50-537 50-219 50-337 50-219 50-537	F Q A Q
8210070101 8210070103 8210070112 8210070117 8210070118	8210070029 8210070029 8210070109 8210070106 8210070029	82/07/16 82/07/16 82/09/29 82/09/20 82/07/14	50-537 50-537 50-445 50-317 50-537	DAFPA	8210070280 8210070292 8210070283 8210070283 8210070284	8210070027 8210070027 8210070277 8210070027 8210070277	82/07/16 82/07/16 82/09/22 82/07/16 82/10/04	50-537 50-537 50-293 50-537 50-315	A Q C
8210070119 6210070121 6210070123 6210070125 6210070124	8210070029 8210070007 8210070029 8210070106 8210070029	82/07/16 82/08/10 82/07/16 82/07/20 82/07/16	50-537 50-244 50-537 50-317 50-537	0 0 0	8210070287 8210070291 8210070293 8210070294 8210070298	8210070278 8210070027 8210070027 8210070290 8210070029	82/10/04 82/07/16 82/07/16 82/10/04 82/07/16	50-312 50-537 50-537 50-312 50-537	G C A G A
8210070128 8210070129 8210070130 8210070131 8210070134	8210070029 8210070127 8210070106 8210070029 8210070029	82/07/16 82/10/05 82/09/20 82/07/16 82/07/16	50-537 50-454 50-317 50-537 50-537	0 0 0 0	8210070301 8210070302 8210070308 8210070308 8210070310	8210070027 8210070299 8210070029 8210070296 8210070029	82/07/16 82/10/04 82/07/16 82/09/24 82/07/16	50-537 50-397 50-537 50-278 50-537	A Q A Q A
8210070135 8210070138 8210070139 8210070142 8210070144	8210070007 8210070029 8210070007 8210070029 8210070141	82/08/10 82/07/14 82/08/10 82/07/14 82/07/15	50-244 50-537 50-29 50-537 50-397	0 0 0 0	8210070312 8210070313 8210070314 8210070315 8210070316	8210070307 8210070029 8210070305 8210070029 8210070307	82/09/24 82/07/16 82/09/22 82/07/16 82/09/24	70-344 50-537 50-272 50-537 70-344	D S D
8210070146 8210070148 8210070151 8210070154 8210070156	8210070029 8210070029 8210070029 8210070029	82/07/16 82/07/16 82/07/16 82/07/16 82/08/13	50-537 50-537 50-537 50-537 CONTRACT	C F A F	8210070318 8210070322 8210070323 8210070327 8210070330	8210070029 8210070317 8210070029 8210070029 8210070317	82/07/16 82/09/22 82/07/16 82/07/16 82/09/22	50-537 50-277 50-537 50-537 50-277	D D D
8210070157 6210070161 8210070163 8210070165 8210070166	8210070029 8210070158 8210070029 8210070007 8210070029	82/07/16 82/10/04 82/07/16 82/08/10 82/07/16	50-537 50-508 50-537 50-244 50-537	A G A P D	8210070331 8210070332 8210070333 8210070335 8210070342	8210070319 8210070029 8210070324 8210070029 8210070337	B2/10/04 B2/07/16 B2/10/05 B2/07/16 B2/07/22	50-312 50-537 50-285 50-537 50-220	Q D O D
B210070170 B210070172 B210070174 B210070179 B210070181	8210070029 8210070007 8210070029 8210070029 8210070178	82/07/16 82/08/10 82/07/16 82/07/16 82/09/24	50-537 50-269 50-537 50-537 50-219	C G C A S	8210070345 8210070346 8210070347 8210070350 8210070355	8210070341 8210070340 8210070029 8210070337 8210070348	82/09/24 82/09/29 82/07/16 82/09/22 82/10/04	50-219 50-293 50-537 50-220 50-438	9 8 0 9 A
8210070182 8210070185 8210070184 8210070187 8210070188	8210070029 8210070007 8210070029 8210070007 8210070177	82/07/14 82/08/10 82/07/14 82/08/10 82/09/29	50-537 50-266 50-537 50-266 50-277	A P D P O	8210070356 8210070358 8210070359 8210070363 8210070366	8210070352 8210070348 8210070351 8210070348 8210070361	62/10/05 62/10/04 62/09/22 62/10/04 62/09/27	50-245 50-438 50-311 50-438 50-247	G A B A
8210070190 8210070191 8210070193 8210070195 8210070196	8210070029 8210070007 8210070189 8210070029 8210070007	82/07/16 82/08/10 82/09/16 82/07/16 82/08/10	50-537 50-266 50-522 50-537 FOIA	DPCC	8210070367 8210070369 8210070377 8210070377 9210070381	8210070362 8210070364 8210070368 8210070371 8210070357	82/10/04 82/09/22 82/09/22 82/09/22 82/09/20	50-333 50-445 50-272 50-311 50-309	0 0 0
6210070198 6210070200 8210070202 8210070205 8210070206	8210070007 8210070029 8210070029 8210070007 8210070029	82/08/10 82/07/16 82/07/16 82/08/10 82/07/16	FOIA 50-537 50-537 50-246 50-537	С Р С	8210070385 8210070387 8210070388 8210070393 6210070374	8210070363 8210070378 8210070380 8210070376 9210070383	92/08/13 82/10/04 82/09/22 82/09/24 82/09/13	40-6422 50-460 50-272 50-271 40-6622	0 8 Q
8210070207 8210070208 8210070216 8210070217 6210070218	8210070029 8210070007 8210070214 8210070007 8210070007	82/07/16 82/08/10 82/09/23 82/08/10 82/08/10	50-537 50-266 50-286 50-266 50-266	P Q P	8210070400 8210070410 8210070418 8210070418 9210070421	8210070392 8210070409 8210070409 8210070411 8210070411	82/09/22 82/08/18 82/08/18 82/09/10 82/09/10	50~443 71~9150 71~9150 FOIA FOIA	a
8210070222 6210070223 6210070225 6210070226 6210070231	8210070029 8210070029 8210070029 8210070007 8210070221	82/07/16 82/07/16 82/07/16 82/08/10 82/09/22	50-537 50-537 50-537 50-266 50-311	A A Q S	8210070423 9210070426 8210070426 9210070431 8210070434	8210070417 6210070411 8210070411 8210070411 8210070411	82/09/29 82/09/10 82/09/10 82/09/10 82/09/10	FOIA FOIA FOIA FOIA	
8210070235 8210070240 8210070241 8210070247 8210070248	8210070007 8210070239 8210070238 8210070245 8210070246	82/08/10 82/09/22 82/09/27 82/09/29 82/09/22	FOIA 70-33 50-219 50-293 50-311	5 5 5	6210070436 8210070441 8210070445 8210070447 8210070446	8210070411 8210070411 8210070411 8210070411 8210070411	82/09/10 82/09/10 82/09/10 82/09/10 82/09/10	FDIA FOIA FOIA FOIA	
8210070251 8210070252 8210070253 8210070256 8210070258	8210070029 8210070249 8210070029 8210070029 8210070254	82/07/16 82/09/22 82/07/16 82/07/16 82/09/22	50-537 50-311 50-537 50-537 50-311	A A A B	8210070451 8210070454 8210070458 8210070459 8210070464	8210070411 8210070411 8210070411 8210070456 8210070411	B2/09/10 B2/09/10 B2/09/10 B2/09/17 B2/09/10	FOIA FOIA FOIA CONTRACT FOIA	
8210070259 8210070260 8210070262 8210070264 8210070266	8210070029 8210070029 8210070029 8210070029 8210070029	82/07/16 82/07/16 82/07/16 82/07/16 82/07/16	50-537 50-537 50-537 50-537 50-537	ACCFA	8210070465 8210070467 8210070468 8210070471 8210070473	8210070029 8210070411 8210070411 8210070411 8210070411	82/07/16 B2/07/10 82/07/10 82/07/10 82/07/10	50-537 FDIA FDIA FDIA FDIA	D

TO PRINCIPAL DOCUMENTS

ACCESSIO:	I NUMBER				ACCESSION	NUMBER			
	PRINCIPAL	DATE	SUBJECT	FNC	CLOSURE	PRINCIPAL DOCUMENT	DATE 195UED	SUBJECT CATEGORY	
6210070475 6210070478 6210070480 6210070482 6210070482	8210070411 8210070411 8210070411 8210070411 8210070411	82/09/10 82/09/10 82/09/10 82/09/10 82/09/10	FOIA FOIA FOIA FOIA FOIA	921 821 821 821	10080214 10080215 10080216 10080217 10080228	8210080212 8210080015 8210080015 8210080015 8210080227	82/10/04 82/07/12 82/07/12 82/07/12 82/07/12	50-206	
8210070485 6210070486 8210070488 8210070489 6210080002	8210070411 8210070411 8210070411 8210070411 8210080001	82/09/10 82/09/10 82/09/10 82/09/10 82/09/14	FUIA FUIA FOIA FUIA 50~237	821 821 821	10080230 10080232 10080237 10080240 10080250	8210080221 8210080225 8210080225 8210080234 8210080248	82/09/29 82/08/25 82/08/25 82/09/28 82/10/06	50-324 5 71-9167 71-9167 50-366 S 50-395 0	}
8210080005 8210080007 8210080022 8210080030 8210080031	8210080003 8210080004 8210080012 8210080027 8210080027	82/09/10 82/09/21 82/09/21 82/09/22 82/09/22	XPORTLIC CONTRACT CONTRACT 50-295 50-295	92 92: 92: 82:	10080253 10080254 10080257 10080258 10080259	8210080249 8210080248 8210080252 8210080254 8210080248	82/10/05 82/10/06 82/10/01 82/09/27 82/10/06	50-344 0 50-395 0 50-250 5 50-267 P 50-395 0) ;
8210080032 8210080034 8210080035 8210080038 8210080040	8210080020 8210080020 8210080033 8210080034 8210080037	82/09/16 82/09/16 82/09/09 82/08/13 82/09/08	FOIA FOIA XPORTLIC FOIA XPORTLIC	82 82 82	10080285 10080287 10080287	8210080240 8210080277 8210080282 8210080283 8210080284	82/09/30 82/10/04 82/10/04 82/10/04 82/10/05	50~482 M 50~416 S 50~416 S 50~346 G 50~416 S	3 3
8210080042 8210080044 8210080047 8210080051 8210080054	8210080037 8210080036 8210080036 8210080015 8210080015	82/09/08 82/08/13 82/08/13 82/07/12 82/07/12	XPORTL IC 50-269 50-287 50-289 FOIA	82: 82:	10080297 10080298 10080299 10080311 10080320	8210080294 8210080295 8210080293 8210080302 8210080319	82/06/22 82/10/05 82/10/05 82/10/05 82/09/09	TOPREP 50-416 S 70-2789 70-754 XPDRTL1C	i
8210080055 8210080057 8210080064 8210080079 8210080080	8210080053 8210080015 8210080015 8210080063 8210080076	82/09/23 82/07/12 82/07/12 82/09/29 82/10/05	50-537 FOIA 50-317 50-219 50-275	82: 82:	10150053 10150051 10150018 10080331	8210080321 8210080327 8210120015 8210120015 8210120015	82/09/15 82/09/16 82/08/20 82/08/20 82/08/20	XPORTLIC XPORTLIC FOIA FOIA FOIA	
8210080085 8210080091 8210080096 8210080100 8210080101	8210080015 8210080015 8210080015 8210080095 8210080015	82/07/12 82/07/12 82/07/12 82/09/28 82/07/12	50-244 50-289 50-289 50-397 FOJA	82 82 82	10120027 10120030 10120050 10120053 10120055	8210120015 8210120015 8210120047 8210120049 8210120015	82/08/20 82/08/20 82/10/04 82/09/23 82/08/20	FOIA FOIA 50-346 P REVIEW GRP FOIA	
8210080102 8210080106 8210080112 8210080114 8210080118	8210080078 8210080015 8210080015 8210080015 8210080015	82/09/30 82/07/12 82/07/12 82/07/12 82/07/12	50-29 FOIA 50-313 50-334 50-259	82: 82: 82:	10120057 10120062 10120066 10120068 10120073	8210120015 8210120015 8210120015 8210120015 8210120058	82/08/20 82/08/20 82/08/20 82/08/20 82/09/24	FOIA FOIA FOIA FOIA 50-382	D)
9210080122 8210080125 8210080127 8210080128 8210080132	8210080015 8210080015 8210080120 8210080015 8210080127	82/07/12 82/07/12 82/10/04 82/07/12 82/09/22	50-324 50-302 50-416 50-346 50-315	92 82 82	10120075 10120112 10120123 10120132 10120139	8210120015 8210120103 8210120103 8210120103 8210120134	82/08/20 82/07/12 82/07/12 82/07/12 82/09/27	F01A F01A 50-537 6 50-400 6 50-317 F	0
8740000 5	1	82/07/12 82/09/22 82/07/12 82/07/12	50-333 50-315 50-247 50-220 50-219	65. 85. 85.	10120140 10120143 10120150 10120151 10120161	8210120103 8210120103 8210120146 8210120103 8210120103	82/07/12 82/07/12 82/10/01 82/07/12 82/07/12	50-537 A 50-537 A 71-6347 50-244 F	4
			10-255 10-293 10-387 10-312	85 83 85	10120164 10120166 10120170 10120174 10120176	8210120155 8210120158 8210120103 8210120169 8210120103	80/12/18 82/09/30 82/07/12 82/10/01 82/07/12	50-293 E 71-9001 FOIA 71-9034 FOIA	3
				85 83 85	110120181 210120188 210120196 210120196	8210120103 8210120103 8210120180 8210120103 8210120194	82/07/12 82/07/12 82/10/01 82/07/12 82/10/06	71-6703 FOIA	P K
				82 82 82	210120202 210120225 210120233 210120243 210120247	8210120103 8210120215 8210120222 8210120240 8210120241	82/07/12 82/10/01 82/09/15 82/10/04 82/10/06	99999 50~333 F	P R O
				85 83 85	10120250 210120252 210120281 210120283 210120283	8210120248 8210120246 8210120276 8210120278 8210120280	82/10/04 82/10/01 82/10/05 82/10/01 82/10/06	50-329 4	P A P
				92 92 82	210120286 210120289 210120293 210120299 210120300	8210120278 8210120284 8210120280 8210120291 8210120296	82/10/01 82/09/27 82/10/06 82/10/08 82/10/04	50-327 (GA999 50-259 (P P P
				82 82 82	210120304 210120305 210120308 210120307 210120312	8210120301 8210120297 8210120291 8210120301 8210120311	82/10/05 82/10/04 82/10/06 82/10/05 82/09/15		P O

	N NUMBER			ACCESSION NUMBER	
ENCLOSURE	PRINCIPAL	DATE	SUBJECT	PRINCIPAL DATE	SUBJECT
	DDCUMENT	ISSUED	CATEGORY	ENCLOSURE DOCUMENT ISSUED	CATEGORY
8210120315 8210120316 8210120317 8210120319 8210120329	8210120301 8210120291 8210120311 8210120325	82/10/05 82/10/08 82/09/15 82/09/15 82/09/20	0A999 50-259 g 0A999 0A999 Waste Mot	8210130193 8210130189 82/10/08 8210130196 8210130192 82/10/01 8210130197 8210130195 82/10/01 8210130201 8210130197 82/09/28 8210130208 8210130204 92/10/04	50-271 R 50-254 B 50-244 B 50-249 S 50-280 S
8210120330	8210120321	82/09/15	CONTRACT	8210130210 8210130206 82/09/30	50-289 P
8210120331	8210120326	82/10/06	REVIEW GRP	8210130213 8210130204 82/10/04	50-280 S
8210120335	8209280426	82/09/20	GEN TEC IS	8210130214 8210130212 82/09/30	50-313 S
8210120336	8210120334	82/09/24	71-9010	8210130215 8210130200 82/10/07	50-373 R
8210120340	8210120339	82/10/01	71-9037	8210130215 8210130204 82/10/04	50-280 S
8210120342	8210120338	82/09/22	CONTRACT	8210130222 8210130221 82/09/21	50-546 0
8210120350	8210120347	82/09/29	CONTRACT	8210130223 8210130220 82/09/20	50-366 8
8210120352	8210120349	82/09/24	71-9964	8210130225 8210130218 82/10/01	50-29 8
8210120353	8210120351	82/08/30	WASTE MOT	8210130227 8210130217 82/09/29	50-311 8
8210120357	8210120354	82/09/28	CONTRACT	8210130232 8210130228 82/10/01	50-336 8
8210120362	8210120361	82/10/05	CONTRACT	8210130235 8210130230 82/09/30	50-29 8
8210120364	8210120363	82/09/20	CONTRACT	8210130236 8210130234 82/09/30	50-373 6
8210120366	8210120365	82/09/16	CONTRACT	8210130244 8210130242 82/10/08	50-261 R
8210120384	8210120381	82/09/13	71-5908	8210130250 8210130247 82/10/07	50-537 A
8210120386	8210120379	82/08/20	WASTE MOT	8210130253 8210130251 82/09/30	50-254 8
8210120399 8210120401 8210120419 8210120422 8210120423	8210120392 8210120391 8210120411 8210120417 8210120416	82/09/24 82/09/30 82/09/28 82/09/27 82/10/03	50-331 F CONTRACT 27-39 CONTRACT 50-389 M	8210130254 8210130252 82/10/07 8210130258 8210130256 82/05/28 8210130263 8210130262 82/10/07 8210130264 8210130264 82/10/07 8210130267 8210130264 82/10/07	50-309 P 50-321 S 50-349 K 50-329 K
8210120425	8210120414	82/09/30	CONTRACT	6210130274 8210130269 82/09/27 6210130285 8210130278 62/09/30 8210130286 8210130289 82/10/07 6210130287 82/10130257 82/10/06 8210130296 8210130291 82/10/06	50-341 8
8210120432	8210120427	82/09/29	CONTRACT		50-341 8
8210120440	8210120436	82/09/27	CONTRACT		50-307 P
8210120458	8210120454	82/09/22	CONTRACT		50-389 E
8210120471	8210120467	82/09/24	CONTRACT		50-277 G
8210120480	8210120475	82/09/30	50-62 P	8210130297 8210130294 82/10/07	50-358 A
8210120487	8210120475	82/09/30	50-62 P	8210130306 8210130302 82/09/29	50-54 P
8210120488	8210120483	82/09/29	CONTRACT	8210130309 8210130303 82/10/05	70-135
8210120492	8210120475	82/09/30	50-62 P	8210130315 8210130311 82/10/07	50-537 A
8210120494	8210120490	82/09/27	CONTRACT	8210130319 8210130310 82/10/01	50-302 8
8210120508	8210120497	82/09/10	CONTRACT	8210130328 8210130324 82/09/28	50-254 8
8210120517	8210120510	82/09/30	CONTRACT	8210130337 8210130335 82/10/07	50-247 0
8210120541	8210120534	82/09/30	CONTRACT	8210130342 8210130338 82/09/29	50-317 P
8210120550	8210120540	82/09/27	CONTRACT	8210130345 8210130340 82/09/29	50-311 8
8210120551	8210120546	82/09/24	50-254 F	8210130349 8210130344 82/10/04	50-267 R
6210120556	8210120549	82/09/30	CONTRACT	8210130350 8210130347 82/10/06	50-220 R
8210120560	8210120557	82/09/17	50-315 P	8210130358 8210130351 82/09/29	50-311 B
8210120565	8210120557	82/09/17	50-315 P	8210130361 8210130352 82/10/01	50-387 B
8210120590	8210120584	82/09/15	50-298 P	8210130362 8210130353 82/09/30	50-29 P
8210120604	8210120591	82/09/10	40-8745	8210130364 8210130356 82/09/28	50-346 S
8210120613 8210120624 8210120636 8210120640 8210120642	8210120607 8210120619 8210120627 8210120627 8210120627	82/09/27 82/09/20 82/09/23 82/09/23 82/09/23	CONTRACT 40-8781 50-341 A 50-341 A 50-341 A	8210130374 8210130369 82/09/27 8210130388 8210130382 82/09/30	50-309 P 50-387 S 50-341 Q 50-313 B 50-387 S
8210120645 8210120647 8210130005 8210130007 8210130014	8210120643 8210120643 8210130004 8210130004 8210130008	82/07/24 82/07/24 82/07/23 82/07/23 82/09/22	50-261 F 50-261 F 50-329 F 50-329 F CONTRACT	8210130498 8210130493 82710701 8210130403 8210130400 82709724 8210130408 8210130400 82709724	50-254 R 50-331 B 50-409 Q 50-409 G 50-346 B
8210130029 8210130038 8210130043 8210130054 8210130061	8210130024 8210130024 8210130024 8210130032 8210130058	82/09/20 82/09/20 82/09/20 82/09/23 82/09/28	50-416 P 50-416 P 50-416 P CONTRACT CONTRACT	8210130416 8210130400 82/09/24 8210130419 8210130411 82/09/28 8210130423 8210130413 82/09/27	50-346 8 50-409 0 50-247 8 50-254 8 50-460 0
8210130074	8210130071	82/09/28	CONTRACT	8210130431	50-22 R
8210130080	8210130078	82/09/17	XPORTLIC		50-280 G
8210130087	8210130075	82/09/28	50-289 T		50-460 G
8210130103	8210130099	82/10/06	50-317 Q		50-257 8
8210130104	8210130101	82/09/28	50-395 T		XPORTLIC
8210130112 8210130114 8210130128 8210130132 8210130137	8210130105 8210130105 8210130124 8210130129 8210130133	82/09/28 82/09/28 82/09/30 82/10/07 82/10/01	50-338 F 50-338 F 50-346 S 50-321 R 50-331 8	8210130457 B210130448 82/10/06 8210130459 B210130451 82/10/05 8210130462 8210130456 82/10/06	50-327 \$ 50-155 0 50-461 9 50-335 \$ 50-317 6
8210130145 8210130156 8210130162 8210130163 8210130167	821013013B 8210130144 8210130157 8210130160 8210130165	82/10/08 82/09/30 82/10/07 82/09/30 82/10/07	50-255 R 50-255 B 50-276 B 50-184 R 50-259 B	8210130473 8210130464 82/09/30 8210130478 8210130469 82/10/01 8210130479 8210130472 82/09/30	50-155 0 50-254 8 50-341 8 50-293 8 50-325 8
8210130170 8210130174 8210130180 8210130184 8210130185	8210130164 8210130172 8210130177 8210130181 8210130183	82/09/29 82/10/07 82/10/01 82/10/06 82/09/28	50-311 B 50-259 B 50-369 B 50-461 G 50-366 B	8210130486 8210130417 82/10/05 8210130493 8210130469 82/10/01 8210130497 8210130489 82/10/04	50-361 8 50-529 0 50-361 8 50-325 8 70-1100

TO PRINCIPAL DOCUMENTS

ACCESSION NUMBER				ACCESBIC	N NUMBER			
PRINCIPAL ENCLOSURE DOCUMENT	DATE ISSUED	SUBJECT CATEGORY	,	ENCLOSURE	PRINCIPAL DOCUMENT	DATE JEBUED	GUBJECT CATEGOR	
8210130505 B2101303047 B210130507 B210130500 B210130508 B210130501 B210130511 B210130501 B210130517 B210130507	82/10/04 82/09/30 82/09/29	50-329 50-280 50-361 50-254 50-331	T 8 8 8 8 P	8210150123 8210150128 8210150128 8210150133 8210150134	8210150116 8210150122 8210150100 8210150126 8210150130	82/09/24 82/10/05 82/09/24 82/10/12 82/09/14	50-369 50-213 50-324 50-352 70-824	9 8 0 A
8210130522 8210130513 8210130523 8210130514 8210130524 8210130515 8210130527 8210130514 8210130530 8210130520	82/09/16 82/09/29 82/09/16	50-313 50-483 50-289 50-483 50-302	8 9 8 9	8210130140 8210150142 8210150143 8210150152 8210150155	8210150127 8210150135 8210150131 8210150146 8210150148	82/09/29 81/07/07 82/09/23 81/03/27 82/09/29	50-272 50-220 50-267 50-255 50-272	55055
8210130531 8210130517 8210130533 8210130510 8210130535 8210130527 8210130540 8210130541 8210130550 8210130539	82/10/05 82/10/08 82/10/08	50-29 50-282 50-364 50-366 PR	8 P 8	8210150158 8210150159 8210190144 8210150170 8210190176	8210150150 8210150151 8210150149 8210150162 8210150163	82/10/11 82/10/08 82/09/21 82/09/24 82/10/12	50-266 50-275 50-438 50-324 50-528	R G O A
8210130555 8210130484 8210130557 8210130547 8210130558 8210130553 8210130559 8210130555 8210130552 8210130552	82/08/04 82/09/30 82/10/06	50-483 50-461 50-317 50-247 50-335	0 8 0 8	8210150178 8210150179 8210150180 8210150180 8210150182	8210150148 8210150154 8210150174 8210150171 8210150173	62/10/12 82/10/01 81/08/24 82/09/23 62/10/08	50-322 50-277 50-263 50-438 TOPREP	7 6 8 0
8210130566 8210130563 8210130569 8210130565 8210130573 8210130571 8210130577 8210130571 8210130578 8210130568	82/10/05 82/10/07 82/10/07	50-306 50-259 50-341 50-341 50-317	9 P P	8210150188 8210150189 8210150174 8210150175 8210150201	8210150168 8210150171 8210150187 8210150171 8210150185	82/10/12 82/09/23 82/09/23 82/09/23 82/09/30	50-322 50-438 50-338 50-438 50-334	T Q Q Q
8210130579 8210130572 8210130582 8210130571 8210130584 8210130583 8210130590 8210130587 6210130592 8210130587	82/10/07 82/10/06 82/10/01	50-328 50-361 50-320 50-331 CONTRACT	8 P P 8	8210150204 8210150206 8210150207 8210150208 8210150219	8210150197 8210150168 8210150171 8210150199 8210150215	82/09/14 82/10/12 82/09/23 82/09/27 82/09/17	70-143 50-322 50-438 50-334 70-1201	T Ø 5
8210150003 8210150001 8210150011 8210150005 8210150012 8210150004 8210150014 8210150001 8210150017 8210150001	82/09/24 82/08/13 62/09/30	50-293 50-416 50-369 50-324 50-293	9 9 9	8210150223 8210150226 8210150230 8210150231 8210150232	8210150168 8210150214 8210150209 8210150225 8210150221	82/10/12 82/09/27 82/10/04 82/10/05 82/10/01	50-322 50-317 50-390 50-327 50-289	0 Q Q
8210150018 8210150018 6210150019 8210150008 8210150020 8210150004 8210150021 8210150008	82/09/24 82/08/13 82/09/24	50-334 50-416 50-369 50-369 50-324	0 0 0	8210190235 8210150237 8210150239 8210150240 8210150241	8210150214 8210150225 8210150227 8210150168 8210150207	82/09/27 82/10/05 82/09/17 82/10/12 82/10/04	50-317 50-327 70-27 50-322 50-390	0 0 T 0
8210150024 8210150005 8210150025 8210150004 8210150027 8210150005 8210150028 8210150005 8210150032 8210150005	82/08/13 82/09/24 82/09/24	50-416 50-369 50-416 50-416 50-416	9 9	8210150245 8210150230 8210150251 8210150255 8210150256	8210 (50225 8210 (50168 8210 (50209 8210 (50249 8210 (50225	82/10/05 82/10/12 82/10/04 82/10/08 82/10/05	50-327 50-322 50-370 50-282 50-327	Q T Q Q
8210150034 8210150008 8210150039 8210150035 8210150040 8210150008 8210150045 8210150036	82/10/05 81/02/20 82/09/30	50-324 50-324 50-335 50-324 50-324	9 9 9	8210150257 8210150258 8210150260 8210150263 8210150265	8210150168 8210150246 8210150209 8210150253 8210150168	82/10/12 82/09/27 82/10/04 82/09/17 82/10/12	50-322 50-271 50-370 50-249 50-322	T 0 0 0 1
8210150046 8210150041 8210150049 8210150034 8210150049 8210150034 8210150052 8210150035 8210150055 8210150055	82/10/05 81/10/08 82/10/05	50-324 50-324 50-237 50-324 50-322	8 0 0	8210150268 8210150267 8210150272 8210150274 8210150278	8210150209 8210150262 8210150168 8210150246 8210150209	82/10/04 82/09/27 82/10/12 82/09/27 82/10/04	50-390 50-389 50-322 50-271 50-390	0 T 0
9210150062 8210150055 8210150065 8210150055 8210150066 8210150055 8210190066 8210150066	82/09/30 92/09/29 82/09/29	50-370 50-324 50-311 50-272 70-1113	9 8	8210150281 8210150283 8210150283 8210150287 8210150290	821015016B 8210150271 8210150209 8210150280 821015016B	82/10/12 82/10/07 82/10/04 81/06/08 82/10/12	50-322 50-333 50-390 50-320 50-322	T G G S T
8210150074 821015007: 8210150075 821015007: 8210150076 821015007: 8210150082 821015007: 8210150083 821015007.	82/09/29 2 82/10/04 2 82/10/04	50-348 50-272 50-348 50-348 50-289	9 9 9	8210130272 8210130275 8220130276 6210130303 8210150303	8210150282 8210150288 8210150279 8210150279 8210150209	82/10/06 82/10/05 82/10/12 82/09/27 82/10/04	50-277 50-324 50-322 50-277 50-390	P Q Q Q
8210150084 821015007 8210150084 821015007 8210150089 821015008 8210150091 821015008 8210150093 821015008	92/10/04 91/02/09 6 92/10/05	50-249 50-348 50-311 50-289 50-311	8 6 6 8	82{0150307 8210150308 8210150313 8210150313 8210150315	8210150300 8210150291 8210150279 8210150306 8210150304	82/10/12 81/02/27 82/10/12 82/10/08 82/09/10	50-155 50-324 50-322 50-470 50-390	0 8 0 E G
8210150101 821015007 8210150102 821015007 8210150103 821015007 8210150104 821015010 8210150112 821015007	7 81/10/13 6 82/09/15 0 82/09/24	50-413 50-249 50-424 50-324 50-219	8 0 8	8210150316 8210150319 8210150319 8210150324 8210150326	8210150312 8210150306 8210150099 8210150279 8210150322	82/10/05 82/10/08 82/07/30 82/10/12 82/10/11	50-334 50-470 50-311 50-322 50-341	6 6 6 6
8210150113 821015010 8210150114 821015010 8210150118 821015010 8210150120 821015010 8210150121 821015011	B B2/09/24 9 B2/09/29 0 B2/09/24	50-324 50-324 50-311 50-324 50-272	9 9 9 8	8210150330 8210150331 8210150333 8210150334 8210150335	8210150322 8210150323 8210150329 8210150318 8210150322	82/10/11 82/09/16 82/10/06 82/09/20 82/10/11	50-341 50-390 50-321 50-518 50-341	0 0 P 0

ACCESSION					ACCESS10	NUMBER			
ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGOR		ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGOR	
8210150337 8210150339 8210150343 8210150344 8210150344	8210 50279 8210 50311 8210 50322 8210 50338 8210 50322	82/10/12 82/09/30 82/10/11 82/10/11 82/10/11	50-322 50-311 50-341 50-344 50-341	0 5 0 9	8210180073 8210180075 8210180076 8210180078 8210180079	8210180070 8210180028 8210180070 8210180028 8210180070	82/10/06 82/08/20 82/10/06 82/08/20 82/10/06	50-206 FDIA 50-206 FDIA 50-206	P
8210150350 8210150351 8210150352 8210150353 8210150355	8210150328 8210150279 8210150322 8210150347 8210150347	82/09/23 82/10/12 82/10/11 82/10/04 82/10/07	CONTRACT 50-322 50-341 50-382 50-390	G G A	8210180080 8210180081 8210180083 8210180085 8210180087	8210180028 8210180028 8210180074 8210180028 8210180082	82/08/20 82/08/20 82/10/07 82/08/20 82/10/07	FOIA FOIA 50-244 FOIA 50-244	P P
8210150358 8210150365 8210150368 8210150371 8210150373	8210 150345 8210 150279 8210 150356 8210 150361 8210 150362	82/09/22 82/10/12 82/10/08 82/10/07 82/10/15	50-335 50-322 50-277 70-143 50-424	Q Q R	8210180087 8210180070 8210180091 8210180092 8210180094	8210180028 8210180082 8210180068 8210180028 6210180062	82/08/20 82/10/07 82/09/12 82/08/20 82/10/07	FOIA 50-244 50-286 FOIA 50-244	P R
8210150376 8210150377 8210150380 8210150386 8210150390	8210150361 8210150364 8210150361 8210150385 8210150381	82/10/07 82/10/11 82/10/07 82/09/28 81/08/24	70-143 50-263 70-143 50-263 50-282	P (1 S	8210180076 8210180100 8210180100 8210180102 8210180105	8210180028 8210180028 6210180097 8210180028 8210180028	82/09/20 82/09/20 82/10/01 82/08/20 82/08/20	FOIA FOIA 50-10 FOIA FOIA	R
6210150393 8210150401 8210150402 8210150408 6210150408	8210150279 8210150396 8210150279 8210150279 8210150403	82/10/12 82/09/17 82/09/20 82/09/20 82/10/06	50-322 50-261 50-322 50-259 70-143	G G G	8210180107 8210180108 8210180107 8210180111 6210180113	8210180103 8210180028 8210180104 8210180028 8210180028	82/10/14 82/08/20 82/10/14 82/08/20 82/08/20	70-143 F01A 50-416 F01A F01A	R
8210150410 6210150411 6210150413 6210150422 6210150427	8210150279 8210150405 8210150407 8210150279 8210150434	82/10/12 82/10/06 82/10/11 82/10/12 82/10/05	50-322 50-295 50-250 50-322 50-315	Q R P C P	8210180115 8210180116 8210180121 8210180121	8510180150 8510180058 8510180058 8510180058	92/08/20 92/08/20 82/08/20 82/08/20 82/10/05	AID9 AID9 AID9 AID9 AID9	8
8210150457 8210150477 8210150495 8210150500 8210150502	8210150449 8210150473 8210150487 8210150364 8210150497	82/10/11 82/09/22 82/09/30 82/10/11 62/09/28	50-35B 70-143 50-254 50-243 50-409	0 0 P	8210180125 8210180127 8210180129 8210180130 8210180132	8210180028 8210180028 8210180028	92/08/20 82/08/20 82/10/05 82/08/20 82/08/20	FOIA FOIA 50-316 FOIA FOIA	8
8210150504 8210150509 8210150512 8210150517 8210150521	8210150364 8210150364 8210150499 8210150513 8210150513	82/10/11 82/10/13 82/10/08 82/10/08	50-263 50-263 50-528 64999	PPG	8210180133 8210180136 8210180137 8210180137 8210180140	8210180124 8210180028 6210180131 8210180028 8210180028	82/09/22 82/08/20 82/10/04 82/08/20 82/08/20	50-317 FOIA 50-346 FOIA FOIA	р В
8210150522 8210150524 8210150527 8210150528 8210150530	8210150518 8210150513 8210150279 8210150519 8210150523	82/10/07 82/10/08 82/10/12 82/10/04 82/09/28	50-369 04999 50-322 50-287 50-10	F Q P Q	8210180145 8210180146 8210180150 8210180152 8210180153	8210180028 6210180142 6210180028 8210180028 8210180149	82/08/20 82/10/14 82/08/20 82/08/20 82/10/08	FOIA 50-454 FOIA FOIA 50-244	o P
8210150535 8210150536 8210150538 8210150540 8210150543	8210150517 8210150532 8210150523 8210150532 8210150539	82/10/06 82/10/08 82/09/28 82/10/08 82/10/01	50-287 QA999 50-10 QA999 50-10	P G Q	8210180157 8210180159 8210180159 8210180161 8210180162	8210180028 8210180147 8210180028 8210180147 8210180154	82/08/20 82/10/08 82/08/20 82/10/08 82/10/08	FOIA 50-244 FOIA 50-244 50-295	P P
6210150544 6210150604 6210150607 6210150613 6210150616	8210150532 8210150594 8210150605 8210150607 8210150594	82/10/08 82/09/30 82/09/01 82/08/31 82/09/30	GA999 50-315 70-1739 40-2259 50-315	F	8210180163 8210180164 8210180168 8210180171 8210180173	8210180154 8210180028 8210180028 8210180028 8210180028	82/10/13 82/08/20 82/08/20 82/08/20 82/08/20	50-359 FOIA FOIA FOIA FOIA	A
6210150649 6210150648 6210180007 6210180008 6210180026	8210150621 8210150621 8210180004 8210180006 8210180025	82/09/30 82/09/30 82/10/12 82/10/12 82/09/23	50-244 50-244 50-349 50-445 50-346	FOKP	8210180175 8210180176 8210180178 8210180191 8210180194	8210 180147 8210 180028 8210 180028 8210 180186 8210 180028	82/10/07 82/08/20 82/08/20 82/10/05 82/08/20	50-304 FOIA FOIA 50-255 FOIA	5
8210180030 8210180032 8210180034 8210180036 8210180038	8210180028 8210180028 8210180028 8210180028	82/08/20 82/08/20 82/08/20 82/08/20	FOIA FOIA FOIA FOIA		8210180197 8210180197 8210180200 8210180201 8210180208	8210 180028 8210 180174 8210 180028 8210 180175 8210 180204	82/08/20 82/10/12 82/08/20 82/09/20 82/09/20	FOIA 50~10 FOIA 50-312 50-352	P P C
8210180040 8210180041 8210180042 8210180043 8210180046	8210180028 8210180028 8210180028 8210180028	82/08/20 82/08/20 82/08/20 82/08/20	FOIA FOIA FOIA FOIA		8210180213 8210180215 82101802219 8210180222	8210180028 8210180028 8210180028 8210180028 8210180223	82/08/20 82/08/20 82/08/20 82/08/20 82/09/27	FOIA FOIA FOIA FOIA 50-352	ø
8210180049 8210180051 8210180054 8210180057 8210180058	8210180028 8210180028 8210180028 8210180028	82/08/20 82/08/20 82/08/20 82/08/20	FOIA FOIA FOIA FOIA		8210180229 8210180234 8210180239 8210180247 8210180248	8210180028 8210180028 8210180028 8210180028 8210180243	62/09/20 62/08/20 62/08/20 62/08/20	F01A F01A 50-2&4 F01A 50-528	P A
8210180060 8210180061 8210180064 8210180066 8210180072	8210180055 8210180028 8210180028 8210180028 8210180028	82/10/08 82/08/20 82/08/20 82/08/20 82/08/20	50-269 FOIA FOIA FOIA FOIA	P	8210180251 8210180257 8210180260 8210180262 8210180266	8210180028 8210180029 8210180028 8210180028 8210180028	82/08/20 82/08/20 82/08/20 82/08/20 82/08/20	FOIA FOIA FOIA FOIA	

ACCESSION				ACCE8910h			
ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGORY	ENCLOSURE	PRINCIPAL DOCUMENT	PATE ISSUED	SUBJECT CATEGORY
8210180270 8210180275 8210180277 8210180282 8210180284	8210180028 8210180028 8210180028 8210180028 8210180028	82/08/20 82/08/20 82/08/20 82/08/20 82/08/20	FOIA FOIA FOIA FOIA	8210180427 8210180428 8210180429 8210180430 8210180431	8210180028 8210180028 8210180028 8210180028 8210180028	62/08/20 82/08/20 82/08/20 82/08/20 82/08/20	FOIA FOIA FOIA FOIA
8210180287 8210180290 8210180298 8210180298 8210180301	8210180028 8210180028 8210180028 8210180028	82/08/20 82/08/20 82/08/20 82/08/20	FOIA FOIA FOIA FOIA	8210180432 8210180433 8210180434 6210180435 8210180436	8210180028 8210180028 8210180028 8210180028 8210180028	82/08/20 82/08/20 82/08/20 82/08/20	FOIA FOIA FOIA FOIA FOIA
8210180304 8210180307 8210180310 8210180312 8210180315	8210180028 8210180028 6210180028 8210180028 8210180028	82/08/20 82/08/20 82/08/20 82/08/20	FOIA FOIA FOIA FOIA	8210190002 6210190004 6210190010 6210190016 6210190017	8210170001 8210170003 8210170005 8210170013 8210170013	82/09/29 82/09/30 82/09/29 82/09/29	CONTRACT CONTRACT CONTRACT 50-321 F 50-321 F
8210180318 8210180319 8210180324 8210180326 8210180328	8210180028 8210180028 8210180028 8210180028 8210180028	82/08/20 82/08/20 82/08/20 82/08/20 82/08/20	FOIA FOIA FOIA FOIA	8210190024 8210190025 8210190026 8210190029 8210190037	8210190020 8210190018 8210190020 8210190022 8210190030	82/10/01 82/09/30 82/10/01 82/10/05 82/09/28	50-344 F CONTRACT 50-344 F 50-271 S CONTRACT
8210180332 8210180333 8210180335 8210180337 8210180338	8210180327 8210180028 8210180028 8210180028 8210180329	82/09/28 82/08/20 82/08/20 82/08/20 82/09/30	CONTRACT FOIA FOIA FOIA CONTRACT	8210170040 8210170046 8210170051 8210170058 8210170063	8210170036 8210170042 8210170042 8210170030 8210170037	82/10/01 82/10/01 82/10/05 82/09/22	50-315 F 50-321 F 50-321 F 50-373 B CONTRACT
8210180340 8210180341 8210180343 8210180344 8210180344	8210 180028 8210 180028 8210 180028 8210 180028 8210 180028	92/08/20 92/08/20 92/08/20 92/08/20 92/08/20	FOIA FOIA FOIA FOIA	8210190073 8210190077 8210190087 8210190095 8210190103	8210170066 8210170067 8210170076 8210170072 8210170077	82/10/01 82/10/07 82/09/24 82/09/30 82/09/29	50-34B F 50-333 B CONTRACT REVIEW GRP 50-369 F
8210180347 8210180348 8210180349 8210180351 8210180352	8210180028 8210180329 8210180028 8210180028 8210180028	82/08/20 82/09/30 82/08/20 82/08/20 82/08/20	FOIA CONTRACT FOIA FOIA	8210190105 8210190108 8210190115 8210190121 8210190124	8210190102 8210190097 8210190112 8210190112 8210190112	82/09/30 82/09/29 82/10/06 82/10/06 82/10/06	CONTRACT 50-369 F FDIA FDIA FDIA
8210180353 8210180354 8210180358 8210180359 8210180360	8210180028 8210180028 8210180028 82101800354 8210180028	82/08/20 82/08/20 82/08/20 82/08/12 82/08/20	F01A F01A F01A 40-8786 F01A	8210170141 8210170152 8210170154 8210170156 8210170161	8210190132 8210190144 8210190145 8210190149 8210190145	82/09/23 82/09/30 82/09/39 82/09/30	CONTRACT FO1A 50-269 P CONTRACT 50-269 P
8210180362 8210180363 8210180366 8210180367 8210180370	8210 180357 8210 180028 8210 180028 8210 180028 8210 180028	82/08/20 82/08/20 82/08/20 82/08/20	CONTRACT FOIA FOIA FOIA FOIA	8210190146 8210190167 8210190169 8210190173 8210190177	8210170158 8210170162 8210170145 8210170158 8210170172	82/07/28 82/07/30 82/07/29 82/07/28 82/07/21	50~387 F CONTRACT 50~269 P 50~307 F CONTRACT
8210180371 8210180372 8210180373 8210180374 8210180374	8210180365 8210180028 8210180028 8210180028	82/09/29 82/08/20 82/08/20 82/08/20	CONTRACT FOIA FOIA FOIA	8210190182 8210190185 8210190186 8210190191 8210190194	8210190179 8210190180 8210190178 8210190189 8210190178	82/09/21 82/09/29 82/09/30 82/09/30	CONTRACT 50-320 F 50-250 F FOIA 50-250 F
				8210170178 8210170204 8210170207 8210170215 8210170223	9210280402 8210170179 8210170179 8210170210 8210170217	82/09/30 82/09/15 82/09/15 82/09/30 82/09/30	FOIA 50-440 F 50-440 F CONTRACT CONTRACT
				8210190231 8210190237 8210190244 8210190256 8210190261	8210190228 8210190235 8210190240 8210190246 8210190254	82/10/14 82/10/01 82/10/11 82/09/03 82/10/07	50-312 Q 50-293 B 50-261 B 40-299 50-346 B
				8210190270 8210190277 8210190282 8210190283 8210190287	8210190264 8210190266 8210190274 8210190278 8210190266	82/10/12 82/10/12 82/10/04 82/10/13 82/10/12	50-338 8 50-315 9 50-334 8 50-312 R 50-315 9
				8210190293 8210190296 8210190317 8210190323 8210190328	8210190269 6210190290 8210190309 6210190309 6210190309	82/10/12 82/10/06 82/10/08 82/10/08 82/10/08	50-263 B 50-317 S 50-361 S 50-361 B 50-361 S
				8210190337 8210190339 8210190342 8210190346 8210190349	8210170327 6210170230 8210170340 8210170344 6210170347	82/10/12 82/09/30 82/10/12 82/10/04 82/09/22	50-330 B CONTRACT 50-315 B 50-373 B 50-285 Q
				8210190355 8210190356 8210190359 8210190361 8210190362	8210190353 8210190353 8210190358 8210190360 8210190360	82/10/11 82/10/11 82/10/11 82/10/05 82/10/05	50-305 Ø 50-305 Ø 50-346 Ø 50-331 Ø 50-331 Ø

ACCESSION	Y NUMBER				ACCEBBI	ON NUMBER			
ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJEC CATEGO		ENCLOSURE	PRINCIPAL DOCUMENT	DATE 155VED	SUDJEC CATEOO	
8210190348 8210190372 8210190374 8210190386 8210190389	8210190366 8210190369 8210190371 8210190378 8210190380	62/09/28 62/10/14 62/10/12 62/10/14 62/10/13	50-397 QA979 50-335 50-327 50-315	- G - F - B - B	8210190475 8210190475 8210190478 8210190487 8210190490	8210190669 8210190665 8210190676 8210190677 8210190686	82/10/04 82/10/01 82/10/01 82/10/08 82/10/15	50-266 50-397 50-315 50-302 50-29	G R B
8210190398 8210190404 8210190412 8210190415 8210190419	8210190375 8210190380 8210190403 8210190380 8210190413	82/10/12 82/10/13 82/10/13 82/10/13	50-219 50-315 50-249 50-315 50-498	8 S G	8210170474 8210170700 8210170702 8210170704 8210170707	8210190682 8210190658 8203050387 8210190701 8210190699	82/10/04 82/10/04 82/02/16 82/10/04 82/10/04	50-373 50-254 50-317 50-247 50-255	9 9 9
8210170420 8210170424 8210170427 8210170428 8210170427	8210170411 8210170417 8210170421 8210170411 8210170422	82/10/15 82/10/13 82/09/29 82/10/15 82/10/12	50-333 50-416 50-255 50-333 50-282	0 0 0 P	6210190714 6210190715 8210190720 6210190723 8210190733	8203050387 8210190689 8210190709 8210190722 8210190731	82/02/16 82/10/05 82/10/14 82/10/12 82/10/06	50-317 50-295 50-261 50-348 50-344	0 8 P R 0
8210170435 8210170437 8210170437 8210170444 8210170447	8210190411 8210190431 8210190432 8210190352 8210190421	82/10/15 82/09/30 82/10/07 82/10/12 82/09/29	50-333 50-382 50-282 50-375 50-255	9 9 9 9	8210190734 8210190734 8210190734 8210190744 8210190745	8210190728 8210190727 8210190731 8210190737 8210190726	82/10/12 82/10/08 82/10/06 82/10/07 82/10/08	50-284 50-314 50-344 50-373 50-306	8 8 8
82 10190452 82 10190454 82 10190455 82 10190457 82 10190466	8210190431 8210190448 8210190450 8210190352 8210190019	82/07/30 82/10/11 82/10/13 82/10/12 82/10/06	50-382 50-409 50-361 50-395 50-322	G G P A	8210190746 8210190751 8210190751 8210190757	8210190736 8210190739 8210190742 8210190749 8210190748	82/10/12 82/10/06 82/10/15 82/10/07 82/10/15	50-285 50-329 50-369 50-315 50-324	R G R B
8210190468 8210190471 8210190476 8210190481 8210190493	8210190462 8210190458 8210190472 8210190462 8210190483	82/07/29 82/10/05 82/10/06 82/07/29 82/10/08	50-373 50-249 50-336 50-373 50-295	9 5 6 9	8210190760 8210190760 8210190762 8210190766 8210190771	8210190753 8210190725 8210190754 8210190754 8210190763	82/10/12 92/10/01 92/10/08 82/09/27 82/09/27	50-254 GA799 50-324 GA999 50-440	F 8 0
8210190494 8210190500 8210190501 8210190503 8210190506	8210190487 8210190492 8210190478 8210190498 8210190490	82/09/29 82/10/15 82/10/05 82/09/29 82/10/04	50-373 50-395 50-361 50-373 50-206	5 P G B B	8210190773 8210190776 8210190785 8210190787 8210190803	8210170767 8210170772 8210170780 8210170763 8210170797	92/10/12 82/10/01 82/10/12 82/09/27 82/10/12	50-364 50-445 50-254 50-440 50-317	RGPGG
8210190508 8210190511 8210190514 8210190515 8210190516	8210190505 8210190504 8210190509 8210190507 8210190497	82/10/12 82/10/05 82/09/29 82/10/05 82/09/28	50-395 50-366 50-373 50-272 50-313	P 8 8 P 0	8210190820 8210200004 8210200007 8210200013 8210200014	8210190816 8210200001 8210200002 8210200009 8210200010	82/07/27 82/10/15 82/07/29 82/10/15 82/10/10	50-445 70-143 50-373 50-400 50-311	G S Q R
8210190525 8210190526 8210190533 8210190539 8210190543	8210190522 8210190517 8210190530 8210190531 8210190537	82/09/29 82/10/07 82/10/12 82/09/22 82/10/08	50-373 50-313 State Pr 50-285 50-247	999	8210200021 8210200024 8210200035 8210200039 8210200042	8210200026 8210200028 8210200028 8210200028	82/10/15 82/02/03 82/10/13 82/10/15 82/10/13	50-400 50-333 50-443 50-333 50-443	0 R 0 P 0
6210190552 8210190556 8210190558 8210190567 8210190569	8210190544 6210190549 8210190545 8210190561 8210190562	82/10/15 82/10/01 82/10/06 82/10/13 82/09/28	50-269 50-344 50-368 50-416 50-397	R 0 5 8 0	8210200048 8210200049 8210200063 8210200068 8210200083	8210200043 8210200024 8210200046 8210200046 8210200074	82/10/06 82/10/13 82/10/15 82/10/15 82/10/12	50-280 50-443 50-277 50-277 50-322	P 0 P P 0
8210190573 8210190577 8210190578 8210190579 8210190582	8210190536 8210190570 8210190572 8210190568 8210190576	82/10/08 82/10/13 82/10/08 82/07/30 82/10/04	50-373 50-320 50-315 50-295 50-397	SPSGE	9210200084 8210200089 8210200090 8210200096 8210200106	8210200084 8210200074 8210200085 8210200093 8210200104	82/10/15 82/10/10 82/10/10 82/10/10	50-400 50-322 50-272 50-331 70-820	G R R
8210190586 8210190588 8210190591 8210190598 8210190599	8210190576 8210190572 8210190580 8210190594 8210190548	82/10/04 82/10/08 82/10/07 82/09/28 82/09/30	50-397 50-315 50-244 50-312 50-295	E 8 0 P 0	8210210010 8210210018 8210210038 8210210044 8210210048	8210210006 821021015 8210210015 821021033	82/10/07 82/10/12 82/08/30 82/10/07		
8210190601 8210190602 8210190603 8210190608 8210190612	B2101905B9 8210190595 8210190594 B210190596 B210190605	82/09/29 82/10/05 82/09/28 82/09/22 82/09/30	50-373 50-366 50-312 50-482 50-312	0 8 P 0	8210210053 8210210055 8210210056 8210210056 8210210056				
8210170614 8210170615 8210170618 8210170624 8210170626	8210190609 8210190604 8210190580 8210190613 8210190617	82/10/08 82/10/11 82/10/07 82/10/07 82/10/05	50-348 50-255 50-244 50-295 50-295	8 9 9	8210210072 821021008 821021008 821021009				
8210170628 8210170636 8210170637 8210170647 8210170647	8210170420 8210170432 8210170580 8210170580 8210170437	82/10/07 82/10/07	50~255 50~27 50~244 50~244 50~255	8 0 0 8	821021011 82102101 82102101 821021011 821021011				
8210190654 8210190664 8210190667 8210190668 8210190674	821019043B 8210190443 8210190455 8210190463 8210190466	82/10/13 82/10/12 82/09/27	50-409 50-331 50-267 50-213 50-325	0 R P 6	85105(011 85105(01) 85105(01) 85105(01) 85105(01)				

PAINCE P	ACCESSI	NUMBER					NUMBER			
201001015 201001014 20100705 201000000 201000000 201000000 201000000 201000000 201000000 201000000 201000000 201000000 2010000000 2010000000 2010000000 2010000000 2010000000 2010000000 2010000000 2010000000 2010000000 2010000000 2010000000 2010000000 2010000000 20100000000 2010000000 2010000000 20100000000 20100000000 20100000000 20100000000 20100000000 20100000000 20100000000 20100000000 20100000000 201000000000 201000000000 201000000000 2010000000000		DOC UMENT	ISSUED	CATEGOR		ENCLOSURE	PRINCIPAL DOCUMENT	ISSVED	SUDJECT CATEODR	Y
Selection Sele	8210210161 8210210162 8210210178 8210210179	8210210147 8210210144 8210210174 8210210173	82/09/29 82/10/05 82/09/20 82/10/20	CONTRACT 50-272 CONTRACT 50-320	G	8210220092 8210220097 8210220100 8210220108	8210220064 8210220095 8210220095 8210220103	82/10/01 82/10/14 82/10/14 82/10/13	40-8111 50-280 50-280 50-245 50-245	5 5 5
Selication Sel	8210210200 8210210206 8210210213	8210210185 8210210174 8210210201	82/09/15 82/10/15 82/10/06	50-271 50-13 50-244	P G G	8210220138 8210220138	8210220123 8210220127 8210220130	82/09/28 82/10/12 82/10/14	50-498 40-1162 50-400 50-298 50-400	0 0 0
Septiminary	8210210236 8210210238 8210210240	8210210231 8210210231 8210210232	82/10/06 82/10/04 82/10/19	50-334 50-271 50-537	G G	8210220145 8210220147 8210220150	8210220127 8210220139 8210220131	82/10/12 82/10/04 82/10/18	50-400 50-400 50-324 50-416 50-29	0 0 0 8 0
### ### ### ### ### ### ### ### ### ##	8210210244 8210210293 8210210299	8210210255 8210210285 8210210272	82/10/04 82/10/11 82/09/29	50-220 50-387 50-287	G B P	8210220162 8210220163 9210220165	8210220140 8210220140	82/10/08 82/10/04 82/09/27	50-424 50-416 50-400 40-2259 40-2259	G S Q
SECTION SECT	8210210307 8210210316 8210210321	8210210300 8210210313 8210210313	82/10/07 82/10/07 82/10/07	50-247 50-309 50-309	0	8210220173 8210220174 8210220179	8210220169 8210050398 8210220177	82/10/04 82/09/23 82/10/14	70-371 50-324 50-447 70-371 50-438	0 A 0
Selicition Sel	8210210347 8210210358 8210210364	8210210344 8210210351 8210210351	82/10/18 82/10/15 82/10/15	50-454 50-440 50-440	Q Q	8210220199 8210220199 8210220191	8210220185 8210220180	85\10\08 85\09\58 85\10\13	50-219 TOPREP 50-438 50-416 50-277	Q G S R
8210210449 8210210439 821071045 50-289 T 8210220229 8210220219 82107075 50-289 8210210440 8210210440 8210210439 821071045 8210210440	6210210400 8210210403 8210210410	8210210391 8210210395 8210210395	82/10/18 82/09/30 82/09/30	50-358 50-305 50-305	G P	8210220201 8210220201 8210220211	8210220195 8210220204 8210220204	82/10/15 82/10/15 82/10/15	50-416 50-245 50-424 50-424 50-424	8 0 0
8210210457 8210210338 82/10/16 50-272 Q 8210220239 82/10/18 50-41 8210210467 8210210338 82/10/16 50-217 R 821022024 8210220259 82/10/18 70-68 8210210467 8210210464 82/10/06 50-272 Q 8210220267 8210220266 82/10/18 70-68 8210210470 8210210459 82/10/18 50-286 P 8210220267 8210220267 82/10/18 50-48 8210210477 8210210459 82/10/18 50-286 P 8210220274 8210220267 82/10/18 50-48 8210210477 8210210459 82/10/18 50-272 Q 8210220274 8210220269 82/10/18 50-41 8210210505 8210210505 8210210508 82/10/05 50-272 Q 8210220274 8210220269 82/10/18 50-41 8210210505 8210210508 82/10/05 50-37 T 8210220274 8210220269 82/10/20 50-53 8210210505 8210210508 82/10/05 80-373 T 8210220276 8210220269 82/10/20 50-53 8210210525 8210210508 82/10/05 80-373 T 8210220276 8210220269 82/10/20 50-53 8210210525 8210210508 82/09/30 40-3453 8210220289 8210220289 82/10/20 50-33 8210220289 82/10/20 50-33 8210220289 82/10/20 50-33 8210220289 82/10/20 50-33 8210220289 82/10/20 50-33 8210220289 82/10/20 50-33 8210220289 82/10/20 50-33 8210220289 82/10/20 50-33 8210220289 82/10/20 50-33 8210220289 82/10/20 50-33 8210220289 82/10/20 50-33 8210220289 82/10/20 50-33 8210220289 82/10/20 50-33 8210220289 82/10/20 50-33 8210220289 82/10/20 50-34 P 8210220289 82/10/20 50-33 82/10/20 50-33 82/10/20 50-33 82/10/20 50-33 82/10/20 50-34 P 8210220289 82/10/20 50-34 P 8210220289 82/10/18 50-30 82/10/20 50-34 P 8210220299 8210220299 82/10/18 50-30 82/10/20 50-30 82/10/20 50-30 82/10/20 50-30 82/10/20 50-30 82/10/20 50-30 82/10/20 50-30 82/10/20 50-30 82/10/20 50-30 82/10/20 50-30 82/10/20 50-30 82/1	8210210434 8210210436 8210210444	8210210428 8210210433 8210210438	82/10/15 82/10/11 82/07/28	50-289 50-387 CONTRACT	8	8210220222 8210220232 8210220234	8210220217 8210220227 8210220227	82/10/07 82/10/04 82/10/07	50-424 50-321 50-348 50-338 50-498	0 5 0 8 A
Selection Sele	8210210451 8210210457 8210210469	8210210435 8210210328 8210210464	92/10/05 82/10/15 82/10/06	50-272 50-317 50-272	R G	8210220293 8210220262 8210220264	8210220252 8210220259 8210220260	82/10/18 82/10/08 82/10/13	50-528 50-482 50-416 70-687 50-261	R A B
8210210543 8210210544 82/09/20 50-317 F 8210220286 8210220277 82/10/15 50-33 8210210540 8210210544 82/09/20 50-317 F 8210220286 8210220286 8210220277 82/10/14 50-32 8210210540 8210210544 82/09/20 50-317 F 8210220288 8210220288 8210220288 82/09/20 50-317 F 8210220288 8210220288 8210220288 82/09/20 50-319 F 8210220288 8210220288 82/09/20 50-319 F 8210220288 8210220288 82/09/20 50-319 F 8210220289 82/09/20 50-319 F 8210220299 82/09/30 50-319 F 8210220299 82/09/30 50-25 8210220007 8210220299 82/09/30 50-25 8210220007 8210220299 82/09/30 50-25 8210220028 82/09/30 50-25 82	8210210477 8210210505 8210210512	8210210464 8210210502 8210210508	82/10/06 82/07/29 82/10/05	50-272 CONTRACT 50-373	a	8210220274 8210220276 8210220279	8510550598 8510550598 8510550598	82/10/20 82/10/20	50-498 50-414 50-537 50-537 50-313	00000
8210210555 8210210548 82/09/20 50-346 P 8210220291 8210220280 82/10/15 50-33 8210210555 8210210548 82/09/20 50-346 P 8210220279 8210220288 82/10/20 50-58 8210210558 8210210548 82/09/20 50-346 P 8210220277 8210220288 82/10/20 50-58 8210210558 8210210548 82/09/20 50-346 P 8210220277 8210220288 82/10/20 50-348 82/09/20 50-346 P 8210220277 8210220288 82/10/20 50-348 82/09/20 50-346 P 8210220277 8210220288 82/10/20 50-348 82/09/20 CONTRACT 8210220298 8210220279 82102020279 82102020279 8210220279 8210220279 8210220279 8210220279 8210220279 8210220279 8210220279 8210220279 8210220279 8210220279 8210220279 8210220279 8210220279 8210220279 8210220279 8210220279 8210220279	8210210543 8210210544 8210210550	8210210539 8210210544 8210210548	82/04/21 82/09/23 82/09/20	70-2955 50-317 50-346	Р	8210220283 8210220284 8210220287	8210220268 8210220280 8210220277	02/10/20 02/10/15 02/10/14	50-416 50-537 50-335 50-321 50-537	8 0 0
8210210394 8210210376 82/09/30 CONTRACT 8210220297 8210220277 8210220277 8210220200 82/10/14 50-32 8210210394 8210310384 82/09/30 CONTRACT 8210220303 8210220290 82/10/15 50-32 8210220007 8210220006 82/10/19 50-278 P 8210220304 8210220299 82/10/08 50-278 8210220317 8210220315 82/10/08 50-293 P 8210220317 8210220317 8210220277 8210220279 82/10/08 50-25 8210220028 8210220025 82/09/29 70-1257 8210220317 8210220294 82/10/08 50-25	8210210553 8210210555 8210210554	8210210548 8210210545 8210210548	82/09/20 82/09/30 82/09/20	50-346 50-29 50-346	P P	8210220291 8210220292 8210220295	8210220280 8210220277 8210220268	82/10/15 82/10/14 82/10/20	50-416 50-335 50-32! 50-537 50-335	8 0
8210220028 8210220025 82/09/29 70-1257 8210220317 8210220296 82/10/08 50-25	8210210581 8210210594 8210220007	9210210574 9210210584 9210220006	92/09/30 82/09/30 82/10/19	CONTRACT CONTRACT 50-278	r F	8210220299 8210220303 8210220304	8210220277 8210220280 8210220296	82/10/14 82/10/15 82/10/08	50-366 50-321 50-335 50-250 50-321	P G G
8210220056 9210220052 92/10/15 50-302 8 9210220320 9210220308 92/10/15 70-11	8210220028 8210220046 8210220056	8210220025 8210220047 8210220052	82/09/29 82/09/17 82/10/15	70-1257 NUREO 50-302	6	8210220317 8210220319 8210220320	821022029A 8210220312 8210220308	82/10/08 82/10/14 82/10/15	50-250 50-250 50-140 70-1113 50-390	Q Q
8210220044 8210220060 82/10/14 50-336 8 8210220327 8210220318 82/10/15 50-36 8210220067 8210220365 82/10/15 30-416 8 8210220329 8210220296 82/10/16 50-25 8210220070 8210220066 82/10/14 40-8111 8210220330 8210220312 82/10/14 50-16	8210220067 8210220067 8210220070	8210220060 8210220065 8210220066	82/10/14 82/10/11 82/10/01	50-336 50-416 40-8111	6	8210220327 8210220329 8210220330	8210220318 8210220312 8210220312	82/10/15 82/10/08 82/10/14	50-140 50-349 50-250 50-160 50-370	0 8 0 0
8210220080 8210220066 82/10/01 40-8111 8210220344 8210220340 82/10/13 50-39 8210220085 9210220081 92/10/08 50-327 8 82102200832 8210220331 82/10/13 50-24 8210220086 8210220346 82/10/01 40-8111 821022035 8210220331 82/10/04 50-28	8210220080 8210220080 8210220080	8210220081 8210220081	82/10/01 82/10/08 82/10/01	40-8111 50-327 40-8111	8	8210220346 8210220352 8210220356	8210220340 8210220344 8210220331	82/10/15 82/10/13 82/10/04	50-160 50-395 50-244 50-280 50-387	8 0 9 1

ACCESS 10	NUMBER					IN NUMBER			
ENCLOSURE	PRINCIPAL DOCUMENT	DATE	SUBJEC CATEOD		ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJEC CATEGO	RY
8210220369 8210220369 8210220374 8210220385 8210220388	8210220344 8210220363 8210220367 8210220378 8210220384	82/10/13 82/10/20 82/10/13 82/10/15 82/09/28	50-244 50-275 50-352 50-318 50-321	9 2 9 8	6210250184 6210250184 6210250196 6210250198 6210250201	8210250181 8210250192 8210250195 8210250197 8210250208	82/10/04 82/10/01 82/09/23 82/10/08 82/08/30	TOPREP 50-133 50-341 50-275 50-338	R F R F
8210220398 8210220401 8210220405 8210220404 8210220408	8210220392 8210220396 8210220387 8210220387	82/10/08 82/10/12 82/10/12 82/10/08	50-280 50-259 50-440 50-438 50-280	9 9	8210250218 6210250227 6210250231 6210250232 6210250253	8210250214 8210250222 8210250226 8210250224 8210250248	82/10/15 82/10/18 82/10/14 82/10/04 82/10/20	50-361 50-341 50-345 50-461 50-483	8 0 0
8210220413 8210220417 8210220418 8210220421 8210220422	9210220392 9210220407 9210220411 9210220415 9210220387	82/10/08 82/10/05 82/10/12 82/10/07 82/10/12	50-280 0A999 50-271 50-339 50-438	9 9	8210250261 8210250262 8210250264 8210250273 8210250273	8210250251 8210250258 8210250254 8210250254	82/10/11 82/10/13 82/10/19 82/10/15 82/10/19	50-331 50-266 50-387 50-361 50-387	8 8 8 8
8210220427 8210220430 8210220431 8210220432 8210220435	8210220420 8210220420 8210220428 8210220387 8210220424	82/10/12 82/10/12 82/10/18 82/10/12 82/10/07	70-1113 70-1113 50-414 50-438 50-281	9 0 5	8210250278 8210230279 8210230279 8210230297 8210250279	8210250268 8210250270 8210250283 8210250286 8210250272	82/10/12 82/10/12 82/10/14 82/10/07 82/10/13	50-237 50-346 50-237 50-346 50-368	S S C S
8210220437 8210220442 8210220443 8210220446 8210220448	8210220420 8210220420 9210220438 8210220387 8210220439	82/10/12 82/10/12 82/10/15 82/10/12 82/10/19	70-1113 70-1113 50-395 50-438 50-170	S Q Q	8210250300 8210250314 8210250327 8210250332 8210250333	8210250289 8210250304 8210250323 8210250323 8210250323	82/10/11 82/09/22 82/10/18 82/10/21 82/10/18	50-331 50-249 50-135 50-289 50-155	3 B P O P
8210220450 8210220461 8210220462 8210220466 8210220471	8210220441 8210220454 8210220458 8210220459 8210220457	82/10/07 82/10/04 82/10/08 82/10/18 82/09/29	50-339 50-338 50-416 50-390 50-413	8 8 9	8210250337 8210250339 8210250342 8210250343 8210250348	8210250323 8210250330 8210250336 6210250334 8210250328	82/10/18 82/10/19 82/10/07 82/10/15 82/09/22	50-155 50-375 50-331 50-244 50-249	P Q B S
8210220474 8210220476 8210220480 8210220482 8210220485	8210220469 8210220464 8210220469 8210220469 6210220469	82/10/18 82/07/27 82/10/18 82/10/18 82/10/18	50-327 40-6422 30-327 50-327 50-327	Q Q Q	8210250350 8210250352 8210250361 8210250372 8210250373	8210250334 8210250344 8210250351 8210250363 8210250367	82/10/07 82/10/15 82/10/08 82/10/20 82/10/19	50-331 50-266 50-528 50-213 50-387	0 9 9 P
8210220492 8210220494 8210220496 8210220499 8210220500	8210220489 8210220489 8210220489 8210220495 8210220495	82/10/18 82/10/18 82/10/18 82/10/18	50-324 50-324 50-324 50-261 50-261	0 0	8210250375 8210250374 8210250377 8210250370 8210250380	8210250351 8210250364 8210250369 8210250367 8210250381	82/10/08 82/10/15 82/10/14 82/10/19 82/10/14	50-528 50-282 50-387 50-387 50-387	8 8 8
8210220501 8210220503 8210220504 8210250008 8210250021	8210220495 8210220489 8210220495 8210250006 8210250019	92/10/18 92/10/18 92/10/18 92/09/27 92/07/30	50-261 50-324 50-261 40-8681 40-299	0 0	8210250387 8210250387 8210250390 8210250372 8210250373	8210250384 8210250382 8210250384 8210250168 8210250340	82/10/12 82/10/06 82/10/15 82/10/06 82/10/04	50-331 50-311 50-312 50-275 50-315	888
8210250033 8210250050 8210250051 8210250056 8210250057	8210250030 8210250048 8210250048 8210250054 8210250053	82/09/30 82/09/21 82/09/21 82/08/27 82/10/06	NUREQ 50-335 50-335 40-8402 50-311	P P	8210250394 8210220395 8210240010 8210240011 8210240012	8210250340 8210250340 8210250006 8210250006 8210250006	82/10/04 82/10/04 82/10/05 82/08/30 82/10/05	50-315 50-315 50-302 70-2968 50-302	PPF
8210250059 8210250041 8210250070 8210250074 8210250075	8210250058 8210250060 8210250067 8210250067 8210250072	82/10/19 82/10/21 82/10/15 82/10/15 82/10/07	50-322 70-143 50-240 50-240 50-341	P P Q	6210240014 8210240018 8210240041 8210240049 8210240080	8210260013 8210260017 8210260038 8210260038 8210260079	82/09/30 82/09/31 82/09/02 82/09/18	40-6622 40-8681 70-820 70-820 40-3453	
8210250077 8210250078 8210250080 8210250093 8210250095	6210250067 8210250067 8210250072 8210250084 8210250088	82/10/15 82/10/15 82/10/07 82/10/11 82/10/15	50-260 50-260 50-341 50-344 50-318	P P G 61 81	8210260091 8210260099 8210260137 8210260137 8210260118	8210260086 8210260096 8210190764 8210260116 8210260115	82/06/09 82/08/26 82/10/07 82/10/18 82/10/19	WASTE MC 40-8761 50-397 50-250 50-373	A S S
8210250097 8210250101 8210250109 8210250113 8210250114	8210250092 8210250094 8210250105 8210250110 8210250105	82/10/12 82/10/15 82/10/07 82/10/12 82/10/07	50-219 50-259 50-373 50-70 50-373	PPOPO	8210260123 8210260125 8210260127 8210260129 8210260131	8210240126 8210260122 8210260122 8310260120	82/10/15 82/10/08 82/10/05 82/10/08 82/10/05	50-368 50-334 GA999 50-334 GA999	S F
8210250126 8210250128 8210250140 8210250141 8210250147	8210250114 8210250121 8210250137 8210250135 8210250145	65/10/15 85/10/50 85/10/14 85/10/18	50-254 QA999 50-361 GA999 50-247	9 8	8210260136 8210260141 8210260166 8210260167 8210260169	8210240133 8210240134 8210240159 8210240163 8210240145	82/10/21 82/10/20 82/10/22 82/10/11 82/10/13	50-338 50-322 50-395 50-334 50-29	P P 8
9210250153 9210250161 9210250163 9210250163	B21025014B B210250154 B210250157 B210250152 B210250155	82/10/07 82/10/13 82/10/15 82/10/15 82/10/18	50-254 50-317 50-368 50-373 50-254	88757	8210260175 8210260180 8210260183 8210260184 8210260185	8210260170 8210260178 8210260176 8210260177 8210260182	82/10/19 82/10/19 82/10/18 82/10/21 82/10/15	50-333 50-313 50-255 50-220 50-219	8 9 9
8210250171 8210250175 8210250177 8210250178 8210250183	8210250167 8210250164 8210250155 8210250173 8210250177	82/10/08	50-275 50-344 50-254 50-362 50-282	P 9 9 8	8210260187 8210280191 8210280195 8210280196 8210280196 8210280200	8210260188	82/10/13 82/10/15 82/10/20 82/10/20 82/10/16	50-219 50-219 50-329 50-328 50-309	9 0 8

ACCESSION NUMBER				N NUMBER		
PRINCIP ENCLOSURE DOCUME	it issued	SUBJECT CATEGORY	ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGORY
8210260208 8210260 8210260221 8210260 8210260222 8210260 8210260223 8210260 8210260226 8210260	99 82/10/18 110 82/10/18 112 82/10/20 119 82/10/19	50-307 8 50-373 8 50-257 5 50-304 8 50-334 8	8210260530 8210260538 8210260542 8210260547 8210260547	8210260525 8210260535 8210260526 8210260535 8210260543	82/09/28 82/09/24 82/10/06 82/09/24 82/09/01	CONTRACT 50-320 P 50-10 P 50-320 P 40-8027
8210240230 B210260 8210260234 8210260 8210260234 8210260 8210260239 8210260 8210260239 8210260	24 92/10/22 25 92/09/29 27 92/10/19	50-72 R 50-72 R 50-320 G 50-373 B 50-322 T	8210260552 8210260558 8210260550 8210260561 8210260569	8210260535 8210260494 8210260557 8210260559 8210260568	82/09/24 82/10/12 82/09/03 82/09/28 82/08/30	50-320 ₽ QA999 40-8102 CONTRACT 70-143
8210260240 8210260 8210260242 8210260 8210260246 8210260 8210260247 8210260 8210260254 8210260	232 82/10/12 232 82/10/12 241 82/10/01	CONTRACT 50-322 T 50-322 T 50-387 Q 50-295 S	8210260575 8210260579 8210260579 8210270009 8210270020	8210260572 8210260572 8210260581 8210270008 8210270015	82/10/08 82/10/08 82/09/16 82/10/12 82/10/22	50-440 F 50-440 F 50-201 0 50-309 0 50-537 0
8210260257 8210260 8210260263 8210260 8210260265 8210260 8210260266 8210260 8210260270 8210260	260 82/10/18 245 82/10/22 256 82/10/18	50-387 Q 50-305 8 50-327 Q 50-325 8 50-387 Q	8210270023 8210270033 8210270036 8210270041 8210270051	8210270015 8210270027 8210270015 8210270015 8210270046	82/10/22 82/10/12 82/10/22 82/10/23	50-537 G CCNTRACT 50-537 G 50-537 G 50-447 A
8210260280 8210260 8210260284 8210260 8210260287 8210260 8210260293 8210260 8210260297 8210260	282 82/09/29 281 82/10/19 290 82/10/19	CONTRACT CONTRACT 50-337 8 50-338 8 50-373 8	8210270052 8210270056 8210270060 8210270064 8210270068	9210270015 8210270015 8210270015 8210270015 8210270015	82/10/22 82/10/22 82/10/22 82/10/22	50-537 0 50-537 0 50-537 0 50-537 0 50-537 0
8210260301 8210260 8210260310 8210260 8210260313 8210260 8210260314 8210260	307 82/10/22 309 82/10/22 311 82/10/18	50-298 G 50-454 G 50-302 G 50-373 B 50-155 G	8210270069 8210270070 8210270079 8210270081 8210270085	8210270015 8210270067 8210270074 8210270077 8210270074	82/10/22 82/09/03 82/09/07 82/09/14 82/09/07	50-537 0 70-687 71-6639 40-2061 71-6639
8210240318 8210240 8210240321 8210240 8210240325 8210240 8210240336 8210240 8210240337 8210240	917 82/10/19 923 82/10/21 931 82/10/21	50-324 8 50-373 8 50-324 P 50-369 P 50-440 0	8210270088 8210270095 8210270019 8210270113 8210270118	8210270077 8210270090 8210270083 8210270104 8210270104	82/09/14 82/10/25 82/09/20 82/10/15 82/10/15	40-2061 50-289 0 50-251 8 50-267 P
8210240339 8210240 8210240345 8210240 8210240351 8210240 8210240352 8210240	941 82/10/22 940 82/09/17 941 82/10/22	50-333 0 40-8610 TOPREP 40-8610 50-260 8	8210270127 8210270139 6210270142 8210270144 8210270152	8210270124 8210270132 8210270136 8210270132 8210270149	82/10/25 82/10/08 82/10/07 82/10/08 82/10/05	50-584 A 50-369 F 50-272 P 50-369 F XPORTLIC
8210260354 8210260 8210260360 8210260 8210260369 8210260 8210260367 8210260 8210260377 8210260	346 #2/10/19 344 #2/10/18 357 #2/10/15	50-387 P 50-339 B 50-325 S 50-335 S 50-302 Q	8210270149 8210270177 8210270183 8210270183 8210270183	8210270164 8210270165 8210270179 8210270180 8210270184	82/09/29 81/05/26 82/09/14 82/08/25 82/10/22	TOPREP 50-309 9 40-8577 40-8502 50-275 P
8210240377 8210240 8210240382 8210260 8210260384 8210260 8210260385 8210260 8210240386 8210260	372 82/10/18 380 82/10/22 366 82/10/22	50-387 P 50-341 Q 50-454 Q 50-387 P 50-333 8	8210270193 8210270197 8210270203 8210270208 8210270215	8210270190 8210270195 8210270199 8210270204 8210270212	82/10/20 82/09/02 82/09/28 82/10/26 81/12/07	50-382 K 40-8102 TOARTMOD 50-338 P 50-280 B
8210260391 8210260 8210260392 8210260 8210260404 8210260 8210260407 8210260 8210260410 8210260	380 82/10/22 397 82/10/21 381 82/10/19	50-335 Q 50-454 Q 50-537 Q 50-259 B 50-324 P	8210270220 8210270221 8210270223 8210270224 8210270224	8210270212 8210270207 8210270207 8210270212 8210270222	81/12/07 82/09/29 82/09/29 81/12/07 82/08/27	50-280 8 CONTRACT CONTRACT 50-280 8 40-8632
8210260411 8210260 8210260424 8210260 8210260435 8210260 8210260441 8210260 8210260446 8210260	416 82/10/21 416 82/10/21 432 82/10/17	50-295 8 50-361 P 50-361 P 50-336 8 50-260 8	8210270230 8210270239 821027020 821027024 8210270247	8210270224 8210270227 8210270234 8210270237 8210270242	82/07/28 82/07/26 82/10/22 81/05/15 82/09/24	CONTRACT 57-902 G 50-275 R 50-318 8 40-8027
8210260463 8210260 8210260465 8210260 8210260470 8210260 8210260477 8210260	457 92/10/20 453 82/10/18 472 92/10/21	50-348 8 50-309 0 50-348 8 50-206 P	8210270248 8210270249 8210270254 8210270257 8210270257	8210270244 8210270245 8210270251 8210270252 8210270256	81/06/05 81/05/18 81/12/15 81/05/22 82/10/08	50-317 S 50-213 S 50-247 S 50-317 S 50-266 F
		8 A P B 8	8210270240 8210270261 8210270268 8210270269 8210270271	9210270259 9210270256 9210270267 9210270266 9210270267	82/10/12 82/10/08 82/10/22 81/05/20 82/10/22	50-338 P 50-246 F 50-334 P 50-317 8 50-334 P
	176 82/10/2 2	E P 50-335 G	8210270273 8210270275 8210270275 8210270280 8210270288	8210270272 8210270274 8210270276 8210270279 8210270270	81/06/01 81/05/20 81/05/22 81/05/01 82/10/19	50-317 8 50-317 8 50-317 8 50-317 6 50-155 P
8210260511 8210260 8210260515 8210260 8210260520 8210260 8210260521 9210260 8210260524 8210260	976 92/10/22 516 82/09/28 518 92/09/16	50-241 P 50-335 G CONTRACT 50-272 F 50-272 F	8210270297 8210270302 6210270303 8210270304 8210270307	8210270294 8210270294 8210270294 8210270301 8210270314	82/10/15 82/10/15 82/10/15 82/10/15 82/09/29	50-266 P 50-266 P 50-266 P ORG 50-312 P

ACCESSIO	NUMBER					ON NUMBER			
ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGOR	Y	ENCLOSURE	PRINCIPAL DOCUMENT	DATE 18SUED	SUBJEC CATEGO	
8210270320 8210270325 8210270332 8210270355 8210270360	9210270314 9210270319 9210270327 9210270352 9210270352	82/09/29 82/10/13 82/10/14 82/10/18 82/10/18	50-312 50-346 50-382 50-272 50-272	P M P P	8210280200 8210280201 8210280201 8210280205 8210280205	8210280174 8210280174 8210280176 8210280203 8210280211	81/04/03 82/10/25 82/10/25 81/04/14 82/10/22	50-318 50-277 50-277 50-317 50-275	8 P P 8
6210270366 8210270376 8210270382 8210270386 8210270387	8210270352 8210270373 8210270372 8210270372 8210270372	82/10/18 82/09/15 82/10/13 82/10/13 82/10/13	50-272 40-8824 50-346 50-346 50-346	P P P	8210280219 8210280224 8210280229 8210280232 8210280233	8210280215 8210280223 8210280223 8210280223	82/10/19 82/10/13 82/10/13 82/10/13 82/09/30	50-387 50-305 50-305 50-305 CONTRACT	8 0 0
8210270395 8210270402 8210270407 8210270413 8210270419	8210270393 8210270399 8210270403 8210270411 8210270416	82/10/12 82/09/13 82/10/20 82/09/30 82/09/30	CONTRACT CONTRACT CONTRACT 50-387 CONTRACT	x	8210280244 8210280248 8210280255 8210280257 8210280278	8210280241 8210280241 8210280247 8210280263 8210280275	82/10/12 82/10/12 81/04/23 81/04/16 82/10/22	50-397 50-397 50-317 50-317 50-324	0 0 5 B F
8210270427 8210270428 8210270429 8210270430 8210270432	8210270423 8210270425 8210270423 8210270426 8210270426	82/09/23 82/09/23 82/09/23 82/10/08 82/10/08		F F	8210280284 8210280293 8210280297 8210280298 8210280301	8210280277 8210280271 8210280286 8210280275 8210280276	81/04/03 82/10/22 82/10/22 82/10/21 81/04/16	50-318 50-250 50-460 50-266 50-317	SFOPS
8210270436 8210270437 8210270438 8210270439 8210270452	8210270434 8210270423 8210270423 8210270435 8210270448	82/10/12 82/09/23 82/09/23 82/09/03 82/09/27	70-1151 70-1510 70-1510 40-8681 XPORTLIC		02102803138 20102803158 21102803158 2110820158 9110920158	8210280287 8210280299 8210280305 8210280311 8210280310	82/10/14 82/10/05 81/04/10 82/10/01 82/10/05	50-275 CONTRACT 50-317 71-9057 CONTRACT	B
8210280017 8210280019 8210280020 8210280021 8210280024	8210280013 8210280014 8210280013 8210280013	82/10/12 82/07/17 82/10/12 82/07/17 82/09/17	F01A 50-369 50-324	F P P	8510580335 8510580331 8510580330 8510580351 8510580351	8210280013 8210280322 8210280324 8210280327 8210280318	82/09/17 82/10/01 82/10/14 82/10/05 81/05/12	FOIA 71-4346 50-279 CONTRACT 50-317	0
8210280027 8210280031 8210280036 8210280037 8210280041	8210280013 8210280033 8210280033 8210280033	82/09/17 82/09/17 82/10/08 82/10/08 82/10/08	50~336 50-322 50-322	P F F	8210280333 8210280337 8210280341 8210280342 8210280345	8210280329 8210280334 8210280336 8210280338 6210280343	82/10/01 82/09/17 81/04/17 82/09/17 82/09/21	71-6745 71-6677 50-318 71-6678 71-6119	ន
8210280042 8210280047 8210280048 8210280049 6210280051	8210280013 8210280013 8210280045 8210280046 8210280045	82/09/17 82/09/17 82/10/08 82/09/10 82/10/08	50-324 50-409 40-8745	P P F	8210280351 8210280354 8210280359 6210280354 8210280372	8210280348 8210280354 8210280357 8210280361 8210280368	82/10/26 82/10/05 82/07/16 82/10/12 82/10/13		RP F
8210280053 8210280055 8210280059 8210280061 8210280063	8210280045 8210280045 8210280056 8210280058 8210280058	82/10/08 82/10/08 82/10/04 82/10/08 82/10/08	50-409 XPORTLIC 50-255	F F F	8210280374 8210280375 8210280380 8210280383 8210280397	8210280370 8210280361 8210280378 8210280378 8210280386	82/10/07 82/10/12 82/10/12 82/10/12 82/10/15	50-315	F
8210280068 8210280074 8210280078 8210280082 8210280084	8210280066 8210280071 8210280075 8210280013 8210280080	82/10/19 82/10/20 82/10/19 82/09/17 82/10/19	50~213 50~346 50~261	S S S P S	8210280406 8210280408 8210280413 8210280417 6210280421	8210280402 8210280397 8210280397 8210280415 8210280415	82/09/30 82/10/12 82/10/12 82/10/14 82/10/14		F
8210280095 8210280100 8210280103 8210280110 8210280112	8210280013 8210280013 8210280094 8210280013 8210280108	82/09/17 82/09/17 82/10/15 82/09/17 82/10/12	50-250 50-29 FOIA	P P P	8210280424 8210280425 8210280427 8210280430 8210280432	8210280419 8210280423 8210280419 8210280428 8210280428	82/10/12 82/10/15 82/10/12 82/10/18 82/10/18	50-305 50-295 50-247	F F P P
8210280114 8210280120 8210280125 8210280124 8210280128	8210280108 8210280117 8210280122 8210280117 8210280123	82/10/12 82/10/12 82/10/22 82/10/12 82/10/15	50-313 50-295 50-373 50-295 50-311	F 0 F 8	8210280445 8210280447 8210280453 8210270003 8210270006	B210280442 B210280442 B210280452 B206270053 B206270053	82/10/12 82/10/12 82/09/21 82/10/04 82/10/04		
8210280131 8210280138 8210280141 8210280143 8210280145	8210280129 8210280136 8210280134 8210280136 8210280142	82/10/20 82/10/12 82/10/20 82/10/12 82/10/06	50-273 50-271 50-318 50-271 50-267	8 F 9 F 0	8210290027 8210290032 8210290036 8210290041 8210290043	8210270023 6210270023 8210270023 8210270038 8210270023	82/09/03 82/09/03 82/09/03 82/10/12 82/09/03	50~285	F F
8210280149 8210280150 8210280154 8210280154 8210280159	8210280142 8210280144 8210280148 8210280152 8210280148	82/10/06 82/10/20 82/10/12 82/10/15 82/10/12	50-247 50-293 50-3 50-311 50-3	9 8 8 8	8210270048 8210270051 8210270053 8210270053 8210270057	9210290023 9210290023 8210290023 8210290050 8210290054	82/09/03 82/09/03 82/09/03 82/10/23 82/10/13	50-142 FOIA 50-416	Q F B
8210280165 8210280168 8210280171 8210280174 8210280174	8210280158 8210280164 8210280164 8210280170 8210280170	82/10/25 82/10/13 82/10/13 82/10/13	50-348 50-282 50-282 50-461 50-461	P 0 0	8210270058 8210270060 8210270065 8210270066 8210270066	8210290023 8210290047 8210290023 8210290023 8210290062	82/09/03 82/10/08 82/09/03 82/09/03 82/10/13	FOIA FOIA	F B
8210280184 8210280186 8210280190 8210280195 8210280198	8210280180 8210280183 8210280185 8210280191 8210280194	82/10/21 82/10/22 81/04/08	40-7580 50-223 50-460 50-318 50-277	R Q S P	8210290047 8210290047 8210290071 8210290072 8210290077	8210270023 8210270043 8210270042 8210270068 8210270047	82/09/03 79/08/16 82/10/04 82/10/15 82/10/08	50-336 50-289	A P Q F

ACCESSION NUMBER				N NUMBER		
PRINCIPAL ENGLOSURE DOCUMENT		JECT FEGORY	ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGORY
8210290078 B210290075 8210290080 8210290075 8210290081 8210290073 8210290087 8210290083 8210290088 8210290047	82/10/22 50-2 82/10/19 50-3 82/10/25 50-4 82/10/15 50-2 82/10/08 50-1	866 S 116 S 270 S	6210270286 8210270270 8210270272 8210270301 8210270304	8210290284 8210290278 8210290289 8210290300 8210290300	82/10/21 82/10/24 82/10/19 82/10/08 82/10/08	50-375 S 50-358 Q 50-364 S 50-184 Q 50-184 Q
8210270087 8210270084 8210270070 8210270085 8210270073 8210270084 8210270074 8210270077 8210270077 8210270077	82/10/15 50-3 82/10/15 FOIA 82/10/15 50-3 82/10/14 50-3 82/10/22 50-3	1 122 Q 128 S	8210270313 8210270314 8210270320 8210270321 8210270322	621029030B 8210290310 8210290316 6210290317 6210290319	82/10/18 82/10/06 82/10/26 82/10/13 82/09/24	50-287 S 50-272 8 50-206 V 50-259 S 50-275 R
8210290104 8210290094 8210290107 8210290103 8210290113 8210290110 8210290128 8210290115 8210290130 8210290115	82/10/14 50-3 82/10/08 50-2 82/10/01 50-3 82/10/04 50-3 82/10/04 50-3	20 Q 124 P 187 P	8210270329 8210270331 8210270332 8210270334 8210270338	8210290326 8210290325 8210290311 8210290327 8210290335	62/10/14 62/10/15 62/10/25 62/10/12 82/10/21	50-321 \$ 50-325 \$ 50-416 \$ 50-321 \$ 50-395 \$
8210270131 8210270104 8210270132 8210270125 8210270133 8210270124 8210270136 8210270129 8210270137 8210270129	82/10/18 CONT 82/10/15 50-3 82/10/29 50-4 82/10/04 50-3 82/10/26 50-4	122 G 16 S 187 P	8210270339 8210270342 8210270344 8210270345 8210270347	8210290333 8210290336 8210290341 8210290340 8210290337	82/10/22 82/10/15 82/10/12 82/10/23 82/10/13	50-261 8 50-324 8 50-322 0 50-416 8 50-338 8
8210290143 8210290140 8210290144 8210290141 8210290146 8210290140 8210290148 8210290140 8210290157 8210290147	82/09/21 50-3 82/10/19 TOPR 62/09/21 50-3 82/09/21 50-3 82/10/08 50-2	EP 13 P 13 P	8210290391 8210290352 8210290356 8210290359 8210290361	8210270348 8210270346 8210270350 8210270347 8210270353	82/10/25 82/10/13 82/10/04 82/10/21 82/10/04	50-416 S 50-325 S 50-322 G 50-321 S 50-272 S
8210290163 8210290154 8210290173 8210290171 8210290175 8210290169 8210290180 8210290169 8210290183 8210290169	82/10/27 50-3 82/10/14 50-2 82/10/22 50-2 82/10/22 50-2 82/10/22 50-2	44 Q 06 P 06 P	8210270364 8210270365 8210270371 8210270372 8210270372	8210290357 8210290355 8210290368 8210290367 8210290373	62/10/07 62/10/14 62/10/15 62/10/13 62/10/12	50-366 S 50-269 S 50-259 S XPORTLIC 50-321 S
8210270194 8210270187 8210270197 8210270190 8210270207 8210270207 8210270207 8210270206 8210270210 8210270208	82/10/15 50-2 82/10/15 50-2 82/10/08 50-3 82/10/14 50-3 82/10/08 50-3	69 B 87 G 66 S	8210270380 8210270381 8210270385 8210270385 8210270385	8210290377 8210290374 8210290378 8210290378 8210290378	82/10/26 82/10/20 82/10/20 82/10/20	50-327 G 50-366 B 50-346 P 50-346 P 50-346 P
8210270217 8210270212 8210270218 8210270214 8210270222 8210270217 8210270227 8210270228 8210270232 8210270231	82/10/25 50-2 82/10/06 50-2 82/10/18 50-2 82/09/23 50-3 82/10/14 50-2	72 S 75 S 29 A	8210290392 8210290398 8210290416 8210290417 8210290418	8210270383 6210270376 6210270414 6210270413 6210270414	82/10/12 82/09/28 82/10/04 82/10/07 82/10/04	70-2944 CONTRACT 50-338 P 50-344 Q 90-338 P
8210290241 8210290238 8210290244 8210290243 8210290270 8210290244 8210290272 8210290262 8210290276 8210290264	82/10/14 70-3; 82/10/21 50-3; 82/10/22 50-3; 82/10/22 50-2;	24 8 90 8 21 8	8210270421 8210270422 8210270428 8210270431 8210270436	8210270414 8210270420 8210270412 8210270426 8210270426	92/10/04 92/10/08 92/09/23 92/10/04 92/10/04	50-338 P CONTRACT 50-317 P 50-266 P 50-266 P
8210290279 8210290277 8210290280 8210290275 8210290281 8210290278 8210290282 8210290244 8210290285 8210290278	82/10/14 50-3: 82/10/13 50-2: 82/10/24 50-3: 82/10/22 50-2: 82/10/26 50-3:	73 0 58 0 80 8	8210270437 8210270441 8210270444 8210270451 8210270454	8210270412 8210270426 8210270412 8210270447 8210270447	82/09/23 82/10/04 82/09/23 82/09/22 82/09/22	50-317 P 50-266 P 50-317 P 50-275 0 50-275 0

APPENDIX A

DEFINITIONS OF DOCKET 50 CATEGORIES

A. APPLICATION/CONSTRUCTION STAGE DOCUMENTS AND CORRESPONDENCE

This category follows the application from submission to the day preceding the issuance of an operating hoense. It includes all correspondence and documents with substantive technical content that do not fall into other specific categories. Included are

- 1. Application for construction permit
- 2. General Information submitted with construction permit application.
- 3 Amendments and changes to items 1 and 2
- 4. NRC questions, requests for additional information, and applicant responses
- 5. Correspondence and documents relating to unresolved design and construction issues.
- 6 Meeting announcements and summaries of meeting discussions on issues of item 5.
- 7. Correspondence regarding the Preliminary Safety Analysis Report (PSAR).
- 8. Information on laws and changes in regulations or policy that affect the status of the application (NEPA, Water Quality Improvement Act, Water Pollution Control Act, etc.).
- 9 Construction Permit, amendments, and correspondence relating to the construction permit.
- 10 Scheduling of license application submission or review.
- 11 Environmental review information
- 12. Application for operating license
- 13. General Information submitted with operating license application
- 14. Amendments and changes to items 12 and 13.
- 15. Correspondence regarding the Final Safety Analysis Report (FSAR).
- 16. Correspondence and documentation on generic technical matters highlighted by an event at another facility which may affect the subject facility, not covered by an IE Bulletin.
- 17. Reports of site visits.
- 18. Backup technical documents (e.g., topical reports) submitted in support of the application.

B. UTILITY PRELIMINARY SAFETY ANALYSIS REPORT (PSAR) AND AMENDMENTS

This category is strictly limited to the items listed below. All related correspondence is filed in Category A.

- 1. Preliminary Safety Analysis Report (PSAR) submitted by utility (formerly called Hazards Summary Report or Safety Analysis Report).
- 2. Amendments and changes to the PSAR.

C. UTILITY ENVIRONMENTAL REPORT (ER), AMENDMENTS AND CORRESPONDENCE

This category is strictly limited to the items listed below. Other environmental documents and correspondence are filed in Categories A, D, M, P or R.

- 1. Environmental Report (ER) submitted by the utility.
- 2. Amendments and supplements to the ER.
- 3. Transmittal and acknowledgement letters
- 4. Information on scheduling of submittal or review of ER.
- 5. NRC questions, requests for additional information, and applicant responses.
- 6. Federal register notices citing the availability of items 1 and 2.
- 7. Correspondence relating to the review of ER.
- 8. Meeting announcements or reports of meetings where the primary subject of discussion is the ER.

D. NRC DRAFT AND FINAL ENVIRONMENTAL (IMPACT) STATEMENTS (DES AND FES), SUPPLEMENTS AND CORRESPONDENCE

This category is strictly limited to the items listed below. Other environmental documents and correspondence are in categories A, C, M, P or R.

- 1. Draft and Final Environmental (Impact) Statements (DES and FES) prepared by the NRC.
- 2. Supplements to the DES and FES.
- 3. Correspondence relating to the DES and FES.
- 4. Comments from other federal, state and local government agencies.
- Transmittal and acknowledgement letters.
- 6. Documents related to NRC review of environmental issues or of ER obtained for purposes of writing the environmental statements.

- 1. Satety Evaluation Report (SER) prepared by the NRC (formerly called NRC-AEC Hazard Analysis Report).
- 2. Supplements to SER.
- 3. Correspondence relating to SER.
- 4. Federal register notices citing availability of items 1 and 2.
- 5. Information on scheduling of SER submittals and review.
- 6. Requests for additional information for use in preparing SER; responses to such requests.
- 7. Meeting announcements or reports of meetings where the primary subject of discussion is the SER.
- 8. Transmittal and acknowledgement letters.

F. SECURITY, MEDICAL, EMERGENCY AND FIRE PROTECTION PLANS

All plans in this category are individual submissions. Information submitted as part of the PSAR or FSAR is excluded

- 1. Fire Hazard Protection Plan and surveys.
- 2. Plant evacuation correspondence.
- 3. Safeguards Contingency Plans.
- 4. Review of Health Physics Program.
- 5. Correspondence relating to aforementioned plans.
- 6. Supplements, changes and revisions to plans.

G. LEGAL AND ADJUDICATORY CORRESPONDENCE

This category contains all non-antitrust legal and adjudicatory documentation, except for transcripts, briefings and testimony, which are filed in category T.

- 1. Atomic Safety and Licensing Board (ASLB) and Atomic Safety and Licensing Appeal Board (ASLAB) hearing related documents.
- 2. Federal register notices regarding hearings.
- 3. Requests to make appearances at hearings,
- 4. Motions, briefs, arguments, statements and related correspondence filed by participants for hearings.
- 5. Transmittal of supporting documents (e.g., SER, FES) to the boards.
- 6. Correspondence to and from intervenors.
- 7. Board orders and decisions.
- 8. Petitions for Commission action.
- 9. Legal filings and Commission orders and decisions resulting from item 8.

This category includes documents with little or no bearing on the status of the application or license. Items that have no substantive technical content or meaning for the status of the license or application are included.

- 1 Change of address notifications
- 2 Changes in structure of organization.
- 3. Changes in service lists.
- 4. NRC requests to applicant for additional copies of documents.
- 5. Correspondence from the public requesting information about the facility and NRC responses.
- 6. Correspondence on strictly administrative matters.
- 7. Letters of support, concern or opposition to the facility.
- 8 Correspondence regarding the Local Public Document Rooms (LPDRs).
- 9. Professional qualification statements not pertaining to the hearing process.

I. FINANCIAL INFORMATION

This category contains all financial information except that submitted as part of the application or its amendments or relating to the imposition of civil penalties.

- 1. Company annual reports.
- 2. Separately submitted financial information and related correspondence.

J. INSURANCE AND INDEMNITY INFORMATION

- 1. Indemnity agreements and amendments.
- 2. Endorsements insurance policies.
- ² Other correspondence regarding indemnity and insurance matters.

K. UTILITY FINAL SAFETY ANALYSIS REPORT (FSAR) AND AMENDMENTS

This category is strictly limited to the items listed below. All related correspondence falls in category A or P.

- 1. Final Safety Analysis Report (FSAR) (formerly called Final Hazards Summary Report).
- 2. Amendments and changes to the FSAR.
- 3. Federal register notices citing availability of items 1 and 2.
- 4. Transmittal and acknowledgement letters.
- 5. Certificates of service to the FSAR.

L. LIMITED WORK AUTHORIZATION (LWA) AND RELATED CORRESPONDENCE

This category is limited to documents pertaining to Limited Work Authorizations (LWA) whereby applicants can carry out limited site preparation and construction prior to the granting of a construction permit

- 1. Limited Work Authorizations (LWA) and amendments.
- 2 Correspondence pertaining to work performed under LWAs.

M. ANTITRUST REVIEW AND ANTITRUST CORRESPONDENCE

- 1. Document submitted as part of the applications for a construction permit and operating license entitled "Information Requested by the Attorney General for Antitrust Review".
- 2 Correspondence where the primary topic of discussion is antitrust matters
- 3. All antitrust proceeding related documents except for hearing transcripts, testimony and briefings, which are filed in category N

N. ANTITRUST HEARING TRANSCRIPTS, TESTIMONY AND BRIEFINGS

This category contains word-for-word transcripts of hearings, testimony and briefings in antitrust matters. Related correspondence falls in category M.

O. ADVISORY COMMITTEE ON REACTOR SAFEGUARDS (ACRS) REPORTS AND CORRESPONDENCE

- Correspondence and letter reports relating to Advisory Committee on Reactor Safeguards (ACRS) reviews
- 2 Correspondence from ACRS
- 3 Announcement of ACRS meetings
- 4 Transmittal and acknowledgement letters
- 5. ACRS reports.
- 6. Statements and written testimony by ACRS members or presented by individuals at ACRS proceedings.
- 7 Minutes at ACRS Subcommittee Meetings.

P OPERATING LICENSE STAGE DOCUMENTS AND CORRESPONDENCE

This file assumes the position of the Application/Construction Stage (category A) file for general technical items dated from the issuance of the operating license to the application for termination of the license

- 1. Operating license, amendments, proposed amendments, changes and related correspondence.
- 2. Technical specifications and changes.

TOPE , OF INVITIO I BING A

- 4. Federal register notices citing availability of items 1 and 2.
- 5. Correspondence regarding the Final Safety Analysis Report (FSAR).
- All general technical correspondence, meeting announcements or meeting summaries relating to technical specifications, the operating license or technical issues arising after the issuance of the operating license.
- 7. Correspondence regarding codes (e.g., ASME), regulations, laws or changes in policy that may affect plant operation or bear on the operating license
- 8. Information on the Standard Review Plan (STP).
- 9. Results of surveys or tests conducted in accordance with the technical specifications (not periodic reports, which fall in category R).
- 10. Correspondence relating to NRC's Systematic Evaluation Program (SEP).
- 11. Owner's group meeting announcements and reports.
- 12. Quality assurance information
- 13. Environmental matters (technical).
- 14. Emergency core cooling system documents.
- 15. Radioactive waste information.
- 16. Correspondence regarding expansion of spent fuel storage pool.
- 17. Start-up test reports.
- 18. Correspondence and documentation on generic technical matters highlighted by an event at another facility which may affect the subject facility; not covered by an IE Bulletin.
- 19. Reports of site visits.

Q. INSPECTION REPORTS; IE BULLETINS, CIRCULARS AND INFORMATION NOTICES; CIVIL PENALTIES AND RELATED CORRESPONDENCE

- 1 Inspection reports.
- 2. IE Bulletins (formerly called Regulatory Operations (RO) Bulletins), Circulars and Information Notices.
- 3. Responses by applicant to IE correspondence.
- 4. Applicant's determination of proprietary nature of inspection reports.
- 5. Letters concerning areas of noncompliance.
- Pre-service and in-service inspections and procedures.
- 7. Correspondence and orders relating to imposition and payment of civil penalties, including Notification of Significant Enforcement Actions (EN s).
- 8. Any correspondence relating to inspection and enforcements that does not specifically relate to incidents or events as defined in category S.

R. PERIODIC OPERATING REPORTS AND RELATED CORRESPONDENCE

This category includes periodic reports of a routine nature

- Monthly, semiannual, or annual operating reports (other than financial).
- 2. Periodic environmental monitoring, effluent testing, or similar reports.
- 3. Periodic personnel exposure reports.
- 4. Operational Logbooks

Logbooks on Environmental Data Logbooks on Radiological Data Operations Log on Plant Systems Core Plant Status Summary Sheets

5. Correspondence or other documents relating to the above listed items.

S. REPORTABLE OCCURRENCES, PNOS, PNSs AND RELATED CORRESPONDENCE

This category contains all materials relating to abnormal, unusual, reportable or nonroutine occurrences or events. This includes

- 1. All 24-hour, 10-day, 30-day, interim and final Licensee Event Reports (LER s) and follow-up correspondence (also called incident reports, abnormal occurrence reports and reportable occurrences)
- 2. Potential or possible reportable deficiency reports and related correspondence.
- 3. Personnel exposure reports
- 4 Construction deficiency reports submitted under 10 CFR 50.55e.
- 5. Preliminary Notification of Occurrence (PNO s) and Preliminary Notification of Safeguards Events (PN s)
- 6. Environmental Technical Specifications violation reports and Environmental Eyent reports.
- 7. Part 21 Reports of defects and noncompliance.
- 8. Correspondence or other documents relating to items 1-7.

T. TRANSCRIPTS, TESTIMONY AND BRIEFINGS ON NON-ANTITRUST MATTERS

This category contains all word-for-word transcripts, except for antitrust matters (category N), testimony and briefings, and congressional matters (category U).

- 1. Atomic Safety and Licensing Board (ASLB) and Atomic Safety and Licensing Appeal Board (ASLAB) transcripts.
- 2. Testimony and statements submitted to ASLB and ASLAB.
- 3. Commission meeting transcripts.
- 4. NRC staff briefings to the Commission.
- 5. Statements and written testimony submitted at Commission meeting or hearings.
- 6. Transcripts of utility briefs to NRC staff.
- 7. Advisory Committee on Reactor Safeguards (ACRS) meeting transcripts.

U. CONGRESSIONAL/EXECUTIVE CORRESPONDENCE

This category contains correspondence on substantive matters. Routine responses to constituent inquiries are filed in category H.

- 1. Statements and testimony before Congress or before bodies/committees appointed by the Executive or Legislative Branches
- 2. Preparatory and backup documents for item 1.
- 3. Correspondence to and from NRC Office of Congressional Affairs, Congress and the Executive Branch on other than constituent response matters

V. LICENSING OPERATORS AND RELATED CORRESPONDENCE

- 1 Operator licenses or administrative information bearing on licensing of operators.
- 2 NRC examination results.
- 3 Power plant examination summary sheet.

W. DECOMMISSIONING STAGE DOCUMENTS AND CORRESPONDENCE

This file assumes the position of the Operating License Stage (category P) file for general technical items from the application for termination of the operating license onward.

- 1. Application for authority to voluntarily surrender license.
- 2. Application to dismantle the facility and dispose of component parts.
- Technical documents submitted in support of items 1 and 2, such as: Decommissioning Plan,
 Dismantling Plan, Environmental Report on Dismantling, Safety Analysis Report on Decommissioning.
- 4 Documents relating to disposal of radioactive material and decontamination of the site,
- 5. Other correspondence relating to above items,
- 6. All documentation relating to the ongoing operation of the plan, formerly filed in category P.

X. ONSITE LOW-LEVEL WASTES STORAGE

This category contains items related to the onsite storage of low-level radioactive wastes generated onsite.

APPENDIX R

DEFINITIONS OF NONDOCKETED CATEGORIES

10CFR - Commission Meeting Records

This category contains documentation pertaining to open and closed Commission meetings. It includes:

- 1. Sunshine Act Federal Register notices.
- 2. Full, written explanation of closed meetings.
- 3. Certification of General Counsel on closed meetings.
- 4. Commission Determination Statements regarding the public disclosure of transcripts of Commission meetings.
- 5. Verbatim unofficial and official transcripts or portions of transcripts of open and closed Commission meetings made publicly available in accordance with provisions of 10CFR Part 9, the Sunshine Act, and Commission policies.
- 6. Enclosures to released transcripts, including applicable viewgraphs, staff papers, and staff correspondence.
- 7. Staff requirements memoranda for open meetings; memoranda to record, record of votes of Commissioners on items under consideration at meetings

ACRS - Advisory Committee on Reactor Safeguards

This category contains documentation pertaining to the responsibilities of the Advisory Committee on Reactor Safeguards. ACRS serves as an independent advisory committee to the Commission in safety-related areas. The committee provides advice with respect to the hazards of new or existing nuclear facilities and the adequacy of related safety standards. The documents in this category are:

- 1. Verbatim transcripts of ACRS subcommittee and full committee meetings relating to facility license applications and safety-related matters.
- 2. ACRS meeting announcements; description of meeting agendas.
- 3. ACRS-generated reports, memoranda and correspondence that are publicly available.
- 4. ACRS consultant reports, comments and related correspondence.
- 5. ACRS and NRC technical correspondence pertaining to safety matters under review by the Advisory Committee on Reactor Safeguards.

COMMISSION - NRC Commissioners

This category contains documentation pertaining to the daily conduct of Commission business in the Office of the Commissioners, including

1. Incoming and outgoing correspondence to and from the Commissioners relating to official NRC business, including reports and other enclosures.

 Weekly Information Reports (SECY series number) prepared by the Executive Director for Operations (EDO) for the Commissioners, providing a summary of key events and items of interest undertaken by individual staff and program offices.

NOTE. For transcripts of Commission meetings, see 10CFR category. For all other staff papers with a SECY series designation prepared for Commission review, see SECY category.

CONTRACT - NRC Contracts and Modifications

This category contains documentation pertaining to AEC and NRC contracts and Interagency Agreements, including:

- 1. Notifications of issuance of request for proposal (RFP) and invitations for bid (IFB).
- 2. Solicitations (RFP or 1FB) issued by the NRC.
- 3. Notifications of contract execution, specifying contract number, project title, contractor name, contract type, funding, and period of performance.
- 4. Contractual documents and contract modifications, if any.

DISCLOSURE - Financial Disclosure Information

This category contains financial disclosure information in accordance with the Ethics in Government Act of 1978.

FOIA - Freedom of Information Act Requests and Releases

This category contains requests for agency records and records released in accordance with the provisions of the Freedom of Information Act (FOIA). Documents in this category include:

- 1. Requests made by any member of the public (assigned an identifying number YY-NNN for last two digits of the year—numerical sequence) for NRC records made in accordance with the provisions of the Freedom of Information Act.
- Correspondence between the NRC and the requester relevant to the processing, appeal, denial or granting of an FOIA request.
- 3. Records or portions of records released in response to specific requests made under FOIA.

GEN TECH IS - Generic Technical Issues

This category contains records pertaining to unresolved safety issues of a generic nature that are being analyzed by the Division of Nuclear Reactor Regulation.

- 1. Draft reports of action plans to accomplish generic tasks in the regulatory program.
- 2. Correspondence with industry and internal correspondence regarding the methodologies, analyses, and programmatic and technical aspects of issues.

- 3. Meeting notifications and minutes.
- 4. Interim findings and status reports on generic tasks addressing related aspects of generic technical issues.

I&E - Inspection and Enforcement

This category contains bulletins, circulars and information notices that are issued by the Office of Inspection and Enforcement. These issuances describe particular events that occur at a facility that may require some follow-up action on the part of licensees. Also included in this category are preliminary notifications of events (PNOs).

- 1. I&E Circulars, which describe an event at a licensed facility and are informational in nature.
- 2. I&E Information Notices, which are similar to circulars but are preliminary in nature and issued shortly after an event has occurred.
- 3. I&E Bulletins, which describe an event at a licensed facility and request all recipients to perform certain actions as a result of this event.
- 4. Preliminary Notifications of Events (PNOs), which provide updated information of an event of safety or public interest significance.

NOTE: For letters forwarding the above issuances, utility responses to such issuances, and related correspondence, see Category Q of individual docket categories.

MISC - Public Document Room Miscellaneous

This category contains documents that do not fall into the scope of the other nondocketed categories.

NUREG - NUREG Reports and Related Correspondence

These documents are formal reports issued by the U.S. Nuclear Regulatory Commission which carry the NUREG series code and correspondence pertaining to those reports. NUREG reports are accounts of work performed either by the NRC staff or by NRC contractors.

- 1. These reports are normally final work products and are characterized by the following criteria:
 - a. They are predecisional documents which present information to be considered in Commission licensing and policy decisions.
 - b. They present the results of Commission licensing and policy decisions.
 - c. They present the results of technical research conducted for the Commission.
- 2. Correspondence from industry, government and interested members of the public commenting on reports or requesting clarification or interpretation.
- 3. Internal NRC memoranda summarizing meetings or discussions pertaining to the content of the reports.

This category contains correspondence with professional organizations and associations; records other than Regulatory Guides that pertain to the activities of NRC's Office of Standards Development, and emergency petitions not assigned Petition for Rulemaking (PRM) numbers that request the Commission to take immediate action on some issue. Included are

- 1. Meeting summaries and technical correspondence between NRC and professional associations and international bodies, such as the Atomic Industrial Forum and the International Atomic Energy Agency.
- 2. Correspondence between NRC's Office of Standards Development and other government agencies in which both parties have joint regulatory responsibility, e.g., EPA has authority to control all radioactive pollutants emitted into the air.
- 3. Internal memoranda, correspondence between NRC and Congress, and other technical correspondence dealing with the role and activities of the Office of Standards Development.
- 4. Statements, motions, orders and correspondence dealing with emergency petitions filed by parties on such topics as fire protection and re-analysis of the capacity of operating U.S. plants to withstand earthquakes.

NOTE: For Regulatory Guides and comments to Regulatory Guides issued by the NRC Office of Standards Development, see the REGGD category.

For petitions for rule makings filed by the public to amend, rescind or change an NRC regulation, see the PRM category.

PR - Proposed Rule

This category contains records dealing with NRC staff proposals to adopt, amend or repeal a Commission regulation. Proposed Rules (PRs) are normally the result of a Commission determination that sufficient grounds exist for it to proceed with a petition for change in an NRC regulation (PRM) filed by an outside party or person. The documents in this category are:

- 1. Federal Register notices stating the terms or substance of the proposed rule or a specification of the subject and issues involved.
- 2. Text of the Proposed Rule (PR),
- 3. Comments, statements, information, opinions or arguments on the proposed change to a part of the Code of Federal Regulations, Title 10.
- Requests from the nuclear industry, organizations and other parties for written interpretations
 of the PR.

PRM - Petition for Rulemaking

This category contains records dealing with petitions filed with the Commission by an outside party to issue, amend or rescind an NRC regulation. Included are:

- Petitions filed by any interested person or party to issue, amend or rescind an NRC regulation.
- 2. Federal Register cause notices of the filing of the petition.

- o. Correspondence between NRC and the petitioner regarding the status and substance of the petition.
- 4. Comments from the nuclear industry, professional associations, public interest groups and others in favor of or in opposition to the PRM.

NOTE For staff recommendations to the Commissioners on whether the PRM should be denied or issued as a Proposed Rule, see the SECY category.

For Commission review of staff recommendations, see the 10CFR category.

PROJ - Projects-Predocket Licensing

This category contains records pertaining to two classes of projects (1) commercial nuclear power plants for which NRC has full licensing responsibilities, and (2) government-owned reactors for which NRC provides technical expertise and occasional review. Both classes are identified with a "P" prefix, followed by a series of numbers.

l. "Pre-docketed" commercial nuclear power plants

This category contains all documentation up until the time that the NRC considers the application and the Preliminary Safety Analysis Report (PSAR) is submitted by the utility for staff review. The unit is then assigned a docket number, and transferred to the Docket 50 category.

These documents are grouped together in categories, designated by alphabetic characters. These are the same categories as those used for the Docket 50 series.

- A. Application/Construction Stage
 - 1. Application submitted by the utility.
 - 2. Meeting notices, summaries and correspondence discussing the completeness and adequacy of the PSAR.
 - 3. Applicant's Quality Assurance Manual.
 - 4. Early site review information.
 - 5. Backup technical documents submitted in support of the application.
 - 6. Early site visits.
- B. Utility PSAR and Amendments
 - 1. PSARs submitted by the utility.
 - 2. Amendments and changes to the PSAR.
 - 3. Transmittal letters.
 - 4. Letters acknowledging receipt of the PSAR.
- G. Adjudicatory Correspondence
 - 1. Motions, briefs, orders, et al. pertaining to pre-hearing conferences, if any.
- M. Antitrust Correspondence
 - 1. Submittals and related material pertaining to the antitrust review.

- Inspection reports of the applicant's quality assurance program.
- Notices of deviations.
- 3. Follow-up correspondence resolving deviations cited.

Government-owned reactors

Meeting summaries and technical correspondence between NRC and other government technical personnel related to test reactors, critical experiments, and DOD reactors on navy ships and other sites.

PT21 - Noncompliance Reports and Related Correspondence

Deficiency reports are performed in compliance with Part 21 of Title 10 of the Code of Federal Regulations and include.

- 1. Reports by firms involved in the nuclear industry concerning noncompliance with NRC regulations or the existence of defects which could create a substantial safety hazard.
- 2. Correspondence pertaining to the NRC review of reports to assess the possibility of generic defects.
- 3. NRC inspection reports of defects cited
- 4. Correspondence specifying appropriate follow-up actions taken by the Agency.

QA999 - Quality Assurance Inspections

This category contains inspection reports of vendors' quality assurance programs and follow-up correspondence. Each vendor facility is assigned a docket number and is part of the QA999 series.

Vendors are defined here as companies, both U.S. and foreign, that are engaged in the design or the manufacture of nuclear components for plants licensed by NRC. QA comprises all those planned and systematic actions necessary to provide adequate confidence that a structure, system or component being manufactured will perform satisfactorily once it is put in service. The controlling e 10 CFR Part 50, Appendix B, vendor QA topical reports, and the PSAR and FSAR by utilities for specific facilities. Documents in this category include:

ection reports, conducted on a quarterly or semi-annual basis, of vendor sites. Inspecover the design, fabrication, construction and testing of structural systems and

ns.

3. Vendor corrective actions and other follow-up correspondence associated with the resolution of inspection findings.

REGGD - Regulatory Guides

This category contains new and revised regulatory guides issued by the Commission and related correspondence. These guides describe for the industry and the public methods acceptable to the NRC by the staff in evaluating specific problems or postulated accidents, or provide guidance to applicants. Included are.

- 1. Federal Register notices announcing the issuance and availability of a proposed regulatory guide.
- 2. Revised or newly issued Regulatory Guides.
- 3. NRC value/impact assessment and industry codes, when applicable, that pertain to the issuance of a specific Regulatory Guide.
- 4. Comments submitted by the nuclear industry and interested members of the public regarding a proposed Regulatory Guide.
- 5. Summary of meetings held in the NRC to discuss proposed Regulatory Guides.

NOTE: For documentation pertaining to other work products and activities of the NRC Office of Standards Development, see the Organization category.

RES - Research and Technical Assistance Reports

This category contains reports, generally of an interim nature, submitted by NRC contractors providing research and technical assistance to the Commission. It also includes documentation pertaining to research activities of the Commission. Included are:

- 1. Project description documents.
- 2. Letter reports of accomplishments and data reports; for example,
 - a. model documentation reports
 - b. code documentation reports
 - c. code verification reports
- 3. Pre-test prediction reports.
- 4. "Quick look" reports.
- 5. Informal experimental data reports and post-irradiation examin
- 6. Conceptual design descriptions.
- 7. Letter reports of foreign travel and site visits by cont
- 8. Letter, monthly, quarterly, interim or annual status or projects contracted for by the NRC.
- Meeting summaries and correspondence dealing with to and technical assistance contracts.
- 10. Staff Research Information Letters (RILs) transmitting pleted research programs.

NOTE: For final reports of research conducted by contracto

REVIEW GRP - NRC Research Review Groups

This category contains records pertaining to the activities of N groups provide a broad base of technical expertise to aid mana

projects, new research projects, and priorities within the technical areas covered by the research review group. Documents in this category are:

- 1. Agendas for quarterly review group meetings.
- 2. Summary numutes of review group meetings representing views expressed, including dissenting views.
- 3. Research plans and predicted results of major experiments; presentations by research contractors.
- 4. Comments on meetings from attendees, including representatives from contractors, universities, vendors and other agencies.
- 5. Internal memoranda relating to topics under discussion.

RM - Rulemakings

This category contains records pertaining to public hearings held on proposed changes (PRs) to the Commission's regulations. Hearings are instituted at the discretion of the Commission based on the importance and the magnitude of the subject under consideration. Documents in this category include:

- 1. Designations of the presiding officer and any special directions for the conduct of the hearing.
- 2. Notifications of hearing board meetings
- 3. Petitions, motions, testimony and statements submitted by parties to the hearings.
- 4. Hearing board orders and rulings.
- 5. Technical reports submitted as evidence in the proceeding.
- 6. Reports, if any, of the special board to the Commission regarding a rulemaking proceeding.

SECY - Position Papers Before the Commission

This category consists of staff papers prepared for the information or approval of the Commissioners which are assigned a SECY report series code. Included are:

- Commission Action papers, which normally include alternatives and recommendations by the staff on a given issue and require Commission action.
- 2. Consent Calendar items and Policy Session items.

NOTE: For Weekly Information Reports prepared by EDO to the Commissioners providing a summary of key events and items of interest undertaken by staff and program offices, see the NRC Commissioners category.

STATE PROG — State Programs

This category contains records that pertain to the Commission's activities and interaction with State governments. Areas covered include: (1) the State Agreements Program, whereby States may assume certain of the NRC's regulatory authority over nuclear materials; (2) the Agency's role in assisting

of haison and cooperative activities regarding such functions as licensing and siting. It includes.

- 1. Correspondence between and among NRC Office of State Programs and State officials, mostly State haison officers, regarding
 - a. cooperative programs in such technical areas as radiation control, emergency response planning to radiological incidents, water quality and transportation surveillance.
 - b technical assistance to Agreement States in reviewing applications, compliance actions, developing regulations, and other areas.
- 2. Agendas, reports and transcripts of regional workshops and training programs on current matters of policy and regulations, i.e. decommissioning and facility siting.
- 3. State Legislative Reports.
- 4 Agreement State Licensing Statistics Reports

NOTE For specific uranium milling and mining projects in which the Agency is providing technical assistance to States, see the Projects category.

TOPREP - Vendor Reports and Related Correspondence

This category contains topical reports, generally of a technical generic nature, submitted by vendors, and correspondence pertaining to the NRC review of these reports. General vendor related correspondence that is not docket specific is also included in this category.

- 1. Topical reports, dealing with such technical matters as specifications, testing and safety submitted by architect, engineers and other vendors
- 2. Revisions, modifications and amendments to topical reports.
- 3. Correspondence between NRC and vendors pertaining to the review of submittals.
- 4. Meeting agendas, summaries, minutes and correspondence pertinent to vendor activities, programs, methodologies and design criteria.

NOTE For reports submitted by utilities that are written by vendors on their behalf and that relate to docketed cases, see the categories for the Docket 50 series.

WASTE MGT - Nuclear Waste Management

This category is topical in nature and contains records dealing with the activities of the NRC Division of Waste Management. Each topic has been assigned a number, with the series designated by a WM prefix. These documents deal primarily with NRC's interaction with DOE and its future role in licensing and regulating DOE facilities designed for the disposal of high-level waste in geologic repositories. This category will be enlarged later to include records dealing with low-level waste issues and tasks. The documents in this category are

- 1. Meeting agenda and minutes of DOE/NRC meetings in which DOE presents information on their geological exploration program to identify sites for nuclear waste repositories.
- 2. Briefings by DOE on research being conducted on spent fuel storage and nuclear waste management.

in the waste isolation Pilot Plan (WIPP) for burial of defense wastes.

4. NRC draft staff guides for developing positions on the content and format of environmental reports for geological repositories.

XPORTLIC - Export and Import Licenses

This category contains records relating to the issuance of licenses to export or import nuclear facilities and materials. Included are:

- 1. License applications and amendments to export or import special nuclear material, source material, byproduct material, reactors, nuclear facility components or reactor materials.
- 2. Correspondence between NRC and applicant or licensee pertaining to the review or status of a pending application or license amendment.
- 3. Commission letters requesting Executive Branch views.
- 4. Review and findings of the Executive Branch on whether issuance of a license would be inimical to U.S. common defense and security.
- 5. Correspondence from foreign governments, international organizations, and members of the public.
- 6. Staff position papers (SECY series code) prepared for Commissioners review of import or export licenses.
- 7. Filings pursuant to hearing requests or intervention petitions, if any.
- 8. Hearing records and decisions.
- 9. Memoranda from the Office of the Secretary to the Executive Director for Operations regarding the Commission decision on issuance of a proposed license.
- 10. Licenses, license amendments and license renewals for types specified in item 1.

NOTE: For transcripts of Commission meetings and papers submitted for Commissioner consideration or information, see 10CFR category.

NRC FORM 335 US NUCLEAR REGULATORY COMMISSION BIBLIOGRAPHIC DATA SHEET	1 REPORT NUMBER (Assigned by DDC) NUREG-0540 Vol. 4, No. 10
4 TITLE AND SUBTITLE (Add Volume No. 11 sopropriate) Title List of Documents Made Publicly Available	2 (Leave blank)
October 1-31, 1982	3 RECIPIENT'S ACCESSION NO
7 AUTHORISI	5 DATE REPORT COMPLETED MONTH YEAR
PERFORMING ORGANIZATION NAME AND MAILING ADDRESS (Include Zigno Division of Technical Information and Document (Office of Administration U.S. Nuclear Regulatory Commission Washington, DC 20555	Control DATE REPORT ISSUED MONTH YEAR January 1983 6 (Leave blank)
2 SPONSORING ORGANIZATION NAME AND MAILING ADDRESS HINCLUDE ZIE	
Same as 9, above.	11 FIN NO
3 TYPE OF REPORT PE	RIOD COVERED (Inclusive dates)
Monthly	
5. SUPPLEMENTARY NOTES	14 (Leave olank)
This document is a monthly publication containing received and generated by the U.S. NRC. This into material associated with civilian nuclear power pactive materials, and (2) nondocketed material repertinent to its role as a regulatory agency. The Personal Author Index, Corporate Source Index, Reference to Principal Documents Index.	ormation includes (1) docketed plants and other uses of radio- eceived and generated by NRC ne following indexes are included:
KEY WORDS AND DOCUMENT ANALYSIS 174	DESCRIPTORS
b IDENTIFIERS'OPEN ENDED TERMS	
AVAILABILITY STATEMENT	19 SECURITY CLASS (This report) 21 NO OF PAGES Unclassified 20 SECURITY CLASS (This new) 22 PRICE
11 1 2 m 3 + 6 d	• • •

Unlimited